Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

December 1-31, 1982

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Alphabetic Arrangement of Docket Items by Facility Name xv
Docketed Items
Low Level Radwaste Disposal Sites — Docket 27 1
Domestic Licensing of Source Material — Docket 40 1
Domestic Licensing of Production and Utilization Facilities — Docket 50
Domestic Licensing of Special Nuclear Material — Docket 70
Packaging of Radioactive Material for Transport and Transportation of
Radioactive Material Under Certain Conditions — Docket 71
Licensing of Independent Spent Fuel Storage — Docket 72
Nondocketed Items
10 CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues
I&E — Inspection and Enforcement
MISC — Public Document Room Miscellaneous
NUREG — NUREG Reports and Related Correspondence
ORG — Correspondence with Other Organizations
PR — Proposed Rule 404
PRM — Petition for Rulemaking
PROJ — Projects - Predocket Licensing 406
PT 21 — Noncompliance Reports and Related Correspondence
QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides 408
RES — Research and Technical Assistance Reports
REVIEW GROUP — NRC Research Review Groups 411
SECY — Position Papers Before the Commission 411
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASTE MGT Nuclear Waste Management
XPORTLIC — Export and Import Licenses
Personal Author Index 423
Corporate Source Index 453
Report Number Index
Cross Reference of Enclosures to Principal Documents
Appendix A — Definitions of Docket 50 Categories
Appendix B — Definitions of Nondocketed Categories B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:


- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- 1. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence



- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR - Proposed Rule

PRM — Petition for Rulemaking

PROJ -- Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES - Research and Technical Assistance Reports

REVIEW GRP -- NRC Research Review Groups

RM - Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASH - Regulatory Publications-Pre-NUREG Series

WASTE MGT -- Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1) NUREG—NUREG Reports and Related Correspondence

2
8203090207 NUREG/CR-1672 V02
RISK ASSESSMENT METHODOLOGY DEVELOPMENT FOR WASTE ISOLATION
IN GEOLOGIC MEDIA. Technical Review of Documents
NUREG/CR-1262, NUREG/CR-1376, NUREG/CR-1377, NUREG/CR-1397 &
NUREG/CR-1608.

5) STEVENS, C.A., FULLWOOD, R.A., BASIN, S.L. Science Applications, Inc.
FIN B-6694. SAI-262-81-PA. 82/02/28. Division of Risk Analysis.

123 p. Available at NRC. \$6,00. 12176:217.

- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order

3. The address for the PDR is

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Ra	dwaste Disposal Sites — Docket 27		40-8102	Exxon Co USA, Houston, TX	6
27-039	Sheffield, IL, U.S. Ecology, Inc	1	40-8135	Minnesota Mining & Manufacturing,	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40.0000	St. Paul, MN	
27-048	Richland, WA, US Ecology, Inc	1	40-8200	Cleveland-Cliffs Iron Co , Casper, WY	6
			40-8348	Minerals Exploration Co., Los Angeles, CA	6
Domestic Lice	nsing of Source Material — Docket 40		40-8355	Amax Speciality Metals Corp., Parkersburg, WV	6
40-0017	Dow Chemical Co., Midland, MI	ı	40-8380	Rocky Mountain Energy Co , Broomfield, CO	6
40-0086	W. R Grace & Co., Pompton Plains, NJ	1	40-8452	Bear Creek Uranium Co, Casper, WY	6
40-0299	Union Carbide Corp, Grand Junction, CO	1	40-8511	Cotter Corp., Golden, CO	6
40-1162	Western Nuclear Corp., Jeffrey City, WY	1	40-8584	Minerals Exploration Co , Los Angeles, CA	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8602	Silver King Mines, Inc., Casper, WY	7
40-1478	Spencer Chemical Co , Kansas City, MO	2	40-8610	Stepan Chemical Co , Maywood, NJ	7
40-1606	Vitro Engineering Co.	2		Energy Fuels Nuclear, Inc., Denver, CO	7
40-2061	Kerr-McGee Chemical Corp.,	2	40-8681	-	7
40.0116	Oklahoma City, OK	2	40-8697	Rocky Mountain Energy Co , Denver, CO	
40-2116	Vitro Engineering Co.	2	40-8698	Plateau Resources, Ltd., Grand Junction, CO	7
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	7
40-3265	Vitro Engineering Co.	3	40-8743	Conoco, Inc., Denver, CO	7
40-3392	Allied Chemical Corp., Morristown, NJ	3	40-8745	Ogle Petroleum, Inc., Casper, WY	8
40-3453	Atlas Mineral, Inc., Denver, CO	3	40-8752	Pinal Minerals & Mining, Ltd., Miami, AZ	8
40-4492	Federal-American Partners, Riverton, WY	3	40-8768	Kerr-McGee Nuclear Corp.,	
40-6500	Energy, Dept. of, Canonsbug, PA	3	10 0100	Oklahoma City, OK	8
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	5	40-8771	Melapai Resources Co , Phoenix, AZ	8
40-6659	Getty Oil Co Petrotomics Co., Shirley Basin, WY	5	40-8781	Teton Exploration Drilling Co., Inc. Casper, WY	8
40-6940	Kawecki Berylco Industries, Inc.,	_	40-8783	Uranerz USA, Inc., Casper, WY	8
40-7086	Boyertown, PA Army, Dept. of, White Sands, NM	5 5	40-8786	Uranium Resources, Inc., Richardson, TX	8
40-8006	Kerr-McGee Corp., Oklahoma City, OK	5	Domestic Licer Docket 50	nsing of Production and Utilization Facilities —	
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5	50-3	Indian Point Station, Unit 1	8
40-8064	Exxon Minerals Co. USA, Houston, TX	5	50-5	Pennsylvania State Univ. Research Reactor	10
40-8084	Rio Algom Corp., Moab, UT	5	50-10	Dresden Nuclear Power Station, Unit I	10

Docket	Name	Page	Docket	Name	Page
50-13	Babcock & Wilcox Co., Critical Facility	11	50-237	Dresden Nuclear Power Station, Unit 2	32
50-20	Massachusetts Institute of Technology Research Reactor	12	50-243	Oregon State Univ Research Reactor	37
50-25	Dow Chemical Co. TRIGA Reactor	12 12	50-244	Robert Emmet Ginna Nuclear Plant, Unit !	37
50-27	Washington State Univ. Research Reactor	12	50-245	Millstone Nuclear Power Station, Unit 1	39
50-29	Yankee-Rowe Nuclear Power Station	12	50-246	Advanced Critical Reactor Experiment	41
50-54	Union Carbide Research Reactor	14	50-247	Indian Point Station, Unit 2	41
50-70	General Electric Test Reactor	14	50-249	Dresden Nuclear Power Station, Unit 3	48
50-83	Univ of Florida Training Reactor	14	50-250	Turkey Point Plant, Unit 3	51
50-89	General Atomic Co	14	50-251	Turkey Point Plant, Unit 4	54
50-97	Cornell Univ. Zero Power Reactor	15	50-254	Quad-Cities Station, Unit 1	56
50-111	North Carolina State Univ. Research Reactor	15	50-255	Palisades Nuclear Plant	59
50-112	Univ. of Oklahoma Research Reactor	15	50-259	Browns Ferry Nuclear Power Station, Unit 1	62
50-124	Virginia Polytech Institute Training Reactor	15	50-260	Browns Ferry Nuclear Power Station, Unit 2	65
50-128	Texas A&M Univ. Research Reactor	16	50-261	H. B Robinson Plant, Unit 2	68
50-129	West Virginia Univ. Research Reactor	16	50-262	Brigham Young Univ Research Reactor	70
50-133	Humboldt Bay Power Plant, Unit 3	16	\$0-263	Monticello Nuclear Generating Plant	70
50-142	UCLA Training Reactor	16	50-265	Quad-Cities Station, Unit 2	72
50-148	Univ. of Kansas Research Reactor	16	50-266	Point Beach Nuclear Plant, Unit 1	75
50-150	Ohio State Univ Research Reactor	16	50-267	Fort St Vrain Nuclear Generating Station	77
50-151	Univ of Illinois Research Reactor	17	50-269	Oconee Nuclear Station, Unit 1	80
50-155	Big Rock Point Nuclear Plant	17	50-270	Oconee Nuclear Station, Unit 2	82
50-156	Univ. of Wisconsin Research Reactor	20	50-271	Vermont Yankee Nuclear Power Station	83
50-157	Cornell Univ. Research Reactor	20	50-272	Salem Nuclear Generating Station, Unit 1	85
50-163	General Atomic Co	20	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	87
50-170	National Naval Medical Center	20	50-277	Peach Bottom Atomic Power Station, Unit 2	92
50-182	Purdue Univ. Research Reactor	21	50-278	Peach Bottom Atomic Power Station, Unit 3	95
50-184	National Bureau of Standards Reactor	21	50-280	Surry Power Station, Unit 1	98
50-186	Univ. of Missouri Research Reactor	21	50-281	Surry Power Station, Unit 2	101
50-187	Space Radiation Research Reactor	21	50-282	Prairie Island Nuclear Station, Unit 1	105
50-193	Rhode Island & Providence Plantations AEC	21	50-285	Fort Calhoun Station, Unit 1	106
50-201	West Valley Reprocessing Plant	21	50-286	Indian Point Station, Unit 3	109
50-206	San Onofre Nuclear Station, Unit 1	21	50-287	Oconee Nuclear Station, Unit 3	114
50-213	Haddam Neck Plant	25	50-289	Three Mile Island Nuclear Station, Unit 1	116
50-219	Oyster Creek Nuclear Power Plant	27	50-293	Pilgrim Nuclear Power Station, Unit 1	121
50-220	Nine Mile Point Nuclear Station, Unit 1	31	50-295	Zion Nuclear Power Station, Unit 1	122
50-225	RPI Critical Experiment	32	50-296	Browns Ferry Nuclear Power Station, Unit 3	126

Docket	Name	Page	Docket	Name	Page
50-298	Cooper Nuclear Station	129	50-352	Limerick Generating Station, Unit 1	217
50-301	Point Beach Nuclear Plant, Unit 2	131	50-353	Limerick Generating Station, Unit 2	220
50-302	Crystal River Nuclear Plant, Unit 3	133	50-354	Hope Creek Nuclear Station, Unit 1	223
50-304	Zion Nuclear Power Station, Unit 2	135	50-355	Hope Creek Nuclear Station, Unit 2	224
50-305	Kewaunee Nuclear Power Plant	138	50-356	Univ of Illinois LOPRA Research Reactor	224
50-306	Prairie Island Nuclear Station, Unit 2	140	50-358	William H Zimmer Nuclear Station, Unit 1	224
50-309	Maine Yankee Atomic Power Plant	141	50-361	San Onofre Nuclear Station, Unit 2	228
50-311	Salem Nuclear Generating Station, Unit 2	144	50-362	San Onofre Nuclear Station, Unit 3	232
50-312	Rancho Seco Nuclear Generating Station	146	50-364	Joseph M Farley Nuclear Plant, Unit 2	235
50-313	Arkansas Nuclear One, Unit 1	149	50-366	Edwin I Hatch Nuclear Plant, Unit 2	237
50- 31 5	Donald C. Cook Nuclear Power Plant, Unit 1	152	50-367	Bailly Generating Station	240
50 -316	Donald C. Cook Nuclear Power Plant, Unit 2	155	50-368	Arkansas Nuclear One, Unit 2	240
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	157	50-369	William B. McGuire Nuclear Station, Unit 1	243
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	160	50-370	William B McGuire Nuclear Station, Unit 2	245
50-320	Three Mile Island Nuclear Station, Unit 2	162	50-373	LaSalle County Station, Unit 1	246
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	165	50-374	LaSalle County Station, Unit 2	250
50-322	Shoreham Nuclear Power Station	168	50-375	Nuclear Examination Reactor	252
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	171	50-382	Waterford Generating Station, Unit 3	252
50-324	Brunswick Steam Electric Plant, Unit 2	173	50-387	Susquehanna Steam Electric Station, Unit 1	256
50-325	Brunswick Steam Electric Plant, Unit 1	176	50-388	Susquehanna Steam Electric Station, Unit 2	259
50-327	Sequoyah Nuclear Plant, Unit 1	179	50-389	St. Lucie Plant, Unit 2	261
50-328	Sequoyah Nuclear Plant, Unit 2	182	50-390	Watts Bar Nuclear Plant, Unit 1	263
50-329	Midland Plant, Unit 1	184	50-391	Watts Bar Nuclear Plant, Unit 2	266
50-330	Midland Plant, Unit 2	188	50-395	Virgil C. Summer Nuclear Station, Unit 1	268
50-331	Duane Arnold Energy Center	191	50-396	Univ. of Virginia Cavalier Reactor	273
50-332	Barnwell Reprocessing Plant	194	50-397	WPPSS Nuclear Project, Unit 2	273
50-333	James A. Fitzpatrick Nuclear Power Plant	194	50-400	Shearon Harris Nuclear Power Plant, Unit 1	275
50-334	Beaver Valley Power Station, Unit 1	195	50-401	Shearon Harris Nuclear Power Plant, Unit 2	277
50-335	St. Lucie Plant, Unit 1	198	50-404	North Anna Power Station, Unit 3	278
50-336	Millstone Nuclear Power Station, Unit 2	201	50-409	La Crosse Boiling Water Reactor	278
50-338	North Anna Power Station, Unit 1	202	50-410	Nine Mile Point Nuclear Station, Unit 2	281
50-339	North Anna Power Station, Unit 2	206	50-412	Beaver Valley Power Station, Unit 2	282
50-341	Enrico Fermi Atomic Power Plant, Unit 2	209	50-413	Catawba Nuclear Station, Unit 1	282
50-344	Trojan Nuclear Plant	211	50-414	Catawba Nuclear Station, Unit 2	285
50-346	Davis-Besse Nuclear Power Station, Unit 1	213	50-416	Grand Gulf Nuclear Station, Unit 1	288
50-348	Joseph M. Farley Nuclear Plant, Unit 1	217	50-417	Grand Gulf Nuclear Station, Unit 2	293

Docket	Name	Page	Docket	Name	Page
50-423	Millstone Nuclear Power Station, Unit 3	294	STN-50-509	WPPSS Nuclear Project, Unit 5	342
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	295	50-513	WPPSS Nuclear Project, Unit 4	342
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	296	50-514	Pebble Springs Nuclear Plant, Unit 1	343
STN-50-437	Floating Nuclear Plant	296	50-515	Pebble Springs Nuclear Plant, Unit 2	343
50-438	Bellefonte Nuclear Plant, Unit 1	297	STN-50-518	Hartsville Nuclear Plant, Unit 1	343
50-439	Bellefonte Nuclear Plant, Unit 2	299	STN-50-519	Hartsville Nuclear Plant, Unit 2	344
50-440	Perry Nuclear Power Plant, Unit 1	301	STN-50-520	Hartsville Nuclear Plant, Unit 3	345
50-441	Perry Nuclear Power Plant, Unit 2	305	STN-50-521	Hartsville Nuclear Plant, Unit 4	345
50-443	Seabrook Nuclear Station, Unit 1	309	50-522	Skagit Nuclear Power Project, Unit 1	346
50-444	Seabrook Nuclear Station, Unit 2	312	50-523	Skagit Nuclear Power Project, Unit 2	347
50-445	Comanche Peak Steam Electric Station, Unit 1	316	STN-50-528	Palo Verde Nuclear Station, Unit 1	348
50-446	Comanche Peak Steam Electric Station, Unit 2	317	STN-50-529	Palo Verde Nuclear Station, Unit 2	351
STN-50-447	GESSAR-238	319	STN-50-530	Palo Verde Nuclear Station, Unit 3	353
STN-50-454	Byron Station, Unit 1	320	50-537	Clinch River Breeder Reactor	355
STN-50-455	Byron Station, Unit 2	322	STN-50-546	Marble Hill Nuclear Station, Unit 1	358
STN-50-456	Braidwood Station, Unit 1	324	STN-50-547	Marble Hill Nuclear Station, Unit 2	359
STN-50-457	Braidwood Station, Unit 2	325	STN-50-553	Phipps Bend Nuclear Station, Unit 1	361
50-458	River Bend Station, Unit 1	326	STN-50-554	Phipps Bend Nuclear Station, Unit 2	361
50-459	River Bend Station, Unit 2	328	STN-50-556	Black Fox Station, Unit 1	362
50-460	WPPSS Nuclear Project, Unit 1	328	STN-50-557	Black Fox Station, Unit 2	362
50-461	Clinton Power Station, Unit 1	329	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	362
50-462	Clinton Power Station, Unit 2	332	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	363
50-466	Allens Creek Nuclear Station, Unit 1	332	Domestic Licer	nsing of Special Nuclear Material Docket 70	
STN-50-482	Wolf Creek Generating Station	333	70-0025	Rockwell International Corp ,	
STN-50-483	Callaway Plant, Unit 1	334	70 0025	Canoga Park, CA	363
STN-50-485	Sterling Power Nuclear Project, Unit 1	336	70-0027	Babcock & Wilcox Co , Lynchburg, VA	364
STN-50-486	Callaway Plant, Unit 2	336	70-0033	Texas Instruments, Inc., Attleboro, MA	364
STN-50-488	Perkins Nuclear Station, Unit 1	336	70-0036	Combustion Engineering, Inc., Windsor, CT	364
STN-50-489	Perkins Nuclear Station, Unit 2	336	70-0135	Babcock & Wilcox Co., Apollo, PA	364
STN-50-490	Perkins Nuclear Station, Unit 3	337	70-0 143	Nuclear Fuel Services, Inc., Erwin, TN	364
STN-50-491	Cherokee Nuclear Station, Unit 1	337	70-0146	Spencer Chemical Co., Kansas City, MO	366
STN-50-492	Cherokee Nuclear Station, Unit 2	337	70-0258	Illinois, Univ. of, Urbana, IL	366
STN-50-493	Cherokee Nuclear Station, Unit 3	338	70-0340	Spencer Chemical Co., Kansas City, MO	367
STN-50-498	South Texas Project, Unit 1	338	70-0371	UNC Naval Products, Inc., Uncasville, CT	367
STN-50-499	South Texas Project, Unit 2	339	70-0687	Union Carbide Corp., Tuxedo, NY	367
STN-50-508	WPPSS Nuclear Project, Unit 3	341	70-0698	Westinghouse Electric Corp., Pittsburgh, PA	367

Docket	Name	Page	Docket	Name	Page
70-0734	GA Technologies, Inc., San Diego, CA	367	Packaging of Re	adjoactive Material for Transport and Transportat	lon
70-0754	General Electric Co, Pleasanton, CA	367	of Radioactive	e Material Under Certain Conditions - Docket 71	
70-0820	United Nuclear Corp., Wood River Junction, RI	367	71-0170	General Electric Co	371
70-0824	Babcock & Wilcox Co., Lynchburg, VA	368	71-0206	Pryor Foundry, Inc.	371
70-1100	Combustion Engineering, Inc., Windsor, CT	368	71-0370	Amersham Corp.	371
70-1113	General Electric Co, Wilmington, NC	368	71-0394	Nuclear Sources & Services, Inc.	371
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	368	71-0454	Atomic Energy of Canada, Ltd.	371
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	369	71-0474	Navy, Dept. of	371
70-1193	Kerr-McGee Nuclear Corp,		71-0483	Fairchild Weston Systems, Inc	371
	Oklahoma City, OK	369	71-0484	Nebraska Public Power District	371
70-1201	Babcock & Wilcox Co , Lynchburg, VA	369	71-0486	INTEC Inspection, Inc.	371
70-1257	Exxon Nuclear Co , Inc , Richland, WA	369	71-0487	Army, Dept of	371
70-1308	General Electric Co., San Jose, CA	369	71-0488	Ramsey Construction & Fabricating Co., Inc.	371
70-1334	AVCO Everett Research Laboratory, Inc , Everett, MA	369	71-0489	Sacramento Municipal Utility District	372
70-1359	IRT Corp , San Diego, CA	369	71-0490	Inspection Services Corp.	372
70-1430	Mt Sinai Hospital Medical Center,	207	71-4909	Model GE 21PF-1, General Electric Co	372
70-1430	Chicago, IL	369	71-5086	Model UNC-2600, United Nuclear Corp	372
70-1621	Duquesne Light Co., Pittsburgh, PA	370	71-5461	Model: ORNL TRU, Energy, Dept. of	372
70-2487	St Clare's Hospital, Denville, NJ	370	71-5469	Model: HNPF Spent Fuel Shipping Cask,	277
70-2792	Lower Bucks Hospital, Bristol, PA	370		Energy, Dept. of	372
70-2872	RS Holding, Inc., Cleveland, OH	370	71-5740	Model: ORNL TRU Calif., Energy, Dept. of	372
70-2895	Spectro Chem Laboratories, Inc , Franklin Lakes, NJ	370	71-5796	Model: 181375, 181361, Advanced Medical Systems, Inc.	372
70-2926	Detroit Edison Co., Detroit, MI	370	71-5814	Model: NRBK-41, -42 & -43, Energy, Dept of	372
70-2928	Tennessee Valley Authority	370	71-5907	Model: ORNL In Pile Capsule, Energy,	
70-2941	Tennessee Valley Authority, Chattanooga, TN	370		Dept of	372
70-2949	Arizona Public Service Co., Phoenix, AZ	370	71-5939	Model GE-1500, General Electric Co.	372
70-2955	Edlow International Co., Washington, DC	370	71-5942	Model: GE-700, General Electric Co.	372
70-2957	Florida Power & Light Co., Miami, FL	370	71-5957	Model: BMI-1, Battelle Columbus Laboratory	372
70-2960	Kansas Gas & Electric Co., Wichita, KS	370	71-5971	Model GE-200, General Electric Co.	373
70-2964	Consumers Power Co., Jackson, MI	370	71-6003	Model M-130, Energy, Dept. of	373
70-2965	Consumers Power Co., Jackson, MI	371	71-6144	Model: B-2, U.S Ecotogy	373
70-2968	Cleveland Electric Illuminating Co.,		71-6347	Model: FSV-3, General Atomic Co.	373
	Cleveland, OH	371	71-6495	Model: PADUCAH Demonstration Cask, Energy, Dept. of	373

Docket	Name	Page	Docket	Name	Page
71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	373	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	374
71-6601	Model. CNS 8-120, Chem-Nuclear Systems, Inc.	373	71-9099	Model. ATR, Exxon Nuclear Idaho Co.	374
71-6717	Model 6717-B, Gamma Industries	373	71-9111	Model. CNS 6-80-2, Chem-Nuclear Systems, Inc	374
71-9001	Model. IF-300, General Electric Co.	373	71-9126	Model: 20, 20A, 50, 50A, Gamma Industries	374
71-9006	Model: 500-SU, Automation Industries, Inc	373	71-9127	Model: 100, 100A, 200, 200A, Gamma Industries	374
71-9010	Model: NLI-1/2, NL Industries, Inc	373	71-9128	Model, C-8, Gamma Industries	374
71-9015	Model. TN-8, -8L, No Users	373	71-9132	Model T-3, Energy, Dept of	374
71-9032	Model. 650, Technical Operations, Inc	373	71-9150	Model PAT-2, Energy, Dept. of	375
71-9033	Model: 660 & 660E, Technical Operations, Inc.	374	71-9151	Model HN-100, Series 3, Hittman Nuclear & Development Corp.	375
71-9044	Model: GE-1600, General Electric Co	374	71-9156	Model, IR-50, Industrial Nuclear Co.	375
71-9073	Model. OH-142, Nuclear Packaging, Inc.	374	71-9157	Model IR-100, Industrial Nuclear Co	375
71-9079	Model, HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	374	71-9167	Model Type B, Amersham Corp	375
71-9081	Model CNS-1600, Chem-Nuclear Systems, Inc.	374	71-9852	Model DT-14, Energy, Dept of	375
71-9086	• • • • • • • • • • • • • • • • • • • •	374	Licensing of I	ndependent Spent Fuel Storage - Docket 72	
71-9089	Development Corp	374	72-0001	Morris Operations, General Electric Co.	375
(1-2083	Model, HN-100S, Hittman Nuclear & Development Corp.	374	72-0002	Virginia Electric & Power Co.	375
71-9094	Model. CNS 14-195-H, Chem-Nuclear Systems, Inc.	374			

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 27			Minnesota Mining & Manufacturing, St. Paul, MN	40-8135	6
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Ogle Petroleum, Inc., Casper, WY	40-8745	8
Richland, WA, U.S. Ecology, Inc.	27-048	1	Pathfinder Mines Corp., Riverton, WY	40-2259	2
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	Pathfinder Mines Corp., Shirley Basın, WY	40-6622	5
Domestic Licensing of Source Material — Docket	ហ		Pinal Minerals & Mining, Ltd., Miami, AZ	40-8752	8
Allied Chemical Corp., Morristown, NJ	40-3392	3	Plateau Resources, Ltd., Grand Junction, CO	40-8698	7
Amax Speciality Metals Corp., Parkersburg, WV	40-8355	6	Rio Algom Corp., Moab, UT	40-8084	5
Army, Dept. of, White Sands, NM	40-7086	5	Rocky Mountain Energy Co , Broomfield, CO	40-8380	6
Atlas Mineral, Inc., Denver, CO	40-3453	3	Rocky Mountain Energy Co., Denver, CO	40-8697	7
Bear Creek Uranium Co., Casper, WY	40-8452	6	Silver King Mines, Inc., Casper, WY	40-8602	7
Cleveland-Cliffs Iron Co., Casper, WY	40-8200	6	Spencer Chemical Co., Kansas City, MO	40-1478	2
Conoco, Inc., Denver, CO	40-8743	7	Stepan Chemical Co , Maywood, NJ	40-8610	7
Cotter Corp., Golden, CO	40-8511	6	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Dow Chemical Co., Midland, MI	40-0017	1	Teton Exploration Drilling Co., Inc., Casper, WY		7
Energy Fuels Nuclear, Inc., Denver, CO		7		40-8728	8
Energy, Dept. of, Canonsburg, PA	40-8681	•	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	
	40-6500	3	Union Carbide Corp., Grand Junction, CO	40-0299	1
Exxon Co. USA, Houston, TX	40-8102	6	Uranerz USA, Inc., Casper, WY	40-8783	8
Exxon Minerals Co. USA, Houston, TX	40-8064	5	Uranium Resources, Inc., Richardson, TX	40-8786	8
Federal-American Partners, Riverton, WY	40-4492	3	Vitro Engineering Co.	40-1606	2
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	5	Vitro Engineering Co.	40-2116	2
Kawecki Berylco Industries, Inc., Boyertown, PA	40-6940	5	Vitro Engineering Co.	40-3265	3
Kerr-McGee Chemical Corp.,			W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Oklahoma City, OK	40-2061	2	Western Nuclear Corp., Jeffrey City, WY	40-1162	1
Kerr-McGee Corp., Oklahoma City, OK	40-8006	5	Domestic Licensing of Production and Utilization F	acilities —	
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	5	Docket 50	aciities —	
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	8	Advanced Critical Reactor Experiment	50-246	41
Melapai Resources Co., Phoenix, AZ	40-8771	8	Allens Creek Nuclear Station, Unit 1	50-466	332
Minerals Exploration Co., Los Angeles, CA	40-8348	6	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	295
Minerals Exploration Co., Los Angeles, CA	40-8584	6	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	296

Name	Docket	Page	Name	Docket	Page
Arkansas Nuclear One, Unit 1	50-313	149	Cooper Nuclear Station	50-298	129
Arkansas Nuclear One, Unit 2	50-368	240	Cornell Univ Research Reactor	50-157	20
Babcock & Wilcox Co. Critical Facility	50-13	11	Cornell Univ Zero Power Reactor	50-97	15
Bailly Generating Station	50-367	240	Crystal River Nuclear Plant, Unit 3	50-302	133
Barnwell Reprocessing Plant	50-332	194	Davis-Besse Nuclear Power Station, Unit 1	50-346	213
Beaver Valley Power Station, Unit 1	50-334	195	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	87
Beaver Valley Power Station, Unit 2	50-412	282	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	171
Bellefonte Nuclear Plant, Unit 1	50-438	297	Donald C Cook Nuclear Power Plant, Unit 1	50-315	152
Bellefonte Nuclear Plant, Unit 2	50-439	299	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	155
Big Rock Point Nuclear Plant	50-155	17	Dow Chemical Co TRIGA Reactor	50-25	12
Black Fox Station, Unit 1	STN-50-556	362	Dresden Nuclear Power Station, Unit 1	50-10	10
Black Fox Station, Unit 2	STN-50-557	362	Dresden Nuclear Power Station, Unit 2	50-237	32
Braidwood Station, Unit 1	STN-50-456	324	Dresden Nuclear Power Station, Unit 3	50-249	48
Bratdwood Station, Unit 2	STN-50-457	325	Duane Arnold Energy Center	50-331	191
Brigham Young Univ. Research Reactor	50-262	70	Edwin I Hatch Nuclear Plant, Unit 1	50-321	165
Browns Ferry Nuclear Power Station, Unit 1	50-259	62	Edwin I Hatch Nuclear Plant, Unit 2	50-366	237
Browns Ferry Nuclear Power Station, Unit 2	50-260	65	Enrico Fermi Atomic Power Plant, Unit 2	50-341	209
Browns Ferry Nuclear Power Station, Unit 3	50-296	126	Floating Nuclear Plant	STN-50-437	296
Brunswick Steam Electric Plant, Unit 1	50-325	176	Fort Calhoun Station, Unit 1	50-285	106
Brunswick Steam Electric Plant, Unit 2	50-324	173	Fort St. Vrain Nuclear Generating Station	50-267	77
Byron Station, Unit 1	STN-50-454	320	General Atomic Co	50-89	14
Byron Station, Unit 2	STN-50-455	322	General Atomic Co	50-163	20
Callaway Plant, Unit 1	STN-50-483	334	General Electric Test Reactor	50-70	14
Callaway Plant, Unit 2	STN-50-486	336	GESSAR-238	STN-50-447	319
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	157	Grand Gulf Nuclear Station, Unit 1	50-416	288
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	160	Grand Gulf Nuclear Station, Unit 2	50-417	293
Catawba Nuclear Station, Unit 1	50-413	282	H.B. Robinson Plant, Unit 2	50-261	68
Catawba Nuclear Station, Unit 2	50-414	285	Haddam Neck Plant	50-213	25
Cherokee Nuclear Station, Unit 1	STN-50-491	337	Hartsville Nuclear Plant, Unit 1	STN-50-518	343
Cherokee Nuclear Station, Unit 2	STN-50-492	337	Hartsville Nuclear Plant, Unit 2	STN-50-519	344
Cherokee Nuclear Station, Unit 3	STN-50-493	338	Hartsville Nuclear Plant, Unit 3	STN-50-520	345
Clinch River Breeder Reactor	50-537	355	Hartsville Nuclear Plant, Unit 4	STN-50-521	345
Clinton Power Station, Unit 1	50-461	329	Hope Creek Nuclear Station, Unit 1	50-354	223
Clinton Power Station, Unit 2	50-462	332	Hope Creek Nuclear Station, Unit 2	50-355	224
Comanche Peak Steam Electric Station, Unit 1	50-445	316	Humboldt Bay Power Plant, Unit 3	50-133	16
Comanche Peak Steam Electric Station, Unit 2	50-446	317	Indian Point Station, Unit 1	50-3	8

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 2	50-247	41	Oyster Creek Nuclear Power Plant	50-219	27
Indian Point Station, Unit 3	50-286	109	Palisades Nuclear Plant	50-255	59
James A Fitzpatrick Nuclear Power Plant	50-333	194	Palo Verde Nuclear Station, Unit 1	STN-50-528	348
Joseph M Farley Nuclear Plant, Unit 1	50-348	217	Palo Verde Nuclear Station, Unit 2	STN-50-529	351
Joseph M. Farley Nuclear Plant, Unit 2	50-364	235	Palo Verde Nuclear Station, Unit 3	STN-50-530	353
Kewaunce Nuclear Power Plant	50-305	138	Peach Bottom Atomic Power Station, Unit 2	50-277	92
La Crosse Boiling Water Reactor	50-409	278	Peach Bottom Atomic Power Station, Unit 3	50-278	95
LaSalle County Station, Unit i	50-373	246	Pebble Springs Nuclear Plant, Unit 1	50-514	343
LaSalle County Station, Unit 2	50-374	250	Pebble Springs Nuclear Plant, Unit 2	50-515	343
Limerick Generating Station, Unit 1	50-352	217	Pennsylvania State Univ Research Reactor	50-5	10
Limerick Generating Station, Unit 2	50-353	220	Perkins Nuclear Station, Unit 1	STN-50-488	336
Maine Yankee Atomic Power Plant	50-309	141	Perkins Nuclear Station, Unit 2	STN-50-489	336
Marble Hill Nuclear Station, Unit 1	STN-50-546	358	Perkins Nuclear Station, Unit 3	STN-50-490	337
Marble Hill Nuclear Station, Unit 2	STN-50-547	359	Perry Nuclear Power Plant, Unit 1	50-440	301
Massachusetts Institute of Technology Research Reactor	50-20	12	Perry Nuclear Power Plant, Unit 2	50-441	305
Midland Plant, Unit 1	50-329	184	Phipps Bend Nuclear Station, Unit 1	STN-50-553	361
Midland Plant, Unit 2	50-330	188	Phipps Bend Nuclear Station, Unit 2	STN-50-554	361
Millstone Nuclear Power Station, Unit 1	50-245	39	Pilgrun Nuclear Power Station, Unit 1	50-293	121
Millstone Nuclear Power Station, Unit 2	50-336	201	Point Beach Nuclear Plant, Unit 1	50-266	75
Millstone Nuclear Power Station, Unit 3	50-423	294	Point Beach Nuclear Plant, Unit 2	50-301	131
Monticello Nuclear Generating Plant	50-263	70	Prairie Island Nuclear Station, Unit 1	50-282	105
National Bureau of Standards Reactor	50-184	21	Prairie Island Nuclear Station, Unit 2	50-306	140
National Naval Medical Center	50-170	20	Purdue Univ Research Reactor	50-182	21
Nine Mile Point Nuclear Station, Unit 1	50-220	31	Quad-Cities Station, Unit 1	50-254	56
Nine Mile Point Nuclear Station, Unit 2	50-410	281	Quad-Cities Station, Unit 2	50-265	72
North Anna Power Station, Unit 1	50-338	202	Rancho Seco Nuclear Generating Station	50-312	146
North Anna Power Station, Unit 2	50-339	206	Rhode Island & Providence Plantations AEC	50-193	21
North Anna Power Station, Unit 3	50-404	278	River Bend Station, Unit 1	50-458	326
North Carolina State Univ. Research Reactor	50-111	15	River Bend Station, Unit 2	50-459	328
Nuclear Examination Reactor	50-375	252	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	37
Oconee Nuclear Station, Unit 1	50-269	80	RPI Critical Experiment	50-225	32
Oconee Nuclear Station, Unit 2	50-270	82	Salem Nuclear Generating Station, Unit 1	50-272	85
Oconee Nuclear Station, Unit 3	50-287	114	Salem Nuclear Generating Station, Unit 2	50-311	144
Ohio State Univ. Research Reactor	50-150	16	San Onofre Nuclear Station, Unit 1	50-206	21
Oregon State Univ. Research Reactor	50-243	37	San Onofre Nuclear Station, Unit 2	50-361	228

Name	Docket	Page	Name	Docket	Page	
San Onofre Nuclear Station, Unit 3	50-362	232	Vermont Yankee Nuclear Power Station	50-271	83	
Seabrook Nuclear Station, Unit 1	50-443	309	Virgil C. Summer Nuclear Station, Unit 1	50-395	268	
Seabrook Nuclear Station, Unit 2	50-444	312	Virginia Polytech Institute Training Reactor	50-124	15	
Sequoyah Nuclear Plant, Unit 1	50-327	179	Washington State Univ. Research Reactor	50-27	12	
Sequoyah Nuclear Plant, Unit 2	50-328	182	Waterford Generating Station, Unit 3	50-382	252	
Shearon Harris Nuclear Power Plant, Unit 1	50-400	275	Watts Bar Nuclear Plant, Unit 1	50-390	263	
Shearon Harris Nuclear Power Plant, Unit 2	50-401	277	Watts Bar Nuclear Plant, Unit 2	50-391	266	
Shoreham Nuclear Power Station	50-322	168	West Valley Reprocessing Plant	50-201	21	
Skagit Nuclear Power Project, Unit 1	50-522	346	West Virginia Univ Research Reactor	50-129	16	
Skagit Nuclear Power Project, Unit 2	50-523	347	William B. McGuire Nuclear Station, Unit 1	50-369	243	
South Texas Project, Unit 1	STN-50-498	338	William B. McGuire Nuclear Station, Unit 2	50-370	245	
South Texas Project, Unit 2	STN-50-499	339	William H. Zimmer Nuclear Station, Unit 1	50-358	224	
Space Radiation Research Reactor	50-187	21	Wolf Creek Generating Station	STN-50-482	333	
St. Lucie Plant, Unit 1	50-335	198	WPPSS Nuclear Project, Unit 1	50-460	328	
St. Lucie Plant, Unit 2	50-389	261	WPPSS Nuclear Project, Unit 2	50-397	273	
Sterling Power Nuclear Project, Unit 1	STN-50-485	336	WPPSS Nuclear Project, Unit 3	STN-50-508	341	
Surry Power Station, Unit 1	50-280	98	WPPSS Nuclear Project, Unit 4	50-513	342	
Surry Power Station, Unit 2	50-281	101	WPPSS Nuclear Project, Unit 5	STN-50-509	342	
Susquehanna Steam Electric Station, Unit 1	50-387	256	Yankee-Rowe Nuclear Power Station	50-29	12	
Susquehanna Steam Electric Station, Unit 2	50-388	259	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	362	
Texas A&M Univ. Research Reactor	50-128	16	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	363	
Three Mile Island Nuclear Station, Unit 1	50-289	116	Zion Nuclear Power Station, Unit 1	50-295	122	
Three Mile Island Nuclear Station, Unit 2	50-320	162	Zion Nuclear Power Station, Unit 2	50-304	135	
Trojan Nuclear Plant	50-344	211	Domestic Licensing of Special Nuclear Materia	terial — Docket 70		
Turkey Point Plant, Unit 3	50-250	51	Arizona Public Service Co., Phoenix, AZ	70-2949	370	
Turkey Point Plant, Unit 4	50-251	54	AVCO Everett Research Laboratory, Inc.,			
UCLA Training Reactor	50-142	16	Everett, MA	70-1334	369	
Union Carbide Research Reactor	50-54	14	Babcock & Wilcox Co., Apollo, PA	70-0135	364	
Univ. of Florida Training Reactor	50-83	14	Babcock & Wilcox Co , Lynchburg, VA	70-0027	364	
Univ. of Illinois LOPRA Research Reactor	50-356	224	Babcock & Wilcox Co , Lynchburg, VA	70-0824	368	
Univ. of Illinois Research Reactor	50-151	17	Babcock & Wilcox Co., Lynchburg, VA	70-1201	369	
Univ. of Kansas Research Reactor	50-148	16	Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	371	
Univ. of Missouri Research Reactor	50-186	21	Combustion Engineering, Inc , Windsor, CT	70-1100	368	
Univ. of Oklahoma Research Reactor	50-112	15	Combustion Engineering, Inc., Windsor, CT	70-0036	364	
Univ. of Virginia Cavalier Reactor	50-396	273	Consumers Power Co., Jackson, MI	70-2965	371	
Univ. of Wisconsin Research Reactor	50-156	20	Consumers Power Co., Jackson, MI	70-2964	370	

Name	Docket	Page	Name	Docket	Page
Detroit Edison Co , Detroit, MI	70-2926	370	Atomic Energy of Canada, Ltd	71-0454	371
Duquesne Light Co., Pittsburgh, PA	70-1621	370	Fairchild Weston Systems, Inc.	71-0483	371
Edlow International Co , Washington, DC	70-2955	370	General Electric Co.	71-0170	371
Exxon Nuclear Co , Inc , Richland, WA	70-1257	369	Inspection Services Corp	71-049 0	372
Florida Power & Light Co., Miami, FL	70-2957	370	INTEC Inspection, Inc.	71-0486	371
GA Technologies, Inc , San Diego, CA	70-0734	367	Model. 100, 100A, 200, 200A, Gamma Industries	71-9127	374
General Electric Co , Pleasanton, CA	70-0754	367	Model 181375, 181361, Advanced Medical	D. ##0<	250
General Electric Co., San Jose, CA	70-1308	369	Systems, Inc	71-5796	372
General Electric Co , Wilmington, NC	70-1113	368	Model. 20, 20A, 50, 50A, Gamma Industries	71-9126	374
Illinois Univ. of, Urbana, IL	70-0258	366	Model, 500-SU, Automation Industries, Inc	71-9006	3 73
IRT Corp., San Diego, CA	70-1359	369	Model. 650, Technical Operations, Inc.	71-9032	373
Kansas Gas & Electric Co., Wichita, KS	70-2960	370	Model. 660 & 660E, Technical Operations, Inc.	71-9033	374
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	369	Model: 6717-B, Gamma Industries	71-6717	373
Lower Bucks Hospital, Bristol, PA	70-2792	370	Model ATR, Exxon Nuclear Idaho Co.	71-9099	374
Mt. Sınaı Hospital Medical Center, Chicago, IL	70-1430	369	Model. B-2, U S Ecology	71-6144	373
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	364	Model: BMI-1, Battelle Columbus Laboratory	71-5957	372
Rockwell International Corp., Canoga Park, CA	70-0025	363	Model C-8, Gamma Industries	71-9128	374
RS Holding, Inc., Cleveland, OH	70-2872	370	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc	71-9094	374
Spectro Chem Laboratories, Inc., Franklin Lakes, NJ	70-2895	370	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	374
Spencer Chemical Co., Kansas City, MO	70-0146	366	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	374
Spencer Chemical Co , Kansas City, MO	70-0340	367	Model CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	373
St. Clare's Hospital, Denville, NJ	70-2487	370	Model: CNS-1600, Chem-Nuclear Systems, Inc	71-9081	374
Tennessee Valley Authority	70-2928	370	Model: DT-14, Energy, Dept. of	71-9852	375
Tennessee Valley Authority, Chattanooga, TN	70-2941	370	Model: FSV-3, General Atomic Co	71-6347	373
Texas Instruments, Inc., Attleboro, MA	70-0033	364	Model: GE 21PF-1, General Electric Co	71-4909	372
UNC Naval Products, Inc , Uncasville, CT	70-0371	367	Model: GE-1500, General Electric Co	71-5939	372
Union Carbide Corp., Tuxedo, NY	70-0687	367	Model: GE-1600, General Electric Co	71-9044	· 374
United Nuclear Corp , Wood River Junction, RI	70-0820	367	Model, GE-200, General Electric Co.	71-5971	373
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	367	Model: GE-700, General Electric Co.	71-5942	372
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	368	Model: HN-100, Series I, Hittman Nuclear & Development Corp.	71-9086	374
Westinghouse Electric Corp , Pittsburgh, PA	70-1151	369	Model HN-100, Series 2 & 2A, Hittman Nuclear		
			& Development Corp.	71-9079	374
Packaging of Radioactive Material for Transport a	nd Tuananauta	tion	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	375
of Radioactive Material Under Certain Condition	Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	374		
Amersham Corp.	71-0370	371	Model: HN-200, Hittman Nuclear &	(1-200X	217
Army, Dept. of	71-0487	371	Development Corp	71-6574	373

Name	Docket	Page	Name	Docket	Page
Model: HNPF Spent Fuel Shipping Cask, Energy,	71 5460	370	Model. T-3, Energy, Dept. of	71-9132	374
Dept. of	71-5469	372	Model: TN-8, -8L, No Users	71-9015	373
Model: IF-300, General Electric Co.	71-9001	373	Model: Type B, Amersham Corp.	71-9167	375
Model: IR-100, Industrial Nuclear Co.	71-9157	375		71-5086	372
Model IR-50, Industrial Nuclear Co.	71-9156	375	Model: UNC-2600, United Nuclear Corp		
Model: M-130, Energy, Dept. of	71-6003	373	Navy, Dept. of	71-0474	371
Model NLI-1/2, NL Industries, Inc.	71-9010	373	Nebraska Public Power District	71-0484	371
			Nuclear Sources & Services, Inc.	71-0394	371
Model: NRBK-41, -42 & -43, Energy, Dept. of	71-5814	372	Pryor Foundry, Inc.	71-0206	371
Model: OH-142, Nuclear Packaging, Inc.	71-9073	374	Ramsey Construction & Fabricating Co., Inc.	71-0488	371
Model: ORNL in Pile Capsule, Energy, Dept of	71-5907	372	•		
Model: ORNL TRU Calif., Energy, Dept. of	71-5740	372	Sacramento Municipal Utility District	71-0489	372
Model. ORNL TRU, Energy, Dept. of	71-5461	372			
Model PADUCAH Demonstration Cask, Energy, Dept. of	71-6495	373	Licensing of Independent Spent Fuel Storage — Docket 72		
			Morris Operations, General Electric Co.	72-0001	375
Model. PAT-2, Energy, Dept of	71-9150	375	Virginia Electric & Power Co	72-0002	375

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL. U.S. ECOLOGY, INC.

- 8212010476 Forwards "Tritium Migration Investigation Status Rept "
 GAYNOR, R K US Ecology, Inc (Formerly Nuclear Engineering)
 82/11/11 US Ecology, Inc (Formerly Nuclear Engineering) 1p
 16/270-210
- B212010477 "Tritium Migration Investigation Status Rept "

 * US Ecology, Inc (Formerly Nuclear Engineering) B2/11/10 App
 16270 211
- DOCKET 27-047 BARNNELL, SC. CHEM-NUCLEAR SYSTEMS, INC
- B212290005 Application for amends to Licenses 46-13536-01 & 46-19524-01.to reflect merger of Chem-Nuclear Sys.Inc into Waste Mgt.Inc HUIZENOA.H W Waste Management. Inc HUIZENOA.H W Chem-Nuclear Systems. Inc B2/10/29 DAVIS.J © Division of Fuel Cycle & Material Safety 1p 16607 234
- 82:1228054: Forwards Haste Mgt. Inc & Chem-Nuclear Sys. Inc 82:1029 1tr requesting amends to Licenses 46-13536-01 & 46-19524-01. to reflect change in licensee name REIS. HF Lowenstein, Newman, Reis. Axelrad & Toll REIS, HF Waste Hanagement, Inc REIS, HF Chem-Nuclear Bystems, Inc 82/11/01 DAVIS, J 6 Office of Nuclear Material Safety & Safeguards, Director 10 16:5973 049
- 8212230383 Forwards Amend 22 reflecting change in corporate address effected by merger w/t/MI Holdings, Inc per 821029 request License 46-13936-01 changed to 12-13536-01 SCARRAD. RA Low Level Waste Licensing Branch 82/11/23 HUIZENGA, H W Chem-Nuclear Systems, Inc. 2pp. 16540 248
- DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC.
- BP12270010 Forwards revised SNM license acceptable to licensee, providing sound basis for settlement of outstanding license issue SCOVILLE.J J US Ecology. Inc (Formerly Nuclear Engineering) 82/09/27 MARTIN.J Division of Waste Management 17pp 16607 216
- B?12230162 Amend 15 to Radioactive Matls License WN-1019-2 for UB Ecology, Inc. authorizing use of 60,000 Ci of any radioactive matl & 36,000 kg source matl * Washington, State of 82/10/11 26pp 16544 013
- 8212280538 Proposes language to be included in SNM license to insure licensee is cognizant of continuing authority of State of WA over licensee activities HANREY: M Washington, State of 82/11/30 FONNER, R Regulations Division 2pp 16593 050

DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI
- GP12020034 Forwards plan for decommissioning Midland.MI thorium slag storage site for License STB-527 OLSON,R A Dow Chemical Co 82/10/21 PAGE.R Q Division of Fuel Cycle & Material Bafety 7pp 16308 334

- G212100183 Responds to 821102 ltr re-movement of soil contaminated w/thorium residues from Dow Chemical Co to Bag City site Dow proposal requesting authorization to consolidate contaminated soil being reviewed DAVIB. J @ Office of Nuclear Material Safety & Safeguards, Director 82/11/26 WALKER, Michigan, State of, Dept of Public Health 3pp 16399 001
- DOCKET 40-0086 W R ORACE & CO , POMPTON PLAINS, NJ
- BP12060509 Responds to B21108 ltr re constituent concern over thorium contamination in Hayne NJ "Radiological Burvey of Sheffield Brook" encl for info W/o encl DIRCKS, NJ Office of the Executive Director for Operations 82/11/26 BRADY, N F Senate 4pp 16348 006
- --8212060511 Requests info re constituent M Casson 821014 ltr expressing concern about thurium contamination in Wagne, NJ BRADY, N F Senate 82/11/08 KAMMERER, C C Office of Congressional Affairs 2pp 16348 010
- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CD
- BP12030252 Documents 821025 telcon w/Union Carbide Corp re 1981 evaporation pond insp rept Evaporation pond erosion protection restored w/2 ft of cobbles No further action required FLEMING.T E Region 4. Office of Director 82/11/23 Region 4. Office of Director 1p 16316 359
- 8212040513 Requests extension until 830107 for response re GA program, per NRC 821021 request Delay due to preparation of quarterly repts & holidays HONO, 7 Union Carbide Corp 82/11/23 WOOLSEY, R T Uranium Recovery Licensing Branch (p. 14348 005
- 8212230186 Advises that 10CFR40 65 quarterly rept for third quarter 1982 will be submitted by due date but w/o info for 40CFR190 monitoring Extension for submittal of mati requested MONO, T Union Carbide Corp 82/11/23 PETTENOILL, H Uranium Recovery Licensing Branch 1p 16543 278
- B212270074 Forwards "Reporting Requirements for Union Carbide Corp. Third Guarter, 1982" WDNG, T Union Carbide Corp 82/11/24 BROWN, G D Region 4. Office of Director 2pp 16573 001
- --8212270083 "Reporting Requirements for Union Carbide Corp. Third Quarter, 1982" * Union Carbide Corp 82/11/24 290pp 16573 003
- 8212270063 Submits review of dose calculation & compliance evaluation of environ montioring data for First & Second Quarters 1982, submitted 820803 & 1007 Licensee in compliance w/ 400FR190 SOLLENBERGER, D Low Level Waste Licensing Branch 82/12/09 Low Level Waste Licensing Branch 1000 Level Waste Licensing Bran
- DOCKET 40-1162 WESTERN NUCLEAR CORP , JEFFREY CITY, WY
- 8212130105 Provides info in response to 821015 ltr Wells 17 & 25 cleaned 24-h before sampling & again on 821005 Add cleaning showed improvement in water quality data Disposal of spent acid discontinued in 1977 BOODEN. 9 Hestern Nuclear, Inc. (subs of Phelps Dodge Corp) 82/11/10 GARCIA.P Uranium Recovery Licensing Branch ip 14417 257

- B212030255 Discusses major findings of IE insp of tailings mgt practices at Split Rock Mill on 820901 Measures taken by licensee to control nigration of tailings effective No further action required GARCIA,P J., PETTENSILL.H J. Region 4. Office of Director B2/11/19 Region 4. Office of Director 2pp 16316 360
- B212070052 Advises that sampling & analysis re environ monitoring data for Jan-June 1982 acceptable GARCIA.P J Region 4. Office of Director 82/11/26 Region 4. Office of Director 3pp 16356 277
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN
- 8212300025 Discusses monitoring program of Edgement seep area addressing unresolved item b including chemical & radiological sampling of seep area & similar control areas Access to uninhabited area should be restricted UBHNSON.T L Region 4. Office of Director 82/12/17 Region 4. Office of Director 3pp 16624 283
- DOCKET 40-1478 SPENCER CHEMICAL CO . KANSAS CITY, MO
- 8212280007 Add1 response to FOLA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A FELTON.J H Division of Rules and Records 82/11/29 BARNES.C Affiliation Unknown 2pp 16590 141
- --8212280012 Requests correspondence re Spencer Chemical Co be sent to listed address COBS.G H Kerr-KcQee Corp 62/09/06 JQHNSQM.L Atomic Energy Commission ip 16590 144
- BOCKET 40-1606 VITRO ENGINEERING CO
- 821216080 Add1 response to FDIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA.Vitro Mfg Co & Vitro Rare Hetals Co Forwards documents listed in App A Remaining info under review FELTON, J M bivision of Rules and Records 82/09/30 BLACK, A E Buchanan, Ingersoll, Rodewald, Kyle & Juerger 7pp 16447 312
- --8212160534 Source Hatl License C-3820 for Vitro Corp of America, authorizing use of 300 lbs thorium-bearing residues containing 13 lbs thorium DELAMEY.J C Atomic Energy Commission 57/09/09 1p 16449 015
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK
- 8212210512 Forwards corrected paragraphs to health physics manual per telcon request SHELLEY, H.J. Kerr-McGee Corp. 82/11/04 NIXON, H.A. Uranium Fuel Licensing Branch tp. 16502 349
- --82:2210515 Corrected paragraphs to health physics manual * Kerr-HcOpe Corp 82/10/28 2pp 16502 350
- 8212130432 Forwards applications to City of West Chicago & State of IL for permit to construct incinerator sys
 DENNY, I L. Kerr-McGes Chemical Corp (subs of Kerr-McGes Corp)
 82/11/10 NIXON W A Division of Fuel Cycle & Material Safety
 23pp (6415 021
- 8212010487 Responds to 821015 ltr re Kerr-McGee installation of incinerator at Rare Earths facility Action valid per Amend 2 to License STA-583 impact on public limited to exhaust gas cleanup sys PAGE-R O Uranium Recovery Licensing Branch 82/11/18 SPELMAIN J West Chicago, IL Ip 16270 255
- 8212070474 Discusses 821116 telcon re D Mausshar6t request to tour Hest Chicago Rare Earths facility on 821117 NIXON,M A Dévision of Fuel Cycle & Material Safety. 82/11/24 Division of Fuel Cycle & Material Safety ip 16355 264
- 8212130237 Responds to questions re amend application raised in 821116 telcon Wood stored in 81dg 2 will be tept on factory site & protected from weather until incinerated Bidgs 10.11.14 & 16 surveyed Contamination minor SHELLEY.N J. Herr-McGee Corp. 82/11/27 NIXON.W A. Uranium Fuel Licensing Branch 3pp 16410 332

- B21227047B Objections to Amends 5 & 6 to License STA-583 Informal hearing on amends protested Assurance that new amends will employ control procedures permitted under Amend 1 & 3 requested SPELMAN, H J West Chicago, IL SPELMAN, H J Harold J Spelman & Associates B2/11/29 MAUSSHARDT, D B Division of Fuel Cycle & Material Safety Bpp 16551 Q67
- B212100174 Trip rept of B21117 site visit to Kerr-McGee facility at West Chicago. IL re-proceeding to be followed in resolution of dispute over License Amends 5 & 6 MAUSSHARDT.D B NRC No Detailed Affiliation Given 82/11/30 NRC No Detailed Affiliation Given 3pp 16378 349
- 8212140359 Requests permission for Oak Ridge Associated Univs to perform radiological surveys on property Property may have low levels of radioactive contamination from Kerr-McGee Rare Earth Facility Goil samples taken along Kress Creek KEPPLER.J O Region 3. Office of Director 82/11/30 Nichiret Shoshu Temple 3pp 16401 038
- 8212130167 Comments on Kerr-McGee 821011 proposal to extend License 516-583 for 25 yrs Kerr-McGee should remain responsible for contaminated matl while matl on site Proposal potentially conflicts w/termination requirements

 SPELMAN.H J Harold J Spelman & Associates SPELMAN.H J West Chicago, IL 82/12/01 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 4pp 16414 055
- 8212i40470 Forwards list of documents for initial record in NRC hearing re Amends 5 % 4 to license Relevant documents will be added to list W/o encl
 RMINELANDER, J Shaw. Pittman. Potts & Trowbridge 82/12/01
 HAUSSHARDT.D B Office of Nuclear Material Safety &
 Safeguards. Director 2pp 16431 319
- B212270467 Comments on behalf of Kerr-McGee, re B21011 proposal to sitend license for 25-yrs City of West Chicago assumes that proposal amends application for stabilization plan approval Hearing on proposed amend requested SPELMAN.H J Harold J Spelman & Associates SPELMAN.H J West Chicago, IL B2/12/01 CUNNINGHAM R E Division of Fuel Cycle & Material Safety 4pp 16568 354
- B212100496 Ack receipt of documents designated as initial record in NRC Hearing 2 re Amends 5 & 6 to License SUA-583 Addl documents will be sent as generated AMUSSHARDT.D B Defice of Nuclear Material Safety & Safeguards.Director 82/12/02 RHINELANDER, J Shaw, Pittman. Potts & Trowbridge ip 16389 055
- DOCKET 40-2116 VITRO ENGINEERING CO
- 8212160080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA.Vitro Mfg Ca & Vitro Rare Metals Co Forwards documents issted in App A Remaining info under review FELTON, J M Division of Rules and Records 82/09/30 BLACK, A & Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312
- --8212160505 Source Matl License C-4625 for Vitra Corp of America, authorizing use of 25.000 lbs of sludge containing U for processing DELANEY, J C Atomic Energy Commission 59/03/16 Vitra Engineering Co lp 16449 010
- --8212160510 Requests that term of License C-3748 be extended to 600131 or new license be issued Effective date of renewal or new license requested by 570302 LITTEL.E Q Vitro Engineering Co 57/02/27 DELANEY, J C Atomic Energy Commission in 16449 011
- ---9212160513 Source Matl License C-3948 for Vitro Corp of America, authorizing use of 25,000 lbs sludge containing natural U for processing DELANEY,J C Atonic Energy Commission 58/01/08 LITTEL, E G Vitro Engineering Co Ip 16449 012
- --8212160525 Application for source math license to receive various quantities of sludge containing natural U concentrations of 40%-70% by weight from Mestinghouse
 LITTEL, E. G. Vitro Engineering Co. 57/12/26 2pp 16449 013
- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8212070063 Advises that environ monitoring data submitted on 820831 acceptable
 SOLLENGERGER, D Low Level Waste Licensing Branch 82/11/26 Lo
 Level Waste Licensing Branch 4pp 16356 267

- BP12230155 Forwards "Guarterly Effluent Monitoring Rept, Jul - Sept 1982." per 10CFR40 & License Condition 54 POYSER.R W Pathfinder Mines Corp 82/11/30 SULLENBERGER, D Uranium Recovery Licensing Branch 1p 16544 040
- --8212230163 "Quarterly Effluent Monitoring Rept, Jul Sept 1982 " * Pathfinder Mines Corp 82/11/30 10pp 16544 041

DOCKET 40-3265 VITRO ENGINEERING CO

- 8212160080 Add1 response to FBIA request for records re receipt, processing, storage or removal of source matl at Canonsburg, PA,Vitro Meg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining into under review FELTON.J M Division of Rules and Records 82/09/30 BLACK, A & Buchanan, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312
- --8212160337 Authorizes receipt & transfer of V &/or thorium source matl Specific license must be obtained by 610514 JUHNBON, L Atomic Energy Commission 61/04/06 Vitro Engineering Co 1p 16448 067
- --8212160341 Authorizes license to receive & possess 1 lb source math during term of license for fabrication DELANRY.J C Atomic Energy Commission 58/09/08 Vitro Engineering Co 1p 16448 068
- --8212160350 Application for license to receive thorium oxide from Heavy Minerals Co Requests that license authorize shipment of coated rod to Atlantic Research Corp for testing LITTEL.E 0 Vitro Engineering Co 58/09/05 2pp 16448 069

DOCKET 40-3392 ALLIED CHEMICAL CORP , MORRISTOWN, NJ

- 8212160060 Application for Amend 5 to License SUB-926, increasing possession limit of natural U from 50 million 1b to 75 million 1b CIPOLLA.A J Allied Chemical Corp 82/10/29 NIXON,W A Vranium Fuel Licensing Branch 5pp 16447 253
- --8212160067 Requests remittance of minor amend fee for review of 821029 application to amend License SUB-326 WEISB.D License Fee Management Branch 82/11/16 CIPOLLA.A J Allied Chemical Corp ip 16447 258

DOCKET 40-3453 ATLAS MINERAL, INC . DENVER, CO

- 8212030281 Forwards Securities & Exchange Commission 10-K Rept & Annual Financial Rept for FY82, supplementing 821029 submittal resurety agreement w/UT Board of Oil, 0as & Mining BLUBAUDH, R E Atlas Minerals 82/11/09 SMITH.R D Uranium Recovery Licensing Branch 21pp 16322 266
- ~-8212030282 Annual Financial Rept, 1982 FARLEY, E R Atlas Minerals 82/09/14 45pp 16322 288
- B212270401 Forwards "Gamma Survey of Tailings Pond & Perimeter, Third Guarter 1982" EDWARDS:D L Atlas Minerals B2/11/22 SMITH, R D Uranium Recovery Licensing Branch 1p 16590 003
- --8212270405 "Qamma Survey of Tailings Pond & Perimeter, Third Quarter 1982 " * Atlas Minerals 82/11/22 73pp 16590 004
- 8212290123 Responds to 821104 ltr re location for background air particulate monitoring site Location of Bite 5 satisfactory provided NRC objective is to determine radionuclide concentrations representative of source BLUBAUGH, R E Atlas Hinerals B2/12/02 PETTENGILL, H Region 4, Office of Director 2pp 16606 332

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8212070407 Forwards chemical data for water samples omitted from semiannual rept for Jan-June 1982 ANDRUS, N J Faderal American Partners 82/11/08 GILLEN, D Office of Nuclear Material Safety & Bafeguards, Director 30pp 16356 197.

- 8912010295 Submits review of second half of 1981 environ monitoring rept & air sampling data omitted from first half rept Control TLD should be added TLDs at old camp may be deleted Map showing monitoring locations should be updated GILLEN.D M Region 4. Office of Director 82/11/22 Region 4. Office of Director 59 16271 272
- 8212230170 Lists info which would suppl record & facilitate more knowledgeable final decision on approval/disapproval of proposed in-pit tailings disposal plan ACKERMAN, W C Wyoming, State of 82/11/24 ANDRUS, N Federal American Partners 4pp 14544 009

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

- 8212170405 Forwards DES. "Remedial Actions at Former Vitro Rare Metals Plant Site. Canonsburg, VA County. PA" (CAMPBELL, RH Energy, Dept of 82/12/03 NIXDN, WA Uranium Fue) Licensing Branch 5pp 16481 001
- --8212170409 "Remedial Actions at Former Vitro Rare Metals Plant Site. Canonsburg, UA County, PA" * Emergy, Dept of DOE/EIS-0076-D 82/11/30 574pp 16481 009
- G212160080 Add1 response to FOIA request for records re receipt, processing storage or removal of source mati at Canonaburg. PA, Vitro Mg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review FELTON. J M Division of Rules and Records G2/09/30 BLACK. A E Buchanan, Ingersoll, Rudewald. Kyle & Buerger 7pp 16447 312
- --8212160082 Forwards recent correspondence re facility
 DUBINSKI.L Atomic Energy Commission 63/11/08 KIRKMAN.R &
 Atomic Energy Commission 1p 16448 245
- --B212160097 Forwards 630715 ltr to AEC from Vitro describing proposal for temporary storage of tailings & for decontamination of bldgs & southment at facility Ltr dtd 630814 amending license & decontamination limits encl NUSBBAUHER: D A Atomic Energy Commission 63/11/08 GERUSKY.T Pennsylvania, State of 2pp 16448 247
- ~-8212160105 Forwards followup insp rept for License SUC-315 on 621220 Noncompliance noted failure to decontaminate bidgs \(\lambda\) unauthorized entry into facility CLEVELAND, R S Atomic Energy Commission 63/10/25 PRICE.E R Atomic Energy Commission 3pp 16448 248
- ~-8212160123 Advises that inspirept of License SUC-315 should be completed immediately despite lack of results on analytical samples DUBINSKI. Atomic Energy Commission 63/10/23 KIRKMAN, R W Atomic Energy Commission 1p 16448 264
- -8212160131 Provides results of resurvey of Bldgs 14 & 16 Bldg 14 had U tailings Tailings removed & properly packaged for disposal Bldg 16 radiation level unchanged MURPHY, J D Allied-Crossroads Nuclear Corp 66/01/11 RUDER, R 7 Vitro Engineering Co 1p 16447 358
- --B212160140 Forwards 31 soil, sludge, water & vegetation samples for analysis KIRKMAN, R W Atomic Energy Commission 43/10/17 SILL, C W Atomic Energy Commission 1p 16448 269
- --B212160144 Thirty-one soil, sludge, water & vegetation samples * Atomic Energy Commission 65/10/11 Spp
- --8212160161 Provides results of close-out survey at facility, including lagoon area, plant area & Bidgs 14 & 16 Related info encl NELSON,P R Atomic Energy Commission 65/11/09 Atomic Energy Commission 79p 16448 030
- ~-B212160168 Confirms ER Resner of AEC 631007 visit to facility to collect grab samples.per telcon CURRAN.J E Vitro Engineering Co 63/10/03 BUCKLEY.F J Buckley Insurance Agency ip 16448 274
- --B212160182 Requests final close-out facility insp as soon as practicable Final survey results supplied by Allied-Crossroads Nuclear Corp forwarded to Region 1 on 651005
 BROCKETT.T W Atomic Energy Commission 65/10/07 NELSON, R Atomic Energy Commission 1p 16448 039

DOCKETED ITEMS

- --B212160191 Confirms that licensee 630717 % 26 ltrs in response to 630628 followup ltr completes enforcement action re insp of License SUC-315 on 62120,630103 % 0218 followup insp should be conducted to determine progress PAGE.R G Abomic Energy Commission 63/09/18 DUBINSKI.L Atomic Energy Commission 1p 16448 277
- --8212160193 Forwards Allied-Crossroads health physics survey rept re facility Related info encl MARPHY.J D Allied-Crossroads Nuclear Corp 65/09/30 NUSSBAUMER.D A Atomic Energy Commission 3pp 16448 041
- --Poi2160197 Requests that during followup facility inspirepresentative samples be obtained from specific locations & analyzed for natural U & thorium. Th-230 & Re-226 NUSSBAUMER. D A Atomic Energy Commission 69/09/12 PAGE.R G Atomic Energy Commission 1p 16448 278
- --B212160214 Advises that AEC license required for possession of stored U remidues contained by weight more than 0 05% AEC authorization required to dispose of or transfer mat1 by methods not specified by 10CFR20
 NUSSBAUMER.D A Atomic Energy Commission 63/09/13 TERRELL, J 0 Health & Human Services: Dept of, 1p 16448 279
- ~-8212160293 Discusses 630812 meeting w/JE Van Zandt re current status of problems associated w/Vitro Corp of America in Canonsburg, PA Licansee responsible for control of tailings until adequate disposal method determined LQU, L D Atomic Energy Commission 63/08/12 DUBINSKI, L Atomic Energy Commission 200 16448 292
- --8212160260 Amends Condition 8 of License SUA-315 for storage & decontamination only at facility Results of analyses & surveys after decontamination showing that conditions specified in 630502 ltr have been met requested NUSSBAUMER. D. A. Atomic Energy Commission 63/08/14 1p 16449 057
- --B212160264 Health physics survey conducted at Vitro Rare Metals Plant in Canonsburg, PA Related into enc! MURPHY, J D Vitro Engineering Co 63/07/24 8pp 16448 290
- --8212100273 Source Matt License SUA-315 for Vitro Corp of America to store 23 tons of U contained in 4.458 tons of milling by-product residual matt only at facility in accordance w/ procedures of 6/0521 application RUBSBAUMER, D.A. Atomic Energy Commission 61/06/23 1p 16448 058
- --8212160284 Forwards 630607 memo from Region 1 requesting that licensee be contacted in order to determine status of property wirespect to ownership & possession DUBINSKI.t. Atomic Energy Commission 63/06/11 PRICE,E R Atomic Energy Commission ip 16448 300
- --B212160307 Requests add1 info re description of storage area including procedures & facilities used to prevent unauthorized persons from entering area & procedures for preventing spread of airborne radioactive contamination while in storage AUSSGAUMER, D.A. Atomic Energy Commission 61/05/29 LITTEL, E.G. Vitro Engineering Co. ip 16448-061
- --B212160315 Forwards application for source matl license to cover possession of stockpiles of residue still on hand Pending completion of disposal arrangement negotiations re proposed new source matt license should be issued LITTEL.E G Vitro Engineering Co 61/05/12 Atomic Energy Commission 2pp 16448 062
- --B2:2160352 Source Matt License R-179 for Vitro Corp of America, authorizing use of 48.000 tons of milling byproduct residue matt containing 0 5% 0-308 on dry basis through import from Canada

 JOHNSON.L Atomic Energy Commission 54/08/16 ip 16448 319
- --8212160362 Discusses burial of U bearing residues at facility Licensee covered by timely application until burial operation & facility satisfactorily completed BROCKETT.T W Atomic Energy Commission 65/08/09 Atomic Energy Commission 2pp 16448 071
- --8212360370 Confirms 650615 talcon re buriel of U bearing residues at facility Removal of U residues not begun but state has given permission Effort may not be completed until Sept.1965
 BROCKETI.T W Atomic Energy Commission 65/06/13 KIRKHAN,R W, DAVIS.J G, HAGEMAN.R C Atomic Energy Commission 1p 16448 073 1

- --8212160388 Discusses burial of U bearing residues at Canonsburg, PA by Vitro Corp of America State must issue permit Region 1 will make closeout check survey DUBINSKI, L. Atomic Energy Commission 65/03/10 KIRKMAN, R W , DAVIS, J Q , HAGEMAN, R C Atomic Energy Commission ip
- --8212160424 Discusses Div of Compliance insp of facility Licensee wants to sell property & has prospective buyer Residue stockpile must be disposed of first BLARCOM.E C. Atomic Energy Commission 69/03/13 Atomic Energy Commission 3pp 16448 328
- --8212160432 Advises of 630212 insp of facility status of compliance w/10CFR30. "Licensing of Byproduct Hatl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation." Records re regulations should be available KIRKMAN.R W Atomic Energy Commission 63/02/11 DIBB.G Vitro Engineering Co ip 16448 362
- --B212160435 Application to renew License SUC-315,formerly operated by Vitro Rare Metals Co LITTEL.E G Vitro Engineering Co 64/06/02 NUBSBAUMER.D A Atomic Energy Commission 3pp 16448 139
- --B212160436 Advises of 630212 insp of records re-status of compliance w/iOCFR30. "Licensing of Byproduct Matl.iOCFR40." "Control Source Matl" & IOCFR40. 'Sids for Profection Against Radiation "Records re-regulations should be available XIRMMAN.R & Atomic Energy Commission 63/02/01 DIBB.9 Vitro Engineering Co. ip 16449 001
- --B212160459 Notifies that facility bldgs & grounds w/exception of area fenced off around pile of radioactive contaminated soil & matliare released for occupancy LISBON.J Pensylvania, State of 64/04/24 CURRAN,J Vitro Engineering Co. ip 16448 154
- --8212160464 "Health Physics Survey of Vitro Former Rare Metals Plant, Canonsburg, PA " MURPHY, J D Atomic Energy Commission 64/03/19 4pp 16448 162
- --B212160466 Advises of 630103 inspire status of compliance w/10CFR30, "Licensing of Byproduct Matl," 10CFR40, "Control of Source Matl" & 10CFR20, "Stds for Protection Against Radiation "Records to regulation should be available KIRKMAN.R W Atomic Energy Commission 62/12/27 BRANNAN,C D , CURRAN,J Vitro Engineering Co 1p 16449 002
- ~-B212160471 Advises of 621220 insp of facility & status of compliance w/10CFR30, "Licensing of Byproduct Matl." 10CFR40, "Control of Source Matl" & 10CFR20, (Stds for Protection Against Radiation " Records should be available KIRKMAN.R W Atomic Energy Commission 62/12/12 BRANNAN,C D , CURNAN,J Vitro Engineering Co ip 10449 003
- --8212160485 Analytical results of samples collected by Region 1 during followup insp on 631007

 * Atomic Energy Commission 63/10/09 3pp 16448 168
- --8212160506 Partial results of environ samples from facility area • Atomic Energy Commission 63/11/20 6pp 16448 R21
- --B212160516 Forwards trip rept of meeting w/PA Btate Health & Vitro Corp of America re facility DUBINSKI,L Atomic Energy Commission 63/11/21 KIRKMAN,R W Atomic Energy Commission ip 16448 228
- --8212160527 Discusses insp of activities under License SUC-315 on 631009 at Canonsburg.PA & on 631016 in NY Noncompliance noted failure to conduct surveys of unrestricted areas outside fenced restricted area at facility PRICE A Atomic Energy Commission 63/11/11 LITTEL.E Q Vitro Engineering Co. 3pp. 16448 239
- --8212160583 Forwards EC Van Blarcom 631105 memo re Div of Compliance insp of facility DUBINSKI,L Atomic Energy Commission 63/11/08 KIRKMAN,R W Atomic Energy Commission 2pp 16448 242
- --B212160587 Discusses reinsp of facility. Final disposition of old radium bearing fatlings not resolved VAN BLARCOM.E Atomic Energy Commission 63/11/05 Atomic Energy Commission ip 16448-244
- 8212220010 Forwards "Results of Radiological Survey at Canonsburg Sita Vicinity Property CA 133," per 791221 itr NOTT.W E Energy, Dept of 82/10/26 SCARANO,R A Uranium Recovery Licensing Branch ip 16529 103

- --8212220013 "Results of Radiological Survey at Canonsburg Site Vicinity Property CA 133 " * Dak Ridge National Laboratory 82/09/30 49pp 16529 104
- DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY
- 8212030270 Issues Amend 11 to License SUA-442 revising Condition 28 to delete ref to piezometer T-5 & to require installation of new piezometer in northern abutment section SMITH,R D Region 4. Office of Director 82/11/19 Pathfinder Mines Corp 2pp 16316 309
- --8212030272 Recommends issuance of amend to License SUA-442, revising Condition 28 to delete ref to piezometer T-5 & to require installation of new piezometer in northern abutment section GARCIA,P J , PETTENGILL,H J Region 4, Office of Director 82/11/19 Region 4, Office of Director 4pp 16316 311
- 82:2230079 Forwards analysis of samples taken from tailings pond wells on 8208:2 Tailings water quality monitoring data for 1982 requested to help determine if discrepancy between wells LIDSTONE.C Hypming, State of 82/12/02 PETTENGILL,H Uranium Recovery Licensing Branch 11pp 16544 327
- 8212300129 Forwards sample analyses performed by Camp Dresser & McKee on Pathfinder Shirley Basin tailing pond well samples Trip rept dtd 820817 & C Schugarts 820927 ltr re corrected rept encl LIDSTONE, C Wyoming, State of 82/12/02 : Recovery Licensing Branch 11pp 16624 252 PETTENGILL, H Uranium
- 8212290132 Forwards "Environ Monitoring Data W/Dose Calculations.Third Guarter 1982 " GMITH.J C Pathfinder Mines Corp 82/12/09 SOLLENBERGER.D Uranium Recovery Licensing Branch 1p 16606 294
- --8212290136 "Environ Monitorino Data W/Dose Calculations, Third Quarter * Pathfinder Mines Corp 82/12/09 27pp 16606 295
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CO . SHIRLEY BASIN, WY
- GP12230084 Requests ruling on effect of proposed corporate mod on license Planned change would not affect property ownership of mine & mili facilities
 YDUNO.0 S Detty Oil Co (Petrotomics) 82/12/02 PETTENGILL. VYOUNG, OS Octty Dil Co (Petrotomics) 82/12/02 PETTENGILL, H Uranium Recovery Licensing Branch ip 16544 325
- 8212270325 Informs that data necessary to complete 10CFR40 65 & 40CFR190 repts has not been received Repts should be submitted no later than 821221 PFAFF, B J Getty Oil Co (Petrotomics) 82/12/07 JONES, B Uranium Recovery Licensing Branch ip 16555 324
- DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA
- B212020122 Trip rept of B21118 visit to Boyertown & Reading.PA facilities & 821119 visit to Revero.PA facility re license WYNOARDEN:S D Office of Nuclear Material Safety & Safeguards.Director 82/11/24 CROW.W T Office of Nuclear Material Safety & Safeguards.Director 1p 16308 299
- 8212230389 Forwards list of environ questions requiring written response in order to complete review of environ info submitted on 820806 as part of renewal action for License WYNGARDEN,S Uranium Fuel Licensing Branch 82/12/13 COYLE,F.T Kawecki Berylco Industries, Inc. 5pp. 16540 234
- DOCKET 40-7006 ARMY, DEPT OF, WHITE SANDS, NM
- 8212210412 IE Insp Findings & Licensee Ack dtd 821208-10 of License SUB-734 Insp findings no violations observed SHOPENNIN M Region 4. Office of Director 82/12/10 2pp

- DOCKET 40-8006 KERR-MCGEE CORP , OKLAHDMA CITY, OK
- 8212210184 IE Insp Findings & Licensee Ack dtd 821116 of License BUB-936 Insp findings no violations observed Steps taken to correct violations identified during last insp verified BHGPENN,N M Region 4. Office of Director 82/11/16 2pp 16484 336
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP / OKLAHOMA CITY, OK
- 9212230379 Forwards recent sampling data for new Monitor Well 2331 Well used for groundwater chemistry monitoring associated w/ injection well SHELLEY, N J Kerr-McGee Corp 82/12/06 KOSLA, B M Uranium Fuel Licensing Branch 2pp 16529 356
- --82122303B0 Sampling data for new Monitor Well 2331 WIDMANN.R K Kerr-McGee Corp 82/11/29 2pp 1A529 35B
- 8212140659 Trip rept of 821129 visit to Univ of MO in Rolla, MO & 821201 & 02 site visit to Kerr-McGee facility in Gore, UK re vendor requests to amend License SUB-1010 in area of waste injection wells KOSLA.B. WYNOARDEN.S D., RHODES, M. Uranium Fuel Licensing Branch 82/12/09 CROW, N.T. NRC No Detailed Affiliation Given 2pp 16464 188
- 8212270563 Revision to 820901 application to amend License SUB-1010 for 212270363 Revision to 820901 application to amend License SUB-const of sludge processing plant Facility changes & layout revised Revisions to App A included in Sequoyah 820924 license renewal application SHOLLEY, W. J. Kerr-McGee Corp. 82/12/10 PAGE, R. G. Uranium Recovery Licensing Branch. 42pp. 16548 308
- DOCKET 40-8064 EXYON MINERALS CO USA, HOUSTON, TX
- 82:122:0536 Forwards "Expanded R&D Pilot U Solution Mine Restoration & Post-Restoration Program," in accordance w/License Conditions 28 & 27 of License SUA-1064 GILCHRIST, J E Exon Corp 82/09/17 LINEHAN, J J Uranium Recovery Licensing Branch 1p 14502 273
- --8212210542 "Expanded R&D Pilot U Solution Mine Restoration & Post-Restoration Program " * Exron Corp 07151 82/09/17 14pp 16502 274
- 8212060456 Notification of 821020 meeting w/NRC in Cheyenne.WY to discuss restoration of acid patterns & Minerals Exploration Wyoming, State of 82/10/07 MARTIN.L , OGLE.K , IEL.P Wyoming, State of 1p 16343 310 SCHMITTDIEL, P
- 8212010056 Reviews second quarterly rept No actions necessary as result of review KALMAN,K L , LINEHAN,J J Region 4. Office of Director B2/11/22 Region 4. Office of Director 2pp 16271 340
- 8212300017 Discusses 820628-0702 insp of Highland Operation are a to examine activities conducted under Licenses SUA-1139 & 1064 re radiation safety Infraction found w/SUA-1064 License Condition 13, "Restoration Phase of Monitor Wells " KALMAN, K L , LINEMAN, J Region 4, Office of Director 82/12/17 SMITH, R D Region 4, Office of Director 3pp 16628 188
- DOCKET 40-8084 RIG ALGOM CORP , MOAB, UT
- 8212030278 Requests assurance that license will be extended in event Reg Outde 3 5 renewal document delayed beyond B21130 filing deadline.per 821102 telcon HARDY.B L Rio Algom. Ltd B2/11/09 GARCIA.P Uranium Recovery Licensing Branch ip 16322.315
- 8212030274 Forwards data emitted from Second Quarter 1982 environ monitoring Pept HARDY.B L Rio Algom, Ltd B2/11/16 Office of Nuclear Material Bafety & Safeguards,Director [Spp 16316 276
- 8212040004 Reviews Rio Algom Corp 820901 land use survey No change in land use occurred that would result in significant increased impact to public or environs MOCLSEY,R T. PETTEMOLL.H J. Region 4, Office of Director 82/11/19 Region 4, Office of Director Ip 16325 336

- 6212230404 Forwards application for renewal of License SUA-1119. authorizing use of natural U for production of U oxide as authorizing use of the covery Licensing Uranium Recovery Licensing Branch Ip 16541 001
- --8212230411 Application for renewal of License SUA-1119, authorizing use of natural U for production of U oride as yellowcake Wione oversize figure Aperture card is available in PDR LAMFOLM D Rio Algom. Ltd 62/12/31 384pp id541 002
- B/12280074 Reviews repts submitted under 40CFR190 & 10CFR40 &5 requirements for Second Quarter 1982 Licensee in compliance WOOLSEY.R T Region 4. Office of Director 82/11/29 Reg Office of Director 4pp 16590 166
- 82:12270331 Forwards corrected Th-230 air particulate analyses reported In 821116 addendum to Second Quarterly Rept. 1982

 IMARDY.B L Rio Algon, Ltd 82/12/02 NRC - No Detailed

 Affiliation Oliven ip 16595 325
- DOCKET 40-8102 EXXON CO USA, HOUSTON, TX
- B.12030285 Application for administrative amend to License SUA-1139 to recycle tailings solution from tailings basin to mill for use in milling process & for transport of mill tailings to tailings basin SMANNON, J B tailings basin SMANNCN.J B Eizon Corp 82/11/05 PETTENGILL,K J Uranium Recovery Licensing Branch Jpp 16316 216
- 8212060496 Forwards review of environ monitoring data & 400FR190 dose Assessment for Second Quarter 1982
 JONES S Z Region 4. Office of Director 82/11/26
 Office of Director 5pp 16348 015 Region 4.
- BY12230063 Requests confirmation of authorization to receive 60 $55-\rm gallon$ drums of unprocessed U ore & 20 drums of depleted U are U ore YARNICK.T P Erzon Comp. 82/12/06 PETTENGILL.H J. Umanium Recovery Licensing Branch . 1p. 16544-361
- DOCKET 40-8135 MINNESOTA MINING & MANUFACTURING, ST PAUL, MN
- 8,12220262 IE Insp Findings & Licensee Act dt6 821213 of License STB-1127 Insp findings no noncompliance noted BURGIN.R E Division of Project & Resident Programs 82/12/13 lp [6518 330
- DOCKET 40-8200 CLEVELAND-CLIFFS IRON CO . CASPER. NY
- 8212030306 Notifies that State of NY will not release Cleveland Cliffs In Co from responsibility until vegetation established, probably in Spring 1983 No source natl license will be assued until corrective actions taken (CHANCELLOG, R. A. Hyoming State of 82/11/16 SMITH, R. D. Orfice of Director 1p 16316 336
- DOCKET 40-8348 MINERALS EXPLORATION CO . LOS ANGELES, CA
- 8F1217043B Informs of Dept of Environ Quality position re groundwater restoration, based on Aug 1982 restoration status rept If samples taken from uells at end of nonth show geotechnical stability then wells can be plugged & reclamation begun ENGELMANY.R Wyoming. State of 82/11/22 ABRAMO.J Union Dil Co ENGELMANY.R Wyoming. State of of California 1p 16478 134
- DOCKET 40-6355 AMAX SPECIALITY METALS CORP . PARKERSBURG, NV
- 8712090208 Responds to 821103 Itr espressing concern over toxicity of soil samples taken from LB Foster Co site Surveys revealed presence of buried esecution/thorium residues from pilot plant operations Air sampling revealed low radioactivity D'REILLY, J.P. Region 2: Office of Director B2/11/17 Affiliation Uninown 2pp 16362 344

- DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO . BROOMFIELD, CO
- 8212060456 Notification of 821020 meeting w/NRC in Cheyenne,WY to discuss restoration of acid patterns & Minerals Exploration restoration SCHMITTDIEL, P
- 8212030284 Forwards requested groundwater quality data for Patterns 1.2 & 3 at Nine Mile Lake Project Data includes well sampling results for important water quality parameters from Feb-Sept 1982 . Rocky Mountain Energy Co 82/11/01 @GLE,K M te of 3pp 16316 219 NEUGARN M R Wyoming, State of
- --8212030295 Groundwater quality data for Feb-Sept 1982 * Rocky Mountain Energy Co 82/11/01 18pp 163 16316 222
- 8212230183 Forwards pH sample analyses for Monitor Wells M-16 & M-18 & analyses for Pattern 2 U concentrations during 1 yr of stabilization monitoring per 821118 telcon request NEUMANN M R Rocky Mountain Energy Co 82/11/19 KALMAN K Uranium Recovery Licensing Branch 28pp 16540 267 02/11/19 KALMAN, K 16540 267
- 8212010059 Advises that Amend 3 for License Condition 37 required submittal of surety instrument & is exempt from feas KALMANAK L Low Level Waste Licensing Branch LINEMAN, J J Region 4, Office of Director 82/11/22 MILLER, W O License Fee Management Branch 1p 16271 339
- BP12030264 Reviews Rocky Mountain Energy Co second quarterly environ monitoring rept for Apr-June 1982

 KALMAD K L , LINEHAN J Region 4. Office of Director 82/11/23

 Region 4. Office of Director 3pp 16316 320
- DOCKET 40-8452 BEAR CREEK URANIUM CD , CASPER, WY
- 82:12030254 Informs that U Recovery Field Ofc opened in Lakewood, CO on 821004 Licensing work will continue in Washington.DC through Apr 1983 to assure least disruption during transition period
 SMITH.R D Region 4. Office of Director 82/11/04 YELLICH, J
 Bear Creek Uranium Co 2pp 16316 342
- 821228C079 Submits compliance evaluation of B20915 duse calculations per 400FR190 requirements for Second Quarter 1982 Mill in compliance w/requirements SOLLEE/BERGER, D. Low Level Waste Licensing Branch 82/11/24 L. Level Waste Licensing Branch 3pp 16590 170
- 8212290157 Forwards environ monitoring rept for Third Quarter 1982, per 10CFR40 65 BLOSSOM, J K Beer Creek Uranium Co 82/12/06 Licensing Branch Ip 16606 322 Uranium Recovery
- --8212270161 Environ monitoring rept for Third Quarter 1982 * Bear Creek Uranium Co 82/12/06 9pp 16606 323
- DOCKET 40-8511 COTTER CORP , GOLDEN, CO
- 9212030258 Forwards addl info addressing NRC concerns re in-plant safety portion of renewal application, in response to NRC 820707 ltr 82/11/03 PETTENGILL.H J Uranium 17pp 16317 324 MCCLUSKEY, J P Cotter Corp 82, Recovery Licensing Branch 17pp
- DOCKET 40-8584 MINERALS EXPLORATION CO , LOS ANGELES, CA
- 8212070456 Suggests complementary review of Minerals Exploration application for amend to License SUA-1350, modifying tailings disposal scheme e Wyoming, State of 82/11/1; «Ina Branch ip 16355 263 82/11/12 SMITH, D Uranium Recovery Licensing Branch 1p
- B212210558 Advises that on B21105, airborne concentration of radioactive mat1 exceeded specified limit when yellowcake spilled during packaging operations No worker exposure believed to have occurred Device to prevent overfilling will be installed SNYDER.H L Union 76 Minerals Exploration Co 82/11/17 Director's Office, Office of Inspection and Enforcement Spp 14509 243 16529 343

DOCKETED ITEMS

DUCKET 40-8502 SILVER KING MINES. INC . CASPER, WY

82/12230391 Comments on review of 820827 preoperational environ monitoring rept for Jan-Jul 1982 for License SUA-1356 Except for high U area, monitoring data rept shows background environ levels of radionuclides
SOLLENBERGER, D Low Level Waste Licensing Branch PETTENGILL, H J Region 4. Office of Director 82/12/14 Low Level Waste Licensing Branch 3pp 16540 229

DOCKET 40-8610 STEPAN CHEMICAL CD , MAYWOOD, NJ

B212290368 Discusses IE Insp Rept 40-8610/82-01 conducted on 820929 No noncompliance noted Issues which need to be resolved include schedule for amending license to include thorium & rationale for depth of different boreholes

MARTIN T T Division of Engineering & Technical Programs 82/12/15

O'BRIEN: J Stepan Chemical Co 2pp 16586 162

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO

- 82:12070509 Forwards data sheets for Monitor Wells 1-5 % 7-2 % culinary water well chemical analyses, omitted from Second Guarter 1982 effluent & monitoring rept BAKER.C E Energy Fuels Nuclear, Inc. 82/11/15 GILLEN,D Uranium Recovery Licensing Branch 10pp 16354 275
- 8P12020001 Discusses results of annual land use survey covering White Mass Mill operational paried from Jul 1981-Jul 1982, submitted 820806 No addi review or licensing action required GILLEND M. LINEMAN, J.J. Region 4. Office of Director 82/11/22 Region 4. Office of Director 1p. 14308 302
- B212030229 Reviews Energy Fuels Nuclear 820726 tailings retention sys annual insp summary for June 1981-June 1982 Tailings retention sys operating as designed w/no major problems or conditions that would lead to failure GILLEI,D M , LINEHAN,J J Region 4. Office of Director 82/11/23 Region 4. Office of Director 2pp 16316 337
- GE/1203023B Summary of G20913 meeting w/Energy Fuels Nuclear in Silver Spring.MD re tailings reclamation program, reclamation costs & proposed surety arrangements GILLEN.D M , LINEHAN.J J Region 4. Office of Director 62/11/23 Region 4. Office of Director 7pp 16317 352
- 8P12030244 Trip rept of 821012 meeting w/Energy Fuels Nuclear in Denver,CO re long-tarm stability aspects of revised White Mesa tallings reclamation plan & 821013 visit to Pinal Minerals & Mining Heap Leach Site near Globe,AZ GILLEN,D M , LINEMAN,J J Region 4, Office of Director 82/11/23 Region 4, Office of Director 3pp 16316 339
- 8F12030251 Reviews Energy Fuels Nuclear 820827 10CFR40 45 environ monitoring rept for Apr-June 1982 Reported data within applicable limits Chemical groundwater data will be sent as suppl to second quarter rept GLLEN, D.M. . LINEHAN, J.J. Region 4, Office of Director 82/11/23 Region 4, Office of Director 4pp 16316 355
- 82/12290012 Forwards "Effluent & Monitoring Rept.Jul Sept 1982" BAKER, C.E. Energy Fuels Nuclear, Inc. 82/11/24 Glilen, D. Uranium Fuel Licensing Branch ip 16607-183
- --8212270013 "Effluent & Monitoring Rept. Jul Bept 1982 " * Energy Fuels Nuclear, Inc. 82/11/23 32pp, 16607 184
- GF12280040 Reviews dose evaluation & compliance evaluation forwarded in 820827 ltr re 40CFR190 compliance for Becond Quarter 1982 SDLLENBERGER, D Low Level Waste Licensing Branch 82/12/01 Low Level Waste Licensing Branch 3pp 16591 359

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO . DENVER, CO

82:2060456 Notification of 82:020 meeting w/NRC in Cheyenns, WY to discuss restoration of acid patterns & Minerals Exploration restoration
1850H.0 Wyoming, State of 82/10/07 MARTIN, L., OGLE, K., SCHMITTDIEL, P. Wyoming, State of 1p 16343 310

- BP12230183 Forwards pH sample analyses for Monitor Wells M-16 & M-18 & analyses for Pattern 2 U concentrations during 1 yr of stabilization monitoring.per 82118 telcon request NEUMANN, M R Rocky Mountain Energy Co 82/11/19 KALMAN, K Uranium Recovery Licensing Branch 28pp 14540 267
- DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8211020241 Forwards "Earthwork QC Overview & Ag-Built Drawings Const of Stage I Tailings Impoundment & Dam. Shootaring Canyon U Project.Garfield County.UT," per License Conditions 42 & 43 GERDEMAN.F H Plateau Resources. Ltd 82/09/17 FLEMING.T E Uranium Recovery Licensing Branch 1p 15915 249
- --8211020246 "Earthwork GC Overview & As-Built Drawings Const of Stage & Tailings Impoundment & Dam. Shootaring Canyon U Project.
 Garfield County, UT "
 GORDON, B B Moodward-Clyde Consultants. Inc 82/07/28 57pp
 15915 250
- ~~8211020252 "Embankment Foundation & Slush Orouting Photographs & Qeologic Map " Wiene oversize map & 37 photographs Aperture card is available in PDR # Plateau Resources, Ltd 82/09/30 12pp 15915 307
- 8212070045 Advises that 820924 annual land use survey for mill acceptable fLEMING.TE , PETTENGILL.H J Region 4, Office of Director 82/11/29 Region 4, Office of Director 2pp 16335 361
- 8212270319 Informs that add1 data re tailings dam compaction rept will be delayed due to Mountain States Mineral Enterprises law suit
 - DERDEMAN, F. H. Plateau Resources, Ltd. 82/11/30 FLEMING, T. E. NRC - No Detailed Affiliation Given. 1p. 16955-323
- 8212300120 Notifies that submittal of requested test result data retailings den compaction repts will be delayed due to use of data in Mountain States Mineral Enterprises suit, per NRC 021028 request GERDEMAN,F H Plateau Resources, Ltd 82/11/30 FLEMING.T E NRC No Detailed Affiliation Given ip 16624 249
- B212280093 Advises that UT Div of Wildlife Resources review of Platonu Resources Ltd proposed monitoring of wildlife not necessary Recommends annual samples of fauna & biota be taken from tailings impoundment area FLEMINO, T E Region 4. Office of Director 82/12/01 Region 4. Office of Director 2pp 16592 i19
- 8212270340 Informs that due to recent resignation of DJ Allen, RJ Cerr has been appointed environ & radiological health supervisor effective 821207 GERDEMAN, F U Plateau Resources, Ltd 82/12/08 FLEMING, T E NRC - No Detailed Affillation Given 2pp 18555 361

DOCKET 40-8728 TETON EXPLORATION BRILLING CO . INC . CASPER, WY

- 8212170443 Issues Amend 7 to License SUA-1373, revising License Conditions 10,23,25,27 & 30 to reduce environ & in-plant radiation safety monitoring requirements between conclusion of R&D activities & startup of proposed mining operations SHITH-R D Region 4. Office of Director 82/11/26 Tetor Lxploration Drilling Co . Inc. 2pp. 16478 135
- --8212170459 Safety evaluation recommending issuance of amend to Licensu 8VA-1373, revising License Conditions 10, 23, 25, 29 & 30 to reduce environ & in-plant radiation monitoring requirements between R&D activities & startup of mining operations ROSG, PW , LINEMAN, JJ Region 4, Office of Director 82/11/26 App 16478 137

DOCKET 40-8743 CONOCO: INC . DENVER: CO

- B21213012B Reviews Conoco, Inc application for permit to mine U ore at Moore Ranch Mine & Sand Rock Mill Project in Campbell County, HY Approval recommended w/listed stipulations LIDBTORE, C NRC No Detailed Affiliation Given B2/11/01 NRC No Detailed Affiliation Given Spp 16417:152
- B212060330 Forwards correspondence w/Btate of WY from B00B12 to B10724 re air quality permit GUIOLEY, TW CONDCO, Inc (Continental Gil Co) B2/11/18 FLEMING, T NRC No Detailed Affiliation Given 49pp [6328: 113

i

DOCKETED ITEMS

- --8212060336 "Study of Use of Porous Wind Fences to Reduce Fugitive Dust Transport at Mohave Generating Station "
 RADIEV.R L . HACCREADY.F B AeroVironment, Int AV-R-9563R
 80/07/31 68pp 16323 164
- BP12290145 Forwards responses to USGS.WY State Engineers of & EPA comments on Sand Rock Mill Project OUTGLEY, TH. CONDOS.Inc. (Continental Gil Co.) 82/12/08 FLEMING.T NRC No Detailed Affiliation Given 10pp 16606 28 16606 284
- DOCKET 40-8745 OGLE PETROLEUM, INC , CASPER, WY
- 8212070461 Requests advice re-fulfilling radiation safety officer specialized health physics training requirements.per Amond 3.by 821231 Licensee unable to find course of adequate CATCHPOLE, O J Ogle Petroleum, Inc 82/10/04 Lyn Uranium Recovery Licensing Branch 4pp 16354 285 LINEHAN, J J
- 8212100033 Submits final rept re 821010 leak in evaporation ponds at Bison Basin Mine Liquid detected in R&D pond stand pipe Caused by 3-inch guncture in gond line Hole patched using manufacturer recommended procedures CATCHPOLE.0 J Ogle Petroleum. Inc 82/11/10 SHITH.D Uranium Recovery Licensing Branch FRANCIS.E Myoming. State of lipp 14399-360
- B212170404 Forwards "Second Semiannual Rept for 820222-0924"
 SAUNDERS, G A Ogle Petroleum, Inc. 82/11/12 SHITH, D Uranium
 Recovery Licensing Branch 19 16480 013
- --8212170407 "Second Semiannual Rept for 820222-0824 "
 * Ogle Petroleum Inc 82/11/12 266pp 16480 16480 014
- 8212070490 Forwards check covering 821004 amend request Requests extension be revised from 6 to 12 months due to slow down in offering of radiation safety courses CATCHFOLE, 0 J Ogle Patroleum, Inc. 82/11/15 WEISS, D License Fee Management Granch in 16354 274
- 8212030235 Reviews Ogle Petroleum Inc 820409 excursion notification of Monitor Wall M-17 & 820721 quarterly excursion rept for Monitor Wells M-14,M-17 & M-72 Well M-72 not discussed as well was covered in previous memo YDUNG:YA. LINEHAN.J J Region 4. Office of Director 82/11/23 Region 4. Office of Director 4pp 16317 348
- B212280045 Discusses semiannual rept for Jul-Dec 1981 submitted B20420 Rept meets requirements Environ & operational data mest may permissible concentrations
 LINEMAMAU D Division of Resident, Reactor Project & Engineering Programs B2/12/01 Region 4, Office of Director 3pp Programs 82/12/01 16593 008
- 9212230219 Notifies that 821005 Unit 2 aquifer pumping test did not adequately demonstrate one ione confinement Test not conducted as approved by NRC Positive finding an evaluation of neu test using ratio method would allow authorization Shiffly D Uranium Recovery Licensing Branch 82/12/07 Ogle Petroleum, Inc. 299 14540-354
- DOCKET 40-8752 PINAL MINERALS & MINING, LTD . MIAMI, AZ
- 9212030244 Trip rept of 921012 meeting w/Energy Fuels Nuclear in Denver CO re long-term stability aspects of revised White Hesa tailings reclanation plan & 821013 visit to Pinal Hinerals & Mining Heap Leach Site near Olobe. AZ GILLEN, D M . LINEHAN, J J Region 4, Office of Director 82/11/23 Region 4. Office of Director 3pp 16316 339
- DOCKET 40-8768 KERR-HOGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 6212100403 Forwards second & third Guarter 1982 repts for G-Sand In-Site U Recovery R&D Project SHELLEY.H J Kerr-McGee Nuclear Corp 82/11/09 SCARANO.R A Division of Waste Managament 1p 16389 082
- --8212100407 "G-Sand In-Situ U Recovery R&D Project Second Quarterly Rept.Apr-June 1982." * Kerr-McGee Nuclear Corp. 82/11/09 55pp 16389.083
- -- 8212100410 "G-Sand In-Situ U Recovery R&D Project Third Quarterly Rept.

- 8212270149 Responds to items in NRC 821103 ltr re environ monitoring repts for First & Second Quarter 1982 FREEMAN,M S Kerr-McDes Nuclear Corp 82/12/07 LINEHAN.J J Uranium Recovery Licensing Branch 2pp 16606 282
- DOCKET 40-8771 MELAPAT RESOURCES CO , PHOENIX. AZ
- 8212230121 Notifies that cost data requested in 821115 ltr re License Condition 58 will be provided prior to injection of Liebviant BECK.M Malapai Resources Co 82/12/01 Recovery Licensing Branch 1p 16544 345 LINEHAN, J Uranium
- DOCKET 40-8781 TETON EXPLORATION DRILLING CO , INC . CASPER, WY
- B212080042 Forwards addl info re DES requested as result of public comment & review Weep hole in Figure 2-5 clarified Solid waste will be transported to Eizon licensed tailing facility APPEL:R R United Nuclear Corp 82/11/04 LINEHAN, J Region 4. Office of Director 4pp 16367 142
- DOCKET 40-8783 URANER2 USA, INC , CASPER, WY
- 8212280435 Forwards third quarter rept for 1982 SOMERVILLE.K 0 Uranerz USA.Inc 62/10/29 Recovery Licensing Branch 1p 15590 194 LINEHAN, J J Uranium
- --8212280439 Third quarter rept for 1982 * Uraner: USA.inc 62/10/29 87pp 16590 195
- 8212270264 Forwards rau data used in calculating upper control limits SCHMIDT.C Uraneri USA.Inc 82/11/19 YOUNG.Y Uranium Recovery Licensing Branch 8pp 16551 047
- DOCKET 49-8786 URANIUM RESOURCES, INC., RICHARDSON, TX
- 8212030261 Forwards decommissioning plan for wellfield & process facility Decommissioning will begin within 90 days PELIZZAM S Uranium Resources, Inc 82/10/14 LINEHAN, J Uranium Recovery Licensing Branch ip 16317 341
- --8212030263 Decommissioning plan for wellfield & process facility * Uranium Resources: Inc 82/10/14 5pp 16317 342
- 821228004| Conments on review of Resources, Inc quarterly rept (Apr 15-Jul 15.1982) Monitor well fluid level measurements do not indicate significant problem w/wellfield balance MESTBROOK.K B Region 4. Office of Director 20661 82/12/03 Region 4. Office of Director 3pp 16993 003

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1 F Security, medical, energency & fire protection plans

- B212140353 Advises that util will conduct annual ensite drill of emergency plan on 821208 Albernate drill dates are 821201 & 15 O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/09 HAYNES, R C Region 1, Office of Director 1p 16401 025 24X Fiche 50-003,82/11/09,8212140353
- 8212220096 Staff requirements memo re 821119 briefing by FEMA on status of emergency preparedness findings Conclusions re removal of deficiencies & overall adequacy of emergency plans will be submitted between 821203 & 17 CHILK.S J Dffice of the Secretary of the Commission 82/11/24 Office of the Secretary of the Commission 1p 16529 151 24X Fiche 50-003.82/11/24,8212220006
- B212030124 Responds to 820902 ltr describing corrective actions re significant deficiencies identified in FEMA 820730 rept. "Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts " HAYNEBAR C Region I. Office of Director 82/11/26 O'100LE, J D Consolidated Edison Co of New York, Inc. 2pp 16306 296 24X Fiche 50-003,82/11/26,8212030124

- --B212030248 Forwards description of activities planned or underway to correct deficiencies identified in FEMA interim findings on adequacy of radiological emergency response preparadness of state b local govts; per 820803 request 0.100LE, J D Consolidated Edison Co of New York. Inc 82/09/02 HAYNES, R C Region 1, Office of Director 11pp 16306 298 24X Fiche 50-003.82/11/26.8212030124
- GP/12220037 Releases public version of revised emergency plan implementing procedures FELTON. JM Division of Rules and Records B2/12/13 Document Management Branch ip 16527 336 24X Fiche 50-003,82/12/13,82/0220037
- --B212220042 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1001 remobilization of onsite emergency organization & IP-1039 reaffsite contamination checks
 D/TOOLE, J D Consolidated Edison Co of New York, Inc. 82/12/01
 HAYNES, R C Region 1, Office of Director ip 16527 337 24X
 Fiche 50-003, 82/12/13, 8212220037
- --8212220044 Public version of revised emergency plan implementing procedures, including Procedures IP-1001 re mobilitation of onsite emergency organization & IP-1039 re offsite contamination checks FINCH.0 L. Consolidated Edison Co. of New York, Inc. 82/11/08 43pp 16527 338 24X Fiche 50-003,82/12/13,8212220037
- 88'12210409 Forwards Event Notification Forms Part I & II to better prepare shift crews for questions NRC duty officer may ask during emergency notification STAROSTECKI.R Division of Project & Resident Programs 82/12/16
- B212290275 Releases public version of page changes to emergency procedures document FELTON J M Division of Rules and Records 82/12/20 Documen Management Branch 1p 14604 086 24X Fiche 50-003,82/12/20, B212290275
- --4212270302 Forwards public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/12/08 HAYNES, R C Region 1. Office of Director 1p 16606 087 24X Fiche 50-003, 82/12/20, 8212270275
- --B212270309 Public version of page changes to smergency procedures document re determination of magnitude of release & effect on offsite personnel One oversize drawing encl Aperture card is available in PDR SMITH, M Consolidated Edison Co of New York, Inc. B2/11/08 20pp 16606 08B 24X Fiche 50-003,82/12/20,821227025

!! General correspondence

- 8212270428 Responds to 821130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830110 scheduled DIRCKS,N J Office of the Executive Director for Operations 82/12/20 BRADLEY,B Senate 2pp 16568 339 24X Fiche 50-003,82/12/20,8212270428
- --B212270431 Forwards DK & FL Cinquement B20730 ltr requesting resumption of hearings on safety of plants
 BRADLEY.R Senate B2/11/30 Office of Congressional Affairs
 5pp 16568 341 24X Fiche 50-003, 82/12/20, 8212270428
- P Operating license stage documents & correspondence
- 8212070285 Notifies that radiological effluent Tech Specs & offsite dose calculation manual will be submitted by 830201 & 0401, respectively O'TOCLE. J D Consolidated Edion Co of New York, Inc. 82/12/01 VARGA. & A Operating Reactors Branch i ip 16339, 113, 24X Fiche 50-003, 82/12/01, 8212070285
- BP08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re sub, requirements Comments requested within 30 days of ltr 8vc list encl EISEMHUT.D G Division of Licensing BZ/12/09 Consolidated Edison Co of New York, Inc. 29pp 16629-247 24X Fiche 50-000,82/12/09,8208190263
- --B211220096 "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events," final draft MOREHOUSE, J. H., LINER, R. T., JOHNSON, B.W. Science Applications, Inc. NRC-03-82-131 B2/09/32 Division of Licensing 276pp 16629 281 24X Fichs 50-003, 82/12/09, 8208190263

- 6212270108 Forwards Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, safety evaluation & notice of issuance & availability Amends modify facility organization structure & testing requirements on containament isolation values HANNON, J N Operating Reactors Branch 1 62/12/11 0'TQOLE, J D Consolidated Edison Co of New York, Inc. 4pp 16553 200 24% Fiche 50-003, 82/12/11, 8212270108
- --B212270111 Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, modifying facility organization structure for Units 1 & 2 & testing requirements on containment isolation valves & snubber Tech Spacs for Unit 2 VARGA. S A Gperating Reactors Branch 1 B2/12/11 39pp 14553 204 24% Fiche 30-003, 82/12/11,8212270108
- --B212270113 Safety evaluation supporting Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively * Office of Nuclear Reactor Regulation, Director 82/12/11 4pp 1693 243 24X Fiche 50-003, 82/12/11, 8212270108
- --8212270117 Notice of issuence % availability of Amends 31 & 82 to Licenses DPR-5 & DPR-26.respectively VARGA.S A Operating Reactors Branch i 82/12/11 2pp 16853 247 24% Fiche 50-003.82/12/11.8212270108

Q Inspection reports, IE Bulletins & correspondence

- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recurculation Sys Piping at BHR Plants "Svc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Cansolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/19 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Bvc list encl DEYDUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pg 16411 865 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/90 Consolidated Edison Co of New York, Inc 356pp 16387 088 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bvc list encl DEYOUNG: RC Director's Office: Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc J13pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- B20B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYQUND,R C Director's Office. Office of Inspection and Enforcement B2/12/16. Consolidated Edison Co. of New York, Inc 127pp 16628 191 24X Fichs 50-000, 82/12/16,8208190267
- 8212220366 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE Info Notice 82-05 One util representative should be available to participate in antire meeting STAROSIECKI, R Division of Project & Resident Programs, 82/12/16 0'TODLE, J D. Consolidabed Edison Co. of New York, Inc. 3pp 16517 173 24% Fiche 50-003.82/12/16.8212220366
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDANNEL Division of Engineering & Quality Assurance, 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 273 3/4X Fiche 50-000,82/12/20,8208190268

T Hearing transcripts on non-antitrust matters

B212300235 Transcript of Commission 021221 meeting in Washington, BC re possible action concerning emergency preparedness at facilities Supporting documentation & vieugraphs encl * Commissioners 62/12/21 121p 16624 037 24X Fiche 50-003,82/12/21,8212300235

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
P Operating license stage documents & correspondence

6212030010 Informs of method for leak testing non-TRIGA (PATR) fuel elements fuel pellets will be loaded into separate aluminum tubes & sealed by arc welding to form fuel tube Record will verify integrity LEVINE.S H Pennsylvania State Univ 62/11/30 CARTER.R E Standardization & Special Frojects Branch 3pp 16304 231 24X Fiche 50-005,82/11/30.6212030010

DUCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, energency & fire protection plans

- BB12030283 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 82/11/30 Bocument Management Branch ip 16316 253 24X Fiche 50-010.82/11/30. 8212030283
- -- 8212030284 Forwards public version of revised emergency planimplementing procedures including Procedure EPIP 100-2 re shift turnover w/technical support ctr & environ teams activated Receipt forms & procedure histories encl SCOTT.D J Commonwealth Edison Co 82/11/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 16316 255 24X Fiche 50-010,82/11/30,9212030283
- ~-8212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover witechnical support ctr & environ teams activated & Commonwealth Edison Co 82/11/17 14pp 16316 262 24X Fichs 50-010,82/11/30,8212030283
- 8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pro-Established Onsite & Offsite Monitoring Locations (Maps) " FELTON. JM Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07,
- --821213002B Forwards public version of Revision i to Emergency Plan Roplementing Procedure EC-2, "Pre-Established Chaite & Offsite Monitoring Locations (Maps) "Revised table of contents encl PAJOASKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417 063 26% Fiche 50-000, 82/12/07, 8212130017
- ~-8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" PAJOMSXI, J E , LITERSKI, L A Commonwealth Edison Co 82/11/29 4pp 16417 065 24X Fiche 50-000.82/12/07.8212130017
- 8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood anner not prepared IRAKM.T R Commonwealth Edison Co 82/12/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000.82/12/07,8212140243
- 8212220175 Releases public version of revised generating station energency plan implementing procedures FELTON. JM Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fische 50-000.82/12/10, 82/12/20175
- ~-B212220190 Forwards public version of revised generating station amergency plan implementing procedures.including Procedures ED-3 re demand politing of meteorological data & ED-20 re emergency forecast request PAJONSKI.J E Commonwealth Edison Co 82/11/15 DENTON.H R. Office of Nuclear Reactor Regulation. Director ip 16529 030 24X Fiths 50-000.82/12/10.8212220179

- --B212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand golling of meteorological data & ED-20 re emergency forecast request LITERBXI,L A, PAJDHSKI,J E. Commonwealth Edison Co. B2/10/13 48pp 16527 031 24% Fiche SD-000,82/12/10.8212220175
- B212230019 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/12/15 Dacument Management Branch 1p 16545 350 24X Fiche 50-010, 82/12/15. B212233019
- --8212230028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1. "Guarterly Inventory of First Aid Supplies " SCOTT-D J Commonwealth Edison Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16545 351 24X Fiche 50-010, 82/12/15.8212230019
- --B212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Guarterly Inventory of First Aid Supplies" Revised Index enc!

 4 Commonwealth Edison Co 82/11/22 6pp 16545 354 24X Fiche 50-010,82/12/15,8212230019
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER.J C Region 3. Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000 82/12/16, 82102/0104
- B212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-20 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21)
 HILLER.J R Division of Engineering & Technical Programs 82/12/20 REED.C Commonwealth Edison Co 2pp 16562 120 24X Fiche 50-010, 82/12/20, 8212280214
- --8212280220 IE Safeguards Insp Rept 50-010/82-20.50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref ICCFR73 21) CHRISTOFFER.6 Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010.82/12/20.8212280214
- 8212300167 Releases public version of revised generating station the respective plan telephone directory FELTON. J M Division of Rules and Records 82/12/20 Document Management Branch ip 16612 215 24% Fiche 50-000,82/12/20,8212300167
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory HOORE:R D Commonwealth Edison Co 82/12/02 DENTON,H R Office of Nuclear Reactor Regulation. Director 1p 16612 216 24x Fiche 50-000.82/12/20.8212300167
- --8212300199 Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/11/05 60pp 16612 217 24K Fiche 50-000.82/12/20.8212300167
- H General correspondence
- 82:12280176 Notifies of change in mailing address for NRC licensing math WRIOHT, 0 N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82:12:20 EISENHUT, D.G. Division of Licensing ip 16556-135 24X Fiche 50-000.82/12/20, 82:12280176
- P Operating license stage documents & correspondence
- 8212140001 Add1 response to FOIA request for five categories of socuments re SEP Forwards documents listed in App A No socuments located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON.J M Division of Rules and Records 82/11/03 GALLO.J Isham. Lincoln & Beale 2pp 16433 354 24X Fiche 50-000,82/11/03,8212140001
- --7908090435 Forwards individual plant summaries re seismic capability & recommended interim actions Older SEP plants have less inherent margins to withstand lateral dynamic loads DAVIS,D K Systematic Evaluation Program Branch (Pre 791030) 79/06/18 VOLLMER,R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X Fiche 50-000,82/11/03,82(214000)

- --8009110797 Forwards excerpt from utils 680801. "Rept to Stockholders," re effect of 680515 tornadoes on util 345 kV sys DENION.H R Atomic Energy Commission 68/08/14 TEDESCO, R L Atomic Energy Commission 2pp 16434 254 24X Fiche 50-000,82/11/03.8212140001
- 8P12220212 Forwards Revision 82 to CE-1-A, "QA Program for Nuclear Generating Stations"
 5WARTZ.E D Commonwealth Edison Co 82/12/14 MAASS, W.P. Guality
 Assurance Branch 1p 16518 007 24% Fiche 50-000, 82/12/14, M2(2)20212
- --B212E20231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A RZ2 B2/11/01 17pp 16518 009 24X Fiche 50-000, B2/12/14.6212220212

O Inspection reports. IE Bulletins & correspondence

- 8706190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMF Plants "Syc list encl
 DEYQUNO.R C Director's Office. Office of Inspection and Enfancement 82/10/28 Consolidated Edison Co of New York. Inc 112pp 16462 163 24% Fiche 50-000. 82/10/28.8208190240
- G:OB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BO! & Model 802 Thermoluminescent Dosimeters " Svc list enc!
 COBB.L. I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372-142 24% Fiche 80-000,82/ti/05.8208190245
- BPOB190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quelity Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8:08190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlorks " 9vc list enci DEYOUND.R C Director's Office. Office of Inspection and Inforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8212060036 Ack receipt of 821028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 & 50-247/82-18 STREETER.JF Region 3, Office of Director 82/11/26 REED.C Commonwealth Edison Co 1p 16313 284 24X Fiche 50-010,82/11/26, 8212060036
- --8212060045 Responds to NRC 620928 ltr re violations noted in IE Insp Repts 50-010/82-13.50-237/82-17 & 50-249/82-18 Corrective actions inservice leak test performed on water leg portion of torus level mod Training session scheduled DELOEDRGE, L O Commonwealth Edison Co 82/10/28 KEPPLER, J Q Region 3, Office of Director 3pp 16313 285 24X Fiche 50-010,82/11/26.8212060036
- 8212170300 Forwards IE Insp Repts 50-010/82-19,50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted LITELS W S Division of Engineering & Technical Programs 82/11/29 REED. C Commonwealth Edison Co 2pp 16483 206 24X Fishe 50-010,82/11/29,8212170300
- --8212170306 IE Insp Repts 50-010/82-19, 50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted Major areas inspected licensee actions on previously identified items REIMANN.F W , JACKIM.I N Division of Engineering & Technical Programs 82/11/24 4pp 16453 208 24X Fiche 50-010, 82/11/29, 8212170300
- B2/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards G2/11/30 cpnsolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8212030178 Forwards final SALP Repts 50-010/82-10,50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981, discussed at 1E mpt meeting on 820602 Util 820618 comments on SALP rept addressed KEPPLER. J 9 Region 3. Office of Director 82/12/01 REED. C Commonwealth Edison Co 3pp 16303 228, 24X Fiche 50-010,82/12/01,8212030178
- ---8212030185 SALP Repts 50-010/82-10,50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981 Mgt attention warranted in areas of plant operations, radiological controls & review committee activities
 * Region 3, Dffice of Director 82/05/31 47pp 16303 231 24X Fichs 50-010,82/12/01,8212030178

- 8208190259 [E Bulletin 82-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 820B190261 (E Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list enc! JCRDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14462 064 24x Fiche 50-600, 82/12/03, 8208190261
- 8212170196 Forwards IE Insp Repts 50-010/82-18,50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/12/03 KEED.C Commonwealth Edison Co 2pp 16450 132 24X fiche 50-010,82/12/03,8212170194
- --8212170201 IE Insp Repts 50-010/82-18,50-237/82-25 & 50-249/82-25 on B21002-29 No noncompliance noted Major areas inspected headquarters & regional requests, operational safety verification, monthly maint observation & LERs TONGUE, Y M . STASEK, S . WALKER, R D Division of Project & Resident Programs B2/12/01 Bpp 16450 155 24X Fiche 50-010,82/12/03, 8212170196
- 8:08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 8:2/12/16 Consolidated Edison Co of New York. Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8:/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 273 24x (iche 50-000, 82/12/20, 8208190268
- 8212280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-17 Details & notice of violation withheld (ref 10CFR73 21) MILLER, J R Division of Engineering & Technical Programs 82/12/20 REED, C Commonwealth Edison Co 2pp 16562 120 24X Fiche 50-010, 82/12/20, 8212280214
- --8212280220 IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-247/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref | IOCFR73 21) CHRISTOFFER, Q. KNICELEY, J.R. CREED, J.R. Division of Emergency Preparadness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214
- BP12280070 Requests addition of RE Farrell to unescorted access list to vital & protected areas Individual possesses G clearance KEPPLER, J G Regian 3. Office of Director 82/12/22 REED. C Commonwealth Edison Co lp 16565 136 24X Fiche 50-010.82/12/22. REED. C Commonwealth Edison Co lp 16565 136 24X Fiche 50-010.82/12/22.
- R Periodic operating roports & related correspondence
- BR12140077 "1982 Evaluation Dresden Nuclear Power Station Comm Ed Co "
 * Institute of Nuclear Power Operations 82/11/30 39pp
 16403 171 24X Fiche 50-010.82/11/30.8212140077
- 8212140112 Forwards monthly operating repts for Nov 1982 SCOTT.D J. Commonwealth Edison Co. 62/12/01 Director's Office, Office of Inspection and Enforcement 1p 16408 204 24X Fiche 80-010.02/12/01.0212140112
- --0212140120 Monthly operating repts for Nov 1782 SCHROEDER B A Commonwealth Edison Co 82/12/01 16408 205 24X Fiche 50-010, 82/12/01, 8212140112
- DOCKET 50-13 BABCOCK & HILCOX CO CRITICAL FACILITY
 P Operating license stage documents & correspondence
- 8212030262 Responds to 821027 memo re planned reorganization of McDermott. Inc Conditions imposed on QA Co during formation should apply to 8&W DENTON, HR Office of Nuclear Reactor Regulation, Director 82/11/19 CUNNINGHAM.O H Office of the Executive Legal Director. ip 16316 349 24% Fiche, 50-013,82/11/17,8212030262

- DOCKET 50-20 MASSACHUSETTS INST OF TECH. RES REACTOR

 F Security, medical, smergency & fire protection plans
- B212150211 Approves 821013 Revision 27 to SAR which affects physical security plan for reactor facility Changes consistent w/provisions of 10CFR50 54(p) & do not decrease effectiveness of plan THOMAS,C O Standardization & Special Projects Branch 82/12/08 CLARK,L Massachusetts Institute of Technology 2pp 16447 663 24% Fiche 50-020,82/12/08/8212150211
- P Operating license stage documents & correspondence
- 8212280406 Application to amend License R-37, consisting of Tech Spec changes revising frequencies for surveillance testing of ECCS & charcoal filters in bldg pressure relief sys & Revision 28 to BAR revising testing frequency for ECCS CLARK. L Massachusetts Institute of Technology 82/12/22 THDMAS. C Standardization & Special Projects Branch 2pp 16960 042 24% Fiche 50-020, 82/12/22,8212280406
- --9212280411 Proposed Tech Spec changes revising frequencies for surveillance testing of ECCS & charcoal filters in bldg pressure relief sys SAR Page & 6 re tests & surveillance enc1 # Massachusetts Institute of Technology 82/12/22 6pp 15550 044 24X Fiche 50-020,82/12/22,8212280406

DUCKET 50-25 DOW CHEMICAL CO TRICA REACTOR

- C Utility Environmental Report (ER), amends & correspondence
- 82:122:10246 IE Safeguards Inap Rept 70-0025/82-10 on 82:1018-20 & itOl-05 No noncompliance noted Major areas inspected physical inventory & inventory verification & independent safeguards inspected physical inventory betails withheld (ref 10CFR2 790) NEL50N-G B , NORDERNAUG-L R Division of Radiological Safety & Safeguards Program 82/12/13 1p 16483 016 24X Fiche 50-025,82/12/14,82/22/10240

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

- Q Inspection reports. IE Bulletins & correspondence
- 8212130269 Forwards IE Insp Rept 50-027/82-03 on 821108-10 No noncompliance noted STERNBERQ.D M Division of Resident. Reactor Project & Engineering Programs 82/11/24 NYMAN.C J Washington State Univ 2pp 16390 161 24X Fiche 50-027.82/11/24.8212130269
- --B212130270 IE Insp Rept 50-027/82-03 on 821108-10 No noncompliance noted Major areas inspected organization logs, records, reviews & audits, requalification training, procedures, surveillance & experiments

 JOHNSON, A.D., TOTH, A.D., DODDS, R.T. Division of Resident, Reactor Project & Engineering Programs 82/11/23 5pp 16390-163 24X Fiche 50-027,82/11/24.8212130269

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

- F Security, medical, emergency & fire protection plans
- 8212140394 Forwards info re amergency operations facility (EOF) per 621201 teleon & Generic Ltr 61-10 Const of permanent primary.permanent bactup & interim EOFs complete KAY.J A Yankse Atomic Electric Co 62/12/06 CRUTCHFIELD.D Decasting Reactors Branch 5 2pp 16401 271 24X Fiche.50-029,82/12/06.8212140394
- 8212210149 Forwards add1 info to prepare shift creus operating nuclear plants for types of questions NRC duty officer may ask via NRC emergency notification sqs
 STAROSTECKI.R. Division of Project & Resident Programs 82/12/16
 HE1DER.L. H. Yantee Atomic Electric Co. 5pp. 16485-161 24X
 Fiche 50-029,82/12/16.8212210149
- J Insurance & indomnity information
- 8212300333 Forwards Endorsement 102 to NELIA Policy NF-76 & Endorsement 65 to MAELU Policy MF-26
 SINIBIL M Harsh & McLennan, Inc. H & M Nuclear Consultants, Inc Div 82/12/27 SALTMAN, J D Assistant Director for State & Licensee Relations 3pp 16594 072 24X Fiche 50-029, 82/12/27, 8212300333

- P Operating license stage documents & correspondence
- B211080101 Forwards Amend 74 to License DPR-3 Amend revises administrative controls section of Tech Specs to modify organizational structure & to reflect changes in titles CRUTCHFIELD D. Operating Reacturs Branch 5 82/11/02 KAY, J A Yankee Atomic Electric Co. 2pp. 15993-075 24X Fiche 50-029, 82/11/02.8211080101
- ~~8211080105 Amend 74 to License DPR-3 revising administrative controls section of Tech Specs to modify organizational structure & to reflect changes in titles CRUTCHFIELD, D. Operating Reactors Branch S. 82/11/02 7pp 15973 077 24X Fiche 50~029, 82/11/02, 8211080101
- --8211080107 Safety evaluation supporting Amend 74 to License DPR-3
 CARUSO,R Office of Nuclear Reactor Regulation, Director
 62/11/02 2pp 15/93 084 24% Fiche 50-029,82/11/02,8211080101
- --B211093110 Notice of issuance & availability of Amend 74 to License DPR-3 CRUTCHFIELD,D Operating Reactors Branch 5 82/11/02 2pp 15993 086 24X Fiche 50-029,82/11/02,8211080101
- GP12340001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 82/2140001
- ---/908090435 Forwards individual plant summaries re seismic capability to recommended interim actions Older SEP plants have less inherent nargins to withstand lateral dynamic loads DAVIS.D K. Systematic Evaluation Program Branch (Pre 791030) 79/06/18 VOLLMER.R H. Assistant Director for Systematic Evaluation Program (Pre 791030) Spp. 16434 321 24X Fishe 50-000, 82/11/03.8212140001
- --B203310470 Forwards SEP seismic completion plan to perform review parallel u/license efforts to complete SEP Topic III-6, seismic design Lomsiderations, for Group II plants HERMANN, R Systematic Evaluation Program Branch 82/03/08 RUSSELL, H T Systematic Evaluation Program Branch 5pp 14434 276 24X Fiche 50-000, 82/11/03.8212140001
- --0212140147 Discusses SEP site-specific spectra project Project in figural stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references re site-specific spectra (SEF Topic III-6) encl LEVIN.H A Systematic Evaluation Program Branch 79/11/13 EISENHUT,D & Division of Operating Reactors 4pp 16426 300 244 Fiche 50-000,82/11/03,8212140001
- 8212020356 Advises that draft safety evaluation input re SEP Topic VI-4. "Containment Isolation Sys" considered final input to integrated safety assessment CARUSO.R Operating Reactors Branch 5 82/11/24 KAY. J A Yankee Atomic Electric Co 2pp 16278 180 24% Fiche 50-029, 82/11/24, 8212020356
- BJ12020300 Application for Proposed Change 178 to License DPR~3, revising Tech Spec mar allowable peak rod linear heat generation rate limits as determined by Core XVI LOCA analysis
 MEIDER: I. H. Yankee Atomic Electric Co. B2/11/26. Office of Nuclear Reactor Regulation, Director 2pp. 16277 339 24X fiche 50-029, 82/11/26, 8212020300
- --8212020304 Proposed Tech Spec Change 17B revising max allowable prak rod linear heat generation rate limits as determined by Core XVI LOCA analysis a Yankee Atomic Electric Co 82/11/26 lipp 16277 341 24X Fiche 50-029,82/11/26,8212020300
- B212060026 Submits info re steam generator tube integrity, per B21026 generic itr No appreciable problems in steam generator tube integrity area identified KAY. J A Yankee Atomic Electric Co B2/11/29 CRUTCHFIELD, D Uperating Reactors Branch 5 2pp i6313 300 24X
- 8212070040 Advises that util util submit operator procedures, design details for diesel generator load shedding & Tech Specs at least 3 months prior to placing protection scheme in svc installation scheduled for 1984 refueling outage RAY, J A Yenkes Atomic Electric Co 82/11/30 CRUTCHFIELD, D Operating Reactors Branch 5 ip 16327 354 24% Fiche 50-029, 82/11/30, 8212070040

- Giri2070047 Requests examption from requirements of 10CFR50 44(c)(3)(i) requiring containments w/purge/repressurization sys as primally means of hydrogen control be provided w/internal hydrogen recombiner or ability to install recombiner KAY, J.A. Yankee Atomic Electric Co. 82/12/01 CRUTCHFIELD, D. Uperating Reactors Branch 5. 4pp. 16327-330 24X
- SE12130228 Forwards revised final evaluation of SEP Topic XV-16.

 "Radiological Consequences of Failure of Small Lines
 Carrying Primary Coglant Outside Containment " Doses meet
 acceptance criteria
 CARUSU, R Operating Reactors Branch 5 82/12/01 KAY, J A Yankee
 Atomic Electric Co App 16390 123 24X Fiche 50-029,82/12/01.
 8252130228
- G:12080376 Forwards Amend 77 to License DPR~3, safety evaluation & notice or issuance & availability Amend incorporates provisions required for operation w/refueled Core XVI into lech Specs (RUTCHFIELD.D. Operating Reactors Branch 5 82/12/03 KAY, J A Yankee Atomic Electric Co. 2pp. 16392-323 24X fiche 50-029, 82/12/03, 8212080376
- --0212080389 Amend 77 to License DPR-3, incorporating provisions required for operation w/refueled Core XVI into Tech Specs CRUICHFIELD.D Operating Reactors Branch 5 82/12/03 49pp 16392 325 24X Fiche 50-029, 82/12/03, 8212080376
- --8212080403 Notice of issuance & availability of Amend 77 to Licensu DPR-3 CRUICHFIELD, D. Operating Reactors Branch 5 82/12/03 2pp 16353 033 24X Fiche 50-029, 82/12/03, 8212080376
- G./12130223 Forwards final revision to offsite dose calculation manual Manual will be used for implementing requirements of proposed radiological effluent Tech Specs submitted in H20930 ltr

 KAY, J A Yankee Atomic Electric Co B2/12/06 CRUTCHFIELD, D Operating Reactors Branch 5 ip 16398 183 24X fisch 50-027, 82/12/06, 8212130223
- --0212133227 Off-site dose calculation manual HODODDN, A D , DILLINGS, W D Yankee Atomic Electric Co 82/12/01 123pp 16398 184 24% Fiche 50-029,82/12/06,8212130223
- GPOB190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISEN-UT.D 0 Division of Licensing B2/12/09 Consolidated Ldison Co of New York, Inc. 29pp 16629 247 24X Fishe 50-000.82712/09.8208190263
- E:12140259 Advises that requirements of TMI Action Items I A 1 2 4, "Upgrading Reactor Operator & Senior Reactor Operator Iraining," & II B 4, "Training for Mitigating Core Damage," have been met SER & technical evaluation rept forwarded CRUTCH-IELD.D Operating Reactors Branch 5 82/12/09 KAY, J A Yankee Atomic Electric Co 4pp 16401 312 24X [1che 50-027, 82/12/09, 82/12140259]
- -8212140260 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 I & II B 4," technical evaluation rept * Science Applications, Inc NRC-03-82-076 SAI-186-029-14 82/08/17 NRC No Detailed Affiliation Given 14pp 16401 316 24X Fiche 50-029,82/12/09,82/2140259
- G?:12140103 Generic Ltr 82-28 to all licensess of operating Westinghouse \$ C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Gnofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISERHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24% Fiche 50-000.82/12/10.6212140103
- Gi:12270365 Forwards SER & proprietary & nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11,8-60)," technical evaluation rapts Proprietary rept withheld (ref 10CFR2 770) GRUTCHFIELD, D Operating Reactors Branch 5 82/12/16 KAY, J A Yankee Atomic Electric Co 3pp 16532 247 24X Fichs 50-027,82/12/16,8212270365

- --82:2270367 Safety evaluation re environ qualification of safety-related electric equipment Info for items in ARC Categories I B, II A & II B justifying continued operation requested within 30 days

 * Orfice of Nuclear Reactor Regulation, Director 82/12/16 App 16532 250 24X Fiche 50-029,82/12/16.82:12270355
- --B207010124 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts (F-1), B-60), Yankee Atomaic Electric Co, Yankee Rowe," technical evaluation rept CRANE, C. J. Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-463 82/05/28 LE,N.B., SHEMANSKI,P. NRC No Detailed Affiliation Given 422pp 16532 256 24X Fiche 50-027,82/12/16.8212270365
- 8P1223023B Forwards Amend 7B to License DPR-3, safety evaluation & notice of issuance & availability Amend revises max allowable peak rod linear heat generation rate limits CRUTCHFIELD.D Operating Reactors Branch 5 82/12/17 KAY, J A Yankee Atomic Electric Co 2pp 16508 238 24X Fiche 30-029, 82/12/17. 821223023B
- --8212230243 Amend 78 to License DPR-3, revising max allowable peak rod linear heat generation rate limits as determined by revised core XVI LOCA limits CRUICHFIELD, D Operating Reactors Branch 5 82/12/17 4pp 14508 240 24
- --8212530248 Safety evaluation supporting Amend 78 to License DPR-3 LOIS.L., VOQLEMEDE.J., GILL.A. Office of Nuclear Reactor Regulation. Director 82/12/17 5pp 16508 244 24X Fiche 50-029,82/12/17.8212230238
- --82:2230264 Notice of issuance & availability of Amend 78 to License PR-3 WAMBACH, T V Operating Reactors Branch 5 82/12/17 2pp 16508 249 24X Fiche 50-029,82/12/17,8212230238
- 8:12280476 Forwards "Yankee SEP Integrated Assessment " KAY, J.A. Yankee Atomic Electric Go. 82/12/23 CRUTCHFIELD, D Uperating Reactors Branch 5 lp. 16556-254 24X Fiche 50-029, 82/12/23, 8212280476
- --8212280480 "Yankee SEP Integrated Assessment" * Yankee Atomic Electric Ca 82/12/31 297pp 16556 255 24X Fiche 50-029,82/12/23,8212280476
- O Inspection reports: IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wail, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svr list ent DEYGUNG.R C Director's Office, Office of Inspection and Lifortement 82/10/28 Conscilásted Edison Co of New York, Inc 112p 16462 163 24x Fiche 50-000, 82/10/28,8208190240
- G::08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model 802 Thermoluminescent Desimeters " Svc list nc1 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche. 30-000, 82/11/05, 8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Liercise Requirements " Svr list entl JORDAN.E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- B208190296 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUND: R C Director's Office Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190296
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CO88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Llectrical Penetration Assemblies " Byc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03.8208190259

- B.:08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay bockets "Svc list encl JDRDAN.E Division of Engineering & Guality Assurance 82/12/03 Compolidated Edison Co of New York: Inc _ 110pp 16462 064 24x Fiche 80-000.82/12/03.8208190261
- 8208190267 1E Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND, R C Director's Effice. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000, 82/12/16.8208190267
- 8P!2220418 Informs of interviews to be conducted similar to NRC study conducted in Mar 1982 re IE Info Notice 82-05. "Increasing Frequency of Drug-Related Incidents" Util will be contacted shortly to arrange interviews M/o stated NNREG STAROSTECKI.R Division of Project & Resident Programs 82/12/16 HEIDER.L H yankee Atomic Electric Co 2pp 16503 268 24X Fiche 50-029, 82/12/16, 8212220418
- BLOB190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of Rew York. Inc 108pp 16628 293 24: Fiche 50-000.82/12/20.8208190268
- M Periodic operating reports & related correspondence
- 87:12390126 Forwards monthly operating rept for Oct 1982 HEIDER:L H Yankee Atomic Electric Co 82/11/03 Office of Resource Management. Director 1p 16583-220 24X Fiche 50-007, 82/11/03,8212290126
- --8212290130 Monthly operating rept for Oct 1982 PHILLIPS, J Yankee Atomic Electric Co 82/11/05 5pp 14583 221 24X Fitch 50-027, 82/11/03,8212290126
- S Reportable occurrences. LERs & related correspondence
- EP12140184 Forwards updated LER 82-034/01T-1 AUTIO.H A Vantee Atomic Electric Co 82/12/03 HAYNES.R C Region i. Office of Director 1p 16410 214 24X Fiche 50-029, 82/12/03.8212140184
- --B2121401B7 Updated LER 82-034/01T-1 on 821009, leak detected on main coolant pump (vent line Gaused by incompatibility of reducing insert w/main coolant sys Carbon steel components replaced Wistainless steel
 FRENCH, L D Yankee Atomic Electric Co. 82/12/03 Region 1,
 Office of Director 2pp (6410-215 24X Fiche 50-029,82/12/03,8212140184)
- 82)2150155 Forwards LER 82-039/03L-0 AUTID.H A Yankee Atomic Electric Co 82/12/06 HAYNES.R C Region 1, Office of Director 1p 16430 183 24x Fiche 50-029.82/12/06,8212150155
- --8212150160 LER 82-039/03L-0 on 821106, emergency diesel generator 1 tripped causing de-amergization of emergency motor control ctr Caused by failure of mechanical seal on low pressure safety injection pump Seal replaced FRENTH. L D Yankee Atomic Electric Co 82/12/06 Region 1, 02/12/06 Director 1p 16430 184 24X Fiche 50-029, 82/12/06, 8212150155
- 8212210278 Foruards LER 82-040/03L-0 AUTIO.H A Yankse Atomic Electric Co 82/12/10 HAYNES,R C Region 1. Office of Director 1p 16483 033 24% Fiche 50-029.82/12/10,8212210278
- --8212210283 LER 82-040/03L-0 on 821112, in Mode 6, vital bus distribution panel de-energised when circuit breaker 1CB inadvertently opened Caused by length of electrical conduit striking circuit breaker switch Personnel Instructed to use caution RICE.D A Yantee Atomic Electric Co 82/12/10 Region 1. Office of Director 1p 14483 034 24% Fiche 50-029, 82/12/10, 9212210278
- 8212270251 Forwards LER 82-041/03L-0 AUTIO.H A Yankee Atomic Electric Co 82/12/16 HAYNES.R C Region 1. Office of Director 1p #6582 041 24X Fiche 50-027.82/12/16.8212270251
- --8212290258 LER 82-041/03L-0 on 821116.during Mode 6.while performing rain coolent sys pressure channel callor procedure.Loop 1 channel initiation setpoint found out of Tech Spec limits Caused by drift in main control board indicator HAY.E L Yankee Atamic Electric Co 82/12/16 Region 1, Office of Director 1p 16382 042 24X Fiche 50-029.82/12/16.

- 8:12270310 Forwards LER 82-042/03L-0 AUTIO.H A Yankee Atomic Electric Co 82/12/17 HAYNES.A C Hegion I, Office of Director 1p ,16588 027 24X | 11che 50-027.82/12/17.8212270310
- --8212290316 LER 82-042/03L-0 on 821117.loop 2 low pressure scram setpoint found out of Tech Spec limits Caused by drift in main control board indicator Indicator recallbr MAY.E L Vankee Atomic Electric Co 82/12/17 Region 1, Office of Director ip 14588 028 24X Fiche 50-027,82/12/17,8212290310

DDCKET 50-54 UNION CARBIDE RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 5./12070173 Forwards response to 821104 request for add1 info & add1 lech Spec changes re renewal fo License R-61 VITH.N H Union Carbide Corp 82/11/22 THOMAS.C D Standardization & Special Projects Branch 14pp 16337 001 24% [1che 50-094.82/11/22,8212070173
- --8212070162 Proposed Tech Spec changes re frequency of pool water analysis & inclusion or radiation organization in description of organizational structure * Union Carbide Copp 82/11/22 4pp 16337 015 24x Fiche 50-054,02/11/22 8212070173
- B71203015B Suppl to 800523 amend to License R-81 re renewal & Tech Spec changes Footnote re Tech Spec 3 2 3 presently requiring that ion chamber of third channel be operable prior to reactor startup should be deleted Marked-up Tech Specs encl VOTH. If H Union Carbide Corp 82/11/27 BERNARD, H Standardisation & Special Projects Branch 2pp 16303 001 24X Fichs 50-054.82/11/29.8212030158

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- G Adjudicatory correspondence
- G.12280276 Requests delay to respond to 821021.1112 & 17 memoranda & orders due to inaccessability of documents needed for complete response Partial response to GE 821123 requests provided 1VRK. J. Affiliation Unknown 82/12/20 FRYE, J. H., LINENBERGER, G., FOREMAN, Atomic Safety and Licensing Board Panel 2pp 16561 230 24% Fiche 50-070.82/12/20.8212280276
- G212300022 Grants J Turk petition for extension until 830105 to respond to ASLB G21119 memorandum & order Other petitioners & intervenors granted same extension NRC response due by 630117 FRYE.J H Atomic Safety and Licensing Board Panel 82/12/27 TURK.J Affiliation Unknoon 1p 16598 310 24X Fiche 50~070.82/12/27,8212300022

BOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

R Periodic operating reports & related correspondence

- 8712070004 Forwards "Annual Progress Rept of Univ of FL Training Reactor," Sept 1981-Aug 1982 DIALN J Fiorids Univ of Gainesville 82/11/30 Standardisation & Special Projects Branch ip 16327 244 24x Fiche 50-083,82/11/30,8212070004
- --8212070007 "Annual Progress Rept of Univ of FL Training Reactor,"
 Sept 1981-Aug 1982
 DIAI.N J. VERNETSON.W G Florida. Univ of, Gainesville
 ORO-4014-12 82/11/30 26pp 16327 245 24X
 Fiche 50-083.82/11/30.8212070004

DOCKET 50-87 GENERAL ATOMIC CO

J Insurance & indemnity information

B212060142 Provides response to B21013 request for clarification re Indeanity Agreement B-9 & corporate mane DENTON.H R Office of Nuclear Reactor Regulation, Director G2/11/22 MDMRY.H R GA Technologies, Inc / Ogneral Atomic Co ip 14325 354 24X Fiche 50-089, 82/11/22,8212060142

- P Operating license stage documents % correspondence
- 8, 12060142 Provides response to 821013 request for clarification re Indennity Agreement 8-9 % corpolate name BENTON:H R Office of Nuclear Reactor Regulation, Director 02/11/22 MORFY:W R GA Technologies, Inc /General Atomic Co 1p 16325-354 24/ Fiche 50-089,82/11/22.8212060142
- NOCKET 50-97 CORPELL UNIV ZERO POWER REACTOR
- f. Uperating license stage documents & correspondence
- GP12680598 Notification of 821207-09 meetings w/Cornell Univ & LASL $i\pi$ Cornell No to discuss review of reactor facilities for license renewal processing questions sent to Cornell & LASL drast technical evaluation reps MERNARD. H Standardization & Special Projects Branch 82/11/23 THCMAS. C O Standardization & Special Projects Branch 3pp 16379 350 24x Fiche 50-097.82/11/23.8912080598
- R Periodic operating reports & related correspondence
- SP12140632 Forwards annual operating rapts for Licenses R-80 & R-89 for two yes ending 820630 ADERHCLD.H C. Carnell Univ 82/12/06 Region 1, Office of Director 1p 16409 001 24% Fiche 50-097.62/12/06.8212140232
 - H212140238 Annual operating repts for Licenses R-BO & R-89 for two yrs anding 820a30

 ADERHOLD H C Cornell Univ 82/12/04 Region 1, Office of Director 3pp 16409 002 24% Fiche 50-097,82/12/06,8212140232
- 8/12140469 Forwards "Annual Operating Ropts" for period ending June 1581 b June 1582 M/o encis 1581 b June 1582 M/o encis ADERPC.D.H C Cornell Univ 82/12/06 Director's or Inspection and Enforcement 1p 16404 012 24X Fiche 50-077, 82/12/06, 82/12/40469
- 8:12140146 "Annual Operating Rept. Jul 1980-June 1981" ADEPHGLD. H C Cornell Univ 82/12/14 Region 1, Office of Director 3pp 16408 173 24 (Fiche 50-097, 82/12/14, 8212140144
- DOUBLET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR W Decorrissioning Stage Documents & Correspondence
- G.·12070185 Advises that decommissioning will take longer than anticipated due to technical difficulty of breaking up heavily teinforced concrete Humber of demolition workers increased Work will be camplete by B30120 COCKRELL.R G North Carolina State Univ B2/12/03 ERICKSON,P Standardization & Special Projects Branch ip 16335-258 24X [iche 50-111, 82/12/03, 8212/070185]

- DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR
- f Security, medical, emergency & fire protection plans
- 8212010051 Releases public version of licensee info re status of FELTON J M Division of Rules and Records 82/11/24 Docum Management Branch 1p 16289 202 24% Fiche 50-112,82/11/24, 8212010061 Document
- --6212010066 Bubmits public version of status of emergency plan due 621103 Plan submitted on 820420 complies w/requirements No new plan need be developed or submitted TERRELL.C W Oklahoma. Univ of 62/10/27 DATES,E F EP Licensing Branch ip 16289 203 24X Fichs 50-112.82/11/24.6212010061
- G2:12:150040 Forwards IE Safeguards Insp Repts 50-112/82-02 & /0-1439/62-02 on 82:1025-29 No noncompliance noted MADSEH G L Division of Resident Reactor Project & Engineering Programs 82:12:209 UPHEGROVEN R CHahoma, Univ of 2pp 14421 322 24X Fiche 50-112,82/12/09,82:12:150040
- --B212150049 IE Safeguards Insp Repts 50-112/82-02 & 70-1430/82-02 212180049 IE Safeguards Insp Repts 50-112/82°02 & 70-1430/82°02 on 821025-29 No noncompliance noted Major areas inspected nuclear nati control & accountability, including facility organization & operation Details withheld (ref 10CFR2 790) CALD'KELL,R A , KELLY,J A Division of Resident, Reactor Project & Engineering Programs 82/11/30 ip 16421 324 24% Fiche 50-112,82/12/09.8212150040

- & Inspection reports, IE Bulletins & correspondence
- GP12070126 Forwards IE Insp Rept 50-112/82-01 on 820913-15 & notice //20/01co relegios to the horse to the horse to the holds of the horse to the horse
- 8212070130 Natice of violation from insp on 820913~15 * Division of Resident. Reactor Project & Engineering Programs 82/11/11 2pp 16327 057 24X Fiche 50-112,82/11/11,8212070126
- -8212070133 IE Insp Rept 50-112/82-01 on 820913-15 Noncompliance noted enzovasca in inspirent socializes—of on escolation Noncompliance noted failure to perform audit, failure to property conduct surveillance, lack of clear responsive method of keeping operating procedures up-to-date & technically correct SCHUM.W S. HURPH).M E. REDAND.R T. Division of Resident. Reactor Project & Engineering Programs 82/11/05 10pp 16327-059-24% Fiche 50-112,82/11/11.8212070126
- GP12150040 Forwards IE Safeguards Insp Repts 50-112/B2-02 & /0-1439/B2-02 on 821025-29 No noncompliance noted MADSEN 6 L Division of Resident, Reactor Project & Engineering Programs 82/12/09 UPTHEGROVEN R Oklahoma Univ of 2pp 16421 322 24X Fichs 50-112.82/12/09.B212150040
- --B212150049 IE Bafeguards insp Repts 50-112/82-02 & 70-1430/82-02 on 821025-29 No noncompliance noted Major areas inspected nuclear math control & accountability.including facility organization & operation Details withheld (ref 10CFR2 790) CALDWELL R A , KELLY, J A Division of Resident, Reactor Project & Engineering Programs 82/11/30 1p 16421 324 24X Fiche 50-112,82/12/09.8212150040
- V Operator Examinations
- 8/12060226 Contents on proposed requalification program Region will interface w/NRR when listed items resolved GAGLIARDD. J E Division of Resident, Reactor Project & Engineering Programs 82/12/01 IERRELL, 6 W Oklahoma, Univ of 10 16312 170 244 Fichs 50-112.82/12/01.8212060226
- --8212060230 Forwards requalification program for Univ of BK, for approval TERRELL.C H Oxlahoma, Univ of 82/10/11 CAGL[ARDD, J Region 4. Office of Director Ip 16312 171 24% Fiche 50-[12,82/12/01, 8212060226
- DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR P Operating license stage documents & correspondence
- G:12280211 Forwards confirmation by Reactor Safety Committee chairman that proposal for Tech Spec change reviewed & approved W Virginia Polytechnic Institute 82/12/22 Division of Licensing 1p 18562 279 24X Fiche 50-124,82/12/22,8212280211
- --8212280213 Forwards application to amend License R-62, revising Tech Specs to delete ultrasonic flow detector w/paddle wheel detector U/17 accuracy min HDLIAN P D Virginia Polytechnic Institute 82/12/14 THOMAS C Standardization & Special Projects Branch ip 16552 280 24x Fiche 50-124, 82/12/22, 8212280211
- --8212280216 Application to amend License R-62, revising Tech Specs to delete ultrasonic flow detector w/paddle wheel detector w/IX accuracy min HDLIAN.P D Virginia Polytechnic Institute 82/09/24 THOMAS.C O Standardization & Special Projects Branch 1p 16562 281 24X Fiche 50-124, 82/12/22, 8212280211
- --0212283217 Proposed Tech Specs deleting ultrasonic flow detector w/paddle wheel detector w/1% accuracy min * Virginia Polytechnic Institute 82/09/24 4pp 16562 282 24% Fiche 30-124,82/12/22,8212280211

DOCKET 50-128 TEXAS ASM UNIV RESEARCH REACTOR

9 Reportable occurrences, LERs & related correspondence

B212100279 RO on 821017.power level indication dropped approx 15% on both sarety channels On B21027.electromagnet current for shim sarety 2 went to zero Causes not stated Electromagnet

MODERS, D. Telas ALM Univ. College Station, TX 82/10/29 MADERS, G. Region 4, Office of Director 3pp 16376 299 (14X Fiche 50-128, 82/10/29, 8212100299

DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR
P. Operating license stage documents & correspondence

GP12030118 Informs that last fuel elements for AGN-211 reactor sent to Univ or ON on 821119, completing disposal of all reactor components u/exception or Ra/Be startup source Plans to conduct radiation survey of former reactor site underway BLACKSHAN, O. L. Nest Virginia Univ 52/11/29 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16303-014 24X Fiche 50-129, 82/11/29, 8215030118

DUCKET 50-193 HUMBQLDT BAY POWER PLANT, UNIT 3

@ Inspection reports. IE Builetins & correspondence

8/08190240 IE Gulletin 82-03.Revision 1. "Stress Cracking in Thirk-Wall, Large-Diameter, Stainless Steel.Recirculation Sys Piping at BRA Plants : S/c list encl
DEYGUNG.R C Director's Office. Office of Inspection and
Enforcement 82/10/28 Consolidated Edison Co of New York, lic
112pp 16462 163 24X Fiche 50-600, 82/10/28.8208190240

9:03190245 IE Info Natice 82-42. "Defects Observed in Panasonic Model 801 5 Model 802 Thermuluminescent Dosimeters " Svc list oncl COBB.L I Division of Fuel Facilities, Materials 5 Safeguards 82/11/05 Consolidated Edison Co of New York Inc 110pp 16372-142 24x Fiche 50-000.82/11/05.8208190245

9,08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Fiercise Requirements" Svc list encl JARDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Constituted Edison Co. of New York, Inc. 109pp. 16411

8708190296 IE Info Notice 82-46. 'Defective & Obsolete Combination Padlocks ' Svc list and DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 055 24X Fiche 50-000.82/11/26.8208190256

8,08190257 IE info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Sic list enci COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82/11/30 Consolidated Edison Co. or New York. Inc. 354pp. 16387 OZB 24% Fishe 50-000 82/11/30.8208190257

8208190259 IE Bulletin 82-04, 'Deficiencies in Primary Containment Liectrical Penetration Assemblies "Svo list encl DEYBUMG, RC Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Disc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259

8208190261 IE Info Notice 82-49. "Failures of Agestat CR 0095 Relay Sockets " Svc list encl JURDAN,E L. Divisson of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp. 16462 064 24) Fiche 50-000. 82/12/03. 8208190261

8)*08196267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list entl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 92/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-600,82/12/16,8208190267

8708190268 IE Info Natice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27' Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20 8208190268 R Periodic operating reports 3 related correspondence

SP12290182 Forwards monthly operating rept for Oct 1982
MEEKS E D Pacific Gas & Electric Co 82/11/02 Office of Resource Management, Director 1p 16580 091 24X
fiche 50-133.82/11/02.8212290182

- B212290186 Monthly operating rept for Oct 1982 DERMS. P Pacific Gas & Electric Co B2/11/02 4pp 14580 097 24x Fiche 50-133.82/11/02.8212290182

INDUKET 50-142 UCLA TRAINING REACTOR

© Adjudicatory correspondence

Beigo60236 Hemprandum & order menorializing B21124 & 1201 telcons & rulings on discovery re Contention XXI on emergency planning LUEBKE.E A. PARIS.O H., FRYE.J. H. Atomic Safety and Licensing Board Panel 82/12/02 California Univ of Los Angeles 5pp 16312 274 24X Fiche 50-142.82/12/02 8212060236

G212070013 Forwards NRC opposing citations to Committee to Bridge the Cap (CBG) statement of mat1 fact attached to CBG motion for summary disposition of Contention XIII MOUDLEAD.C P Hearing Branch 1 62/12/03 FRYE, J.H., PARIS.O H., LUERKE, E.A. Atomic Safety and Licensing Board Panel Jpp 16327 240 24X Fiche 50-142 82/12/03.8212070013

B212140456 Answers to Interrogatories C(1).u(17).C(18) C(19) C(22) & C(24) Certificate of Svc encl WDODHEAD.C P Hearing Branch 1 82/12/13 Committee to Bridge the Cap 16pp 16404 047 24x Fiche 50~142 82/12/13 8212140456

DOCKET 50-148 UNIV OF VANSAS RESEARCH REACTOR

li General correspondence

8.12270379 FOIA request for documents re Univ of KS research reactor BARNES,C Affiliation Unknown 82/11/09 Division of Technical Information & Document Control 1p 16568 346 24X Fiche 50-148.82/11/09.8212270379

G2122/0586 Responds to FOIA request for documents to Univ of KS research reactor Request referred to PDR for processing FELTON. JM Division or Rules and Records 682/11/18 BARNES. C Affiliation Unknown 1p 16568 347 24% Fiche 50-148,82/11/18.

P Operating license stage documents 5 correspondence

B/12020211 Responds to 821006 & 13 questions re annual operating & decormissioning costs for facility NRC practice assumes state legislature unil appropriate adequate funds for decormissioning state univ reactors THOMAS.C O Standardiration & Special Projects Branch 82/11/24 BARNES.C Kensas, Univ of 3pp 16302-321 24X Fiche 50-148, 82/11/24, 821202021

BP12280524 FOIA request for documents in possession of licensee re receiptions, disposal & storage of radioisotopes under License R-78 HARNES, C. Affiliation Unknown 82/11/25 Office of Administration 2pp 16593-030 24% Fiche 50-148,82/11/25, 8212280524

BP12E80527 Responds to FOIA request for documents in possession of licensee re receiptives, disposal & storage of radioisatopes under License R-78 Request not applicable to records in possession of licensee FELTON. J M Division of Rules and Records 82/12/14 BARNES, C Affiliation Unknown 10 16593-032 24X Fiche 50-148,82/12/14,82/12280527

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8P12010071 Releases public version of emergency preparedness plan FELTON, J M Division of Rules and Records 82/11/24 Document Management Branch Ip 16289 281 24X Fiche 50-150, 82/11/24, 8212010071

--B212010074 Forwards public version of emergency preparedness plan TALNAGI,J W Ohio State Univ 82/11/02 BATES,G EF Licensing Branch 1p 16289 282 24X Fiche 50-150,82/11/24,8212010071

- 8212010079 Public version of emergency preparedness plan e Ohio State Univ 82/11/30 53pp 16289 283 24x Fiche 50-150, 82/11/24, 8212010071
- DOCHET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR
- Q Inspection reports IE Bulletins & correspondence
- B212140396 Forwards IE Safeguards Insp Repts 50-151/82-01,50-356/82-02 & 70-0258/82-01 on 821117-19 & notice of violation Insp rept details withheld (ref 10CFR2 790) details withheld (raf 10CFR2 790)
 MILLER, J.R. Division of Engineering & Technical Programs 82/12/09
 MILEY, G.H. Illinois, Univ. of, Urbana-Champaign 2pp 16404-344
 P4X Fiche 50-151,82/12/09,8212140396 92/12/AB
- 8212140377 Notice of violation from insp on 821117-19 MILLER, J. R. Division of Engineering & Technical Programs 82/12/09 1p 16404 346 24X Fiche 50-151,82/12/09,8212140396
 - 8212140414 IE Safeguards Insp Repts 50-151/82-01.50-356/82-02 & 70-0258/82-01 on 821117-19 Nancompliance noted failure to include items containing SMM on annual inventory & to submit 742 forms Details withheld (ref 10CFR2 790) MADEDA, T J , CREED, J R Division of Engineering & Technical Programs 82/12/06 ip 16404 347 247 Fiche 50-151.82/12/09, 8212140396
- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8k12070300 Documents 821202 telcon re emergency operations facility Facilities for four plants completed Table encl VANDEWALLE, D. J. Consumers Power Co. 82/12/03 CRUTCHFIELD, D. Uperating Reactors Branch 5 2pp. 16343 196 24% Fiche 50-000, 82/12/03, 8212070300
- 02:12090387 Forwards IE Safeguards Insp Rept 50-155/82-18 on 82:025-29
- No noncomptiance noted
 MILLER, J.R. Division of Engineering & Technical Programs 82/12/03
 DEWITTR B Consumers Power Co. 2pp. 16364-349 24X
 Fiche 50-155, 82/12/03, 8212090387
- --B212090396 IE Bafequards Insp Rept 50-155/82-18 on 821025-29 No ELECTRICATE IE Barequards Insp Rept 50-155/62-18 on 821025-27 No noncompliance noted Major areas inspected security plan & implementing procedures access controls & previous items of noncompliance Details withheld (ref 100FR73 21)
 CHRISTOFFER, 0 , BELANGER, J. L., CREED, J. R. Region 3, Office of Director 82/12/02 ip 16364 351 24X Fiche 50-155,82/12/03,6212070387
- GP1210021B Responds to 821109 ltr re Revision 5 to security plan Modified screening program changes submitted as Revision & in 821105 ltr in 82:105 ltr VANDEWALLE.D J Consumers Power Co 82/12/08 CI Operating Reactors Branch 5 1p 16376 073 24X Fiche 50-000,82/12/08,8212100218 CRUTCHFIELD, D
- GP:12100285 Advises that changes to security & suitability, training & qualification plans submitted 821005 do not decrease safeguards effectiveness NRC approval of changes in accordance w/100FNSO 54(p) not required VANDEWALLE, D. J. Consumers Power Co. 82/12/08 CRUTCHFIELD, D. Operating Reactors Branch 5 [p. 16377 145 24X Fiche 50-000, 82/12/08, 8212100285
- GP12220304 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site amergancy operations facility KEPPLER. J O Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, page 252-252-252 6212220306
- G Adjudicatory correspondence
- G212020361 Response opposing licensee request for immediate review of partial initial decision re-criticality Piecemeal review unnecessary & would delay hearings Certificate of Svc encl SEMMEL, H Christa-Maria SEMMEL, H Antioch School of Law, Washington, DC 82/11/27 Atomic Safety and Licensing Appeal Panel 9pp 16270-325 24X Fiche 50-195, 82/11/29, 8212020361
- BP12070127 Forwards util 821029 ltr to NRC transmitting info re NRC review of seismic stability of overhead crane inside containment Info relevant to unlitigated portion of O'Neill Contention II C Related correspondence GALLO, J Isham, Lincoln & Beale OALLO, J Consumers Power Co 82/12/02 BLOCH, P B. PARIS, D H . SHON, F J Atomic Safety and Licensing Board Panel 125pp 16326 079 24% Fiche 50-155, 82/12/02,8212070127

- 8212070114 Order granting applicant motion to permit immediate appeal from ASLB 821027 partial initial decision since decision has likely immediate consequences Terms of ASLAB 821004 order waived to allow appeal
 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/12/03
 Consumers Power Co. 5pp. 16327 101 24X Fishe 50-155,82/12/03,
- BP12070247 Answer opposing licensee motion for stay of effectiveness of decision on criticality Licensee has had adequate time to prepare amended application Greater delays will result if stay granted Certificate of Svc encl
 SEMMEL.H Antioch School of Law, Washington, DC 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16339 150 24X Fiche 50-155, 82/12/03,8212070247
- --8212070303 Response opposing licensee request for immediate review of partial initial decision re criticality Review unnecessary.

 Delay in proceeding is licensee fault Need to maintain full core offload not demonstrated core offload not demonstrated SEMMEL.H Christa-Marıa SEMMEL.H Antıoch School of Law. Washington, DC 82/12/03 Atomic Safety and Licensing Appeal Panel 7pp 16339 152 24% Fiche 50-155,82/12/03,8212070247
- G212070327 Partial response to ABLB 820914 order directing util to demonstrate certain evidentiary deficiencies in emergency planning have been remedied, are not serious or are being remedied through adequate interim compensatory actions GALLO.J. COPELAND, V. G. Consumers Power Co. GALLO.J. Isham, Lincoln & Beale 82/12/03 14pp 16337 220 24X Fiche 90-155.82/12/03.8212070327
- --8212070330 Affidavit of JM Tyler re M1 State Police Emergency Mgt Div.
 training activities including radiological emergency
 planning & state & local official training
 TYLER, J M Consumers Power Co TYLER, J M Michigan, State of
 82/12/02 28pp 16337 234 24X Fiche 50-155.82/12/03.8212070327
- --8212070337 Affidavit of E Muma re training of bus drivers for Charlevoix Public School District & program being developed for training & qualifying personnel of other support groups needed during radiological emergency MUMA. E. Consumers Power Co. MUMA. E. Charlevoix. MI. 82/12/01 9pp. 16337 262 24X Fiche 50-155.82/12/03.8212070327
- --8212070340 Affidavit of WW Miller re annual training of support hosp emergency room staffs & ambulance crews around plant MILLER, W W Consumers Power Co 62/12/01 4pp 16337 271 24x Fiche 50-155, 62/12/03.6212070327
- --8212070345 Affidavit of GT Lasater showing adequate & current list of invalids, senior citizens & others needing transportation assistance in emergency planning zone is being maintained & plan for evacuation is in place
 LASATER.O T Consumers Power Co LASATER.O T Charlevoix.MI 82/12/01 20pp 16337 275 24X Fiche 50-155.82/12/03.8212070327
- --8212070349 Affidavit of A Saworski re mumber & availability of Charlevoix County Public Transit Bys buses for invalid evacuation from 5-mile emergency planning zone SAMORGKI.A Consumers Power Co SAMORGKI.A Charlevoix.MI B2/12/01 4pp [6337 295 24X Fiche 50-155.82/12/03.8212070327
- --B212070352 Motion for extension to respond to partions of ASLB 821021 order re Contentions 9(4) 4. 9(5) Certificate of Svc encl 9ALLO, J. COPELAND, V. 9. Consumers Pawer Co. OALLO, J. Isham, Lincoln & Beale 82/12/03 Atomic Safety and Licensing Board Pamel 7pp 16337, 299 24X Fiche 50-155.82/12/03.8212070327
- 8212080315 Memorandum & order denying util B21124 motion for stay of effectiveness of ABLD 821029 order Extension of time to comply w/order granted Util filing due within 60 days of issuance of ABLAB decision on util exceptions to order BLOCH.P B . PARIB.O H . BHON.F J Atomic Safety and Licensing Board Panel 82/12/07 Gonsumers Power Co Spp 16353 347 24X Fiche 50-155, 82/12/07, 8212080315
- 8212160223 Forwards application for subposens directing HR Denton to
- ---8212160227 Application for subposed directing HR Denton to appear for deposition on 821230 in Washington DC re Denton 820728 memo to ABLB Draft subposed & Certificate of Byc enci GALLO, J Consumers Power Co 82/12/13 Atomic Safety and Licensing Board Panel 1 1pp 16446 089 24X Fiche 50-155,82/12/13,8212160223

- 8212160509 Memorandum & order denying util 821213 application for subposes of HR Denton w/o prejudice ASLB lacks jurisdiction to reopen record on issue pending before ASLAB BLOCH.PB. PARIS, DH., SHON.FJ Atomic Safety and Licensing Board Panel 82/12/14 Consumers Power Co 2pp 16442 120 24% Fiche 50-155, 92/12/14, 8212160509
- 8212210258 Brief in support of exceptions filed to ASLB 821203 order granting idmediate appeal from 821029 partial initial decision on neutron multiplication factor O'Meill Contention 111 E-2 should be dismissed W/Certificate of Svc GALLO.J. THORNTON.P Consumers Power Co CALLO.J Isham, Lincoln & Beale 82/12/16 Abomic Safety and Licensing Board Panel 30pp 16483 269 24X Fiche 50-155.82/12/16.8212210258
- 8212210011 Advises of NRC/applicant agreement re NRC witness depositions Witnesses ML Broots & DB Fieno will be available for depositions on S21229 in Bethesda.HD GBDDARD.R J Hearing Branch 3 82/12/17 BLCCH.P.B. SHON.F.J. PARIS.O H Atomic Safety and Licensing Board Panel 2pp 16490-146 24X Fiche 50-155.82/12/17.8212210011
- 8212210285 Further response to ASLB 820914 order re Subcontention 9(4) on evacuation of school children & Subcontention 9(5) on list of invalids Sufficient measures being taken to maintain current list of invalids & senior citizens GALLO, J. COPELAND. V. O. Consumers Power Co. GALLO, J. Isham. Lincoln & Beele 82/12/17 12pp 16497 045 24X Fiche 50-155, 82/12/17, 8212210285
- --B212210287 Affidavit of VR Clack explaining evacuation procedures & routes for school children
 CLACK.V R Consumers Power Co OLACK.V R Charlevols, MI
 82/12/15 15pp 16497 067 24X Fiche 50-155, 82/12/17, 8212210285
- --8212210292 Affidavit of OT Lasater re results of recent updating of list of invalids & senior citizens to be evacuated during energency LASATER, OT Consumers Power Co. LASATER, OT Charlevoli, MI 82/12/16 9pp 16497 072 24X Fishe 50-155.82/12/17,8212210285
- --B212210276 Arfidavit of F Hooper re District Health Dept 3 cooperation w/Charlevoix County Sheriff to identify persons w/special care needs who would need assistance to evacuate Certificate of Svc enc!
 HD07ER: F Consumers Power Co HD0PER: F Charlevoix.MI
 82/12/14 Bpp 16497 GBI 24X Fiche 50-155.82/12/17, B212210285
- 8P12280292 Motion for protective order re deposition of H Denton on criticality issue Deposition must be delayed until all parties available, since intervenors have not received reasonable notice of deposition Certificate of Svc encl SEMMEL.H Christa-Haria SEMMEL.H Antioch School of Law. Hashington: DC 62/12/23 Atomic Safety and Licensing Board Panel 5pp 18561 396 24x Fiche 50-155, 82/12/23, 8212280292
- 8212300015 Menorandum & order denying Sunflower Alliance 821223 motion for protective order re HR Denton deposition Matter beyond ASLB jurisdiction BLOCK.P B Atomic Safety and Licensing Board Panel 82/12/27 Sunflower Alliance ip 16598 308 24X Fiche 50-155,82/12/27, 22/23/2015
- 9212300176 Advises that NRC will make witnesses available for depositions on 830510.due to intervenor counsel inability to attend depositions originally scheduled for 821229 GDDDARD.R J Hearing Branch 3 82/12/27 BLOCH.P B , SHON,F J , PARIS.D H Atomic Safety and Licensing Board Panel ip 16598 106 24X Fiche 50-155,82/12/27,8212300176
- P Operating license stage documents & correspondence
- G212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON J M Division of Roles and Records 62/11/03 GALLO, J Isham, Lincoln & Beale 2pp 14433 354 24X Fiche 50-000, 82/11/03, G212140001
- --7908090435 Forwards individual plant summaries re seismic capability & recommended interim actions Older SEP plants have less inherent margins to withstand lateral dynamic loads DAVIS:D K Systematic Evaluation Program Branch (Pre 791030) 79/06/18 VOLLMER:R H Assistant Director for Systematic Evaluation Program (Pre 791030) Spp 16434 321 24% Fiche 50-000,82/11/03.82(2(4000)

- --B203310670 Forwards SEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6.
 seismic design considerations for Group II plants
 HERMANN,R Systematic Evaluation Program Branch 82/03/08
 RUSSELL,W T Systematic Evaluation Program Branch 5pp
 16434 276 24X Fiche 50-000,82/11/03,8212140001
- --8204010021 Forwards evaluation for SEP Topic VI-4, "Containment Ivolation Sys." Outstanding items include insufficient isolation provisions in test, vent & drain lines & no isolation or leak detection provisions on ECCS subsystem SPEIS.TP Assistant Director for Reactor Safety 82/03/24 LANAS.G Assistant Director for Safety Assessment 34pp [6434-329 24X Fiche 50-000.62/11/03.8212140001
- --8207203474 Discusses problems w/completion of SER Topic 111-6 reseismic design considerations by 820930 Actions required to attempt to meet schedule listed HERRING, 8 S. Systematic Evaluation Program Branch 82/07/12 RUSSELL, N. T. Systematic Evaluation Program Branch 3pp 16434 326 24X Fiche 50-000, 82/11/03,8212140001
- --8212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references resite-spectra (SEP Topic III-6) encl
 LEVIN.H A Bystematic Evaluation Program Branch 79/11/13
 ETBERHUT.D Q Division of Operating Reactors 4pp 16436-300-244 Fiche 50-000.62/11/03.8212140001
- 8212030137 Forwards evaluation of SEP Topic III-1, "Classification of Structures. Components & Sys (Seismic & Quality) "Into re fracture toughness, full radiography requirements, valves & pipe cyclic loads on piping/fatigue analysis provided TONER, K.A. Consumers Power Co. 82/11/23 CRUTCHFIELD. D. Operating Reactors Branch 5 58pp 16306 041 24X Fiche 50-155, B2/11/23. G212030137
- BP12020255 Forwards safety evaluation of SEP Topic VI-1, "Organic Matle & Post-Accident Chemistry," based on licensee 820316 safety assessment rept Facility fails to meet current licensing criteria CRUTCHFIELD, D. Operating Reactors Branch 5 82/11/24 VANDEHALLE, D. J. Consumers Power Co. 8pp. 16279 339 24X Fishe 50-155,82/11/24,8212020255
- 8212020266 Forwards final evaluation of SEP Topic III-4 A, "Tornado Mássiles" Sys & components inadequately protected from tornado missiles Evaluation will be basic input to integrated safety assessment CRUTCHFIELD. D. Operating Reactors Branch 5 82/11/29 VANDENALLE, D. J. Consumers Power Co. 20pp. 16288-330 24X Fiche 50-155.82/11/29,8212020266
- 8212020332 Forwards evaluation of SEP Topic III-4 B. "Turbine Missiles" Turbine protection sys mod should be considered during integrated assessment Descriptions of sys need clarification GRUTCHFIELD D Operating Reactors Branch 5 82/11/29 VANDEHALLE, D. J. Consumers Power Co. 19pp. 16279 212 24: Fiche 50-155.82/11/29.8212020332
- 8P12020095 "Review of Big Rock Point Plant Request for Deformal of TME Action Items Considered Nonessential," inter(m rept PDLA5KI, J P., SULLIVAN.W H., GENTILLON,C D. EG&O. Inc. FIN A-4442 B212020095 82/11/30 CHON,E Division of Safety Technology 60pp 16309 080 24X Fichs 30-155.82/11/30,8212020095
- 8212230322 Responds to comments on SEP Topics VI-2 D. "Mass & Energy Release for Possible Pipe Breaks Inside Containment" & VI-3 "Containment Pressure & Heat Removal Capability "CRUTCHFIELD. D Operating Reactors Branch 5 82/11/30 VANDEWALLE.D J Consumers Fower Co 16pp 16507 293 24X Fiche 50-155,82/11/30,8212230322
- 8212070297 Forwards revised draft evaluation of SEP Topic III-3 A. "Effects of High Hater Levels on Structures " Containment & turbine bldgs, core spray room & stack adequately designed to withstand effects of design basis flooding level CRUICHFIELD.D Operating Reactors Branch 5 82/12/02 VANDEWALLE.D J Consumers Power Co 8pp 16339 116 24X Fiche 50-155,82/12/02,8212070299
- 8212090117 Notification of 821216 meeting w/util in Bethesda, MD to discuss status of seismic evaluation under SEP EMCH:R Derating Reactors Branch 5 82/12/08 CRUTCHFIELD. D Operating Reactors Branch 5 4pp 16357 268 24X Fische 50-155,82/12/08,8212090117

DOCKETED ITEMS

- OPID:SOOO Forwards Containment Bys Branch final evaluation of SEP lopic VI-4 "Containment Isolation Bys " Isolation valves would be more appropriately located between containment & high pressure HX CRUICHFIELD.D Operating Reactors Branch 5 82/12/09 VANDEWALLE.D J Consumers Power Co 47pp 16421 276 24X Fishe 50-155, 82/12/09, 8212150030
- B212230354 Forwards technical evaluation rept of SEP Topic ItI 2, "Wind & Tornado Loadings Big Rock Point Nuclear Plant"
 CRUTCHFIELD D Operating Reactors Branch 5 NRC-03-79-118
 B2/12/09 VANDEWALLE D Consumers Power Co 14pp 16511 266 24X (Iche 50-155, 82/12/09, 8212230354
- --B209230377 'Wind & Tornado Loadings, CPC. Big Rock Point Nuclear Plant," technical evaluation rept BARRETT, D. J. AOARMALR Franklin Institute/Franklin Research Center TER-C5257-405 B2/09/21 PERSINKO, D. NRC No. Detailed Affiliation Oliven 98pp 16511 280 24X Fiche 50-155, B2/12/09, B212230354
- B212170032 Submits response to NRC final SER on SEP Topic III-4 B,
 "Turbine Missiles" GE probabilistic analyses show very low
 probability of turbine sys failure even at runaway speeds
 SEP topic complete
 TONER, K A Consumers Fower Co 82/12/13 CRUTCHFIELD, D Operating
 Reactors Branch 5 2pp 16450 352 24X Fiche 50-155, 82/12/13,
 R321273082
- G212220209 Forwards revised final safety evaluation on SEP Topics V-11 A. "Requirements for Isolation of High & Low Pressure Sys" & V-11 B. "RHE Interlock Requirements" CRUTCHFIELD. Deprating Reactors Branch 5 G2/12/15 VANDEWALLE: D J Consumers Power Co 6pp 16503 004 24X Fiche 50-155,82/12/15.8212220209
- OP12230429 Forwards revised SER on SEP Topic VII-3, "Sys Required For Safe Shutdown" Design acceptable pending decision on Reg Guide 1 97. Revision 3 backfit CRUTCHFIELD, D Operating Reactors Branch 5 82/12/17 VANDEWALLE, D J Consumers Power Co 5pp 16503 302 24X [iche 50-155,82/12/17.8212220429]
- 8212230342 Application to amend License DPR-6, revising Tech Specs to replace min critical heat flux ratio w/min critical power ratio Tech Spec change request necessary to increase thermal power level Class III fee encl
 VANDEMALLE, D. J. Consumers Power Co. 82/12/20 CRUTCHFIELD, D. Uperating Reactors Branch 5 App. 16505 185 24X
 Fiche 50-155, 82/12/20, 8212230342
- --8212230343 Proposed Tech Spec replacing min critical heat flux ratio w/nin critical power ratio ** Consumers Power Co 82/12/20 2pp 16505 191 24X Fiche 50-155,82/12/20,8212230342
- B212E80103 Forwards application to amend License DPR-6, changing Tech Specs to clarify existing requirements to bring facility into closer agreement w/Midland Tech Specs & to achieve closer conformance w/STS
 VANDEMALLE,D J Consumers Power Co 82/12/20 CRUTCHFIELD, D Derating Reactors Branch 5 2pp 16564 197 24X
 Fiche 50-155, 82/12/20, 8212280103
- --U212280107 Application to amend License DPR-6.changing Tech Specs to clarify existing requirements to bring facility into closer agreement w/Hidland Tech Specs & to achieve closer conformance w/STS DEWITT.R B Consumers Power Co 82/12/17 App 16564 199 24X Fiche 50-155.82/12/20,8212280103
- --0212280113 Proposed changes to Tech Specs to clarify existing requirements, to bring facility into closer agreement w/ Midland Tech Specs & to achieve closer conformance w/818 * Consumers Power Co 82/12/17 14pp 14544 203 24X Fiche 50-155,82/12/20,8212280103
- G212290267 Forwards Amend S5 to License DPR-6, safety evaluation & notice of issuance & availability Amend changes Tech Specs by replacing shift technical advisor w/cm-call technical advisor CRUTCHFIELD, D Operating Reactors Branch 5 82/12/22 VANDEWALLE, D J Consumers Power Co 3pp 16581 048 24X Fiche 50-155, 82/12/22, 8212290267
- --8212270270 Amend 55 to License DPR-6, changing Tech Specs by replacing shift technical advisor w/on-call technical advisor GRUTCHFIELD, D. Operating Reactors Branch 5 82/12/22 5pp 16561 051 24X Fiche 50-155.82/12/22.8212270267
- --B212270274 Safety evaluation supporting Amend 53 to License DPR-6 * Office of Nuclear Reactor Regulation, Director 82/12/22 3pp 16581 056 24X Fiche 30-155,82/12/22,8212270267

- --8212290278 Notice of issuance & availability of Amend 55 to License DPR-6 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/22 2pg 16581 059 24X Fiche 50-155,82/12/22,8212290267
- 8212300330 Provides explanation of start date for new inservice testing interval b submittel date for revised inservice testing program.per 821209 conference telcon Revised inservice testing program expected in early Jan 1983 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/22 VANDEMALLE.D J Consumers Power Co 4pp 16594 234 24X Fiche 50-155,82/12/22,8212300330
- 82/2170149 "1982 Evaluation of Big Rock Point Nuclear Plant, CPC "
 * Institute of Nuclear Power Operations 82/12/31 37pp
 16450 229 24X Fiche 50-155,82/12/31,8212170149
- O Inspection reports, IE Bulletins & correspondence
- 820B190240 IE Builetin 82-03.Revision 1, "Stress Cracking in Thick-Wall Large-Diameter. Stainless Steel Recirculation Sys Piping at BWR Flants "Syc list encl
 DEYGUND, R C Director's Defice. Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dos (meters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 80-000.82/11/05.8208190245
- 8208190251 1E Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 197 44x Fiche 50-000,82/11/18,8208190251
- 8212080509 Forwards IE Insp Rept 50-155/82-17 on 820911-1022 & notice of violation SPESSARD, R L Division of Project & Resident Programs 82/11/22 DEWITT, R B Consumers Power Co 2pp 16352 072 24x Fiche 50-155, 82/11/22, 8212080509
- --8212083515 Notice of violation from insp on 820911-1022 SPESSARD,R L Division of Project & Resident Programs 92/11/22 2pp 16352 074 24X Fiche 50-155, 82/11/22, 8212080509
- --8212080522 IE Insp Rept 50-155/82-17 on B20911-1022 Noncompliance noted four control copy vols of facility prints containing discrepancies in changes issued MRIGHT.0 C . PARKER M E . BOYD.D C Division of Project & Resident Programs B2/11/19 7pp 16352 076 24X Fiche 50-155.G2/11/22. B212080509
- G212030019 Forwards "Seismic Capacities of Masonry Walls at Big Rock Foint Nuclear Generating Plant" per BEP Topic III-6. in response to NRC 820920 request for add1 info on IE Bulletin BO-11. "Masonry Wall Design" Detailed responses discussed BORDINE.T C Consumers Pawer Co B2/11/24 CRUTCHFIELD.D Operating Reactors Branch 5 10pp 16304 338 24X Fishe 50-155.82/11/24.8212030019
- --8212030025 "Seismic Capacities of Masonry Walls at Big Rock Point Nuclear Generating Plant" HEGLEY, D.A. BANON, H. Structural Mechanics Associates SKA 13703 02 82/08/31 62pp 16304 348 24% Fiche 50-155,82/11/24, 8212030019
- 8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" 8vc list encl DEYOUND.R C Director's Uffice. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8209190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syr list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards, 82711/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24% Fiche 50-000,82/11/30,8208190257
- B20Bi90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Gvc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259

- 8208190261 iE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Syc list encl 82/12/03
 - pockets " ave list enci JORDAN, EL Division of Engineering & Quality Assurance Consolidated Edison Co of New York, Inc 110pp 16462 Fiche 50-000, 82/12/03, 8208190261 16462 064
- 8212090387 Forwards IE Safeguards Insp Rept 50-155/82-18 on 821025-29 No nonconfilance noted MILLER, J.R. Division of Engineering & Technical Programs 82/12/03 DEWITTER B. Consumers Power Co. 2pp 16364-349 24X Fiche 50-155
- --8212090396 1E Safeguards Insp Rept 50-155/82-18 on 821025-29 No 12090396 le Safeguards Insp Rept 30-133/82-18 on 321025-27 Nu noncompliance noted Major areas inspected security plan & implementing procedures, access controls & previous items of noncompliance Details withheld (ref 100FR73 21)
 CHRISTOFFER.O., BELAKOER.J.L., CREED.J.R. Region 3, Office of Director 82/12/02 1p [6364 351 24% Fiche 50-155,82/12/03,6212090387
- 8212170148 Forwards IE Insp Rept 50-155/82-13 on 820914-19 & notice of violation LITILE WS Division of Engineering & Technical Programs DEWITT.R B Consumers Power Co 2pp 16450 276 24X Fithe 50-155.82/12/03.8212170148 82/12/03
- --8212170154 Natice of violation from insp on 820816-19 LITTLE, W S Division of Engineering & Technical Programs 82/12/03 2pp 16450 278 24X Fiche 50-155,82/12/03.8212170148
- --8212170162 IE Inspt Rept 50-155/82-13 on 820816-19 Noncompliance noted surveillance test for ventilation fire dampers or emergency lighting units not performed & failure to adhere to administrative procedures RAMSEY, C. ULIE, J., WILLIAMS, C.C. Region 3, Office of Director 82/11/22 18pp 16450 280 24X Fiche 50-155,82/12/03,8212170148
- GP12170145 Ack receipt of GP1201 ltr informing NRC of steps taken to correct violations noted in JE lnsp Rept 50-155/82-09
 NORELIUS, C E Division of Engineering & Technical Programs
 B2/12/10 DENITY.R B Consumers Power Co ip 16450 266 24X Fiche 50~155, 82/12/10, 8212170145
- --8212170150 Responds to NRC 820717 ltr re violations noted in IE Insp Rept 50-155/82-09 Corrective actions nuclear operations issued ltr requiring all evaluations be performed within 30 days or issuance of corrective action document VALDEWALLE, D J Consumers Power Co 82/12/01 KEPPLER, J G Region 3. Office of Director 4pp 18450 267 24X Fiche 50-155,82/12/10.8212170145
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for 208190267 IE 1960 Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp [6628]91 24X Fichs 50-000.82/12/16.8208190267
- 8212280131 Forwards "Seismic Evaluation of Safety-Related Electrical Equipment at Big Rock Point Nuclear Plant." in response to IE Info Notice 80-21 re anchorage & support of safety-related electrical equipment BORDINE.T C Consumers Power Co 82/12/16 CRUTCHFIELD.D Operating Reactors Branch 5 7pp 14563 144 24X Fische 50-155.82/12/16.8212260131
- --8212280134 "Sersmic Evaluation of Safety-Related Electrical Equipment at Big Rock Point Nuclear Plant " + URS Corp URS/JAD 8051 82/07/31 32pp 16563 151 24x Fiche 50-155,82/12/46,8212280131
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list end! JORDAN,E L. Division of Engineering & Quality Assurance 82/12/2: Consolidated Edison Co of New York, Inc. 108pp 16628 293 2: Fiche 50-000.82/12/20,8208190268
- R Pariodic operating reports & rolated correspondence
- G212300332 Forwards monthly operating rept for Oct 1982 HOFFMAN, D.P. Consumers Power Co. 82/11/03 Director's Office, Office of Inspection and Enforcement 1p. 16594-005 24X Fighe 50-155, 62/11/03, 8212303392
- --8212303341 Monthly operating rapt for Oct 1982 AMSTUTI.S R Consumers Power Co 82/11/03 App 16574 006 24X Fiche.50-155,82/11/03,8212300332

- 9 Reportable occurrences, LERs & related correspondence
- 8212030114 PND-111-82-128 chemistry lab sink drain discovered routed to plant sewerage sys (onsite septic tank & leach field) instead of radwaste sys Bludge from septic tank dumped in nunicipal sanstary severage sys Drain capped
 LOVENDALE, P. C., OREGER, L. R. Region 3, Office of Director
 2pp 14304 301 24% Fiche 50-155.82/11/24.8212030114 62/11/24
- 8212100304 Forwards LER 82-030/03L-0 BORDINE, T C Consumers Power Co 82/12/02 KEPPLER, J G Regi Office of Director 1p 16376 276 24X Fiche 50-155,82/12/02. Penion 3. B212100304
- --8212100307 LER 82-030/03L-0 on 821105, audible alarm unit for fire detection aquipment in zones 1 & 2 of electrical equipment room found inoperative Caused by loase wiring at panel termination on Pyrotronics Model FI U-6 Hire reconnected * Consumers Power Co 82/12/02 Region 3, Office of Director ip 16376 277 24x Fiche 50-155, 82/12/02, 8212100304
- DOCKET 50-154 UNIV OF WISCONSIN RESEARCH REACTOR S Reportable occurrences. LERs & related correspondence
- 8212140195 RO during wk of 821128, proper operation of intrusion alarm within interval specified in physical security plan not verified Caused by employee oversight Alarm immediately CASHWELL.R J Hisconsin. Univ of Madison 82/12/08 Division of Licensing Ip 16409 337 24x Fiche 50-156.82/12/08.8212140195
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR R Periodic operating reports & related correspondence
- --8212140238 Annual operating repts for Licenses R-80 & R-89 for two yrs ending 820630 ADERHOLD.H C Cornell Univ 82/12/06 Region 1, Office of Director 3pp 16409 002 24X Fiche 50-097,82/12/06,8212140232
- 8212140469 Forwards "Annual Operating Repts" for period ending June 1981 & June 1982 W/o encls ADERHOLD.H C Cornell Univ 82/12/06 Director's Office, Uffice of Inspection and Enforcement 1p 14404 012 24X Fiche 50-097/82/12/06.8212140469
- G212140146 "Annual Operating Rept. Jul 1980-June 1981 "
 ADERHOLD, H C Cornell Univ 82/12/14 Region I, Office of
 Director 3pp 16408 173 24X Fiche 50-097,82/12/14,8212140146
- DOCKET 50-163 OFWERAL ATOMIC CO. J Insurance & indemnity information
- 8212040142 Provides response to 821013 request for clarification re Indemnity Agreement 8-9 & corporate name DENTON: H R Dffice of Nuclear Reactor Regulation, Director 82/11/22 HDMRY, H R GA Technologies, Inc. /General Atomic Co 16325 354 24X Fiche 50-089,82/11/22,8212060142 MOWRY, W R GA Technologies, Inc /General Atomic Co Jp 24X Fiche 50-089,82/11/22,8212060142
- P Operating license stage documents & correspondence
- 8212040142 Provides response to B21013 request for clarification re Indemnity Agreement B-9 & corporate name DENTON H R Office of Nuclear Reactor Regulation, Director 82/11/22 MOWRYW R GA Technologies, Int /General Atomic Co 14325 354 24X Fiche 50-089.82/11/22.8212040142
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER @ Adjudicatory correspondence
- 8212030223 Notice of I Stillman 821218 notice of deposition in New York,NY re all issues upon which deponent has aided Citities for Nuclear Reactor Safety Certificate of Syc encl BACHEAN,R G Hearing Branch | 82/12/01 3pp 16306 288 Fiche 50-170, 92/12/01, 8212030223 24X

Hearing transcripts on non-antitrust matters

8P12030105 Corrected transcript of 821015 prehearing conference in Bethesda.MD Pp 81-168 Supporting documentation enc! • Atomic Safety and Licensing Board Panel 82/10/15 93pp 1a303 101 24X Fiche 50-170.82/10/15.8212030105

DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

P. Operating license stage documents & correspondence

BP12130238 Application to amend License R-87, changing Tech Specs to bring surveillance intervals into agreement w/ANS 15 1 & revising min qualifications for radiological control afficer
STANSBERRY.E R Purdue Univ 82/12/06 THOMAS, C O Standardization & Special Projects Branch 1p 16390 127 24X Tiche 50-182,82/12/06,8212130238

--B212130240 Proposed Tech Spec changes to bring surveillance intervals into agreement w/ANS 15 i & revise min qualifications for radiological control officer

* Purdue Univ 82/12/06 App 16390 130 24X
Fiche 50-182,82/12/06.8212130238

DOCKET 59-184 NATIONAL BUREAU OF STANDARDS REACTOR

O Inspection reports, IE Bulletins & correspondence

8212290393 Ack receipt of 821104 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-184/82-02 STARDSTECKIR Division of Project & Resident Programs 82/12/23 CARTER.R S Commerce. Dept of, National Bureau of Standards 2pp 16586 292 24X Fiche 50-184.82/12/23.8212290393

--8212270402 Responds to NRC B21008 ltr re violations noted in IE [nsp Rept 50-184/82-02 Corrective actions subj individual checked out on pneumatic facility & was on approved list of users CARTER.R S Commerce.Dept of, National Eureau of Standards B2/11/04 STAROSTECKI.R Division of Project & Resident Programs 2pp 16586 294 24% Fiche 50-184.82/12/23.8212290393

S Reportable occurrences, LERs & related correspondence

8212210411 RC on 821126, during routine refueling operations, fuel element 345 fell to upper grid in transfer from core position D-1 to D-7 Caused by operating difficulty in E-2 transfer arm Clement removed & seated CARTER.R S Commerce, Dept of 82/12/06 STAROSTECKI, R Division of Project & Resident Programs ip 16493 057 24X Fiche 50-184, 82/12/06, 8212210411

DOCKET 53-186 UNIV OF MISSOURI RESEARCH REACTOR

P Operating license stage documents & correspondence

G212080331 Application for amend to License R-103, increasing inventory of irradiated fuel MCKIBERN.JC, ALGER.D M Missauri, Univ of Columbia 62/12/03 Office of Nuclear Reactor Repulation, Director 2pp 16353 335 24X Fiche 50-184.62/12/03.6212080331

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8212130271 Forwards IE Safeguards Insp Rept 50~187/82-02 on 821013-15 & notice of violation
SPENCER.O S Division of Radiological Safety & Safeguards Program
82/11/24 CRANDALL.W Northrop Corp 2pp 14389 251 24X
Fiche 50~187,82/11/24,8212130291

- ~~8212130294 Notice of violation from insp on 821013-15 WENSLAWSKI,F A Division of Radiological Safety & Safeguards Program 82/11/24 ip 14389 253 24X Fiche 50-187,82/11/24, 8212130291
- ~~8212130278 IE Safeguards Inep Rept 50-187/82-02 on 821013-15 Noncompliance noted annual calibr of area radiation & continuous air monitors not performed from 1980-02 CILLIS.M. NENBLANSKI.F.A. BOOK,H.E. Division of Radiological Safety & Safeguards Program 82/11/23 14pp 16389 254 24X Fiche 50-187,82/11/24,8212130271

G Inspection reports, IE Bulletins & correspondence

82/12/30291 Forwards IE Safeguards Insp Rept 50-187/82-02 on 82/013-15 & notice of violation SPENCER.0 S Division of Radiological Safety & Safeguards Program 82/11/24 CRAMDALL.W Northrop Corp 2pp 16389 251 24X Fiche 50-187,82/11/24,8212130291

--8212130294 Notice of violation from insp on 821013-15 MERISLAWSKI.F.A. Division of Radiological Safety & Safeguards Program 82/11/24 1p (6389 253 24% Fiche 50-187, 82/11/24, 8212130291

--8212130298 IE Safeguards Insp Rept 50-187/82-02 on 821013-15
Noncompliance noted annual calibr of area radiation &
continuous air monitors not performed from 1980-82
CILLIS,M., UENSLAWSKI,F.A., BOUK,H.E. Division of Radiological
Safety & Sareguards Program 82/11/23 14pp 16389 254 24X
Fiche 50-187,82/11/24,8212130291

R Periodic operating reports & related correspondence

8212080194 Forwards "Natural Environ Radioactivity Survey for Period of Sept 1981-Aug 1982" CRANDALL:WE Northrop Corp 92/10/27 Director's Office, Office of Inspection and Enforcement 1p 16354 045 24X Fiche 50-187. 82/10/29, 8212080194

--B212080200 "Natural Environ Radioactivity Survey for Period of Sept 1981-Aug 1982 " AVANT. D. COZENS, 9., WOODS, J. Northrep Corp. 82/10/29 9pp 16354-046 24X Fiche 50-187, 82/10/29, 8212080194

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

G Inspection reports, IE Bulletins & correspondence

B2122904BB Forwards IE Insp Rept 50-193/02-02 on 821108-09 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/12/15 DIMEOLIO.A F Rhode Island, State of 2pp 16583 265 24X Fiche 50-193.82/12/15.82122904BB

--B212290490 Notice of violation from insp on 821108-09 * Division of Project & Resident Programs 82/12/15 in 16593 267 24% Fichs 50-193, 82/12/15, 8212270488

--8212270492 IE Insp Rept 50-193/82-02 on 821108-09 Noncompliance nated failure to have monitoring sys & emergency procedures for criticality accident KINNEY.W H. KEIMIG.R R. Division of Project & Resident Programs 82/12/13 5pp 16583 268 24X Fiche 50-193.82/12/19.8212290488

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

P Operating license stage documents & correspondence

GP12130430 Trip rept of 820813 site visit re completion of work involved in investigating physical characteristics of Rockwell waste tanks Addl time & funding needed to complete work Review of draft final rept would not affect schedule CLARK, A T Advanced Fuel & Bpent Fuel Licensing Branch 82/08/18 ROUSEL C Advanced Fuel & Spent Fuel Licensing Branch 12 16413 083 24X Fiche 50-201.82/08/18,8212130430

DDCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT (

F Security, medical, omergency & fire protection plans

8212070002 Notifies that SEP Topic IX-6. "Fire Protection," completed Request for exemption from implementation schedule under review PAULSON: (4 Decreting Reactors Branch 5 82/12/02 DIETCH, R Southern California Edison Co. 2pp. 16327 235 24X Fiche 80-206.82/12/02.8212070002

BR12090532 Forwards IE Safeguards Insp Repts 50~204/82-29 & 50~361/82-29 on 821031-1105 & notice of violation Notice of violation & insp rept withheld fref 10CFR2 790)
NORDERHAUG, L R Division of Radiological Safety & Safeguards
Program B2/12/04 PAPAY, L T Southern California Edison Co 2pp 16366 106 24X Fiche 50~206.82/12/06, 8212090532

- 8212140151 Responds to 821202 toloon request & documents 821122 & 23 conversations re emergency response facilities Facility declared operational on 821001 BASKIN.K P Southern California Edison Co 82/12/07 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16408 169 24X Fiche 50-206.82/12/07.8212140151
- 8212170158 Informs of current revisions to schedules for availability of qualitication documentation for electrical equipment, updating 820702 & 0907 schedules KRIEGER.R N Southern California Edison Co 82/12/15 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16459 231 24X Fiche 50-206, 82/12/15, 8212170158
- 8212170164 Forwards "Conceptual Study of Remote Shutdown Panel & Associated Circuits Evaluation re App R.Section III 2 3 & NRC Request for Info," supplementing 820530 response to Generic Ltr 81-12.4td 810220

 BASKIN.K P Southern California Edison Cc 82/12/15

 CRVICHFIELD. D Operating Reactors Branch 5 2pp 16457 233 24X Fiche 50-206,82/12/15,8212170164
- --B212170168 "Conceptual Study of Remote Shutdown Panel & Associated Circuits Evaluation re App R. Section III G 3 & NRC Request for Info "

 * Southern California Edison Co * San Diego Gas & Electric Co 82/12/31 71pp 16459 235 24% Fiche 50-206.82/12/15.8212170164
- J Insurance & indemnity information
- 9212270171 Forwards Endorsements 89 & 90 to NELIA Policy NF-146. Endorsements 77 79 to MAELU Policy MF-79. Endorsement 35 to NELIA Policy NF-282. Endorsement 1 to NELIA Binder EB-87 & Endorsement 1 to MAELU Binder X9-87 ROCCO, J Southern California Edison Co 82/12/20 DINITZ. I Antitust & Economic analysis Branch (Usility Finence) 19pp 16538 347 24K Fiche 50-206.82/12/20.8212270171
- P Operating license stage documents & correspondence
- 8212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of regaining documents continuing Documents available in PDR FELTON.J M Division of Rules and Records 82/11/03 GALLO, J Isham. Lincoln & Beale 2pp (6433 354 24X Fiche 50-000,82/11/03, 6212140001
- --7908140421 Forwards, for review, summary & questions re seismic re-evaluation & RCS mod HURRAY, R C Laurence Livermore Laboratory 79/08/03 LEVIN, H A Systematic Evaluation Program Branch (Pre 791030) 12pp 16435 001 24X Fiche 50-000, 82/11/03, 8212140001
- --7912190426 Notifies of info required from applicant re independent confirmatory piping analysis BUSNAK,R J Kechanical Engineering Branch 79/12/06 RUSENSTEIN.L, Light Water Reactors Branch 4 2pp 16435-014 244 Fiche 50-000-82/11/03,8212140001
- ---B001180235 Comments on evaluation of ground motion modelling study Any choice of design evaluation should be sufficiently flexible to allow for changes in spectrum REITER.L. Geosciences Branch 80/01/03 JACKSON.R E Geosciences Branch 3pp 16435 016 24X Fichs 50-000.82/11/03, 8212140001
- --B0021300Bl Discusses assessment impact of earthquake data upon facility modeling study, "Samulation of Earthquake Ground Hotion "
 Recommends that will provide program outline for assessing data impact upon calibr of slip function
 JACKSION,R Geosciences Branch B0/01/21 CRUTCHFIELD,D
 Systematic Evaluation Program Branch 2pp 16435-019 24X
 Fiche 50-000.82/j1/03.8212140001
- --8002270255 Recommends that util be asked to submit outline of proposed scope, schedule & evaluation criteria for seismic re-evaluation program by 800401 Justification for continued operation until plan completed should be submitted CRUTCHFIELD.D Systematic Evaluation Program Branch 80/02/05 EISENHUT.D Q Division of Operating Reactors 2pp 14434 256 24% Fiche 50-000, 82/11/03,8212140001
- --B003310092 Suggests review of existing high resolution seismic profiling to define possible Christianitos-Offshore Deformation Zone USGC to assist JACKGON,R E Geosciences Branch 60/03/18 KNIGHT J P Assistant Director for Engineering ip 16434 258 24x Fiche 50-000,82/11/03,8212140001

· `\

- --8005050726 "Vertical Spectra from 1979 Imperial Earthquake" + Southern California Edison Co 80/03/31 24pp 16435 021 244 Fiche 50-000,82/11/03,8212140001
- --800&070164 Forwards proposed outline for responding to JL Smith 771114 petition re seismic data Adequate basis may exist for demying petition provided steps are taken by licensee to develop more complete program CRUTCHFIELD, D. Operating Reactors Branch 5 80/05/23 LAINAS, G. Assistant Director for Safety Assessment KNIGHT. J. Assistant Director for Components & Structures Engineering 5pp 16435-046 24% Fiche 50-000.82/11/03,821240001
- --800409078B Forwards five Items re ground motion modelling for facility W/o encls REITER.L. Geosciences Branch B0/04/14 SHERBURNE,R California, State of 1p 14435 045 24X Fiche 50-000,82/11/03, B212140001
- --B007230260 Forwards transcripts of B00520-21 meetings w/licensee reneed for addl offshore seismic profiles W/o encl CARDONE,A T Geosciences Branch B0/06/04 AMIMOTO,F California, State or ip 16435-052 24X Fiche 50-000,82/11/03,8212140001
- --8009290433 Request for procurement NRR-78-184 to execute mod to "Simulation of Earthquake Ground Notions for San Onofre Nuclear Generating Station Unit 1" Contractor K Aki VOLCHER.R H Division of Engineering FIN 8-6531 80/06/13 5pp 16435 053 24X Fiche 50-000, 82/11/03,8212140001
- --8010150236 Request for procurement NRR-60-143 to award sole source contract to JE Luco for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station"

 VOLLMER: R H Division of Engineering FIN 8-6898-0 80/08/04
 7pp 16435 057 24% Fiche 50-000, 82/11/03, 8212140001
- --8010150242 Requests for procurement NRR-80-145 to award sole source contract to R Harrmann for "Followen to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
 VOLLMERIR H Division of Engineering FIN 8-6878-0 80/08/04
 7pp 16435 065 24X Fiche 50-000, 82/11/03,8212140001
- --8010150246 Request for procurement NRR-80-144 to award sole source contract to K Aki for "Followon to Simulation of Earthquake Ground Hotions for San Onofre Nuclear Generating Station VOLLMER.R H Division of Engineering FIN G-6858-0 80/08/04 7pp 16434 247 24% Fiche 50-000.82/11/03.8212140001
- --B010170283 Forwards Div of Engineering 800704 memo re seismic rept related to SEP review for transmittal to appropriate hearing boards EISEMHUT,D G Division of Licensing 80/09/23 NOVAK,T Assistant Director for Operating Reactors TEDESCO,R Division of Licensing ip 16435 078 24% Fiche 50-000,82/11/03,8212140001
- --B010170287 Provides outline of rept. "Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station.Unit 1.
 Suppl III " Rept may be useful to hearing boards concerned w/near-field earthquake motion

 VDLLMER.R H Division of Engineering 80/09/04 EISENHUT.D G
 Division of Licensing 1p 16435-079 24X Fiche 50-000.82/11/03.8212140001
- ~-8110170952 Provides addl info supporting conclusion that three northern columns of turbine bldg cannot be modified per 810928 ltr due to limitations created by adjacent structures BASVIN.K P. Southern California Edison Co. 81/10/06 CRUTCHFIELD.D. Operating Reactors Branch 5. 3pp. 16435 080 24X Fichs 50-000.82/11/03.8212140001
- --Bi12ii0356 Discusses Biii17:18 & 19 telcons w/licensee re need for extensive mods to preliminary seismic design of spent fuel bidg submitted in June 1981 (ref BEP Topic III-6) Details of new mods will be evailable after B20125 RUSSELL.H T Systematic Evaluation Program Branch B1/11/20 Systematic Evaluation Program Branch B20125 Fiche 50-000,82/11/03,8212140001

- ---8203310670 Forwards SEP seismic completion plan to perform review parallel u/license efforts to complete SEP Topic III-6. seismic design considerations, for Group II plants HERIMANN, R. Systematic Evaluation Program Branch 82/03/08 RUSSELL, N.T. Systematic Evaluation Program Branch 5pp 16434 276 24X Fiche 50-000, B2/11/03,8212140001
- --G212340149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references resite-specific spectra (SEP Topic III-6) encl
 LEVIN.H A Systematic Evaluation Program Branch 79/11/13 EISENHUT,D 0 Division of Operating Reactors 4pp 16436 300 24% Fiche 50-000,82/11/03.8212140001
- BP12010047 Forwards pages omitted from June 1980 LLL technical evaluation re overpressure mitigation sys encl in NRC 821028 ltr PAULSGN, W.A. Operating Reactors Branch 5 82/11/04 DIETCH, R Southern California Edison Co. 14pp 16260 319 24X Fiche 50-206, 82/11/04, 8212010047
- 8212020252 Discusses util response to SEP Topic VIII~1 A, "Potential Equipment Failures Associated W/Degraded Grid Voltage " Topic complete for purposes of Integrated assessment PAULSON.W Operating Reactors Branch 5 82/11/23 DIETCH.R Gouthern California Edison Co 2pp 16279 335 24X Fiche 50-206.82/11/23.8212020252
- 6212020137 Responds to 821004 ltr providing addl comments supporting position that fee not applicable to 820625 application Fee position reassessed in light of addl info No fee due for clarification of Tech Specs MILLER.W O License Fee Management Branch 82/11/24 BASKIN.K P Southern Callfornia Edison Co 1p 16308 287 24X Fiche 50-206.82/11/24.8212020157
- Bi-12140366 Forwards marked-up draft of radiological ETS annotated w/review comments from site visit Telcon suggested to discuss comments wotil EG&O 8 NRC representative SERRAMOU # EG&O. Inc. 82/11/24 KRIEGER: 8 Southern California Edison Co. 99pp. 16401 044 24x Fiche S0-206.82/11/24,8212140366
- GP12010D23 Forwards summary of resolution for items discussed at 821110 meeting re SEP Topic III-6, "Seismic Design Considerations" Evaluations supporting NRC review also encl PAULSON. W Operating Reactors Branch 5 82/11/24 DIETCH. R Southern California Edison Co. 11pp. 16260 137 24X Fiche 50-206. 82/11/24. 9212010023
- --B210260403 Submits detailed comments on structural review of seismic re-evaluation Subcontractor rept submitted w/o critical review due to time constraints Uncertainty in soil structure interaction & concrete tensile strength discussed NELSON, TA Lawrence Livermore Laboratory 82/10/15 HERMANN, R Systematic Evaluation Program Branch 7pp 16260 151 24% Fichs 50-206,82/11/26,8212010023
- --8212010036 "Review of Seismic Re-evaluation of Reactor Bidg & Balance of Flant Structures of San Unoffe Nuclear Generating Station, Unit 1 "TSAI, N C NOT Engineering, Inc 82/09/30 84pp 16260 155 24X Fiche 50-206,82/11/26,8212010023
- B212020250 Forwards comments re NRC 820914 evaluation of util response to BEP Topic IV-2, "Reactivity Control Sys"

 KRIEGER, R W Southern California Edison Co 82/11/30
 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16279 337 24X

 Fiche 50-206, 82/11/30, 8212020250
- B≥12020293 Advises that return to power date delayed beyond 821128
 Precise date cannot be established at present Return to
 power dependent on NRC approval of acceptability of util
 resgonse to SEP Topic III-6. "Schedule for Seismic Mods"
 BASKINIK P Southern California Edison Co 82/11/30
 CRUICHFIELD. D Gperating Reactors Branch 5 2pp 16279 333 24X
 Fiche 50-206.82/11/30.8212020253
- 82:12060239 Summarizes status of open items identified at 820728-30 meeting w/NRC re SEP Topic III-6 concerning seismic design re-eveluation, supplementing util 820826 & 0915 responses BABKIN.K P Southern California Edison Co 82/11/30 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16312 267 24X Fiche 50-206, 82/11/30.8212060239
- 8212020307 Requests add1 info re SEP Topic II-4 F, "Settlement of Structures & Duried Equipment" per 811102 safety assessment Response requested within 30 days of receipt of ltr PAULSON,W A Operating Reactors Branch \$ 82/12/01 DISTCH.R Southern California Edison Co 16pp 16277 318 24X Fiche \$0-206,82/12/01,8212020307

- 8212060269 Forwards Revision 2 to "PMR Safety & Relief Valve Adequacy Rept for San Onofre Unit 1 " Addi valve specific analyses will be submitted as suppl by 830601 BASKIN, K P Southern California Edison Co 82/12/02 CRUTCHFIELD D Operating Reactors Branch 5 2pp 16311 088 24X Fiche 50-206, 82/12/02.8212060269
- --B212060276 Revision 2 to "PWR Safety & Relief Valve Adequacy Rept for San Onofre, Unit 1 " Safety valve discharge piping adequacy analysis encl Wyfour oversize drawings Aperture cards are available in PDR KELLY, R E Westinghouse Electric Corp 82/11/30 90pp 16311 091 24X Fiche 50-206, 82/12/02.8212060269
- 82:12070266 Submits info for post-implementation review of NUREO-0737, ltpm II B 3, "Post-Accident Sampling Sys " W/six oversize drawings Aperture cards are available in PDR BASKIN,K P Southern California Edison Co 82/12/03 CRUTCHFIELD. D Operating Reactors Branch 5 9pp 16336 352 24X Fiche 50-206,82/12/03,8212070266
- 82/12100009 Forwards revised safety evaluation re SEP Topic VIII-4, "Electrical Penetrations of Reactor Containment " Design of electrical protection circuits for containment penetrations does not meet licensing criteria Design changes recommended PAULSON, W.A. Operating Reactors Branch 5 82/12/06 DIETCH, R Bouthern California Edison Co. Spe. 16379 149 24x Fiche 50-206.82/12/06.8212100009
- B212100020 Forwards revised SER of SEP Topic VI-4. "Containment Isolation Sys." based on additinfo contained in KP Baskin B21122 itr Design acceptable if visual display provided to show safety injection sys block status PAULSON.W A Deprating Reactors Branch 5 92/12/06 DIETCH.R Southern California Edison Co App 16379 126 24X Fiche 50-206.82/12/06.8212100020
- 8212080283 Notification of 821217 meeting w/util in Bethesda, MD to appeal certain NRC positions re SEP Topic III-6, "Seismic Design Considerations" PAULSON. WA Operating Reactors Branch 5 82/12/07 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16354 183 24X Fiche 50-206.82/12/07.8212080283
- 8212090103 Submits schedule for completion of draft safety assessments on SCP Topics III 5A & III 5B.per NRC 821112 ltr Topics for which evaluations have been received will be submitted by 830115
 BASKIN.K P Southern California Edison Co 82/12/07
 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16357 303 24X
 Fiche 50-206.82/12/07.8212090103
- 8212130204 Forwards evaluation of SEP Topic IX-1. "Fuel Storage." based on 820427.0701 & 1116 submittals Fuel storage facility acceptable Structural capability ro seismic capacity will be a eviewed in SEP Topic III-6 re tornado missiles PAULSON.W Operating Reactors Branch 5 82/12/07 DIETCH.R Southern California Edison Co 13pp 16076 180 24X Fiche 50-206.82/12/07.8212130204
- 8P08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications: Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl ETSENHUT: D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York: Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 8P12200063 Informs that proposed changes to Tech Spec will be provided approx 60 days prior to return to power from current outage, in response to 820920 Generic Ltr 82-16 & NUREO-0737 KRIEOER.R W Southern California Ed-16 & NUREO-0737 CRUICHFIELD.D Operating Reactors Branch 5 2pp 16474,310 24X Fiche 50-206,82/12/09,8212200063
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumention sys Bvc list encl EISENHUT, D 0 Division of Licensing 82/12/10 Yanker Atomic Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,82/12/40103
- 8P12200028 Provides current schedule for completion of long-term emergency operating instruction effort re NUREO-0737, Item 1 C 1

 BASKIN, K P Southern California Edison Co 82/12/13
 CHUTCHFIELD.D Operating Reactors Brench 5 2pp 16474 271 24X
 Fiche 30-206, 82/12/13, 8212200028

- BP12210293 Summary of B21007 meeting w/util re status of guideline preparation for development of emergency operating instructions for facility, per TMI Action Item IC 1 PAVLBON. WA Operating Reactors Branch 5 B2/12/13 Operating Reactors Branch 5 B2/12/13 Operating B212210293
- 8212160018 Notification of 821216 meeting w/util in Bethesda, MD to discuss analysis criteria re seismic re-evaluation, SEP Topic III-6 PAULSON, M Operating Reactors Branch 5 82/12/14 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16446 123 24X Fiche 50-206, 82/12/14, 82(2160018
- 8212210001 Informs of add1 action to be taken to verify adequacy of station electric distribution sys Study will be performed to optimize transformer tap settings Revised settings will be implemented prior to startup from current outage BASKIN, K.P. Bouthern California Edison Co. 82/12/14 CRUTCHFIELD.D. Operating Reactors Branch 5 ip 16485.259 24X Fiche 50-206.82/12/14.8212210001
- B212170158 Informs of current revisions to schedules for availability of qualification documentation for electrical equipment, updating 820702 & 0907 schedules MRIEGER,R W Southern California Edison Co 82/12/15 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16459 231 24X Fiche 50-206.82/12/15.8212170158
- 8212220447 Forwards final evaluation of GEP Topic XV-2. "Spectrum of Sys Piping Faitures Inside & Outside of Containment " Qualification of main feedwater sys to function in required mode under accident conditions should be addressed PAULSON, H. A. Operating Reactors Branch 5 82/12/17 DIETCH. R Southern California & Edison Co. 10pp 16503 292 24X Fiche 50-206.82/12/17.8212220447
- 8212220198 Forwards responses to NRC questions re-seismic re-evaluation of fuel storage bldg.per SEP Topic III-6 Detailed model of structure & digitized time histories used in evaluation oncl
 BASKIN.X P Southern California Edison Co 82/12/20
 CRUTCHFIELD.D Operating Reactors Branch 5 576pp 16520 197 24X
 Fiche 50-206.82/12/20,8212220198
- O Inspection reports. IE Bulletins & correspondence
- 8212290023 FOIA request for documents re EE Kent allegations concerning facilities
 COMENIE M , CARPENTER, T , JACOBSON, J Grange County Alliance for Survival 62/10/27 FELTON, J M Division of Rules and Records
 ip 16607 055 24X Fiche 50-206.82/10/27,8212290023
- 8208170240 IE Bulletin 82~03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants "Syc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York. Inc 112pp 14462 163 24X Fiche 50~000. 82/10/28. 8208170240
- BPOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!
 COBB.L. I Bivision of Fuel Facilities, Materials & Safeguards
 E2/11/05 Consolidated Edison Co of New York, Inc. 110pp
 16372 142 24x Fiche 30-000.82/11/05.8208190245
- 8:08190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc. 109pp. 16411
- 8212040154 Forwards IE Imap Repts 50-204/82-33 % 50-341/82-33 on 821025-28 % motice of violation BODK-M E Region 5. Office of Director 82/11/19 PAPAY.L T Southern California Edison Co 4pp 16313 120 24X Fiche 50-204.82/11/19,8212060156
- --8212060161 Notice of violation from insp on 821025-28 Region 5, Office of Director 82/11/19 App 16313-122 24X Fiche 50-206.82/11/19.8212060156
- --82[2060168 IE Insp Repts 50-206/82-33 & 50-361/82-33 on 821025-28 Noncomptioner noted failure to post notice to workers, described in IOCFRI9 11. Paragraph 3 YUHAS. O.P. MENSLAMBKI. F.A. BOOK. H.E. Division of Radiological Safety & Safeguards Program 82/11/18 9pp 16313 126 24X Fiche 50-206.82/11/19.822060156

- BPOB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list enci DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 055 24X Fiche 50-000,82/11/24,8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Syc list encl CO88.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 82:12170369 Forwards 1E Insp Repts 50-206/82-31,50-361/82-31 & 50-362/82-27 on 82:1015-11:15 No noncompliance noted BISHOP, T W Division of Resident: Reactor Project & Engineering Programs 82:11:1/30 PAPAYL T Southern California Edison Co 4pp 16455 279 24% Fiche 50-206.82/11/30.82:12:70369
- --8212170376 IE Insp Repts 50-206/82-31,50-361/82-31 & 50-342/82-27 on 821015-1115 No noncompliance noted Major areas inspected allegations re design imadequacies & deficiencies in implementation of welding codes & stds
 HERNANDEZ, G., WARNER, W. J., KIRSCH, D. F. Division of Resident,
 Reactor Project & Engineering Programs 82/11/30 43pp
 16455-263 24X Fichs 50-206,82/11/30,8212170369
- --B212170383 Requests notification if list of items to be submitted by 821103 re welding code requirements not correct ENGELKENR H Region 5, Defice of Director 82/10/29 PAPAY, L T Southern California Edison Co. 1p 16455 326 24X Fiche 50-206,82/11/30,8212170369
- --8212170384 Responds to NRC 821029 ltr re allegations concerning const quality & welding code requirements PAPAY, LT Southern California Edison Co 82/11/03 ENOELKEN, RH Region 5, Office or Director 11pp 16455 327 24X Fiche 50-204, 82/11/30, 8212170369
- --8212170385 Forwards Bechtel B21027 response to allegations re const quality, per request made at 82103 site meeting CURRAN, J M Southern California Edison Co 82/11/03 KIRSCH, I) F Region 5, Office of Director 37pp 16455 338 24Y Fiche 50-206, 82/11/30, 8212170369
- --B2120B0291 Transmits reply to B21029 request for technical assistance in evaluating EE Kent Allegation Items 2.5.6 & B Evaluation concludes allegations unsubstantiated EISEANUT.D 0 Division of Licensing B2/11/30 CREWS.J L Division of Resident. Reactor Project & Engineering Programs 1P 16456 013 24% Fiche 50-206.82/11/30.82(2170369
- --B211290023 Forwards safety evaluation of E Kent allegations re weldments at plants Allegations have πο merit & no further action should be taken
 JOHNSTON, W V Assistant D(rector for Materials & Qualifications Engineering B2/11/17 NOVAK.T M Assistant Director for Licensing 14pp 16456 D14 24X Fiche 50-206, B2/11/30, 8212170369
- B70B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp. 16411 317 24X Fiche 50-000, B2/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agestat CR 0095 Relay Bockets " Svc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8212290030 Partial response to FDIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1, 2, 4, 9, 10, 15 & 16 listed in App A Remaining documents will be released when inspirent issued Tapes available in PDR FELTON, JM Division of Rules and Records 62/12/03 CARPENTER, T Grange County Alliance for Survival 3pp 16607 056 24X
- --8212290035 Summarizes 821006 telcon w/J O'Dell (LA Times) re EE Kont allegations concerning welding practice at facilities KIRSCH,DF Division of Resident, Reactor Project & Engineering Programs, 82/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16607 077 24% Fiche 50-206,82/12/03,82/12290030
- --8212290039 Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities CURRAN, J M Southern California Edison Co 82/10/07 KIRSCH, D F Region 3. Defice of Director 48pp 16607 079 24X Fiche 50-206, 82/12/03.8212290030

- W/Rent KIRSCH, D.F. Division of Resident. Reactor Project & Engineering Programs 82/10/22 CURRAN, J. Southern California Edison Co. 1p. 16507 127 24% Fiche 50-206.82/12/03.8212290030
- ~-8212290049 Figure NB-4250-1, "Welding End Transitions Max Envelope," w/annotation "Example of Approx Slopes Discovered 821025 at San Onofre Nuclear Generating Stations " Charts re welding # pipe support encl
 # pipe
- GE:12070532 Forwards IE Safeguards Insp Repts 50-204/82-29 & 50-36f/82-29 on S21031-1105 & notice of violation Notice of violation & insp rept withheld (ref 100FR2 790) NORDERHAUG.L R Division of Radiological Safety & Safeguards Program 82/12/06 PAPAY.L T Southern California Edison Co 16366 105 24X Fiche 30-206.82/12/06.8212090532
- 8R12130329 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/82-26 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/12/09 PAPAYL J Southern California Edison Co 16359 285 24X Fiche 50-206,82/12/09.8212130329
- --8212130333 Responds to NRC 821021 ltr re violations noted in IE Insp Rept 50-206/82-26 Corrective actions missing evaluations will be identified & corrected through 821119 Nuclear Audit & Review Committee evaluation will be completed by 830429 PAPAY.L T Southern California Edison Co 82/11/19 ENGELKEN,R H Region 5. Office of Director 3pp 16389 286 24X Fiche 50-206.62/12/09.8212130329
- BP08170267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Honitoring " Svc list encl DEVOUND.R C Director's Office, Office of Inspection and Enforcement E2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- B£08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Tupe ITE-27" Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14428 293 20 Fiche 50-000, 82/12/20, 8208190268 82/12/20
- A Periodic operating reports & related correspondence
- E:12290102 Forwards monthly operating rept for Oct 1982 NAY.H B Southern California Edison Co 82/11/15 Resource Management, Director 1p 16583 234 24X Fiche 50-206.82/11/15.8212290102 Office of
- --6212270104 Monthly operating rept for Oct 1982 SPEER, M J Southern California Edison Co 82/1 14563 235 24X Fiche 50-204, 82/11/15, 8212270102 82/11/15
- S Reportable occurrences, LERs & related correspondence
- BE12140360 Forwards LER 82-027/03L-0 Detailed event analysis submitted RAY.H B Southern California Edison Co 82/12/02 ENGELKEN,R N Region 5, Office of Director 2pp 16401 041 24X Fiche 50-206, 82/12/02, 8212140360
- --8212140368 LER 82-027/03L-0 on 821103. letdown isolation ball valve CV-526 outside containment failed to remain in open position after two cycling attempts Gaused by sticking latching arm in valve actuator Investigation continuing RAY. H S Southern Callfornia Edison Co. 82/12/02 Region 5, Dffice of Director 1p. 16401-043 24X Fiche 50-206,82/12/02,8212140360

DOCKET 50-213 HADDAM NECK PLANT

- F Security, medical, emergency & fire protection plans
- 8212030165 Forwards IE Insp Rept 50-213/82-18 on 820929-1001 No noncompliance noted

 MARTIN.T T Division of Engineering & Technical Programs 82/11/1;
 CDUNBIL.W G Connecticut Yankes Atomic Power Co 2pp 16306 105
 24K Fiche 50-213.82/11/17.8212030165
- --8212030175 IE Imsp Rept 50-213/82-18 on 820929-1001 No moncompliance noted Major areas inspected security plan & implementing procedures, security organization, records, repts & training & qualification & contingency plans MCKEOWN,L M , GODY,A T Region 1, Office of Director 82/11/10 5pp 16306 107 24X Fiche 50-213,82/11/17,8212030165

- B212150036 Forwards Revision 1 to suitability, training & qualification plan Revision withheld (ref 10CFR2 790(d) & 10CFR2 21) COUNSIL W 0 Connecticut Yankee Atomic Power Co 82/11/22 EISENMUT. D G Division of Licensing 1p 16421 235 24% Fiche 50~213. B2/11/22, B212150036
- 8P12020299 Forwards Revision 3 to safeguards contingency plan Revision withheld (ref. 10CFR2 790 & 10CFR73 21)
 CDUNSIL, N. G. CAGNETTALJ P Connecticut Yankee Atomic Power Co.
 82/11/24 CRUTCHFIELD. Operating Reactors Branch 5 2pp
 16277 352 24X Fiche 50-213,82/11/24,8212020299
- 8212140074 Forwards IE Insp Rept 50-213/82-19 on 820927-1107 No nancompliance noted
 STAROBTECKI,R Division of Project & Resident Programs 02/11/29
 COUNSIL,N 0 Connecticut Yankee Atomic Power Co 2pp 16408 321
 24X Fiche 50-213.82/11/29.8212140074
- --B2121400B4 IE Insp Rept 50-213/82-19 on B20927-1107 No noncompliance noted Major areas inspected review of periodic & special repts. TMI action plan items, by-product matl license, offsite emergency response & receipt of new fuel REBELOWSKI, T. BR100S.L. ELGASSER.T.C. Division of Project & Resident Programs B2/11/7 lipp 16408-323 24X Fichs 50-213.82/11/29.8212140074
- GP12020123 Notification of 821201 meeting w/util in Bethesda.MD to discuss licensee request for exemption from certain requirements of Section III B of App 8 re safe shutdown requirements of Section III B or App x re-sare shutdown capability in event of fire
 ERICKSON.P B Operating Reactors Branch 5 82/11/30
 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 16272 040 24X
 Fiche 50-213, 02/11/30, 0212020123
- 8212090114 Responds to Generic Ltr 82-25 re BNL request for assistants in field testing new measurement equipment & inventory techniques developed to aid in strengthening IAEA safeguards Addl info available should be sent expeditiously CGUNSIL, W G Connecticut Yankee Atomic Power Co CGUNSIL, W G Northeast Nuclear Energy CO (subs of Northeast Utilities) 82/11/30 EISENHUT.D G Division of Licensing ip 16037 272 24x Fiche 50-000.62/11/30.8212090114
- 8212140210 Summary of 821201 menting w/utils & Debevoise & Lieberman in Bethesda, MD re fire protection, App R safe shutdown requirements & exemption request ERICKEON, P B Operating Reactors Branch 5 82/12/09 Operating Reactors Branch 5 44pp 16406 263 24X Fiche 50-213,82/12/09,
- 82:12280119 Forwards info supporting 10CFR50 App R review, including safe shutdown fire zone analysis.PRA for proposed alternate shutdown sys & clarification of technical issues, intended for presentation during 82:1201 meeting w/NRC COUNSIL.N 0 . FEE,N F Connecticut Yankee Atomic Power Co 82/12/15 EISENHUT.D 0 Division of Licensing 50pp 16564 074 24X Fiche 50-213.02/12/15.6212280119
- G212210305 Provides add1 info to better prepare shift crews operating facility for questions asked by NRC duty officer during telephone notifications Encl event notification form should telephone notifications that event notification form should be disseminated STARGSTECKI, R Division of Project & Resident Programs 82/12/16 CDUNSIL, N O Connecticut Yankee Atomic Power Co 6pp 16497 101 24X Fishe 50-213.82/12/16.8212210305
- P Operatino license stage documents & correspondence
- 8212140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON.J M Division of Rules and Records 82/11/03 GALLO.J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- --Bi12160327 Forwards Structural Mechanics Associates Bi1208 comments re 11210032/ Forwards Structural Mechanics Associates B11208 comments SEP Topic III-6 on seismic design considerations, for concurrence Marked-up summary document also encl NELSON, T A Laurence Livermore Laboratory B1/12/11 CHEN,PY Bystematic Evaluation Program Branch Bpp 14435 083 24X Fiche 50-000,82/11/03,8212140001
- --B203310670 Forwards BEP seismic completion plan to perform review parallel w/license efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants HERMANN, R Systematic Evaluation Program Branch B2/03/08 RUSSELL, W T Systematic Evaluation Program Branch 5pp 16434 276 24% Fichs 50~000, 82/11/03, 8212140001

- --B212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Group & all other comments should be received by 791130 Listing of references resite-specific spectra (SEP Topic [III-6] encl
 LEVIN.H A Systematic Evaluation Program Branch 79/11/13
 EISENHUT.D Q Division of Operating Reactors 4pp 16436 300
 24X Fiche 50-000.82/11/03.8212140001
- 8212070289 Summariles analysis of flood level in response to SEP Topic III-3 A. "Effects of High Mater Level on Structures "Containment, primary auxiliary bldg, diesel generator bldg & safety-related tanks protected against flood at 30 ft COUNSIL. W Q . CAGNETTA. J P Connecticut Yantee Atomic Power Co 82/11/24 CRUTCHFIELD D Operating Reactors Branch 5 2pp 16339 015 24% Fiche 50-213,82/11/24.8212070289
- 8212060157 Responds to Generic Ltr 82-22 re steam generators Haddam Nect steam generator performance excellent Max of 21 tubes replaced since 1979 Millstone Unit 2 replaced max of 429 Radiation protection program established COUNSIL, W Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Utilities 92/11/29 EISENHUT, D. G Division of Licensing 3pp 16313 117 24X Fiche 50-000, 82/11/29, 8212060157
- 8212070102 Forwards final SER on SEP Topic VI-10 A. "Testing of Reactor Trip Sys & ESFs. Including Response Time Testing " Changes to Tech Specs for surveillance testing & hardware provisions recommended CRUTCHFIELD.D Operating Reactors Branch 5. 82/12/03 COUNSIL.W G Connecticut Yankee Atomic Power Co 14pp 16327 277 24X Fiche 50-213.82/12/03.8212070102
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EIEENHUT, D © Division of Licensing 82/12/09 Consolidated Edison Ca of New York Inc 29pp 16629 247 24X Fiche 50-000.82/12/09.8208190263
- 82/2140103 Ceneric Ltr 82-28 to all licensees of operating Westinghouse & C-E FWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISEMBURD OF Division of Licensing 82/12/10 Yentee Atamic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 03313/4069
- 82:2220377 Forwards evaluation of SEP Topic VI-4. "Containment Isolation Sys " Dutstanding items include use of simple check valves outside containment as automatic isolation valve & lack of redundant sys for certain open sys CRUTCHFIELD. D Operating Reactors Branch 5 82/12/13 COUNSIL.# 6 Connecticut Yankor Atomic Power Co J3pp 16517 194 24X Fiche 50-213.92/12/13.5212220377
- 82(2230089 Forwards SER & proprietary & monpreprietary technical evaluation repts of environ qualification of safety-related equipment Four major qualification deficiencies listed Proprietary rept withheld (ref 10CFR2 790) CRUTCHFIELD D Operating Reactors Branch 5. 82/12/13 COUNSIL.W G Connecticut Yankee Atomic Power Co 3pp 16506 012 24X Fiche 50-213,82/12/13,8212230089
- --B212230094 SER of environ qualification of safety-related electric equipment four major qualification deficiencies listed * Office of Nuclear Reactor Regulation, Director 82/12/13 6pp 16506 015 24% Fichs 30-213,82/12/13
- --8212230110 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60) Hadden Neck Plant." technical evaluation rept CRANE, C J Franklin Institute/Franklin Research Center TER-05257-440 82/06/07. LE.N B , SHEMANSKI, P NRC No Detailed Affiliation Given 366pp [6504 02] 24% Fiche 50-213.82/12/13, 8212230089.
- 8212210059 Application to amend License DPR-16, changing Tech Specs 3 17 & 3 18 to reduce peak linear heat generation rate limit & change power vs offset envelopes to reflect lowered linear heat generation rate
 COUNSIL.H O Connecticut Yankee Atomic Power Co 82/12/14
 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16492 253 24X
 Fiche 50-213, 82/12/14, 8212210059
- --8212210063 Proposed changes to Tech Specs 3 17 & 3 18, reducing peak linear heat generation rate limit & changing power vs offset anvelopes to reflect lowered linear heat generation rate * Connecticut Yankee Atomic Power Co 82/12/14 7pp 16492 256 24% Fiche: 30-213,82/12/14,8212210059

- 8212210121 Submits results of discharge piping analyses in response to NUREG-0737.1tem II D 1, "Performance Testing of PWR Relief t Safety Valves' COUNSIL.W C Connecticut Yankee Atomic Power Co COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W C Northeast Utilities 82/12/15 EISENIUT.D G Division of Licensing 4pp 16485 084 24X Fiche 50-000,82/12/15,
- B212210127 Forwards SER & technical evaluation rept advising of resolution of NUREG-0737. Items I A 2 1, "Upgraded Reactor Operator & Benior Reactor Operator Training " & II B 4, "Training for mitigating Core Damage ' CRUTCHFIELD D Operating Reactors Branch 5 82/12/15 CCUNSIL,W 6 Connecticut Yankee Atomic Power Co 5pp 16484 179 24% Fiche 50-213,82/12/15,8212210127
- --8207030343 "Improvements in Training & Requalification Programs as Required By TMI Action Items I A 2 1 & II B 4," technical evaluation rept * Science Applications, Inc. NRC-03-82-074 SAI-186-027-05 82/09/01 NRC - No Detailed Affiliation Given 18pp 16484 184 24X Fichs 50-213.82/12/15.8212210127
- 82122302\$7 Provides addl info re main steam line break w/continued feedwater addition in response to PRC 821027 ltr Increased flow rates will not adversely affect containment response COUNSIL.4 G . CAGNETTA.J P Connecticut Yankee Atomic Power Co 82/12/16 CRUTCHFIELD D Operating Reactors Branch 5 5pp 14507 353 24X Fiche 50-213.82/12/16.8212230257
- 8212220457 Informs that draft SER for SEP Topics II-3 A,II-3 B,
 II-3 B (.II-3 C & III-3 B considered final Quabbin Reservoir
 Dam issues will be addressed in SEP Topic II-4 E, "Dam
 Integrity '
 CRUTCHFIELD,D Operating Reactors Branch 5 B2/12/20 COUNSIL,W C
 Connecticut Yankee Atomic Power Co 3pp 16503 220 24X
 Fiche 30-213, 82/12/20,8212220457
- O Inspection reports. IE Bulletins & correspondence
- B20B190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Dlameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl
 DEYDUNG, R C Director's Orfice, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 820B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolominescent Dosimeters " Syc list cncl COBB.L I Division of Fuel Facilities, Materials & Safeguerds 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fishe 50-000.82/11/05,820B190245
- 8P12030145 Forwards IE Insp Rept 50-213/82-1B on 820729-1001 No noncompliance noted MARTIN. T Division of Engineering & Technical Programs 82/11/17 CDUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 14304 105 24X Fiche 50-213-82/11/17-8212030145
- --B212030175 IE Insp Rept 50-213/62-18 on 820929-1001 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, records, repts & training & qualification & contingency plans MCKEOMNL II, GODY, A T Region 1. Office of Director 82/11/10 Spp 16306 107 24X Fiche 50-213,82/11/17,8212030165
- B208190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.B2/11/18.9208190251
- 8212060376 Informs that routine containment entries rescheduled from weekly to monthly or as required by unusual conditions within containment per IE Bulletin 80-24 Fewer entries result in reduced personnel radiation exposure COUNSIL.W O Connecticut Yankee Atomic Power Co 82/11/24 HAYNES R C Region 1, Office of Director 2pp 16311 079 24X Fichs 50-213,82/11/24,8212060376
- B20B190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2711/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50~000, B2/11/26, B20B190256
- 8212140074 Forwards IE Insp Rept 50-213/02-19 on 020927-1107 No noncompliance noted
 STARGSTECKI.R Division of Project & Resident Programs 82/11/29 COUNSIL.W 0 Connecticut Yankee Atomic Power Co 2pp 16408 321 24X Ficke 50-213, 02/11/29, 0212140074

- -8212140084 IE Insp Rept 50-213/82-19 on 820927-1107 No noncompliance noted Major areas inspected review of periodic & special rapts TMI action plan items, by-product mat license, offsite emergency response & receipt of new fuel REBELOWSKI, T., BRIOGS.C., ELGASBER.T.C. Division of Project & Resident Programs 62/11/17 lipp 16408 323 24X Fiche 50-213,82/11/29,8212140074
- 8:08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguerds 122/11/30 Consolidated Edison Co of New York. Inc. 396pp 16387 028 244 Fiche 50-000.82/11/30.8208190257
- 8208190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORPAN-E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24: Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYOUNG:R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- B2)2220361 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE life Notice 82-05 One util representative should be available to participate in entire meeting STAROSTECKI.R Division of Project & Resident Programs (CDNSTECKI.R Division of Project & Resident Programs (CDNSTE).H O Connecticut Yankes Atomic Power Co 3pp 14517 164 24X Fiche 50-213.82/12/16.8212220361
- BEOSI90268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAM,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 249 Fithe 50-000,82/12/20,8208190268
- GP:2290239 Advises that relief from ASME Code Section XI re volumetric & visual etams of welds 9 internal surfaces of reactor coolant pumps granted for remainder of insp interval.through 871231 or until pump disassembled FR notice encl
 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/21 COUNBIL,W G Connecticut Yankee Atomic Power Co 5pp 16582 103 24X
 Fiche 50-213, 82/12/21.8212290839
- --B212290242 Notice of granting of relief from certain requirements of ASME Code Section XI inservice insp requirements CRUTCHFIELD.D Operating Reactors Branch 5 82/12/21 2pp 16592 109 24X Fiche 50-213, 82/12/21, 82:2290239
- B Reportable occurrences: LERs & related correspondence
- E:12080449 Forwards LER 82-010/03L-0 GRAVES.R H Connecticut Yankee Atomic Power Co 82/12/02 HAYNES.R C Region 1. Office of Director 1p 16352 114 24X Fiche 50-213.82/12/02.8212080449
- --8212080457 LER 82-010/03L-0 on 821113, during preventive maint, operating linkage for containment air recirculation fan bypass damper failed Caused by mechanical failure of connecting linkage Linkage replaced TEST,R 2 Connecticut Yankee Atomic Power Co 82/12/03 Region i, Office of Director 1p 16352 i15 24X Fithe 50-213,82/12/02,82/12/080449
- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT
- B NRC Draft/Final Environmental Statements, suppls & correspondence
- Gf:12280218 Requests extension until 830315 to file response to NRC B21105 request for review of existing FEB for significant changes to facility or environs FIEDLER.P.B General Public Utilities - GPU Service Corp 82/12/21 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16562 124 24X fiche 50-219,82/12/21.8212280218

- F Security, medical, emergency & fire protection plans
- 8212100073 Forwards IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/11/24 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp 16379 090 24K Fiche 30-219, 82/11/24,8212100073
- ~-B212100081 IE Safeguards Insp Rept 50-219/82-27 on B21020-22 No noncompliance noted Major areas inspected measurement & controls, shipping & receiving, storage & internal control, physical inventory, records & repts & mgt & matl control sys DELLA RATTA.A , GODY.A T Region I, Office of Director B2/11/18 6pp 16379 092 24% Fiche 50-219,82/11/24,82(2100073
- 8P12210084 Forwards IE Insp Rept 50-219/82-25 on 821007-1111 (date differences throughout package noted) & notice of violation STAROSTECKI.R Division of Project % Resident Programs 82/11/29 FIEDLER.P B General Public Utilities GPU Service Corp 2pp 16493 020 244 Fiche 50-219, 82/11/29, 8212210044
- ~-B212210089 IE Insp Rept 50-217/82-25 on B21007-1109 Noncompliance noted on 821028.visitor left protected area unescorted Page 9 containing safeguards info deleted (ref 10CFR73 21) COMOILL.C , THOMAS.J , LAZARUS,W Division of Project & Resident Programs 82/11/19 13pp 16493 023 24X Fiche 50-219.82/11/29, 8212210084
- 8212130306 Responds to NRC request for add1 info re nearsite & farsite emergency operating facilities Util responded to Generic itr 81-11 on 820424,810911 & 820401 FIEDLER.P B General Public Utilities GPU Service Corp 82/12/07 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 16389 321 24% Fichs 50-219,82/12/07.8212130306
- BP12170050 Advises that Revision 13 to physical security plan, dtd 821017, acceptable CRUTCHFIELD, D Operating Reactors Branch 5 82/12/07 FIEDLER, P B General Public Utilities - OPU Service Corp ip 16480 363 24X Fiche 50-217, 82/12/07, 8212170050
- 8212210590 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/13 Document Management Branch 1p 16542 318 24X Fiche 50-219,82/12/13. B212210550
- --8212210555 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-10 re emergency radiological surveys onsite & EPIP-25 re nearsite emergency operations facility (NEDF) Revised index encl FIEDLER.P B General Public Utilities GPU Bervice Corp 82/11/29 HAYNES,R C Region 1, DFfice of Director 4pp 16542 319 24X Fiche 50-219,82/12/13,8212210550
- ~-8212210557 Public version of revised emergency plan implementing procedures, including Procedures EPIP-10 re emergency radiological surveys onsite & EPIP-25 re nearsite emergency operations facility (NEOF)

 * Oeneral Public Utilities GPU Service Corp 82/09/23 39pp 16542 323 24X Fiche 50-219,82/12/13,8212210550
- 8212210453 Ack receipt of 820930 & 1129 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-18 Response to Item B of NRC 820830 itr reviewed & violation rescinded Response withheld (ref 10CFR73 21) 8TAROSTECKI.R Division of Project & Resident Programs 82/12/14 FIEDLER.P B General Public Utilities GPU Service Corp 2pp 16489 202 24X fiche 50-219,82/12/14,8212210453
- --8212210460 Forwards revised response to NRC 820830 ltr re violations noted in IE Insp Rept 50-219/82-18 Safeguards markings revised to facilitate NRC handling LAGGART.M W General Public Utilities ~ GPU Service Corp 82/11/29 STAROSTECKI.R Division of Project & Resident Programs 1p 16489 204 24X Fiche 50-217.82/12/14.8212210453
- --0212210468 Forwards response to NRC 820830 ltr re violations nuted in IE Insp Rept 50-219/82-18 Corrective actions instrument rack encls secured Equipment control procedure reviewed Safeguards info withheld (ref 10CFR2 790 & 10CFR2 21) FIEDLER,P B General Public Utilities GPU Service Corp 82/09/30 STARGSTECKIR, Division of Project & Resident Programs 4pp 16489 205 24% Fiche 50-219,82/12/14,8212210453
- 82/12290477 Forwards IE Safeguards Insp Rept 50-219/82-26 on 82/012-15 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs 82/12/15 FIELDER, P B General Public Utilities - 6PU Service Corp 2pp 16583 258 24X Fiche 50-219,82/12/15,8212290477

- --8212290479 IE Safeguards Insp Rept 50-2(9/82-26 on 821012-15 No noncompliance noted Major areas inspected security plan, implementing procedures, organization & program audit, records & repts, testing & maint & locks, keys & combinations MADDEN, H., SMITH, G., GDDY, A.T. Division of Engineering & Technical Programs 82/11/24 3pp 16583-260 24% Fiche 50-219,82/12/15, 82/12/90477
- 82:12230299 Notifies that insufficient info prevents determination of tolling schedule requirements per (OCFRSO 4B(c) to 820630 request for eigmption from 10CFRSO App R requirements Schedules computed from 820630 EISENHUT.D G Division of Licensing 82/12/17 FIEDLER,P B General Public Utilities GPU Service Corp 3pp 16508 283 24% Ficha 50-219.82/12/17.8212230299
- 8212290408 Responds to 821124 ltr re delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 Submittal date of 821231 acceptable MARIIN.T T Division of Engineering & Technical Programs 82/12/27 FIEDLER.F B General Public Utilities GPU Service Corp Ip 14586 350 24x Fiche 50-219,82/12/27,8212290408
- --8212290410 Informs of delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 until 821231, due to playated level of mgt attention needed to review revised emergency plan FIEDLER.P D General Public Utilities GPU Service Corp 62/11/24 SMITH.O H Division of Emergency Preparedness & Operational Support | Ip 16586 351 24X Fiche 50-219,82/12/27,821230408 8212290408

G Adjudicatory correspondence

- BP12300174 Forwards complaint filed in connection w/traumatic back injury suffered by J Bruschi at facility Complaint alleges injury resulted from unfit & unsafe working place & exposure to radioactive matis investigation instacted HARWARD, J E American Nuclear Insurers B2/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 10gg 16598 096 24X Fiche 50-219,82/12/27,8212300174
- J Insurance & indemnity information
- 82:2:40352 Forwards Endorsement 65 to MAELU Policy MF-44 & Endorsement elkiaussk forwards endorsement of to inclu rullty print a endorsement B4 to NELIA Policy NF-164 MOREAU.W N General Public Utilities - GPU Service Corp B2/12/10 SALTIMAN.J Antitrust & Economic analysis Branch Utility Finance) Gpp 1640. 151 24X Fiche S0-219,82/12/10.8212140362
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8212100074 Responds to ACRS 821109 comments on leakage detection in 212100974 Responds to ACRS 821107 comments on leakage detection in SEP integrated assessment rept Visual insp of emergency condenser steam line piping acceptable unless not supported by limiting leakage rate Draft NUREG-0822 will be revised DENTON-NR Office of Nuclear Reactor Regulation, Director 82/12/02 BHEWMON,P S ACRS — Advisory Committee on Reactor Safeguards 7pp 16397 026 24% Fiche 50-219,82/12/02,8212100074
- P Operating license stage documents & correspondence
- 8212060063 Informs that draft SERs re SEP Hydrology Topics II-3 A. II-3 B.II-3 B i.II-3 C & III-3 C. transmitted by 820624 & 30 ltrs.considered final Evaluation will be basic input to outerstondingree renal gyaluation util de basic input to integrated assessment CRUTCHFIELD.D Operating Reactors Branch 5 82/08/27 FIEDLE Ceneral Public Utilities - QPU Service Corp 2pp 16314 020 Fachs 50-219.82/08/27.8212060063 FIEDLER, P B
- G212140001 Add1 response to FdIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M. Division of Rules and Records G2/11/03 GALLO, J Isham. Lincoln & Beale 2pp 16433 354, 24X Fiche 50-000, 82/11/03, 8212140001
- --7908140784 Forwards "Tentative Plan for Beismic Reanalysis of Critical Structural Sys of Oyster Creek Unit 1 " 79/08/02 LEVIN.H A MURRAY.R C Laurence Livermore Laboratory 79/08/02 LEVIN.H A Systematic Evaluation Program Branch (Pre 791030) 1p 16435 093 24% Fiche 50-000.82/11/03.82/2140001
- --790B1407B9 "Tentative Plan for Beismic Reanalysis of Critical Structural Sys of Dyster Creek Unit " HA-S M E040, Inc 79/08/02 17pp 16435 094 24X Fiche 50-000, 82/11/03, 8212140001

- --B002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping systematics banchmarking per code verification program SHAO,L C Assistant Director for Engineering Programs 79/10/3D EISENHUT,D Q Division of Operating Reactors 1p 16435 iii 24% Fiche 50-000.82/11/03.8212140001
- --8005280555 Forwards rept, "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis." prepared by NCT Engineering. Inc MURRAY.R C Lawrence Livermore Laboratory 80/05/19 ALL ISON. Systematic Evaluation Program Granch ip 16435-112 24X Fiche 50-000.82/11/03.8212140001
- --B005280561 "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis " Prepared for LLL TSALT NCT Engineering, Inc. FIN A-0233 80/05/31 NRC No Detailed Affiliation Given 50pp 16435 113 24X Fiche 50-000,82/11/03,8212140001
- -BioSiloSi2 Forwards two consultant repts & list of open items re SEP Topics III-6 re seismic design consideration & III-11 re component integrity W/o consultant repts CRUTCHFIELD, D Derating Reactors Branch 5 81/03/20 FINFROCK, I R Public Service Electric & Gas Co of New Jersey 3pp 16434 261 24% Fiche 50-000, 82/11/03, 8212140001
- ADJIE 2005A Generic Ltr 82-27 to all BWR licensees of operating reactors nit220056 Generic Ltr 82-2/ to all blub licenses of operating reduce except LACBWR. Big Rock Point, Dreaden i Humboldt Bay.
 applicants for OL & holders of CP re transmittal of NURGO-0763 & NURGO-0783 Svc list enc! M/o stated enc!
 EISENHUT.D @ Division of Licensing 82/11/15 General Public Utilities - QPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, 8211230066
- 8212060247 Forwards schedules & resolutions for SEP Topics II-5 B.V-5. VIII-3 B.V-12 A.XV-16,XV-18,III-4 A.VI-7 A 3,VI-10 A. II-3 B.II-3 B. II-3 C.III-1, III-2, III-3 A.III-3 C. III-4 A.III-4 B.III-4 D.III-5 A.III-5 B & III-6 CLARK,P R General Public Utilities OPU Service Corp 82/11/29 CRUYCHFIELD,D Operating Reactors Branch 5 17pp 16313 158 24X Fiche 50-219,82/11/29,8212060247 16313 158 24X
- B212070097 Forwards SER & proprietary & nonproprietary technical evaluation repts re environ qualification of safety-related electric equipment Justification for continued operation must be reaffirmed & addI info submitted CRUTCHFIELD. D Operating Reactors Branch 5 82/11/30 FIEDLER.P & General Public Utilities ~ GPU Service Corp 3pp 16328 001 24% Fiche 50-219,82/11/30,8212070097
- --8207150169 "Review of Licensey Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts: "final technical evaluation rept CRAME.C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-453 82/07/09 LE:N 8 NRC No Detailed Affiliation Given 516pp 16328 010 24X Fiche 50-219.82/11/30,8212070097
- BP12080206 Forwards SER re radiological field operations training program Qualification criteria per 821008 telcon, acceptable CRUTCHFIELD.D Operating Reactors Branch 5 82/12/03 FIELDER.P B General Public Utilities - GPU Service Corp 2pp 16354 001 24X Fiche 50-219, 82/12/03, 6212080204
- -8212080211 SER supporting proposed Tech Spec Section 6 3 2 re sadiological field operations training program # Office of Nuclear Reactor Regulation, Director 82/12/03 16354 003 24X Fiche 50-219,82/12/03.8212080204 քթը
- BP:12210019 Tech Spec Change Request 100 for amend to License DPR-16, changing App A re inservice insp surveillance requirements for snubbers
 FIEDLER.P B General Public Utilities GPU Service Corp 82/12/16
 Office of Nuclear Reactor Regulation, Director 5pp 16490 164
 24X Fiche 50-219,82/12/10,8212210019
- --0212210020 Proposed Tech Specs re inservice insp surveillance requirements for snubbers

 Oneral Public Vilities - GPU Service Corp 82/12/10 22pp
 16490 169 24% Ftche 50-219,82/12/10,82/2210019
- SU12280313 Application to amend License DPR-16.consisting of Tech Spec change limiting oxygen content to 4% Class III exemption fee 82/12/15

- O.12230310 Forwards request for add1 info re NUREG-0737. Item 11 D i.
 "Safety/Relief Valve Testing " Info should be submitted
 within 90 days of itr receipt
 CRUTCHFIELD. D Operating Reactors Branch 5 82/12/17 FIEDLER.P B
 General Public Utilities OPU Service Corp 3pp 16507 316 24X
 - Fiche 50-219, 82/12/17, 8212230310
- G [napection reports, IE Bulletins & correspondence
- 8.08190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Mallitarge-Diameter: Stainless Steel, Recirculation Sys Piping at BRR Plants " Syc list encl BEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82~42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminascent Dosimeters " Svc list
 - COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/1/705 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8209190245
- 8208170251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JDRDAH, E. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 197 24X fiche 50-000, 82/11/19, 8208190251
- GP12030030 Forwards IE Insp Rept 50-219/62-23 on 620914-17 & notice
 - of violation

 MARTHN.T T Division of Engineering & Technical Programs 82/11/18

 TIEDLER.P B General Public Utilities ~ OPU Service Corp 2pp

 16305 061 24% Fiche 50-219, 82/11/18, 8212030030
- --8212030033 Notice of violation from inap on 820914-17

 * Division of Engineering & Technical Programs 82/11/18 2pp 16305 063 24X Fiche 50-219, 82/11/18 8212030030
- --8212030037 IE Insp Rept 50-219/82-23 on 820914-17 Noncompliance noted failure to follow air particulate sampling schedule & failure to calibr entire thermal monitoring sys JANO, J C. JACKESON J J. BORES, R J Division of Engineering & Technical Programs 82/11/10 lipp 16305-065 24X Fiche 50-219, 82/11/18, 8212030030
- 8212100073 Forwards IE Safeguards Insp Rept 50-217/82-27 on 821020-22 No noncompliance noted

 NARTHALT Division of Engineering & Technical Programs 82/11/24

 FIEDLER.P B General Public Utilities - GPU Service Corp 2pp
 16377 090 24x Fiche 50-219,82/11/24.6212100073
- --8212100081 IE Safeguards Insp Rept 50-219/82-27 on 821020-22 No noncompliance noted Major areas inspected measurement & controls, shipping & receiving, storage & internal control, physical inventory, records & repts & mgt & matl control sys DELLA RATTA, A. GODY, A T. Region i, Office of Director & 6pp 14379 092 24X fiche 50-219,82/11/24,8212100073 89/11/1B
- GCOG190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks "Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Anforcement B2/11/26 Consolidated Edison Co of New York, 1 11/26 Consolidated Edison Co of New York, Inc 24X Fiche 50-000:82/11/26:8208190256 16411 065
- 82:12040332 Informs of revision to routine insp interval for visual insp of spanger surfaces & ultrasonic test & due penetrant exam of feedwater noticles Future insps uill be conducted per schedule outlined in Table 2 of NUREG-06:19
 [FIEDLER.P B General Public Utilities QPU Service Corp B2/11/29
 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16312 079 24X
 [Fiche 50-219, 82/11/29, 82:2060332]
- GP12210084 Forwards IE Insp Rept 50-219/82-25 on 821007-1111 (date differences throughout package noted) & notice of violation STARGSTECKLOR Division of Project & Resident Programs 82/11/29 FIEDLER/P B General Public Utilities GPU Service Corp 2pp 16493 020 24x Fiche 50-219,82/11/29,8212210084.
- --8212210087 Notice of violation from insp on 821007-1109 * Division of Project & Resident Programs 82/11/27 16493 022 24X Fiche 50-219,82/11/29,8212210084
- --8212210089 IE Insp Rept 50-219/82-25 on 821007-1109 Noncompliance #12210097 IE Insp Rept 50-219/82-25 on 821007-1109 Nancompliance noted on 821028, visitor left protected area unescorted Page 9 containing safeguards info delated (ref 100FR73 21) COMBILL.C : THOMAS, J , LAZARUS, W Division of Project & Resident Programs 82/11/19 13pp 16493 023 24% Fiche 50-219,82/11/29,8212210084

- 8208190257 IF Into Notice 82-47. "Transportation of Tune A Guantities 208190237 IE Info Notice 82-47. "Transportation of Type A Quant of Non-Fissile Radioactive Mati " Swc list encl COBB.L I Division of Fuel Facilities, Materials & Safaguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 14387-028 24X Fiche 50-000.82/11/30.8208190257
- 8212070014 Discusses IE insp on 811103-820317 & forwards notice of PROPOSITE Discusses IE insp on diffusion of civil penalty violation & notice or proposed imposition of civil penalty HAYNES.R C Region in Office of Director 82/11/30 FIEDLER.P B General Public Utilities - GPU Service Corp 5pp 16356 281 24 Fiche 50-219, 82/11/30, 8212070014
- --B212070021 Notice of violation & notice of proposed imposition of Civil penalty in amount of \$40,000 Noncompliance noted surveillance testing of A isolation condenser motor driven valve V-14-30 inadequate to demonstrate operability HAYNES, R C Region 1. Office of Director 82/11/3 16355 285 24x Fiche 50-219, 82/11/30,8212070014
- 8212080556 Responds to Questions 1 & 4 of IE Bulistin 82-03, Revision 1 re ultrasonic test methods detecting intergranular stress corrosion crecking in thick walled piping Response subj to change Related info enci | IEOLER.P B General Public Utilities GPU Service Corp 82/12/01 HAYNEGER C Region 1, 0ffice of Director 24pp 16352 013 24X Fiche 50-219, 82/12/01.8212080554
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " 8vc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8708190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8212080347 Ack receipt of 821025 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-20
 STARGSTECKLR Division of Project & Resident Programs 62/12/03
 FIEDLER.P B General Public Utilities GPU Service Corp 1p
 16393 325 24% Fiche 30-219.82/12/03.8212080347
- --B212080394 Responds to NRC 820922 ltr re violations noted in IE Insp Rept 50-219/82-20 Corrective actions Diesel Generator 1 lube oil heater pump control switch returned to on position & revision to general drywell clearance issued FIEDLER.P B General Public Utilities OPU Service Corp R2/10/25 STAROSTECKIR Division of Project & Resident Programs 3pp 16353 326 24X Fiche 50-219.88/12/03.8218080347
- 8212220466 Forwards IE Insp Rept 50-219/82-22 on 820908-1006 & notice of violation
 STAROSTECKI.R Division of Project & Resident Programs 82/12/07 FIEDLER.P B Oeneral Public Utilities ~ OPU Service Corp 16504 021 24x Fiche 50-219,82/12/07,8212220466
- --8212220468 Notice of violation from inst on 820708-1006 * Division of Project & Resident Programs 82/ 14504 023 24X Fichs 50-219, 82/12/07,8212220466
- --8212220473 IE Insp Rept 50-219/82-22 on 820908-1006 Noncompliance 212220473 IE Insp Rept 50-219/82-22 on 820908-1006 Noncompliance noted failure to maintain fully operable isolation trip sysfor isolation condensers during maint on isolation valvas CONGILL.C . THOMAS.J . TRIPP.L E Division of Project & Resident Programs 82/10/22 lipp 16504 024 24X Fiche 50-219,82/12/07,8212220466
- 82:2210019 Tech Spec Change Request 100 for amend to License DPR-16, changing App A re inservice insp surveillance requirements
- --B212210020 Proposed Tech Bpecs re inservice insp surveillance requirements for snubbers * Oeneral Public Utilities ~ OPU Service Corp 82/12/10 22pp 16490 169 24X Fiche 50-219.82/12/10,8212210019
- 8212210453 Ack receipt of 820930 & 1129 ltrs informing NRC of steps Placitudes are receipt of 320740 & 1127 ltms informing NRC of Steps taken to correct violations noted in IE linep Rept 50-219/82-18 Response to Item ID of NRC 820830 ltm reviewed & violation rescinded Response withheld (ref 10CFR73 21), STAROSTECKI.R Division of Project & Resident Programs, 82/12/14-FIECLER, PB Comeral Public Utilities - OPU Service Corp 2pp 16489 202 24X Fiche 50-219,82/12/14,8212210453

- --B212210460 Forwards revised response to NRC 820830 ltr re violations noted in IE Insp Rept 50-219/82-18 Safeguards markings revised to facilitate NRC handling LAGGART.M W General Public Utilities GPU Service Corp 82/11/29 STAROSTECKI.R Division of Project & Resident Programs ip 16489 204 24X Fiche 50-219.82/12/14.8212210453
- --B2[22]0469 Forwards response to NRC B20830 ltr re violations noted in IE Insp Rept 50-219/82-18 Corrective actions instrument rack encis secured Equipment control procedure reviewed Safeguards info withhold (ref 106FR2 790 & 106FR73 21) FIEDLER, P. B. General Public Utilities GPU Burvice Corp B2/09/30 STAROSTECKI, R. Division of Project & Resident Programs 4pp 16489 205 24X Fiche 50-219,82/12/14,8212210453
- 8212290477 Forwards IE Safeguards Insp Rept 50-219/82-26 on 821012-15
 No noncompliance noted
 MARTIN, T I Division of Engineering & Technical Programs 82/12/15
 FIELDER: P B General Public Utilities GPU Service Corp 2pp
 16383 258 24X Fiche 50-219.82/12/15.8212290477
- --8212290479 IE Safeguards Insp Rept 50-219/82-26 on 821012-15 No noncompliance noted Major areas inspected security plan. implementing procedures organization & program audit, records & repts testing & maint & locks; keys & combinations MADDEN, N. SMITH, O., GODY, A. T. Division of Engineering & Technical Programs 82/11/24 3pp 16583 260 24% Fishe 50-219.82/12/15, 8212870477
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list and DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8008190268 IE info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list entl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edition Co of New York, Inc 108pp 16628 293 24x Fiche 50-000.82/12/20.8208190268
- 8212290408 Responds to 821124 itr re delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 Submitted date of 821231 acceptable MARTIN,T T Division of Engineering & Technical Programs 82/12/27 FIEOLER,P B General Public Utilities GPU Service Corp 19 16586,350 24% Fiche 50-219,82/12/27.6212290408
- --B212290410 Informs of delay in submitting responses to Apps B & C of IE Emergency Preparedness Appraisal Rept 50-219/82-01 until 821231, due to elevated level of mgt attention needed to review revised emergency plan FIE0LER,P B Owneral Public Utilities OPU Service Corp 82/11/24 SAITH,O H Division of Emergency Preparedness & Operational Support ip 16584 351, 24X Fiche 50-219.82/12/27, cryspon408

R Periodic operating reports & related correspondence

- 82:12290127 Forwards monthly operating rept for Oct 1982 FIEDLER.P 8 General Public Utilities - OPU Service Corg 82/11/11 Office of Resource Management, Director 3pp 15583 210 24X Fiche 50-219,82/11/11.8212290127
- --B212290134 Honthly operating rept for Oct 1982 BARAN,R Ceneral Public Utilities - GPU Service Corp 82/11/03 7ap 16583 213 24X Fiche 50-219, 82/11/11,8212290127
- 8212210040 Forwards thirtieth quarterly rept. "Study of Hoodborer Populations re Ogster Creek Generating Station. 820821-1120 "
 FIERLER.P B. General Public Utilities GPU Service Corp 82/12/10
 HAYNES.R C Region i. Diffice of Director ip 16491 008 24X
 Fiche 50-219.82/12/10.8212210040
- ---B212210044 "Btudy of Woodborer Populations to Dyster Creek Generating Station, 820821-1120," thirtieth quarterly rept HILLMAN, R.E., BELMORE, C.J. Battelle New England Marine Research Laboratory, 82/11/30 23pp, 16491 009 24X Fiche 50-219,82/12/10.8212210040
- S Reportable occurrences, LERs & related correspondence
- 8001140342 RO 30/219/80/1-1p on 800105, while performing electromatic relief valve operability test electromatic relief valve D failed to open Cause undetermined Corrective action to be determined.

 CARROLLI T. Jersey Central Power & Light Co 80/01/07 3pp 90017.245 24% Fiche 50-219,80/01/07,8001140342

- 8212080511 Forwards LER 82-053/03L-0 Detailed event analysis encl | IEDLER.P B General Public Utilities - OPU Service Corp 82/11/22 HAYNES.R C Region 1. Office of Director 3pp 16352 001 24X Fiche 50-219,82/11/22.8212080511
- ~-8212080525 LER 82-053/09L-0 on 821022 during brush change on recirculation pump D motor generator set, recirculation pump E tripped Caused by current overload on recirculation pump E Fung E restarted Worn brushes on motor generator replaced HUTKO. K General Public Utilities GPU Service Corp 82/11/22 Region L. Office of Director 1p 16352 004 24X Fiche 50-219,82/11/22,8212080511
- 8:12010138 EN-82-036 notice of violation to proposed imposition of civily penalties will be issued to util approx 821130 Action based on inadequate surveillance testing to establish valve operability HARBER, G. AKELRAD, J. Director's Office, Office or Inspection and Enforcement 82/11/23 ip 16258 081 24X Fiche 50-219.82/11/23, 82/2010158
- 8:1206014B LER 82-056/01P on 821120, during insp of 24-volt do battery charger A2, broaker found in tripped position Caused by satpoint drift for overvoltage relay on battery charger output breaker Gutput breaker reset & closed FIEDLER.P B General Public Utilities GPU Service Corp 82/11/23 HAYMES.R C Region i. Office of Director 3pp 16313 149 24X Ficha 50-219.82/11/23,8212040148
- 8212080240 Forwards LER 82-051/03L-0 Detailed event analysis encl | IEDLER.P B General Public Utilities - GPU Service Corp 82/11/23 | MAYNES.R C Region 1. Office of Director 4pp 16394 174 24X | Fiche 50-219, 82/11/23, 8212080240
- --8212080263 LER 82-051/03L-0 on 820930.unmonitored release of radioactive liquid to soil around waste surge tank, pump & attached drain pipang occurred Caused by severe pitting in bottom (0 ft of sidewall & bottom of tank
 HACAR.C Oeneral Public Utilities GPU Service Corp 82/11/22
 Region 1. Office of Director 1p 16354 178 24X
 Fiche 50-219,82/11/23,8212080240
- 8212080349 Forwards LER 82-055/01P-0 FIEDLER.P B General Public Utilities - GPU Service Corp 82/11/24 HAYRES.R C Region 1. Office of Director 1p 16352 005 24X Fiche 50-219, 82/11/24, 8212080349
- --B212080359 LER 82-055/01P-O on 821(15, stack gas not monitored continuously due to breaker trip on stack gas sample pump 8 Cause under investigation Stack gas sample pump A put into svc Condition under review

 * General Public Utilities GPU Service Corp 62/11/24 Region 1. Office of Director ip 16352 006 24X Fiche 50-219,82/11/24-8212080349
- BRI2080398 Forwards LER 82-054/03L-0 Detailed event analysis encl FLEDLER:F B General Public Utilities - OPU Service Corp 82/11/24 HAYNES:R C Region 1. Office of Director 3pp 16352 280 24X (iche 50-219, 82/11/24:8212080388
- ~-8212080395 LER 82-054/03L-O on 831105 after completing TIP trace, ball valve on TIP machine 3 failed to close Caused by moisture buildup around in-shield limit switch operating aro Arm cleaned & switch aligned MURDOCK, R J General Public Utilities GPU Service Corp 82/11/24 Region 1, Office of Director ip 16952 283 24X Fiche 50-219,82/11/24.8212080388
- BP:12140169 Forwards LER 82-052/01T-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/12/02 HAYNES.R C Region 1. Office of Director 3pp 16409 357 24X Fiche 50-219, 82/12/02.8212140169
- --8212140177 LER 82-052/01T-0 on 820828, environ release occured w/
 radwaste discharge monitor out of eve w/o performing second
 sample analysis Caused by personnel error Procedure change
 initiated requiring signed liquid release permit
 HOMMAN-B General Public Utilities GPU Service Corp 82/12/02
 Region 1, Office of Director 1p 16409 360 24X
 Fiche 50-219,82/12/02,8212140169
- 80:2210372 Forwards LER 82-056/01T-0 Detailed event analysis encl FIEDLER.P B General Public Utilities - GPU Service Corp 82/12/08 HAYNES.R C Region I. Office of Director 4pp 16494 305 24X Fiche 50-219.82/12/08/8212210372
- --B212210377 LER 82-056/01T-0 on 821120, output breaker for A2 24-volt dc battery charger tripped Caused by setpoint drift of overvoltage relay Breaker checked & closed & relay setpoint adjusted CUSTODIO.D B General Public Utilities GPU Service Corp S2/12/08 Region 1. Office of Director 1p 16494 309 24X Fiche 50-219,82/12/08.8212210372

By1214016B PND-1-82-079 on 821209, reactor shutdown scheduled to correct increasing unidentified drywell leakage Possibly Caused by reactor recirculation pump seal degradation Shutdown scheduled for 5 days
1HOMAS, J. LAZARUS, W., KEIMIG, R. Region 1, Office of Director 82/12/09 19 14410 210 24X Piche 50-219,82/12/09,8212140168

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, energency & fire protection plans

- BP12030034 Ack receipt of 820903 ltr transmitting action plan progress rept for Apr-June 1982 in response to Health Physics Appraisal Rept 30-220/80-11 MARTSM.T T Division of Engineering & Technical Programs 82/11/08 RHDDE.G K Niagara Kohawk Power Corp 2pp 16304 113 24X Fiche 50-220.82/11/08.8212030034
- ~B212030050 Submits action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11 Improvements made to radiation protection program MANGAH, C V Niagara Mohawk Power Corp 82/09/03 HAYNES, R C Region 1. Office of Director 7pp 14304 115 24X Fiche 50-220, 82/11/08, 8212030034
- Q212030018 Forwards IE Insp Rept 50-220/82-20 on 821126-29 No Honcompliance noted MARTIN T T Division of Engineering & Technical Programs 82/11/17 RHODE 6 K Niegara Mohauk Power Corp 2pp 16304 201 24X Fiche 50-220-82/11/17-82(2030018
- --B212030023 IE Insp Rept 50-220/B2-20 on 821026-27 No noncompliance noted Major areas inspected implementation of corrective actions for health physics appraisals significant appraisal findings * licensee action on previous insp findings NIMITZ.R L , SHANBAV.M M Region 1. Office of Director 82/11/16 13pp 16304 303 24X Fiche 50-220.82/11/17.8212030018
- \$212020302 Forwards TMT action item implementation schedule per 820416, 0607,0820,0930 & 1001 Ites Items will be completed prior to startup from current recirculation piping replacement outage MANGAN.C V Niagara Mohawk Power Corp 82/11/29 EISENHUT, D 6 Division of Licensing 3pp 16277 336 24% Fiche 50-220,82/11/29, 8212020302
- B:·12060204 Forwards response to B21103 request for add1 info re alternate shutdom capability for postulated control room fire MANGAN.C V Niagara Hohawk Power Carp 82/12/03 VASSALLO, D B Operating Reactors Branch 3 36pp 16313 011 24X Fiche 50-220.82/12/03.8212060204
- BP12090104 Responds to request re emergency operations facilities per Generic Ltr Bir10 Info requested previously transmitted MANGAN, C V Niagara Mohawk Power Corp B2/12/06 EISENHUT, D 0 Division of Licensing 1p 16357 282 24X Fiche 50-220,82/12/06, N212090104
- 8912210131 Forwards addl info to prepare shift crews operating nuclear plants for type of questions NRC duty officers may ask via IRC emergency notification sys STARGSTECKI, R Division of Project & Resident Programs 82/12/16 RHDDE.0 K , SEIBERT, C R Niagara Mohawk Power Corp 6pp 16485 188 24% Fiche 50-220,82/12/16,8212210131

P Operating license stage documents & correspondence

- 8?it230056 Generic Ltr 82-27 to all BWR licensess of operating reactors except LAGBUR, by Rock Point Dresden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl W/o stated encl EISEMHUT, D O Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000,82/11/15,8211230066
- G:12020102 Advises that response to B20621 technical evaluation rept re comparison of effluent Tech Spacs & offsite dose calculational manual util be submitted by B30301, not 821[30 as stated in 82[025] the Tech Spacs & manual being revised MANGAN, C V Niagara Mohawk Power Corp 82/11/24 VASSALLO, D B Operating Reactors Branch 2 ip 16272 028 24X Fiche 50-220, 82/11/24, 82[2020102]
- 8212020302 Forwards TMI action item implementation schedule per 8204iá, 0.607,0820,0930 & 1001 ltrs Items will be completed prior to startup from current recirculation piping replacement outage MANGAN, C V Niagara Mohawk Power Corp 82/11/29 EISENHUT, D 0 Division of Licensing 3pp 16277-336 24X Fiche 50-220,82/11/29,8212020302

- 8P12080159 Forwards design info the Class IE protection sys being installed on motor generator sets Three oversite figures illustrating revised control, instrument on-line power & protective package encl Aperture cards are available in PDR MANGAN, C V Niagara Mohawk Power Corp 82/12/01 VASSALLD, D B Operating Reactors Branch 2 3pp 16354 241 24X Fiche 50-220,82/12/01.9212080159
- B212130284 Forwards safety evaluation of response to NUREG-0737, Item II K 3 25. "Effect or Loss of AC Power on Pump Seals" Present facility design acceptable Demonstration of pump seal performance during loss of cooling water unnecessary VASSALLO, D B Operating Reactors Branch 2 82/12/01 DISE, D P Niagara Mohawk Power Corp 7pp 16418 244 24% Fiche 50-220,82/12/01,8212130284
- GP12090154 Forwards results of automatic depressurization sys logic studies & description of proposed mode Studies included BHR small break LOCA accident outside primary containment safe shutdown analysis & Mark I containment load mitigation MANGAN,C V Niagara Mohawk Power Corp 82/12/03 EISENHUT,D G Office of Nuclear Reactor Regulation. Director 4pp 16359 113 24X Fiche 30~220,82/12/03,8212090154
- B212170266 Advises that upon completion of current outage for replacement of saferends & recirculation piping, Cycle 7 operation uill continue for approx i yr prior to refueling Mod schedule encl MANGAN, C V Niagara Mohawk Power Corp 82/12/15 VASSALLO, D B Operating Reactors Branch 2 2pp 16457 175 24X Fiche 50-220.82/12/15.8212170266
- 8212270265 Responds to NRC 82110B request for info re implementation of NUREO-0313.Revision 1 Info will be provided by 830101 MANGAN.C V Niagara Mohawk Fower Corp 82/12/20 VASSALLO.D B Operating Reactors Branch 2 1p 16/530 326 24x Fiche 50-220.82/12/20,8212270265
- BP12270393 Informs that schedule for providing info re NUREG-0737. Item II B 3 on post-accident sampling capability will not be provided until 821228.per 820726 request MANGAN.C V Niagara Mohawk Power Corp 82/12/20 EISFNHUT.D 9 Division of Licensing 1p 16530 015 24X Fiche 50-220.82/12/20, post027082
- Q Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin B2-03.Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl
 DEYOUNG.R C Director's Defice, Office of Inspection and
 Enforcement B2/10/28 Consolidated Edison Co of New York, lic
- B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000 B2/11/05 B208190245
- 8P12030034 Ack receipt of 820903 ltr transmitting action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11 MARTIN.T T Division of Engineering & Technical Programs 82/11/08 RHODE.6 K Niagara Mohawk Power Corp 2pp 16304 113 24 X Fiche 50-220, 82/11/08, 8212030034
- --8212030050 Bubmits action plan progress rept for Apr-June 1982, in response to Health Physics Appraisal Rept 50-220/80-11 Improvements made to radiation protection program MANGAN, C V Niagara Mohawk Power Corp 82/09/03 HAYNES, R C Region I. Office of Director 7pp 16304 115 24X Fiche 50-220,82/11/08,8212030034
- G212030018 Forwards IE Insp Rept 50-220/82-20 on 821126-29 No noncompliance noted MARTIN T Division of Engineering & Technical Programs | 82/11/17 RHODE O K Niagara Mohawk Power Corp 2pp 16304 201 24X Fiche 50-220,82/11/17,8212030018
- --8212030023 IE Insp Rept 50-220/82-20 on 821026-27 No noncompliance noted Major areas inspected implementation of corrective actions for health physics appraisal, significant appraisal findings & licensee action on previous insp findings NIMITZ.R L. SHANBAKY, M M Region I. Office of Director 82/11/16 i3pp. 16304 303 24X Fiche 50-220,82/11/17,8212030018
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Lyarcise Requirements" Syc list encl JORDANIE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251

- 8208190256 IE Info Notice 82~46. "Defective & Obsolete Combination Padiocks " 5vc list enc! DEYOUND, R C Director's Office. Office of Inspection and Enforcement #2711/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24% Fiche 50~000, 82/11/26,8208190256
- 82/08190297 TE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! CD86.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 35App 16387 028 24x Fiche 50-000.82/11/30.8208190257
- 8708190257 IE Builetin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc fist encl DEYGUNG-R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fichs 50-000,82/12/03.8208190259
- B20B190261 IE info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JGRDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462-064 24 Fiche 50-000,82/12/03.9208190261
- 8212140397 Ack receipt of 821022 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-14
 57:ROSTECKLIR Division of Project & Resident Programs 82/12/07
 HKICER, O K Niagara Mohawk Power Corp 2pp 16404 018 24X
 Fiche 50-220.82/12/07.6212140397
- B212140406 Responds to NRC 820922 ltr re violations noted in IE Insp Rept 50-220/82-14 Corrective actions radiation work germit procedure revised to provide reasonable & enforceable documentation requirement LEMPGES T E Niagara Mohawk Power Corp 82/10/22 STAROSTECKI, R Division of Project & Resident Programs 3pp 16404 020 24X Fiche 50-220.82/12/07.8212140397
- GP12150207 Act receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Imag Rept 50-220/82-17 STARDSTECKI, R Division of Project & Resident Programs 82/12/10 RHODE, G K Niagara Mohawk Power Corp 2pp 16430 264 24X Fiche 50-220.82/12/10.8212150207
- --8212150213 Responds to NRC 821019 ltr re violations noted in IE Insp Rept 50-220/82-17 Corrective actions 812 out of seven outstanding items re IE circulars closed out & IE Circular 80-22 will be closed by 830101 LEMPGES, I & Niagara Mohawk Power Corp Division of Project & Resident Programs 2pp (6430 266 24X Fiche 50-220, 62/12/10.8212150207
- B./12220509 Requests written statement within 30 days of itr re use or disposition of Raychen-Flamtrol cables Generic qualification tests for cables no longer acceptable JORDAN.E.L. Division of Engineering & Quality Assurance 82/12/10 RHODE, C.K. Niagara Mohawk Power Corp 3pp 16523-097 24X Fishe 50-220, 82/12/10, 8212220508
- 8:08190267 IE info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring" Svt list enc!
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- C212220413 Advises of plans to conduct interviews w/util personnel re drug & alcohol abuse & rehabilitation programs, as result of IE Info Notice 82-05. "Increasing Frequency of Drug-Related Incidents " Topic areas encl STAROSTECKI.R Division of Project & Resident Programs 82/12/16 RHODE.O K Niagera Hohowt Fower Corp 2pp 16503 358 24X Fiche 50-220, 82/12/16, 8212220413
- 8/12220476 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/82-01 BTAROSTECKLR Division of Project & Resident Programs 82/12/16 RHODE.0 & Niagara Hohauk Power Corp 2pp 16504/018 24X Fiche 50-220.82/12/16.8212220476
- --B212220479 Responds to NRC 820913 ltr re violations noted in IE Imsp Rept 82-220/B2-01 Corrective actions two phase operating procedure review program will be completed by 840101 LEMPGES.T & Niagara Mohawk Power Corp 82/10/29 STAROSTECKI.R Division of Project & Resident Programs Ip 16504.020 24X Fiche 50-220,82/12/16,8212220476
- 8208190268 JE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24x Fiche 50-000,82/12/20,8208190268

- R Periodic operating reports & related correspondence
- 8212140029 Forwards monthly operating rept for Nov 1982 LEMPGE5.T E Niagara Mohawk Power Corp 82/12/07 Director's Office, Office of Inapection and Enforcement 1p 16409 286 24X Fiche 50-220, 82/12/07.8212140029
- --0212149031 Monthly operating rept for Nav 1982 RDMAN.T II Niagara Mohawk Power Corp 82/12/03 4pp 16409 28/ 24% Fische 50-220.82/12/07.82/12140029
- 5 Reportable occurrences, LERs & related correspondence
- B2/2290414 Forwards LER 82-015/03L-0 LEMPGES.T E Niagara Mohawk Power Corp 82/12/16 HAYNES R (Region 1, Office of Director 1p 16585 190 24X fiche 50-220.82/12/16.8212290416
- --B212290430 LER 82-015/O3L-0 on 821117 & 18, deluge valves 101N & 1015, protecting reserve power transformer, intentionally made inoperable to replace pressure switches to upgrade fire protection says Deluge says returned to says after mod RABY, J., NEJLD,R. Miagara Mohawk Power Corp. 82/12/16 Region 1, Orfice of Director 1p. 16595 191 24X Fiche 50-220, 82/12/16, 82/12/90416.

DOCKET 50-225 RPT CRITICAL EXPERIMENT

- P Operating Incense stage documents & correspondence
- GP1214010.3 Generic Ltr B2-28 to all licensees of operating Westinghouse & C-E PURS (except Arkansas Nuclear Dne. Unit 2 & San Onofre 2 & 3) re imadequate core cooling instrumentation sys Svc list encl
 LISENBUT.D & Division of Licensing 82/12/10 Yankee Atomic Liectric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10. (2)2140103
- & Inspection reports, IE Bulletins & correspondence
- 9708190268 IE Info Notice 82-50. "Mad of Solid State AC Undervoltage Relays Type ITE-27" Syc list encl JGRDAN.E L Division or Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24% [iche 50-000, 82/12/20, 8208190268]
- NOCKET 50-237 DRESOEN NUCLEAR POWER STATION, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- BP12030283 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/11/30 Document Management Branch (p. 16316-253 R4X Fiche 80-010.82/11/30, 14212030283
- --B21203)286 Forwards public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 reshift turnover u/technical support ctr & environ teams activated Receipt forms & procedure histories encl SCOTT.D J Commonwealth Edison Co B2/11/19 DENION, HR Office Reactor Regulation, Director 7pp 16316 255 24X Fiche 50-010, 82/11/30, 8212030283
- --8212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover witechnical support ctr & environ teams activated * Commonwealth Edison Co 82/11/17 14pp 16316 262 24X fich* 50-010,82/11/30,8212030283
- U:12070383 Forwards info re emergency operations facilities per U21122 & 1202 requests info previously submitted by telcon Nequest for written response unnocessary burden on icensee DELOEDROE. U. D. Commonwealth Edison Co. 02/12/03 EISENHUT. D. Q. Division of Licensing 2pp 16365 051 24X Fiche 50-000,82/12/03,6212070363
- BE/12130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Ciffsite Konitoring Locations (Haps)" FELTON: J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000,82/12/07, #212130017

DOCKETED ITEMS

- -U212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Orriste Monitoring Locations (Maps) " Revised table of contents encl PAJJUSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC ~ No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, 82/12/07, 8212130017
- -8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Unsite & Offsite Munitoring Locations (Maps)" PAJOHSKIJ E., LITERSKI, L.A. Commonwealth Edison Co. 82/11/29 4pp 16417-065 24* Fiche 50-000.82/12/07.8212130017
- 8.412140243 Advises of distribution of revisions to "Generating Station Limergency Plan" Braidwood annex not prepared TRAMMIT R Commonwealth Edison Co 82/12/07 DENTUN.H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000.62/12/07.8212140243
- 82/12210118 Forwards IE Emergency Preparedness SERs 50-237/62-27 & 50 249/82-27 during Nov 1981 & June 1982, respectively No noncompliance noted in the series of the seri
- --B2:2210124 IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dtd Nov 1981 & June 1982, respectively Planning stds met PHILLIPS, II P. AXELSON, N. L., PAPERIELLO, C. J. Region 3, Office of Director 82/12/07 29pp 16485 091 24X Fiche 50-237, 82/12/10, 6212210118
- GP12220175 Releases public version of revised generating station emergency plan implementing procedures ELTUR. J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fiche 50-000,82/12/10, 62107-0175
- --U2(2220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 te demand polling of meteorological data & ED-20 re emergency rorecast request PAJONEXE. J E Commonwealth Edison Co 82/11/15 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 1p 16529 030 24(Fiche 50-000, 82/12/10,8212220175
- --G212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKIL A , PAJ
- Util2230019 Releases public version of revised emergency plan implementing procedura FELTON, J M Division of Rules and Records 82/12/15 Document Nanagement Branch 1p 16545-350 24X Fiche 50-010,82/12/15, 0212230019
- U212230028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1. "Quarterly Inventory of First Aid Supplies" SCOTT.D J Commonwealth Edison Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 16545 351 24X Fiche 50-010, 82/12/15,8212230019
 - 0212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-i, "Quarterly Inventory of First Aid Supplies" Revised index encl
 4 Commonwealth Edison Co 82/ii/22 App 1A545 354 24X Ficha 50-010
- Bil 2E20306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site comergency operations facility KEPPLER. J G Region 3. Office of Director Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16. R212220306
- 8:12280214 Forwards IE Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21)
 MILLER, J R Division of Engineering & Technical Programs 82/12/20 REED, C Commonwealth Edison Co 2pp 16562 120 24X
 [-iche 50-010, 82/12/20, 8212280214]

- --8212280220 IE Safeguards Insp Rept 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 100FR73 21) CHRISTOFFER.0 Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010, 82/12/20, 8212280214
- 8212300167 Releases public version of revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000.82/12/20.8212300167
- B212300179 Forwards public version of revised generating station emergency plan telephone directory MOORE.R D Commonwealth Edison Co B2/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000, 82/12/20, 8212300167
- --8212300199 Public version of revised generating station emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 82/11/05 60pp 16612 21/ 244 Fichs 50-000,82/12/20,8212300167

G Adjudicatory correspondence

- 8212070160 Hemorandum & order granting licenses 820818 request to dismiss proceeding w/o prejudice Util received authority to increase spent fuel pool storage capacity making shippent of spent fuel between plants unnocessary JDHNSON,E B., STODER, G.J., MILHOLLIN, G.L. Atomic Safety and Licensing Board Panel BZ/12/03 Commonwealth Edison Co. 4pp. 16336-320 24X Fishe 50-000.82/12/03.8212070160
- H General correspondence
- B212280176 Notifies of change in masling address for NRC licensing matl HRIOHT,0 N Illinois, State of, Dept Nuc Safety (formarly Dept Public Health) B2/12/20 FISENHUT, D & Division of Licensing ip 16556 135 24% Fiche 50-000,82/12/20,8212280176
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B212230277 Forwards, for info, ACRS 821213 ltr to NJ Palladino.
 consisting of ACRS rept on SEP review of plant
 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/14 DELGEORGE.L
 Commonwealth Edison Co 1p 16508 273 24% Fiche 50-237, 82/12/14, 0212230277
- --B212220534 Summarizes ACRS 272nd meeting on 821207-11 re SEP review of facility Review of full term OL will be deferred until actions completed on remaining SEP topics, unresolved safety issues & THI action plan items
 SHENMON.P ACRS Advisory Committee on Reactor Safeguards
 B2/12/13 PALLADINO.N J Commissioners 3pp 14508 274 24X
 Fiche 50-237,82/12/14,8212230227
- P Operating license stage documents & correspondence
- BPILI70509 Forwards SERs referenced in NUREG-0823.App A, "Integrated Plant Safety Assessment Rept for Dresden Nuclear Power Station.Unit 2." for review CRUTCHFIELD.D Operating Reactors Branch 5 82/10/27 BHEWMON.P B ACR8 Advisory Committee on Reactor Safeguards ip 16380 218 24X Fiche 50-237.82/10/27,8211170509
- --B211160015 Forwards for review, draft integrated plant safety assessment rept (NUREG-0823) Rept will be one basis in considering issuance of full-term OL to replace provisional OL MIRAGLIA.F Assistant Director for Gafety Assessment 82/10/29 SHEMMON.P S ACRS Advisory Committee on Reactor Gafeguards Ip 16380 219 24X Fiche 50-237.82/10/29.8211170509
- BP12140001 Addl response to FOIA request for five categories of documents re BEP Forwards documents listed in App A No documents located subj. to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO,J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000,82/11/03,8312140001
- --7906040228 Recommends EG&G perform analyses of recirculation sys,LPC1 suction & seismic test example problem 1 in support of seismic evaluation rept GTEVENSON,J D Woodward-Clyde Consultants, Inc 79/05/25 JABDDUR,K N Division of Operating Reactors 10pp 16435 163 24X Fiche 50-000.82/11/03.8212140001

- --7907100659 Forwards proposed insertion to systematic evaluation program rept Section 2.2 re geology, seismicity & site conditions HALL.N J N M Newmark Consulting Engineering Services NRC-03-78-150 79/07/05 LEVIN.H A . HOFMAYER.C Division of Operating Reactors 3pp 16434-270 24X Fiche 50-000,82/11/0J. 8212140001
- 7907240319 Forwards replacement pages to SEP seismic review evaluation MALL.U J N.M. Newmark Consulting Engineering Services NRC-03-78-150 79/07/20 LEVIN.H A Systematic Evaluation Program Branch (Pre 791030) 3pp 16435 173 24x Fiche 50-000.82/11/03.8212140001
- --/908080624 Forwards Section 4 to be added to Chapter 1 of SEP seismic review evaluation HALLIH J N M Newmark Consulting Engineering Services NRC-03-78-150 79/08/02 LEVIN.H A Systematic Evaluation Program Granch (Pre 791030) 3pp 16435 178 24X Fiche 50-000, 62/11/03.6212140001
- ---/909280656 Summary of 790902 telcon w/NM Newmark & WJ Hall re sgismic evaluation rept CHEN.P Y Systematic Evaluation Program Branch (Pre 791030) 79/08/21 KUG.P F Systematic Evaluation Program Branch (Pre 791030) 2pp 16435-176 24X Fiche 50-000,82/11/03,82(214000)
- 79:1150252 Discusses issuance of SSRT rept Revised computation of furbine design parameters submitted by consultant renders rept inaccurate NRC should make final decision re issuance NEMMARK, N M N N Newmark Consulting Engineering Services 79/11/12 EISENBUT, D G Division of Operating Reactors 2pp 16435 181 24K Fiche 50-000, 82/11/03, 8212140001
- --8002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Gode used for reamalysis of puping sys requires benchmarking per code verification program SMAGLL C Assistant Director for Engineering Programs 79/10/30 EISENHUT, D G Division of Operating Reactors in 14435 III 244 Fiche 30-000.82/11/03.8212140001
- --BOO4010318 Comments on "Seismic Analysis of Reactor Internals," Math supplied in rept useful in defining mass & stiffness characteristics of vessel internals & supports but does not answer design question in NUREO/CR-0891
 STEVENSON: T D Woodward-Clyde Consultants, Inc BO/03/25
 JABBOUR, K N Systematic Evaluation Program Brench 1p
 16434 273 24% Fiche 50-000, 82/11/03, 821/2140001
- --BOOSO70778 Forwards input to SEP Topics III-6 & III-11.consisting of NUREO/CR-0891. "Seismic Review for SEP" & EGG-EA-5065, "Surmary of Piping Calculations Performed for SEP " Repts should be transmitted to licensee NUREO only sincl CRUTCHFIELD.D Systematic Evaluation Program Branch 60/04/14 ZIEMANN,D L Systematic Evaluation Program Branch 2pp 16435 163 24X Fiche 50-000, 82/11/03,8212140001
- --8005070798 "Seismic Review for SEP "
 NEMMARK.N K , HALL.W J , KENNEDY.R P Lawrence Livermore
 Laboratory NUREO/CR-089! 79/07/31 [78pp Available at NTIS
 16435 185 24X Fiche 50-000, 82/11/03, 8212140001
- --8009110797 Forwards excerpt from utils 680801. "Rept to Stockholders," re effect of 680915 tornadaes on util 345 kV sys
 DENTON.H R Atomic Energy Commission 68/08/14 YEDESCO.R L
 Atomic Energy Commission 2pp 16434 254 24X
 Fiche 50-000.82/11/03.8212140001
- 3/11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACSWR, Big Rock Point Dreaden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl W/o stated encl EISENHUT. B G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 9211230066
- 3P12030043 Forwards clarification of util position in areas identified by NRC as not meeting current criteria, per SEP Topic VI-4, "Containment Isolation Sys" RAUSCH.T J Commonwealth Edison CO 82/11/18 O'CONNOR.P Operating Reactors Branch 5 4pp 16304 106 24X Fiche: 50-237, 82/11/18, 8212030043
- P12060207 Submits addi info re SEP Topics III-2, "Wind & Tornado Loadings" & JII-7 B. "Basign Loads.Design Criteria & Loading Combinations."

 RAUSCH.T J Commonwealth Edison Co 82/11/22 O'CONNOR,P Operating Reactors Branch 5 5pp 16312 259 24X Fiche 50-237.82/11/22.8212060207

- 87:12060267 Submits info re SEF Topic III-1, "Quality Group Classification Components & Sys." in response to NRC 820309 | fr Operating temp ranges & thickness of mat] illustrate brittle fracture is of no concern RAUSCH.T J Commonwealth Edison Co 82/11/22 O'CONNOR,P Operating Reactors Branch 5 8pp 16312 310 24x Fische 50-237,82/11/22,8212060267
- Bi:12090301 Advises that capacity discharge test demonstrates ability of battery sys to deliver FSAR required loads & to meet manufacturer rating, per SEP Topic VIII-3 A. "Station Battery Capacity Test Requirements"
 RAUSCH.T.J. Commonwealth Edison to 82/12/03 0'CONNOR.P diperating Reactors Branch 5 2pp 16364 361 24X
 Fiche 50-237.82/12/03.8212090301
- GP12140172 Provides outline re position on 34 open topics summarized in Chapter 4 of integrated assessment RAUSCH. T.J. Commonwealth Edison Co. 82/12/06. O'CONNER, P. Operating Reactors Branch 5. Bpp. 164(0.197. 24X Fiche 50-237, 82/12/06, 8212140172
- B212160326 Forwards Revision 1 to "Secund 10-Yr Inservice Insp & lesting Program. Dresden Units 2 & 3 " Response to NRC questions & comments & procedures for reactor vessel 1.000 psi & ASIME hydrostatic tests & quarterly valve timing encl RAUSCH.T J Commonwealth Edison Co 82/12/10 EISENHUT.D G Division of Licensing 44pp 16441 088 24X Fiche 50-237.82/12/10.0212160326
- --B212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing Program Dresden Units 2 & 3 " + Commonwealth Edison Co 82/12/31 268pp 16441 132 24X Fiche 90-237, 82/12/10, 8212160326
- BP12210036 Responds to NRC concerns re SEP Topic IX-5, "Ventilation bys " ESF ventilation sys adequate following loss of offsite power event RAUSCH, 7 J Commonwealth Edison Co B2/12/13 O'CONNOR, P Operating Reactors Branch 5 7pp 16485 349 24X Fiche 50-237, 82/12/13, 8212210036
- BP12220212 Forwards Revision 22 to CE-1-A, "GA Program for Nuclear Generating Stations"

 WARTZ, ED Commonwealth Edison Co 82/12/14 HAASS, W.P. Quality Assurance Branch 1p 165/8 007 24x Fiche 50-000, 82/12/14, 321220912
- --8212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000,82/12/14.8212220212
- B212230277 Forwards, for info.ACRS 821213 ltr to NJ Palladino, consisting of ACRS rept on SEP review of plant CRUTCHFIELD, D. Operating Reactors Branch 5 82/12/16 DELOEURGF.L. Commonwealth Edison Go 1p 16508 273 24X Fiche 50-237,82/12/16,8212230277
- --8212220534 Summarizes ACRS 272nd meeting on 821209-11 re SEP review of facility Review of full term QL will be deferred until actions completed on remaining SEP topics unresolved safety issues & THI action plan items

 SHEIMON.P ACRS Advisory Committee on Reactor Safeguards
 82/12/13 PALLADINGN J Commissioners 3pp 16508 274 24X
 Fiche 50-237, 82/12/16.8212230277
- 8212280117 Forwards addl info re NUREO-0737. Item II F 1, "Addl Accident Monitoring Instrumentation," per NRC 821109 request Pressure manitoring sys provided w/separate loop for narrow range monitoring SNARTZ.E D Commonwealth Edison Co 82/12/20 EISENHUT.D G Division of Licensing 9pp 16564 062 24X Fiche 50-000.82/12/20, 8212280117
- 8212280343 Forwards addl info re NUREG-0737. Items II F 1 4.5 & 6
 "Containment Pressure, Water Level & Hydrogen Monitoring,"
 per Crutchfield 821109 Itr
 SWARTZ.E D Commonwealth Edison Co 82/12/20 EIBENHUT, D G
 Division of Licensing 9pp 16561 053 24% Fiche 50-000, 82/12/20, 8212280343
- B212290190 Application to amend License DPR-25, revising Tech Specs to allow use of fuel assemblies designed & mfg by Exxon Nuclear Co for ensuing Cycle 9 reload & future reloads RAUSCH, T J Commonwealth Eduson Co 82/12/21 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 18pp 16581 223 24X Fiche 50-237, 82/12/21, 8212290190
- --8212270193 Proposed Tech Specs allowing for use of Exxon Nuclear Co fuel assemblies for ensuing Cycle 9 reload & future reloads * Commonwealth Edison Co 82/12/21 58pp 16581 241 24X Fiche 50-237,82/12/21.8212270190

- G212290199 Revision 1 to "Dresden Unit 2 LOCA Analysis Using EXEM/BWK Evaluation Model MAPLHOR Results " BRAUN.D J. JENSEN.S E. KAYER.W V Exxon Nuclear Co., Inc. (subs of Exxon Corp.) XM-NF-82-8B ROI 82/12/02 20pp 14381 300 24X Fiche 50-237.82/12/21.8212290190
- ~-8212290205 Nonproprietary version of Revision 1 to "Plant Transient Analysis for Dresden Unit 2.Cycle 9" MELLEY.R H , COOKE.G C STOUT.R B Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-NF-82-84(NP) R01 82/12/07 42pp 16581 321 24X Fiche 50-237.82/12/21,8212290190
- ~-B212290215 Nonproprietary version of Revision 1 to "Dresden Unit d' Cycle 9 Reload Analysis " CHANGLER.J C. STOUT.R D. NILLIAMSON,H E Exton Nuclear Co., Inc (subs of Exton Corp.) XXI-NF-82-7/(NP) RO1 82/12/06 33pp 14582
- 8;'12280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment SMARTZ.E D Commonwealth Edison Co 82/12/22 EISENHUT. D 9 Division of Licensing 18pp 16556 161 24X Fiche 50-000.82/12/22, B21280212
- 8:'12280263 Clarifies position on rlassification of major mods to BWR Mark 1 Containment per 821216 ltr RAUSCH.T J Commonwealth Edison Co 82/12/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14561 307 24X [iche 50-000, 82/12/22,8212280263]
- G. Inspection reports, IE Bulletins & correspondence
- BP:08190240 IE Builetin 82-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants "Syc list encl DE:70UNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- BPOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters " Syc list enc!

 COBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 140372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Livercise Requirements" Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8P08190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl BEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- --0212060045 Responds to NRC 020928 ltr re violations noted in IE Insp Repts 50-010/82-13,50-237/82-17 & 50-249/82-18 Corrective actions inservice leak test performed on water leg portion of torus level mod Training session scheduled DELOCORRIL O Commonwealth Edison Co 82/10/28 KEPPLER, J O Region 3, Office of Director 3pp 16313 285 24X Fishe 50-010,82/11/26,8212060036
- GF12170300 Forwards IE Inap Repts 50-010/82-19,50-237/82-24 & 50-249/82-26 on 621104-05 No noncompliance noted LITTLE N 9 Division of Engineering & Technical Programs 62/11/29 REED. C Commonwealth Edison Co 2pp 16453 206 24X Fische 50-010,82/11/29,8212170300
- --B212170306 IE Insp Repts 50-010/82-19,50-237/82-26 & 50-249/82-26 on G21104-05 No noncompliance noted Major areas inspected licensee actions on previously identified items REIMANN,F W. JACKIW,I N. Division of Engineering & Technical Programs 62/11/24 4pp 16453 208 24X Fiche 50-010,82/11/29,8212170300
- B./OB190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radigactive Mat] " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards G2/11/30 Consolidated Edison Co of New York, Inc 356pp 16307 028 24X Fiche 50-000,82/11/30,8208190257

- BP12030178 Forwards final SALP Repts 50-010/B2-10, 50-237/B2-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981, discussed at IE mgt meeting on 820602 Util 820418 comments on SALP rept addressed KEPPLER.J O Region 3. Office of Director 82/12/01 REED.C Commonwealth Edison Co 3pp 16303 228 24% Fiche 50-010.B2/12/01, B212030178
- --B212030185 SALP Repts 50-010/82-10.50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981 Mgt attention warranted in areas of plant operations, radiological controls & review committee activities

 * Region 3, Office of Director 82/05/31 47pp 16303 231 24X Fiche 50-010, 82/12/01.8212030178
- B2:1206:029 Forwards response to IE Bulletin B2-03 re stress carrosian cracking in thick wall, large diameter stainless steel recirculation sys piping at BWRs Dresden response only addresses Item 4 Other Info will be provided by startup RAUSCH, T J Commonwealth Edison Co 82/12/01 KEPFLER. J O Region 3. Office of Director 10pp 16313 288 24% Fiche 50-000.82/12/01, 8212060029
- 8:12080837 Forwards response to Revision I to IE Bulletin 82-03 re stress corrosion cracking in thick-wall, large diameter stainless steel rectrculation sys piping Addl info for Dresden 2 due prior to startup from Spring 1963 outage RAUSCH, T J Commonwealth Edison Co 82/12/01 KEPPLER, J Q Region 3, Office of Director 10pp 16352 086 24% Fiche 50-000,82/12/01,8212080537
- 8POB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Liectrical Penetration Assemblies " Svc list encl DEYBUNDOR C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JDRDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 04X Fiche 50-000,82/12/03.8208190261
- 8212170196 Forwards IE Insp Repts 50-010/82-18,50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/12/03 REED. C Commonwealth Edison Co 2pp 16450 153 24X fiche 50-010,82/12/03.82121/0196
- 8212170201 IE Insp Repts 50-010/82-18.50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted Major areas inspected headquarters & regional requests operational safety verification, monthly maint observation & LERs TONQUE, T M , STABEK, S , WALKER, R D Division of Project & Resident Programs 82/12/01 8pp 16450 155 24X Fiche 50-010.82/12/03, 8212170196
- BP12160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp & Testing Program, Dresden Units 2 & 3 " Response to NRC questions & comments & procedures for reactor vessel 1,000 psi & ASME hydrostatic tests & quarterly valve timing encl RAUBCH, T J Commonwealth Edison Co 92/12/10 EISENHUT, D 0 Division of Licensing 44pp 16441 088 24X Fiche 50-237,82/12/10,82/12/10/326
- --B212160334 Revision 1 to "Second 10-Yr Inservice Insp & Testing Program Dresden Units 2 & 3 " * Commonwealth Edison Co B2/12/31 268pp 16441 132 24X Fiche 50-237, B2/12/10, 8212160326
- 8212210118 Forwards IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 during Nov 1981 & June 1982, respectively No noncompliance noted HIND, J A Division of Emergency Preparedness 82/12/10 REED, C Commonwealth Edison Co 2pp 16485 088 24X Fiche 50-237, 82/12/10, 6212210118
- --8212210124 IE Emergency Preparedness BERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex ded Nov 1981 & June 1982, respectively Planning stds met PHILLIPS.H P , AXELSON.W L. , PAPERIELLO.C J Region 3, Office of Director 82/12/07 29pp 16485 091 24X Fiche 50-237, 82/12/10, 8212210118
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Syc list encl DEYOUNG:R C Director's Office of Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York

- 8212270295 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/82-21, 50-249/82-27, 50-25/82-17 & 50-265/82-19
 NORELIUS, C E Division of Engineering & Technical Programs
 82/12/16 REED, C Commonwealth Edison Co 2pp 16530 085 24X
 Fiche 50-000, 82/12/16, 8212270295
- --8212270303 Responds to NRC 821026 ltr re violations noted in IE Insp. Repts 50-237/82-21.30-249/82-22.50-254/82-17 & 50-265/82-19 Corrective actions annual audits of all active AE firms performing safety-related work required DELOGORAGE.L O Commonwealth Edison Co. 82/11/24 KEPPLER.J G Region 3. Office of Director 4pp. 16530 087 24X Fiche 50-000.82/12/16.8212270295
- ---8212270307 "EDS-NUTECH Interface Control Instructions," Revision 0 T8CHUDI,W F NUTECH (Nuclear Technology, Inc.) 82/07/30 22pp 16530 091 24X Fiche 50--000, 82/12/16,8212270295
- 8212270313 "IE Bulletin 79-14 & TAP Piping Evaluation. Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision 0 * NUTECH (Nuclear Technology, Inc.) 82/10/01 9pp 14530 113 24% Fiche 50-000.82/12/16.8212270295
- 8212280110 Provides final status rept of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Complete & final listings of portions of sys failing to meet FAAR requirements under NUFECH responsibility encl RAUSCH.T J Commonwealth Edison Co 82/12/17 KEPPLER.J Q Region 3. Office of Director 3pp 14564 191 24X Fiche 50-000.82/12/17, 8212280110
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24) Fiche 50-Q00.62/12/20.8208190268
- B212280214 Forwards IE Safeguards Insp Repts 50-010/B2-20, 50-237/B2-28 & 50-249/B2-29 on B211(5-19 Details & notice of violation withheld (ref 10CFR73 21)
 MILLER, J R Division of Engineering & Technical Programs 92/12/20
 REED, C Commonwealth Edison Co 2pp 16562 120 24X
 Fiche 50-010, B2/12/20, B212280214
- --B212280220 IE Safeguards Insp Repts 50-010/B2-20, 50-237/B2-28 & 50-249/B2-29 on B21115-19 Noncompliance noted failure to adequately control security-related key as required by security plan. Debails withheld (ref 10CFR73 21) CHRISTOFFER.0 , KNICELEY, JR , CREED, JR Division of Emergency Preparedness & Operational Support B2/12/15 2pp 16562 122 24X Fiche 50-010,82/12/20,8212280214
- 8P12280070 Requests addition of RE Farrell to unescorted access list to vital & protected areas individual passesses Q clearance KEPPLER.J @ Region 3. Office of Director 82/12/22 REED. C Commonwealth Edition Co 1p 16969 136 24% Fiche 50-010.82/12/22, 82(2280070
- R Periodic operating reports & related correspondence
- 8212140077 "1982 Evaluation, Drosden Nuclear Power Station, Comm Ed Co "
 * Institute of Nuclear Power Operations 82/11/30 39pp
 16403 171 24X Fishe 50-010.82/11/30.8212140077
- B212140112 Forwards monthly operating repts for Nov 1982 BCGTT.D J Commonwealth Editon Co B2/12/01. Director's Office, Office of Inspection and Enforcement ip 16408 204 24X Fiche 50-010. B2/12/01.8212140112
- ---8212140120 Monthly operating repts for Nov 1982 SCHRUEDER.B A Commonwealth Edison Co 82/12/01 28pp 16408 205 24X Fiche 50-010.82/12/01.8212140112
- S Reportable occurrences, LERs & related correspondence
- 8212290344 Forwards updated LER 82-036/03X-1 8CUTT.D J Commonwealth Edison Co 82/11/16 KEPPLER, J Q Region 3. Office of Director. ip 16586 217 24X Fiche 50-237, 82/11/16, 8212290344
- --B212290345 Updated LER 82-036/03X-1 on B20723, during normal startup, gain adjustment factor for average power range monitors 2 & 3 exceeded 1 02 Gaused by procedural deficiencies Average power range monitor gain adjusted SCHROEDER: B A Commonwealth Edison Co 82/11/16 Region 3, Office of Director 2pp 16586 218 24X Fiche 50-237,82/11/16, B212290344

- 82:2290398 Forwards updated LER 82-037/03X-1 SCOTT.D J Commonwealth Edison Co 82/11/22 KEPPLER, J G Region 3. Orfice of Director 1p 16586 347 24X Fiche 50-237,82/11/22, 82:2294398
- --8212290409 Up dated LER 82-037/03X-1 on 820724, during final hours of 12-h zenon soak period, average power range monitor (APRM) gain adjustment factor for APRM 4 & exceeded 1 02 Caused by procedural deficiency Procedures will be modified SCHRDEDER. B A Commonwealth Edison Co 82/11/22 Region 3. Office of Director 2pp 16586 348 24X Fichs 50-237, 82/11/22, 8212290398
- G212020275 Forwards updated LER 82~042/01X-1 SCOTT, D J Commonwealth Edison Co 82/11/24 KEPPLER.J G Region 3. Office of Director 1p 16288 350 24X Fiche 50~237.82/11/24, 8212020275
- --B212020280 Updated LER 82-042/01X-1 on 821002, during normal operation, following torus hi/lo level alarm, sightglass isolation & vent valves reported open w/nn indication of excess makeup Caused by operator error Valves locked closed HOLLAND, P Commonwealth Edison Co 82/11/24 Region 3, Office of Director 2pp 16288 351 24X Fiche 50-237,82/11/24, 8212020275
- BP12100215 Forwards LER 82-046/03L-0 SCOTT.D J Commonwealth Edison Co 82/11/24 KEPPLER, J Q Region 3. Office of Director ip 16376 074 24X Fiche 50-237, 82/11/24, 82/12100215
- --B2121002i6 LER B2-046/03L-O on B21109.during normal operation.high range boron test for standby liquid control.DCP 1100-4, revealed boron concentration below Tech Specs Caused by inadequate procedure for sys leakage Procedure revised COYLE.L Commonwealth Edison Co 82/11/24 Region 3, Office of Director 19 16376 075 24X Fiche 50-237.62/11/24.8212100215
- 8212100312 Forwards LER 82-045/03L-0 SCOTT.B J Commonwealth Edison Co 82/12/01 KEPPLER.J 0 Region 3. Office of Director 1p 16376 274 24% Fiche 50-237.82/12/01. 8212100312
- 8212100319 LER 82-045/03L-O on 821106 during load reduction all AGAF found greater than 1 02 Caused by substantial fraction of rated power change associated w/rapid changes in Fesdwater flow Dain adjustments made to average power range monitors BEVERLY. K Commonwealth Edison Co 82/12/02 Region 3, Office of Director 1p 16376 275 24X Fiche 50-237,82/12/01, 8212100312
- GP12170122 Forwards LER 82-044/03L-0 SCOTT.D J Commonwealth Edison Co 82/12/03 KEPPLEP.J Q Region 3. Office of Director 1p 16453 001 24X Fiche 50-237.82/12/03. 82/12/70122
- --B212170130 LER 82-044/03L-O on 821107.2/3 diesel generator trouble alarm annunciated in control room due to lubricating oil pump being off & tripped breaker Caused by bad bearing in lubricating oil pump mutor Deviation rept enci RMEE.5 J Commonwealth Edison Co 82/12/03 Region 3, Office of Director 2pp 16453 002 24X Fiche 50-237,62/12/03,821270122
- B212090415 PNO-JII-82-132 on 821203. Discusse declared alert when level of flood-swollen IL River threatened svc water pumps & diesel fire pumps inside crib house Shutdown initiated Alert canceled on 821204 Units returned to power on 821205 WALKER.R, TONGUE.T. SPESSARD.R Region 3, Office of Director 82/12/06 1p 16365 032. 24% Fishe 50-237,82/12/06.8212090415
- BP12210157 Forwards LER 82-047/03L-0 SCOTT.D J Commonwealth Edison Co 82/12/06 KEPPLER.J 0 Region 3- Office of Director ip 16484 313 24% Fiche 50-237.82/12/06. B212210157
- --B212210160 LER 82-047/OGL-O on 821117, while performing DIS 5003, reactor vessel low water level ECCS initiation, LIS 263-72A found set at 11.6 inches delta P Caused by defective procedure LIS 263-72A reset & setpoints revised COYLE, L M Commonwealth Edison Co 82/12/O6 Region 3, Office of Director ip 16484 314 24X Fiche 50-237, 82/12/O6, 8212210157
- G212280472 Forwards LER 62-050/01T-0 SCOTT.D J Commonwealth Edison Co 82/12/13 KEPPLER.J G Region 3. Office of Director ip 16556 023 24X Fiche 50-237.62/12/13, 6212280472

- --8212289479 LER 82-050/01T-C on 821203, during cribhouse insp. discovered intake water level at 509 ft 2 inches Caused by rising river level from heavy rainfall later level rose to 509 ft 6 inches before receding CHRISTEL. B Commonwealth Edison Ca 82/12/13 Region 3, Office of Director 2pp 16556 024 24X Fiche 50~237,82/12/13,821220137
- B212220207 PMD-III-B2-136 on B21216,male employee found dead on fourth level or reactor blig No radioactive contamination detected Radiation levels measured less than 5 m/h Investigation underway
 TOMOUS, T , WALKER, R , STREETER, J Region 3, Office of Director B2/12/16 1p 16518 331 24X Fiche 50-237, B2/12/16, B212220207
- 1 Hearing transcripts on non-antitrust matters
- 8212020258 Transcript of ACRS Subcommittee on SEP 821130 meeting in Washington DC Pg 1-257 Supporting documentation encl * ACRS Advisory Committee on Reactor 9afeguards 82/11/30 359pp 16276 266 24X Fiche 50-000, 82/11/30, 8212020258

DOCKET 50-243 OREOON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

- 8:12150248 Releases public version of corrected pages to emergency response plan FLTCM. J M Division of Rules and Records 82/12/07 Document Management Branch ip 16446 292 24X Fiche 50-243.82/12/07.6212150248
- --B212150252 Forwards public version of corrected pages to 821103 emergency response plan WANO.C H Ohio State Univ 82/11/27 Office of Nuclear Reactor Regulation, Director 1p 16446 295 24X Fiche 50-243,82/12/07, 8213-180268
- -- 8212150257 Public version of corrected pages to 821103 emergency response plan * Dhio State Univ 82/11/27 App 16446 296 24X Fishe 30-243,82/12/07,8212150248
- @ Inspection reports, IE Bulletins & correspondence
- 8212050173 Forwards IE Insp Rept 50-243/82-03 on 821019-21 No noncompliance noted STERHBERG.D M Division of Resident, Reactor Project & Engineering Programs 82/11/12 WANG.C H Oregon State Univ 4pp 16313 078 24X Fiche 50-243,82/11/12,8212060173
- --8212040178 IE Insp Rept 50-243/82-03 on 821019-21 No noncompliance noted Major areas inspected logs & records, review & audit procedures, requalification training, surveillance, experiments & miscellaneous independent insp effort WILLETT, D J , DODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/10 9pp 16313 082 24X Fitche 50-243,82/11/12,8212060173

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

- 8212020271 Requests that next full-scale emergency exercise per IOCFRSO App E be held no later than 830630 due to prior co-mitments of NRC FEMA & State of NY to support exercises at other facilities MAIER J E Rochester Gas & Electric Corp 82/11/18 CRUTCHFIELD, D Openating Reactors Branch 5 p 16288 250 24X Fiche 50-244, 82/11/18, 8212020271
- 8P12030035 Forwards IE Safeguards Insp Rept 50-244/82-20 on 820927-30 No noncompliance noted MARTIN,T T Division of Engineering & Technical Programs 82/11/18 MAIER,J E Rochester Gas & Electric Corp 2pp 16304 122 24X Fiche 50-244, 82/11/18, 8212030035
- --B212030038 IE Safeguards Insp Rept 50-244/82-20 on 820927-30 No noncompliance noted Major areas inspected security plan & procedure implementation, security organization & security sys power supply Security info deleted (ref 10CFR73 21) OULLAP.J M., BAILEY, R.J., GODY.A.T. Region 1, Office of Director 82/11/15 4pp 16304 124 24X Fiche 50-244,82/11/18,8212030035
- BRI2070094 Forwards application for amend to License DPR-18 & proposed Tech Specs re audits of emergency plan & security plan MAIER, J. E. Rochester Gas & Electric Corp. 82/12/01 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director 1p. 16327-356 24X Fiche 50-244, 82/12/01, 8212070094

- --B212070095 Application for amend to License DPR-IB re audits of emergency plan & security plan MAIER.JE Rothester Gas & Electric Corp B2/12/01 Jpp 14327 357 24% Fiche 50-244/82/12/01/B212070094
- --8212070098 Proposed Tech Spec Page 6 5-9 re audit of emergency & security plan audits Safety evaluation encl # Rochester Ges & Electric Corp 82/12/01 2pp 16327 360 24X Fiche 50-244.82/12/01.82120770094
- 8212140240 Notifies that emergency operations facility located 18 miles from site No backup facility required No interim facility used before establishing permanent facilities MAIER.J E Rochester Gas & Electric Corp 82/12/07 CRUTCHFIELD.D Operating Reactors Branch 5 lp 14407 299 24X Fichs 50-244.82/12/07.8212140240
- B212290375 Forwards IE Bafeguards Insp Rept 50-R44/82-23 on B2]libi-19 k notice of violation MARTIN.T T Division of Engineering & Technical Programs B2/12/13 MAIER.JE Rochester Gas & Electric Corp 2pp 16586-352 24X Fiche 80-244, B2/12/13, B122990375
- --0212270377 Notice of violation from insp on 821116-17 * Division of Engineering & Technical Programs 82/12/13 Ip 16586 354 24X Fiche 50-244, 82/12/13,8212270375
- --B212270383 IE Safeguards Imsp Rept 50-244/82-23 on 821116-19
 Noncompliance noted failure to conduct physical inventuries
 of SNM at less than 12-month intervals & failure to follow
 physical inventory instructions
 DELLA RATTA. A., ODDY. A T. Region 1. Office of Director 82/12/08
 6pp 16586-355 24X Fishe 50-244-82/12/13.8212270375
- J Insurance & indomnity information
- 8212280258 Forwards Endorsements 1,2 & 3 to NELlA Certificate N-14 & MAELU Certificate M-14 SINIBI,J M Harsh & HoLennan, Inc. M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN,J Assistant Director for State & Licensee Relations 19p 16561 250 24X Fiche 50-244,82/12/21,8212280288
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 82:12010502 Summary of 265th ACR8 meeting on 820506-08 in Washington, DC re Ginna restart safety evaluation. Wolf Creek CL review. Palisades BEP review.mergency response capability of plants & safety-related equipment qualification program * ACR8 Advisory Committee on Reactor Safeguards 82/11/26 ACR8 Advisory Committee on Reactor Safeguards 605pp 16294 131 24% Fiche 50-000, 82/11/26, 8212010502
- P Operating license stage documents & correspondence
- 8212140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON. J M Division of Rules and Records 82/11/03 GALLO. J 1sham. Lincoln & Beale 2pp 16433 354 24X Fiche 50-000.82/11/03, 8212140001
- --7909180332 Forward minutes of 790830 meeting w/util in Reading,PA re seismic analysis modeling NELEON:TA Laurence Livermore Laboratory 79/09/12 LEVIN:H Systematic Evaluation Program Branch (Pre 791030) 4pp 16436 016 24X Fiche 50-000:82/11/03:8212140001
- --G002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program.

 EHAO, L. C. Assistant Director for Engineering Programs 79/10/30 EISENHUT, D. O. Division of Operating Reactors ip 16435 111 24X Fiche 50-000,82/11/03.8212140001
- --8[12270035 Summary of 810907 maeting w/util re SEP seismic review List of attendees and CHENG.TM Systematic Evaluation Program Branch 81/12/14 RUSSELL.W T Systematic Evaluation Program Branch 4pp 16436 020 24X Fiche 50-000, 82/11/03.8212140001

- 8212070074 Forwards application for amend to License DPR-18 & proposed Tech Specs to audits of emergency plan & security plan MAIER.J E Rochester Gas & Electric Corp 82/12/01 DENTON.H R Uffice of Nuclear Reactor Regulation. Director 1p 16327 356 24x Fiche 50-244.82/12/01.8212070074
- --8212070075 Application for amend to License DPR-18 re audits of emergency plan & security plan HAIER, J E Rochester Gas & Electric Corp 82/12/01 3pp 16327 367 24K Fiche 50-244, 82/12/01,8212070094
- --0212070078 Proposed Tech Spec Page 6 5-9 re audit of emergency & security plan audits Safety evaluation enc!
 * Rochester Gas & Electric Corp 82/12/01 2pp 16327 360 24X
 Fiche 50-244.82/12/01.8212070094
- G212070282 Notifies that response to 621026 Generic Ltr 82-22, "Congressional Request for Info re Steam Generator Tube Integrity," will not be provided Info necessary to respond to issue not readily available MAIER J E Rochester Gas & Electric Corp 62/12/01 CRUTCHFIELD.D Operating Reactors Branch 5 1p 16343 194 24X Fiche 50-244,62/12/01,62/2070282
- B212080384 Advises of expected completion dates for TMI Items II B 2 re radwaste remote control sys. II B 3 re post-accident sampling sys. II D 1 re safety & relief valve testing & III D 3 4 re control room HVAC mods
 MAIER. J E Rochester Gas & Electric Corp 82/12/02 CRUTCHFIELD. D
 Operating Reactors Branch 5 3pp 16352 286 24X
 Fiche 50-244.82/12/02.8212080384
- 8212140404 Forwards application to amend the conse DPR-18, revising App A Tech Specs to clarify requirements for heatup & cooldown per analysis of reactor vessel surveillance capsule T Amend fee encl HAIER. J E Rochester Gas & Electric Corp 82/12/08 DENTAN, H R Dffice of Nuclear Reactor Regulation. Director ip 16403-214 24X Fiche 50-244.82/12/08.8212140404
- --B212140408 Application to amend License DPR-18.clarifying & revising App A Tech Spec requirements for heatup & cooldown per analysis of reactor vessel surveillance capsule T MALERJ E Rochester Cas & Electric Corp 82/12/08 2pp 16403 215 24% Fiche 50-244, 82/12/08,8212140404
- --B212140413 Proposed App A Tech Spec changes to clarify requirements for heatup & cooldown requirements replacing Pages 3 1-5, 3 1-6, 3 1-7, 3 1-12, 3 1-13, 3 1-14 & 4 3-1 4 Rochester Gas & Electric Corp 82/12/08 9pp 16403 218 24x fiche 50-244,82/12/08,8212140404
- --B212140420 "Analysis of Capsule T From Rochester Gas & Electric Corp, RE Ofine Nuclear Plant.Reactor Vessel Radiation Surveillance Program"

 YANICHKO.S E , ANDERSON.S L , SHOGAN.R P Hestinghouse Electric Corp HCAP-10066 82/04/30 83p 16403 226 24X Fiche 50-244,82/12/08.8212140404
- 8208190263 Generic Ltr 92-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of itr Bvc list encl EISEN-MUT.D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York Inc 29pp 16529 247 24X Fiche 50-000, 82/12/09, 8208190263
- G212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear Gne. Unit 2 & San Onefre 2 & 3) re inadequate core cooling instrumentation sys Svc list enc! EISENHUT.D O Division of Licensing 82/12/10 Yanker Atomic Electric Co 27pp 16690 035 24X Ficha 50-000.82/12/10.82/12/10/03
- B212200008 Forwards SER & proprietary & nonproprietary technical evaluation repts re environ qualification of safety-related slectrical equipment Plans for qualification or reglacement of equipment in Categories I B. II A & II B requested CRUTCHFIELD.D Operating Reactors Branch 5 B2/12/13 MAIER.J E Rockester Oas & Electric Corp 3pp 24x Fiche 50-244,82/12/13,8212200008
- --8212200013 SER re environ qualification of safety-related electrical equipment Add1 info on qualification or replacement of equipment in Catagories I.B.II A & II B required 4 Office of Nuclear Reactor Regulation, Director 82/12/13 5pp 16476 044 24X Fiche 50-244,82/12/13,8212200008

- --8207010149 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60)," technical evaluation rept CRANE, C J Franklin Institute/Franklin Research Center NRC 03-79-118 TER-05257-454 82/05/28 LE.N B , SHEMANSKI.P NRC No Detailed Affiliation Given 475pp 16476 049 24x Fiche 50-244,82/12/13,8212200008
- B212210372 Forwards BER supporting resolution of NUREG-0737, Items II E 4 2 6, "Operable Valves or if Closed Must be Scaled Closed" & II E 4 2 7, "Primary Containment High Radiation to Close Vent & Purge Valves" CRUTCHFIELD, D Operating Reactors Branch 5 82/12/15 MAIER, J E Rochester Gas & Electric Corp App 16474 274 24% Fiche 50-244, 82/12/15, 8212210392
- 8212210456 Forwards "Reactor Containment Bidg Integrated Leak Rate Test May 1982 " Facility within Tech Spec limits MAIRR J E Rochester Cas & Electric Corp 82/12/15 CRUTCHFIELD D Operating Reactors Branch 5 1p 16489 209 24X Fiche 50-244, 82/12/15, 8212210456
- --8212210461 "Reactor Containment Bldg Integrated Leak Rate Test.May 1982" * 011bert/Commonwealth Cos 82/12/15 75pp 16489 210 24X Fiche 50-244.82/12/15.8212210456
- 8P12220243 Advises that Exxon Nuclear Co rept re upper plenum injection will be submitted by mid-Feb 1983 Only Exxon fuel will be in reactor until Epring 1984 outage Westinghouse fuel response will be answered as part of 1984 fuel reload MAIER-J E Rochester Gas & Electric Corp 82/12/15 CRUTCHFIELD.D Operating Reactors Branch 5 ip 14518 328 24X Fiche 50-244, 82/12/15, 8212220243
- 8212280388 Forwards Revision 3 to QA manual describing inservice pump & valve testing program for Jan 1981-Dec 1990 Revision provides clarification & changes re pump test frequency & performance parameters
 MAIER J E Rochester Gas & Electric Corp 82/12/25 CRUTCHFIELD.D
 Operating Reactors Branch 5 2pp 16539 041 24X
 Fiche 50-244,82/12/21,8212280388
- --8212280391 Revision 3 to GA manual re inservice pump & valve testing program for Jan 1981-Dec 1990 ANDERSON.C R Rochester Gas & Electric Corp 82/12/21 35pp 16557 043 24% Fichø 50-244,82/12/21.8212280388
- @ Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 62/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Ficha 50-000.82/11/05.8208190245
- 8208190851 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 197 24X Fiche 50-000, 82/11/18,8208190251
- 8212030035 Forwards IE Bafeguards Insp Rept 50-244/82-20 on 820727-30 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs, 82/11/18 HAIER: JE Rochester Gas & Electric Corp 2pp 16304 122 24X Fiche 50-244.82/11/18.8212030035
- --8212030038 IE Safeguards Insp Rept 50-244/82-20 on 820927-30 No noncompliance noted Major areas inspected security plan & procedure implementation, security organization & security sys power supply Security into deleted (ref 10CFR73 21) DUNLAR, J M , BAILEY, R J , GODY, A T Region 1, Office of Director 82/11/15 4pp 16304 124 24% Fiche 50-244, 82/11/19, 8212030035
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Evc list encl DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 82/11/24 Consolidated Edison Co of New York, In 127pp 16411 045 24X Fiche 50-000.82/11/26.8208190256

- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16987 028 24% Fiche 50-000.82/11/30.8208190257
- 88'08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Llectrical Penetration Assemblies " Svc list encl DEYGUNO, R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 1641: 317 247 Fiche 50-000, 82/12/03, 8208190259
- 8POB190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JURDANE L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24) Fiche 50-000.82/12/03.8208190261
- G212220350 Forwards IE Insp Rept 50-244/82-19 on 820927-1001 & notice of violation
 MARTIN T T Division of Engineering & Technical Programs 82/12/07
 MARER.J E Rochester Gas & Electric Corp 2pp 16517 153 24X
 Fiche 50-244
- --8212220354 Notice of violation from insp on 820727-1001 * Division of Engineering & Tachnical Programs 82/12/07 ip 16517 155 24X Fiche 50-244,82/12/07,8212220350
- --8212220358 IE Insp Rept 50-244/82-19 on 820927-1001 Noncompliance noted failure to provide for egress from high radiation areas per 10CFR20 203(c)(5)
 CCLLINS,D J. SHANBAKY,M Region 1, Office of Director 82/12/06
 8pp 16517 156 24X Fiche 50-244,82/12/07,8212220350
- GP12290375 Forwards IE Safeguards Insp Rept 50-244/82-23 on B21116-19 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 82/12/13 MAIGR.J E Rochester Gas & Electric Corp 2pp 16586 352 24X Fiche 50-244,82/12/13,8212290375
- --8212270377 Notice of violation from insp on 821116-19 * Division of Engineering & Technical Programs 82/12/13 lp 16586 354 24X Ficha 50-244,82/12/13,8212270375
- --B212290383 IE Safeguards Insp Rept 50-244/82-23 on 821116-19
 Noncompliance noted failure to conduct physical inventories
 of SNM at less than 12-month intervals & failure to follow
 physical inventory instructions
 DELLA RATTA, A., GDDY, A. T. Region 1. Office of Director 82/12/01
 App 16584, 355 24K Fiche 50-244, 82/12/13, 8212290375
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24x Fiche 50-000, 82/12/16, 8208190267
- 62:12220451 Forwards listing of topic areas for discussion at Region 1/ licenses meeting on drug & alcohol abuse programs per IE linfo Notice 82-05 & NUREG-0903 M/o NUREG STARGSTECKI, R Division of Project & Resident Programs 82/12/16 MAIER, J E Rochester Gas & Electric Corp 3pp 16504 277 24X Fiche 50-244, 62/12/16.8212220451
- 8208170268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list enc: JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24% Fiche 50-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- BP12270163 Forwards monthly operating rept for Oct 1782 BNOW, B.A. Rochester Oas & Electric Corp. 82/11/05 Office of Resource Management. Director 1p 16582 197 24X Fiche 50-244, 82/11/05, 8212270163
- --8212290166 Monthly operating rept for Oct 1982 MCNAMARA:A E Rochester Gas & Electric Corp 82/11/05 5pp 16582 198 24X Fiche 50-244,82/11/05,8212290163
- S Repartable occurrences, LERs & related correspondence
- 9212270066 FOIA request for SECY-92-5B, "Media Attention to Preliminary Evaluation of Operator Actions During Ginna Event 1982 " KING, A P United Kingdom 82/10/20 Office of Administration 1p 16553 160 24X Fiche 50-244,82/10/20,8212270066

- 8212290095 FOIA request for seven categories of info Documents will be Used in PSC Case 281666 on behalf of Rochester Gas & Electric Corp ratepayers re 820125 accident at facility Waiver of fees requested SCHLISSELID A New York, State of 82/11/01 FELTON.J Division of Rules and Racords 4pp 16607 235 24X Fiche 50-244,82/11/01. 6212290055
- 8212060169 Forwards LER 92-026/03L-0 MAIER.J E Rochester Gas & Electric Corp 82/11/24 HAYNES,R C Region 1. Office of Director 1p 16313 088 24% Fiche 50-244, 82/11/24, 8212060169
- --8212060175 LER B2-026/03L-0 on B21026, during performance of PT-3. containment spray sys periodic test.check valve 8620 failed to close promptly Cause not stated Maint performed on valve & retest indicated acceptable performance BODINE, J C Rochester Gas & Electric Corp 82/11/24 Region 1, Office of Director 1p 16313 089 24X Fiche 50-244,82/11/24,8212060169
- 8712270062 Responds to FOIA request for SECY-82-58, "Media Attention to Preliminary Evaluation of Operator Actions During Ginna Event 1982" Documents available in PDR FELTON J H Division of Rules and Records 82/11/26 KING, A P United Kingdom ip 16553 159 24X Fiche 50-244,82/11/26. B212270062
- S212290060 Partial response to FOIA request for saven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl FELTON. J M Division of Rules and Records 82/11/30 SCHLISSEL.D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060
- --B212270065 Forwards SER input (Task 82-05) re steam generator math accountability controls at facility Hath accountability controls used during 1982 steam generator mode included major improvements over controls used in 1975 STARGSTECKI, R. Division of Project & Resident Programs 82/05/19 EISE(HUT) D. O. Division of Licensing Spp 16607 257 24X Fiche 50-000,82/11/30.8212270060
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT !

 F Security, medical, emergency & fire protection plans
- BR12070124 Forwards proposal for revision to modified amended security plan Proposal withheld (ref 10CFR73 21) COUNSIL.W 0. WERNER, R.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W 0. Northeast Utilities B2/11/18 CLARK.R A. Operating Reactors Branch 3. CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 16329-341. 24X Fiche 50-245,82/11/18, B212070124
- 8212090114 Responds to Generic Ltr 82-25 rs BNL request for assistance in field testing new measurement equipment & inventory techniques developed to aid in strengthening IAEA safeguards Addi info available should be sent expeditiously COUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/30 EISENBUT.D O Division of Licensing Ip 16957 272 24X Fiche 50-000.82/11/30,8212090114
- 82/12210576 Releases public version of revision to emergency plan FELTON.J M Division of Rules and Records 92/12/10 Document Management Branch ip 16543 014 24X Fiche 50-245,82/12/10.
- ~~B212210579 Forwards public version of Revision 10 to emergency plan ST PIERRE, M Northeast Nuclear Energy Co Csubs of Northeast Utilities) B2/12/13 EIGENHUT, D @ Division of Licensing 1p 14543 015 24X Fichs 50-245, 82/12/10,8212210576
- --8212210581 Public version of Revision 10 to emergency plan * Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 200pp 16543 016 24X Fiche 50-245.82/12/10, 8212210576
- J Insurance & indemnity information
- 8212280063 Forwards Endorsement 83 to NELIA Policy NF-173 & Endorsement 75 to HAELU Policy MF-52 BINISI, J M Karsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/12/21 SALTZMAN, J D Assistant Director for State & Licensee Relations Spp 16564 276 24X Fiche 50-245,82/12/21,8212880063

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8212230287 Forwards P Shawmon 821213 ltr re ACRS rept on SEP Phase II review CRUTCHFIELD.D Operating Reactors Branch 5 82/12/16 COUNSIL.V Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 16511 120 24% Fiche 50-245.82/12/16.8212230287 COUNSIL.W G
- --8212220544 Summarizes ACRS 272nd meeting on 621209-11 re SEP review of Facility
 SHEWHON,P ACRS - Advisory Committee on Reactor Safeguards
 82/12/13 PALLADING:N J Commissioners 3pp 16511 121 24X
 Fichs 50-245.82/12/16.8212/230287
- P Operating license stage documents & correspondence
- BP110B0297 Forwards four oversize drawings & info re reactor protection sys power monitoring sys design mod Proposed changes to Tach Specs will be submitted w/Cycle 9 reload package on B20901 Aperture cards are available in PDR COUNSIL, W 0 . MERNERIR P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W 0 . Northeast Utilities 82/08/18 CRUICHIELD. D Operating Reactors Branch 5 Bpp 16002 217 24X Fiche 50-245, 82/08/18, 8211080237
- B212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in FDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- --G002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reamalysis of piping systemules benchmarking per code verification program SHAO, L.C. Assistant Director for Engineering Programs 79/10/30 EIBENUUT, D.O. Division of Operating Reactors 1p 16435 111 24% Fiche 50-000, 82/11/03, 8212140001
- ---B010220355 Forwards SEP info re slides for end-of-yr review of FYB0 effort, info summarizing renaining SEP effort & preliminary instructure spectra for facility
 NELSON, T.A. Laurence Livermore Laboratory B0/10/20 CHENO, T.M. Systematic Evaluation Program Branch 28pp 16436 039 24X
 Fiche 50-000, 82/11/09, 8212140001
- 8212170321 Application to amend Licenses DPR-21 & DPR-65 by 2)2170321 Application to amend Licenses MPN-21 & MPN-65 by incorporating radiological effluent Tech Specs into safety Tech Specs COUNSIL.H © Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H © Northeast Utilities 82/11/22 CLARK.R A Operating Reactors Branch 3 3pp 16453 280 24X Ficher 50-245, 62/11/22 8212170321
- --8212170323 Radiological effluent monitoring & offsite dose calculation manual * Northeast Utilities B2/11/30 117pp 16454 037, 24X
 - Fiche 50-245,82/11/22,8212170321
- BP12070286 Summarizes relative elevations of equipment in intake structure, in response to SEP Topic II-3 C, "Bafety-Related Water Supply (UHB) "Sufficient redundancy would not preclude plant from achieving & maintaining safe shutdown COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 82/11/29 CRUTCHFELD.D Operating Reactors Branch 5 Spp 16039 010 24% Fiche 50-245,82/11/29-8212070286
- B212010100 INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM Milistons Nuclear Power Station Unit 1 Darket No 50-245 (Northeast Nuclear Energy Company) * Office of Nuclear Reactor Regulation, Director NUREO-0824 DRFT 62/11/30 478pp 16292 001 24X Fiche 50-245,82/11/30,8212010100
- 82:2:00277 Provides info to resolve concerns re ventilation stack Pailure to meet design basis criteria of SEP Topic III-2, "Wind & Formado Loadings " Consequences of failure "Mino & Formaco Loadings " consequences or reliure acceptable COUNSIL.H D. CAGNETTA.J P. Northeast Nuclear Energy Co (subs of Northeast Utilities 82/12/03 CRUTCHFIELD.D Operating Reactors Branch 5 4pp. 16277 097 24X Fichs 50-245.82/12/03.8212100277

- B2:12170279 Forwards info re SEP Topics VI-7 A 3, "ECCS Actuation Sys" & IX-5, "Ventilation Sys " Supporting documentation of test procedures & results encl CONVSIL.M 9, CAGNETTAL J P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 9 Northeast Utilities 82/12/03 CRUTCHFIELD.D Operating Reactors Branch 5 24pp 14461 158 241 Fiche 50-245, B2/12/03, B212170279
- 8212i70117 Discusses current status of segmented test rod bundle in light of GE rept of reconstitution activities at EOC-8, supplementing util 810520 & 821102 ltrs COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/06 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 16452 352 24X Fiche 50-245.82/12/06.8212170117
- G212150128 Forwards application for amend of Licenses DPR-2) & DPR-65, reflecting merger of CT Light & Power Co & Hartford Electric Go Class I & II fees encil COWSELL W & Northeast Nuclear Energy Co (subs of Northeast Utilities) COWSELL W & Northeast Utilities B2/12/08 CLARK A Operating Reactors Branch 3 CRUICHFIELD, D Operating Reactors Branch 5 2pp 16425 229 24X Fiche 50-245.82/12/08, paring 1918 8212150128
- ---8212150142 Application for amend of Licenses DPR-21 & DPR-45, reflecting merger of CT Light & Power Co & Hartford Electric Co + Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/08 7pp 16425 PSI 24X Fichs 50-245,82/12/08,8212150128
- BP12170197 Application to amend Licenses DPR-21 & DPR-65, reflecting merger of Hartford Electrical Light Co w/CT Light & Power Co CO COUNBIL.H G Northeast Nuclear Energy CO (subs of Northeast Utilities) COUNBIL.H G Northeast Utilities 82/12/08 CLARK.R A Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5 9pp 16450 144 24X Fiche 50-245.82/12/08. G212/70199
- 8212200100 Forwards SER & nonproprietary & proprietary "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11, B-60), "Vo)s 1 & 11, technical evaluation rept Proprietary rept withhold CRUTCHFIELD. D Operating Reactors Branch 5 82/12/13 (GUNSIL, W 9 Northeast Nuclear Energy Co (subs of Northeast Outlities) 11pp 16470-337 24X Fiche 50-245,82/12/13,8212200100
- --8207010396 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification Safety Evaluation Repts (F-11.8-60)," Vols [& II.technical evaluation rept CRANE. C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-459 VOI-02 82/05/28 LE.N B NRC No Detailed Affiliation Given 779pp 16470 339 24X Fiche 50-245,82/12/13,8212200100
- 8212230287 Forwards P Shewmon 821213 ltr re ACRS rept on SEP Phase II review CRUTCHFIELD.D Operating Reactors Branch 5 82/12/16 COUN: Northeast Nuclear Energy Co (subs of Northeast Utilities) 16511 120 24X Fiche 50-245.62/12/16.8212230287 COUNSIL, W G
- --B212220544 Summarizes ACRS 272nd meeting on 821209-11 re SEP review of facility SHEUMON.P Facility
 SHEHMON,P ACRS - Advisory Committee on Reactor Safeguards
 82/12/13 PALLADIND,N J Commissioners 3pp 165[1 121 24X
 Fiche 50-245,82/12/16,8212230287
- 8212230305 Requests response to request for add1 info re NUREG-0737.

 Item II D 1. "Safety Relief Valve Yesting." within 90 days
 CRUTCHFIELD.D Operating Reactors Branch 5 B2/12/17 COUNSIL.W G
 Northeast Nuclear Energy Co (subs of Northeast Viilities) Spo
 16507 068 24X Fiche 50-245.82/12/17.8212230305
- 8P12270152 Notifies that mechanistic evaluation of discrete pipe break locations, in order to demonstrate Safety Factor 4 for normal operating load, will be completed in late 1983 w/mpds implemented during 1984 outage COUNSIL.H 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H G Northeast Utilities 82/12/17 CRUTCHIFIELD.D Operating Reactors Branch 5 ip 16538 342 24X Fiche.50-245, 82/12/17, 8212270152
- 8212290447 Forwards Teledyne Engineering Svcs "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Point Unit I." consisting of analysis summary & results & description of mods.per NNGE-0661 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL.W O Northeast Utilities 82/12/23 CRUTCHFIELD.D Operating Reactors Branch 5 ip 16584 328 2 Fiche 50-245,82/12/23.8212290447 16584 328 24X

--8212290452 "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Point Unit 1:" chnical rept Teledyna Enginearing Services TR-5318-1 R00 82/12/02 App 16584 330 24/ Fiche 50-245.82/12/23,8212290447

@ Inspection reports, IE Bulletins & correspondence

- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thickrubivored in Hulletin M2-03, Nevision is "Stress Cracking in Thick"
 Mail: Large-Diameter, Stainless Steel, Recirculation Sys Piping
 at BWR Plants "Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 1(2pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 6,08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 % Model 802 Thermoluminescent Dosimeters " Svc list COBB. C. 1 COBB.C. I Division of Fuel Facilities. Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York. Inc. 110pp 16372 142 244 Fiche 50-000,62/11/05,6208190245
- 8208190251 IE Into Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.02/11/18,8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiots "Svc list encl
 DEYQUNG:R C Director's Office, Office of Inspection and
 Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- B±08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L ! Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16367 028 24% Fiche 50-000.82/11/30,8208190257
- BP12100071 Responds to 821028 IE Bulletin 82-03 Revision 1 re insp of Piglobo? Response to Beloze IE Bulletin 82-03, Revision 1 re insp or large-diameter, stainless steel, recirculation sys piping Action Item 4 re ultrasonic testing procedures addressed Responses to Items 1-3 included w/821105 ltr Figures encl CDUKSIL, 0 Contheast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, 0 Northeast Utilities 82/11/30 HAYNES, R C Region 1, Office of Director 13pp 16379 077 24X Fiche 50-245,82/11/30,8212100071
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment DEFOUNDED TO BUTTERIN 22-04. "Deficiencies in Frimary Containment Electrical Penetration Assemblies" Syc list encl
 DEYQUING.R. C. Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co. of New York, Inc. 113pp. 16411 317 24X Fichs 50-000.82/12/03.8208190259
- D:08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Societs" Svc list encl
 JCRDAN.E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York. Inc 110pp 16462 064 24)
 Fiche 50-000,82/12/03,8208190261
- BP12140208 Ack receipt of 821119 ltr informing NRC of steps taken to re-examine nondestructive welds due to insp by unqualified technician HARTHAT Division of Engineering & Technical Programs 82/12/4 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 16409-332 24X Fiche 50-245,82/12/09.8212140208
- --8212140221 Responds to NRC 821102 ltr re resolution of nondestructive exam of uelds All 13 welds re-examined w/no reportable
 - exam or using All 13 welds re-examined Wind reportable indications
 CQUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CQUNSIL.W G Northeast Utilities 82/11/17
 HAYNES.R C Region 1. Office of Director 1p 16407 333 24X
 Fiche 50-245, 82/12/07, 8212140208
- B20B190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York. Inc 127pp 1662B 191 24X Fiche 50-000.82/12/16.8208170267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage

R Periodic operating reports & related correspondence

- B212290224 Forwards monthly operating rept for Oct 1982 MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA,E J Northeast Utilities B2/11/09 (of Resource Management, Director ip 16578 057 24X Fiche 50-245, B2/11/09, B212290224 Office
- --B212290229 Monthly operating rept for Oct 1982 HARRAN.O Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/08 5pp 16578 038 24Y Fiche 50-245. 82/11/09:8212290224
- S Reportable occurrences, LERs & related correspondence
- GP12030180 Forwards LER 82-025/031-0 Detailed event analysis encl MRDCZKA-E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRCZKA-E J Northeast Utilities 82/11/24 HAYNES,R C Region I. Office of Director 2pp 16303 208 Fiche 50-245,88711/24,8212030180
- --B212030187 LER B2-025/03L-0 on 821026, pressure switch 263-55C tripped above Tech Spic during reactor vessel high pressure functional & calibr test Caused by setpoint drift Switch reset & satisfactorily tested THULL.TS Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1. Office of Director 1p 16303 210 24X Fiche 50-245,82/11/24.8212030180
- B212080445 Forwards LER 82-026/03L-O Detailed event analysis encl MRDC2KA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRDC2KA,E J Northeast Utilities 82/12/03 HAYNES,R C Region 1, Office of Director 2pp 16352 168 2-Fiche 50-245, 82/12/03, 8212080445 16352 168 24X
- --B212080453 LER 82-026/03L-0 on 821104.steam tunnel temp switches 261-16A, i6B, i6B, i8B, i8C & IBD tripped above setpoint Caused by setpoint drift Switches adjusted to required setpoint SCHMEIKERFT-FHUL Northeast Nuclear Energy Co (subs of Northey Utilities) SCHMEIKERT-THAL Northeast Utilities B2/12/03 Region 1. Dffice of Director 1p 16352 170 24X Fiche 50-245,82/12/03.8212080445
- G212160358 Forwards LER B2-027/03L-0 Detailed event analysis encl MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MRDCZKA,E J Northeast Utilities 62/12/10 HAYNES,R C Region 1, Office of Director 3pp 16442 290 24X Fiche 50-245, 82/12/10.8212160358
- --9212160371 LER 62-027/03L-0 on \$21111, while performing automatic bloodown logic test, automatic pressure relief relays timed out at 125-8 k 123-8 Caused by instrument setpoint drift due to high control room temp Betpoint reset & tested THULL, Y S Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/10 Region 1. Office of Director 1p 16442 293 24% Fiche 50-245, 82/12/10, 8212160358

T Hearing transcripts on non-antitrust matters

B212020258 Transcript of ACRS Subcommittee on SEP B21190 meeting in Washington.DC Pp 1-257 Supporting documentation and ACRS - Advisory Committee on Reactor Eafeguards 82/11/30 357pp 16276 266 24% Fiche 50-000.82/11/30.821202025

DOCKET 50-246 ADVANCED CRITICAL REACTOR EXPERIMENT P Operating license stage documents & correspondence

8Bi1230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dreaden i, Humboldt Bay, applicants for CL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 Evc list encl Wo stated encl & 18ENHUT, D G Division of Licensing 82/11/15 General Public Utilities - OPU Bervice Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15,8211230066

DOCKET 50-247 INDIAN POINT STATION, UNIT 2 F Security, medical, emergency & fire protection plans

82:01:90499 Presents probabilistic safety study risk frequency & consequence data for proposed addition of seasmic humpers for control bidg & transfer switches for alternate shutdown Port Convers. Stage Consolidated Edison Co of New York, Inc. 82. VARQA, S.A. Operating Reactors Branch (12pp. 15740-054 Fiche 50-247, 82/10/08, 8210190499 82/10/08

- --8210170510 "Indian Point Unit 2 Control Bidg Seismic Improvement Analysis " NARVER.R B , WESLEY.D A Structural Mechanics Associates SMA 12901 03 82/08/31 80pp 15740 067 24X Fiche 50-247.82/10/08, 8210170499
- 82:2140353 Advises that util will conduct annual ensite drill of emergency plan on 82:1208 Alternate drill dates are 82:201 & 15
 O'TOCLE. J D Consolidated Edison Co of New York. Inc 82/11/09
 HAYNES R C Region 1. Office of Director ip 16401 025 24X
 Fiche 50-003.62/11/09.82:12140353
- 8212030141 Forwards IE Safeguards Insp Rept 50-247/82-16 on 920726-30 & notice or violation Details & notice of violation withheld (ref 100FR73 21)

 MARTIN.T T Division of Engineering & Technical Programs 82/11/19 0/TD0LE.J D Consolidated Edison Co of New York, Inc. 2pp 16306 021 24x Fiche 50-247.82/11/19.8212030141
- --8212030147 IE Safeguards Insp Rept 50-247/82-16 on 820726-30
 Noncompliance noted failure to meet testing requirements for special purpose detectors & failure to meet security plan requirements Safeguards details withheld (ref 1007R73 21)
 BAILEY,R J , HADDEN, W , CODY, A T Region 1. Office of Director 52/11/19 7pp 16306 023 24X Fiche 50-247.82/11/19,8212030141
- B212220006 Staff requirements memo re B21119 briefing by FEMA on status of amergency preparedness findings Conclusions re removal of deficiencies & overall adequacy of emergency plans will be submitted between B21203 & 17
 CMILKS J Office of the Secretary of the Commission B2/11/24
 Office or the Secretary of the Commission Ip 16529 151 24X
 Fiche 50-003,82/11/24.6212220006
- 8212030124 Responds to 820702 ltr describing corrective actions re significant deficiencies identified in FEMA 820730 rept, "Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts" HAYNESIR C Region (, Office of Director 82/11/26 D/TOOLE, J D Consolidated Edison Co of New York, Inc. 2pp. 16306 276 24X Fiche 50-003.82/11/26.8212030124
- --B212030248 Forwards description of activities planned or underway to correct deficiencies identified in FEMA interim findings on adequacy of radiological emergency response preparedness of state & local govets.per 820803 request 0.7500LE.J D Consolidated Edison Co of New York. Inc 82/09/02 HAYNES.R C Region 1. Office of Director 15pp 16306 298 24x Fiche 50-003,82/11/26,8212030124
- 8212220037 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/13 Document Management Branch ip 16527 336 24X Fiche 50-003,82/(2/13, 8212220037
- --B212220042 Forwards public version of revised emergency plan implementing procedures including Procedures IP-1001 remobilization of onsite emergency organization & IP-1039 reoffsite contamination checks
 Q*TUOLE: J D Consolidated Edison Co of New York, Inc 52/12/01
 HAYNES, R C Region 1. Office of Director 1p 16527 337 24X
 Fiche 50-003, 82/12/13, 8212220037
- --B212220046 Public version of revised emergency plan implementing procedures, including Procedures IP-1001 re-mobilitation of Onsite emergency organization & IP-1039 re-offsite contamination checks
 FINCH. © L. Consolidated Edison Co. of New York, Inc. 82/11/08
 43pp 16527 338 24X Fithe 50-003.82/12/13.8212220037
- GP12270120 Forwards requested info re emergency operating facility (EOF) EOF located onsite in Buchanan svc ctr bldg approx 2,000 ft from reactor bldg
 D/TOOLE.J D Consolidated Edison Co of New York, Inc 02/12/15 VARGA, S A Operating Reactors Branch 1 3pp 16536 307 24X Fiche 50-247, 62/12/15, 8212270120
- B212210409 Forwards Event Notification Forms Part I & II to better prepare shift crows for questions NRC duty officer may ask during emergency notification
 STAROSTECKIR. Division of Project & Resident Programs 82/12/16
 D'TODLEJ D Consolidated Edison Co of New York, Inc 6pp
 16493.088 24X Fiche 50-003,82/12/16,9212210409
- 8212280084 Forwards FEMA 821217 ltr transmitting "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station "HAYNES,R C Region 1. Office of Director 82/12/17 3'700LE,J D Consolidated Edison Ca of New York, Inc. 2pp 16557 192 24X Fiche 50-247,82/12/17,8212280084

- --8212280087 Forwards "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station "
 FHOMAS.L. M Federal Emergency Management Agency 82/12/17 DIRCKS.W J Office of the Executive Director for Operations 3pp 16557 194 24X Fiche 50-247,82/12/17,8212280084
- --8212280092 "Update Rept on Status or Remedial Actions Cited in 820730 Interior Findings on Adequacy of Radiological Emergency Response Preparation or State & Local Govts at Indian Point Nuclear Power Station "
 PETRONE, F.P. Federal Emergency Management Agency 82/12/14 52pp 14557 197 24X Fiche 50-247,82/12/17,8212280084
- SP12290295 Releases public version of page changes to emergency procedures document FELTON. JM Division of Rules and Records 82/12/20 Document Management Branch 1p 16406 086 24X Fiche 50-003,82/12/20, B212290295
- --8212270302 Forwards public version of page changes to emergency procedures document re determination of magnitude of release & effect on offsite personnel O'TOOLE. J D Consolidated Edison Co of New York, Inc. 82/12/08 HAYNES.R C Region 1. Office of Director 1p 16606 087 24% Fiche 50-003,82/12/20,8212270275
- --8212270308 Public version of page thanges to emergency procedures document re determination of magnitude of release & effect on offsite personnel One oversite drawing encl Aperture card is available in PDR
 SMITH-H Consolidated Edison Co of New York, Inc 82/11/08 20pp 16604 088 24% Fiche 50-003.82/12/20.82(229095)
- 8:12270214 Decision CLI-82-38 ruling that no shutdown or enforcement action required re-state of emergency planning FEMA determined that remedial action will be feasible Problems w/local govts beyond licensee control CHILK.S J Office of the Secretary of the Commission 82/12/22 27ap 16597 128 24X Fiche 59-247.82/12/22.8212270214
- G Adjudicatory correspondence
- 9212070073 Forwards Director's Decision DD-82-12.denging 10CFR2 206 petition to suspend operation immediately until FEMA identified deficiencies corrected DEYGUNO.R C Director's Office of Inspection and Enforcement 82/11/26 WEISS.E R Public Interest Research Group. New York SHOLLY.S C Union of Concerned Scientists WEISS.E R Harmon & Weiss ip 16354 353 24X Fiche 50-247.62/11/26, 9212070073
- --B2120700B1 Director's Decision DD-82-12.denying UCS & NY PIRG 820B04 10CFR2 206 petition to suspend operation immediately until FERM identified deficiencies corrected DEYOUMO, R C Director's Office, Office of Inspection and Enrorcement 82/11/26 Bpp 16304 354 24X Fithe 50-247.82/11/26,8212070073
- 8212020321 Order granting West Branch Conservation Assoc 821124 request for permission to fale replies to licensee interrogatories on Contention 2 2a late Good cause shown GLEASON. J P Atomic Safety and Licensing Board Panel 82/11/30 West Branch Conservation Association 2pp 16279 194 24X Fiche 50-247, 82/11/30,8212020321
- 8212070189 Motion for orders compelling discovery of utils re 820621 Interrogatories 1 11 % compelling NRC to produce documents on routine & unscheduled releases of radiation Certificate of Svc ancl Related correspondence RODRIOUEZ,P Parents Concerned About Indian Point 82/11/30 Atomic 8afety and Licensing Board Panel 3pp 16335 128 24% Fiche 50-247, 82/11/30,8212070189
- B212020318 Requests ASLB issue order modifying schedule in ASLB 821115 memorandum & order, rescheduling Westchester County testimony from 830103 to 830101 Time between filing of testimony & hearing commencement insufficient

 MCROAN.C Power Authority of the State of New York BRANDENBURG, B Consolidated Edison Ca of New York, Inc. MOROAN.C Morgan Associates 82/12/01. OLEASON, J P., SHON, F J., PARIS, D H. Atomic Safety and Licensing Board Panel 2pp 16279 178 24x

 Fiche 50-247, 82/12/01, 8212020318
- 8212050103 Motion to dismiss Contentions 2 1(a) & (d) re filtered vented containments & separate containments respectively & 2 2(b) re specific pressurized thermal shock responses W/Certificate of Svc BRANDERBURO. B Consolidated Edison Co of New York, Inc MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 82/12/01. Atomic Safety and Licensing Board Panel 10pp 16316 123 24% Fiche: 50-247,88/12/01.8212060103

- 8M12060098 Response to interrogetories & document requests re Commission Questions 2 & 5 Related correspondence SHOLLY, S C , BLUM. J M Union of Concerned Scientists BLUM. J M New York Univ 82/12/02 Consolidated Edison Co of New York, Inc 30pp 16316 133 24X Fichs 50-247,82/12/02,8212060098
- BBIR060241 Memorandum & order granting util B21201 request for postponement or hearing scheduled for wk of B30103 until wk of B30110 Parties presenting evidence concurring in request GLEASON.J P. Atomic Safety and Licensing Board Panel 82/12/02 Consolidated Edison Co. of Neu York, Inc. 2pp. 16312 245 24X Fiche 50-247.82/12/02,8212040241
- BR12040077 Response to 820714 first set of interrogatories & request for documents re Commission Questions I & 2 SHOLLY, S C, BLUM, J M Union of Concerned Scientists BLUM, J M New York Univ 62/12/03 Diffice of the Executive Legal Director 14pp 16314 300 24x Fiche 50-247,82/12/03,8212060077
- 8212060089 Notice of JF Mayer 821207 deposition in Bethesda, MD refiltered vented containment sys Certificate of Evc encl BLUM, J M Union of Concerned Scientists SLUM, J M New York Univ 82/12/03 Spp 16314 313 24X Fiche S0-247, 82/12/03, 8212060077
- Gi·12070246 Motion for mod of hearing schedule, delaying hearings until 820315 Hearing dates as scheduled conflict w/830308 emergency exercise Both NY State & Suffolk County witnesses will be engaged in exercise Certificate of Svc encl FEINBERG, J D New York, State of Energy Office 82/12/03 Atomic Eafety and Licensing Boord Panel 8pp 16327 284 24X Fiche 50-247, 82/12/03, 8212070246
- 8P120700B7 Forwards three ads published in listed newspapers sponsored by utils informing of safe plant operation Info provided per ASLB oral directive at 820123 public hearing BRANDENDURG, B Consolidated Edison Co of New York, Inc. LEVIN, J.J. Power Authority of the State of New York LEVIN, J.J. Morgan Associates 82/12/03 GLEASON, J.P., SHON, F.J., PARIS, D.H. Atomic Safety and Licensing Board Panel. Spp. 16357-175 24X Fiche 50-247, 82/12/03, 8212070087
- Bil2230337 Urges that plants not return to svc until adequaty of emergency planning & preparedness guaranteed Worst case accident could result in many thousands of fatalities RYAN, A B New York, NY 82/12/03 PALLADINO, N J , AMEARNE, J , GILINSKY, V Commissioners 2pp 16505 132 24X Fiche 50-247, 82/12/03, 8212230337
- GP12070209 Response in apposition to licensee 821201 motion to dismiss contentions Requirements arising under Contention 2 2(b) should be transferred to NRC & licensees Certificate of Svc encl FLEISHER/Z S West Branch Conservation Association 82/12/04 Atomic Safety and Licensing Board Panel 3pp 16333 181 24X Fiche 50-247,82/12/04,8212070209
- GC12070213 Motion to compel discovery of Con Ed re evaluation of hybrid closed cooling sys Matl requested for Contention 2 2(a) Certificate of Syc enci Related correspondence FLEISHER. Z S West Branch Conservation Association 82/12/04 Atomic Safety and Licensing Board Panel 2pp 16329 360 24X Fiche 50-247. 62/12/04.8212070213
- G2:2080310 Supplemental response to first set of interrogatories & document requests on ASLB Questions 1,2 & 5
 COLARULLI,P F Power Authority of the State of New York
 (OLARULLI,P F Morgan Associates 82/12/06 Union of Concerned Scientists 35pp 16354 010 24X Fiche 50-247,82/12/06,8212080310
- 8212090990 Advises of attempted contact re W Fleisher deposition Utils intend to take deposition next wk re Contention 2 2(a)
 BRANDENBURG. B. Consolidated Edison Co. of New York, Inc.
 CCLLARULLI,P. F. Power Authority of the State of New York 82/12/04
 FLEISHER. I. S. West Branch Conservation Association 19 16987 174
 24X Fiche 50-247,82/12/04,8212090090
- 3212090101 Supplemental response to interrogatories on Commission Guestions 1 & 2 Certificate of Svc encl SMOLLY.S C. BLUW. M Union of Concerned Scientists 82/12/07 Office of the Executive Legal Director 17pp 16357 284 24X Fiche 50-247.82/12/07.8212090101
- SP12100103 Memorandum & order memorializing rulings of 821203 telcon Schedule for UCS.utils & NRC modified as listed Deadline for notice of depositions of UCS witnesses for Question 1 to be negotiated GLEASON.UP Atomic Safety and Licensing Board Panel 82/12/08 8pp 16379 105 24X Fiche 50-247.82/12/08.8212100103

- BJ12140423 Responses apposing West Branch Conservation Assoc 821104 application for reinstatement of Contention 2 2(d) & Assoc 821104 objection to ASLB restatement of Contention 2 2(b) Certificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York, Inc. MGRGAN, C Power Authority of the State of New York MGRGAN. C Morgan Associates 82/12/09 Atomic Safety and Licensing Board Panel 8pp 16404 199 24% Fiche 50-247.82/12/09.8212140420
- BP12150017 Answer objecting to State of NY motion for mod of hearing schedule Change in witness testimony schedule burdensome Certificate of Svc Onci.
 POSNER:P Parents Concerned About Indian Point B2/12/09 Atomic Safety and Licensing Board Panel 1p 16421 (BO 24X Piche 50-247, B2/12/09, 82:2150017
- GP12150022 Notice of concurrence w/Parents Concerned About Indian Point objection to State of NY motion to modify hearing schedule Further postponent of witness testimony unwarranted & burdensome to UCS/PIRO fo NY & witnesses HOLT.J Union of Concerned Scientists HOLT.J Public Interest Research Oroup, New York 82/12/09 1p 16421 231 24X
- 8212130208 Order scheduling 830110 evidentiary hearing in White Plains, NY OLEABON, J.P. Atomic Safety and Licensing Board Panel 82/12/10 1p 16397-015 24X Fiche 50~247.82/12/10.8212130208
- G212130252 Forwards Westchester County 821205 1tr to Commissioner Palladino re offsite emergency preparedness to comply w/ex parts communications regulations STUCKY.S W Docksting & Services Branch 82/12/10 Office of the Executive Legal Director 1p 16396 230 24X Fiche 50-247. B2/12/10.8212130252
- --8212130254 Urges that facilities not be restarted until emergency response plans are fully workable & implementable State of emergency planning & preparedness in Westchester County still inadequate DELBELLO, A B Westchester County, NY 82/12/05 PALLADINO, N J Commissioners 12pp 1639& 231 24X Fiche 50-247, 82/12/10, 8212130252
- 82)2140242 Response in opposition to State of NV motion for mod of hearing schedule moving hearing commencement on Cummission Questions 3 & 4 to 830315 Extension to 830314 for testimony on questions not opposed KAPLAN.C New York.NV 82/12/10 Atomic Bafety and Licensing Board Panel 2pp 16407 304 24X Fiche 50-247, 82/12/10, 8212140242
- 8212140384 Notification of witnesses on Commission Question 2 BLUM, J M Union of Concerned Beientists 82/12/10 2pp 16404 320 24% Fiche 50-247,02/12/10.8212140384
- --8212140393 Notice of deposition of NRC witnesses HR Denton, BH Hanauer, RK Blond & FH Rowsome re testimony to be provided Denton & Hanauer will also be examined on decision criteria & process & CRAC & CRAC2 accident consequence codes BLUM.J M Union of Concerned Scientists B2/12/10 2pp 16404 322 24X Fiche 50-247, 82/12/10.8212140384
- ~-B212140400 Notice of deposition of util witnesses DC Bley, BJ Garrick, S Kaplan & DC Richardson re probabilistic safety study Certificate of Bvc encl BLUM, J M Union of Concerned Scientists 92/12/10 App 14404 323 24X Fiche 50-247, 82/12/10, 8212140384
- 8212140439 Motion for leave to file encl reply to West Branch
 Conservation Assoc 821204 reply to licensee 821201 motion
 to dismiss certain contenting If Assoc had participated in
 telcon. Utils would have orally replied
 BRANDENBURO, B Consolidated Edison Co of New York, Inc. LEVIN. J J
 Power Authority of the State of New York LEVIN. J Morgan
 Associates 82/12/10 Atomic Safety and Licensing Board Panel
 2pp 16405 249 24X Fiche 50-247,82/12/10,8212140439
- ~ 8212140446 Reply to West Branch Conservation Assoc 821204 reply to licensee 821201 motion to dismiss certain contentions Assoc misconstrues Commission intent in establishing proceeding Contention 2 2(b) should be struck W/Certificate of Svc BRANDENBURG, B Consolidated Edison Co of New York, Inc LEVIN. J J Power Authority of the State of New York LEVIN.J J Morgan Associates 82/12/10 Atomic Safety and Licensing Board Panel 7pp 16405 251 24x Fiche 50-247,82/12/10,8212140437.
- 8212140451 Forwards Rockland County resolution calling for closing of plants for failure to remedy emergency planning deficiencies by expiration of 120-day clock THORSEN, E.O. Rockland County, NY 82/12/10 PALLADINO, N.J. Commissioners 3pp 16404 355 24X Fiche 50-247, 82/12/10, 82/12/40451

- 8212160289 Notice of I Levi, D Pisello & R Piccioni 821229 depositions in Nr.NY re testimony on Commission Question E Certificate of Svc and Related correspondence BRANDENBURG. B Consolidated Edison Co of New York. Inc. MORGAN. C Power Authority of the State of New York. MORGAN. C Morgan Associates 82/12/10 App. 16446-068-24X Fiche 50-247.82/12/10.
- 8212150116 Response to licenses 821201 motion to dismiss Contentions 2 1(a).2 I(d) & 2 2(b) Supports dismissal of Contention 2 2(b) Hest Branch Conservation Assoc filings show that Assoc will not pursue issue Certificate of Svc encl MODRE. J & Hearing Branch 1 82/12/13 Atomic Safety and Litensting Board Panel 8pp 16427 351 24X Fiche 50-247.82/12/13, 8212150116
- 8212200032 Qualifications statements for UCS/NY PIRO ultnesses on Commission Question 2 Prof qualifications & Certificate of Svc encl BLUM, J H Union of Concerned Scientists 82/12/13 11pp 16473 351 24x Fiche 50-247,82/12/13.8212200032
- 6912170169 Advises that NRC does not intend to seet authorization to reply to West Branch Conservation Assoc 821124 objections to restatement of Contention 2 2(b) No new arguments raised MODRE. J E. Hearing Branch 1 82/12/14 QLEASON. J P. PARIS. O H. SHON. F J. Atomic Safety and Licensing Board Panel 1p 16450 22: 24X Fiche 50-247.82/12/14.8212170169
- 8212140375 Order requesting ASLB provide recommendations called for in CLI-81-23 no later than 830729 CMILK, 9 J Office of the Secretary of the Commission 82/12/15 Atomic Safety and Licensing Board Panel 19 16442 341 24X Fiche 50-247.82/12/15.8212160375
- 8212170174 Response to Parents Concerned About Indian Point 821130 motion to compel discovery against utils & response opposing Parents request to file new document request on NRC Protective order requested Certificate of Svc encl MCGURREN.H J Hearing Branch 1 82/12/15 Atomic Safety and Licensing Board Panel 5pp 16450 163 24X Fiche 50-247.82/12/15.6212170174
- 8212200097 Memorandum & order granting NRC motion for protective order re answer to UCS/NY PIRQ Interrogatory 5 NRC is not required to compile list of NRC criticisms of plant probabilistic safety study nor to formulate position GLEASDN. J P Atomic Safety and Licensing Board Panel 92/12/15 Office of the Erecutive Legal Director 2pp 16470 140 24X Fiche 50-247.82/12/15.8212200097
- 8212220293 Reply opposing licensee 821210 motion for leave to file reply to Hest Branch Conservation Assoc response to licensee 821201 motion Licensee is harassing Assoc Certificate of Svc encl fleISHER, Z S West Branch Conservation Association 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16517 188 24x Fiche 50-247,82/12/15,8212220293
- 8P12220220 Advises that H Kaminski snadvertently omitted from amended witness lists Order of witnesses listed Related correspondence VETERE.L A Westchester County.NY 82/12/16 OLEASON, J P. PARIS.O H. SHOW, F J Atomic Safety and Licensing Board Panel ip 16503 001 24X Fiche 50-247, 82/12/16.8212220220
- --B212220226 Response to State of NY motion to modify hearing schedule Unnecessary to delay testimony of all other available sitnesses until County & State witnesses available Certificate of Svc encl.

 VETERE, L. A. Heatchester County, NY 82/12/16 Atomic Safety and Licensing Board Panel 2pp 16503 CO2 24X Fiche 50-247, 62/12/16,8212200220
- 8212230261 Urgrs plants not be reopened until emergency preparedness plans adequate BIALIK, El New York, State of B2/12/16 PALLADINO, N Commissioners ip 16508 188 24X Fache 50-247.82/12/16, R212230261
- 8212230331 Forwards 821213 ltr inadvantently sant to J Hendrie Attendance at 830110 evidentiary hearing requested MANTELLIA N Affiliation Unknown 82/12/14 PALLADINO. N Commissioners. 1p 16505 157 24X Fichs. 50-247. 82/12/16. 8212230331
- --8212230336 Ack receipt of 821210 invitation to attend evidentiary hearing in White Plains, My Attendance certain unless accident postepones hearing MANTELL.A N. Affiliation Unknown 82/12/13 HENDRIE, J Atomi Safety and Licensing Board Panel 1p 16505 158 24X Fichs 50-247,82/12/16,8212230331

- BP12210235 Memorandum & order memorializing 821215 & 16 telcons & dismissing Parents Concerned About Indian Point & West Branch Conservation Assoc 821130 & 1204 discovery motions PARISIO H Atomic Safety and Licensing Board Panel 82/12/17 Parents Concerned About Indian Point 2pp 16484 234 24X Fishe 50-247, 82/12/17, 8212210235
- 8012210238 Supplementation of interrogatory response naming Guestion ; witnesses Certificate of Svc encl
 BLUM, J M Union of Concerned Scientists 82/12/17 5pp
 14484 236 24% Fiche 50-247, 82/12/17, 8212210238
- B212210320 Forwards Congressman RL Ottinger 821201 ltr to util seeking testimony before Congress re investigation Util 821203 response encl
 LEVIN-J J Margan Associates 82/12/17 PALLADINO, N J ,
 AHRANE, J F , GILINSKY, V Commissioners 6pp 16496 246 24X
 Fiche 50-247: 82/12/17.8212210320
- 8/J2220246 Supplemental response to first set of intelrogatories & document requests under Commission Question 1 Prof qualifications encl Related correspondence HARTZHAN.R M Friends of the Earth HARTZHAN.R M New York City Audubon Society 82/12/17 Consolidated Edison Co of New York Inc 32pp 14518 280 24X Fiche 50-247,82/12/17.6212220244
- 8212220271 Responses to interrogatories & document requests re Commission Guestion & Certificate of Svc encl BRANDENDURO. B Consolidated Edison Co of New York. Inc. PRAIT. C M Power Authority of the State of New York. PRAIT. C M. Morgan Associates 82/12/17 Parents Concerned About Indian Point 15pp 16517 280 24X Fiche 50-247.62/12/17,8212220271
- 8212230187 Response to motion to compel discovery re Commission Gusstion & Certificate of Svc encl Related correspondence BRANDENBURG, B Consolidated Edison Co of New York, Inc. PRATT, C M Power Authority of the State of New York PRATT, C M Horgan Associates 82/12/17 Parents Concerned About Indian Point 14pp 16511 007 24X Fiche 50-247.82/12/17.8212230187
- B/12230235 Urges that units not be returned to syc until emergency planning concerns resolved BRODSKY.R L Westchester County.NY DE MARCO.J W. HOCHDERQ.A G Commissioners B2/12/17 PALLADINO.N J., AMEARNE.J F., GILINBKY.V Commissioners 3pp 16511 060 24X fiche 50-247.B2/12/17.B2/12/20335
- 8212280014 Lists documents being withheld as privileged that were requested by SC Shally (UCB) in UCB/NY PIRQ first set of interrogatories & document requests on Commission Questions 1.2 & 5 NUREO/CR-2666 forthcoming MCGURREN.H J. Hearing Branch 1 82/12/17 BLUM.J M New Yor: Univ 2pp 16564 290 24X Fiche 50-247.82/12/17.8212280014
- B2:12280285 Response in opposition to State of NY motion for mod of hearing schedule Since motion relates to scheduling of testinony within allotted time frame, no further hearing delay necessary Certificate of Svc encl MORGAN. C Power Authority of the State of New York MORGAN. C Morgan Associates 82/12/17 Atomic Safety and Licensing Board Famel 7pp 16561 327 24X Fiche 50-247, 82/12/17, 8218280285
- G212210267 Response in support of State of NY B21203 motion for mod of schedule for hearing testimony on Commission Questions 3 & 4 Eitersion needed in order for witnesses to participate in emergency planning exceptiese Certificate of Svc encl MOORE, J E Hearing Branch 1 B2/12/20 Atomic Safety and Licensing Board Panel 5pp 16489 170 24X Fiche 50-247.82/12/20, 8212210267
- G212210332 Response opposing Con Ed B21215 mailgram requesting A6LB to grant previously filed motion to dismiss Contentions 2 ((a) & 2 1(d) Prejudice caused by UCS/NY PIRQ tandiness not equal to requested sanctions Certificate of Syc and MODREJ E Hearing Branch (B2/12/20 Atomic Safety and Licensing Board Panel 7pp 16497 013 24X Fiche 50-247.82/12/20, G212210332
- B21222039B Memorandum supporting Con Ed B21215 renewed motion to dismiss UCS/NY PIRG Contentions 2 1(a) & 2 1(d) UCS continues to act immune from orders of ASLB: notwithstanding Judge Paris admonition Certificate of Svc enc! HORGAN: C Power Authority of the State of New York MORGAN: C Morgan Associates B2/12/20 Atomic Safety and Licensing Board Panel 9pp 16503 223 24X Fiche 50-247, B2/12/20, S212220398
- 8212230241 Strongly urges that units not be returned to svc until emergency planning concerns resolved STEINGUT.R., STERN.H J., GREITZER.C New York, NY 82/12/20 PALLADINO.N J., AHEARNE.J.F., GILINGKY, V. Commissioners (ipp 16508 145 24X Fiche, 50-247, 82/12/20, 8212230241

- 8212230270 Urges plants not be restarted until workable emergency plan implemented
- mented 5 New York,NY 82/12/20 PALLADINO,N J Commissioners 16507 358 24% Fiche 50-247,82/12/20,8212230270
- 8712280273 Response in opposition to State of NY motion for mod of hearing schedule State did not meet heavy burden of persuasion required to extend hearings Certificate of Svc
- BRANDENBURG, B Consolidated Edison Co of New York, Inc. 6 Atomic Safety and Licensing Board Panel App. 16562-067 Fishe 50-247,82/12/20,8212280273 82/12/20
- 82:12230181 Menorandum & order granting licensee 82:1210 motion to reply to West Branch Conservation Assoc (WBCA) reply to util 82:1201 motion to dismiss contentions Util 82:1201 motion to dismiss also granted MBCA motion for reinstatement denied GLEASON.J P. SHON.F J. Atomic Safety and Licensing Board Panel 82/12/21 Consolidated Edison Co. of New York. Inc. 7pp
- 87:12230188 Memorandum & order granting Parents Concerned About Indian Point 821130 request to place specified documents issued by NRC prior to 1979 into LPDR GLEASON.J P Atomic Safety and Licensing Board Panel 82/12/21 Parents Concerned About Indian Point 6pp 16511 106 24X Fireha 80-247.82/12/21 8212230188

Fiche 50-247, 82/12/21, 8212230188

- BP12230358 Order extending time, until 821229, for Commission to decide whether to review IE Director 821126 denial of UCS request for action filed under 10CFR2 206 CHILK, S.J. Office of the Secretary of the Commission 82/12/21 Ip 16511 161 24X Fiche 50-247, 82/12/21, 8212230358
- 8212230228 Urges FEMA update rept be given consideration in decision to reopen facilities Large number of emergency deficiencies still renain MENIZEL.J S Affiliation Unknown 82/12/22 PALLABINO,N J , AHEARNE,JF , ASSELSTINE.J K Commissioners 15pp 16511 032 24x Fiche 50-247,82/12/22,8212230228
- G2:122702;4 Decision CLI-82-38, ruling that no shutdown or enforcement action required re state of emergency planning FEMA determined that remedial action will be feasible Problems w/ local govts beyond licensee control CHILLS J Office of the Sceretary of the Commission 82/12/22 27pp 16937 128 24% Fiche 50-247,82/12/22,8212270214
- GP12280008 Forwards FEMA 821217 1tr to Ofc of Executive Director for Operations re current status of offsite emergency planning transmitting update rept W/o encl
 HASSELL.DF Hearing Branch | 82/12/22 GLEASON, JP, SHON, FJ,
 PARIS.D H Atomic Safety and Licensing Board Panel | Ip 16564 289
 24X Fiche 50-247, 62/12/22, 8212280008
- GF12280011 Advises that invoice for copying documents requested by SC Shally on 82/214 forthcoming Topying accuments requested by MCGRE.J E Hearing Branch 1 82/12/22 WEISS, E R Harmon & Weiss 1p 16565 144 24X Fiche 50-247,82/12/22,8212280011
- BF:12270249 Order CLI-82-41.granting in part & denying in part,UCS 821008 motion to direct NRC to reschedule meeting All parties must be informed of scheduling of meetings CHILK.8 J Office of the Secretary of the Commission 62/12/23 Union of Concerned Scientiets 3pp 16530 357 24X Fiche 50-247,82/12/23.8212270249
- E£:12300012 Memorandum & order dismissing West Branch Conservation Assoc 621215 motion to deny licensee motion for leave to reply ticensee motion granted, rendering instant motion moot GLEASON. J P Atomic Safety and Licensing Appeal Panel 62/12/23 West Branch Conservation Association 2pp 16578 227 24X Fiche 50-247, 82/12/23, 8212300012
- 8212300014 Memorandum & order denying licensee 821201 motion & 821215 renewed motion to dismiss Contentions 2 1(a) & 2 1(d) UCS failure to meet 821210 deadline minor since delay did not prejudice parties

 GLEASON, J P Atomic Safety and Licensing Board Panel 82/

 Consolidated Edison Co of New York, Inc 4pp 16598 218

 Fiche 50-247,82/12/23,8212300014 82/12/23
- 8212280326 Forwards revised Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
 GTUCKY: B W Docketing & Services Branch B2/12/27 P
 Authority of the State of New York ip 16562 084 24X
 Fiche 50-247. B2/12/27,B212280326 Power
- --8212280332 Corrected Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
 CHILK-S J Office of the Secretary of the Commission 82/12/23
 Vnion of Concerned Scientists App 16562 085 24%
 Fiche 50-247,82/12/27,8212280326

- B212300191 Ack receipt of summary of Steam Generator Dwners Group B20729 meeting Request being filed for delay in delivering testimony on Question 2 2 1 in order to obtain previously testimony on Question 2 2 1 34 order to occasi plantices stable info FLEISHER, Z S West Branch Conservation Association MODRE, J Hearing Dranch 1 ip 16598 023 24X fiche 50-247, 82/12/27, 821230019
- 8212300197 Notice of continuation of Contentions 3 & 4 FLEISHER.Z S West Branch Conservation Association 82/12/27 ip 16598 024 24X Fiche 50-247.82/12/27.8212300197
- --8212300201 Request for delay in filing testimony on Question 2 1 1 until 830112 in order to obtain addition Certificate of Syc FLEISHER, Z S West Branch Conservation Association Atomic Safety and Licensing Board Panel 2pp 14598 025 24X Fiche 50-247, 82/12/27, 8212300197
- G2:2300230 Motion for expedited order compelling continuation of GR Thompson & SC Sholly depositions as witnesses on Contentions 2 1(a) & 2 1(d) Witness testimony incomplete Contentions 2 1(a) & 2 1(d) Witness testimony incomplets
 Certificate of 5 vc encl
 BRANDENBURG, B Consolidated Edison Co of New York, Inc
 MORRAN, C M Power Authority of the State of New York MORRAN, C M
 Morgan Associates 82/12/28 Atomic Safety and Litensing Board
 Panel 14pp 16598 004 24X Fiche 50-247, 82/12/28, 8212300230
- ii General correspondence
- G212230323 Forwards Rockland County Resolution 796 calling for closing of plants for failure to remedy emergency planning deficiencies SEIGERMAN, V K Rockland County, NY 82/12/13 PA SEIDERMAN, V K Rockland County, NY 82/12/13 PALLADINO, N Commissioners 2pp 16505 134 24K Fiche 50-247, 82/12/13, G212230323
- 82/12270428 Responds to 821130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830:110 scheduled DIRCKS,W J Office of the Executive Director for Operations 82/12/20 BRADLEY.B Senate 2pp 16568 339 24X Fiche 50-003.82/12/20.8212270428
- --B212270431 Forwards DX & FL Cinqueman1 820730 ltr requesting resumption of hearings on safety of plants
 BRADLEY, R Senate B2/11/30 Office of Congressional Affairs
 5pp 16568 341 24X Fishe 50-003,82/12/20,821270428
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8212070077 Forwards "Review of Indian Point Probabilistic Safety AVERY.R Argonne National Laboratory 82/10/20 DKRENT.D ACRS ~ Advisory Committee on Reactor Safeguards DKRENT.D California, Univ of, Los Angeles 1p 16354 320 24X Fiche 50-247,82/10/20, 8212970077 Study " AVERY.R
- --B2120700B3 "Review of Indian Point Probabilistic Safety Study " AVERY,R: CHO,D H: BEITRICH,L W Arganne National Laboratory 82/09/30 ARS Advisory Committee on Reactor Safeguards 30pp 16354 321 24X Fiche 50-247.82/10/20
- P Operating license stage documents & correspondence
- 8212030287 Forwards request for add1 info to complete post-implementation review of NUREG-0737. Items II F 1 4. II F 1 5 & II F 1 6 re containment monitors Response within 30 days VAROA.S A Derating Reactors Branch 1 82/11/18 0'TOOLE Consolidated Edison Co of New York, Inc 10pp 16317 314 Fiche: 50-247, 82/11/18, 8212030257 O'TOOLE, J D
- 8212090205 Forwards response to 821027 1tr re draft BNML analysis of elauvuzus roruards response to 821027 Itr re draft INML analysis liquid pathway consequences due to basement penetration as presented in Indian Point probabilistic safety study BAYNE, J P Power Authority of the State of New York D'TODLE, J Consolidated Edison Co of New York, Inc 82/11/29 VARGA, S A Operating Reactors Branch 1 14pp 16362 346 24X Fiche 50-247, 82/11/29, 8212090205 O'TOOLE, J D
- 0212070285 Notifies that radiological effluent Tech Specs & offsite dose calculation manual will be submitted by 830201 & 0401. dose calculation manual will be submitted by 830201 & 0401, respectively O'TOOLE, J D Consolidated Edison Co of New York, Inc. 82/12/01 VAROA, S A Operating Reactors Branch 1 lp 16339 113, 24X Fiche 50-003, 82/12/01, 8212070285

- BP12080559 Advises that review of util evaluation of design differences per 800509 & 820527 ltrs complete Design acceptable per 800211 confirmatory order Updated evaluation of differences between Units 2 & 3 enc. VARQA-S A Operating Reactors Branch 1 82/12/01 O'TOOLE, T D Consolidated Edison Co of New York, Inc. 13pp. 16368-337 24) Fiche 50-247, 82/12/01.8212080369
- 8212130030 Requests review of Unit 3 technical evaluation rept researching qualifrication of auxiliary feedwater sys Apparent discrepancies between Units 2 & 3 should be addressed VAROA.5 A Operating Reactors Branch I 82/12/02 0'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 16417 051 24X Fiche 50-247, 82/12/02.8212130030
- 32:12:30232 Forwards analyses of control room ceilings w/fragility of ceiling structures & effects of failure on core melt frequency due to seismic events, in fulfillment of 82:10:13 commitment re probabilistic safety study WAYNE, J P Power Authority of the State of New York O'TODLE, J D Consolidated Edison Co of New York. Inc 82:12:706 Operating Reactors Branch 1 7pp 16370 134 24X Fiche 50-247, 82:12:706, 82:12:30232
- 8212130288 Forwards further details re gas turbins operation Continued satisfactory gas turbins operation in future will confirm usefulness of gas turbins reliability improvements O'TOOLE.J P Consolidated Edison Co of New York, Inc. 82/12/06 VARGA, S.A. Operating Reactors Branch 1 3pp 16389-316 24X Fiche 80-247.82/12/06.8212130288
- 8208190263 Generic Ltr 82-32 to all FWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of the Svc list encl EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc. 29pp 16629 247 24X Fiche 50-000.82/12/09.8208190263
- BP:12140103 Generic Ltr 82-28 to all licensees of operating Mestinghouse & G-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list enci EISENHUT, D 0 Division of Licensing 82/12/10 Yankee Atomic flectric Co 27pp 16690 035 24X Fiche 50-000.82/12/10, 82/12/40103
- 8212270108 Forwards Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, safety evaluation & notice of issuance & availability Amends modify facility organization structure & testing requirements on containment (solation valves HANNON, J N Operating Reactors Branch 1 82/12/11 G'TOOLE, J D Consolidated Edison Co of New York, Inc. 4pp 16553 200 24X Fiche 50-003.82/12/11.8212270108
- --8212270111 Amends 31 & 82 to Licenses DPR-5 & DPR-26, respectively, modifying facility organization structure for Units I & 2 & testing requirements on containment isolation valves & snubber Tech Specs for Unit 2 VARCA: S A Operating Reactors Branch 1 82/12/11 39pp 16553 204 24X Fiche 50-003.82/12/11.8212270108
- --82(2270113 Safety evaluation supporting Amends 31 & 82 td Licenses DPR-5 & DPR-26, respectively + Office of Nuclear Reactor Regulation, Director 16593 243 24% Fische 50-003,82/12/11.8212270108
- --82(2270117 Notice of issuance & availability of Amends 31 & 82 to Licenses DPR-5 & DPR-26.respectively VARGALS A Operating Reactors Branch I 82/12/11 2pp 14553 247 24% Fiche 50-003,82/12/11.8212270108
- 0212280364 Forwards current status of actions taken on probabilistic safety stody Results of evaluation of soil/backfill containment bldg interaction expected in Spring 1983 0'YOULE.J D. Consolidated Edison Co. of New York, Inc. 82/12/14 VAROA.S A. Operating Reactors Branch 1 2pp 16560 072 24X Fiche 50-247.82/12/14.8212280364
- BEI2280837 Forwards application for amend to License DPR-26, adding Yech Specs 3 14 & 4 17 to establish limiting conditions for appraction & surveillance requirements for severe hurricans condition Africavit of Svc & Class III fee encl
 0/T00LE, J D Consolidated Edison Co of New York, Inc 82/12/17 VARGA, 8 A Operating Reactors Branch | 2pp 14561 207 24X Fichs 50-247, 82/12/17, 8212280237
- ~-B212280243 Application for amend to License DPR-24, adding Tech Specs 3 14 & 4 17 to establish limiting conditions for operation & surveillance requirements for severe hurricane condition O'TOCLE.J D Consolidated Edison Co of New York. Inc 82/12/17 2pp 16361 209. 24X Fiche 50-247, 82/12/17, 9212280237

- --B212280248 Proposed Tech Specs 3 14 & 4 (7, establishing limiting conditions for operation & surveillance requirements for severe hyrricane condition Safety assessment encl * Consolidated Edison Co of New York, Inc 82/12/31 6pp 16561 211 24X Fiche 50-247, 82/12/17, 8212280237
- SB12300273 Forwards status of plant mods w/estimated date of completion.per NUREG-0737. Items II B 3.II F 1.III A 1 2 & 1II D 3 4 Administrative procedures revised per Generic Ltr 82-12 O'TOOLE.J D Consolidated Edison Co of New York, Inc 82/12/23 VARQA,S A Operating Reactors Branch 1 3pp 16595 247 24% Fiche 50-247.82/12/23,8212300273
- B£12300352 Responds to NRC 821118 ltr requesting add1 info re NUREG-0737. Items II F 1 4.5 & 6 re containment pressure, water level & hydrogen monitors: respectively Info to be submitted on or before 830501 O'TGOLE. J D Consolidated Edison Co of New York, Inc 82/12/23 VARGA: \$A Operating Reactors Branch 1 ip 16594 222 24X Fiche 50-247.82/12/23.8212300352
- & Inspection reports. IE Bulletins & correspondence
- B:/08j90240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BUR Plants " Svc list encl DEYGUNG.R C Director's Office of Finspection and Enforcement B2/10/28 Consolidated Edison Co of New York, luc 112pp 16462 163 24X Fiche 50-000,82/10/28.6208190240
- 8P08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 16372 142 24x Fiche 50-000,82/11/05,8208190245
- 8708190291 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8200190251
- 8212030141 Forwards IE Safeguards Insp Rept 50-247/82-16 on 820726-30 & notice or violation Details & notice of violation withheld (ref 100FR73 21)
 MARTIN, T T Division of Engineering & Technical Programs 82/11/19 0/100ErJ D Consollabed Edison Co of New York, Inc 2pp 16306 021 24X Fische 50-247,82/11/19,8212030141
- --8212030147 IE Safeguards Insp Rept 50-247/82-16 on 820726-30
 Noncompliance noted failure to meet testing requirements for special purpose detectors & failure to meet security plan requirements Safeguards details withheld (ref 10CFR/3 21)
 84LEY,R J. MADDEN,W . GODY, A T. Region I. Office of Director 82/11/19 7pp 16306 023 24X Fiche 50-247,82/11/19,8212030141
- 8212060235 Forwards IE Insp Rept 50-247/82-22 on 821019-22 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/11/22 0'T0QLE.J D Consolidated Edison Co of New York. Inc 2pp 16312 180 24X Fiche 50-247.82/11/22.8212060235
- --8212060237 IE Insp Rept 50-247/82-22 on 821019-22 No noncompliante noted Major areas inspected inservice tenting surveillance program for pumps & valves REMITO.HA , BETTENHAUSEN.L Division of Engineering & Technical Programs 62/11/17 8pp 16312 182 24X Fiche 50-247.82/11/22, 8212060235
- B20B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEVOUND:R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc [27pp 16411,065 24% Fiche 50-000.82/11/26,8208190256
- 8/12070296 Forwards response to 821004 request for add1 info re 1E Bulletin 80-04, "PMR Main Steam Line Break W/Continuod Feedwater Add:tion" No single failure will preclude main feedwater isolation under design basis steam line break O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/29 VARGA:S A Operating Reactors Branch 1 Spp 16339 066 24X Fiche 50-247,82/11/29,8212070296
- 82:2140137 Forwards IE Insp Rept 50-247/82-20 on 82:001-31 No noncompliance noted 8TAROSTECKI.R Division of Project & Resident Programs 82/11/29 0 TOOLE.J D Consolidated Edison Co of New York, Inc 16408-181 24X Fiche 50-247,82/11/29,82:12140137

- --8212140140 IE Insp Rept 50-247/82-20 on \$21001-3! No noncompliance noted Major areas inspected licensee actions on previous items, operational safety verification, plant tours, facility maint surveillance observations & prefueling activities FOLEY. T. KOLTAY. P. REBELOWSKI: 7 Division of Project & Resident Programs 82/11/24 16pp 16408 183 24X Fiche 50-247,82/11/29,8212140137
- B. OB190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list ent! COBS.L. I Division of Fuel Facilities. Materials & Safeguards B2/11/30 Consolidated Edissin Co of New York, Inc 356pp 16387 028 244 Fiche 50-000.82/11/30.8208190257
- 8):08]90259 [E Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Dic 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Reloy Sockets ' Svc list encl JORDAM, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462 064 24x Fiche 50-000, 82/12/03,8208190261
- BP:2170170 EN-82-039 on 821214, notice of violation & notice of proposed imposition of civil penalties to be issued Action based on alleged noncompliance re radiological surveys, degradation of security & operability of boron tank MOSANO,R, FLACK,E, AXELRAD,J Director's Office, Office of Inspection and Enforcement 62/12/13 ip 16450 140 24X Fiche 50-247, 82/12/13, 8212170170
- 8./08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Oas Monitoring " Svc list enci DEYOUNG: A C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- G212220366 Forwards list of topic areas for discussion at upcoming meeting on drug & alcohol abuse programs instituted per IE Info Notice 82-05 One util representative should be available to participate in entire meeting STAROSTECKIR Division of Project & Resident Programs (U*TOOLE.J D Consolidated Edison Co of New York, Inc 3pp 16517 173 24X Fiche 50-003,82/12/16.8212220366
- 6208190268 IE info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- BP12270358 Ack receipt of 821018 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-247/82-18 STAROSTECKI.R Division of Project & Resident Programs 62/12/20 0/100LE.J D Consolidated Edison Co of New York, Inc 2pp 16530 049 24% Fichs 50-247,82/12/20,8212270358
- 8212270361 Responds to NRC 820917 ltr re violations noted in IL Insp Rept 50-247/82-18 Corrective actions Temporary Procedure Change TPC-62-101 issued to resolve discrepancy between Procedure 4-26 & Tech Sper Section 3 6A O'TOOLE, J D Consolidated Edison Co of New York, Inc 82/10/18 STARDSTECKI, R Division of Project & Resident Programs 4pp 16530 051 24X Fiche 50-247, 82/12/20, 8212270358
- R Periodic operating reports & related correspondence
- G:12280219 Forwards monthly operating rept for Nev 1982 & update on isfueling info per Hartfield 780118 request O'TOCLE. J D Consolidated Edison Co of New York, Inc 82/12/15 MCD0KALD. W O Office of Resource Management, Director 16562 126 24X Fiche 50-247,82/12/15.8212280219
- --8212280221 Honthly operating rept for Nov 1982 Refueling info encl EICH, E Consolidated Edison Co of New York, Inc 82/12/02 8pp 16542 127 24% Fiche 50-247,82/12/15,8212280219
- 5 Reportable occurrences, LERs & related correspondence
- 8212040146 Forwards LER 62-045/01T-0 U/TQQLE, J D Consolidated Edison Co of New York, Inc 82/11/22 HAYNESI,R C Region 1. Office of Director 1p 16313 152 24X Fiche 50-247, 82/11/22, 8212040146

- --82:2060152 LER 82-045/01T-0 on 82:108, upper end plug from one fuel rod within assembly F-44 separated from fuel tube Cause pending investigation Affected fuel assembly will be replaced LIMD9ES.C Consolidated Edison Co of New York, Inc. 82/11/22 Region i. 0ffice of Director 2pp 16313 153 24X Fiche 50-247.82/11/22/82/2060146
- 8P12080297 Forwards LER B2-044/03L-0 U'TGOLE, J D Consolidated Edison Co of New York, Inc. 82/11/28 HAYNES,R C Region 1. Office of Director 1p 16353 358 24X Fiche 50-247, 82/11/28, 8212080297
- --8212080311 LER 82-044/03L-0 on 821029, three of first 10 snubbers tested did not meet acceptance criteria for lock-up rate % bleed Cause will be submitted following test completion Defective snubbers replaced HINRICHS.9 Consolidated Edison Co of New York, Inc 82/11/28 Region 1. Office of Director ip 16353 359 24X Fiche 50-247,82/11/28.8212080297
- 8712150023 Forwards LER 82-046/03L-0 0'TOOLE, J D Consolidated Edison Co of New York, Inc 82/11/29 HAYNES,R C Region 1. Office of Director 1p 16421 232 24X Fiche 50-247, 82/11/29, 8212150023
- --8212150027 LER 82-046/03L-0 on 821030, during transfer of blended makeup, i5 gallon spill occurred through valve N336 Caused by defective diaghragm on closed valve 370 Valve bonnet for valve 336 & bonnet & diaphragm for valve 370 replaced HIMRICHS.0 Consolidated Edison Co of New York, Inc. 82/11/29 Region t. Office of Director 2pp 16421 233 24X Fiche 50-247,82/11/29,8212150023
- BP12150080 Forwards LER B2-045/01T-0 D'TOULE, J D Consolidated Edison Co of New York, Inc B2/12/01 HAYNES, R C Region 1, Office of Director 1p 16430 162 24X Fiche 50-247, 82/12/01, B212150080
- --8212150084 LER 82-045/01T-0 on 821108, video tape insp revealed that upper end plug from fuel rod within assembly separated from fuel tube Cause not stated Assembly replaced LIMGGES.C Consolidated Edison Co of New York. Inc 82/11/22 Region 1. Office of Director 2pp 16430 163 24X Fiche 50-247, 82/12/01.8212150080
- 8212210119 Forwards LER 82-047/03L-0 0/TOCLE.J D Consolidated Edison Co of New York, Inc. 82/12/04 HAYNES, R C Region 1. Office of Director 1p 16485 141 24X Fiche 50-247, 82/12/04,8212210119
- --8212210140 LER 82-047/03L-0 on 821104, during refueling/maint outage, pressuriter safety valves discovered outside tolerance cause not stated Valves refurblebed, readjusted & toested HIMRICHS.9 Consolidated Edison Co of New York, Inc. 82/12/04 Region 1. Office of Director 2pp 16485 142 24X Fiche 50-247, 82/12/04, 8212210119
- 82:12210128 Forwards LER 82-048/03L-0 0/TOCLE.J D Consolidated Edison Co of New York, Inc 82/12/05 HAYNES:R C Region I. Office of Director ip 16485 194 24X Fiche 50-247,82/12/05,8212210128
- --8212210133 LER 82-048/03L-0 on 821105, air flow through reactor containment fan coaler unit 24 charcoal filter found 7% less than required by Tech Specs Cause under investigation Fresh charcoal placed in trags & sys retested HINRICHS:0 Consolidated Edison Co of New York, Inc 82/12/05 Region 1. Office of Director ip 16485 175 24% Fiche 50-247,82/12/05.8212210128
- T Hearing transcripts on non-antitrust matters
- B212070049 Transcript of 521203 telephone conference in Washington,DC Pp 4:856-4:888 * Atomic Safety and Licensing Board Panel 82/12/03 33pp 14327 295 24% Fiche 30-247.82/12/03,8212070049
- BP1215000B Forwards RL Goldferb testimony & lists order of witnesses to testify Related correspondence VETERE/LA Westchester County, NY 82/12/09 GLEABDN, J.P., PARIS, O.H., BMON, F.J. Atomic Sefety and Licensing Board Penel 1p 14421 130 24X Fiche 50-247,82/12/09,8212150008
- B212150013 Yestimony of RA Goldfarb re law enforcement conterns w/
 emergency plan ASLB should consider effectiveness of
 emergency plan w/o adequate police communications sys
 Certificate of Svc encl
 GGLDFARB.R A Westchester County.NY GOLDFARB.R A Ossining, NY
 82/12/09 Spp 16421 131 24X Fiche 50-247.82/12/09.8212150008

- 8212300235 Transcript of Commission 821221 meeting in Hashington.DC repossible action concerning emergency preparedness at facilities Supporting documentation & viewgraphs encl * Commissioners 82/12/21 121pp 16624 037 24X Fiche 50-003.82/12/21,8212300235
- U Congressional/Executive Correspondence
- 6:/12230341 Requests NRC statement of Commission basis for determination that reasonable assurance exists that public health & safety will be adequately protected in event of large nuclear accident UDALL.M K House of Rep. Interior & Insular Affairs 82/12/15 PALLADING.N J Commissioners 2pp 16511 126 24X Fiche 30-247.62/12/15/8212230341
- 6212230276 Urges consideration of all info re adequacy of emorgency plans & current state of amergency preparedness All steps must be taken to ensure adequacy of emergency planning FISH. H, OILMAN.B, BINONAM.J House of Rep B2/12/20 Commissioners 3pp 16508 277 24X Fiche 50-247.82/12/20.
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, nedical, emergency & fire protection plans
- BP12030283 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 82/11/30 Document Management Branch ip 16316 253 24X Fiche 50-010, 82/11/30, H212030283
- --8212030286 Forwards public version of revised emergency plan implementing procedures including Procedure EPIP 100-2 reshift turnover witechnical support ctr & environ teams activated Receipt forms & procedure histories encl SCOTI.D J Commonwealth Edison Co 82/11/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 7pp 16316 255 24% Fiche 50-010,82/11/30.8212030283
- --8212030287 Public version of revised emergency plan implementing procedures, including Procedure EPIP 100-2 re shift turnover u/technical support ctr & environ teams activated commonwealth Edison Co 62/11/17 14pp 16316 262 24X Fiche 50-010, 82/11/30, 8212030283
- 8212090393 Forwards info re emergency operations facilities per 021122 & 1202 requests Info previously submitted by telicon Request for written response unnecessary burden on licensee DELGEORGE, L O Commonwealth Edison Co 82/12/03 EISENHUT, D G Division of Licensing 2pp 16365 051 24X Fiche 50-000, 82/12/03, 82/2070383
- 8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Uffsite Monitoring Locations (Maps)"
 FELTON, J H Division of Rules and Records 82/12/07 Documen Management Branch ip 6417 062 24X Fiche 50-000, 82/12/07, 6212130017
- --B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EO-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "Revised table of contents enc!
 PAJDUSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -- No Detailed Affiliation Given 2pp 16417 063 24X
 Fiche 50-000,82/12/07.8212130017
- -8212130041 Public version of Revision I to Emergency Plan Implementing Procedure EO-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "PAJOHSKI, J. E. LITERSKI, L. A. Commonwealth Edison Co. 82/11/29 4pp 16417 065 24X Fiche 50-000,82/12/07,8212130017
- GP12140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMM, T.R. Commonwealth Edison Co. 82/12/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16409-302 24X Fiche 50-000.82/12/07.8212140243
- 8212210118 Forwards IE Emergency Preparedness SERs 50-237/82-27 & 50-247/82-27 during Nov 1981 & June 1982, respectively No noncompliance noted HIND.J A Division of Emergency Preparedness 82/12/10 REED.C Commonwealth Edison Co. 2pp 16485 088, 24X Fiche 50-237,82/12/10,8212210118

- --8212210124 IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dtd Nov 1981 & June 1982, respectively Planning stds met PHILLIPS,M P Region 3, Office of Director 82/12/07 29pp 16485 091 24X Fichs 50-237,82/12/10,8212210118
- 8212220175 Releases public version of revised generating station omergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fiche 50-000,82/12/10,8212220175
- --8212520190 Forwards public version of revised generating station energency plan (mplementing procedures, including Procedures ED-3 re denand polling of meteorological data & ED-20 re emergency forecast request PAJOHSKI.J E Commonwealth Edison Co 82/11/15 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 16529 030 24% Fichs 50-000,82/12/10,8212220175
- --H212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSXI, L A , PAJOHSKI, J E Commonwealth Edison Co 82/10/13 48pp (4527 031 24X Fiche 50-000, 82/12/10, 8212220175
- BPIR230019 Releases public version of revised emergency plan implementing procedure FELTON.JM Division of Rules and Records 82/12/15 Document Management Branch 1p 16545-350 24X Fiche 50-010.82/12/15.8212230019
- --921223002B Forwards public version of Revision i to Emergency Plan Implementing Procedure EPIP 500-1, "Quarterly Inventory of First Aid Supplies" SCOTT.D J Commonwealth Edison Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 16545 351 24X Fiche 50-010,82/12/15,8212230019
- --8212230042 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP 500-1, "Guarterly Inventory of First Aid Supplies " Revised index encl * Commonwealth Edison Co 82/11/22 App 16545 354 24X Fiche 50-010,82/12/15,8212230019
- BRI2R20306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site remergency operations facility KEPPLER, J.O. Region 3, Office of Director 82/12/16 Commonwealth Edison Co. 3pp. 16503-351 24X Fiche 50-000.82/12/16, 6212220306
- 8P12280214 Forwards IE Safeguards Insp Repts 50-010/82-20,50-237/82-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10CFR73 21)
 MILLER, J.R. Division or Engineering & Technical Programs 82/12/20 REED.C. Commonwealth Edison Co. 2pp 16562 120 24X
 Fiche 50-010,82/12/20,8212280214
- --B212280220 IE Safeguards insp Repts 50-010/82-20.50-237/82-28 & 50-249/82-27 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Details withheld (ref 10CFR73 21) CHRISTUFFER.0 Division of Emergency Preparedness & Operational Support 82/12/15 2pp 16562 122 24X Fiche 50-010.82/12/20, 6212280214
- BB12300167 Releases public version of revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167
- ---B212300179 Forwards public version of revised generating station emergency plan telephone directory MDDRER D Commanwealth Edison Co 82/12/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000,82/12/20,8212300167
- --B212300197 Public version of revised generating station emergency plan telephone directory GALLED P Commonwealth Edison Co B2/11/05 60pp 16612 217 24X Fiche 50-000.82/12/20,8212300167

G Adjudicatory correspondence

- GP12070160 Memorandum % order granting licensee 820818 request to dismiss proceeding w/o projudice Util received authority to increase spent fuel pool storage capacity,making shipment of spent fuel between plants unnocessary JOHNSON,E B , STOBER,G J , MILHOLLIN,G L Atomic Safety and licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp 16336 320 24X Fiche 50-000.82/12/03.8212070160
- H General correspondence
- G./12280176 Notifies of change in mailing address for NRC licensing matling matter of the state of the state
- P Operating license stage documents & correspondence
- B2]2020110 "Analysis of Spectrum of Large-Break LOCAs in BWR/3 Using TRAC-BD1." Vols 1 & 2.interim rept DAVIS.C B E0&G. Inc FIN A-6047 B212020110 B2/10/31 ODAN,F Office or Nuclear Regulatory Research, Director 243pp 16310 033 24X Fiche 50-249.82/10/31.8212020110
- 8.12140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located sub; to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 QALLO, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000,82/11/03,6312140001
- --8009110797 Forwards excerpt from utils 680801, "Rept to Btockholders," re effect of 680515 tornadoes on util 345 kV sys DEMFON.H R Atomic Energy Commission 68/08/14 TEDESCO,R L Atomic Energy Commission 2pp 16434 254 24X Fichs 50-000.62/11/03.8212140001
- E/H230066 Generic Ltr B2-27 to all BMR licensees of operating reactors except LACBUR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for GL & holders of CP retrieval to the following transmittel of NUREO-0763 & NUREO-0763 Svc list encl W/o stated encl LISENHUT, D @ Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X
- 82:12160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp & Festing Program, Dresden Units 2 & 3 " Response to NRC questions & comments & procedures for reactor vessel 1.000 psi & ASME hydrostatic tests & quarterly valve timing encl RAUSCH.T J Commonwealth Edison Co 82/12/10 EISENHUT.D 9
 Division or Licensing 44pp 16441 088 24X Fiche 50-237.82/12/10.8212160326
- --9212160334 Revision I to "Second 10-Yr Inservice Insp & Testing Program Dresden Units 2 & 3 " * Commonwealth Edison Co 82/12/31 250pp 16441 132 24X Fische 50-237,82/12/10,8212160326
- --8212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 14518 007 24X Fiche 50-000, 82/12/14, 8212220212
- GP12280117 Forwards add1 info re NUREG-0737, Item II F i. "Add1 Accident Monitoring Instrumentation." per NRC 821109 request Pressure monitoring sys provided w/separate loop for narrow range monitoring SHARTZ.E D Commonwealth Edison Co G2/12/20 EISENHUT, D G Division of Licensing 7pp 16564 062 24X Fiche 50-000, 82/12/20, 8212280117
- 09/12380343 Forwards addl info re NUREO-0737. Items II F 1 4.5 & 6
 "Containment Pressure, Mater Level & Hydrogen Monitoring,"
 per Crutchfield 821109 ltr
 SMARTZ.E D Commonwealth Edison Co 82/12/20 EISENHUT, D 0
 Division of Licensing 9pp 16561 053 24X Fiche 50+000, 82/12/20,
 8212280343
- B?12280212 Forwards updated schedule for engoing environ qualification testing programs, per 810528 commitment BMARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D 9 Division of Licensing 18pp 16556, 161 24X Fiche 50-000, 82/12/22, 8212280212

- 8212280263 Clarifies position on classification of major mods to BWR Mark I Containment per 821216 ltr RAUSCH.T J Commonwealth Edison Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 307 24X Fichs 50-000.82/12/22,8212280263
- O Inspection reports. IE Bulletins & carrespondence
- Bir08170240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Paping at BWR Plants "Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Inforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 82/08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372-142 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan (xercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- BrD8190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8209190256
- G212060036 Ack receipt of 821028 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-13, 50-237/82-17 % 50-249/82-18
 BYRETER, JF Region 3, Office of Director 82/11/26 REED.C Commonwealth Edison Co 1p 16313 284 24% Fiche 50-010,82/11/26,8212060036
- --B212060045 Responds to NRC B20728 ltr re violations noted in It Insp Repts 50-010/82-13, 90-237/82-17 & 50-247/82-18 Corrective actions inservice leak best performed on water leg portion of torus level med Training session scheduled DELOEDROEL O Commonwealth Edison Co B2/10/28 KEPPLER. J G Region 3, Dffice of Director 3pp 16313 285 24X Fiche 50-010,82/11/26,8212060036
- 82/12/70300 Forwards IE Insp Repts 50-010/82-19.50-237/82-26 & 50-249/82-26 on 82/104-05 No noncompliance noted LITTLE.W 8 Division of Engineering & Technical Programs 82/11/29 REED.C Commonwealth Edison Co 2pp 16453 206 24X Fiche 50-010.82/11/29.8212170300
- --8212170306 IE insp Repts 50-010/82-17,50-237/82-26 & 50-249/82-26 on 821104-05 No noncompliance noted Major areas inspected licensee actions on previously identified items REIMANN,F W., JACKIW,I N. Davision of Engineering & Technical Programs 62/11/24 4pp 16453 208 24X Fiche 50-010,82/11/27,8212170300
- 8:08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mat!" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York
- 8212030178 Forwards final SALP Repts 50-010/82-10.80-237/82-14 & 50-247/82-15 for assessment period Jul 1980-Dec 1981, discussed at IE mgt meeting on 820602 Util 820648 comments on 8ALP rept addressed KEPPLER.J O. Region 3. Office of Director 82/12/01 REED.C Commonwealth Edison Co Spp 16303 228 24% Fiche 50-010.82/12/01, 8212030178
- --8212030185 BALP Repts 50-010/82-10,50-237/82-14 & 50-249/82-15 for assessment period Jul 1980-Dec 1981 Mgt attention warranted in areas of plant operations, radiological controls & review committee activities

 * Region 3, Office of Director 82/05/31 47pp 16303 231 24X Fiche 50-010,82/12/01,8212030178
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUND,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259

- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay hockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc | Hopp | 16462 064 | 24x Fiche 50-000, 82/12/03, 8208190261
- 8212170196 Forwards IE insp Repts 50-010/62-18,50-237/82-25 & 50-249/82-25 on 821002-29 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/12/03 REED.C Commonwealth Edison Co 2pp 16450 153 24% Fichs 50-010,82/12/03.8212170196
- --B212170201 IE Insp Repts 50-010/B2-18,50-237/B2-25 th 50-249/B2-25 on B21002-27 No noncompliance noted Major areas inspected headquarters & regional requests operational safety verification, monthly maint observation & LERs TONOUE, I M., STASEK, S., MALKER, R. D. Division of Project & Resident Programs B2/12/01 Bpp 16450 155 24X Fiche 50-010.82/12/03, B212170196
- Gal2160326 Forwards Revision 1 to "Second 10-Yr Inservice Insp & lesting Program, Bresden Units 2 & 3 " Response to NRC questions & comments & procedures for reactor vessel 1,000 ps; & ASME hydrostatic tests & quarterly valve timing enc! RAUSCH: T J Commonwealth Edison Co 82/12/10 EISENHUT, D G Division of Licensing 43pp 16441 088 24X Fiche 50-237,82/12/10, 82/2160324
- --8212160334 Revision 1 to "Second 10-Yr Inservice insp & Testing Program Dresden Units 2 & 3 " * Commonwealth Edison Co 82/12/3: 268pp 16441 132 24X Fiche 50-237, 82/12/10 8212160326
- 8212210118 Forwards IE Emergency Preparedness SERs 50-237/82-27 & 50-249/82-27 during Nov 1981 & June 1982, respectively No nancopyliance noted HIND, J A Division of Emergency Preparedness 82/12/10 REED, C Commonwealth Edison Co. 2pp. 16485-088 24% Fiche 50-237,82/12/10,8212210118
- --8212210124 IE Emergency Preparadness SERs 50-237/82-27 & 50-249/82-27 Major areas inspected emergency plan & site-specific annex dtd Nov 1981 & June 1982, respectively Planning stds met PHILLIPS.M P . AXELSON.W L . PAPERIELLO.C J Region 3. Office of Director 82/12/07 29pp 16485 091 24X Fiche 50-237.82/12/10, 8212210118
- 8208190247 IE Info Natice 82-49, "Correction for Sample Condutions for Air & Cas Monitoring " Svc list enc! DE10UNO, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Concellated Edison Co of New York, Inc 127pp 16428 191 24X Fiche 50-000.82/12/14.8208190267
- B212270295 Ack receipt of 821124 ltm informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-237/82-21, 50-249/82-22, 50-254/82-17 & 50-245/82-19 NORELIUS.C E. Division of Engineering & Technical Programs 62/12/16 REED, C. Commonwealth Edition Co. 2pp. 16530 085 24% Fiche 50-000, 82/12/16, 8212270275
- --B212270303 Responds to NRC 021026 ltr re violations noted in IE Insp Repts 50-237/02-21,50-249/02-22.50-254/02-17 & 50-265/02-19 Corrective actions annual audits of all active AE firms performing safety-related work required DELOCORCE, L O Commonwealth Edison Co 02/11/24 MEPPLER, J Q Region 3. Office of Director 4pp 16530 087 24X Fichs 50-000,02/12/16,8212270293
- --8212270313 "IE Bulletin 79-14 & TAP Piping Evaluation, Guad Cities Units 1 & 2 & Dreaden Units 2 & 3," Revision 0 • NUTECH (Nuclear Technology, Inc.) 82/10/01 9pp 16530 113 246 Fiche 50-000, 82/12/16, 8212270295
- B212280110 Provides final status rept of IE Builetin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Complete & final listings of portions of sys failing to meet FSAR requirements under NYECH responsibility enci RAUSCH.T.J. Commonwealth Edison Co. 62/12/17 KEPPLER.J.G. Region G. Ofrice of Director. 3pp. 16564 191 24X Fichs 50-000,82/12/17,8212280110
- 8212290376 Forwards IE Insp Rept 50-249/82-28 on 821107.10 & 12 & notice of violation
 LITTLE.W S Division of Engineering & Technical Programs 82/12/17
 REED.C Commonwealth Edison Co 2pp 16586 270 24X
 Little 50-249,82/12/17,8212290376

- --8212290380 Notice of violation from insp on 821109,10 & 12 LITTLE,M S Division of Engineering & Technical Programs 82/12/17 ip 16586 272 24X Fiche 50-249,82/12/17,8212290376
- --8212290386 [E Insp Rept 50-249/82-28 on 821109.10 % 12 Noncompliance noted Revision 3 to DTS 8237 on calculation of core thermal power -- technical staff method reviewed % approved w/o review & approved of associated computer program ROBINSON.D L , JACKIM.I N Region 3. Office of Director 82/12/10 6pp 16386 273 24% Fiche 50-249.83/12/17.82122903/6
- 8208190268 IE Info Notice 82-50, "Mod of 8011d State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E C Division of Engineering & Quality Assurance 82/12/40 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x [(che 50-008,82/12/20,8208190268
- 8/12/28/0214 Forwards IE Bafeguards Insp Repts 50-010/82-20.50-237/62-28 & 50-249/82-29 on 821115-19 Details & notice of violation withheld (ref 10/2673 21)
 MILLER, J R D(vision of Engineering & Technical Programs 82/12/20 REED, C Commonwealth Edison Co 2pp 16562 120 24X | 1che 50-010, 82/12/20.8212280214
- --G212280220 [E Safeguards Insp Repts 50-010/82-20, 50-237/82-28 & 50-249/82-29 on 821115-19 Noncompliance noted failure to adequately control security-related key as required by security plan Betails withheld (ref [OCFR73 21] CHRISTOFFER.0, KNICELEY.J R. CREED, J R. Division of Emergency Preparedness & Operational Support 92/12/15 2pp 16562 [22 24X Fiche 50-010.82/12/20,8212280214
- B212280070 Requests addition of RE Farrell to unescorted access list to vital & protected areas Individual possesses Q clearance MEPPLER, J O Region 3. Office of Director 82/12/22 REED, C Commonwealth Edison Co 1p 16565 136 24X Fiche 50-010,82/12/22,6212280070
- R Periodic operating reports & related correspondence
- 8.42140077 "1982 Evaluation. Dresden Nuclear Power Station. Comm Ed Co " * Institute of Nuclear Power Operations 82/11/30 39pp 14403 171 24% Fiche 50~010.82/11/30.8212140077
- G212140112 Forwards monthly operating repts for Nov 1982 SCOTT.D J Commonwealth Edison Co 82/12/01 Director's Office. Orfice of Inspection and Enforcement Ip 16408 204 24X Fiche 50-010.82/12/01.8212140112
- --8212140120 Monthly operating repts for Nov 1982 SCHRDEDER.B A Commonwealth Edison Co 82/12/01 28pp 16403 205 24X Fiche 50-010,82/12/01,8212140[12
- S Reportable occurrences, LERs & related correspondence
- BP12680375 Forwards updated LER 82-008/03x-1 SCOTT.D J Commonwealth Edi≰on Co 82/11/04 KEPPLER, J G Reqion 3. Office of Director ip 16353 310 24X Fiche 90-249,82/11/04. 0212080375
- --B2120803B1 Updated LER 82-008/03X-1 on 820126, while performing refuel surveillance DIS 2300-7, callibr testing discovered HPC1 temp suitches 237(A, 23726, 2370C & 2370D above Tech Spec limit Caused by vibration loosening set screus ANANDAPPA: A Commonwealth Edison Co 82/11/04 Region 3, Office of Director 2pp 16353 311 24X Fiche 50-249,82/11/04, 8212080375
- GP12290472 Forwards updated LER 82-028/03X-1 SCOTT.D J Commonwealth Edison Co 82/11/08 KEPPLER, J Q Region 3. Office of Director 1p 16583 255 24X Fichs 50-249,82/11/08, 8212290472
- --B212290478 Updated LER 82-028/03X-1 on 820708, switch PS 1554 F tripped above Tech Spec limit Caused by poor maint on HX during bottom head removal allowing water to fall onto instrument rack Rack covered & linkage tested CDYLE, L Commonwealth Edison Co 82/11/08 Region 3, Office of Director 2pp 16583 256 24% Fiche 50-249,82/11/08,8212290472
- BP12020337 Forwards LER 82-044/03L-0 SCOTT.D J Commonwealth Edison Co 82/11/19 KEPPLER.J O Region D. Office of Director 1p 16278 175 24X Ficho 50-249,82/11/15. 8212020337

- 8212020357 LER 82-044/03L-0 on 821102, during routine surveillance, 212020357 LER 92-044/03L-0 on 821102, during routine surveill DIS-700-3, high trip (rod block) on source range monitor 24 found to trip above allowable limits Caused by setpoint drift on hi alarm potentiometer Setpoint reset BETWERLY, K Commonwealth Edison Co. 82/11/15 Region 3, of Director 1p 16278 176 24% Fiche 50-249,82/11/15. Region 3, Office
- OPI2170134 Forwards updated LER 82-038/03X-1 SCOTT,D J Commonwealth Edison Co 82/11/15 KEPPLER,J Q Regio 7, Office of Director 1p 16439 166 24X Fiche 50-249,82/11/15,
- --9212170139 Updated LER 82-038/03X-1 on 821001 during main steam line 212170139 Updated LER BZ-USB/USX-1 on MEJOUI.during main steam line high redulation scram & isolation surveillance radiation monitor 1705-2A tripped at 1.400 m/h Caused by instrument drift Setpoint adjusted to 1.460 m/h RHEE.S Commonwealth Edison Co BZ/11/15 Region 3, Office of Director ip 14459 147 24X Fiche 50-249, 82/11/15, 8212170134
- 0/12020239 Forwards LER 82-043/03L-0 3, Office of Director ip 16274 153 24X Fiche 50-249.82/11/14.
- --8212020248 LER 82-043/03L-0 on 821028.magnetrol level switches 82D & ### Description of the property of the propert 9212020239
- GP:12170218 Forwards LER 02-046/03L-0 5COTT.D J Commonwealth Edison Co 82/12/03 KEPPLER.J Q Regio 3. Office or Director 1p 16459 354 24X Fiche 50-249.82/12/03.
- G212170225 LER 82-046/03L-0 on 821112.water discovered spraying from 1-inch drain line off bottom of feedwater regulator isolation valve 3A Caused by cracked weld at 1-inch chain line due to stresses from thermal effects CHRISTEL B Commonwealth Edison Co 82/12/03 Region of Director ip 16459 355 24% Fiche 50-249,82/12/03,82/12/03 Region 3, Office
- 8212070415 PNO-111-82-132 on 821203 licenses declared alert when level of flood-swallen IL River threatened svc water pumps & diesel fire pumps inside crib house Shutdown initiated Alert canceled on B21204 Units returned to power on B21205 Hults returned to power on B21205 HALKER, T. TONGUE, T. SPESSARD, R. Region 3, Office of Director B2/12/06 ip 16365 032 24% Fichs 50-237.82/12/06.B212090415
- G212170077 Forwards LER 62-047/03L-0 SCOTT, D J Commonwealth Edison Co G2/12/06 KEPPLER, J G Regio 3. Office of Director 1p 16450 319 24X Fiche 50-249,82/12/06.
- B212170102 LER 82-047/03L-0 on 821117, during normal operation, w/reactor vessel low water level ECCS initiation in progress. IS
 263-72-C found set at til 0 inches delta P Caused by
 defective procedure LIS 263-72-C reset
 CDYLE. L Commonwealth Edison Co. 82/12/06 Region 3, Office of
 Director 1p 16450 320 24X Fiche 50-249,82/12/06,8212170097
- 8./12290369 Forwards updated LER 82-037/03X-1 SCOTT, D J Commonwealth Edison Co 82/12/10 KEPPLER, J G Regio 3. Office of Director 1p 16586 361 24X Fiche 50-249,82/12/10.
- ELECTUSED Updated LER 82-037/03X-1 on 820922.during normal operation. TIP ball valve 3E would not automatically recluse using control suitch Caused by possible hardened lubrication causing valve to drag Spring retensioned to overcome drag MORGAN, W.E. Commonwealth Edison Co. 82/12/10. Region 3. Office of Director 2pp 14586-362 24X Fiche 50-249,82/12/10,8212290369 --B2122703B5 Updated LER 82-037/03X-1 on 820922.during normal operation.
- 0212290329 Forwards LER 02-048/03L-0 17T, D. J. Commonwealth Edison Co 82/12/20 KEPPLER, J G Regio Office of Director 1p 16586 231 24X Fiche 50-249,82/12/20, SCOTT, D J
- --B212270333 LER 82-048/03L-0 on 821126, during normal operation, oxygen analyzer failed w/high oxygen alarm up in control room Caused by failure of light bulb for light unit that activates photoelectric cell of analyzer Bulb replaced ATA: H Commonwealth Edison Co B2/12/20 Region 3, Office of Director 2pp 16586 732 24X Fiche 50-247,82/12/20.8212270327

- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8212090529 Forwards IE Insp Repts 50-250/82-11 % 50-251/82-11 on DANCE, H C Division of Project & Resident Programs 82/10/2
 UHRIG, R E Florida Power & Light Co 2pp 16366 108 24X Fiche 50-250, 82/10/29, 8212070529
- --8212090540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 No el20/0340 le insp kepts 30-23/92-11 a 30-23/24-11 on U210/4-08 / noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys HUFFMAN.6 N . JENKINS.G R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X Fiche 50-250,82/10/29,8212090529
- 8P12290040 Partial response to FDIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl FELTON.J M Division of Rules and Records 82/11/30 GCHLISSEL,D A New York, State of 7pp 14607 239 24X Fiche 50-000, 82/11/30, 8212290060
- --8212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire Repts 50-250/75-07 & 50-251/75-07 corrective actions fire stops installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary bldg above main corridor doors UHRIG.R C Florida Power & Light Co 75/06/20 MOSELEY.N C Region 2. Atlanta. Office of the Director 2pp 16607 355 Fiche 50-000.82/11/30.8212290060
- --B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14
 Deviation observed one tray of control cables in Unit 3
 control rod drive room & cable trays exiting auxiliary
 bldg did not have fire stops installed
 HARDIN,A K Region 2. Atlanta. Office of the Director 75/05/6
 9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212290060 75/05/27
- J Insurance & indemnity information
- GP12020335 Forwards Endorsements 40 & 61 to NELIA Policy NF-185 & Endorsements 50 & 51 to MAELU Policy MF-55
 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc.
 Div G2/11/19 GALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 16279 151 24X Fiche 50-250, 82/11/18,8212020335
- 8912300202 Forwards Endorsements 1.2 & 3 to NELIA Certificates N=25 & N=26 & Endorsements 1.2 & 3 to MAELU Certificates M=25 & 192/12/27 SALITMAN, J Assistant Nington Consultants, Inc. Div M-26
- SALTIMAN, J Assistant Director for State & Licensue 37pp 16598 050 24X Fiche 50-250,82/12/27,8212300202
- 8212300243 Forwards Endorsement 62 to NECIA Policy NF-185 & Endorsement 12 to MAELU Policy MF-35 BUCK.J R Marsh & McLennan. Inc , M & M Nuclear Consultants, Inc Div 82/12/27 SALTZMAN.J Assistant Director for State & Licensee Relations 3pp 16595 273 24X Fiche 50-250, 82/12/27, 8212300243
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B212070435 Discusses summary of ACRS Reactor Operations Subcommittee B20927 meeting re Turkey Point cold overpressure incident lech Specs do not properly address situations in which availability of certain sys more vital to safe operation BINFORD, FT Oak Ridge National Laboratory B2/10/19 MAJOR, R ACRS Advisory Committee on Reactor Safeguards 1p 16355 336 24X Fiche 50-250,82/10/19.6212070435
- P Operating license stage documents & correspondence
- B2:2170273 Forwards "Turkey Point Unit 3 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance" & "Turkey Point Unit 4 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance" W/o rept for Unit 4 UHRIGR E Florida Power & Light Co 82/12/03 EISENHUT.D Q Division of Licensing 2pp 16461 183 24X Fiche 50-250.82/12/03, 8212170273
- --8212170276 "Turkey Point Unit 3 Containment Structure Post-Tensioning Sys Tenth-Yr Surveillance " GREENK , LEE, K Y Bechtel Corp 82/07/31 107pp 16461 J85 244 Fiche 50-250,82/12/03.8212170273

- 8208190263 Generic Ltr 82-92 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subjirequirements Comments requirested within 30 days of ltr Svc list encl EISE/HHUT, D. G. Division of Licensing 82/12/07 Consolidated Edison Co of New York, Inc. 27pp. 16629 247 24X Fiche 50-000,82/12/09,8208190263
- 8912140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PNRs (except Arkansas Nuclear One, Unit 2 & San Dinofre 2 & 3) re insadequate core cooling instrumentation sys Svc list encl EISENHUT, D @ Division of Licensing 62/12/10 Yankee Atomic Electric Co 27pp 16690 035 24x Fiche 50-000,82/12/10, H212140103
- GP12210190 Informs that util will utilize Westinghouse optimized fuel assemblies during Fall 1983 refueling UHRIGR E Florida Power & Light Co 62/12/13 EISENHUT, D G Division of Licensing 1p 16484 353 24X Fiche 50-250,82/12/13,6212210190
- OP12290534 Forwards safety & technical evaluations for environ qualification of safety-related electrical equipment Reaffirmation of justification for continued operation & info re Categories | B.11 A & || B requested VARGA.5 A Operating Reactors Branch | B2/12/13 UHRIG.R E Florida Pour & Light Co || 3pp | 16608 061 24% Fiche 50-250,82/12/13.8212290534
- --8212270535 SER re environ qualification of safety-related electrical equipment

 * Operating Reactors Branch 1 82/12/13 5pp 16408 064 24% Fiche 50-250,82/12/13.8212270534
- --8210070227 "Review of Licensees Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60). Torkey Point Unit 4," Vols 1 & 2, technical evaluation rept PANDEY, S. Franklin institute/Franklin Research Center NRC-03-79-118 TER-C\$257-480 82/09/30 LE.N D NRC No Detailed Affiliation Given 778pp 16608 069 24% Fiche 50-250,82/12/13:8212290534
- --B212290535 "Review of Licensee Resolution of Butstanding Issues From NRC Equipment Environ Gualification SERs (F-11 & B-60)," Vols t & 2. (sechnical evaluation rept FANDEY, 8 Franklin Institute/Franklin Research Center TER-05257-479 82/09/30 LE, N E , SHEMANSKI, P NRC No Dotailed Affiliation Given 807pp 16610 128 24X Fiche 50-250,82/12/13,8212290534
- 8212300068 Forwards safety evaluation & technical evaluation rept supporting station electric distribution sys voltages VAROA/S A Operating Reactors Branch I 82/12/17 UHRIG,R E Florida Power & Light Co 2pp 16624 213 24X Fiche 50-250-82/12/17,8212300068
- --8212300071 SER supporting station electric distribution sys voltages * Operating Reactors Branch 1 82/12/27 Spp 16624 215 24X Fiche 50-250, 82/12/17, 8212300068
- --8209230424 "Adequacy of Station Electric Distribution Sys Voltages for Turkey Point Nuclear Generating Plant Units 3 & 4." technical evaluation rept SELAN.J C Laurence Livernore Laboratory F[N A-0250 UCLD-19148 82/08/08 NRC - No Detailed Affiliation Given 13pp 16624 220 24X Fichs 50-250.82/12/17.8212300068
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel. Recirculation Sys Piping at BKR Plants " Syc list encl BEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc J12pp 16462 163 24% Fiche 50-000.82/10/28.8208190240
- B212090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on B21004-10 Nd noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/29 UHRIG,R E Florida Power & Light Co 2pp 16366 108 24X Fiche 50-250,82/10/29,8212090529
- --8212090540 IE Insp Repts 50-250/82-i1 & 50-251/82-i1 on 821004-08 No moncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys HUFFMAN O N . JENKINS O R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 16366 110 24X Fichs 50-250,82/10/29,8212090529

- U208190245 IE Into Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list cnc!

 (OBB.L I Division of Fuel Facilities, Materials & Sareguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fichs 50-000.82/11/05.8208190245
- 8212990490 Forwards IE Insp Repts 50-250/82-31 & 50-251/82-31 on B21018-22 No noncompliance noted DANCE,H C Region 2, Office of Director 82/11/12 UHRIG.R C [forida Power & Light Co 2pp | 16365 344 24x [riche 50-250.82/11/12.8212090490]
- -8212070500 IE Insp Repts 50-250/82-31 % 50-251/82-31 on 821018-22 No noncompliance noted Major areas inspected radiation protection program including qualification of staff, training & radiological protection procedures HOSEY, C. M. DEOS, B. T. DARR, K. P. Division of Engineering & Technical Programs 82/11/12 10pp 16365-346 24X Fichs 50-250,82/11/12,8212090490
- B212090407 Ack receipt of B21029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-29 & 50-25/482-29 JANCE, H C Division of Praject & Resident Programs 82/11/16 UHRIO, R E Florida Power & Light Co ip 16366 001 24X Fiche 50-250.82/11/16.B212090487
- --B212070503 Responds to NRC 870727 ltr re-violations noted in IE Insp. Repts 50-250/82-27 & 50-251/82-27 Corrective actions procedure revised to clarify policy for tagging motor operated valves
 UHRIG.R E Florida Power & Light Co 82/10/27 D'REILLY, J P Region 2. Office of Pirector 2pp 16366 002 24X
 Fiche 50-250, 82/11/16, 8212090487
- --8212090510 Forwards IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820724-0826 & notice of violation DANCE, H C Division of Project & Resident Programs 82/09/29 UMRIGAR E Florida Power & Light Co 2pp 16366 004 24% Fiche 50-250, 82/11/16, 8212090487
- --B212090518 Notice of violation from insp on B20724-0826 * Division of Project & Resident Programs B2/09/29 ip 16366 006 24X Fiche B0-250.82/11/161.8212090491
- --8212090524 IE Insp Repts 50-250/82-29 % 50-251/82-29 on 820724-0826 Noncompliance noted failure to follow equipment clearance procedure for motor operated valve in safety injection sys VD07-LCMELL, R. JULIAN. C Division of Project & Resident Programs 82/09/24 App 16366 007 24X Fiche 50-250.82/11/16.8212090487
- 82/08/9025) IE Info Notice 82-44. "Clarification of Emergency Plan Lyarcise Requirements" Svc list encl JORDAN, E.L. Division of Engineering 5 Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 144/1 199 2/47 Fiche 50-000, 82/11/18, 8208/90251
- G20B190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUNG.R C Director's Dffice, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000, 82/11/26, 8208190256
- 8/08/190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl (OBB: L I Division of Fuel Facilities, Materials & Safeguards 02/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 82:12270060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR prafiles for Ginna & Indian Point 3 encl FELTON, J M Division of Rules and Records 82/11/30 ScHLISSEL, D A New York, State of 7pp 16607 237 24X Fiche 50-000, 82/11/30,8212270060
- ---B212290064 Ack receipt of 750714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08 MOSELEY, N C Region 2. Atlanta, Office of the Director 75/08/01 UNRIO, R E Florida Power & Light Co ip 16607 332 24X Fiche 50-000, 82/11/30, 8212290060
- --8212270066 Responds to NRC 750525 ltr reviolation noted in IE Insp. Repts 50-250/75-08 & 50-251/75-08 Corrective actions superseded procedures for surveillance testing removed & latest revision placed in control room on 750526 UHRIGRE Florida Power & Light Co. 75/07/14 MOBELEY, N.C. Region 2. Atlanta, Office of the Director Spp. 16607 333 24X Fiche 50-000, 82/11/30, 8212270060

- --8212290073 Forwards IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance moted MOSELEY,N C Region 2, Atlanta, Office of the Director 75/06/25 UHRIG,R E Florida Power & Light Co 2pp 16607 336 24X Fiche 50-000,82/11/30,8212290060
- --B212240078 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test HARDIN,A K , LONG,F J , WILBER,H A Region 2, Atlanta, Office of the Director 75/06/24 15pp 1660/338 24X Fiche 50-000,82/11/30.8212290060
- --9212290092 Forwards listed documents re IE Insp Repts 50-250/75-07 & 50-251/75-07 Documents filed in LPDR MOGELEY.N C Region 2. Atlanta. Office of the Director 75/07/21 SUBER,F T Homestead.FL tp 16607 353 24X Fiths 50-000.82/11/30.8212290060
- --G212270097 Forwards listed documents re IE Insp Repts 50-250/75-16 & 50-251/75-16 Documents filed in LPDR
 MOSELEY,N C Region 2, Atlanta, Office of the Director 76/01/05
 PEELER,E Florida International Univ 1p 16607 281 24X
 Fiche 50-000,82/11/30.8212290060
- --8212290090 Ack receipt of 790620 ltr informing NRC of steps taken to correct deviation noted in 1E Insp Repts 50-250/79-07 & 50-251/75-07
 MOSELEY,N C Region 2. Atlanta, Office of the Director 75/07/21
 UHRIG:R E Florida Fower & Light Co ip 16607 354 24X
 Fiche 50-000,82/11/30,8212290060
- --B212270092 Ack receipt of /51227 ltr informing NRC of steps taken to correct violation noted in IE (nsp Repts 50-250/75-16 & 50-251/75-16 LONG.F J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 76/01/05 UHRIG.R E Florida Power & Light Co Ip 16607 282 24X Fichs 50-000, 82/11/30.8212270060
- --B212290094 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 % 50-251/75-07 Corrective actions fire stops installed in cable trays in Unit 4 control rad drive com & entrance to auxiliary bldg above main corridor doors UHRIO.R E Florida Power / Light Co 75/06/20 MDEELEY,N C Region 2, Atlanta, Office of the Director 2pp 16607 358 24X Fiche 50-000, B2/11/30, B212290060
- GP12290097 Responds to NRC 751209 ltr re violation noted in IC Insp Repts 50-250/75-16 & 50-291/75-16 Corrective actions overdue inservice insp rept transmitted to NRC on 751120 & procedure written to describe scheduling & preparation of repts UHRIG.R E Florida Power Light Co 75/12/29 MOSELEY,N C Region 2. Atlanta. Uffice of the Director 2pp 16607 283 24X Fiche 50-000,82/11/30.8212290060
- -B212290100 Forwards IE Insp Regts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FSAR commitment observed MOSELEY:N C Region 2. Atlanta, Office of the Director 75/05/29 UHRIO.R E Florida Power & Light Co 2pp 16407 357 R4X Fiche 50-000, B2/11/20. B212290060
- -B212270101 Forwards IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted MGSELEY,N C Region 2. Atlanta, Office of the Director 75/12/09 URR10.R E Florida Power A Light Co 2pp 16607 285 24X Fishe 50-000, B2/11/30, B212290060
- --B21229010B Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation from FGAR commitment observed Licensee requested to inform NRC of plans for implementing FSAR commitment LONG.F J Region 2. Atlanta. Office of the Director 75/05/27 SEYFRIT,K V Office of Inspection & Enforcement. Office of the Director ip 16607 359 24X Fiche 50-000.82/11/30.8212270060
- --8212270109 IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted failure to submit Unit 4 inservice insp rept to NRC within 90 days HARDINA K , LEWIS,R C , HERDT, A R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/05 17pp 16607 287 24% Fiche 50-000,82/11/30,8212270060
- --B212290113 Forwards listed documents re IE Insp Repts 50-250/75-17 & 50-251/75-17 Documents filed in LPDR
 MOSELEY, N C Region 2. Atlanta, Office of the Director 76/02/13
 PEELER, E Florida International Univ ip 16607 304 24X
 Fiche 50-000, 82/11/30, 8212290060

- --B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14
 Deviation observed one tray of control cables in Unit 3
 control rod drive room & cable trays exiting auxiliary
 bldg did not have fire stops installed
 HARDIN,A K . LONG,F J Region 2. Atlanta, Office of the Director
 75/05/27 9pp 16607 360 24X Fiche 50-000, B2/11/30, B212290060
- --B212270124 Responds to NRC 760113 ltr reviolations noted in IE Insp Repts 50-250/75-17 & 50-251/75-17 Corrective actions drums of radwaste properly barricaded & all licensed operators will be brought up to date w/requalification quiz schedule UHRIO.R E Florida Power & Light Co 76/02/02 MOSELEY, N C Region 2. Atlanta. Dffice of the Director Spp 16607 306 24X Fiche 50-000,82/11/30,8212290060
- --8212270127 Forwards IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted LONG:F J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 76/01/13 UMF10,R E Florida Power & Light Co 2pp 16607 311 24X Fiche 50-000, 82/11/30.8212270060
- --B212290137 IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 0301 HARDIN.A K , LEWIS.R C , RDGERS.R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/12 18pp 16607 313 24% Fiche 50-000,82/11/30,8212270060
- 8/08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Liectrical Penetration Assemblies "Syc list enci DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 6208190261 IE Info Notice 62~48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDANE L Division of Engineering & Quality Assurance 62/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- 8208190267 [E Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUND.R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20,8208190268
- R Periodic operating reports & related correspondence
- 8:12270153 Forwards monthly operating repts for Oct 1982 WILLIAMS, J W Florida Power & Light Co 82/11/15 Office of Resource Management, Director ip 16582 226 24X Fiche 50-000: 82/11/15,8212270153
- ---8212270169 Monthly operating repts for Oct 1982 PACE:P Florida Power & Light Co 82/11/15 12pp 16582 227 24% Fiche 50-000.82/11/15.8212270153
- GP12150180 Forwards "Groundwater Munitoring Program Summary Rept. Jul 1981-June 1982 " UKRIO.R E Florida Power & Light Co 82/12/03 G'REILLY. J P Region 2, Office of Director ip 16427 196 24X Fiche 50-250, 82/12/03, 8212150180
- 8212150183 "Oroundwater Monitoring Program Bummary Rept. Jul 1981-June 1982" * Dames & Hoore 82/07/27 126pp 16427 197 24X Fiche 50-250,82/12/03.8212150180
- 8 Reportable occurrences. LERs & related correspondence
- 8212090356 Forwards updated LER 81~013/02X-2 WILLIAMS, J W Florida Power & Light Co 82/12/02 O'REILLY, J P Region 2. Office of Director ip £6365 135, 24X Fiche 50-250, 82/12/02, 8212090356

- --B212090371 Updated LER 81-013/02X-2 on 810710, small void in concrete found immediately below equipment hatch barrel Cause not stated Similar void confirmed on Unit 4 Voids repaired SERRY. E Florida Power & Light Co 82/12/02 Region 2, Office of Director 2pp 16365 136 24X Fichs 50-250,82/12/02, 8212090356
- G212100219 Forwards LER 92-015/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16376 093 24X Fishe 50-250, 82/12/03, 8212100219
- ~-8212100220 LER 82-015/03L-0 on 821104 during normal operation, 3A high head safety injection pump failed to start from manual operation Cause undetermined Pump breaker racked out & back in Repairs made to breaker

 BERRY, Z E Florida Power & Light Co 82/12/03 Region 2,

 Office of Director 2pp 16376 094 24X Fiche 50-250,82/12/03,

 R212100219
- G?12210202 Forwards LER 82-018/017-0 WILLIAMS, J N Florida Power & Light Co 82/12/15 O'REILLY, J P Region 2. Office of Director ip 16484 315 24X Fiche 50-250, 82/12/15, 8212210202
- --8212210207 LER 82-018/01T-0 on 821201.during full power operation, 3A load ctr de-energized following trip of 4-kV breater 3AA08 Cause undetermined Breaker protective relays will be tested during next outage BERRY. Z E Florida Power & Light Co 82/12/15 Region 2, Office of Director 1p 16484 316 24X Fiche 50-250,82/12/15, 8212210202
- 0212280164 Forwards LER 82-017/03L-0 WILLIAMS, J W Florida Power & Light Co 82/12/20 O'REILLY, J P Region 2. Office of Director 1p 16563 220 24X Fiche 50-250, 82/12/20, 8212880164
- --8212280167 LER 82-017/03L-0 on 821117, during control room mods, two fire barrier penotrations disabled antentionally for longer than 7 days Action taken to implement approved design mods to control room ARIAS. J. Florida Power & Light Co. 82/12/20 Region 2. Office of Director 1p t6563 221 24X Fiche 50-250,82/12/20,82/12/20,82/12/20,82/280164
- 0212280170 Forwards LER 82-016/03L-0 WILLIAMS, J W Florida Power & Light Co B2/12/20 O'REILLY, J P Region 2. Office of Director Ip 16563 142 24X Fiche 50-250, 82/12/20, 8212280170
- --8212280175 LER 82-016/03L-D on 821119, during insp of fire protection sys, fire barrier penetration (laundry room west doors) found nonfunctional New doors/parts ordered 2 will be installed upon receipt ARTAS. J Florida Power & Light Co 82/12/20 Region 2, Office of Director ip 16563 143 24X Fichs 50-250,82/12/20.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, amergency & fire protection plans

- B212070529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on B21004-10 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/10/29 UHRIO-R E Florida Power & Light Co 2pp 16366 108 24X fiche 50-250, 82/10/29 6212070529
- --8212070540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 No noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys HUFFMAN, 0 N Bivision of Emergency Preparedness & Operational Support 82/10/29 19pp 14364 110 24X Fiche 50-250,82/10/29,8212090529
- G212270060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR.LPDR profiles for Ginna & Indian Point 3 encl FELTON.J M Division of Rules and Records 82/11/30 SCHLISSEC.D.A New York State of 7pp 16407 237 24X Fiche 50-000.82/11/30.6212290060
- --9212270074 Responds to NRC 750527 itr re deviation noted in IE Insp Rapts 30-250/75-07 & 30-251/75-07 Corrective actions fire steps installed in cable trays in Unit 4 control rad drive room & entrance to auxiliary bldg above main corridor doors UHRIG-R E Florida Power & Light Co 75/06/20 MGECLEY, N C Region 2. Atlants. Office of the Director 2pp 14607 355 24X Fiche 50-000, 82/11/30, 8212290060

- --8212270114 IE Insp Repts 50-250/75-07 % 50-251/75-07 on 750512-14
 Deviation observed one tray of control cables in Unit 3
 control rod drive room & cable trays exiting auxiliary
 bidg did not have fire stops installed
 HARDIN.A K Region 2. Atlanta, Office of the Director 75/05/27
 9pp 16607 360 24X Fiche 50-000,82/11/30,8212290060
- J Insurance & indemnity information
- SE12020335 Forwards Endorsements 60 & 61 to NELIA Policy NF-185 & Lndorsements 50 & 51 to MAELU Policy MF-55
 FIELDER, J. Marsh & McLennan, Inc., M & M. Nuclear Consultants, Inc. Div. 82/11/18 SALTAMAN, J. Assistant Director for State & Licensee Relations 5pp 16279 151 24X Fiche 50-250,82/11/18.8212020335
- BC12300202 Forwards Endorsements 1.2 & 3 to NELIA Certificates N-25 & N-26 & Endorsements 1.2 & 3 to MAELU Certificates M-25 & M-26 DUCKLJR. Marsh & McLennau Inc., M & M Nuclear Consultants, Inc. One
- N=26 DUCK.JR Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 82/12/27 SALTZMAN.J Assistant Director for State & Licenses Relations 37pp 16598 Q50 24X Fiche 50-250, 82/12/27, 8212300202
- 8212300243 Forwards Endorsement 62 to NELIA Policy NF-185 & Endorsement 52 to MAELU Policy MF-55

 DUCK.J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 82/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16595 273 24X Fiche 50-250, 82/12/27, 8212300243
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8P12070435 Discusses summary of ACRS Reactor Operations Subcommittee 820929 meeting re Turkey Point cold overpressure incident Tech Specs do not properly address situations in which availability of certain sysmore vital to safe operation BINFORD.FT Clak Ridge National Laboratory 82/10/19 MAJOR.R ACRS Advisory Committee on Reactor Safeguards ip 16358 336 24X Fiche 50-250.82/10/19.8212070435
- P Operating license stage documents & correspondence
- BP08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements forwards Science Applications, Inc. draft rept re sub, requirements Comments requested within 30 days of itr Svc list encl EISE(M-WT, D.G. Division of Licensing 82/12/09 Consolidated Edison Co. of New York, Inc. 29ep 16629 247 24X Fiche 50-000. 82/12/09. 8208190263
- GE12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E FWRs (except Arkansas Nuclear One, Unit 2 & San Gnofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 82/12/40103
- 8212210190 Informs that util will utilize Westinghouse optimized fuel assemblies during Fall 1983 refueling
 UMRIO.R E Florida Power & Light Co 82/12/13 EISENHUT, D 0
 Division of Licensing to 16484 353 24X Fiche 50-250,82/12/13,
 B212210190
- BP12290534 Forwards safety & technical evaluations for environ qualification of safety-related electrical equipment Reaffirmation of justification for continued operation & info re Categories I B. II A & II B requested VARGA: 5 A Operating Reactors Branch 1 82/12/13 UHRIG.R E florida Pouer & Light Co 3pp 16608 061 24X Fiche 50-250, 82/12/13, 8212290534
- --B212290535 SER re environ qualification of safety-related electrical equipment

 * Operating Reactors Branch 1 82/12/13 5pp 16608 064 24X Fiche 50-250,82/12/13,8212290534
- --8210070227 "Review of Licensers Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-I1 & B-60), Turkey Point Unit 4." Vols 1 & 2-technical evaluation rept PANDEY, S Franklin Institute/Franklin Research Center NRC-03-79-118 TER-CS257-480 82/09/30 LE,N B NRC No Detailed Affiliation Given 778pp 16608 069 24X Fiche 50-250,82/12/19,8212290534
- --8212270536 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60)." Vois 1 & 2, technical evaluation rept PANDEY, 8 Franklin Institute/Franklin Research Center TER-C5287-479 82/09/30 LE, N B , SHEMANSKI, P NRC No Detailed Affiliation Given 807pp 16610 128 24X Fiche 50-280,82/12/13,8212270534

- 8/1230006B Forwards safety evaluation & technical evaluation rept supporting station electric distribution sys voltages VARGA.S A Operating Reactors Branch 1 B2/12/17 UHRIG.R E Florida Power & Light Co 2pp 16624 213 24X Fiche 50-250.62/12/17.821230006B
- --G212300071 SER supporting station electric distribution sys voltages * Operating Reactors Branch 1 82/12/27 5pp 16624 215 24X Fiche 50-250.82/12/17.8212300068
- --B209230424 "Adequacy of Station Electric Distribution Sys Voltages for Turkey Point Nuclear Generating Plant Units 3 & 4.7" technical evaluation rept SELAN, J C Laurence Livermore Laboratory FIN A-0250 UCID-1914B B2/08/08 IRC No Detailed Affiliation Given 13pp 16624 220 24% Fiche 50-290.82/12/17.8212300048

Q Inspection reports, IE Bulletins & correspondence

- 82-08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BWR Plants "Swc list encl DEYQUNO. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- GP12090529 Forwards IE Insp Repts 50-250/82-11 & 50-251/82-11 on G21004-10 No noncompliance noted BANCE, H C Division of Project & Resident Programs 82/10/29 UHRIO.R E Florida Pawer & Light Co 2pp 16366 108 24X Fiche 50-250, 82/10/29, 82/2090529
- -8212070540 IE Insp Repts 50-250/82-11 & 50-251/82-11 on 821004-08 Na noncompliance noted Major areas inspected followup on previous emergency preparedness findings & experience data on installation & operation of public notification sys HUFFMAN.G N . JENKINS.G R Division of Emergency Preparedness & Operational Support 82/10/29 19pp 14366 110 24X Fiche 50-250,82/10/29,8212090529
- EPOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 5 Model 802 Thermolyminescent Dosimeters " Syc list cacl COB8.L f Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 90-000,82/ii/05,8208190245
- GP12090490 Forwards IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted DANCE.H C Region 2. Office of Director 82/11/12 UHRIG.R E Itorida Pouer & Light Co 2pp 16365 344 24X Fiche 50-250, 82/11/12, 8212090490
- --8212070500 IE Insp Repts 50-250/82-31 & 50-251/82-31 on 821018-22 No noncompliance noted Major areas inspected radiation protection program.including qualification of staff, training % radiological protection procedures HOSEY.C M. DEBS.B T. BARR, K P. Division of Engineering & Technical Programs 82/11/12 iOpp 16365 346 24X Fiche 50-250,82/11/12,8212070470
- GP12090487 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29 DANCE.H C Division of Project & Resident Programs 82/11/14 UHRIG.R E Florida Power & Light Co ip 14366 001 24X Fiche 50-250.82/11/16.8212090487
- B212070503 Responds to NRC B20927 ltr re violations noted in IE Insp. Repts 30-250/82-29 & 50-251/82-29 Corrective actions procedure revised to clarify policy for tagging motor operated valves
 UHRIG.R E Florida Power & Light Co. B2/10/29 D'REILLY, J P. Regian 2. Office of Director 2pp. 16366-002 24X
 Fishe 50-250, B2/11/16, B212090487
- --8212090510 Forwards IE Insp Repts 50-250/82-29 & 50-251/82-29 on 820726-0826 & notice of violation BANCE:HC Division of Project & Resident Programs 82/09/29 UHRIG:RE Florida Power & Light Co 2pp 16366-004 24X Fiche 50-250.82/11/16.8212090487
- --8212090518 Notice of violation from insp on 820724-0826 * Division of Project & Resident Programs 82/09/29 i 16366 006 24X Fiche 50-250,82/11/16,8212090487
- --B212070524 IE Insp Repts 50-250/B2-29 & 50-251/B2-29 on B20726-0B26 Noncompliance noted failure to follow equipment clearance procedure for motor operated valve in safety injection sys VOOT-LOWELL, R , JULIAN, C Division of Project & Resident Programs B2/09/24 6pp 16366 007 24X Fiche 50-250, B2/11/16, B212070487

- 8708190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 30-000.82/11/18,8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYGUNG.R C Director's Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 085 24Y Fiche 50-000/82/11/26/8208190256
- 62/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24% Fiche 50-000,82/11/30,8208190257
- 6212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents I & 2 already in PDR App B documents available in PDR LPDR profiles for Onna & Indian Point 3 encl FELTON, J M Division of Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24% Fichs 30-000, 82/11/30, 8212290060
- --8212290064 Ack receipt of 750714 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-08 & 50-251/75-08 MDSELEY,N C Region 2, Atlanta, Office of the Director 75/08/01 UHRIG.R E Florida Power & Light Co ip 16407 332 24X Fiche 50-000,82/f1/30.8212290040
- --B212290068 Responds to NRC 750625 itr re violation noted in 1E Insp Repts 50-250/75-08 & 30-251/75-08 Corrective actions superseded procedures for surveillance testing removed & latest revision placed in control room on 750526 UMRIO.R E Florida Power & Light Co 75/07/14 MOSELEY,N C Region 2. Atlanta. Office of the Director 3pp 16607 333 24X Fiche 50-000.82/11/30.8212290660
- --B212290073 Forwards IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted MOSELEY, N C Region 2. Atlanta, Office of the Director 75/06/25 UHRIG.R E Fibrida Power & Light Co 2pp 16607 336 24X Fiche 50-000, 82/11/30, 8212290060
- --8212290070 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test HARDIN.A K , LONG.F J , WILBER.H A Region 2, Atlanta, Office of the Director 75/06/24 15pp 16607 338 24X Fiche 50-000,82/11/30,821229066
- ~~8212270082 Forwards listed documents re IE Insp Repts 50-250/75-07 & 50-251/75-07 Documents filed in LPDR
 HOSELEY, N C Region 2. Atlanta, Office of the Director 75/07/21
 RUBER, F T Homostead, FL 1p 16407 353 24X
 Fiche 50-000, 82/11/30, 8212270060
- --8212270087 Forwards listed documents re IE Insp Repts 50-250/75-16 & 50-251/75-16 Documents filed in LPDR
 MOSELEY, N C Region 2. Atlants. Diffice of the Director 76/01/05
 PEELER.E Florids International Univ 1p 16607 281 24%
 Fichs 50-000, 82/11/30, 8212270040
- --B212290090 Ack receipt of 750620 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 MGELEY, N C Region 2. Atlanta, Office of the Director 75/07/21 UHRIO:R E Florida Power & Light Co ip 16607 354 24X Fichs 50-000, R8/11/30. 8212290060
- --8212290092 Ack receipt of 751229 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-250/75-16 & 50-251/75-16 LONG, F J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/05 UHR10,R E Florida Power & Light Co ip 16607 282 24% Fiche 50-000,82/11/30,8212290060
- --8212290D94 Responds to NRC 750529 ltr re deviation noted in IE Insp Repts 50-250/75-07 & 50-251/75-07 Corrective actions fire stops installed in cable trays in Unit 4 control rod drive room & entrance to auxiliary blog above main corridor doors UHRIG.R.E Florida Power & Light Co 75/06/20 MOSELEY.N C Region 2. Atlanta. Office of the Director 2pp 16407 355 24X Fiche 50-000, 82/11/30, 8212290060

- --8212290077 Responds to NRC 751209 ltr re-violation noted in IE Insp. Repts 50-230/75-16 % 50-251/75-16 Corrective actions overdue inservice insp rept transmitted to NRC on 751120 & procedure written to describe scheduling & preparation of repts UHRIG-R E Florida Power & Light Co 75/12/27 MOSELEY,N C Region 2, Atlanta. Office of the Director 2pp 16607 283 24X Fiche 50-000,82/11/30.8212290050
- --B212290100 Forwards IE Insp Repts 50-250/75-07 & 50-291/75-07 on 750512-14 Deviation from FSAR commitment observed MOSELEY.N C Region 2. Atlanta, Office of the Director 75/05/29, UHRIG.R E Florida Fower & Light Co 2pp 16607 357 24X Fichs 50-000, 82/11/30, 8212290060.
- --8212290101 Forwards IE Insp Repts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted MOSELEY.N C Region 2. Atlanta. Office of the Director 75/12/09 UHRIGR E Florida Power & Light Co 2pp 16607 285 24X Fiche 50-000.82/11/30.8212290060
- --B2:2290108 Forwards IE Insp Repts 50-250/75-07 & 50-251/75-07 on 7505:2-14 Deviation from FSAR commitment observed Licensee requested to inform NRC of plans for implementing FSAR commitment LONG, F.J. Region 2, Atlanta, Office of the Pirector 75/05/27 SEYFRIT, K.V. Diffice of Inspection & Enforcement, Office of the Director 1p 16607 359 24X Fiche 50-000, 82/11/30, 8212270060
- --82[2270109 IE insp. Regts 50-250/75-16 & 50-251/75-16 on 751105-21 Noncompliance noted failure to submit Unit 4 inservice insp rept to NRC within 90 days HARDIN:A K., LEWIS.R C., PERDT.A R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 75/12/05 17pp 16607 287 24X Fiche 50-000.82/11/30,82[2270060
- ~-8212290113 Forwards listed documents fo IE Insp Repts 50~250/75-17 & 50~291/75-17 Documents filed in LPDR
 MGSELEY.N C Region 2. Atlants. Office of the Director 76/02/13
 FEELER.E Florida International Univ ip 16607 304 24%
 Fiche 50-000.82/11/30.8212290060
- --B212270114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14 Deviation observed one tray of control cables in Unit 3 control rod drive room & cable trays exiting auxiliary bidg did not have fire stops installed HARDIN A X , LONG, F J Region 2, Atlanta, Diffice of the Director 75/05/27 9pp 16607 360 24X Fiche 50-000, 82/11/30, 8212270060
- --B212290118 Acy receipt of 760202 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-250/75-17 & 50-251/75-17 LONG.F J Region 2: Atlanta, Reactor Operations Nuclear Support Branch 76/02/13 UMRIG.R E Florida Power & Light Co is 16607 305 24% Fiche 50-000. B2/11/30.B212270060
- --8212290124 Responds to NRC 760113 ltr re valuations noted in IE Insp. Repts 50-250/75-17 & 50-251/75-17 Corrective actions drums of raduate properly barricaded & all licensed operators will be brought up to date w/requalification quir schedule UHRJ9.R E Floride Power & Light Co 76/02/02 MOSELEY.N C Region 2. Atlanta. Office of the Director 5pp 16607 306 24X Fiche 50-000.82/11/30.8212290060
- --82:2290:129 Forwards IE Insp Repts 50-250/79-17 & 50-251/75-17 on 75:209-12 & 14-19 Noncompliance noted LONG: F J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 76:01/13 URRIG.R E Florida Power & Light Co Rep 14607 31: 24X Fiche 50-000, 82/11/30.82:2290060
- --8212270137 IE Imap Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-17 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 0301 HARDIN:A K , LEWIS:R C , ROGERS,R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/01/12 18pp 16607 313, 244 Fiche 50-000, 62/11/30, 8212290060
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYUUNO.R C Director's Office Office of Inspection and Enforcement 82/12/03 Consolidated Efison Co of New York, Inc 113pp. 16411 317 24X Fiche 50-000,82/12/03.8208190259
- BP08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03. Consolidated Edison Co of New York, Inc 110pp 16462.064 24x Fiche 50-000.82/12/03.8208190261

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Cas Monitoring " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 87/08190268 IE Info Notice 82-50, "Mod of Golid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000:82/12/20.8208190268
- R Periodic operating reports & related correspondence
- 8212290153 Forwards monthly operating repts for Oct 1982 WILLIAMS, J W Florida Power & Light Co 82/11/19 Office of Resource Management, Director 1p 16582 226 24X Fiche 30-000.82/11/15.8212290153
- --8212290149 Monthly operating rapts for Oct 1982 PACE:P Florida Power & Light Co 82/11/15 12pp 16582 227 24X Fiche 50-000.82/11/15.8212290153
- G:12150180 Forwards "Groundwater Monitoring Program Summary Rept, Jul 1981-June 1982 " UHRIO,RE Florida Power & Light Co 82/12/03 D'REILLY, J P Region 2. Office of Director 1p 16427 196 24X Fiche 50-250,82/12/03,8212150180
- ~-8212150183 "Groundwater Manitoring Program Summary Rept, Jul 1981-June 1982 "
 • Dames & Moore 82/07/27 126pp 16427 197 24X Fiche 50-250, 82/12/03, 8212150180
- DDCKET 50-254 QUAD-CITIES STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8P12030053 Ack receipt of 821108 ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification restart & stop of 15-ninute clock provided KEPPLERIJ O Region 3. Office of Director 82/11/30 REED, C Commonwealth Edison Co 1p 16304 143 24% Fiche 50-254.82/11/30, 8212030053
- --8212030056 Responds to NRC 820930 ltr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Addl corporate emergency planning positions budgeted for 1983 RAUSCH.T J Commonwealth Edison Co 82/11/08 KEPPLER, J G Region 3. Office of Director 3pp 16304 144 24X Fiche 50-254,82/11/30,8212030053
- B212030268 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16316 276 24X Fiche 50-254,82/11/30, 8212030268
- --8212030273 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 330-6 re air sampling under accident conditions & GEP 330-17 re air radiation monitoring sys Receipt form encl KDVACK.T J. GERNER.L Commonwealth Edison Ca 82/10/18 DENTON.H R. NRC NO Detailed Affiliation Given Ip 16316 2/8 24% Fiche 50-254.82/11/30,8212030268
- --8212030279 Public version of revised emergency plan implementing procedures including Procedures GEF 330-6 re air sampling under accident conditions & GEP 330-79 re air radiation monitoring sys # Commonwealth Edison Co 82/10/18 17pp 16316 279 24X Fich 50-254.82/11/30.8212030268
- BP12040172 Ack receipt of B21116 ltr informing NRC of steps taken to correct violations noted in NRC B21012 ltr re timeliness of emergency planning exercise submittals HINDLA Division of Emergency Preparamenss & Operational Support B2/12/01 REED.C Commonwealth Edison Co Ip 16313 086 24X Fiche 50-254,82/12/01,8212060172
- ---B212040181 Responds to NRC 821012 ltr re timeliness of scenerio submittals to FEMA Region VII FEMA Region VII to be included in submittals & meetings associated wifuture exercises RAUSCH, T. J. Commonwealth Edison Co 82/11/16 KEPPLER. J Q Region 3. Office of Director ip 16313 087 24% Fiche 50-254,82/12/01.8212050172

- 0212090325 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/82-80 & 50-265/82-21 MILLER, JR Division of Engineering & Technical Programs 82/12/
- -8212070338 Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-245/82-21 Corrective actions withheld (ref 100FR73 21)
 DELGEORGE.L G. Commonwealth Edison Co. 82/11/29 KEPPLER.J G. Region 3. Office of Director ip. 16365-104 24X
 Fichs 50-254,82/12/03.8212090325
- S212070383 Forwards info re emergency operations facilities per 621122 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee DELOEDROP.L. O Commonwealth Edison Co 82/12/03 EISEMMUT, D C Division of Licensing 2pp 16365 051 24X Fithe 50-000.82/12/03, 8212080383
- SE12140179 Responds to items re fire protection safe shuddown analysis, discussed in 920917 telephone conference Core can maintain water level above top of active fuel w/o initiation of RCIC flow for max of 14 minutes RAUSCH, T. J. Commonwealth Edison Co. 92/12/06 EISENHUT, D. G. Division of Licensing 3pp 16410 205 24X Fiche 50-254,82/12/06, GRE2140179
- B2:12160127 Ack receipt of 820621 itr transmitting changes to security plan. Revision 11 Change consistent w/provisions of 10CFRSO 54(p) & does not decrease effectiveness of plan VASSALLO.D B Operating Reactors Dranch 2 82/12/06 DELGEORGE.L O Commonwealth Edison Co 3pp 16447 206 24X Fishe 50-254.82/12/06 3212160127
- GP12130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure E0-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps)" | ELITON JH Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000,82/12/07, 821312017
- --0212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl PAJOWSKI, J Commonwealth Edison Co 82/11/01 DENTON, H.R. NRC -- No Debailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, 82/12/07, 8212130017
- --8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EC-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"

 PAJOMSKIJE Commonwealth Edison Co 82/11/29 4pp 16417 065 244 Fishe 50-000, 82/12/07, 8212130017
- GP12140243 Advises of distribution of revisions to "Generating Station Imergency Plan " Braidwood annex not prepared TRAMM-TR Commonwealth Edison Co 82/12/07 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000, 82/12/07, 8212140243
- BP12220175 Releases public version of revised generating station emergency plan implementing procedures
 FELTON, J M Division of Rules and Records B2/12/10 Document Nanagement Branch 1p 16529 029 24X Fiche 50-000, B2/12/10, B212220175
- --B212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJOMSKI.J E Commonwealth Edison Co 82/11/15 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 16527 030 24X Fichs 50-000,82/12/10,8212220175
- --B212220202 Public version of revised generating station emergency plan implementing procedures.including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI,L A Commonwealth Edison Co 82/10/13 48pp 16527 031 24X Fiche 50-000,82/12/10.8212220175
- 82/12220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility
 KEPPLER.J O Region 3. Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fichs 50-000.82/12/16, 6212220306

- 8212300167 Releases public version of Fevised generating station emergency plan telephone directory FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000.82/12/20, 18212300167
- --B212300179 Forwards public version of revised generating station emergency plan telaphone directory MODRE:R D Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000,82/12/20.8212300167
- --8212300199 Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/11/05 60pp 16612 217 244 Fiche 50-000, 82/12/20,8212300167
- GP12300400 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/22 Document Management Branch ip 16613 203 24X Fiche 50-254,82/12/22, G212300400
- 9212300405 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation Receipt form encl
 Commonwealth Edison Co 82/12/08 DENTON, H R NRC - No Detailed Affiliation Given 2pp 16613 204 24X Fiche 50-254, 82/12/22.8212300400
- --8212300409 Public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site evacuation * Commonwealth Edison Co 82/12/08 12pp 16613 206 24X Fiche 50-254,82/12/22.8212300400
- G Adjudicatory correspondence
- 8P12070160 Memorandum & order granting licensee B20B18 request to dismiss proceeding u/o prejudice Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary JDHMSON.E B , STOBER.Q J , MILHOLLIN.Q L Atomic Safety and Licensing Board Panel B2712/03 Commonwealth Edison Co 4p; 16336 320 24X Fiche 50-000, B2/12/03, B212070160
- ii General correspondence
- 8712280176 Notifies of change in mailing address for NRC licensing mat! MRIGHT,O N Illinois, State of Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT,D O Division of Licensing ip 16556 135 24X Fiche 50-000,82/12/20,8212280176
- P Operating license stage documents & correspondence
- 8P11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBHR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl W/n stated encl EIGENHUT.D 9 Division of Licensing 82/11/15 General Public Utilities OPU Bervice Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066
- SP12130275 Forwards safety evaluation of BWR comers group 810522.0921 & 820902 responses to NUREG-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals " Responses acceptable VABSALLO,D B Operating Reactors Branch 2 82/12/01 DELOCORGE,L Commonwealth Edison Co 7pp 16418 213 24X Fiche 50-254.82/12/01, 8212130275
- BP12160013 Forwards ltrs from engineering firms supporting spent fuel rack mod at facilities Min gap of 2.5 inches between racks does not invalidate previous seismic analyses if racks symmetrically loaded Restoration of 3-inch gap planned RAUSCH, T. J. Commonwealth Edison Co. BR/12/10 EISENHUT, D. D. Division of Licensing. Spp. 16446 074 24% Fiche 50-254.82/12/10, B212160013
- B312280397 Informs of removal of two metal specimens from reactor vessel,per Tech Spec & &-i requirements RAUSCH.T.J. Commonwealth Edison Co. B2/12/13 KEPPLER.J.O. Region 3, Dffice of Director ip 16561 041. 24% Fiche 50-254,82/12/13,8212280357
- B212220212 Forwards Revision 22 to CE-1-A, "GA Program for Nuclear Cenerating Stations."
 BHARTZ,E D Commonwealth Edison Co 82/12/14 HAA88,W P Guality
 Assurance Branch ip 16518:007 24X Fiche 50-000.82/12/14,
 B21220012

- --8212220231 "QA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14,821220212
- GP12280117 Forwards add1 info re NURES-0737. Item II F 1. "Add1 Accident Monitoring Instrumentation." per NRC 821109 request Pressure monitoring sys provided w/separate loop for narrow lange monitoring SMARTZ.E D Commonwealth Edison Co 82/12/20 EISENHUT.D 0 Division of Licensing 7pp 16564 062 24X Fiche 50-000.82/12/20.6212280117
- 8212280343 Forwards addl info re NUREG-0737. Items II F 1 4,5 & & "Containment Pressure. Water Level & Hydrogen Monitoring," per Crutchfisial 821109 ltr SWARTZ. E D Commonwealth Edison Co 82/12/20 EISENHUT. D G Division of Licensing 9pp 16561 053 24X Fiche 50-000, 82/12/20, 8212280343
- 8212270111 Application for amend to License DPR-29, consisting of change to Tech Specs allowing normal power operation for no more than one refueling cycle w/one main steam drain line isolation valve exhibiting excessive leakage W/o Tech Specs RAUSCH.T.J. Commonwealth Edison Co. 82/12/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16582 241 24X Fiche 50-254,82/12/20,8212270111
- 8212290407 Discusses activities & insps performed on feedwater & control rod driveling notates during Fall 1982 refueling outage
 RAUSCH T J Commonwealth Edison Co 82/12/20 KEPPLER, J Q Region
 3, Office of Director 3pp 16586 344 24% Fiche 50-254,82/12/20, GR12290407
- 8212280212 Forwards updated schedule for engoing environ qualification testing programs.per 810528 commitment SWARTZLE D. Commonwealth Edison Co. 82/12/22 EISENHUT, D. 9 Division of Licensing 18pp 16556 161 24% Fiche 50-000, 82/12/22, 8212280212
- 82:12280243 Clarifies position on classification of major mods to BWR Mark 1 Containment per 82:1214 ltr
 RAUSCHIT J Commonwealth Edison Co 82/12/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 16561 307 24X Fiche 50-000.82/12/22:8212280243
- 6212300138 Confirms 821220 telcon authorization for change to Tech Spec as requested by 821220 ltr Amend revised Tech Spec allowing operation w/one main steam drain isolation valve inoperable License amend, evaluation & notice of isolation valve inoperable LAIMAS.0 C Assistant Director for Operating Reactors 82/12/23 DELGEORGE.L Commonwealth Edison Co 2pp 16624 191 24X [iche 50-254.82/12/23,8212300138]
- G. Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping of BHR Plants " Svc list encl DEVOUNO, R C Director's Office, Office of Inspection and Enforcement E2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- SPOS190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards
- COUBL. I Division of Fuel Facilities, Materials & Safeguards B2/11/03 Consolidated Edison Co of New York, Inc. 110pp 16372-142 24X Fiche 50-000,82/11/05,8208190245
- 8212020308 Forwards IE Insp Repts 50-254/82-15 & 50-265/82-17 on 620630-0902 & notice of violation MILLER,R Division of Engineering & Technical Programs 82/11/16 REED.C Commonwealth Edison Co 2pp 16278 147 24X Fishe 50-254 62/11/16 8212020308
- --8212020310 Notice of violation from 1849 on 820820-0902 MILLER, J. R. Division of Engineering & Technical Programs 82/11/14 tp 16278 149 24X Fiche 50-254, 82/11/16, 8212020308
- --8212020314 1E Insp Repts 50-254/82-15 & 50-265/82-17 on 820830-0902 Noncompliance noted failure to use strong tight packages for transportation of low specific activity radwaste HUETER.L J. ORANT.W B. GREGER,L R. Regson 3, Office of Director 82/10/12 7pp 14278 150 24X Fiche 50-254,82/11/16,8212020308
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 62/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000,82/11/18.8208190251

- 8212030187 Forwards IE Insp Repts 50-254/82-18 & 50-245/82-20 on 820908-1022 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/11/19 REED, C Commonwealth Edison Co 2pp 16307 083 24X Fiche 50-254, 82/11/19, 8212030187
- --8212030197 IE Insp Repts 50-254/82-18 & 50-265/82-20 on 020908-1022 No noncompliance noted Major areas inspected maint-refueling, training, vessel internal insp-reactor scram feedwater sparger mod & followups on significant events & LERs CHRISSOTIMOS.N., DUFONT,S.G., WALKER,R.D. Region 3, Office of Director 82/11/19 10pp 16307-085 24X Fiche 50-254.82/11/19, 8212030187
- 8212060191 Forwards IE Insp Repts 50-254/82-21 & 50-265/82-23 on 621026-29 No noncompliance noted MILLER, J. R. Division of Engineering & Technical Programs 62/11/23 REED. C. Commonwealth Edison Co. 2pp 16313-055 24x Fiche 50-254, 82/11/23, 8212060191
- --8212060197 IE Insp Repts 50-254/82-21 & 50-265/82-29 on 821026-29 No noncompliance noted Major areas inspected normal operational & refueling radiation protection activities, staffing, training & status of certain NUREG-0737 items HUETER, L J , MILLER, D E , OREGER, L R Region 3, Office of Director 82/11/23 9pp 16313 057 24x Fiche 50-254.82/11/23, 8212060191
- G208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement BE/11/26 Consolidated Edison Co of New York. Inc 127pp 1641
- B20B190257 IE Info Notice B2-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc. 394pp 16387 028 24% Fiche 50-000, B2/11/30.8208190257
- 8212030053 Ack receipt of 82110B ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification restart \$\delta\$ stop of 15-minute clock provided KEPPLER.J \$\text{9}\$ Region 3. Office of Director \text{82/11/30}\$ REED, C Commonwealth Edison Co. ip 16304 143 24X Fische 50-254.82/11/30, 8212030053
- --B212030056 Responds to NRC B20730 ltr re problems identified in Paragraph 5 of IE Emergency Prepareduses Appraisal Repts 50-254/82-14 & 50-254/82-16 Addi corporate emergency planning positions budgeted for 1783
 RAUSCHIT J Commonuealth Edison Co 82/11/08 KEPPLER, J Q Region 3. Dffice of Director 3pp 16304 144 24X Fiche 50-254,82/11/30,8212030053
- 8212060029 Forwards response to 1E Bulletin 82-03 re stress corrosion cracking in thick wall, large diameter stainless steel recirculation sys piping at BMRs Dresden response only addresses Item 4 Other info will be provided by startup RAUSCH 7 J Commonwealth Edison Co 82/12/01 KEPPLER, J G Region 3, Office of Director 10pp 16313 288 24X Fiche 50-000,82/12/01,8212060039
- 8;12080537 Forwards response to Revision 1 to IE Bulletin 82-03 re stress corrosion cracking in thick-wall, large diameter stainless steel recirculation sys piping Addl info for Dresden 2 due prior to startup from Spring 1983 outage RAUSCH.T J Commonwealth Edison Co 82/12/01 KEPPLER.J 9 Region 3. Office of Director 10pp 16352 056 24X Fiche 50-000,82/12/01, 8212080537
- 8208190259 IE Builetin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Ca of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consalidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000,82/12/03,8208190261
- 8212090325 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-254/82-20 & Fechnical Programs 82/12/03 REED. C Commonwealth Edison or Ip 16365 103 24X Fiche 50-254, 82/12/03, 8212090325

- --8212090338 Responds to NRC 821029 ltr re-violations nated in IE Sareguards Insp Repts 50-254/82-20 & 50-265/82-21 Corrective actions withheld (ref 10CFR/3 21) DELOCORGE, L. O. Commonwealth Edison Co. 82/11/29 KEPPLER, J. G. Region 3, Office of Director 1p 16365 104 24X Fiche 50-254,82/12/03,8212090325
- OPICIO0145 Discusses util 821001 response to IE Insp Repts 50-254/82-13 & 50-265/82-15 re multiplet analysis capability in AAIS software Alternative in-depth review of AAIS acceptable. provided that NRC concerns addressed in review PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/12/04 RAUSCH.T J Commonwealth Edison Co ip 16376 042 24% Fiche 50-254.82/12/06.8212100145
- 8:08:90267 IE info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 8212270295 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-237/82-21. ft0-249/82-22. 50-254/82-17 & 50-265/82-19 NGRELIUS.C E Division of Engineering & Technical Programs 82/12/16 REED.C Commonwealth Edison Co 2pp t6530 085 24X fiche 50-000.82/12/16.8212270295
- --B212270303 Responds to NRC B21026 ltr re violations noted in IE Insp Repts 50-237/B2-21, 50-249/B2-22, 50-254/B2-17 % 50-245/B2-19 Corrective actions annual audits of all active AE firms performing safety-related work required DELGEORGEL O Commonwealth Edison Co B2/11/24 KEPPLER, J G Region 3, Office of Director 4pp 16530 087 24X Fiche 50-000, 82/12/16, 8212270295
- --8212270307 "EDS-NUTECH Interface Control Instructions," Revision O TSCHUDI.W F NUTECH (Nuclear Technology, Inc.) 82/09/30 22pp 16530 091 24X Fiche 50-000.82/12/16.8212270295
- --8212270313 "IE Bulletin 79-14 % TAP Piping Evaluation, Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision O 4 NUTECH (Nuclear Technology, Inc.) 82/10/01 9pp 16530 113 24X Fiche 50-000.82/12/16.8212270275
- | G212290346 Forwards IE Insp Repts | 50-254/82-25 & 50-265/82-27 on | R21115-19 No | noncompliance | noted | LITTLE.W S | Division of Engineering & Technical Programs | 82/12/16 | REED.C | Commonwealth Edison Co | 2pp | 16586 177 | 24X | Fiche | 50-254, 82/12/16, 8212290346 | |
- --6212290348 IE Insp Repts 50-254/82-25 & 50-265/82-27 on 621115-19 No noncompliance noted Major greas inspected honlicensed personnel & licensed operator requalification training procedures & records & surveillance scheduling program FARRELL.R E. PESCHEL.J H. HAWKINS.F C. Division of Engineering & Technical Programs B2/12/14 Spp 16596 179 24% Fiche 50-254,82/12/16,8212290346
- OP:12280110 Provides final status rept of HE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys " Complete & final listings of portions of sys failing to meet FBAR requirements under NUTCH responsibility encl RAUSCH.T.J. Commonwealth Edison Co. 82/12/17 KEPPLER.J.G. Region 3. Office of Director 3pp 16564 191 24X Fiche 50-000,82/12/17,8212280110
- 6:06190268 lE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, C L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- 8912290407 Discusses activities & insps performed on feedwater & control rod driveline nazzles during Fall 1982 refueling outage RAUSCH, T J Commonwealth Edison Co 82/12/20 KEPPLER, J C. Region 3, Office of Director 3pp 16586 344 24X Fiche 50-254,82/12/20,8212290407
- R Periodic operating reports & related correspondence
- B2:2140443 "Evaluation of Guad Cities Nuclear Power Station -Commonwealth Edison Co.1982 " # Institute of Nuclear Power Operations 82/11/08 39pp. 16405 210 24X Fiche 50-254.82/11/08.8212140443
- 8212130176 Forwards monthly operating repts for Nov 1782 KALIVIANAXIB N Commonwealth Edison Co 82/12/01 Director's Office, Office of Inspection and Enforcement 1p 16376 151 24X Fiche 50-254, 82/12/01.8212130176

- --6212130202 Monthly operating repts for Nov 1982 BUSS. R D Commonealth Edison Co 82/12/01 2ipp 16396 152 24% Fichs 50-254,82/12/01.8212130196
- DOCKET 50-255 PALISADES NUCLEAR PLANT

 F Security, medical. emergency & fire protection plans
- B2:12070300 Documents B2:1202 telcon re emergency operations facility Facilities for four plants completed Table encl VANDEWALLE.D J Consumers Power Co 82/12/03 CRUTCHFIELD.D Uperating Reactors Branch 5 2pp 16343 156 24X Fiche 50-000. B2/12/03. B2:12070300
- 8712090409 Submits add1 info in response to NRC 820701 questions re fire protection Exemption request re disconnect/connect procedure of leads at penetration for auxiliary shutdown panel source range monitor encl
 JOHNSON B D Consumers Power Co 82/12/06 CRUTCHFIELD.D Uperating Reactors Branch 5 5pp 16365 008 24X fichs 50-259.82/12/06.8212090409
- G2:12:1002:18 Responds to 82:1109 ltr re Revision 5 to security plan Modified screening program changes submitted as Revision 6 in 82:105 ltr VANDEHALLE, D. J. Consumers Power Co. 82:12:08 CRUTCHFIELD, D. Operating Reactors Branch 5 ip 16:376-073 24X [iche 50-000.82:12:08.82:12:002:18]
- 8:12100285 Advises that changes to security & suitability, training & qualification plans submitted 821105 do not decrease safeguards effectiveness NRC approval of changes in accordance u/10CFR50 54(p) not required VANDENALLE, D U Consumers Power Co 82/12/08 CRUTCHFIELD, D Uperating Reactors Branch 5 1p 16377 145 24X (1che 50-000-82/12/08,8212100285
- 0212130203 Forwards Safeguards Div regulatory effectiveness review conducted on 820913-17 Response requested within 30 days Encl withheld (ref 100ER/3 21)
 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/09 VANDEWALLE, D J Consumers Power Co 2pp 16396 179 24X Fiche 50-255, 82/12/09, 8212130203
- 8212230275 Forwards response to IE Safeguards Insp Rept 50-255/82-25 Response withheld (ref 10CFR73 21) VANDEWALLE: D J Consumers Power Co 82/12/15 CRUTCHFIELD: D Operating Reactors Branch 5 1p 16507 399 24X Fiche 50-255
- B±12220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPPLER, J 0 Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fichs 50-000, B2/12/16. 8212220306
- 8212280382 Confirms 821221 telcon extending due date for response to NRC 621213 ltr on regulatory effectiveness review to 830201 Security-related findings & observations will be addressed VANDEWALLE.D J Consumers Power Co 82/12/22 CRUTCHFIELD.D Operating Reactors Branch 5 1p 16598 362 24X Fiche 50-295,82/12/22,8212280382
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8212010502 Summary of 265th ACRS meeting on 820806-08 in Washington.DC re-01nna restart safety evaluation.Wolf Creek OL review. Palisades SEP review.mergency response capability of plants & safety-related equipment qualification program * ACRS Advisory Committee on Reactor Safeguards 82/11/26 ACRS Advisory Committee on Reactor Bafeguards 82/11/26 PACRS Advisory Committee on Reactor Bafeguards 403pp 16294 131 PAX Fiche 50-000.82/11/26.8212010502
- P Operating license stage documents & correspondence
- B212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLD, J Isham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, B2/11/03, B212140001
- ---7907300565 Discusses pipe support mods made as result of seismic design analysis problems Agrees piping systems as modified conform to ANSI B 31 I Related info encil
 SILVER.R D Operating Reactors Branch 2 (Pre 790625) 79/05/18
 EISENHUR,D Q Division of Operating Reactors 14pp 16436 025
 24% Fiche 50-000,82/11/03.6212140001

- --B002200995 Notifies that review & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program SHAD.L C Assistant Director for Engineering Programs 79/10/30 EISENHUT.D & Division of Operating Reactors ip 16435 life 24X Fiche 50-000,82/11/03,8212140001
- --B005280355 Forwards rept. "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis." prepared by NCT Engineering, Inc MURRAY.R C Laurence Livermore Laboratory 80/05/19 ALLISON.D Systematic Evaluation Program Branch 1p 16435 112 24X Fiche 50-000.82/11/03.8212140001
- --8005280561 "Role of Radiation Damping in Impedance Function Approach to Soil-Structure Interaction Analysis " Prepared for LLL TSAI.T NCT Engineering, Inc. FIN A-0233 80/05/31 NRC No Detailed Affiliation Given 50pp 16435 113 24x Fiche 50-000, 82/11/03, 8212140001
- --Bl010801iB Trip rept of B01117-19 site visit to observe site-specific features re SEP structural plactrical & systopic review Related info encl MICHAELS: T & Technical Support Branch 80/12/17 RUSSELL.W T Technical Support Branch 171pp 16436 120 24X Fiche 50-000,82/11/03.8212:40001
- ~-8201180567 Forwards Mechanical Engineering Branch review of SEP Topic III~5 B, "High Energy Line Break Butside Containment " High energy line break analysis of auxiliary feedwater sys to be included in licensee reponse to NVESC-0737 Item II E 1 1 XNIGHT.J P Assistant Director for Components & Structures Engineering BI/I2/24 LAINAS; C C Assistant Director for Safety Assessment 10pp 16436 067 24X Fichs 50-000,82/II/03. 8212140001
- --B202180460 Forwards Revision 1 to evaluation rept on SEP Topic VI-4, "Containment Isolation Sys," for facility Rept considers util comments received in BiOBIO & B20204 ltrs Conclusions of original rept remain unchanged SPEIS.TP Assistant Director for Reactor Safety 82/01/27 LANYAS.Q Assistant Director for Safety Assessment 43pp 16436 078 24X Fiche 50-000.82/11/03.8212140001
- --8204270491 Submits comments on SEP Topic III-6. "Seismic Design Considerations"
 JOHNSTON, N. V. Assistant Director for Materials & Qualifications Engineering 82/03/30 VOLLMER.R H. Division of Engineering ip 16436-077 24X Fiche 50-000.82/11/03.8212140001
- 6P12070192 Forwards Amend 71 to License DPR-20 & notice of issuance & availability Amend revises Tech Specs to allow revised testing intervals for RHR sys CRUTCHFIELD.D Operating Reactors Granch 5 82/12/01 VANDEWALLE, D J Consumers Power Co 3pp 16335 118 24X Fiche 50-255, 82/12/01. 8215070192
- --82:2070201 Amend 71 to License DPR-20, revising Tech Specs to allow revised testing intervals for RHK sys CRUICHFIELD. D Operating Reactors Branch 5 82/12/01 5pp 16335 121 24X Fiche 50-255,88/12/01.8212070192
- --8212070210 Notice of issuance & availability of Amend 71 to License BPR-20 CRUTCHFIELD, D Operating Reactors Oranch 5 82/12/01 2pp 16335 126 24% Fiche 50-255,82/12/01.8212070172
- 3212080340 Forwards SER supporting util implementation of TMI Items II B 4. "Training for Mitigating Core Demage" & I A 2 1. "Immediate Upgrading of Reactor Operator & Sensor Reactor Operator Training & Qualifications "
 CRUTCHFIELD, D Deparating Reactors Branch 5 82/12/02
 VANDERALLE, D J Consumers Power Co 4pp 16392 085 24X
 Fiche. 50-255, 82/12/02, 8212090340
- -8209030322 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 I & II B 4 for Palisades Nuclear Plant: technical evaluation rept * Brience Applications, Inc. NRC-03-82-096 SAI-186-029-20 S2/08/31 NRC No Detailed Affillation Given 16pp. 16352 087 24X Fiche 50-295, 82/12/02, 8212080340
- 212130224 Forwards, "SEP. High Energy Line Breaks Inside Containment, Palisades Nuclear Station, Phase IV Summary of Results, Revision O "Rept incorporates results of fracture mechanics analysis
 TONER, K. A. EDS Nuclear, Inc. 82/12/09 CRUICHFIELD, D. Operating Reactors Branch 5. 2pp 16397, 017 24X Fiche 50-255, 82/12/09, G212130224

- --8212130227 "SEP, High Energy Line Breaks Inside Containment Palisades Nuclear Station Phase IV Summary of Results " # EDS Nuclear, Inc 02-0340-1108 R00 82/11/30 317pp 16397 019 24X Fiche 50-255, 82/12/09,8212130224
- BP12200070 Forwards application to amend License DPR-20, changing Teth Spec Section 3 3 1 % Table 4 2 1 to reduce required boron concentration in safety injection tank T-828 for remainder of Cycle 5
 VANDEMALLE, D J Consumers Power Co 82/12/15 CRUTCHFIELD, D Uperating Reactors Branch 5 1p 16473 342 24X
 Fiche 50-283, 82/12/15, 8212200070
- --8212200075 Application to amend License DPR-20 changing Tech Spec Section 3 3 1 & Table 4 2 1 to reduce required boron concentration in safety injection tank T-828 for remainder of Cycle 5 DEMITT.R B Consumers Power Co 82/12/15 2pp 16473 343 24y Fiche 50-255.82/12/15.6212200070
- --9212200082 Proposed changes to Tech Spec Section 3 3 1 & Table 4 2 1 to reduce required boron concentration in safety injection tank T-828 for remainder of Cycle 5 * Consumers Power Co 82/12/15 3pp 16473 345 24X Fiche 50-255,82/12/15,8212200070
- 6212210459 Forwards safety evaluation & technical evaluation rept re
 TMI Action Item II E I 2. "Auxiliary Feedwater Sys Automatic
 Initiation & Flow Indication " Sys comply w/NRC long-term
 safety requirements
 CRUTCHFIELD,D Operating Reactors Branch 5 82/12/16
 VANDEMALLE,D J Consumers Power Co 4pp 16489 149 24X
 Fiche 50-255, 82/12/16, 8212210459
- B209140103 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication." technical evaluation rept KAUCHEN.JE Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-298 92/09/08 KENDALL.R NRC - NI Detailed Affiliation Given 15pp 16489 153 24X Fiche 50-255,82/12/16.8212210459
- 6/12280083 Forwards application for amend to License DPR-20, changing (ech Specs Section 6 re administrative controls, to include revised working hour guidelines per NRC Generic Ltr 82-12 & NUREO-0737, Item I A 13

 VANDE(ALLELD J Consumers Power Co 82/12/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16565 096 24X

 Fiche 50-255, 82/12/20, 8212280083
- --B212280087 Application for amend of License DPR-20, changing Tech Specs Section 6 re administrative controls to include revised working hour guidelines per NRC Generic Ltr 82-12 & NUREG-0737. Item I A 1 3
 DEHITT.R B Consumers Power Co 82/12/20 6pp 16565 098 24X
 Fiche 50-255, 82/12/20, 8212280083
- --0212280094 Proposed changes to Tech Specs Section 6 re administrative controls

 * Consumers Power Co 82/12/20 23pp 16565 104 24X
 Fiche 50-255, 92/12/20, 8212280083
- 8212300031 Forwards Amend 72 to License DPR-20 & notice of issuance & availability Amend changes Tech Spacs re SEP Topics III-7 (.V-10 B V--II A CRUTCHFIELD D Operating Reactors Branch 5 82/12/21 VANDEWALLE,D J Consumers Power Co Jpp 16598 164 24X Fiche 50-255.82/12/21.8212300031
- --8212300038 Amend 72 to License DPR-20, changing Tech Specs re BEP (opics III-7 C, "Dome Delamination," V-10 B. "RHR Sys Reliability" & V-11 A. "Requirements for Isolation of High & Low Pressure Sys "
 CRUICHFIELD, D. Operating Reactors Branch 5 82/12/21 7pp 16598 167 24X Fiche 50-255.82/12/21.8212300031
- --B212300044 Notice of issuance t availability of Amend 72 to License OPR-20 CRUICHFIELD.D Operating Reactors Branch 5 82/12/21 2pp 16598 176 24X Fiche 50-255,82/12/21,82(2300031
- G Inspection reports, IE Bulletins & correspondence
- B20B190240 IE Bulletin B2-03.Revision 1, "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Redirculation Sys Piping at BMR Plants "Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.62/10/28.8208190240

- 6208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model HOI & Model 802 Thermoluminescent Dosimeters " Svc list oncl COBB.L I Division of Fuel Facilities, Materials & Safeguards
 - encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05,8208190245
- SP12030121 Forwards IE Insp Rept 50-255/82-26 on 821001-31 No noncompliance noted
- noncompliance noted
 STRECTER. JF Division of Project & Resident Programs 82/11/17
 DEWITT.R B Consumers Power Co 2pp 14303 291 24X
 Fiche 50-255, 82/11/17, 8212030121
- --8212030129 IE Insp Rept 50-255/82-26 on 821001-31 No noncompliance noted Major areas inspected operational safety verification, plant trip review, monthly maint, monthly surveillance, design changes & mods & independent insp effort UDROCKSEN, B L , HELLER, J K , BOYD, D C Division of Project & Resident Programs 82/11/16 dpp 16303 293 24X Fiche 50-255, 82/11/17, 8212030121
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Libercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24x fische 50-000.82/11/18.8208190251
- 82:08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000;82/11/26,8208190256
- GP12020347 Forwards response to B21006 request to rescind Provisions A 1 & C of NRC B10309 order to upgrade regulatory performance Consideration based on NRR approval of B21112 lech Spec change request re safety mgt function KEPPLER.J O Region 3. Office of Director B2/11/24 DEWITT.R B Consumers Power Co ip 16278 177 24X Fiche 50-255.82/11/26. B212020347
- --B212020351 Requests recinding NRC 810309 order to upgrade regulatory performance due to significant improvement over last 1 5-yrs Schedule for action discussed VANDEWALLE, D J Consumers Power Co 82/10/06 KEPPLER, J G Region 3, Office of Director 2pp 16278 178 24X Fiche 50-255,82/1(/26,8212020347
- G7:0B190257 | E Info Notice 82-47. "Transportation of Type A Gwantitios of Non-Fissilo Radioactive Mat!" Svc list encl
 CDBG.L | Division of Fuel Facilities, Materials & Safeguards
 B2/11/30 Consolidated Edison Co of New York, Inc 354pp
 16387 028 24X Fiche 50-000,82/11/30,8208190257
- G212170087 Forwards IE Insp Rept 50-255/82-27 on 821118 No noncompliance noted
 LITELW S Division of Engineering & Technical Programs 82/11/30 DEWITTER B Consumers Power Co 2pp 16451 001 24X Fiche 50-255,82/11/30,8212170087
- --8212170074 IE Insp Rept 50-255/82-27 on 821118 No noncompliance noted Major areas inspected 10CFR21 activities, previous insp findings & IE Bullotin 78-14 & 82-02 activities WARD, K D. DANIELSON, D H Region 3. Office of Director 82/11/29 3pp 16452 003 24% Fiche 50-255,82/11/30,8212170087
- BP12280330 Responds to request for plans for corrective action re B21028 IC Insp Rept 50-255/B2-22 concerning radiological environ monitoring program Corrective actions instituted to eliminate weaknesses Completion dates listed (GINSON: B D Consumers Power Co 82/12/02 KEPPLER: J Q Region 3, Dffice or Director 3pp 16560 094 24X Fichs 50-255, B2/12/02, B212280330
- Bi:06190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 82/0B190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JURDAM,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp 16462 064 24) fiche 50-000,82/12/03,8208190261
- 8212230275 Forwards response to IE Safeguards Insp Rept 50-255/82-25 Response withheld (ref 10CFR73 21) VANDEWALLE,D J Consumers Power Co 82/12/15 CRUTCHFIELD,D Operating Reactors Branch 5 ip 16507 359 24X Fiche 50-255,82/12/15.8212230275

- BPOB190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
 127p 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc: JORDAN,E L. Division or Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24X fiche 50-000,82/12/20.8208190268
- R Periodic operating reports & related correspondence
- 8212130247 Forwards monthly operating rept for Nov 1982 KENNEDY, D M Consumers Power Co 82/12/06 NRC - No Detailed Affiliation Given 1p 16396 214 24X Fiche 50-255,82/12/06, 8212130247
- --8212130250 Monthly operating rept for Nov 1982 PETERSON.D A Consumers Power Co 82/12/06 3pp 16396 217 24< Fiche 50-255.82/12/06.8212130247
- S Reportable occurrences, LERs & related correspondence
- 8212020325 Forwards LER 82-040/03L-0 JOHNSON, R D Consumers Power Co 82/11/23 KEPPLER, J G Region 3. Office of Director 1p 16279 160 24X Fiche 50-255, 82/11/23, 8212020325
- --B212020331 LER 82-040/03L-0 from 821028-1118, safety injection tank B level reached Tech Spec limits 13 times Caused by minor leakage past loop check valve & tank check valve or fill & drain valve Loss of level indication compounded problem * Consumers Power Co B2/11/23 Region 3, Office of Director 3pp 16279 161 24X Fiche 50-255, 82/11/23, 8212020325
- BP12060357 Forwards nonradiological NPDES permit violation repts for May-Oct 1982 JOHNSON, B D. Consumers Power Co. B2/11/24 KEPPLER, J Q. Region 3, Bffice of Director ip 16311 009 24X Fiche 50-255,82/11/24, B2120A0357
- --8212060371 NPDES noncompliance notification on 821004, max measured TRC value in mixing basin was 0 75 ppm during chlorination of cooling tower A Gaused by excessive chlorine feed for plant conditions Chlorination terminated FOBES, R L. Consumers Power Ca 82/10/13 ip 16311 010 24X Fiche 50-255,82/11/24,8212060357
- --8212060382 RPDES noncompliance motification on 820927, routine weekly sample for oil & grease collected measured 23 0 mg/l Caused by malfunction of emulsion breaker & oil removal sys Emulsion breaker oil filters changed FOBES.R L Consumers Power Co 82/10/12 ip 16311 011 24X Fiche 30-255,62/11/24,8212060357
- --8212060392 NPDE9 noncompliance motification on 820920, routine weekly oil to grease sample collected measured 123 mg/l Caused by malfunction of emulsion breaker sys Emulsion breaker oil filters changed on 820921 FURES, R. L. Consumers Power Co. 82/10/01, 1p. 16311 012 24X Fiche 50-255,82/11/24.8212060957
- --B212060396 NPDES noncompliance notification on 820731, daily max limit of 20 mg/l for oil & grease was exceeded 6 days, resulting in monthly average limit of 15 mg/l being exceeded Cause unknown Oil absorbent pillows changed FDBEG.R L Consumers Power Co 82/08/16 lp 16311 013 24X Fiche 50-255,82/11/24,8212060357
- --B212060412 NPDES noncompliance notification on 820722 & 23.routine pil & grease samples measured 26 5 mg/l & 31 8 mg/l, respectively Gause unknown Dil absorbent pillows changed & floating oil removal devices emptied FOBES.R L. Consumers Power Co 82/09/06 ip 16311 014 24X Fiche 50-255,82/11/24.8212060357
- --8212060421 NPDES noncompliance notification on 820720 routine uil to grease sample indicated 23 5 mg/l concentration Cause unknown Oil absorbent pillows in tank T-41 changed FODES, R L. Consumers Power Co 82/07/30 Ip 16311 015 24X Fiche 50-255,82/11/24,8212060357
- --B212060431 NPDES nancompliance notification on 820712,13 & 14.routine oil & grease samples indicated 21 7 mg/l, 25 5 mg/l & 112 5 mg/l renovel files in emulsion breaking sys Oil filters changed FOBES.R L Consumers Power Co 82/07/22 Ip 16311 016 24X Fiche 50-255.82/11/24.8212060357

- --8212060444 NPDES noncompliance notification on 820528, 29 & 30, routing oil & grease samples indicated 37 7 mg/1, 23 1 mg/1 & 20 B mg/1, respectively Caused by malfunction of oil treatment skid & associated equipment Oil removal filters changed ZIMMERMAN, R. & Consumers Pour Co 62/07/07 3pp 16311 017 24X Fiche 50-255,82/11/24,8212060357
- 82;2060067 Forwards LER 92-042/017-0 JOHNSON, B D Consumers Power Co 82/11/29 MEPPLER, J O Region 3, Office of Director 1p 16314 293 24% Fiche 50-255,82/11/29, 8212040047
- --B2)2060073 LER 82-042/017-0 on 821112, monthly sample of T-B2D (D safety injection tank) showed boron concentration below Tech Spec limit Caused by minor leakage past loop check valve & tank check valve Primary coolant leak monitored # Consumers Power Co B2/11/29 Region 3, Office of Director 2pp 16314 294 24X Fiche 50-255, 82/11/29, 8212040047
- 8212080261 Forwards LER 82-041/03L-0 JGHN80N.B D Consumers Power Co 82/11/30 KEPPLER.J 0 Region 3. Uffice of Director 1p 16354 203 24% Fiche 50-255, 82/11/30. 8212080261
- --8212080271 LER 82-041/03L-0 on 821030.during startup.primary cooling sys sample indicated dose-equivalent [-131 at 1 38 mCi acceding 1 0 mCi limit Caused by todine spiking after change in thermal power Purification flow increased consumers Power Co 82/11/30 Region 3. Office of Director 4pp 16354 204 24X Ficha 50-255,82/11/30.8212080246
- 8212100313 Forwards LER 82-043/03L-0 JOHNSON 8 D Consumers Power Co 82/12/02 KEPPLER, J G Region 3, Office of Director ip 16377 066 24% Fiche 50-255, 92/12/02. 8212100313
- --B212600317 LER 82-043/03L-0 on 82f102.T-82D (D safety injection tank) level dropped below Tech Spec limit of 186 inches Level (ndicating sys & associated alarms failed to respond to level change Caused by leakage past fill & drain valve + Consumers Power Co 82/12/02 Region 3, Diffice of Director 1p 16377 067 24% Fiche 50-255,82/12/02.8212100313
- 8212100249 RD on 821203. safety injection tank T-828 boron concentration fell below Tech Specs & could not be restored within required 1-h limit
 RRIGHIR M Consumers Power Co 82/12/03 KEPPLER. J Region 3.
 Office of Director 3pp 16376 114 24% Fiche 50-255, 82/12/03.
 8212100249
- G212270215 Forwards LER 82-044/01T-0 JOHNSON, B D Consumers Power Co 82/12/13 KEPPLER, J & Region 3, Office of Director 1p 16536 203 24X Fiche 50-255, 82/12/13, 8212270215
- --0212270228 LER 62-044/01T-0 on H2:130.determined that feed breakers & cables to MCC-1 & MCC-2 might overload following LOCA Caused by original load study based on incorrect data New requirements to shed loads instituted

 * Consumers Power Co B2/12/13 Region 3, Office of Director 2pp 16334 204 24% Fiche 50-265, 62/12/13,8212270215
- 8212280450 Forwards LER 62-045/01T-0 JOHNSON,8 D Consumers Power Co 62/12/15 KEPPLER.J Q Region 3, Office of Director 1p 16856 Off 24% Fiche 50-255,82/12/15, 6212280450
- --B212280464 LER 82-045/01T-0 on B21203.T-B28 safety injection tank B level reached itmit of 198 (nches w/boron concentration below limit Caused by minor leakage past loop check valve & tank check valve or fill & drain valve Leak rate monitored * Consumers Power Co 82/12/15 Region 3. Office of Director 2pp 14556 016 24% Fiche 50-255.22/12/15.6212280460
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- BP12030212 Act receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-30. 50-259/82-30. 50-259/82-30. 50-259/82-30. 50-259/82-30. LEWIS.R C. Division of Project & Resident Programs 82/11/30 PARRIS.H 6 Tennessee Valley Authority 1p 16307 067 24X Fiche 50-259.82/11/30.8212030212
- --8212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30, Corrective actions withheld (ref 100FR73 21) MILLS, L. M. Tennessee Valley Authority 82/11/19 O'REILLY, J. P. Region 2. Office of Director ip 16307 068 24X Fiche 50-259, 82/11/30, 8212030212

- --8212030226 Forwards IE Safeguards Insp. Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 920920-24 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) LEWIS.R C Division of Project & Resident Programs 82/10/19 PARRIS,H O Tennessee Valley Authority 2pp 16307 069 24X Fiche 50-239,82/11/30,8212030212
- --8212030202 IE Insp Repts 50-259/82-30.50-260/82-30 & 50-296/82-30 on 820720-24 Noncompliance noted in areas of locks keys & combinations, physical barriers protected areas, lighting & access control Details withheld (ref 10CFR73 21) HALL.8 L. Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24% Fiche 50-259, 82/11/30.8212030212
- 8212080100 Releases public version of revised radiological emergency plan implementing procedures
 FELTON J M Division or Rules and Records 82/12/02 Document Management Branch ip 16367 276 24X Fiche 50-259, 82/12/02, B212080100
- --82(2059)08 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 resemengency plan classification logic & IP-4 resite area emergency Receipt form enci MILLS.L M. Tennessee Valley Authority 82/11/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16367-277-24% Fiche 50-259, 82/12/02.8212080100
- --82(2080)12 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-4 re site area emergency & IP-21 re operations support ctr + Tennessep valley Authority 82/11/01 76pp 16367 280 24% Fiche 50-259, B2/12/02, B212080100
- SP12090080 Act receipt of B21124 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts to-239782-34. 50-240782-36 to-2746/82-36 LEMIS.R C Division of Project & Resident Programs 82/12/06 PARRIS.H G Tennessee Valley Authority 2pp 16357 236 24X Fische 50-259.82/12/06.8212090080
- --U212090092 Responds to NRC 821022 itr re violations noted in IE Safeguards Insp Repts 50-259/82-36.50-260/82-36 & 50-259/82-36 Corrective actions withheld (ref 100FR73 21) MILLS.L.H. Tennessee Valley Authority 82/11/24 O'REILLY, J.P. Region 2. Office of Director ip 16357 238 24X Fiche 50-259,82/12/06,8212090080
- --B212090108 Forwards IE Sefeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-07 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) 0'RETLLY, J P Region 2, Office of Director 82/10/22 PARRISH G Tennessee Valley Authority 2pp 16357 239 24X Fiche 50-259,82/12/06,8212090080
- --9212070124 IE Safeguarde Insp Repts 50-257/82-36, 50-260/82-36 & 50-276/82-36 on 820708-07 Noncompliance noted in area of access controls betails withheld (ref 100FR73 21)
 TILLMAN.A Division of Engineering & Technical Programs
 82/10/20 1p 16357 241 24X Fiche 50-259, 82/12/06, 82120
- 8212170104 Releases public version of revised emergency plan implementing procedures FELTON.JM Davision of Rules and Records 82/12/10 Document Management Branch Ip 16478 104 24X Fiche 50-259,82/12/10.
- --8212170108 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-6,-7 & -29 re emergency telephone listings MILLS.L M Tennessee Valley Authority 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16478 IOS 24X Fiche 50-259,82/12/10.8212170104
- ---B212170112 Public version of revised emergency plan implementing procedures, including Procedures IP-6,-7 \$ -23 re emergency telephone listings
 * Tennessee Valley Authority 82/11/30 7pp 16478 107 24X Fiche 50-259, 82/12/10.8212170104
- 8212170227 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will be completed by 830801 MILLS,L M Tønnessee Valley Authority, 82/12/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 16462 02: P4X Fiche 50-000,82/12/13,8212170227

6 Adjudicatory correspondence

- GC12280028 Forwards nonproprietary "RWR-1 Radwaste Vol Reduction Sys" & NRC topical rept evaluation Matl should aid in settlement negotiations W/o encl RAMSON.R J Hearing Branch 4 82/12/23 PYLE.R B Pyle, R B Ip 16565

(4 General correspondence

- Ge12140478 Forwards missing Pages 65 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear
 - low level radwase storage facility at Sequoyah Nuclear Plant M/o encl LOYSEN.P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 DREY.L A Affiliation Untrown to 16431 321 24X Tiche 50-000.82/11/23.8212140478
- --B212140486 Requests missing pages to EIA on low level radwaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant
- DREY,L A Affiliation Unknown 82/11/08 Office of Nuclear Material Safety & Safeguards, Director 1p 16431 322 24X Fiche 50-000,82/11/23,8212140478

J Insurance & indemnity information

- 8-12020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 DUCK-J-R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 8-2/11/18 HAINES, H L American Nuclear Insurers ip 14288-356-24X Fiche 50-000.82/11/18,8212020269
- 6212280261 Forwards Endorsement 63 to NELIA Policy NF-198 & AZEROGEL Forwards Endorsement 63 to NELIA Policy NF-178 & Indorsement 53 to MECL Policy MF-66
 BUCK.J R. Harsh & McClennan. Inc. M & M. Nuclear Consultants. Inc. Div. 82/12/22
 SALTZMAN.J Assistant Director for State & Licensee Relations
 Spp. 16561.304
 24X Fiche 50-259, 82/12/22, 8212280261
- BP12290246 Forwards Certificates of Insurance N-3B,N-39 & N-40 for Indorsements 1,2 & 3 to NELIA Policy NF-198 & Certificates of Insurance M-3B,M-39 & M-40 for Endorsements 1,2 & 3 to of Insurance M-38.6-39 6 M-40 for Endorsements 1,2 6 3 to MAELU Policy MF-66
 DUCK.J R Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 82/12/23 SALTZMAN, J Assistant Director for State & Licansue Relations 55pp 16582 045 24X Fiche 50-259,82/12/23,8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

- 8212140323 Forwards FSAR Figure 10 7-2, "Mechanical Control Diagram Raw Cooling Water Sys," inadvertently omitted from 820812 submittal SOURCE STATE OF THE STATE OF THE SOURCE STATE OF THE SOURCE STATE STATE OF SOURCE STATE STATE STATE SOURCE SOURCE
- P Operating license stage documents & correspondence
- 82:11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBMR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Seve list encl W/o stated encl LISENHUT, D G Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X
- 9/12140479 SOLOCA DUTSIDE CONTAINMENT AT BROWNS FERRY UNIT 1-ACCIDENT -12140479 SBLOCA DUTSIDE CONTAINMENT AT BROWNS FERRY UNIT 1-ACCIDENT SEGUENCE ANALYSIS CONDON, W A , HARRINGTON, R M , GREENE, S R Oak Ridge National Laboratory FIN B-0452 NUMEGO/CR-2672 VOI 82/11/30 Office of Nuclear Regulatory Research, Director 280pp 16433 074 24X Fiche 50-259, 82/11/30, 8212140479
- S012090118 Confirms arrangements for 821215 meeting in Region 2 ofc re MSIV leakage at Unit 2 Proposed agenda encl O'REILLY, J P Region 2. Office of Director 82/12/01 PARRIS, H G Tennessee Valley Authority 2pp 16357 274 24X Ficha 50-259, 82/12/01, 8212090118
- OP12090346 Confirms 821102 telcon re 821202 enforcement conference r:12070046 Confirms BEIIO2 telcon re BEI202 enforcement conference in Atlanta. GA to discuss results of survey of waste oil facilities & plans for disposing of waste oil D'REILLY. J.P. Region 2. Office of Director BE/12/01 PARRIS, H & fennessee Valley Authority 2pp 16365 157 24X
 Fiche 50-259.82/12/01.8212090346

- 8212070288 Advises that NUREG-0737, Item II K 3 27, "Common Ref Level," #12070288 Advises that NUMEG-0/3/: Item II K 3 27. "Common Ref L will be reviewed w/control room design review as required by ltem I D I Assessment team recommendations will be considered final resolution MILLS, L M Tennessee Valley Authority 82/12/03 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 2pp 16339 O 24X Fiche 50-259, 82/12/03, 82/2070288
- 8212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-6B, changing duration of containment integrated leak rate test from 24-h to 8-h MILLS.L M Tennessee Valley Authority 82/12/03 DENTON,H R Office of Muclear Reactor Regulation, Director 3pp 16357 192 74X Fichs 50-297.82/12/03.8212090083
- --8212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h Justification for proposed revisions encl * Tennessee Valley Authority 82/12/03 35pp 16357 195 24X Fiche 50-259,82/12/03.8212090083
- 8:12270192 Forwards item-by-item description of responses discussed during 821027 telcon w/F Clemenson re technical evaluation rept. "Control of Heavy Loads NUREC-0054." For facility MILLS.L M Tennessee Valley Authority 82/12/14 VASSALLO, D B Operating Reactors Branch 2 44pp 16537 303 24X Fiche 50-259, 82/12/14, 8212270192
- 8P12280085 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h MILLS.L M Tennessee Valley Authority 82/12/17 DENTON.H R Uffice of Nuclear Reactor Regulation. Director 2pp 16564 238 24X Fiche 50-259.82/12/17.8212280085
- ~-8212280088 Proposed Tech Spec changes re bypassing of main steam line tunnel temp switches for up to 4-h * Tennessee Valley Authority 82/12/17 16pp 16564 240 24X Fiche 50~259,82/12/17.8212280085
- 8212280295 Forwards draft response to 821108 request for addl info re implementation of Revision 1 to NUREO-0313 on matl selection & processing for BUR coolant pressure boundary piping MILLS.L M Tennessee Valley Authority 82/12/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 10pp 16562 (24% Fiche 50-259, 82/12/20, 8212280295
- --G212280276 Revision 4 to "Liquid Penetrant Exam Using Color Contrast Removable Method " * Tennessee Valley Authority Fiche 50-259,82/12/20,8212280295 82/03/01 14pp 16562 017 24X
- --8212280297 Revision 1 to "Ultrasonic Exam of Nuclear Power Plant Piping "
 BENTLEY,N R Tennessee Valley Authority 82/09/02 24pp 16562 031 24X Fiche 50-259,82/12/20,8212280295
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-208190240 IE Bulletin B2-03.Revision 1, "Btress Cracking in Thick-Wall).targe-Diameter, Stainless Steel.Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000,82/10/28,8208190240
- 87/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list
- COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000,82/11/05.8208190245
- 8212090456 Ack receipt of 821022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-24. 50-240/82-24 & 50-296/82-24. LEWIS,R C Division of Project & Resident Programs 82/11/12 PARRIS.H 0 Tennessee Valley Authority 1p 16364 009 24X Ficha 50-259,82/11/12,8212090456
- --8212070461 Responds to NRC 820921 ltr re violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 Corrective Repts 30"237/82-24:30-260/82-24 & 50-276/82-24 corrective actions evaluation concerning adequacy of review process will be provided by 830102 MILLS:L H Tennessee Valley Authority 82/10/22 G'RE Region 2. Office of Director 5pp 16364 010 24X Fiche 50-259.82/11/12.8212090456 O'REILLY, J.P.

- --B212090467 Forwards 1E Insp Repts 50-259/82-24.50-260/82-24 & 50-296/82-24 on 820725-0825 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/09/21 PARRIS, H G Tennessee Valley Authority 2pp 16364 015 2AX Fiche 50-259,82/11/12.8212090436
- --8212090471 Notice of violation from insp on 820726-0825 4 Division of Project & Resident Programs 82/09/21 2pp 16364 017 24X Fiche 50-259, 82/11/12.8212090456
- --8212090479 IE Insp Ropts 50-259/82-24,50-260/82-24 & 50-296/82-24 on 820726-0825 Noncompliance noted post-maint testing not conducted on scram pilot valves & test criteria did not incorporate requirements & acceptance limits CMASE.J W. PAULK.O L., CANTRELL.F S. Division of Project & Resident Programs 92/09/09 10pp 16364-019 24X Fiche 50-259,82/11/12,8212090456
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000.82/11/18/8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 1270p 16411 045 24% Fiche 50-000.82/11/26.8208190285
- 8208190257 [E Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB:LI Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- G212030212 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-289/82-30.50-280/82-30.50-280/82-30.50-200/82-80.50-200/82-80.50-200/82-80.50-200/82-80.50-
- --8212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30.50-260/82-30 & 50-294/82-30 Corrective actions withheld (ref 100FR73 21) MILLS.L H Tennesses Valley Authority 82/11/19 (1'REILLY, J P Region 2, Office of Director in 16307-068 24X Fichs 50-259,82/11/30.8212030212
- --G212030226 Forwards IE Safeguards Insp Repts 50-269/82-30, 50-260/82-30 & 50-266/82-30 on 820920-24 & notice of violation Rept details & notice of violation withheld (ref 100FR73 21) LEVIS, R C Division of Project & Resident Programs 82/10/19 PARRIS, H O Tennessee Valley Authority 2pp 18307 089 24X Fiche 50-259, 82/11/30, 8212030212
- --B212030232 IE insp Repts 50-259/82-30, 50-240/82-30 & 50-296/82-30 on 820920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers protected areas, lighting & access control Details withheld (ref 10CFR73 21) HALL.B L , GOODE, W : MCGUIRE, D R Division of Engineering & Technical Programs 82/10/14, 2pp 16307 071 24X Fiche 50-259,82/11/30,8212030212
- BROG190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Syr list encl BEYQUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of Naw York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462:064 24X Fiche 50-000,82/12/03,8208190261
- 8212070080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-237/82-36. 50-240/82-36 & 50-296/82-36 LEMIS, R C Division of Project & Resident Programs 82/12/06 PARRIS, H G Tennessee Valley Authority 2pp 16357 236. 24X Fiche 50-259. 82/12/06. 6212070080
- --B212090092 Responds to NRC 821022 ltr re violations noted in IE Safegoards insp Repts 50-259/82-36.50-260/82-36 & 50-294/82-36 Corrective actions withheld (ref 10CFR73 21) MILLS, L M Tennassee Valley Authority 82/11/24. 0'REILLY, J P Region 2. Office of Director 1p 16057 238 24X Fiche 50-259,82/12/06,8212090080.

- --8212070108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 b 50-296/82-36 on 820908-09 & notice of violation Rept details t notice or violation withheld (ref 10CFR73 21) 0'REILLY.J P Region 2, Office of Director 82/10/22 PARRIS.H O Tennessee Valley Authority 2pp 16357 239 24X Fiche 50-259, 82/12/06/8212090080
- --B212090124 IE Safeguards Insp Repts 50-259/82-36,50-260/82-36 & 50-276/82-36 on 820908-09 Noncompliance nuted in area of access controls Details withheld (ref 100FR/3 21) TILLMAN.A . MCGUIRE, D R Division of Engineering & Technical Programs 82/10/20 ip 16357 241 24% Fiche 50-239,82/12/06.821209080
- 8/212170345 EN-82-041 on 821217, notice of violation & proposed imposition of civil penalty in amount of \$3,125 will be issued to licensee for defective packaging in two shipments of low-specific activity ladwaste to Richland.WA BROCKETT, T. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 82/12/14 ip 16452 362 24X Fiche 50-259,82/12/14,8212170345
- 82/08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring" Svc list enci DEVGUNG.R C Director's Office. Dffice of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, lnc 127pp 16428 191 24% Fische 50-000,82/12/16.8208190247
- 8:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- B.º12270281 Forwards monthly operating repts for Oct 1782 JONES, O T Tennessee Valley Authority 82/11/10 Office of Resource Management, Director 1p 16581 074 24X Fiche 50-259, 82/11/10, 8212290281
- ~-8212E90287 Monthly operating repts for Oct 1982 THOM.7 Tennessee Valley Authority 82/11/01 39pp 16581 0/5 24% Fiche 50~259.82/11/10.8212290281
- 8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
 MILLS, L M Tennessee Valley Authority 82/11/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16304 210
 24% Fiche 50-000, 82/11/30, 8212030071
- S Reportable occurrences, LERs & related correspondence
- B212020348 Forwards LER 82-088/03L-0 GREEN H J Tennessee Valley Authority 82/11/23 O'REILLY, J P Region 2. Office of Director 1p 16288 359 24X f Iche 50-289, 82/11/23, 82/2020348
- --821R020354 LER 82-088/03L-0 on 821028 discovered momentary breach of secondary containment due to personnel access airlock doors between Unit 2 reactor & turbine bldgs being opened at same time Caused by misaligned splenoid Solenbid realigned CARTER-8 Tennessee Valley Authority 82/11/23 Region 2. Office of Director 2pp (6288-360-24X Fiche 50-259,82/11/23, 2019/2020
- 8212030039 Forwards LER 82-094/03L-0 GREEN.H J Tennessee Valley Authority 82/11/26 O'REILLY, J P Region 2, Office of Director 1p 16304 128 24X Fiche 50-259.82/11/26.8212030039
- ---8212030044 LER 82-094/03L-0 on 821027, smoke detector X5-39-66XM alarmed, potentially masking signals from other detectors Caused by water in detector Firewatch established & water removed ** Tennessee Valley Authority 62/11/26 Region 2, Office of Director 2pp 16304 129 24X Fiche 50-259, 82/11/26, 8212030039
- BP12090109 Forwards LER B2-093/01T-0 GREEN.H J Tennessee Valley Authority B2/11/30 O'REILLY, J P Region 2. Office of Director ip 16357 279 24X Fiche 50-259. B2/11/20. B212090109
- --B212090116 LER 82-093/01T-0 on B21118, safety injection valves 4 2 B-31.
 4 2 B-36 & 4 2 B-37 left in normally open position contrary
 to requirement that valves be administratively controlled w/
 power lifted Caused by procedural inadequacy
 KRAUSE, L. L. Tennessee Valley Authority B2/11/30 Region 2.
 Office of Director 2pp 16357 280 24X Fiche 50-259,82/11/30,
 B212090109

- GP12090280 Forwards LER 82-089/03L-0 GREEN.H J Tennessee Valley Authority 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 14365 267 24X Fichs 50-289, 82/12/03.8212090280
- --8212090291 LER 82-089/03L-0 on 821103, during primary containment purge sys filter pressure drop test.primary purge sys failed to achieve required flow rate Caused by clogged HEPA filters New filters installed & satisfactorily tested MULLING K. Tennessee Valley Authority 82/12/03 Region 2, 0ffice of Director 2pp 16365 268 24X Fiche 50-259,82/12/03,8212090280
- --3212090369 LER 82-093/03L-0 on 821104, secondary containment breached when turbine to reactor bldg doors opened simultaneously during door interlock maint Caused by insufficient control while interlocks inoperable Door watch instructions written CARTERS Tennessee Valley Authority 82/12/03 Region 2, Office of Director 2pp 16364 191 24X Fiche 50-259,82/12/03.
- 9.12140440 Forwards LER 82-091/03L-0 ORECN,H J Tennessee Valley Authority 82/12/09 O'REILLY,JP Regian 2. Office of Director 1p 16404 178 24X I iche 50-259, 82/12/08,8212140440
- ~-8212140444 LER 82-091/03L-0 on 821107, during diesel generator monthly test control room operator unable to raise speed of diesel generator D Caused by failed Woodward Governor Co microswitch Suitch replaced CHRISTOPHER.W Tennessee Valley Authority 62/12/08 Region 2, Office of Director 2pp 16404 179 24X Fiche 50-259,82/12/08, 8212140440
- 8./12150046 Forwards LER 82-092/03L-0 GREEN-H J Tennessee Valley Authority 82/12/10 G'REILLY, J P Region 2. Office of Director 1p 16430 191 24X fiche 50-259, 82/12/10,8212150066
- --B212150069 LER 82-092/03L-0 on 821116, reactor pressure switches PS-68-93 & PS-68-64 found operating below Tech Spec requirements Caused by calibr drift Switches recalibr & returned to svc IRBY.B J Tennessee Valley Authority 82/12/10 Region 2, Office of Director 3pp 16430 192 24X Fiche 50-259,82/12/10, R912150066
- 8P12280147 Forwards LER 82-076/01T-0 ORECN:H J Tennessee Valley Authority 82/12/20 G'REILLY, J P Region 2, Ofrice of Director ip 16563 119 24X Fishe 50-259: 82/12/20,8212280147
- --8212280153 LER 82-096/01T-0 on 821206.during startup.control rod 18-51 double notched from 08 to 12.resulting in large reactivity insertion & causing reactor to scram Cause attributed to normal degradation of control rod drive seals WIROD.M D Tennessee Valley Authority 82/12/20 Region 2. Office of Director 2pp 16563 120 24X Fiche 50-259.82/12/20, 8212280147
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 09/12030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-299/82-30. 50-260/82-30 to 50-296/82-30 LEMIS.R C Division of Project & Resident Programs 82/11/30 PARRIS.H 0 Tennesses Valley Authority ip 16307 067 24X Fiche 50-259. 82/11/30.8212030212
- --B212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref 10CFR73 21) MILLS.L H Tennessee Valley Authority 82/11/19 O'REILLY, J P Region 2. Office of Director ip 16307 068 24X Fiche 50-259,82/11/30.8212030212
- ~-8212030226 Forwards IE Safeguards Insp Repts 50~259/82~30.50~260/82~30 & 50~276/82~30 on 820920~24 & notice of violation Rept details & notice of violation withheld (ref 100FR73 21) LEHIS,R C Division of Project & Resident Programs 82/10/19 PARRIG.H O Tennessee Valley Authority 2pp 16307 069 24X Fiche 50~259,82/11/30.82(2030212

- ---8212030232 IE Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 on 820920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers protected areas, lighting & access centrol Details withheld (ref 10CFR73 21) HALL. B L Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24% Fiche 50-259.82/11/30.8212030212
- 8P120B0100 Releases public version of revised rediplogical emergency plan implementing procedures FELTGH.J M Division of Rules and Records 82/12/02 Document Management Branch 1p 16367 276 24X Fiche 50-259,82/12/02.8212080100
- --8212080108 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic & IP-4 re site area emergency Receipt form enci MILLS,L M Tennesse Valley Authority 82/11/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 16367 277 24X Fiche 50-257,82/12/02.8212080100
- --B2120B0112 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic. IP-4 re site area emergency & IP-21 re operations support ctr # Tennessee Valley Authority B2/11/01 7App 16367 280 24X Fiche 50-259, 82/12/02,8212080100
- 8212090080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-289/82-36.50-2460/82-36 50-294/82-36 LEWIS,R C Division of Project & Resident Programs 82/12/06 PARRIS.H G Tennessee Valley Authority 2pp 16357 236 24X Fiche 30-259,82/12/06.821209080
- --B212070072 Responds to NRC B21022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21) MILLS, L. H. Tannessee Valley Authority 82/11/24 O'REILLY, J. P. Region 2. Office of Director in 16357 238 24X Fiche 50-259, 82/12/06/8212090080
- --8212070108 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-276/82-36 on 820708-07 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) O'REILLY, J.P. Region 2. Office of Director 82/10/22 PARRIS, H O Tennessee Vailey Authority Rpp 16357 239 24% Fichs 50-259, 82/12/06, 8212070080
- ---8212090124 IE Safeguards Insp Repts 50-259/82-36,50-260/82-36 & 50-296/82-36 on 820908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21) TILLMAN, A Division of Engineering & Technical Programs 62/10/20 ip 14357 241 24X Fiche 50-259,82/12/06,8212090080
- 8212170104 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16478 104 24% Fiche 50-259.82/12/10, 8212170104
- --8212170108 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings MILLS,L H Tennessee Valley Authority 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16478 105 24X Fiche 50-259, 82/12/10.8212170104
- --G212170112 Public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency telephone listings
 * Tennessee Valley Authority 62/11/30 7pp 16478 107. 24X
 Fiche 50-259,82/12/10,8212170104
- 8212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training. Training per 10GFR30 54(p) will be completed by 830801 MILLB.L H Tennessee Valley Authority 82/12/13, DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 16462 020 24X Fiche 50-000, 82/12/13,8212170229

O Adjudicatory correspondence

8P12280028 Forwards nonproprietary "RWR-1 - Radwaste Vol Reduction Sys" & NRC topical rept evaluation Matl should aid in settlement magnetiations W/o encl RAMBON, R.J. Hearing Branch 4, 82/12/23 PYLE, R.B., Pyle, R.B. 1p 16545 143 24X Fichs 50-259, 82/12/23, 8212280028

DOCKETED ITEMS

H General correspondence

- 82:2140478 Forwards missing Pages 65 & 66 of EIA re jou level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear
 - Plant W/O enci LOYSEN.P Advanced Fuel & Spent Fuel Licensing Branch B2/11/23 DREY.L A Affiliation Unknown ip 16431 321 24X Fiche 50-000, 82/11/23, 9212140478
- ~~6212140486 Requests missing pages to EIA on low level radwasts storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Bequoyah Nuclear Plant DREYLL A Affiliation Unknown 82/11/08 Uffice of Nuclear Paterial Safety & Safety and s. Director 1p 16431 322 24X Fiche 50-000. 82/11/23. 8212140478

J Insurance & indemnity information

- 82:12020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 DUCK, J. R. Marsh & McLennan, Inc. M & M. Nuclear Consultants, Inc. Div 82:4116 HANES, H. & American Nuclear Insurers ip 16288-356

 V4x Fich# 50-000-82/11/18,8212020269
- 8P12280261 Forwards Endorsement 63 to NELIA Policy NF-198 & Indorsement 53 to MAELU Policy MF-66
 8UCK.J R. Harsh & McLennan, Inc. M & M Nuclear Consultants, Inc. Div 82/12/22 SALTZMAN.J Assistant Director for State & Licensee Relations 3pp 16561 304 24X Fiche 50-259.82/12/22,8212280261
- 6/12270246 Forwards Certificates of Insurance N-38,N-39 & N-40 for Endorsements 1,2 & 3 to NELIA Policy NF-198 & Certificates of Insurance M-38,M-39 & M-40 for Endorsements 1,2 & 3 to
- of Insurance M-38, M-39 & M-40 for Endorsements 1,2 & 3 to MAELU Policy NF-66
 DUCK,J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div. 82/12/23 GALTZMAN,J Assistant Director for State & Licensee Relations 55pp 16582 045 24% Fiche 50-259, 82/12/23,8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

- 6.412140323 Forwards FSAR Figure 10 7-2. "Mechanical Control Diagram Raw Cooling Water Sys." inedvertently emitted from 8208/2 submittal
 - AdMER.D S Tennessee Valley Authority 82/12 Office or Nuclear Reactor Regulation, Director P4X Fiche 50-259,82/12/07.82(214032) 82/12/07 DENTON.H R rector 2pp 16402 DS

P Operating license stage documents & correspondence

- BP11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors 'ileguoch Generic Ltr 82-27 to all BWA literasees of oper ricept LACCRWA. Dig Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NURSC-0763 & NURSC-0763 Svc list encl N/o stated encl LIBERHUT, D G Division of Licensing 82/11/15 G Utilities - GPU Bervice Corp 22pp 16387 004 24X fiche 80-000, 82/11/15, 821/230066 General Public
- BP1207011B Confirms arrangements for S21215 meeting in Region 2 ofc re MSIV leakage at Unit 2 Proposed agenda entl O'REILLY.JP Region 2, Office of Director 82/12/01 PARRIS,N G Tennessee Valley Authority 2pp 16357 274 24X Fiche 50-259, 82/12/01,821207011B
- 8212090346 Confirms 821102 tolcon re 821202 enforcement conference Algorouse Confirms Bailor tollon to bailor elliptement conference in Atlanta.GA to discuss results of survey of waste oil dractifities & plans for disposing of waste oil GractLLY.J P Region 2. Office of Director 82/12/01 PARRIS.H G Tennessee Valley Authority 2pp 16365 157 24%

 Fiche 50~259.82/12/01.8212090346
- 8212070298 Advises that NUREG-0737, Item 11 K 3 27, "Common Ref Level," will be reviewed w/control room design review as required by Item I D 1 Assessment team recommendations will be tonsidered final resolution
 HILLB.L. M Tennessee Valley Authority 82/12/03 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 16339 0
 24% Fiche 50-297.82/12/03.6212070288 1A339 013
- 8212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing duration of containment integrated leak rate test from 24-h to 8-h HILLS, L H Tennessae Valley Authority 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 16357 192 24% Fiche 50-259,82/12/03,8212090083

- --8212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h Justification for proposed revisions encl * Tennessee Valley Authority 82/12/03 34pp 16357 195 24X Fich
- 8912170134 Application to amend License DFR-52, requesting changes P12170136 Application to amend License DFR-52 requesting change needed to reflect surveillance testing of electrical sys Info suppls 821015 & 1117 applications MILLS.L M Tennesses Valley Authority 82/12/10 DENTON.H R Giffice of Nuclear Reactor Regulation. Director 2pp 16453 00 24X Fiche 50-260,82/12/10,8212170136
- --B212170140 Proposed Tech Spacs reflecting surveillance testing of electrical sys

 * Tennessee Valley Authority

 Fiche 50-260, 82/12/10, 8212170136 82/12/10 3pp 16453 006 24%
- 8212270192 Forwards iten-by-item description of responses discussed during 821027 teleon w/F Clemenson re technical evaluation rept. "Control of Heavy Loads NURES-O654." For facility MILLS.L M Tennessee Valley Authority 82/12/14 VASSALLO.D B Operating Reactors Branch 2 44pp 16997 303 24x Fiche 50-257.82/12/14.8212270192
- BP12280085 Application to amend Licenses DPR-33.DPR-52 & DPR-68, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h HILLS,L H Tennesses Valley Authority 82/12/17 DENTON,H R Dffice of Nuclear Reactor Regulation, Director 2pp 16564 2: 24X Fiche 50-259,82/12/17,8212280085
- --8212280088 Proposed Tech Spec changes re bypassing of main steem line tunnel temp switches for up to 4-h * Tennessee Valley Authority 82/12/17 16pp 16564 240 24X Fiche 50-239,82/12/17.8212280085
- 8£12280275 Forwards draft response to 821108 request for add1 info re implementation of Revision 1 to NUREG-0313 on mat1 selection & processing for BWR coolant pressure boundary MICLS.L M Tennessee Valley Authority 82/12/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 10pp 16562 00/ PAX Fiche 50-259,82/12/20,8212280295
- & Inspection reports, IE Bulletins & correspondence
- B2:08190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping of BMR Plants " Syc list encl BEYBUND, RC Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, luc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208170240
- 8:08:90245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 t Model 802 Thermoluminescent Dosimeters" Svc list (CBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000.82/11/05,8208190245
- GP12090456 Ack receipt of 821022 ltr informing NRC of steps taken to carrect violations noted in IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-260/82-24 & 50-260/82-24 & EMIS.R C Division of Project & Resident Programs 82/11/12 PARRIS.H Q Tennessee Valley Authority 10 16364 009 24X Fiche 50-259, 82/11/12, 8212090456
- ---B212090461 Responds to NRC 820921 ltr re violations noted in IE Insp Repts 50-259/82-24,50-260/82-24 & 50-296/82-24 Corrective actions evaluation concerning adequacy of review process will be provided by 830102 MILLS, L.M. Tennessee Valley Authority 82/10/22 D'REILLY, J.P. Region 2, Office of Director 5pp 16364 010 24X Fiche 50-259,82/11/12.8212090456
- --8212090467 Forwards IE Insp Rapts 50-259/82-24,50-260/82-24 & 50-296/82-24 on 820725-0825 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/09/21 PARRIS.H 0 Tennessee Valley Authority 2pp 16364 015 24X Fiche 50-299,82/11/12.8212090436
- --8212090471 Notice of violation from insp un 820726-0825 # Division of Project & Resident Programs 82/09/21 16344 017 24X Fiche 50-259, 82/11/12, 8212090454

- -B212070479 IE Insp Repts 50-259/82-24.50-260/82-24 & 50-296/82-24 on 820726-0825 Noncompliance noted post-maint testing not conducted on scram pilot valves & test criteria did not incorporate requirements & acceptance limits CMASE. J W. PAULK. 6 L. CANTRELL. F S Division of Project & Resident Programs 82/09/09 10pp 16364 019 24X Fiche 50-259.82/11/12.8212090456
- BPOB190251 IE Info Notice 82-44, "Clarification of Emergency P)an Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co. of New York, Inc. 109pp 1641
- 8708190256 IE Info Notice 82-46. "Defective & Obsolete Combination Madlocks " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- GEOB190257 IE Into Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COSB.L I Division of Fuel Facilities. Materials & Safeguards G2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24% Fiche 50-000,82/11/30.8208170257
- G.12030212 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/623-30, 50-260/62-30 & 50-259/628-30 & 50-200
- --8212030220 Responds to NRC 821019 ltr re violations noted in IL Sareguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref loCFR73 21) MILLS.L. M. Tennesse Valley Authority 82/11/19 0'REILLY, J.P. Region 2, 0ftice of Director [p. 16307 068 24X Fiche 50-259, 82/11/30, 8212030212
- --B212030226 Forwards IE Safeguards Insp Repts 50-259/82-30,50-260/82-30 & 50-296/82-30 on 820920-24 & notice of violation Rept details & notice of violation withheld free 100ER73 21) LEMIS.R C Division of Project & Resident Programs 82/10/19 PARRIS.H C Tennessee Valley Authority 2pp 16307 069 24X Fiche 50-259,82/11/30,8212030212
- --B212030232 IE Insp Repts 50-259/82-30.50-260/82-30 & 50-296/82-30 on B20920-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers -- protected areas. lighting & access control Details withheld (ref 10CFR73 21) HALL, B L . GUDDE, R W . NCGUIRE, D R Division of Engineering & Technical Programs B2/10/14 2pp 16307 071 24X Fiche 50-259, 82/11/30, 8212030212
- 6:06190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets ' Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consultdated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- BP:2090080 Act receipt of 821124 lt: informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-239/82-34. 50-239/62-34. 50-239/62-34. 50-246/82-34. LEWIS.R C Division of Project & Resident Programs 82/12/04. PARRIS.H G Tennesses Vailey Authority 2pp 16357 236 24X Fiche 50-259.82/12/04.8212090080
- --B212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards Insp Repts 30-259/82-36.50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16357 238 24X Fiche 50-259,82/12/06.8212090080
- --B212070109 Forwards IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 on 820908-09 & notice of violation eept details & notice of violation withheld (ref 10CFR73 21) O'REILLY, J P Region 2, Office of Director 82/10/22 PARRIS, H O Tennessee Valley Authority 2pp 16357 239 24% Fichs 50-259, 82/12/06, 8212090080

- --8212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-294/82-36 on 820908-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR73 21)
 T(LLMAN.A., MCGUIRE.D.R. Division of Engineering & Technical Programs 82/10/20 ip 16357-241 24% Fiche 50-259,82/12/06,8212090080
- 6712170345 EN-82-041 on 821217.notice of violation 5 proposed imposition of civil penalty in amount of \$3.125 will be issued to licenses for defective packaging in two shipments of low-specific activity radwaste to Richland. WA BROCKETT, T. AXELRAD. J Director's Office. Office of Inspection and Enforcement 82/12/14 p 14452 362 24X Fiche 50-259,82/12/14, B212170345
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- GP12290281 Forwards monthly operating repts for Oct 1982 JONES.0 T Tennessee Valley Authority B2/11/10 Office of Resource Management. Director 1p 16581 074 24X Fiche 50-259.82/11/10.8212290281
- --8212270287 Monthly operating repts for Oct 1982 THOM.T Tennessee Valley Authority 82/11/01 39pp 16581 0/b 24< Fiche 50-259,82/11/10.8212290281
- 8P12030071 Forwards central emergency control ctr mateorological data availability statistics for Apr-Sept 1782
 MILLS.L M Tennessee Valley Authority 82/11/30 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 16304 210
 24X Fiche 50-000,82/11/30.8212030071
- S Reportable occurrences. LERs & related correspondence
- 8712020143 Forwards LER 82-035/03L-0 GREEN,H J Tennessee Valley Authority 82/11/23 O'RE(LLY, J P Region 2. Office of Director ip 16274 167 24X Fiche 50-260,82/11/23,8212020143
- --8212020153 LER 82-035/03L-0 on 821101.during refueling outage.upper mechanical snubber on main steam line D found inoperable Cause unknown Pacific Scientific snubber P8A-10 S/N 474 replaced & functionally tested KERR.T Tennessee Valley Authority 82/11/23 Region 2. Office of Director 2pp 16274 168 24X Fiche 30-260.82/11/23, 82/2020143
- BP12090143 Forwards revised LER 82-026/03X-1 OREEN.H J Tennessee Valley Authority 82/11/30 O'REILLY.J P Region 2. Office of Director Ip 16359 169 24X Tiche 50-260.82/11/30.8212090143
- --8212090153 Revised LER 82-026/03X-1 on 820819, during refueling outage maint on recircultation sus hydraulic snubbers, snubber BSIA found lou on fluid & declared inoperable Caused by fluid leakage at D rings in hydraulic oil tube fittings KERR: T Tennessee Valley Authority 82/11/30 Region 2, Office of Director 2pp 16399 170 24X Fiche 50-240,82/11/30, 8212090149
- 8212150101 Ferwards LER 82-036/03L-0 QREEN.H J Tennessee Valley Authority 82/12/10 O'REILLY, J P Region 2. Office of Director ip 16430 355 24X Fichs 50-260.82/12/10.8212150101
- --8212150104 LER 82-036/03L-O on 821113.during refueling outage.reactor bidg continuous air monitor 2-90-250 became inoperable due to broken drive belt on sample gump Gaused by normal wear Std v-belt for Switter Model 325 svc air pump replaced THORPE.D Tennessee Valley Authority 82/12/10 Region 2. Office of Director 2pp 16430 356 24X Fiche 50-240,82/12/10,8212150101
- 8212220463 Forwards LER 82-039/01X-0 OREEN.H J Tennessee Vailay Authority 82/12/17 O'REILLY.J P Region 2. Office of Director 1p 14504 254 24X Fiche 50-240.82/12/17,8212820463

- ~~B212220472 LER 82-039/01X-0 on 821204.during fuel outage, level switches LS-73-574 & 578 found inoperable Caused by stuck Robert Shaw Model B278-C3 level switch floats Floats freed & level switches recallbr
 - Model B2/70-03 terms served with the served at the served at the IRGV.B J Tennessee Valley Authority 82/12/17 Region 2. Office of Director 2pp 16504 255 24% Fiche 50-260,82/12/17. 8212220463
- 8212280099 Forwards LER 82-037/03L-0 OREEN.H J Tennessop Valley Authority 82/12/20 O'REILLY, J P Region 2. Office of Director 1p 16564 221 24X Fiche 50-260,82/12/20,8212280099
- --0212280106 LER 82-037/03L-0 on 821122, while performing local leak rate tests during refueling outage total as-found leakage from primary containment found greater than allowable, per Tech Spec 4 7 A 2 g Causad by deterioration of valve seating MCPHERSON.R Tennessee Valley Authority 62/12/20 Region 2, Office of Director 5pp 16564 222 24x Fiche 50-260,82/12/20,821280099
- 8212280453 PND-II-82-138 cracks detected in two branch connection welds of ring header during ultrasonic exam per IE Bulletin 82-03 & NUREG-0313. Revision I Confirmatory radiographic tests planned Util will contract w/GE for analysis BLAKE, J J . VERRELLII D M Region 2. Office of Director 82/12/22 2pp 14556 004 24% Fiche 50-260.82/12/22.8212280453

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans
- 82:12070345 Forwards IE Insp Rept 50-261/82-37 on 821012-15 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/11/03 UTLEY,E E Carolina Power & Light Co ip 16365 137 24X Fiche 50-261,82/11/03
- --8212090351 IE Insp Rept 50-261/82-39 on 821012-15 No noncompliance noted Major areas inspected emergency preparedness exercise CLINE. W E. JENKINS. 9 R Region 2. Office of Director 82/11/02 12pp 16365 140 24X Fiche 50-261.82/11/03,8212090345
- GP12290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl FELTON, J B Division of Rules and Records 82/11/30 SCHLISSEL, D A. New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060
- --B212270155 Responds to NRC 731211 ltr re-violations noted in IE Insp Rept 50-261/75-14 Corrective actions quarterly calibr of survey instruments will be performed per Health Physics Procedure HP-11 by 760131 & Procedure HP-1 will be revised UTLEY, E.E. Carolina Power & Light Co. 76/01/05 MOSELEY, N.C. Region 2. Atlants. Office of the Director 4pp 16608-018 24X Fiche SD-000, 82/11/30, 8212270060
- --8212270165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliances noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" caller data PARKER.R C , LEMIS.R C , WHITENER.H L. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/16 17pp 16608 024 24x Fiche 50-000.82/11/30,8212270060
- 8P12100015 Confirms & documents previous info submitted in response to Generic Ltr 81-10, "Emergency Operations Facility (EDF) "Original util response submitted 810218 EDF located onsite & constructed of concrete ZIMMERMAN, 8 R Canolina Power & Light Co. 82/12/06 VARGA, S A Operating Reactors Branch | 3pp. 16379 160 24X Fische 50-261, 82/12/06, 8212100015
- 8/12/20487 Forwards draft SER App R exemption request Exemption denied Licenses required to provide capability to achieve cold shutdown within 72-h VARGA S A Operating Reactors Branch 1 82/12/10 UYLEY.E C Carolina Power & Light Co 38pp 16523 206 24X Fiche 50-261.82/12/10.8212220487
- P Operating license stage documents & correspondence
- 8212040130 Forwards notice of proposed issuance of amend to License DPR-23, in response to 820701 & 0716 ltrs describing plans to replace steam generators during 1963 refueling outage VARGA.S A Operating Reactors Branch 1 82/11/18 UTLEY.E E Carolina Power & Light Co 3pp 16322 353 24X Fiche 50-261,82/11/18,8212060130

- --B212060137 No+ice of proposed issuance of amend to License DPR-23 VARGA:S A Operating Reactors Branch 1 82/11/18 4pp 16322 356 24X Fiche 50-261.82/11/18.8212060130
- 8212060069 Responds to Generic Ltr 82-22 re steam generator tube maint Plant has experienced occasional minor tube leakage over last 4 yrs Replacement steam generators have been ordered & replacement will start in late 1983 EURY.L W Carolina Power & Light Co 82/11/29 EISENHUT.D G Division of Licensing 2pp 16314 291 24X Fiche 50-261.82/11/29.8212060069
- 8212140459 CONCENTRATIONS OF COPPER-BINDING PROTEINS IN LIVERS OF BLUEGILLS FROM THE COOLING LAKE AT THE H B ROBINSON NUCLEAR POWER STATION HARRISON,F L . LAM, J R Lawrence Livermore Laboratory FIN A-0119 NURES/CR-2822 82/11/30 Office of Nuclear Regulatory Research, Director 40pp Available at NRC \$4.50 16418 325 24X 11che 50-261.82/11/30,8212140459
- 8212040013 Forwards proprietary "HB Robinson Loss of Feedwater Transient at 1,955 MMt Model Description & Results " Rept withheld (ref 10CFR2 790) ZIMMERMAN.S R Carolina Power & Light Co 82/12/01 VARGA.S A Operating Reactors Branch 1 5pp 16313 279 24x Fiche 30-261.82/12/01.6212040013
- SP12100021 Advises that response to deficiencies noted in "Control Room Habitability Evaluation MO Robinson Steam Electric Generating Plant: "uil not be submitted until 830601, due to increased scope of evaluation 71MMERMAN.S R Carolina Fower & Light Co 82/12/07 VARGA.S A Uperating Reactors Branch 1 [p 16379 132 24X [iche 50-261,82/12/07,8212100021
- B?1210007B Forwards project plan for resolving pressurized thermal shock issue Independent consultant will review & assess inverall program
 UTLEY, E E Camplina Power & Light Co B2/12/07 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 14po 16379 163
 24X Fishs 50-861, B2/12/07, B21210007B
- UP12150004 Informs that NRC recommendation that util provide plan addressing pressurfied thermal shock issue unnecessary Util B21207 commitment adequately addresses issue EURY.L W Carolina Power & Light Co 82/12/08 PALLADING, N J Gormissioners 2pp 16422 331 24X Fiche 50-26t, 82/12/08, R212150004
- 四次のB190243 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of itr Svc list encl EISENがUT、D G Division of Licensing 82/12/09 Consolidated Edison Co of New York・Inc 29pp 16627 247 24% Fiche 50-000、82/12/09、8208170263
- G:/12130313 Forwards revised "HB Robinson Unit 2 Inservice Insp Program." Interval 2.810307-910307. Incorporating items discussed during 821018.21 & 26 telcons Revision supersedes 610310 & 1231 submittals ZIMMERHAN.S R Carolina Power & Light Co 82/12/09 VARGA, S A Uperating Reactors Branch 1 p 16389 345 24X fiche 50-261.82/12/09.8212130313
- G:/12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One.Unit 2 & San Onefre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISEMHUT, D & Division of Licensing 82/12/10 Yankee Atomic Flettric Co 27ep 14690 035 24X Fiche 50-000,82/12/10, 6212140103
- Bi:12220465 Forwards Amend 73 to License DPR-23, safety evaluation & notice of issuance & availability Amend removes 3 effective full-pouer nonths during Cycle 9 operations REGUA:0 Operating Reactors Branch 1 82/12/10 UTLEY.E E Carolina Pouer & Light Co 2pp 16523 180 24X | Iche 50-261, 82/12/10,8212220465
- --8212220470 Amend 73 to License DPR-23, removing 3 effective full-power months during Cycle 9 operations VARGA,8 A Decrating Reactors Branch 1 82/12/10 2pp 16523 182 24X Fiche 50-261,82/12/10.8212220465
- --8212220474 Bafety evaluation supporting Amend 73 to License DPR-23 * Office of Nuclear Reactor Regulation, Director 82/12/10 App 16523 184 24X First 50-241.02/12/10,8212220465
- G212220477 Notice of issuance & availability of Amend 73 to License DPR-23 VARQA, G A Operating Reactors Branch 1 82/12/10 2pp 18523 190 24X Fiche 50-261,82/12/10,8212220465

- G.12300083 Forwards request for add1 info re NUREG-0737. Item II E 1 2,
 "Auxiliary Feedwater Sys Automatic Initiation & Flow
 Indication " Response to all open items requested within 60 days
 VARGA. S A Operating Reactors Branch 1 82/12/10 UTLEY. E Carolina Power & Light Co 8pp 16624 266 24X
 Fiche 50-261.82/12/10.8212300083
- G,1221005B Forwards responses to draft technical evaluation rept re util submittals in response to NUREC-0612. "Control of Heavy loads "Changes to insp of lifting devices, use of qualified operators & replacement of defective devices implemented TIMMERMAN, 5 R Carolina Power & Lipht Co 82/12/15 VARGA, S A Operating Reactors Branch | 51pp 16485 176 24X Fiche 50-261, 82/12/15, 8212210068
- 8/12210418 Responds to 820724 request for add1 design info re NUREG-0737. Item II B 3. "Post-Accident Sampling Sys " Sys will be described in revision to updated FSAR by 803722 IIMERMAN, S R Carolina Power & Light Co 82/12/15 VARGA, S A Uperating Reactors Branch I Ip 16493 094 24X Fiche 50-261, 82/12/15, 8212210418
- 8212290200 Discusses 820415 response to Generic Ltr 82-05 re NUREO-0737. Item II 8 3. "Post-Accident Sampling" & commitment to have sys operational by 830101 Due to problems, operational date revised to 830211

 FURR. B J Carolina Power & Light Co 82/12/21 EISENHUT, D G

 Division of Licensing 2pp 16578 199 24X Fiche 50-261,82/12/21,8212290200
- GP12280078 Responds to Generic Ltr 82-16 re NUREG-0737 Tech Specs, discussing status of items applicable to plant IMMERIANS R Carolina Power & Light Co 82/12/23 EISENHUT, D 0 Division of Licensing 6pp 16565 127 24X Fiche 50-261,82/12/23,8212280078
- G:12290469 Staff requirements memo summarizing 821209 discussion & voter in Washington. DC repressurized thermal shock actions. Levelopment of proposed rule establishing radiographic test. NDT screening criturian recommended. CHILK. S. J. Office of the Secretary of the Commission 82/12/23 DIRCKS, W. J. Office of the Executive Director for Operations 2pp. 16606-084 24X Fiche 50-261,82/12/23.8212290469
- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IF Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at 8kR Plants " Syc list encl UEYOUNG.R C Director's Office. Office of Inspection and Cnforcement 82/10/28 Consolidated Edison Co of New York. Inc 182p 16462 163 24X Fiche 50-000.82/10/28.8208190240
- GM12090345 Forwards IE Insp Rept 50-261/82-39 on 921012-15 No noncompliance noted VERRELLIDM Division of Project & Resident Programs 92/11/03 UTLEV, E E Carolina Pawer & Light Co ip 16365 139 24X Fiche 50-261, 92/11/03, 8212090345
- 8212090351 IE Insp Rept 50-261/82-39 on 821012-15 No noncompliance noted Major areas inspected emergency preparedness exercise CLINE.W E. JENKINS. 9 Region 2. Office of Director 82/11/02 12pp 16365 140 24% fiche 50-261.82/11/03,8212090345
- B#0B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list cncl COBB.L I Division of Futl Facilities, Materials & Bafeguards BZ/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000,82/11/05,8208190245
- G712090281 Forwards IE Insp Rept 50-261/82-38 on 821103-05 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/11/16 UTLEY,E E Carolina Power & Light Co 2pp 16365 260 24X Fiche 50-261,82/11/16,8212090281
- -U212090288 IE Insp Rept 50-261/82-38 on 821103-05 No nancompliance noted Major areas inspected radiological environ monitoring, mgt & administrative controls, implementation of monitoring program, analytical OC & interlab comparison program CUMINGHAM, A L , MONTGOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/15 Spp 16365 262 244 Fiche 50-261.82/11/16.8212090281
- 8908190251 IE Info Notice 82-44, "Clarification of Emergency Plan Izercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Editson Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251

- 8212090464 Confirms 821124 mgt meeting in Atlanta, GA to discuss enforcement significance re shipping of contaminated matl Proposed meeting agenda encl G'REILLY, J.P. Region 2. Office of Director 82/11/18 UTLEY, E. Carolina Power & Light Co. 2pp 16364 121 24X Fiche 50-261, 82/11/18, 8212090464
- 8:08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYQUNG: C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc. 127pp 16411 065 24% Fiche 50-000; 82/11/26.8208190256
- 8,08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radicactive Matl " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards BZ/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 8212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Oinna & Indian Point 3 encl
 FELYON, J M Division or Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060
- --8212270121 Forwards listed documents re IE Insp Rept 50-261/75-15 Documents filed in LPDR MCSELTY.N C Region 2. Atlanta, Office of the Director 76/01/2. Hartsville,SC 1p 16608 006 24X Fiche 50-000.82/11/30, 0212200040
- --8212290125 Ack receipt of IE Insp Rept 50-261/75-15 on 751124-25 No proprietary info UTLEY.E E Carelina Power & Light Co 76/01/14 MOSELEY.N C Region 2. Atlanta, Office of the Director ip 16608 007 24X Fiche 50-000, 82/1/30.8212/90060
- --8212290133 Forwards IE Insp Rept 50-261/75-15 on 751124-25 No noncompliance noted MOSELEY, N C Region 2, Atlanta, Office of the Director 75/12/24 JONES, J A Carolina Power & Light Co 2pp 16608 008 24X Fiche 50-000, 82/11/30, 8212290060
- --B21227013B IE Insp Rept 50-261/75-15 on 751124-25 No noncompliance noted Major areas inspected inservice inspersolts & procedures & eddy current inspersolts and generator tubes PARKER, R. C., LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch HERDI, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/12/17 6pp 1640B 010 24X Fiche 50-000, 82/11/30,8212270060
- 8212270144 Furwards listed documents re IE Insp Rept 50-261/75-14 Documents filed in LPDR MOSELEY.N C Region 2. Atlanta, Office of the Director 76/01/10 Hartsville, SC 1p 16608 016 24X Fiche 50-000, 82/11/30, 8212270060
- --8212290148 Ack receipt of 760105 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-261/75-14 LONG:F J Region 2. Atlanta: Reactor Operations Nuclear Support Branch 76/01/13 JONES: J A Carolina Power & Light Co ip 16608 017 24X Fiche 50-000, 82/11/30,821229006
- --B212290155 Responds to NRC 751211 ltr re violations noted in It Insp Rept 50-261775-14 Corrective actions quarterly catifir of survey instruments will be performed per Health Physics Procedure HP-11 by 760131 & Procedure HP-1 will be revised UTLEY,E E Carolina Power & Light Co 76/01/05 MOSELEY, N C Region 2. Atlanta. Office of the Director 4pp 16608 018 24X Fiche 50-000,82/11/30.8212270060
- --G212290158 Forwards IE Insp Rept 50-261/75-14 on 751104-19 Noncompliance noted MDSELEY,N C Region 2, Atlanta, Office of the Director 75/12/11 JONES.J A Carolina Power & Light Co 2pp 16608 022 24X Fiche 50-000,82/11/30
- --B212290165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliances noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" callor data PARKER.R C . LEMTS.R C . WHITENER.H L Region 2, Atlanta, Reactor Operations Nuclear Support Branch 75/12/16 17pp 16608 024 24% fiche 50-000,82/11/30,8212290060
- BPDB190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259

- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay
- Societs " Svc list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co. of New York, Inc. 110pp 16462-064 24X
 Fiche 50-000.62/12/03.8208190261
- 8E12130313 Forwards revised "HB Robinson Unit 2 Inservice Insp Program," Interval 2,810307-910307, incorporating items discussed during 821018.21 t 26 telcons Revision supersedes 810310 t (231 submittals ZIMMERMAN,S R Carolina Power t Light Co 82/12/09 VARGA Operating Reactors Branch 1 1p 16387 345 24X Fiche 50-261,82/12/09,8212130313 82/12/09 VARGA, S A
- --8212130317 Revised "HB Robinson Unit 2 Inservice Insp Program,"
- Interval 2.810307-910307

 * Carolina Power & Light Co 84
 Fiche 50-261,82/12/09.8212130313 82/12/09 78pp 16389 346 24X
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG: R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York
- B208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 273 P4X Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- BP12060199 Forwards monthly operating rept for Nov 1982 STARKEY.R B Carolina Power & Light Co 82/12/03 DEYGUNG.R C Director's Office Office of Inspection and Enforcement 1p 16313 047 24X Fiche 50-261.82/12/03.8212060199
- --8212050201 Monthly operating rept for Nov 1982 MORRIS,H B Carolina Power & Light Co 62/12/0(3pp 16313 048 24% Fiche 50-261,82/12/03,8212050199
- 9 Reportable occurrences, LERs & related correspondence
- 8212030004 PNO-11-82-131 on 821128 leaking injection valve resulted in caustic contamination of condensate storage tank by 20 gallons of 50% sodium hydroxide Secondary coolant also contaminated Sampling & evaluation underway
 HEHL-C W , BEMIS.P Region 2, Office of Director 82/11/30 ip 16304 225 24% Fichs 50-261,82/11/30,8212030004
- 8212090120 Forwards LER 82-016/03L-0
- --8212090128 LER 82-014/03L-0 on 821103.containment fan cooler HVH-3 eactivism can deruto/val-o on BillUS, containment fan cooler HVH-3 failed to restart during periodic test performance Caused by defective time delay relay in motor breaker control circuit Time delay relay replaced COX.H T Caroline Power & Light Co 82/11/30 Region 2, Office of Director 2pp 16357 232 24X Fiche 50-261,82/11/30, 8212090120
- 8212300272 Forwards LER 82-018/01L-0 BTARKEY, R B Carolina Power & Light Co 82/12/23 O'REILLY, J P. Region 2, Office of Director 1p 16594 001 24x Fiche 50-261, 82/12/23, 8212300272
- --8212300296 LER 82-018/01L-0 on 821213.at 81% power.low temp overpressure protection sys pressure transmitters found callbr incorrectly Caused by calculational error on zero adjust correction on initial 1978 callbr data sheets COX.H Y Carolina Power & Light Co 82/12/23 Region 2, Office of Director 3pp 16594.002 24X Fiche 50-241.82/12/23, 8212300272

V. Operator Examinations

8212090122 Infoms that written & oral exams scheduled for 830221 List Provouce intense that unitten & grain erams scheduled for B30221 Lis of encil referenced hat I required for operator licensing exam must be furnished by B21220 to meet schedule Requirements for conducting exams also encil VERRELLI, DH Division of Project & Resident Programs. 82/12/02 FURR B.J. Capolina Power & Light Co 4pp 16357 264 24X Fiche. 50-261.82/12/02.8212070122

- DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- BP12160731 Releases public version of revised reactor facility rmergency plan FELTON, J M D FELTON, J.M. Division of Rules and Records 82/12/10 Docum Management Branch 1p 16464 177 24% Fiche 50-262,82/12/10.
- --9212160734 Forwards public version of revised reactor facility DIXON, D.R. Brigham Young Univ 82/12/03 THOMAS, C.O. Standardization & Special Projects Branch 1p 16464 178 24X Fiche 50-262,82/12/10.8212160731 emergency plan DIXON, DR Br
- --8212160742 Public version of revised reactor facility emergency plan * Brigham Young Univ 82/12/03 9pp 16464 177 24x Fiche 50-262,82/12/10,8212160731
- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT F Security, medical, emergency & fire protection plans
- GP12100016 Forwards IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022 A notice of violation NGRELIUS.C E Division of Engineering & Technical Programs 82/11/24 GIBERTS.D E Northern States Power Co 2pp 1: 24X Fiche 50-263.82/11/24.8212100016 16375 339
- -- B212100019 Notice of violation from insp on 820927-30,1012-13 & 1022 NOREL IUS. C E E Division of Engineering & Technical Programs 2pp 16375 335 24X Fiche 30-263,82/11/24,8212100016
- --- @212100023 IE Insp Rept 50-263/82-11 on 820927-30.1012-13 & 1022 el2100023 it Insp Rept 50-263/82-11 on 820927-30.1012-13 t 1022
 Noncompliance noted failure to conduct airburne activity
 survey during operation of box compactor & to conduct
 filtration sys air flow evaluation
 LDVENDALE/P C , GRANT.W B , GREGER.L R Division of Engineering &
 Technical Programs 82/11/22 9pp 16375 337 24x
 Fichs 50-263,82/11/24,8212100016
- BP12090343 Ack receipt of B21122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-263/82-13 50-263/82-13 MILLER, J. R. Division of Engineering & Technical Programs 8: LARSON, C. E. Northern States Power Co. 1p. 16365-086 24X Fiche 50-263,82/12/03,8212096343 82/12/03
- --8212090352 Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Rept 50-263/82-13 Corrective actions LARSON,C E Northern States Power Co B2/11/22 MILLER, J R Division of Engineering & Technical Programs ip 16345 087 249 Fiche 50-263,82/12/03,8212090343
- BP12140244 Forwards changes to security plan, to be incorporated in forthcoming revision Changes withheld (ref 10CFR2 790)
 MUSOUR.D Northern States Power Co 82/12/10 Office of Nuc Reactor Regulation. Director 2pp 16409 306 24X
 Fiche 50-263.82/12/10.8212140244 Office of Nuclear
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPPLER.JO Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 821220306
- P Operating license stage documents & correspondence
- BP11230066 Generic Ltr B2-27 to all BWR licensets of operating reactors except LACBWR. Big Rock Point, Dresden 1. Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0783 Ex NUREO-0783 Svc list encl W/o stated encl EISENNUT, D @ Division of Licensing B2/11/15 General Public Utilities GPU Bervice Corp 22pp 16387 004 24X fiche 50-000, 82/11/15, 8211230066
- 8212070391 Forwards payment for 920930 license amend request re source range monitor count rate MUBDLF.D Northern States Power Co 82/11/17 DIGOS.R M License Fee Management Branch 2pp 16336 326 24X Fiche 50-263.82/11/17, 8212070391

- 82:12090008 Forwards Amend 12 to License DPR-22, safety evaluation, technical evaluation rept & notice of issuance & availability Amend incorporates surveillance requirements associated w/reactor protection monitoring sys VASSALLO, D B Operating Reactors Branch 2 82/11/30 MU90LF.D M Northern States Power Co 2pp 16384 274 24X Ciche 50-263.82/11/30.6212090008
- --8212090010 Amend 12 to license DPR-22, incorporating limiting conditions for operation & surveillance requirements associated U/reactor protection monitoring surveillance VASSALLO.D 0 Operating Reactors Branch 2 82/11/30 4pp 16384 276 24X Fiche 50-263.82/11/30.8212090008
- --8212090012 Safety evaluation supporting Amend 12 to License DPR-22 * Orrice of Nuclear Reactor Regulation, Director 82/11/30 2pp 16384 280 24% Fiche 50-263.82/11/30.8212090008
- --B212090023 "Technical Evaluation Rept on Monitoring of Electric Power to Reactor Protection Sys for Monticello Nuclear Generating Plant," supporting Amend 12 to License DPR-22 SELAN, J C Lawrence Livermore Laboratory FIN A-0250 (UCID-19145 B2/07/16 NRC - No Detailed Affiliation Given 9pp 16384 282 24X Fiche 50-263 B2/11/30,8212090008
- --B212090026 Notice of issuance % availability of Amend 12 to License DPR-22 VASSALLO.D B Operating Reactors Branch 2 92/11/30 2pp 16384 292 24X Fiche 50-263,82/11/30,8212090008
- GP12090009 Forwards safety evaluation re BMR owners group 810522,0921 & 820902 responses to NUREO-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Response acceptable VASSALLO, D 9 Operating Reactors Branch 2 82/12/01 MUSOLF, D M Northern States Power Co 2pp 16384 267 24X [ithe 50-263,82/12/01,8212090009]
- --8212090011 Safety evaluation of BWR owners group generic response to NUREG-0737. Item II K 3 25, 'Effect of Loss of AC Power on Pump Seals "

 * Operating Reactors Branch 2 82/12/01 Spp 16384 269 24X Fiche 50-263, 82/12/01, 8212090009
- BP12280032 Forwards Amend 13 to License DPR-22, safety evaluation & notice of issuance & availability Amend changes Tech Specs to incorporate revised safety & operating limits associated w/operation during Fuel Cycle 10 VASSALLO, D B Operating Reactors Branch 2 B2/12/06 MUSDLF, D M Northern States Power Co 2pp 16593 089 24X Fiche 50-263, 82/12/06, 8212280002
- 8212280003 Amend 13 to License DPR-22, changing Tech Spacs to incorporate revised safety & operating limits associated w/operational facility during Fuel Cycle 10 VASSALLO, D B Operating Reactors Branch 2 82/12/06 9pp 16593 090 24X Fiche 50-263,82/12/06,8212280002
- --0212280004 Safety evaluation supporting Amend i3 to License DPR-22 4 Office of Nuclear Reactor Regulation, Director 82/12/06 Bpg 16593 099 24X Fiche 50-263,82/12/06,8212280002
- --U212280006 Notice of issuance & availability of Amend 13 to License PPR-22 VASSALLO, D B Operating Reactors Branch 2 82/12/06 2pp 18593 107 24X Fiche 50-263, 82/12/06.8212280002
- 8:12210544 Forwards Amend 14 to License DFR-22, safety evaluation & notice of issuance & availability Amend approves regain to recirculation sys piping & authorizes resumption of power LISENHUT, D G Division of Licensing 82/12/10 MUSQLF, D M Northern States Power Co 4pp 16502 239 24X Fiche 50-263,82/12/10,8212210544
- 8212210547 Amend 14 to License DPR-22.approving repairs to recirculation sys piping authorizing resumption of power & changing Tech Spocs limiting conditions for coolant leak detection sys VASSALLO.D B Operating Reactors Branch 2 82/12/10 6pp 16502 243 24X Fiche 50-263,82/12/10,8212210544
- --8212210548 Safety evaluation supporting Amend 14 to License DPR-22 * Office of Nuclear Reactor Regulation, Director 82/12/10 19pp. 16502 249 24X Fiche 50-263.82/12/10.8212210544
- --8212210552 Notice of issuance & availability of Amend 14 to License ppR-22 VASSALLO, D B Operating Reactors Branch 2 82/12/10 2pp 16502 268 24% Fiche 50-263,82/12/10,8212210544

- 8212210325 Forwards plant-unique analysis repts Vols 1-5 & App A Repts describe analyses conducted for suppression chamber vent sys, suppression chamber internals & safety relief valve discharge piping MUSQLF, D. Northern States Power Co. 82/12/15 Dffice of Nuclear Reactor Regulation, Director 2pp. 16497 135 24x Fiche 50~263,82/12/15,8212210325
- --8212210327 Vol 1.Revision 1.to plant-unique analysis rept, "General Criteria & Loads Nathodology " BONDRE, J R . MASTERSON, R E . MULFORD, T J NUTECH (Nuclear Technology, Inc.) NSP-74-101 R01 82/11/30 217pp 16497 138 24X Fiche 50-263.82/12/15.8212210325
- --8218210330 Vol 2. Revision 1.to plant-unique analysis rept, "Suppression Chamber Analysis" Chamber Analysis" BENTING.K H. MCINNES.I D. MULFORD.I J. NUTECH (Nuclear Technology, Inc.) NSP-74-102 ROI 82/11/30 184pp 16497 355 24x Fiche 50-263.82/12/15.8218210325
- 8212210333 Vol 3, Revision i.to plant-unique analysis rept, "Vent 8ys Analysis" HBU.T J , MCINNEG.I D , MULFORD, T J NUTECH (Nuclear Technology, Inc) NSP-74-103 ROL 82/11/30 209pp 16498 179 24X Fiche 50-263,82/12/15,8212210325
- --B212210337 Vol 4.Revision 1.to plant-unique analysis rept. "Internal Structures Analysis" BENTING,K W., MCINNES,I D., MULFORD,T J. NUTECH (Nuclear Technology, Inc.) NSP-74-104 RO1 82/11/30 37pp 16499 028 24X Fiche 90-263,82/12/15.8212210325
- 0212210342 Vol 5. Revision 1.to plant-unique analysis rept, "Safety Relief Volvo Discharge Line Piping Analysis " HERLEKAR. A S . AXLINE. J W . MULFORD. T J NUTECH (Nuclear Technology, Inc.) NSP-74-105 R01 62/11/30 144pp 14499 061 244 Fiche 50-263, 82/12/15,8212210325
- --β212210346 App A.Revision 1.to plant-unique analysis rept. "Monticello Responses to Previous Plant-Unique Analysis Rept Current Containment & Piping Licensing Issues"
 * NUTECH (Nuclear Technology, Inc.) NSP-74-105A RO1 B2/11/30 90pp 16499 207 24X Fiche 50-263. B2/12/15, B212210325
- BP12220545 Requests add1 fees re util 820924 application for Tech Spec changes re surveillance clarification, reactor protection sys monitoring requirements & jet pump surveillance DIGOS.R M License Fee Management Branch 82/12/15 MUSOLF.I) Northern States Power Co 1p 16523 351 247 Fiche 50-263, 82/12/15,8212220545
- & Inspection reports, IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping of BHR Plants " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 820B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 802 K Model 802 Thermoluminescent Dostmeters" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York. Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,820B190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list enc! JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24X Fiche 30-000,82/11/18.8208190251
- BP12100016 Forwards IE Insp Rept 50-263/82-11 on 820927-30, 1012-13 & 1022 & notice of violation NGRELIUB.G E Division of Engineering & Technical Programs 82/11/24 OIBERTS,D E Northern States Power Co 2pp 16375 333 24X Fiche 50-263,82/11/24.8212100016
- --8212100019 Notice of violation from insp on 820927-30,1012-13 & 1022 NORECIUS, C E. Division of Engineering & Technical Programs 82/11/24 2pp 16375 335 24X Fiche 50-263,82/11/24,8212100016
- --8212100023 IE Insp Rept 50-263/82-11 on 820927-30,1012-13 & 1022
 Noncompliance noted failure to conduct airborne activity
 survey during operation of box compactor & to conduct
 filtration sys air flow evaluation
 LOVENDALE,P C . GRANT.W B . GREGER, L R Division of Engineering &
 Technical Programs 82/11/22 pp 16375 337 24X
 Fiche 50-263,82/11/24,8212100016

- BPOB190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, lnc 127pp 16414 065 24% Fiche 50-000.82/11/26.8208170256
- 8208190257 IE Info Natice 82-47, "Transportation of Type A Quantities pf Non-Fissile Radioactive Matl " Svc list enc! COSS.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 336pp 16387 028 24X Fiths 50-000.82/11/30.8208190257
- 8212210007 Advises that concerns & requirements re IE Builetin 80-06, "ESF Reset Controls." satisfied SER & technical evaluation forwarded VABSALLO,D 8 Operating Reactors Branch 2 82/12/01 MUSOLF,D M Northern States Power Co 2pp 16527 346 24% Fichs 50-263, 82/12/01,8212210007
- --Bio5210384 "Technical Evaluation of Licenses's Response to IE Bulletin 80-06 or Engineered Safety Feature Roset Controls for Monticello Nuclear Generating Plant " HACKETT, D B EG&O, Inc FIN A-0281 E00-1183-4210 81/05/30 6pp 16529 350 24X Fiche 50-263,82/12/01,8212210007
- 8P08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement, 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317, 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JGRDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche
- 8212090343 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-263/82-13
 MILLER, J. R. Division of Engineering & Technical Programs 82/12/03 LARSON.C E. Northern States Power Co. ip 16365-086 24X
 Fiche 50-263,82/12/03.8212090343
- --8212070352 Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Rept 50-263/82-13 Corrective actions withheld. LARSON: C E. Northern States Power Co. 82/11/22 MILLER. J R Division of Engineering & Technical Programs ip 16365-087 24X Fiche 50-263,82/12/03.8212090343
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG: R C. Director's Office, Office of Inspection and Enforcement. 82/12/16 Consolidated Edison Co of New York, Inc 127pp. 16628 191. 24X Fiche 50-000,82/12/16.8208190267
- 8208190268 IE info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance. 82/12/20 Consolidated Edison Co. of New York. Inc. 108pp. 16628.273 24X Fiche. 50-000.82/12/20.8208190258
- S Reportable occurrences, LERs & related correspondence
- 8212140344 Forwards updated LER 82-013/017-3 MUSOLF, D. Northern States Power Co 82/12/05 Region 3. Office of Director 1p. 16401, 358 24X Fiche 50-263, 82/12/06, 8212140344
- --82;2140357 Updated LER 82-013/017-3 on 820728,1020,31 & 1102.during preparation for repair of E.C & F saferends.thru wall leaks found on each saferend Caused by interpranular stress corrosion cracking Defects repaired HAMKER.S Northern States Power Co 82/12/06. Region 3, Office of Director 1p 16401 359 24X Fiche 50-263,62/12/06.
- 82:22:0247 PNO-III-82-135 on 82:213, maint worker suffered second dagree burns from contaminated steam during replacement of packing on main steam line drain isolation valve Worker treated & released State of MN will be notified WALKER, R., BARRETT, P., STREETER, J., Region 3, Office of Director 82/12/14, Ip. 16483:316, 24X Fiche 50-263,82/12/14,8212210247

- 8212270276 PNG-III-82-138 on 021217, turbing generator developed high vibration reading on bearing 5 due to worn bearing Unit to be taken to cold shutdown for repair of bearing BROWN, C., WALKER, R., STREETER, J. Region 3, Office of Director 82/12/17 1p 14530 310 24X Fiche 50-263,82/12/17,8212270276
- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B212030053 Ack receipt of 821108 1tr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-28482-14 & 50-265/82-16 Clarification restart & stop of 15-minute clock provided KEPPLER, J G Region 3. Office of Director 82/11/30 REED, C Commonwealth Edison Co. 19 16304 143 24X Fiche 50-254.82/11/30, REED, C Commonwealth Edison Co.
- --8212030054 Responds to NRC 820730 ltr re problems identified in Paragraph 5 of IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-254/82-14 & ddd corporate emergency planning positions budgeted for 1783 RAUSCH.7 J Commonwealth Edison Co 82/11/08 KEPPLER, J G Region 3. Office af Director 3pp 16304 144 24X Fiche 50-254,82/11/30,8212030053
- BP1203026B Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/11/30 Documen Management Branch ip 16316 276 24X Fiche 50-254,82/11/30. U21203026B
- r-8212030273 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 330-6 re air sampling under accident conditions & GEP 330-79 re air radiation monitoring sys Receipt form encl KOVACK,T J. GERNER.L. Commonwealth Edison Co. 82/10/18 DENTON,H R. NRC No Detailed Affiliation Given ip 16316 2/8 24% Fichs 50-254,82/11/30,8212030268
- --8212030279 Public version of revised emergency plan implementing procedures, including Procedures OEP 330-6 re air sampling under accident conditions & OEP 330-79 re air radiation monitoring sys

 * Commonwealth Edison Co 82/10/18 17pp 16316 279 24X
 Fiche 50-254,82/11/30,8212030268
- G212060172 Ack receipt of 821116 ltr informing NRC of steps taken to correct violations noted in NRC 821012 ltr re timeliness of emergency planning exercise submittals
 HIND J A Division of Emergency Preparedness & Operational Support 82/12/01 REED.C Commonwealth Edison Co ip 16313 086 24X Fithe 50-254, 82/12/01.8212060172
- --B212040181 Responds to NRC B21012 ltr re timeliness of scenario submittals to FEMA Region VII FEMA Region VII to be included in submittals & meetings associated w/future exercises RAUSCH.T J Commonwealth Edison Co B2/11/16 KEPPLER, J G Region 3. Office of Director 1p 16313 CB7 24X Fiche 50-254.82/12/01.B212060172
- 8212090325 Ack receipt of 821127 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 10-294/82-20 & 50-264/82-21 HILLER, J R Division of Engineering & Technical Programs 82/12/03 REED.C Commonwealth Edison Co 1p 16365 103 24X Fiche 50-254.82/12/03.8212090325
- ---8212090338 Responds to NRC 821029 ltr reviolations noted in IE Bafeguards Insp Repts 50-254/82-20 & 50-265/82-21 Corrective actions withheld (ref 10CFR73 21)
 DELGEORGE. O Commonwealth Edison Co 82/11/29 KEPPLER, J G Region 3, Office of Parector ip 16365 104 24X
 Fiche. 50-254, 82/12/03, 8212090325
- 8212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee DELEGORGE, L.O. Commonwealth Edison Co. 82/12/03 EISENHUT, D.G. Division of Licensing 2pp 16365 051 24X Fiche 50-000,82/12/03,8212090383
- 88:2140179 Responds to items re fire protection safe shutdown analysis, discussed in 820917 telephone conference Core can maintain water level above tap of active fuel w/o initiation of RCIC flow for max of 14 minutes

 RAUSCH.T. J Commonwealth Edison Co 82/12/06 EISENHUT, D G
 Division of Licensing 3pp 16410 205 24X Fiche 50-254, 82/12/06, 82/1240179

- 8.12160127 Ack receipt of 820621 ltr transmitting changes to security plan. Revision ii Change consistent w/provisions of lOCFRSO 54(p) & does not decrease effectiveness of plan VASSALLO, D B Operating Reactors Branch 2 82/12/06 PELGEORGE, L D Commonwealth Edison Co 3pp 16447 206 24X Fiche 50-254, 82/12/06, 8212160127
- G212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, 'Pre-Established Onsite & Offsite Monitoring Locations (Maps) " FELTON, IN Division of Rules and Records B2/12/07 Document Nanagement Branch 1p 16417 062 24X Fiche 50-000, 82/12/07.
- --B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl PAJDMSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 14417 063 24X Fiche 50-000, 82/12/07. 8212130017
- --8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Unsite & Offsite Monitoring Locations (Maps)"
 PAJUMSKI.J E Commonwealth Edison Co 82/11/29 App 16417 065 24K Fiche 50-000.82/12/07.8212130017
- OUI2140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared 1RAMM. T. R. Commonwealth Edison Co. 82/12/07 DENTON, M.R. Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Jiche 50-000. 62/12/07. 8212140243
- GF12220175 Releases public version of revised generating station emergency plan implementing procedures FELTON. J M. Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 029 24X Fiche 90-000,82/12/10,021220175
- --B212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures FD-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJOHSKI.J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16529 030 24% Fiche 50-000, 82/12/10,8212220175
- --8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI,L A Commonwealth Edison Co 82/10/13 48pp 16527 031 24X Fiche 50-000, 82/12/10,8212220175
- G212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 MEPPLER.J G Region 3. Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 80-000,82/12/16,821220306
- 8212300167 Releases public version of revised generating station emergency plan telephone directory FELTON J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000,82/12/20, 8212300167
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory MOORE/R D Commonwealth Edison Co 82/12/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 16612-216 24X Fiche 50-000,82/12/20,8212300167
- --8212300199 Public version of revised generating station emergency plan telephone directory GALLE.D P Commonwealth Edison Co 82/11/05 60pp 14612 21/ 24% Fiche 50-000,82/12/20,8212300167
- G212300400 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/22 Documen Management Branch 1p 16613 203 24X Fiche 50-254,82/12/22, 8212300400
- B212300405 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing & GEP 360-3 re site systemation Receipt form encl

 **Commonwealth Edison Co B2/12/08 DENTON, H R NRC No Detailed Affiliation Given 2pp 16613, 204 24X Fiche 50-254, 82/12/22, B212300400

- --8212300409 Public version of revised emergency plan implementing procedures, including Procedures GEP 310-T3 re prioritized notification listing % GEP 360-3 re site evacuation * Commonwealth Edison Co 82/12/08 12pp 14613 206 24X Fiche 50-254.82/12/22.8212300400
- 9 Adjudicatory correspondence
- 8212070160 Memorandum & order granting licensee 820818 request to dismiss proceeding w/o prejudice Util received authority to increase spent fuel pool storage capacity, making shipment of spent fuel between plants unnecessary JCHNSON.E B Acomic Safety and Licensing Board Panel 82/12/03 Commonwealth Edison Co 4pp 16336 320 24X Fiche 50-000.82/12/03.0312070160
- R General correspondence
- 8?12280176 Notifies of change in mailing address for NRC licensing matl WRIGHT, G N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D G Division of Licensing ip 16556 135 24X Fiche 50-000,82/12/20,8212280176
- P Operating license stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBWR. Big Rock Point, Dreaden 1. Humboldt Bay, applicants for GL & holders of CP rot transmittal of NUREO-0783 &vc list encl W/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16/387 004 24x Fiche 50-000, 82/11/15, 8211230066
- G212130275 Forwards safety evaluation of BHR owners group 810522,0921 & 820902 responses to NUREO-0737. Item II K 3 25, "Effect of Loss of AC Power on Pump Seals "Responses acceptable VASBALLO, D B Operating Reactors Branch 2 82/12/01 DELOEDRGE, L Commonwealth Edison Co 7pp 16418 213 24X Fiche 50-254,82/12/01,6212130275
- 8212160013 Forwards ltrs from engineering firms supporting spent fuel rack mod at facilities Min gap of 2 5 inches between racks does not invalidate previous seismic analyses if racks symmetrically loaded Restoration of 3-inch gap planned RAUSCH, T J Commonwealth Edison Co 82/12/10 EISENHUT, D 0 Division of Licensing 3pp 14446 074 24X Fiche 50-254,82/12/10,8212160013
- 8212220212 Forwards Revision 22 to CE-1-A, "GA Program for Nuclear Generating Stations" SWARTZ, E.D. Commonwealth Edison Co. 82/12/14 HAASS, W.P. Guality Assurance Branch ip 14518 007 24X Fiche 50-000, 82/12/14, no.12220212
- --8212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Ca CE-1-A R22 82/11/01 17pp 16518 009 24% Fiche 50-000, 82/12/14,8212220212
- BP12280117 Forwards add1 info re NUREC-0737, Item II F 1, "Add1 Accident Monitoring Instrumentation," per NRC 821109 request Pressure monitoring sys provided w/separate loop for narrow range monitoring BMARTZ, E D. Commonwealth Edison Co 82/12/20 EISENHUT, D 0 Division of Licensing 9pp 14564 062 24% Fiche 50-000, 62/12/20, G212280117
- B212280343 Forwards addl info re NUREQ-0737. Items Il F 1 4.5 & 6
 "Containment Pressure Hater Level & Hydrogen Monitoring,"
 per Crutchfield 821107 itr
 SWARTZ.E D Commonwealth Edison Co 82/12/20 £ISENHUT.D G
 Division of Licensing 9pp 16561 053 24X Fiche 50-000.82/12/20,
 8212280343
- 6212290111 Application for amend to License DPR-29, consisting of change to Tech Specs allowing normal power operation for no more than one refueling cycle w/one main steam drain line isolation valve exhibiting excessive leakage N/o Tech Specs. RAUSCH: T. J. Commonwealth Edison Co. 82/12/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16582 241 24X Fiche 50-254.82/12/20.821227011
- SP12280212 Forwards updated schedule for ongoing environ qualification testing programs per 810528 commitment SWARTZ.E D Communuealth Edison Co 82/12/22 EIBENHUT.D Q Division of Licensing 18pp 16556-161 24X Fiche 50-000.82/12/22, 8212280212

- 82/12280263 Clarifies position on classification of major mods to BHR Mark / Containment per 82/216 ltr RAUSCH TJ Commonwealth Edison Co 82/12/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 14561 307 24X Fiche 50-000, 82/12/22,8212280263
- G Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter:Stainless Steel.Recirculation Sys Piping at Bir Plants "Syc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000.82/10/28.8208190240
- 6208190245 1E Info Notice 92-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
 CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000.82/11/05,8208190245
- 6212020308 Forwards IE Insp Repts 50-254/62-15 & 50-265/82-17 on B20830-0902 & notice of violation MILLER,R Division of Engineering & Technical Programs 82/11/16 REED.C Commonwealth Eduson Co 2pp 16278 147 24X Fiche 50-254, 82/11/16, 8212020308
- --8212020310 Notice of violation from insp on 820830-0902 MILLER,J R Division of Engineering b Technical Programs 52/11/16 ip 16278 149 24X Fiche 50-254,82/11/16,8212020308
- --B212020314 IE Insp Repts 50-254/82-15 & 50-265/82-17 on B20830-0902 Noncompliance noted failure to use strong.light packages for transportation of low specific activity radwaste HUETER.L.J. GRANT.H B. OREGER.L R. Region 3. Diffice of Director 82/10/12 9pp 16278 150 24X Fiche 50-254.82/11/16.8212020308
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24 Fiche 50-000, 82/11/18,8208190251.
- 8212030187 Forwards IE Insp Repts 50-254/82-18 & 50-265/82-20 on 820908-1022 No noncompliance noted STREETER. J F Division of Project & Resident Programs 82/11/19 REED. C Commonwealth Edison Co 2pp 16307 083 24x Fiche 50-254.82/11/19.8212030187
- --B212030197 IE Insp Repts 50-254/B2-10 & 50-265/B2-20 on B2090B-1022 No noncompliance noted Major areas inspected maint-refueling, training, vessel internal inspireactor scram feedwater sparger mod & fallowups on significant events & LERs CHRIGSUTINOS,N., DUPONT,S.G., WALKER,R.D. Region 3, Dffice of Director 82/11/19 10pp 16307 085 24X Fiche 50-254,82/11/19,8212030187
- 8212040191 Forwards IE Insp Repts 50-254/82-21 & 50-245/82-23 on 821024-29 No noncompliance noted HILLER, J R Division of Engineering & Technical Programs 82/11/23 REED. C Commonwealth Edison Co 2pp 16313 035 24X Fiche 50-254,82/11/23,8212060191
- --B212060197 IE Insp Repts 50-254/82-21 & 50-265/82-23 on B21026-29 No noncompliance noted Major areas inspected normal operational & refueling radiation protection activities, staffing, training & status of certain NUREG-0737 Items HUETER, U J. MILLER, D E., GREGER, L R. Region 3, Office of Director 82/11/23 7pp 16313 037 24X Fiche 50-254,82/11/23, 8212060191
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256.
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Math " Svc list encl COB8.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 24% Fichs 50-000, 82/11/30, 8208190257
- 8212030053 Ack receipt of 821108 ltr informing NRC of steps taken to resolve problems identified in IE Emergency Preparedness Appraisal Repts 50-254/82-14 & 50-265/82-16 Clarification restart & stop of 15-minute clock provided KEPPLER.J 0 Region 3: Office of Director 82/11/30 REED.C. Commonwealth Edison Co ip 16304 143 24X Fiche 50-254.82/11/30, 8212030053

- --8212030056 Responds to NRC 820930 ltr re problems identified in Parapraph 5 of JE Emergency Preparedness Appraisal Repts 50-254/82-14 % 50-265/82-16 Addl corporate emergency planning positions budgeted for 1983 RAUSCH, T J Commonwealth Edison Co 82/11/08 KEPPLER, J G Region 3. Office of Director 3pp 16304 144 24X Fiche 50-254,82/11/30,8212030053
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary.Containment Electrical Penetration Assemblies " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Syr list encl
 JORDAN.E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x
 Fiche 50-000.82/12/03.8208190261
- G212090325 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-265/82-21
 MILLER, J R Division of Engineering & Technical Programs G2/12/03 REED, C Commonwealth Edison Co ip 16365 103 24X Fiche 50-254,82/12/03,8212090325
- --821209033B Responds to NRC 821029 ltr re violations noted in IE Safeguards Insp Repts 50-254/82-20 & 50-265/82-21 Corrective actions ulthheld (ref 10CFR73 21)
 DELOEGREEL D Commonwealth Edison Co 82/11/29 KEPPLER, J C Region 3, Office of Director p 16365 104 24x
 Fiche 50-254,82/12/03,8212090325
- 82:2100145 Discusses will 82:1001 response to IE Insp Repts 50-254/82-13 & 50-265/82-15 re multiplet analysis capability in AAIB saftware Alternative in-depth review of AAIS acceptable, provided that NRC concerns addressed in review PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/12/06 RAUSCH.T J Commonwealth Edison Co ip 16376 042 24% Fiche 50-254,82/12/06.8212100145
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Arr & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208170267
- B212270295 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/82-21, 50-249/82-82, 50-254/82-17 & 50-245/82-19
 NORELIUB.C E Division of Engineering & Technical Programs B2/12/16 RED.C Commonwealth Edison Ca 2pp 16530 085 24X Fiche 50-000, 82/12/16, 8212270295
- --8212270303 Responds to NRC 821026 ltr re violations noted in IL Insp. Repts 50-237/82-21.50-249/82-22.50-254/82-17 & 50-269/82-19 Corrective actions annual audits of all active AE firms performing safety-related work required DELOEORGE. D. Commonwealth Edison Co. 82/11/24 KEPPLER, J. G. Region 3. Office of Director 4pp 16530 007 24X Fiche 50-000, 82/12/16, 8212270275
- --8212270307 "EDS-NUTECH Interface Control Instructions." Revision 0 TSCHUDI.W F NUTECH (Nuclear Technology, Inc.) 82/09/30 22µp 16530 091 24X Fiche 50-000,82/12/16,8212270295
- --8212270313 "IE Bulletin 79-14 & TAP Piping Evaluation, Quad Cities Units 1 & 2 & Dresden Units 2 & 3," Revision 0 * NUTECH (Nuclear Technology, Inc.) 82/10/01 9pp 16530 113 24% Fiche 50-000,82/12/16,8212270295
- 8212290346 Forwards IE Insp Repts 50-254/82-25 & 50-269/82-27 on 821115-19 No noncompliance noted LITTLE, W 8 Division of Engineering & Technical Programs 82/12/16 REED, C Commonwealth Edison Co 2pp 16586 177 24% Fiche 50-254,82/12/16,8212290346
- --821229034B IE Insp Repts 50-254/82-25 & 50-265/82-27 on 821115-19 No moncompliance noted Major areas inspected nonlicensed personnei & licensed operator requalification training procedures & records & surveillance scheduling program FARRELL, R E , PEBCHEL, J K , HAKKINS, F C Division of Engineering & Technical Programs 82/12/14 Spp 14586 179 24X Fiche 50-254,82/12/16,8212270346
- 8212280110 Provides final status rept of IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Complete & final listings of portions of sys failing to meet FSAR requirements under NUTECH responsibility encl RAUSCH.T J Commonwealth Edison Co 82/12/17 KEPPLER.J G Region 3. Office of Director 3pp 16564 191 24% Fiche 50-000,82/12/17.

- SPOBL90268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Kelays Type ITE-27" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp. 16628
- R Periodic operating reports & related correspondence
- 8P1214D443 "Evaluation of Quad Cities Nuclear Power Station Commonwealth Edison Co. 1982 " # Institute of Nuclear Power Operations 82/11/08 39pp 16405 210 24X Fiche 50-254.82/11/08.8212140443
- BP12130196 Forwards monthly operating repts for Nov 1982
 KALIVIANAKIS.N Commonwealth Edison Co 82/12/01 Director's
 Uffice. Office of Inspection and Enforcement ip 16396-151 24X
 Fiche 50-254.82/12/01.8212130196
- --G212130202 Monthly operating repts for Nov 1982 8058:R D Commonwealth Edison Co 82/12/01 21pp 16376 152 24% Fiche 80-254,82/12/01.8212130196
- S Reportable occurrences. LERs & related correspondence
- 9P12080390 Forwards LER 82-023/03L-0 KALIVIANAKIS: N Commonwealth Edison Co 82/11/30 KEPPLER, J Region 3. Office of Director 1p 16352 314 24X Fishe 50-265, 82/11/30, 8212080390
- --0212080404 LER G2-023/03L-0 on 921104, turbine step valve could not be reset during HPCI testing, preventing turbine operation Caused by corroded contacts on valve hydraulic oil pressure suitch Switch replaced HPCI switches cleaned BUSS.R Commonwealth Edison Co 62/11/30 Region 3, Office of Director 1p 16352 315 24X Fiche 50-265, 82/11/30, 8212080390
- 82:12100328 Forwards supplemental LER 82-018/03L-1 KALIVIANAKIS N Commonwealth Edison Co 82/12/01 KEPPLER, J Region 3, Office of Directon 1p 16377 048 24x Tiche 50-265, 82/12/01.8212100328
- --8212100335 Supplemental LER 82-018/03L-i on 821006, emergency diesel generator tripped on high temp after loading Caused by fouling of diesel generator cooling water sys Both HX replaced KAEPPEL, F. Commonwealth Edison Co. 82/12/01 Region 3, Office of Director 1p 16377 049 24X Fiche 50-265,82/12/01,
- DOCKET SO-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- BP12070099 Forwards revised Page 10 3 to safeguards plan Page withheld (ref 10CFR2 790 & 73 21)
 BURBTEIN: S Wisconsin Electric Power Co 82/12/02 DENTON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 ip 16327 271 24X
 Fiche 50-266.82/12/02,8212070099
- GP122800B2 Responds to Burstein 821110 & 1202 ltrs re addition of Chapter 10 to physical security plan Changes acceptable Ltrs withheld (ref 10CFR73 21) CLARK.R A Operating Reactors Branch 3 82/12/13 FAY, C, W Wisconsin Electric Power Co 1p 16593 087 24X Fiche 50-266. 82/12/13, 8212280082
- BRI2220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility
 KEPPLER.J O Region 3. Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16, 82/12/20306
- 9212290324 Confirms plans for 830110 mgt meeting in Milwaukee.WI refree protection concerns Written responses to IE Insp Repts 50-266/82-17 & 50-301/82-17 deferred until 830125 NGRELIUS.C E Division of Engineering & Technical Programs 82/12/23 BURSTEIN.6 Misconsin Electric Power Co ip 16587 157 24X Fiche 50-266,82/12/23,8212290324
- Adjudicatory correspondence
- 82:12080251 Supports steam generator tube sleaving BLAHA:0 : ENGELBRECHT,L : SCHMODCK,D Two Rivers.WI 82/11/29 BLOCH:P Atomic Safety and Licensing Board Panel ip 16354.126 P4X Fiche 50-266,82/11/29,8212080251

- 8/12130191 Special prehearing conference order memorializing 621118 conference MI Environ Decade 620810 petition to intervene dismissed since Decade wilfully failed to attend conference BLOCH, P.B., KLINE, J.R., PAXTON, H.C. Atomic Safety and Licensing Board Panel 82/12/10 Wisconsin's Environmental Decade 189116398 131 24x Fiche 50-266, 82/12/10,8212130191
- 8212230357 Forwards licensee proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W. Wisconsin Electric Power Co. 82/12/20 BLOCH, P. B., KLINE, J. R., PAXTON, H. C. Atomic Safety and Liconsing Board Panel ip 16511 207 24X Fiche 90-266, 82/12/20, 8212230357
- --8212230359 Proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes by inserting sleeves Certificate of Svc encl
 CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw, Fithman, Potts & Trowbridge 82/12/20 31pp 16511 208 24X Fiche 50-266,82/12/20 8212230357
- G212270316 Notice of appeal from B21210 special prehearing conference order dismissing Decade B20810 & 1105 petitions to intervene Affidavit of malling encl ANDERBOR, P. Misconsin's Environmental Decade 82/12/20 3pp 16530
- B212270323 Brief supporting appeal from 821210 special prohearing conference order denying 820810 petition to intervene & request for extension of time to complete brief Dismissal of petition on stated grounds contrary to law ANDERSON.P Hisconsin's Environmental Decade 82/12/20 Atomic Safety and Licensing 80 and Panel 15pp 16530 215 24X Fich 50-266-82/12/20,8212270323
- P Operating license stage documents & correspondence
- B212170040 Ack receipt of B21123 ltr transmitting Class I fee for G20930 application Basis for not remitting additional requested fee acceptable PIGGS, R M License Fee Management Branch B2/12/03 FAY, C W Wisconsin Electric Power Co 1p 16480 362 24X [sche 50-266.82/12/03,8212170040
- 6:/08190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of itr Svc list encl EISENHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc. 29pp 16629 247 24X Fiche 50-000 82/12/09, 8208190263
- 8:12140103 Generic Ltr 82-28 to all licenses of operating Westinghouse & C-E PWR* (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core conling instrumentation sys Svc list encl EISENHUT, D @ Division of Licensing 82/12/10 Yankee Atomic Liettric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,6212140103
- 8212170326 Refs Westinghouse 791206 ltr in response to RA Clark 821108 request for ECCS evaluation model addressing two loop upper plenum injection plants Calculations for worst case large break & sensitivity studies will be submitted by 830225 IAY.C W Hisconsin Electric Power Co 82/12/10 DENYON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 2pp 16453 224 24X Fiche 50-266,82/12/10,8212170326
- BP12210056 Comments on technical evaluation rept re seismic qualification of auxiliary feedwater sys.per 821112 request Recommendation to acquire complete SBE level of seismic capacity constitutes unhorcessary & expensive backfit HAY, C H Hisconsin Electric Power Co 82/12/15 DENION, H R, Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 5pp 16492-248 24X Fichs 50-266, 82/12/15, 8212210056
- 8212220422 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request B6 to address MMREG-0707. Item II K. 3 3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr 82-16 FAY.C W Wisconsin Electric Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Uperating Reactors Branch 3 3pp 16503 278 24X Fiche 50-266, 82/12/15,8212220422

- --B212220427 Proposed Tech Spec Change Request 86 addressing requirements of NUREC-0737, Item II K 3 3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr
 - # Hisconsin Electric Power Co 92/12/15 1p 16503 201 24x Fight 50-266,82/12/15,8212220422
- 8212270125 Discusses installation of RCS gas vent sys during Fall 1982 refueling dutage Several minor mode to as-designed piping & piping supports necessary to accommodate interferences from other components & sys in containment FAY.C W Hisconsin Electric Power Ca 82/12/17 DENTON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 2pp 16538 310 24% Fiche 50-266.82/12/17.8212270125
- B212290300 Confirms B21215 telcon w/NRC clarifying wtil B21027 ltr re reg guide & QA program commitments per steam generator replacement project FAYIC W Hisconsin Electric Power Co B2/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 16581 221 24X Fiche 50-266, 82/12/22, 8212290300
- BB12290095 Forwards "Evaluation of Pressurizer Safety & Relief Valve Sys for Point Beach Nuclear Plant," in further response to NUREO-0737, Item [1 D i re relief & safety valve testing FAY.C H Wisconsin Electric Power Co 82/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 16589 169 24X Fiche 50-266, 82/12/23, 9212290095
- --B212290104 "Evaluation of Pressurizer Safety & Relief Valve Bys for Point Beach Nuclear Plant " W/two oversize drawings Aperture cards are available in FDR MCKINNEY,T R, RAMSEY,B L, RAZLAFF,W J EDS Nuclear, Inc 09-0870-001 ROO 82/12/21 64pp 16589 172 24X Fiche 50-266,82/12/23,8212290075
- 8212270143 Forwards response to 821116 request for add1 info re steam generator repairs Approx 900 personnel could receive radiation exposure during repairs FAY.C W Hisconsin Electric Power Co 82/12/23 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 9pp (6583 197 24% Fiche 50-266, 82/12/23,8212290143
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants." Syc list encl
 BEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edition Co of New York. Inc 112pp 14462-163 24% Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc Jist encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05,8208190245
- 820B190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- B308190286 IE Info Notice 82~46, "Defective & Obsolete Combination Padlocks " Bvc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 14411 065 24% Fische 50-000, 82/11/26, 8208190254
- 8208190257 [E Info Notice 82-47, "Transportation of Type A Guantities of Non-Fistile Radioactive Matl " Svc list enc! CD88.L.L. Division of Fuel Facilities, Materials & Bafeguards 82/11/30. Consolidated Edison Co of New York, Inc 396pp 14387 028 24X Fiche 50-000,82/11/30.8208190257.
- 8Pi2170177 Forwards IE Insp Repts 50-266/82-17 & 50-301/82-17 on 820628-0701 & 08 & notice of violation.

 MORELIUS, C E Division of Engineering & Technical Programs 82/11/30 SURSTEIN, B Wisconstin Electric Power Co 3pp 16450 192 24X Fiche 50-266, 82/11/30, 8212170177.
- --BRI217D1B1 Notice of violation from insp on 820628-0701 & OB NGRELIUS/C E Division of Engineering & Technical Programs' 82/11/30 4pp 16450 195, 24X Ficher 50-266, 82/11/30, 8212170177

- --8212170189 IE Insp Repts 50-266/82-17 & 50-301/82-17 on 620628-070! & OS Roncompliance noted inadequate surveillance testing, nonrunctional genetration fire barrier & incomplete development & implementation of administrative controls RAMSEY.C., ULIE.J. GROBE.JA Region 3. Office of Director 82/09/20 21pp 16490 199 24X Fiche 50-266.82/11/30.8212170177
- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNO,R C Disector's Office, Office of Inspection and Enforcement 82/12/03 Consplidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 82:08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDANIEL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8212100221 Ack receipt of 821129 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 30-266/82-12 & 50-301/82-12 KEPPLER, J Q Region 3, Office of Director 82/12/07 BURSTEIN, S Wisconsin Electric Power Co 2pp 16377 101 24X Fiche 50-266,82/12/07,8212100821
- --8212100222 Responds to NRC 820915 ltr re-violations noted in IE Insp. Repts 50-266/82-12 & 50-301/82-12 Corrective actions review of containment entry control procedures & controls & interchangeability of keys changed FAY.C W Wisconsin Electric Power Co 82/10/15 KEPPLER, J G Region 3. Office of Director 4pp 16377 103 24X Fiche 50-266,82/12/07.8212100221
- ~-8212100223 Add1 response to NRC 820915 ltr reviolation noted in IE
 Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions
 area roped off, conspicuously posted & flashing lights used
 as warning device
 FAV.C W Wisconsin Electric Power Co 82/11/29 KEPPLER, J C
 Region 3. Office of Director 3pp 16377 107 24X
 Fiche 50-266,82/12/07,8212100221
- B.º08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 80:12280361 Responds to IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " No Bunker Ramo penetration assemblies installed initially or during backfit & mad FAV.C N (fisconsin Electric Power Co 82/12/17 KEPPLER, J O Region 3. Office of Director 1p 16560 077 24X Fiche \$0-266, 82/12/17.8212280361
- 8212270332 Forwards IE Insp Rept 50-266/82-22 on 821102-03 & 18 No moncompliance noted LITTLE N S Division of Engineering & Technical Programs 82/12/17 BURSTEIN 8 Nisconsin Electric Power Co 2pp 16586 203 24X Fiche 50-266, 82/12/17,8212270332
- --8212270336 lE insp Rept 50-266/82-22 on 821102-03 & 18 No noncompliance noted Major areas inspected inservice insp procedures, work activities & NDE personnel certifications & data WARD, K D , KEY, W J , CILIMBERG, R Region 3, Office of Director 82/12/10 7pp 16586 205 24X Fiche 50-266,82/12/17,8212270332
- 8PO8190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27." Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628
- R Periodic operating reports & related correspondence
- B212290253 Forwards revised monthly operating repts for Aug 1982 for Units 1 & 2 & revised Sept 1982 rept for Unit 2 FAY.C W Hisconsin Electric Power Co 82/11/17 Office of Resource Management, Director 1p 16582 037 24X Fiche 50-266,82/11/17,8212290253
- --8212290257 Revised manthly operating repts for Aug 1982 FAY.C W Wisconsin Electric Power Co B2/09/07 2pp 16582 038 24% Fiche 50-266.82/11/17.8212290253
- --8212290262 Revised monthly operating rept for Sept 1982 FAY.C W Wisconsin Electric Power Co 82/10/04 1p 16582 040 24X Fiche 50-266.82/11/17.8212290253

- BP12210297 Forwards monthly operating repts for Nov 1982 FAY.C W Misconsin Electric Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director ip 16497 089 24X Fiche 50-266, 82/12/10, 8212210297
- --B212210279 Monthly operating repts for Nov 1982 FAY, C. W. Hisconsin Electric Power Co. B2/12/06. 11pp 16497-090. 24X Fiche 50-266, 82/12/10, 8212210297
- 5 Reportable occurrences, LERs & related correspondence
- GP12020276 Forwards LER 82-021/03L-0 FAY.C W Misconsin Electric Power Co 82/11/24 KEPPLER, J G Region 3, Office of Director in 16288 253 24X Fiche 50-266, 82/11/24, 8212020276
- --8212020201 LER 82-021/03L-0 on 821102 during installation of new fire protection equipment fire detectors were de-energized Caused by misunderstanding between plant & contractor personnel New detectors installed & tested satisfactorily FAY.C # Wisconsin Electric Power Co 82/11/24 Region 3. Office of Director 3pp 16288 254 24X Fiche 50-266,82/11/24,8212020276
- 82:12100224 Forwards LER 82-022/01T-0 FAY,C N Wisconsin Electric Power Co 82/12/03 KEPPLER,J G Ragion 3. Office of Director ip 16376 067 24X Cicke 50-266.82/12/03.8212100224
- --8212100225 LER 82-022/01T-0 on 821111.eddy current insp verified mechanical damage in excess of Tech Spec plugging limit after 821105-06 annular search indicated presence of foreign objects in steam generator Cause not stated Objects removed FAY.C II Ulsconsin Electric Power Co 82/12/03 Region J. Diffice of Director Spp 16376 068 24X Fiche 50-266,82/12/03,8312100224
- GP12;00202 LER 82-026/01T-0 on 821206. reactor protection rack relay dropout time found to be excessive upon being de-energized Caused by coil filler epoxy leak into plunger cavity, inhibiting movement Also reportable per Part 21 LINK.R E Wisconsin Electric Power Co 82/12/07 KEPPLER, J G Region 3, Office of Director ip 16376 214 24X Fiche 50-266, 82/12/07, 8212100202
- Bi:12170161 Forwards LER 82-024/03L-0 FAV.C W Wisconsin Electric Power Co 82/12/09 KEPPLER, J G Region 3, Office of Director ip 16450 222 24X Fiche 50-266, 82/12/09.8212170161
- --0212170172 LER 82-024/03L-0 on 821116 during review of test data steam flow transmitter FT-465 discovered 0 177% nonconservative Caused by nonconservative static zero shift Instrument recallshr
 FAV.C N Misconsin Electric Power Co 82/12/09 Region 3, Office of Director 2pp 16450 223 24X Fiche 50-266 82/12/09,
- B\$'12270177 Forwards updated LER 82-022/01T-1 FAY,C W Hisconsin Electric Power Co 82/12/09 KEPPLER,J G Region 3. Office of Director ip 16535 116 24X Fiche 50-266, 82/12/09, 8212270177
- --B212270202 Updated LER B2-022/01T-1 on B21111.eddy current testing indications of mechanical damage in excess of plugging limit verified Cause not stated Foreign objects removed FAY,C W Wisconsin Electric Power Co B2/12/07 Region 3, Office of Director Spp 16535 117 24X Fiche 50-266,82/12/07, B212270177
- GP12270239 Forwards updated LER 82-017/017-1 FAV.C W Wisconsin Electric Power Co 82/12/10 KEPPLER, J 9 Region 3, Office of Director 1p 16537 198 24X (1the 50-266, 82/12/10, 8212270239
- --0212270246 Updated LER 92-017/01T-1 on 021030.verified that indications for four steam generator A tubes & three steam generator B tubes exceeded 40% plugging limit during eddy current exam on 021026-30 Cause not stated Tubes mechanically plugged FAY,C W Wisconsin Electric Power Co 82/12/10 Region 3, Office of Director 7pp 16537 197 24% Fiche 50-266, 02/12/10, 02(2270237
- G212280158 Forwards LER 62-025/03L-0 FAYrC W Wisconsin Electric Power Co 62/12/16 KEPPLER; J G Region 3. Office of Director ip 16564 016 24X Fithe 50-266, 82/12/16, 8212280158

- --8212280162 LER 82-025/03L-0 on 821117, while reviewing test data, two 480-volt safeguards undervoltage relays found not meeting O volt time delay spec Relays adjusted to within spec & returned to syc FAY.C W Hisconsin Electric Power Co 82/12/16 Region 3, Office of Director 2pp 16564 017 24% Fiche 50-266, 82/12/16, 8212280158
- 8P12290322 Forwards LER 82-026/01T-0 FAY, C W Hisconsin Electric Power Co 82/12/20 KEPPLER, J G Region 3, Office of Director 1p 16589 137 24X Fiche 50-266, 82/12/20, 8212290322
- --B212290327 LER 82-026/017-0 on 821206, reactor protection relays found to remain in energized position after being de-energized Caused by coil filter epoxy leaking into plunger cavity Failed coils replaced FAY.C W Wisconsin Electric Power Co 82/12/20 Region 3, Defice of Director 3pp 16589 138 24% Fiche 50-266, 82/12/20, 8212290322
- DUCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- BN12200050 Advises of scheduled medical emergency exercise on B21115 Exercise will commence early on day shift & involve transport of one or more simulated victims to offsite medical facilities for examination & treatment HORST, F. J. Public Service Co. of Colorado. B2/10/19 CDLLINS, J. T. Region 4. Office of Director ip 16474 254 24X Fiche 50-267, B2/10/19, B212200050
- 8J12200006 Informs that 920802 submittal of revised radiological emergency response plan implementing procedures reviewed Procedures will be evaluated during next emergency preparedness appraisal followup MADSEN. G L. Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, OR Public Service Co of Colorado Ip 16473 047 244 Fiche 50-267-82/11/02, 8212200006
- ~-B212200011 Notifies that revision to radiological emergency response plan implementing procedures will be submitted under separate cover Revision includes cross-ref to other related procedures

 HAREMBOURG, D W Public Service Co of Colorado B2/08/02

 COLLING, J T Region 4. Office of Director 2pp 16473 050 24x

 Fiche 50-267, 82/11/02, 8212200006
- 8P12200025 Ack receipt of 820824 response to NRC 820810 ltr re fac(lity early warning sys MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE.O R Public Service Co of Colorado 1p 16474 007 24X fiche 50-267.82/11/02.8212200025
- --G212200035 Responds to NRC 620810 request for info re distribution of radios to people who may move into 3-mile emergency plenning zone (EP2) Util Flagging sys gives high lavel of confidence of identifying changes in 5-mile EP2
 MAREMBURGO DW Public Service Co of Colorado 82/08/24
 MADSEN, GL Division of Resident. Reactor Project & Engineering Programs 3pp 16474 008 24X Fiche 50-267.82/11/08.8212200025
- 8P12200094 Ack receipt of 920708 ltr re Confirmatory Action Item 3 from 820104-15 emergency preparedness appraisal Response acceptable Full evaluation to be made during followop appraisal later in yr MADEEN. 6 L Division of Resident. Reactor Project & Engineering Programs 82/11/02 LEE. 0 R Public Service Co of Colorado 3pp 16474 300 24X Fiche 50-267,82/11/02,8212200084
- ---B212200090 Informs of completion of Confirmatory Action Item 3 re
 offsite radiological monitoring Capability from Jan 1982
 emergency preparedness appraisal Installation of iodine
 monitoring instrumentation completed
 MAREHBOURD, D. W. Public Service Co. of Colorado. 82/07/08
 COLLINS, J. T. Region 4. Office of Director. 2pp. 16474 301. PAX
 Fiche 50-267,82/11/02,8212200084
- 8212200096 Ack receipt of 820712 ltr submitting updated radiological emergency response plan MADSEN, 0 L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEC, 0 R Public Service Co of Colorado in 16474 290 24X Fiche 50-267,82/11/02,8212200096
- ---8212200098 Notifies that updated radiological emergency response plan being forwarded under separate cover, per 820315 request MAREMBDURO.D W Public Service Co of Colorado 82/07/12 CCLLINB.J T Region 4. Office of Director 19 14474 291 24X Fiche 50-267, 82/11/02 8212200096

- 8212200108 Ack receipt of D Warembourg 820810 ltr containing updated radiological emergency response plan MADSEN.O.L. Division of Resident. Reactor Project & Engineering Programs 82/11/02 LEE.O.R. Public Service Co. of Colorado. 1; 16470 094 24% Fiche 50-267.82/11/02.8212200108
- --8212200117 Forwards, under separate cover, updated radiological emergency response plan per JT Collins 820315 request Only visitors ctr procedure & radiological emergency response planning field procedure should be retained MAREMBOURG, D W Public Service Co of Colorado 82/08/10 COLLINS, J T Region 4, Office of Director 1p 16470 097 24X Fiche 50-267, 82/11/02,8212200108
- BP12200109 Ack receipt of 82092; revised radiological emergency response plan implementing procedure All future correspondence remergency preparedness should be sent to JL Montgomery MADEEN.G.L. Division of Resident. Reactor Project & Engineering Programs 82/11/02 LEE, O.R. Public Service Co. of Colorado. Ip 14470 098 24% Fiche 50-267.82/11/02.8212200109
- --B212200116 Forwards revised radiological emergency response plan implementing procedures W/o encl WAREMBOURG, D W Public Service Co of Colorado B2/09/21 COLLINS, J T Region 4, Office of Director 1p 16470 099 24X Fiche: 50-267, 82/11/02, 8212200109
- 8212210023 Act receipt of 820908 ltr responding to violations noted in IE Insp Rept 50-267/82-14 Requests date by which radiological emergency kit checklist will be equipped w/items on inventory list MADSEN. G L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE, O R Public Service Co of Colorado 2pp 16490 178 24% Fichs 50-267, 82/11/02, 8212210023
- --8212210024 Responds to NRC B20811 ltr re violations noted in IE Insp Rept 50-267/82-14 Corrective actions util will provide add! RERP implementing procedure to provide further guidance on assuring personnel accountability of area residents WAREMBCURO. D W Public Service Co of Colorado 82/09/08 WADSEN. O L Division of Resident, Reactor Project & Engineering Programs 7pp 16490 200 24X Fiche 50-267.82/11/02,8212210023
- 8212210167 Ack receipt of 820917 ltr in response to IE Emergency Appraisal Audit Rept 50-267/82-01 on 820104-15 MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE.O R Public Service Co of Colorado ip 16484 257 24X Fiche 50-267.82/11/02.8212210167
- --B212210173 Responds to IE Emergency Appraisal Audit Rept 50-267/82-01 of App B items on 820104-15 App B preparedness improvement items ent WAREMBOURG, D W Public Service Co of Colorado 82/09/17 COLLINS, J T Region 4. Office of Director 41pp 16484 258 24X Fiche 50-267, 82/11/02, 8212210167
- 8212200043 Advises that medical emergency exercise rescheduled for 821116 BORST, F J Public Service Co of Colorado 82/11/03 COLLINS, J T Region 4. Office of Director 3pp 16470 135 24X Fiche 80-267, 82/11/03, 8212200043
- 8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents Ci-C4 partially withheld (ref FOIA Exemptions 3.5 % 7) FECTON, J M Division of Rules and Records 82/11/05 HCGARRY, J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50~000, 82/11/05, 8212070425
- --8212070473 Concludes that all Region 4 licensees in compliance \(\u03c4/820701\) deadline for implementation of prompt notification sys COLLING, J T Region 4. Office of Director 82/02/01 GRIMES, B K Division of Emergency Proparedness 2pp 16355 104 24X Fiche 50-000.82/11/05.8212070425
- B212200030 Documents telcon between LM McBride & JA Kelly re unescorted access to facility for German THIR 300 staff Unescorted access will be granted under listed clearance criteria. Hritten concurrence requested MAREMBOURD, D W Public Service Co of Colorado 82/11/08 CGLLINS. J T Region 4, Office of Director 2pp 16474 266 24X Ficher 50-267, 82/11/08, 8212200030
- 8212290328 Discusses ORNL Rept TM-8171 re emergency warning sys Rept findings invalid in terms of specific refs re effectiveness or improvements needed in facility sys HAREMOUNG. D. W. Public Service Co. of Colorado. 82/12/09. CLARK.R Operating Reactors Branch 3 2pp 16589 141 24X Fishe 50-267,82/12/09.8212290328

- 8212270431 Informs that revised Chapter 9 of amended security plan, submitted in 820611 ltr.approved License amend will be issued to update existing license condition on physical protection & incorporate security plan revisions MADSEN.O L. Division or Resident. Reactor Project Engineering Programs 82/12/21 LEE.O R Public Service Co. of Colorado 2pp 16585 195 24x Fiche 50-267.82/12/21.8212290431
- P Operating license stage documents & correspondence
- B212290374 Forwards response to telephone inquiries re status of NUREO-0737. Item III D 3 4, "Control Room Habitability" WAREHBOURG.D W Public Service Co of Colorado 82/11/18 CLARK.R A Operating Reactors Branch 3 2pp 16586 307 24: Fishe 50-2267. 82/11/18. B212290374.
- BP12020409 Forwards request for add1 info re NUREG-0612. "Control of Heavy Loads " Further Clarification needed to adequately address areas discussed Comments encl for review Reply requested within 30 days of receipt of 1th CLARK, R A Deprating Reactors Branch 3 82/11/19 LCE, D R Public Service Co of Colorado 3pp 16297 341 24X Fiche 50-267, 82/11/19,8212020409
- 8212270319 Provides proposed resolutions to 821005 requests included in safety evaluation supporting Amend 28 to Tech Specs Method for calculating outlet temp of 7 northwest boundary regions incorporated in operator training program WAREMBOURG, D. Public Service Co. of Colorado. 82/11/22 CLARK, R. A. Operating Reactors Branch 3. 11pp. 16589-124. 24X

 Fiche 50-267, 82/11/22, 8212290319
- 8212070084 Advises that issue of valve configuration resolved for facility
 CLARK,R A Operating Reactors Branch 3 82/11/26 LEE,Q R Public Service Co of Colorado 2pp 16354 318 24X Fiche 50~267, 82/11/26,8212070084
- 8212150226 Requests review of encl LASL rept on recommendations recontrol rod drive mechanism overtemp problem Commitment in form of Tech Spec limitation to ensure temps do not exceed 215 F requested CLARK.R A Operating Reactors Branch 3 62/12/02 LEE.O R Public Service Co of Colorado 17pp 16447 001 24X Fighe 50-267.82/12/02.8212150226
- 8212210012 Ack receipt of 821015 application proposing update to inservice insp & testing program Fech Specs surveillance requirements Application not exempt from fee requirements Class III fee requested DIGOS.R M License Fee Management Branch 82/12/03 LEE, O R Public Service Co of Colorado ip 14502 360 24% Fiche 50-267, 82/12/03.8212210012
- SP12280504 Informs of transfer of authority & responsibility for conducting reviews & evaluations commensurate w/implementing established licensing & regulatory requirements from Div of Licensing to Region 4
 EISEMHUT, D © Division of Licensing 82/12/03 GAOLIARDO, J
 Division of Resident, Reactor Project & Engineering Programs 2p;
 16590 137 24X Fishe 50-267,82/12/03.8212280504
- 8d12210520 Forwards independent evaluation of OA Co Rept GA-Ai6764: containing analysis of first plateout probe Reasonable agreement exists w/plateout probe measurements MAGNER.F C Division of Resident, Reactor Project & Engineering Programs 82/12/06 LEE.D R Public Service Co of Colorado 2p; 16943 243 24X Fiche 50-267.82/12/06.8212210520
- 8P12290403 Forwards proposed revisions to Tech Specs re organization, review & audit-administrative controls Clarifications of submittals, itrs & discussions provided MAREMBOURG, D. Public Service Co. of Colorado. 82/12/13. MAONER, P. C. Region 4, Orfice of Director. 4pp. 16587 002. 24X Fiche 50-267, 82/12/13, 8212290403
- ---B212270405 Draft composite for Tech Spec Section AC 7 1 re organization, review & audit-administrative controls * Public Service Co of Colorado B2/12/13 24pp 16567 006 24X Fiche 50-267,82/12/13.8212270403
- BR12290421 Forwards Amend 29 to License DPR-34, safety evaluation & notice of issuance & availability Amend deletes requirement for monthly trip test of ultrasonic steam pipe rupture detectors

 WAGNER, P.C. Division of Resident, Reactor Project & Engineering Programs 82/12/13 LEC, D.R. Public Service Co. of Colorado. 3pp 16585 201 24X Fiche 50-247, 82/12/13, 8212290421

- ---B212270427 Amend 27 to License DPR-34, deleting requirement for monthly trip tests of ultrasonic steam pipe rupture detectors MADSEN,O L Division of Resident, Reactor Project & Engineering Programs 82/12/13 4pp 16585 204 24X Fiche 50-267,82/12/13,8212270421
- --8212290437 Notice of issuance & availability of Amend 29 to License DPR-34 MADSEN,O L. Division of Resident, Reactor Project & Engineering Programs 82/12/13 2pp 16585 211 24% Fiche 50-267,82/12/13, 8212290421
- 8212290423 Responds to 821012 Generic Ltr 82-18 re operator requalification Approach contrary to INPO objective of operator training, capability of industry to police itself & long-term proposed accreditation program MAREMBURGO, D W Public Service Co of Colorado 82/12/13 WILKINSON, E P Institute of Nuclear Power Operations 2pp f6585 IBB 24X Fiche 50-267, 82/12/13, 8212290423
- 8212290368 Forwards four oversize P&IDs Aperture cards are available in PDR W/one proprietary oversize P&ID Aperture card is available in Central Files
 LEBLANC, J Public Service Co of Colorado 82/12/15 NRC No Detailed Affiliation Given in 16586-154 24X
 Fiche 50-267.82/12/15.8212290388
- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- BP12200084 Ack receipt of B2070B ltr re Confirmatory Action Item 3 from B20104-15 emergency preparedness appraisal Response acceptable Full evaluation to be made during followup appraisal later in yr MADSEN.O L Division of Rosident, Reactor Project & Engineering Programs 82/11/02 LEE.O R Public Service Co of Colorado 3pp 16474 300 24% Fiche 50-267.82/11/02.8212200084
- --B212200090 Informs of completion of Confirmatory Action Item 3 re offsite radiological monitoring capability from Jan 1982 emergency preparedness appraisal Installation of iodine monitoring instrumentation completed WAREMBURG, D W Public Bervice Co of Colorado 82/07/08 COLLINS, J T Region 4. Office of Director 2pp 16474 301 24X Fiche 50-267, 82/11/02, 8212200084
- 8212210023 Ack receipt of 820908 ltr responding to violations noted in IE Insp Rept 50-267/82-14 Requests date by which radiological emergency kit checklist will be equipped writens on inventory list MADSEN.0 L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE.0 R Public Service Co of Colorada Opp 16490 198 24X Fiche 50-267,82/11/02,8212210023
- --8212210024 Responds to NRC B20811 ltr re violations noted in It Insp Rept 50-267/62-14 Corrective actions util will provide add! RERP implementing procedure to provide further guidance on assuring personnal accountability of area residents WAREHBOURG, D W Public Service Co of Colorado 82/07/08 MADSEN, Q L Division of Resident, Reactor Project & Engineering Programs 7pp 16490 200 24X Fiche 50-267,82/11/02,8212210023
- 8212210167 Ack receipt of 820917 ltr in response to IE Emergency Appraisal Audit Rept 50-267/82-01 on 820104-15 MADSEN O L Division of Resident, Reactor Project & Engineering Programs 82/11/02 LEE,O R Public Service Co of Colorado 1; 16484 257 24X Fiche 50-267,82/11/02,8212210167
- --8212210173 Responds to IE Emergency Appraisal Audit Rept 50-267/82-01 of App B items on 820104-15 App B preparedness improvement items encl WAREMBOURO, D W Public Service Co of Colorado 82/09/17 COLLINS, JT Region 4, Office of Director 41pp 16484 258 24X Fiche 50-267, 82/11/02. 8212210167
- B208190245 IE Info Notice 82-42, "Defects Observed in Panesonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list succl C088.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp. 14372 142 24X Fiche 50-000/82/11/05,8208190245

- 82:2070255 Forwards IE Insp Rept 50-267/82-24 on 82:1001-31 & notice of violation MADBEN, G.L. Division of Resident, Reactor Project & Engineering Programs 82/11/17 LEE.O.R. Public Service Co. of Colorado 2pp 16339 127 24X Fiche 50-267,82/11/17,82:12070255
- --8212070256 Notice of violation from insp on 821001-31 * Division of Resident, Reactor Project & Engineering Programs 82/11/17 2pp 16337 129 24% Fiche 50-267.82/11/17.8212070255
- --8212070260 IE Insp Rept 50-267/82-24 on 821001-31 Noncompliance noted failure to follow std clearance point form requirements & failure to comply w/procedures
 DICKERSON.M N. PLUMLEE.G L. HESTERMAN.T F. Division of Resident,
 Reactor Project & Engineering Programs 82/11/09 9pp
 16539 131 24X Fishe 50-267.62/11/17.8212070255
- 82/08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Lxercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8212200092 Provides revised paragraph to 821103 response to IE Insp. Rept 50-267/82-19 Ltr inadvertently contained error in date when full compliance of CN 653 achieved LEE, O. R. Public Service Co. of Colorado 62/11/29 COLLINS, J. T. Region 4. Office of Director ip 16470 049 24X Fiche 50-267,821/1/29,8212200092
- ~-8212200101 Responds to NRC 821006 ltr re violations noted in lk Insp Rept 50-247/82-19 Corrective actions CN 653 completed LEE, O R Public Service Co of Colorado 82/11/03 COLLING, J T Region 4, Office of Director 29pp 16470 050 24v Fiche 50-267, 82/11/29, 8212200092
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati " Svc list enc! CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000.82/11/30.8208190257
- 8:08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Flectrical Penetration Assemblies" Svc list entl DEYGUNG.R C Director's Office. Office of Inspection and Cnforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Societs " Svc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24X Fich 50-000: 82/12/03. 8208190261
- 8P12210012 Ack receipt of 821015 application proposing update to inservice insp & testing program Tech Specs surveillance requirements Application not exempt from fee requirements Class III fee requested DIOOS,R M License Fee Management Branch 82/12/03 LEE.O R Public Service Co of Colorado [p 16502 360 24X liche 50-267.82/12/03.8212210012
- B212290367 Responds to NRC B21117 itr re violations noted in IE Insp Rept 50-267/B2-24 Corrective actions std clearance form for control rod drives revised to allow positioning of breaker during removal or installation IEE, O R Public Service Co of Colorado 82/12/06 COLLINS. J 7 Region 4. Office of Director 3pp 16586 261 24X Fiche 60-267.82/12/06.8212290367
- 8212270460 Advises that IE Insp Rept 50-267/82-16 canceled MADBEN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/15 LEE, G R Public Service Co of Colorado ip 16585 221 24% Fiche 50-267.82/12/15.8212270460
- BPOBI90267 IE Info Notice B2-49, "Correction for Bample Conditions for Air & Oas Monitoring " Svc list encl DEYGUNG:R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16,8208190267
- 87/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

- R Periodic operating reports & related correspondence
- GE:12210102 Forwards revised monthly operating rept for Sept 1982 MAREMBOURG, D. Public Service Co. of Colorado 82/11/01 GAMMILL, W.P. Assistant Director for Operating Reactors 1p 16491 053 24x Fiche 50-267.82/11/01.6212210102
- --9212210112 Revised monthly operating rept for Sept 1982 MCBRIDE.L M Public Service Co of Colorado 92/10/06 9pp 16491 052 24X Fiche 50-267, 82/11/01-8212210102
- 8.12200074 Porwards monthly operating rept for Oct 1982 MAREMBURG.D Public Service Co or Colorado 82/11/08 Director's Office. Office of Inspection and Enforcement 2pp 16474 283 24x Fichs 50-267, 82/11/08, 8212200074
- SP12E70371 Forwards monthly operating rept for Nov 1982 MAREMBDURG, D. W. Public Service Co. of Colorado. 82/12/14 GAMMILL, W.P. Office of Nuclear Reactor Regulation, Director. 1; 16585-282 24X Fiche 50-267,82/12/14,8212290391
- --8212290394 Monthly operating rept for Nov 1982 MCBRIBE, L M Public Service Co of Colorato 82/12/07 8pp 16586 283 24X Fiche 50-267, 82/12/14, 8212290391
- 5 Reportable occurrences, LERs & related correspondence
- 9212200123 Forwards LER 62-043/03L-0 Detailed event analysis encl MARE/MBQURG, D Public Service Co of Colorado 82/11/24 COLLINS.J T Region 4, Office of Director 5pp 16470 142 24X Fiche 50-267.62/11/24.8212200123
- --B212200128 LER 62-043/03L-0 on 821027 & 28, average PCRV cooling water sys injet & outlat temps fall below 100 F Caused by insufficient heat to maintain foop averages w/both loops in svc Auxiliary heat obtained & operators reinstructed FULLER.C Public Service Co of Colorado 82/11/24 Region 4, Office of Director 1p 16470 147 24X Fiche 50-267.82/11/24.82/2200123
- GP:12290297 Forwards LER 02-044/03L-0 Detailed event analysis encl WAREHOURG, D. Public Service Co. of Colorado 82/12/08 COLLINS, J. T. Region 4. Office of Pirector 5pp 16581 215 24X Fiche 50-267, 82/12/08.8212290297
- --8212290303 LER 82-044/03L-0 on 821110 & il primary coolant dempoint temp exceeded Tech Spec limits Caused by water in reactor vessel veporizing faster than helium purification sys could function Reactor power decreased FULLER.C Public Service Co of Colorado 82/12/09 Region 4, Office of Director ip 1658/ 220 24X Fiche 50-267,82/12/08, 8212200297
- GP12290426 Forwards LER 82-045/03L-0 WAREMBOURG, D Public Service Co of Colorado 82/12/15 COLLINS, J T Region 4. Defice of Director Ip 16585.179 24X Fiche 90-267, 82/12/15, 8212270426
- --8212270440 iER 82-045/03L-O on 821119, loop I FCRV coding water outlet temp suceded Tech Spec limit Caused by inadvertent operation of wrong valve by nonlicensed personnel Proper valve lineup established Mater temp stabilized FULLER.C Public Service Co of Colorado 82/12/15 Region 4, Office of Director App 16585 180 24% Fiche 50-267.82/12/15, 8212290426
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1
- F. Sacurity, medical, emergency & fire protection plans
- 8212130069 Forwards info on emergency offsite facilities (EOF), per R Birkel 821203 request & Deneric Ltr 81-10 Const of permanent primary & backup EOF completed TUCKER.H B Dute Power Ca 92212203 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E 0 Licensing Branch 2pp 16390 185 24X Fiche 50-000,82/12/03.8212130069
- BP12070044 Revieus util 820419 % 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test STOLZ, J F Operating Reactors Branch 4 B2/12/07 TUCKER, H B Dute Power Co 2pp 16384-244 24X Fiche 50-000, 82/12/07, R212070044
- 9212230093 Releases public version of revision to crisis mgt glan & revisions to crisis mgt plan implementing procedures FELTON: J M Division of Rules and Records: 82/12/15 Document Management Branch 1p 16542/026 24X Fiche 50-000,82/12/15,8212230093

- --8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
 TUCKER.H 8 Duke Power Co 62/12/02 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM,E 0 Operating
 Reactors Branch 4 2pp 16542 027 24X Fiche 50-000.62/12/15,
 8212230093
- --8212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet enc! Apprture card available in PDR VAUGHN.R E Dute Power Co 82/11/29 9pp 16542 029 24X Fiche 50-000,82/12/15,8212230093
- --9212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 2 re crisis news group plan & 5 3 if re McOuire crisis phone directory VAUGHN,R E Duke Power Co 82/11/29 260pp 16542 038 24X Fiche 50-000,82/12/15,8212230093
- BP122B0351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly 1UCKER.H B Duke Power Co S2/12/21 DENTON, H R Office of Nuclear Reaction Poincetor 2pp 16560 087 24X Fiche 50-269, 82/12/21, 8212280351
- --8212280367 Proposed Tech Spec revision changing frequency of station security plan 2 implementing procedure audits from once every 2 yrs to yearly * Dute Pouer Co 82/12/21 ip 16560 089 24X Fiche 50-269, 82/12/21, 8212280351
- P Operating license stage documents & correspondence
- B212010185 Forwards Amends 116,116 & 113 to Licenses DPR-39,DPR-47 & DPR-55,respectively,safety evaluation & EIA & notice of Issuance & availability Amend ravises Tech Spec restrictions on burning low level contaminated oil MAGNER,P C Operating Reactors Branch 4 82/11/15 TUCKER,H B Duke Power Co 3pp 16271 232 24X Fiche 50-269,82/11/15, 7012010185
- ---B212010193 Amends 116 i16 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Spec restrictions on burning low level contaminated oil STOLE.7 J Operating Reactors Branch 4 B2/11/15 Bpp 16271 235 24X Fiche 50-269, B2/11/15 8212010185
- ~-B212010205 Safety evaluation & EIA supporting Amends 116,116 & 113 to Licenses DPR-3B, DPR-47 & DPR-55 respectively • defice of Nuclear Reactor Regulation, Director 16271 243 24% Fiche 50-269,82/11/15,8212010185
- --B212010276 Notice of issuance & availability & negative declaration of Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively STOLZ, J. F Operating Reactors Branch 4 82/11/19 2pp 16271 249 24X Fiche 50-269, 82/11/15,8212010185
- BP12010392 Forwards Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & iPR-55, respectively, safety evaluation & notice of issuance & availability Amends incorporate digital logic channels & emergency power switching logic HAGNER, P.C. Operating Reactors Branch 4 B2/11/22 TUCKER, H.B. Duke Power Co. 3pp. 16271 030 24X Fiche 50-269, 82/11/22, B212010392
- --8212010418 Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively, incorporating digital logic channels & emergency power switching logic & revising bases to define redundant component testing STOLZ, JF Operating Reactors Branch 4 82/11/22 28pp 14271 033 24X Fiche 50-269, 82/11/22, 8212010392
- --8212010421 Safety evaluation supporting Amends 117.117 & 114 to Licenses DPR-38.DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 82/11/22 4pp 16271 061 24X Fichs 50-269.82/11/22.8212010392
- ---8212010488 Notice of issuance & availability of Amends 117,117 & 114 to Licenses DPR--38 DPR--47 & DPR--55, respectively STOLZ-J F Operating Reactors Branch 4 82/11/22 2pp 16271 065 24X Fiche 50-269,82/11/22,8212010392
- 8212070370 Forwards license amend fee in response to 821108 ltr TUCKER.H B Dute Power Co. 62/11/22 DIGGS.R M License Fee Management Branch. 2pp 16336 324 24X Fiche 50-269.82/11/22, 6212070370

DOCKETED ITEMS

- B212070341 Forwards responses to NUREG-0737. Item II B 3, "Post-Accident Sampling Sys " W/14 oversize drawings Aperture cards are available in PDR TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Dffice of
 - available in PDR TUCKER, H B Duke Power Co 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 32pp 16340 252 24% Fiche 50-269, 82/12/01, 8212070341
- --8212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys " DEAK.A N. MCCONNELL:T Duke Power Co 82/05/17 18pp 16340 305 24X Fiche 50-269, 82/12/01.8212070341
- --8212070392 "Post-Accident Containment Air Bempling System " W/twelve oversize drawings Aperture cards are available in PDR * Dute Power Co 82/01/29 89pp 16340 324 24X Fiche 50-269,82/12/01.8212070341
- --8212070395 "Post-Accident Liquid Sampling System " W/nine oversize drawings Aperture cards are available in PDR Duer Co 82/01/29 376pp 16341 053 24X Fiche 50-269,82/12/01.8212070341
- G?12100355 Summary of G21130 meeting w/util re use of Mark BZ fuel assemblies in future reload cores Viewgraphs encl MAGNER, P.C. Operating Reactors Branch 4 92/12/01 Operating Reactors Branch 4 54pp 16399 041 24X Fiche 50-269,82/12/01. G212100355
- B./12150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-269/82-37, 50-270/82-37 & 90-287/82-37 1UCKER.H B Duke Power Ca 02/12/08 DENTON.H R Office of Nuclear Reactor Regulation. Director STOLZ.J F Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-269.82/12/08.8212150073
- 8:08190263 Openeric Ltr 82-32 to all PWR licensess re-potential steam generator-related generic requirements Forwards Science Applications. Inc draft repi re-subj requirements Comments requested within 30 days of ltr Svc list enci EISEM-NUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 8212130190 Comments on status of Unresolved Safety Issue A-49 re pressurized thermal shock for facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rep¹ 1UCKER.H B Duke Power Co 82/12/09 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 16396 129 24X Fiche 50-269,82/12/09,8212130190
- G.:12270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREO-0737.

 Item II F.2. "Inadequate Core Cooling "
 LISENIVIT.D 0 Division of Licensing 82/12/10 TUCKER, H B Duke Power Co 2pp 14555 338 24X Fiche 50-249.82/12/10.8212270335
- --8212270338 Order for license mod to conform w/specs of NUREQ-0737.

 Item II F 2 Checklist for specific review encl

 E18ENHVI, D 0 Division of Licensing 82/12/10 Duke Power Co
 11pp 16555 339 24% Fiche 50-269,82/12/10,8212270335
- GP12210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during B20818-19 meetings delayed until 830131, per util 821110 commitment TUCKER. H B Duke Power Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director STOL7. J F Operating Reactors Branch 4 ip 16485 247 24x Fiche 50-269,82/12/15,8212210079
- G212280351 Application to amend Licenses DPR-36.DPR-47 & DPR-55.
 revising App A Tech Specs to change frequency of station
 security plan & implementing procedure audits from once
 every 2 yrs to yearly
 TUCKER.H B Duke Power Co 62/12/21 DENTGN,H R Office of
 Nuclear Reactor Regulation, Director STOLZ.JF Operating Reactors
 Branch 4 2pp 16560 087 24% Fiche 50-269.82/12/21.8212280351
- --8212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly * Dute Power Co 82/12/21 1p 16560 089 24X Fiche 50-269, 82/12/21, 8212280351

- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter. Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl
 DEVOUND, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 14462 163 24X Fichs 50-000. 82/10/28. 8208190240
- B212090181 Forwards IE Insp Repts 50~269/82-39.50~270/82-39 & 50~287/82-39 on 820915~1010 No noncompliance noted DAKCE.H C Division of Project & Resident Programs 82/10/29 TUCKER.H B Dake Power Co 2pp 16359 197 24X Fiche 50~269.82/10/29.8212070181
- --B212070187 IE Insp Repts 50-269/82-39,50-270/82-39 & 50-287/82-39 on B20915-1010 No noncompliance noted Major areas inspected operation safety verification maint activities, surveillance testing startup testing & TMI action item implementation ORDERS, W. FALCONER, D. BRYANT, J. C. Division of Project & Resident Programs 82/10/28 7pp 16389 199 24X Fiche 50-269,82/10/29,8212090181
- BiO8190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model BO2 Thermolyminescent Dosimeters " Svc list encl COB8.L I Division of Fuel Faculties, Materials & Safeguards B2/11/05 Consolidated Edison Ca of New York, Inc 110pp 14072 142 247 Fichs 50-000, 82/11/05, 8208190249
- GRIGO90420 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants," Item 1 for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 will be pravided following next refueling outage TUCKER.H B Duke Power Co 82/11/15 O'REILLY, J.P. Region 2, Office of Director 4pp 16365 033 24X Fiche 30-269,82/11/15,82(2090420)
- 8212060310 Orants 820830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bidg spray sys piping Bafety evaluation encl 5TOLZ. J. F. Operating Reactors Branch 4 82/11/16 TUCKER. H. B. Duks Power Co. 6pp. 16323-351 24X Fiche 50-269, 82/11/16, 82(2060310
- --B212040313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping STOLZ, J F Operating Reactors Branch 4 82/11/16 2pp 16323 357 24X Fiche 50-269,82/11/16,8212060310
- 82-08190281 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 1641
- EPO8190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list encl DEYQUNG,R C Director's Office Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411,065 24X Fiche 50-000,82/11/26,8208190256
- 82/03:90257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fistile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- BPOB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" By: list Encl DEYOUNDER C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc. 113pp 16411,317, 24X Fiche 50-000,82/12/03.8208190259
- 82/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Syc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche: 50-000, 82/12/03, 8208190261
- GPI2270390 Ack receipt of payment of civil penalties in response to notice of violation Addl corrective actions will be examined during future insp
 AXELRAD. J A Director's Office, Office of Inspection and Enforcement 82/12/03 TUCKER. H B Duke Power Co 2pp
 14546 034 24X Fiche 50~249, 82/12/03, 8212270390

- 89:12:50073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-267/82-37. 50-270/82-37 & 50-287/82-37 TUCKER, H B Duie Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14427 339 24X Fiche 50-267, 82/12/08, 82(2150073
- B20B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYGUNG.R C Director's Office. Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York. Inc
 127pp 16628 191 24% Fiche 50-000.B2/12/16.820B190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp. 16428 293 247 Fiche 50-000.82/12/20.8208190268
- R Pariodic operating reports & related correspondence
- 8212210421 Forwards monthly operating repts for Nov 1982 TUCKER,H B Dute Power Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16493 058 24X fiche 30-269, 82/12/15.8212210421
- --8212210426 Monthly operating repts for Nov 1982 REAVIS,J A Duke Power Co 82/12/15 16pp 16493 059, 24X Fiche 50-269,82/12/15,8212210421
- PUCKET 50-270 GCONEE NUGLEAR STATION. UNIT 2

 F Security, medical: emergency & fire protection plans
- 8P12130067 Forwards info on emergency offsite facilities (EGF), per R Birkel 821203 raquest & Øeneric Ltr 81-10 Const of permanent primary & backup EGF completed TUCKER.H B Buke Power Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E Ø Licensing Branch 4 2pp 16370 186 24X Fiche 50-000,82/12/03.8212130069
- BP12090044 Reviews util 920419 & 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test STOLZ.J F Operating Reactors Branch 4 B2/12/07 TUCKER.H B Duke Power Co 2pp 16384 244 24X Fiche 50-000.82/12/07. B212090044
- 6212230073 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures FELTON. JM Division of Rules and Records 82/12/15 Document Hanagement Branch ip 16542 026 24X Fiche 50-000,82/12/15,821220093
- --8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
 TUCKER.H B Dute Power Co 82/12/02 DENTON.H R Defice of
 Nuclear Reactor Regulation. Director ADENSAM.E G Operating
 Reactors Branch 4 3pp 16542 027 24X Fishe 50-000.82/12/15,
 8212230093
- --B2(2230124 Public version of Revision 7 to crisis mgt plan Dne oversite pamphlet encl Aperture card available in PDR VAUGHN, R E Duke Power Co 82/11/29 7pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230073
- --8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3 2 re crisis news group plan & 5 3 li re hcduire crisis phone directory VAVSHIN RE Duke Power Cb. 82/11/29 280pp 16542 038 24x Fiche 50-000, 82/12/15,8212230093
- 82:12280351 Application to amend Licenses DPR-38.DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly TUCKER.H 8 Duke Pawer Co 82/12/21 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp 16560 087 24X Fiche: 50-269, 82/12/21, 8212280351.
- --8212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly 4 Duke Power Co 82/12/21. Ip 16560 089. 24X Fiche 50-269,82/12/21,8212280351

- P Operating license stage documents & correspondence
- BP12010185 Forwards Amends 114,116 & 113 to Licenses DPR-38, DPR-47 & DPR-55; respectively, safety evaluation & EIA & notice of issuance & availability Amend revises Tech Spec restrictions on burning low level contaminated oil HAGNER, PC Operating Reactors Branch 4 82/11/15 TUCKER, H B Duke Pouer CO 3pp 16271 232 24X Fiche 50-269,82/11/15, D2:0210185
- --8212010205 Safety evaluation & EIA supporting Amends 116.116 & 119 to Licanses DPR-38.DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 82/11/15 &pp 16271 243 24% Fiche 50-267.82/11/15 8212010185
- --8212010276 Notice of Issuance & availability & negative declaration of Amends 116 & 116 & 113 to Licenses DPR-38.DFR-47 & DPR-35, respectively STOLZ.J F Operating Reactors Branch 4 82/11/15 2pp 16271 249 24X Fiche 50-249,82/11/15.8212010185
- BR12010392 Forwards Amends 117,117 & 114 to Licenses DPR-38.DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends incorporate digital logic channels & emergency power switching logic WARNER, P.C. Operating Reactors Branch 4 82/11/22 TUCKER, H.E. Duke Power Co. 3pp. 14271-030 24X Fiche 50-269.82/11/22, 8212010392
- --8212010418 Amends 117, 117 & 114 to Licenses DPR-38, DPR-47 & DPR-55, respectively, incorporating digital logic channels & emergency power switching logic & revising bases to define redundant component testing STOL2, J F Operating Reactors Branch 4 82/11/22 28pp 16271,033 24X Fiche 50-269,82/11/22,8212010392
- --8212010421 Safety evaluation supporting Amends 117.117 & 114 to Licenses DPR-93.DPR-47 & DPR-55 respectively * Office of Nuclear Reactor Regulation. Director 82/11/22 4pp 16271 061 24X Fiche 50-269, 82/11/22.8212010392
- --8212010488 Notice of issuance & availability of Amends 117.117 & 114 to Licenses DPR-38.DPR-47 & DPR-95.respectively STOL2.J F Operating Reactors Branch 4 82/11/22 2pp 16271 065 24X Fiche 50-269.02/11/22.8212010392
- 8212070370 Forwards license amend fee in response to 821108 ltr TUCKER.N 8 Duke Power Co 82/11/22 DIGGS.R M License Fee Management Branch 2pp 16336 324 24X Fiche 50-269,82/11/22, 8212070370
- 82:1207034: Forwards responses to NUREG-0737. Item II B 3, "Post-Accident Bampling Bus " W/14 oversize drawings Aperture cards are available in PDR TUCKER.H B Duke Power Co B2/12/01 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J.F Operating Reactors Branch 4 32pp 16340:252 24X Fiche 50-269, 82/12/01.8212070341
- --8212070348 "Estimate of Failed Fuel Based on I-131 Concentration " HULL.P. ONEN, T B Dute Power Co 82/08/03 22pp 16340 283 24% Fiche 50-269,82/12/01.8212070341
- --B212070392 "Post-Accident Containment Air Sampling System " W/twelve oversize drawings Aperture cands are available in PDR * Duke Power Co 82/01/29 89pp 16340 324 24X Fiche 50-269,82/12/01.8212070341
- --8212070395 "Post-Accident Liquid Sampling System " W/nine oversize drawings Aperture cards are available in PDR

 * Duke Power Co 82/01/29 376pp 16341 053 24x
 Fiche 50-269,82/12/01.8212070341
- 8212100355 Summary of 821130 meeting w/util re use of Mark 82 fuel assemblies in future reload cores Viewgraphs encl HAGNER, P.C. Operating Reactors Branch 4 82/12/01 Operating Reactors Branch 4 54pp 16399,041 24X Fiche 50-269,82/12/01,8212100355
- B212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 50-247/82-37. 50-270/82-37 & 50-287/82-37 TUCKER.H B Duke Power Co 82/12/08 DENTON,H R Dffice of Nuclear Reactor Regulation, Director STDL2.JF Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-247.82/12/08.8212150073

- 82°08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re sub; requirements Comments requested within 30 days of ltr Svc list enci EISENNUT.D G Division of Licensing 82/12/09 Consolidated Ldison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000.82/12/09,8208190263
- 8 '12130170 Comments on status of Unresolved Safety Issue A-47 repressurized thermal shock for facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rept
 TUCKER.H B Duke Power Co 82/12/09 DENTON,H R Office of Nuclear Reactor Regulation, Director STGLZ,JF Operating Reactors Branch 4 2pp 14376 127 24X Fiche 50-249.82/12/09.8212130190
- 8/12270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREQ-0737, Iten II F 2. "Inadequate Core Cooling "EISENVUID Q Division of Licensing 82/12/10 TUCKER
- --G212270338 Order for license med to conform w/specs of NUREO-0737, Item II F 2 Checklist for specific review encl EIGENHUT, D 0 Division of Licensing 82/12/10 Duke Power Co Ilpp 16955 339 24X Fiche 50-269,82/12/10,8212270338
- GF12210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during 820818-19 meetings delayed until 830131.per util 821110 commitment TUCKER.H B Duke Power Co 82/12/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 61012.JF Operating Reactors Branch 4 lp 16485-247 24X Fichs 50-269,82/12/15,8212210079
- Giri 2280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, ravising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once overy 2 yes to yearly TUCKER, H B Duke Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 570L2, J F Degrating Reactors Branch 4 2pp 16560 087 24X Fiche 50-269, 82/12/21,8212280351
- ~~9212280367 Proposed Tech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly

 4 Duke Power Co 82/12/21 1p 16560 089 24X
 Fiche 50~269,82/12/21,8212280351

0 Inspection reports, IE Bulletins & correspondence

- 82/03190240 IE Bulletin 92-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BRR Plants "Syc list encl
 UEYOUNG, R C Director's Office, Office of Inspection and Inforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8:12090181 Forwards IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/10/29 14CKER.H B Dute Power Co 2pp 16359 197 24X Fiche 50-269, 82/10/29, 8212090181
- --8212070189 IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted Major areas inspected operation safety verification maint activities, surveillance testing, startup testing & THI action item implementation ORDERS, W. FALCONER, D. BRYANT, J.C. Division of Project & Resident Programs 82/10/28 7pp 16359 199 24X Fiche 50-269, 82/10/29, 8212090181
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 t. Model 802 Thermoluminescent Dosimeters "Syc list enc!

 C080.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 90-000,82/11/05.8208190245
- B212090420 Forwards response to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants," Item 1 for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 uill be provided following next refueling outage TUCKER, H B Duke Power Co B2/11/15 O'REILLY, J P Region 2, Office of Director 4pp 16365 033 24X Fichs 50-269,82/11/15, B212090420
- 8212060310 Grants 820830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping Safety svaluation encl STOLX.V F Operating Reactors Branch 4 82/11/16 TUCKER.H B. Duke Pouer Co App 16323.351 24X Fiche 50-269.82/11/16. R812060310

- --B212060313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping STOL7.7 F Operating Reactors Branch 4 B2/11/16 2pp 16323 357 24X Fiche 50-269, 82/11/16,8212060310
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- 8208190256 1E Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 lE Info Notice 82~47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svr list encl CO88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000,82/11/30,8208190257
- 8POB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svr list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 14X Fiche 50-000.82/12/03.8208190261
- BP12150073 Requests clarification of conditional snubber aperability as described in certain Tech Specs Request due to discussion in 1E Insp Repts 50-287/82-37.50-270/82-37 & 50-287/82-37 TUCKER.H B Duke Power Co 82/12/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 16427 339 24% Fiche 50-269.82/12/08.8218150073
- 8708190267 TE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 87:08190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000, 82/12/20,8208190268

R Periodic operating reports & related correspondence

- 8P12210421 Forwards monthly operating repts for Nov 1982 TUCKER.H B Duke Power Co 82/12/15 Director's Office of Inspection and Enforcement 1p 16493 058 24X Fiche 30-269.82/12/15.8212210421
- --8212210428 Monthly operating repts for Nov 1982 REAVIS.J.A. Duke Pawer Co 82/12/15 16pp 16493 059 24X Fiche 50-269,82/12/15,8212210421
- DOCKET 50-271 VERMONT YANKEE MUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- BP12140098 Forwards IE Insp Rept 50-271/82-19 on 821005-1101 & notice of violation BTAR08TECKI, R Division of Project & Resident Programs 82/11/30 MURPHY, W P Vermont Yankes Nuclear Power Corp 2pp 16409 268 24X Fichs 50-271, 82/11/30, 82121 40098
- --G212140105 Notice of violation from insp on B21005-1101.
 * Division of Project & Resident Programs, B2/11/30 ip 16409 270 24X Fiche 50-271, B2/11/30, B212140098.
- 821214013 IE Insp Rept 50-271/82-19 on 821005-1101 Noncompliance noted failure to maintain fire control area free of combustible mails as required by Administrative Procedure AP 0042 & Tech Spec 6 5 A RAYMONO.H J. OALLO.R M Division of Project & Resident Programs 82/11/16 15pp 16409 271 24X Fiche.50-271,82/11/30,8212140098

- 82:2210295 Provides add1 info re types of questions NRC duty officer may ask in telephone rents made via NRC emergency notification sys Event notification form encl STARDSTECKI.R Division of Project & Resident Programs 82/12/16 MURPHY.W P Vermont Yankee Nuclear Power Corp App 16497 004 24x Fichs 50-271.82/12/16.8212210295
- P Operating license stage documents & correspondence
- 8211230066 Generic Ltr 62-27 to all GMR licensees of operating reactors ercept LACGMR. Big Rock Point, Dresden i, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl M/o stated encl EISENHUT, O G Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16397 004 24% Fiche 50-000, 82/11/15, 9211230066
- 8P:2280005 Forwards Amend 73 to License BPR-28, safety evaluation, notice of (squance & availability & technical evaluation rept Amend changes Tech Specs rescram discharge volvent & drain valve surveillance ROONEY, V. L. Operating Reactors Branch 2 82/11/27 SINCLAIR, J.B. Varmont Yankse Nuclear Power Corp. 2pp. 16592 186 24X Fichs 50-271, 82/11/29, 8212280005
- --8212280007 Anend 73 to License DPR-28, changing Tech Specs re scram discharge vol vent & drain valve surveillance VASSALLO, D B Operating Reactors Branch 2 82/11/29 7pp 16592 188 24X Fiche 50-271, 82/11/29, 8212280005
- --9206160113 "BuR Scram Discharge Vol Long-Term Mods," technical evaluation rept MCPA.E Franklin Institute/Franklin Research Center NRC-03-81-130 ERR-05906-64 82/06/11 ECCLESTON, K NRC No Detailed Affiliation Given 49p 16592 195 24X Fichs 50-271,82/11/29,8212280005
- --8212280015 Safety evaluation supporting Amend 73 to License DPR-28 = Office of Nuclear Reactor Regulation. Director 82/11/29 2/pp 16592 243 244 Fiche 50-271.82/11/29.8212280005
- --82/2280027 Notice of isquance & availability of Amend 73 to License DPR-28 VASSALLO,D B Operating Reactors Branch 2 82/11/29 2pp 16592 245 24X Fiche 50-271,82/11/29,8212280005
- 8212270212 Forwards final "Mark I Containment Program Plant Unique Analysis Rept of Torus Sugression Chamber " BINCLAIR. J B Vermont Yankee Nuclear Power Corp 82/11/30 VASSALLO, D B Licensing Branch 2 ip 16538 157 24X Fiche 50-271, 82/11/30, 8212270212
- --8212270218 Fina] "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber" * Teledure Engineering Services 7R-5319-1 82/11/30 140pp 16538 158 24X Fiche 50-271, 82/11/30.8212270212
- 8212130158 Forwards safety evaluation of DWR owners group 810522,0921 & 820902 responses to NUREO-0737. Item II K 3 25. "Effect of toss of AC fower on Pump Seais "Response acceptable WABSALLO, D 8 Operating Reactors Granch 2 82/12/01 SINCLAIR, J D Vermont Yankee Nuclear Fower Corp 7pp 16410 288 24X Fiche 50-271.82/12/01.8212130158
- 8212090374 Advises that util requires addl time before submitting final draft of radiological ETS & offsite dose calculation manual Draft radiological ETS util be submitted by 830117 & offsite dose calculation manual by 830201 SINCLAIR. J B Vermont Yankee Nuclear Power Corp 82/12/06 VASSALLO, D B Deprating Reactors Branch 2 1p 16365 055 24X Fiche 50-271, 62/12/06, 8212090374
- 6212140379 Application to amend License DPR-28 revising App A Tech Specs to reflect administrative changes Class II fee encl HEIBER.L H Vermont Yankee Nuclear Power Corp 82/12/07 Dffice of Nuclear Reactor Regulation, Director 2pp 14404 190 24X Fiche 50-271,82/12/07.6212140379
- ~-8212140448 Proposed Tech Specs changing title of assistant plant manager to maint superintendent * Versont Yankee Nuclear Power Corp 82/12/07 3pp 16404 192 24X Fiche 50-271.82/12/07.8212140379
- 8212280492 Comments on review of NUREG-0737, Action Item II E 4 2, "Containment Isolation Dependability," Positions 6 & 7 Item considered closed VASSALLO, D B Operating Reacture Branch 2 82/12/09 SINGLAIR, J B Vermont Yankee Nuclear Power Corp. 3pp 16590 352 24X Fiche. 50-271, 82/12/09, 8212280492

- 8212100310 Responds to NRC 821102 request for addl info re degraded grid voltage protection Info will be submitted 3 months prior to installation of degraded grid voltage mod during 1984 refueling outage SINCLAIR. J. B. Vermont Yankee Nuclear Power Corp. 82/12/10 VASSALUD. P. Operating Reactors Branch 2 lp. 16376-278 24% Liche 50-271, 82/12/10, 8212100310
- 82:12210138 Responds to 82:1104 request for add1 info re adequacy of station electrical distribution sys voltages Proposed change to Tech Specs not warranted since transformer sporability olready covered by existing Tech Specs (SINCLAIR, J.B. Vermont Yankee Nuclear Power Corp. 82:12/16 VASBALLO, D.B. Operating Reactors Branch 2 2pp. 16485-186 249 Fiche 50-271, 82:12/16, 82:12210138
- & Inspection reports, IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Mall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants " Syc list encl DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York. Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list ricl CORB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/36 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- BPOB190256 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities or Non-Fissile Radioactive Matl " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- GP12140098 Forwards IE Insp Rept 50-271/82-19 on 821005-1101 & notice of violation STARGSTECKI, R Division of Project & Resident Programs 82/11/30 MURPHY, W P Vermont Yankee Nuclear Fower Corp 2pp 16409 268 24X Fichs 50-271,82/11/30,8212140098
- --8212140109 Notice of violation from insp on B21005-1101 * Division of Project & Resident Programs 82/11/30 ip 14409 270 24% Fiche 50-271, 82/11/30,8212140098
- --8212140113 IE Imsp Rept 50-271/82-19 on 821005-1101 Noncompliance noted failure to maintain fire control area free of combustible matls as required by Administrative Procedure AP 0042 & Tech Spec 6 9 A RAYMOND, N J , GALLO. R M Division of Project & Resident Programs 82/11/16 15pp 16409 271 24X Fiche 50-271,82/11/30,8212140098
- 82/06190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG.R C Director's Office. Defice of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, list 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462-064 24X Fiche 50-000, 82/12/03.8208190261
- 8%12270388 Ack receipt of 821112 ltr containing payment of civil penalties in response to 821015 notice of violation AKELRAD, J A Director's Office, Office of Inspection and Enforcement 82/12/10 CQMAMP.W F Vermont Yankes Nuclear Power Corp 2pp 16568 352 24X Fiche 50-271,82/12/10,8212270388
- 8208170267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16.8208190267

- G2/12/20423 Forwards list of topic areas for discussion at upcoming Region I/licensee meeting on drug & alcohol abuse programs. as discussed in IE Info Notice 82-05 & MUREO-0903 Meeting date & time to be arranged STAROSTECKI.R Division of Project & Resident Programs 82/12/16 MURPHY.N P Vermont Yankee Nuclear Power Corp 4pp 16503 282 24X Fiche 50-271.82/12/16.8212220423
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp. 16428 273 24X Fiche 50-000. 82/12/20.8208190268
- H Periodic operating reports & related correspondence
- BP:12150174 Forwards monthly operating rept for Nov 1982 MURPHY.N P Vermont Yankee Nuclear Power Corp 82/12/09 Office of Resource Management. Director 2pp 16430 150 24x (iche 50-271.82/12/09.8212150174
- --9212150176 Monthly operating rept for Nov 1982 BURGER, F J Vermont Yankee Nuclear Power Gorp 82/12/09 App 16430 152 24X Fiche 50-271, 82/12/09, 8212150174
- S Reportable occurrences, LERs & related correspondence
- 82:12030117 LER 82-071/01P on 82:1128 during investigation of leak in sycuater piping to component cooling HV 12 radiography of vendor weld joint should pocket in weld investigation to determine cause underway
 MIDURALH J Public Service Electric & Gas Co of New Jersey
 B2/11/30 HAYNES,R C Region 1. Office of Director 1p
 16/306 030 24% Fiche 50-271,82/11/30.82:20/30117
- 82:12270378 Forwards LER 82-024/03L-0 PÉLLETIER.J P Vermont Yankee Nuclear Power Corp 82/12/13 HAYNES.R C Region 1. Office of Director 1p 16586 304 24) Fiche 50-271.82/12/13,8212270378
- --8212290384 LER 82-024/03L-0 on 821115, interval for weekly control rod exercise exceeded by 5 6 h Caused by personnel error Applicable personnel reinstructed in requirements of surveillance testing program PFLLETIER, J P Vermont Vankee Nuclear Power Corp 82/12/13 Region 1. Office of Director 2pp 16586 305 24X Fiche 50-271,82/12/13,8212290378
- DOCKET 53-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

 | Security, medical, emergency & fire protection plans
- 8.12010462 Confirms that Div of Safeguards regulatory effectiveness review scheduled for 821203 & 06-10 Info re review encl Review uill evaluate security program & safeguards regulations
 VARGA, S.A. Operating Reactors Branch 1 82/11/23 UDERITZ, R.A. Public Service Electric & Oas Co. of New Jersey App. 16501-327-24X Fache 50-272,82/11/23,8212010462
- 67·12(30212 Responds to B21202 telcon re emergency operations facility survey Facility 7 5 miles from generating station & consists of concrete block facility within concrete block bldg Protection factor is 13 Ventilation sys isolable LIDEN-E A Public Service Electric & Oas Co of New Jersey B2/12/06 VARGA,S A Operating Roactors Branch 1 2pp 16.390 IIB 24X Fiche 50-272,02/12/06,8212130212
- GRI2270435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/62-28 on 820812 No reply required MARTIN-T T Division of Engineering & Technical Programs 82/12/1. UDERITZ:R A Public Service Electric & Gas Co of New Jersey 2p. 16585 222 24X Fiche 50-272, 82/12/14, 8212290435
- --B2i2290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on B20812 Areas discussed implementation & mgt of physical security program BMITH, 0 C , MCKEONN, L M , ODDY, A T Division of Engineering & Technical Programs 82/12/07 App 16585 224 24X Fiche 50-272, 82/12/14, 8212290435
- GP12210038 Offers addl info to prepare operating shift crews to respond to types of questions NRC duty officer may ask re telephone repts made via NRC emergency notification sys STAROSTECKI. R Division of Project & Resident Programs 82/12/16 UDERITZ, R A Public Service Electric & Gas Co of New Jersey App 16490 214 24X Fiche 50-272,82/12/16.8212210038

- 8212300306 Confirms 821220 telcon re fire protection program review Snoke detectors & nonsafety-grade source range neutron flux monitors will be installed & i h fire barrier math will be urapped on B diesel control cable trays

 LIDEN: E A Public Service Electric & Gas Co of New Jørsey

 82/12/22 VAROA, S A Operating Reactors Branch i ip 16594 209

 24X Fiche 50-272,82/12/22,8212300306
- P. Operating license stage documents & correspondence
- 8):11230046 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBWR. Big Rock Point, Dresden 1. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl W/o stated encl LISENHUT. D 0 Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16367 004 24X Fiche 50-000, 82/11/15, 8211230046
- 8212010155 Submits add1 info to support 821005 request for amend to Licenses DPR-70 & DPR-75 Info includes analysis results demonstrating motivation for Tech Spec change & effects on core limits & axial offset DNB limits LIDEN.E A Public Service Electric & Oas Co of New Jorsey 82/11/18 VARCA: S A Operating Reactors Branch 1 8pp 16258 094 24X Fiche 50-272,82/11/18,8212010155
- B?120f0148 Forwards Revision I to "Safety Evaluation of PBEG Rud Exchange Methodology," for info LIDENLE A Public Service Electric & Gas Co of New Jersey 82/11/24 VARGAS A Operating Reactors Branch 1 3pp 16258 111 24X Fiche 50-272,82/11/24.8212010148
- --G212010150 "Safety Evaluation of PSEG Rod Exchange Methodology," Revision 1 BLAKE,R A., BROWN,R T., ROSENFELD,E S. Public Service Electric & Gas Co. of New Jersey NFO 004 RO1 B2/11/16 34pp 16238 114 24% Fiche 50-272,82/11/24,8212010148
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of itr Svc list encl EISENNUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24x fiche 50-000.82/12/09,8208190263
- Bi12140103 Generic ttr 82-28 to all licensees of operating
 Westinghouse & C-E Pilks (except Arkansas Nuclear One, Unit 2
 & San Onofre 2 & 3) re inadequate core cooling
 instrumentation sys Svc list enc!
 EISEN-NUT, D 0 Division of Licensing 62/12/10 Yankee Atomic
 Liectric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10,
 8212140103
- G:12160623 Notification of B21214 meeting w/util in Bethesda. MD to discuss util proposal for restructuring safety review functions ROSS: W. J. Operating Reactors Branch 1 B2/12/14 VARGA, S. A. Operating Reactors Dranch 1 2pp 16466 035 24X Fiche 50-272, 82/12/14-B212166623
- G?12300072 Notification of G30104 significant licensee meeting w/util for presentation of GA organizational & functional changes TRIPP.L E Division of Project & Resident Programs 82/12/21 Division of Project & Resident Programs 2pp 16624 280 24X Fiche 50-000, 62/12/21, 6212300072
- O Inspection reports. IE Bulletins & correspondence
- 82:08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, luc 112pp 16462 163 24X Fiche 50-000, 82/10/28,8208190240
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimoters " Svc list that COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pg 16372 142 24X Fiche 50-000, B2/11/05, B208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison to of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251

- 8212060278 Forwards IE Insp Repts 50-272/82-27 & 50-311/82-26 on H20928-1108 & notice of violation STAROGIECKI.R Division of Project & Resident Programs 82/11/22 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2p; 16312 036 24X Fiche 30-272,82/11/22,8212060278
- --8212060281 Notice of violation from insp on 820928-1108 * Division of Project & Resident Programs 82/11/22 2pp 16312 038 24X Fiche 50-272, 82/11/22, 8212060278
- --8212060287 IE Insp Repts 50-272/82-2/ & 50-311/82-26 on 820928-1108
 Noncompliance noted failure to perform surveillance in time
 specified & failure to observe limiting condition of
 operation on fire protection instrumentation
 NORRHOLM:N J . SUMMERS,R . TRIPP.L E Division of Project &
 Resident Programs 82/11/09 18pp 16312 040 24x
 Fiche 50-272,82/11/22.8212060278
- 8708190256 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNGAR C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 14411 065 24X Fiche 50-000.82/11/26.8208190256
- 8P12030144 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-22 & 50-311/82-21 MARTIN.T T Division of Engineering & Technical Programs 82/11/2 UDERITZ.R A Public Service Electric & Gas Co. of New Jersey Ip 16306 112 24X Fiche 50-272.82/11/27,8212030144
- --8212030153 Responds to NRC 82[019 ltr re violations noted in IL Insp Repts 50-272/82-22 & 50-311/82-21 Corrective actions Mater M-137 properly recalibrimeters M-76 & M-184 accounted for & inadequate housekeeping conditions corrected UDERITZ,R A Public Service Electric & Gas Co of New Jersey 82/11/19 HAYNESIR C Region 1 Office of Director Spp 16306 113 24X Fiche 50-272.82/11/29.8212030144
- 8708190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Compolidated Edison Co of New York, Inc 35App 16387 028 24X Fiche 50-000,82/11/30,8208190257
- BPO8190259 IE Bulletin 82-04. "Deficiencies in Primary Containment flectrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, lic [13pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- B20B190261 IE info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN EL Division of Engineering & Guality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,820B190261
- 8212140124 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-25 & 50-31/92-24 STAROSTECKI.R Division of Project & Resident Programs 82/12/06 UDERITZ.R A Public Service Electric & Oas Co of New Jersey ip 16408 240 24% Fiche 50-278.82/12/06.8212140124
- --B212140133 Responds to NRC B21006 ltr re violations noted in IE Insp Repts 50-272/B2-25 & 50-311/B2-24 Corrective actions Tech Spec 3 0 4 will be discussed w/personnel Tech Spec 3 3 3 5 limiting condition for operation not violated UDERITZ.R A Public Service Electric & Gas Co of New Jersey B2/11/05 HAYNES,R C Region (Office of Director 4pp 16408 241 24X Fiche 50-272, B2/12/06, B212140124
- 82:12200020 Submits addt info per IE Bulletin 80-11, "Masonry Wall Design," in response to NRC request One oversize drawing onel Aperture card is available in PBR LIDEN,E A Public Service Electric & Gas Co of New Jersey 82:12/08 VARQA,S A Operating Reactors Branch 1 3pp 16470 186 24X Fiche 50-272,82/12/08,8212200020
- BP12290435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 No reply required MARTIN T T pivesion of Engineering & Technical Programs 82/12/14 UDERSTAR A Public Service Electric & Gas Co of New Jersey 2pp 16585 222 24% Fiche 50-272,82/12/14.8212290435
- --8212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed implementation & mgt of physical security program SKITH C C , MCKEGWN, L M , CODY, A T. Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24% Fiche 50-272,82/12/14.8212290435

- B.'08190267 [E Info Notice 82-49, "Correction for Sample Conditions for Air & Gas homitoring " Svc list encl DEYQUNG.R C Director's Diffice. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Dic 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- 8P12220444 Forwards listing of topic areas for discussion at Region 1/ licensee meeting on drug & alcohol abuse programs per IE linfo Notice 82-05 & NUREC-0903 No NUREC STAROSTECKI.R Division of Project & Resident Programs 82/12/16 UDERITZ.R A Public Service Electric & Gas Co of New Jersey Spp 16503 322 24/ Fiche 50-2/2.82/12/16.8212220444
- 8,08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division or Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24y Fiche 50-000,82/12/20,8208190268
- it Periodic operating reports & related correspondence
- GP12230268 Forwards monthly operating rept for Nov 1982 MIBURA.H J Public Service Electric & Gas Co of New Jersey 82/12/10 Director's Office, Office of Inspection and Enforcement ip 16508 251 24% Fiche 50-272,82/12/10/8212230268
- --8212230271 Monthly operating rept for Nov 1982 MILLER,L K Public Service Electric & Oas Co of New Jersey 82/12/10 13pp 16508 252 24% Fiche 50-272,82/12/10,8212230268
- BP12280066 Forwards NPDES discharge monitoring rept for Nov 1982 NILLER.L K Public Service Electric & Gas Co of New Jersey 02/12/15 BAKER.R A , LUNDIN.C Environmental Protection Agency 1p 16564 256 24X Fiche 50-272.82/12/15,8212280066
- --8212280038 NPDES discharge monitoring tept for Nov 1982 MILLERIL K. Public Service Electric & Gas Co. of New Jersey 82/12/14 19pp 16564 257 24X Fiche 50-272,82/12/15,8212280066
- 3 Reportable occurrences, LERs & related correspondence
- B712060271
 Forwards
 LER
 82-083/031-0
 Detailed event analysis encl

 MIDURAL H
 Public
 Service
 Electric
 & Gas
 60
 of New Jersey

 B2/11/17
 HAYNES
 R
 C
 Region
 1.
 Office of Director
 3pp

 14312
 070
 24X
 Fishe
 50-272
 82/11/17
 8212060291
- --8212050278 LER 82-083/03L-0 on 821102, during routine shutdown operation, tomp recorder for air temp-delts T channels was not printing Caused by failure of pinion gear on chart drive motor Motor replaced FRAMM. R Public Service Electric & Gas Co of New Jersey 82/11/17 Region 1, Office of Director ip 16312 073 24y Fiche 50-272.82/11/17,8212060291
- BP12060302 Forwards LER 82-085/017-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Co of New Jersey B2/11/17 HAYMES.R C Region 1. Office of Director 3pp 14312 107 244 Fiche 50-272,82/11/17.8212040302
- --B212060308 LER 82-085/01T-0 on 821113, due to resulting loss of F & G group buses, automatic starting reature of I & 2 diesel fire pumps disabled Gaussel by planned maint on station power transformer 12 Maint completed & power restored FRAHM. R Public Service Electric & Gas Co of Naw Jersey 82/11/17 Region I. Office of Director ip 14312 110 24X Fiche 50-272,82/11/17.8212060302
- Birl2060309 Forwards LER 82-086/03L-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey B2/11/24 HAYNES.R C Region 1. Office of Director 3pp 16312 086 24% Fithe 50-2/2.B2/11/24.B212060309
- --8212040316 LER 82-086/03L-0 on 821027, five fire barrier genetrations found non-functional during routine surveillance Caused by inadequate sealing Original surveillance procedure failed to specifically identify penetrations Procedure revised FRAHM.R Public Service Electric & Oas Co of New Jersey 82/11/27 Region i. Office of Director ip 16312 087 24x Fiche 50-272,82/11/24.8212040309
- 8212080356 Forwards LER 82-090/01T-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey 82/11/24 HAYNES.R C Region 1. Office of Director 3pp 16353 321. 24x Fiche 50-272.82/11/24.8212080356

- --8212080364 LER 82-090/01T-0 on 821121.video insp of removed fuel assemblies revealed cladding ruptures on element in fuel assembly D-20 Cause unknown Vendor to conduct more detailed investigation FRAHM, R Public Service Electric & Gas Co of New Jersey 82/11/24 Region 1. Office of Director ip 16353 324 24X Fiche 50-272,82/11/24,8212080356
- EP:12140053 Forwards LER 92-098/03L-0 Detailed event analysis encl PIDURA.H J Public Service Electric & Gas Co of New Jersey B2/11/24 H4YNES.R C Region i. Office of Director 3pp 16409 286 24% Fishe 50-272.B2/11/24.B212140053
- --8212140040 LER 82-088/03L-0 on 821109, fire observed in fire detection instrumentation panel 1FP3 Panel de-energized & several fire detectors rendered inoperable Caused by failure of panel alarn buzzer relay Relay replaced FRAHI, R Public Service Electric & Gas Co of New Jersey 82/11/24 Region 1, Office of Director ip 16408 289 24X Fiche 50-272, 82/11/24 8212140053
- 9712140076 Forwards LER 82-087/03L-0 Detailed event analysis encl HIDURA:H J Public Service Electric & Gas Co of New Jersey 82/11/24 HAYMES:R C Region 1. Office of Director 3pp 16408 247 24X Fiche 50-272.82/11/24.8212140076
- -8212140082 LER 82-087/03L-0 on 821109, during refueling operations, alarms indicated fire protection deluge aus had been actuated No apparent cause determined Charcoal filters involved replaced FRAHM. Public Service Electric & Gas Co of New Jersey 82/11/24 Region 1, Office of Director ip 16408 250 24X Fiche 50-272,82/11/24,8212140076
- 8:12060195 PND-1-82-076 on 821122, through-wall leak discovered in sec water piping associated w/component cooling water HX Caused by corrosion Corrective actions still under development TRIPP, L E , KEIMIG, R Region 1, Office of Director 82/12/01 ip 16313 054 24X Fiche 50-272,82/12/01.8212060195
- BP12220330 Forwards LER 82-091/01T-0 Detailed event analysis enc)
 M1BURA.H J Public Service Electric & Gas Co of New Jersey
 B2/12/08 HAYNES.R C Region 1. Office of Director 3pp
 16517 184 244 Fiche 50-276, 82/12/08. 8212220300
- --8212220310 LER 82-091/01T-O on 821130, leakage discovered from weld on svc water piping to component cooling HX 12 Caused by degradation of weld 2 similar joints due to type of filler metal used 2 corrosive environ of svc water sys FRAHM.R Public Service Electric & Gas Co of New Jersey 62/12/09 Region 1: Office of Director 1p 16517 187 24X Fiche 50-27P, 82/12/08. 8212220300
- DOCKET 50-275 DIABLO CANYON NUCLEAR PONER PLANT, UNIT 1

 F Security, medical, energency & fire protection plans
- G:12060251 Forwards IE Insp Rept 50-275/82-36 on 821003-30 No noncompliance noted BIEHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/22 CRANE, P A Pacific Gas & Electric Co Ppp 16312 279 24X Fiche 50-275,82/11/22,8212040251
- --8212040261 IE Insp Rept 50-275/82-36 on 821003-30 No noncompliance noted Major areas inspected surveillance testing physical security maint. TMI task action plan items emergency drill & design changes & mod CARLSCR. J D . MENDONCA. M M . KIRBCH. D F Division of Resident, Reactor Project & Engineering Programs 82/11/19 5pp 16312 283 24X Fiche 50-275,82/11/22,8212060251
- 8212080057 Releases public version of revised emergency plan implementing procedures FELTON, JM Division of Rules and Records 82/12/02 Document Management Branch 1p 16367 214 24X Fiche 50-275,82/12/02, 8212080057
- --8212080063 Forwards public version of revised emergency plan implementing procedures, including Procedures EP OP-18A reloss of charging & EP OP-18B reloss of normal letdown CRANE.P A Pacific Gas & Electric Co 82/11/24 ENGELKEN.R H Region S. Office of Director 2pp 16367 215 24X Fiche 50-275,82/12/02.8212080057
- --8212080071 Public version of revised emergency plan implementing procedures including Procedures EP 0P-18A re loss of charging EP 0P-180 re loss of normal lettoum & EP R-1 re personnel injury or illness (radiologically-related) THORMBERRY. R C Pacific Gas & Electric Co 82/11/03 55pp 16367 217 24% Fiche 50-275,82/12/02,8212080037

- 8212130070 Confirms permanent & Interim emergency operations facilities info per 821202 verbal request Permanent & Interim sites located 11 7 miles from facilities Interim structure complete & successfully tested CRANE, P A Pacific Oas & Electric Co 82/12/07 KNIGHTON, O W Licensing Branch 3 ip 16391 164 24X Fiche 50-275, 82/12/07, 8212130070
- BP12280160 Forwards "Verification of Fire Protection Provided for Auxiliary Feedwater Sys. Control Room Ventilation & Pressurization Sys. Safety-Related Portion of 4160-Volt Flectrical Sys." Number 18. Revision O KRECHTING, J E Stone & Webster Engineering Corp 82/12/15 DENTON: HR Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5. Office of Director MANEATIS. G A Pacific Gas & Electric Co 1p (6563-124-24X Fiche 50-275,82/12/15,821280160)
- --8212280163 "Verification of Fire Protection Provided for Auxiliary Feedwater Eys, Control Room Ventilation & Pressurization Sys. Safety-Related Portion of 4160-Volt Electrical Sys." SESTAK.F. Stone & Webster Engineering Corp. 82/12/15 16pp 16563 126 24% Fiche 50-275, 82/12/15.8212280160
- Bi:12220217 Forwards application to amend License DPR-76.changing lech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 52-17 & 82-23
 CRANE, P A Pacific Gas & Electric Co 82/12/17 DENTON.H R
 Office of Nuclear Reactor Regulation, Director ip 16503 Oil 24X
 Fichs 50-275.82/12/17.8212220217
- --8212220225 Application to amend License DPR-76, changing Tech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures

 MANEATIS, 0 A Pacific Gas & Electric Co 82/12/17 2pp
 18803 012 24X Fiche 50-275, 82/12/17, 821222021/
- --8212220229 Proposed Tech Spec changes modifying audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 82-17 & 82-23

 * Pacific Gas & Electric Co. 82/12/17 1p 16503 014 24X
 Fiche 50-275.82/12/17.8212220217
- Q Adjudicatory correspondence
- B?12060104 Order extending time until 821208 for Commission to act to review NRR Director 820922 denial of Joint Intervenors 10CFR2 206 petition CHILK.S J Office of the Secretary of the Commission 82/12/01 Commissioners ip 6314 362 24X Fiche 50-275,82/12/01. 6212060104
- B2120900BA Motion for extension of time until 821220 to file brief apposing intervenor exceptions to ASLB decision Time extension necessary due to meetings on east coast (ertificate of Svc encl CRANG.P A Pacific Oas & Electric Co 82/12/06 Atomic Safety and Licensing Appeal Panel 4pp 16057 188 24x (iche 50-275, 92/12/06, 8212070084
- GP12070097 Order extending time until 821215 for Commission to act to 1eview NRR Director 820922 denial of Joint Intervenors 10CFR2 204 petition CHICK'S J Office of the Secretary of the Commission 82/12/07 Commissioners ip 16357 283 24X Fiche 50-275,82/12/07, 8212090097
- BP12150051 Order extending time until B21222 for Commission to act to review NRR Director B20922 denial of Joint Intervenors 10CFR2 206 petition CHILK, S.J. Office of the Becretary of the Commission 82/12/14 Commissioners 1p 16422 323 24X Fiche 50-275,82/12/14, 1212150051
- Bil2150057 Order extending time until 821221 for Commission to respond to ALAB-681 CHILK: S J Office of the Secretary of the Commission 82/12/14 Commissioners ip 16431 007 24X Fiche 50-275,82/12/14.
- 82/12220374 Brief opposing util & NRC 821108 briefs supporting exceptions to ASLB requirement that NRC receive FEMA finding of adequacy of State of CA radiological emergency response plan before plant can be litensed W/Certificate of Svc BROWN-H H California, State of BROWN-H H Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/12/20 Atomic Safety and Licensing Appeal Panel 9pp 16517 251 24X Fiche 50-275,82/12/20,8212220374

- 8212280123 Response in opposition to Joint Intervenors briefs in support of exceptions to ASLB 820831 order authorizing NRR director to issue full power DL No new arguments placed before ASLAB Centificate of Syc enci NORTON.B Pacific Cost & Electric Co NORTON.B Norton, Burke, Berry & French 82/12/20 Atomic Safety and Licensing Appeal Panel 40pp 16564 140 24% Fiche 50-275,82/12/20.8212280123
- 8212280288 Brief in apposition to util t NRC briefs in support of exception to 820831 (nittal decision Desire for more expeditions licensing is patently inadequate excuse for ignoring regulatory stok Certificate of Svc encil REYNOLDS, J R Joint Intervenors-Diable Canyon REYNOLDS, J R Center for Law in the Public Interest 82/12/20 Atomic Sefety and Licensing Appeal Panel 229p 14961 334 24x Fishe 50-275,82/12/20,8218280288
- GP122J0360 Order extending time, until 821229, for Commission to decide whether to review NRR Director 820922 denial of Joint Intervenors request for action filed under 10CFR2 206 CHILK, S. J. Office of the Secretary of the Commission 82/12/22 p. 16311 165 24X Fiche 50-275.02/12/22, 8212230360
- 8212270217 Memorandum & Order CLI-82-39, rolling on three questions certified on 820716 Issuance of suspension order & stablishment of independent design verification program not intended to deprive adjudicatory boards of jurisdiction CHILK, S. J. Office of the Secretary of the Commission 82/12/23 7pp 16536 206 24X Fiche 50-275,82/12/23,8212270217

Il General correspondence

- 8212130375 Responds to 821025 request for add1 info on design verification program Util corrective action program ger SECY 82-414.principal reason for determining that design verification effort goes beyond Commission order LISEMHUT.D 0 Division of Licensing 82/11/24 SIEGEL, 8 M Toward Utility Rate Normalization 3pp 16412 085 24X Fiche 50-275.82/11/24.8212130395
- --8211020166 Requests elaboration on encl newspaper article re mod & investigation program at facility
 SIECEL 8 H Affiliation Unknown 82/10/25 DENTON, H NRC No Detailed Affiliation Oiven 3pp 16412 088 24X
 Fiche 50-275,82/11/24.8212130375
- GP12170373 Advises that 821115 ltr to Chairman Palladino re seismic qualification of turbine bldg & recommendation for independent analysis by BNL will be provided to other Commissioners
 EISENHUT, D 9 Division of Licensing 82/12/08 ROESET, J Roesset. J M 4pp 16478 085 24X Fiche 50-275.62/12/08, 82/2170373
- --8212170378 Clarifies 821110 statements re seismic qualification of turbine bldg Recommendation for independent analysis by BNL. Justified Transmittal of clarifications to other Commissioners requested ROESSET. J H. Roesset. J H. 82/11/15 PALLADING, N. J. Commissioners 1p 14478 088 24X Fiche 50-275,82/12/08,8212170373

f Operating license stage documents & correspondence

- 8212030190 Forwards Sections 2 1 5, "Intake Structure," 2 2 2, "Small Bore Piping," 2 2 4, "Small Bore Pipe Supports" & 2 6 3, "Instrumentation Tubing & Tubing Supports," to Phase I final rest for design verification program CRANE, P A Pacific Cas & Electric Co 82/11/19 EISEMHUT, D @ Division of Licensing 129pp 14304 118 24X F(che 50-275, 82/11/19.8212030190
- 8212030253 Board Natification 82-105 forwards RH Volimer 820930 memb to DG Eisenbut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT.D 0 Division of Licensing 82/11/24 PALLADINO.N J. GTLINSKY.V V. AHEARNE.J F. Commissioners 2pp 16316 240 24% Fiche 50-000,82/11/24,8212030253
- --8212030265 Discusses alleged design deficiency in ABME Code Class I piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Dfc of investigations will assist in evaluation VOLLMER.R H Division of Engineering 82/09/30 EISENHUT.D 0 Division of Licensing 5pp 16316,247 24X Fiche 50-000, 82/11/24,8212030283

- 8212060340 Board Notification 82-120 forwards Teledyne Engineering Sv., B21112 rept, RL Cloud Associates 821105 ltr w/open items, 85W B21112 repts & RF Reedy, Inc 821112 rept w/open items re design verification program, Phase I EISEKHWI, D 0 Division of Licensing 92/11/24 PALLADING, N . OILINSKY, V . AHEARNEJ J Commissioners 4pp 16323 142 24X Fiche 50-275, 82/11/24, 8212060340
- 8P12270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREQ-0784. Chapter 10 as RS II > all documents pertaining to reactor tooling methods Forwards documents listed in app FELTON. J M Division of Rules and Records 82/11/26 SHOULY, S (Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418
- --82:1050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK.T M Assistant Director for Licensing 62:09:24 Division or Licensing 1p 16549 278 24X Fiche 50-000.82/11/26, 82:2270418
- B212010190 Submits status update on Wiegel & Seed repts re effects of storn & tsunami waves & scismic events on facility break—water Final repts for ongaing analysis re potential wave forces & request for fech Spec amend will be sent Dec 1982 CRANE, P A Pacific Gas & Electric Co 82/11/29 KNIGHTON, G Wilcensing Branch 3 2pp 16258 085 24X Fiche 50-275.82/11/29, 8212010190
- 8/1203019i Submits revised schedule for upgrading Class IE plant vent radioactive gas & particulate monitoring sys.RE-14 A & B & 28 A & B Work will be completed by 830214 contingent on iesuits of qualification test
 (RANE.P A Pacific Gas & Electric Co 82/i1/29 KNIGHTON.G W Licensing Branch 3 to 16306 269 24X Fiche 50-275.82/11/29, 8212030191
- G212080697 Forwards list of drawings & data needed for BNL independent analysis, per SECY-82-414 Notification requested if info cannot be provided within 2 was of receipt of itr Analysis not substitute for design efforts now underway FISENHUT, D 0 Division of Licensing 62/12/01 CRANE, P A Pacific Cas & Electric Co 6pp 16372 346 24X Fiche 50-275, 82/12/01, 8212080697
- Gi'l2150217 Notification of cancellation of 821209 meeting w/util, Bechtel & contractor in San Francisco.CA to discuss status of design verification program Phases I & II BCHIERLING.H E Licensing Branch 3 82/12/01 KNIGHTON, G W Licensing Branch 3 4pp 16447 022 24X Fiche 50-275,82/12/01, 8212150217
- B212150223 Notification of B21209 meeting w/util.Bechtel & contractor in Ban Francisco.CA to discuss status of design verification program Phases 1 & II SCHIERLING.H E Licensing Branch 3 B2/12/01 KNIGHTON, 0 W Licensing Branch 3 4pp 16447 O18 24X Fishe 50-275, B2/12/01, G212(5022)
- 9/12230306 Provides response to 821123 ltr requesting S&W document, change in format of engineering open item file sys & more camplete description of 27 files opened to date
 JOHNBON, A E feledyne Engineering Services 82/12/01 HUBBARD, R & MHB Technical Associates 2pp 16507 319 24X
 Fiche 50-275,82/12/01.8212230306
- 62:12070235 Forwards schedule info for 821208 meeting on facility design verification program per request Info contains estimated schedules for fuel loading, lou power testing & full power operation Completion based on three-step licensing approach CRANE.P A Pacific Oas & Electric Co 82/12/02 EISENRUT.D @ Division of Licensing 3pp 16327-317 24X Fiche 50~275,82/12/02,0212070235
- GP:12170038 Requests changes to QA program, Revision 1 scope of responsibility Project completion effort responsibility thould be clearly defined EIBENHUT. DG Division of Licensing 62/12/02 CRANE, PA Pacific Gas & Electric Co 5pp 16478 008 24x Fiche 50-275.82/12/03, 6212170038
- BY12100206 Requests add1 info re BNL analysis of containment annulus structure COMPER.W E , CHIN.S L Teledyne Engineering Services 82/12/03 SCHIERLING.M E Office of Nuclear Reactor Regulation, Director 1p 16377-110 24X Fiche 50-275.82/12/03.8212100206
- 60:12:100271 Requests info from BNL analysis re containment annulus structure COMPER.W E , CHIN.S L Teledyne Engineering Services 82/12/03 SCHIERLING.W E Office of Nuclear Reactor Regulation, Director ip 16376-273 24X Fiche 50-275.82/12/03.8212100271

- 8,12140473 Requests approval of encl three-step licensing proposal for restoration of low power testing authority & issuance of full power license, presented at 821110 meeting w/NRC CANE, P A Pacific Gas & Electric Co 82/12/03 EISENHUT, D G Division of Licensing 19pp 16403 336 24X Fiche 50-275,82/12/03, H212140473
- GP12080479 Concurs w/licensee 021203 request for restoration of low power license & stopuise licensing schedule to full power Schedule for proposed 3-step licensing & transmittal forms encl COOPER, W E Teledyne Engineering Services 82/12/06 EIGENHUT, D Q Davisson of Licensing 3pp 16380 215 24X Fiche 50-275,82/12/06.
- 8/12130281 Board Notification 82-125 forwards info re recent ACRS evaluation of PWR flow blockage during natural circulation EISENHUT, D.G. Division of Licensing 82/12/06 PALLADINO, N., GILINSXV, V. AMERANE, J. Commissioners 3pp 16418 251 24X (-1616 50-000, 82/12/06, 821213028)
- --8212130289 Requests all PWR licensing & appeal boards be informed of ACRS evaluation of flow blockage during natural circulation MATTSON,R J Division of Systems Integration (post 811005) 82/12/03 EISENHUT.D Division of Licensing App 14418 254 24% Fiche 50-275,82/12/06.8212130281
- --0212130293 Advises that encl ACRS 820907 memo is being made publirly available per House Committee on Interior & Insular Affairs request FRALEY, R F ACRS Advisory Committee on Reactor Safeguards 82/11/10 DETOON, H R Office of Nuclear Reactor Regulation, Director ip 16418 260 24X Fiche 50-275,82/12/06.82121,30281
- --8211230137 Comments on extent of acceptance of proposals relactions & resolution plans for integral systesting & TMI Action Item II K 3 30 Owners must resolve issues expeditiously to avoid licensing issue delays

 DEMION.H R Office of Nuclear Reactor Regulation, Director B2/11/16 PARKER.K 0 Duke Power Co 5pp 16418 274 24Y

 Ficha 50-275, 82/12/06. 8212130281
- -H212130305 Comments on NRC program to address concerns w/thermal hydraulic behavior of 8&W plants during transients & accidents GERDA & SRI-II facilities as now proposed will be inadequate to address NRC concerns
 SHEMMON.P ACRS Advisory Committee on Reactor Safeguards
 82/10/13 DIRCKS, W J Office of the Executive Director for Operations 1p 16418 278 24X Fiche 50-275,82/12/06,8212/302R1
- 8:12830041 Board Notification 82-127 forwards info ie status of activities performed under independent design verification program EIBERHUT, D 0 Division of Licensing 82/12/06 PALLADIND, N , GILINSKY, V , AHEARNE, J F Commissioners 17pp 16945 001 24 Fiche 50-275, 82/12/06, 8212230041
- 97)2140276 Forwards Revision O to "Independent Design Verification Program Boils Outdoor Water Storage Tanks," Interim Technical Rept 16
 DENISON,E Robert L Cloud Associates, Inc 82/12/08 DENION,H R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director MANEATIS,G A Pacific Gas & Electric Co 19 16404 272 24X Fiche 50-275,82/12/08,8212140276
- --0212140277 Revision O to "Independent Design Verification Program Soils - Outdoor Water Storage Tanks," Interim Technical Rept 16 MONEILL.R. DENIGON.E Robert L Cloud Associates, Inc. 82/12/08 46pp 16404 274 24% Fiche 50-275,82/12/08.8212140276
- 8:12230045 Board Notification 82-128 forwards info re design verification program EISERHUT.D 0 Division of Licensing 82/12/08 PALLADINO,N J GILINSKY,V, AHEARNE,J F Commissioners App 16546 001 24X Fiche 50-275,82/12/08,8212230045
- 8412220017 Staff requirements memo re 821209 meeting on Phase II of design verification program per SECY-82-414 Commission Umanimously approved recommendations replacing Figure 3 w/ Figure 1; per util 821203 ltr CHILK, S J Office of the Secretary of the Commission 82/12/09 DIRCKS J Office of the Secretary of the Commission 82/12/09 116529 094 24X Fiche 50-275,82/12/09,8212220017
- BP12230049 Board Notification 92-125A forwards info re PWR flow blockage Info supple Board Notification 82-125 EISENHUT, D 9 Division of Licensing 82/12/09 PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 3pp 16545 338 24X Fiche 30-000, 82/12/09, 8212230049

- --8212230058 Forwards Fraley 821207 memo re flow blockage by steam during natural circulation in PWRs
 EISENHUT.D & Division of Licensing 82/12/07 LAINAS.G
 Assistant Director for Departing Reactors 1p 16545 341 247
 Fiche 50-000,82/12/09.8212230049
- GPI 2150195 Forwards Revision 0 to "Verification of Pressure, Temp. Humidity & Submergency Environ Used for Safety-Related Equipment Spec ," Interim Technical Rept 14 & Open Item Rept Forms 9028 & 9029 SESTAM, F. Stone & Webster Engineering Corp. 62/12/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. A. Region 5. Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 3pp. 16430 268 24% Fiche 50-275.82/12/10,8212150195
- --8212150200 Revision 0 to "Verification of Pressure, Temp, Humidity & Submergency Environ Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room, "Interim Technical Rept 14
 SESTAK, F. Stone & Webster Engineering Corp. 82/12/06. 38pp. 16430. 272 24X Fiche. 50-275, 82/12/10,8212150195
- 8212210014 Forwards current design details & data in response to NRC G21201 ltr & EECY-82-414 BNL should elaborate on how info will be used Requests meeting w/NRC & BNL by 821222 to discuss matl CRANE.P A Pacific Oas & Electric Co 92/12/10 EISENHUT.D G Division of Licensing 8pp 16490 148 24X Fiche 50-275.82/12/10, 0212210014
- BP12150164 Forwards "Diable Canyon Unit 1 Independent Design
 Verification Program HVAC Duct & Supports Interim Technical
 Rept 15 Revission 0 " Interim Technical Rept 14 will be
 issued by S&W
 DENISON.E Robert L Cloud Associates, Inc 82/12/13 DENION, H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN, R H
 Region 5, Office of Director MANEATIS, O A Pacific Oas & Electric
 Co 1p 16430 198 244 Fiche 30-275, 82/12/13, B21250164
- --G212150170 "Diable Canyon Unit 1 Independent Design Verification Program HVAC Duct & Supports Interim Technical Rept 15, Revision 0 " MANSON, DENISON.E Robert L Cloud Associates, Inc B2/12/10 52pp 16430 200 24X Fiche 50-275, 82/12/13, 82/2150164
- 8212210002 Forwards "Pressurizer Safety & Relief Line Evaluation." summary rept Summary rept CRANE.P A Pacific Gas & Electric Co 82/12/13 DENTON.H R Diffice of Nuclear Reactor Regulation, Director 2pp 16485 276 24X Fiche 50-275,82/12/13.8212210002
- 8212210005 "Pressurizer Bafety & Relief Line Evaluation," summary rept BMITH.L C , HAZLETT, T L , CHANG.K C Pacific Gas & Electric Co AM-56A-2534 82/11/30 7ipp 16485 278 24K Fiche 50-275,82/12/13.8212210002
- 8/12/140278 Forwards agenda for 82/12/14-15 meetings in San Francisco.CA for technical discussion of RL Cloud & Associates requests for info COOPER.W E Teledyne Engineering Services 82/12/14 NRC No Detailed Affiliation Given 3pp 16402 107 24% Fiche 50-275.82/12/14.82/12/140278
- G212210037 Provides Natl Register of Historic Places eligibility notification of plant Archeological Site SLO-2
 * Interior, Dept of, National Park Service 92/12/14 KERRIGAN, J D NRC No Detailed Affiliation Given 2pp 16470 212 24X Fiche 50-275, 82/12/14, 8212210037
- 8212220434 Board Notifications 82-125 & 82-125A forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission EIBENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 4pp 16523 103 24X Fiche 50-000.82/12/14,8212220434
- --8212220438 Provides suppl to 820907 memo re flow blockage by steam during natural circulation in PMRs Accident analyses upon which operating procedures are based give no credit for condensation by repressuritation ETHERINOTON. E ACRS Advisory Committee on Reactor Bafeguards 82/12/06 SHEWMON.P 0 ACRS Advisory Committee on Reactor Safeguards 3pp 16523 IS1 24X Fiche 50-275.82/12/14, 8212220434
- 9212220440 Board Notifications 92-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of FMRs Results do not adversely impact present position on reliance on natural circulation NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X fiche 50-000, 82/12/14, 8212220440

- --8212220448 Forwards suppl to H Etherington 620907 memo re flow blockage by steam during natural circulation in PNRs FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation. Director MNOGUE, R Office of Nuclear Regulatory Research, Director Ip 16523 164 24X Fiche 50-275,82/12/14,8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NBVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14-82/2220461
- --U212220475 Requests that all Westinghouse & C-E PWR licensing boards be notified of results of Bemiscale S-UT-8 tests Sufficient info to draw conclusion unavailable MATTSON.R J Division of Systems Integration (post 611005) 82/11/23 NRC - No Petailed Affiliation Given 4pp 16523 176 24X Fiche 50-275,82/12/14,8212220461
- 8212220482 Board Notification 82-124 forwards RJ Mattson 821123 memo ro Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed EISECHUT, D.G. Division of Licensing 82/12/14 PALLADINO, N.J., GILINSKY, V., AHEARNE, J.F. Commissioners 4pp 16523 199 24X Fiche 50-000, 82/12/14, 82/2220482
- G21R200080 Forwards, "Diablo Canyon Unit 1 Independent Design Verification Program Piping-Addi Bamples," Revision O. Interim Tachnical Rept 17 DENISON-E Robert L Cloud Associates, Inc. 82/12/15 DENION.H R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Defice of Director MANEATIS,Q A Pacific Qas & Electric Co. 1p. 16470 187 24X Fiche 50-275.82/12/15,8212200080
- ---8212200095 "Diable Cangon Unit 1, independent Dasign Verification Program Piping-Addl Samples," Revision 0, Interim Technical Rept 17 DENISON,E Robert L Cloud Associates, Inc. 82/12/14 75pp 16470 191 24X Fiche 50-275, 82/12/15,8212200080
- 80/12220217 Forwards application to amend License DPR-76, changing lech Specs to modify audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 62-17 & 82-23
 CRANE, P A Pacific Oas & Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16503 011 24X Fiche 50-275, 82/12/17, 8212220217
- --8212220225 Application to amend License DPR-76, changing Tech Specs to modify audit frequency from 24 to 12 months for emergency to security plans to implementing procedures MAKEATIB, CA Pacific Cas & Electric Co 82/12/17 2pp 16503 012 24X Fichs 50-275, 82/12/17.8212220217
- --8212220229 Proposed Tech Spec changes modifying audit frequency from 24 to 12 months for emergency & security plans & implementing procedures per Generic Ltrs 82-17 & 82-23 * Pacific Gas & Electric Co 82/12/17 1p 16503 014 24X Fiche 50-275,82/12/17,8212220217
- 86'12270371 Forwards add1 info re mechanical & HVAC equipment outdoor storage tanks & electrical equipment & Instrumentation per Phase I final rept for design vorification program Results for large & small bore plying & pipe supports updated CRANE.P A Pacific Cas & Electric Co 82/12/17 EISENHUT, D C Division of Licensing 120pp 16535 347 24X Fiche 50-275, 62/12/17,8212270371
- 8212280078 Forwards Piping Problems 8-116,8-117 & 8-118 to enable UNL to perform analyses Meeting w/NRC & BNL scheduled for 821221 H/o enc! CRANE.P A Pacific Gas & Electric Ca 82/12/17 EISENHUT.D O Division of Licensing 2pp (6564 227 24% Fiche 50-275,82/12/17,8312280078
- 8212270276 Forwards Interim Technical Repts 17.20,21 & 22
 KRECHTING.J E Stone & Webster Engineering Corp 82/12/20
 DENTON, H R Office of Nuclear Reactor Regulation, Director
 ENGELMEN.R.H Region 5. Office of Director MANEATIS.Q A Pacifi
 Gas & Electric Co 2pp 14535 257 24X Fiche 50-275.82/12/20,
 8212270276
- --B212270279 Interim Technical Rept 19. Revision O. "Verification of Post-LOCA Portion of Radiation Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room Vent & Pressurfiation Sys."

 SESTAK.F. Stone & Habiter Engineering Corp. STRATOULY.D. Teledyne Engineering 82/12/16. 21pp. 16535-262-24X. Fiche 50-275,82/12/20,8212270296

- 8212270301 Interim Technical Rept 20. Revision 0, "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressuriation Sys" SEBTAK, F. Stone & Webster Engineering Corp. STRATOULY, D. Teledyne Engineering Services. 82/12/16. 23pp. 16535-283. 24X Fiche 50-275.82/12/20.8212270296
- B212270310 Interim Technical Rept 21, Revision 0, "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room Ventilation & Pressuriation Sys "
 SESTAK, F. Stone & Webster Engineering Corp. STRATOULY, D.C. Teledyne Engineering Services 82/12/15 1App. 16535-306 24X Fiche 30-275, B2/12/20, B2/2270276
- 8212270312 Interim Technical Rept 22. Revision 0, 'Verification of Mechanical/Nuclear Portion or Auxiliary Feedwater Sys " SESTAKIF Stone & Webster Engineering Corp STRATOULY. D C Teledyne Engineering Services 82/12/17 25pp 16535-323 21% Fiche 50-275, 82/12/20. 8212270296

1 -

- GP12230210 Requests temporary relief from requirements of Tech Spec 4 9 7 for 120 days in order to effect mods to fuel handling bldg CRANE.P A Pacific Gas & Electric Co B2/12/21 KNIGHTON.G W Licensing Branch 3 7pp 16510 313 24X Fiche 50-275.82/12/21, 8212230210
- GP12230278 Forwards Revision 2 to "Diable Canyon Project QA Program," in response to DO Eisenhul 821202 request CRANE,P A Pacific Gas & Electric Co 82/12/21 KNIGHTON,C W Licensing Branch 3 ip 16507 051 24X Fiche 50-275,82/12/21, 0212230278
- B212280475 Board Notification 82-132 forwards info items re status of activities performed under design verification program Submittal includes RF Reedy, Teledyne, SEW & RL Cloud Assoc repts
 LISEMHUT.D G Division of Licensing 82/12/22 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 4pp 16591 001 24% Fiche 50-275,82/12/22.8212280495
- 8P12290458 Forwards "Verification of High Energy Line Breaks & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation & Pressuritation Sys." Interim Technical Rept 23. Revision O KRECHTINO.JE Stone & Webster. Inc 82/12/22 DENTON.H R Office of Nuclear Reactor Regulation. Director ENGELKEN.R H Region 5. Office of Director MANEATIS.O A Pacific Gas & Electric Co Ip 16585 108 24X Fiche 50-275,82/12/22.8212290458
- ~~8212270462 "Verification of High Energy Line Breaks & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurfiation Sys." Interim Technical Rept 23.Revision 0
 SEBTAK.F Stone & Webster, Inc 82/12/20 20pp 16585 109 24x
 Fiche 50-275,82/12/22.8212290458
- 8"12290205 Forwards draft interim technical rept, "Phase II Addl Sample & Addl Verification "Rept will be issued in approved form after incorporation of comments Recommends Jan 1983 meeting to aid in preparing presentation on Phase II efforts COOPER.N E Teledyne Engineering Services 82/12/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ENGELKEN.R H Region 5. Office of Director MANEATIS.O A Pacific Gas & Electric Co 2pp 16578 148 24X Fiche 50-275,82/12/23.8212290205
- --8212270207 "Phase II Addl Sample & Addl Verification," draft interim technical rept SESTAK, F. Stone & Webster Enganeering Corp. 82/12/23 35pp 16578 150 24X Fiche 50-275,82/12/23,8212270205
- 8212270231 Forwards Interim Technical Repts 24,25 & 26, "Verification of 4160-Volt Barety-Related Electrical Distribution Sys Design Review," "Verification of Auxiliary Feedwater Bys Electrical Design" & "Verification of Control Room "
 KRECHTING.J E Stone & Webster Engineering Corp 82/12/23
 DENTON.H R Uffice of Nuclear Reactor Regulation, Director ENGELMEN, R H Region 3, Office of Director MANKATIS.G A Pacific Gas & Electric Co 1p 16589 236 24X Fiche 50-275,82/12/23, U212270231
- --8212270237 "Verification of Auxiliary Feedwater Sys Electrical Design,"
 Interim Technical Rept 25.Revision 0
 SEBTAK.F Stone & Webster Engineering Corp STRATOULY, D C
 Teledyne Engineering Services 25 ROO 82/12/21 17pp
 14587 238 24X Fiche 50-275,82/12/23.8212270231

- --0212270243 "Verification of 4160-Volt Safety-Related Electrical Distribution Sys." Interim Technical Rept 24, Revision O SESTAM, F Stone & Mebster Engineering Corp STRATOULY, D C Teledyne Engineering Services 24 ROO 82/12/21 21pp 16589 257 24X Fiche 50-275, 82/12/23, 8212290231
- --8212270250 "Verification of Control Room Ventilation & Pressurization Sys Electrical Dasign." Interim Technical Rept 26. Revision 0 SESTAK.F Stone & Webster Engineering Corp STRATQULY.D C Teledyne Engineering Services 26 ROO 82/12/21 20pp 14599 278 24X Fiche 50-275,82/12/23,8212270231
- @ Inspection reports. IE Bulletins & correspondence
- 87:08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants "Svc list encl
 DEVGUNO, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 14462 163 24x Fiche 50-000, 82/10/28, 8208190240
- 8,'08190245 IE Info Natice 82-42, "Defects Observed in Panasonic Model (101 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 244 Fiche 50-000, 82/11/05,8208190245
- G212040353 Forwards IE Insp Rept 50-275/62-31 on 821012-15 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/11/15 CRAME.P A Pacific Gas & Electric Co 2pp 14311 082 24X Fichs 50-275.82/11/15.8212040353
- --B212060364 IE Insp Rept 50-279/82-31 on B21012-15 No noncompliance noted Major areas inspected revised program for handling design changes & mods, implementation procedures, interviews w/licensee & Bechtel personnel & drawing control program MORRILL,P J. CARLSON. J D. KIRSCH. D F. Division of Resident, Reactor Project & Englineering Programs 82/11/15 App 16311 084 24X Fiche 50-275,82/11/15,8212060353
- G7:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x fiche 50-000, 82/11/18, 8208190251
- 8212060251 Forwards IE insp Rept 50-275/82-36 on 821003-30 No noncompliance noted BISHOP:TW Division of Resident, Reactor Project & Engineering Programs 82/11/22 CRANE.P A Pacific Cas & Electric Co 2p 16312 279 244 Fiche 50-275,82/11/22,8212060251
- --8212050261 IE Insp Rept 50-275/82-36 on 821003-30 No noncompliance noted Major areas inspected surveillance testing physical security maint. TMI task action plan items, emergency drill & design changes & mod CARLSON, JD , MENDONCA, M M , KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/19 5pp 16312 283 24X Fiche 50-275, 82/11/22,8212060251
- BP12060155 Discusses 820208 ltr re adequacy of NUREO-0842, "Insp Rept of Preliminary Rept.Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units I & 2 " Questions posed through 820423 Ofc of Inspector & Auditor review answered PALLADING, N J Commissioners B2/11/23 UDALL, M K House of Rep , Interior & Insular Affairs 2pp 16325 232 24X (iche 50-275, 82/11/23, 8212060155
- --8212060164 Discusses 820204 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept.Seismuc Reverification Program at Diablo Canyon Nuclear Power Plant. Units 1 & 2 " Questions posed through 820423 Ofc of Inspector & Auditor review answered PALLADINO.N J Commissioners 82/11/23 OTTINOER.R House of Rep . Energy & Commerce 2pp 16325 234 24X Fishe 50-275.82/11/23.8212060155
- --9212060177 Submits review of NUREO-0862. "Insp Rept of Preliminary Rept.Seismic Reverification Program at Diablo Ganyon Nuclear Power Plant, Units 1 & 2." per Udall 620208 & Ottinger 820204 requests Investigation conducted in 2 phases CUMMINGS. J. Office of Inspector & Auditor 82/07/30 PALLADINO, N. Commissioners 7pp 16928 236 24X Fiche 50-275, 82/11/23, 8212060155
- 8POBI90256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Byo list encl DEYDUNG:R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256

- B212130169 Forwards IE Insp Rept 50-275/82-35 on B21025-29 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Enganeering Programs 82/11/26 CRANE.P A Pacific Gas & Electric Co App 16396 089 24% Fich
- --8212130171 IE Insp Rept 50-275/82-35 on 821025-27 No moncompliance noted Hajor areas inspected const & mod activities.including site tour-mods to piping & electrical raceway supports BURDOIN, J F , ZWETZIG, O B Division of Resident, Reactor Project & Engineering Programs 82/11/26 App 16396 093 24X Fiche 50-275, 82/11/26, 8212130169
- B./08190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COSB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Defice, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190241 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Backets " Svc list enc! JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fichs 50-000.82/12/03.8208190261
- B:/08190267 IE Info Notice B2-49. "Correction for Sample Conditions for Air & Qas Monitoring " Syc list encl
 DEYDUNG,R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- 8708190248 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Helays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 30-000: 82/12/20.8208190268
- R Periodic operating reports & related correspondence
- GP12290214 Forwards monthly operating rept for Oct 1982 THORNBERRY,R C Pacific Gas & Electric Co 82/11/02 Division of Data Automation & Management Information lp 16578 190 24X fiche 50-275, 82/11/02, 8212270214
- --8212270218 Monthly operating rept for Oct 1982 KCLLY,W J Pacific Gas 7: Electric Co 82/11/01 4pp 16578 191 24X Fiche 50-275,82/11/02,8212270214
- BP12060047 Forwards "Diablo Canyon Verification Program," Semimenthly Rept 26 for B21109-1122 CRAKE.P A Pacific Oas & Electric Co B2/11724 DENTON,H R Office of Nuclear Reactor Regulation. Director ENGELKEN,R H Hagion 5. Office of Director 1p 16313 205 24X Ficha 50-275, B2/11/24, 9212060047
- --8212060053 "Diablo Canyon Verification Program," Semimonthly Rept 26 for 821109-1122 * Pacific Oas & Electric Co 82/11/24 64pp 16313 206 24X Fiche 50-275,82/11/24,8212060047
- 8212010206 Forwards "Independent Design Verification Program Semimonthly Status Rept for Nov 1982 " COOPER, WE Teledyne Engineering Services 82/11/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENSELKEN, R.H. Region 5, Office of Director MANEATIS, O.A. Pacific Oas & Electric Co. 1p. 16260-055 24X Fiche 50-275.82/11/26.8212010206
- --8212010211 "Independent Design Verification Program Bemimonthly Status Rept for Nov 1982" * Teledyne Engineering Services 82/11/26 83pp 16260 056 24X Fiche 50-275,82/11/26.8212010206
- --B212010225 Forwards conference notes from B21104 working meeting w/Diablo Canyon Project, util. Bechtel, NRC & Teledyne Engineering re engineering open items generated in electrical & instrument/controls area KRECHTINO.J E Stone & Webster Engineering Corp B2/11/22 DENTON.H R Office of Nuclear Reactor Regulation, Director ENDELKEN.R H Region 5, Office of Director MANEATIS, C A Pacific Oas & Electric Co 22pp 16260 033 24X Fiche 50-275,82/11/26,8212010206

- 8212140281 Forwards "Independent Dasign Verification Program, TES-SM-Det Semimonthly Rept ; CODPER, NE Teledyne Engineering Services 82/12/10 DENTON,H R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director MANEATIS,G A Baltimore Gas & Electric Co 1p 16404 207 24X Fiche 50-275,82/12/10,8212140281
- --8212140285 "Independent Design Verification Program.TES-5M-Dec Seminonthly Rept" * Feledyne Engineering Services 82/12/10 58pp [6404 208 24X Fiche 50-275,82/12/10,821214028[
- BP12;40447 Forwards Semimonthly Progress Rept 22 re independent design verification program for S2[1]2-1210, consisting of Open Item Repts 7003-7004 REEDV, RF RF Reedy, Inc. B2/12/10 DENTON, HR Office of Nuclear Reactor Regulation, Director ENGELECKEN, H Region 5, Office of Director HNREATIS, O. Pacific Gas & Electric Co. 10pp 16405 001 24X Fiche 50-275,82/12/10,82[2]40447
- 8212170217 Forwards "Diablo Canyon Design Verification Program."

 Semimonthly Rept 27 for 92123-1206

 CRANE,P A Pacific Gas & Electric Co 82/12/10 DENTON,H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN,R H
 Region 5, Office of Director 1p 16461 311 24X

 Fiche 50-275.82/12/10.8212170217
- ---8212170223 "Diablo Canyon Design Verification Program," Semimonthly Rept 27 for 621823-1206 * Pacific Oas & Electric Co 82/12/10 Alpy 16461 312 24X Fiche 50-275,82/12/10.8212170217
- 8912290366 Forwards "Gemimonthly Rept 28 Diablo Canyon Verification Program." summarizing progress of technical work for 821207-20 GRANE, P A Pacific Gas & Electric Co 82/12/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ENGELKEN, R H Region 5, Office of Biractor 1p 16587 030 24X Fiche 50-275,82/12/23,8212290366
- --B212290372 "Semimonthly Rept 28 Diable Canyon Verification Program"
 Pacific Oas & Electric Co. 82/12/23 62pp. 16587 031 247
 Fiche 50-275,82/12/23,8212293056
- 8P12290146 Forwards "Diable Cangen Nuclear Power Plant Independent
 Design Verification Program Benimenthly Status Rept for Dec
 1982"
 CDDFER.W E Teledyne Engineering Services 82/12/24 DENTON.H R
 Office of Nuclear Reactor Regulation, Director ENGELKEN.R H
 Region 5, Office of Director MANEATIB.G A Pacific Gas & Electric
 Co ip 16583 101 24X Fiche 50-275.82/12/24.8212290146
- --B212370152 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Status Rept for Dec 1782 " • Teledyne Engineering Services 82/12/24 97pp 16582 102 24% Fiche 50-275,82/12/24.8212270146

B. Reportable occurrences, LERs & related correspondence

- 8P12210116 Forwards LER 82-011/03L-0 SHIFFER.J D Pacyfic Gas & Electric Co 82/11/24 ENGELKEN.R H Region 5. Office of Director 1p 16485 120 24X Fiche.50-275.82/11/24.8212210116
- ~-8212210123 LER 82~011/03L~0 on 921024, steam generator blowdown effluent line flow rate measurement device FR-93 found imperable prior to fuel load Caused by worn motor gear assembly Design change will correct erroneous readings KELLY,W J. Pacific Gas & Electric Co 82/11/24 Region 5, Office of Director 2pp 16485 121 24X Fiche 90-275.82/11/24, 8212210116
- 8212130253 PNS-V-82-004 on 821207. Bureau of Alcohol, Tobacco & Firearms arrested JA Junot & charged Junot u/possession of three destructive devices w/intent to use devices to destroy or damage portions of plant.

 SCHUBTER.H D . SCHAEFER.D.W Region 5, Office of Director 82/12/07 1p 16394 253 24X Fiche. 50-275, 82/12/07, 8212130253
- T Hearing transcripts on mon-antitrust matters
- B212270450 Unofficial transcript of Commission 821208 meeting in Washington DC re discussion & possible vote on facility Phase II reverification program & ASLB certification Pp 1-21
 * Commissioners 82/12/08 24pp 16571 313 24X
 Fiche 50-273,82/12/08.8212270450

- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 f Security, medical, emergency & fire protection plans
- 8912160480 Forwards IE Insp Repts 50-277/82-16 & 50-278/82-16 on 821021-1130 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/12/03 DALTRUFF, S L Philadelphia Electric Co 2pp 16442 087 24X Fiche 50-277, 82/12/03, 8212160480
- --8212160486 Notice of violation from insp on 821021-1130 * Division of Project & Resident Programs 82/12/03 ip 16442 089 24X Fiche 50-277,82/12/03,8212160480
- --8212160491 IE Insp Repts 90-277/82-16 & 50-278/82-16 on 821021-1130 Noncompliance noted failure to meet Teth Spec fire watch requirements BLOUGH, A R , MCCABE, E C Region 1, Office of Director 82/12/03 21pp 16442 090 24X Fiche 50-277.82/12/03,8212160480
- 87:12100036 Responds to NRC 82:1202 telcon questions re design of progressy operations facility Existing shielding sufficient for meeting NUREO-0578 personnel dose criteria, but exceeds Generic Ltr 81-10 criteria
 DALTROFF, S L Philadelphia Flectric Co 82/12/06 STOLZ, J F Operating Reactors Branch 4 3pp 16379 043 24% Fiche 50-277, 82/12/06, 8212100036
- BP12210129 Forwards IE Safequards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No noncompliance noted MARTINIT Division of Engineering & Technical Programs 82/12/04 DALTROFF,8 L Philadelphia Electric Co 2pp 16485 134 24X Fiche 50-277, 82/12/06,8212210129
- G212210134 IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 pn G21016-22 No noncompliance noted Major areas inspected security plans & implementing procedures, security organization mgt & personnel Safeguards info deleted DWRLAP.J M , GODY.A T Division of Engineering & Tochnical Programs G2/11/30 Spp 16485-136 24% Fiche 50-277, 82/12/06, 8212210129
- GP:12150181 Releases public version of revised emergency plan implementing procedures FELTOV.JH Division of Rules and Records 82/12/07 Document Management Branch 1p 16437 283 24X Fiche 50-277.82/12/07.
- --0212150187 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-2058 re radiation survey groups & EP-209 re telephone list for emergency use Affidavit of Byr encl DALTROFF, S.L. Philadelphia Electric Co. 82/11/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 16437 284 24% Fiche 50-277,82/12/07,8212150181
- --8212150193 Public version of revised emergency plan implementing procedures, including Procedures EP-2058 re radiation survey groups & EP-209 re telephone list for emergency use # Philadelphia Electric Co 82/10/20 59pp 16437 288 24X Fiche 50-277, 82/12/07, 8212:50181
- B_c·12210174 Provides add1 info to assist shift crews making telephone tepts via NRC emergency notification sys Sample event notification form used by NRC duty officer encl STAROSTECKI.R Division of Project & Resident Programs 82/12/16 DALTROFF,S.L. Philadelphia Electric Co. App. 16484 250 24X Fiche 50-277,82/12/16,8212210174
- 8212230313 Notifies that review of DL & App A Tech Specs performed in response to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73 40(d) & STS for audits of safeguards contingency plan Contingency plan adopted DALTROFF, 8 L Philadelphia Electric Co 82/12/17 EISENHUT, D 0 Division of Licensing 2pp 16507 360 24X Fiche 50-277,82/12/17,82/1230313
- G Adjudicatory correspondence
- 8212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacatsons Centificate of Byc and JEHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 167 24X Fichs 50-000.82/12/08, PORTHANDER
- 8212140438 Order extending time until 821227 for TMI & Peach Bottom intervenors to file petition for review of ALAB-701 CHILK, S. J. Office of the Secretary of the Commission 82/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 24X Fichs 50-000, 82/12/13, 8212140438

- 8212210009 Advises that intervenor petition for review of ALAB-701 should be served on MRC when filed BORDENICK, B M Hearing Branch 3 62/12/16 JOHNSRUB, J Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, 8212210009
- 9/12300134 Petition for review of consolidated radon proceedings Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration Certificate of Svc encl
 JGHMSRUD, J H Environmental Coalition on Nuclear Power 82/12/27
 Commissioners 15pp 16598 112 24% Fiche 50-000.62/12/27, 8212300134
- P Operating license stage documents & correspondence
- 8:12100365 Requests verification that entl acceptance criteria for NUREO-0737, Item II K 3 22, "Automatic Switchover of RCIC Sys Swction" satisfied Response requested within 30 days STOLZ, J F Operating Reactors Branch 4 82/08/04 BAUER, E G Philadelphia Electric Co 4pp 16389 193 24X Fiche 80-277, 82/08/04, 8212100365
- BP12080566 Requests participation.cooperation & support of NRC research project, "Task Analysis of Nuclear Power Plant Control Room trews"

 SCHWENCER.A Licensing Branch 2 B2/11/09 DALTROFF, S L
 Philadeiphia Electric Co 2pp 16368 350 24X
 Fiche S0-277,82/11/09,8212080566
- 6/*11230046 Generic Ltr 82-27 to all DWR licenses of operating reactors except LACBUR, Big Rock Point, Dresden 1. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0795 Svc list encl U/o stated encl CISECHNUT, D 0 Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/(1/15, 821)230046
- G212090119 Forwards info re site geology.confirming telcon w/MB Fairtile DALTROFF,S L Philadelphia Electric Cp 82/11/30 STOLZ,J F Operating Reactors Branch 4 20pp 16357 249 24X Fiche 50-277,82/11/30,8212090119
- 8212060096 Forwards application to amend Licenses DPR-44 & DPR-56, thanging surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test
 BRADLEY,E J Philadelphia Electric Co 82/12/01 DENTON,H R
 Diffice of Nuclear Reactor Regulation, Director tp 16314 345 24X
 Fiche 50-277,82/12/01,82/2060096
- --B212060106 Application to amend Licenses DPR-44 & DPR-56, changing surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test BAUER, E G , BRADLEY, E J , DALTROFF, S L Philadelphia Electric Co B2/12/01 App 16314 346 24X Fiche 50-277,82/12/01,8212060096
- --8212040109 Proposed changes to surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test

 * Philadelphia Electric Co 82/12/01 4pp 16314 352 24X Fiche 50-277,82/12/01,8212060094
- E:/2130211 Responds to MRC 021101 request for add1 info re util 011001 response to Generic Ltr 01-04 concerning Revision 1 to MUREO-0313 Responses to Items 4.5d & 6d will be submitted no later than 021215
 DALTROFF.S L Philadelphia Electric Co 02/12/03 STOLZ, J F Operating Reactors Branch 4 13pp 16462 277 24X
 Fiche 50-277, 02/12/03, 0212130211
- --B212170094 "Manual Ultrasonic Exam of Pressure Piping Welds," Revision 59 WALKER,8 Southwest Research Institute 81/11/30 3Bpp 16462 290 24X Fiche 50-277, 82/12/03, 8212130211
- --0212170101 "Induction Heating Stress Improvement, Implementation Planning & Field Procedure Development," final rept BERTOSSA.D C., FITYSIMMONS, M., ZSCHALER, W.A. General Electric Co EPRI NP-2527-LD 82/08/31 197pp 16462 328 24X Fithe 50-277, 02/12/03, 0212130211
- -8212170111 "Residual Stress Improvement by Means of Induction Heating "
 * Ishikawajima Harima Heavy Industries Co ,Ltd EPRI
 NP-81-4-LD 81/03/31 354pp 16463 165 24X
 Fiche 50-277,82/12/03.821213021!

- 8:/12140385 Requests relief from 791211 commitment re containment purge & vent valve operation to allow insp in drywell of primary sys during low power Justification provided DALTROFF, B L Philadelphia Electric Co 82/12/09 STOLZ, J F Operating Reactors Branch 4 2pp 16402 113 24% //iche 50~277, 82/12/09.8212140385
- 8P12170063 Confirms approval of 821209 request for extension of time re 791211 commitment to purge containment for no more than 90-h per yr Purging should be limited to 115-h for one time only during ongoing shutdown & restart STOLZ.JF Operating Reactors Branch 4 82/12/09 BAUER, E 6 Philadelphia Electric Co 2pp 16480 348 24X Fiche 50-277, 82/12/09, 8212170063
- 8212130058 Forwards amend to application to amend Licenses DPR-44 & UPR-36 Amend revises & updates list of shock suppressors proposed for inclusion in Tech Specs BRADLEY, E. J. Philadelphia Electric Co. 82/12/13 DENTON, H. R. Office of Nuclear Reactor Regulation. Director ip 16427-326 24X (1che 30-277, 82/12/13, 8212/5058
- --B212150062 Amend to application to amend Licenses DPR-44 & DPR-56, revising & updating list of shock suppressors proposed for inclusion in Tech Specs BAUER, 6 9. BRADLEY, E J. Philadelphia Electric Co. 82/12/13 12pp 16427 327 24% Fiche 50-277,82/12/13,8212150058
- 88:12170315 Responds to NRC request for add1 info on Mark I plant-unique analysis rept submitted on 820430 Results of torus attached piping sys analyses & questions re safety relief valve discharge piping will be addressed in addendum to rept KEMPER.J S Philadelphia Electric Co 82/12/14 STOL2.J F Operating Reactors Branch 4 12pp 16453 193 24X Fiche 50-277.82/12/14.8212170315
- B212210312 Endorses BHR owners group 810522 rept re NUREC-0737, Item 2 K 3 25 concerning consequences of less of cooling water to reactor recirculation pump seal coolers, per 821028 request Rept results applicable to facilities DALTROFF, B L Philadelphia Electric Co 82/12/14 EISENHUT, D 9 Division of Licensing 2pp 16494 309 24X Fiche 50-277, 82/12/14, 8212210312
- B212170248 Identifies need for 3-month delay in schedule to replace daseous chlorination sys w/liquid sodium hypochlorite sys, per NUREG-0737, Item III D 3 4, "Control Room Habitability Requirements"

 DALTROFF, S. L. Philadelphia Electric Co. 82/12/15 EISENHUT, D 0 Division of Licensing 2pp 16459 203 24X Fichs 50-277, 82/12/15, 6212170248
- BP12170265 Forwards application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs re operability & surveillance requirements for scram discharge vol vent & drain isolation valves BRADLEY, E. J. Philadelphia Electric Co. 82/12/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 16456 170 24X Fiche 50-277, 82/12/15, 8212170265
- --G212170275 Application to amend Licenses DPR-44 & DPR-56, revising Tech Specs we operability & surveillance requirements for scram discharge vol vent & drain isolation valves Certificate of Svc entl * Philadelphia Electric Co 82/12/15 Spp 16456 171 24X Fiche 50-277.82/12/15.8212170265
- --B2:2170280 Revised Tech Spec tables re operability & surveillance requirements for scram discharge vol & drain isolation valves

 * Philadelphia Electric Co 82/12/15 Spp 16496 196 24X
 Fiche 50-277,82/12/15,8212170265
- 82:12170289 Forwards proprietary rept. "Induction Heating Stress Improvement for Stainless Stell Piping " Affidavit encl Rept withheld (ref 10CFR2 790) DALTROFF, 8 L. Philadelphia Electric Co 82/12/15 8TOLZ, J F Operating Reactors Branch 4 20pp 16486 033 24X Fiche 50~277, 82/12/15, 8212170289
- 8212230220 Forwards SER for environ qualification of safety-related electrical equipment Requests plans for Categories I B.II A & II B & schedule for proposed corrective actions within 90 days Technical evaluation encl Proprietary version withheld STOLZ.J F Operating Reactors Branch 4 82/12/20 BAUER, E 9 Philadelphia Electric Co 3pp 16512 020 24X Fiche 50-277, 82/12/20, 8212230220
- --8212230230 Safety evaluation supporting util compliance w/environ qualification of safety-related electrical equipment * Office of Nuclear Reactor Regulation, Director 62/12/20 5pp 16512 023 24% Fiche 50-277,82/12/20,8212230220

- --8212230280 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60). Peach Bottom Atomic Power Stations Units 2 & J. Vols 1 & 2." technical evaluation rept CRANE, C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-02237-493 82/08/03 LE.N B , SHEMANSKI, P NRC No Detailed Affiliation Given 1.461pp 16512 028 24x Fiche 50-277,82/12/20.8212230220
- 8212270167 Verifips that acceptance criteria for mod providing automatic suitchover of RCIC sys suction has been satisfied per NUREG-0737. Item II K 3 22 Mod completed on both units Emergency procedure provided for plant operators DALTROFF, S L Philadelphia Electric Co 82/12/20 STOLZ, J F Operating Reactors Branch 4 2pp 16538 345 24% Fiche 50-277, 82/12/20, 8212270167
- 8212290235 Clarifies program for implementation of NUREG-0737. Item II B 4 re training for mitigating core damage in response to B21205 meeting request Training for plan manager should be Ilmited considering past experience & knowledge DALTROFF. B L Philadelphia Electric Co 62/12/22 STOLZ. J F Operating Reactors Branch 4 3pp 14582 170 24X Fiche 50-277. 62/12/22. 8212290235
- B212280452 Informs of new for extension in implementation schedule for installation of new meteorological monitoring sys required by NUREG-0737, Item III A 2:due to structural deficiencies in weather tower Revised schedule expected by 82015
 DALTROFF, B L Philadelphia Electric Co B2/12/23 EISENHUT, D G Division of Licensing 2pp 16556 013 24X Fiche 50-277, 82/12/23, 8212280452
- @ Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping of BMR Flants " Syc list end!
 DEYOUND. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Commolidated Edison Co of New York. Inc 112pp 16462 163 24X Fiche 50-000. 82/10/28. 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list onc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05, Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York Inc 109pp 16411 199 24x Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYGUNG.R.C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 055. 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Mat! " Svc list enc! CO85.L! Division of Fue! Facilities, Materials & Safeguards B22t1/30 Consolidated Edison Co of New York, Inc 356pp 14387 028, 24X Fiche 50-000,82/11/30,8208190257.
- 8208190259 IE Bulletin B2-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies." Svc list encl. DEYGUNG:R C Director's Office, Office of Inspection and Enforcement B2/12/03. Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259.
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets" Svc list enc: JORDAN, E. L. Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche-50-000,82/12/03,8208190261,
- 8212080314 Act receipt of 821109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 50-278/82-14 STARDSTECKI.R. Division of Project & Resident Programs 82/12/03 BALTROFFS L Philadelphia Electric Co ip 16353 350 24X Fiche 50-277.82/12/03/812/080314
- --8212080323 Responds to NRC 820929 ltr re-violations noted in IE Insp. Repts 50-277/82-14 & 50-278/82-14 Corrective actions health physics personnel instructed to more forcefully check locked doors when performing surveillance test DALTROFF, B.L. Philadelphia Electric Co. 82/11/09 STAROSTECKI, R. Division of Project & Resident Programs 2pp 16353 351. 24X Fishs 50-277, 82/12/03, 8212080314

- 8212160480 Forwards IE [nsp Repts 50-277/82~16 & 50-278/82~16 on 821021-1130 & notice of violation STAROSIECKI, R Division of Project & Resident Programs 82/12/03 DALTROFF, S L Philadelphia Electric Co 2pp 16442 087 24X Fiche 50-277, 82/12/03, 8212160480
- --B212160486 Notice of violation from insp on 821021-1130 * Division of Project & Resident Programs 82/12/03 ip 16442 089 24X Fiche 50-277, 82/12/03, 8212160480
- --8212160491 IE Insp Repts 50-277/82-16 & 50-278/82-16 on 921021-1130 Noncompliance moted failure to meet Tech Spec fire watch requirements BEUU9H. A R. HCCABE. E C. Region 1. Office of Director 82/12/03 21pp 16442 090 24% Fiche 50-277.82/12/03,8212160480
- 87:12210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No honcompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/12/06 DALTROFF, S L Philadelphia Electric Co 2pp 16485 134 24X I iche 50-277, 82/12/06, 8212210129
- --8212210134 IE Safeguards insp Repts 50-277/82-22 & 50-278/82-21 on 821016-22 No noncompliance noted Major areas inspected security plans & implementing procedures security organization mgt & personnel Safeguards info deleted DUWLAP.J M . GODY.A T Division of Engineering & Technical Programs 82/11/30 Spp 16485 136 24X Fiche 50-277/82/12/06, 8212210129
- G2:12140335 Requests relief from 771211 commitment re containment purge & vent valve operation to allow insp in drywell of primary sys during low power Justification provided DALTROFF.S & Philadelphia Electric Co 82/12/09 STOLZ, J F Operating Reactors Branch 4 2pp 16402 113 24x Fiche 50-277, 82/12/09.8212340335
- BP0B190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl

 BEVQUNG.R C Director's Office, Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York, Inc

 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 8212220412 Advises that meeting will be arranged to discuss IE Info Notice 82-05. "Increasing Frequency of Drug-Related Incidents" List of topic areas to be discussed encl STAROSTECKI, R Division of Project & Resident Programs 82/12/16 DALIROFF, S L Philadelphia Electric Co 2pp 16503 354 24X Fiche 50-277, 82/12/16, 8212220412
- 8:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- B212020349 Forwards "Thermal Mapping Rept 82-7 for 821027 for Thermal Monitoring Requirements" Info covers isotherm surveys per App 8 FT9 reporting requirements WILSEY, W B Philadelphia Electric Co 82/11/24 IPPOLITO, T A Operating Reactors Branch 3 ip 16278 005 24x Fiche 50-277, 82/11/24, 8212020349
- --8212020352 "Thermal Mapping Rept 82-7 for 821027 for Thermal Monitoring Requirements " * Philadelphia Electric Co 82/11/24 4pp 16278 006 24X Fiche 50-277.82/11/24.8212020349
- BP12160055 Forwards monthly operating repts for Nov 1982 COONEY, M J Philadelphia Flectric Co 82/12/10 Director's Uffice, Office of Inspection and Enforcement 1p 16446 131 24X Fichs 50-277, 82/12/10/8212160055
- --8212160058 Monthly operating repts for Nov 1982 ALDEN.N M Philadelphia Electric Co 82/12/10 9pp 16446 132 24X Fiche 50-277,82/12/10,8212160055
- 8212210158 Forwards Thermal Mapping Rept 82-8 re isotherm surveys for 82119.in compliance w/App 8 to ETS
 WILLSEY,W 8 Philadelphia Electric Co 82/12/15 IPPOLITO,T A Operating Reactors Branch 3 1p 16484 308 24X
 Fiche 50-277,82/12/15,8212210158
- --8212210162 "Thermal Mapping Rept 82-8 for B21119 for Thermal Monitoring Requirements " * Philadelphia Electric Co 82-8 82/11/19 4pp 16484 309 24X Fiche 50-277.82/12/15.8212210158

- S Reportable occurrences, LERs & related correspondence
- 8212150061 LER 82-038/03L-0 on 821106 & 08. isolation valves 5V2671C, SV2671D & SV2671A in sample lines to oxygen analyzers failed to fully close Caused by accumulation of dirt on seat & valve disk Valves disassembled, cleaned & rebuilt COONEY.M J Philadelphia Electric Co 82/12/02 HAYNES, R C Region 1, Office of Director ip 16430 251 24X Fiche 50-277.82/12/02.8212150061
- BP12160415 LER 82-032/03L-0 en B21114, during surveillance test, no air flowed from B main control room emergency ventilation fan Caused by fan damper controller being out of adjustment Controller adjusted sys tested & returned to svc CORNEY, M J Philadelphia Electric Co B2/12/14 Region 1, Office of Director 1p 16442 283 24X Fiche 50-277, 82/12/14, 8212160415
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 6:12360480 Forwards IE Insp. Repts 50-277/82-16 & 50-278/82-16 on C21021-1130 & notice of violation FRARGSTECKI, R. Division of Project & Resident Programs 82/12/03 DALTROFF, S. L. Philadelphia Electric Co. 2pp. 16442 087 24X Fiche 30-277, 82/12/03/82/160480
- --B212160486 Notice of violation from insp on 821021-1130 * Division of Project & Resident Programs 82/12/03 ip 16442 089 24X Fiche 50-277,82/12/03.8212160480
- --8212160491 IE Insp Repts 50-277/82-16 % 50-278/82-16 on 821021-1130 Noncompliance noted failure to meet Tech Spec fire watch requirements BLGUGH.A R Region 1. Office of Director 82/12/03 21pp 16442 090 24% Fiche 50-277,82/12/03.8212160480
- 87:12100036 Responds to NRC 82:1202 tolcon questions re design of emergency operations facility Existing shielding sufficient for meeting NUREO-0578 personnel dose criteria, but exceeds Generic Ltr 81-10 criteria
 DALTROFF, S L Philadelphia Electric Co 82/12/06 STOLZ, J F Operating Reactors Branch 4 3pp 16379 043 247
 Fiche 50-277.82/12/06.82:2100036
- 87:12210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/12/06 DALTROFF, S L. Philadelphia Electric Co. 2pp 16485 134 24X Fiche 50-277, 82/12/06, 8212210129
- --0212210134 IE Safeguards Insp Repts 50-277/02-22 & 50-278/02-21 on E21018-22 No noncompliance noted Major areas inspected security plans & implementing procedures security organization mgt & personnel Safeguards info deleted DNLAP, JM Division of Engineering & Technical Programs 82/11/30 5pp 16485 134 24X Fichs 50-277.082/12/06.0212210129
- 82:12:50:8: Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82:12:707 Document Management Branch ip 16437 283 24X Fiche 50-277,82:12:07,82:12:50:8:
- --8212150187 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-2058 re radiation survey groups & EP-207 re telephona list for emergency use Affidavit of Svc encl
 DALTROFF, S L Philadelphia Electric Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16437 284 244 Fiche 50-277, 82/12/07, 8212150181
- --B212150193 Public version of revised emergency plan implementing procedures, including Procedures EP-2050 re radiation survey groups & EP-209 re telephone list for emergency use 4 Philadelphia Electric Co. 82/10/20 59pp 16437 288 24X Fiche 50-277, 82/12/07, 8212150181
- BR12210174 Provides add1 info to assist shift crews making telephone repts via NRC emergency notification sys Sample event notification form used by NRC duty officer enci STAROSTECKI, R Division of Project & Resident Programs B2/12/16 DALTROFF, S L Philadelphia Electric Co 6pp 16484 250 24X Fiche 50-277.82/12/16.8212210174

- 8212230313 Notifies that raview of QL & App A Tech Specs performed in response to 821030 Generic Ltr 82-23 re inconsistency between requirements of 100FR73 40(d) & STB for audits of safeguards contingency plan Contingency plan adopted DALTROFF, SL Philadelphia Electric Co 82/12/17 EISENHUT, D G Division of Licensing 2pp 16507 360 24X Fighs 50-277,82/12/17,8212230313
- G Adjudicatory correspondence
- 8212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Svc encl JCHNSRUD. J H Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 167 24X Fiche 50-000, 82/12/08, 8212140184
- B212140438 Order extending time until 821227 for TMI & Peach Bottom intervenors to file petition for review of ALAB-701 CHILK.S J Office of the Socretary of the Commission 82/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 24X Fiche 50-000.82/12/13.8212140438
- 82:12210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed BORDENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J Affiliation Unknown 2pp 16486 005 24X Fiche 50-000, 82/12/16, 8212210009
- 8P12300134 Petition for review of consolidated radon proceedings Commission should grant financial assistance to intervenors, should reopen record on all issues & remand case for full consideration Certificate of Svc encl
 JOHNSRUD, J H Environmental Coalition on Nuclear Power 82/12/2;
 Commissioners 15pp 16598 112 24X Fiche 50-000,82/12/27,8212300134
- P Operating license stage documents & correspondence
- B212100345 Requests verification that encl acceptance criteria for NUREQ-0737. Item II K 3 22. "Automatic Switchover of RCIC Sys Suction" satisfied Response requested within 30 days STOLZ. J F Operating Reactors Branch 4 82/08/04 BAUER. E Q Philadelphia Electric Co 4pp 16389 193 24X Fiche 50-277.82/08/04.8212100365
- 8:12080546 Requests participation.cooperation & support of NRC research project, "Task Analysis of Nuclear Power Plant Control Room Crews"

 SCHWENCER.A Licensing Branch 2 82/11/09 DALTROFF, S L
 Philadelphia Electric Co 2pp 14369 350 24X
 Fiche 50-277, 82/11/09, 8212080564
- 82:1230056 Generic Ltr 82-27 to all BMR licensees of operating reactors except LACBMR. Big Rock Point, Dresden 1, Humboldt Bay, applicants for QL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Svc list encl W/o stated and EISENHUT, D @ Division of Licensing 82/fi/15 General Public Utilities OPU Service Corp 22pp 16387 004 24x Fiche 50-000, 82/fi/15.82i1230066
- 8212020036 Confirms 821119 telephone authorization amending Tech Spec for 1-time extension of 7-day limiting condition for operation re operability of RHR HX Extension expires on 821124 LAINAS.0 C Assistant Director for Operating Reactors 82/11/23 BAUER.E G Philadelphia Electric Co 4pp 16308 329 24X Fiche 30-278.82/11/23.8212020036
- B212090119 Forwards info re site geology, confirming telcon w/MB Fairtile DALTROFF, B L Philadelphia Electric Co B2/11/30 STOLZ, J F Operating Reactors Branch 4 20pp 16:357 245 24X Fiche 50-277, 822/11/30, 8212090119
- 8P12060076 Forwards application to amend Licenses DPR-44 & DPR-56, changing surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test

 BRADLEY.E J Philadelphia Electric Co 82/12/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 16914 345 24X
 Fiche 50-277, 82/12/01.8212060076
- --B212060106 Application to amend Licenses DPR-44 & DPR-56, changing surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test BAUER.E Q . BRADLEY.E J . DALTROFF.S L Philadelphia Electric Co 82/12/01 6pp 16314 346 24X Fiche 50-277,82/12/01,8212060096

- --8212060109 Proposed changes to surveillance requirements of Tech Specs to permit alternate method of performing core spray loop flow rate test

 # Philadelphia Electric Co 82/12/01 4pp 16314 352 24X
 Fiche 50-277,62/12/01.8212080096
- 8P12130211 Responds to NRC 821101 request for add1 info re util 811001 response to Generic Ltr 81-04 concerning Revision 1 to NUREG-0313 Responses to Items 4.56 & 6d will be submitted no later than 821215 DALTROFF.8 L Philadelphia Electric Co 82/12/03 STGLZ.J F Operating Reactors Branch 4 13pp 16462 277 24X Fiche 50-277.82/12/03.8212130211
- --B212170094 "Manual Ultrasonic Exam of Pressure Piping Welds," Revision 59 HALKER,S Southwest Research Institute 81/11/30 38pp 16462 290 24% Fiche 50-277,82/12/03.8212130211
- --8212170101 "Induction Heating Stress Improvement Implementation Planning & Field Procedure Development," final rept BERTUSSA.D C., FITZSIMMONS, M., ZSCHALER, W.A. General Electric Co EPRI NP-2527-LD 82/08/31 1979p 16462 328 24X Fiche 50-277,82/12/03,8212130211
- ---82[217011] "Residual Stress Improvement by Means of Induction Heating "

 * Ishikawajima Harima Heavy Industries Co.ild EPRI
 NP-81-4-LD 81/03/31 354pp 16463 165 24X
 Fichs 50-277.82/12/03.8212130211
- G212100075 Forwards amend to B21019 application for amend to License DPR-56 Amend changes dates required for insp of inaccessible pipe support hydraulic smubbers BRADLEY.E J Philadelphia Electric Co B2/12/07 DENTON.H R Uffice of Nuclear Reactor Regulation, Director 1p 16379 098 24X Tiche 30-278,82/12/07.8212100075
- ~ 8212100079 Amend to 821019 application for amend to License DPR-56.
 changing dates required for image of inaccessible pipe
 support hydraulic anubbers Certificate of Svc enci
 BAUER E G . BRADLEV.E J Philadelphia Electric Co 92/12/07
 6pp 16379 099 24X Fiche 50-278.82/12/07.8212100075
- GP12160531 Forwards Amend 86 to License DPR-56, safety evaluation & notice of issuance & availability Amend temporarily extends insp interval for two inaccessible hydraulic snubbers GEARS, Q E Operating Reactors Branch 4 B2/12/07 BAUER, E Q Philadelphia Electric Co 3pp 16466 236 24X Fiche 50-278,82/12/07,8212160531
- --8212160544 Amend 86 to License DPR-56 temporarily extending insp interval for two inaccessible hydraulic snobbers 570LZ.J F Operating Reactors Branch 4 82/12/07 4pp 16465 239 24% Fiche 30-278.82/12/07.8212160531
- --8212160551 Safety evaluation supporting Amend 86 to License DPR-56 * Office of Nuclear Reactor Regulation, Director 82/12/07 2pp 16466-243 24% Fiche 50-278-82/12/07-8212160531
- --B212160960 Notice of issuance & availability of Amend 86 to License DPR-56 BTGLZ.JF Operating Reactors Branch 4 82/12/07 2pp 16466 245 24X Fiche 50-278,82/12/07.8212160531
- B212130058 Forwards amend to application to amend Licenses DPR-44 & DPR-56 Amend revises & updates list of shock suppressors proposed for inclusion in Tech Specs
 BRADLEY.E J Philadelphia Electric Co 82/12/13 DENTON H R
 Office of Nuclear Reactor Regulation, Director ip 16427-326 24x
 Fiche 30-277,82/12/13,8212150059
- --B212150062 Amend to application to amend Licenses BPR-44 & DPR-56, revising & updating list of shoct suppressors proposed for inclusion in Tech Specs
 BAUER: 8 9. BRADLEY: B J Philadelphia Electric Co 82/12/13
 12pp 16427 327 24% Fiche 50-277.82/12/13.8212150058
- 6212170315 Responds to NRC request for addl info on Mark I plant-unsque analysis rept submitted on 620430 Results of torus attached piping sys analyses & questions re safety relief valve discharge piping uill be addressed in addendum to rept KEMPER. J S Philadelphia Electric Co. 82/12/14 BTOL7. J F. Operating Reactors Branch 4 12pp 16453 193 24X Fiche 50-277.82/12/14.8212170315
- 8212210312 Endorses EMR owners group B10592 rept re NURBO-0737, Item 2 K 3 25 concerning consequences of loss of cooling water to reactor recirculation pump seal coolers, per 821028 request Rept results applicable to facilities BALTROFF, S L. Philadelphia Electric Co. 82/12/14 BISENHUT, D 9 Division of Licensing 2pp 16496 309 24% Fiche 50-277,82/12/14,8212210312

- 82:2170248 Identifies need for 3-month delay in schedule to replace gaseous chlorination sys w/liquid sodium hypochlorite sys. per NUREG-0737, ftem III D 3 4, "Control Roam Habitability Requirements"

 DALTROFF: S L Philadelphia Electric Co 82/12/15 EISENHUT.D G Division of Licensing 2pp 16459 203 24X Fiche 50-277,82/12/15,8212170248
- BP12170265 Forwards application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs re operability & surveyllance requirements for scran discharge vol vent & drain isolation valves BRADLEY.E J Philadelphia Electric Co 82/12/15 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 1p 16456 190 24X Fiche 30-277. 82/12/15.82/2170265
- --82(2)70275 Application to amend Licenses DPR-44 & DPR-56, revising Tech Specs re operability & surveillance requirements for scram discharge vol vent & drain isolation valves Certificate of Byc encl # Philadelphia Electric Co 82/12/15 5pp 16456 191 24X Fiche 30-277,82/12/15,82/2170265
- --B212170280 Revised Tech Spec tables to operability & surveillance requirements for scram discharge vol & drain isolation valves

 * Philadelphia Electric Co 82/12/15 5pp 16456 196 24X Fiche 50-277,82/12/15,8212170265
- 8212170289 Forwards proprietary rept, "Induction Heating Stress Improvement for Steinless Stell Piping " Affidavit encl Rept withheld (ref 100FR2 790) DALTROFF,8 L Philadelphia Electric Co 82/12/15 STOLZ.J F Operating Reactors Branch 4 20pp 16456 033 24X Fiche 50-277,82/12/15,8212170289
- 8P12230220 Forwards SER for environ qualification of safety-related electrical equipment Requests plans for Categories I B. II A & II B & schedule for proposed corrective actions within 90 days Technical evaluation encl Proprietary version withheld STOLZ, J F Operating Reactors Branch 4 82/12/20 BAUER, E G Philadelphia Electric Co 3pp 16512 020 24X Fiche 50-277, 82/12/20, 8212230220
- --8212230230 Safety evaluation supporting util compliance w/environ qualification of safety-related electrical equipment
 * Office of Nuclear Reactor Regulation, Director 82/12/20 'p
 16512 023 244 Fiche 50-277-82/12/20,8212230220
- --8212230250 Nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Peach Bottom Atomic Power Stations Units 2 & J. Vols 1 & 2." technical evaluation rept CRANE.C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-03257-493 52/08/03 LE.N 0 . SHEMANSKI.P NRC No Detailed Affiliation Given 1.461pp 16512 028 24x Fiche 50-277,82/12/20.8212230220
- 8th 12270167 Verifies that acceptance criteria for mod providing automatic switchover of RCIC sys suction has been satisfied per NUREO-0737. Item II Y 3 22 Mod completed on both units Emergency procedure provided for plant operators DALTROFF, S L. Philadelphia Electric Co. 82/12/20 STDLZ, J F Operating Reactors Branch 4 2pp. 16538 345 24X Fiche 50-277. 82/12/20, 8212270167
- 82:12270219 Documents conformance of analyses of Reload 5 lead test assemblies w/epproved methods & criteria contained in NEDE-24011-P-A-4. "OE Std Application for Reactor Fuel "Description of assemblies withheld (ref 10CFR2 790) DALTROFF.8 L Philadelphia Electric Co 82/12/20 STOLZ, J C Operating Reactors Branch 4 7pp 16536 266 24X Fiche 50-278,82/12/20,8212270219
- 8212290235 Clarifies program for implementation of NUREQ-0737, Item II B 4 re training for mitigating core damage in response to 821208 meeting request Training for plan manager should be limited considering past experience & knowledge DALTROFF. S L Philadelphia Electric Co 82/12/22 STOLZ, J F Operating Reactors Branch 4 3pp 14582 170 24X Fiche 50-277.82/12/22.8212270235
- 8212280452 Informs of need for extension in implementation schedule for installation of new meteorological monitoring sys required by NUREO-0737, Jtem III A 2. due to structural deficiencies in weather tower Revised schedule expected by 830115 DALTROFF, 8 L Philadelphia Electric Co 82/12/23 EISENHUT, D 9 Division of Licensing 2pp 16556 013 24X Fiche 50-277,82/12/23,8212280452,

G. Inspection reports, IE Bulletins & correspondence

- 8:08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter: Stainless Steel, Recirculation Sys Piping of BRR Plants "Sys list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24% Fiche 50-000.82/10/28.8208190240
- 8.08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model Edg & Model 802 Thermoluminescent Dosimeters." Syc list encl.

 CGBB.L. [Division of Fuel Facilities, Materials & Safeguards
 - CQBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp 14372-142 24X Fiche 50-000,82/11/05.8208190245
- 8PO8190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list oncl JORDAM: E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24X Fiche 50-000:82/11/18.8208190251
- 61:08190254 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks" Svc list encl DEYDUNG.R C Director's Office Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% fiche 50-000.82/11/26.8208190256
- BE08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBBL I Division of Fuel Facilities, Materials & Safeguards 32/11/30 Consolidated Edison Co of New York, Inc 356pp 14/387 028 24X Fiche 50-000.82/11/30,8208190257
- 8:08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Byo list encl DEYGUNG.R C Director's Orfice. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc il 3pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 82/08190361 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Nockets" Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc. 110pp 16462 064 24x Fiche 50-000.82/12/03.8208190261
- 62/12080314 Ack receipt of 821109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-14 & 10-278/82-14 STARGSTECKI, R Division of Project & Resident Programs 92/12/03 PALIROFF, S L Philadelphia Electric Co ip 16353 350 24X Fiche 50-277.82/12/03.8212080314
- --B212080323 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-277/82-14 % 50-278/82-14 Corrective actions health physics personnel instructed to more forcefully check locked doors when performing surveillance test DALTROFF, S. L. Philadelphia Electric Co. 82/11/09 STAROSTECKI, R Division of Project & Resident Programs 2pp 16353 351 24X Fishe 50-277, 82/12/03.8212080314
- 8/12160480 Forwards IE Insp Repts 50-277/82-16 & 50-278/82-16 on 821021-1130 & notice of violation 87ARGSTECKI.R Division of Project & Resident Programs 82/12/03 DALIROFF, 5 L Philadelphia Electric Co 2pp 14442 087 24X Fichs 50-277, 82/12/03, 8212160480
- --B212160486 Notice of violation from insp on 821021-1130 * Division of Project & Resident Programs \$2/12/03 ip 16442 087 24X Fiche 50-277, 82/12/03, 8212160480
- --8212160491 IE Insp Repts 50-277/BR-16 & 50-278/82-16 on 821021-1130 Noncompliance noted failure to meet Tech Spec fire watch requirements BLOUGH, A.R., MCCABE, E.C. Region 1, Office of Director 82/12/03 21pp 16442 070 24X Fiche 50-277, 82/12/03, 8212160480
- 6212210129 Forwards IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on 821018-22 No noncompliance noted MARTIN T Division of Engineering & Technical Programs 62/12/06 DALTROFF,S L Philadelphia Electric Co 2pp 16485 134 24X Fiche 50-277, 82/12/06, 8212210129
- --8212210134 IE Safeguards Insp Repts 50-277/82-22 & 50-278/82-21 on B21018-22 No noncompliance noted Hajor areas inspected security plans & implementing procedures, security organization mgt & personnel Safeguards info deleted DUNLAP.J M , GODY, A T Division of Engineering & Technical Programs 82/11/30 Spp (4485-136 24X Fiche 50-277,82/12/06,8212210129

- GP12100075 Forwards amend to B21019 application for amend to License DPR-56 Amend changes dates required for insp of inaccessible pipe support hydraulic snubbers BRADLEY.E J Philadelphia Electric Co B2/12/07 DENTON.H R D
- --B212100079 Amend to B21019 application for amend to License DPR-56. changing dates required for insplof inaccessible pipe support hydraulic snubbers Certificate of Svc encl BAUER, E O. BRADLEY, E J. Philadelphia Electric Co. B2/12/07 6pp. 16379 099 24X Fiche 50-278, 82/12/07, 8212100075
- 8212160531 Forwards Amend 86 to License DPR-56, safety evaluation & motice of issuance & availability Amend temporarily extends insp interval for two inaccessible hydraulic snubbers GEARS, 0 E Operating Reactors Branch 4 B2/12/07 BAVER, E G Philadelphia Electric Co 3pp 16466 236 24X Fiche 50-278, 82/12/07, 8212160531
- --8212160544 Amend 86 to License DPR-56, temporarily extending inspinterval for two inaccessible hydraulic snubbers STOLI, J.F. Operating Reactors Branch 4 82/12/07 4pp 16466 237 24% Fiche 50-278, 82/12/07, 8212160531
- --8212160551 Safety evaluation supporting Amend 86 to License DPR-56 * Office of Nuclear Reactor Regulation, Director 62/12/07 2pp 16466 249 24X Fithe 50-278, 62/12/07, 6212160531
- --8212160560 Notice of issuance & availability of Amend 86 to License PPR-56 STCL7.JF Operating Reactors Branch 4 82/12/07 2pp 16466 245 24X Fiche 50-278, 82/12/07.82(216083)
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 821220412 Advises that meeting will be arranged to discuss IE Info Notice 82-05. "Increasing Frequency of Drug-Related Incidents " List of topic areas to be discussed encl STAROSTECKIR Division of Project & Resident Frograms 82/12/16 DALTROFF, B L. Philadelphia Electric Co 2pp 16509 354 24X Fiche 50-277.82/12/16.8212220412
- 8708190268 IE lnto Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDÁN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 29:3 24) Fiche 50-000.82/12/20.8208190268

R Periodic operating reports & related correspondence

- 8:12020349 Forwards "Thermal Happing Rept 82-7 for 821027 for Thermal Monitoring Requirements" Info covers isotherm surveys per App 8 ETS reporting requirements WILLESY, W 8 Philadelphia Electric Co 82/11/24 IPPOLITO. T A Cherating Reactors Branch 3 p 16278 005 24X Fiche 50-277.82/11/24,8212020349
- --5212020352 "Thermal Mapping Rept 62-7 for 621027 for Thermal Munitoring Requirements" * Philadelphia Electric Co 62/11/24 4pp 16278 006 24X Fiche 50-277,82/11/24.8212020349
- BP12160055 Forwards monthly operating repts for Nov 1982 COUNEY, M J Philadelphia Electric Co 82/12/10 Director's Office. Office of Inspection and Enforcement 1p 16446 131 24X Fiche 50-277. 82/12/10.8212160055
- ---8212160058 Monthly operating repts for Nov 1982 ALDEN,N M Philadelphia Electric Co 82/12/10 9pp, 16446 132 24X Fiche 50-277,82/12/10,8212160055
- 8212210158 Forwards Thermal Mapping Rept 82-B re isotherm surveys for 821119.in compilance w/App B to ETS WILLBEY, W B Philadelphia Electric Co 82/12/15 IPPOLITO, T.A. Operating Reactors Branch 3 ip 16484 308 24X Fiche 30-277.82/12/15/8212210158.
- --8212230162 "Thermal Mapping Rept 82-8 for 821119 for Thermal Monitoring Requirements" * Philadelphia Electric Co 82-8 82/11/19 4pp 16484 309 24X Fiche 50-277,82/12/15,8212210188.

- S Reportable occurrences. LERs & related correspondence
- SP12030205 Forwards LER 82-022/01T-0 Detailed event analysis submitted COONEY.M J. Philadelphia Electric Co. B2/11/19 HAYNES,R C Region 1. Office of Director. 3pp. 16304-033 24X Fiche 50-278.02/11/19,9212030205
- --8212030208 LER 82-022/017-0 on 821104, RMR HX leaked radioactive water into intake structure via high pressure svc water piping on 821025-1102 Caused by leak between inner floating head & drain connector HX repaired COUNEY.M J Philadelphia Electric Co 82/11/19 Region 1, Office of Director ip 16304 034 24% Fiche 50-278.82/11/19, 891202025

DOCKET 50-280 SURRY POWER STATION. UNIT 1

- F Security, modical, emergency & fire protection plans
- 6212060138 Forwards supplemental SER addressing open items re App Rincluding approval of proposed mod concerning relocation of one charging pump.sec water pump & respective water source facility in compliance w/App R requirements VARGALS A Operating Reactors Branch | B2/11/18 STEWART.W L Varginia Electric & Power Co 7pp 16325-355 24X Fiche 50~280.82/11/18.82/2060138
- 9212060338 Grants requested exemption from requirement of App R Section III 6 to IOCFRSO re installation of fixed fire suppression sys in control room VARGA, 6 A Greating Reactors Branch 1 82/11/24 STEWART, W L Virginia Electric & Power Co 2pp 16323 345 24X Fiche 50-280, 82/11/24, 8212060338
- --82:2050339 Exemptions from requirement of App R Section III G to 10CFRSO re installation of fixed fire suppression sys in control room EISENHUT.D O Division of Licensing 82/11/24 Virginia Electric & Power Co 3pp 16323 347 24X Fiche 50-280.82/11/24, 8212050338
- 8212060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tach Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan STEMARTH L. Virginia Electric & Power Co. 82/12/01 DENTON, H.R. Offics of Nuclear Reactor Regulation. Director VARGA, S.A. Uperating Reactors Branch I. 2pp. 16312-112 24x Fiche 50-280.82/12/01.8212060303
- --8212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan * Virginia Electric & Power Co 82/12/01 5pp 16312 114 24x Fiche 50-280,82/12/01,8212060303
- 8912090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 LEHIS.R C Division of Project & Resident Programs 82/12/06 STEMARY.H L Virginus Electric & Power Co 2pp 16359 236 24X Fiche 50-280.62/12/06.8212090166
- --8212090169 Forwards supplemental response to 821008 ltr re 820908 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response withhold (ref 10CFR73 21)
 SIEWART.W L Virginia Electric & Power Co 82/11/17
 O'REILLY.J P Region 2. Office of Director 10 16357 238 24X
 Fiche 50-280,82/12/06.8212090166
- --G212090175 Responds to NRC 820908 ltr re violations noted in IE Insp Repts 50-280/82-23 \$ 50-281/82-23 Corrective actions withheld (ref 1007R73 21) LEASBURO.R H Virginia Electric & Power Co 82/10/08 O'REILLY.J P Region 2. Office of Director 1p 16359 239 24x Fiche 50-280.82/12/06.8212090166
- --8212070180 Forwards IE Safaguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
 LEMIS.R C Division of Froject & Resident Programs 82/09/08
 LEASBURG,R H Virginia Electric & Power Co 2pp 16359 240 24%
 Ficha: 30-280, 08/12/06.8212070166
- --8212070185 IE Bafeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Details withheld (ref 10CFR73 21) MODRE D.E. MCOURE, D.R. Division of Engineering & Technical Programs 82/07/03 2pp 16359 242 24X Fichs 50-280,82/12/06,8212090166

- EP12090419 Forwards add1 info re status of emergency response facilities locations & constitupplementing 810401 & 820408 responses to Generic Ltr 81-10 transmitting NUREG-0676, per request STEWART. W. L. Virginia Electric & Power Co. 82/12/06 DENTON, H. Diffice of Nuclear Reactor Regulation, Director 2pp. 16364 2/6 24X Fiche 50-000, 82/12/06, 8212070419
- Bil2150059 Forwards revised security drawings Drawings withheld (ref IOCFR2 790)
 STEMARTW L. Virginia Electric & Power Co. 92/12/09 DENTON, H. K. Office of Nuclear Reactor Regulation. Director VARQA, S. A. Operating Reactors Dranch I ip. 16427-362 24X
 [Iche 50-000.82/12/09.82/2150059
- 8212170036 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16478 003 24X Fiche 50-280, 82/12/10. 8212170036
- --8212170041 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 Of, "Emergency Manager Controlling Procedure" STELMART.II L Virginia Electric & Power Co 82/12/01 O'REILLY.J P Region 2, Office of Director 1p 16478 004 ,*4X Fiche 50-280, 82/12/10.8212170034
- --G212170044 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 Of, "Emergency Manager Controlling Procedure "COLFK SAUNDERS,R T Virginia Electric & Pawer Co 82/11/18 3pp 16478 005 24X Fiche 50-280,82/12/10,8212170036
- 82/12220281 Responds to util 82/028 ltr np Revision 7 to security program Revision consistent w/10CFR50 34(p) provisions & acceptable Encl to 82/028 ltr withheld (ref 10CFR73 21) VAROA.S A Operating Reactors Branch 1 82/12/10 STEWART.W L Virginia Electric & Power Co 2pp 16523 307 24% Fiche 50-280, 82/12/10, 8212220281
- GE12220481 Forwards drart SER re App R exemption requests Justification that lavel of protection afforded by existing fire protection measures in whengency suitch gear rooms equivalent to App R requirements not provided VARCA. S A Operating Reactors Branch 1 82/12/10 STEWART, W L Virginia Electric & Power Co 7pp 16523 192 24X [ithe 50-280, 82/12/10,821222048]
- BP12170024 Forwards request for add1 info re security training & qualification plans, per util B20917 ltr
 CLARK.R A Operating Reactors Branch 3 82/12/13 STEWART.W L
 Virginia Electric & Fower Co 4pp 16480 335 24X
 Fiche 50-000.82/12/13.8212170024
- 8212170494 Releases public version of revised local govt radiological theoremcy response plans FELTON.J H Division of Rules and Records 82/12/13 Document Management Branch 1p 16479 142 24X Fiche 50-280.82/12/13.
- --B212170497 forwards public version of revised local govt radiological emergency response plans for Counties of Surry, Isle of Might, York & James City & Cities of Newport News & Williamsburg, VA STEMART, M L. Virginia Electric & Power Co. 82/12/01 O'REILLY, J P. Region 2, Office of Director 1p. 16479 144 24X Fiche 50-280, 82/12/13, 8212170454
- --B212170458 Public version of revised local govt radiological emergency response plans for Counties of Surry Isle of Hight York & James City & Cities of Newport News & Williamsburg VA * Virginia Electric & Power Co 82/11/30 928pp 16479 145 24X Fiche 50-280 82/12/13 8212170454
- 8212300195 Responds to 821013 ltr re protection of safeguards info Safe acceptable provided that safe located within protected area VARGA.S A Operating Reactors Branch I 82/12/15 STEWART, W L Virginia Electric & Power Co 2pp 16612 329 24X Fiche 50-280,82/12/15,8212300195
- GP12270179 Informs that although 821209 ltr forwarding sacurity drawings failed to contain safeguards statement drawings were properly secured marked & identified as safeguards info.

 STEWART W. L. Virginia Electric & Power Co. 82/12/20 DENTON, H & Office of Nuclear Reactor Regulation. Director VARGA, S. A. Operating Reactors Branch | ip. 16509 010 24X Fishe 50-000.82/12/20.8212270179

P Operating license stage documents & correspondence

- 8212060134 Forwards response to NRC B21026 questionnaire re steam generator tube integrity Data for each facility compiled in separate sections
 STEMART.W.L. Virginia Electric & Power Co. B2/12/01 DENTON.H R diffice of Nuclear Reactor Regulation. Director EISENHUT.D 0
 Division of Licensing 5pp 16314-070 24X Fiche 50-000.82/12/01.8212060134
- GP12060284 Notifies that neither facility has add1 Tech Specs to be submitted in response to Generic Ltr 82-16 re status of NURGO-0737 items STEWART.W L Virginia Electric & Power Co 82/12/01 DENTON.H R Uffice of Nuclear Reactor Regulation, Director EISENHUT,D G Division of Licensing 1p 16312 058 24% Fiche 50-000,82/12/01,8212060284
- GP12060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tech Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan STEWART. H. Urrginia Electric & Power Co 82/12/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S.A. Operating Reactors Branch 1 2pp 16312 112 24X Fiche 50-280, 82/12/01, 8212060303
- --82(2060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan * Virginia Electric & Power Co 82/12/01 5pp 16312 114 24x Fiche 50-280.82/12/01
- B712100012 Advises that Generic Issue 3-24 re containment purge & iNI Item II E 42 re containment isolation dependability complete Summary of review listed Tech Specs will be issued separately VARGA. 5 A Operating Reactors Branch | B2/12/07 STEWART, W L Virginia Electric & Power Co 3pp 14397 235 24X fiche 50-280. B2/12/07. 8212100012
- BEOB190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications. Inc draff rept re subjirequirements Comments requested within 30 days of ltr Syc list encl EISENHUT.D Q Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 27pp 16687-247 24X Fiche 50-000.82/12/09.8208190263
- Billi40103 Generic Ltr 82-28 to all licenses of operating Hestinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumention sys Svc list encl £15EMHUT.D 0 Division of Licensing 82/12/10 Yankee Atomic Flectric Co 27pp 16690 035 24X Fiche 50-000.82/12/10, U212140103
- 8):12280257 Forwards remittance for Invoice B-0069 for review of Amend 4 to Topical Rept VEP-1. "QA Program Operations Phase." submitted on 820921 & approved on 821006 STEWART.W L Virginia Electric & Power Co 82/12/22 DENTON.H R Office on Nuclear Reactor Regulation. Director BARRY,L W Division of Accounting 1p 16561 269 24X Fiche 50-000.82/12/22.
- GE:12280349 Forwards Class II fee to cover review of 82:1201 suppl to amend Licenses DPR-32 & DPR-37 STEWART: N L Virginia Electric & Power Co 82:12/22 DENTON, H R Defice of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Branch 1 p 16561 042 24X Fiche 50-280, 82:12/22.8212280349
- 6212290191 Informs that completion date, per 820823 supplemental response to Generic Ltr 82-05, "Post-Accident Sampling Sys." will be extended to 830601 Status rept expected in Mar 1983 STEWART.N L Virginia Electric & Power Co 82/12/27 DENTON.H R Gifice of Nuclear Reactor Regulation. Director EISENHUT, D 0 Division of Licensing 3pp 16578 052 24X Fiche 50-280.82/12/27, IZ212290191

@ Inspection reports. IE Bulletins & correspondence

- 8212090267 Forwards IE Insp Repts 50-280/82-26 & 50-281/82-26 on 821004-08 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/10/26 LEASBURG: H Virginia Electric & Power Co 2pp 16362 301 24X Fiche 50-280, 82/10/26, 8212090267
- --8212070277 IE Insp Repts 50-280/82-26 & 30-281/82-26 on 821004-08 No mancompliance noted Major areas inspected pipe supports & restraints & Type B & C containment leakage rate testing BRODKS.E H , JAPE.F Division of Project & Resident Programs 82/10/25 4pp 16362 303 24X Fiche 50-280.82/10/26.8212090267

- 8208190240 IE Bulistin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at Birk Plants " Syc list encl
 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8212090285 Advises that SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 have been reviewed & approved Overall performance adequate No reply required O'REILLY.J P Region 2. Office of Director 82/11/03 LEASBURG.R H Virginia Electric & Pawer Co 2pp 16365 208 24X Fiche 50-000.82/11/03.8212090285
- --8212090298 Forwards SALP Repts 50-280/82-19.50-281/82-19.50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 LEWIS.R C Division of Project & Resident Programs 62/08/04 LEASOURG.R H Vingtina Electric & Power Co 2pp 16365 210 24X Fiche 50-000, 82/11/03.8212090285
- --8212090306 SALP Repts 50-280/82-19,50-281/82-19,50-338/82-24 & 50-3397/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational GA Region 2, Office of Director 82/08/04 31pp 16365 212 24X Fiche 50-000,82/11/03,8212090285
- B20B190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list incl
 CDB1.1 Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- 8212090276 Ack receipt of B21027 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-280/82-24 & 50-281/82-24

 DANCE, H C Division of Project & Resident Programs 82/11/18
 STEWART. W L Virginia Electric & Power Co ip 16365-270 24X
 Fiche 50-280.829/11/18.8212090276
- --6212090286 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-280/82-24 & 50-281/82-24 Corrective actions valve pit roofs covered wifire retardant plastic & seeled STEHART. W. Virginia Electric & Power Co 82/10/29 O'REILLY, J. P. Region 2. Office of Director 3pp 16365 271 24X Fiche 50-280, 82/11/18 3212090274
- ---8212070300 Forwards IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0903 & notice of violation DAKCE.H C Division of Project & Resident Programs 82/09/29 LEASBURG.R H Virgina Electric & Power Co 2pp 16365 274 24X Fichs 50-280, 82/11/16.8212090276
- --8212090304 Notice of violation from insp on 820802-0903 * Division of Project & Resident Programs 82/09/29 ip 16365 276 244 Fiche 30-280.882/11/18.8212090274
- --B212090313 IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0903 Noncompliance noted roof leak caused by previous maint work degraded safety-related equipment BURKE.D J : DAVIB.M J : GRDERS.H J Division of Project & Resident Programs 82/09/28 9pp 16365 277 24X Fiche S0-280,82/11/18, 8212090276
- BF/12090215 Ack receipt of B20716 & 1105 ltrs infurming NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10

 DANCE, H C Division of Project & Resident Programs 82/11/19
 STEMART, W L Virginia Electric & Power Co 1p 16362 279 24X Fiche 50-280, 82/11/19, 8212090215
- --8212090217 Responds to NRC B20507 ltr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions Administrative Procedure 56 re ignition sources amended to classify areas for purposes of controlling sources STEWART.W C Virginia Electric & Power Co 82/11/05 0'RETILLY.J P Region 2, Office of Director 2pp 16362 280 24X Fiche 50-280,82/11/19,8212090215
- --8212090218 Responds to NRC 820607 ltr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions process vent sys mod designed & Administrativa Procedure 56 amended re safety-related areas LEASBURGNR H Virginia Electric & Power Co 82/07/16 0'REILLY, J P. Region 2, Office of Director 4pp 16362 282 24X Fiche 50-280,82/11/19,8212090215

- --8212090220 Confirms telcon re IE Insp Repts 50-280/82-10 & 50-281/82-10 Response will be submitted by 820717 LEASBURGAR H Virginia Electric & Power Co 82/07/06 O'REILLY, J P Region 2, Office of Director 1p 16362 286 24X Fiche 50-280, 82/11/19,8212090215
- --8212090223 Forwards IE Insp Repts 50-280/82-10 & 50-281/82-10 on 820401-30 & notice of violation DANCE, H C Division of Project & Resident Programs 82/06/07 LEASBURG, R H Virginia Electric & Power Co 2pp 16262 287 24x Fiche 50-280.82/11/19.8212090215
- --8212090226 Notice of violation from insp on 820401-30 * Division of Project & Resident Programs 82/06/07 2pp 16362 289 24% Fiche 50-280,82/11/19,8212090215
- --8212070234 IE Insp Repts 50-280/82-10 & 50-281/82-10 on 820401-30 Noncompliance noted failure to follow fire protection program implementing procedures BURKE, D J , CAVIS.M J , UKLIAN, C A Division of Project & Resident Programs 82/04/04 iOpp 16362 291 24X Fiche 50-280.82/11/19, 8212090215
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks," Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp juic
- 8708170257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list enc! CDBs.L I Division of Fuel Facilities. Haterials & Safeguards 82/11/30 Consolidated Edison Co of New York. Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- B212290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents ! & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 enc!
 FELTON, J M Division of Rules and Records 82/11/20 SCHLISSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30,8212290060
- --8212270170 Ack receipt of 761206 ltr informing NRC of steps taken to correct violation noted in JE Insp Repts 50-280/76-14 & 50-281/76-14 LONG,F J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 77/01/14 PROFFITI.W L Virgania Electric & Power Ca tp 16508 041 24% Fiche 50-000.82/11/30.8212270060
- --B212290172 Responds to NRC 761021 ltr re violation noted in JE Insp Repts 50-280/76-14 & 50-281/76-14 Corrective actions Administrative Procedure 22 redistributed & importance of proper documentation practices emphasized STALLINOS.C N Verginia Electric & Power Co 76/12/06 MOSELEY.N C Region 2. Atlanta, Office of the Director 4pp 16408 042 24X Fiche 30-000.82/11/30.8212270060
- ---9212270178 Forwards IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted LONG.F J Region 2. Atlanta, Reactor Operations Nuclear Support Branch 76/10/21 PROFFITT.W L Virginia Electric & Power Co 2pp 16508 046 24X Fiche 50-000.82/11/30,8212290060
- --8212270184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted failure to follow log book entry & review & initial requirements specified in Administrative Procedure 29 SINKULE,M V , LEWIS.R C , ROCERS.R F Region 2, Atlanta, Reactor Operations Nuclear Support Branch 76/10/19 13pp 16608 048 24% Fiche 30-000,82/11/30,8212270060
- 8908190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidate Edison Co of New York, Inc 113pp. 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets." Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24 Fiche: 50-000. 82/12/03. 8208190261
- @212090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in 16 Sefeguards Insp Repts 50-280/82-23 & 80-281/82-23 LEWIS.R C Division of Project & Resident Programs 82/12/06 STEMART.W L Virginia Electric & Power Co 2pp. 16357 236 24) Fiche: 50-280, 82/12/06, 8212090166.

- --82[2070167 Forwards supplemental response to 821008 ltr re 820908 [E Safeguards Insp Repts 50~280/82-23 & 50~281/82-23 Response uithheld (ref 10CFR73 21) STEMART, W L Virginia Electric & Power Co 82/11/17 O'REILLY, J P Region 2, Office of Director 1p 16359 238 24x Fiche 50~280,82/12/06,8212090166
- --8212090175 Responds to NRC 820908 ltr re-violations noted in IE lisp Repts 50-280782-23 & 50-281782-23 Corrective actions withheld (ref 10CFR73 21) LEASBURG:R H Virginia Electric & Power Co 82/10/08 0'REILLY, J P Region 2, Office of Director 1p 16359 239 247 Fiche 50-280,88/12/06,8212090166
- --8212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
 LEWIS,R C Division of Project & Resident Programs 82/09/08
 LEASBURG,R H Virginia Electric & Power Co 2pp 16359 240 242
 Fiche 50-280,82/12/06,8212090166
- --8212090185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Details withheld (ref IOCFR73 21) MODRE, D E . MCGUIRE, D R Division of Engineering & Technical Programs 82/09/03 2pp 16359 242 24X Fiche 50-280,82/12/06,8212090166
- 86:08190247 IE info Notice 92-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEYQUNO, R C Director's Office. Office of Inspection and Enforcement 82:12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000:82/12/20.8208190268
- B212290261 Forwards Revision I to inservice insp program titEWART.W L Virginia Electric & Power Co 82/12/27 DENTON:H R Office of Nuclear Reactor Regulation. Director 2pp 16587 106 24X Fische 50~280:82/12/27.8212290261
- --8212290264 Treervice insp program. Revision 1 STEWART:N & Virginia Electric & Power Co 82/12/27 263pp 16587 107 24X Fiche 50-280. 82/12/27, 8212290261
- R Periodic operating reports & related correspondence
- 8/12290238 Forwards monthly operating repts for Oct 1982 & corrected page to monthly operating rept for Sept 1982 W/o corrected page STEMART. H L Virginia Electric & Power Co 82/11/15 HALLER. N M Office of Resource Management, Director 1p 16582 116 24% Ficha 50-280.82/11/15.8212270238
- --B212270244 Monthly operating repts for Oct 1982 JONES, V Virginia Electric & Power Co 62/11/05 52p 16582 117 24X Fiche 50-280, 82/11/15,8212270238
- S Reportable occurrences, LERs & related correspondence
- 8212020090 Forwards LER 82-121/03L-0 WILEGN, J L Virginia Electric & Power Co 82/11/24 O'REILLY, J P Region 2. Office of Director Ip 16272 022 24X Fiche 50-280, 82/11/24, 8212020090
- --8212020096 LER 82-121/03L-O on 821026, alarm setpoint for liquid wasto monitor RM-LM-108 exceeded allowable Tech Spec limits Caused by instrument drift Operator took administrative control for high alarm isolation Monitor recalibr

 WILSON J L Virginia Electric & Power Co 82/11/24 Region 2. Office of Director 2pp 16272 023 24X Fiche 50-280,82/11/24. 8212020090
- B212090086 Forwards LER: 82-110/03L-0 & 82-060/03L-0
 WILSON, J L Virginia Electric & Power Co 82/11/30 O'REILLY, J P
 Region 2, Office of Director ip 16357 180 24x
 Fiche 50-280.82/11/30,8218090085
- --8212070071 LER 82-110/03L-0 on 821104 & 18, specific activity samples of RCS indicated dose equivalent I-131 level greater than Tech Specs Caused by fwel element defect in reactor core Sampling frequency implemented until level decreased W1L50N.J L. Virginia Electric & Power Co 82/11/30 Region 2, Office of Director App 16357 181 24X Fiche 50-280,82/11/30,8212090086

- --8212090098 LER 82-060/03L-0 on 821102 charging pump svc water pump 2-SM-P-108 experienced loss of suction pressure Caused by insufficient NPSH Pump vented to restore NPSH WILSON, J L Virginia Electric & Power Co 82/11/30 Reg;on 2. Office of Director 3pp 16357 185 24X Fiche 50-280, 82/11/30, B212090086
- BD12290060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Ginna & Indian Point 3 encl
 FELTON, J M Division of Rules and Records 82/11/30 SCHLISSEL.D A New York, State of 7pp 16607 239 24X Fiche 50-000, 82/11/30, 8212290060
- --8212290069 RO 76-12 on 760909, low pressure alarm occurred on safety injection accumulator C.resulting in pressure reduction Caused by partially open HCV 1936 body to bonnet leaks on HCV 1938 & 1934 Valves repaired & accumulator repressurized STALLINGS.C M Virginia Electric & Power Co 76/10/01 MOSELEY.N C Region 2. Atlanta. Office of the Director 5pp 16607 263 24X Fiche 50-000, 82/11/30.82:2290060
- --8212290075 RQ 76-13 on 760916, normal boric acid makeup to vol control tank could not be accomplished due to plugging of chemical & vol control sys line 1-inch-CH-56-152 Cause unknown Line will be inspected for indications of salidification STALLINGS.C M Virginia Electric & Power Co 76/10/20 MOSELEY.N C Region 2. Atlanta, Office of the Director 5pp 16607 267 24X Fiche 50-000, 82/11/30.8212290060
- --8212270080 RG 76-07 on 760713 monthly average of gaseous & airborne particulate wastes for previous 12 months found greater than Tech Spec limit Caused by interpretational changes in Tech Spec Section 3 ii B New limit approved STALLINGS.C M Virginia Electric & Power Co 76/09/24 MDSELEY.N C Region 2. Atlanta. Office of the Director 5pp 16607 273 24X Fiche 50-000, 82/11/30, 8212270060
- 8212210365 Forwards LERs 82-070/03L-0,82-113/03L-0 & 82-116/03L-0 WILSON,J L Virginia Electric & Power Co 82/12/13 O'REILLY,J P Region 2, Office of Director ip 16494 278 24X Fiche 50-280,82/12/13,8212210365
- ---B2122103B3 LER 82-070/03L-0 on B21119, routine walkdown of svc bldg revealed open barrier penetration w/no fire watch posted Caused by removal of temporary seal on penetration Fire watch posted Penetration resealed WILSOH, J. L. Virginia Electric & Power Co. 82/12/13 Region 2, Office of Director. 2pp. 16494-279. 24X Fiche 50-280, 82/12/13, 8212210365
- --8212210388 LER 82-113/03L-0 on 821121, radiation monitor recorder found inoperable Caused by slipped drive cable Drive cable reinstalled & recorder returned to svc WILSUN, J L Virginia Electric & Power Co 82/12/13 Region 2, Office of Director 2pg 16494 281 24X Fiche 50-280,82/12/13,8212210345
- --8212210397 LER 82-116/03L-0 on 821113, containment spray chemical addition tank level decreased below Tech Spec limit Caused by loss of vol due to leakage past manual isolation valve during maint Valve torqued shut Tank refilled WILSON, J. Virginia Electric & Power Co. 82/12/13 Region 2, Office of Director. 3pp. 16494 283 24X Fiche 50-280, 82/12/13, 8212210365
- B212280126 Forwards LERs 82-105/03L-0,82-117/03L-0 & 82-072/03L-0 WILSON, J L Varginia Electric & Power Co 82/12/17 O'REILLY, J P Region 2. Office of Director 1p 16562 306 24X Tiche 50-280,82/12/17,8212280126
- --8212280140 LER 82-105/03L-0 on 821123, amplifier reading for heat tracing panel 7, circuit 7A, fell below acceptance criteria On 821126, low reading detected for panel 8 Caused by excessive heat Defective heat tracing replaced & tested WILSON, J.L. Virginia Electric & Power Co. 82/12/17 Region 2, Office of Director 2pp 16562 307 24X Fiche 50-280, 82/12/17, 8212280126.
- --8212280152 LER 82-117/03L-0 on 821129, specific activity samples of RCS indicated dose equivalent I-131 level greater than Tech Spec limit Caused by fuel element defect in reactor core Accelerated sampling frequency implemented WILSON, J. ... Virginia Electric & Power Co. 82/12/17 Region 2, Office of Director ... 3pp. 14562 309 24X Fiche 50-280, 82/12/17, 8212280126

- --B212280206 LER 82-072/03L-O on B21126, amplifier readings heat tracing panel 11. circuit 2A. fell below acceptance criteria Caused by overheating due to maladjusted thermostat Defective heat tracing replaced & tested WILSON. J L Virginia Electric & Power Co 82/12/17 Region 2, Office of Director 2pp 16562 312 24X Fiche 50-280.82/12/17, 8212280126
- Y Dry Cask Independent Spent Fuel Storage Installations
- B212220170 Advises that application for dry cask IBFSI docketed on B21015 Application evaluated for completeness & acceptability Details of cask must be provided to NH Davison before licensing action can be completed ROUSE, L. C. Advanced fuel & Spent Fuel Licensing Branch 82/12/03 LEASBURG. R. H. Virginia Electric & Power Co. 2pp. 16523 361 24x Fiche 50-280, 82/12/03. 8212220170
- 8712220005 Forwards notice of consideration of matl license for storage of spent fuel transmitted to Ofc of FR for publication ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/06 LEASBURG.R H Virginia Electric & Power Co 2pp 16529 144 24% Fiche 50-280,82/12/06.8212220005
- --8212220007 Notice of consideration of matl license for storage of spint fuel ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 4pp 16529 146 24X Fiche 50-280,82/12/04,8212220005
- 8/12/230147 Notice of correction of typographical error in 8/21/209 FR notice re consideration of matls license for storage of spent fuel ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/10 2pp 16544 056 24X Fiche SO-280.82/12/10.8212230147
- DOCKET 50-281 SURRY POWER STATION. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8P12040138 Forwards supplemental SER addressing open items re App R, including approval of proposed mod concerning relocation of one charging pump.svc water pump % respective water source Facility in compliance w/App R requirements VARGALS A Operating Reactors Branch 1 82/11/18 STEWART. W L Virginia Electric & Power Co 7pp 16325 355 24X Fiche 50-280.82/11/18.8212040138
- 8212060338 Grants requested exemption from requirement of App R Section III 0 to 10CFR50 re installation of fixed fire suppression tys in control room VAROA.5 A Operating Reactors Branch 1 82/11/24 STEWART.W L Virginia Electric & Power Co 2pp 16323 345 24X Fiche 50-280,82/11/24,8212060338
- --8212060339 Exemptions from requirement of App R Section III G to 10CFR50 re installation of fixed fire suppression sys in control room EISENHUT, D G Division of Licensing 82/11/24 Virginia Electric & Power Co 3pp 16323
- 8212060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tech Specs re hours staff will be performing safety-related functions & audit frequency of station emergency plan
 STEWART. W L Virginia Electric & Power Co 82/12/01 DENTON, H R Office or Nuclear Reactor Regulation, Director 2pp 16312 112 24X Fiche 50-280,82/12/01.8212060303
- ---B212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of station emergency plan

 * Virginia Electric & Power Co 82/12/01 5pp 16312 114 24X Fiche 50-280,82/12/01.8212060303
- 8212070166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 LEWIS.R C Division of Project & Resident Programs 82/12/06 STEMART.W L Virginia Electric & Power Co 2pp 16359 236 249 Fichs 50-280.82/12/06.8212070164
- --8212070167 Forwards supplemental response to 821008 ltr re 820708 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 Response withheld (ref 100FR73 21)
 STEMART.W.L. Virginia Electric & Power Co 82/11/17
 O'REILLY, J. P. Region 2. Office of Director 1p 16357 238 .MX
 Fichs 50-280,82/12/06.8212070166

- -8212090175 Responds to NRC 820908 ltr re violations noted in IE Insp Repts 50-280/82-23 & 50-281/82-23 Corrective actions withheld (ref 10CFR73 21) LEFSBURG, R H Virginia Electric & Power Co 82/10/08 G'REICLY, J P Region 2. Office of Director 1p 16359 239 24X Fiche 50-280,82/12/04.8212090164
- --B212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 920816-20 & notice of violation Notice of violation & rept details withheld (ref 10CFR/3 21)
 LEHIS,R C Division of Project & Resident Programs 92/09/08
 LEASBURG,R H Virginia Electric & Power Co 2pp 16359 240 2/Fiche 50-280,82/12/06.8212090166
- --8212070185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Details withheld (ref 10CFR73 21) MODRE.D E Division of Engineering & Technical Programs 82/09/03 2pp 16359 242 24X Fiche 50-280.82/12/04.8212090166
- 82:12070419 Forwards addl info re status of emergency response facilities locations & constisupplementing 810601 & 820408 responses to Generic Lir 81-10 transmitting NWRE9-0474.per
- request
 STEMART.M L Virginia Electric & Power Co 92/12/06 DENTON, M R
 Office of Nuclear Reactor Regulation, Director 2pp 16364 276
 24x Fiche 50-000,82/12/06,6212090419
- 82:2150059 Forwards revised security drawings Drawings withheld (nef 100FR2 790)
 6TEMART.H L Virginia Electric & Power Co 82/12/09 DENTON.H R Office of Nuclear Reactor Pegulation, Director VARGA, S A Operating Reactors Dranch | 1p 16427 362 24X fiche 50-000, 82/12/09, 8212150059
- BP12170036 Releases public version of revised emergency plan implementing procedure FELTUN J M Division of Rules and Records 82/12/10 Docum Hanagement Branch 1p 16478 003 24X Fiche 50-280:82/12/10. 8212170036
- --B212170041 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 Oi. "Emergency Manager Controlling Procedure" STENART.N L Virginia Electric & Power Ca B2/12/O1 D'RETLLY.J P. Region 2. Office of Director ip 16478 004 24x Fiche 50-280.82/12/10.8212170036
- -9212170044 Public version of Revision 1 to Emergency Plan Implementing Procedure EPIP-1 Of, "Emergency Manager Controlling Procedure ' Procedure " COX.F H : SAUNDERS.R T - Virginia Electric & Power Co 3pp - 16478 005 - 24X Fiche 50-280,62/12/10,8212170036
- OP122P0281 Responds to util 821029 ltr re Revision 7 to security program Revision consistent u/10CFR50 54(p) provisions & acceptable Encl to 821028 ltr withheld (ref 10CFR73 21) VARGALS A Decrating Reactors Branch 1 82/12/10 STEWART, W Virginia Electric & Power Co 2pp 16523 307 24X Fiche 50-280.82/12/10.8212220281 STEWART, W L
- 8912220481 Forwards draft SER re App R exemption requests Just: fication Fixeeurol rorwards draft BEH re App R elemption requests Justific, that level of protection afforded by silsting fire protection measures in emergency switch gear rooms equivalent to App R requirements not provided VAROA. S A Operating Reactors Dranch 1 82/12/10 STEMART, W L Virginia Electric & Power Co 7pp 16523 192 24X Fiche 50~280, 82/12/10, 8212220481
- 8:12170024 Forwards request for add1 info re security training & qualification plans.per vtil 820917 ltr CLARK.R A Operating Reactors Branch 3 82/12/13 STEWART, W L Virginia Electric & Power Co 4pp 16480 335 24X Fiche 50-000.82/12/13.8212170024
- GP12170454 Releases public version of revised local govt radiological emergency response plans FELTON, J M Division of Rules and Records 82/12/13 Document Management Branch 1p 16479 [42 24X Fiche 50~280, 82/12/13, 8212170454
- ---8212170457 Forwards public version of revised local govt radiological emergency response plans for Counties of Surry, Isle of Hight-York & James City & Cities of Newport News & Williamsburg, VA SIEWART, W L. Virginia Electric & Power Co. 82/12/01 O'REILLY, J.P. Region 2. Office of Director ip 16479 144 24X Fichs 50-280,82/12/13,8212170454

- --8212170458 Public version of revised local govt radiological emergency response plans for Counties of Surry, Isle of Wight, York & James City & Cities of Newport News & Williamsburg, VA * Virginia Electric & Power Co 82/11/30 228pp 16479 145 24X Fiche 50~280,82/12/13,8212170454
- 8212300175 Responds to 821013 ltr re protection of safeguards info Safe acceptable, provided that safe located within protected area VARQA: B A Operating Reactors Branch 1 82/12/15 STEWART, W L Virginia Electric & Power Co 2pp 16612 329 24X Fiche 50-280, 02/12/15, 0212300195
- 82:2270179 Informs that although 82:1207 ltr forwarding security drawings failed to contain safeguards statement, drawings were properly secured, marked & identified as safeguards INFO
 STEWART, U. L. Virginia Electric & Power Co 82/12/20 DENTON, H.R.
 Offlice of Nuclear Reactor Regulation, Director VARGA, S.A.
 Operating Reactors Branch I ip 16539 010 24X
 Fiche 50-000, 82/12/20,8212270179
- P Operating license stage documents & correspondence
- B212040134 Forwards response to NRC 821026 questionnaire re steam generator tube integrity Data for each facility compiled in separate sections STEMART.W.L. Virginia Electric & Power Co. 82/12/01 DENTON, H.R. Diffice of Muclear Reactor Regulation. Director EISENHUT, D.Q. Division of Licensing. Spp. 16314-070 24X Fiche 50-000, 82/12/01, 8212060134
- BP12060284 Notifies that meither facility has addi Tech Spors to be submitted in response to Generic Ltr 82-14 re status of NUREO-0737 items BTEMART N. L. Virginia Electric & Power Co. 82/12/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director RISENHUT, D. G. Division of Licensing ip 16312-038 24% Fiche 50-000, 82/12/01, 16312-038 24% Fiche 50-0000, 82/12/01, 82/12/01, 82/12/01, 82/12/01, 82/12/01, 82/12/01, 82/12/01, 82/12/
- 8012060303 Application for amend to Licenses DPR-32 & DPR-37 Amend revises Tech Spacs re hours staff will be performing safety-related functions & audit frequency of station safety-related functions & about trequency or section comergency plan
 STEWART, W.L. Virginia Electric & Power Co. 82/12/01 DEN
 Office of Nuclear Reactor Regulation, Director VARGA, S.A.
 Operating Reactors Branch 1 2pp 16312 112 24X
 Fiche 50-280, 82/12/01, 8212060303 DENTON, H R
- --8212060315 Proposed Tech Spec changes re hours staff will be performing safety-related functions & audit frequency of # Virginia Electric & Power Co 82/12/01 5pp 16312 il4 24X Fiche 50-280, 82/12/01, 8212060303
- 8P12100012 Advises that Generic Issue 8-24 re containment purge & TMI Item II E 4 2 re containment isolation dependability complete Summary of review listed Tech Specs will be issued complete summary of review listed lech speck will be separately VAROA S A Operating Reactors Branch I 82/12/07 Virginia Electric & Power Co 3pp 16399 235 24 Fiche 50-280 82/12/07 8212100012 07 STEWART, W L 24X
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements forwards Science Applications: Inc draft rept re subj requirements Comments requested within 30 days of lir Svc list encl EISENHUT.D @ Division of Licensing 82/12/09 Conso Edison Co. of New York. Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263 Consolidated
- 8212130327 Advises of repair within ASME Class 2 sys boundary during 821207 maint outage Basis for request for relief from postrepair test requirements per ASME Section XI provided STEMART.W.L. Virginia Electric & Power Co. 82/12/09 DENTON, H.R. Uffice of Nuclear Reactor Regulation. Director VARGA, S.A. Operating Reactors Branch 1 2pp 16389 270 24X Fiche 50-281, 82/12/09, 8212130327
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENRUI, D 0 Division of Licensing 82/12/10 Yankee & Electric Co 27pp 16690 035, 24X Fiche 50-000,82/12/10,82121401032 Yankee Atomic Electric Co 8212140103
- 8212280073 Forwards theck in payment of fees for review of request for relief from requirements of ABME Section XI
 STEMART.W.L. Virginia Electric & Power Co. 82/12/21 DENTON.H R
 Office of Nuclear Reactor Regulation, Director VARGA.8 A
 Operating Reactors Branch i ip 16564 235 24X
 Fiche 50-281.82/12/21.8212280073

- 87:12280257 Forwards remittance for Invoice B-0063 for review of Amend A to Topical Rept VEP-1. "GA Program Operations Phase." submitted on 82:0921 & approved on 82:1006 STEWART. W L Virginia Electric & Power Co 82/12/22 DENTON, H R Office of Nuclear Reactions Regulation, Director BARRY, L W Division of Accounting ip 16561 267 24X Fiche 50-000.B2/12/22.
- B212280349 Forwards Class II fee to cover review of 821201 suppl to amend Licenses DPR-32 & DPR-37 STEMART.W.L. Virginia Electric & Power Co. 82/12/22 DENTON.H.R. Uffice of Nuclear Reactor Regulation. Director VARGA.S.A. Operating Reactors Branch 1 p. 16561 042 24X Fichs 50-280.82/12/22.8212280349
- B212290191 Informs that completion date, per 820823 supplemental response to Generic Ltr 82-05, "Post-Accident Sampling Sys." will be extended to 830601 Status rept expected in Mar 1983 STEWART.W L. Virginia Electric & Power Co. 82/12/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director & ISENNUT, D.O. Division of Licensing. 3pp. 16578-052 24X Fiche 50-280.82/12/27, 2010390181
- Q Inspection reports, IE Bulletins & correspondence
- ##12090267 Forwards IE Insp Repts 50~280/82~26 & 50~281/82~26 on ##21004~08 No noncompliance noted DANCE, H C Division of Project & Resident Programs ##82/10/26 LEASBURG, R H Virginia Electric & Power Co 2pp 16362 301 24X Fichs 50~280, 82/10/26, 8212090267
- --8212090277 IE Insp Repts 50-280/82-26 & 50-281/82-26 on 821004-08 No noncompliance noted Major areas inspected pape supports & restraints & Type B & C containment leakage rate tosting BROOKS.E H , JAPE.F Division of Project & Resident Programs 82/10/25 4pp 16362 303 24X Fiche 50-280.82/10/26.8212090267
- 82/08/90240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BKR Plants "Syc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000, 82/10/28,8208/90240
- 9712090285 Advises that GALP Repts 50-280/82-19,50-281/82-19,
 50-038/82-24 & 50-039/82-24 have been reviewed & approved
 Overall performance adequate No reply required
 O'REILLY, J P Region 2. Office of Director 82/11/03
 LEASBURO, R H Virginia Electric & Power Co 2pp 16365 208 24X
 Fichs 50-000, 82/11/03,8212090285
- --8212090306 SALP Repts 50-280/82-19.50-281/82-19.50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational GA * Region 2, Office of Director 82/08/04 31pp 16365 212 24X Fiche 50-000,82/11/03.8212090285
- 820B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BO1 & Model BO2 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000,82/11/05,820B190245
- 82/0819025] IE Info Notice 82-44, "Clarification of Emergency Plan I xercise Requirements " Svc list encl JORDAN, E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X Fiche 50-000 82/11/18,8208190251
- 8212090276 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-24 & 50-281/82-24 DANCE,H C Division of Project & Resident Programs 82/11/18 BTEHART,W L Virginia Electric & Power Co 1p 16365 270 24% Fiche 50-280.82/11/18,8212090275
- --8212090286 Responds to NRC 820929 ltr re violations noted in It Insp Repts 50-280/62-24 & 50-281/82-24 Corrective actions valve pit roofs covered w/fire retardant plastic & sealed STEWART,W L. Virginia Electric & Power Co. 82/10/29 O'REILLY, J.P. Region 2. Office of Director 3pp 16365 271 24X Fiche 50-280, 82/11/18, 8212090276

- --8212090300 Forwards IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0903 & notice of violation DAKCE.H C Division of Project & Resident Programs 82/09/29 LEASBURD.R H Virginia Electric & Power Co 2pp 16365 274 24X Fichs 50-280.82/11/18.8212090276
- ---8212090304 Notice of violation from insp on 820802-0903 * Division of Project & Resident Programs 82/09/27 16365 276 24% Fiche 50-280.82/11/18.8212090276
- --8212070313 IE Insp Repts 50-280/82-24 & 50-281/82-24 on 820802-0703
 Noncompliance noted roof leak caused by previous maint work
 degraded safety-related equipment
 BURKE.D J., DAVIS.M J., GRDERS.W J. Division of Project & Resident
 Programs 82/07/28 9pp 16365-277 24X Fiche 50-260, 62/11/18,
 8212070274
- G212090215 Ack receipt of 820716 % 1105 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 DANCE-H C Division of Project * Resident Programs 82/11/19 STEWART, W L Virginia Electric * Power Co ip 16362 279 247 Fiche 50-280.82/11/19,8212090215
- --8212090217 Responds to NRC 820607 ltr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions Administrative Procedure 56 re ignition sources amended to classify areas for purposes of controlling sources STEWART.UL Virginia Electric & Power Co 82/11/05 U/REILLY, J F. Region 2. Office of Director 2pp 16062 280 '4) Fiche 50-280.82/11/19.8212090215
- --B212090218 Responds to NRC B20607 itr re violations noted in IE Insp Repts 50-280/82-10 & 50-281/82-10 Corrective actions process vent sys mod designed & Administrative Procedure 56 amended re safety-related aroas LEASBURG.R H Virginia Electric & Power Co 82/07/16 O'REILLY, J P. Region 2. Office of Director 4pp 16362 282 247 Fiche 50-280,82/11/19,8212040215
- --8212090220 Confirms telcon re IE Insp Repts 90-280/82-10 & 90-281/82-10 Response will be submitted by 820717 LEASBURG, R H Virginia Electric V Power Co 82/07/06 O'REILLY, J P. Region 2. Office of Director ip 16362 286 24) Fiche 50-280,82/11/19,8212090215
- 8212090223 Forwards IE Insp Repts 50-280/82-10 to 50-281/82-10 on 820401-30 to notice of violation DANCE, H C Division of Project & Resident Programs 82/06/07 LEASBURGER H Virginia Electric & Power Co 2pp 16362 287 24X Fichs 59-280,82/11/19.8212090215
- ---8212090226 Notice of violation from insp on 820401-30 * Division of Froject & Resident Programs 82/06/07 2pp 16362 289 24X Fiche 50-280. 82/11/19.8212090215
- --8212070234 IE Insp Repts 50-280/82-10 & 50-281/82-10 on 820401-30 Nancampliance noted failure to failow fire protection program implementing procedures BURKE.D J. DAVIE.H J. JULIAN.C A Division of Project & Resident Programs 82/04/04 10pp 16362 271 24X Fiche 50-280, 82/11/19, 8212070215
- 8P08190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl BEYOUNG:R C Director's Office Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc. 354pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- GP12290060 Partial response to FD1A request for seven categories of info Forwards documents listed in App A Documents [& 2 already in PDR App B documents available in PDR LPDR profiles for Ginna % Indian Point 3 enc! FELTON.J M Division of Rules and Records 82/11/30 SCHLISBEL.D A New York, State of 7pp 16607 239 24X Fiche 50-000,82/11/30,8212290060
- --0212290170 Ack receipt of 761206 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/76-14 & 50-281/76-14 LONG, FJ Region 2, Atlanta, Reactol Operations Nuclear Support Branch 77/01/14 PROFFITT, W L Virginia Electric & Fower Co ip 16608 041 24% Fiche 50-000,82/11/30,8212290060

- --8212290172 Responds to NRC 761021 ltr re violation noted in IE Insp Repts 50-280/76-14 & 50-281/76-14 Corrective actions Administrative Procedure 29 redistributed & importance of proper documentation practices emphasized STALLINGS.C M Virginia Electric & Power Co 76/12/06 MOSELEY,N C Region 2, Atlanta, Office of the Director 4pp 16698 042 24X Fiche 50-000, 82/11/30,8212270060
- --8212270178 Forwards IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17 Noncompliance noted LONG, F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 76/10/21 PROFFITT, N.L. Virginia Electric & Power Co 2pp 16608 046 24X Fiche 50-000.82/11/30.8212290060
- --82:2290184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760915-17
 Noncompliance noted failure to follow log book entry &
 review & initial requirements specified in Administrative
 Procedure 29
 SINKULE, N V . LEMIS.R C . ROGERS.R F Region 2, Atlanta, Reactol
 Operations Nuclear Support Branch 76/10/19 13pp 16608 048
 24/ Fische 50-000.82/11/30.8212270060
- BPOB190259 IE Bulletin B2-04. "Deficiencies in Primary Containment Flectrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office, Defice of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc IISpp 1641: 317 24% Fiche 50-000. B2/12/03. B208190259
- 8:08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay fockets " Sic 1(st encl JORDANIE L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Liche 50-000.82/12/03.8208190261
- 0./12090166 Ack receipt of 821008 & 1117 ltrs informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 LEMIS.R C Division of Project & Resident Programs 82/12/06 STEWART.W L Virginia Electric & Power Co 2pp 16359 236 24X Fiche 50-280, 82/12/04,8212090166
- -8212090169 forwards supplemental response to 821008 ltr re 820908 IE Safeguards Insp Repts 50-280782-23 & 50-281782-23 Response withheld (ref (0CFR73 21) STEWART.W L Virginia Electric & Power Co 827[1/17 O'REILLY, J P Region 2, Office of Director Ip 16359 238 24x Fiche 50-280,827[2/06,82[2090]166
- -0212090175 Responds to NRC 820908 ltr re violations noted in IE Insp. Repts 50-280/02-23 & 50-281/02-23 Corrective actions withheld tref 100FR73 21)

 LEASBURG.R H Virginia Electric & Power Co 82/10/08

 O'REILLY, J P Region 2, Office of Director ip 16359 239 P4x
 Fiche 30-280,82/12/06.8212090166
- -8212090180 Forwards IE Safeguards Insp Repts 50-280/82-23 & 50-281/ 82-23 on 820816-20 & notice of violation Notice of violation & rept details withheld (ref 100FR73 21) LENIS.R C Division of Project & Resident Programs 82/09/08 LEASBURG.R H Virginia Clectric & Power Co 2pp 16359 240 24. Fiche 80-280.82/12/06.8212090166
- --8212070185 IE Safeguards Insp Repts 50-280/82-23 & 50-281/82-23 on 820816-20 Noncompliance noted failure to control access to defensive position & to equip personnel w/communication devices for vital areas Datails withheld (ref 10CFR/3 21) MOGRED E , MCGUIRE, D R Division of Engineering & Technical Programs 82/09/03 2pp 16359 242 24X Fiche 50-280,82/12/06,8212090166
- 8/12220276 Advises that 821207 request for relief from 1977 ASME Section XI requirements for inservice insp hydrostatic tests granted Relief allows replacement of 1 9-inch drain valves upstream of main steam trip valve w/o performing test VARCALS A Operating Reactors Branch 1 82/12/10 STEWART, W L Virginia Electric & Power Co. 3pp 16523 258 24X Fiche 50-281, 82/12/10, 821/220276
- --G212R20299 Notice of granting of relief from ASME Code Section XI inservice insp requirements VAROA/S A Operating Reactors Branch 1 G2/12/10 2pp 16523 261 24X Fiche 50-281, G2/12/10, G212220296
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list and!
 DEYOUNG:R C Director's Office Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc. 127pp 16628 191 24X Fithe 50-000.82/12/16.8208190267

- 82/08170268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Helays Type ITE-27" Svc list encl JORDAN: EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000: 82/12/20: 8208190268
- 8212290459 Forwards "Inservice Insp Program Interval 2.830429-930428 "
 STEWART W L. Virginia Electric & Power Co 82/12/27 DENTON H R
 Office of Nuclear Reactor Regulation, Director EISENHUT, D 9
 Division of Licensing ip 16583 273 24X Fiche 50-281,82/12/27,
 B212290459
- --8212290474 "Inservice Insp Program, Interval 2,830428-930428"
 * Virginia Electric & Power Co 82/12/22 397pp 16583 274
 24% Fithe 50-281,82/12/27,8212290459
- R Periodic operating reports & related correspondence
- BP12290238 Forwards monthly operating repts for Oct 1982 & corrected page to monthly operating rept for Sept 1982 W/o corrected page STEWART.W L Virginia Electric & Power Co. 82/11/15 HALLER,N N Defice of Resource Management, Director Ip 16582 116 24X Fiche 50-280.82/11/15, 8212290238
- --8212290244 Monthly operating repts for Oct 1982 JONES, V Virginia Electric & Power Co 82/11/05 52pp 16582 117 24X Fiche 50-280, 82/11/15,8212290238
- S Reportable occurrences, LERs & related correspondence
- 8712070084 Forwards LERs 82-110/03L-0 \$ 82-060/03L-0 WILSON, J. Virginia Electric & Power Co 82/11/30 O'REILLY, J.F. Regian 2, Office of Director ip 16387 180 24X Fiche 50-280, 82/11/30, 8212070086
- --B212070078 LER 82-060/03L-0 on 821102 charging pump avo water pump 2-5N-P-10B experienced loss of suction pressure Caused by insufficient NPBH Pump vented to restore NPBH WILSON, J.L. Virginia Electric & Power Co. 82/11/30 Region P Office of Director. 3pp. 16357-105. 24X Fiche 50-280,82/11/30,8212090884
- G/12270060 Partial response to FOIA request for seven categories of info Forwards documents listed in App A Documents 1 & 2 already in PDR App B documents available in PDR LPDR profiles for Oinna & Indian Point 3 encl FELTON. J M Division of Rules and Records 82/11/30 SCHLISSEL, D A New York, State of 7pp 16607 239 24X Fiche 50-000,82/11/30,8212270060
- --8212290085 RO 76-05 on 760915, pressurizer level fell below 45% level setpoint, resulting in decreases of pressurizer pressure & vol control tank level Caused by leaking tube in steam generator A Cause of tube failure will be evaluated STACLINGS.C M Virginia Electric & Power Co 76/09/29 MGSELEY.N C Region 2. Atlanta. Office of the Director 5pp 16607 278 24% Fiche 50-000, 82/11/30, 8212290060
- BP12070130 Forwards LERs 82-068/03L-0,82-065/03L-0 & 82-067/03L-0 WILSON J L Virginia Electric & Power Co 82/12/03 O'REILLY, J P Region 2, Office of Director in 16359 181 24X Fiche 50-281,82/12/03,8212070130
- --0212090134 LER 82-069/03L-0 on 821106, charging pump syc water pump 2-5M-P-10A failed to develop sufficient discharge pressure Caused by corroded carbon steel stud on packing gland housing & lack of NPSM Packing matl & studs replaced W1L5DM JL Virginia Electric & Power Co 82/12/03 Region 2, Office of Director 3pp 16359 182 24X Fiche 50-281,82/12/03,8212090130
- --8212090137 LER 82-069/03L-0 on B21104, charging pump svc water pump 2-SH-P-10B experienced loss of suction pressure Caused by insufficient NPSH Pump vented to restore NPSH WILSON, J. Virginia Electric & Power Co 82/12/03 Region 2, Office of Director 3pp 16359 185 24X Fiche 50-281, 82/12/03, 8212090130
- --B212070144 LER 82-068/03L-0 on 821112, during performance of PT 18 69, TV-CC-2098 would not close when manually operated from control room Caused by sticking pilot valve that controls air flow from valve actuator Pilot valve replaced WILSON, J L. Virginia Electric & Power Co. 82/12/03 Region 2, Office of Director 3pp 16359 188 24X Fiche 50-281,82/12/03,8212070130
- 8212150067 Forwards LER 92-067/03L-0. WILSON, J. Virginia Electric & Power Co 82/12/09 D'REILLY, J.P. Region 2, Office of Director 1p 16431 021 24X Fichs 50-281, 82/12/09, 8212150067

- --8212150087 LER 82-067/03L-0 on 821109, w/unit at full power, electrical fire barrier penetration found improperly sealed Cause unknown Fire watch established & penetration temporarily sealed Permanent sealing to be completed by 830101 WH.SON, J. Virginia Electric & Power Co. 82/12/09 Region 2. Office of Director 2pp 16431 022 24X Fiche 50-281,82/12/09, 8212190647
- 6P12210365 Forwards LERs 82-070/03L-0.82-113/03L-0 & 82-116/03L-0 WILSON, J. L. Virginia Electric & Power Co 82/12/13 0'REILLY.J.P. Region 2, Office of Director 1p 16494 278 24X Fiche 50-280.82/12/13.8212210365
- --9212210393 LER 92-070/03L-0 on 921119, routine walkdown of svc bldg revealed open barrier penetration w/no fire watch posted Caused by removal of temporary seal on penetration fire watch posted Penetration resealed WILSON, J L Virginia Electric & Power Co 82/12/13 Region 2, Office of Director 2pp 16494 279 24X Fiche 50-280, 82/12/13, 8212210365
- 8212280126 Forwards LERs 82-105/03L-0,82-117/03L-0 & 82-072/03L-0 WILSON, J. L. Virginia Electric & Power Co. 82/12/17 O'REILLY, J.P. Region 2, Office of Director 1p 16562 306 24X Fiche 50-280,82/12/17,8212280126
- --B212280206 LER B2-072/03L-0 on B21126, amplifier readings heat tracing panel 11.crcult 2A.fell below acceptance criteria Caused by overheating due to maladjusted thermostat Defective heat tracing replaced & tested HILSON.J. Uriginia Electric & Power Co B2/12/17 Region 2 Office of Director 2pp 16562 312 24X Fiche 50-280,82/12/17, REJEROLDA
- Y Dry Cask Independent Spent Fuel Storage Installations
- CP12220170 Advises that application for dry cask ISFSI docketed on B21015 Application avaluated for completeness & acceptability Details of cask must be provided to NH Davison before licensing action can be completed ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 LEASBURG.R H Virginia Electric & Power Co 2pp 16523 361 24X Fiche 50-280.82/12/03.8212220170
- 8P12220005 Forwards notice of consideration of matilicense for storage of spent fuel transmitted to Ofc of FR for publication ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/06 LEASBURG.R H Virginsa Electric & Power Co 2pp 16529 144 24X Fiche 50-280, 82/12/06, 8212220005
- --G212220007 Notice of consideration of matl license for storage of spent fuel ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 4pp 16529 146 24X Fiche 50-280,82/12/06,8212220005
- G212230147 Notice of correction of typographical error in 821209 FR notice re consideration of matls license for storage of spent fuel ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/10 2pp 16544 056 24X Fiche 50-280, 82/12/10, 8212230147
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- GP12030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 620921-1031 No nancompliance noted BY STREETER, J F Division of Project & Resident Programs 62/11/17 LARSON, C E Northern States Power Co 2pp 16306 031 24X Fiche 50-282, 82/11/17, 8212030134
- --8212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs FEIERABEND, C D , REYES, L Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134
- 8212210329 Forwards IE Insp Repts 50-282/82-18 & 50-304/82-18 on B21013-15 & 1109 No noncompliance noted HIND J A Division of Emergency Preparedness & Operational Support B2/12/02 LARSON, C E Northern States Power Co 3pp 16496 229 24X Fichs 50-282,82/12/02,82122/0329
- --B212210340 IE Insp Repts 50-282/82-18 % 50-306/82-18 on 821013-15 % 1109 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr PATTERSON, J P. LICKUS, R M. AXELSON, W L. Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 23P 24% Fiche 50-282,82/12/02,8218210329

- BP12140279 Requests exemption,under 10CFR50 48(c)(b), from automatic suppression requirement of App R. Section III & 3 for control room MUSDLF, D. Northern States Power Co. B2/12/06 Office of Nuclear Reactor Regulation, Director 3pp 16402 104 24X Fiche 50-262.82/12/06.8212140279
- 8P12220045 Advises that 820520 & 0823 exemption requests granted extending deadline for installation of emergency lighting until 830101 Add1 time needed to complete engineering analysis, procurement & installation EISENNUT, D @ Division of ticensing 82/12/08 MUSOLF, D M Northern States Power Co 4pp 16526 355 24X Fithe 50-282,82/12/08,8212220045
- --B212220048 Exemption granting extension for installation of emorgency lighting until B30101 DENTON-H R Office of Nuclear Reactor Regulation, Director B2/12/08 Northern States Power Co 7pp 16526 359 247 Fiche 50-282,82/12/08,8212220045
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J G Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24% Fiche 50-000, 82/12/16, 131123/2004
- BP12300412 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/22 Document Management Branck ip 14613 075 24X Fiche 50-262,82/12/22, PD12300412
- --8212300416 Forwards public version of revised Emergency Plan Implementing Procedures F3-5 re emergency notifications. F3-10 re personnel accountability & F3-23 re emergency sampling WARD.E.C. Northern States Power Co. 82/12/15. Region 3, Office of Director ip 16613-076 24X Fiche 50-282.82/12/22, 82/12/30412
- --B212300417 Public version of Emergency Plan Implementing Procedures F3-5 re emergency notifications.F3-10 re personnel accountability & F3-23 re emergency sampling SCHUELKE.D A Northern Status Power to 62/11/04 102pp 16613 077 24X Fiche 50-282.62/12/22.6212300412
- P Operating license stage documents & correspondence
- BP12090057 Forwards Revision I to 750847 license amend request to change Tech Specs re containment leakage rate testing, incorporating required changes No fee appropriate since request submitted earlier
 MUSDLF.D. Northern States Power Co. 82/12/03. Office of Nucliar Reactar Regulation. Director Ip. 16399 041—24X
 Fiche 50-282,82/12/03.8212090057
- --B212090059 Revision 1 to 750807 license amend request to change Trch Spec re containment leakage rate testing MUSDLF.D Northern States Power Co B2/12/03 20pp 16359 042 244 Fiche 50-282, 82/12/03,8212090057
- BP12090172 Forwards add1 info re methods of compliance w/NUREG-0737.

 Item II B 3 on post-accident sampling sys.in response to B20908 request

 MUSDLF, D Northern States Power Co B2/12/03 Office of Nuclear Reactor Regulation, Director 11pp 16359 221 24X Fiche 50-282,82/12/03,B212070172
- 8708190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re sub, requirements Comments requested within 30 days of ltr Svc list encl LISE(N-UT, D 0 Division of Licensing 82/12/07 Consolidated Edison Co of New York. Inc 27pp 16627 247 24X fiche 50-000,82/12/09.8208190263
- 8212140411 Forwards summary of NRC review of Exxon Nuclear Co thermal hydraulic methodology for mixed cores in PWRs Encl TOPROD sensitivity & thermal margin studies submitted on 820618 & 29, respectively, remain valid Comments requested COOKE, O C Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/12/09 MOLDNICH, J J Core Performance Branch 7pp 1640J 382 24X Fiche 50-282,82/12/09,8212140411
- 87:2140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One,Unit 2 & 8an Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EIBENHUT, D 0 Division of Licensing 82/12/10 Yankee Atomic EIBENHUT, D 0 Division of Licensing 82/12/10 Onother Beauty Struck Society 16/90 035 24% Fiche 50-000,82/12/10,82(2):140103

- 8F:12170262 Responds to 821106 request for ECCS model specifically treating upper plenum injection Exion model will be ready for submittal by 830131 MUSOLF.D. Northern States Power Co. 82/12/10 Office of Nuclear Reactor Regulation. Director 1p 16455-207 24% Fichs 50-282.82/12/10,8212170262
- 0:12210290 Forwards NSPNAD-B101P, Revision 1. "Qualification of Reactor Physics Methods for Application to Prairie Island Units." & NSPNAD-B102P, Revision 1. "Reload Bařety Evalvation Methods for Application " Repts withheld (ref 10CFR2 790) MUSQLF, D. Northern States Power Co. 82/12/13 Office of Nuclear Regulation, Director 1p. 16497-134 24X (1che 50-282, 82/12/13, 8212210290
- 4 Inspection reports. IE Bulletins 2 correspondence
- 8:08190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall. Large-Diamoter: Stainless Steel. Recirculation Sys Piping at BWR Plants " Syc list encl DEYGUNG. R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 82'08190245 IE info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermojuminescent Dosimeters." Svc. list oncil COBB.L. I Division of Fuel Facilities, Materials & Safeguards 62211/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 24x Fiche 50-000.82/11/05.8208190245
- 8212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1031 No noncompliance noted STRETER. JF Division of Project & Resident Programs 82/11/17 LARSON.C E Northern States Power Co 2pp 16306 031 24X Fichs 50-282,82/11/17,8212030134
- 8212030150 iE Insp Repts 50-282/82-17 & 50-306/82-17 on 820921-1931 No noncompliance noted Major areas inspected preparation for refueling fire drills & exercises operations safety verification followup on fuel oil spill & followup on LERs FIERABEND. O . REYES.L Division of Praject & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282.82/11/17,8212030134
- 80:08190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 243 [iche 50-000.82/11/18.8208190251]
- 80:08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocts" Svc list enc! UEVOUVO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- B208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Mati " Svc list encl (LOBBL I Division of Fuel Facilities, Materials & Safeguards (B2711/30) Consolidated Edison Co of New York, Inc. 356pp 16387 028 24Y Fiche 50-000, 82/11/30, 8208190257
- G:12210329 Forwards IE Insp Repts 50-282/82-18 % 50-306/82-18 on G21013-15 % 1109 No noncompliance noted HIND. A Division of Emergency Préparedness & Operational Support B2/12/02 LARSON.C E Northern States Power Co 3pp 16496 229 :44 Fiche 50-282/82/12/02.821/22/0329
- B212210340 IE Insp Repts 50-282/82-18 % 50-304/82-18 on 821013-19 % 1109 No noncompliance noted Major areas inspected emergency exercise especially command & control of control room, technical support ctr & operations support ctr PATTERSON.J P. LICKUS.R M. AXELSON.W L Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 232 24(Fiche 50-282.82/12/02,8212210329
- BJ'08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl BEYOUNG:R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 80:08190261 [E Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche 50-000, 62/12/03, 8208190261

- 8:12270292 Forwards IE Insp Repts 50~282/82-19 & 50~306/82-19 on #21126 No mancompliance noted LITILE:W S Division of Engineering & Technical Programs 82/12/10 LARSDN.C E Northern States Power Co 2pp 16530 122 24X Fiche 50~282, 82/12/10, 8212270292
- --B212270305 IE Insp Repts 50-282/B2-i9 & 50-306/B2-i9 on B21126 No noncompliance noted Major areas inspected review of inservice insp procedures.NDE personnel certifications & data & IE Bulletin 78-i2 activities MARDA D . DANIELSON.D H Region 3, Office of Director 4pp 16530 124 24X Fiche 50-282,82/12/10,8212270292
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 14628 191 24X Fiche 50-000.82/12/16.8208190247
- G212280325 Responds to IE Bulletin 82-04 No electrical penetration assemblies referenced in bulletin in use or planned for use in eafety-related sys LARSDN,C E Northern States Power Co 82/12/17 KEPPLER,J G Region 3. Diffice of Director ip 16562:087 24X Fiche 50-282,82/12/17,6212280325
- 8208190248 IE Info Natice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Evc list encl JARDAN,E L Division of Engineering & Quality Assurance 92/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X Fiche 50-000.82/12/20.8208190248
- S Reportable occurrences, LERs & related correspondence
- 82)2020311 Forwards LER 82-020/03L-0 MUSDLF, D. Northern States Power Co. 82/11/24 Region 3. Office of Director 1p. 16291 003 24X Fiche 50-282,82/11/24,8212020311
- --8212020317 LER 82-020/03L-0 on 82102A.during surveillance test.
 auxiliary bidg special vent sys PAC filter 121 exhibited DOP
 removal efficiency of 98 6%. less than Tech Specs
 requirement Caused by ioose filters Filters tightened
 HUMSTAD.A A Northern States Power Co 82/11/24 Region 3.
 Office of Director ip 16291 004 24X Fiche 50-282.82/11/24,
 8212020311
- 8P12080420 Forwards LER 82-022/03L-0 MUSCLF.D Northern States Power Co 82/11/30 Region 3, Office of Director 1p 16352 178 24X Fiche 50-282,82/11/30,8212080420
- --8212080427 LER 82-022/03L-0 on 821112 during power operation control power lost to dissel cooling water pump 22 rendering pump inoperable Gaused by loose fuse clip Clip repaired & pump tested satisfactorily HUNSTAD. A A Northern States Power Co 82/11/30 Region 3, Dffice of Director ip 16352 177 24X Fiche 80-282,82/11/30 8212080420
- DDCKET 50-285 FORT CALHOUN STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8P12070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3, 5 & 7) FELTON, J M Division of Rules and Records 82/11/03 MCGARRY, J M Debevoise & Liberman 5pp 16355 003 24% Fiche 50-000,82/11/05,8212070425
- --8212070473 Concludes that all Region 4 licensess in compliance w/820201 deadline for implementation of prompt notification sys COLLINS.J T Region 4. Office of Director 82/02/01 GRIMES.B K Division of Emergency Preparedness 2pp 16355 104 24X Fiche 50-000, 82/11/05, 8212070425
- 8212200022 Forwards IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted SEIDLE W C Division of Resident, Reactor Project & Engineering Programs 82/11/09 JONES W C Omaha Public Power District 2pp 16473 095 24X Fiche 50-285/82/11/08/8212200022
- ---B212200033 IE Insp Rept 50-285/82-23 on 620913-16 No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures & review of appropriate licensee documents MONFOOMERY. J. L. JOHNSON. W. D. Division of Resident, Reactor Project & Engineering Programs 82/11/04 11pp 16473 097 24X Fiche 50-285, 62/11/08, 8218200022

- 8212010236 Advises that Revision 11 to physical security plan acceptable NRC must be notified within 2 months of plan change Encls to 820827 1tr withheld (ref 10CFR73 21) CLARK.R A Operating Reactors Branch 3 82/11/24 JONES.W C Omaha Public Power District 2pp 16290 310 24X Fichs 50-285.82/11/24.8212010236
- 82120B0380 Documents info provided by 821202 telcon re plant emergency operations facility (EOF) Communications will be installed within 2 months In interim.temporary EOF operational JONES.W C Omaha Public Power District 82/12/03 CLARK.R A Operating Reactors Branch 3 2pp 14392 287 24X Fiche 50-285.82/12/03.8212080380
- 8P12100227 Discusses IE Emergency Preparedness Appraisal Rept 50-285/81-35 on 820918 Rept contains comments re technical support ctr operation which should be reviewed SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/12/07 JONES.W C Omaha Public Power District ip 16374 170 24% Fiche 50-285.82/12/07.8212100227
- --B212100244 Advises that util officially declared permanent technical support ctr operational on 820912, in response to findings re IE Emergency Preparedness Appraisal Rept 30-285/81-35 JONES W C Omaha Public Power District 82/10/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs Ip 16376 171 24X Fiche 50-285,82/12/07.8212100227
- B212130312 Responds to 821030 Generic Ltr 82-23 re inconsistency between requirements of 10CFR73 40(d) & STS concerning independent reviews of safeguards contingency programs No Tech Spec changes necessary Audit controls in place JONES, W C Omaha Public Power District B2/12/07 EISENHUT, D G Division of Licensing 2pp 16389 319 24X Fiche 50-285,82/12/07,8212130312
- 8912210021 Ack receipt of 820818 ltr responding to NRC 820625 BALP rept 50-287/81-37 CDLLINS.J T Region 4, Office of Director 82/12/14 JONES.W C Omaha Public Power District ip 16490 191 24X Fiche 50-285.82/12/14.8212210021
- --8212210022 Responds to recommendations noted in NRC 820625 SALP Rept 50-287/81-37 Corrective actions station fire protection revised in Mar 1982 to include mgt responsibility & quarterly fire brigade drills initiated JONES.H C Quaha Public Power District 82/08/18 SEIDLE.H C Division of Resident, Reactor Project & Engineering Programs App 16470 192 24X Fiche 50-285.82/12/14,8212210021
- P Operating license stage documents & correspondence
- B212010458 Forwards safety evaluation & technical evaluation rept.

 "Improvements in Training & Requalification Programs as
 Required by TMI Action Items I A 2 I & II & 4 " Upgraded
 reactor & senior reactor operator programs acceptable
 CLARK.R A Operating Reactors Branch 3 NRC-03-82-096 82/11/17
 JUNES,W C Danka Public Power District 2pp 16270 270 24X
 Fiche-50-285,82/11/17,8212010458
- --B212010464 Safety evaluation supporting upgraded reactor & senior reactor operator training & training to mitigate core damage per NUREG-0737 Items I A 2 1 & II B 4

 * Operating Reactors Branch 3 82/11/17 3pp 16270 272 24X Fiche 50-285,82/11/17,8212010458
- --8207080445 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4." technical evaluation rept

 * Science Applications, Inc NRC-03-82-096 SAI-186-029-25, B2/07/01 NRC No Detailed Affiliation Given 15pp 16270 275, 24X Fiche 50-285, 82/11/17,8212010458
- 82:12020093 Forwards response to congressional request for info (Generic Ltr 82-22) re steam generator tube integrity Only tube-related problems addressed JONES, W.C. Omaha Public Power District 82/11/22 EISENHUT, D.G. Division of Licensing, 3pp 16272-025 24X Fiche 50-285, 82/11/22, 02:12020093
- B212020119 Notifies that util decided to pursue approval for installation of revised apent fuel storage rack design which will utilize combination of Boraflex & non-Boraflex racks Revised application will be submitted by B30101 UNNES. W C Omha Public Power District B2/11/23 CLARK,R A Operating Reactors Branch 3 2pp 16272 031 24X Ficher 50-285,82/11/23,8212020119

- 8P12060028 Forwards application for amend to License DPR-40, changing Tech Specs to incorporate necessary safety limits & limiting conditions for operation for Cycle 8 Certificate of Sveence
- * LeBosuf, Lamb, Leiby & MacRae * Omaha Public Power District B2/11/24 DENTON, H R Defice of Nuclear Reactor Regulation, Director 19 16311 181 24X Fiche 50-285,82/11/24,8212060028
- --8212060032 Application for amend to License DPR-40, changing Tech Specs to incorporate necessary safety limits & limiting conditions for operation for Cycle 8

 JONES, W.C. Chana Public Power District 82/11/22 2pp
 16311 183 24X Fiche 50-285, 82/11/24,8212060028
- --8212060035 Proposed Tech Spocs resafety limits & limiting safety sysettings
- * Omaha Public Power District 82/11/22 201pp 16311 185 24x Fiche 50-285,82/11/24,8212060028
- GP1206043B Forwards info re evaluation of raw water pump, charging pump & containment ventilation fan motors
 JONES, M C Omaha Public Power District 82/12/01 CLARK, R A
 Operating Reactors Branch 3 8pp 16311 001 24X
 Fiche 50-285,82/12/01,8212040438
- 8212070419 Advises that post-accident sampling sys inoperable as of 821130.per TMI Action Item II B 3 Minor software problem identified in microprocessors during 821127 final sys checkout Bys expected to be operational by 830103
 JONES, W C Dmaha Public Power District 82/12/01 CLARK, R A Operating Reactors Branch 3 ip 16336 351 24X
 Fiche 50-285,82/12/01.8212070419
- BP12060254 Forwards responses to NRC 820714 ltr re criteria for NUREO-0737, Item II B 3, "Post-Accident Sampling Sys " One oversize drawing encl Aperture card is available in PDR JONES, H C Domaha Public Power District 82/12/03 CLARK, R A Operating Reactors Branch 3 18pp (6312-121 24X Fiche 50-283, 82/12/03, 8212060254
- GPOB190263 Generic Ltr 82-32 to all PMR licensees re potential steam generator-related generic requirements Forwards Ecience Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT.D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16627 247 24X Fiche 50-000.62/12/09.8208190263
- G212140416 Forwards responses to NRC B21012 audit findings & recommendations on procedures & training re pressurized thermal shock
 JONES, W.C. Omaha Public Power District B2/12/09 CLARK, R.A. Uperating Reactors Branch 3 3pp 16403 315 24X [iche 50-285, B2/12/07, B212140416
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear Dne;Unit 2 & San Oboffee 2 & 3) re inadequate core cooling instrumentation sys Svc list enc C EISENHUT.D 0 Division of Licensing 82/12/10 Yankee Atomic EISENHUT.D 0 27pp 16690 035 24% Fiche 50-000,82/12/10, 9212140103
- 8P12210197 Forwards response to 821013 request for add1 info re NUREO-0737. TMI Action Item II K 3 25. "Power to Reactor Coolant Pump Seals " Thermal barrier HX type sys utilized JONES, W C Omaha Public Power District 82/12/17 CLARK, R A Operating Reactors Branch 3 3pp 16484 329 24X Fiche 50-285.82/12/17.8212210199
- 8212280197 Provides status of NUREG-0737.1tem II B 3. "Post-Accident Sampling Bys " Schedule revised to factor in need for RCB operation New schedule for operation projected 3 months following end of refueling outage

 JONES.W C Omaha Public Power District 82/12/17 CLARK,R A Operating Reactors Branch 3 2pp 16962 091 24X

 Fiche. 50-285, 82/12/17, 8212280197
- B212230317 Forwards application for amend to License DPR-40, allowing operation of plant at nominal reactor core level of 1,500 MHC Class III amend fee encl # LeBoeuf, Lamb, Leiby & MacRae # 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director Ip 16507 310 24X Fiche 50-285, 82/12/22, 8212230317
- --8212230326 Application to amend ticense DPR-40.allowing operation of plant at mominal reactor core power level of 1.500 MMt JONES W C Omaha Public Power District 82/12/21 5pp 16507 311 24X Fiche 50-285.82/12/22.8212230317

Q Inspection reports: IE Bulletins & correspondence

- BP08190240 IE Bulletin 82-03. Revision i, "Stress Cracking im Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24x Fiche 50-000.82/10/28.8208190240
- B208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svt list contl
 COBB.L J Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 244 Fiche 50-000, 82/11/05.8208190245
- G212200022 Forwards 1E Insp Rept 50-285/82-23 on 820913-16 No moncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/08 JONES, W C Omaha Public Power District 2pp 16473-095 24X Fiche 50-285,82/11/08,8212200022
- U212200033 IE Insp Rept 50-285/82-23 on 820913-16 No noncompliance noted Major areas inspected licensee performance to capabilities during full-scale expectise of emergency plans to procedures to review of appropriate licensee documents MONIGOMERY, J. L. JOHNSON, W.D. Division of Resident, Reactor Project to Engineering Programs 82/11/04 11pp 16473 097 24% Fiche 50-285,82/11/09,8212200022
- 9212100228 Forwards IE Insp Rept 50-285/82-20 on 820907-10 No moncompliance noted SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 82/11/09 JONES.W C Gmaha-Public Power District 2pp 15376-172 24X Fiche 50-285,82/11/09,8212100228
- --B21210023 IE Insp Rept 50-289/82-20 on B20907-10 No nencompliance noted Major areas inspected environ protection programs for operations including organization & administration, audits & radiological environ.chemical & thermal monitoring WILBORNL . CHANEY, H D . MURRAY, B . Region 4, 9ffice of Director 62/11/01 14pp 16976 174 24X Fiche 50-285,62/11/09,0212100428
- 8P12030104 Forwards IE Insp Rept 50-285/82-24 on 821018-22 No noncompilance nated GEIDLE-W C Division of Resident, Reactor Project & Engineering Programs 82/11/14 JONES.W C Omaha Public Power District 2pp 16303 194 24X Fiche 50-285.82/11/14.8212030104
- GP12030119 Forwards IE Insp Rept 50-285/82-25 on 821001-31 No noncompliance noted SEIDLE-W C Division of Resident, Reactor Project & Engineering Programs 82/11/17 JONES-W C Omaha Public Power District 2pp 16303 008 24X Fiche 50-285,82/11/17,8212030119
- --8212030126 IE Insp Rept 50-295/82-25 on 821001-31 No noncompliance noted Major areas inspected operational safety verification, surveillance testing maint & plant operations YANDELL. A . JOHNSON W D Division of Resident, Reactor Project & Engineering Programs 82/11/15 4pp (6303-010-24X Fiche 50-285,82/11/17,8212030119
- B:'OB190251 IE Info Notice B2-44. "Clarification of Emergency Plan Frencise Requirements " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 14411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8Pi2070145 Ack receipt of 821101 itr transmitting 830101 schedulo for implementation of 3-yr 9A audit matrix. In response to IE Performance Appraisal Rept 50-285/81-24 Schedule acceptable SEIDLE.N C Division of Resident, Reactor Project & Engineering Programs 82/11/22 JONES.U C Omaha Public Power District Ip 16327 041 24X Fiche 50-285.82/11/22.8212070145
- --B212070150 Notifies that util new QA audit matrix will be implemented by 830101, in response to IE Performance Appraisal Rept 50-285/81-24 JONES, WC Omaha Public Power District B2/11/01 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 16327 042 24% Fiche 50-285, 82/11/22, 8212070145

- B208190256 IE Info Notice 82-46, "Befective & Obsolete Combination Padlocks" Svc list encl DEVOUND: R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8:08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 8212060266 Forwards inservice insp program plan for 1980-1983, incorporating changes & additions since 780928 transmittal JONES, W.C. Omaha Public Power District 82/12/01 CLARK, R.A. Operating Reactors Branch 3 2pp 16312 318 24x Jiche 50-285, 82/12/01.8212060266
- --8212060268 Inservice insp program plan for 1980-1983 * Omaha Public Power District 82/08/31 51pp 16312 322 24x Fiche 50-285,82/12/01.8212060266
- 85/08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Bvc list encl BEYDUNO:R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03,8208190259
- 82°08190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets" Syc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edisan Co of New York, Inc 110pp 16462 064 24) Fiche 50-000,82/12/03.8208190261
- GP12100227 Discusses IE Emergency Preparedness Appraisal Rept 50-285/81-35 on G20915 Rept contains comments re technical support ctr operation which should be reviewed GEIDLE.W C Division of Resident, Reactor Project & Engineering Programs 82/12/07 JUNES.W C Omaha Public Power District 1p 16376 170 24X Fiche 50-285, 82/12/07.8212100227
- --G212100244 Advises that util officially declared permanent technical support ctr operational on S20912.in response to findings re IE Emergency Proparadness Appraisal Rept 50-285/81-35 JONES.W C Omaha Public Power District 82/10/18 SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs ip 16376 171 24X Fiche 50-285,82/12/07,8212100227
- BP12210021 Ack receipt of 820818 ltr responding to NRC 820825 SALP rept 50-287/81-37 COLLING. J T Region 4. Office of Director 82/12/14 JONES.W C Camba Public Poper District 1p 16490 191 24X Fiche 50-285.82/12/14.8212210021
- --8212210022 Responds to recommendations noted in NRC 820625 SALP Rept 50-287/81-37 Corrective actions station fire protection revised in Mar 1982 to include mpt responsibility & quarterly fire brigade drills initiated JUNES. N C Omaha Public Power District 82/08/18 SEIDLE. W C Division of Resident. Reactor Project & Engineering Programs Δρ 16490 192 24X Fiche 50-285,82/12/14.8212210021
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16.8208190267
- BP:08190268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000 82/12/20,8208190268
- R Periodic operating reports & related correspondence
- 89:12200059 Forwards monthly operating rept for Nov 1982
 JONES W C Umaha Public Power District 82/12/13 DEYOUNG, R C
 Director's Office, Office of Inspection and Enforcement ip
 16473 304 24X Fiche: 50-285, 82/12/13, 8212200059
- --B212200064 Monthly operating rept for Nov 1982 MATTHEWS.T P Omaba Public Power District 82/12/10 9pp 16473 305 24X Fiche 50-285, 82/12/13,8212200059

- S Reportable occurrences, LERs & related correspondence
- 8912030009 Forwards LER 82-019/03L-0 JONES W C Omaha Public Power District 82/11/23 SEIDLE, W C Division of Resident. Reactor Project & Engineering Programs 1p 16304 226 24X Fiche 50-285.82/11/23.8212030009
- --B212030013 LER B2-019/03L-0 on 821024,MBIVs HCV-1041A & HCV-1042A stopped three to four degrees off seat when signaled to close Caused by binding between valve packing & shaft Fackings sprayed w/penetrant oil ABEL-8 L Omaha Public Power District B2/10/28 Region 4, Office of Director 4pp 16304 227 24X Fithe 50-285,82/11/23,8212030009
- 82:2100247 PNO-1V-82-045 on 82:203, plant shut down by turbine/reactor trip Excessive vibration of turbine reported prior to shutdown Caused by two damaged journal bearings on high pressure turbine Two wk shutdown estimated JOHNSON, W D , YANDELL, L A Region 4, Office of Director 82/12/06 p 16376 049 24X Fiche 50-285,82/12/06,8212100247

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

- F Security, medical, emergency & fire protection plans
- 87:12220006 Staff requirements memo re 82:1119 briefing by FEMA on status of emergency preparedness findings Conclusions re removal of deficiencies & overall adequacy of emergency plans will be submitted between 82:200 & 17
 CHILK-8 J Office of the Secretary of the Commission 82/11/24
 Office of the Secretary of the Commission ip 16529 181 24X
 Fiche 50-286,82/11/24,82:2220006
- 82:2060307 Ack receipt of 820702 response to NRC 820803 ltr re plans for correcting significant deficiencies identified in FEMA 820730 rept on radiological emergency prepareness of state & local govts
 HAYNESIR C Region 1, Office of Director 82/11/26 BRONS, J C Power Authority of the State of New York 2pp 16311 037 24X Fiche 50-286,82/11/26,8212060307
- 82:12130352 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 164:3 084 24X Fiche 50-286,82/12/07, 82:12130352
- --G212130355 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1003 re obtaining meteorological data & IP-1004 re MIDAS computer sys dose assessment models

 BRONS.J C Power Authority of the State of New York 62/11/26

 HAYNES,R C Region 1. Office of Director Ip 16413 085 24)
 Fiche 50-286,82/12/07.8212130352
- --8212130357 Public version of revised emergency plan implementing procedures, including Procedures IP-1003 re obtaining mateoralogical data & IP-1004 re MIDAS computer sys dose assessment models LOMANACO, L. M. DRONS, J. C. Power Authority of the State of New York 82/11/24 73pp 16413 086 24X Fiche 50-286, 62/12/07, 8212130352
- 8912220234 Discusses correction to probabilistic safety study base case fire risk & quantification of risk reduction due to installation of alternate cabling sys per 821029 ltr BAYNE. J P Power Authority of the State of New York 82/12/15 VAROA. S A Operating Reactors Branch 1 5pp 16518 312 24X Fichs 50-286, 82/12/15, 8212220234
- 6212280084 Forwards FEMA 821217 ltr transmitting "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Onyts at Indian Point Nuclear Power Station "HAYNES,R C Region i Office of Director 82/12/17 0/100LE,J D Consolidated Edison Co of New York, Inc 2pp 16557 192 R4X Fiche 50-247,82/12/17.8212280084
- --B212280087 Forwards "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Fower Station"

 THOMAS, L M Federal Emergency Management Agency 82/12/17
 DIRCKS, W J Office of the Executive Director for Operations 3pp 16557 194 24X Fiche 50-247.82/12/17,8212280084

- --8212280092 "Update Rept on Status of Remedial Actions Cited in 820730 Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Pauer Station " PETRONE.F P Federal Emergency Management Agency 82/12/16 52pp 16557 197 24X Fiche 50-247.82/12/17.8212280084
- 82/12/280186 Forwards FEMA 82/12/17 ltr & update rept on status of remedial actions cited in 820730 "Interim Findings on Adequacy of Radiological Emergency Response Preparation of State & Local Govts at Indian Point Nuclear Power Station "
 HAYNES, R C Division of Engineering & Technical Programs 82/12/17
 BRONS, J C Power Authority of the State of New York 2pp
 16562 199 24X Fiche 50-286,82/12/17,8212280186
- 9 Adjudicatory correspondence
- 8212070073 Forwards Director's Decision DD-82-12.denying 10CFR2 206 petition to suspend operation immediately until FEMA identified deficiencies convected DEYOUNO.R C Director's Office of Inspection and Enforcement 82/11/26 (MEISS.E R Public Interest Research Group, New York SHOLLV.8 C Union of Concerned Scientists MEISS.E R Harmon & Meiss ip 16354 333 24X Fiche 50-247.82/11/26, 8212070073
- --B212070081 Director's Decision DD-82-12, denying UCS % NY PIRG B20804 IOCFR2 206 petition to suspend operation immediately until FEMA identified deficiencies corrected DEYOUNG.R C Director's Difice. Difice of Inspection and Enforcement B2/11/26 Spp 16354 354 24X Fiche 50-247, B2/11/26.8212070073
- B212020321 Order granting West Branch Conservation Assoc 821124 request for permission to file replies to licensee interrogatories on Contention 2 2a late Good cause shown GLEASON, J.P. Atomic Safety and Licensing Board Panel 82/11/30 West Branch Conservation Association 2pp 16279 194 24X liche 50-247, 82/11/30, 8212020321
- 8212070189 Motion for orders compelling discovery of utils re 820621
 Interrogatories 1 11 % compelling NRC to produce documents
 on routine & unscheduled releases of radiation Certificate
 of Svc encl Related correspondence
 RODRIGUEZ.P Parents Concerned About Indian Point 82/11/30
 Atomic Safety and Licensing Board Panel 3pp 16333 128 24X
 Fiche 50-247.82/11/30.8212070189
- G21202031B Requests ABLD issue order modifying schedule in ASLB B2111b memorandum & order rescheduling Westchester County testimony from 830103 to B30110 Time between filing of testimony & hearing communicement insufficient MCRGAN.C Power Authority of the State of New York BRANDENBURG.B Consolidated Edison Co of New York, Inc. MCRGAN.C Morgan Associates B2/12/01 GLEASCN, J P., SHKN, F J. PARIS.O H. Atomic Safety and Licensing Board Panel 2pp 16279 198 24X Fiche 30-247, 82/12/01, 8212020318
- GP12060103 Motion to dismiss Contentions 2 i(a) & (d) re filtered vented containments & separate containments respectively & P 2(b) re specific pressorized thermal shock responses W/Certificate of Svc BRANDENBURG, B Consolidated Edison Co of New York. Inc MORGAN, C Power Authority of the State of New York MRGAN, C Morgan Associates 82/12/01 Atomic Safety and Licensing Board Panel 10pp 16316 123 24X Fiche 50-247,82/12/01.8212060103
- GP12060241 Memorandum & order granting util 821201 request for postponement of hearing scheduled for wk of 830103 until wk of 8301010 Parties presenting evidence concurring in request GLEASON, J P Atomic Safety and Licensing Board Panel 82/12/02 Consolidated Edison Co of New York, Inc 2pp 16312 265 24X Fiche 50-247.82/12/02.8212060241
- 8212060077 Response to 820716 first set of interrogatories & request for documents re Commission Questions 1 & 2 SHOLLY, S C, BLUK, J M Union of Concerned Scientists BLUM, J M New York Univ 82/12/03 Office of the Executive Legal Director 14pp 16314 300 24X Fiche 50-247,82/12/03.8212060077
- --8212060087 Notice of JF Meyer 821207 deposition in Bethesda.MD refiltered vented containment sys Certificate of Svc encl BLUM.J M Union of Concerned Ecientists BLUM.J M New York Univ 82/12/03 5pp 16314 313 24X Fiche 50-247.82/12/03. 8212060077
- 8/12070246 Motion for mod of hearing schedule, delaying hearings until 020315 Hearing dates as scheduled conflict w/830308 emergency exercise Both NY State & Suffolk County witnesses will be engaged in exercise Certificate of Svc senf FEINDERG, J D New York, State of, Energy Office 02/12/03 Abomic Safety and Licensing Board Panel 8pp 16329 204 24X Fiche 50-247, 82/12/03, 8212070246

- GP12090087 Forwards three ads published in listed newspapers sponsored by utils informing of safe plant operation info provided per ASLB oral directive at 820123 public hearing BRANDERNBURG, B Consolidated Edison Co of New York, Inc. LEVIN.J. J. Power Authority of the State of New York LEVIN.J. J. Morgan Associates 92/12/03 GLERSON.J.P., SHON, F.J., PARIS.O.H. Atomit Safety and Licensing Board Panel. Spp. 16357-175 24X Fiche 90-247.62/12/03,8212090087
- BP12230937 Urges that plants not return to svc until adequacy of emergency planning & preparedness guaranteed Worst case accident could result in many thousands of fatalities RYAN.4B New York.NY 82/12/09 PALLADINO.N J. AHEARNE, J. GILINSKY, V. Commissioners 2pp 16505 132 24% Fiche 50-247, 82/12/03, 8212230337
- GP12070209 Response in apposition to licensee 821201 motion to dismiss contentions Requirements arising under Contention 2 2(b) should be transferred to NRC & licensee Cortificate of Sive encl.

 FLEISHER: 2 Wast Branch Conservation Association 02/12/04 Atomic Safety and Licensing Roard Panel. 3pp. 16333-181 24X fiche 50-247, 82/12/04, 8212070209
- GF:12070213 Motion to compel discovery of Con Ed re evaluation of hybrid closed cocking sys Math requested for Contention 2 2(a) Certificate of Svc encl Related correspondence FLEISHER. IS West Branch Conservation Association 82/12/04 Atomic Safety and Licensing Board Panel Rep 16329 360 24X Fiche 50-247, 82/12/04, 82(2070213
- GP12080310 Supplemental response to first set of interrogatories & document requests on ASLB Questions 1.2 & 5
 COLARUCLI.P F Fower Authority of the State of New York
 COLARUCLI.P F Morgan Associates 82/12/06 Union of Concerned
 Scientists 35pp 16354 010 24X Fiche 50-247,82/12/06,8212080310
- GP12090090 Advises of attempted contact re W Fleisher deposition Utils intend to take deposition next uk re Contention 2 2(a)
 IRANDENBURG. 8 Consolidated Edison Co of New York Inc
 COLARQUELT, P F Power Authority of the State of New York 82/12/06
 FLEISHER, Z S West Branch Conservation Association ip 16357 174
 24X Ficho 50-247, 82/12/06, 8212090090
- S212090101 Supplemental response to interrogatories on Commission Guestions (& 2 Certificate of Svc enc.)
 SHOLLY 5 C. BLUM.J M. Union of Concerned Scientists 82/12/07 Office of the Executive Logal Director 17pp 16357 284 24X fiche 50-247, 82/12/07, 8212070101
- Gilli00103 Memorandum & order memorializing rulings of 821203 telcon Schedule for UCS utils & NRC modified as listed Deadline for notice of depositions of UCS witnesses for Question I to be legotiated OLEASON JP Atomic Safety and Licensing Board Panel 82/12/08 dpg 16379 105 24x Fiche 50-247, 82/12/08, 8212100103
- GP12140423 Responses opposing West Branch Conservation Assoc B21104
 Application for reinstatement of Contention 2 2(d) & Assoc
 U21104 objection to ASLO restatement of Contention 2 2(b)
 Certificate of Svc enci
 URANDENBURG. B Consolidated Edison Co of New York, Inc MORGAN, C
 Power Authority of the State of New York MORGAN, C Morgan
 Associates 62/12/09 Atomic Safety and Licensing Board Panel
 Opp 16404 199 24X Fichs 50-247,82/12/09,82/2140423
- 8212150017 Answer objecting to State of NY motion for mod of hearing schedule Change in uitness testimony schedule burdensone Certificate of Svc encil MOSNER, P. Parents Concerned About Indian Point 82/12/09 Atomic Safety and Licensing Doard Panel 1p 16421 180 24X (1che 50-247, 82/12/09, 8212150017
- GP12150022 Notice of concurrence w/Parents Concerned About Indian Point objection to State of PY motion to modify hearing schedule Further postponent of witness testimony unwarranted & burdensome to UGS/PIRO of NY & witnesses 100.7-J Union of Concerned Scientists HOLT. J Public Interest Research Group, New York 82/12/07 ip 16481 231 24X Fiche 50-247.82/12/07.8212150022
- BF12130209 Order scheduling 830110 evidentiary hearing in White Plains, NY OLEASON, J.P. Atomic Safety and Licensing Board Panel 82/12/10 ip 16397-015 24X Fiche 50-247, 82/12/10, 8212130208
- GPI2(30252 Forwards Hestchester County B2(205 ltr to Commissioner Palladino re offsite emergency proparedness to comply w/exparts communications regulations STUCKY, B W Docketing & Services Branch B2/12/10 Defice of the Escutive Legal Director ip 16376 230 R4X Fiche 50-247, U2/12/10,82(212)30252

- --8212130254 Urges that facilities not be restarted until emergency response plans are fully workable & implementable State of emergency planning & preparedness in Westchester County etil inadequate

 DELBELIO. A B Hestchester County, NY 82/12/05 PALLADINO, N J Compissioners 12pp 16396 231 24X Fiche 50-247,82/12/10, B212130252
- 8212140242 Response in opposition to State of NY motion for mod of hearing schedule moving hearing commencement on Commission Questions 3 & 4 to 830315 Extension to 830314 for testimany on questions not opposed KAPLAM; C New York, NY 82/12/10 Atomic Bafety and Licensing Board Panel 2pp 16409 304 24x Fiche 50-247.82/12/10.8212140242
- 8212140384 Notification of witnesses on Commission Guestion 2 BLUM, J M Union of Concerned Scientists 82/12/10 2pp 16404 320 244 Fiche 50-247.82/12/10,82(2140384
- --G212140393 Notice of deposition of NRC witnesses HR Denton SH Hanaud, RM Blond & FH Rowsome re testimony to be provided Denton & Hanaud will also be examined on decision criteria & process & CRAC & CRAC2 accident consequence codes
 BLUM, J H Union of Concerned Scientists B2/12/10 2pp
 14404 322 24X Fiche 50-247, 82/12/10,8212140384
- --3212140400 Notice of deposition of util witnesses DC Bley, BJ Garrick, S Kaplan & DC Richardson re probabilistic safety study Centificate of Svc entl SEUM, J M Union of Concerned Scientists 82/12/10 App 16404 323 24X Fiche 50-247, 82/12/10,8212140384
- B212140439 Motion for leave to file ench reply to West Branch Conservation Assoc 821204 reply to licensee 821201 motion to dismiss certain contentions If Assoc had participated in telcon, utils would have onally replied BRANDENBURO. B Consolidated Edison Co of New York, Inc LEVIN. J Power Authority of the State of New York LEVIN. J Morgan Associates 62/12/10 Atomic Safety and Licensing Board Panel Ppp 16405 249 24X Fiche 50-247.82/12/10.8212140439
- 8212140446 Reply to West Branch Conservation Assoc 821204 reply to licensee 821201 motion to dismiss certain contentions Assoc misconstrues Commission intent in establishing proceeding Contention 2 2(b) should be struck W/Certificate of Svc BRANDENBURG.B Consolidated Edison Co of New York, Inc LEVIN.J J Power Authority of the State of New York LEVIN.J J Morgan Associates 82/12/10 Atomic Safety and Licensing Board Panel 7pp 16405 201 24X Fiche 50-247.82/12/10.8212140437
- 8212140451 Forwards Rockland County resolution calling for closing of plants for failure to remedy emergency planning deficiencies by expiration of 120-day clock THURSEN, E O Rockland County, NY 82/12/10 PALLADINO, N J Commissioners 3pp 16404 355 24X Fichs 50-247, B2/12/10, G212140451
- BP12160289 Notice of I Levi.D Pisello & R Piccioni 821229 depositions in NY.NY re testimany on Commission Question I Certificate of Svc encl Related correspondence BRANDENBURG.B Consolidated Edison Co of New York, Inc MOROAN.C Power Authority of the State of New York MOROAN.C Morgan Associates 92/12/10 App 16446 068 24X Fiche 50~247.82/12/10, 9212160289
- 82:12:50:16 Response to licensee 82:1201 motion to dismiss Contentions 2:1(a),2:1(d) & 2:2(b) Supports dismissal of Contention 2:2(b) West Branch Conservation Assoc filings show that Assoc will not pursue issue Certificate of Svc encl MOGRE, J.E. Hearing Branch 1:82/12/13 Atomic Safety and Licensing Board Panel Spp 14427-351 244 Fiche 50-247.82/12/13, 82:12:150:14
- GP12200032 Gualifications statements for UCS/NY PIRG witnesses on Commission Guestion 2 Prof qualifications & Certificate of Gvc ancl HLUM, J M Union of Concerned Stientists 82/12/13 11pp 16473 331 24x Fichs 30-247, 82/12/13, 8212200032
- B212170169 Advises that NRC does not intend to seek authorization to reply to West Branch Conservation Assoc 821124 objections to restatement of Contention 2 2(b) No new arguments raised MODRE, J.E. Hearing Branch 1 82/12/14 QLEASON, J.P., PARIS, D.H., SHON, F.J. Atomic Safety and Licensing Board Panel, 1p 16450 221 24X Fiche 50-247,82/12/14,8212170169
- G212160375 Order requesting ASLB provide recommendations called for in CLI-81-23 no later than 830727 CHILK.5 J Office of the Secretary of the Commission 82/12/15 Atomic Safety and Licensing Board Panel ip 16442 341 24X Fichs 50-247, 62/12/15,8212160375

- B212170174 Response to Parents Concerned About Indian Point 821130 motion to compel discovery against utils & response opposing Parents request to file new document request on NRC Protective order requested Certificate of Svc encl MCGURREN.H J Hearing Branch 1 82/12/15 Atomic Safety and Licensing Board Panel 5pp 16450 163 24X Fiche 50-247,82/12/15,8212170174
- B212200077 Memorandum & order granting NRC motion for protective order reamswer to UCS/NY PERG Interrogatory 5 NRC is not required to compile list of NRC criticisms of plant probabilistic safety study nor to formulate position GLEAGON, JP Atomic Safety and Licensing Board Panel 82/12/15 Uffice of the Executive Legal Director 2pp 16470 140 24X Fiche 50-247, 82/12/15, 8212200097
- 8212220273 Reply opposing licensee B21210 motion for leave to file reply to West Branch Conservation Assoc response to licensee B21201 motion Licensee is harassing Assoc Certificate of Svc encl
 FLEIGHER, Z S West Branch Conservation Association 82/12/15
 Atomic Safety and Licensing Board Panel 3pp 16517 188 24X
 Fiche 50-247, 82/12/15, 8212220293
- 8212220220 Advises that M Kaminski inadvertently omitted from amended witness iists Order of witnesses listed Related correspondence
 VEIRRE, L A Restchester County, NY 82/12/16 GLEASON, J P ,
 PARIS, O H , SHON, F J Atomic Bafety and Licensing Board Panel 1p 15503 Ott 24% Fiche 50-247, 82/12/16, 8212220220
- --8212220226 Response to State of NY motion to modify hearing schedule Unnecessary to delay testimony of all other available witnesses until County & State witnesses available Certificate of Svc encl
 VETERE, LA Westchester County, NY 82/12/16 Atomic Safety and Licensing Board Panel 2pp 16503 002 24X Fiche 50-247, 82/12/16.8212220220
- G212230261 Urges plants not be reopened until emergency preparedness plans adequate UIALIK.E I New York, State of 82/12/16 PALLADINO, N Commissioners ip 16508 188 24% Fiche 50-247,82/12/16, G212230261
- 6212230331 Forwards 821213 ltr inadvertently sent to J Hendrig Attendance at 830110 evidentiary hearing requested MANTELLA N Affiliation Unknown 82/12/14 PALLADINO, N Commissioners ip 16505 157 24X Fiche 50-247, 82/12/16, 8212230331
- --8212230336 Ack receipt of 821210 invitation to attend evidentiary hearing in White Plains NY Attendance certain unless accident postpones hearing MANTELL, A M Affiliation Unknown 82/12/13 HENDRIE, J Atomic Safety and Licensing Board Panel 1p 16505 198 24X Fiche 50-247,82/12/16,8212230331
- 6:12210235 Memorandum & order memorializing 821215 & 14 telcons & dismissing Parents Concerned About Indian Point & West Branch Conservation Assoc 82:130 & 1204 discovery motions PARIS.O H Atomic Safety and Licensing Board Panel 82/12/17 Parents Concerned About Indian Point 2pp 16484 234 24X Fiche 50-247,82/12/17,6212210235
- 9212210238 Supplementation of interrogatory response naming Question 1 witnesses Certificate of Svc encl BLUM, J M Union of Concerned Scientists 82/12/17 5pp 16484 236 24X Fichs 50-247.82/12/17,8212210238
- 8212210320 Forwards Congressman RL Ottinger 821201 ltr to util seeking testimony before Congress re investigation Util 821203 response encl
 LEVIN.J J Morgan Associates 82/12/17 PALLADINO,N J ,
 AHEARNE,J F , 01LINSKY,V Commissioners 6pp 16496 246 24X
 Fiche 50-247,82/12/17.8212210320
- 8212220246 Supplemental response to first set of interrogatories & document requests under Commission Guestion 1 Prof qualifications encl Related correspondence HARTZMAN,R M Friends of the Earth HARTZMAN,R M New York City Audubon Society 82/12/17 Consolidated Edison Co of New York Inc 32pp 16518 280 24X Fichs 50-247,82/12/17,8212220246
- B212220271 Responses to interrogatories & document requests re Commission Question & Certificate of Svc encl BRANDENBURG. B Consolidated Edison Co of New York, Inc PRATT.C M Power Authority of the State of New York PRATT.C M Morgan Associates 82/12/17 Parents Concerned About Indian Point #5pp 16517 280 24X Fiche 50-247,82/12/17.8212220271

- G212230187 Response to motion to compel discovery re Commission Question 6 Certificate of Syc encl Related correspondence BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. PRAIT, C.M. Power Authority of the State of New York, PRAIT, C.M. Morgan Associates 82/12/17 Parents Concerned About Indian Point 14pp 16511 007 24X Fiche 50-247,82/12/17,8212230187
- 8212230235 Urges that units not be returned to svc until emergency planning concerns resolved
 BRODSKY: R L Westchester County, NY DE MARCO, J W . HOCHBERG: A G Commissioners 92/12/17 PALLADINO, N J . AHEARNE, J F . GILINEKY, V G212230235
- 8212280014 Lists documents being withheld as privileged that were requested by SC Sholly (UCS) in UCS/NY PIRG first set of interragatories & document requests on Commission Questions 1.2 & 5 NUREG/CR-2666 forthcoming NCOURREN.H J Hearing Branch 1 B2/12/17 BLUM.J M New York Univ 2pp 16564 290 24% Fiche 50-247, B2/12/17, B21280014
- 8212280285 Response in opposition to State of NY motion for mod of hearing schedule Since motion relates to scheduling of testimony uithin allotted time frame no further hearing delay necessary Certificate of Svc enc!

 MORGAN.C Power Authority of the State of New York MORGAN.C Horgan Associates 82/12/17 Atomic Safety and Licensing Board Panel 7pp 16561 327 24% Fiche 50-247,82/12/17,8212280285
- 8212210267 Response in support of State of NY 821203 motion for mod of schedule for hearing testimony on Commission Questions 3 \$ 4 Extension needed in order for witnesses to participate in emergency planning excercises Certificate of Svc encl MOORE, J E Hearing Branch 1 82/12/20 Atomic Safety and Licensing Board Panel 5pp 16489 170 24X Fiche 50-247,82/12/20,8212210267
- 8212210332 Response opposing Con E6 821215 mailgram requesting ASLII to grant previously filed motion to dismiss Contentions 2 1(a) & 2 1(d) Prejudice caused by UCS/NY PIRG tandiness not equal to requested sanctions Certificate of Svc encl MOORE, J E Hearing Branch 1 82/12/20 Atomic Gafety and Licensing Board Panel 7pp 16497 013 24X Fiche 50-247.82/12/20.8212210332
- G212220398 Memorandum supporting Con Ed G21215 renewed motion to dismiss UCB/NY PIRO Contentions 2 1(a) & 2 1(d) UCS continues to act immune from orders of ASLB notwithstanding Judge Paris admonition Certificate of Svc encl MDRGAN. C Power Authority of the State of New York MDRGAN. C Morgan Associates G2/12/20 Atomic Safety and Licensing Unard Panel 9pp 16503 223 24% Fiche 50-247, 82/12/20, G2(2220398)
- BP12230241 Strongly urges that units not be returned to svc until emergency planning concerns resolved STEINOUT, R. BTERN, H.J. GREITZER, C. New York, NY 82/12/20 PALLADINO, N.J. AMEARNE, J.F., GILINSKY, V. Commissioners 11pp 14508 145 24X Fiche SO-247, 82/12/20, 8212230241
- 8212230270 Urges plants not be restarted until workable emorgency plan implemented FINK, 8 New York, NY 82/12/20 PALLADING, N J Commissioners 2pp 16507 358 24X Fiche 50-247,82/12/20,8212230270
- 8P122B0293 Response in opposition to State of NY mution for mod of hearing schedule State did not meet heavy burden of persuation required to extend hearings Certificate of Byc rncl
 BRANDENBURO. B Consolidated Edison Co of New York, Inc 82/12/20 Atomic Safety and Licensing Board Panel App 16562 047 24X Fiche 50-247.82/12/20.82122B0293
- 8212230181 Memorandum & order granting licensee 821210 motion to reply to West Branch Conservation Assoc (WBCA) reply to util 821201 motion to dismiss contentions Util 821201 motion to dismiss also granted WBCA motion for reinstatement denied GLEAGON, J P , SHON, F J Atomic Safety and Licensing Board Panel 82/12/21 Consolidated Edison Co of New York, Inc 7pp 16510 230 24X Fiche 50-247.82/12/21.6212230181
- 82:12230188 Memorandum & order granting Parents Concerned About Indian Point 82:1130 request to place specified documents issued by NRC prior to 1979 into LPBR GLEASON, J.F. Atomic Safety and Licensing Board Panel 82/12/21 Parents Concerned About Indian Point App (A511 106 24X Fiche 50-247.82/12/21,82:12230188
- 8212230358 Order extending time, until 821229, for Commission to decide whether to review IE Director 821126 denial of UCS request for action filed under 10CFR2 206 CHILK.S J Office of the Secretary of the Commission 82/12/21 19 14511 161 24X Fiche 50-247.82/12/21, 8212230358

- 8212230228 Urges FEMA update rept be given consideration in decision to reopen facilities Large number of emergency deficiencies still remain HENZEL.J S Affiliation Uninoun 82/12/22 PALLADINO,N J. AHEARNE,J F. ASSELSTINE.J K Commissioners 15pp 16511 032 24X Fiche 50-247,82/12/22,8212230228
- 82/12270214 Decision CLI-82-38.ruling that no shutdown or enforcement action required re-state of emergency planning FEMA determined that remedial action will be feasible Problems w/local govts beyond licensee control CHILK.S J Office of the Secretary of the Commission 82/12/22 27pp 16537 128 24X Fiche 50-247.82/12/22,8212270214
- G:12280008 Forwards FEMA 921217 ltm to Ofc of Executive Director for Uperations re current status of offsite emergency planning transmitting update rept W/o encl HASSELL.D F Hearing Branch 1 82/12/22 GLEASON.J P , SHON.F J PARIS.O H Atomic Safety and Licensing Board Panel ip 16564 26 24X Fiche 50-247.82/12/22.8212280008
- SP12280011 Advises that invoice for copying documents requested by 5C Sholly on 821214 forthcoming MOGRE, J E Hearing Branch 1 82/12/22 WEISS,E R Harmon & Weiss 1p 16555 144 24x Fichs 50-247, 82/12/22, 8212280011
- 8.12270249 Order CLI-82-41, granting in part & denying in part, UCS 821008 motion to direct NRC to reschedule meeting All parties must be informed of scheduling of meetings CHILX, S J Office of the Secretary of the Commission 82/12/25 Union of Concerned Scientists 3pp 16530 357 24X Fiche 50-247, 82/12/23, 8212270249 82/12/23
- 8212300012 Memorandum & order dismissing West Branch Conservation Assoc 821215 motion to deny licensee motion for leave to reply Licensee motion mot of the see motion granted rendering instant motion moot OLEASON, J.P. Atomic Safety and Licensing Appeal Panel 82/12/29 West Branch Conservation Association 2pp 16598-227 24X / 1che 50-247.82/12/23.8212300012
- 82:12300014 Memorandum & order denying licensee 82:201 mption & 82:215 renewed motion to dismiss Contentions 2 1(a) & 2 1(d) UCS failure to meet 82:210 deadline minor since delay did not Projudice parties

 GLEAGON J P Atomic Bafety and Licensing Board Panel 82/
 Consolidated Edison Co. of New York: Inc. App. 14598 218

 Tiche 30-247, 82/12/23,8212300014
- 0212280326 Forwards revised Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
 STUCKY, S W Docketing & Services Branch 82/12/27 Pc
 Authority of the State of New York 1p 16562 084 24X
 Fiche 50-247, 82/12/27, 8212280326
- --8212283332 Corrected Page 3 to NRC Order CLI-82-41 & separate view of Commissioner Roberts
 CHILK,S J Office of the Secretary of the Commission
 Union of Concerned Scientists 20p 14542 083 24)
 Fiche 50-247, 82/12/27, 8212280324
- GP12300191 Ack receipt of summary of Steam Generator Duners Group G20729 meeting Request being filed for delay in delivering testinong on Question 2 2 1 in order to obtain previously inaccessible Info FLEISHER. Z S West Branch Conservation Association 82/12/27 MCGRE. J Hearing Branch 1 ip 16598 023 24X [1che 50-247.82/12/27.8212300191
- Q712300197 Notice of continuation of Contentions 3 & 4
 FLEISHER, 2 5 West Branch Conservation Association 82/12/27 1p
 16578 024 24% Fiche 50-247,827/12/27,8212300197
- --8212300201 Request for delay in filing testimony on Question 2 i i until 830112 in order to obtain add1 anfo Certificate of Svc enc) FLEISHER, I B West Branch Conservation Association 82/12/27 Atomic Safety and Licensing Board Panel 2pp 16598 025 24X Fiche 50-247,82/12/27,8212300197
- 8212300230 Motion for expedited order compelling continuation of GR Thompson & SC Sholly depositions as witnesses on Contentions 2 1(a) & 2 1(d) Mitness testimony incomplete Concentions 2 143 / 2 140 Mitness Vestimony incomplete Certificate of Svc encl BRANDENSURO, B Consolidated Edison Co of New York Inc NORGAN C M Power Authority of the State of New York MURGAN, C M Morgan Associates 82/12/28 Atomic Safety and Licensing Board Panel 14pp 16598 004 24% Fiche 50-247, 82/12/28, 8212300230

H General correspondence

- BM12230323 Forwards Rockland County Resolution 796 calling for closing of plants for failure to remedy emergency planning deficiencies deficiencies SEIGERMAN, V K Rockland County. NY 82/12/13 PALLADING, N Commissioners 2pp 16505 134 24X Fiche 50-247, 82/12/13, 8212230323
- GP1227042B Responds to 821130 ltr forwarding constituent concern re temporary suspension of hearings Approx 10 wks of hearings beginning 830110 scheduled DIRCKS.W J Office of the Executive Director for Operations 82/12/20 BRADLEY.B Senate 2pp 16568 337 24X /iche 50-003.82/12/20.821227042B
- --B212270431 Forwards DX & FL Cinquemant 820730 1tr requesting resumption of hearings on safety of plants
 GRADLEY, R Senate 82/11/30 Office of Congressional Affairs
 5pp 16568 341 24X Fiche 50-003,82/12/20,8212270428
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BP12070077 Forwards "Review of Indian Point Probabilistic Safety Study "
 AVERY, R Argonne National Laboratory 82/10/20 DKRENT, D ACRS
 Advisory Committee on Reactor Safequards DKRENT, D California
 Univ of, Los Angeles Ip 16354 320 24X Fiche 50-247,82/10/20, DKRENT, D ACRS -
- --8212070083 "Review of Indian Point Probabilistic Safety Study "
 AVERY, R., CHO, D. H., DETTRICH, L. W. Argonne National Laboratory
 B2/09/30 ACRS Advisory Committee on Reactor Safeguards
 30pp 16384 321 24% Fiche S0-247,82/10/20,82/2070077
- P Operating license stage documents & correspondence
- OPI2090205 Forwards response to B21027 ltr re draft BNWL analysis of liquid pathway consequences due to basement penetration as presented in Indian Point probabilistic safety study BAYNE, J P Power Authority of the State of New York O'TOOLE; J D Consolidated Edison Co of New York. Inc 82/11/27 VAROA, S A Uperating Reactors Branch 1 14pp 16362 346 24X Fiche 50-247, 82/11/27, 8212090205
- 8?12130023 Advises of proposed meeting during second wk of Dec in Bethesds.MD to discuss concerns re seismic qualification of auxiliary feedwater say VARQA.5 A Operating Reactors Granch 1 82/12/02 SINCLAIR.L Power Authority of the State of New York 2pp 16410 346 24) Fiche 50-286.82/12/02.8212130023 SINCLAIR, L W
- --8211060556 "Indian Point 3 Nuclear Power Plant, Seismic Qualification of Auxiliany Feedwater Sys." technical evaluation rept
 * Lawrence Livermore Laboratory 82/10/15 NRC No Detailed
 Affiliation Given '9pp 16410 348 24X Fiche 50-286,82/12/02,
- BP12130030 Requests review of Unit 3 technical evaluation rept resoismic qualification of auxiliary feedwater sys Apparent discrepancies between Units 2 t 3 should be addressed VARGA, S A Operating Reactors Branch 1 82/12/02 O'TOOLE, J E Consolidated Edison Co of New York, Inc. 2pp. 16417-051 24X Fithe 50-247, 82/12/02. 8212130030 O.LOOFE' 1 D
- 8212130330 Forwards response to Congressional Subcommittee on Oversight & Investigation questionnaire on steam generator tube integrity (Generic Ltr 82-22)
 BAYNE.J P Power Authority of the State of New York 82/12/03
 EISEYHUT.D 0 Division of Licensing 4pp 16389 274 24X
 Fiche 80-286.82/12/03,8212130330
- 8212100214 Advises that util will respond to NRC 821130 meeting request for submittal of revised versions of radiological effluent Tech Specs & offsite dose calculation manual by 830201 BAYNE, J P Power Authority of the State of New York 82/12/06 VARGA, 5 A Operating Reactors Branch 1 2pp 16376 079 24X [iche 50-286, 82/12/06, 8212100214
- BP12100288 Forwards response to Items 2 & 4(a) of Encl 1 to 820315 ltr re control of heavy loads Responses to Items 5,4(b) & 7 will be provided by 830301 BAYNE,J P Power Authority of the State of New York 82/12/06 VARGA,S A Operating Reactors Branch 1 14pp 16377 068 24X Fiche 50-286, 82/12/06, 8212100288

- 8P12270259 Forwards nonproprietary "Indian Point Unit 3 Steam Generator Siewing Rept." & Nestinghouse Authorization CAM-02-62
 Submittal supercedes 821018 Authorization CAM-02-50
 BAYNE.J P Power Authority of the State of New York 82/12/06
 VARGA.S A Operating Reactors Branch 1 2pp 16536 273 24X
 Fiche 50-206.82/12/06.8212270259
- --0212270263 Authorizes utilization of previously furnished affidavit in support of facility info re proprietary aspects of application for withholding or affidavit should ref CAM-82-62 & be addressed to author W/o encl affidavit WIESEMANN, R. A. Hestinghouse Electric Corp. 082/10/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 16536 275 24X Fiche 50-286,82/12/06.8212270259
- --8212270266 Nonproprietary "Indian Point Unit 3 Steam Generator Sleeving Rept "Proprietary info deleted * Wastinghouse Electric Corp WCAP-10146 82/09/30 211pp 16535 277 24X Fiche 50-286,82/12/06.8212270259
- 8208190263 Generic Ltr 82-32 to all PWR licensees re-potential steam POBI90263 Generic Ltr 82-32 to all PMR licensees re potential ste-generator-related generic requirements Forwards Science Applications, Inc dreft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EfBENHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 29pp 14629 247 24X Edison Co of New York, Inc 27 F(she 50-000, 82/12/07, 8208170263
- 8P12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENHUT, D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24% Fiche 50-000, 62/12/10. Instrumentation EISENHUT, D 0 Divis 0212140103
- 8212210322 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Local Leakage Rate (Type B & C) Testing" & final rept by Ebasco per 10CFRSO App J BRONS, J C Power Authority of the State of New York 82/12/15 Clffice of Nuclear Reactor Regulation, Director 2pp 16496 13: 24X Fiche 50-286,82/12/15,8212210322
- --8212210323 "Reactor Containment Bldg Integrated Leak Rate Test.Local Leakage Rate (Type 8 & C) Testing " Power Authority of the State of New York 82/12/31 30pp 16495 138 24X Fiche 50-286.82/12/15.8212210322
- --- 8212210324 "Reactor Containment Bldg Integrated Leak Rate Test," final rept GRAASB.J. DILLON,P Ebasco Services, Inc. (subs. of Enserch Corp.) 82/08/04 55pp 16496 169 24X Fiche 50-286,82/12/15.
- 8P12210426 Forwards plant-specific evaluation of safety & relief valve performance re NUREG-0737. Item II D 1.per 810929 request Final piping rept expected by Apr 1983 W/two oversize drawings Aperture cards available in PDR BAYNE. J P Power Authority of the State of New York 82/12/15 VARGA. 8 A Operating Reactors Branch 1 22pp 16490 124 24X Fishe 50-286.82/12/15.8212210426
- G Inspection reports, IE Bullstins & correspondence
- 92D8190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BNR Plants " Syc list encl IEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Cansolidated Edison Go of New York. Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list
- conci conci of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05.8208170245
- 8208190251 IE Info Notice 82-44. "Charification of Emergency Plan Exercise Requirements " Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 92/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000,82/11/18,8208190251

- 8212030123 Forwards IE Insp Rept 50-286/82-19 on 821016-1115 No noncompliance noted
 BTAROBTECKI.R Division of Project & Resident Programs 82/11/19
 BIRONS.J C Power Authority of the State of New York 2pp
 16303 309 24X Fiche 50-286,82/11/19,8212030123
- --8212030128 IE Imag Rept 50-286/82-19 on 821016-1115 No noncompliance 212030128 IE Insp Rept 50-286/82-19 on 821016-1115 No noncompliance noted Major areas inspected shift logs & records. surveillance maint, receipt of improperly packaged radiological maths & review of monthly operating rept KENNY, T. J. KISTER, H. Division of Project & Resident Programs 82/11/17 7pp 16303 311 24X Fiche 50-286,82/11/19.8212030173
- 8208190256 IE Info Notice 82-46. "Defective * Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24% Fiche 50-000.82/11/26.8208190256
- Ge'0B190257 IE Into Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Cansolidated Edison Co. of New York, Inc. 336pp 16387 028 24% Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list enci DEYQUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B208190261 IE Info Notice B2-48, "Failures of Agastat CR Q075 Relay Bockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNG, RC Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208170267
- 820B19026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co. of New York, Inc. 108pp. 16628 293 24x fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- 0212290156 Forwards monthly operating rept for Oct 1902 BRDNS.J C Power Authority of the State of New York B2/11/16 Uffice of Resource Management, Director 1p 16582 219 24X Fiche 30-286,82/11/10.8212290156 82/11/10
- --8212270140 Monthly operating rept for Oct 1982 AUTERING.L Power Authority of the State of New York 6pp 16582 220 24% Fiche 30-286.82/11/10.8212290156 82/11/01
- 8212140064 Forwards monthly operating rept for Nov 1982 BRONS, J. C. Power Authority of the State of New York B2/12/09 Office of Nuclear Reactor Regulation, Darector 1p 16408 306 Fiche 50-286, 82/12/09, 8212140064
- B212140070 Monthly operating rept for Nov 1982 AUTERIND.L Power Authority of the State of New York Opp 16408 307 24% Fiche 50-286,82/12/09,8212140064 82/12/01
- B Reportable occurrences, LERs & related correspondence
- 8:12210417 PND-I-92-081 on 821215, two nuclear electronic technicians suffered third degree burns from electrical shock while working on 6,900-volt bus work in reactor coolant pump breaker panel Caused by employee making contact w/bus KISTER, GREENMAN Region I. Office of Director 82/12/16 1p 16493 095 24X Fiche 50-286,82/12/16,8212210417
- 1 Hearing transcripts on non-antitrust matters
- 8212070049 Transcript of 821203 telephone conference in Washington, DC Pp 4,854-4.888 * Atomic Safety and Licensing Board Panel 82/12/03 33pp 16327 295 24% Fiche 50-247,82/12/03,8212070049

- 821215000B Forwards RL Goldfarb testimony & lists order of witnesses to testify Related correspondence VETERGLA Hestchester County,NY 82/12/07 QLEASON,JP, PARIS,QH, SHON,FJ Atomic Safety and Licensing Board Panel ip 14421
- -- 8212150013 Testimony of RA Goldfarb re law enforcement concerns w/
 dmergency plan ASLB should consider effectiveness of
 dmergency plan A/o adequate police communications sys
 Gentificate of Svc enc!
 GOLDFARB R A Wastchester County, NY GOLDFARB, R A Ossaning, NY
 82/12/09 5pp 16421 131 24X Fiche 50-247,82/12/09,8212150008
- 8212300235 Transcript of Commission 821221 meeting in Washington DC reposible action concerning emergency preparedness at facilities Supporting documentation & viewgraphs encl # Commissioners 82/12/21 12/pp 16624 037 24X fichs 50-286.82/12/21-9212300235
- U Congressional/Elecutive Correspondence
- 82/12/20/341 Requests NRC statement of Commission basis for determination that reasonable assurance exists that public health & safety will be adequately protected in event of large nuclear accident UDALL.M K. House of Rep : Interior & Insular Affairs 82/12/15 PALLADIND:N J. Commissioners 2pp 16511 126 24X Fichs 50-247.82/12/15,821/22/30341
- GP12230276 Urges consideration of all info re adequacy of emergency plans & current state of emergency preparedness All steps must be taken to ensure adequacy of emergency planning ISBH-H, OILMAN, B, BINGHAM, J House of Rep. B2/12/20 Commissioners 3pp 16508-277 24X Fiche 50-247,82/12/20, B212200276
- POCKET 50-287 OCONEC NUCLEAR STATION, UNIT 3

 F Security, medical, energency & fire protection plans
- BPJ2330069 Forwards info on emergency offsite facilities (EOF), per R Birket B2J203 request & Generic Ltr B1-10 Const of permanent primary & backup EOF completed TUCKER.H B Dute Power Co 82/12/03 DENTON.H R Dffice of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 2pp 16390 186 24% Fiche 50-000,82/12/03,8212130069
- GP12090044 Reviews util 820419 & 0727 Itrs me security personnel requalification requirements Annual supervisor observation considered sufficient requalification test BTOLZ.d F Operating Reactors Branch 4 82/12/07 TUCKER.H B Dute Power Co 2pp 16384 244 24X Fiche 50-000,82/12/07,82/19/20/20/204
- OP12230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures FELTON.J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000.82/12/15, 8212230093
- --G212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures TUCKER.H B Duke Power Co 62/12/02 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Operating Reactors Branch 4 2pp 16542 027 24X Fiche 50-000.82/12/15.
- --8212230124 Fublic version of Revision 7 to crisis mpt plan One oversize parphiet encl Aperture card available in FDR VAUGHU, R E Duke Power Co 82/11/29 9pp. 16542 029 24X Fiche 50-000, 62/12/15, 6212230093
- -8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 2 re crisis news group plan & 5 3 11 re McGuire crisis phone directory YAUGHIR E Bute Fower Co 82/11/27 280pp 14542 038 24X Fiche 50-000,82/12/15,8212230093
- BP12280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Specs to change frequency of station security plan & implementing procedure audits from once every 2 yes to yearly TUCKER.H B Duke Power Co 82/12/21, DENTON,H.R Office of Nuclear Reactor Regulation, Director 2pp 16560-087, 24X Fiche 30-269,82/12/21.8218280351
- --8212280367 Proposed Fech Spec revision changing frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly 4 Dute Power Co 82/12/21 1p 16560 089, 24X Fichs 50-269,82/12/21,8212280351

- 9 Adjudicatory correspondence
- 8212060079 Response to interrogatories & document requests re Commission Questions 2 & 5 Related correspondence SMOLLY.S C. BLUM.J M Union of Concerned Scientists BLUM.J M New York Univ 82/12/02 Consolidated Edison Co. of New York. Inc. 30pp 16316 133 24X Fiche 50-247.82/12/02.8212060078
- P Operating license stage documents & correspondence
- G212010185 Forwards Amends 116.116 & 113 to Licenses DPR-3B.DPR-47 & DPR-55, respectively, safety evaluation & EIA & notice of isswance & availability Amend revises Tech Spec restrictions on burning low level contaminated oil MAGNER, P. C. Operating Reactors Branch 4 82/11/15 TUCKER, H.B. Duke Power Co. 3pp. 16271 232 24X Fiche 50-269, 82/11/15, 82(2010186)
- --B212010193 Amends 116,116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Spec restrictions on burning low level contaminated oil STOLE, JF Operating Reactors Branch 4 82/11/15 Spp 16271 235 24% Fiche 50-269, 82/11/15, 8212010185
- --G212010205 Safety evaluation & EIA supporting Amends 116,116 & 113 to Licenses DPR-38.DPR-47 & DPR-55, respectively # Dffice of Nuclear Reactor Regulation, Director 82/11/15 6pp 16271 243 24X Fiche 30-269.82/11/15,8212010185
- --8212010274 Notice of issuance & availability & negative declaration of Amends 116, 116 & 113 to Licenses DPR-38, DPR-47 & DPR-55, respectively STOL7.J F Operating Reactors Branch 4 82/11/15 2pp 16271 249 24X Fiche 50-269,82/11/15,8212010185
- B212010372 Forwards Amends 117.117 & 114 to Licenses DPR-38.DPR-47 & DPR-55.respectively, safety evaluation & notice of issuance & availability Amends incorporate digital logic channels & emergenty power switching logic WAONER.P C Operating Reactors Branch 4 82/11/22 TUCKER,H B Duke Power Co 3pp 16271 030 24X Fiche 50-269.82/11/22.8212010392
- --8212010418 Amends 117.117 & 114 to Licenses DPR-36.DPR-47 & DPR-55, respectively, incorporating digital logic channels & emergency power switching logic & revising bases to define redundant component testing STOL7.JF Decrating Reactors Branch 4 82/11/22 28pp 16271 033 24X Fiche 50-269,82/11/22,8212010392
- --B212010421 Safety evaluation supporting Amends 117.117 & 114 to Licenses DPR-3B, DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 82/11/22 App 16271 061 24X Fiche 50-269, 82/11/22 8212010392
- --82;2010488 Notice of issuance & availability of Amends 117,117 & 114 to Licenses DPR-35, DPR-47 & DPR-55, respectively STDL2.JF Operating Reactors Branch 4 82/11/22 2pp 16271 065 24% Fiche 50-269, 82/11/22,8212010392
- B212070370
 Forwards
 license amend fee in response to 821108 ltr

 TUCKER.H. B
 Duke
 Power Co
 82/11/22
 DIGGS.R M
 License Fee

 Management
 Branch
 2pp
 16336-324
 24X
 Fische 50-269.82/11/22.

 B212070370
 3Planch
 3Planch
 3Planch
 3Planch
 3Planch
- B212070341 Forwards responses to NUREO-0737. Item II B 3, "Post-Accident Sampling Sys " W/14 oversize drawings Aperture cards are available in PDR TUCKER. H B Dute Power Cp 82/12/01 DENTUN, H R Office of Nuclear Reactor Regulation, Director 8TDL7. J F Dperating Reactors Branch 4 32pp, 16340 252 24X Fiche 50-269, 82/12/01. 8212070341.
- --8212070348 "Estimate of Failed Fuel Based on I-131 Concentration " HULL.F. GMEN.T B Duke Power Co 82/08/03 22pp 16340 283 24X Fiche. 50-249, 82/12/01.8212070341
- --8212070392 "Post-Accident Containment Air Sampling System " W/twelve oversize drawings Apenture cards are available in PDR * Duke Power Co 62/01/29 87pp 16340 324 24X Fiche 50-264,82/12/01.8212070341
- --8212070395 "Post-Accident Liquid Sampling System " W/nine oversize drawings. Aperture cards are available in PDR * Duke Power Co 82/01/29 376pp 16341 053 R4X Fiche 50-269, 82/12/01/8218070341

- 8212100355 Summary of 821130 meeting w/util re use of Mark DZ fuel assemblies in future reload cores Viewgraphs encl WAGNER, P.C. Operating Reactors Branch 4 82/12/01 Operating Reactors Branch 4 54pp 16379 041 24X Fichs 50-269,82/12/01.6212100355
- B212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in IE Insp Repts 30-287/82-37, 30-270/82-37 to 50-287/82-37 TUCKER, H B Duke Power Co 82/12/08 DENTON H R Diffice of Nuclear Reactor Regulation, Director 870L7. J F Operating Reactors Branch 4 3pp 16427 339 24X Fiche 50-269,82/12/08,8212150073
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re sub, requirements Comments requested within 30 days of ltr Svc list encl EISENHUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fichs 50-000,82/12/09,8208190263
- BP12130190 Comments on status of Unresolved Safety Issue A-49 re pressurized thermal shock for facilities Recent calculations confirming that no near-term safety concern exists should be reflected in NRC rept TUCKER, H B Duke Power Co B2/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactor Branch 4 2pp 16396 129 24X Fiche 50-269,82/12/07,8212130190
- 8212270335 Forwards order for license mod re installation of inadequate core cooling instrumentation sys as specified in NUREG-0737.

 Item II F 2. "Inadequate Core Cooling "
 EISENHUT.D 0 Division of Licensing 82/12/10 TUCKER.H B Duke
 Power Co 2pp 16559 338 24X Fiche 50~269.82/12/10.8212270335
- --82(2270338 Order for license mod to conform w/specs of NUREG-0737, Item II F 2 Checklist for specific review encl EISENHUI.D 0 Division of Licensing 82/12/10 Duke Power Co 11pp 16555 337 24X Fiche 50-269.82/12/10.82(2270335
- 9212210079 Advises that submittal of revised radiological effluent Tech Specs incorporating agreements reached during 820818-19 meetings delayed until 830131, per util 821110 commitment TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 50L2, JF Operating Reactors Uranch A Ip 16485 247 24X Fiche 50-269, 82/12/15, 8212210079
- B212280351 Application to amend Licenses DPR-38, DPR-47 & DPR-55, revising App A Tech Space to change frequency of station security plan & implementing procedure audits from once every 2 yrs to yearly TUCKER, H B Duke Power Co 82/12/21 DENTUN, H R Office of Nuclear Reactor Regulation, Director STOLZ, JF Operating Reactors Branch 4 2pp 16560087 24X Fiche 50-269, 82/12/21, 8212280351
- --8212280367 Proposed Tech Spec revision changing frequency of statson excurity plan & implementing procedure audits from once every 2 yrs to yearly * Duke Pouer Co 82/12/21 ip 16560 089 24X Fiche 50-269, 82/12/21 8218280351
- Q Imagection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Bvc list encl
 DEYOUNG, R C Director's Office. Diffice of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000, 82/10/28,8208190240 ,
- 8212090181 Forwards IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/10/29 TUCKER, H B Duke Power Co 2pp 16359 197 24X Fiche 50-269, 82/10/29, 8212090181
- --B212090189 IE Insp Repts 50-269/82-39, 50-270/82-39 & 50-287/82-39 on 820915-1010 No noncompliance noted Major areas inspected operation safety verification maint activities, surveillance testing startup testing & TMI action item implementation ORDERS.W. FALCONER.D. BRYANT.J.C. Division of Project & Resident Programs 82/10/28 7pp 16359 199 24X Fiche 50-269,82/10/29, 8212090181
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminascent Dosimeters " Svc list encl CBBD.L.I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245

- 82:2090420 Forwards response to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PHR Plants," Item 1 for Unit 1 & Items 2 & 4 for Unit 3 Response to Items 2 & 4 for Units 1 & 2 will be provided following next refveling outage TUCKER.H B Duke Power Co 52/11/15 D'REILLY.J P Region 2. Dffice of Director 4pp 16365 033 24X Fiche 50-269,82/11/15,8212090420
- 8212040310 Grants 820830 request for relief from volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping Safety evaluation encl STOLZ.J F Operating Reactors Branch 4 82/11/16 TUCKER.H B Duke Power Co App 16323 351 24X Fiche 50-269.82/11/16.
- --8212060313 Notice of granting relief from ASME Code requirements for volumetric exams of piping welds in sections of containment sump & reactor bldg spray sys piping STOL7.J F Operating Reactors Branch 4 82/11/16 2pp 16323 357 24% Fiche 50-269.82/11/16.8212060310
- BBOSI90251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 80-000, 82/11/18.8208190251
- 8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Swc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards G2/11/30 Consolidated Edison Co of New York, Inc. 35App 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24% Fiche 50-000, 82/12/03, 8208190259
- 8208170261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Syc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000, 82/12/03, 8208190261
- 8212150073 Requests clarification of conditional snubber operability as described in certain Tech Specs Request due to discussion in 1E Insp Repts 50-269/82-37, 50-270/82-37 t 50-287/82-37 TUCKER.H B Duke Power Co 82/12/08 DENTON.H R Office of Muclear Reactor Regulation, Director Jap 16427 339 24X Fiche 50-269, B2/12/08, B212150073
- 8P08190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG.R C Director's Office of Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 1GBpp. 1462
- R Periodic operating reports & related correspondence
- 0212210421 Forwards monthly operating repts for Nov 1782 TUCKER, H B Duke Power Co 82/12/15 Director's Office of Inspection and Enforcement 1p 16493 058 24X Fishe 50-269, 02/12/15,8212210421
- --8212210428 Monthly operating repts for Nov 1982 REAVIS, J.A. Duke Power Co. 82/12/15 16pp 16493 059 24X Fiche 50-269,82/12/15,8212210421
- S Reportable occurrences, LERs & related correspondence
- B2:2090221 Forwards LER 82-012/01T-0 Detailed event analysis encl TUCKER.H B Duke Power Co 82/12/01 O'REILLY.J P Region 2. Office of Director 3pp 14361 342 24X Fiche 50-287,82/12/01, 82:2090221

- 8212070225 LER 82-012/01T-0 on 821117 stean generator tube leak of 0 5 gpm indicated by condensate stean air ejector offgas radiation monitor Caused by cracts in tubes 65-1.68-4.78-4. 78-8 J. 83-5 Tubes removed from svc for lab analysis horris JF Gute Poler Co 82/12/01 Region 2. Defice of Director ip 16-351 347 24X Fiche 50-287.82/12/01.8212090221
- 88:12150144 PtO-11-82-135 on 8212(1) unit shut down after discovery of O 2-gpm leat in steam generator 8 No abhormal release of radicativity associated w/e.ent Unit will be out of svc approx 2 whs 16"ATOVIS A , DANCE.H C Region 2 Office of Director 82/12/13 pp 16430 187 24% Fichs 50-287,82*12/13.8212150144
- E: 12300124 FO on 821213. Region 2 informed of two manual containment isolation alves discovered open Rept providing details delayed due to investigation Rapt will be completed by C018231 TUDEER H B Duke Power Co 82/12/23 O'REILLY, J P Region 2, Lifties or Director ip 18598 033 24X Fiche 50-287, 82/12/23, C212323224
- 60:12300264 RO 287/82-14 primary to secondary leat discovered in steam generator 38 Rept will not be submitted until 830107 contrary to previous commitment 102684 H3 Duke Pouer Co. 82/12/23 D'REILLY, J.P. Region 2, Office or Director 1p. 16595-255 24X Fiche 50-287,82/12/23,
- DUCKET 50-287 THREE MILE ISLAND NUCLEAR STATION. UNIT 1

 F. Security medical, energency & fire protection plans
- --8212030207 IE Insp Rept 50-287/82-17 on 820908-10 & 1004-08 No noncompliance noted Major areas inspected actions taken to resolve deficiencies identified in NUREG-0752, "Control Room Design Review Rept for IMI-1" PETRONA: C RICHARDS. S BETTENHAUSEN.L Region 1. Office of Director 82/11/17 20pp 18304 010 24X Fiche 50-289.82/11/19, 8212030193
- 8.412030215 Forwards IE Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted MARTINITY Division of Project & Resident Programs 82/11/19 HUMILL H D General Public Utilities GPU Service Corp 2pp 16307 053 24x Fiche 50-289,82/11/19,8212030215
- --G212030221 IE Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted Major areas inspected fire protection/prevention program including fire brigade training ignition source & cambustible matter control of FIMACL A E RETTENHAUSEN.L Division of Project & Resident Programs 82/11/12 7pp 16307 055 24X Fiche 50-289/82/11/19, 6212030215
- G: 12060054 Forwards Revision 16 to modified amended physical security plan Revision withheld (ref 10CFR2 790) Extension requested to 831201 to install equipment to permit radio communications in all plant areas eliminating dead spots HUMRILL.H D General Public Utilities GPU Service Corp 82/11/30 STOLZ.J F Operating Reactors Branch 4 to 16314 344 24x Fische 50-289, 82/11/30, 8212060054
- 89:12070251 Forwards tabular listings "Common Encl Identification Rept Equipment" per 821105 request for justification of compliance v/App R fire protection HVKILLH D General Public Utilities - GPU Service Cucp 82/12/02 EISEN-51.0 0 Division of Licensing 2pp 16333 270 24X Fichs 50-267 82/12/02.8212070251
- --8212070253 "Common Enci Identification Rept Equipment "
 General Public Utilities GPU Service Corp 82/11/24 362pp
 16333 292 24% Fiche 50-289, 82/12/02.8212070251
- B7:2160397 Forwards IE Insp Rept 50-289/82-12 on 820810-11.1006-08 & 1103 Mo noncompliance noted MARTIM 7 T Division or Engineering & Technical Programs B2/12/03 HMKILL H D General Public Utilities OPU Service Corp 16442 346 24% Fiche 50-289.82/12/03.8212160397
- --8212160406 IE Insp Rept 50-269/82-12 on 820810-11,1006-08 & 1103 No noncompliance noted Major areas inspected emergency preparedness exercise observation, evaluation & insp TERC, N H, CRCKER, H M Division of Emergency Preparedness & Operational Support 82/12/01 8pp 16442 348 24X Fiche 50-289,82/12/03,8212160397

- B212080519 Forwards info re emergency offsite facility in response to R Jacobs B21203 telcon request Permanent backup emergency offsite facility completed HUKILL.H D General Public Utilities GPU Service Corp B2/12/06 STOLT.J F Operating Reactors Branch 4 2pp 16352 083 24X Fiche 50-289, 82/12/06, 8212080519
- --8212220388 IE Insp Rept 50-287/82-25 on 821104.03,08 & 09 No nancompliance nobed Major areas inspected followup on items from IE Emergency Preparedness Appraisal Rept 50-287/81-20 on 810713-24
 TERC:N M. COHEN, I. CROCKER, H. W. Division of Emergency Preparedness & Operational Support 82/11/30 6pp 14517 23.3 24X Fichs 50-289,82/12/07.8212220383
- 8212220415 Forwards listings of major employers within facility emergency planning zone, in response to NRC request MCKELVY, O A General Public Utilities GPU Service Corp 82/12/00 KANTOR, F NRC No Detailed Affiliation Oiven 7pp 16504 001 24X Fiche 50-289,82/12/08,8212220415
- --B212220421 Forwards listings of hotels, motels, campgrounds & marinas within facility emergency planning zone HCKELVY, O A General Public Utilities GPU Service Corp B2/11/16 KANTGR.F NRC No Detailed Affiliation Given 7pp 16504 008 24X Fiche 50-287, 82/12/08, 8212220415
- 8212300141 Notification of 821223 significant licensee meeting w/util in King of Prussia.PA to discuss 820811 emorgency preparedness exercise results KEIMIG.R R Region I. Office of Director 82/12/20 Region 1. Office of Director 82/12/20 Region 1. Office of Director 50-289.82/12/20.
- 8212290371 Confirms 821223 meeting at Region 1 ofc to discuss 820811 mergency preparedness exercise results documented in 16 Emergency Preparedness Appraisal Rept 50-289/82-12 % to solicit comments re personnel performance during exercise STARDSTECKI, R Division of Project & Resident Programs 82/12/22 HUKILL, H D General Public Utilities CPU Bervice Corp 2pp 16586 264 24X Fiche 50-289,82/12/22,8212290371
- G Adjudicatory correspondence
- 8212010186 Comments on immediate effectiveness of decisions & supplications to Commission questions re TLDs
 ADLER,R H. Pennsylvania, State of 82/11/27 PALLADING,N J ,
 GILINGKY,V , AHEARKE,J F. Commissioners 2pp 16298-083
- 8212010192 Opposition to Commonwealth of PA 821112 petition for review of ALAB-698, objecting to portion re dosimetry for offsite emergency workers No important public policy question raised ASLB & ASLAB resolved facts in consistent manner TROWERIDGE, G F Metropolitan Edison Co TROWERIDGE, O F 8haw, Pittman, Potts & Trowbridge 82/11/29 Commissioners 10pp 16258 030 24X Fiche 50-289, 82/11/29, 82/2010192
- --8212010200 Response to NRC 821112 petition for Commission review of ALAB-698 Licenses does not object to petition Commission should establish schedule for filing briefs on issue raised by NRC petition Cartificate of Svc encl TROWBRIDGE OF Metropolitan Edison Co TROWBRIDGE OF Metropolitan Edison Co TROWBRIDGE OF Shaw. Pittman, Potts & Trowbridge 82/11/29 Commissioners 5pp 16258 041 24X Fiche 50-289, 82/11/29,8212010192
- 8212010195 Response to party & public comments at Commission 821109 meeting in Harrisburg,PA Public opinion is 100% against decision to restart at present time Bvc list encl AAMODT.M M Aamodts. The 82/11/29 7pp 16258 046 24X Fiche 50-289,82/11/29,8212010195
- 8212010032 Answer opposing MM Aamodt 821115 petition for Commission review of ASLAB Decision, ALAB-697, on emergency planning for farmers exceeds regulation requirements M/Certificats of Syc RAMY, J.R. Hearing Branch 4 82/11/30 Commissioners 15pp 16260 353 24X Fiche 50-289,82/11/30,8212010032
- 8P12010034 Response to Commission 821006 order inviting parties to respond to matters raised at Commission 821109 public meeting in Harrisburg.PA re restart NRC has no comments beyond NRC 821111 Itr Certificate of Syc encl GOLDBERO, J. R. Hearing Branch 2 82/11/30 7pp 16260 346 24X Fiche 50-289, 82/11/30, 8212010034

- GP12020346 Forwards corrected response to public & party comments at Commission 821109 meeting in Harrisburg.PA
 AAMODI.M M Aamodts. The 82/11/30 PALLADINO,N J , GILINSKY, V ,
 AHEARNE.J F Commissioners ip 16291 023 24X
 Fiche 50-289,82/11/30,8212020346
- --8212020401 Corrected version of response to public & party comments at Commission 821109 meeting in Harrisburg.PA Public is 100% against decision to restart plant at present time Svc list encl AMMODT.M Aamodts. The 82/11/29 7pp 16291 024 24% Fiche 50-289.82/11/30.8212020346
- B212020364 Response opposing Aamodt 821115 petition for review of portions of ALAB-697 re emergency planning for farmers Factual issues; resolved consistently by ASLB & ASLAB Questions of public policy not raised W/Certificate of Svc TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Bhaw, Pittman, Potts & Troubridge 82/11/30 Commissioners 8pp 16278 130 24X Fiche 50-289,82/11/30,8212020364
- 8212020377 Comments on matters raised during 921109 oral argument before Commission ASLB findings re resolution of concerns which caused Commission to suspend CL should be affirmed Certificate of Svc encl TROUDE 106E-0 F Metropoliten Edison Co 82/11/30 16pp 16291 007 24X Fiche 50-289, 82/11/30. 8212020377
- BP12030210 Motion for extension of 10 days from date of receipt of Commonwealth of PA B21112 petition for review of ALAB-698 to respond to petition NRC was not served by Commonwealth Certificate of Svc enci GRAY, J R Hearing Branch 4 82/12/01 Commissioners 6pp 16304 037 24X Fiche 50-287,82/12/01.8212030210
- GP12060092 Order extending time until 821213 for Commission to act to review ALAB-699
 CHILK.S J Office of the Secretary of the Commission 82/12/02
 Commissioners ip 16316 077 24X Fiche 50-289,82/12/02,82:2060092
- 82:2060242 Order extending time until 82:208 for NRC to file response to Commonwealth of PA petition for review of ALAD-698 CHILK, 8 J Office of the Socretary of the Commission 82/12/03 Office of the Executive Legal Director 1p 16312 264 24X Fiche 50-289, 82/12/03, 82:2060242
- 8212070134 Advises of personnel changes since close of record on mgt issues.per procedure authined in util 821001 ltr Svc list encl Related correspondence BLAKE.E L Shaw. Pittman. Patts & Trowbridge BLAKE.E L Hetropolitan Edison Co 82/12/03 EDLES.O J. BUCK.J H. KOHL.C N Atomic Safety and Licensing Appeal Panel 4pp 16327 067 24X Fiche 50~289.82/12/03,9212070134
- 8212070165 Advises that pleadings should be served on JR Gray at listed address.not on JR Tourtellotte WAGNER.M E Hearing Branch 4 82/12/06 Metropolitan Edison Co lp 16335 314 24X Fiche 50-289.82/12/06.8212070165
- 6212070170 Discusses 621203 meeting w/FEMA & Dauphin County,PA Board of Commissioners na Dauphin County May 1962 nonbinding referendum on restart, comments made at Commission 821109 meeting & omergency planning DENTON,H R Office of Nuclear Reactur Regulation, Director 82/12/06 PALLADINO,N J. OILINSKY,V. AHEARNE, J. Commissioners 1p 16335 298 24X Fiche 50-269,82/12/06,8212070170
- 8212070183 Order extending time until 830114 for Commission to act to review ALAD-697 & ALAB-698
 CHILK: S J Office of the Secretary of the Commission 82/12/06 Commissioners ip 16335 262 24X Fiche 50-289.82/12/06.
 R912070183
- B312090802 Motion to defer consideration of Commonwealth of PA petition for partial review of ALAB-699, until 830117 Substantial agreement in principle reached on issue of personnel dosimetry requirements W/Certificate of Svc ADLER, R W Pennsylvania, State of 82/12/06 Commissioners 5pp 16365 327 24X Fiche 50-289,82/12/06,8212090502
- 8212070242 Answer opposing Commonwealth of PA 821112 petition for Commission review of ALAD-698 on dosinetry for amergency workers Through use of self-reading dosineters & procedures, workers adequately protected Certificate of Bvc encl GRAY.J R Hearing Branch 4 82/2/08 Commissioners 15pp 16363 229 24X Fiche 50-289,82/12/08.8212090242

- 8212140432 Decision ALAB-705, affirming LBP-81-60 which rejected UCS Contention 20 re analysis of environ effects of Class 9 accidents Commission 800613 policy statement on Class 9 accidents applicable Judge Edles dissenting opinion encl SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/12/10 43pp 16405 155 24X Fiche 50-289,82/12/10.8212140432
- B212150045 Order extending time until B21220 for Commission to act to review ALAB-699 CHILK, S.J. Office of the Secretary of the Commission B2/12/13 Commissioners tp 16422 330 24% Fiche 50-289,82/12/13. B212150045
- BF12160271 Motion for partial withdrawal of Commonwealth of PA exceptions as moot Exception 1 as applied to Operator G should be withdrawn Ecception 3 should be withdrawn conditioned on ABLAB approval of licensee offer ADLER.R W Pennsylvania, State of 82/12/13 Atomic Safety and Licensing Appeal Panel 5pp 16442 358 24% Fiche 50-289,82/12/13.8212/160271
- BP12160297 Forwards memos of telcons u/citizens re restart STUCKY,S W Docketing & Services Branch 82/12/15 Office of the Crecutive Legal Director 4pp 16446 064 24X Fiche 50-289, 82/12/15, 8212160297
- 8P12210272 Reply to licensee response to 821109 oral argument Licensee assertions & argument were made in licensee response for first time No sufficient reliable means of DHR exists Certificate of Svc and WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Harmon & Weiss B2/12/16 9pp 16483 235 24X Fichs 50-289, 82/12/16, 8212210272
- 8212210336 Forwards corrected Page 3 to UCB 821216 reply to licensed response to 821107 oral arguments WEISS.ER Harmon & Weiss WEISS.ER Union of Concerned Scientists 82/12/17 PALLADINO.N J , AHEARNE.J , ASSELSTINE, J Commissioners ip 16496 335 24X Fiche 50-289,82/12/17, 2212210324
- --8212210339 Corrected Page 3 to UCS 821216 reply to 11consee responded to 821109 oral arguments * Union of Concerned Scientists 82/12/17 Commissioners [p 16496 336 24X Fiche 50-289:82/12/17:8212210336
- GP12220266 Order extending time until B21229 for Commission to act to review ALAD-699 CHILK 5 J Office of the Secretary of the Commission B2/(2/20 Commissioners to 16517 362 24X Fiche 50-289,87/12/20, 321272024A
- 8212270008 Response supporting Commonwealth of PA 821206 motion to defer consideration of Commonwealth 821112 petition for partial review of ALAB-698 Agreement negotiations underway Certificate of Svt encl GRAY, J R Hearing Branch 4 82/12/22 Commissioners 17pp 16538 300 24% Fiche 50-289.82/12/22.8212270008
- Q212300008 Request for extension until 830107 to provide comments on Commission 821217 meeting Delay necessary due to counsel absence & need to analyze NRC generic 1tr on emergency feedwater sys & util responses Cortificate of Svc encl WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 82/12/27 Commissioners App 16598 132 24X Fiche 50-269, 82/12/27, 8212300008
- OP12300002 Patition for review of ALAB-705,upholding ASLB rejection of UCS Contention 20 re NEPA evaluation of Class 9 accident NRC policy statement requires analysis of Class 9 accident in proceeding Certificate of Svc encl WEISS, ER Union of Concerned Scientists WEISS, ER Harmon & Weiss 82/12/28 Commissioners lipp 14598 153 24% Fiche 50-289,02/12/28,8212300002
- 8P12300142 Order granting UCS 821227 request for extension until 83010/ to file comments on Commission 821217 meeting Extension granted to all parties CHILK, B J Office of the Secretary of the Commission 82/12/29 Union of Concerned Scientists ip 16597 328 24X Fiche 50-289, 82/12/29, 8212300142
- B212300147 Memorandum & order ALAB-708, reopening record to clarify adequacy of core DHR in event of loss of main feedwater or small break LOCA All testimony due by 830126 Evidentiary hearing will commence on 830208 Briefs due by 830228 TOMPKINS, B.A. Atomic Safety and Licensing Appeal Panel 82/12/29 45pp 16597 283 24X Fiche 50-289,82/12/29,8212300147

- 8212300242 Forwards corrected copy of petition for review of ALAB-705, filed 821228 Original filed w/o pages numbered & w/seme typographical errors M/o encl MEISS.E R Harmon & Weiss WEISS.E R Union of Concerned Scientists 82/12/27 Atomic Safety and Litensing Board Panel 1p 16595 276 24% Fichs 50-289.82/12/29.8212300242
- 8012300246 Comments on Commission B21217 meeting re LLL technical evaluation rept on seismic qualification of auxillary feedwater sys Comments confirmed in util 021220 ltr to NRC Certificate of Svc encl TROMBRIDGE.0 F Metropolitan Edison Co B2/12/27 App 16595 235 24X Fiche 50-289.82/12/29.8212300246
- BP12300250 Response in opposition to UCS 821227 request for extension of time to provide comments on Commission 821217 meeting Insufficient cause shown for delay Certificate of 8vc encl PROMBRIDGE, OF Metropolitan Edison Co TROMBRIDGE, OF Shaw, Pittman, Potts & Trowbridge 82/12/27 Commissioners 7pp 16595 266 24X fiche 50-287,82/12/27.8212300290
- 8012300362 Petition for review of B21213 Decision ALAB-705, which rejects UGS Contention 20 & calls for public assessment of risk Case appropriate for Commission review Certificate of Svc encl WEISB, E.R. Union of Concerned Scientists WEISB, E.R. Harmon & Weiss 82/12/29 Commissioners 11pp £6974.243 24X Ciche 50-289.82/12/29.8212300362
- H General correspondence
- GP12070042 Responds to B21018 ltr forwarding constituents K & M Scott 821015 ltr re sirens in prompt public notification sys FEMA & local govt agencies should be contacted DIRCKS, M J Office of the Executive Director for Operations 82/11/18 0000LING, B House of Rep 4pp 16356 259, 24X fiche 50-289, 82/11/18-6312070062
- --8212070068 Requests views & comments on constituents K & B Conner 821015 for re sirens in prompt public notification sys 000DLING.B House of Rep 82/10/18 KAMMERER.C Office of Congressional Affairs 2pp 16356 265 24X Fiche 50-289, 82/11/18,8212070062
- GP12080280 Demands Commission order permanent closing of plant CNDRASIK, M. HOLT, J. Public Interest Research Group, New York 82/12/01 PALLADING, N. J. AHEARNE, J., OILINSKY, V. Commissioners 2pp 16384 211 24% Fiche 90-289,02/12/01.8212080280
- BP12070027 Expounds on NRC B20809 ltr ro performance of steam generators in event of transients &/or accidents Preliminary info indicates max tube to tube wheet difference in temp during worst case accident will be less than 30 F CISENHUT.D 0 Division of Licensing 82/12/02 LEMIS.M I Lewis, M 1p 16356 280 24% Fichs 50-289,82/12/02.8212070027
- P Operating license stage documents & correspondence
- 821227003B Forwards "THI-1 Recovery Regenerative Neutron Source Retainer Eran." "Eran of THI-1 Reactor Vessel O-Ring & Control Red Drive Mechanism Closure Insert," final rept & "Final Rept on Failure Aralysis of Incomel A00 Tubes " MCCRACKEN.C Chemical Engineering Branch 82/10/27 BENARDYA,V Chemical Engineering Branch 10 14349 001 24% Fiche 50-289, 82/10/27,821227003B
- 8212270042 "THI-1 Recovery Regenerative Neutron Bource Retainer Exam "
 MCINTEER,W A. BAIN.Q H Babtock & Wilcox Co RDD 83 5487 01
 B2/05/20 22pp 16547 002 24% Fiche 50-289.82/10/27.8212270098
- --8212270047 "Exam of THI-1 Reactor Vesset O-Ring & Control Rod Drive Mechanism Closurs Insert," Pinal rept BATY-D L Batock & Wilsox Co. RDD 83 5490/5491 02 82/06/03 74pp 16549 024 24% Fiche 50-289, 82/10/27, 8212270038
- --G212270056 "Final Rept on Failure Analysis of Incomel 600 Tubes from Once Through Steam Generator A B B of THI-1" W/three oversize figures Aperture cards are available in FDR AGRAMAL.A K, STIEGELMEYER.W, BERRY.W E Battella Mamorial Institute. Columbus Laboratories B2/06/30 132pp 16549 100 24X Fiche 50-289,82/10/27,8212270038
- BP12060147 Requests comments on encl bechnical evaluation rept re
 Multi-Plant Action Plan C-14, "Seismic Qualification of
 Auxiliary Feedwater Sys." for facility Present sys unlikely
 to withstand SSE Comments & add info needed by 821220
 STOLZ, J. F. Operating Reactors Branch 4 82/11/16 HUKILL, H. D.
 General Fublic Utilities GPU Service Corp. 13pp. 16328 341 24x
 (iche 50-289,82/11/16.8212060147

- BP12010342 Advises that radiological field operations training program per util 920223 ltm acceptable subj to incorporation of certain experience requirements for radiological control forement technicians Safety evaluation forwanded STGLZ. J F Operating Reactors Branch 4 82/11/17 HUKILL.H D General Public Utilities GPU Service Corp 3pp 16271 324 24X fiche 50-287.82/11/17.8212010342
- --8212010347 Bafety evaluation supporting radiological field operations training program subj to listed mods
 + Defice of Nuclear Reactor Regulation, Director 82/11/17 Spp 16271 327 24% Fiche 50-289, 82/11/17, 8212010342
- BP1227004) Board-Notification 82-118 forwards 82:103 technical evaluation rept. "TMI-1 Reisnic Qualification of Auxiliary Feedwater Sys," re hearing on issue of emergency feedwater sys reliability LAINAS. C C Assistant Director for Operating Reactors 62/11/22 Atomic Bafety and Licensing Appeal Panel 5pg 16353 343 24% Fiche 50-289:82/11/22.8212270041
- -- 8211110483 Forwards "Beismic Qualifications of Auxilary Feedwater Syn," technical evaluation rept.submittled in response to Multiplant Action Item C-14 per Generic Ltr 81-14 Condensor hotuall supply lines seismic capability questionable MIRROLIA, F J Assistant Director for Bafety Assessment 82/11/07 LAINAS, G C Assistant Director for Operating Reactors 11pp 16953-348 24X Fiche 50-287, 82/11/22, 8212270041
- OP12060908 Summary of 821018-17 meetings w/util re steam generator recovery program
 JACQDS.R H Operating Reactors Branch 4 82/11/23 Operating
 Reactors Branch 4 108pp 16344 020 24X Fiche 90-289,82/11/23,
 12122060508
- BF:120702B4 Forwards application for amend to License DPR-50, proposing Tech Spec Change Request 117 extending current Tech Spec requirements to provide NRC more detailed info on aircraft movements RKKFLL-H D General Public Utilities GPU Service Corp 62/11/30 STOLZ, J F Operating Reactors Branch 4 2pp 16365-184 24X Fichs 30-287, 82/11/30,8212070284
- --B212090R93 Application for amend to License DPR-50, proposing Tech Spec Change Request 119, extending current Tech Spec requirements to provide NRC more detailed info on aircraft movements Description of change & Certificate of Svc encl HUKILL, H D General Public Utilities - GPU Service Corp 82/11/30 3pp 16365 185 24X Fiche 50-289, 82/11/30, 0212090284
- OPIZO90501 Forwards "Pressurizer Relief Bys Piping & Support Evaluation Rept for THI-1 Rept fulfills requirement of NUREO-0737. Item 11 D 1. "Relief & Safety Valve Testing " HUKILL,H D. General Public Utilities - GPU Service Corp 82/12/03 EIBENHUT.D O Division of Licensing Epp 16364 123 24X fiche 50-289, 82/12/03.8212090501
- GP12130281 Board Notification 82-125 Forwards into re-recent ACHB evaluation of PHR flow blockage during natural circulation EFSEMHUT, D 0 Division of Licensing 82/12/06 PALLADIND, N , OILLINSKY, V , AHEARNE, J Commissioners 3pp 16418 251 24X Fiche 30-000 82/12/06, 8212130281
- OPIRISOLOA Forwards summary of Test Procedure TP 664/2. Bection 9 5.
 "Determination of Baturation Margin & RCS Pressure vs Time
 Following Simulated Loss of Pressurized Heaters," to fulfill
 HI3214 partial initial decision requirements
 NUMILL.H D General Public Utilities OPU Service Corp B2/12/07
 BTOLZ.JF Licensing Branch 4 HAYNESPR C Region 1. Office of
 Director 6pp 16390 179 24% Fiche 50-289.82/12/07.8212130104
- GP12140466 Natifies that inservice pump & valve testing program upgrade will reflect Section XI.DIV I.of ABME Boller Pressure Vessel Code.permitting pump testing to be performed quarterly rather than monthly HUKILL.H D. General Public Utilities OPU Service Corp. 82/12/07 STGLZ.J F. Operating Reactors Branch 4 ip 16404 GAS 24X Fiche. 50-289-82/12/07.8212140466.

- 820B190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EIBEMHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16627 247 24X Fiche 50-000, 82/12/09, 8208190263
- BP12230020 Board Notification 82-118A forwards info re spismic capability of auxiliary feedwater sys EISENHUT, D.G. Division of Licensing 82/12/09 PALLADING, N.J. GILINSKY, V. AHEARNE, J.F. Commissioners App. 16940-294 24X Fiche 80-289, 82/12/09, 8212230020
- -0212070005 Responds to 021117 request to review LLL technical evaluation rept re seismic capability of auxiliary feedwater sys QC Lainas 021122 board notification memo also reviewed Testimony on hearing unchanged MATT80N.R J Division of Bystems Integration (post 01005) 0212003 CISENHUF.D O Division of Licensing 1p 16540 296 24X Fiche 00-289, 02/18/09, 0212230080
- --8212230033 Forwards Miraglia 821103 memo w/LLL rept re seismic qualification of auxiliary feedwater sys Board natification needed Restart hearing record did not include low probability natural events
 EISENHUT.D Q Division of Licensing 82/11/19 MATTSON.R Division of Systems Integration (post 811005) VOLLMER,R Division of Engineering ip 16840 297 24% Fichs 50-289.82/12/09.8212230020
- BP12230049 Board Notification 82-125A forwards info re PWR flow blockage Info suppls Board Notification 82-125 CIBERMUT.D 0 Division of Licensing 82/12/09 PALLADING, N. J. GILINSKY, V. A.MEGANCI, J. Commissioners 3pp 16545-338 24X Fich 50-000, 82/12/09, 8212230049
- --B212230088 Forwards Fratey B21207 memo re flow blockage by steam during natural circulation in PWRs
 EIGENHUT, D Q Division of Licensing B2/12/09 LAINAS, Q
 Assistant Director for Operating Reactors ip 16545-341 P4X
 Fithe 50-000.B2/12/09.B212230049
- BP12230070 Board Notification 62-127 forwards info re reporting of aircraft movements at Harrisburg Airport & computation of aircraft crash probabilities by util FIBE MHUT, D 0 Division of Licensing 62/12/07 PALLADING, N, OILINSKY, V, ANEARNY, J F. Commissioners 3pp 16545 217 24X Fiche 50-287, 02/12/07, 02/12300/07
- 0.12140180 Updates 821124 response to Generic Ltr 82-22, "Steam Constator Tube Integrity "Exposure estimate will be higher than previously indicated CLARK.P.R. General Public Utilities GPU Service Corp. 82/12/10 (ISEN#UT.D.C. Division of Licensing 2pp. 16410 208 24X Fiche 50-289, 82/12/10.8218140180
- 8):12150110 Forwards SER for return to svc after repair of steam generators Final plans for steam generator & RCS cleanup & results of post-repair testing will be addressed at later date Affidavit enci Rept withheld (ref 10CFR2 770) CLARK, P.R. General Public Utilities QPU Bervice Corp. 82/12/10 E18ENPUT.D Q Division of Licensing 2pp 16430 338 24X Fiche 50-287,82/12/10.8212150110
- 82(21501)3 Affidavit of JH Taylor re BER for return to svc after repair of steam generators B&W info considered proprietary TAYLOR, J H. Babcock & Hilcox Co 82/12/03 7pp 16430 340 P4X Fishe 50-289, 82/12/10,8212150110
- GP12230023 Forwards order modifying License DPR-BO requiring installation of inadequate core cooling instrumentation sysconforming to design parameters in NUREG-0737. Item II F 2 EIBENHUT, D. O Division of Licensing B2/12/10 HUKILL, H D General Public Utilities GPU Service Corp App 16546 027 24X Fiche 50-289. 82/12/10.8212230023
- --8212230030 Order modifying License DPR-50, requiring installation of inadequate core cooling instrumentation sys conforming to design parameters in NUREQ-0737. Item II F 2
 EIEENRUT.D. Q Division of Licensing 82/12/10 General Public Utilities 900 Service Corp 11pp 16546 031 24X
 Fiche 50-289, 82/12/10, 8212230023
- EPI2170119 Forwards summary status rept for items requiring NRC certification prior to restant per 770809 order & notice of hearings Items not related to 770809 order, but requiring verification of completion, also encl
 ARNOLD, R C Oeneral Public Utilities OPU Service Corp 82/12/1DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 16450-300 24x Fiche 80-289,82/12/14.8212170119

- 8P12210017 Informs that revisions to NUREO-0737. Item I A I 3 re staff working hours will be included in Tech Spec change request per 820615 Generic Ltr 82-12 Revision expected by Jan 1983 HUKILL, H D General Public Utilities GPU Service Corp B2/12/16 L158PHUT, D H Division of Licensing 1p 16490 162 24X [iche 50-287, 82/12/16.8218210017
- 8212270134 Forwards response to Generic Ltr 82-16 re Tech Specs required by NUREO-0737 items NUKILL, N D General Public Utilities - GPU Service Corp 82/12/1/ LISEMHUT, D O Division of Licensing 3pp 16538-017 24X Fiche 90-289, 82/12/17.02312270134
- 8212270268 Forwards responses to issues addressed in 821116 technical evaluation rept for seismic qualification of emergency feedwater sys All identified long-term sys mods will be completed by next refueling outside HUKILL.H D. General Public Utalities GPU Service Corp. 82/12/20 FIGLZ.J F. Operating Reactors Branch 4 Spp. 16590 313 247 Fiche 50-289, 82/12/20,8212270260
- 8/12290197 Advises that Util has issued Revision 9 to Section 7 3 of Corrective Maint Procedure MP 1407-1 to patential for work on non-QC component to effect nuclear safety, fulfilling intent of B10827 ASLB partial initial decision MUXILL, H D General Public Utilities GPU Service Corp 82/19/21 STGLZ.J F Operating Reactors Dranch 4 1p 16578 147 24X [iche 50-289, 82/12/21, 8212290197
- GP12300335 Board Notification 62-133 forwards JF Stoll 821210 ltm & SJR based on encl comproprietary & proprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D 60), TMI-1," Vals 1 & 2 I ISEMHUT, D 0 Division of Licensing G2/12/27 PALLADING, N J, GILIMBRY, V , ASSELSTIME, J K Commissioners 3pp 16597 21k 347 Fiche 50-269, 62/12/27, 6212300335
- --0212300339 Forwards SER based on "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-1 & 0-60). FMI-1." Vols 1 & 2 Proprietary rept withheld (ref 10CFR2 790)

 STOL7.J F Operating Reactors Branch 4 82/12/10 HUKILL.H D General Public Utilities GPU Service Corp 2pp 16599 215 F4X Fiche 50-289,82/12/27,8218200335
- --8212300342 SER supporting continued operation pending completion of licenses environ qualification program based on "Review of Licenses Resolution of Outstanding Issues from NRC Equipment Environ Qualification SERs (F-11 & D-60), TMI-1, "Vols 1 & 2 & Office of Nuclear Reactor Regulation, Director 02/12/10 App (6599-217 24x Fiche 50-269, 82/12/27, 82127003)5
- 8212300348 Nonproprietary "Review of Licenses Resolution of Dutstanding Issues From NRC Equipment Environ Qualification Sites (F-11 & B-60).TM(-1, " technical evaluation rept. Vols 1 & 7. PANDEY, S Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05207-492 02/11/05 bill MANSKI, P NRC Nn Detailed Affiliation Given 040pp 16597 223 24X Fiche 30-209.02/12/27.0212300339
- O Inspection reports, IE Bulletins & correspondence
- 80:08190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at SNR Plants "Swc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York. Int 112pp 16462 163 24X Fichs 50-000.82/10/28.0208170240
- BP08190245 IE Info Natice 82-42, "Defects Observed in Panasonic Model 802 thermoluminescent Desimeters" Sec list one!

 COMB.L. I Division of Fuel Pacilities, Materials & Gafeguards 82/11/09 Consolidated Fdison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000, B2/11/00, B200190245
- 8008190251 IE Info Notice BR-44, "Clarification of Emergency Plain Liercise Requirements " Svc list encl JORDANIC L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24X fiche 50-000.82/11/18.8208190251
- 8212030193 Forwards IE Insp Rept 50-287/82-17 on 820708-10 & 1004-08 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs HUKILL-H D General Public Utilities OPU Genvice Corp 16304 do8 24X Fiche 50-289, 82/11/19, 8212030193

- --8212030207 IE Imap Rept 50-289/82-17 on 820908-10 & 1004-08 No noncompliance noted Major areas inspected actions taken to resolve deficiences identified in NUREG-0752. "Control Room Design Review Rept for IMI-1"

 PETRONE, C. RICHARDS, S. BETTENHAUSEN, L. Region 1, Office of Director 82/11/17 20pp 16304 010 24% Fiche 50-289.82/11/19.8212030193
- 8212030215 Forwards 1E Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted MARTIN, T T Division of Project & Resident Programs 92/11/19 HUXILL-H D General Public Utilities - OPU Service Corp 2pp 16307 053 244 Fich
- --8212030221 IE Insp Rept 50-289/82-23 on 821018-22 No noncompliance noted Major areas inspected eire protection/prevention program, including fire brigade training, ignition source & combustible matl control FIRMELIA E . BETTENHAUSENIL Division of Project & Resident Programs 62/11/12 7pp 16307 055 24X Fiche 50-289.82/11/19, 8212030215
- 8708190256 IE Info Natice 82-46, "Defective & Obsolete Combination Padlocks" Svc list end DEYOUVG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 82/08190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Mat! " Svc list enc! CBBs.L ! Division of Evel Facilities Materials & Safeguards 62/11/30 Consolidated Edison Co of New York | Inc 356pp 14387 028 24x Fiche 50-000.82/11/30.8208190257
- 8/08190259 IE Bulletin 82-04. "De+iciencies in Primary Containment Liectrical Penetration Assemblies " Syc list and DEVOUNG.R C Birector's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 15411 317 24x Fiche 50~000.82/12/03.8208190259
- EPOBI90251 IE info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets ' Suc fist encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462-064 P4X Fiche 50-000, 62/12/03, 8208190261
- G.P22160597 Forwards IE Insp Rept 50-289/82-12 on 820810-11, 1006-08 & 1103 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 82/12/03 HUXILL.H D General Public Utsilities GPU Service Corp 2pp 16-142 346 24X Ficha 50-289, 82/12/03, 8212160397
- -6212160406 IE Insp Rept 50-287/82-12 on 620810-11,1006-08 & 1103 No noncompliance noted Major areas inspected swengency preparedness electise observation, evaluation & insp TERC.N H. CROCKER.H W. Division of Emergency Preparedness & Operational Support 82/12/01 8pp 16442-348 24X Fiche 50-289,82/12/03,821216097
- BD12220393 Forwards IE Insp Rept S0-287/82-25 on 821104.05.06 & 09 No Honcompliance noted MARTIN. F. T. Division of Engineering & Technical Programs 82/12/07 HORILLH B General Public Utilities ~ GPU Service Corp 14517 231 24X Fiche 50-289.82/12/07.8212220383
- --B212220383 IE Insp Rept 50-287/82-25 on 821104.05.08 & 07 No noncompliance noted Major areas inspected followup on items from IE Energency Preparedness Appraisal Rept 50-287/81-20 on 810713-24

 TERC.N M. COHEN. I. GROCKER. H. W. Division of Emergency Preparedness & Operational Support 82/11/30 App. 16517-233-244 Fiche 50-289.82/12/07.8212220383
- 8P12220457 Forwards IE Insp Rept 5D-289/82-21 on 821005-1108 & notice of violation STARGSTECKLR Division of Project & Resident Programs 82/12/09 HOWILL-H D General Public Utilities GPU Service Corp 2pp 16504 264 24X Fiche 50-289/82/12/09/8212220459
- --6212220469 Notice of violation from insp on 821005-1108 * Division of Project & Resident Programs 82/12/09 1; 16504 266 24% Fiche 50-289, 82/12/09, 8212220459
- --8212220478 IE Insp Rept 50-289/82-21 on 821005-1108 Noncompliance noted failure to purform safety evaluation CONTE.R. THANUS.L. YOUNG.F. Division of Project & Resident Programs 82/12/09 10pp 16504 267 24X Fiche 50-289,82/12/09,8212220459

- 8P12220464 Forwards IE Insp Rept 50-289/82-23 on 821012-28 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/12/09 HUKILL.H D General Public Utilities GPU Service Corp 2pp 16504 034 24X Fiche 50-289,82/12/09,8212220464
- --8212220467 Notice of violation from insp on 821012-28 + Division of Project & Resident Programs 82/12/09 ip 16504 036 24% Fiche 50-289, 82/12/09, 8212220464
- --8212220471 IE Insp Rept 50-287/82-22 on 821012-28 Noncompliance noted failure to perform adequate radiation survey o'NEILL B. BARR, K. FASANG, A. Division of Project & Resident Programs 62/11/27 lipp 16504-037 24X Fiche 50-289,82/12/09,8212220464
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUND.R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Conselidated Edison Co of New York. Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8PO8190248 IE Info Notice 82-50, "Mod of Sulid State AC Undervoltage Relays Type ITE-27" Svc list encl UCRDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp. 16628
- 8/12290371 Confirms 821223 meeting at Region 1 ofc to discuss 820811 emergency preparedness exercise results documented in IE Emergency Preparedness Appraisal Rept 50-289/82-12 & to solicit comments respersonnel performance during exercise STAROSTECKLR Division of Project & Resident Programs 82/12/22 HUKILL-H D General Public Utilities 0PU Service Corp 2pp 16586-264 24X Fiche 50-289-82/12/22-8212290371
- R Periodic operating reports & related correspondence
- G./12210232 Forwards monthly operating rept for Nov 1982 HUKILL.H D General Public Utilities - OPU Service Corp 82/12/15 Division of Data Automation & Management Information 1p 16484-072 24X Ficho 50-289, 82/12/15.8212210232
- --8212210234 Monthly operating rept for Nov 1982 SMYTH.C W General Public Utilities - GPU Service Corp 82/12/15 App 16484 074 24X Fiche 50-289,82/12/15,8212310232
- S Reportable occurrences. LERs & related correspondence
- GP12140228 Forwards LER 82-015/03L-0 MUNIALL H D General Public Utilities - GPU Service Corp 82/12/02 HAYNES,R C Region 1, Office of Director 1p 16408 359 24X fiche 50-289,82/12/02,8212140228
- --8212140239 LER 82-015/03L-0 on 821103.1 5-inch irregular diameter hole found in floor fire barrier penetration seal Caused by unsealed opening fire watch posted Seal repaired on 821109 STEPHENSON.C J General Public Utilities GPU Service Corp 82/12/02 Region 1, Office of Director 3pp 16408 360 24X Fiche 50-287,82/12/02.8212140228
- T Hearing transcripts on non-antitrust matters
- 8£12300116 Transcript of Commission 821216 meeting in Washington, DC re order to all PWRs, except TMI-1, requiring mod to inadequate core cooling sys Pp 1-3 # Office of the Secretary of the Commission 82/12/16 6pp 16624 241 24% Fiche 50-287,82/12/16.8212300116
- Sti2280037 Unofficial transcript of B21217 public meeting in Washington.DC re briefing on Board Notification 82-118A, "TMI Seismic Capability of Auxiliary Foedwater Sys "Pp 1-57 Supporting documentation encl Commissioners 82/12/17 A3pp 16592 291 24X Fiche 50-289.82/12/17.8212280037
- BP12210319 Forwards transcript of Commission 821217 meeting re restart Parties have until 821230 to submit comments on transcript W/o encl CHILK, B J Office of the Secretary of the Commission 82/12/20 NRC - No Detailed Affiliation Given ip 16496 252 24X Fiche 50-289, 82/12/20,8212210319

- DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8212060270 Ack receipt of 921117 request for approval of rescheduling 1983 annual full-scale emergency exercise from May 1983 to June 1983 Request forwarded to proper branch fur consideration MARTIN.T T Region 1. Office of Director 82/11/29 HARRINGTON.H D Boston Edison Co 1p 16312 142 24X Fiche 50-293.82/11/29,8212060270
- --B212060272 Requests approval of rescheduled 1983 annual full-scale emergency exercise from May 1983 to June 1983, per FEMA 821027 request FEMA ltr encl MORISI, A V Boston Edison Co 82/11/17 BORES, R J Division of Emergency Preparedness & Operational Support 2pp 16312 143 24% Fiche 50-273,82/11/27,8212060270
- 87:12100031 Submits requested info re primary & backup emergency operations facility (EOF) EOF completed & operational in Mar 1781
 MORIBI.A V Boston Edison Co 82/12/06 VASSALLO, D B Operating Reactors Branch 2 2pp 16377 031 24X Fiche 50-293,82/12/06,8212100031
- 8P12(30037 Forwards Revision 9 to modified amended security plan Revision withheld (ref 100FR73 21) MCRISI.A V Boston Edison Co 82/12/06 VASSALLO,D B Operating Reactors Branch 2 1p 16390 173 24X Fiche 50-293.82/12/06. R
- 8212150219 Ack receipt of 820915 & 1022 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/02-19
 STAROSTECKI.R Division of Project & Resident Programs 82/12/10 HARRINGTON N D Boston Edison Co 2pp 16430 252 24X Fiche 50-293,82/12/10,8212150219
- --8212150224 Responds to NRC 820816 ltr reviolations noted in IE Insp Rept 50-293/82-19 Corrective actions watch engineer unblocked fire door & returned door to closed position & door mechanism repaired HARRINGTON, W D Boston Edison Co 82/09/15 STARUSTECKI, R Division of Project & Resident Programs 7pp 16430 254 24X Fiche 50-293.82/12/10.8212150219
- --8212150233 Submits supplemental response to NRC 820816 ltr reviolation noted in IE Insp.Repts 80-273/82-04 & 50-273/82-19 Plan to correct deviations between local leak rate testing sketches & valve lineup checklists enc.)

 HARRINGTON, W.D. Boston Edison Co. 82/10/22 STAROSTECKI, R.

 Division of Project & Resident Programs 3pp 16430 261 24)

 Fiche 50-273,82/12/10.8212150219
- B212170305 Application to amend License DFR-35, requesting relief from Tech Spec re fire barrier penetration scals HONARD, J E Boston Edison Co B2/12/15 VASSALLO, D B Operating Reactors Branch 2 4pp 16456 131 24X Fiche 50-273,82/12/15, R212170305
- --B212170310 Proposed Tech Spec changes to Section 3 12 F, revising limiting condition of operation for specific fire barrier. currently requiring establishing continuous fire patrol when penetration fire barrier not functional

 * Buston Edison Co 82/12/15 2pp 16456 135 24X Fiche 50-273,82/12/15,8212170305
- 6212210015 Advises of procedures for reporting events via emergency notification sys Advance knowledge of types of info should improve effectiveness of calls Dissemination of encl forms to shift crews will alleviate further confusion STAROSTECKI.R Division of Project & Resident Programs 82/12/16 HARRINOTON, W D Boston Edison Co &pp 16490 196 24X Fiche. 50-293, 82/12/16,8212210015
- J Insurance & indemnity information
- B212280441 Forwards Certificate of Insurance N-31 for Endorsements 1.2 & 3 to NELIA Policy NF-188 & Certificate of Insurance M-31 for Endorsements 1.2 & 3 to MAELU Policy MF-58 SINISI.J M Maysh & McLennan.Inc . M & M Nuclear Consultants, Inc Diy 82/12/20 SALTZMAN.J D Assistant Director for State & Licensee Relations 19pp 14554 038 24X Fiche 50-293.82/12/20, 8212280441

P Operating license stage documents & correspondence

- B211230046 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBMR.Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0783 & NUREG-0783 Svc list ent II/0 stated ent EISEM-WIT.D G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 247 Fiche 50-000, 82/11/15, 8211230066
- 8212100014 Advises that util response to THI Item II K 3 25 re effect of loss of ac power on pump seals acceptable since response endorsed BWR owners group position VASSALLO.D 8 Operating Reactors Branch 2 82/12/01 MORISI.A V Boston Edison Co 7pp 16379 228 24% Fiche 50-273.82/12/01.
- 8212140139 Requests schedular relief from requirements of NUREG-0737, Item I A I 3, "Shift Manning " Relief required due to high failure rates of exam candidates & attrition rate of existing personnel New implementation date now Apr 1984 MDRISI. V Boston Edison Co 82712709 VASSALLO.D B Operating Reactors Branch 2 2pp 16408 233 249 Fiche 50-293,82/12/09, 82612140139
- 8212170305 Application to amend License DPR-35 requesting relief from lech Spec re fire barrier penetration seals MONARD. J E Oston Edison Co 82/12/15 VASSALLO, D 3 Operating Reactors Branch 2 App 16456 [3] 24X Fiche 50-293.82/12/15, 8212170305
- --B212170310 Proposed Tech Spec changes to Section 3 12 F, revising limiting condition of operation for specific fire barrier, currently requiring establishing continuous fire patrol when penetration fire barrier not functional # Boston Edison Co 82/12/15 2pp 16456 135 24% Fiche 50-293.82/12/15.8212170305
- BP12270474 Comments on NURES-0737. Item I C 6 "Verify Correct Performance of Operating Activities" Commitment to modify station policy & procedures to reflect criteria requested within 45 days of itr date VASSALLO,D B Operating Reactors Branch 2 82/12/20 MORISI.A V Hoston Edison Co 3pp 16566 361 24X Fiche 50-273.82/12/20.
- O Inspection reports: IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thirk-Wall, Large-Diameter; Stainfess Steel.Recirculation Sys Piping at BMR Plants "Syc list enci DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.02/10/28.8208190240
- 8:08190245 IE Info Notice 82-42, "Detects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Ewel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 80-000,82/11/05,8208190245
- 62:08190351 IE Info Notice 82-44. "Clarification of Emergency Plan Frencise Requirements " Svc list encl JORDAN-E L Division or Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 ,'4/ Fiche 50-000:82/11/18.8208190251
- 8212030195 Forwards IE Insp Rept 50-293/82-28 on 821012-14 No noncompliance noted MARTIN-T T Division of Engineering & Technical Programs 82/11/19 HARRINGTON-N D Boston Edison Co 2pp 16304 070 24X Fiche 50-293-82/11/19-8212030195
- --8212030200 IE Insp Rept 50-293/82-28 on 821012-14 No noncompliance noted Major areas inspected scram discharge vol 4 associated piping design.per IE Bulletins 80-17 4 79-14 & NUREO-0803 EAPEN.P K. BETTENHAUSEN.L Division of Engineering & Technical Programs 82/11/17 3pp 16304 092 24X Fiche 50-293.82/11/19, 8212030195
- 8208190256 IE Info Notice 82-46. "Defective & Dosolete Combination Padlocks " Svc list enc! | IEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 35App 16387 028 24/ Fiche 50-000,82/11/30,8208190257

- 8.08190259 IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG:R C Director's Orfice: Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113p 16411 317 24x Fiche 50-000.82/12/03.8208190259
- 8/08/90261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets' Svc list enci JORDANIE L pivision of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24 [iche 50-000 82/12/03, 8208/9026]
- G,1221045B Forwards "Second 10-Yr Insp Program." w/specific request for code relief.per 10CFR50 55a(g) & ASME Section XI 4/13 oversize drawings Aperture cards are available in PDR One drawing illegible NORISI.A V Boston Edison Co 82/12/03 VASSALLO.D B Operating Reactors Branch 2 2pp 16486 007 24X Fiche 50-293.82/12/03. (2)2210458
 - 0212210462 "Second 10-Yr Insp Program," Dec 1982 * Beston Edison Co 82/12/31 38pp 16486 007 24X Fiche 50-293.02/12/03.0212210498
- GM:2150219 Ack receipt of 820915 & 1022 litrs informing NRC of steps taken to correct violations noted in IE Insp Rept to-2973/82-19 GTARGETECKI.R Division of Project & Resident Programs 82/12/10 HARPINGTON, M. D. Boston Edison Co. 2pp 16430 252 24X Fiche 50-293.82/12/10.82(2150219
- --G212150224 Responds to NRC 820816 ltr re violations noted in IE Insp Regt 50-293/82-19 Corrective actions watch engineer unblocked fire door & returned door to closed position & door mechanism repaired HARRINGTON N D Boston Edison Co 82/09/15 STARDSTECKI, R Division or Project & Resident Programs 7gp 16430 254 24X Fiche 50-293,82/12/10.8212150219
- 6212150233 Submits supplemental response to NRC 920816 ltm reviolation noted in IE [nsp Repts 50-293/82-04 the State of th
- 3.12210025 Forwards summary of 82)117 mgt meeting at site re development 'implementation of util performance amprovement program STAROSTECKI.R Division of Project & Resident Programs 82/12/15 HARRINGTONN D Boston Edison Co Sop 16440 207 24X Highe 50-273.62/12/15.8212210025
- 8:'08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Cas Monitoring " Svc list encl BELOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000, 92/12/16, 8208190267
- 6,12220402 Forwards NUREG-0903 containing results of initial round of intervieus re establishment of drug & alcohol abuse & rehabilitation program conducted per IE Info Notice 82-05 Util will be contacted to arrange intervieus W/o NUREG STAROSTEGLIR Division of Project & Resident Programs 82/12/16 HARRINGTON N D Boston Edison Co 3pp 16503 216 24X Fiche 50-293, 82/12/16,8212220402
- 8.708190268 IE Info Notice 82 50. "Mod of Solid State AC Undervoltage Keleys Type ITE-27" Svc list encl JORDAN EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc. 108pp. 16628-293 24X Tiche 50-000-82/12/20,8208190268
- DP12290422 Ack receipt of B21214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-24 STARGSTECKI.R Division or Project & Resident Programs B2/12/23 HARRINGTON N D Boston Edison Co 2pp 16585 184 24X Fiche 50-293-82/12/23-8212270422
- --8212290433 Responds to NRC 821112 ltr re violations noted in IE Insp Rept 50-273/82-24 Corrective actions missing sign replaced & new sign designed/Procedures 7 9 2 5 2 1 17 revised on 821117 to contain proper language usage re discharges HARRINGTON, W D Boston Edison Co 82/12/14 STAROSTECKI, R W Division of Project & Resident Programs 3pp 14585 184 24X Fiche 50-273,82/12/23.8212290422

- S Reportable occurrences, LERs & related correspondence
- 8212060198 Forwards LER 82~050/03L-0 MATHIS.C J Boston Edison Co 82/11/26 HAYNES.R C Region 1. Office of Director 1p 16313 051 24X Fiche 50~273,82/11/26, R212060198
- --8212060200 LER 82-050/03L-0 on 821026, four fire doors did not meet NFPA & UL code criteria Caused by personnel improperly affixing warning sign holders Repairs made, personnel cautioned & procedure revised WHITNEY, 0 G Boston Edison Co 82/11/26 Region 1. Office of Director 2pp 16313 052 24X Fiche 50-293, 82/11/26, 8212060198
- 8212060210 Forwards LER 82-052/03L-0 MATHIS,C J Roston Edison Co 82/11/26 HAYNES,R C Region 1: Uffice of Director Ip 16313 182 24X Fiche 50-293,82/11/26,
- --B212060220 LER 92-052/03L-0 on 821028; recirculation pump A MO set inadvertently tripped while troubleshooting ground indication for 125-volt dc circuit Caused by inadequate info avaitable to troubleshooters info upgraded HHITNEY, O G Boston Edison Co 82/11/26 Region 1, Office of Director ip 16313 183 24x Fiche 50-293, 82/11/26, 8212060210
- GP12210067 Forwards LER 02-055/03L-0 MATHIB.C J Boston Edison Co 82/12/10 HAYNES.R C Region F. Uffice of Director 1p 16492 272 24X Fiche 50-293.82/12/10, 0212210067
- -- -8212210071 LER 82-055/03L-0 on B21115, during surveillance test for RCIC sys, sys isolated due to high steam line flow Caused by failure of resistor PN 8270-281 in power supply to ECM of turbine control Resistor replaced WHITNEY, 0 q Boston Edison Co 82/12/10 Region i, Office of Director ip 16492 273 24X Fiche 50-293, B2/12/10, B212210067
- 9212210148 Forwards LER 82-053/03L-0 MATHIS, C J Boston Edison Co 82/12/10 HAYNES, R C Region 1, Office of Director 1p 16485 149 24% Fiche 50-293,82/12/10, 8212210148
- 82(2210153 LER 82-053/03L-0 on 821110, ground fault alarm observed on 125-volt dc battery circuit & traced to limit switch circuitry for MDV2301-3 Caused by valve packing steam leakage Packing tightened for short-term fit WHITNEY, O 0 Boston Edison Co 82/12/10 Region 1, Office of Director ip 14485 150 24X Fiche 50-293.82/12/10.8212210148
- 8712210249 Forwards LER 82-054/03L-0 MATHIS.C J Boston Edison Co 82/12/10 HAYNES.R C Region 1. Office of Director Ip 16483 314 24X Fiche 50-293, 82/12/10, 8212210249
- --82(2210264 LER 82-054/03L-0 on 821111, RPS relay 5AK-30 did not respond when D MSIV inboard valve tested for 10% closure Caused by Failed limit switch fuse removed Repairs to limit switch added to next drywell entry procedures
 WHITNEY, 0 G Boston Edison (0 82/12/10 Region), Office of Director ip 14483 315 24% Fiche 50-293,82/12/10,82/22/10249
- DOCKEF 50-295 ZION NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- BP12060232 Forwards IE Gafety Evaluation Repts 50-295/B2-23 & 50-304/B2-20 of emergency preparedness % SER HIND JA Division of Emergency Preparedness & Operational Support B2711/19 REED, C Commonwealth Edison Co 2pp 16312 201 24X Fiche 50-295/B2/11/19, B212060232
- --8212060238 [E Safety Evaluation Repts 50-275/82-23 & 50-304/82-20 of emergency preparedness plan Emergency plan acceptable PHILLIPS, M P . AXELSON, W L . PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/11/18 lp 16312 203 24% Fiche 50-275,82/11/19,8212060232
- --8212060255 SER of emergency preparedness plan Plan acceptable * Region 3. Office of Director 82/11/30 27pp 16312 204 24x Fiche 50-295,82/11/19,8212060232
- 8a·12130363 Approves enci route to transport spent reactor fuel Route meets regulatory requirements of 10CFR73 37 SMERR.T 5 Material Transfer Safeguards Licensing Branch 82/11/23 DANESE.F L Nuclear Assurance Corp 8pp 16415 013 24X Fiche 50-295, 82/11/23, 8212130363

- GP32070065 Forwards revised exemption requests documenting info provided at B21104 & OS meetings re post-fire shutdown capability capability LENTINE.F G Commonwealth Edison Co 82/11/29 DENTON,H R Of Of Nuclear Reactor Regulation. Director 88pp 16326 010 24X Fiche 50-295, 82/11/29, 8212070065 Office
- \$212090383 Forwards info re emergency operations facilities per \$2122 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee DELGEORGE, LO Commonwealth Edison Co 82/12/03 EISENHUT, D C Division of Cicensing 2pp 16365 051 24X Fiche 50-000,82/12/03,8212090389
- 8212130149 Releases public version of revision to emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/12/03 Docum Management Branch ip 16410 295 24X Fiche 50-295.82/12/03. f2/2130149 Document
- --B212130153 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generation Station Emergency Plan Conditions " Procedure change request form enci PLIML, G Commonwealth Edison Co 82/11/19 DENTON, H R NRC Nr. Detailed Affiliation Given 3pp 16410 297 24X
- ---8212130156 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generating Station Procedure EPIP 330-1. "Classification of Generating Station Emergency Plan Conditions "

 ** Commonwealth Edison Co 82/11/16 16pp 16410 300 24% Fiche \$0~295.82/12/03,8212130149
- B212430017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Offste Monitoring Locations (Maps)" FELTON.JM Division of Rules and Records 82/12/07 Documer Namagement Branch 1p 16417 062 24X Fiche 50-000,82/12/07. 8212130012
- --4212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl PAJOHSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, 82/12/07, 82/2130017
- --B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 PAJUMSKI, J E Commonwealth Edison Co 82/11/29 4pp 16417 (465 24 (Fiche 50-000, 82/12/07, 8212130017
- GY12140243 Advises of distribution of revisions to "Generating Station Fmergency Plan" Braidwood annex not prepared TRAMM.T.R. Commonwealth Edison Co. 62/12/07 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000.62/12/07.8212140243
- GP12220175 Releases public version of revised generating station remergency plan implementing procedures
 FELTON.JM Division of Rules and Records 82/12/10 Document
 Nanagement Branch 1p 16527 029 24X Fiche 50-000,82/12/10,
 82/122/20175
- --8212220190 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand pulling off meteorological data & ED-20 re emergency forecast request PAJONSKI, J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16529 030 24% Fiche 50-000, 82/12/10.8212220175
- --8212220202 Public version of revised generating station emergency plan implementing procedures including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI, L A Commonwealth Edison Co 82/10/13 18529 031 24X Fiche 50-000, 82/12/10,8212220175
- 8P12R10454 Forwards add1 info documenting discussions at 821104 & 05 meeting w/NRC & BNL re remaining open items from technical evaluation rept. "Post-Fire Shutdown Capability"

 LENTINE: FO Commonwealth Edison Co 82/12/15 DENTON.H R Offi of Nuclear Reactor Regulation, Director 39pp 16489 285 24X Fiche 50-295, 82/12/15.8212210454 Office

- 8212220304 Discusses layout of communications equipment required in control room, onsite technical support ctr 4 near-site emergency operations facility

 KEPPLER.J G Region 3, Office of Director 82/12/16

 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16.
- 8212290083 Releases public version of corrected page to emergency plan implementing procedure FELTON-J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16606 343 24x Fiche 50-295, 82/12/20. 8212290083
- --8212270086 Forwards public version of corrected Page 4 to Emergency
 Plan Implementing Procedure EPIP 410-1 Receipt form encl
 PLIMIL, G Commonwealth Edison Co 82/11/30 DENTON, H R NRC No
 Detailed Affiliation Given 2pp 16606 344 24X
 Fiche 50-295, 82/12/20, 8212290083
- --B2122900B9 Public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1 8 Commonwealth Edison Co 82/11/30 1p 16606 346 24X Fiche 50-295, 82/12/20, 8212290083
- PIREYUUYU Releases public version of revision to emorgoncy plan implementing procedure FELTON, J.M. Division of Rules and Records 82/12/20. Docum Management Branch 1p. 16606-334 24X Fiche 50-295,82/12/20, 8212290098 8/12290098 Releases public version of revision to emergency plan
- --B212290105 Forwards public version of Revision 6 to Emergency Plan Implementing Procedure EPTP 110-1, "Station Director" Receipt form & procedure change request form enci PLIML. G Commonwealth Edison Co 82/11/24 DENTON, H R 1880 No Detailed Affiliation Given 2pp 16406-335 24X Fiche 50-295, 82/12/20, 8212290098
- --B212290110 Public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director" Revised index
- B212290509 Releases public version of revised emergency plan implementing procedure FELTON, J II Division of Rules and Records 82/12/20 Docum Management Branch 1p 16593 349 24X Fiche 50-295,82/12/20,8212290509 Document
- --8212290511 Forwards public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1. "Emergency Phone List " Procedure change request encl PLIML.0 Commonwealth Edison Co 82/11/24 BENTON, H R NR(No Detailed Affiliation Given 2pp 16593 350 24X Fiche 50-295, 82/12/20.8212290509
- --8212290513 Public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Plane List"
 + Commonwealth Edison Co 82/11/22 6pp 16593 352 24%
 Fiche 50-295, 82/12/20.8212290509
- 82)2300167 Releases public version of revised generating station pmergency plan telephone directory FELTON, J M Division of Rules and Records 82/12/20 Document Branch ip 16612 215 24X Fiche 50-000, 82/12/20 Document
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory MODRE,R D. Commonwealth Edison Co. 82/12/02 DENTON,H R. D. Of Nuclear Reactor Regulation, Director ip 16612-216 24X Fiche 50-000,82/12/20.8212300167
- -8212300199 Public version of revised generating station emergency plan telephone directory GALLE.D.P. Commonwealth Edison Co. 82/11/05 60pp. 16612 21/ 24/ Fiche 50-000, 82/12/20, 8212/300167
- BP12290419 Forwards proposed agenda for B30104-05 site visit by security review committee re safeguards requirements KEPPLER.J O Region 3, Office of Director 82/12/27 REED.C Commonwealth Edison Co 2pp 16587 099 24X Fiche 50-295,82/12/27,8212270415
- H General correspondence
- 8P12280176 Notifies of change in mailing address for NRC licensing matl
 MRIGHT.ON Illinois, State of, Dept Nuc Safety (formerly Drpt
 Public Health) 82/12/20 EISENHUT,D 0 Division of Licensing
 1p 16556 135 24% Fiche 50~000,82/12/20,8212280176

- P Operating license stage documents & correspondence
- Gri20704() FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facilities

 OUIGO.C Pollution & Environmental Problems, Inc. 82/10/18

 Division of Rules and Records ip 16356-001 24X

 Fiche 50-279, 82/10/18-92/20704()
- B212050471 OPERATOR ACTION EVENT THEES FOR THE ZION 1 PRESSURIZED WATER MEACTOR

 BROWN R G , VOMHERRMANN, J , QUILLLAM, J F E08G, Inc NUREO/CR-2888 B2/10/31 Office of Nuclear Regulatory Research, Director 204pp 16348 020 24% Fiche 50-275, 82/10/31, 8212060471
- GP12070414 Responds to FDIA request for all records on embrittlement, thermal shock.corrosion & cracking of reactor pressure vessel at facility Records available at PDR FELTON.J K Division of Rules and Records 82/11/05 GUIGG.C Pollution & Environmental Problems. Inc. 4pp 16356 002 247 [tche 50-279.82/11/05.8212070414
- 67:2060086 Clarifies 820712 ltr re seismit design of auxiliary feeduater sys branch piping Piping criteria utilized for all 1E 6011etin 79-14 work as documented in 54th Procedure 2PP-1 iENTINE.F @ Commonwealth Edison Co 62/11/29 DEMITON, H R Office Procedure 2PP-1 iENTINE.F Reactor Regulation, Director 1p 16316 120 24X Fiche 50-295,82/11/29,8212060086
- 6P12050219 Requests approval to delay implementation of due dates to accompodate current schedule requirements for Items II 8 2. "Plant Shielding," II 9 3. "Post-Accident Sampling." & II F 1. "Accident Monitoring Instrumentation" LENTIME.F 0. Commonwealth Edison Co. 82/11/29 EISENHUT.D 0 Division of Licensing 2pp. 16013-190. 24X Fiche 50-295.82/11/29, 0212060219
- --B212060430 Notice of Pollution & Environ Problems, Inc B21011 request for action relicensed use of high burnup nuclear fuel & ability of facility reactor vessels to withstand erbrittlement

 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 62/11/30 | 1p | 16343 309 | 24% Fiche 50-295, 62/11/30, 8212040422
- 8/12070472 Forwards Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends tevise Tech Specs to allow release of radinactive gas decay tank contents
 #ISO(NTON.D Operating Reactors Branch | 82/11/30 DELGEDROE, LO Commonwealth Edison Co. 3pp. 16351-342 24% Fiche 50-295, 62/11/30, 8212070472
- --B212070478 Amends 78 % off to Licenses DPR-39 % DPR-48, respectively, revising Tech Specs to allow release of radioactive gas decay tank contents VARGA. S A Operating Reactors Branch 1 82/11/30 8pp 16351 345 24X Fiche 50-295, 82/11/30, 8212070472
- U212070482 Notice of issuance & availability of Amends 78 & 68 to Licenses DFR-37 & DPR-48, respectively VAROA: S.A. Operating Reactors Branch i 82/11/30 2pp 16351 353 24X Fiche 50-275,82/11/30,8212070472
- BP12130231 Application to amend Licenses DPR-37 & DPR-48, changing Section 3 9 2 of Tech Specs to clarify operability requirements for containment penetration & weld channel pressurfiation sys | ENTINE.F 0 Commonwealth Edison Co 02/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16397 001 24X [1che 50-275, 82/12/03, 8212130231
- --G212130235 Proposed changes to Spection 3 7 2 of Tech Specs, clarafying operability requirements for containment penetration & weld channel pressurization sys * Commonwealth Edison Co 82/12/03 2pp 16377 003 24X Fiche 30-295,82/12/03,8212130231

- B:12090006 Confirms emergency authorization to amend Licenses DPR-39 & DPR-48 on B21203 Amend revises penetration pressurization tys
 LAINAS, G.C. Assistant Director for Operating Reactors 82/12/06
 DELGEGROE, L.D. Commonwealth Edison Co. 2pp. 16379-357 24X
 [iche 90-295, 82/12/06, 82/2090006
- B7:12130035 Informs of add1 delay in implementation of offsite dose assessment portion of A-model Required radiation monitoring sys uill be installed by 830215 per NUREG-0737, lems If F1 i & If F1 2 tenting. F0 Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16370 174 24X Fiche 50-298,82/12/07,8212130035
- 8208190263 Generic Etr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of Itr Svc list encl EISE/MHUT. D © Division of Licensing 82/12/09 Consolidated Edison Co of New York Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09. 8208190263
- GP12140103 Generic Ltr G2-28 to all licensees of operating Westinghouse & C-E PNRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISE(4FUT. D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16670 035 24X Fiche 50-000, 82/12/10, G212140103
- 821215014; Forwards proprietary BER & technical evaluation rept,
 "Review of Licensee Resolution of Outstanding Issues From
 NRC Equipment Environ Qualification BERs (F-11.D-60) "
 Justification for continued operation due in 30 days
 VAROA.S A Operating Reactors Branch 1 82/12/14 DELOEUROE.L O
 Commanuealth Edison Co 2pp 16427 345 24X Fiche 50-295,82/12/14,
 8212150141
- B212220212 Forwards Revision 22 to CE-1-A, "GA Program for Nuclear Cenerating Stations" SWARTZ, E D Commonwealth Edison Co 82/12/14 HAASS, W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000,82/12/14, 821222021
- --0212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 02/12/14,8212220212
- Gf:12220431 Comments on NRC alternative Tech Specs re auxiliary feedwater sys, prepared in response to util 791231 & 800312 submittals Proposed Tech Specs acceptable, w/exception of minor editorial changes noted in encl
 LENTINE, F 0 Commonuealth Edison Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 16503 311 24X Fiche 50-275, 82/12/15, 8212220431
- G212220517 Forwards approved spent nuclear fuel route as requested in B20914 ltr BERR.T 9 Material Transfer Safeguards Licensing Branch 82/12/16 DAMESE.F L Nuclear Assurance Corp 2pp 16823 041 24X Fiche 50~295.82/12/16.8212220517
- --B212220520 "Spent Nuclear Fuel Route, BMI, West Jefferson, OH to Zion Nuclear Power Station, Zion, IL " SHERR, T S Material Transfer Safeguards Licensing Branch 82/11/23 10pp 16523 043 24X Fiche 50-295, 82/12/16, 8212220517
- 8212210369 Requests NRC concurrence or comments on revised schedule for implementation of fuel mgt program topical rept LENTINE;F O Commonwealth Edison Co 82/12/17 THOMAS,C O Standardization & Special Projects Branch 3pp 16494 275 24x Fiche 50-275,82/12/17.8212210369
- BP12270453 Forwards Amends 79 & 69 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for penetration pressurization sys to define operating conditions HIO0INTON, D L Operating Reactors Branch 1 82/12/20 BELGEORGE, L O Commonwealth Edison Go 2pp 16606 060 24% Fiche 50-295,82/12/20,8212290453
- --8212270456 Amends 79 & 69 to Licenses DFR-39 & DFR-48, respectively, revising Tech Specs for penetration pressurization sys to define conditions of operation, applicable modes & actions taken for inoperable sys VAROA, 5 A Operating Reactors Branch 1 02/12/20 7pp 16604 062 24X Fiche 30-293, 82/12/20,8212290453
- --8212270461 Safety evaluation supporting Amends 77 & 69 to Licenses PPR-39 & DPR-48, respectively * Office of Nuclear Reactor Regulation, Director 16606 069 24X Fiche 50-275,82/12/20,8212290453

- --8212270464 Notice of issuance & availability of Amends 79 & 69 to Licenses DPR-39 & DPR-4B, respectively VAROA, B A Operating Reactors Branch 1 82/12/20 2pp 18606 072 24X Fiche 50-295, 82/12/20, 8212290453
- B:12280212 Forwards updated schedule for engoing environ qualification testing programs.per 810528 commitment SMARTI, E D Commonwealth Edison Co 82/12/22 EISENHUT, D 9 Division of Licensing 18pp 16556 161 24X Fiche 50-000,82/12/22, B212280212
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1, "Btress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl DEYDUND, R C Director's Office, Office of Inspection and Lnforcement 82/10/28 Cansolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- B208190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model
 B01 & Model B02 Thermoluminescent Dosimeters " Svc list
 pnc!
 COBB.L. I Division of Fuel Facilities, Materials & Safeguards
 B22/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24% Fiche S0-000.82/11/05,8208190245
- 8212080282 Forwards IE Insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0903 & 20-22 No noncompliance noted MILLER, J R Division of Engineering & Technical Programs 82/11/12 REED, C Commonwealth Edison Co. 2pp 16354 186 24X Fiche 50-295, 82/11/12,8212080282
- --8212080296 IE insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0703 & 20-22 No noncompliance noted Major areas inspected compliance w/NUREO-0737. Item II F I 3.allegations forwarded by IL Dept of Nuclear Safety & radiation protection program MILLER, D E . PAUL.R A . OREOER.L R Division of Engineering & Technical Programs 82/11/10 15pp 16354 188 24X Fichs 50-295,82/11/12.8212080282
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Frencise Requirements" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- G212060232 Forwards IE Bafety Evaluation Repts 90-295/82-23 & 50-304/82-20 of emergency preparedness & BER MEND. JA Division of Emergency Preparedness & Operational Support B2/11/19 REED. C Commonwealth Edison Co 2pp 16312 201 247 Fiche 50-295, 82/11/19, 8212060232
- ---8212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of emergency preparedness plan Emergency plan acceptable PHILLIPS.M P . AXELBON.W L . PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/11/18 ip 16312 203 24% Fiche 50-295,82/11/19,8212060232
- --8212060255 SER of emergency preparedness plan Plan acceptable • Region 3, Office of Director 82/11/30 27pp 16312 204 24X Fiche 50-295, 82/11/19, 8212060232
- BYOB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUNG,R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 1641
- 8212060050 Summarizes 821103 meeting w/US Atty & law enforcement agencies in Chicago. IL re IE Investigation Repts 50-295/81-32 & 50-304/81-30 & status of ongoing investigation KEPPLER. J O Region 3, Office of Director 82/11/27 JONES. G C Illinois, State of 2pp 16314 075 24X Fiche 50-295, 82/11/29, 8212080050
- B; OB190257 IE Info Notice B2-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Math" Svc list encl C088.L I Division of Fuel Facilities, Materials & Bafeguards B2/11/30 Consolidated Edison Co of New York, Inc 354pp 14387 028 244 Fiche 50-000.82/11/30,8208190257
- BPOBI90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bvc list enci BEYOUNO, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000, 82/12/03, 8208190259

- 6:08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24y [iche 50-000,82/12/03,8208190261]
- 8/12170109 Forwards IE Insp Repts S0-295/82-20 & 50-304/82-18 on 821025-29 & notice of violation NORELIUS: C E Division of Engineering & Technical Programs 82/12/03 REED: C Commonwealth Edison Co 2pp 16452 336 24X Fiche 50-295 82/12/03 8212170109
- --8212170114 Notice of violation from insp on 821025-29 NORELIUS.C E Division of Engineering & Technical Programs 82/12/03 2pp 14452 338 24X Fiche 50-275.82/12/03.8212170109
- --8212170121 IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-29 Noncompliance noted form not used to track operator progress & current status of operator training Out-of-tolerance parameters & valve stroke times not recorded FARRELLIR E , HASSE,R A , PESCHEL, J M Division of Engineering & Technical Programs 82/12/02 9pp 16452 340 24% Fiche 50-295,82/12/03,8212170109
- 63:12130183 Forwards add1 info re tE Bulletin 80-11, "Masonry Walls," in response to NRC 82:1022 Itr Eighteen walls qualified using horizontal reinforcement LENTINE.F 0 Commonwealth Edison Co 82/12/08 EISENHUT.D 0 Division of Licensing 18pp 16376 099 24X Fiche 50-295.82/12/08. R212120183
- --8212280062 IE Insp Repts 50-245/82-27 & 50-304/82-24 on 621115-19 No honcompliance noted Major areas inspected radwaste sys, including effluent release rates, records & reaks, procedures for controlling releases & containment air cleaning sys MILLER, DE , GRANT, N B , GREGER, L R Division of Engineering & Technical Programs 82/12/10 7pp 16564 281 24X Fiche 50-295,82/12/10,8212280058
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 12/2p 16628 191 24X Fiche 50-000.82/12/16.8208190267
- GP12290389 Forwards IE Insp Repts 50-295/82-29 & 50-304/82-26 on U21115-16 No noncompliance noted LITLE: W S Division of Engineering & Yechnical Programs 82/12/17 REED. C Commonwealth Edison Co 2pp 16586 296 24X Fiche 50-295, 82/12/17, 8212290389
- --8212290400 IE Insp Repts 50-295/82-29 & 50-304/82-26 on 821115-16 No noncompliance noted Major areas inspected actions in response to IE Builetin 79-14.work procedure review & observation of work
 YIN.1 T. DANIELSON.D H. Division of Engineering & Technical Programs 82/12/10 6pp 14584 298 24X Fiche 50-295.82/12/17, 8212290389
- 8008190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Helays Type ITE-2) " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- GP12140055 Forwards monthly operating repts for Nov 1982 GRAEGSER: K L Commonwealth Edison Co 82/12/09 Director's Office. Office of Inspection and Enforcement 1p 16408 290 24X Fiche 50-295.82/12/09.8212140055
- --8212140061 Monthly operating repts for Nov 1782 AUSTIN.0 Commonwealth Edison Co 82/12/07 lipp 16408 291 24% Fiche 50-295,82/12/09,8212140055
- 8 Reportable occurrences, LERs & related correspondence
- 8212020234 Forwards LER 82-039/03L-0 GRAESBER: K L Commonweal th Edison Co 82/11/24 KEPPLER: J G Region 3. Office of Director 1p 16274 104 24X Fiche 50-295: 82/11/24: 8212020234

DOCKETED ITEMS

- --8212020237 LER 62-037/03L-0 on 821027. Class 1 pipe tunnel indine monitor RT-PR078 failed low b would not respond to source check Caused by high voltage drifting to point below detector knee JAKUBAITIS. T.C. Commonwealth Edison Co. 82/11/24 Region 3. Office of Director ip 16274 105 244 Fiche 50-295. 82/11/24. 8212020234
- --D212020265 LER 82-040/99x-0 on 821025, QA fire pump taken out of svc on 821018 found still inoperable Cause not stated Parts on order Dissel driven fire pump tested once per uk Design & procedures adequate Pump returned to svc by end of yr NYXIEL.A Commonwealth Edison Co 82/11/24 Region 3, Office of Director 1p 16291 006 24X Fiche 50-295,82/11/24,8212020272
- 82/12/40321 Forwards LER 82-041/03L-0 GRAESSER, K. Commonwealth Edison Co. 82/12/08 KEPPLER, J G Region 3, Office of Director 1p 16401 282 24% I iche 50-295, 82/12/08, 8212140321
 - 6212140327 LER 82-041/03L-0 since May 1975, plant operated w/low stramline pressure compensation lead/lag setting different than current Mestinghouse large steam break analysis Caused by inadequate procautions, limitations & setpoints manual CANTMELL-P F Commonwealth Edison Co 82/12/08 Region 3, Office of Director ip 16401 283 24X Fiche 50-295,82/12/08,6212140321
- GP12170307 Forwards LER 82-042/03L-0 GRAESSER.K & Commonwealth Edison Co 82/12/09 KEPPLER.J G Hegion 3. Office of Director 1p 16456 137 24X fiche 50-295, 82/12/07, 8212170307
- 8212170312 LER 82-042/03L-0 on 821116, RHR miniflow control valve switch IFIC-610A failed & miniflow valve would not close at 1,000 gpm per design Caused by Barton Model 288 micro-switch nut-of-tolerance Mod initiated to replace switch BIMODELI.8 L. Commonwealth Edison Co. 82/12/09 Region 3, Office of Director Ip 16456 138 24X Fiche 50-275,82/12/09,8212170307
- 0212280432 Forwards LER 82-045/03L-0 GRAESSER,K L Commonwealth Edison Co 82/12/17 KEPPLER,J G Region 3, Office of Director 1p 16556 066 248 (iche 50-295, 82/12/17, 8212280432
- ~-8212280442 LER 82-045/03t-0 on 821208, control room makeup charcoal filter sys chemical analysis showed upstream & downstream filter efficiencies below 99% Caused by nurmal deterioration due to airborn contaminants Filters replaced STAMMER, F. Commonwealth Edison Co. 82/12/17 Region 3, Office of Director 1p 16556 067 24X Fiche 50-295.82/12/17.
- 5/12280450 Forwards LER 82-043/03L-0 GRAEGSER: K & Commonwealth Edison Co 82/12/17 KEPPLER: J & Region 3: Office of Director 1p 16956 011 24X Fiche 50-295. 82/12/17:0212280450
- --8212280451 LER 82-043/03L-O on 82111; heater failure alarm discovered on boric acid tank suction line to boric acid transfer pump dine of two heat trace circuits failed Caused by valve on suction line leaking borated water Valve repaired KAPLAN, 8 A Commonwealth Edison Co. 82/12/17 Region 3, Office of Director in 16556 012 24X Fiche 50-295, 82/12/17, 821280450
- 6:12280244 Forwards LER 82-044/03L-0 GRAEGSER,K C. Commonwealth Edison Co. 82/12/21 KEPPLER,J G Region 3, Office of Director 1p 16561 271 24X fiche 50-295, 62/12/21, 8212280244
- --8212280249 LER 82-044/03L-O on 821129, penetration pressurization (PP) air compressor O failed to unload on demand Caused by corroded inlet yaive unloaders All suction/discharge valves & associa+ed internal components rebuilt SHIM.K Commonwealth Edison Co 82/12/21 Region 3, Office of Director 2pp 16561 272 24X Fiche 50-295, 82/12/21, 8212280244

- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- BP12030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-30. 50-259/62-30. 50-259/62-30. 50-2016-30 kg-20-2016-30 kg-2016-30 kg-2016-3
- --BR12030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Ensp Repts 50-259/82-30.50-260/82-30 & 50-296/82-30 Corrective actions withheld (ref IOCFR73 21) MILLS.L.M Tennessee Valley Authority 82/11/19 O'REILLY.JP Region 2. Office of Director ip 16307 068 24X Fiche 50-259.82/11/30.8212030212
- --8212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 30-296/82-30 on 820920-24 & notice of violation Rept details & notice of violation withheld (ref lQCFR73 21) LEMIS.R C Division of Project & Resident Programs 82/10/19 PARRIS.H O Tennessee Valley Authority 2pp 16307 069 24% Fiche 50-259, 82/11/30, 8212030212
- --8212030232 IE Insp Repts 50-259/82-30.50-260/82-30 & 50-296/82-30 on 820720-24 Noncompliance noted in areas of locks, keys & combinations, physical barriers -- protected areas, lighting & access control Details withheld (ref 10CFR73 21)

 HALL. B L Division of Engineering & Technical Programs 82/10/14
 2pp 16307 071 24% Fiche 50-259.82/11/30.8212030212
- BP12080100 Releases public version of revised radiological emorquncy plan implementing procedures
 FELTON J M Division of Rules and Records B2/12/02 Document Management Branch 1p 16367 276 24X Fiche 50-259, 82/12/02, 8212080100
- --8212080108 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic & IP-4 re site area emergency Receipt form encl HILLS.L M Tennessee Valley Authority 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16367 277 244 Fiche 50-259, 82/12/02, 8212080100
- --B2120B0112 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logics IP-4 re site area emergency & IP-31 re operations support ctr 4 Tennessee Valley Authority 82/11/01 76pp 16367 280 24x Fiche 50-259, 82/12/02, 821208100
- 8712090080 Ack receipt of 821124 1tr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts
 90-259/82-36, 50-260/82-36 & 50-296/82-36
 LEWIS, R C Pivision of Project & Resident Programs 82/12/04
 PARRIS, H O Tennessee Valley Authority 2pp 16357 236 24X
 Fiche 50-259, 82/12/06, 8212090080
- ~~8212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-36.50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 100FR73 21) MILLS.L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2. Office of Director ip 16357 238 24X Fiche 50-259.82/12/06.8212090080
- --B212070108 Forwards IE Sefeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-276/82-36 on 820708-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) O'REILLY, J.P. Region 2, Office of Director 82/10/22 PARRIS, H 0 Tennessee Valley Authority 2pp 16357 239 24X Fiche 50-259, 82/12/06, 8212070080
- --8212070124 IE Bafeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-276/82-36 on 820708-09 Noncompliance noted in area of access controls Details withheld (ref 10CFR3 21)
 TILLMAN, A Division of Engineering & Technical Programs
 82/10/20 10 16357 241 24X Fiche 50-259, 82/12/06, 8212090080
- 8212170104 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16478 104 24X Fiche 50-259, 82/12/10, 8212170104.

- --8212170108 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-6, -7 & -23 re emergency testephone listings
 MILLS.L M Tennessee Valley Authority 82/12/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16478 IO5 24X Fiche 30-259,82/12/10.8212170104
- --8212170112 Public version of revised emergency plan implementing procedures, including Procedures IP-6,-7 & -23 re emergency telephane listings
 * Tennessee Valley Authority 82/11/30 7pp 16478 107 24X Fiche 50-259,82/12/10,8212170104
- 8212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will completed initial training Training per IOCFR50 54(p) will be completed by 830801 MILLS, L M Tennessee Valley Authority 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16462 020 24X Fiche 50-000, 82/12/13, 8212170229

G Adjudicatory correspondence

- BP122B0028 Forwards nonproprietary "RWR-1 Radwaste Vol Reduction Sys" & NRC topical rept evaluation Matl should aid in settlement negotiations W/o encl RAMSON.R J Hearing Branch 4 82/12/23 PYLE.R B Pyle. R B ip 16565.143 24X Fiche 50-259,82/12/23.82122B0028

H General correspondence

- BP12140478 Forwards missing Pages 65 & 66 of EIA re low level radwarts storage for Browns Ferry Nuclear Plant & SER & EIA on low level radwaste storage facility at Sequoyah Nuclear Plant W/o encl LOYSEN,P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 DREV,L A Affiliation Unknown ip 16431 321 24X Fiche 50-000, 92/11/23, 8212140478
- --8212140486 Requests missing pages to EIA on low level radwaste storage at Orowns Ferry Nuclear Plant & copies of SER & EIA for Sequoyah Nuclear Plant oclear Plant Affiliation Unknown 82/11/08 Office of Nuclear Material Safety & Safaguards Director ip 16431 322 24X Fiche 50-000,82/11/23.8212140478

J Insurance & indemnity information

- 8712020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies DUCK.JR Marsh & McLennan,Inc. M & Muclear Consultants,Inc. Div 82/11/18 HAINES,H L Amprican Nuclear Insurers ip 16288-356 82/11/18 HAINES, H.L. American Nuclear Insurers 1p P4X Fiche 50-000, 82/11/18, 8212020269
- 8212280241 Forwards Endorsement 43 to NELIA Policy NF-198 & elmacousci romanos indorement 63 to Macile Policy Nr-198 a Endorsement 53 to Macile Policy Nr-66 DUCK.J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 82/12/22 SALTZMAN.J Assistant Director for State & Licensee Relations Spp 14541 304 24X Fiche 50-259, 82/12/22, 8212280261
- 8212290246 Forwards Certificates of Insurance N-3B.N-39 & N-40 for Endorsements 1.2 & 3 to NELIA Policy NF-17B & Certificates of Insurance M-3B.N-39 & M-40 for Endorsements 1.2 & 3 to MAELU Palicy MF-66
 DUCK. J R Marsh & McLennan. Inc . M & M Nuclear Consultants. Inc Div 82/12/23 SALTZMAN. J Assistant Director for State & Licensee Relations 55pp 16582 045 24X Fiche 50-259.82/12/23.8212290246

K Utility Final Safety Analysis Report (FSAR) & amends

- 8212140323 Forwards FSAR Figure 10 7-2, "Mechanical Control Diagram Raw Cooling Water Sys," inadvertently omitted from 820812 submittal RAMMER, D.S. Tennesses Valley Authority 82/12/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16402 054 P4X Fiche 50-259, 82/12/07, 8212140323
- P Operating license stage documents & correspondence
- 8211230046 Generic Ltr 82-27 to all BWR licensees of operating reactors Place of the service of the service

- 8P12090118 Confirms arrangements for 821215 meeting in Region 2 ofc re MSIV leakage at Unit 2 Proposed agenda encl O'REILLY, J P Region 2 Office of Director 82/12/01 PARRIS, H C Tennessee Valley Authority 2pp 16357 274 24X Fiche 50-259. 82/12/01, 8212090118
- 8212090346 Confirms B21102 telcon re 821202 enforcement conference in Atlanta.OA to discuss results of survey of waste oil facilities & plans for disposing of waste oil O'REILLY.J F Region 2. Office of Director 82/12/01 PARRIS, H C Tennessee Valley Authority 2pp 16365 157 24x Fiche 50-259, 82/12/01.8212090346
- 8212070288 Advises that NUREG-0737, Item II K 3 27, "Common Ref Level." will be reviewed w/control room design review as required by Item I D 1 Assessment team recommendations will be Item (D) Assessment even recommendations will be considered final resolution
 MILLS.L. M Tennessee Valley Authority 82/12/03 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 16339 0
 24X Fiche 50-259.82/12/03.8212070288 2pp 16339 013
- 8212090083 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing duration of containment integrated leak rate test from 24-h to 8-h MILLS.L M Tennessee Valley Authority 82/12/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 16357 192 C4X Fiche 50-259,82/12/03,8212090083
- --8212090088 Proposed Tech Spec revisions changing duration of containment integrated leak rate test from 24-h to 8-h Justification for proposed revisions encl

 * Tennessee Valley Authority 82/12/03 36pp 16357 195 24X
 Fiche 50-259,82/12/03.8212090083
- B212270192 Forwards item-by-item description of responses discussed during B21027 telcon w/F Clemenson re technical evaluation rept. "Control of Heavy Loads NUREG-0654," for facility MELSIL M Tennessee Valley Authority 82/12/14 VASSALLD, D R Operating Reactors Branch 2 44pp 16539 303 24x Fiche 50-259, 82/12/14, 8212270192
- 8P122800B5 Application to amend Licenses DPR-33,DPR-52 & DPR-48. Placebuods Application to amend Licenses DPR-33,DPR-52 & DPR-68, changing Tech Specs re bypassing of main steam line tunnel temp switches for up to 4-h MILLS.L M Tennessee Valley Authority 82/12/17 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp 16564 2. P4X Fiche 80-259,82/12/17.8212280085
- --B212280088 Proposed Tech Spec changes to bypassing of main steam line tunnel temp switches for up to 4-h * Tennessee Valley Authority 82/12/17 16pp 16564 240 24X Fiche 50-259,82/12/17.8212280085
- 82:12280295 Forwards draft response to 82:108 request for addl info re implementation of Revision 1 to NUREG-03:3 on mat! selection & processing for BNR coalant pressure boundary piping MILLB.L M Tennessee Valley Authority 88/12/20 DENTON.H R Uffice of Nuclear Reactor Regulation, Director 10pp 16562 (P4X Fiche 50-259.82/12/20.8212280295 16562 007
- @ Inspection reports, IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Audil.Lange-Diameter. Stainless Steel. Recirculation Sys Piping at INM Plants " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 143 24X Fichs 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dusimeters " Syc list enel COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16472 142 24% Fiche 50-000.82/11/05,8208190245
- GP12090456 Ack receipt of 821022 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/02-24, 50-260/02-24 & 50-296/02-24 LEWIS.R C Division of Project & Resident Programs 82/11/12 PARRIS.H 0 Tennessee Valley Authority 19 16264 009 24X Fiche 80-259, 82/11/12, 8212090456
- --8212070461 Responds to NRC 820921 ltr re violations noted in 1E Insp Repts 50-259/82-24,50-240/82-24 & 50-296/82-24 Corrective repts 30-297/82-24.50-260/82-24 & 50-296/82-24 Corrective actions evaluation concerning adequacy of review process will be provided by 830102 MILLS.L.M Tennessee Valley Authority 82/10/22 O'REHLLY.J P Region 2. Office of Director 5pp 16364 010 24X Fiche 50-259,82/11/12.8212090456

- --8212070467 Forwards IE Insp Repts 50-259/82-24,50-260/82-24 & 50-296/82-24 on 820725-0825 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/09/21 PARRIS.H C Tennessee Valley Authority 2pp 16364 015 24X Fiche 50-259,82/11/12.8212070456
- --8212090471 Notice of violation from insp on 820726-0825 * Division of Project & Resident Programs 82/09/21 2pp 16354 017 24X Fiche 50-259.82/11/12.8212070456
- --8212070477 IE Insp Repts 50-259/82-24, 50-260/82-24 & 50-296/82-24 on G20726-0825 Noncompliance noted post-maint testing not conducted on scram pilot valves & test criteria did not incorporate requirements & acceptance limits CHASE.J W. FAULK.O L. CANTRELL.F S Division of Project & Resident Programs 82/09/09 10pp 16364 019 24X Fiche 50-259,82/11/12,8212070456
- 8:08190251 IE info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- GPOBI90256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list and DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L.! Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edisproco of New York, Inc 35App 14387 028 24X Fiche 50-000.82/11/30.8208190257
- Gri2030212 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259782-30. 50-260782-30 & 50-296782-30 LeWIS.R C Division of Project & Resident Programs 82/11/30 PARRIS.H G Tennessee Valley Authority 1p 16307 067 24X Fiche 50-259. 62/11/30, 8212030212
- --8212030220 Responds to NRC 821019 ltr re violations noted in IE Safeguards Insp Repts 50-259/82-30.50-260/82-30 & 50-276/82-30 Corrective actions withheld (ref 100FR73 21) MILLS, L. M. Tennessee Valley Authority 82/11/19 D'REILLY, J. P. Region 2. Office of Director ID 16307 068 24X Fiche 50-259, 82/11/30.8212030212
- --8212030226 Forwards IE Safeguards Insp Repts 50-259/82-30, 50-260/82-30 & 50-276/82-30 on 820920-24 t notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) LEMIS.R C Division of Project & Resident Programs 82/10/19 FARRIS.H O Tennessee Valley Authority 2pp 16307 069 24X Fiche 50-269,82/11/20.8212030212
- B212030202 IE Insp Repts 50-259/82-30.50-260/82-30 & 50-296/82-30 on B20920-24 Noncompliance noted in areas of locks.keys & combinations.physical barriers protected areas,lighting & access control Petails withheld (ref 100FR73 21) HALL.B L . GOODE.R N . MCGUIRE.D R Division of Engineering & Technical Programs 82/10/14 2pp 16307 071 24X Fichs 50-259.82/11/30.8218030212
- 8P08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list gnc! BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 JE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Swc list encl JORDAM E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 9/12070080 Ack receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 LEWIG.R C Division of Project & Resident Programs 82/12/06 PARRIS.H G Tennessae Valley Authority 2pp 16057 236 24X Fiche 50-259, 82/12/06, 6212070030
- -- G212090092 Responds to NRC 821022 ltr re violations noted in IE Safeguards insp Repts 50-259/82-36, 50-260/82-36 & 50-296/82-36 Corrective actions withheld (ref 10cfR73 21) MILLS.L.H. Tennessee Valley Authority 82/11/24 0'REILLY, J.P. Region 2, Office of Director ip 16357 238 24X Fiche 50-259, 82/12/06, 8212090080

- --B21209010B Forwards IE Safeguards Insp Repts 50-259/82-36.
 50-260/82-36 & 50-296/82-36 on 820908-09 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21)
 0'REILLY, J.P. Region 2, Office of Director 82/10/22
 PARRIS.H Q. Tennessee Valley Authority 2pp 16357 239 24X
 Fiche 50-259,82/12/06.8212090080
- --8212090124 IE Safeguards Insp Repts 50-259/82-36, 50-260/82-36 & 50-294/82-36 on 820908-09 Noncompilance noted in area of access controls Details withheld (ref 100FR73 21)
 TILLHAN.A . HCGUIRE. D R Division of Engineering & Technical Programs 82/10/20 ip 16357 241 24X Fiche 50-259, 82/12/06, 821209080
- 8212170345 EN-82-041 on 821217.notice of violation & proposed imposition of cavil penalty in amount of \$3.125 will be issued to licensee for defective packaging in two shipments or low-specific activity radwaste to Richland.WA BROCKETT. 7 Director's Office, Office of Inspection and Enforcement 82/12/14 1p 16452 362 24X Fiche 50-296,02/12/14,8212170345
- 8708190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Oas Monitoring " Svc list enc! BEYDUND, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16.8208190267
- 87:08190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14628 273 24X Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- 8212270281 Forwards monthly operating repts for Oct 1782 JONES O T Tennessee Valley Authority 82/11/10 Office of Resource Management, Director Ip 16581 074 24X Fiche 50-259.82/11/10,9212290281
- --8212270287 Monthly operating repts for Oct 1982 THOM: T Tennessee Valley Authority 82/11/01 37pp 16581 0/5 24% Fiche 50-259,82/11/10,8212270281
- GAI2030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982 HILLS.L II Tennessee Valley Authority 82/11/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000.82/11/30.82/2030071
- S Reportable occurrences, LERs & related correspondence
- 0?12020261 Forwards LER 82-051/03L-0 GREEM H J Tennesse Valley Authority 82/11/17 O'REILLY, J P Region 2. Office of Director ip 16279 360 24X Fiche 50-296.82/11/17.8212020261
- ~~8212020264 LER 82-051/03L-0 on 821021, during normal operation, drywell CAM 3-90-256 removed from svc for maint due to erratic flow caused by vibration Packing on flow control valve NMC Model AM-31 UF continuous air monitor tightened THORPE, D Trannessee Valley Authority 82/11/17 Region 2, Office of Director 2pp 16279 361 24% Fiche 50-296,82/11/17,8212020264
- 8212020116 Forwards LER 82-052/03L-0 GREEN H J Ternessee Valley Authority 82/11/23 O'REILLY, J P Region 2. Office of Director tp 16272 047 24X fichs 50-294, 82/11/23, 8212020116
- --8212020124 LER 82-052/02L-0·on 821103, CAM 3-RR-90-256 (drywell atmosphere monitor) became inoperable Caused by sample pump failure due to normal end of svc life Schwitzer Series 328 vacuum pump rebuilt & returned to svc PORTER.M R Fennessee Valley Authority 82/11/23 Region 2. Office of Director 2pp 16272 048 24X Fiche 50-296,82/11/23,82(2020)16
- BP12020240 Forwards updated LER 82-043/03X-1 GREEN,H J Tennessee Valley Authority 82/11/23 O'REILLY,J P Hegion 2. Office of Director 1p 16274 149 24X Fiche 50-296.82/11/23.8212020240
- --B212020244 Updated LER B2-043/03X-i on B20907,generator/flywheel ball bearing on 480-volt reactor motor operated valve board 3DN motor generator set became noisy Caused by lack of lubricant film on bearing surfaces Bearing replaced AARON.JR Tennessee Valley Authority 82/11/23 Region 2, Office of Director. 3pp 16274 150 24X Fiche 50-296,82/11/23, 8212020240

- 8:)2150071 Forwards LER 82-054/03L-0 OREEN:H J Tennessee Valloy Authority 82/12/09 O'REILLY, J P Region 2. Office of Director ip 16431 009 24x Tiche 50-296.82/12/09.8212150071
- 8212150076 LER 82-054/03L-0 on 821110 low-pressure main steamline pressure switch 3-PS-1-76 had setpoint less than Tech Spec requirements Caused by setpoint drift Switch recallbr & returned to svc
 IRB7.8 J Tennessee Valley Authority 82/12/09 Region 2. Gfrice of Director 3pp 16431 010 24X Fiche 50-296.82/12/09, 62/15/6071
- 82:12150107 Forwards LER 82-053/03L-0 GREEN.H J Tennessee Valley Authority 82/12/09 O'REILLY, J P Region 2. Office of Director ip 16431 001 24X Fiche 50-296, 82/12/09, 8212150107
- --8212150111 LER 82-053/03L-0 on 821111, while performing daily background source check of turbine bidg continuous air monitor 3-90-251, inlet hose found disconnected Probably caused by failure to securely latch quick disconnect fittings THORRED Tennessee Valley Authority 82/12/09 Region J. Office of Director 2pp 16431 002 24X Fiche 50-296,82/12/09, 8212150107

DOCKET 50-298 COOPER NUCLEAR STATION

- F Security, medical, emergency & fire protection plans
- GP12070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents CI-C4 partially withheld (ref FOIA Exemptions 3.5 & 7) [ELTON, J M Division of Rules and Records 82/11/05 MCGARRY, J M Dabevoise & Liberman Spp 16395 009 24X Fiche 50-000,82/11/05, 1230202025
- --B212070432 Summary of B20412 meeting w/util in Region 4 ofc re concerns 8 enforcement options being considered pertaining to inadequaties in installation of emergency warning sys GACLIARDO.JE Division of Resident, Reactor Project & Engineering Programs B2/04/23 COLLINS.JT Region 4, Office of Director 2pp 16395 012 24X Fichs 50-000, B2/11/05, B212070425
- --8212070437 Forwards J Pilant B20524 ltr describing util actions taken to upgrade public notification sys Tone alert radios will be available for all residences within 10-mile emergency planning zone not covered by fixed sirens COLLINS.J T Region 4. Office of Director 82/05/26 ORIMES.B K Division of Emergency Preparedness ip 16355 014 24X Fiche 50-000,82/11/05,8212070425
- --421207044: Forwards questions from Commission Ahearne rp facility enforcement action HARDING,V Commissioners 82/05/28 DEYOUNG,R Director's Office. Office of Inspection and Enforcement 5pp 16355 019 24X Fiche 50-000,82/11/05,8212070425
- --B212070457 Requests draft Commission statement for issuance of proposed civil penalty to util Statement should indicate Commission approval of issuance of notice of violation & proposed civil penalty re notification sys

 CHILK, S. J. Office of the Secretary of the Commission 82/0//21

 BICKWITL Defice of the General Counsel 1p 16355 041 24X

 Fichs 50-000,82/11/05,8212070425
- --0212070473 Concludes that all Region 4 licensees in compliance w/820001 deadline for implementation of prempt notification sys COLLINS.U T Region 4. Office of Director 82/02/01 ORIMES.B K Division of Emergency Preparedness 2pp 16355 104 24X Ficha 50-000.82/11/05.8212070425
- --G21207049i Forwards radiological emergency response plans for facility 8 state & local entities within emergency planning zones Plans do not meet requirements of NUREG-0654 Revision 1 * Nebtaska Public Power District G1/01/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 46pp 16355 107 24X Fiche 50-000, 82/11/05, 8212070425
- B212030159 Application for amend to License DPR-A6.consisting of proposed changes to Tech Specs assuring continuous operable water supply for fire fighting sys from two fire pumps Class III amend fee submitted PILANT.J M Nebraska Public Power District 82/11/24 VASSALLO.D B Operating Reactors Branch 2 2pp 16307 095 24X Fishe 50-298.82/11/24.8212030159
- --8212030162 Proposed changes to Tech Specs assuring continuous operable water supply for fire fighting sys from two fire pumps

 Nebraska Public Power District 82/11/24 52pp 16307 097
 244 Fiche 50-298,82/11/24,8212030159

- 8P) 2070137 Ack receipt of 820806 ltr informing NRC of steps taken to correct open items noted in IE Insp Rept 50-298/82-08
 MADSEN.0 L Division of Resident, Reactor Project & Engineering Programs 82/12/01 PILANT.JM Nebraska Public Power District 2pp 16326 238 24X Fiche 50-298.82/12/01.8212070137
- --B212070141 Responds to NRC 820701 ltr re open items noted in IE Insp Rept 80-298/82-08 Corrective actions microfiche reader/ printer & file will be removed from NRC space in technical support ctr PILANT.J M Nebraska Public Power District 82/08/06 COLLINS.J T Region 4. Office of Director 11pp 16326 240 24X Fiche 50-298,82/12/01.8212070137
- G2:2070402 Responds to NRC 82:202 telcon request for info re emergency operation facility Permanent backup facility presently available PILANT, J M Nebrasia Public Power District 82/12/02 VASGALLO, D B Operating Reactors Branch 2 ip 14334 342 24X fiche 50-278.82/12/02.8212070402
- BP12080506 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/82-28 J Kelly chief of physical security section, plans 821208-09 visit to examine protective resource sys CQCLINS; J T Region 4: Office of Director 82/12/03 PILANT; J M Nebraska Public Power District 1p 16352 105 24X Fiche 50-298,82/12/03,8212080506
- 6212130336 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16413 244 24X Fiche 50-298,82/12/07, #2012180336
- --8212130342 Forwards public version of revised emergency plan implementing procedures, including Procedures 5 7 7 reactivation of technical support ctr & 5 7 9 reactivation of emergency operations facility PILANT.J M Nebraska Public Power District 82/11/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 116413 245 24X Fiche 50-298, 82/12/07.8212130336
- --B212130346 Public version of revised emergency plan implementing procedures, including Procedures 5 7 7 re activation of technical support ctr & 5 7 9 re activation of emergency operations facilities LESSOR.L C . SAVER.J . WHITMAN.D Nebraska Public Power District 82/11/08 150pp 16413 246 24X Fiche 50-298.82/12/07, 8212130336
- B:/12280379 Advises that commitment date.per 820604 ltr.re NUREQ-0737.

 Item II A 1 2. "Upgrade Emergency Support Facilities." will
 not be met/due to extensive contractual negotiations & legal
 vevieus

 PILANT.J M Nebraska Public Power District 82/12/16
 EISENHUT.D 0 Division of Licensing 1p 16560 052 24X
 Fische 50-278.82/12/16.8212280379
- P Operating license stage documents & correspondence
- G2:12070425 Responds to FDIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents Ci-C4 partially withheld (ref FOIA Exemptions 3.5 & 7) FELTON.J M Division of Rules and Records 82/11/05 McGARRY.J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000,82/11/05. G2!2070425
- B212070455 Forwards Commissioner Roberts dissenting view on facility enforcement action (EA-B2-46)
 LAVERTY, J H NRC No Detailed Affiliation Given S2/07/07.
 CHILK, S J Office of the Secretary of the Commission 10pp 16395 031 24X Fiche 50-000, B2/11/05, B212070425
- --B212070467 Statement by Commissioner Roberts disagreeing w/Commission decision Fine of \$30.000 proposed for failure to comply w/ regulatory requirement Util should not be cited & fined for commission of matl false statements Related info encl RDBERTS, T M Commissioners 82/11/05 7pp 16355.094 24X Fiche 50-000.82/11/05,8212070425
- --B212070500 Discusses Commission 820528 briefing re proposed enforcement action against util CHILK.8 J Office of the Secretary of the Commission 92/06/08 DIRCKS,W J Office of the Executive Director for Operations ip 16355

- 3211230046 Generic Ltr 92-27 to ail BWR licensess of operating reactors except LACBUR, Big Rock Point, Dresden 1. Mumboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISEM/NUT. D G Davision of Licensing 32/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24x Fiche 50-000, 82/11/15, 8211230066
- 3212030159 Application for amend to License DPR-46, consisting of proposed changes to Tech Specs assuring continuous operable water supply for fire fighting sys from two fire pumps Class III amend fee submitted 71LANF, J M Nebraska Public Power District 82/11/24 VASSALLO.D B Operating Reactors Branch 2 2pp 16307 095 24X Fiche 50-298.82/11/24.8212030159
- --8212030162 Proposed changes to Tech Specs assuring continuous operable water supply for fire Fighting sys from two fire pumps
 * Nebraska Public Power District 82/11/24 52pp 16307 097 244 Fiche 50-278,82/11/24,8212030159
- 6.12070175 Responds to Franklin Research Ctr 821029 request for info re plant unique analysis rept concerning Mark I containment program All small & large bore piping associated w/containment sys considered in evaluations PILANT. J. Nebraska Public Power District 82/12/01 VASSALL(). D B Operating Reactors Branch 2 5pp 16334 325 24X Fiche 50-298.8712/01.8212070175 Fiche 50-298, 82/12/01, 8212070175
- GF12130276 Forwards safety evaluation of BWR puners group 810522,0921 & 020902 responses to NUREG-0737, Item II K 3 25, "Effect of Loss of AC Pouer on Pump Seals " Responses acceptable VASSALLO, D B Operating Reactors Branch 2 82/12/01 PILANT, J rl Nebraska Public Power District 7pp 16418 220 24X [iche 50-298,82/12/01,8212130276
- 8212100273 Responds to NRC 821108 request for addl info re response to Generic Ltr 81-04 Selection of welds in loop of large bore reactor recirculation piping will be examined during 1983 refueling outage PICANT, J M Nebr VASSALLO, D B Operating Reactors Branch 2 48pp 16374 221 Fiche 50-298, 82/12/02, 8212100293
- 6212100171 Provides add1 info in response to 811005 draft technical evaluation rept re Guideline 4 of NUREG-0612 on special lifting devices
 PILANT.J M Nebraska Public Power District 82/12/03
 EISENHUT.D 0 Division of Licensing 2pp 16373 348 24X
 Fiche 50-298.82/12/03.8212(00)7)
- 8212280084 Forwards SER for NUREO-0737. Items I A 2 1, "Immediate Upgrading or Reactor Operation & Senior Reactor Operator Training & Qualifications" & II B 4, "Training for Mitigating Core Damage " Items complete VASSALLO, D 8 Operating Reactors Branch & 82/12/07 PILANT, J N Nebraska Public Power District 16pp 14593 053 24X Fiche \$0-298, 82/12/07, 8212280086
- G Inspection reports, IE Bulletins & correspondence
- BPO7180063 FOIA request for documents re 820809 notice of violation & order imposing civil penalty & proposed requirement concerning conduct of mgt audit set forth in order MCGARRY. J M Debevoise & Liberman 82/09/02 FELTON, J M Division finds and Records 2pp 16355 001 24% Fighe 50-298, 82/09/07, 8207180065
- 820Bi90240 lE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc last encl
 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list HOLE Model BUX INFORMATION INSCENT DOSINGLETS - SYC 115: encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8212070425 Responds to FOIA request for documents re 820809 notice of violation & order impasing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3,5 & 7) FELTON, J M Division of Rules and Records 82/11/05 MCOARRY, J M Debevoise & Liberman 5pp 16355 003 24X Fiche 50-000,82/11/05,000,000,000

- -8204140162 Comments on proposed imposition of civil penalty for 206140162 Comments on proposed imposition of civil penalty for failure to complete early warning sys by 820301 Site & classification of penalty discussed SIECEL, B Operating Reactors Branch 2 82/06/08 NOVAK, T M Assistant Director for Operating Reactors 3pp 16355 027 Fiche 50-000.82/11/05.8212070425
- --5212070443 Forwards B Siegel views re proposed enforcement action (EA-62-46) Agressive action warranted Further action will not be taken until response to 820603 nemo received DIRCKS,W J Office of the Elecutive Director for Operations 82/06/16 PALLADINO:N , GILINSKY,V , AHEARNE, J Commissioners 1p 16355 024 24X Fiche 50-000.82/11/05.8212070425
- B212070444 Forwards view expressed by project manager re pending enforcement matter

 EISENHUI.D G NRC - No Detailed Affiliation Given 82/0.

 CASE.E Office of Nuclear Reactor Regulation. Director

 LIEBERNIAN.J Director's Office. Office of Inspection and
 Enforcement ip 16355 025 24X Fiche 50-000.82/11/05.

 6212070425
- --8212070447 Forwards memo from II Siegel re views on pending enforcement action against licenses Encl should be treated as "For Official Use Only "

 NOVAK.T M NRC No Detailed Affiliation Given 82/06/08
 EISENHUI,D G NRC No Detailed Affiliation Given 1p
 16365 026 24X Fiche 50-000,82/11/05.8212070425
- --8212070452 Continues to support enforcement action (EA-82-46) proposed 2120/0432 Continues to support emforcement action (EA-82-46) proj in 820033 itr DIRCNS.W J Office of the Executive Director for Operations 82/05/21 PALLADIND.N , QILINEKY.V , AMEARNE, J Commissioners Ip 16355 030 24% Fiche 50-000,82/11/05,8212070425
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Trendise Requirements " Svc list end! JORDAN E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 (24) Fiche 50-000.82/11/18.8208190251
- SP12100197 Discusses issuance of SALP Rept 50-298/82-24 for Jul 1981-F)2100197 Discusses issuance of SALP Rept 50-298/82-24 for Jul 1981-June 1982 Since util did not comment on evaluation, SALP board rept issued as NRC rept COLLINS.J T Region 4. Office of Director 82/11/24 PILANT.J M Nebraska Public Power District 2pp 16377 111 24% Fiche 50-298,82/11/24,8212100197
- --8212100212 Forwards SALP Rept 50-298/82-24 for Jul 1981-June 1982 Comments requested by 821018 MADSEM, G L Division of Resident, Reactor Project & Engineering Programs 82/09/22 PILANT, J M Nebraska Public Power District 2pp 16377 113 24X Fiche 50-298, 82/11/24,8212100197
- 9212100213 SALP Rept 50-298/82-24 for Jul 1981-June 1982 licensee performance rated as Category I

 WESTERMAN, T F , MADSEN G L Division of Resident, Reactor Project
 & Engineering Programs 82/07/20 22pp 16377 115 24X
 Fiche 50-278, 82/11/24, 8212100197
- 8212100245 Forwards IE Insp Rept 50-298/82-31 on 821001-31 No PI21002A5 Forwards It IIIPP Nep. -- ...
 noncompliance noted
 MADEEN.9 L Division of Resident, Reactor Project & Engineering
 Programs B2/11/24 PILANT, J M Nebraska Public Power District
 Ppp 16376 129 24% Fiche 50-298,62/11/24,6212100265
- --8212100271 IE Insp Rept 50-298/82-31 on 821001-31 No noncompliance noted Hajor areas inspected operational safety verifications monthly surveillance & maint observations, plant trips, safety set challenges & licensee event followup DUBDIS.D.C., MCCRORY,S.L., MESTERMAN,T.F. Division of Resident, Reactor Project & Engineering Programs 82/11/23 App. 16376-181 24% Fiche 50-298.82/11/24/8212100265
- 82/08190296 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000 82/11/26 8208190296
- 8708190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- GP12070137 Ack receipt of 820806 ltr informing NRC of steps taken to correct open items noted in IE Insp Rept 50-278/82-08
 MADBEN, & L. Division of Resident, Reactor Project & Engineering Programs 82/18/01 FileNT, JM Nebraska Public Power District Opp 16326 238 244 Fiche 50-278,82/18/01.8212070137

- 8212070141 Responds to NRC 820701 itr re open items noted in IE Insp Rept 50-298/82-08 Corrective actions microfiche reader/ printer & file will be removed from NRC space in technical support ctr PILANT.J M Nebraska Public Power District 82/08/06 COLLINS.J T Region 4. Office of Director Tipp 16326 240 24X Fiche 50-298.82/12/01.8212070137
- 3.08190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies "Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Cansolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 82/0819026: IE Info Notice 82~48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN EL Division or Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X (1the 50-000, 82/12/03, 820819026)
- B. 12080596 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~278/82-28

 J Kelly chief of physical security section, plans 821208-07
 visit to examine protective resource sys
 COLLINS. J T Region 4. Office of Director 82/12/03 PILANT, J N
 Nebraska Public Power District 19 16392 109 24X
 Fische 50-298, 82/12/03, 9212080506
- 8/12140403 Approves proposed mgt appraisal plan & schedule described in G2100B, 1119 & 23 responses to order modifying license, effective immediately Plan should be initiated as soon as possible COLLINS. J T Region 4. Office of Director 92/12/07 JONES.C R Nebraska Public Power District 1p 16405 141 24X Fishe 50-278, 82/12/07. 8212140403
- - G2122832413 Notice of violation from inspin 821018-22

 * Division of Resident, Reactor Project & Engineering Programs

 82/12/08
 1p
 16560 031
 24X Fiche 50-298,82/12/08.8212280409
- --B212280420 IE Insp Rept 50-298/82-30 on 821018-22 Noncompliance noted multiple failures to perform blennial procedure review, primarily in maint area REDAND,R T , WESTERMAN,T F Division of Resident, Reactor Project & Engineering Programs 82/11/30 App 16540 032 24X Fiche 50-298,82/12/08.8212280409
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVOUNG: R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- G.'OB19026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc Jist encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X [sche 50-000.62/12/20.8208190268
- It Periodic operating reports & related correspondence
- C::12290312 Forwards monthly operating rept for Oct 1982 LESSOR.L C Nebraska Public Power District 82/11/02 Office of Resource Management, Director 1p id588 029 24X Fithe 50-298.82/11/02.8212270312
- --0212270315 Monthly operating rept for Oct 1982 BALLINDER,P L Nebraska Public Power District 02/11/02 App 16598 030 24% Fiche 50-298, 02/11/02, 0212290312
- S Reportable occurrences, LERs & related correspondence

8212300106

- 82:12300106 Forwards LER 82-023/03L-0 Detailed event analysis submitted LE88GR.L. C Nebraska Public Power District 82/12/23 COLLINS.J F Region 4. Office of Director 3pp 16598 249 24X Fiche 50-298.82/12/23.8212300106
- --8212300111 LER 82-023/03L-O on 821128, while snubber CS-57 taken out of svc to repair oil leak, snubber found inverted Caused by Loose extension tube locknut allowing snubber to rotate Snubber replaced BALLINGER, P. Nebraska Public Power District 82/12/23 Region 4. Office of Director 1p 16598-252 24X Fiche 50-298.82/12/23.

T Hearing transcripts on non-entitrust matters

- GP12070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely uithheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3,5 & 7) FELTON. J M Division of Rules and Records 82/11/05 MCGARRY, J M Debevoise & Liberman Spp 16355 003 24X Fiche 50-000, 82/11/05, B212070425
- --B212070496 Forwards transcript of closed Commission 820528 discussion of enforcement action Exemption 5 used to close meeting Recommendations re release of portions to public needed by 820611
 CHILK.S J Office of the Secretary of the Commission 82/06/01
 DIRCKS.W J Office of the Elecutive Director for Operations 2pp 16355 154 24% Fiche 50-000.82/11/05.8212070425
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 H. Security, medical, emergency & fire protection plans
- GP12070079 Forwards revised Page 10 3 to safeguerds plan Page withheld tref 10CFR2 790 & 73 21)
 BURSTEIN,5 Wisconsin Electric Power Co 82/12/02 DENTON, H R
 Orfice of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 ip 16327 271 24X
 Fishe 50-266 82/12/02.8212070079
- GPi2280082 Responds to Burstean 821110 & 1202 ltrs re addition of Chapter 10 to physical security plan Changes acceptable Ltrs withheld (ref 100FR73 21) CLARK.R A Operating Reactors Branch 3 82/12/13 FAY,C W Wisconsin Electric Power Co Ip 16593 087 24X Fische 50-266, 82/12/13,8212280082
- G212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility (KEPPLER.J O Region 3. Defice of Director 62/12/16 Curmonwealth Edison Co 3pp 16503 351 24% Fiche 50-000,82/12/16. G212220306
- 8:12290324 Confirms plans for 830110 mgt meeting in Milwaukee.WI re fire protection concerns Written responses to IE Insp Repts 50-266/82-(7 & 50-301/82-17 deferred until 830125 NORELIUS, C E Division of Engineering & Technical Programs 82/12/23 BURSTEIN.S Wisconsin Efectric Power Co Ip 16589 15/ 24X Fiche 50-266.82/12/23.8212290324
- & Adjudicatory correspondence
- Birl2080251 Supports steam generator tube sleeving BLAHA.0., ENCELBRECHT,L., SCHMODCK,D. Two Rivers,WI 82/11/29 BLOCH,P. Atomic Safety and Licensing Board Panel ip 16354-126-24X Fiche 50-266,82/11/29,B212080251
- 8212230357 Forwards licensee proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Wisconsin Electric Power Co 82/12/20 BLOCH, P B , KLINE, J R , PAXTON, H C Atomic Safety and Licensing Board Panel 1p 16511 207 24X Fiche 50-266, 82/12/20, 8212230357
- --B212230359 Proposed findings of fact & conclusions of law in form of proposed initial decision re repair of corroded steam generator tubes by inserting sleeves Certificate of 8vc enci
 CHURCHILL, B W. Hisconsin Electric Power Co. CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge 82/12/20 31pp 16511 208 24X Fiche 50-266, B2/12/20, B212230357
- GP12270316 Notice of appeal from 921210 special prehearing conference order dismissing Decade 820810 & 1805 petitions to intervene Affidavit of mailing encl ANDERSON.P Wisconsin's Environmental Decade 82/12/20 3pp 14530 281 24X Fiche 80-246.82/12/20.8212270316
- 8212270323 Brief supporting appeal from 821210 special prehearing conference order denying 820810 petition to intervene & request for extension of time to complete brief Dismissal of petition on stated grounds contrary to law ANDERSON.P Wisconsin's Environmental Decade 82/12/20 Atomic Safety and Licensing Board Panel 15pp 16530 215 24X Fiche 50-266, 82/12/20, 8212270323

- P Operating license stage documents & correspondence
- UP12:70040 Ack receipt of B2:123 ltr transmitting Class I fee for 82:0933 application Basis for not remitting additional requested fee acceptable UIGGS.R M. License Fee Management Branch 82/12/03 FAY.C W. Wisconsin Electric Power Co. 1p. 16480-362 24% Fiche 50-266.82/12/03.8212170040
- 8.º08190263 Generic Ltr 82-32 to all PMR licenses repotential steam generator-related generic requirements Forwards Science Applications, Inc draff rept re sub, requirements Comments requested within 30 days of ltr Svc list encl EISEMHJT. D © Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc. 29pp 16629 247 24X Fiche 50-000, 82/12/09.8208190263
- 6/12140103 Generic Ltr 82-20 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re insdequate core cooling instrumentation says Svc list encl EISE(HWIT, D & Division of Licensing 82/12/10 Yankee Atomic Licentic Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 52/12/10(13)
- 8(12)70326 Refs Westinghouse 791206 ltr in response to RA Clark 82110B request for ECCS evaluation model addressing two loop upper plenum injection plants Calculations for worst case large break & sensitivity studies will be submitted by 830225 FAY.C W Wisconsin Electric Power Co 82/12/10 DENTON,H R Uffice or Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Granch 3 2pp 16453 224 24% Fiche 50-266,82/12/10,8212170326
- G/12210056 Comments on technical evaluation rept re-seismic qualification or auxiliary feedwater system 921112 request Recommendation to acquire complete SSE level of seismic capacity constitutes unnecessary & expensive backfit (AV.C.W. Uisconsin Electric Power Co 62/12/15 DENTON.H R Defice of Ruclear Reactor Regulation, Director CLARK.R A Operating Reactors Granch 3 5pp 16492 248 24X (Inche 50-266, 82/12/15, 8212210056
- BY 12220422 Application to amend Licenses DPR-24 & DPR-27, consisting of lech Spec Change Request 86 to address NUREG-0737, ltem 11 K 3 3. "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr 82-16 [AY.C W Usconsin Electric Power Co 82/12/15 DENTON, H R Diffice or Nuclear Reactor Regulation, Director CLARK, R A Uperating Reactors Branch 3 3pp 16503 278 24X [iche 50-266, 62/12/15, 8212220422]
- U212220427 Proposed Tech Spec Change Request 85 addressing requirements of NUREC-0737. Item [I K 3 3, "Reporting Safety & Relief Valve Failures & Challenges," in response to Generic Ltr 52-16
 - * Misconsin Electric Power Co 82/12/15 1p 16503 281 24X Fiche 50-266,82/12/15,8212220422
- 6:12290095 Forwards "Evaluation of Pressurizer Safety & Relief Volve bys for Point Beach Nuclear Plant," in further response to NUREO-0737. Item II D I re relief & safety valve testing FAY.C W Hisconsin Electric Power Co 82/12/23 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK, R A Uperating Reactors Branch 3 2pp 16589 169 24X fiche 50-266, 82/12/23, 9212290095
- --8212290104 "Evaluation or Pressuriser Safety & Relief Valve Suc for Point Beach Nuclear Plant" W/two oversize drawings Aperture cards are available in PDR MCKINKEY.T R . RAMSEY.B L . RAZLAFF, W J EDS Nuclear. Inc 09-0970-001 ROO 82/12/21 64pp 16589 172 24X Fiche 50-264,82/12/23.82122790075
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Syc list encl DEFOUNG, R C Director's Office, Office of Inspection and Enforcement 92/10/20 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- BYOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model 802 Thermoluminescent Dosimaters " Svc list incl COBB.L ! Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 244 Fiche 80-000, B2/11/05.8208190245

- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. (09pp. 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- BP0B190286 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl
 pEY0UNG:R C Director's Office, Office of Inspection and Enforcement 82/11/24 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8408190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list and COBB.C. I Division of Fuel Facilities. Materials & Safeguards 82/11/30 consolidated Edison Co of New York. Inc 356pp 13387 028 24X Fiche 50-000.82/11/30.8208190257
- --8212170[8] Notice of violation from insp on 820428-0701 & 08 NORELIUS.C E Division of Engineering & Technical Programs 82/11/30 4pp 16450 195 24X Fiche 50-266.82/11/30,8212170177
- --8212170189 IE Insp Repts 50-266/82-17 & 50-301/82-17 on 820628-0701 & 08 Noncompliance noted imadequate surveillance testing, nonfunctional penetration fire barrier & incamplete development & implementation of administrative controls RAMSEY.C., ULIE.J., OROBE.J.A. Region 3. Office of Director 82/09/20 21pp 16450 199 24X Fiche 50-266.82/11/30.8212170177
- 82:08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment ilectrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-4B, "Failures of Agastat CR 0095 Relay Bockets " Byo list encl JORDAW: E L Division of Engineering & Quality Assurance 82/12/03 Conselldated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 82:12100221 Ack receipt of 82:129 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 KEPPLER. J O Region 3. Office of Director 82/12/07 BURSTEIN, S Hisconsin Electric Power Co 2pp 16377 101 24X Fiche 30-266.82/12/07.82:12100221
- --B212100222 Responds to NRC 820915 ltr re violations noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions review of tuntainment entry control procedures & controls & interchangeability of keys changed FAI.C W Wisconsin Electric Power Co 82/10/15 KEPPLER, J & Region J. Office of Director 4pp 16377 103 24X Fiche 50-266, 82/12/07.8212100221
- --8212100R23 Add1 response to NRC 820915 ltr re violation noted in IE Insp Repts 50-266/82-12 & 50-301/82-12 Corrective actions area roped off.conspicuously posted & flashing lights used as warning device FAY.C W Wisconsin Electric Power Co 82/11/29 KEPPLER, J G Region 3, Office of Director 3pp 16377 107 24X Fichs 50-266,82/12/07.8212100221
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 62:12280361 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" No Bunker Ramo penetration assemblies installed initially or during backfit & nod FAY, C W Wisconsin Electric Power Co 82/12/17 KEPPLER, J G Region 3, Office of Director 1p 16560 077 24X Fichs 50-266, 82/12/17, 8212280361
- 8208190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl. JORDANIE L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X Fiche 50-000,82/12/20,8208190248

- R Periodic operating reports & related correspondence
- 8212290253 Forwards revised monthly operating repts for Aug 1982 for Units 1 & 2 & revised Sept 1982 rept for Unit 2 FAY.C H Misconsin Electric Power Co 82/11/17 Office of Resource Management, Director ip 16582 037 24X Fiche 50-266,82/11/17.8212290253
- --8212290257 Revised monthly operating lepts for Aug 1982 FAY.C W Wisconsin Electric Power Co 82/09/07 2pp 16582 038 24% Fiche 50-266.82/11/17.8212290253
- ---3212270262 Revised monthly operating rept for Sept 1782 FAY.C W Misconsin Electric Power Co 82/10/04 ip 16582 040 24X Fiche 50-266.82/11/17.8212270253
- 8212210297 Forwards monthly operating repts for Nov 1982 FAV.C W Wisconsin Electric Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director 1p 16497 089 24X Fiche 50-266, 82/12/10,8212210297
- --B212210299 Monthly operating repts for Nov 1982 FAY.C W Wisconsin Electric Power Co B2/12/06 11pp 16497 090 24X Fiche 50-286.82/12/10.8212210297
- S Reportable occurrences, LERs & related correspondence
- B212100208 Forwards LER 82-009/017-0 FAY,C W Hisconsin Electric Power Co 82/12/03 KEPPLER,J 0 Region 3, Office of Director 1p 16376 216 24X Fiche 50-301, 82/12/03, 8212100208
- ---82121032i1 LER 82-009/01T-0 on 821122.axial flux differential monitoring program & alarm found inadvertently halted from 821120-22 w/o manually logging flux differential Caused by operator diagnosing backup computer problem FAV.C W Wisconsin Electric Power Co 82/12/03 Region 3, Office of Director 2pp 16376 217 24X Fiche 50-301,82/12/03.
- 8:12280114 Forwards LER 82-010/03L-0 FAY, C W Wisconsin Electric Power Co 82/12/15 KEPPLER, J 0 Region 3. Office of Director 1p 14564 059 24X Fiche 50-301.82/12/15.8212280114
- --8212280115 LER 82-010/03L-0 on 821110, during surveillance test TS-11, secondary boric acid heat tracing circuits found inoperable Caused by internal defect which tripped breaker 1852-429A Breaker replaced FAY, C W Wisconsin Electric Power Co 82/12/15 Region 3, Office of Director 2pp 14564 060 24X Fiche 50-301,82/12/15, 8212280114

DDCKET 50-302 CRYBTAL RIVER NUCLEAR PLANT, UNIT 3
F Security, medical, emergency & fire protection plans

- 8P12070132 Discusses NRC emergency radio communications & results of 821028 site meeting Radio sys will be brought to plant during emergency High frequency established for hurricane alert Placement of antennas outlined O'REILLY, JP Region 2, Office of Director 82/11/24 HANCOCK, JA Florida Power Corp 3pp 16357 317 24X Fiche 50-302,82/11/24,8212090132
- 8P1210D006 Submits info re emergency operations facility, in response to G21202 request Const completed on 821015
 HEBTAFER R R Florida Power Corp 82/12/06 STOLZ, J F Operating Reactors Branch 4 1p 16373 362 24X Fiche 50-302,82/12/06, R21210D006
- 8212140089 Documents 821208 telcon responding to NRC request for addl info re 10CFRSO App R fire study, dtd 821029 & superseding 820650 submittal Revised Table 1 & Figure 2 encl WESTAFER, 0 R Florida Power Corp 82/12/09 EISENHUT, D 0 Division of Licensing 14pp 16408 256 24X Fiche 50-302,82/12/09, 8212140089
- G212220284 Confirms 821019 telcon rs App R submittal Util response to 1 tem 11.App R encl Automatic starting of diesel generators on loss of voltage relied upon for safe plant shutdown in event of fire
 WEBIAFER.O R. Florida Power Corp 82/12/17 EISENHUT, D Q
 Division of Licensing 1p 16517 191 24X Fiche 50-302,82/12/17,8212220284

- H General correspondence
- BP12060084 Documents recent organizational change in nuclear licensing area All previous authorizations withdrawn, effective 821201 HANCOCK, J. A. Florida Power Corp. 82/12/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16316-067 24X Fiche 50-302, 82/12/01, 8212060084
- 8P12290177 Requests that Bureau of Intergovernmental Relations be removed from distribution list D correspondence previously addressed to D9 Mardis be sent to author MESTAFER: 6 R Florida Power Corp 82/12/17 DENTON.H R Office of Nuclear Reactor Regulation, Director ip \$6578 038 24X Fiche 50-302, 82/12/17. 8212290177
- P Operating license stage documents & correspondence
- 82:1090043 Provides detailed specs re Orion boron & chloride analyzor equipment to be used to fulfill requirements of NUREO-0737.

 Item [I B 3, "Post-Accident Sampling Capability"
 Implementation espected during Refuel 4

 BAYNARD, P Y Florida Power Corp B2/11/03 STOLZ, J F Operating Reactors Branch 4 2pp 16004 001 24X Fiche 50-302, B2/11/03, B2/11/09043
- Bi12010160 Forwards Amend 59 to License DPR-72, safety evaluation & notice of issuance & availability Amend allows will to change modes wintermediate pressure relief line isolation valve replaced w/pipe cap STOLZ.JF Operating Reactors Branch 4 82/11/17 HANCOCK, JA Florida Power Corp 3pp 16290 281 24X Fiche 50-302, 82/11/17, 8212010160
- --8212010164 Amend 59 to License DPR-72 allowing util to change modes w/intermediate pressure reliaf line isolation valve replaced w/pipe cap STOL7. JF Operating Reactors Branch 4 82/11/17 4pp 16290 284 24X Fiche 50-302
- --8212010167 Safety evaluation supporting Amend 59 to Cicense DFR-72 # Office of Nuclear Reactor Regulation. Director 82/11/17 2/pp 16290 289 24X Fishe 50-302.82/11/17.8212010160
- --8212010172 Notice of issuance & availability of Amend 59 to License DPR-72 STOLZ, J.F. Operating Reactors Granch 4 82/11/17 2pp 16290 291 24X Fiche 50-302,82/11/17.8212010160
- G212010329 Forwards Amend &O to License DPR-72, safety evaluation & notice of issuance & availability Amend identifies post-accident monitoring instrument readouts w/racorders & changes measurement units for reactor coolant flow MINER.9 Operating Reactors Branch 4 82/11/23 HANCGCK, J A Florida Power Corp 3pp 16271 284 24% Fiche 90-302, 82/11/23, 82/2010/29
- --B212010330 Amend 60 to License DPR-72, identifying post-accident monitoring instrument readouts w/recorders & changing measurement units for reactor coolant flow from percent to 1b per hour STOL7.J F Operating Reactors Branch 4 82/11/23 5pp 16271 287 24X Fiche 50-302, 82/11/23, 8212010329
- --8212010331 Safety evaluation supporting Amend 60 to License DPR-79 * Office of Nuclear Reactor Regulation, Director 92/11/23 2/pp 16271 292 24X Fiche 50-302.82/11/23.8212010329
- --8212010332 Notice of 1940ance & availability of Amend 60 to Licenso DPR-72 STOLZ: J F Operating Reactors Branch 4 82/11/23 2pp 16271 294 24% Fiche 50-302,82/11/23.8212010329
- GP:2060225 Submits response to NUREG-0612, "Control of Heavy Loads" Income instrument container hoist derated to capacity of 1,000 lb BAYNARD.P Y Florida Power Curp 82/12/01 STOLZ, J F Operating Reactors Branch 4 3pp 16312 233 24X Fiche 50-302,82/12/01, GP:2040295
- B212150236 Forwards safety evaluation supporting operation of once-through steam generator blowdown lines pressurized from cold shutdown to 15% rated thermal power until Refueling V STOLZ.J F Operating Reactors Branch 4 82/12/07 HANGGCK, J A Floride Power Corp 2pp 16446 353 24% Fiche 50-302,82/12/07.8212150236
- --8212150240 Safety evaluation supporting operation of once-through steam generator bloodown lines pressurized from cold shutdown to 15% rated thermal power until Refueling V * Office of Nuclear Reactor Regulation, Director 82/12/07 Jp 16446 355 24% Fiche 50-302, 62/12/07.8212150236

- 8:08190263 Generic Ltr 82-32 to all PNR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 29pp 16629 247 24X [iche 50-000, 82/12/09,8208170263]
- 8412270381 Forwards SER of util responses to TMI Action Item II E 4 2.
 "Min Containment Pressure Setpoint" Setpoint acceptable
 5TCL2.7 F Operating Reactors Branch 4 82/10/10 HANCOCK, J A
 Florida Power Corp 2pp 14564 037 24% Fiche 50-302.82/12/10.
 R2192737881
- --9212270395 SER supporting util response to TMI Action Item II E 4 2.
 "Min Containment Pressure Setpoint"

 * Operating Reactors Branch 4 82/12/10 3pp 16566 041 24X
 Fiche 50-302, 82/12/10,8212270381
- G::12270409 Forwards order for license mod requiring installation of inadequate core cooling instrumentation system NUREG-0737, Item II F 2 EISENHUT, D G Division of Licensing 82/12/10 HANGOCK, J A Florida Power Corp 2pp 16572 343 24X Fiche 50-302,82/12/10,
- --0012270411 Order for license mod requiring installation of inadequate core cooling instrumentation sys.per MAREG-0737. Item II F 2 Checklist for reviewing sys.macl EISEMHUT. D G Division of Licensing 82/12/10 Florida Power Corp 11pp 16572 345 24X Fiche 50-302.82/12/10.8212270409
- GPIC220270 Responds to Item 10 of 820819 request for add1 info re 1MI Item II E 1 1, "Auxiliary Feedwater Sys Evaluation" Response to Item 4 & 8 re TMI Item II E 1 2, "Emergency feedwater Upgrade," to be submitted upon resolution WESTAFER, G R Florida Power Corp 82/12/17 STGLZ, J F Operating Reactors Branch 4 7pp 16517 353 24X Fichs 50-302, 82/12/17, 62/12/220270
- 4 Inspection reports, IE Bulletins & correspondence
- 80:00190240 IE Bulletin 82:03.Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82:10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000.82/10/28,8208190240
- 8:08:90245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters." Svc. list uncl COBB. I Division of Fuel Facilities. Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York. Inc. 110pp 18:372-142 24X Fiche 50-000.82/11/05.8208170245
- GP12090423 Confirms 821105 teleon re arrangements for 821124 mgt meeting in St Petersburg.FL Heeting will review results of first phase of NRC annual appraisal of util regulatory performance Proposed agenda encl LEMIS.R C Division of Project & Resident Programs 82/11/16 MANCOCK.J A Floride Power Corp 3pp 16364 266 24X Fiche 50-302.82/11/16.8212090423
- G:08190251 IE Info Notice 82-44, "Ctarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN: E. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York: Inc. 109pp. 16411 199 24X [tche 50-000,82/11/18,8208190251
- 8:08190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padiacks " Svc list encl DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 068 24X Fiche 80-000, 82/11/26, 8208190256
- 8:08190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl CGBB.L I Division of Fuel Facilities. Materials & Safeguards G2/11/30 Consolidated Edison Co of New York
- OF 08190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies" Svc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411'317, 24X Fiche 50-000,82/12/03.8208190259

- 8/08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,8208190261
- GPUB190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 [9] 24X Fiche 50-000.82/12/16.8208190267
- GR12220530 Ack receipt of 820119 % 0827 applications for changes in administrative controls section of Tech Space & relief from requirements of ASME Code Section XI for visual & volumetric insp of reactor vessels & head cladding MILLER, N O License Fee Management Branch 82/12/16 HANCOCK, J Florida Power Corp 2pp 16523 039 24% Fiche 50-302, 82/12/16, 8212220530
- G:OB19026B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/RO Consolidated Edison Co of New York, Inc 108pp 14628 293 24X Fiche 50-000,82/12/20,8208190248
- R Periodic operating reports & related correspondence
- 89:12140048 Forwards monthly operating rept for Nov 1982 WESTAFER.O R Florida Power Corp 82/12/09 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 1: 16408 281 24X Fiche 50-302, 82/12/09, 8212140048
- 8212140051 Menthly operating rept for Nev 1982 BOCART,D Florida Fower Corp 82/12/02 4pp 16408 282 24X Fiche 50-302,82/12/09.8212140048
- 9 Reportable occurrences. LERs & related correspondence
- G212020045 Forwards LER 82-068/03L-0
 BAYNARD, P Y Florida Power Corp G2/11/24 O'REILLY, J P Region
 2. Office of Director 1p 16272 057 24X Fiche 50-302,82/11/24,
 G212020045
- --8212020052 LER 82-048/03L-O on 821029, feedwater ultrasonic flow indicator FW-312-FI found inoperable during daily surveillance, rendering emergency feedwater train A inoperable Caused by insufficient cable clearance BROWN, C 9 Florida Power Corp 82/11/26 Region 2, Office of Director 2pp 16272 058 24X Fiche 50-302,82/11/24,8212020045
- BP12020063 Forwards LER 82-067/03L-0 BAYNARD.P Y Florida Power Corp 82/11/24 D'REILLY.J P. Region 2. Office of Director 1p 16272 001 24X Fiche 50-302,82/11/24, 0212020063
- --8212020071 LER 82-047/03L-O on 821028, feedwater ultrasonic flow indicator FW-313-FI discovered inoperable Caused by defective scale card Bcale card replaced & functional check satisfactorily completed HUOHES,P O Florida Power Corp 82/11/26 Region 2, Office of Director 2pp 16272 002 24X Fiche 50-302,82/11/24,8212020063
- --B212020087 LER 82-049/03L-0 on B21029, remote & local 175-ft wind direction channels found out of tolerance Caused by failed direction sensor, Sensor replaced & instrument recalibr Meteorological monitoring sys under evaluation BROWN:C 9 Florida Power Carp B2/11/26 Region 2, Office of Director 2pp 16272 012 24X Fiche 50-302,82/11/24,8212020077
- G212030102 PND-II-02-130 on B21125, high airborne radioactivity levels caused evacuation of plant auxiliary bidg Caused by packing plug hole in letdown valve. No personnel contaminated Gassous islease 8% of Tech Bpc limit
 ROGOE, J F , DANCE, H C Region 2. Office of Director 82/11/27
 2pp 16304 111 24% Fiche 30-302,82/11/27,8212030102
- 8212150085 PND-II-82-130A on 821125, madvertent release of radioactive water amounted to 80% of plant instantaneous liquid concentration release limit Preliminary licensee calculation indicated limit exceeded 40% NEJFELT.0 M. DANCE:H C. Region 2, Office of Director 82/12/07 lp 16430 160, 24% Fiche 50-302,82/12/07,8212150085

- 8212150099 Forwards LER 82-070/03L-O Detailed event analysis encl WESTAFER, O R Florida Power Corp 82/12/07 O'REILLY, J P Region 2. Office of Director 2pp 16427 359 24X Fiche 50-302,82/12/07, 8212180099
- --B212150102 LER 82-070/03L-0 on 821107, during Mode 1, nuclear overpower Channel B tripped due to failure of reactor coolant flow transmitter RC-14A-FT2 Caused by shorted capacitor in power supply Capacitor replaced & transmitter returned to svc HUOHES,P 0 Florida Power Corp 82/12/07 Region 2, Office of Director ip 16427 361 24X Fiche 50-302.82/12/07,8212150099
- GEL2150105 Forwards LER 82-071/03L-0 WESTAFER, 0 R Florida Power Corp 82/12/07 D'REILLY, J P Region 2, Office of Director 1p 16430 360 24X Fiche 50-302, 82/12/07, 8212150105
- ~-B21213010B LER B2-071/03L-0 on B21114, during Mode 1, radiation monitor RM-A5, control room iodine channel found indpenable Caused by failure of rotary selector switch Switch replaced & monitor placed in svc BRGWN, C O Florida Power Corp B2/12/07 Region 2, Office of Director 2pp 16430 361 24X Fichs 50-302, 82/12/07, 8212150105
- 3212150046 Forwards LER 82-073/04T-0 BAYNARD.P Y Florida Power Corp 82/12/10 O'REILLY, J P Region 2. Office of Director ip 16422 324 24X Fiche 50-302,82/12/10, 6212150046
- --8212150053 LER 82-073/04T-0 on B21126, isolation setpoint on liquid waste effluent monitor (RM-L7) not sufficiently conservative to preclude release in excess of 10CFR20 Cavsed by inadequate process Procedure revised HUGHES,P 0 Florida Power Corp 82/12/10 Region 2, Office of Director 5pp 16422 325 24X Fiche 50-302,82/12/10,8212150046
- GP12150060 Forwards LER 82-072/03L-0

 BAYNARD,P Y Florida Power Corp 82/12/10 0'REILLY.J P Region
 2, Office of Director 1p 16427 323 24X Fiche 50-302,82/12/10,8212180060
- ---8212150064 LER 82-072/03L-0 on 821125.determined reactor coolant water leaking to nuclear syss closed cycle cooling sys through letdown cooler 8 Gausad by thermal shock due to long isolation during rapid restoration to sys Cooler replaced HUGHES,P O Florida Power & Light Co 82/12/10 Region 2, Office of Director 2pp 16427 324 24X Fiche 50-302,82/12/10,8212150060
- 8212220314 Forwards LER 82-074/03L-0 HAYNARD, P Y Florida Power Corp 82/12/16 D'REILLY, J P Region 2, Office of Director 1p 16517 181 24X Fiche 50-302, 82/12/16, 1821220314
- --8212220322 LER 82-074/03L-0 on 821116, during performance of 8P-186, control complex charcoal filters failed Freen portion of surveillance required by Tech Specs Caused by moisture absorption by charcoal filters Filters replaced & tested BROWN.C O Florida Power Corp 82/12/16 Region 2. Office of Director 2pp 16517 182 24x Fiche 50-302,82/12/16.8212220314
- 8212280060 PND-II-82-137 on 821222, during feed & bleed operation to remove boron from reactor coolant water-radiation monitor in auxiliary bldg sounded twice resulting in two evacuations Probably caused by compressor leak BROWNLEE V Region 2. Office of Director 82/12/22 2pp 16565 139 24X Fiche 50-302.82/12/22.8212280060
- BOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B212060232 Forwards IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of emergency preparedness & SER HIND, J A Division of Emergency Preparedness & Operational Bupport 82/11/19 RED, C Commonwealth Edison Co 2pp 16312 201 24X Fiche 50-295, 82/11/19, 8212060232
- --8212060238 IE Safety Evaluation Repts 50-295/82-23 & 50-304/82-20 of emergency preparedness plan Emergency plan acceptable PHILLIPS: N P Division of Emergency Preparedness & Operational Support 82/11/18 Ip 16312 203 24X Fiche 50-295,82/11/19,8212060232
- --B212060255 SER of emergency preparedness plan Plan acceptable # Region 3, Office of Director 82/11/30 27pp 16312 204 24) Fiche 50-295, 82/11/19, 8212040232

- GPI2070055 Forwards revised elemption requests documenting info provided at 821104 & 05 meetings re post-fire shutdown capability LENTINE,F 0 Commonwealth Edison Co 82/11/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 88pp 16526 010 24X Fiche 50-295, 82/11/29, 8212070050
- G212090383 Forwards info re emergency operations facilities per G21122 & 1202 requests info proviously submitted by telcon Request for written response unnecessary burden on licensee DELGEORGE, L O Commonwealth Edison Co 92/12/03 EISENHUT, D G Division of Licensing 2pp 16365 051 24X Fiche 50-000 62/12/03, B212090383
- Gri2130149 Releases public version of revision to emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/12/03 Document Nanagement Branch ip 16410 275 24X Fiche 50-295,82/12/03. 0212130149
- --B212130153 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generation Station Emergency Plan Conditions" Procedure change request form entl
 PLIML, G. Commonwealth Edison Co. 82/11/19 DENTON, H.R. NRC No. Detailed Affiliation Given 3pp. 16410 297 24x
 Fiche 50-275,82/12/03,8212130149
- --8212130156 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP 330-1, "Classification of Generating Station Emergency Plan Conditions"

 * Commonwealth Edison Co 82/11/16 14pp 16410 300 24X
 Fiche 50-295,82/12/03.8212130149
- QJE2130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EO-2. "Pre-Established Onsite % Uffsite Monitoring Locations (Maps)" FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24% Fichs 50-000, 82/12/07, 8212130017
- --8212130028 Forwards public version of Revision 1 to Emergency Plantinglementing Procedure EG-2, "Pre-Established Clasite & Offsite Monitoring Locations (Maps) " Revised table of contents enc! PAJONEKI, J. Commonwealth Edison Co. 62/11/01 DENTON, H.R. NKC No Detailed Affiliation Given 2pp 16417-063 24X Fiche 50-000, 82/12/07-8212130017
- -G212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 PAJOWSKI, J E Commonwealth Edison Co 82/11/27 4pp 16417 065 244 Fishe 50-000.82/12/07.8212130017
- 6k12140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annox not prepared FRAMM.TR Commonwealth Edison Co. 82/12/07 DENTON,HR Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000, 82/12/07,8212140243
- GY12220175 Releases public version of revised generating station emergency plan implementing procedures FELTON, JM Division of Rules and Records 82/12/10 Document Management Branch 1p 16527 029 24X Fiche 50-000, 82/12/10, 1810220175
- --B212220190 Forwards public version of revised generating station emergency plan implementing procedures including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJOMBKI.J E Commonwealth Edison Co 82/11/15 DENTON.H R Defice of Nuclear Reactor Regulation, Director ip 14529 030 24X Fiche 50-000.82/12/10.8212220175
- --8212220202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand politing of meteorological data & ED-20 re emergency forecast request LITERBKI, L A Commonwealth Edison Co 82/10/13 48pp 16527 031 24X Fiche 50-000, 82/12/10,8212220175
- B212210454 Forwards add1 info documenting discussions at B21104 & 05 meeting u/NRC & INC re remaining open items from technical evaluation rept, "Post-Fire Shutdown Capability"

 LENTINE,F G Commonwealth Edison Co 82/12/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 39pp 16489 285 24X Fiche 50-295, B2/12/15,B212210454

- 8212223306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility KEPPLER.J O Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16.8212220306
- B2122700B3 Releases public version of corrected page to emergency plan implementing procedure FELTON.J M Division of Rules and Records 82/12/20 Document Management Branch lp 16606 343 24X Fiche 50-295,82/12/20, 82122700B3
- --8212290086 Forwards public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1 Receipt form encl PLIML 6 Commonwealth Edison Co 82/11/30 DENTON, H R NRC No Detailed Affiliation Given 2pp Fiche 50-295, 82/12/20.8212290093
- --8212270089 Public version of corrected Page 4 to Emergency Plan Implementing Procedure EPIP 410-1 * Commonwealth Edison Co 82/11/30 1p 16606 346 24X Fiche 50-279, 82/12/20.8212270083
- 8212290098 Releases public version of revision to emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/12/20 Documen Management Branch 1p 16606 334 24X Fiche 50-295.82/12/20, 8212290098
- --0212270105 Forwards public version of Revision 6 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director" Receipt form & procedure thange request form encl PLIML-0 Commonwealth Edision Co 82/11/24 BENTON, H R NRC - No Detailed Affiliation Given 2pp 16606 335 24x
- 8212790507 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch Ip 16593 349 24X Fiche 50-295,82/12/20, B212270509
- --8212290511 Forwards public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List" Procedure change request encl PLIML-0 Commonwealth Edison Co 82/11/24 BENTON, H R NRC - No Detailed Affiliation Given 2pp 16593 350 24X Fiche 50-295, 82/12/20,8212290509
- --8212270513 Public version of Revision 8 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List" * Commonwealth Edison Co 82/11/22 6pp 16593 352 24X Fiche 50-275.82/12/20.8212270507
- B212300167 Releases public version of revised generating station theorem of the state of the sta
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory MODRER D Commonwealth Edison Co 82/12/02 DENTON, H R OPPic of Nuclear Reactor Regulation. Director 1p 16612 216 24X Fichs 50-000, 82/12/20, 8218300167
- --8212300199 Public version of revised generating station emergency plan telephone directory GALLE.D P Componwealth Edison Co 82/11/05 & dopp 16612 21/ 24X Fiche 50-000,82/12/20.8212300167
- 8212290415 Forwards proposed agenda for 830104-05 site visit by security review committee re safeguards requirements KEPPLER. J 9 Region 3. Office of Director. 82/12/27 REED. C Commonwealth Edison Co. 2pp. 16587-099 24X Fiche 50-295,82/12/27,8212270415
- H General correspondence
- B212280176 Notifies of change in mailing address for NRC licensing mat! WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENMUT, D 0 Division of Licensing ip 14556 135 24% Fiche 50-000,82/12/20,8212280176

- P Operating license stage documents & correspondence
- B212070411 FDIA request for all records on embrittlement thermal shock, corrosion & cracking of reactor pressure vessel at facilities
 GUIGO,C Pollution & Environmental Problems, Inc. 82/10/18
 Division of Rules and Records in 16356 001 24X
 Fiche 50-275, 82/10/18, 8212070415
- 8P12070414 Responds to FOIA request for all records on embrittlement, thermal shock.corrosion & cracking of reactor pressure vessel at facility Records available at PDR FELTON.J M Division of Rules and Records 82/11/05 guigg.C Pollution & Environmental Problems. Inc 4pp 16356 002 24X Fiche 30-295,82/11/05,8212070414
- 89/12010452 Summary of 821115 mesting w/util re interim inservice testing program WigginYON.D L. Operating Reactors Branch I 82/11/19 Operating Reactors Branch I 4pp 16270 222 24X Fichs 50-295.82/11/19, 8212010452
- BP120600B6 Clarifies 820712 ltr re seismic design of auxiliary feeduater sys branch piping Piping criteria utilized for all LE Bulletin 77-14 work as documented in S&W Procedure ZPP-1 LENTINE.F 9 Commonwealth Edison Co 82/11/29 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 1p 16316 120 24X Fichs 50-295,82/11/29,82120600B6
- B:/12040217 Requests approval to delay implementation of due dates to accommodate current schedule requirements for Items II B 2. "Plant Shielding." II B.3. "Post-Accident Sampling." & II F 1. "Accident Monitoring Instrumentation "
 LENTINE.F G Commonwealth Edison Co 62/11/27 EIGENHUT.D G Division of Licensing 2pp 16313 190 24X Fiche 50-295,82/11/29,8212040219
- 8212060422 Forwards FR notice of receipt of 821011 request for action re licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement Request being treated per 10CFR2 206
 DENTON-R R Office of Nuclear Reactor Regulation, Director 82/11/30 GUIGO.C obsolete code ip 16343 308 24X Fiche 50-275,82/11/30,8212060422
- --8212060430 Notice of Pollution & Environ Problems. Inc 821011 request for action re licensee use of high burnup nuclear fuel & ability of facility reactor vessels to withstand embrittlement DENTON.H R Office of Nuclear Reactor Regulation, Director 82/11/30 p 16343 309 24X fiche 80-295.82/11/30,821204042?
- GP12070472 Forwards Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends revise Tech Specs to allow release of radioactive gas decay tank contents
 WIOOINTON, D Operating Reactors Branch 1 82/11/30 DELGEDRUE, t D Commonwealth Edison Co 3pp 16351 342 24X Fiche 50-295, 82/11/30, 8212070472
- --8212070478 Amends 78 & 48 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs to allow release of radioactive gas decay tank contents
 VAR6A: S A Operating Reactors Branch | 82/11/30 Bpp 14351 345 24X Fiche 50-295, 82/11/30,8212070472
- --B212070482 Notice of issuance & availability of Amends 78 & 68 to Licenses DPR-39 & DPR-48, respectively VARGA: S A Operating Reactors Branch 1 82/11/30 2pp 16351 353 24X Fiche 50-295, 82/11/30,8212070472
- 8212130231 Application to amend Licenses DPR-39 & DPR-48, changing Section 3 9 2 of Tech Specs to clarify operability requirements for containment penetration & weld channel pressurization sys

 LENTIME FO Commonwealth Edison Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16397 001 24X Fiche 50-295, 82/12/03, 8212130231
- --8212130236 Proposed changes to Section 3 9 2 of Tech Specs, clarifying operability requirements for containment penetration & weld channel pressurization sys
 * Commonwealth Edison Co 82/12/03 2pp 16397 003 24X
 Fiche 50-295, 82/12/03, 8212130231
- BF/12090004 Confirms emergency authorization to amend Licenses DPR-39 & DPR-49 on 821203 Amend revises penetration pressurization sys LAINAB, 9 C Assistant Director for Operating Reactors 82/12/06 DELGEORDEL 0 Commonwealth Edison Co 2pp 16379 357 24X Fiche 30-275,82/12/06,8212090006

- G212130035 Informs of add1 delay in implementation of offsite dose assessment portion of A-model Required radiation monitoring cys until be installed by B30215.per NUREG-0737.

 Items [I F i i t II F i 2

 LENTINE.F G Commonwealth Edison Co 62/12/07 DENTON.H R Offic of Nuclear Reactor Regulation. Director 2pp 16390 174 24X Fishe 50-295. 62/12/07. 8212130035
- G. OBI 90263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Ecience Applications, Inc. draft rept re subj requirements Comments requested within 30 days of itr Svc list encl EISENHUT, D. O. DIVISION of Licensing 82/12/09 Consolidated Edison Co. of New York, Inc. 29pp. 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- BP12140103 Generic Ltr 82-28 to all licensees of operating Hestinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & 8an Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl El8EKH/UT.D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10, 62/2140103
- GP:12150141 Forwards proprietary SER & technical evaluation rept,
 "Review or Licensee Resolution of Outstanding Issues From
 NRC Equipment Environ Qualification SERs (F-II, B-60) "
 Justification for continued operation due in 30 days
 VARGA.S A Operating Reactors Branch 1 82/12/14 DELGEORGE, L D
 Commonwealth Edison Co 2pp 16427 345 24X Fiche 50-295,82/12/14,
 (2212150141
- 821222012 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Cenerating Stations" SWARTZ.ED Commonwealth Edison Co 82/12/14 HAASS.W.P. Quality Absurance Branch ip 16518 007 24X Fiche 50-000,82/12/14. G212220212
- --8212220231 "QA Program for Nuclear Generating Stations," Revision 2d * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14.8212220212
- 6.):2220431 Comments on MRC alternative Tech Specs re auxiliary feeduater sys.prepared in response to util 791231 & 800312 submittals Proposed Tech Specs acceptable, w/exception of minor editorial changes noted in enc!

 i.ENTIFE; F 0 Commonwealth Edison Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 14503 311 24X Fisce 50-295, 82/12/15, 8212220431
- SP12220517 Forwards approved spent nuclear fuel route as requested in U20914 ltr SHERRITS Material Transfer Safeguards Licensing Branch 62/12/16 DANCSE:FL Nuclear Assurance Corp 2pp 16523 041 24X Fiche 50-295.82/12/16.8212220517
- --8212220520 "Spent Nuclear Fuel Route BMI, West Jefferson CH to Zion Nuclear Power Station. Zion IL " SHERR, T S Material Transfer Safeguards Licensing Branch 82/11/23 10pp 16523 043 24X Fiche 50-295,82/12/16,8212220017
- G212210369 Requests NRC concurrence or comments on revised schedule for implementation of fuel mgt program topical rept LENTINE, F 0 Commonwealth Edison Co 82/12/17 THOMAS, C D Standardization & Special Projects Branch 3pp 16494 275 24X Fiche 50-295.82/12/17.8212210369
- BP12290453 Forwards Amends 79 & 69 to Licenses DPR-39 & DPR-4B, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for penetration pressurisation sys to define operating conditions WIGGINTON.D.C. Operating Reactors Branch 1 B2/12/20 DELOCORGE.L.D. Commonwealth Edison Co. 2pp 16606 060 24X Fishe 50-275, 82/12/20.8212290453
- --8212270456 Amends 79 & 67 to Licenses DPR-37 & DPR-48, respectively, revising Tech Specs for penetration pressurisation sys to define conditions of operation, applicable modes & actions taken for inoperable sys VARGA. 5 A Operating Reactors Branch 1 82/12/20 7pp 16606 062 24X Fiche 50-275, 82/12/20.8212270453
- --B212270461 Safety evaluation supporting Amends 79 & 49 to Licenses DPR-39 & DPR-48, respectively * Office or Nuclear Reactor Regulation, Director 82/12/20 3pp 16606 069 24X Fiche 50-275,82/12/20,8212290453
- -92;2290464 Notice of issuance & availability of Amends 79 & 69 to Licenses DPR-39 & DPR-48.respectively VARGA.S A Operating Reactors Branch 1 82/12/20 2pp 16605 072 24X Fiche 50-295.82/12/20.8212290453

- 8712280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment SWARTZ, E D Commonwealth Edison Co 82/12/22 EISENHUT, D Q Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212
- O (inspection reports, IE Bulletins & correspondence
- 8:'08:90240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8:RF Plants " Svc list encl
 DEYOUNG, R C Director's Office, Defice of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24% Fiche 90-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list nc1 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50-000,82/11/05,8208170245
- 8212080282 Forwards IE Insp Repts 50-295/82-18 & 50-304/82-16 on 820830-0903 & 20-22 No noncompliance noted MILLER, J R Division of Engineering & Technical Programs 82/11/12 REED. C Commonwealth Edison Co 2pp 16354 186 24X Fiche 50-295, 82/11/12,8212080282
- --8212080296 IE Insp Repts 50-295/82-18 & 50-304/82-16 on B20830-0903 & 20-22 No noncompliance noted Major areas inspected compliance w/NUREG-0737.1 tem II F 1 3.ellegations forwarded by IL Dept of Nuclear Safety & radiation protection program MILLER, D E , PAUL, R A , GREGER, L R Division of Engineering & Technical Programs B2/11/10 15pp 16354 188 24X Fiche 50-295.82/11/12.8212080282
- BP08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 90-000, 82/11/18, 8208190251
- 6712060232 Forwards IE Safety Evaluation Repts 50-295/62-23 & 50-304/62-20 of emergency preparedness & SER HIND. J A Division of Emergency Preparedness & Operational Support 82/11/19 REED. C Commonwealth Edison Co Rpp 16312 201 24X Fiche 50-295, 82/11/19, 8212060232
- --8212060238 IE Safety Evaluation Repts 50-275/82-23 & 50-304/82-20 of emergency preparedness plan Emergency plan acceptable PHILLIPB; M P , AXELSON, W L , PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 82/11/18 ip 16312 203 244 Fichs 50-275, 82/11/19, 8212060232
- 8708190254 IE Info Notice 82-44, "Defective & Obsolete Combination Paglocks " 8vc list encl DEYCUND.R C Director's Office Office of Inspection and Enforcement B2/11/24 Consolidated Edison Co of New York, Inc 127pp 14411 065 24% Fiche 50-000.82/11/26.8208190254
- BP12060050 Summarizes 821103 meeting w/U5 Atty & law enforcement agencies in Chicago. IL re II Investigation Repts 50-299/801-32 & 50-309/81-30 & status of ongoing investigation ReptiseR. J 9 Region 3. Office of Director 82/11/29 JONES. 6 C Illinois, Blate of 2pp 16914-075 24X Fiche 50-275,82/11/29,1212040550
- 8POB190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safequards 82/11/30 Consolidated Edison Co of New York, Inc 35App 16387 028 24X Fichs 50-000,82/11/30,8208190257
- BPOB190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JDRDAN:EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,8208190261
- BP12170109 Forwards IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-27 & notice of violation NORELIUS, C E Division of Engineering & Technical Programs 82/12/03 REED, C Commonwealth Edison Co 2pp 16452 336 24X Fiche 50-295, 82/12/03, 8212170109

- --8212170114 Notice of violation from insp on 821025-29 NORELIUS.C E Division of Engineering & Technical Programs 82/12/03 2pp 16452 336 24x Fiche 50-295.82/12/03.8212170109
- --8212170121 IE Insp Repts 50-295/82-20 & 50-304/82-18 on 821025-29 Noncompliance noted form not used to track operator progress & current status of operator training Out-of-tolerance parameters & valve stroke times not recorded FARRELL,R E , HASSE,R A , PEBCHEL,J M Division of Engineering & Technical Programs 82/12/02 9ps 16452 340 24X Fiche 50-275,827(12/03.8212170109
- 8212130183 Forwards add1 info re IE Sulletim 80-11, "Masonry Walls."
 in response to NRC 821022 Itr Eighteen walls qualified
 using horizontal reinforcement
 LENTINE.F 0 Commonwealth Edison Co 82/12/08 EISENHUT.D G
 Division of Licensing 1899 16396 099 24X Fiche 50-295,82/12/08,
 6212130183
- 9212280058 Forwards IE Insp Repts 50-295/82-27 & 90-304/82-24 on 821115-19 No noncompliance noted MILLER.J R Division of Engineering & Tachnical Programs 82/12/10 REED, C Commonwealth Edison Co 2pp 16564 279 24% Fiche 50-295.82/12/10.8212280058
- --B212280062 IE Insp Repts 50-295/82-27 & 50-304/82-24 on 821115-19 No noncompliance noted Major areas inspected radwaste sys, including effluent release rates, records & repts, procedures for controlling releases & containment air cleaning sys MILLER, D E . GRANT, H B . GREOER, L R Division of Engineering & Technical Programs & 82/12/10 7pp 16364 281 24X Fiche 50-295,82/12/10.8212280058
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8212290389 Forwards IE Insp Repts 50-295/82-29 & 50-304/82-26 on 821115-16 No noncompliance moted LITTLE, W 8 Division of Engineering & Technical Programs 82/12/17 REED, C Commonwealth Edison Co 2pp 16586 296 24X Fiche 50-295,82/12/17,8212290389
- --8212270400 IE Insp Repts 50-295/82-29 & 50-304/82-25 on 821115-16 No noncompliance noted Major areas inspected actions in response to IE Bulletin 79-14. work procedure review & observation of work

 YIM, I T. DANIELSON, D. H. Division of Engineering & Technical Programs 82/12/10 opp 14586 298 24X Fiche 50-275,82/12/17,8212290389
- 8708190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000,82/12/20,8208190268
- R Periodic operating reports & related correspondence
- 82:12:40055 Forwards monthly operating repts for Nov 1982 ORACESER, K L Commonwealth Edison Co. 82/12/09 Director's Office, Office of Inspection and Enforcement ip 16408 270 24X Fiche 50-295:82/12/09,82:2140055
- --8212140061 Honthly operating repts for Nov 1982 AUSTIN, G Commonwealth Edison Co 82/12/07 lipp 16408 291 24X Fiche 50-295.82/12/09.8212140055
- DOCKET 50-309 KEMAUNEE NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- B212090257 Notifies of relocation of emergency operations facility Relocation satisfies requirements of NUREO-0694 Communications drill will be conducted prior to move OIESLER.C W. Wisconsin Public Service Corp. 82/11/29 ORIMES.B Division of Emergency Preparedness 1p 16363 244 24X Fiche 50-305.82/11/27,8212090257.
- 8212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility KEPPLER.J 0 Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp. 16503 351. 24X Fiche: 50-000, 82/12/16, 8212220306

- B212270003 Releases public version of revised radiological emergency response plan implementing procedure FELTON-J M Division of Rules and Records 82/12/16 Document Management Branch 1p 16551 276 24X Fiche 50-305,82/12/16, 8212270003
- --B212270007 Forwards public version of Revision A to Radiological Emergency Response Plan Implementing Procedure EP-ENV-68, "Site Access Facility Environ Sample Analysis Relocation" GIESLER.C W Wisconsin Public Service Corp. B2/12/09 DENTON, HR Office of Nuclear Reactor Regulation, Director ip 16531 277 24% Fiche 50-305,82/12/16,82(2270003
- --8212270010 Public version of Revision A to Radiological Emergency Response Plan Implementing Procedure EP-ENV-6B. "Site Access Facility Environ Sample Analysis Relocation " LUNA.C R Wisconsin Public Service Corp 82/11/24 9pp 16551 278 24X Fiche 50-305,82/12/16,8212270003
- 8212280230 Requests approval of proposed change to emergency plan refirst aid training requirements, clarifying Red Cross 3-yr refresher training schedule
 61ESLER.C W Wisconsin Public Service Corp 82/12/22 DENTON.H &
 Uffice of Nuclear Reactor Regulation, Director 2pp 16562 264
 24X Fiche 50-305, 82/12/22, 8212280230
- J Insurance & indemnity information
- 8P12030076 Forwards Endorsement 46 to MAELU Policy MF-71 & Endorsement 58 to NELIA Policy NF-204
 GIESLER: C W Wisconsin Public Service Corp 82/11/30 DINITZ. I Division of Engineering 3pp 16304 298 24X Fiche 50-305, 82/11/30,8212030076
- P Operating license stage documents & correspondence
- 82:2030267 Forwards request for addl info re SER on environ qualification of safety-related equipment & on SER Item 3 4 re temp. ressure & homidity conditions outside containment VARGA: S A Operating Reactors Branch 1 82/11/30 GIESLER.C W Wisconsin Public Service Corp 3pp 16316 346 24X Fiche 50-305,81/11/30.8212030267
- 8212160003 Forwards add1 info re environ qualification of safety-related electrical equipment installed per TMI action plan items Qualification documentation will be submitted by H30(17
 CIESLER.C W Washington Public Power Supply System 82/11/15
 VARGA.S A Operating Reactors Branch 1 605pp 16444 154 24X
 Fiche 50-305,82/11/15,8212160003
- 8212030342 Requests that licensee propose license conditions, similar to condition included in NRC 790801 ltr.re implementation of secondary water chemistry program, within 40 days VARGA.8 A Operating Reactors Branch 1 82/11/29 GIESLER, G W Wisconsin Public Service Corp 2pp 16316 163 24x Fiche 50-305,82/11/29,8212030342
- 9212070492 Forwards Amend 47 to License DPR-43, safety evaluation & notice of issuance & availability Amend revises Tach Specs to include revised table of contents & corrects typographical errors GROTENHUIS, M Operating Reactors Branch i 82/11/29 GIESLER. C W Wisconsin Public Service Corp 2pp 16351 305 24X Fiche 50-305, 82/11/29, 8212070492
- --8212070498 Amend 47 to License DPR-43, revising Tech Specs to include rearrangement of table of contents & correcting typographical errors VAROA. S.A. Operating Reactors Branch 1 82/11/29 29pp 16351 307 24X Fiche 50-305
- --8212070501 Safety evaluation supporting Amend 47 to License DPR-43 * Office of Nuclear Reactor Regulation, Director 62/11/29 4pp 16351 336 24% Fiche 50-305.82/11/29.8212070492
- ---B212070504 Notice of issuance & availability of Amend 47 to Licente DPR-43 VAROA,S A Operating Reactors Branch 1 B2/11/29 2pp 16351 340 24% Fiche 50-305, B2/11/29, B212070492
- 80:12070149 Forwards status rept on NUREO-0737. Items II B 3, "Post-Accident Sampling." II B 4, "Training for Mitigating Core Damage" & II F 1, "Noble Gas Effluent Monitor" & "Sampling & Analysis of Plant Effluents "
 OIESLER.C U Wisconsin Public Service Corp 82/11/30
 EISENWINT, D 0 Division of Licensing Spp 16327 080 24X
 Fiche 50-305.82/11/30.8212070149

- G2120B0026 Ack receipt of G11217 Itr re application fees for review of adequacy of station electrical distribution sys voltages Voltages relate to proposed Amend 29 No fees due MILLER.W D. License Fee Management Branch B2/11/30 GIESLER.C W Wisconsin Public Service Corp. Ip 16367 164 24X Fishe 50-305, 82/11/30. B2120B0026
- 8212070333 Anticipates submittal of proposed Amend 51 to Tech Specs revising item re RCS leakage, before 821228
 01ESLER&C W Wisconsin Public Service Corp 82/12/02 VARGA, S A Operating Reactors Branch 1 1p 16339 009 24X
 Fiche 50-305, 82/12/02, 8212070333
- Bi:12140407 Submits results of evaluation of need to provide around-the-clock chemistry coverage by radiological chemistry technologist Commitment to provide coverage, made in 810910 ltr.retracted GIESLER.C W. Wisconsin Public Service Corp. 82/12/08 EISEMHJT.D O. Division of Licensing Spp. 16403 333 24X Fiche 50-305, 82/12/08, 8212140407
- B20B190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of itr Svc list enci EISCHHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 6:12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Gnofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISERHUT, D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 82/12/40103
- B3:12140143 Corrects typographical error in 82:123 ltr re NUREG-0/37, Item III D 3 4, "Gontrol Room Habitability " Physical mods espected to be completed by June 1983 GIESLER.C W Wisconsin Public Service Corp 82/12/10 EISENHUT.D O Division of Licensing ip 16408 180 24X Fithe 50-305, 82/12/10.8212:40143
- B:12210181 Advises that info to ECCS models incorporating upper plenum injection.per 821101 request, will be submitted no later than G30215 GISSLER.C U Wisconsin Public Service Corp 82/12/15 VARGA.S A Operating Reactors Branch 1 1p 14484 338 24% Liche 50-305, 82/12/15, 8212210181
- BE12270197 Application to amend License DPR-43, revising Tech Specs re limiting conditions for operation, surveillance requirements & administrative controls GIESLER, C.W. Wisconsin Public Service Corp. 82/12/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. App. 16535–155 24X Fiche 50-305, 82/12/20, 8212270197
- --8212270203 Proposed Tech Spec changes re limiting conditions for operation, surveillance requirements & administrative controls

 * Ulsconsin Public Service Corp 82/12/20 24pp 16535 161 24% Fiche 50-305.82/12/20,8212270197
- 9212280193 Provides accuracy & time response info on NUREG-0737. Items If F 1 4.5 & 6 re wide-range containment pressure monitoring sys. sump water level sys & placement of hydrogen monitoring sys of ICSLER, C W Wisconsin Public Service Corp 82/12/22 VARGA, S A Operating Reactors Branch I 2pp 14562 OBB 24X Fiche 50-305, 82/12/22, 8212280193
- 82:12280318 Discusses NUREO-0737 items to be incorporated in revisions to Tech Specs, per Generic Ltr 82-16 & util 82:1220 ltr GIESLER.C W Misconsin Public Service Corp 82:712/23 EISENHUT.D O Division of Licensing 4pp 16:362 073 24% Fiche 50-305, 82:712/23, 82:12260318
- BP12280467 Forwards "Control of Heavy Loads," 6-month response to Generic Ltr B1-07.NUREG-0612 Response to Section 2.2 through 2.4 scheduled to be submitted by B30215 GIESLER.C W. Wisconsin Public Service Corp. B2/12/23 E1SEHHUT, D.G. Division of Licensing 2pp 16556 179 24x Fiche 50-303, 82/12/28, 8212280447
- --9212280473 "Cantrol of Heavy Loads." 6-month response to Generic Ltr 81-07.NURED-0612 * Wisconsin Public Service Corp 82/12/23 68pp 16556 181 24% Fiche 50-305.82/12/23.8212280467

- @ Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl
 DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters" Syc list circl
 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,8208190245
- 8708190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JGRDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24X fiche 50-000, 82/11/18/8208190251
- BP12100141 Forwards IE Insp Rept 50-305/82-18 on 820901-1031 & notice of violation
 SPESSARD,R L Division of Project & Resident Programs 82/11/23 GIEBLER,C W Wisconsin Public Service Corp 2pp 16376 020 24X Fiche 50-305.821/1/23.8212100141
- --8212100144 Notice of violation from insp on 820901-1031 SPESBARD.R L Division of Project & Resident Programs 82/11/23 1p 16376 022 24% Fiche 50-305.82/11/23.8212100141
- --B212100149 IE Insp Rept 50-305/82-18 on 820901-1031 Noncompliance noted failure to perform required surveillance for radiation monitoring channels R-11 & R-12 NELSON: R L , REYES, R A Division of Project & Resident Programs 82/11/23 App 16376 023 24X Fiche 50-305,82/11/23,8212100141
- 8208190256 IE Info Notice 82~46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127p 16411 065 24X Fiche 50-000.82/11/26.8208190256
- BP12040044 Ack receipt of B21112 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-305/82-13
 STREETER: JF Division of Project & Resident Programs 82/11/26
 GIESLER: C W Misconsin Public Service Corp 1p 16313 202 24X
 Fiche 50-305, 82/11/26, 8212040044
- --8212050049 Responds to NRC 821013 ltr reviolations noted in IE Insp Rept 50-305/82-13 Corrective actions duplicate file will be established to assure that documentation of memos will be established GIESLER.C W Wisconsin Public Service Corp 82/11/12 SPE88ARD.R L Division of Project & Resident Programs 2pp 16313 203 24X Fiche 50-305, 82/11/26.8212060044
- 8E0B190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mat1 " Svc list enc] COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 354pp 14387 028 24X Fiche 50-000, 82/11/30, 8208190257
- B208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Llectrical Penetration Assemblies " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259
- 8708190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp. 16462 064 24X Fiche 50-000, 82/12/03,8208190261
- SP12270334 Forwards IE Insp Rept 50-305/82-22 on 821110-12 No noncompliance noted LITTLE.W S Division of Engineering & Technical Programs 82/12/10 GIESLER.C W Misconsin Public Service Corp 2pp 16530 037 24X Fiche 50-305, 82/12/10, 8212270334
- --8212270339 IE Insp Rept 50-305/82-22 on 821110-12 No noncompliance noted Major areas inspected followup on previous insp findings & review of non-licenses personnel training & licensed personnel requalification programs

 HASSE, R A , HAWKINS, F C Region 3, Office of Director 82/12/08 5pp 16530 039, 24% Fiche 80-305,82/12/10/8212270334

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24x Fiche 50-000 82/12/20.8208190268
- R Periodic operating reports & related correspondence
- 8P12290211 Forwards monthly operating rept for Oct 1982 GIESLER.C W Misconsin Public Service Copp 82/11/09 Management Information Branch 1p 16578 135 24X Ficha 50-305.82/11/09. B218290211
- --B2:2270216 Monthly operating rept for Oct 1782
 RUITER, G H Wisconsin Public Service Corp 82/11/01 4pp
 16578 136 24X Fiche 50-305, 82/11/09, 82:2270211
- S Reportable occurrences. LERs & related correspondence
- 8212060090 Lists correct LER numbers for cover ltrs transmitting repts GIEGLER.C W Wisconsin Public Service Corp B2/11/24 KEPPLER, J G Region 3: Office of Director ip 16316 078 24X Fiche 50-308.82/11/24.8212060090
- GP12170167 Forwards LER 92-034/03L-0 GIESLER.C N Hisconsin Public Service Corp 82/12/10 KEPPLER, J G Region 3. Office of Director 1p 16462 028 24X Fiche 50-305.82/12/10.8212170167
- --8212170171 LER 82-034/03L-0 on 821111, valve MS-100A, main steam to turbine driven auxiliary feedwater pump, torqued out when closing Caused by torque switch sticking & manual de-clutch unit out of adjustment Switch & tripper assembly replaced BERNHOFT. S L Wisconsin Public Service Corp 82/12/10 Region 3, Office of Director 1p 16462 029 24X Fishe 50-305,82/12/10,8212/170167
- DBCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8212030134 Forwards IE Insp Repts 50-282/82-17 & 50-306/82-17 pn 820921-1031 No noncompliance noted STREETER, J F Division of Project & Resident Programs 82/11/17 LARSCM C E Northern States Power Co 2pp 16304 031 24X Fiche 50-282,82/11/17,8212030134
- --B212030150 IE Insp Repts 50-282/82-17 & 50-306/82-17 on B20921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills & exercises, operations safety verification, followup on fuel oil spill & followup on LERs FEIERABEND. C. D. Division of Project & Resident Programs B2/11/17 Bpp 16306 033 24X Fiche 50-282, 82/11/17, 8212030134
- 8212210329 Forwards IE Insp Repts 50~282/82-16 & 50~306/82~16 on B21013-15 & 1109 No noncompliance noted HIND, J A Division of Emergency Preparedness & Operational Support 82/12/02 LARBON, C E Northern States Power Co 3pp 16496 229 24X Fiche 50~282,82/12/02. 8212210329
- 8212210340 IE Insp Repts 50-282/82-18 & 50-305/82-18 on 821013-15 & 1107 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr PATTERSON-JP , PAPERIELLD.C J Division of Emergency Preparedness & Operational Support 827/82/01 12pp 16496-232 24X Fiche 50-282,82/12/02,8212210329
- 8212140279 Requests exemption under 10CFR50 4B(c)(b), from automatic suppression requirement of App R.Section III 0 3 for control room MUSDLF, D. Northern States Power Co. 82/12/06 Office of Nuclear Reactor Regulation, Director . 3pp 16402 104 24X Fiche 30~282,82/12/06,8212140279
- 8P12220045 Advises that 820520 & O823 exemption requests granted extending deadline for installation of emergency lighting until 830101 Add time needed to complete engineering analysis-procurement & installation EISENHUT. D 0 Division of Licensing 82/12/08 MUSGLF, D M Northern States Power Co 4pp 16526 355. 24x Fiche 50-282.82/12/08,8212220045

- --8212220048 Exemption granting extension for installation of emergency lighting until 830101 DENTON-H R Office of Nuclear Reactor Regulation. Director 82/12/08 Northern States Power Co 7pp 16526 359 24X Fichs 50-282, 82/12/08, 8212220045
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPPLER.J O Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24% Fiche 50-000,82/12/16,8312203036
- 8212300412 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 075 24X Fiche 50-282,82/12/22, R312300412
- --8212300416 Forwards public version of revised Emergency Plan Implementing Procedures F3-5 re emergency notifications, F3-10 re personnel accountability & F3-23 re emergency sampling WARD, EC Northern States Power Co 82/12/15 Region 3, Office of Director ip 16613 076 24X Fiche 50-282,82/12/22,8212300412
- --8212300417 Public version of Emergency Plan Implementing Procedures F3-5 re emergency notifications.F3-10 re personnel accountability & F3-23 re emergency sampling SCHUELKE,D A Northern States Power Co 62/11/04 102pp 16613 077 24X Fiche 50-282,82/12/22,8212300412
- P Operating license stage documents & correspondence
- G212070057 Forwards Revision 1 to 750847 license amend request to change Tech Specs no containment leakage rate testing, incorporating required changes No fee appropriate since request submitted earlier MUSDLF, D. Northern States Power Co. 82/12/03. Office of Nuclear Reactor Regulation. Director 1p. 16359-041. 24X Fiche 50-282, 82/12/03.8212090057
- --8212090057 Revision 1 to 750807 license amend request to change Tech Spec re containment leakage rate testing MUSGLF,D Northern States Power Co 82/12/03 20pp 16359 042 24X Fiche 50-282, 82/12/03, 8212090057
- GP12090172 Forwards addl info re methods of compliance w/NUREG-0/37. Item II B 3 on post-accident sampling sys.in response to 820908 request MUSQLF.D Northern States Power Co 82/12/03 Office of Nuclean Reactor Regulation, Director 11pp 16399 221 24X Fiche 50-282, 82/12/03, 8212090172
- B208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl CISENHUT.D Q Division of Licensing 62/12/09 Consolidated Edison Co of New York. Inc 27pp 16627 247 24X Fiche 50-000, 82/12/09, 8208190263
- B212140411 Forwards summary of NRC review of Exxon Nuclear Co thermal hydraulic methodology for mixed cores in PWRs Enci TOPROD sensitivity & thermal margin studies submitted on 820418 & 29, respectively, remain valid Comments requested CODKE.9 C Exxon Nuclear Co. Inc (subs of Exxon Corp.) 82/12/09 HOLDMICH.J J Core Performance Branch 7pp. 164/03 322 P4X Fiche 50-282/82/12/09,6212140411
- 8212140103 Generic Ltr 82-28 to all licenses of operating
 Hestinghouse & C-E PWRs (except Arkansus Nuclear One, Unit 2
 & Ban Onofre 2 & 3) re inadequate core cooling
 instrumentation sys Svc list encl
 EISENHUT.D 0 Division of Licensing 82/12/10 Yankee Atomic
 Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,
 8221240103
- 8212170262 Responds to 821104 request for ECCS model, specifically treating upper plenum injection Exxon model will be ready for submittal by 830131 MUSGLF.D Northern States Power Co 82/12/10 Office of Nuclear Reactor Regulation, Director ip 16456 207 24X Fiche 50-282,82/12/10,8212170262
- 8212210290 Forwards NSPNAD-BIOIP, Revision i, "Qualification of Reactor Physics Methods for Application to Prairie Island Units," & NSPNAD-BIO2P, Revision i, "Reload Safety Evaluation Methods for Application " Repts withheld (ref 10GFR2 790) MUSULF, D. Northern States Power Co. 82/12/13 Office of Nuclear Reactor Regulation, Director ip 16497 134 24X Fiche 50-282, 82/12/13, 8212210290

- O Inspection reports: IE Bulletins & correspondence
- 820B190240 IE Bullstin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8MR Plants " Syc list encl
 - DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000,82/10/28,8208190240
- 82:08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 b Model 802 Thermoluminescent Dosimeters " Svc list
 - CO88.L J Division of Fuel Facilities, Materials & Safeguards E2/11/05 Consolidated Edison Co of New York, Inc 110pp 16:372 142 24X Fiche 50-000.82/11/05,8208190245
- 8212030134 Forwards IE Insp Repts 50-282/82~17 & 50-304/82-17 on 820921-1031 No noncompliance noted STREETER.JF Division of Project & Resident Programs 82/11/17 LARSON C E Northern States Power Co 2pp 16306 031 24X Fishe 50-282, 82/11/17, 8212030134
- --B2)2030150 IE Insp Repts 50-282/82-17 % 50-306/82-17 on 820921-1031 No noncompliance noted Major areas inspected preparation for refueling, fire drills % exercises, operations safety verification, followup on fuel oil spill & followup on LERs FEIERABEND, C D , REVES. L Division of Project & Resident Programs 82/11/17 8pp 16306 033 24X Fiche 50-282,82/11/17,8218030134
- 8:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN: E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York: Inc. 109pp 16411 199 24X Fiche 50-000. 82/11/18.8208190251
- G.'OB170256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection, and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.B2/11/26.B208170256
- 9208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/30 Cansolidated Edison Co of New York. Inc 356pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- 8212210329 Forwards IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1109 No noncompliance noted IIND, J A Division of Emergency Preparedness & Operational Support 82/12/02 LARSON, C E Northern States Power Co 3pp 16496 229 24X Fiche 50-282,82/12/02.8212210329
- --8212210340 IE Insp Repts 50-282/82-18 & 50-306/82-18 on 821013-15 & 1107 No noncompliance noted Major areas inspected emergency exercise, especially command & control of control room, technical support ctr & operations support ctr PATTERSON, J P , LICKUS, R M , AXELSON, W L Division of Emergency Preparedness & Operational Support 82/12/01 12pp 16496 237 24% Fiche 50-282/82/12/02/8212210329
- 8.'08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Floctrical Penetration Assemblies " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl
 JCRDAN.E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x
 Fiche 50-000, 82/12/03, 8208190261
- 6:12270292 Forwards IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821126 No noncompliance noted LITTLE.W S Division of Engineering & Technical Programs 82/12/10 LARSON,C E Northern States Power Co 2pp 14530 122 24X Fiche 50-282, 82/12/10, 8212270272
- --0212270305 IE Insp Repts 50-282/82-19 & 50-306/82-19 on 821124 No noncompliance noted Major areas inspected review of inservice insp procedures.NDE personnel certifications & data & IE Bulletin 78-12 activities WARD.K D , DANIELSON.D N Region 3. Office of Director 4pp 16530 124 24X Fiche 50-282.82/12/10,8212270292
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc E27pp 16628 191 24X Fiche 50-000.82/12/16:8208190267

- 8212280325 Responds to IE Bulletin 82-04 No electrical penetration assemblies referenced in bulletin in use or planned for use in safety-related sys LARSON,C E Northern States Power Co 82/12/17 KEPPLER,J 9 Region 3, Office of Director 1p 16562 087 24X Fiche 80-282,82/12/17,8212280325
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 62/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 29J 24y Fiche 50-000, 82/12/20,8208190268
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

 F Security, medical, emergency & fire protection plans
- 8212140435 Forwards "1982 ME Yankee Nuclear Power Station Emergency Response Exercise & Evaluation Plan." detailing scenario & evaluation criteria for 821211 emergency plan exercise GARRITY.J H Maine Yankee Atomic Power Co 82/11/24 HAYNES.R C Region 1. Office of Director 2pp 16405 258 24X Fiche 50-309.82/11/24.8212140435
- ---8212140442 "1982 ME Yankee Nuclear Power Station Emergency Response Exercise & Evaluation Plan " # Maine Yankee Atomic Power Co 82/12/31 192pp 16405 260 24% Fiche 50-309,82/11/24.8212140435
- --8212140453 Forwards util & State of ME objectives for 821211 emergency plan exercise GARRIY. J H Maine Yankee Atomic Power Co 82/09/28 HAYNES.R C Region 1. Defice of Director 5pp 16404 350 24X Fiche 50-309.82/11/24.8212140435
- 8212030291 Releases public version of revision to emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/11/30 Document Management Branch 1p 16322 231 24X Fiche 50-309,82/11/30, 8212030291
- --G212030304 Public version of Revision 2 to Emergency Plan Implementing Procedure 2 50 7. "Emergency Onsite Radiation Monitoring Procedure " Index of Series 250 procedures encl * Maine Yankee Atomic Power Co 82/11/20 33pp 16322 233 24X Fiche 50-309,82/11/30.8212030291
- BP12150159 Forwards IE Insp Rept 50-309/82-16 on B20824-1005 & notice of violation STARDSTECKI, R Division of Project & Resident Programs 82/12/02 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16430 165 24X Fiche 50-309,82/12/02.8212150159
- --8212150169 IE Insp Rept 50-309/82-14 on 820824-1005 Noncompliance noted failure to review & update written Class A procedures for new fuel insp within 2 yr period SMETLAND, P. (ARLUN, B. Division of Project & Resident Programs 82/11/18 14pp 16430 168 24X Fiche 50-309,82/12/02,8212150159
- 8212210349 Forwards IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/12/06 RANDAZZA, J B Maine Vankee Atomic Power Co ' 2pp 16495 163 24x Fiche 50-309,82/12/06,8212210349
- --8212210351 IE Safeguards Insp Rept 50-309/82-20 on 821025-28 No noncompilance noted Major areas inspected security plan & implementing procedures, security organization, security program audit & records Safeguards info deleted MADDEN, W., ODDY, AT Region I. Office of Director 82/12/03 4pp 16495 165 24X Fiche 30-309,82/12/06.8212210349
- 8212270025 Forwards request for addl info to complete review of App R fire protection & safe shutdown Plant manager should be contacted within 10 days of receipt of itr to arrange suitable meeting CLARK, R A Operating Reactors Branch 3 82/12/08 GARRITY, J Naine Yankee Atomic Power Co 6pp 16551 336 24X Fiche 50-309, 82/12/08.8212270025

- 6912160751 Summarizes status of reactor coolant pump lube oil fire eremption request & containment leak testing Meeting requested
 CLARK, R A Operating Reactors Branch 3 82/12/10 GARRITY, J H
 - Cannon o operating reactors Branch 3 82/12/10 Maine Yantee Atonic Power Co 3pp 16465 357 24X Fichs 50-309, 82/12/10, 8212140751
- GP12230046 Releases public version of revised emergency plan implementing procedures FELTON-J M Division of Rules and Records 62/12/15 Docum Management Branch 1p 16545 110 24% Fiche 50-309,82/12/15,
- ~-8212230057 Forwards public version of revised emergency plan implementing procedures, including Procedure 2 50 0 re declaration & catagorization of emergency condition 5 2 50 5 re energency plan training & exercise

 * Maine Yankee Atonic Power Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16545 111 24X
 Fiche 50-309, 82/12/15.8212230046
- --0212230068 Public version of revised emergency plan implementing procedures, including Procedures 2 50 0 re declaration & categorisation of emergency condition & 2 50 5 re emergency plan training & exercise

 * Maine Yankee Atomic Power Co 82.
 24(Fiche 50-309, 82/12/15, 82/12/30046 82/12/04 104pp 16545 113
- 82:12210308 Updates plans for upgraded emergency response facilities Primary emergency operations facility & technical support ctr will be relocated to new staff bldg per NUREO-0596 final design criteria not yet established GARRITY.J H Maine Yankee Atomic Power Co 82/12/16 HEITNEH, K Uperating Reactors Branch 3 2pp 16497 107 24X Liche 50-309.82/12/16.8212210308
- BF:12210344 Provides add1 info to better prepare util shift crews for types or questions NRC duty officer may ask during telephone repts via NRC emergency notification sys Revised event notification form (Parts I & II) encl
 STAROSTECKI, R Division of Project & Resident Programs 82/I2/16
 RANDATZAJ B Maine Yankee Atomic Power Co App 16496 328 24:
 Fiche 50-309,82/12/16,8212210344
- G Adjudicatory correspondence
- GF12060042 Ack receipt of 821020 request for issuance of order to show cause they license should not be revoked or suspended, submitted on behalf of Safe Power for ME Request will be treated as petition under 10CFR2 206
 DENTON-H R Office of Nucloar Reactor Regulation, Director 82/11/30 MURRAY, P.L. Hurray, Plumb & Murray ip 16343 221 24) 82/11/30 MURRAY.P L Hurray, Plumb & Murray Fiche 50-309,82/11/30,8212060042 1p 16343 221 249
- ---9212060046 Notice of Safe Power for HE 821020 request under 10CFR2 206 for issuance of order to show cause why license should not be suspended or revoked DENTON-HR Office of Nuclear Reactor Regulation, Director 92/11/30
- P Operating license stage documents & correspondence
- GE:12010334 Forwards safety eviauation & EO&C technical evaluation on degraded grid protection for Class IE power sys Plant operating procedures, design details & Tech Specs to cover relay setpoint & time delay requested within 120 days CLARK.R A Operating Reactors Branch 3 82/11/12 GARRITY, J H Maine Yankee Atomic Power Co 3pp 16271 296 24X Fiche 50-309.82/11/12.8212010334
- --B212010335 Safety evaluation supporting licenses proposed Level 2 ### 2010-35 Safety evaluation supporting ilensee graposed Ley degraded voltage design providing automatic separation of Class IE power sys from offsite sys if degraded grid exists tointident u/safety injection sys Addi info required PREVATTER NRC ~ No Detailed Affiliation Given 82/11/12 16271 299 24X Fiche 50-309, 82/11/12,8212010334 82/11/12 App
- B212010417 Advises that requirements of NUREO-0737.TMI Action Plan Items I A 2 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training," & II B 4 I, "Training for Mitigating Core Damage:" has been met CLARK.R A Operating Reactors Branch 3 82/11/18 GARRITY, J H Maine Yahize Atomic Power Co 2pp 16267 341 24X Fiche 50-309.82/11/18.8212010417
- --B212010422 Safety evaluation re implementation of NUREO-0737, TM1 Action Items I A Z 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training." & II B 4 1, "Training for Mitigating Core Damage "Items met W1001KS.J T Operating Reactors Branch 3 82/11/18 2pp 16267 343. 24X Fiche 50-307, B2/11/18, B212010417

- --8212010427 "Improvements In Training & Requalification Programs As Required by TMI Action Items 1 A 2 1 & II B 4." technical evaluation rept * Science Applications, Inc. SAI-186-029-23 82/08/17 NRC No Detailed Affiliation Civen 14pp 16267 345 24X Fiche 50-309,82/11/18,8212010417 NRC ~
- 8212070454 Forwards questions re instrumentation & control concerns for feedwater trip sys design Meeting to discuss responses should be arranged within 30 days CLARKIR A Operating Reactors Branch 3 82/11/24 GARRITY, J H 24 GARRITY, J H 24X CLARK.R.A. Operating Reactors Branch 3 82/11/24 Maine Yankee Atomic Power Co. 4pp. 16395-325 241 Fiche 50-309, 82/11/24, 8212070454
- 8212130092 Forwards Amend &B to License DPR-34, safety evaluation & notice of issuance & availability Amend revises Tech Specs to support operation of plant at full rated power during Cycle 7 CLARK.R A Decrating Reactors Branch 3 82/11/29 GARRITY, J H Haine Yanke Atomic Power Co 4pp 16417 072 24X Fiche 50-309, 82/11/29, 8212130092 CLARK, R A
- --8212130095 Amend 48 to License DPR-34, revising Tech Specs to support operation of plant at full rated power during Cycle 7 CLARK, R A Operating Reactors Branch 3 82/11/29 31pp 14417 076 24X Ficbe 50-309, 82/11/29, 8212130092
- --8212130099 Safety evaluation supporting Amend 68 to License DPR-36 * Orfice of Nuclear Reactor Regulation, Director 82/11/29 40pp 16417 107 24X Fiche 50-309,82/11/29,8212130092
- --8212130102 Notice of issuance & availability of Amend 68 to Planautor Notice of Association | Communication | Communicatii | Communication | Communication | Communication | Communication 82/11/29 2pp
- 8212060042 Ack receipt of 821020 request for issuance of order to show cause why license should not be revoked or suspanded, submitted on behalf of Safe Power for ME Request will be treated as petition under 10CFR2 206
 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/11/30 MURRAY.P L Murray, Plumb & Murray Ip 16343 221 24) Fiche 50-309, 82/11/30, 8212060042 241
- --8212060046 Notice of Safe Power for ME 821020 request under 10CFR2 206 for issuance of order to show cause why license should not be suspended or revoked DENTON.H R Office of Nuclear Reactor Regulation, Director 82/11/30 1p 16343 222 24X Fiche 50-309,82/11/30,8212040042
- G212060259 Forwards updates on selected TMI action items per Generic Ltrs G2-05 & G2-10, "Post-TMI Requirements " TMI Action Items II B 2. II B 3. II E 1 2. II F 1. II D 1 2. II D 1 3 & Tites it Berli Buric I ett Firt, DI ett DI Ge Jil D 34 discussed GARRIYV.J H Maine Yankoe Atomic Power Co 82/11/30 CLARK.R A Operating Roactors Branch 3 3pp 16312 269 24X Fiche 50-309, 82/11/30, 8212060259
- 8212150229 Forwards interim position on radiation environs for environ qualification of safety-related electrical equipment open issues Response requested in 30 days
 CLARK, R. A. Operating Reactors Branch 2 82/12/06 GARRITY, J. H. Maine Yankee Atomic Power Co. 3pp. 16437 358 24X
 Fiche 50-309, 82/12/06, 8212150229
- 8212100266 Provides addl info supplementing 810918 & 820827 ltrs to clarify items discussed during 821027 telcon re control of heavy loads GARRITY.J H Maine Yankee Atomic Power Co 82/12/07 CLARK.R A Operating Reactors Branch 3 2pp 16376 137 24X Ficher 10-309.82/12/07.8212100266
- 8212130324 Advises that training program re pressurized thermal shock will not be revised Training program fulfills intent of post-TMI Action Item 1 C 5
 GARRITY, J H Maine Yankee Atomic Power Co 82/12/08 CLARK: R A Operating Reactors Branch 3 2pp 16389 268 24X
 Fiche 50-309.82/12/08.8212130324
- 8212140204 Provides recommendations to improve control room habitability, per NUREO-0737, Item III D 3 4 Redundant dampers not necessary to ensure habitability OARRITYJ H Maine Yankee Atomic Power Co 82/12/OR CLARK, R A Operating Reactors Branch 3 3pp 16409 341 24X Fiche 50-307, 82/12/08, 8212140204
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam RUBINOZOJ Generic Lit 82-32 to all PWR licensees re potent: generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of lit Svc list encl EISENHUT, D 0 Division of Licensing 82/12/09 Consol Edison Co of New York: Inc 27pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263. Consolidated

- 82:2140103 Generic Ltr 82-28 to all licensess of operating
 Mestinghouse & C-E PRRs (except Arkansas Nuclear One,Unit 2
 & San Qnofre 2 & 3) re inadequate core cooling
 instrumentation sys Svc list encl
 EISENNUT, 0 0 Division of Licensing 62/12/10 Yankee Atomic
 Electric to 27pp 16670 035 24X Fishe 50-000,82/12/10,
 62/12/40103
- 8212160751 Summarizes status of reactor coolant pump lube oil fire exemption request & containment leak testing Meeting requested CLARK/R A Operating Reactors Branch 3 82/12/10 GARRITY, J H Maine Yankee Atomic Power Co 3pp 16465 357 24X Fiche 50-309.82/12/10.8212160751
- Q Inspection reports: IE Bulletins & correspondence
- B2:08190240 | E Builetin B2-03, Revision 1. "Stress Cracking in Thick-Wall: Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement B2/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fichs 50-000, 82/10/28, 8208190240
- B20B170245 IE Info Notice 82-42. "Defects Observed in Panasonic Model B01 & Model 802 Thermoluminescent Dosimeters " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000 B2/11/05.8208190245
- 8P08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000,82/11/18,8208190251
- BP12060215 Forwards IE Insp Rept 50-309/82-21 on 821025-27 No noncompliance noted HARTIN, T T Division of Engineering & Technical Programs 82/11/22 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16312 029 24X Fiche 50-309
- --8212050217 IE Insp Rept 50-309/82-21 on 821025-27 No noncompliance noted Major areas inspected inservice insp program KERCH.H. DURR.J Region 1. Office of Director 82/11/19 3pp 16312 031 24X Fiche 50-309.82/11/22.8212060215
- G212070144 Forwards IE Insp Rept 50-309/82-18 on 620927-1001 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 62/11/23 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16327 043 24X Fiche 50-309,82/11/23,8212070144
- --8212070148 IE Insp Rept 50-309/82-18 on 820927-1001 No noncompliance noted Major areas inspected procedure review, test witnessing & results evaluation of local leak rate test & integrated leak rate test & facility tours
 PULLANI, S V, BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/12 9pp 16327 045 24X Fiche 50-309,82/11/23,8212070144
- B20B170256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks "Svc list encl DEYOUNG,R C Director's Office Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208170257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York. Inc 354pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- B212150159 Forwards IE Insp Rept 50-309/82-16 on 820824-1005 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/12/02 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 16430 165 24X Fiche 50-309, 82/12/02, 8212150159
- ---B212150163 Notice of violation from insp on 820824-1005 * Division of Project & Resident Programs 82/12/02 1p 16430 167 24X Fiche 50-307,82/12/02,8212150157
- --8212150169 IE Insp Rept 50-309/82-16 on 820824-1005 Noncompliance noted failure to review & update written Class A procedures for new fuel insp within 2 yr period SHETLAND,P. GALLO,R. Division of Project & Resident Programs 82/11/18 14pp 16430 168 24X Fiche 50-309,82/12/02,8212150159

- BROB190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Liectrical Penetration Assemblies "Svc list encl DEVOUNG,R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sackets " Svc list enct JURDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24x Fiche 50-000, 82/12/03,8208190261
- G212210349 Forwards IE Safeguards Insp Rept 50-309/82-20 on 621025-28 No noncompliance noted MARTIN T Division of Engineering & Technical Programs 82/12/02 RANDAZZA, J G Maine Yankee Atomic Power Co 2pp 16495 163 24, F(che 50-309, 82/12/03, 8212210349
- --8212210351 IE Safaguards Insp Rept 50-309/82-20 on 821025-28 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization, security program audit & records Safeguards info deleted MADDELLW . GDDY.A 7 Region L. Defice of Director 82/12/03 4pp 16499 165 24X Fiche 50-309,82/12/06.8212210349
- 82)12210263 Ack receipt of 821108 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-11
 MARTIN.T T Division of Engineering & Technical Programs 82/12/13
 RANDAIZA, J B Maine Yankee Atomic Power Co 1p 16483 254 24X
 Fiche 50-309, 82/12/13,8212210263
- --B212210266 Responds to NRC 821007 ltr re violations noted in 1E Insp. Rept 50-309/82-11 Corrective actions site inventory of all sources & detectors involving SNM completed & discrepancies identified RANDAZZA.J B Maine Yankee Atomic Power Co 62/11/08 HAYNES.R C Region 1. Office of Director 3pp 16483 255 24X Fiche 50-309,82/12/13,8212210263
- 82:08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVQUNO.R C Director's Office of Pfice of Inspection and Enforcement 82:12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- G212220430 Forwards NUREG-0903 containing results of interviews reduced by alcohol abuse & rehabilitation programs per IE Info Notice 92-05 Util util be contacted shortly to arrange similar interviews W/o NUREG STAROSTECKIR Division of Project & Resident Programs 82/12/16 RANDAZAJ B Maine Yankee Atomic Power Co 3pp 16503 307 24X Fiche 50-309, 82/12/16 8212220430
- 8212220386 Ack receipt of 820727, 28.29 % 1124 1trs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-309782-26 BTARGSTECKI,R Division of Project & Resident Programs 82/12/17 RANDAZZA:J B Maine Yankes Atomic Power Co 1p 16517 239 247 Fiche 50-307, 82/12/17.8212220386
- --B212220390 Responds to NRC 820722 ltr re violations noted in If. Insp Rept 50-309/82-26 Corrective actions low pressure safety injection pumps varieted to be limiting re NPSH GARRITY. J H Haine Yankse Atomic Power Co 82/07/27 HAYNES, R (Region I. Office of Director 2pp 16517 240 24X fiche 50-309,82/12/17.8212220386
- --8212220396 Responds to NRC B20722 itr reviolations noted in It Insp.
 Rept 50-309782-26 Corrective actions evaluation to confirm
 & redefine refueling water tank level & temp limits which
 ensure NPSH for all safeguards pumps completed
 OARRITY, J. H. Maine Yankee Atomic Power Co. 92/11/24 HAYNES, R.C.
 Region 1, Office of Director 3pp 16517 246 24X
 Fiche 50-309,82/12/17,8212220386
- 8208190268 IE Info Notice BR-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JURDAN, EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20,8208190268
- R Periodic operating reports & related correspondence
- BP12270116 Forwards monthly operating rept for Oct 1982 GROCE:R H Maine Yankee Atomic Power Co 82/11/05 Office of Resource Management, Director 1p 16583 228 24X Fiche 50-309, 82/11/05, 8212270116
- --8212270128 Monthly operating rept for Dct 1982 PHILLIPS, J Maine Yankee Atomic Power Co 82/11/04 5pp 16583 227 24X Fiche 50-307, 82/11/05,8212270116

5 Reportable occurrances, LERs & related correspondence

- 9212210165 Forwards updated LER 82-031/03X-1 GARRITY. J M Maine Yankee Atomic Power Co 62/12/07 Region 1. Defice of Director 1p 16484 299 24X Fiche 50-309, 82/12/07. R212210165
- --8212210170 Updated LER 82-031/03X-1 on 820724; scheduled inservice insp of shock suppressors revealed embty hydraulic reservoir on snubber 72; SHP-HSS-110 Caused by Leakage through cylinder seals & valve fittings Snubber rebuilt NELSON:R H Maine Yankee Atomic Power Co. 82/12/07 Region 1, Office of Director 2pp. 16484 300 24X Fiche 50-307,82/12/07, 8212210145
- BP12220456 LER B2-039/01T-0 on B21210. detector response to given core power level found low Caused by reduced leakage neutron flux at ex-core detectors Ex-core detectors adjusted using analytical callor factor WOOD.E C Maine Yankee Atomic Power Co 82/12/10 Region 1. Office of Director 1p 16503 258 24X Fiche 50-309, 82/12/10. B212220454
- 07/12290291 Forwards LER 82-038/03L-0 GARRITY.J H Maine Yankee Atomic Power Co 82/12/14 Region I. Office of Director 1p 16588 010 24% Fiche 50-309, 82/12/14, 0212290291
- --B212290306 LER B2-038/03L-0 on B21109.RHR pump P-12A removed from svr h
 uater level in core dropped balow 23 ft Caused by need to
 install emergency diesel generator improvement mod.coupled
 w/lack of clearly worded Tech Specs License mod forthcoming
 NELSON, R H . CAVIA.A J Maine Yankee Atomic Power Co B2/12/14
 Region J. Office at Director 5pp 16588 011 24x
 Fiche 50-309.82/12/14.8212290291
- G.112220276 PNO- I-82-082 on 021217, confirmatory surface measurements on Chem-Nuclear cask containing 21 drums of compacted radioactive dry waste above spec requirements State of SC considering fine & suspension of waste disposal privileges WHITE-J. DORES, R. Region I. Office of Director 62/12/17 ip 16518 029 24X Fiche 50-309.02/12/17.0212220276
- DNCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8212010462 Confirms that Div of Bafeguards regulatory effectiveness review schoduled for 821203 & 06-10 lnfo re review encl Review will evaluate security program & safeguards regulations VARCA. S A Operating Reactors Branch 1 82/11/23 UDERITZ. R A Public Service Electric & Oas Co of New Jersey 6pp 16501 327 P4X Fiche 50-272,82/11/23.8212010462
- GP12290525 Forwards Amend 15 to License BPR-75, safety evaluation & notice of issuance & availability Amend authorizes deferral of fire protection Tech Spec surveillance requirement from 821205 until first refueling outage in Jan 1983 ROSS, N J Operating Reactors Branch 1 82/12/03 UDERITZ, R A Fublic Service Electric & Cas Co of New Jersey Opp 16605 152 PAX Fichs 50-311.82/12/03.8212290525
- --8212270528 Amend 19 to License DPR-75, deferring 18-month first protection Tech Spec surveillance item from required date of 821205 to startup following final refueling outage in Jan 1983 VAROA.8 A Operating Reactors Branch 1 82/12/03 4pp 16605 155 84X Fiche 50-311.82/12/03.8212290525
- --8212290530 Safety evaluation supporting Amend 15 to License DPR-75 * Office of Nuclear Reactor Regulation, Director 82/12/03 3pp 16605 159 24% Fiche 50-311,82/12/03,8212290525
- --9212290532 Notice of issuance & availability of Amend 19 to License DPR-75 VAROA.5 A Operating Reactors Branch 1 82/12/03 2pp 16605 162 24X Fichs 50-311.82/12/03.8212290525
- GP12130212 Responds to 821202 telcon re emergency operations facility survey Facility 75 miles from generating station & consists of concrete block facility within concrete block bldg Protection factor is 13 Ventilation sys isolable LIDEN.E A Public Service Electric & Gas Co of New Jersey GP/12/06 VAROA: B A Operating Reactors Branch 1 2pp 16390 118 24X Fiche 50-272.82/12/06.8212130212

- 8212290435 Forwards IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 No reply required MARTIN.T T Division of Engineering & Technical Programs 82/12/14 UDERITY.R A Public Service Electric & Gas Co of New Jersey 2pp 16585 222 24X Fiche 50-272,82/12/14,6212290435
- --B212290443 IE Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed implementation & mgt of physical security program SMITH.0 C Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24X Fiche 50-272.82/12/14.8212290435
- 8/12210038 Offers addl info to prepare operating shift crews to respond to types of questions NRC duty officer may ask retelephone repts made via NRC emergency notification sys STAROSTECKI, R Division of Project & Resident Programs 82/12/16 UDERITZ, R A Public Service Electric & Gas Co of New Jersey Opp 16490 214 24Y Fiche 50-272,82/12/16,8212210036
- 8212300306 Confirms 821220 telcon re fire protection program review Smoke detectors & nonsafety-grade source range neutron flux monitors will be installed & 1 h fire barrier matl will be wrapped on B diesel control cable trays
 LIDENE A Public Service Electric & Gas Co of New Jersey
 62/12/22 VAROAS A Operating Reactors Branch 1 1p 16594 209
 24X Fiche 50-272.82/12/22.8212300306

P Operating license stage documents & correspondence

- BP11230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACEPRR, Dig Rock Point, Dreaden I. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREC-0763 & NUREC-0783 Svc list encl W/o stated encl EISENHULD 0 Division of Licensing B2/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X fiche 50-000, 82/11/15, 8211230066
- 8212010155 Submits addl info to support 821005 request for amend to Licenses DPR-70 & DPR-75 Info includes analysis results demonstrating motivation for Tech Spec change & effects on core linits & axial affset DNB limits LIDEN.E A Public Service Electric & Gas Co of New Jersey 82/11/18 VAROA.S A Decreting Reactors Branch 1 Bpp 16258 094 24X Fiche 90-272.82/11/18.8212010155
- BPE2010400 Advises that License DPR-75 is amended per 821122 telecopy Amend extends deadline for completion of repairs to component cooling HX22 LAINAS, G C Assistant Director for Operating Reactors 62/11/23 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 16271 080 24X Fiche 50-311,82/11/23,8212010400
- BP1201014B Forwards Revision 1 to "Safety Evaluation of PSEG Rod Exchange Methodology," for info LIDEM.E A Public Service Electric & Gas Co of New Jersey B2/11/24 VARRALS A Operating Reactors Branch 1 3pp 162'98 H1 24X Fiche 50-272,82/11/24,821201014B
- --0212010150 "Safety Evaluation of PSEQ Rod Exchange Nethodology," Revision | BLAKE,R A . BROWN,R T . ROSENFELD.E S Public Service Electric & Gas Co of New Jersey NFG 004 RO1 82/11/16 34pp 16238 114 24% Fiche 50-272,82/11/24,8212010148
- BP12130192 Requests License Condition 2 L be expanded to include deferral of 18-month surveillance Tech Spec by adding add1 safety evaluation page to Amend 14 granted on B21027 Change is Class III amend Few to be forwarded LIDEM.E A Public Service Electric & Oas Co of New Jersey 82/12/02 VAROA.S A Operating Reactors Branch 1 2pp 16396 149 24X Fichm 50-311.82/12/02.8212130192
- 8:12290525 Forwards Amend 15 to License DPR-75, safety evaluation to notice of issuance & availability Amend authorizes deferral of fire protection Tech Spec surveillance requirement from BZ1205 until first refueling outage in Jan 1983 NOSS, W J Operating Reactors Branch 1 82/12/03 UDERITZ R A Public Service Electric & Gas Co of New Jersey 3pp 16605 152 14X Fiche 50-311,82/12/03,8212290525
- --8212270528 Amend 15 to License DPR-75 deferring 18-month fire protection Tech Spec surveillance item from required date of S21205 to startup following final refueling outage in Jan 1983
 VARGA, S A Operating Reactors Branch 1 82/12/03 4pp 16405 155 24% Fiche 50-311.02/12/03.8212270525
 - 1000 100 ETA 11616 10 017/02/70 00000
- --B212270530 Safety evaluation supporting Amend 18 to License DPR-75 * Office of Nuclear Reactor Regulation, Director B2/12/03 Jpp 14605 159 24% Fiche 50-311,82/12/03,8212270525

1

- -- 6212290532 Notice of issuance & availability of Amend 15 to ergarouse notice or issuance & availability of Amend 15 to License OPR-75 VARGA.5 A Operating Reactors Branch 1 82/12/03 2pp 16605 162 24% Fiche 50-311.82/12/03.8212270525
- 9208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT.D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- G012140623 Notification of B21214 meeting w/util in Bethesda.MD to discuss util proposal for restructuring safety review
- BP:12306072 Notification of 830104 significant licensee meeting w/util for presentation of QA organizational & functional changes TRIPP: L E Division of Project & Resident Programs 82/12/21 Division of Project & Resident Programs 2pp 16624 280 24X (iche 50-000, 82/12/21, 8212300072
- G Inspection reports, 1E Bulletins & correspondence
- B:/OB190240 IE Bulletin BR-03.Revision i. "Stress Cracking in Thick-Wall, Large-Diameter. Stainless Steel.Recirculation Sys Piping at BWR Plants " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.B2/10/28.B208170240
- 82'08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list EGDD, L | Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05.8208190245
- 82:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Frencise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24x Fiche 50-000. 82/11/18, 8208190251
- 8212060278 Forwards IE Insp Repts 50-272/82-27 \$ 50-311/82-26 pm R20928-1108 & notice of violation 5TAROSTECKI,R Division of Project & Resident Programs 82/11/22 UDERITZ,R A Public Service Electric & Oas Co of New Jersey 2pp 16312 036 24% Fiche 30-272,82/11/22.8212060278
- --8212040281 Notice of violation from insp on 820928-1108 * Division of Project & Resident Programs 82/11/22 16312 038 24X Fiche 50-272,82/11/22,8212040278
- -8212060287 IE Insp Repts 50-272/82-27 & 50-311/82-26 on 820928-1108 Noncompliance noted failure to perform surveillance in time specified & failure to observe limiting condition of operation on fire protection instrumentation
 NORRHOLM.N J. SUMMERS.R , TRIPP.L E Division of Project & Resident Programs 92/11/09 18pp 16312 040 24X
 Fiche 50-272,82/11/22.8212060278
- GPO8190256 IE Info Notice 82-46, "Defective & Obsolete Combination OBSIONS IL INFO NOTICE OF THE PROPERTY OF T
- UP 12030144 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-272/82-22 & 50-311/82-21 MARTIN, T Division of Engineering & Technical Programs 82/11/29 UDERITZ, R A Public Service Electric & Gas Co of New Jersey Ip 16306 112 24X Fiche 50-272,82/11/29,8212030144
- --G212030153 Responds to NRC 821019 ltr re violations noted in IE Insp Repts 50-272/82-22 % 50-311/82-21 Corrective actions Repes 30-2/2/84-22 % 50-411/82-21 Corrective actions Mater M-137 properly recalibr, Maters M-76 & M-184 accounted for & inadequate housekeeping conditions corrected UDERITZ,R A Public Service Electric & Qas Co of New Jersey 82/11/19 HAYNES,R C Region 1, Office of Director 5pp 16306 113 24X Fiche 50-272,82/11/29,8212030144
- G:'OB190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radigactive Mati " Svc list encl CDB.L I Division of Fuel Facilities, Materials & Safeguards G2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257

- 8208190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets "Svc list encl
 JORDAN E L Division of Engineering & Guality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000.62/12/03.8208190261
- B212140124 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-25 & 50-311/82-24 STAROSTECKI, R Division of Project & Resident Programs 82/12/06 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 16408 240 24X Fiche 50-272,82/12/06,8212140124
- --8212140133 Responds to NRC 821006 ltr re-violations noted in IL Insp Repts 50-272/82-25 & 50-311/82-24 Corrective actions Tech Spec 3 0 4 will be discussed w/personnel Tech Spec 3 3 3 5 Spec 3 0 4 Will be enscussed wypersonnel lech spec 3 3 3 5 limiting condition for operation not violated UDERITZ.R A Public Service Electric & Gas Co of New Jersey 62/11/05 HAYNES.R C Region 1, Office of Director 4pp 16408 241 24% Fiche 50-272, 82/12/06.8212140124
- 8212200020 Submits addl info per IE Bulletin 80-ii, "Masonry Wall Design," in response to NRC request One oversize drawing encl Aperture card is available in PDR LIDENLE A Public Service Electric & Oas Co of New Jersey 82/12/09 VARGALS A Operating Reactors Branch I 3pp 16470 186 24X Fithe 50-272,82/12/08.8212200020
- 8P12270435 Forwards IE Enforcement Conference Repts 50-272/82-31 b 50-311/82-28 on 820812 No reply required MARTIN, T T Division of Engineering & Technical Programs 82/12/14 UDERITA, R A Public Service Electric b Gas Co of New Jersey 2pp 16585 222 24X Fiche 50-272,82/12/14.8212270435
- --8212290443 [E Enforcement Conference Repts 50-272/82-31 & 50-311/82-28 on 820812 Areas discussed implementation & mgt of physical SMITH, 9 C . MCREGHAN L M . GDDY, A T Division of Engineering & Technical Programs 82/12/07 4pp 16585 224 24X Fiche 50-272, 82/12/14, 8212290435
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for OBIO260 I Listo Notice 32-49. "Correction for Sample Conditions for Air & Gas Monitoring "Svc list enc! DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Eduson Co of New York, Inc 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- 8712220444 Forwards listing of topic areas for discussion at Region 1/ licensee meeting on drug & alcohol abuse programs per IE Info Notice 82-05 & NUREG-0903 W/o NUREG STARDSTECKI.R Division of Project & Resident Programs 82/12/16
 UDERITY.R A Public Service Electric & Gas Co of New Jersey Ipp
 16503 322 24X Fiche 50-272,82/12/16.8212220444
- 820819026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" 8vc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp 16428 293 (24) Fiche 50-000, 82/12/20,8208190268
- R Periodic operating reports & related correspondence
- 82:12270274 Forwards monthly operating rept for Nov 1982
 MIDURA.H J Public Service Electric & Oas Co of New Jersey
 82/12/10 Director's Office, Office of Inspection and Enforcement
 1p 16530 332 24% Fiche 50-311,82/12/10.8212270274
- --8212270280 Monthly operating rept for Nov 1982 MILLER, L. K. Public Service Electric & Gas Co. of New Jersey 82/12/10 17pp 16530 333 24X Fiche 50-311, 62/12/10, 6212270274
- 8212280066 Forwards NPDES discharge monitoring rept for Nov 1982 MILLER, L K Public Service Electric & Oas Co of New Jersey 82/12/15 BAKER, R A . LUNDIN, C Environmental Protection Agency ip 16564 256 24% Fiche 50-272, 82/12/15, 8212280066
- --8212280068 NPDES discharge monitoring rept for Nov 1982 MILLER, L K Public Service Electric & Oas Co of New Jersey 82/12/14 19pp 16564 257 24X Fiche 50-272, 82/12/15, 8212280066

DOCKETED ITEMS

- S Reportable occurrences, LERs & related correspondence
- H21021007B Forwards LER H2-111/01T-0 Detailed event analysis Encl MIDURA: H J Public Service Electric & Gas Co of New Jersey B2/10/06 HAYNES: R C Region 1, Office of Director 429 15745 329. 24X Fiche 50-311.82/10/06.821021007B
- --9210210095 LER 82-111/01T-0 on 821002.small svc water leak of 0.5 gpm discovered on cooling coils of containment fan coil unit 23 Caused by erosion of cooling coils by silt in svc water Beltona metal filler used in repair New coils purchased FRAHN.R Public Service Electric & Gas Co of New Jersey 82/10/06 Region (Dffice of Director ip 15765 333 24X Piche 50-31(,82/10/06,8210210078
- B212060165 Forwards LER 82-131/03L-0 Detailed event analysis encl MIDURA; H J Public Service Electric & Cas Co of New Jersey 62/11/17 HAYNES; R C Region 1, Office of Director 3pp 16311 066 24X Fiche 50-311,82/11/17.8212060165
- --8212060174 LER 82-131/03L-0 on 821028 & 1106,P-250 computer observed operating erratically & RCS subcooling margin monitor declared inoperable Caused by 4-volt dc power supply drifting low Power supply adjusted FRAHM.R Public Service Electric & Oas Co of New Jersey 82/11/17 Region 1. Office of Director 1q 16311 069 24X Fiche 50-311,82/11/17.8212060165
- B212060202 Forwards LER 82-130/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Cas Co of New Jersey B2/f1/17 HAYNES.R C Region 1: Office of Director Spp. 16313 198 24% Fische 50-311,82/11/17,8212060202
- --8212060214 LER 82-130/03L-0 on 821031 & 1105, svc water flow to containment fan coll unit 23 observed Idw. Caused by silt clogging back pressure control valves Valves cycled during cooler leak repair Low flow eliminated when unit started FRAHM: R Public Service Electric & Gas Co of New Jersey 82/11/17 Region I. Office of Director ip 16313 201 24X Fiche 50-311,82/11/17.8212060202.
- 8212080434 Forwards LER 82-135/01T-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 62/11/24 MAYNES: R C Region 1. Office of Director 3pp 16352 171 24X Fiche 50-311.82/11/24,8212080434
- --9212080443 LER 82-125/01T-0 on 821121.during routine surveillance small syc water leaf discovered on cooling coil of containment fair coil unit 25 Caused by silt in syc water Coil repaired New design coils will be installed during next refueling FRAHM.R Public Service Electric & Gas Co of New Jersey 82/11/24 Region 1, Office of Director. Ip 16352 174 24X Fiche 50-311,82/11/24,8212080434
- 8212140079 Forwards LER 82-132/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey 82/11/24 HAYNES: R C Region 1, Office of Director. 3pp 15408 251 24X Fiche 50-311.82/11/24.8212140079
- --B212140085 LER 82-132/03L-0 on 821106 & 15, spurious actuation of safeguards equipment control cabinet 2A resulted in de-energization of vital bus 2A Caused by noise in eys control circuitry. Noise suppression devices will be added FRAHM, R Public Service Electric & Qas Co of New Jersey 82/11/24 Region 1, Office of Director 1p 16408 254 24x Fiche 50-311,82/11/24,8212140077
- B212140099 Forwards LER 82-134/03L-0 Detailed event analysis encl MIDURA: H J Public Service Electric & Gas Co of New Jersey B2/11/24 HAYNES: R. C Region 1. Opfice of Director Spp 14409 264 24X Fiche 50-311,82/11/24.8212140099
- --B212140107 LER 82-134/03L-0 on 821110 during routine surveillance, turbine trip low autostop of pressure channel II bistable observed to trip low Caused by machanical wear in channel pressure suitch. Sustch replaced FRAHM.R Public Service Electric & Gas Co of New Jersey. B2/11/24. Region i. Office of Director ip. 16409 267 24X Fiche 50-311.82/11/24.8212140099
- 8212160048 Forwards LER 82-137/03L-0 Datailed event analysis encl. MIDURA:H J Public Service Electric & Oas Co of New Jersey 82/12/01 HAYNES,R.C Region 1. Office of Director Spp 16446.203. 24% Fiche 50-311.82/12/01.8212160048
- --B212160054 LER 82-137/03L-O:on B21115, during routine operation, control room operator discovered that auxiliary alarm typewriter not printing intelligibly Caused by tilt ring assembly being out of adjustment Assembly readjusted FRAHM.R Public Service Electric & Gas Co of New Jersey, B2/12/01 Region 1, Office of Director 1p 16446 206 24X Fiche: 50-311,82/12/01,8212160048

- 8212160381 Forwards LER 82-133/03L-0 Detailed event analysis encl NIDURA: H J Public Service Electric & Gas Co of New Jarsey 82/12/01 HAYNES,R C Region 1. Office of Director 3pp 16442 342 24X Fiche 50-31.82/12/01.8212160381
- --BR12160390 LER 82-133/03L-0 on 821107, during routine operation, control room operator discovered containment gaseous activity monitor maifunctioned Caused by internation to consection on integrated circuit or circuit board Units reseated FRAHM, R Public Service Electric & Cas Co of New Jersey 82/12/01 Region 1, Office of Director 1p 16442 345 24% Fiche 50-311,82/12/01.8212160381
- B212160379 Forwards LER 82-136/01T-0 Detailed event analysis encl MIDURA.H J Public Service Electric & Gas Co of New Jersey B2/12/01 HAYNES.R C Region 1. Office of Director Jpp 16442 147 24X Fichs 50-311,82/12/01.8212160399
- --B212160414 LER 82-136/01T-0 on B21124, small svc water leak of 0 5 gpm discovered on cooling coil of containment fan coal unit 23 Caused by erosion of cooling coil by silt in svc water Coil blanked off to seal leak FRAHMLR Public Service Electric & Gas Co of New Jersey B2/12/01 Region 1, Office of Director ip 16442 150 24y Fiche 50-311,82/12/01,8212160399
- 8212220391 Forwards LER 82-142/03L-0 Detailed event analysis encl HIDURAH J Public Service Electric & Oas Co of New Jersey 82/12/08 HAYNES.R C Region 1. Office of Director 3pp 16517 260 24% Fiche 50-311,82/12/08.8212220381
- --8212220385 LER 82-142/03L-0 on 821123.steam generator 21 level channel IV indication read 4/ higher than other channels & declared inoperable Caused by failure of channel level transmitter Transmitter replaced FRAHM, R Public Service Electric & Oas Co of New Jersey 82/12/00 Region 1, Defice of Director 1p 16517 263 249 Fiche 50-311.82/12/08.8212220381
- B212220395 Forwards LER 62-138/03L-0 Detailed event analysis encl MIDURA:H J Public Service Electric & Gas Co of New Jarsey B2/12/06 HAYNES,R C Region i. Office of Director Jap 18503 212 24X Fichs 50-311,82/12/08,8212220395
- --8212220406 LER 82-138/03L-0 on 821119, shift supervisor realized that surveillance requirement to check local sightglass levels of accumulators 23 & 24 was overdue Caused by personnel oversight Personnel counseled DICKEY, F Public Service Electric & Gas Co of New Jersey 82/12/08 Region I. Office of Director 1p 16503 215 24% Fiche 50-311, 82/12/08, 8212220395
- B212220420 Forwards LER B2-139/03L-0 Detailed event analysis encl MIDURA,H J Public Service Electric & Qas Co of New Jersey B2/12/08 HAYNES,R C Region 1. Office of Director Jpp 16503 274 24X Fiche 50-311,82/12/08.8212220420
- --B212220424 LER B2-139/O3L-O on B21117,auxiliary feedwater storage tank dropped below Tech Spec min vol of 200,000 gallons Gaused by personnel error Tank level restored & operator counseled DICKEY.F Public Service Electric & Gas Co of New Jersey 82/12/08 Region i, Office of Director Ip 16503 277 24X Fiche 50-311,82/12/08.8212220420
- 8212220433 Forwards LER 82-143/03L-0 Detailed event analysis encl MIBURA:H J Public Service Electric & Gas Co of New Jersey 82/12/08 HAYNES:R C Region I. Office of Director 4pp 15503 317 24X Fiche 50-311.82/12/08.8212220433
- --B212220435 LER 82-143/03L-0 on 821124, during surveillance review, discovered reactor trip breaker manual trip feature not tested before B21119 startup Caused by confusion involving recent changes in procedures re testing of trip breaker FRAHM.R. Public Service Electric & Gas Co of New Jersey B2/12/08 Region i. Office of Director ip 14503 321 247 Fiche 50-311,82/12/08.8212220433
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F Security, medical, smergency & fire protection plans
- 8212130337 Forwards response to 8 Miner 821202 telcon request response operations facility (EOF) Permanent primary EOF located 23 miles from reactor bidg MATTIKOG: J Sacramento Municipal Utility District 82/12/07 STQLZ, JF Operating Reactors Branch 4 2pp 16389 272 24X Fiche 50-312, 82/12/07, 8212130337

- SE12170319 Application for proposed Amend 87 to License DPR-54 relocating one fire hydrant to permit const of new training & records bldg MATTIMOE, J J Sacramento Municipal Utility District 82/12/07 EISENAUT, D G Division of Licensing 1p 16453 171 24X Fishe 50-312, 82/12/07,9212170319
- --8212170320 Proposed Tech Specs for Amend 87 to License DPR-54, relocating one fire hydrant to permit const of new training & records bidg + Sacramento Municipal Utility District 82/12/07 ip 16453 192 24X Fiche 50-312,82/12/07,8212170319
- 0:12130163 Forwards IE Safeguards Insp Rept 50-312/82-39 on 821115-19 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUGL R Division of Radiological Safety & Safeguards Program 82/12/08 MATTIMOE.J J Sacramento Municipal Utility District 2pg 16396 070 24% Fiche 50-312/82/12/08/82/2130163
- 82:12170198 Forwards response to Region 5 comments on security training & qualification plan. Revision 4
 HATTIMDE: J Sacramento Municipal Utility District 82:12:10
 STOLE. J F Operating Reactors Branch 4 4pp 16450 008 24X
 Fiche 50-312. 82:12:10:8212170198
- 8212210439 Informs that next requalification cycle for station blackout training begins after annual operator exams scheduled to be completed by Jan 1983 HATTIMDE, J J Sacramento Municipal Utility District 82/12/15 STOL

G Adjudicatory correspondence

- B212220136 Forwards NURRO/CR-3013 & ED Bylvester affidavit in response to ASLAB 820930 order NRC position in SER re acceptability of current auxiliary feedwater sys until upgraded sys complete remains unchanged LESSY, R P Hearing Branch 3 82/12/01 ROSENTHAL, A B , BUCK, J H , KUHL, C R Atomic Safety and Licensing Appeal Panel 49pp 16503 099 24X Fiche 50-312.82/12/01.8212220136
- --B2:2220141 Affidavit of ED Bylvester in response to ASLAB 820930 order requesting info re auxiliary feedwater sys NRC evaluation awaits licensee info Sys upgrades provide significant improvement over present design W/prof qualifications SYLVESTER: E D Auxiliary Systems Branch 82/12/01 64pp [6503 148 24X Fiche 50-312,82/12/01,8212220136
- BE12200026 Comments responding to ASLAB 821123 Memorandum & Order ALAG-703 ASLAB should modify tentative conclusion & endorse alternative imap program re HPI nozzle radiographic exam BAXTER.T A Sacramento Municipal Utility District BAXTER.T A Shaw, Pittman, Potts & Trowbridge 82/12/14 8pp 16474 273 24) Fiche 50-312,82/12/14.8212200026
- SPIR300004 Advises of status of two items remaining from ALAB-703 NRC comments on frequency of radiographic insps for HPI Notzles C & D encl in S Hou affidavit NRC review of licensee info re auxiliary feedwater sys mods will be submitted by 830331 DESSY.R P Hearings Division 82/12/23 ROSENTHAL.A S . BUCK, J H . ROML, C N Atomic Safety and Licensing Appeal Panel 2pp 145798 144 24X Fiche 50-312.82/12/23.8212300004
- --B212300007 Affidavit of S Hou re ALAB-703 ltem 3 on adequacy of licensee inservice insp program for HPI Nozzles C & D More trequent insps scheduled than schedule proposed by licensee on E21214 warranted Prof qualifications encl HDU. S Office of Nuclear Reactor Regulation. Director 82/12/20 3pp 16598 146 24X Fiche 50-312.82/12/23.8212300004
- 8212300152 Memorandum & order directing NRC to file supplemental response to licensee 821214 submittal re radiographic insport HPI Noirles C & D by 830112 S Hou affidavit is of limited assistance Response should focus on util insposehedule TOMPKINS.D A Abomic Safety and Licensing Appeal Panel 82/12/29 Dffice of the Executive Legal Director 5pp 16578 087 24X Fiche 50-312,82/12/29,8212300152

P Operating license stage documents & correspondence

8212170078 Forwards notice of consideration of issuance of amend to License DPR-54 re 820928 application to permit expansion of spent fuel storage capacity MINER: 8 Operating Reactors Branch 4 82/12/01 MATTIMOE, J Sacramento Municipal Utility District 4pp 16480 280 24X Fiche 50-312,82/12/01,8212170078

- --B212170087 Notice of consideration of issuance of amend to License DPR-54 re 820928 application to permit expansion of spent fuel storage capacity STQLZ.J F Operating Reactors Branch 4 82/12/01 4pp 16480 284 24X Fiche 50-312.82/12/01.8212170078
- B212080110 Notification of B21216 meeting w/B&W owners group in Bethesda.MD to discuss results of long-term program for evaluation of cracking problem in B&W plant makeup nozzles MINER.S Operating Reactors Branch 4 B2/12/03 STULZ, J Operating Reactors Branch 4 B2/12/03 STULZ, J Fiche 50-312.82/12/03.8212080110
- 8212140351 Forwards proposed Amend 62 to DPR-54.consisting of entire Tech Specs.revising environ portion per EG&G request & updating nonenviron portion to include amends approved by NRC as of 790713
 MATTIMOE.J J Sacramento Municipal Utility District 82/12/07 CISENHUT.D G Division of Licensing ip 16402 125 24X
 Fiche 90-312.82/12/07.8212140351
- --8212140356 Proposed Tech Specs, revising environ portion & updating nonenviron portion to include amends approved by NRC as of 790713

 Sacramento Municipal Utility District 82/12/07 388pp 16402 124 24X Fiche 50-312,82/12/07.8212140351
- --8212140363 "Rancho Seco Nuclear Generating Station Offsite Dose Calculation Manual" * Sacramento Municipal Utility District 82/10/31 77pp 14403 077 24X Fishe 50-312,82/12/07,8212140351
- GP12170009 Concurs w/util conclusion that no Tech Spec thanges or addl analyses required to support operation to 305 effective full power days during Cycle 5.per util 820922 & 1102 ltrs STOLZ.J F Operating Reactors Branch 4 82/12/07 MATTIMOE, J J Sacramento Municipal Utility District 3pp 16480 296 24X Fiche 50-312,82/12/07.8212170009
- 82/12/70319 Application for proposed Amend 87 to License DPR-54 relocating one firs hydrant to permit const of new training & records bldg MATTIMDE, J J Secremento Hunicipal Utility District 82/12/07 CISFAHUT, D 0 Division of Licensing ip 16453 191 24X Fiche 50-312, 82/12/07, 82/12/70319
- --8212170320 Proposed Tech Specs for Amend 67 to License DPR-54.
 relocating one fire hydrant to permit const of new training & records bldg
 * Sacramento Municipal Utility District 82/12/07 ip
 14453 192 24X Fiche 50-312,82/12/07.8212170319
- 8212170110 Forwards request for add) info & status rept re NUREG-073/, Item II E J i, "Auxiliary Feedwater Bys Evaluation" Confirmation that required info will be submitted by 830114 requested within 7 days
 STOLZ, J F Operating Reactors Branch 4 82/12/08 MATTIMOE, J J Bacramento Municipal Utility District 62pp 16478 023 24X
 Fiche 50-312,82/12/08,82(2170110
- 8208170263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of itr Svc list enci EISE/HHUT.D 9 Division of Licensing 82/12/09 Consolidated Edison Co of New York: Inc 29pp 16629 247 24X Fithe 50-000, 82/12/09, 8208190263
- GP12170220 Forwards list of hook travel speeds for cranes util reported in response to NURGO-0612 Info requested by C Bomberger of Hestec Svcs. Inc for evaluation of util response MATTIMOE. J J Bacramento Municipal Utility District 82/12/09 MINOR. S Office of Nuclear Reactor Regulation, Director 2pp 14462 011 24X Fiche 50-312,82/12/09.8212170220
- B2:2140391 Application to amend Literus BPR-54, extending 18-month interval between normal reactor refuelings to 24 months for one time only, due to shutdowns resulting from turbine rotor repairs & auxiliary feedwater spray header mods MATTIMDE, J Sacramento Municipal Utility District, 82/12/10 ElecthHUT, D 0 Division of Licensing 3pp 14402 110 24X Fiche 50-312,82/12/10,8212140391
- B2/2140401 Advises that operability test performed on HPIS during refueling outages Monthly operability test conducted on individual pumps, breakers & valves Failure of integrated mode response considered remote COLOMBO.R Sacramento Hunicipal Utility District 82/12/10 HINDR.S NRC No Detailed Affiliation Oiven 1p 16404 319 24X Fiche 50-312.62/12/10.8212140401

- 82/12270396 Forwards order for license mod to implement NUREG-0737. Item 11 F 2 "Inadequate Core Cooling " EISEMHUT, D 0 Division of Licensing 82/12/10 MATTIMOE, J J Sacremento Municipal Utility District 3pp 16573 349 24X Fiche 50-312, 82/12/10.8212270396
- 8212270399 Order for license mod to implement NUREG-0737, Item II F 2.

 "Inadequate Core Cooling"

 EISENHUT.D G Division of Licensing 82/12/10 Sacramento
 Municipal Utility District 11pp 16573 353 24X

 Fich 50-312,82/12/10.8212270396
- GP:[2170255 Notifies that final rept re safety & relief valve testing will not be completed until Mar 1983 PORV block valve issue satisfies NUREO-0737. Item II D 1. closing issue qualification based on CPC 820601 submittal NATTHMOE, J Sacramento Municipal Utility District 82/12/13 510LZ.JF Operating Reactors Branch 4 ip 16456 208 24X Fiche 50-312, 82/12/13, 8212170259
- 8712220241 Lists reasons for delay in implementation of abnormal transfent operating guideline (NUREG-0737. Item I C i) & delay in operator training as stated in 820604 response to Generic Ltr 82-10
 MATTIMOE.J J Sacramento Municipal Utility District 82/12/14
 STGLZ.JF Operating Reactors Branch 4 2pp 16518 005 247
 Fiche 50-312.82/12/14-8212220241
- B212270285 Forwards check to cover fees for Tech Spec waiver re addition to Amend 38 to License DPR-54 COLOMBO.R W Sacramento Municipal Utility District 82/12/20 EJSENHUT.D 0 Division of Licensing ip 14530 318 24X Fiche 50-312.82/12/20.8212270285
- 8212290283 Forwards Amend 42 to License DPR-54, safety evaluation & notice of (sounce & availability Amend changes Tech Spec refueling interval from 18 to 24 months if outage starts on or before 830228 MINER, S. Operating Reactors Branch 4 82/12/20 MATTIMOS, J. Sacramento Municipal Villity District Spp. 16606 249 24X Fiche 80-312, 82/12/20,8212290283
- --B212290288 Amend 42 to License DPR-54, changing Tech Spece for surveillance tests for refueling interval to 24 months provided refueling outage starts by 830228 Upon 1983 startup, definition of interval expires 870L2.
- --8212290293 Bafety evaluation supporting Amend 42 to License DPR-54 # Office of Nuclear Reactor Regulation, Director 82/12/20 2pp 16606 258 24X Fiche 50-312.82/12/20.08/12290283
- --B212290299 Notice of issuance & availability of Amend 42 to License DPR-54 STOLZ:JF Operating Reactors Branch 4 82/12/20 2pp 16606 260 24X Fiche 50-3[2,82/12/20,8212290289
- 6.12580233 Advises that current facility operation acceptable since reactor vessel meth irradiation Tech Specs valid for accumulated neutron fluence corresponding to 5 EFPY Tech Specs being revised to extend applicability period MATTIMOS.JJ Sacramento Municipal Utility District 62/12/22 STOLZ.JF Operating Reactors Branch 4 2pp 16562 266 24x Fiche 50-312.82/12/22.8212280233
- 4 Inspection reports, IE Bulletins & correspondence
- 87:08140240 IE Bullstin 82-03 Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter. Stainless Steel, Recirculation Sys Piping at BNR Plants "Svc list enc! DEWGUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 165 24X Fiche 50-000.82/10/28.8208140240
- 8208190245 IE Into Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thernolominescent Dosimeters " Svc list enc!
 COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24% Fiche 30-000.82/11/05,8208190245
- 8P12060163 Forwards IE Insp Rept 50-312/82-38 on 621001-1104 & notice of violation STERNSERG.D Division of Resident, Reactor Project & Engineering Programs 62/11/16 MATTIMOE, J Sacramento Municipal Utility District 2pp 16313 101 24X Fiche 50-312/82/11/16/8212060163
- --8212060167 Notice of violation from insp on 821001-1104 YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/16 ip 16313 103, 24% Fiche 50-312,82/11/16,8212060163

- --8212060171 IE Insp Rept 50-312/82-38 on 821001-1104 Noncompliance noted failure to log charges in plant status rept CAMTER.H L., O'BRIEN.J P., YOUNG.T Division of Resident, Reactor Project & Engineering Programs 82/11/15 llpp 16313 101 244 Fishe 50-312,82/11/16,8212060163
- 820B190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDANE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 449 Film 30-000, 82/11/18, 8208190251
- B://2060024 Requests add1 info:within 30 days,re IE Bulletin 80-1) on masonry wall design STOLZ: JF Operating Reactors Branch 4 82/11/22 MATTIMDE, J J Sacramento Municipal Utility District 4pp 16325-324 24X Fiche 50-312, 82/11/22, 8212060024
- --8212050027 "Structural Engineering Branch Criteria for Safety-Nelaton Masonry Wall Evaluation" * Operating Reactors Branch 4 81/07/31 Spp 16325 328 209 Fiche 50-312,82/11/22.8212060024
- 8712070033 Forwards order extending time within which penalties must be paid or hearing requested to Enforcement Action 82-50 DEYQUIVO,R C Director's Office, Office of Inspection and Enforcement 82/11/24 MAYTIMOE,J J Sacramente Municipal Utility District 2pp 16354 306 24X Fiche 50-312.82/11/24.8212070033
- --8212070146 Order extending time within which licensee must pay fivil penalty or request hearing on Enforcement Action 82-50 until 30 days after issuance of decision on request for reconsideration

 DEYOUNG R C Director's Office, Office of Inspection and Enforcement 82/11/24 Sacramento Municipal Utility District 2pp 16334 308 24% Fiche 50-312.82/11/24,8212070033
- GPO03190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list and DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, lic 12/pp 16411 065 24% Fiche 50-000, 82/11/26, 8208;90256
- 8/12070277 Forwards add1 info re diesel generator relays reset from control room for reconsideration of order imposing penalties Encl Qualification Evaluation Sys Corp rept to be ittached to 821123 itr MATTIMDE, J. J. Sacramento Municipal Utility District 82/11/29 Uty YOUNG, R.C. Director's Office, Office of Inspection and Enforcement 35pp 16339 078 24X Fiche 50-312,82/11/29,8212070277
- BF/08190257 IE Info Notice 82-47. "Transportation of Type A Quantitics of Non-Fissile Radioactive Matl " Syc list encl
 COSB.L I Division of Fuel Facilities, Materials % Safeguards
 BZ/11/30 Consolidated Edison Co of New York, Inc 356pp
 16397 028 24% Ficha 50-000,82/11/30,8208190257
- BE/12070410 Submits results of steam generator insp & safety evaluation refuture plant operation on B21120.4-5 gpm primary to secondary leak identified in A steam generator Deposits in insp lane region determined to enhance tube corrosion MATTIMOE.JJ Sacramento Municipal Utility District B2/12/01 STOLE.JF Operating Reactors Branch 4 2pp 16336 347 24% Fiche 50-312.82/12/01.8212070410
- GI/OB190259 IE Bulletin B2-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.68/12/03.6808190259
- 8:08190261 IE Info Notice 82~48, "Failures of Agastat CR 0095 Relay Gockets " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/12/03 Consulidated Edison Co of New York, Inc 110pp 16462 064 (4) Fiche 50-000,82/12/03/8208190261
- BP12070220 Informs of results of fiberscope insp of leaking steam generator A tube 77-2 Results do not change G21201 evaluation B&K will review insp documentation MATTINGE J J Sacramento Municipal Utility District 82/12/03 GTOLZ J F Operating Reactors Branch 4 ip 16329 356 24% Fiche 50-312.82/12/03.8212070220
- BP12130163 Forwards IE Safeguards Insp Rept 50-312/82-39 on 821115-19 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 82/12/09 MATTIMOE, J J Sacramento Municipal Utility District 2pp 16396 070 24X Fiche 50-312.82/12/08.82/12/30183

- GE/12170301 Notifies that util unable to provide response to 821103 request for addl analysis re IE Bulletin 60-04, "Main Steam Line Break H/Continued Feedwater Addition," until 830415 MATTIMOE, J J Sacramento Municipal Utility District 62/12/13 570L2, J F Operating Reactors Branch 4 ip 16456 128 24X Fiche 50-312, 62/12/13, 8212170301
- 3:08190267 IE info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DE-10046.8 C Director s Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 244 Fiche 50-000.82/12/16.8208190267
- 9.'08190268 [E Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 1TE-27' Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- GE-12300350 Ack receipt of 821215 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-312/82-38 STERNSERG.D M Division of Resident. Reactor Project & Engineering Programs 82/12/23 MATIMOE. J Sacramento Municipal Utility District ip 16594 229 24X Fiche 50-312.82/12/23.8212300350
- --8212300353 Responds to NRC 821114 ltr re violations noted in IE Insp Rept 50-312/82-38 Corrective actions operators personally directed to comply o/alarm logging requirements in Administrative Procedure 23. Revision 11 MATTIMOE, J J Sacramento Municipal Utility District 82/12/15 ENGELMENT H Region 5, Office of Director 2pp 16594 230 24: Fichs 50-312.82/12/23.8212300350
- It Periodic operating reports & related correspondence
- Girl2170231 Forwards monthly operating rept for Nov 1982 AGDRIGUEZ, R. J. Sacramento Municipal Utility District 82/12/07 Director's Office, Office of Inspection and Enforcement | Ip 16462 013 244 Fiche 90-312,82/12/07,8212170231
- -- B212170235 Monthly operating rept for Nov 1982 GDLOMBO.R Sacramento Municipal Utility District 82/12/07 App L6462 014 24X Fiche 50-312.82/12/07.8212170231
- SG:12200042 Forwards revised monthly operating rept for Oct 1982 RODRIGUES,R J. Sacramento Municipal Utility District 82/12/13 Director's Office, Office of Inspection and Enforcement 1p 16474 201 24X Fiche 50~312.82/12/13
- 9212203048 Revised monthly operating rept for Oct 1982
 CDLOMBOR Sacramento Municipal Utility District 82/11/30 Jp 16474 282 24% Fithe 50-312,82/12/13,9212200049
- Gt: 2270283 Forwards Revision 1 to monthly operating repts for Apr & May 1982 RODRIGUEZ, R.J. Sacramento Municipal Utility District 82/12/15 Hirsefor's Office, Office of Inspection and Enforcement 1p 16530 161 24% Fisch
- --G212270288 Revision 1 to monthly operating rept for Apr 1782 COLOMBO R Sacramento Municipal Utility District 82/04/30 bpp 16530 162 24X Fiche 50-312,82/12/15,8212270283
- U212270191 Revision 1 to monthly operating rept for May 1982 COLOMBD.R Sacramento Municipal Utility District 82/05/31 bpp 16530 167 24X Fiche 50-312.82/12/15,8212270283
- 5 Reportable occurrences, LERs & related correspondence
- G.(17030)110 Forwards LER 82-023/03L-0 Detailed event analysis submitted MATTIFUE, J Sacramento Municipal Utility District 82/10/06 LIGELKEI, R H. Region 5. Office of Director 1p 16303 027 P4X (1che 50-312, 82/10/06, 8212030)10
 - 8212030116 LER 82-023/03L-0 on 820909, weekly nitrogen sys surveillants showed Xe-133 activity 4n auvillary bldg nitrogen header Cause undetermined investigation will be conducted Followsprept on cause & corrective actions will be provided CGLCH80.R W Sacramento Nunicipal Utility District 82/10/06 Region 5. Office of Director 1p 16303 028 24% Fiche 50-312,82/10/06,8212030110
- ISP12030081 Forwards LER 82-027/03L-0 Detailed event analysis submitted MATTIMOF, J. Sacramento Municipal Utility District 82/11/16 FMGELKEN, R.H. Region 5. Office of Director 1p 16303-206 24X 11che 50-312, 62/11/16, 8212030081

- --8212030095 LER 82-027/03L-0 on 821012.weekly surveillance of nitrogen sys revealed presence of contamination in form of Xe-133 Cause undetermined Sys purged % activities reduced to below detectable levels investigation underway Rept will follow COLOMBO.R W Sacramento Municipal Utility District 82/11/08 Region 5. Dffice of Director ip 16303 207 24X Fiche 50-312,82/11/16.8212030081
- BP12040294 Forwards supplemental LER B2-025/04X-1
 MATTIMOE, J J Sacramento Municipal Utility District 82/11/19
 ENGELKEN, R H Region 5. Office of Director 1p 16312 034 24X
 Fiche 50-312,82/11/19,8212060294
- --8212060300 Supplemental LER 82-025/04X-1 on 820918, low oxygen detected downstream in Hadselville Creek during CA Water Quality Board review Caused by impoundment for irrigation purposes Analyst instructed to sample downstream of impoundment COLDMBD.R W Sacramento Municipal Utility District 82/10/27 Region 5. Office of Director ip 16312 O35 24X Fishe 50-312,82/11/19,8212060274
- 6P12030062 RO 82-3i on 821120.oncs-through steam generator A developed 4-8 ypm leak & controlled shutdown commenced Event terminated on 821121 after reaching cold shutdown Followup tept uill be provided in 14 days RODR10UE7.R J Sacramento Municipal Utility District 82/11/22 ENGELKEN.R H Region 5. Office of Director ip 16304 190 24y Fiche 50-312.82/11/22.8212030062
- 8712030091 PNO-V-82-047 on 821120, steam generator tube leak occurred in A steam generator Noble gas release less than 17 of amount allowed by Tech Specs Facility will be shut down for approx 4 wks
 JOHNSON, P. Region 5. Office of Director 82/11/22 1p 16304 103 24X Fiche 50-312,82/11/22,6212030091
- BP120300B4 Forwards LER B2-029/03L-0 Detailed event analysis submitted MATTIMOE. J Sacramento Munscipal Utility District 82/11/24 LNGELKEN.R H Region 5, Office of Director 2pp 16303 203 24X liche 50-312.82/11/24.8212030B4
- 8212030106 LER 82-027/03L-0 on 821026. QA dept reported that portion of auxiliary feedwater start circuit was not being tested per requirements Caused by transposed requirements in Tech Specs Tech Specs will be amended COLOMBO. R W Sacramento Municipal Utility District 82/30/26 Region 5. Office of Director tp 16303 205 24% Fische 50-312,82/11/24,8212030084
- GP12060347 PNO-V-82-049 on 821127, employee fell 20 ft while setting up testing equipment on A steam generator Contamination of 200 dpm received Individual hospitalized w/broken arm & bruises JUHN50N,P , YDUNG,T Region 5, Office of Director 82/11/29 1p 16311 081 24X Fiche 50-312,82/11/29,8212060347
- V Operator Examinations
- B:/12210439 Informs that next requalification cycle for station blackout training begins after annual operator exams scheduled to be completed by Jan 1983 MATTIMOE, J J Sacramento Municipal Utility District 82/12/19 GTDLZ. J F Operating Reactors Branch 4 ip 16493 126 24% [iche 50-312, 82/12/15, 8212210439]
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
- F Security, medical, emergency & fire protection plans
- BP12070425 Responds to FQIA request for documents re B20807 nutice of violation 5 order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FQIA Exemptions 3.5 % 7)
 FELTON.J M Division of Rules and Records 82/11/05 MCGARRY.J M Debevoise & Liberman 5pp 14355 003 24X Fithe 50-000,82/11/05, G212070425
- 8212070473 Concludes that all Region 4 licensees in compliance w/820201 deadline for implementation of prompt notification sys COLLINS.J T Region 4. Office of Director 82/02/01 ORIMES.B K Division of Emergancy Preparedness 2pp 16355 104 24X Fiche 50-000,82/11/05,8212070425
- B2120B0074 Releases public version of revised emergency plan procedure FELTON, J M Division of Rules and Records 82/12/01 Document Management Branch 1p 16367 185 24X Fiche 80-313,82/12/01, B2120B0074

- --8212080082 Forwards public version of Revision 4 to Emergency Plan Procedure 1903 30. "Plant Evacuation "Receipt form ent! 4 Ariansas Power & Light Co 82/11/12 NRC No Detailed Affiliation Given 1p 16367 186 24% Fiche 50-313,82/12/01,8212080074
- --8212080085 Public version of Revision 4 to Emergency Plan Procedure 1903 30. "Plant Evacuation " * Arkansas Power & Light Co 82/11/11 3pp 16367 187 24X Fiche 50-313.82/12/01.8212080074
- 8212090311 Forwards emergency operations facility (EQF) summary infoper 0 Vissing 821203 request & Generic Ltr 82-10 Const of permanent backup EOF completed HARSHALL, JR Artansas Power & Light Co 82/12/06 STGLZ, JF Operating Reactors Branch 4 CLARX, R A Operating Reactors Branch 3 2pp 16365 127 24X Fiche 50-31G,82/12/06,82/209031
- 8212100380 Releases public version of revision to emergency plan implementing procedure FELTON J M Division of Rules and Records 62/12/07 Docum Management Branch Ip 16389 224 24X Fiche 50-313,82/12/07,6212100380 Document
- --B2121003B5 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equapment " Receipt form encl 4 Arkansas Power & Light Co 82/11/29 NRC No Detailed Affiliation Given Ip 16389 225 24% Fiche 50-313.82/12/07.
- --G212100394 Public version of Revision 3 to Emergency Plan Implementing Procedure 1903 60, "Emergency Supplies & Equipment" LEVINE.J M Arkansas Power & Light Co. 62/11/26 75pp 18389 226 24X Fiche 50-313.82/12/07.8212100380
- GP12150272 Releases public version of ack of receipt of licensee ltr transmitting amend to emergency plan FELION. J.M. Division of Rules and Records 82/12/09 Document Hanagement Branch ip 16446-276 24X Fiche 50-313-82/12/08.
- --8212150280 Submits public version of ack of receipt of licensee 82081/
 ltr transmitting Amend 5 to emergency plan info re
 compliance w/requirements of IOCFR50 54(t) re annual review
 & audits of emergency plan requested
 SEIDLE,W C Division of Resident, Reactor Project & Engineering
 Programs 82/11/24 CAVANAUCH,W Arkansas Power & Light Co
 2pp 16446 278 24X Fiche 50-313,82/12/08.8212180272
- --8212150288 Forwards public version of transmittal of Amend 5 to emergency plan. incorporating both State of AR & in-house cornents N/o encl
 MARSHALL.J.R. Arkansas Power & Light Co. 82/08/27 COLLINS. J. Office of Nuclear Regulatory Research. Director DENTON. H. R. Office of Nuclear Reactor Regulation, Director 2pp 16446-280-24X Fiche 50-313.82/12/08.8212150272
- 8:12160542 Forwards draft safety evaluations of util requests for exemptions from fire protection of safe shutdown capability & of safe shutdown capability in event of fire Proposed mods will be reviewed in 1983 Confirmation of 821111 ltr needed CLARK.R A Operating Reactors Branch 3 87012.J J F Operating Reactors Branch 4 82/12/08 CAVANAUGH.W Ankanas Power & Light Co 57pp 16447 125 24X Fichs 50-313.82/12/08.8212160542
- BP12160772 Releases public version of change to Revision 3 to emergancy plan implementing procedure FELTON J M Division of Rules and Records 82/12/10 Document Management Branch ip 16464 160 24X Fiche 50-313,82/12/10,8212160772
- --0212160782 Forwards gublic version of Permanent Change PC-1 to Revision 3 to Emergency Plan Implementing Procedure 1903 22. "Fire or Explosion" Revised index encl LEVINE.J M Arkensas Power & Light Co 82/11/30 NRC -- No Detailed Affiliation Given 19 16464 161 24X Fiche 50-313.82/12/10.8212160772
- --8212160787 Public version of Permanent Change PC-1 to Revision 3 to Emergency Plan Implementing Procedure 1903 22, "Fire or Explosion"
 - * Arkansas Power & Light Co 8: Fiche 50-313.82/12/10.8212140772 82/11/29 3pp 16464 162 24X
- 8P12170012 Releases public version of change to revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16480-299 24X Fiche 50-313,82/12/10.8212/70012

- ~-8212170016 Forwards public version of Change PC-1 to Revision 2 of Emergency Plan Implementing Procedure 1903 24, "Oil Spiil Prevention Control & Countermeasure Plan " A Arlansas Power & Light Co. 82/11/30 NRC No Detailed Affiliation Given ip 16480 300 24% Fiche 50-313.82/12/10, 324212/003
- --G212170025 Public version of Change PC-1 to Revision 2 of Emergency Plan Implementing Procedure 1903 24, "011 Spill Prevention Control & Countermeasure Plan "Revision index encl Artansas Power & Light Co 82/11/29 3pp 16480 301 24X Fiche 50-313, 82/12/10, 8212170012
- 8P12170445 Releases public version of changes to revised emergency plan implementing procedure FELTON.JM Division of Rules and Records 82/12/10 Docume Management Branch 1p 16478 161 24X Fiche 50-313.82/12/10.
- --B212170448 Forwards public version of Change PC-2 to Revision 1 of Emergency Plan Implementing Procedure 1903 61,
 "Communications Equipment Tests"
 # Afransas Power & Light Co 82/11/30 NRC No Detailed Affiliation Given 1p 16478 162 24X Fiche S0-313,82/12/10, 0212170445
- --B212170453 Public version of Change PC-2 to Revision 1 of Emergency Plan Implementing Procedure 1903 61. "Communications Equipment Tests " LEVINE.J M Arkansas Power & Light Co 82/11/29 2pp 16478 163 24X Fiche 50-313,82/12/10.8212170445
- BP12210509 Releases public version of Revision 2 to Emergency Plan Procedure 1903 Of FELTON, J M Division of Rules and Records B2/12/10 Document Management Branch 1p 14502 352 24X Fiche 50-313,82/12/10, R212210508
- ENUME, J.M. Arkansas Power & Light Co. 82/11/30 Detailed Affiliation Given ip 16502 353 24X Fiche 50-313,82/12/10.8212210508
- ~-8212210521 Public version of Permanent Change PC-2 to Revision 2 to Emergency Plan Procedure 1903 01. "Organization & Use of Emergency Plan Implementing Procedures" * Arkansas Power & Light Co. 82/11/19 1p 16502 354 24X Fiche 50-313,82/12/10.8212210508
- BP12220001 Releases public version of revised emergency plan procedure FELTON.J M Division of Rules and Records 82/12/10 Document Management Branch 1p 16529 152 24X Fiche 50-313,82/12/10,
- --G212220002 Forwards public version of Change PC-3 to Revision 4 of Emergency Plan Procedure 1903 43, "Duties of Emergency Radiation Feam " Revised index encl # Arkansas Power & Light Co #2/11/30 NRC No Detailed Affiliation Given 1p 16529 153 24X Fiche 50-313.62/12/10.021320001
- -8212220004 Public version of Change PC-3 to Revision 4 of Emergency Plan Procedure 1903 43, "Duties of Emergency Radiation Team" * Arkansas Power & Light Co 8: Fiche 50-313,82/12/10,8212220001 82/11/19 3pp 16529 154 24X
- 6P12280224 Discusses util 820701 response documenting results of review of fire zones for compliance w/100FR50 48 & App R Alternate shutdown capability would be provided by cross-feed between Units 1 & 2 Special entry for G valves will not be made MARSHALL, JR Arkansas Power & Light Co 82/12/10 EISENHUI, D G Division of Licensing 1p 16562 176 24X Fiche 50-313, 82/12/10, 62:2280224
- 82:22:0526 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records 82/12/13 Docum Management Branch 1p 16502 316 24X Fiche 50-313,82/12/13,82122:0526 Document.
- --B212210534 Forwards public version of revised emergency plan elegations from a rose public version or revised emergency plan implementing procedures 1903 31 re exclusion area evacuation & 1904 03 re auxiliary bldg ventilation exhaust emergency radiation monitor ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Light Co 82/12/06 NRC - No Detailed Affiliation Given 4pp 16502 317 24X Fiche 50-313,82/12/13,0212006 ** Arkansas Power & Arkansas & Ark B21221052A

- --G212210539 Public version of revised emergency plan implementing procedures, including Procedures 1903 31 re exclusion area evacuation & 1904 03 re auxillary bldg ventilation exhaust emergency radiation monitor

 LEVINE, J H Arkansas Power & Light Co 82/12/03 23pp 14502 321 24% Fiche 50-313,82/12/13,8212210526
- G:/12230152 Releases public version of rovised nuclear contingency plan procedure FELTON, J M Division of Rules and Records G2/12/15 Document Management Branch 1p 16543 279 24% Fiche 50-313,82/12/15, G212230152
- --8212230165 Forwards public version of Revision 1 to Nuclear Contingency Flan Procedure 9, "Emergency Response Support"

 MARSHALLJR Arkanses Power & Light Co 82/12/10 COLLINS.J T Region 4. Office of Director EISETH/UT.D 9 Division of Licensing 1p 16543 280 24X Fiche 50-313.82/12/15.8212230152
- --8212230172 Public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergency Response Support" # Arkansas Power & Light Co 82/11/15 86pp 16543 282 24X Fithe 50-313,82/12/15,8212230152
- P Operating license stage documents & correspondence
- 8212060492 INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE ARKANSAS NUCLEAR ONE-UNIT 1 NUCLEAR POHER PLANT Appendices A-D Docket No. 50-313 (Arkansas Power And Light Company) KCLB.G J Sandia Laboratories NUREO/CR-2787 VO2 82/10/31 Division of Risk Analysis 1071pp 16348 274 24X Fichs 50-313.82/10/31.8212060492
- 8712030169 Forwards info re NUREG-0737. Item II B 3, "Post-Accident Sampling Sys," in response to NRC 820701 request Grab sample sys wtilized as backup to online sampling sys MARSHALL, J.R. Arkansas Power & Light Co. 82/11/24 CLARK, R.A. Operating Reactors Branch 3. SYOLZ, J.F. Operating Reactors Branch 4. 12pp. 16306-254. 24x Fiche 50-313,82/11/24,8212030169
- 80:12040262 Requests extension until 830228 to respond to NRC 820921 request for Tech Spec revision re snubber surveillance Extension needed to review implications of ANSI/ASME UNN-1982 MARSHALL, J.R. Arkansas Power & Light Co. 82/11/26 STQLZ, J.F. Uperating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 2pp 16312 272 24% Fiche 50-313,82/11/26,8212060262
- G:/12060333 Requests extension to 830228 for submitta) of App I sevisions
 MARSHALL, JR Arkansas Power & Light Co 82/11/30 STQLZ, JF
 Uperating Reactors Branch 4 CLARK, R A Operating Reactors Branch
 3 2pp 16312 190 24X Fiche 50-313,82/11/30,8212060333
- G:12070284 Forwards summary of analysis of pressurizer safety & relief valve discharge piping as required by NUREG-0737. Item
 IJ D 1 Piping stresses & support loads do not meet code, housever, piping & valves will remain aperable
 MARSHALLJR Arkansas Power & Light Co 82/11/30 STQLZ, J F
 Operating Reactors Branch 4 CLARK, R A Departing Reactors Branch
 3 4pp 16343 195 24% Fiche 50-313.82/11/30,8212070284
- GP12210013 Forwards SER on NUREO-0737. Item II A 2 1. "Upgraded Reactor Operator & Senior Reactor Operator Training" & Item II B 4. "Training for Mitigating Core Damage " Items resolved STOLZ. J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 82/12/01 CAVANAUGH.W Arkansas Power & Light Co 8pp 16543 221 24X Fiche 50-313.82/12/01.8212210013
- GP:12210010 Discusses util request for changes to Tech Specs re steam line break instrumentation & control sys setpoints Schedule for resolving listed concerns requested within 10 days of receipt of ltr STOL7. JF Operating Reactors Branch 4 82/12/06 CAVANAUGH, W Arkansas Fower & Light Co 2pp 16502 361 24X Fiche 50-313, 82/12/06, 8212210010
- GP1210048B Requests confirmation on failures re core flood tanks Submittal on NUREO-0737, Item II K 3 17, "ECCS Outages," did not specifically identify failures STGL7.J F Operating Reactors Branch 4 82/12/08 CAVANAUOH, W Arkansas Power & Light Co 2pp 16389 056 24X Fiche 50-313, 62/12/08,821210048B
- G:/OBI90263 Generic Ltr 82-32 to all PMR licensees re potential steam generator-related generic requirements Forwards Ectence Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT, 0 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X fiche 50-000,82/12/09.8208190263

- 8212170113 Responds to NRC 821109 ltr re NUREG/CR-2787. "Interim Reliability Evaluation Program Amalysis of AR Nuclear One Unit !" Add mods to facility design or operation beyond mods underway not required MARSHALL.JR Arkansas Power & Light Co 82/12/09 STOLZ.JF Operating Reactors Branch 4 2pp 16450 303 24X Fiche 50-313.82/12/09.8212170113
- 8/12270421 Forwards order for mod of licenses, requiring installation of inadequate core cooling instrumentation sys conforming ω/ NUREO-0737. Item II F 2

 EISENHUT. D G Division of Licensing 82/12/10 CAVANAUGH, H
 Arkansas Power & Light Co 2pp 16572 330 24X

 Fiche 50-313, 82/12/10, 8212270421
- --B212270427 Order for mod of licenses requiring installation of inadequate core cooling instrmentation sys conforming w/ NURE9-0737, Item II F 2 Checklist for review of sys encl EISENHUT.D G Division of Licensing B2/12/10 Arkansas Power & Light Co 11pp 16572 332 24X Fiche 50-313.82/12/10, B212270421
- BP12270022 Responds to 821130 ltr requesting extension of response date re App I submittal to 830228 Delay acceptable CLARK.R A Dperating Reactors Branch 3 STOLZ.JF Operating Reactors Branch 4 82/12/14 CAVANAUGH.W Artansas Power & Light Co 2pp 16407 181 24X Fiche 50-313.82/12/14.8212270022
- G012220515 Requests remittance of add1 sum for 821105 application for spent fuel pool expansion
 MILLER,W O License Fee Management Branch 82/12/15 CAVANAUGH,W
 Arkansas Power & Light Co 2pp 16523 027 24X
 Fiche 90-313, 82/12/15,8212220515
- 8212280307 Application for amend to License DPR-51, proposing change to Tech Spec 4 18 re steam generator tubing surveillance to assure that known problem areas are adequately inspected Class III amend fee encl
 ORIFFIN.J M Arkansas Power & Light Co 82/12/17 STOLZ, J F Operating Reactors Branch 4 4pp 16561 086 24X [iche 50-313, 82/12/17,8212280307
- --8212280309 Proposed Tech Spec 4 1B re steam generator tubing surveillance * Arkansas Power & Light Co 82/12/17 5pp 16561 090 24% Fiche 50-313,88/12/17.8212280307
- O Inspection reports, IE Bulletins & correspondence
- 8708190240 IE Builetin 82-03.Revision 1, "Stress Cracking in Thick-Walli.Large-Diameter.Stainless Steel, Recirculation Sys Piping of BHR Plants "Syc list encl DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16452 163 24X Fiche 50-000.82/10/28,8208190240
- 8:0B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BO1 & Model BO2 Thermolyminescent Dosimeters" Syc list encl
 CDR8,L | Division of Fuel Facilities, Materials & Bafeguards
 U2/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24% Fiche 50-000.82/11/05, 8208190245
- 8212210245 Forwards IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/05 CAVANAUGH, M Arkansas Power & Light Co 2pp 14483 317 24X Fiche 50-313,82/11/05,8212210245
- B212210250 IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted Major areas inspected licensee action on previous insp findings, procedures review qualification & espasure control
 BAER, R. WILBORN, L. HOLLEY, W. Division of Resident, Reactor
 Project & Engineering Programs 82/10/28 27pp 16483 319 24x
 Fiche 50-313,82/11/05,8212210245
- BP12140481 Forwards add1 info re IE Bulletin B2-02.clarifying B20929 commitments Results of matl review to determine number of leaks on boited closures listed MARBHALL, J.R. Arkansas Power & Light Co. 82/11/08 COLLINS, J.T. Region 4. Office of Director. Spp. 16403 395 24X [Fiche 50-313.82/11/08.821214048]
- 8POB190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 177 24X Ficher 50-000, 82/11/18, 8208190251

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list enci DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matj " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Censolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- GC12060087 Forwards response to NRC 820914 request for add1 info re inservice insp of reactor coolant pump flywheels Util 820818 litr requested acoustic emission insp as alternative to ultrasonic testing method MARSHALL, J R Artansas Power & Light Co 82/11/30 STDL2, J F Operating Reactors Branch 4 13pp 16316 108 24X Fiche 50-813, 82/11/30, 821206087
- 8208490259 IE Bulletin 62-04, "Deficiencies in Frimary Containment Electrical Penetration Assemblies" Svc list encl UEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche-50-000, 82/12/03,8208190259
- 8:08190261 IE Info Notice 82-48. "Failures of Agastat CR 0075 Relay Sockets" Svc list encl
 JCRDAN.E L. Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24)
 Fiche 50-000,82/12/03,8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list end DEVOUNG.R C Director's Office. Office of Inspection and Enforcement E2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche: 50-000.82/12/16.8208190267
- 82:12280307 Application for amend to License DPR-51, proposing change to Tech Spec 4 16 re steam generator tubing survey. Hance to assure that known problem areas are adequately inspected Class III amend fee eacl GRIFFIN, J M Arkansas Power & Light Co 82/12/17 STOLZ, J F Operating Reactors Brench 4 4pp 14561 086 24X Ficha 50-313, 82/12/17, 8212280307
- --8212280309 Proposed Teth Spec 4 18 re steam generator tubing surveyllance * Arkansas Power & Light Co 82/12/17, 5pp 16561 090 24X Fichs 50-313,82/12/17.8212280307
- 8308190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Gonsolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000,62/12/20,8208190268
- 8212290192 Ack receipt of 821105 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-313/82-19 & 50-348/82-16 BEIOLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/23 CAVANAUOH, Arkansas Power & Light Co ip 16578 132 24X Fichs 50-313,82/12/23.8212290192
- --0212290198 Responds to NRC B21007 ltr re deviation noted in IE Insp Repts 50-313/82-19 & 50-3168/82-16 Corrective actions environ qualification info submitted in 820729 & 0813 ltrs Commitment tracting sys implemented MARSHALL JR Arkansas Power & Light Co 82/11/05 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2p, 16578 133 24X Fiche 50-313,82/12/23.8212290192
- R Pariodic operating reports & related correspondence
- 8212290168 Forwards suppl to "Annual Environ Monitoring Rept.1981" MARSHALL, JR Arkansas Power & Light Co. 82/11/12 COLLINS, J T Region 4, Office of Director 1p 16582 181 24X Fiche 50-313, 82/11/12:8212270168
- -8212290171 Suppl to "Annual Environ Monitoring Rept, 1981"

 * Arkansas Power & Light Co 82/11/12 15pp 16582 182 24X
 Fiche: 50-313, 82/11/12, 8212290148
- 8218290194 Forwards monthly operating rept for Oct 1982 MARSHALL.J R Arkansas Power & Light Co 82/11/15 HALLER, N M Management Information Branch 1p 16578 140 24X Fiche 30-313,82/11/15,8212290194
- --8212370194 Monthly operating rept for Oct 1982 GERTSCH.A J Artenses Power & Light Co 82/11/15 Spp. 14578 141 24X Fiche.50-313.82/11/15.8212270174

- S Reportable occurrences, LERs & related correspondence
- 8212030097 Advises that historical documentation re LER 82-018/03L-0 ω_t , 421119.concerning fire barrier penetrations difficult to retrieve Info will be provided by 821220 MARSHALL. JR Arkansas Power & Light Co 82/11/19 SEIDLE, W C Region 4. Office of Director 1p 16304 110 24X Fiche 50-313.82/11/19,8212030097
- 8212100254 PNO-1V-02-044 on 821203, normal phone communication lost due to local flooding caused by heavy rains & severe weather Backup radio communications feasible from elevated ground northwest of Little Rock Addl heavy rain possible SEIDLE.N C , GAGLIARDD.J E Region 4, Office of Director 82/12/03 2pp 16376 127 24X Fiche 50-313,82/12/03,8212100254
- BP12210166 Forwards LER B2-024/03L-0 MARSHALL, JR Arkansas Power & Light Co 82/12/06 8EIDLE W C Division of Resident, Reactor Project & Engineering Programs 1p 16483 017 24x Fiche 50-313, 82/12/06,8212210166
- --8212210169 LER 82-024/03L-0 on 821104.at 48% power.control rod drive B ac breaker failed to trip Caused by latch adjusting screw being improperly adjusted Breaker replaced MARSHALL.J R Arkansas Power & Light Co 82/12/06 Region 4, Office of Director ip 16483 018 24% Fiche 50-313.82/12/06, 2012/01644
- 8P12270143 LER 82-030/01T-0 on 821214, five tubes in once-through steam generator B found w/greater than or equal to 40% through-wall indications during expanded testing program Further info will be provided in followup rept LEVINE, J M Arkansas Power & Light Co 82/12/13 COLLINS, J T Region 4, Dffice of Director 2pp 1653B 33B 24% Fiche 50-313, 82/12/13, 8212270143
- 82:12290484 LER 82-031/01T-0 plugs found installed in two reactor bldg transmitter sensing input ports, rendering input to engineered warety actuation sys analog channel outside Tach Spec limit Cause not stated LEVINE, J M Arkansas Power & Light Co 82/12/16 (DLLINS, J Region 4, Office of Director 2pp 16583 263 24X Fiche 50-313,82/12/16,8212290486
- 82:12280345 PND-IV-82-049 ports on two transmitters found blocked w/brass pipe plugs Transmitter provided signal to one of three safety channels Licenses conducting investigation JOHNSON, W D. CALLAN, L. J. Region 4, Office of Director 62/12/20 ip 16561 051 24X Fiche 50-313,82/12/20,8212280345
- 8212270321 Responds to 821018 ltr requesting addl info re fire barrier penetration seals per LER 82-018/03L-0 All penetrations & conduits properly sealed MARSHALL.J R Arkansas Power & Light Co 82/12/20 SEIDLE, W C Division of Resident. Reactor Project & Engineering Programs 3pp 16589 154 24X Fiche 90-313,88/12/20,8812290321
- 8212290210 FND-1V-82-050 while in refueling outage special insp found cracked thermal shield bolts During replacement of bolts, bolt heads found separated from bolts Bolts to be replaced w/acceptable fasteners
 JOHNSON W D . CALLAN L J Region 4. Office of Director 82/12/2)

 1p 16578 201 24X Fiche 50-313.82/12/21,8212290210
- DOCKET 50-315 DONALD C CODK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 87:2050007 Forwards 1E Emergency Preparedness Insp Repts 50-315/82-18 & 50-315/82-18 on 821020-22 Discussion of excessive weaknesses rncl H1ND.J A Division of Emergency Preparedness & Operational Support 82/11/15 DDLAN.J E American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co 3pp 16313,336 24% Fiche 50-315,82/11/15.8212060009
- --8212050017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of tay functions & locations PLOSKI.T J. SMITH.M J. AXELSON.W L. Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339 24X Fiche 50-315,82/11/15.8212060009
- B212010033 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/11/24 Document Management Branch Lp 16889 106 24X Fiche 50-315,82/11/24, 8212010033.

- --8212010037 Forwards public version of revised emergency plan implementing procedures, including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 009 re maint of emergency plan procedures Receipt form encl # Indiana & Michigan Electric Co 82/11/16 GRIMES, B NRC No Detailed Affiliation Given ip 16289 107 24X Fiche 50-315,82/11/24,8212010033
- -B212010037 Public version of revised emergency plan implementing procedures, including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 007 re maint of emergency plan procedures

 * Indiana & Michigan Electric Co 82/11/16 23pp 16289 108 24% Fiche 50-315.82/11/24.8212010033
- BP12080087 Releases public version of revised pages to emergency plan procedures index FELTON, JM Division of Rules and Records 82/12/02 Document Managament Branch 1p 16367 190 24X Fiche 50-315.82/12/02. (12)12080089
- -4:212080091 Forwards public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits Receipt form enc! a Indiana & Michigan Electric Co 62/11/23 GRIMES, B NRC - No Detailed Affiliation Given ip 16367 191 24X Fiche 50-315,62/12/02.8212080089
- -3212080096 Public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits * Indiana & Michigan Eloctric Co 82/11/23 8pp 16367 192 24X Fiche 30-315,82/12/02.8212080089
- GP12150323 Releases public version of revision to emergency plan implementing procedures FELTON. J Division of Rules and Records 82/12/07 Document Management Branch ip 16446 219 24X Fiche 50-315.82/12/07, 12/12/50323
- -B212150329 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure PMP 2080 EPP 014, "Personnel Injury" & Revision 1 to PMP 2081 EPP 008, "Emergency Medical Plan Ouidelines "Receipt form encl
 * Indiana & Michigan Electric Co 82/12/01 GRIMES, B NRC No Detailed Affiliation Olven in 16446 220 24X
 Fiche 50-315, 82/12/07, 8212150323
- --0212150335 Public version of Revision 1 to Emergency Plan Implementing Procedure PMP 2080 EPP 014. "Personnol Injury" & Revision 1 to PMP 2081 EPP 008, "Emergency Medical Plan Guidelines"
 Indiana & Michigan Electric Co 82/12/01 12pp 16446 222 24X Fiche 50-315.82/12/07.8212150323
- GP12160001 Forwards proposed Tech Spec Page 6-il for performing audits of energency preparedness programs & safeguards contingency plans (security plan). In response to Generic Ltrs 82-17 & (2-23) ICMITER R S Indiana & Michigan Electric Co 82/12/09 DENTON H R Office of Nuclear Reactor Regulation. Director 2pp 16446-141 24X Fiche 50-315,82/12/09.8212160001
- ~B212160002 Proposed Tech Spec Page 6-11 for performing audits of emergency preparadness programs & safeguards contingency plans (security plan) * Indiana & Michigan Electric Co 82/12/09 3pp 16446 143 24X Fiche 50-315,82/12/09.8212160001
- E:12220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility
 KEPPLER.J G Region 3. Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 30-000, 82/12/16, 8212220306
- J Insurance & indemnity information
- GP12100253 Forwards Endorsement 41 to MAELU Policy MF-79. Endorsement 51 to NELIA Policy NF-206 & Endorsements 10 & 9 to NELIA Hinders EB-64 & EB-45. respectively ALEXICH. M P American Electric Power Service Corp B2/12/07 BENTON H R Office of Nuclear Reactor Regulation, Director Bpp 16376 117 24X Fiche 50-315,82/12/07.8212100253
- B212290213 Forwards Endorsements 95 to NELIA Policy NF-206;45 to MAELU Policy MF-79;1.2:3 & 4 to NELIA Policy N-64:1.2:3 & 4 to MAELU Policy M-64:1.2:3 & 5 to NELIA Policy N-45 & 1:2:3 & 4 to MAELU Policy M-45 & 1:2:3 & 4 to MAELU Policy M-45 BUCKLES. J Marsh & McLennan.inc , M & M Nuclear Consultants, Inc Div 82:12:22 SALTZMAN. J Assistant Director for State & Licenser Relations 43pp 16578 089 24X Fiche 90-315,82/12/22.8212290213

P Operating license stage documents & correspondence

- 8212020002 Notification of 821202 meeting w/util & Exion in Bethesda, MD to discuss outstanding questions on Exxon analysis method for Cycle 4 roload WIGGINION, D. Operating Reactors Branch 1 82/11/24 VARGA, S.A. Operating Reactors Branch 1 2pp 163(7 083 24X Fiche 50-315, 82/41/24, 8212020002
- 8212030125 Follows up 821014 ltr re emergency request for relief from lech Spec 3 5 2 on safety injection gump operability requirements Repairs to south safety injection pump completed & pump returned to operable status on 821016 HUNTER, R S Indiana & Michigan Electric Co 82/11/29 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 16303 318 24X Fiche 50-315, 82/11/29, 8212030125
- -8212030145 Application to amend License DPR-58, requesting relief from Tech Spec 3 5 2 to allow add1 10 days to restore south safety injection pump to operable status Safety evaluation encl Class III amend fee forthcoming HUNTER.R S Indiana & Michigan Electric Co 82/10/14 DENTON.H R Office of Nuclear Reactor Regulation. Director VARGA.S A Operating Reactors Branch 1 4pp 16303 322 24X Fiche 50-315,82/11/29,8212030125
- GP12060072 Forwards completed questionnaire in response to Generic Ltr 82-22 re steam generator tube integrity HUNTER,R S Indiana & Michigan Electric Co 82/11/27 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp 16314 318 14X Fiche 30-315.82/11/29,8212640072
- 8/12090296 Forwards Phase II b response to Encl 3.8ection 2 4 of DG Eisenhut 801222 itr re overhead handling sys operation for control of heavy loads.per NURGO-0612 Two aperture cards available in PDR HUNTER, R S Indiana & Michigan Electric Co 82/12/03 DENTON, H R Defice of Nuclear Reactor Regulation, Director 16pp 16365 190 24X Fiche 50-315,82/12/03,8212090296
- G212100270 Forwards revised inservice test program for safety-related pumps Tech Spec change request reflecting revisions will be provided under separate cover HUNTER, R 8 Indiana & Michigan Electric Co 82/12/06 DENTON, H R DEFICE of Nuclear Reactor Regulation. Director 2pp 16377 OB2 24X Fiche 50-315,82/12/06. B212/00290
- --8212100300 Revision 1 to pump inservice test program

 # Indiana & Michigan Electric Co B2/11/30 3pp 16377 084
 24% Fiche 50-315, 82/12/06, 8212100270
- 8212210125 Forwards update on activities re NUREG-0737. Items II B 3, "Post-Accident Sampling," II F 1, "Noble Gas Monitoring" & III D 3 4, "Control Room Habitability "Info supersedes previous correspondence on topics HUNTER, R 8 Indiana & Michigan Electric Co 82/12/14 DENTON, H & Uffice of Nuclear Reactor Regulation, Director 4pp 16485 130 24X Fiche 30-315, 82/12/14, 8212210125
- 8212270136 Forwards description of coding errors recently discovered in CLABIA computer program Errors associated only w/modeling of flame propagation between containment compartments Coding errors do not affect previously transmitted analyses HUNTER.R S Indiana & Michigan Electric Co 82/12/17 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 16538 137 24X Fiche 50-315.82/12/17.8212270136

Q Inspection reports, IE Bulletins & correspondence

- 8:08190240 IE Builetin 82-03, Revision 1, "Stress Cracking in Thirk-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BAR Plants " Svc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8268190240
- 80'08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl.

 COBB.L I Division of Fuel Pacilities, Materials & Safeguards Consolidated Edison Co of New York, Inc 110pp 16372 142 244 Fiche 50-000.82/11/05.8208190245
- 8P12O40009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 621020-22 Discussion of excessive weaknesses encl HINDIJA Division of Emergency Preparedness & Operational Support 82/11/15 DOLANIJE American Electric Power Service Corp DOLANIJE Indiana & Michigan Electric Co 3pp 16313 336 24X Fiche 50-315, 82/11/15, 8212060009

- --B212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on B21020-22 No moncompliance noted Major areas inspected emergency preparedness exercise Involving observation of key functions & locations PLOSKI, T J , SMITH, M J , AXELSON, M L Division of Emergency Preparedness & Operational Support B2/11/10 32pp 16313 339 24X Fiche 50-315,82/11/15,8212060009
- 8208190251 l£ Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000 82/11/18,8208190251
- 820B190256 IE Info Notice 82-44. "Defective & Obsolete Combination Padlocks " Svc list encl DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- BJ08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards BZ/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc IISpp 14411 317 24X Fiche 50-000.82/12/03.8208190259
- 8P08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Syc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- 8P12280242 Forwards IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820801-0915 & notice of violation (Insp date changes noted throughout rept)
 SPESSARD, R L Division of Project & Resident Programs 82/12/10 DGLAN, J E American Electric Power Service Cong DDLAN, J E Indiana & Michigan Electric Co. 2pp 16561 184 24X Fiche 50-315, 82/12/10, 8212280242
- --8212280246 Notice of violation from insp on 820801-0914 SPESSARD.R L Division of Project & Resident Programs 82/12/10 2pp 16561 186 24X Fiche 50-315,82/12/10,8212280242
- --8212280251 IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820801-0915
 Nancompliance noted failure to remove add1 charging pump &
 safety injection pump circuit breakers from electrical power
 circuit within 1-h
 SMANSON, E R. DUGRY, N E . HILLIAMS, D Division of Project &
 Resident Programs 82/12/03 17pp 16561 188 24X
 Fichs 50-315,82/12/10,8212280242
- 8212270330 Forwards IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 & notice of violation SPESSARD.R & Division of Project & Resident Programs 82/12/15 DDLAN.J E American Electric Power Service Corp DOLAN.J E Indiana & Michigan Electric Co 2ps 16586 188 24% Fiche 50-315,82/12/15.8212290330
- --9212290331 Notice of violation from insp on 820916-1031 SPESSARD: L Division of Project & Resident Programs 82/12/15 Spp 16586 190 244 Fiche 30-4015 82/12/15 8212290330
- --8212270335 IE Insp Repts 50-315/82-17 & 50-316/82-17 on 820916-1031 Noncompliance noted failure to comply w/action requirement & failure to follow clearance permit sys procedure SNANSON.E R. DUBRY.N E . BOYD, D C Division of Project & Resident Programs 82/12/15 11pp 16586 172 24X Fiche 50-315,82/12/15,8212270330
- 8P08190867 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYOUNG: R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8PO8190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" But list enci JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp. 14628-293 P4X Fiche 50-000, 82/12/20, 82/8190268

- 8212280165 Forwards add1 info re inservice insp weld program Revised pages to Table 1.Class 2 components & welds & to Table 2 for components & welds for which relief requested encl.

 HERINGER F Indiana & Michigan Electric Co 82/12/20 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 43pp 16563 335
 24X Fiche 50-315-82/12/20, 8212280165
- R Periodic operating reports & related correspondence
- 8212290419 Forwards monthly operating rept for Oct 1982 & revised repts for Aug & Sept 1982 SMITH W O Indiana & Michigan Electric Co 82/11/12 Office of Resource Management, Director Ip 16584 317 24X Fiche 50-315.82/11/12,8212290419

- --8212290434 Revised monthly operating rept for Sept 1982 TETZLAFF, A L. Indiana & Michigan Electric Co 82/10/04 lp 14584 327 24X Fiche 50-315,82/11/12,8212290419
- B212200119 Forwards monthly operating rept for Nov 1982 SMITH,W G Indiama & Michigan Electric Co 82/12/14 Office of Resource Management, Director 1p (6470 176 24X Fiche 50-315, 82/12/14,8212200119
- S Reportable occurrences, LERs & related correspondence
- GP12020283 Forwards LER 82-099/03L-0 SMITH,W G Indiana & Michigan Electric Co 62/11/23 KEPPLER.J G Region 3. Office of Director ip 16288 251 24x Fiche 30-315.62/11/23.8212020283
- --8212020289 LER 82-097/03L-0 on 821025, during Mode 1, Channel 2 tower containment pressure indication (PPP-320) found reading approx 1/2 lb higher than other channels Caused by water collecting in transmitter junction box causing corrosion PALMER, R A Indiana & Michigan Electric Co 82/11/23 Region 3, Office of Director 1p 16288 252 24X Fiche 50-315,82/11/23,821202283
- 8P12060031 RD on 821123, essential svc water sys motor operated valve WMD-753 failed to open Caused by reverse operation or valve due to incorrect installation of cable feeding motor control ctr during 821117 design change SMITH.N G Indiana & Michigan Electric Co 82/11/24 KEPPLER, J G Region 3, Office of Director 2pp 16313 271 24X Fiche 50-315,82/11/24,8212060031
- 8/12100251 Forwards LER 82-101/01T-0 SMITH.N G Indiana & Michigan Electric Co 82/12/03 KEPPLER, J 6 Region J. Office of Director 1p 16376 046 24X Ficha 50-315, 82/12/03, 8212100251
- --8212100259 LER 82-101/017-0 on 821123, motor operated valve WMQ-753 to west turbine driven auxiliary feed pump would not open Caused by motor damage to NMQ-753 & exhaust fan 1HV-AFP-12 for pump room operating in reverse PALMER, R A Indiana & Michigan Electric Co 82/12/03 Region 3, Office of Director 2pp 16376 047 24X Fiche 50-315, 82/12/03, 8212100251
- G212100322 Forwards LER 82-100/03L-0 SMITH.W G Indiana & Michigan Electric Co 82/12/03 KEPPLER.J G Region 3. Office of Director 1pt 16377 064 24X Ficha 50-315.82/12/03.8212100322
- --B212100327 LER 82-100/03L-0 on 821f05.during normal operation, fire door 437 found inoperable Caused by door scraping on stair step Clearance between door & step improved PIEHL, R H Indiana & Michigan Electric Co 82/12/03 Region 3, Office of Director ip 16377 065 24% Fiche 50-315,82/12/03. 8212100322
- G212170283 Forwards LERs 82-102/03L-0 & 82-103/03L-0 SMITH-W G Indiana & Michigan Electric Co 82/12/08 KEPPLER, J G Region 3, Office of Director ip 16458 049 24X Fiche 50-315, 82/12/08.8212170283

- --8212170292 LER 82-102/03L-0 on 82111B, Prynalarm fire detector in auxiliary bldg Zone 2 alarmed Caused by low setpoint Detector assembly cleaned, verified & returned to svc Setpoint adjusted PALMER, R A Indiana & Michigan Electric Co 82/12/08 Region 3, Office of Director 1p 16458 050 24% Fiche 50-315.82/12/08, 8212170283
- --82:2170296 LER 82-103/03L-0 on 82:127, fire door 387 at entrance to quadrant 2 of auxiliary bldg around containment found in nonconservative configuration Caused by active leaf of double doors closing before inactive leaf WIZNER, D.G. Indiana & Michigan Electric Co. 82/12/08 Region 3, Office of Director 1p. 16458-051 24% Fiche 50-315,82/12/08,82/12/70883

BOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8212060009 Forwards IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of excessive weaknesses oncl. HIND. J.A. Division of Emergency Preparedness & Operational Support

HIND, J A Division of Emergency Preparedness & Operational Support B2/1/15 DDLAN.J E American Electric Power Service Corp 3pp 16313-336 24X Fiche 50-315,82/11/15.8212060009

- --8212060017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations PLOSKI,T J Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339 24X Fiche 50-315,82/11/15,8212060007
- 단기:2010033 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 82/11/24 Document Management Branch 1p 16289 106 24X Fiche 50-315,82/11/24, 3212010033
- 8212010037 Forwards public version of revised emergency plan implementing procedures including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 009 re maint of emergency plan procedures Receipt form encl # Indiana & Michigan Electric Co 82/11/16 GRIMES, B NRC Na Detailed Affiliation Given ip 16289 107 24X Fiche 50-315,82/11/24,8212010033
- ~-8212010039 Public version of revised emergency plan implementing procedures, including Procedures PMP 2080 EPP 011 re natural emergency guidelines & PMP 2082 EPP 009 re maint of emergency plan procedures
 # Indiana & Michigan Electric Co 82/11/14 23pp 16289 108 24% Fiche 50-315,82/11/24,8212010033
- 8912080089 Releases public version of revised pages to emergency plan procedures index FELTON, J M Division of Rules and Records 62/12/02 Document Management Branch 1p 16367 190 24% Fiche 50-315,82/12/02, 6212080089
- --8212080091 Forwards public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits Receipt form enci * Indiana & Michigan Electric Co 82/11/23 GRIMES, D NRC - No Detailed Affiliation Given ip 16367 191 24X Fiche 50-315,82/12/02.8212080089
- --G212080096 Public version of revised Pages 6-13 to emergency plan procedures index re list of exhibits * Indiana & Michigan Electric Co 92/11/23 8pp 16367 192 24% Fiche 50-315,82/12/02/8212080089
- B::12150323 Releases public version of revision to emergency plan implementing procedures FELTON.J K Division of Rules and Records 82/12/07 Document Management Branch 1p 16446 219 24X Fiche 50-315,82/12/07, 8212150323
- --8212150329 Forwards public version of Revision 1 to Emergency Plan
 Implementing Procedure PMP 2080 EPP 014, "Personnel Injury"
 \$\foatine Revision 1 to PMP 2081 EPP 008, "Emergency Medical Plan
 Guidelines" Receipt form encl
 \$\pi\$ Indiana & Michigan Electric Co \(\text{82}\)/2/2/01 GRIMES, B NRC No
 Debailed Affiliation Given 1p 16446 220 24X
 Fiche 50-315,82/12/07,8212150323

- --8212150335 Public version of Revision i to Emergency Plan Implementing Procedure PMP 2080 EPP 014. "Personnel Injury" & Revision i to PMP 2081 EPP 008. "Emergency Medical Plan Guidelines." * Indiana & Michigan Electric Co. 82/12/01 12pp 16446 222 24X Fiche 50-315,82/12/07,8212150323
- 8212140001 Forwards proposed Tech Spec Page 4-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan), in response to Generic Ltrs 82-17 & 82-23 MUNTER, R S Indiana & Michigan Electric Co 82/12/09 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 2pp 16446 141 244 Fichs 50-315, 82/12/09, 8212160001
- --9212160002 Proposed Tech Spec Page 6-11 for performing audits of emergency preparedness programs & safeguards contingency plans (security plan)

 * Indiana & Michigan Electric Co 82/12/09 3pp 16446 143 24x Fiche 30-315.82/12/09.8212160001
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site energency operations facility KEPPLER.J O Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16, 8212220306

J. Insurance & indemnity information

- 82:12100253 Forwards Endorsement 41 to MAELU Policy NF-79, Endorsement 51 to NELIA Policy NF-206 & Endorsements 10 & 9 to NELIA Binders EB-64 & EB-45, respectively ALEXICH, MP American Electric Power Service Corp 82/12/07 DENTON, HR Office of Nuclear Reactor Regulation. Director 8pp 16376 117 24X Fiche 50-315,82/12/07,8212100253
- G212290213 Forwards Endorsoments 55 to NELIA Policy NF-206,45 to MAELU Policy MF-791,2,3 & 4 to NELIA Policy N-641,2,3 & 4 to NELIA Policy N-641,2,3 & 4 to NELIA Policy N-645 & 1,2,3 & 4 to NELIA Policy N-45 & 1,2,3 & 4 to MELIA Policy N-45 & 1,2,3 & 4 to MAELU Policy M-45 BUCKLES,J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. DIV B2/12/22 SALTMAN,J Assistant Director For State & Licenser Relations 43pp 14578 087 24X Fichs 50-315, 89/12/22,8212290213
- P Operating license stage documents & correspondence
- BS:12060072 Forwards completed questionnaire in response to Generic Ltr B2-22 re steam generator tube integrity HUNTER: R 5 Indiana & Michigan Electric Co 82/11/27 DENTON, H R Uffice of Nuclear Reactor Regulation. Director 2pp 16344 318 24X Fiche 80-315, 82/11/29, 8212060072
- G212090296 Forwards Phase II b response to Encl 3. Section 2.4 of DG Eisenhut B01222 itr re overhead handling sys operation for control of heavy loads, per NUREG-0612 Two aperture cards available in PDR HUNTER.R S Indiana & Michigan Electric Co B2/12/03 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 16pp 16365 190 24X Fiche 50-315.82/12/03,8212090296
- GP:12100290 Forwards revised inservice test program for safety-related pumps. Tech Bpec change request reflecting revisions will be provided under separate cover. HUNTER, R. 8. Indiana & Michigan Electric Co. 82/12/06. DENTON, H. R. Uffice of Nuclear Reactor Regulation. Director. 2pp. 16377-082-24X Fiche 50-315,82/12/06,8212100290.
- --8212100300 Revision i to pump inservice test program * Indiana & Michigan Clectric Co 82/11/30 3pp 16377 OB4 24X Fiche 50-315,82/12/06,8212100270
- BH2160573 Bummary of 821202 meeting wilicenses & Exxon re fuel reload for Cycle 4 Tech Bpec description encl WIGOINTON.D L. Operating Reactors Branch 1 82/12/07 Operating Reactors Branch 1 140pp 14466 039 24X Fiche 50-316
- 8212140167 Responds to question re basis for full ECCB flow used in LOCA-ECCS analysis in XN-NF-82-35. Suppl 1.per 821208 telcon, JENBERLS E Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/12/09 ORR.F. Reactor Systems Branch 2pp. 16409 361 24X Fiche 80-316.82/12/09.8212140167
- BP12170179 Application for amend to License DPR-74, consisting of proposed changes to Tech Specs allowing Cycle 4 operation w/Exxon fuel at reactor thermal power level of 3,411 MHt HUNTER.R 8 Indiana & Michigan Electric Co 82/12/09 DENTON,H R Office of Nuclear Reactor Regulation. Director 2pp 16462 038 24X Fiche 50-316,82/12/09,8212/170179

- --B21217018B Proposed changes to Tech Specs allowing Cycle 4 operation w/Exxon fuel at reactor thermal power level of 3.411 MWt Indiana & Michigan Etectric Co 82/12/09 20pp 16462 040 24X Fiche 50-316,82/12/07,8212170179
- G212210125 Forwards update on activities re NUREG-0737. Items II B 3. "Post-Accident Sampling." II F 1. "Noble Gas Monitoring" & III D 3 4, "Control Room Habitability " Info supersedes previous correspondence on topics HUNTER: R S Indiana & Michigan Electric Co 82/12/14 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 4pp 16495 130 24x Fiche 50-315.82/12/14.8212210125
- 8212270336 Forwards description of roding errors recently discovered in CLASIX computer program Errors associated only w/modeling of flame propagation between containment compartments Coding errors do not affect previously transmitted analyses HUNTER:R 8 Indiana & Michigan Electric Co 82/12/17 DENTON, H R Office of Nuclear Reaction Regulation. Director App (6538-137-24X Fiche 50-315.82/12/17.82)2270136
- 8212280404 Forwards Table 1 providing reactivity parameters for Unit 2, consistent u/parameters used in FBAR issued in Jul 1982 OMSLEY.9 F Exon Nuclear Co., Inc. (subs of Exon Corp.) 82/12/20 LICCARDD, R. Reactor Systems Branch 2pp 16560 024 24X Fiche 50-316,82/12/20.8212280404

G Inspection reports. IE Bulletins & correspondence

- 8208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list enci DEYBUNG, R.C. Director's Office Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- 0208190245 IE info Notice 62-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolyminescent Dosimeters " Syc list enc!
 CDB0.1, I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24% Fiche 50-000, 82/11/05, 8208190245
- 8212060009 Forwards IE Emergency Preparadness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 Discussion of extessive weaknesses enc!
 HIND.J A Division of Emergency Preparadness & Operational Support 92/11/15 DULAN.J E American Electric Power Service Corp DULAN.J E Indiana & Michigan Electric Co 3pp 16313 336 24X Fiche 50-315, 82/11/15, 8212060009
- --8212040017 IE Emergency Preparedness Insp Repts 50-315/82-18 & 50-316/82-18 on 821020-22 No noncompliance noted Major areas inspected emergency preparedness exercise involving observation of key functions & locations PLOSKITU , SMITH M J . AXELSON, M L Division of Emergency Preparedness & Operational Support 82/11/10 32pp 16313 339 24X Fiche 50-315,82/11/15,8212060009
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16/11 179 24X Fiche 50-000, 82/11/18, 8208190251
- B20B190256 IE Info Notice B2-44. "Defective & Obsolete Combination Padlocis " Bvc list encl DEYOUNO,RC Director's Office, Office of Inspection and Enforcement B2/11/26 Cansolidated Edison Co of New York, Inc 127pp 14411 065 24X Fiche'50-000.B2/11/26.820B190256
- 62/08190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc. 355pp 16387 028 24X Ficha S0-000, 82/11/30,8208190257
- 8208190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUND,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Commolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets "Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 249 Fiche 50-000,82/12/03,8208190261

- 8212280242 Forwards IE Insp Repts 50-315/82-15 & 50-316/82-15 on 820801-0915 & notice of violation (Insp data changes noted throughout rept)

 SPESSARD, R L Division of Project & Resident Programs 82/12/10 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 16561 184 24X Fiche 50-315, 82/12/10, 8212280242
- --8212280246 Notice of violation from insp on B20801-0914 SPESSARD,R L Division of Project & Resident Programs 82/12/10 2pp 16561 186 24X Fiche 50-315,82/12/10,8212280242
- ---8212280251 IE Insp Repts 50-315/82-15 & 50-314/82-15 on 820801-0915
 Noncompliance noted failure to remove addi charging pump & safety injection pump circuit breakers from electrical power circuit within 1-h
 SWANSON.E R, DUBRY,N E, WILLIAMB,D Division of Project & Resident Programs 82/12/03 17pp 16561 188 24X
 Fiche 50-315,82/12/10/8212280242
- 8212290330 Forwards IE Insp Repts 50-319/82-19 & 50-316/82-17 on 820916-1031 & notice of violation SPESSARD, R L Division of Project & Resident Programs 92/12/15 DDLAN.J E American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co 2pp 16586 188 24X Fiche 50-315.82/12/15,8212270330
- --B212290335 IE Insp Repts 50-315/82-19 & 50-316/82-19 on 820916-1031 Noncompliance noted failure to comply w/action requirement & failure to follow clearance permit aus procedure SKANSON.E R , DUBRY.N E , BOYD.D C Division of Project & Resident Programs 82/12/15 lipp 16586 192 24X Fiche 50-315.82/12/15, 8212290330
- 8208190267 IE Info Natice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " 8vc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, lnc 127pp 16628 171 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Inco Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORBAN.E. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16428 293 247 Fiche 50-000.82/12/20.8208190268
- SP12280165 Porwards add1 info re inservice insp wold program Revised pages to Table 1.Class 2 components & welds & to Table 2 for components & welds for which relief requested enc!
 HERING-R F Indiana & Michigan Electric Co 82/12/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 43pp 16563 335
 24X Fiche 50-315.82/12/20.8212280165
- 8212280310 Forwards description of post-irradiation fuel surveillance program implemented for Exxon 17x17 fuel HUNTER.R 5 Indiana & Michigan Electric Co 82/12/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 16561 138 P4X Fiche 50-316.82/12/22.8212280310
- R Periodic operating reports & related correspondence
- 8212290217 Forwards monthly operating rept for Oct 1982 SMITH.W G Indiana & Michigan Electric Co 82/11/12 Management Information Branch tp 14578/072 24X Fiche 50-316,82/11/12, 8212290217
- --8212290228 Monthly operating rept for Oct 1982 QILLETT, W T , LEASE, R S , SVENSSON, B A Indiana & Michigan Electric Co 82/11/02 6pp 16578 073 24X Fiche 50-316, 82/11/12, 8212270217
- BP12200056 Forwards monthly operating rept for Nov 1982
 BMITH U 0 Indiana & Michigan Electric Co 82/12/14 Management
 Information Branch 1p 16470 016 24X Fiche 50-316,82/12/14,
 R212200054
- -- B212200065 Monthly operating rept for Nov 1982 OILLETT, W T Indiana & Michigan Electric Co 82/12/02 App 16470 017 24X Fiche 50-316, 82/12/14,8212200056
- S Reportable occurrences, LERs & related correspondence
- 8212020229 Forwards LER 82-08B/O3L-0 SMITH W 0 Indiana & Michigan Electric Co 82/11/23 KEPPLER, J G Region 3, Office of Director 1p 16274 090 24X Fiche 50-316, 82/11/23, 8212020229

- --B212020232 LER 82-088/03L-0 on 821029.containment sample isolation valve ECR-21 would not cycle Caused by defective solenoid coil Coil replaced PALMER.R A Indiana & Michigan Electric Co 82/11/23 Region 3, Office of Director 1p 16274 091 24X Fiche 50-316.82/11/23.8212020229
- BP1206004B Forwards LERs 82-089/03L-0 & 82-090/03L-0 SMITH.W 0 Indiana & Michigan Electric Co B2/11/24 KEPPLER.J 0 Region 3. Office of Director in 16314 009 24X Fishe 50-316.82/11/24.821206004B
- --B212060057 LER 82-089/03L-0 on 821027, fire damper 2-HV-ACES-1 failed to close during automatic actuation of carbon dioxide fire protection sys in auxiliary cable vault Caused by failure of guillotine door to close due to dent in door Door repaired MIZNER, D O Indiana & Michigan Electric Co 82/11/24 Region 3, Office of Director ip 16314 010 24X Fiche 50-316,82/11/24, 82/2040048
- --8212060060 LER 82-090/03L-0 on 821026, stem leakage discovered at valve CS-386 in boric acid makeup sys Caused by hole in diaphragm of ITT Orinnell 2-inch valve Cause of hole unknown Diaphragm replaced & flow path returned to svc PICHL:R H . PALMER.R A Indiana & Michigan Electric Ca 82/11/24 Region 3, Office of Director ip 16314 011 24X Fiche 50-316.82/11/24.8212060048
- 8212100177 RO on 821201.west centrifugal charging pump rendered inoperable following mad on east & west centrifugal pump common mini flow line Caused by cut made on pressurized portion of piping Investigation in progress SMITH.W G Indiana & Michigan Electric Co 82/12/02 KEPPLER.J G Region 3. Office of Director 2pp 16373 331 24X Fiche 50-316.82/12/02.8212100177
- G2:2140156 Forwards LER 62-091/03L-0 SMITH-W @ Indiana & Michigan Electric Co 92/12/06 KEPPLER.J G Region 3. Office of Director ip 16410-176 24X Fiche 50-316, 62/12/06. 8212140156
- --9212140165 LER BP-091/03L-O on B21105, during steam generator blowdown, radiation monitor R-19 alarmed, indicating flow continued through Loop I sample valve DCR-301 Caused by leakage due to valve stroke not maintaining positive seat Valve replaced WIZNER, D G , PALMER, R A Indiana & Michigan Electric Co B2/12/06 Region 3. Office of Director ip 16410 177 24X Fiche 50-316, 92/12/06, 82(2140156
- 8.º12170224 Forwards LER's 82-092/03L-0,82-093/03L-0, & 82-094/03L-0 SMITH,W 0 Indiana & Michigan Electric Co 82/12/08 KEPPLER, J & Region 3, Office of Director ip 16459 323 24X I iche 50-316,82/12/08,8212170224
- --B21217022B LER 82-092/03L-O on 821109, during normal operation, ouxiliary cable vault (Zone 11) experienced inadvertent carbon dioxide discharge & Pyralarm detector alarming Caused by water entering base Detector & base replaced PALMER.R A Indiana & Michigan Electric Co 82/12/08 Region 3. Office of Director 1p 16459 324 24X Fiche 50-316.88/12/08, 8212170224
- --8212170232 LER 82-093/03L-0 on 821121.following shutdown, RC8 dose equivalent I--131 concentration exceeded Tech Specs Cause not stated Fuel sipping will be performed during refueling operation PALMER.R A Indiana & Michigan Electric Co 82/12/08 Region 3. Office of Director App 16459 325 24X Fiche 50-314. 82/12/08.8212170224
- --B212170237 LER B2-094/03L-O on B21122, during Mode 5 operation, RCS temp decreased below Tech Spec limit for charging pump operation Caused by loss of four reactor coolant pumps & RHR trains Two of three pumps racked out KRAUSE.DF Indiana & Michigan Electric Co B2/12/0B Region 3. Office of Director 1p 16459 331 24X Fiche 50-316.B2/12/0B, 5212170224
- GP:12170267 Forwards LER 82-095/03L-0 SMITH.W G Indiana & Michigan Electric Co 82/12/10 KEPPLER, J G Region 3, Office of Director ip 16457 167 24X fiche 50-316, 82/12/10.8212170267
- 8212170268 LER 82-095/03L-O on 821111.door to U-2 CD diesel engine fuel oil day tank room designated as Tech Spec related fire door found held open Cause not determined Door secured & redesignated as nonsafety-related fire door SVENSSON.B A Indiana & Michigan Electric Co 82/12/10 Region 3. Office of Director Epp 16457 168 24X Fiche 50-316. 82/12/10.8212170267

- 8212290355 Forwards LER 82-096/01T-0 SMITH W 9 Indiana & Michigan Electric Co 82/12/15 KEPPLER, J G Region 3, Office of Director 1p 16586 220 24X Fiche 50-316, 82/12/15, 8212290355
- --B212290358 LER 82-096/01T-0 on 821201, west centrifugal charging pump rendered inoperable by incorrect cut on mini flow line from pump Caused by poor communication between plant & contractor Cut locations will be verified prior to work BEILMAN, TP Indiana & Michigan Electric Cn 92/12/15 Region 3. Office of Director 2pp 16586 221 24X Fiche 50-316, 82/12/15, 82 12290355
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8212010042 Releases public version of revised emergency response plan implementing procedures FELTON, J M Division of Rules and Records 82/11/24 Document Management Branch ip 16289 131 24X Fiche 50-317,82/11/24, 0212010042
- --8212010050 Forwards public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 8 re immediate action alert & ERPIP 3 7 re immediate action site emergency Receipt form encl

 * Beltimore Gas & Electric Co 82/11/12 CLARK.R A Operating Reactors Branch 3 ip 16289 132 24X Fiche 50-317,82/11/24,8212010042
- --B212010055 Public version of revised emergency response plan implementing procedures including Procedures ERPIP 3 8 resimmediate action -- alert & ERPIP 3 9 resimmediate action -- site emergency

 * Saltimore Gas & Electric Co 82/11/05 19pp 16289 133 24X
 Fiche 50-317, 82/11/24, 8212010042
- GP12130065 Responds to Generic Ltr B2-17, "Inconsistency Between Requirements of 10CFR50 54(t) & STS for Performing Audits of Emergency Preparedness Programs "Difference between "audit" & "review" should be clarified LUNDVALL.A E Baltimore Gas & Electric Co B2/11/29 CLARK.R & Operating Reactors Branch 3 3pp 16391 165 24X Fiche 50-317. 82/11/29, 8212130065
- BP12080491 Confirms info provided in 821202 telcon re status of emergency operations facility (EOF) EOF located on company property, 1 mile from plant structures
 OLSON, R C Baltimore Oas & Electric Co 82/12/03 CLARK, R A
 Operating Reactors Branch 3 ip 16352 262 24X
 Fiche 50-317, 82/12/03, 8212080491
- 8212300204 Releases public version of change to revised list of effective pages to emergency response plan implementing procedures FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16624 158 24X Fiche 50-317,82/12/20,82/2300204
- --B212300209 Forwards public version of Change 5 to Revision 8 of list of effective pages to emergency response plan implementing procedures Receipt form encl

 * Daitimore Gas & Electric Co B2/12/08 CLARK, R A Operating Reactors Branch 3 ip 16624 159 24X Fiche 50-317,82/12/20,8212300204
- --B212300211 Public version of Change 5 to Revision B of list of affective pages to emergency response plan implementing procedures * Baltimore Cas & Electric Co B2/12/0B 17pp 16624 161 24X Fiche 50-317,82/12/20:8212300204
- GB12280200 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 MARTIN, T T Division of Engineering & Technical Programs B2/12/21 BONIAKER, N J Baltimore Gas & Electric Co 2pp 16562 073 24X Fiche 50-317,82/12/21,8212280200
- --8212280208 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 Corrective actions withheld (ref 10CFR73 21) BOWMAKER,N J Baltimore Qas & Electric Co 82/10/27 MARTIN,T T Division of Engineering & Technical Programs ip 16562 075 24X Fiche 50-317,82/12/21.8212280200

- P Operating license stage documents & correspondence
- 8212080012 Responds to 820922 request to withhold info submitted in "Results of Eddy Current Testing on Guide Tubes at Calvert Cliffs Unit 1 After Cycle 5 " Document withheld

CIIFFS Unit I After Cycle 5 " Dacument withheld (ref 10CFR2 790) CLARK.R A Operating Reactors Branch 3 82/11/03 LUNDVALL.A E Haltinore Oas & Electric Co 3pp 16367 179 24X Fiche 50-317.82/11/03.8212080012

- 8212040071 Responds to Generic Ltr 82-22 Plant reduction or outage has not been attributed to leak of maint on steam generators Occupational radiation exposure resulting from routine insp
- LUNDVALL, A E Baltimore Gas & Electric Cd 82/11/24 EISENHUT, D 6 Division of Licensing tp 16316 106 24X Fiche 50-317.82/11/24, 8212060071 82/11/24 FISENHUT.D 0
- 8212070082 Advises that CEN-220(B)-P, "Supplemental Info on FATES3 Stored Energy Conservatism," will be withheld per 10CFR2 790

10CFR2 790 CLARK,R A Operating Reactors Branch 3 B2/fi Baltimore Oas & Electric Co 3pp 16356 271 Fiche 50-317,82/f1/24,8212070082 B2/11/24 LUNDVALL, A E 36 271 24X

- G:12070105 Forwards SER & technical evaluation of "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 I & II B 4 for Calvert Cliffs, Units I & 2 " Units 1 & 2
- CLARK, R A Operating Reactors Branch 3 82/11/24 LUNDVALL, A E Baltimore Gas & Electric Co 4pp 16354 289 24x Fiche 50-317, 82/11/24, 8212070105
- --8212070115 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4.Calvert Cliffs, Units I & 2." technical evaluation rept * Science Applications; Inc. NRC-03-82-096 SAI-186-029-19 82/08/31 NRC No Detailed Affiliation Given 13pp 16354 293 24X Fiche 50-317,82/11/24,8212070105
- 8912070054 Forwards documentation satisfying each criterion of NUREO-0737 Item II B 3. "Post-Accident Sampling." per NRC 820630 request Wome oversize drawing Aperture card is available in PDR Ayarianie in PDR LUNDVALL.A E Baltimore Gas & Electric Co 82/11/30 CLARK,R A Uperating Reactors Branch 3 9pp 16326 001 24X Fiche 50-317.82/11/30.8212070054
- 6912090032 Forwards notice of consideration of issuance of amend re-util 820929 application for revised pressurizer level Tech CLARK,R A Operating Reactors Branch 3 82/11/30 LUNDVALL,A E Baltimors 0as & Eletric Co 3pp 16384 260 24X Fiche 50-317,82/11/30,82/12090032
- --8212090036 Notice of consideration of issuance of amend for revised pre-souriter level Tech Specs CONNER.E L. Operating Reactors Branch 3 82/11/30 4pp 16384 263 24% Fiche 50-317, 82/11/30-8212090032
- G:12210447 Forwards "Integrated Leak Rate Test Rept"
 LUNDVALL, A E Baltimore Oas & Electric Co 82/11/30 CLARK, R A
 Uperating Reactors Branch 3 1p 16486 231 24X
 liche 50-317, 82/11/30.8212210447
- 8212210448 "Integrated Leak Rate Test Rept"

 * Baltimore Gas & Electric Co 82/11/30 47pp 16486 232 24x
 Fiche 50-317,82/11/30,8212210447
- BP12080197 Discusses ambiguity re use of terminology "review" & "audit" in Generic Ltr 82-23 & 10CFR73 40 ANSI Std N18 7-1976 used for strict definition of terms BCKMAKER.N J Baltimore Gas & Electric Co 82/12/02 CLARK.R A Operating Reactors Branch 3 3pp 16354 007 24% riche 50-317,82/12/02,8212080197
- 82/08190263 Generic Ltr 82-32 to all PWR licenses re-potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re-subject requirements Comments requested within 30 days of itr. Svc list encl EISENNUT.D 0 Division of Licensing 82/12/09. Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Gnoffe 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENHUT, D. O Division of Licensing 82/12/10 Yankee & Electric Cd 27pp. 16690 035 24X Fiche 50-000, 82/12/10, 82/12/40103 8212140103

- 9212170252 Informs that source range flux monitoring capability now scheduled to be provided at alternate shutdown panel for Unit 1 by end of Fall 1983 refueling outage & for Unit 2 by end or Spring 1984 outage LUNDVALL.A E Baltimore Gas & Electric Co B2/12/10 CLARK.R A Operating Reactors Branch 3 2pp 16456 209 24X Fiche 50-317.82/12/10.8212170252
- 8212300041 Forwards safety evaluation & technical evaluation repts supporting environ qualification of safety-related electrical equipment Justification for continued operation & qualification or replacement of equipment requested CLARK, R A Operating Reactors Branch 3 82/12/16 LUNDVALL, A E Baltimore Oas & Electric Co 3pp 16624 288 24% Fiche 50-317, 82/12/16, 8212300041
- --8212300048 Safety evaluation supporting environ qualification of safety-related electrical equipment Plans for qualification or replacement of equipment in Topics I 8,11 A & II B requested
 - equater Office of Nuclear Reactor Regulation, Director 82/12/16 5pp 16624 291 24X Fiche 50-317.82/12/16.8212300041
- --8210220483 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Gualification SERs (F-11 & B-60). Calvert Cliffs Nuclear Power Plant Unit I." technical galvation rept
 PAHDEY,B Franklin Institute/Franklin Resparch Center
 NRC-03-79-118 TER-05257-487 82/10/13 LE,N B NRC - No
 Petailed Affiliation Given 650pp 16624 276 24X
 Fiche 50-317,82/12/16,8212300041
- --8210220470 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & 8-60), Calvert Cliffs Nuclear Power Plant Unit 2," technical Calvert Cliffs Nuclear Power Plant Unit 2." technical evaluation rept
 PANDEY, 8 Franklin Institute/Franklin Research Center
 NRC-03-79-118 TER-05257-488 82/10/13 LE, N B NR:
 Detailed Affiliation Given 681pp 16627 001 24X
 Fiche 50-317,82/12/16.8212300041 NRC - No
- GP:122:04:20 Forwards results of review of TMI Action Items I A 1 3, "Limit Overtime," II E 1 1, "Short Term Auxiliary Feedwater Sys Evaluation," & II E 1 2 & II K 3 3 Tech Spec change under teview
 LUNDVALL, A E Baltimore Gas & Electric Go 82/12/17 EIGENHUT, D g
 Division of Licensing 3pp 16493 075 24X Fiche 50-317,82/12/17, 8212210420
- 8212830274 Forwards response to NRC questions on pressurized level limiting conditions Tech Specs Table presenting summary of evaluation of impact of changing water level for each DBE LIPPOLD, W J Baltimore Gas & Electric Co 82/12/17 CLARK, R A Operating Reactors Branch 3 8pp 16508 265 Fiche 50-317, 82/12/17, 8212230274
- @ Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Flants "Syc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112p 16462 163 24% Fiche 50-000, 82/10/28 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermolyminescent Dosimeters " Syc list COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 16372 142 24% Fiche 50-000, 82/11/05, 8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDANIE L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24 Fiche 50-000, 82/11/18, 8208190251
- S212020003 Notification of 821214 significant licensee meeting w/util in Lusby, MD to discuss SALP MCCABE.E Region 1, Office of Director 82/11/19 Region 1, Office of Director 1p 16317 089 24X Fiche 50-317, 82/11/19, 8212020003
- 8212100007 Forwards IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1107 & notice of violation 8TAROSTECKI,R Division of Project & Resident Programs 82/11/24 LUNDVALL, A E Saltimore Gas & Electric Co 2pp 16379 133 24X Fiche 50-317, 82/11/24, 8212100007

- --B2:2100010 Notice of violation from insp on B2:012-1109 * Region 1, Office of Director B2/11/24 ip 16379 135 24X Fiche 50-317, B2/11/24, B2:2100007
- --B212100013 IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109
 Noncompliance noted Unit 2 placed in Mode 6 w/o operable
 audible indication of source range neutron flux in control
 room
 ARCHITZEL,R E , TRIMBLE,D C , MCCABE,E C Division of Project &

ARCHITZEL,R E , TRIMBLE,D C , MCCABE,E C Division of Project & Resident Programs 82/11/17 13pp 16379 136 24X Fiche 50-317,82/11/24,8212100007

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list enci BEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/24 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDBH.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- B212060285 Ack receipt of 821028 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-07 & 50-318/82-07 STAROSTECKI, R Division of Project & Resident Programs 82/12/02 LUNDVALL, A E Baltimore Gas & Electric Co 1p 16312 059 24X Fiche 50-317, 82/12/02, 8212060285
- --8212060293 Responds to NRC 820929 ltr re violatione noted in IE Insp Repts 50-317/82-07 & 50-318/82-07 Corrective actions audit by QA of selected plant procedures which incorporate Tech Spet limits completed LUNDVALL.A E Baltimore Qas & Electric Co 82/10/28 STARGOTECKI.R Division of Project & Resident Programs 3pp 16312 060 24X Fiche 50-317.82/12/02.8212060285
- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEVOUNO,R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- B20B190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list and JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- B212160384 Forwards response to B20914 request to suppl response to IE Bulletin 80-11, "Magonry Wall Design " One oversize drawing encl Aperture card available in FDR LUNDVALL.A E Baltimore Gas & Electric Co 82/12/13 CLARK.R A Operating Reactors Branch 3 97pp 16442 151 24X Fiche 50-317.82/12/13.8212160384
- B20B190267 IE Info Notice B2-49, "Correction for Bemple Conditions for Air & Oas Monitoring " Bvc list encl
 DEYDUNO,R C Director's Office, Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, 820B190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- B212280200 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 MARTIN,TT Division of Engineering & Technical Programs 82/12/21 BOWMAKER,N J Baltimore Gas & Electric Co 2pp 16962 093 24X Fiche 50-317,82/12/21,8212280200
- ---B2122B0208 Responds to NRC B21008 ltr re violations noted in IE Bafaguards Insp Repts 50-317/B2-18 & 50-318/B2-22 Corrective actions withheld (ref 10CRR73 21)
 BOWMAKER,N J Baltimore Qas & Electric Co B2/10/27 MARTIN,T T. Division of Engineering & Technical Programs ip 16562 095
 24X Fiche 50-317,82/12/21,8212280200
- R Pariodic operating reports & related correspondence
- 8212220208 Forwards monthly operating repts for Nov 1782 LOTITO,E M Baltimore Oas & Electric Co 82/12/15 Director's Office, Office of Inspection and Enforcement 1p 16518 317 24) Fiche: 50-317, 82/12/15, 8212220208

- --8212220210 Monthly operating repts for Nov 1982 LOTITO.E Baltimore Gas 5 Electric Co B2/12/15 10pl 16518 318 24X Fiche 50~317, 82/12/15.8212220208
- B Reportable occurrences, LERs & related correspondence
- BP12160259 Forwards LER 81-034/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 81/06/01 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 1p 16442 356 24X Fichs 50-317, 81/06/01, 8212160259
- --B212160270 LER B1-034/03L-Q on B1050B emergency diesel generator li failed to reach rated speed while returning generator to svc Caused by fuel racks & operating linkages stocking & damaged set screw rubbing against linkage LAGIEMSKI, J S. HUSEBY, D E Baltimore Qas & Electric Co 81/06/01 Region i. Philadelphia. Office of the Director (B1/03/01) ip 16442 357 24X Fiche 50-317,81/06/01,8212160459
- B212040149 Nonroutine radiological environ operating rept on B2102/.

 oyster semples collected from Camp Conog revealed presence
 of Ag-110m.less than Aug samples Probably due to
 depuration
 FUHRMAN.GR Baltimore Gas & Electric Co B2/11/23 HAYNES,R C
 Region 1, Office of Director 3pp 16313 146 24X
 Fiche 50-317,82/11/23,8212060149
- 8212060196 Forwards LER 82-066/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 82/11/24 HAYNES,R C Region 1, Office of Director ip 16313 196 24X Fiche 50-317, 82,11/24, 8212060196
- --B212060206 LER 82-066/03L-0 on B21026, reactor protective sys channel B trip units for highpower, thermal margin/low pressure & axial shape index bypassed when Tc failed high Caused by noise producing transmitter circuitry oscillations LAGIEMSKI, J S , HINKLE, L S Baltimore Qas & Electric Co B2/11/24 Region I, Office of Director Ip 16313 [97 P4X Fiche 50-317, 82/11/24.8212060196
- 82:2060301 Forwards LER 82-065/03L-0 RUGSELL.L B Baltimore Gas & Electric Co 82/11/24 HAYNES.R C Region 1. Office of Director 1p 16312 119 24X Fiche 50-317.82/11/24.8212060301
- ---B212060306 LER 82-065/03L-0 on 821025, electrical bus supplying power to containment atmosphere particulate & gaseous radioactivity monitoring says de-energized Caused by ground on tendon inspectation power cable, induced by high winds

 JUNOE, M A. DASSOL F. Balt; more 0as & Electric Co. 82/11/24

 Region 1. Office of Director ip 16312 120 24X

 Fiche 50-317, 82/11/24, 8212060301
- GP120B0441 Forwards LER 82-072/04X-0 RUSSELL-L B Baltimore Gas & Electric Co 82/11/29 HAYNES.R C Region 1. Office of Director ip 16352 112 24X Fiche 50-317, B2/11/29, 82120B0441
- --8212080448 LER 62-072/04X-0 on 821027, higher than normal background radioactive Ag-110m levels found in oyster samples taken from Camp Canoy location on 821123 Caused by natural tendency of oysters to concentrate environ silver BROBST, 0 E Baltimore Gas & Electric Co 82/11/29 Region 1, Office of Director ip 16352 113 24X Fiche 50-317,82/11/29, 8212080441
- G212080456 Corrects 821123 ltr re nonroutine radiological environ operating rept Capacity factor for Oct 1782 was 105 20%, not /2 51% FUHRMAN, G R Baltimore Oas & Electric Co 82/11/27 HAYNES, R C Region 1, Office of Director ip 16352 163 24% Fiche 50-317, 82/11/27, 8212080456
- 8212060305 PND-1-82-077 on 821201.contractor employee intentionally poisoned Junch & placed in refrigerator Employee notified licenses of actions upon discovering lunch missing Warning announced on page sys No known harm occurred ARCHITEL. MCCABE Region 1. Office of Director 82/12/01 ip 16312 111 24% Fiche 50-317.82/12/01.8212060305
- 8912140125 Forwards LER 82-070/01T-0 RVBSELL.L B Baltimore Gas & Electric Co 82/12/02 HAYNES,R C Region 1, Office of Director 1p 16408 236 24X Fiche 50-317,82/12/02,8212140125
- --B212140131 LER 82-070/01T-0 on 821118, chemical vol & cuntrol isolation signal (CVCIS) sys declared inoperable since generation of CVCIS may be prohibited by single failure Cause not stated Corrective action ongoing to verify sys design adequacy PAVIS,0 S , WENGER, L O Baltimore Gas & Electric Co 82/12/02 Region 1, Office of Director 3pp 16408 237 24X Fiche 50-317, 82/12/02,8212140125

- 8212210378 Forward: LER 82-048/03L-0 RUSSELL:L D Baltimore 9as & Electric Co 82/12/08 HAYNES:R C Region 1. Office of Director 1p 16494 302 24X Fich: 50-317.62/12/08.8212210378
- --8212210384 LER 82-068/03L-0 on 821109, during Hode 1, pawer lost to 120-volt ac vital bus Caused by inadvertent opening of & input breaker to inverter supplying bus Mod will be performed to inverter cabinets to prevent inadvertent breaker opening WENDERLICH, R L Baltimore Oas & Electric Co 82/12/08 Region 1, Office of Director 2pp 16494 303 24X Fiche 50-317, 82/12/09, 8212210378
- 8212210043 Forwards LER 82-071/03:-0 RUSSELL/L B Baltimore Gat & Electric Co 82/12/09 HAYNES/R C Region 1. Office of Director 1p 16490 224 24X Fiche 50-317.82/12/09.8212210043
- --8212210048 LER 62-071/03L-0 on 621109.during reactor trip recovery. charging pump 12 breaker usuld not close Caused by dirty breaker charging motor cutoff switch contacts Coll replaced & cutoff switch contacts cleaned UNNOE, M A · BASSOL F Baltimore Cat & Electric Co 82/12/09 Region I. Office of Director 2pp 16490 225 24X Ficha 50-317.62/12/09.8212210043
- 8212210076 Forwards LER 82-073/03L-0 RUSSELL,L B Daltimore Gas & Electric Co 82/12/09 HAYNES.R C Region 1. Office of Director 1p 16485 250 24x Fiche 50-317.92/12/09.8212210076
- --B212210080 LER 82-073/03L-0 on 821110, pressurizer level deviated from program level by more than +/-5% several times Caused by loading of main turbine generator Reanalysis for justification of relaxation of Tech Specs in progress JUNOS.M A Baltimore Oas & Electric Co. 82/12/09, Region 1. Office of Director 1p 16485 251 24% Fichs 50-317, 82/12/09, 82/12210076
- 8212210274 Forwards LER 82-067/03L-0 RUSSELL,L 8 Baltimare Gas & Electric Co 82/12/07 HAYNES.R (Region 1. Office of Director 1p 16497 010 24X Fiche 30-317, 82/12/09.8212210274
- --8212210303 LER 82-067/03L-0 on 821109, safety injection tank high level alarm annunciated despite indicated level within Tech Spec limits Caused by level transmitter 1-LT-34) being out of callby Transmitter to be replaced during next cold shutdown PAVIS, 0 S , RAYNOR, J & Baltimore Gas & Electric Co 82/12/09 Region 1. Office of Director 2pp 16497 011 24X Fiche 50-317,82/12/09.8212210294
- SP12290275 Forwards updated LER 82-071/01X-1 RUSSELL.L B Baltimore Oas & Electric Co 82/12/16 HAYNES.R C Region 1, Office of Director 1p 16581 061 24X Fiche 50-317, 82/12/16.8212290275
- ---8212290282 Updated LER 82-071/01X-1 on 821109 charging pump 12 breaker would not close rendering pump inoperable Caused by dirty breaker charging motor cutoff switch contacts resulting in long coil charging time Burnt coil replaced JUNGELM A. RASBOLL F. Baltimore Oas & Electric Co. 82/12/16 Region 1. Office of Director 2pp 16581-062 24X Fiche. S0-317, 82/12/16. 8212290275
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 80:2010042 Releases public version of revised emergency response plan implementing procedures FELTOM J M Division of Rules and Records 82/11/24 Document Management Branch ip 14289 131 24X Fiche 80-317,82/11/24, 82:2010042
- --8212010050 Forwards public version of revised emergency response plan implementing procedures including Procedures ERPIP 3 2 rational immediate action alert & ERPIP 3 9 rational immediate action site emergency Receipt form encl

 * Baltimore Gas & Electric Co 62/11/12 CLARK, R A Operating Reactors Branch 3 1p. 16289 132 24X Fiche 50-317,82/11/24,8212010042
- --8212010055 Public version of revised emergency response plan implementing procedures, including Procedures ERPIP 3 8 reimmediate action sleet & ERPIP 3 9 re immediate action site emergency

 4 Baltimore Gas & Electric Go 82/11/05 19pp 16289 133 24X Fiche 50-317,82/11/24,8212010042

- 8212130065 Responds to Generic Ltr B2-17. "Inconsistency Between Requirements of 10CFR50 54(t) & STS for Performing Audits of Emergency Preparedness Programs " Difference between "audit" & "review" should be clarified LUNDVALL: A E Baltimore Cas & Electric Co 92/11/29 CLARK: R A Operating Reactors Branch 3 3pp 16391 165 24X Fiche 50-317.82/11/29.8212130065
- 8212080491 Confirms info provided in 821202 telton re status of emergency operations facility (EOF) EOF located on company property, in sile from plant structures
 CLSDN.R G Baltimore Oas & Electric Co 82/12/03 CLARK.R A
- B212300204 Releases public version of change to revised list of effective pages to emergency response plan implementing procedures
 FELTEN.J M Division of Rules and Records 82/12/20 Documen Hanagement Branch 1p 16624 158 24X Fiche 50-317, 82/12/20, 8212300204
- ~-8212300209 Forwards public version of Change 5 to Revision 8 of list of effective pages to emergency response plan implementing procedures Receipt form encl * Baltimore Cas & Electric Co 82/12/08 CLARK.R A Operating Reactors Dranch 3 ip 16624 159 24X Fiche 50-317,82/12/20,8212300204
- --B212300211 Public version of Change 5 to Revision 8 of list of effective pages to emergency response plan implementing procedures

 * Baltimore Gas & Electric Co 82/12/08 17pp 16624 161 2/4X Fiche 80-317,82/12/20,8212300204
- GP12280200 Ack receipt of 821027 ltr informing NRC of steps taken to carrect violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 MARTIN T Division of Engineering & Technical Programs 82/12/21 BUMMAKER, N J Baltimore Gas & Electric Co 2pp 16562 093 24X Fiche 50-317.82/12/21,8212280200
- --8212280208 Responds to NRC 821008 Itr re violations noted in It Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 Corrective actions withheld (ref 10CFR73 21) BOKMAKER,N J Baltimore Gas & Electric Go 82/10/27 MARTIN, F 7 Division of Engineering & Technical Programs (p. 16562 095 24% Fiche 50-317.82/12/21.8212280200
- P Operating license stage documents & correspondence
- 8212080031 Provides relief from ASME Boiler & Vessel Code, Section XI requirement re hydrostatic test pressure, found impractical in 820830 application Acceptable alternate test method approved in accordance w/105FR50 55a CLARK, R A Operating Reactors Branch 3 82/11/19 LUNDVALL, A E Raltimore Gas & Electric Co 2pp 16367 147 24X Fiche 50-318,82/11/19,8212080031
- --8212080036 SER supporting 820830 request for relief from pressure testing requirements of ASME Boiler & Pressure Vessel Code after mod of auxiliary feedwater sys piping & companents # Office of Nuclear Reactor Regulation, Director 82/11/19 3pp 16367 149 24X Fiche 50-318.82/11/19.8212080031
- --8212080040 Notice of granting of relief from ASMC Section XI, inservice insp requirements
 CLARK: R A Derating Reactors Branch 3 82/11/19 2pp
 16367 152 24X Fithe 50-318, 82/11/19, 8212080031
- B212060071 Responds to Generic Ltr B2-22 Plant reduction or outage has not been attributed to leak of maint on steam generators Occupational radiation exposure resulting from routine inspining initial LUNDVALL.A E Baltimora Gas & Electric Co B2/11/24 EISENHUT.D G Division of Licensing ip 16316 106 24% Fiche 50-317.82/11/24, B212060071
- GRI2070105 Forwards SER & technical evaluation of "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 & X II B 4 For Calvert Cliffs, Units I & 2 " CLARK.R A Operating Reactors Branch 3 82/11/24 LUNDVALL.A E Baltimore Gas & Electric Co 4pp 16354 289 24X Fiche 50-317.82/11/24,8212070105
- --8212070115 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 i & II B 4, Calvert Cliffs. Units i & 2." technical evaluation rept * Science Applications, Inc. NRC-03-82-096 SAI-186-029-19 82/08/31 NRC No Detailed Affiliation Given 13pp 16354 293 24X Fiche 50-317.82/11/24,8212070105

- B212070034 Forwards documentation satisfying each criterion of NUREG-0737. Item II B 3, "Post-Accident Sampling," per NRC B20630 request Widne oversize drawing Aperture card is available in PDR LUNDVALL.A E Baltimore Gas & Electric Co B2/11/30 CLARK, R A Operating Reactors Brench 3 9pp 16326 001 24X Fishe 50-317. 82/11/30. B212070054
- 8212070032 Forwards notice of consideration of issuance of amend re util 820729 application for revised pressurizer level Tech Specs CLARK.R A Operating Reactors Branch 3 82/11/30 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 16384 260 24X Fiche 50-317.82/11/30.8212070032
- ~-8212090036 Notice of consideration of issuance of amend for revised pressurizer level Tech Specs CONNER.E L Operating Reactors Branch 3 82/11/30 4pp 16384 263 24X Fiche 50-317,82/11/30.8212090032
- G212090050 Forwards notice of consideration of issuance of amend re util G21015 application for Cycle 5 operation CLARK, R A Operating Reactors Branch 3 B2/11/30 LUNDVALL, A C Baltimore Oas & Electric Co 2pp 16384 237 24X Fiche 50-318, 82/11/30, 8212090050
- --9212070053 Notice of consideration of issuance of amend for Cycle 5 operation CLARK,R A Operating Reactors Branch 3 82/11/30 4pp 16384 240 24X Fiche 50-318,82/11/30,8212090050
- GP12080197 Discusses ambiguity re use of terminology "review" & "audit" in Generic Ltr 82-23 & 10CFR73 40 ANBI 8td Ni8 7-1976 used for strict definition of terms RORMAKER.N J Baltimore Gas & Electric Co 82/12/02 CLARK.R A Gperating Reactors Branch 3 3pp 16354 007 24X Fiche 50-317.82/12/02.8212080197
- OP12200088 Forwards responses to NRC questions re 821015 amend to Cyrle 5 license application LUNDVALL.A E Baltimore Gas & Electric Co 82/12/06 CLARK.R A Operating Reactors Branch 3 app 16474 303 24X Fiche 50-318, 82/12/06, 8212200088
- 8/12270542 Forwards notice of consideration of issuance of amends to License DPR-67 Amend revises Tech Specs re auxiliary feedwater sys CLARK, R A Operating Reactors Branch 3 82/12/06 LUNDVALL, A E Baltinore Oas & Electric Co 3pp 16546 346 24X Fiche 50-318.82/12/06.8212270542
- --8212270546 Notice of consideration of issuance of amends to License DPR-69 CLARK,R A Operating Reactors Branch 3 82/12/06 4pp 16545 349 24X Fiche 50-318,82/12/06.8212270542
- B: 08190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Ecience Applications. Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list enci EISE(MHUT, D & Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc 27pp 16629 247 24X [iche 50-000,82/12/09,8208190263
- EP12140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PURS (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Syc list encl FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q Division of Licensing 82/12/10 Yankee Atomic FISEMHUT, D Q DIVISION ON THE PURPLE PURPLE
- G212170252 Informs that source range flux monitoring capability now scheduled to be provided at alternate shutdown panel for Unit 1 by end of Fall 1983 refueling outage & for Unit 2 by end of Spring 1984 outage LUNDVALL.A E Baltimore Gas & Electric Co 82/12/10 CLARK.R A Operating Reactors Branch 3 2pp 16456 209 24X Fiche 50-317, 82/12/10, 8212170252
- 8212300041 Forwards safety evaluation & technical evaluation repts supporting environ qualification of safety-related electrical equipment Justification for continued operation & qualification or replacement of equipment requested CLARK.R A Operating Reactors Branch 3 82/12/16 LUNDVALL.A E Naltinore Oas & Electric Co 3pp 16624 288 24X Fiche 50-317,82/12/16,9212300041

- --B210220470 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-II & B-60), Calvert Cliffs Nuclear Power Plant Unit 2." technical evaluation rept PAMDEY.8 Franklin Institute/Franklin Research Center NRC-03-79-119 TER-05257-480 82/10/13 LE.N B NRC No Detailed Affiliation Given 681pp 16627 001 24X Fiche 50-317.82/12/16.8212300041
- 8P12210420 Forwards results of review of TMI Action Items I A 1 3, "Limit Overtime." II E 1 i, "Short Term Auxiliary Feedwater Sys Evaluation" & II E 1 2 & II K 3 3 Tech Spec change under review
 LUNDVALL.A E Baltimore Gas & Electric Co 82/12/17 EISENHUT, D G Division of Licensing 3pp 16493 075 24X Fiche 50-317, 82/12/17, 8212210420
- 82:12230274 Forwards response to NRC questions on pressurized level limiting conditions Tech Specs Table presenting summary of evaluation of impact of changing water level for each DBE uncl LIPPOLD.W J Baltimore Gas & Electric Co B2/12/17 CLARK,R A Operating Reactors Branch 3 Bpp 16308 265 24X Fiche 50-317.82/12/17.8212230274
- B212230312 Responds to NRC question on Cycle 5 instrument loop uncertainties Uncertainty includes allowance for drift based on plant experience LIPPOLD.W J Baltimore Oas & Electric Co 82/12/17 CLARK.R A Operating Reactors Branch 3 Opp 16507 071 24X Fiche 50-318,82/12/17,8212230312
- G212270120 Responds to NRC question re Cycle 5 instrument loop uncertainties Instrument loop uncertainty is added algebraically to setpoint of plant parameter used in safety analysis which yields value stated in Tech Specs LTPPOLD.N J Baltimore Gas & Electric Co 62/12/17 CLARK.R A Operating Reactors Granch 3 2pp 16583 226 24X Fiche 50-318,82/12/17,8212270120
- 8212280199 Application for amend to License DPR-69, changing measurement range for Tech Spec Table 3 3-9 re remote shutdown manitoring instrumentation Class III fee encl LUNDVALL, A E Baltimore Gat & Electric Co 82/12/23 CLARK, R A Decrating Reactors Branch 3 4pp 16562 289 24X Fiche 50-318, 62/12/23.8212280199
- --B212280202 Proposed changes to Tech Spec Table 3 3-9 re measurement range changes to remote shubdown monitoring instrumentation * Baltimore Oas % Electric Co 82/12/23 1p 16562 273 24X Ficke 50-318,82/12/23,8212280199
- 821.22901.22 Forwards response to NRC question re impact of NRC-imposed FATEE3 grain size restriction on Cycle 5 operating limits LIPPOLD.W J Baltimore Gas & Electric Co 82/12/27 CLARK.R A Operating Reactors Branch 3 2pp 16583 208 24X Fiche 50-318.82/12/27.821.22901.22
- @ Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fither 50-000, 82/10/28, 8208190240
- B20B190245 IE Info Natice 82~42. "Defects Observed in Panasonic Model BOI & Model BOZ Thermoluminescent Dosimaters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 30-000, B2/11/05, B20B190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Livercise Requirements" Syc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edition Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 82:2020003 Notification of 82:214 significant licensee meeting w/util in Lusby.MD to discuss SALP NCCABE,E Region i. Office of Director 82/11/19 Region I. Office of Director 1p 16317 089 24X Fiche 50-317,82/11/19, 82:2020003
- B212080031 Provides relief from ASME Boiler & Vessel Code, Section XI requirement re hydrostatic test pressure, found impractical in 820830 application Acceptable alternate test method approved in accordance w/10CFR50 55a CLARK, R A Operating Reactors Branch 3 82/11/19 LUNDVALL, A E Baitimore Oas & Electric Co 2pp 14367 147 24X Fiche 50-318, 82/11/19, 8212080031

- --8212080036 SER supporting \$20830 request for relief from pressure testing requirements of ASME Boiler & Pressure Vessel Code after mod of auxiliary feedwater sup piping & components & Orfice of Nuclear Reactor Regulation, Director \$2/11/19 3pp 16367 149 24X Fiche 50-318.82/11/19.8212080031
- --B212080040 Notice of granting of relief from ASME Section XI. inservice insprequirements
 CLARK.R A Operating Reactors Branch 3 82/11/19 2pp
 16367 152 24X Fiche 50-318.82/11/19.8212080031
- 8212100007 Forwards IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/11/24 LUNDVALLA E Baltimore Gas & Electric Co 2pp 16379 133 24X Fiche 50-317.82/11/24.8212100007
- --9212100010 Notice of violation from insp on 821012-1109
 * Region 1. Office of Director 82/11/24 Ip 16379 135 24X
 Fiche 50-317.82/11/24.8212100007
- 8212100013 IE Insp Repts 50-317/82-27 & 50-318/82-23 on 821012-1109 Noncompliance noted Unit 2 placed in Mode 6 w/a operable audible indication of source range neutron flux in control roam ARCHITZEL, R E. TRIMBLE, D C. MCCABE, E C. Division of Project & Resident Programs 82/11/17 13pp 16379 136 24X Fiche 50-317, 82/11/24, 8212100007
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Jun 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 62/08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Mat! "Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- GP12060285 Ack receipt of 821028 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/82-07 & 50-318/82-07 STARGSTECKL/R Division of Project & Resident Programs 82/12/02 LUNDVALL/A E Baltimore Gas & Electric Co ip 16312 059 24X Fiche 50-317.82/12/02/8212060285
- --8212060293 Responds to NRC 820929 ltr re violations noted in IE Insp Repts 50-317/82-07 & 50-318/82-07 Corrective actions audit by OA of selected plant procedures which incorporate Tech Spec limits completed LUNDVALL. A E Baltimore Gas & Electric Co 82/10/28 STAROSTECKIR & Division of Project & Resident Programs Spp 16312 060 24X Fiche 50-317,82/12/02,8212060285
- 8708190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, In 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 RE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Boctets " Svc list encl JORDAN-E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24 Fiche 80-000, 82/12/03.8208190261
- 8212170349 Informs of results of Nov 1982 steam generator eddy current tests Two tubes, one each in steam generators 21 & 22 sludge areas, showed excessive tube wall loss Tubes removed from svc by plugging ends w/mschanical plugs
 LUNDVALL: A E Baltimore Gas & Electric Co 82/12/09 DEYBUNG, R C Director's Office. Office of Inspection and Enforcement 2pp 16456 113 24X Fiche 50-318, 82/12/09, 82(2170349)
- 8212160384 Forwards response to 820914 request to suppl response to IE Builetin 80-11. "Masonry Wall Design " One oversite drawing encl Aperture card available in FDR LUNDVALLA E Baltimore Gas & Electric Co 82/12/13 CLARK, R A Operating Reactors Branch 3 97pp 16442 151 24X Fiche 50-317,82/12/13,8212160384
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000, 82/12/16, 8208190267

- 8208170268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list ancl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14428 293 £47 Fiche 50-000,82/12/20,8208170248
- B212280200 Ack receipt of B21027 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 MARTIN.T T Division of Engineering & Technical Programs 82/12/21 BOWMAKER.N J Baltimore Cas & Electric Co 2pp 16562 093 24% Fiche 50-317,82/12/21,8212280200
- --B212280208 Responds to NRC 821008 ltr re violations noted in IE Safeguards Insp Repts 50-317/82-18 & 50-318/82-22 Corrective actions withheld (ref 10CFR73 21)
 BUWMAKER,N J Baltimore Gas & Electric Co 82/10/27 MARTIN,T 1
 Division of Engineering & Technical Programs ip 14562 095
 24X Fiche 50-317,82/12/21,8212280200
- 8212290338 Forwards fee for inservice insp program request for reliaf from ASKE Code Section XI re hydrostatic pressure testing requirements for mode made to safety-related sys Request clarified & flow diagrams enci LUNDVALL, A E Baltimore Cas & Electric Co 82/12/21 CLARK, R A Operating Reactors Branch 3 Spp 14584 212 24X Fiche SO-318, 82/12/21, 8212290338
- R Periodic operating reports & related correspondence
- 8912220208 Forwards monthly operating repts for Nov 1982 LOTITOLE M Baltimore Gas & Electric Co 82/12/15 Director's Orfice, Office of Inspection and Enforcement 1p 16518 317 2/40 Fiche 50-317, 82/12/15, 8212220208
- --0212220210 Monthly operating repts for Nov 1982 LOTITO:E Baltimore Gas & Electric Co 82/12/15 10pp 16518 318 24X Fiche 50-317, 82/12/15, 8212220208
- S Reportable occurrences, LERs & related correspondence
- 8212060149 Nonroutine radiological environ operating rept on 821027, nyster samples collected from Camp Conoy revealed presence of Ag-110m less than Aug samples Probably due to depuration FUHRMAN, G.R. Baltimore Gas & Electric Co. 82/11/23 HAYNES, R.C. Region I, Office of Director 3pp. (6313-146-24X Fiche 90-317, 82/11/23, 8212060147
- \$212080456 Corrects \$21123 ltr re nonroutine radiological environ operating rept Capacity factor for Oct 1982 was 105 20%, not 72 51%
 FURRYAN, G R Baltimore Gas & Electric Co 82/11/29 HAYNES, R C. Region 1, Office of Director ip 16352 163 24%
 Fiche 50-317, 82/11/29, 8212080456
- 8212060305 PNO-I-82-077 on 821201, contractor employee intentionally poisoned lunch & placed in refrigerator Employee notified licensee of actions upon discovering lunch missing Warning ennounced on page sys No known harm occurred ARCHITZEL, MCCABE Region 1, Office of Director 82/12/01 lp 16312 111 24x Fiche 50-317,82/12/01,8212060305
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- GD12010092 Releases public version of revision to emergency plan implementing procedure FELTON-J H Division of Rules and Records 82/11/24 Document Management Branch ip 16289 338 24X Fiche 50-320, 82/11/24, 8212010092
- --8212010097 Public version of Revision 5 to Emergency Plan Implementing Procedure 1054 6, "Add! Assistance & Notification "
 General Public Utilities GPU Bervice Corp 82/11/05 24pp 16289 337 24X Fiche 50-320, 82/11/24, 8212010092
- B21213031B Summarizes dose reduction at facility in three phases per 821118 presentation Implementation will require close coordination of recovery efforts consistent w/ALARA practices
 KANOA:B K General Public Utilities GPU Service Gorp 82/12/03 BARRETT.L H TMI Program Defice 4pp 16389 278 24x Fiche 50-320.82/12/03.82/2130318

- 8/12220415 Forwards listings of major employers within facility the theory planning ione, in response to NRC request MCKELVY, 0 A General Public Utilities GPU Service Corp 82/12/08 KANTOR, F NRC No Detailed Affiliation Given 7pp 16504 001 24X Fiche 50-289,82/12/08.8212220415
- --8212220421 Forwards listings of hotels, motels, campgrounds & marinas within facility emergency planning zone MCKELVY.G A General Public Utilities -- GPU Service Corp 82/11/16 KANTOR.F NRC Na Detailed Affiliation Given 7pp 14504 008 24X Fiche 50-289, 82/12/08, 8212220415
- Gr12160745 Releases public version of ravised emergency plan implementing procedures FELTON. JM Division of Rules and Records 82/12/10 Document Management Branch Ip 16464 165 24X Fiche 50-320.82/12/10, 7212160745
- --8212160752 Forwards public version of revised Emergency Plan Implementing Procedures 1054-16. "Contaminated Injuries/ Radiation Overexposure" & 1054-21. "Emergency Repair/ Operations" SHAVER.L. General Public Utilities - GPU Service Corp. 82/12/03 DENTOW.H R. NRC -- No Detailed Affiliation Given 1p. 16464-166 24% Fiche 50-320,82/12/10.8212160745
- --0212160764 Public version of revised Emergency Plan Implementing Procedures 1054 16, "Contaminated Injuries/Radiation Overerposure" & 1054 21, "Emergency Repair/Operations " KANGA.B K General Public Utilities - GPU Service Corp 62/11/2 10pp 16464 167 24X Fichs 50-320,82/12/10,8212160745
- 97:12270149 Forwards interim security precautions, pending completion of requested clarification of security plan Encl withheld (ref 10CFR2 790 & 10CFR3 21)
 KANGALB K General Public Utilities GPU Service Corp 62/12/20 SNYDER, B J TMI Program Office Ip 16538 340 24X [1che 50-320, 62/12/20, 62(2270149)
- G?/2280385 Ack receipt of 821108 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 10-320/82-07
 MARTIN.T T Division or Engineering & Technical Programs 82/12/2 KANGA.B K General Public Utilities GPU Service Corp 2pp 14559 018 24X Fiche 50-320.82/12/21.8212280385
- --8212280390 Responds to NRC 821908 ltr re violations noted in II: Safeguards Insp Rept 50-320/82-09 Corrective actions untibheld (ref 10CFR2 790 & 73 21) KANGALS K. General Public Utilities - GPU Service Corp. 82/11/08 MAYNESIR C. Region I. Office of Director ip 16559 020 24X Fiche 50-320.82/12/21.8212280385

G Adjudicatory correspondence

- GP12140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of 8vc encl JOHNGRUD. J H Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 167 24X Fiche 50-000,82/12/0B, 8212140186
- G:12140438 Order extending time until 821227 for TM1 & Peach Bottom intervenors to file petition for review of ALAH-701 CHILK.S J Office of the Secretary of the Commission B2/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 249 [sche 50-000.82/12/13.8212140438]
- BP12210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed BORDENICK, B M Hearing Branch 3 82/12/16 JOHNSRUD, J Affiliation Unknown 2pp 16486 005 24X Fiche 50-000,82/12/16,8212210009
- 8212300134 Petition for review of consolidated radon proceedings
 Cormission should grant financial assistance to intervenors,
 should reopen record on all issues & remand case for full
 consideration Certificate of Byc encl
 JOHNSRUD.J H Environmental Coalition on Nuclear Power 82/12/27,
 Commissioners 15pp 16578 112 24X Fiche 50-000,82/12/27,
 821230134

P Operating license stage documents & correspondence

8005071094 Research Info Ltr 82 transmits preliminary results of research on socio-economic effects of TML accident Direct economic effects include interrupted local production & reduced local income & employment BUDN:TT.R J Gffice of Nuclear Regulatory Research, Director RIL-082 80/02/29 DENTON.H R Gffice of Nuclear Reactor Regulation, Director 4pp 16565 348 24X Fiche 50-320,80/02/29,8005071094

- 8312060395 Supplemental response to 820906 FDIA request for eight categories of documents Forwards documents listed in App A for Items 4 & 5 No other documents subj to request located FELTON. J M Division of Rules and Records 82/11/08 AUDIN.L Affiliation Unknown 2pp [6322 342 24X Fiche 50-320,82/11/08,8212060395
- --B212060403 Items of interest re CRBR fuel cycle environ review spent fuel reprocessing b TMI-2 waste mgt task force for wk ending 820707 • Office of Nuclear Material Safety & Safeguards, Director 82/07/07 1p 16322 145 24% Fiche 50-000, 82/11/08, 8212040395
- 8212010366 Concurs that adequate radiological controls considered in 820721 plan to remove radioactive matis in once through steam generator 2B Detailed procedures (per Tech Spec 6 B 2) required for approval of final sys operation BARRETT, L H TMI Program Office B2/11/16 KANGA, B K General Public Utilities OPU Bervice Corp 3pp 16271 098 24X Fiche 50-320,82/11/16.8212010366
- 8212270028 Responds to 821015 request for comments on Commission paper "Development of Scope of Guidelines to Facilitate Recovery Efforts in Event of Nuclear-Related Accidents at Operating Power Plants "

 DENTON: HR Office of Nuclear Reactor Regulation, Director 82/11/22 MINOGUE: A B Office of Nuclear Regulatory Research, Director 2pp 16551 344 24X Fiche 50-320.62/11/22.8212270028
- BP12020408 Submits review of util 821013 & 1111 SERs re submerged demineralizer sys liner recombiner & vacuum outgassing sys SER acceptable BARRETT.L H TMI Program Office 82/11/23 KANOA.B K Genera Public Utilities OPU Service Corp 4pp 16297 344 24X Fiche 50-320.82/11/23.8212020408
- 8P12020405 Responds to util 821014 proposal to modify nitrogen questing of shipping casks for future EPICOR II prefilter shipments Propused change in conformance w/requirements in NRC 820723 ltr
 BARRETT.L H TMI Program Office 82/11/24 KANGA.B K General Public Utilities OPU Service Corp 2pp 16297 351 24X Fiche 50-320.82/11/24.8212020405
- BP12020407 Submits review of 821103 suppl to reactor coolant processing plan to assess safety aspects of processing reactor coolant w/RCS in depressurized & drained down condition Approves implementation of suppl BARRETTLE H TMI Program Office 82/11/24 KANGA.B K General Public Utilities GPU Service Corp 1p 16297 348 24X Fiche 50-320,62/11/24.8212020407
- 8212060015 Forwards application for amend to License DPR-73 for proposed Tech Spec Change 40.consisting of administrative control changes in areas of responsibility, organization, staff qualifications, review & audit & 80 action ARNOLD.R C General Public Utilities GPU Service Corp 82/11/29 GNYDER:B J TMI Program Office 1p 16311 020 24X fiche 50-320.82/11/29.8212060015
- --B212040019 Application to amend Litense DPR-73 for proposed Tech Spec Change 40, consisting of administrative control changes in areas of responsibility, organization, staff qualifications, review & audit & RO action
 ARNOLD, R Ceneral Public Utilities -- OPU Service Corp ARNULD, R Hetropolitan Edison Co ARNOLD, R Jersey Central Power & Light Co B2/11/29 2pp 16311 021 24X Fiche 50-320.82/11/29, B212040015
- --B212060022 Proposed Tech Spec Change 40.consisting of administrative control changes in areas of responsibility.organization, staff qualifications, review & audit & 80 action & General Public Utilities GPU Service Corp 82/11/29 14pp 16311 023 24X Fiche 50-320.82/11/29.8212060015
- GP12060085 Forwards proposed organization plan. Revision 6 Mutually agreeable implementation plan will be established after approval ARNOLD.R C General Public Utilities GPU Service Corp 82/11/29 SNYDER.B J TMI Program Office 17pp 16314-325 24X Fiche 30-320.82/11/29.8212060085
- 97:2090004 Forwards amended sections to recovery operations plan, as approved Change 18, which changes operability requirements for airborne particulate monitor M/o enci BARRETT, L. H. TMI Program Office 82/11/30 KANGA, B. K. General Public Utilities OPU Service Corp. 2pp. 16379 359 24X Fiche SQ-320, 82/11/30, 8212090004

- 8212280514 "Characterization of TMI-Type Wastes & Solid Products." quarterly progress rept for Jul-Sept 1982 SWYLER.K J. DAYAL.R Brookbaven National Laboratory FIN A-3236 B212280514 B2/11/30 KIM.K Dffice of Nuclear Regulatory Research, Director 27pp 16590 115 24X Fiche 50-320,82/11/30, B212280514
- B212130057 Forwards Procedure 1000-PLN-4010 01, "GPU Nuclear Corp Radiation Protection Plan" KANGA.B K Ceneral Public Utilities - GPU Service Corp 82/12/06 BARRETT.L H TMI Program Office 1p 16391 168 24X Fiche 50-320, 82/12/06,8212130059
- --8212130060 Procedure 1000-PLN-4010 OI, "SPV Nuclear Corp Radiation Protection Plan," Revision O HILDEBRAND, JE, LONG, RL, HUKILL, HD General Public Utilities -GPU Service Corp 82/11/05 15pp 16391 169 24X Fiche 50-320,82/12/06/8212130059
- 8212230056 Forwards Tech Specs inadvertently omitted from NRC 621130 ltr forwarding amended sections to recovery operations plan as approved Change 18
 BARRETT.L H TMI Program Office 82/12/08 KANGA.B K General Public Utilities GPU Service Corp 2pp 16545 333 24Y Fiche 50-320, 82/12/08, 8212230056
- --8212230061 Tech Bpec 4 3 re instrumentation surveillance requirements, inadvertently omitted from NRC 821130 ltr forwarding amended sections to recovery operations plan as approved Change IB * TMI Program Office 82/12/08 3pp 16545 335 24X Fiche 50-320,82/12/08 8212230056
- 8208190263 Generic Ltr 82-32 to all PWR licensess re-potential steam generator-related generic requirements forwards Science Applications. Inc draft rept re-subj requirements Comments requested within 30 days of ltr Svc list encl EISEMHUT.D 9 Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc. 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 8212300260 Requests temporary exemption from surveillance requirements of recovery operations plan. Sections 4 7 3 1.4 7 3 2 & 4 7 3 3 until RCS refilled KANGA. B K General Public Utilities CPU Service Corp 82/12/09 BARRETT, L H TMI Program Office 1p (4595 256 24% Fiche 50-320, 82/12/09, 8212300260
- 8:12230394 Advises that recovery operations plan Change Request 21 resuspension of selected surveillance requirements & mod to Section 4 0 2 b clarifying max time interval for testing denised
 SNYDER, B J 7Mf Program Office 82/12/13 KANOA, B K General Public Utilities OPU Service Corp 3pp 16540 245 24X
 Fiche 50-320, 82/12/13, 8212230384
- GPI2210018 Informs of changes in plans for refilling RCB During refill, pressurizer will not be vented providing added measure of protection against sys overpressurization RANGA.B K Ceneral Public Utilities GPU Service Corp 82/12/14 BARRETIL H THI Program Office 1p 16490 163 24X Fiche 50-320, 82/12/14, 8212210018
- GP12270040 Responds to B21122 ltr re filling & pressurizing of RCS Proposed Plan approved BARRETT.L H TMI Program Office B2/12/14 KANGA,B K General Public Utilities - GPU Service Corp Ip 16607 177 24X Fiche 50-320, 82/12/14,8212270040
- 8212300113 Discusses achedule for EPICOR II prefilter shipments
 Shipments should be completed by end of Third Guarter 1983
 based on commitments from cask vendors Estimated 15
 prefilters will be shipped by end of 1982
 KANGALB K General Public Utilities GPU Service Corp 82/12/15
 BARRETTIL H THI Program Dffice 1p 14598 286 24X
 Fiche 50-320, 82/12/15,8212300113
- BP12230295 Informs of intent to commence shipping submerged demineralizer sys spent liners requiring special passification sys Info demonstrates compliance w/Certificate of Compliance 9152 for CNS 1-13C II shipping container KANGA, B K General Public Utilities GPU Service Corp 82/12/17 BARRETIL H TMI Program Office 3pp 16508 280 24% Fiche 50-320,82/12/17,8212230295
- 8212280029 Requests proprietary drawings containing info on dimensions of all internal components of reactor vessel thermal limits & composition of components shear stress limits & vessel exterior drawings & dimensions SNYDER, B J TMI Frogram Office 82/12/17 KULYNYCH, C E Babcock & Wilcox Co 3pp 16593 124 24X Fiche 50-320,82/12/17,8212280029

- B21230019D Requests remittance of Class III fee for review of B20419 & 0707 applications to separate auxiliary bldg & fuel handling bldg air cleanup exhaust sys. approved B20924 DIGOS,R M License Fee Management Branch 82/12/17 BARTON, J General Public Utilities GPU Service Corp 1p 16624 033 24X Fiche 30-020.82/12/17.8212300190
- Q Inspection reports: IE Bulletins & correspondence
- 8708190240 IE Bulletin B2~03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, lict 112pp 16462 163 24X Fiche 50-000.82/10/28,8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50~000,82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pg 16411 199 (4) Fiche 50-000, 82/11/18, 8208190251
- 8212070106 Forwards IE Insp Rept 50-320/82-13 on 821010-1106 No noncompliance noted STAR0STECKI, R Division of Project & Resident Programs 82/11/23 KANGA: B K General Public Utilities GPU Service Corp 16327 334 24% Fichs 50-320,82/11/23.8212070106
- --8212070111 IE Insp Rept 50-320/82-13 on 821010-1106 No nuncompliance noted Hajor areas inspected licensee action on previous insp findings, routine plant operations, health physics & environ areas & reactor bldg entries
 WIEDE, J. BARR, K. O'NEILL, B. Division of Project & Resident Programs 82/11/22 opp 16327-336 24X Fiche 50-320,82/11/23,8212070106
- BYOB190254 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 244 Fiche 50-000, B2/11/26, 8208190256
- 8708170257 [E Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Conselldated Edison Co of New York, Inc 356pp 16387 028 24x Fiche 50-000, 82/11/30,8208170257
- 8212140311 Forwards 1E Insp. Rept 50-320/82-12 on 820912-1009 & notice of violation
 STAROSTECKI.R. Division of Project & Resident Programs 82/11/30
 KANOA.8 K. General Public Utilities GPU Service Corp. 3pp. 14402 057 24X Fiche 50-320, 62/11/30, 82(2)40311
- ~-B212140315 Notice of violation from insp on 820912-1009 * Division of Project & Resident Programs 82/11/30 ij 16402 060 24% Fiche 50-320.82/11/30.8212140311
- --B212140319 IE Insp Rept 50-320/82-12 on 820912-1009 Noncompliance noted procedures/instructions or procedure changes affecting quality not technically adequate CONYELR, MOSLAK, T. O'NETLL, B. Division of Project & Resident Programs 82/11/04 17pp 14402-061 24X Fiche 50-320,82/11/30,8212440311
- BP08190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies " Svc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03,8208190259
- 8P0B190241 [E Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 P4) Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267

- 87:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fische 50-000, 82/12/20, 8208190268
- 88:12280385 Ack receipt of 82:108 ltr informing NRC of steps taken to torrect violations noted in IE Safeguards Insp Rept 50-320/82-09
 - TO-320/82-09

 MARTIN T T Division of Engineering & Technical Programs 82/12/2

 KANDA. B K General Public Utilities GPU Service Corp 2pp

 16559 018 24% Fiche 50-320, 82/12/21, 8212280385
- --G212280390 Responds to NRC B21008 ltr re violations noted in IE Sareguards Insp Rept 50-320/82-09 Corrective actions withheld (ref 10CFR2 790 % 73 21) KANGA.B K General Public Utilities - GPU Service Corp 62/11/08 HAYNES.R C Region 1. Office of Director 1p 16559 020 24X Fiche 50-320,82/12/21.8212280385
- 8.°12290350 Ack receipt of 821130 ltr informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-320/79-10

STARGSTECKI, R Division of Project & Resident Programs | 82/12/22 | 82/12/22 | 82/12/22 | 82/12/22 | 82/12/22 | 82/12/22 | 82/12/22 | 82/12/23 | 82/12/22 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12/23 | 82/12

- --B212270353 Responds to NRC B01121 ltr re violations noted in RE Investigation Rept 50-320/79-10 Corrective actions periodic review of applicable procedures will be conducted to assure operability verification criteria KANSA.B K General Public Utilities GPU Service Corp BR/I1/30 HAYNES.R C Region 1. Office of Director 2pp 16586 238 24X Fiche 50-320, 82/12/22,8212270350
- R Periodic operating reports & related correspondence
- GP12100176 Submits TMI Program Ofic weekly status rept for wk of m21031-1106
 DARRETT,L H TMI Program Office 82/11/08 DENTON,H R Office of Nuclear Reactor Regulation, Director SNYDER.B J TMI Program Office 6pp 16398 352 24% Fiche 50-220,B2/11/08,B2121001/6
- 9212100170 Submits TMI Program Ofc weekly status rept for wk of #21107-13 PARRETT, L H TMI Program Office 82/11/15 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Diffice 7pp 16398-342 24X Fiche 50-320,82/11/15,8212100170
- 87:12030113 Forwards "Effluent Summary, TMI-2 Liquid & Gaseous Effluents, Jul-Sept 1982 " Rept doses extracted from calculational modes & Ane bounding doses for all cases KANOA, B K General Public Utilities - GPU Service Corp 82/11/19 MAYNES, R C Region 1, Office of Director 1p 16303 016 24X Fiche 50-320, 82/11/19, 82(2030113
- --8212030120 "Effluent Summary,TMI-2 Liquid & Gaseous Effluents,Jul-Bept 1982 " * General Public Utilities - OPU Service Corp 82/11/19 5pp 16303 017 24% Fiche 50-320,82/11/19.8212030113
- GP:12130154 Forwards TMI Program Ofc weekly status rept for wk of H21114-ZO
 RARRETT.L H TMI Program Office 82/11/22 DENTON.H R Office of Nuclear Reactor Regulation, Director SNYDER.B J TMI Program Office 8pp 16410 317 244 Fiche 50-320,62/11/22,821201044
- 83:12070143 Crrata to "Annual Environ Operating Rept for 1981" Extent & nature of herbicide application corrected KANGA: BK General Public Utilities GPU Service Corp 82/11/29 HAYNES:R C Region 1. Office of Director 1p 16327 079 24K Fiche 50-320.82/11/29,8212070143
- 87:12270019 Forwards TMI Program Ofc weekly status rept for wk of 82:121-1204 BARRETT.L H TMI Program Office 82/12/04 DENTON, H R Office of

MARKETTLE H TMT Program Office B2/12/06 DENION.H R Office b Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office Bpp 14551 309 24% Fiche 50-320.B2/12/06,8212270019

- 8:12280519 Forwards TMI program of cweekly status rept for wk of 621205-11
 BARREFT, L H TMI Program Office 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, R J TMI Program Office 7pp 16572 357 24% Fiche 50-320,82/12/13,8212280519.
- 82:12300101 Forwards TMI Program Ofc weekly status rept for wk of 82:1212-18 DARRETT, L. H. TMI Program Office 82/12/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 7pp 16624 234 24% Fiche 50-320.82/12/20,8212300101

- S Reportable occurrences. LERs & related correspondence
- G212060322 Forwards LER 92-034/01L-0 KANGA B K General Public Utilities - GPU Service Corp 82/11/2, H4YNES,R C Region 1. Office of Director 1p 16312 OB2 24X Fithe 50-320, 82/11/22, 8212060322
- --8212060326 LER 82-034/01L-O on 821021,A & B once through steam generator (QTSG) level indications failed Caused by separated electrical connector failed power supply & inadequate procedure Level indicator repaired & calibr CHAPLIN.S D General Public Utilities GPU Service Corp 82/11/22 Region 1. Office of Director 3pp 16312 083 24X Fiche 50-320.82/11/22.8212060322
- 8212150038 Forwards LER 82-036/03L-0 KANGA.B K General Public Utilities - GPU Service Corp 82/12/01 HAYNES.R C Region I. Office of Director 1p 16421 251 24X Fiche 50-320.82/12/01.8212(50038
- --B212150044 LER 82-036/03L-0 on 82102B, tested smoke detectors failed to provide required trip functions & alarms Caused by high voltage do power supply failing to provide proper voltage due to capacitor failure Capacitor replaced CHAPLIN. B D General Public Utilities GPU Service Corp B2/12/01 Region 1, Office of Director 2pp 16421 252 24X Fiche 50-320, 82/12/01, 821215003B
- 8712220449 Forwards LER 82-035/01L-0 KANGA. B K General Public Utilities - GPU Service Corp 82/12/10 HAYNES.R C Region 1. Office of Director 1p 16503 238 24X Fiche 50-320, 82/12/10, 8212220449
- --B212220454 LER B2-035/01L-O on B21110, reactor bldg sump level indicator observed reading high Caused by buildup of sludge in end of sump indicator Indicator line blown free w/20 lb of pressure
 CHAPLIN.S D General Public Utilities GPU Service Corp B2/12/10 Region 1, Office of Director 3pp 16503 239 24x
 Fiche 50-320, 82/12/10, 8212220449
- --8212290240 LER 82-037/01L-0 on 821115, once-through steam generator level indication failed low Cause unknown Instrumentation verified operable & returned to svc CHAPLIN.8 D General Public Utilities GPU Service Corp 82/12/15 Region 1, Office of Director 3pp 16582 113 24X Fiche 50-320, 82/12/15, 8212270233
- 87:12270233 PNO-TM1-82-021 on 82:1217.while replacing aircraft warning lights, employee fell from natural draft cooling tower & listed in serious condition at local hosp WIEBE, J., FASAND.A., BARRETT.L. Region 1, Office of Director 82/12/20 1p 16537 206 24X Fiche 50-320,82/12/20,8212270233
- I Hearing transcripts on non-antitrust matters
- B212270475 Transcript of Advisory Panel on Decontamination of TM1-2 B21117 meeting in Harrisburg, PA Pp J-109 # Commissioners B2/11/17 111pp 16571 182 24X fiche 50-020, 82/11/17, 8212270475
- DOCKET 50-321 EDWIN I HATCH MUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8)12150099 Confirms telcon re emergency facility status per Generic Ltr 82-10 Structure complete & habitable Info equipment not completely installed, but facility operable HECKHAM, J T Georgia Power Co 82/12/08 Office of Nuclear Reactor Regulation, Director ip 16421 138 24X Fiche 50-321, 82/12/08, 8212150009
- J Insurance & indemnity information
- 8012280222 Forwards ANI & MAELU secondary financial protection centificates of insurance N-51, N-67, M-51 & M-67 BUCK, J R Marsh & McLennan.Inc. I & M Nuclear Consultants. Inc. Div 82/12/20 SALTIMAN. J Assistant Director for State & Licensoc Relations 4ipp 16542 135 24X Fiche 50-321, 82/12/20, 8212280222

- 8212280369 Forwards Endorsement 74 to NELIA Policy NF-215 & Endorsement 60 to MAELU Policy MF-78 DUCK.J R Harsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 82/12/20 SALTIMAN, J Assistant Director for State & Licensue Relations 3pp 16560 067 24X Fiche 50-321,82/12/20.8212280369
- P Operating license stage documents & correspondence
- 8212100373 Requests verification that encl acceptance criteria for NUREO-0737. Item II K 3 22, "Automatic Switchover of RCIC Sys Suction.' satisfied Response requested within 30 days STOL7.J F Operating Reactors Branch 4 82/08/04 BECKHAM, J T Georgia Power Co 4pp 16389 220 24X Fiche 50-321,82/08/04.
- G211230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBUR, Big Rock Point. Oresden 1. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Socialist Encl W/o stated encl EISE/HUT. D G Division of Licensing 82/L1/15 General Public Utilities OPU Service Corp 22pp 16587:004 24X Fiche 50-000. 82/11/15.8211230066
- 8212170246 Advises that specific containment & purge valves identified in NRC 821110 ltr are not applicable to facilities Meeting requested to determine status of remaining issue re-purging Eventing

 BECKHAM, J T Georgia Power Co 82/12/13 Office of Nuclear

 Reactor Regulation, Director 1p 16457 178 24X

 Fiche 30-321, 82/12/13, 8212170246
- 8212270450 Informs of post-implementation review of NUREC-0737, Items II F i 4, II F i 5 & II F i 6 re containment pressure, water level & hydrogen manitors Addl info & guidance for answering Questions entl STOLZ.J F Operating Reactors Branch 4 B2/12/17 BECKHAM, J T Georgia Power Co 10pp 16606 074 24x Fiche 50-321.82/12/17. B212270450
- 8212290151 Revises estimated completion date for implementation of NUREC-0737. Item II B 3 to 830401, in response to Generic Ltr 82-05 Interim sampling capabilities per NUREC-0578 provided in 87407 th in 820607 ltr IN ESCOVO 1877
 GUCKA-L T Georgia Power Cp 82/12/20 Office of Nuclear Reac Regulation, Director 1p 16582 239 24x Fiche 50-321,82/12/20,8212290151
- Q Inspection reports. IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-**OBJOCAU It Suffetin 82-03, Mevision 1, "Stress Gracking in Inick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list enci
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82-03, Mevision Consolidated Edison Co of New York, Inc
 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- 8708190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolyminescent Dosimeters " Syc List encl CQ98.L I
- COSS.L I Division of Fuel Facilities, Materials & Safeguards
 B2/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list enci JORDAN.E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24x Fiche 50-000, 82/11/18, 8208190251
- BP08170254 IE Info Notice 82-45. "Defective & Obsolete Combination POBINOSTA IE INTO NOTICE OF THE DESCRIPTION OF THE PROPERTY OF
- 8/08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8212090127 Informs that visual insp conducted on spargers & associat piping & bracket lugs.per [E Bulletin 80-13, "Cracking in Gore Spray Spargers" No cracking observed GUCMA; L T Georgia Power Co. 82/11/30, G'REILLY, J P Region 2, Gffice of Director ip 16357 234 24% Fiche 50-321, 82/11/30, graceconding

- 8212090492 Requests extension until 821215 for submittal of response to IE Bulletin 82-03 re inservice insplof reactor recirculation sys piping Request granted per 821124 telcon GUCHAL. T. Georgia Power Co. 82/11/30 0'REILLY, J.P. Region 2, Office of Director in 16363 287 24X Fishe 50-321,82/11/30.
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edisor Co of New York, 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/12/0 Consolidated Edison Co of New York, Inc 110pp 16462 064 2 Fiche 50-000.82/12/03.8208190261
- 8208190247 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Cas Monitoring " Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- BP08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORBANIE L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000 82/12/20.8208190268
- B212300189 Advises that NRC has no objection to use of 1980 Edition of ASKE Section XI & addenda through Winter 1980 for inservice insp of Category B-H welded supports.in response to 820830 request for relief from 1974 Edition requirements STOLZ, J F Operating Reactors Branch 4 82/12/20 BECKHAM, J T Georgia Power Co 2pp 16624 034 24X Fiche 50-321.82/12/20, 8212300189
- R Periodic operating reports & related correspondence
- 8212170353 Forwards monthly operating repts for Nov 1982 NIX.H C Georgia Power Co 82/12/07 Director's Office. Office of Inspection and Enforcement 1p 18459 191 24% Fiche 50-321.82/12/07.8212170353
- --8212170359 Nonthly operating repts for Nov 1982 SMITH.A Georgia Power Co 82/12/07 10pp 16459 192 24% Fiche 50-321.82/12/07.8212170353
- S Reportable occurrences, LERs & related correspondence
- 8212030170 Forwards revised LER 82-089/01X-1 NIX.H C Georgia Power Co 82/11/18 O'REILLY, J P Region 2, Office of Director 1p 16303 280 24X Fiche 50-321.82/11/18, B212030170
- --0212030174 Revised LER 02-089/01X-1 on 021026 & 1104 during refueling shutdown rejectable linear indications discovered on welds on RHR suction line from recirculation loop 8 & on loops A & SUMNER, H L. Georgia Power Co. 82/11/18 Region 2, Office of Director 2pp 16303 281 24X Fiche 50-321, 82/11/18, 8212030170
- Gi'12070297 RO 50-321/1982-02 on 821014 smoke detection for control room t sprinkler sys isolated due to mod activities Smoke detectors disconnected due to dust created by chipping octivities causing spurious alarms
 NIX.H C Deorgia Power Co 82/11/23 O'REILLY, J P Region 2,
 Office of Director 2pp 16339 114 24X Fiche 50-321,82/11/23.
- G212090216 Forwards LER 92-085/03L-0 NIX,H C Opengia Power Co B2/11/23 D'REILLY,J P Region 2, Office of Director 1p 16363 002 24X Ficha 50-321.82/11/23, 8212090216
- el2090219 LER 82-085/031-0 on Ballos, walknown of TIP withdrawal Lt logic relay wiring revealed two wires installed onto wrong relay Caused by incorrect relay connection diagram Wires will be terminated to correct terminal relays SUMMER.H. Georgia Power Co 82/11/23 Region 2, Office of Director ip 16363 003 24X Fiche 50-321,82/11/23,8212090216
- 8212070330 Forwards updated LER 79-082/03X-2 NIX.H C. Georgia Power Co 82/11/23 O'REILLY.J P Region 2, Office of Director 1p 16365 123 24X Fiche 50-321,82/11/23, 8212070330

- --8212090341 Updated LER 79-082/03X-2 on 790825-27, attempt to perform RCIC pump operability procedure unsuccessful when turbine failed to trip upon mahual signal Caused by burned out turbine trip actuator coils & binding assembly TIPPS.5 B Georgia Power Co. 82/11/23 Region 2. Office of Director ip 16365-124 24X Fiche 30-321.82/11/23,8212090330
- G./12090379 RD 50-321/1979-021, Revision 5 Provides updated data on tritium levels in groundwater samples taken from locations where average value over third quarter of 1982 exceeded samples per ETS Table 3 2-3 NIV.H C. Georgia Pawer Co. 92/11/23 O'REILLY, J.P. Region 2, Office of Director. 4pp. 16364-262. 24X Fiche 50-321, 82/11/23.
- 8P12090140 Forwards LER 82-097/01T-0 Detailed event analysis enti NIX.H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2, Diffice of Director 2pp 16359 174 24X Fiche 50-321,82/11/30,
- --B212070145 LER 82-097/01T-0 on 821114; spent fuel rod broken during visual insp of several spent fuel bundles Caused by severely degraded cladding at point of separation due to corrosion Rod uill be placed back into bundle & bundle flagged SUM-ER.H L Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16359 176 24X Fiche 50-321,82/11/30,8212090140
- 8:12070222 Forwards updated LER 80-078/03X-1 NIX.H C Deorgia Power Co 82/11/30 O'REILLY, J.P. Region 2, Office of Director ip 16362-361 24X Fiche 50-321, 82/11/30, 12123001202
- --8212090207 Updated LER 80-078/03X-1 on 800816.while performing suppression chamber to drywell vacuum breaker sys operability procedure.one closed indication lamp on vacuum breaker H failed to extinguish TIPPS.S B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16362 362 24X Fiche 50-321.82/11/30,8212090202
- G:/12140269 Forwards updated LER 81-095/03X-1 NIX.H C Georgia Power Co 82/11/30 O'REJLLY, J P Region 2. Office or Director ip 16401 019 24X Fiche 50-321, 82/11/30, 6212140269
- --G212140271 Updated LER 81-075/03X-1 on 810708.RCIC steam line differential pressure switch NOIS found actuating above Tech Spec Caused by setpoint drift Switch recallbr.tested & returned to svc TIPPS.S B Georgia Power Co 82/11/30 Region 2. Office of Director 1p 16401 020 24X Fiche 50-321,82/11/30.8212140269
- G/12210083 Forwards LER 92-093/03L-0 NIX.H C Georgia Power Co 82/12/02 G'REILLY, J P Region 2, Difice of Director 1p 16493 036 24X Fiche 50-321, 82/12/02, G212210083
- --B212210088 LER 82-093/03L-0 on 621107. Liquid radwaste discharge monitor auto control to discharge isolation valve found inoperable during liquid radwaste discharge Caused by jumper not being removed after completion of corrective maint Jumper removed TIPPS. 8 B Georgia Power Co 62/12/02 Region 2. Office of Director 1p 16493 037 24X Fiche 50-321,82/12/02.8212210083
- GF:12150007 Forwards updated LER 81-131/03X-1 NIX.H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2. Diffice of Director 1p 16421 136 24X Fiche 50-321,82/12/07, B3/2150007
- --B212190011 Updated LER B1-131/03X-1 on B11202.during HPCI steamline pressure switch test, NO01D switch actuated at 104 psig Caused by setpoint drift Buitches recallbr TIPPS,S B Georgia Power Co B2/12/07 Region 2, Office of Director 1p 14421 137 24X Fiche 50-321,82/12/07,8212150007
- GS:12150014 Forwards updated LER 80-114/03X-1 NIX,H C Georgia Power Co 82/12/07 O'REILLY,JP Region 2, Office of Director 1p 16421 17B 24X Fiche 50-321,82/12/07, 62:2155014
- B21215001B Updated LER 80-114/03X-1 on 801027, during HPC1 steamline pressure switch test.N001A & C switches actuated at 103 psig & N001B & D switches actuated at 106 psig Caused by setpoint drift Switches recalibr TIPPS,S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16421 179 24X Fiche 50-321.82/12/07,8212150014
- G:12190031 Forwards updated LER 80-059/03X-1 NIX.H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Uffice of Director 1p 16421 246 24X Fiche 90-321, 82/12/07, 8212150031

- ~~8212150037 Updated LER 80-057/03X-1 on 800617,2-h after performance of suppression chamber to drywell vacuum broaker sys operability procedure.closed indication F vacuum breaker light found extinguished Caused by burned out lamp PIPPS,S B Ocorgia Power Co 82/12/07 Region 2, Office of Ip 16421 247 24X Fiche 50-321,82/12/07,8212150031
- GPI2170092 Forwards updated LER Bi-109/03X-1
 NIX:H C Georgia Pawer Co 82/12/07 O'REILLY, J P Region 2,
 Office of Director 1p 16452 332 24X Fiche 50-321,82/12/07,
 82/21/70092
- --8212170099 Updated LER 81-109/03X-1 on 810927, surveillance test indicated HPCI steam line pressure switches NO01A & NO01D actuated at 103 & 105 psig.respectively, contrary to Tech Specs Caused by setpoint drift Barksdale switches recalibr TIPPS.S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 14452 333 24X Fiche 50-321.82/12/07,8212170092
- 6P12170166 Forwards revised LER 60-003/03X-1 NIX.H C Georgia Power Co 82/12/07 O'REILLY.J P Region 2. Office of Director ip 16459 343 24X Fiche 50-321.82/12/07. 8212170166
- --G212170202 Revised LER 80-003/03X-1 on 800105.while performing RHK valve operability procedure, outboard shutdown cooling isolation valve F008 opened in 25 8-5 Caused by normal wear 8 human reaction time Valve operator adjusted TIPPS.5 B Georgia Power Co 82/12/07 Region 2. Office of Director 1p 16459 344 24X Fiche 50-321.82/12/07.8212170166
- GP1221018B Forwards LER 82-078/03L-0 NIX.H C Georgia Power Co 82/12/07 O'REILLY, J P Region 2, Uffice of Director 1p 16484 351 24X Fiche 50-321,82/12/07, 821221018B
- --8212210196 LER 82-098/03L-0 on 82110B, discovered that liquid radwaste monitor instrument procedures not performed munthly Caused by inadequate procedures Correct procedures performed monthly TIPPS, 3 B Georgia Power Co 82/12/07 Region 2, Office of Director ip 16484 352 24X Fiche 50-321,82/12/07,8212210188
- 8212150090 PND-II-82-134 on 821208.bomb threat received while in final preparation for full scale emergency drill Security determined call came from security guard posted at entry gate to owner controlled area Guard fired & arrested TILLMAN.A. MCGUIRE.D R Region 2, Office of Director 82/12/09 2pp 16430 189 24X Fiche 50-321.82/12/09.8212150090
- GP12280387 Forwards LER 82-090/03L-0 NIX.H C Georgia Power Co 62/12/14 O'REILLY, J P Region 2. Orfice of Director 1p 16558 355 24X Fiche 50-321,82/12/14, 5212280387
- --B212280392 LER B2-090/03L-O on B21116, during hydraulic shock & sway arreston insp & functional test procedure, snubber found inogerable Caused by component failure due to worn piston rod seal Snubber replaced & returned to operable status TIPPS, S B Ogergia Power Co B2/12/14 Region 2, Office of Director ip 16558 356 24X Fiche 30-321, B2/12/14, B2122B03B7
- 8P12300091 Forwards updated LER 80-058/03X-1 NIX,H C Georgia Pawer Co 82/12/16 O'REILLY,J P Region D. Office of Director ip 16599 032 24X Fiche 50-321.82/12/16. G212300091
- --B212300075 Updated LER 80-058/03X-1 on 800616.during steady-state operation, control rod drive units could not maintain required pressure Caused by cartridge valve 1C11-F(1) leaking at steam packing Valves rebuilt TIPPS.B B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16597 033 24X Fiche 50-321.82/12/16.B212300071
- GP12300265 Forwards updated LER 80-013/03X-1 NIX.H C Georgia Pawer Co 82/12/16 O'REILLY, J P Region 2. Office of Director Ip 16595 206 24X Fiche 50-321,82/12/16, 8212300265
- --0212300270 Updated LER 80-013/03X-1 on 800127 reactor recirculation pump A tripped causing power reduction Caused by electrical short circuit due to steam leak in drywell Terminal board replaced & tested TIPPS.S B Oeorgia Power Co 82/12/16 Region 2. Office of Director ip 16595 207 24X Fiche 50-321.82/12/16.8212300265
- 8:/12300271 Forwards updated LER 81-090/01X-1 NIX,H C Georgia Power Co 82/12/16 O'REILLY,J P Region 2, Office of Director 1p 16595 250 24X Fiche 50-321,82/12/16, 8212300271

- 8212300275 Updated LER 81-090/01%-1 on 810921, performance of RCIC turbine schaust diaphragm pressure instrument showed N012 A-D switches actuating above Tech Spec Caused by setpoint drift Suitches recalibr Design changes implemented TIPPS S 0 Georgia Power Co 82/12/16 Region 2, Office of Director 2pp 16595 251 24X Fiche 50-321.82/12/16,82123002/1
- G212300277 Forwards updated LER 80-023/03X-1 NIY.H C Deorgia Power Cp 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16595 193 24X Fiche 50-321, 82/12/16, G212300277
- ---8212300281 Updated LER 80--023/03X-1 on 830224,HPJC did not actuate until Tech Spec limit passed Caused by instrument drift Spitches calibr & necessary design changes will be implemented TIPPS.S B Oborgia Power Co 82/12/16 Region 2, Office of Director ip 16595 194 24X Fiche 50-321,82/12/16,8212300277
- 82:12300287 Forwards updated LER 80-121/03X-1 NIX.H C Deorgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director Ip 16595 131 24X Fiche 50-321.82/12/16, 8212300287
- --8212300289 Updated LER 80-121/03X-1 on 801211,all points of drywell temp recorder R611 found reading high Caused by faulty slidewire contacts ω printhead mechanism New points installed TIPPS B Georgia Power Co 82/12/16 Region 2, Office of Director 1p 16395 132 24X Fiche 50-321.82/12/16.8212300207
- B212300329 Forwards updated LER 80-050/03X-1 NIX.H C Opengia Power Co 82/12/16 O'REILLY.J P Region 2. Uffice of Director 19 16574 232 24X Fiche 50-321.82/12/16. R212300329
- --B212300337 Updated LER 80-050/03X-1 on 800514.RCIC turbine tripped during manual start attempt after low reactor water level alarm & reactor half scram Caused by incorrect mode of RCIC operation Operating procedure revised TIPPS:8 B Georgia Fower Co 82/12/14 Region 2, Office of Director 1p 16594 233 24X Fiche 50-321,82/12/16.8212300329
- GP12280180 RD 50-321/1982-003 on 821127, air compressor in cooling tower IB fire protection spray sys failed dropping air pilot datection sys pressure Dropped pressure caused actuation of two deluge valves which started fire pumps NIX.H C Georgia Power Co 82/12/17 O'REILLY, J.P. Region 2, Office of Director 3pp 16562 317 24X Fiche 50-321.82/12/17, G212280180
- G212300328 Forwards LER 82-101/017-0 NIX.H C Opengia Power Co 82/12/21 O'RE(LLY, J P Region 2, Office of Director ip 16594 268 24X Fiche 50-321,82/12/21, 8212300328
- --8212300336 LER 82-101/01T-0 on 821208.bomb threat received warning of bomb in switchyard Call traced to security officer from security badge island in security headquarters Officer fired WilkES.7 C Opengia Power Co 82/12/21 Region 2, Office of Director 2pp 16594 269 24X Fiche 50-321.82/12/21.8212300328
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8208290118 FD1A request for documents re suppression pool dynamic loads for facility from 750418-1231 MAFNER, B Affiliation Unknown 82/09/22 Office of Administration 1p. 16553 329 24X Fiche 50-322, 82/09/22,
- GP09150064 FOIA request for documents to suppression pool temp from 770930-1201
 HAFNER, B Affiliation Unknown 82/10/06 Office of Administration ip 16507 048 24X Fiche, 50-322, 82/10/06, 8209150064
- B212290006 FOIA request for documents re pool cooling mode of RHR from Mar Oct 1981
 HAFNER, B Affiliation Unknown 82/10/24 Office of Administration Ip 16607 167 24X Fiche 50~322,82/10/24, 8212290006
- B212010361 Partial response to F01A request for documents re suppression pool dynamic loads for facility from 750418-1231 App A documents encl App B documents available at PDR. FELTON J N Division of Rules and Records B2/11/09 HAFNER, B Affiliation Unknown 3pp 16267 302 24X Fiche 50-322, B2/11/09, B212010361

- --8212010368 Requests info re design of containment relief valve loads Request should be filed within 90 days of receipt of ltr If schedule cannot be met.NRC should be advised within 15 days STOLZ.JF Light Water Reactors Branch 1 75/04/21 WOFFGRD.A W Long Island Lighting Co. 4pp. 16267 305 24X Fiche 50-322.82/11/09.8212010361
- --3212D10371 Advises that schedule for submitting requested containment design info & evaluation will be provided by wk of 750602 Schedule & program being developed in conjunction wiether utils buning Mark II containments & GE WOFFORD. A W Long Island Lighting Co 75/05/15 STQLZ. J F Light Water Reactors Branch 1 1p 16267 309 24% Fiche 50-322.82/11/09.8212010361
- --B212010393 Forwards list of suppression pool & relief valve drawings & info re operation of safety relief valves Description of valves under prompt relief trip & automatic depressurization sys operation will be submitted on 750915 WGFFORD.A & Long Island Lighting Co 75/07/30 STOLZ.J F Light Water Reactors Branch 1 3pp 16267 310 24X Fiche 50-322.82/11/09,8212010361
- --0212010397 Forwards description of BWR Mark II containment supporting program presented at 750630 meeting w/NRC Support program intended to confirm preliminary forcing function rept scheduled to be submitted Sept 1975
 HOFFORD.A W Long Island Lighting Co 75/08/25 STOLZ.J f Light Water Reactors Branch 1 6pp 16267 313 24X Fiche 50-322.82/11/09.8212010361
- --8212010401 Discusses schedule for submitting five items for assessment of BWR Mark II containment structures WDFFORD-A W Long Island Lighting Co 75/11/25 STOLZ J F Light Water Reactors Branch 1 3pp 16267 319 24X Fiche 50-322,82/11/09,8212010361
- 8/11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBUR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl W/o stated encl EISENHUT, D 0 Division of Licensing 82/11/15 General Public Utilities 0PU Service Corp 22pp 16387 004 24% Fiche 50-000.82/11/15, 8211220066
- GP12060037 Requests response to encl evaluation of flood risk estimate within 30 days
 SCHMENGER: A Licensing Branch 2 82/11/24 POLLOCK: M 6 Long Island Lighting Co 10pp 16343 205 24X Fiche 50-382,82/11/24. G212060037
- GP12270037 Add1 response to FOIA request for documents re suppression gool dynamic loads from 750418-1231 Add1 documents available in POR forwards index of PDR file subjs W/o encl FELTON.J M Division of Rules and Records 82/11/24 HAFNER.B Affiliation Unknown 1p 14953 330 24X Fiche 50-322.82/11/24.62/2270039
- B212270009 Responds to FOIA request for documents re pool cooling mode of RHR from Mar Oct 1981 NRC unable to locate documents subj to request Existing info published in SER. NUREG-0420 FELTON-J M Division of Rules and Records 92/11/24 HAFNER. B Affiliation Unknown 1p 16607 168 24X Fiche 50-322,82/11/24,
- B?12290015 Responds to FOIA request for documents re suppression pool temp from 770830-1201 Forwards 770923 ltr to OD Parr transmitting "Comparison of 1/13 Scale Mark II Containment Multivent Pool Swell Data H/Analytical Method" FELTON.J M Division of Rules and Records 82/11/24 HAFNER, B Affiliation Unknown Ip 16607 049 24X Fiche 50-322,82/11/24. G212290015
- GP12010082 Provides substantiation of adequacy of leak test angle during postulated design basis events.per 820809 ltr Containment liner serves as pressure boundary & leak tight membrane during postulated accident SMITH.J L Long Island Lighting Co 82/11/26 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 16260 317 24X fiche 50-322.82/11/26.8212010082
- 0212010165 Forwards sample set of graphs typical of graphs used in plant emergency procedures, in response to verbal request Submittal closes SER Item I C 8 BMITH.J L Long Island Lighting Co 82/11/26 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 16258 087 24X Fiche 50-322,82/11/26,8212010165
- 82'12130235 Board Notification 82-121 forwards evaluation of flood risk estimates as supplemental info to PRA W/o encl NOVAK-T (1 Assistant Director for Licensing 82/11/26 Atomic Safety and Licensing 80ard Panel App 16410 340 24X Fiche 50-322,82/11/26,8212130235

- 67:12070219 Responds to NRC 820929 itr requesting evaluation of concerns expressed by Future Resources Assoc re reactor bldg internal flooding sequences Internal flooding initiator is highly improbable event SMITM. J L Long Island Lighting Co 82/12/02 DENTON. H R Office of Nuclear Reactor Regulation, Director 99pp 16335 014 24X fiche 50-322.82/12/02.8212070219
- 0212140339 Discusses engineering evaluations determining that leak channels retain pressure boundary integrity for load combinations which containment line; will see during design hasis events
 SMITH J L Long Island Lighting Co 92/12/04 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 16401 360 24X lick 50-322, 82/12/04, 8212140339
- G/12210224 Forwards info re adequacy of design margins of Mark I & 1 | Containment sys per NRC 820708 request Rept addresses all items u/exception of Items 3 3 & 3 4 Completion expected by mid-Jan 1983 SMITH-J L Long Island Lighting Co 82/12/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 25p 16484 202 24% Fiche 50-322,82/12/09,8212210224
- GP12170069 Notification of B21215 meeting w/util & BNL in Brookhaven,NY to discuss seismic qualification review team egen items WEINKAM.E J Licensing Branch 2 82/12/13 SCHWENCER.A Licensing Branch 2 3pp 16480 351 24X Fiche 50-322,82/12/13,8212170069
- 6):12210338 Assures that util will continue to maintain safe & retiable facility per General Design Criterion I Commitment discussed POLLOCK.M S Long Island Lighting Co 82/12/16 NOVAK.T H Assistant Director for Licensing 3pp 16497 026 24X Fishe 50~322.82/12/16.8212210338
- E MRC Safety Evaluation Report (SER), suppls & correspondence
- GP11080125 Forwards Revision 4 to S&W "Environ Qualification Rept for Class IE Equipment for Shoreham Nuclear Power Station Unit 1. Long Island Lighting Co." consisting of changes to Apps B.F. & H. to resolve SER Issue 9
 SMITH J L Long Island Lighting Co. 82/11/03 DENION, H.R. Office of Nuclear Reactor Regulation. Director 2pp. 15781 123 24X
 Fiche 50-322,82/11/03,82(1080125
- --B2:1080129 Revision 4 to "Environ Qualification Rept for Class IF Equipment for Shoreham Nuclear Power Station - Unit 1.Long Island Lighting Co " One aperture card available in PDR * Stone & Webster, Inc 82/10/31 2247pp 15981 126 24X Fiche 50-322.82/11/03.8211080125
- GP12010005 Forwards request for specific info re-multiple control sysfailure issue addressed in 820827 ltr.per BER Section 7 7 SCHWENCER.A Licensing Branch 2 82/11/24 POLLOCK.M S Long Island Lighting Co 5pp 16290 225 247 Fiche 50-322.82/11/24. R212010005
- GP12010087 Forwards location-specific radiation dose calculation for OF Leries 200 electric penetrations requested at 821105 meeting Calculations submitted per SER, Item 9, "Environ Qualification"

 SMITH J L. Long Island Lighting Co 82/11/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 31pp (6260-276-24X Fiche 50-322,82/11/26,8212010087
- GP12010165 Forwards sample set of graphs typical of graphs used in plant emergency procedures, in response to verbal request submittail closes SER Item I C 8 GMITH, J L Long Island Lighting Co 82/11/26 DENTON, H R Offic of Nuclear Reactor Regulation, Director 7pp 16258 087 24X Fisch 50-322.82/11/26.8212010165
- G/12220106 Forwards Apps A & D to SER input on environ qualification of safe'ty-related equipment inadvertently missing from 821124 transmittal KEPKA.D A Hearing Branch 3 82/11/29 BRENNER.L., CARPENTER.J.L., MCRRIS.P A Atomic Safety and Licensing Board Panel 7pp 16503 015 24% Fiche 50-322.82/11/29.8212220106
- 8212070127 Responds to NRC 820707 ltr re NRC position on procedures for suppression pool pumphack sus per SER Open Item 37 Alarm response & openating procedures modified SMITH JL Long Island Lighting Co 82/12/03 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 16329 343 24X Fiche 50-322, 82/12/03. 8212070127

- 8212210404 Forwards "Shoreham Nuclear Power Station Qualification Rept, OE 200 Series Electric Penetrations" & Revision I to "200 heries Low Voltage Electric Penetration Qualification Tost Rept," per NRC 820920 ltr.821105 meeting & SER. Item 9
 SMITH. J. Long Island Lighting Co. 82/12/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 16493 127 24 X
 Fiche 50-322, 82/12/14, 8212210406
- --8212210410 "Shoreham Nuclear Power Station Qualification Rept.GE 200 Series Electric Penetrations" * Long Island Lighting Co 82/12/31 48pp 16493 128 24X Fiche 50-322,82/12/14.8212210406
- 8212210414 Revision 1 to "200 Series Low Voltage Electric Penetration Qualification Test Rept" SCHUSTER,R M. LURIA,N G., TERHUNE,J H Long Island Lighting Co 994-76-018 RO1 77/01/20 184pp 16493 176 24X Fiche 50-322,82/12/14,8212210406
- G212230259 Discusses SER Issue II D 1 re safety relief valve operability test program.per NRC B20708 request & util U10725 response Valve discharge piping adequate to sustain effects of low pressure liquid discharge SHITH.J L Long Island Lighting Co B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation. Director 9pp 16508 196 24% [iche 50-322.82/12/15,8212230259]
- 8212270380 Forwards "List of Active Safety-Related Equipment at Gualification Level." per SER Issue 8, "Dynamic Qualification "
 SMITH J L Long Island Lighting Co 82/12/22 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 1p 16536 107 24X Fiche 50-322.82/12/22.8212270380
- --B212270384 "List of Active Safety-Related Equipment at Qualification Level" * Stone & Webster Engineering Corp 02/12/20 51pp 16536 108 24/ Fiche 50-322.82/12/22.8212270380
- F Security, medical, emergency & fire protection plans
- 82:12210213 Forwards addi info to prepare operating shift crews for types of questions NRC duty officer may ask re telephone repts made via emergency notification sys STAROBTECKI,R Division of Project & Resident Programs 62/12/16/POLLOCK.M B Long Island Lighting Co App 16485 003 24X (iche 90-922, 62/12/16.8212210213
- 6 Adjudicatory correspondence
- 8212030040 Advises that QA inspentionce meeting will be conducted un G21127 E Greenman will be contact in Region 1 ofc Beparate arrangements should be made w/util to assure entrance Completion of encl protocol requested HAYNES.R C Region 1. Office of Director 82/11/26 DEMPSEY.P Suffolk County, NY 4pp 16304 134 24X Fiche 50-322.82/11/26, G212030040
- EP12020381 Response opposing Suffolk County 821122 schodule & proposing alternate schedule for consideration of Torrey Pines Review of rept should not be delayed due to lengthy background of GA litigation Certificate of Svc encl LARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 82/11/29 App 16278 113 24X Fiche 50-322,82/11/29,0212020381
- GP12220104 Forwards Apps A & D to SER input on environ qualification of safety-related equipment inadvertently missing from B21124 transmittal REPKA:D A Hearing Branch 3 82/11/29 BRENNER.L. CARPENTER.JL, MORRIS.P A Abomic Safety and Licensing Board Panel 7pp 14503 015 24X Ficho 50-322.82/11/29.8212220106
- BPI2220128 Forwards IE Insp Rept 50-322/82-26 BORDENICK.B M Idearing Branch 3 82/11/27 IRENNER.L J. CARPENTER.J L., MORRIS.P A Atomic Safety and Licensing Board Panel 4pp 16503 027 24% Fiche 50-322.82/11/27.8212220128
- 80)2070003 Forwards EG&Q draft rept EGQ-EA-6109, "Identification & Kanking of Nuclear Plant Structures, 8ys & Components & Graded GA Guidelines Draft "
 RAWSGN, R J Hearing Branch 4 FIN A-6479 82/12/03 BRENNER, L J, MORRIS, P A . CARPENTER, J L. Atomic Safety and Licensing Board Panel 129pp 16327 106 24X Fiche 50-322,82/12/03,8212070009
- 8212070167 Memorandum & order canceling 821213 hearing approving final security settlement agreement granting joint request to terminate proceeding & dismissing proceeding Agreement resolves all concerns LAURENSON, J A. HARBOUR, J Atomic Safety and Licensing Doard Panel 82/12/03 Long Island Lighting Co 3pp 16335 311 24% Fiche 50-322, 82/12/03, 8212070167

- 8712220135 Forwards IE Insp Rept 50-322/82-20 BORDENICK.2 M Hearing Branch 3 82/12/03 BRENNER.L., CARPENTER.J.L., MORRIS.P.A. Atomic Safety and Licensing Board Panel App 16503 083 24% Fiche 50-322.82/12/03.8212220135
- 8P12080247 Provides latest status of SER open items affecting contentions in proceeding & NRC response to two ASLB questions.per ASLB 82(130 requests REPKA.D A Hearing Branch 3 82/12/06 BRENNER.L., CARPENTER.J.L., MCRRIS.P.A Atomic Safety and Licensing Board Panel 3pp 14354 107 24% Fishe 50-322.82/12/06.8212080267
- 8212140463 Joint rept of parties on status & potential litigation schedule of remaining safety issues Certificate of Svc enc!

 MEPKA: D A Hearing Branch 3 IRWIN. D P Long Island Lighting Co LETSCHE, K J Suffoli County, NY 82/12/09 8pp 16404 336 24; Fiche 50-322. 82/12/09, 8212140463
- B212200111 Resolution of Suffolk County Contention 1 re remote shutdown panel Bases provided Certificate of Svc encl REPKA.D A Hearing Branch 3 IRWIN.D P Long Island Lighting Co 82/12/14 12pp 16470 152 24X Fiche 50-322.02/12/14,8212200111
- 8212220166 Forwards NRC 821210 memo & SER input delineating NRC final position on implementation of TMI Item II E 4 2 re high radiation closure signal on purpe/vent containment isolation valves Info relevant to Suffolk County Contention 23 REPKAID A Hearing Branch 3 82/12/14 BRENNER, L., CARPENTER, J. L., MORRIS, P. A. Atomic Safety and Licensing Board Panel 4pp 16503 049 24% Fiche 50-322,82/12/14,8212220166
- 8212270324 Forwards responses to ASLR 821130 request for addl smfo re IE Insp Repts 50-322/82-26 & 50-322/82-29 MUSELER.W J Long Island Lighting Co 82/12/18 EARLEY,A, ELLIS.T Hunton & Williams 19pp 16530 196 24X Fiche 50-322,82/12/18,8212270324
- GD12220142 Frovides progress rept on differing prof opinion of Malapats & SER Open Item 27 re further analysis on multiple control sys fatlures REPKA-D A Hearing Branch 3 82/12/20 BRENNER, L , CARPENTER, J L , MORRIS-P A Atomic Safety and Licensing Board Panel 2pp 16503 097 24X Fiche 50-322.82/12/20.8212220142
- 8212270196 Responses to AGLB 821130 requests for info re lE insp repts Certificate of Svc encl ELLIS.T S Long Island Lighting Co ELLIS.T S Hunton & Hilliams 82/12/21 Spp 16830 064 24% Fiche 80-322.82/12/21,8212270196
- GM12270220 Memorandum & order confirming B21123 & 30 rulings on intervenor refusal to comply w/order to participate in prehearing exams intervenors waived rights to cross-examine re Phase I emergency planning contentions URENNER.L., CARPENTER.J.H., MORRIS.P.A. Atomic Safety and Licensing Board Panel B2/12/22 Palmetto Alliance 24pp 16536 213 24x Fiche 50-322, 82/12/22, 9212270220
- ii General correspondence
- 8209150058 FOIA request for documents re Paragraph IV A 2 C of 10CFR50. App 0 for 810401-0901

 MAFNER, B Affiliation Uninoun 82/09/29 Office of Administration 1p 16607 006 24X Fiche 50-322, 82/09/29, 8209150058
- B212290025 Responds to FOIA request for documents to Paragraph IV A 2 C of 10CFR50.App & for 810401-0901 Forwards documents listed in App A FELTON.J M Division of Rules and Records 82/11/24 HAFNER, B AFFIListion Unknown 2pp 16607 007 24X Fiche 50-322, 82/11/24, 0212290025
- --8107140119 Forwards Matls Engineering Branch SER input to RCPB fracture toughness Exemptions from requirements of Apps 0 & H of 10CR850 can be granted JOHNSTON, W Assistant Director for Materials & Gualifications Engineering 81/07/02 TEDESCO.R L Assistant Director for Licensing 17pp 16607 009 24X Fiche 50-322.82/11/24, 8212290025
- 8212080672 Responds to 821124 memo re inquiry from Congressman W Carney concerning interim licensing of facility Interim licensing will only allow low power testing at earlier time in licensing procedure than now exists

 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/12/03 BOLLEGEN, D Office of the General Counsel App 16379 296 24X Fiche 50-322.82/12/03.82120806/2

- --8212080684 Requests response to Congressman W Carney constituent lits re impact of interim litensing provisions of S B 2330 on NRC budgetary or manpower resources Requests response by 881202 BOLLMERK, P Office of the General Counsel 82/11/24 REMM.T Office of the Executive Director for Operations ip 16379 304 244 Fiche 50-322,82/12/03.6212080672
- --8212080689 Forwards constituent ltrs re NRC policy on possible interim licensing of facility CARNEY.W House of Rep 82/10/24 PALLADING.N J Commissioners 5pp 16379 305 24X fiche 50-322.82/12/03.8212080672
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list enc!
 DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!

 CORB.L I Division of Fuel Facilities, Naterials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- GP12030069 Forwards IE Insp Rept 50-322/82-29 on 821001-29 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/11/18 POLLOCK, M S Long Island Lighting Co 2pp 16304 172 24X Fiche 50-322, 82/11/18, 8212030069
- --8212030083 IE Imsp Rept 50-322/82-29 on 821001-29 No noncompliance noted Major areas inspected allegations re corroded valves & faulty fiberglass piping HIOGINS.J C., GALLO,R M. Division of Project & Resident Programs 82/11/10 13pp 16304 174 24X Fiche 50-322,82/11/18,8212030069
- 8212060234 Forwards IE Insp Rept 50-322/82-27 on 821018-22 No noncompliance nated MARTIN: T Division of Engineering & Technical Programs 82/11/22 POLLOCK,M S Long Island Lighting Co 2pp 16312 192 24X Fiche 50-322, 82/11/22, 8212060234
- --8212060258 IE Insp Rept 50-322/82-27 on 821018-22 No noncompliance noted Major areas inspected preoperational test program status including test procedure implementation, test procedure procedure review.procedure mods & test results evaluation NICHOLAS.H H , BETTENHAUSEN.L Region 1. Office of Director 82/11/17 7pp 16312 194 24X Fiche 50-322.82/11/22.82120602:14
- BPI2070180 Forwards IE Insp. Rept. 50-322/82-28 on 821018-21 Na noncompliance noted MARTIN.T T. Division of Engineering & Technical Programs 82/11/23 POLLUCK.M S. Long Island Lighting Co. 2pp. 16327-034 24X Fichs 50-322, 82/11/23, 8212070120
- --8212070136 IE Insp Rept 50-322/82-28 on 821018-21 No noncompliance noted Major areas inspected licensee work & GC activities re corrective actions for significant deficiencies & outstanding items NARROW, L., DURR, J.P. Region i. Office of Director 82/11/19 5pp 16327 036 24X Fiche-50-322.82/11/23.8212070120
- 8708190254 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks" Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- 8912030040 Advises that OA insp entrance meeting will be conducted on 821127 E Orsenman will be contact in Region 1 ofc Separate arrangements should be made w/util to assure entrance Completion of encl protocol requested ARYMES, RC Region 1, Office of Director. 82/11/26 DEMPSEY, P Suffolk County, NY 4pp 16304 134 24X Fiche 50-322,82/11/26,8212030040
- B2/09/90257 [E Info Notice B2-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/30 consolidated Edison Co of New York, Inc 356pp 16387 Q28 24% Fiche 50-000/82/11/30/8208190257

- 87:08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8,08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Ant & Gas Monitoring " See ist encl
 BEYQUING.R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fichs 50-000.82/12/16.8208190267
- 39:12220453 Forwards listing of topic areas for discussion at Region 1/ licenses meeting on drug & alcohol abuse programs per IE lnfo Notice 82-05 & NUREO-0903 W/o NUREO STAROSTECKI.R Division of Project & Resident Programs 62/12/16
 POLLACK.M S Long Island Lighting Co 3pp 16504 257 24X
 Fiche 50-322,82/12/16,8212220453
- BP:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24X Fiche 50-000. 82/12/20, 8208190268
- 5 Reportable occurrences, LERs & related correspondence
- 8:42160065 Interim deficiency rept re HMA type relays mfg by 0E Initially reported on 821101 0E notified to determine which specific groupings of HMA relays are affected & what actions should be taken HILLIOAN. H Long Island Lighting Co 82/12/07 HAYNES. R (Region 1, Office of Director 2pp 16446 151 24X Fiche 50-322,82/12/07,8212160065 HAYNES R C
- I Hearing transcripts on non-antitrust matters
- G2:12020384 Transcript of 821130 hearing in Bethesda, MD Pp 14,750-14,958 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/11/30 233pp 16278 260 24X Fiche 50-322,82/11/30,8212020384
- 0212030101 Transcript of 821201 hearing in Bethesda, MD Pp 14, 959-15, 157 82/12/01 199pp Atomic Safety and Licensing Board Panel 82/ 305 174 24% Fiche 50-322,82/12/01,8212030101
- 8212060065 Transcript of 821202 hearing in Bethesda, MD Pp 15, 158-18.352 * Atomic Safety and Licensing Board Panel 82/12/02 197pp 16314 094 24X Fiche 90-322,82/12/02,8212060045
- Ož:12070140 Transcript of 821203 hearing in Bethesda, MD Pp 15, 353-15, 474 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/03 16326 251 24% Fiche 50-322, 82/12/03, 8212070140 82/12/03 132pp
- GP12090171 Transcript of 821207 OL hearing in Bethesda, MD Pp 15,477-15.646 Supportive documentation encl * Atomic Bafety and Licensing Board Panel 82/ 16358 170 24X Fiche 50-322.62/12/07.8212090171 82/12/07 231pp
- 92·12100024 Transcript of 821208 hearing in Bethesda.MD Pp 15.662-15, 824 82/12/08 168pp # Atomic Safety and Licensing Board Panel 82/16375 165 24X Fiche 50-322/82/12/08/82/2100024
- BD:2130042 Transcript of 82:209 hearing in Bethesda, MD Pg 15.827-16.017 **

 * Atomic Safety and Licensing Board Panel 82/1691 188 24X Fiche 50-322.82/12/09.8212130042 82/12/09 194pp
- GP12140039 Transcript of 821210 hearing in Bethesda, MD Pp 16,018-16.190 # Atomic Safety and Licensing Board Panel 82/12/10 175pp 16410 001 24X Fiche 50-322.82/12/10.8212140039
- 0212160030 Transcript of 821214 OL hearing in Bethesda, MD Pp 16, 191-16,408 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/12/14 24ipp 16443 273 24X Fiche 50-322.82/12/14.8212160030

- 8212170251 Transcript of 821215 hearing in Bethesda, MD Pp 16,409-.83* Atomic Safety and Licensing Board Panel 82/12/15 230pp 457 179 24X Fiche 50-322,82/12/15,8212170251
- 8212200018 Transcript of 821216 hearing in Bethesda, MD Pp. 16,635-16.821 * Atomic Safety and Licensing Board Panel 82/116473 108 24% Fiche 50-322.82/12/16.8212200018 82/12/16 189pp
- 8212210302 Transcript of 821217 hearing in Bethesda, MD Pp. 16,822-* Atomic Safety and Licensing Board Panel 82/ 16495 312 24% Fiche 50-322,82/12/17,8212210302 82/12/17 184pp
- 8212220455 Transcript of 821220 hearing in Methesda.MD Pp 17:007-17. 193 ** Atonic Safety and Licensing Board Panel 82/12/20 189pp 16504 048 24X Fiche 50-322.82/12/20,8212220455
- 82:12230316 Transcript of 82:1221 hearing in Bethesda, MD Pp 17,194-17,394 Supporting documentation encl # Atomic Safety and Licensing Board Panel 82/12/21 219pp 16507 074 24X Fiche 50-322,82/12/21,8212230316
- B212270227 Testimony of RB Hubbard & FJ Samaniego re Torrey Pines Technology insp of fazility Certificate of Svc encl HUBBARD.R B . SAMANIEGO.F J Suffolk County, NY HUBBARD.R B MHB Technical Associates \$2/12/21 36pp 16536 160 24X Fiche 50-322.82/12/21.8212270227
- G212270230 Transcript of B21222 QL hearing in Bethesda, MD Pp 17,395-17,533 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/22 156pp 16537 220 24X Fiche 50-322,82/12/22,8212270230
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- BP12030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to B6 Eisenhut re alleged design deficiency in ABME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly CISENAUT. D 6 Division of Licensing 82/11/24 PALLADINO, N J , GILINSKY, V , AHEARNS. J F Commissioners 2pp 16316 240 24% fiche 50-000. 82/11/24.8212030253
- --8212030265 Discusses alleged design deficiency in ASME Code Class I pigning Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation ONLINER, R H Division of Engineering 82/09/30 EISENHUT, D C Division of Licensing 5pp 16316 247 24x Fiche 50-000, 62/11/24,8212030253
- 8/12270418 Responds to FDIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREO-0784, Chapter IO as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, B C Union of Concerned Scientists 3pp 16547 233 24X Fiche 90-000, 82/11/26, 8212270418
- ~-0211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK.T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000,82/11/26,8212270418
- 82:120:10:170 Bubmits status update on Wiegel & Send repts re effects of storm & tsunami waves & seismic events on facility break—water Final repts for ongoing analysis re potential wave forces & request for tech Spec amend will be sent Dec 1982 CRANE, P A Pacific Gas & Electric Co 82/11/27 KNIGHTON, O W Licensing Branch 3 2pp 16258 085 24X Fiche 30-275,82/11/27,82/2010/90
- 8P12230306 Provides response to 821123 itr requesting 8%W document, change in format of engineering open item file sys & more complete description of 27 files opened to date JOHNSBN:A E Teledyne Engineering Services 82/12/01 HUBBARD,R B MHB Technical Associates 2pp 16507 319 24X Fiche 50-275,82/12/01.8212230306
- 8P1217003B Requests changes to QA program, Revision 1 scope of responsibility Project completion effort responsibility should be clearly defined EISENHUT.D 0 Division of Licensing 82/12/02 CRANE,PA Pa Oas & Electric Co 5pp 1647B 00B 24X Fiche 50-275,82/12/02.821217003B Pacific

- 8212130281 Board Notification 82-125 forwards info re recent ACRS evaluation of PHR flow blockage during natural circulation EISENHUT, D 0 Division of Licensing 82/12/06 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 3pp 16418 251 24X Fiche 50-000, 82/12/06, 8212130281
- 82/12220017 Staff requirements memo re 82/1209 meeting on Phase II of design verification program per SECY-92-414 Commission unanimously approved recommendations replacing Figure 3 w/ Figure 1, per util 82/203 itr
 CNILK-5 J Office of the Secretary of the Commission 82/12/09 DIRCKS, W J Office of the Executive Director for Operations 1p 16329 076 24% Fiche 50-275,82/12/09.8212220017
- BRI2230049 Board Notification 82-125A forwards info re PWR flow blockage Info suppls Board Notification 82-125 £ISEKHUT.D G Division of Licensing 82/12/09 PALLADING.N J GILINSKY.V A HEARNE, J F Commissioners 3pp 14545 338 24X Fiche 50-000, 82/12/09,8212230049
- ---8212230058 Forwards Fraley 821207 memo re flow blockage by steam during natural circulation in PHRs
 EISENHUT.D 0 Division of Licensing 82/12/09 LAINAS.G
 Assistant Director for Operating Reactors ip ` 16545 341 24X
 Fiche 50-000.82/12/09.8212230049
- 9212210002 Forwards "Pressurizer Safety & Relief Line Evaluation." summary rept CRANE,P A Pacific Gas & Electric Co 82/12/13 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 2pp 16485 276 24X Fiche 50-275,82/12/13.8212210002
- --8212210005 "Pressurizer Safety & Relief Line Evaluation," summary rept SMITH.L C . HAZLETT,T L . CHANG.K C Pacific Gas & Electric Co AM-598-2534 82/11/30 71pp 16485 278 24X Fiche 50-275.82/12/13.8212210002
- 8P12210037 Provides Natl Register of Historic Places eligibility notification of plant Archeological Site SLO-2 # Interior.Dept of. National Park Service 82/12/14 KERRIGAN, J D NRC - No Detailed Affiliation Given 2pp 16490 212 24X Fiche 50-275, 82/12/14, 8212210037
- 9212220434 Board Notifications 82-125 & 82-125A-forwards info re flow blockage during natural circulation All concerns re phanomena of natural circulation flow blockage previously identified by NRC & provided to Commission EISEMHUT. B G Division of Licensing 92/12/14 PALLADINO, N J GLINSKY, V AMERIKE, J Commissioners 4pp 16523 103 24X Fiche 50-000, 82/12/14, 8212220434
- 8712220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NUVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing 800rd Panel 5pp 16523 135 24X Fiche.50-000,82/12/14,8212220440.
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo ro Semiscale S-UT-B test results Phenomena of core level depression & loop scal clearing may be more complex than previously supposed NOVAK: T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8218220461.
- 8212220482 Board Notification 82-124 forwards RJ Mattson 821123 memo rp Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed EISENNUT. B Ø Bivision of Licensing 82/12/14 PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners App 16523 199 24X Fiche 50-000, 82/12/14.8212220482
- 8212210090 Advises that results of design verification program require mods to fuel handling bldg Temporary relief from Tech Spec Action Statement 3 9 7 re handling of loads over fuel pool will be requested CRANE, P A Pacific Gas & Electric Co 82/12/16 KNIGHTON, O W Licensing Branch 3 2pp 16493 016 24X Fiche: 50-323, 82/12/16, 8212210090
- 8/12230278 Forwards Revision 2 to "Diable Canyon Project GA Program," in response to DO Eisenhut 821202 request CRANE.P A. Pacific Gas & Electric Co 82/12/21 KNIGHTON.G W Licensing Branch 3 ip 16507 051 24% Fiche 50-275.82/12/21, 8212230298
- --8212230304 Revision 2 to "Diablo Canyon Project GA Program "
 * Pacific Gas & Electric Co # Brottel Corp 80-TGP-1 RO2
 62/12/21 16pp 16507 052 24X Fiche-50-275,62/12/21,8212230278

- F Security, medical, emergency & fire protection plans
- BP12080057 Releases public Version of revised emergency plan implementing procedures FELTON. JM Division of Rules and Records 82/12/02 Pocument Management Branch ip 16367 214 24X Fichs 50-275, 82/12/02, 82/1208057
- --8212080063 Forwards public version of revised emergency plan implementing procedures, including Procedures EP OP-18A reloss of charging & EP OP-18B reloss of normal letdown CRANE, P A Pacific Gas & Electric Co 82/11/24 ENGELKEN. R H Region 5, Office of Director 2pp 16367 215 24X Fiche 50-275,82/12/02,8212080057
- --8212080071 Public version of revised emergency plan implementing procedures, including Procedures EP OP-18A re loss of charging EP OP-18B re loss of normal letdoun & EP R-1 re personnel injury or illness (radiologically-related) THORNBERRY, R C Pacific Cas & Electric Co 82/11/03 55pp 16367 217 24X Fiche 50-275,82/12/02.8212080057
- 9212130070 Confirms permanent & interim emergency operations facilities info per 821202 verbal request Permanent & interim sites located 11 7 miles from facilities Interim structure complete & successfully fested CANNE.P A Pacific Gas & Electric Co 82/12/07 KNIGHTON, G W Licensing Branch 3 ip 16391 164 24X Fiche 50-275,82/12/07, 8212130070

G Adjudicatory correspondence

- 8P12060104 Order extending time until 821208 for Commission to act to review NRR Director 820782 denial of Joint Intervenors 10CFR2 206 pecition
 CHILK, S J Office of the Secretary of the Commission 82/12/01 Commissioners 1p 16314 362 24X Fiche 50-275,82/12/01.
- 8912090084 Motion for extension of time until 821220 to file brief opposing intervenor exceptions to ASLB decision Time extension necessary due to meetings on east coast Certificate of Svc encl
 CRANE, P A Pacific Gas & Electric Co 82/12/06 Atomic Safety and Licensing Appeal Panel 4pp 16357 188 24X
 Fiche 50-275, 82/12/06, 8212090084
- 8P12090097 Order extending time until 821215 for Commission to art to review NRR Director 820922 denial of Joint Intervenors 10CFR2 204 petition CHILK.5 J Office of the Secretary of the Commission 82/12/07 Commissioners 1p 16357 283 24% Fiche 50-275,82/12/07,821209097
- 8P12150051 Order extending time until 821222 for Commission to act to review NRR Director 820922 denial of Joint Intervenors 10CFR2 206 petition CHILK, 8 J Office of the Secretary of the Commission 82/12/14 Commissioners 1p 16422 323 24X Fiche 50-275,82/12/14.
- BP12150057 Order extending time until 821221 for Commission to respond to ALAB-681 CHILK, 8 J Office of the Secretary of the Commission 82/12/14 Commissioners ip 16431 007 24X Fiche 50-275, 62/12/14.
- SR12220394 Brief opposing util & NRC B21108 briefs supporting exceptions to ASLB requirement that NRC receive FEMA finding of adequacy of State of CA radiological emergency response plan before plant can be licensed W/Certificate of Bvc BROWN, H H California, State of BROWN, H H Kirkpatrick, Lockhart, Hill. Christopher & Phillips 82/12/20 Atomic Safety and Licensing Appeal Panel 9pp 16517 251 24X Fiche 50-275,82/12/20,8212220394
- 8P12280123 Response in opposition to Joint Intervenors briefs in support of exceptions to ASLB 820831 order authorizing NRR director to issue full power QL No new arguments placed before ASLAB Certificate of Svc encl NORTON.B Pacific Oas & Electric Co MORTON.B Norton, Burke, Berry & French 82/12/20 Atomic Safety and Licensing Appeal Panel 40pp 16564 140 24% Fiche 50-275.82/12/20,8212280123
- 8F12280288 Brief in opposition to util & NRC briefs in support of exception to 820831 initial decision Desire for more expeditious licensing is patently inadequate excuse for ignoring regulatory stds. Certificate of Svc encl REYNGLDS, J R Joint Intervenors-Diablo Canyon REYNGLDS, J R Center for Law in the Public Interest 82/12/20 Atomic Safrty and Licensing Appeal Panel 22pp 16561 334 24X Fiche 50-275,82/12/20.8212280288

- B212230360 Order extending time, until B21229, for Commission to decide whether to review NRR Director B20922 denial of Joint Intervenors request for action filed under 10CR2 206 CMILK. S J Office of the Secretary of the Commission B2/12/22 p 16511 165 24X Fiche 50-275.82/12/22.8212230360
- 8P12270217 Memorandum & Order CLI-82-39, ruling on three questions certified on 820716 Issuance of suspension order & establishment of independent design verification program not intended to deprive adjudicatory boards of jurisdiction CHILK, S. J. Office of the Secretary of the Commission 82/12/23 7pp 16536 206 24X Fiche 50-275,82/12/23,8212270217

if General correspondence

- 3212130375 Responds to 821025 request for add1 info on design varification program Util corrective action program per SECY 82-414, principal reason for determining that design verification effort goes beyond Commission order CISEMHUT.D 0 Division of Licensing 82/11/24 SIEOEL.9 M Yoward Utility Rate Normalization 3pp 16412 085 24X Fiche 50-275,82/11/24,8212130395
- --8211020166 Requests elaboration on encl newspaper article re mod & investigation program at facility
 SIEGEL.8 M Affiliation Unknown 82/10/25 DENTON, H NRC No
 Detailed Affiliation Given 3pp 16412 088 24X
 Fiche 50-275
- 82/12170373 Advises that 821115 ltr to Chairman Palladino re seismic qualification of turbine bldg & recommendation for independent analysis by BNL will be provided to other Commissioners EISENMUT, 0 © Division of Licensing 82/12/08 ROESSET, J Roesset, J M 4pp 16478 085 24X Fiche 50-275, 82/12/08, 4212/70373
- --8212170378 Charifies 821110 statements re seismic qualification of turbine bldg Recommendation for independent analysis by BNL justified Transmittal of Clarifications to other Commissioners requested RDESSET, J M Rosset, J M 82/11/15 PALLADINO, N J Commissioners 1p 16478 088 24X Fiche 50-275,82/12/08,8212170373

${\mathbb P}$ Operating license stage documents ${\mathcal V}$ correspondence

- G212140278 Forwards agenda for 821214-15 meetings in San Francisco.CA for technical discussion of RL Cloud & Associates requests for info COOPER.W E Teledyne Engineering Services 82/12/14 NRC Nu Detailed Affiliation Civen 3pp 16402 107 24X fiche 50-275,82/12/14,8212140278
- G Inspection reports, IE Bulletins & correspondence
- SPOBI90240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 62/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208170240
- 820BF90245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model BO2 Thermolominescent Dosimeters " Svc list rnc! COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,820B19024
- GP:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp. 16411 199—1243 Fache 50-000-82/11/18,8208190251
- 82'12060155 Discusses 820209 ltr re adequacy of NUREG-0862, "Insp Rept of Preliminary Rept. Saismic Revenification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2 " Questions posed through 820423 Ofc of Inspector & Auditor review answered PALLADIND, N J Commissioners 82'/11'/23 UDALL, M K House of Rep , Interior & Insular Affairs 2pp 16325 232 24X Fiche 50-275, 82'/11'/23, 8212060155
- --8212060164 Discusses 820204 ltr re adequacy of NUREO-0862, "Insp Rept of Preliminary Rept.Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 & 2" Guestions posed through 820423 Ofc of Inspector & Auditor review answered PALLADIND.N J Commissioners 82/11/23 OTTINGER.R House of Rep : Energy & Commerce 2pp 16925 234 24x Fiche 50-275, 82/11/23, 8212060155

- --B212060177 Submits review of NUREO-0862, "Insp Rept of Preliminary Rept. Seismic Reverification Program at Diablo Canyon Nuclear Power Plant, Units 1 ± 2," per Udall 820208 & Ottinger 820204 requests Investigation conducted in 2 phases CUMMINOS, J. Office of Inspector & Auditor 82/07/30 PALLADINO, N. Commissioners 7pp 16325 236 24X Fiche 50-275, 82/11/23, 8212060155
- 8208190254 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks" 8vc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Mati " Svr list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR C095 Relay Bockets " Svc list enc! JORDANIE L Division of Engineering & Quality Assurance 62/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000, 82/12/03, 8208190261
- B±08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNG.R C Director's Office Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- B/08190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000:82/12/20.8208190268
- S Reportable occurrences, LERs & related correspondence
- BP1204007B Final deficiency rept re water hammer phenomenon in ouriliary saltwater sys Initially reported on 821008 Isolable vacuum breaker added to auxiliary saltwater sys to eliminate water hammer effect Design change farthcoming CRANE.P A Pacific Oas & Electric Co 82/11/08 ENGELKEN.R H Region 5. Office of Director 2pp 16314 356 24X Ficha 50-323,82/11/08,8212060078

DOCKET 90-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2 F. Security, medical, emergency & fire protection plans

- 8212090273 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 VERRELLI.D M Division of Project & Resident Programs 82/11/16 UTLEY, E E Carolina Power & Light Co ip 16365 289 24X Fiche 50-324, 82/11/16, 8212090273
- --8212070287 Responds to NRC 821006 itr re violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight add1 spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current DIET7.CR Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2. Office of Director 3pp 16365 270 24X Fiche 50-324,82/11/16,8212070273
- --8212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820707-10 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X Fiche 50-324,82/11/16,8212090273
- ~~G212090309 Notice of violation from insp on 820907-10 * Division of Project & Resident Programs 82/10/06 2pp 16365 295 24X Fiche 50-324. B2/11/16.8212090279
- ---8212070321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on B20707-10 Noncompliance noted failure to train all personnel required to use respirator protection properly & to have adequate number of spare air cylinders available MILLER, W H , CONLON, T E Division of Engineering & Technical Programs 82/09/28 Bpp 16365-297 24X Fiche 50-324,82/11/16,8212070273

- 82:2100032 Forwards info re emergency operations facility in response to NRC 82:202 verbal request & Generic Ltr 81-10 Info based on util understanding of SECY-82-111
 ZIMMERNAN,S R Carolina Power & Light Co 82:12/06 VASSALLO, D & Operating Reactors Branch 2 Zpp 16379 033 24X
 Fiche 50-524, 82:12:706.52:12:100032
- P Operating license stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBUR, Big Rolk Point, Dreaden 1. Humboldt Bay.
 applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT. D 0 Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X
 Fiche 50-000, 82/11/15, 8211230066
- B212060160 Forwards request for add1 info to complete review of NUREC-0737.Action Items I A 2 I A. "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4. "Training to Hitigate Core Damage "Response requested within 60 days VASSALLO. D B. Operating Reactors Branch 2 82/11/16 UTLEY.E E Carolina Power & Light Co. 2pp 16325 246 24X Fiche 50-324.82/11/16.8212060160
- 8212060111 Forwards safety evaluation re MUREG-0737. Item II F 1 3. "Add1 Accident Monitoring Instrumentation," in response to 810630 & 820804 submittals Licensee proposed calibr
- 8212090307 Endorses BWR owners group B10522 & 0921 repts re NUREG-0737, Item II K 3 25. "Effect of Loss of AC Power on Pump Seals "Loss of Ac power will not significantly degrade recirculation pump seals ZIMMERMAN.5 R Carolina Power & Light Co 82/12/0A VASSALLO, D B Operating Reactors Branch 2 2pp 16365 129 24X Fiche 50-324.82/12/0A.8212090307
- B212100082 Application for amend to License DPR-62, requesting temporary exemption from Tech Spec 3 & 3, permitting 72-h for repairs of B21205 rupture in containment atmosphera control inerting line Expedited review requested 82/12/06 V EURY.L M Carolina Power & Light Co 82/12/0 Operating Reactors Branch 2 3pp 16379 177 Fiche 50-324,82/12/06,8212100082 VASSALLO, D B
- ~-8212100085 Proposed Tech Spec 3 6 6 3 re containment atmosphere oxygen 82/12/05 In 15379 180 24X
 - * Carolina Power & Light Co 8: Fiche 50-324,82/12/05,82(2)0082
- 8212140250 Forwards supplemental info re status of selected NUREG-0/37 requirements covered by Generic Ltrs 82-05 & 82-10.in response to NRC 820317 & 0505 requests

 UTLEY.E E Carolina Power & Light Co 82/12/06 EISENHUT, D Q
 Division of Licensing 3pp 16409 327 24% Fiche 50-324, 82/12/06, 8212140250
- B2:2140255 Request for amend to Licenses PPR-71 & DPR-62, revising, clarifying & providing editorial corrections to Tech Specs ra ATWŚ TO AIMS EURY,L W Carolina Power & Light Co 82/12/04 VA Operating Reactors Branch 3 2pp 16401 332 24X Fiche-50-324,82/12/06,8212140255
- --8212140257 Proposed Tech Specs for Licenses DPR-71 & DPR-62, revising, clarifying & providing editorial corrections re ATMS

 * Carolina Power & Light Co. 82/12/06 22pp 16401 334 24X Fiche 50-324, 82/12/06, 8212140255
- GP12150296 Requests application fee for Tech Spec changes re removal of MAPLHOR reduction penalty be remitted within 15 days of 1tr receipt
- 82:2170355 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs to incorporate organization changes Revisions suppl BIO728 submittal EURYL W Carolina Power & Light Co B2/12/10 VASSALL Operating Reactors Branch 2 2pp 16456 053 24X Fiche. 50-324, B2/12/10, B212170355 VASSALLO D B
- --8212170363 Proposed Tech Spec changes re administrative controls * Carolina Power & Light Co. 82/12/10 58pp 16484 055 2 Fiche 50-324,82/12/10.8212170355

- 8212170338 Supplemental application for amend to Licenses DPR~71 & PRP-SS Changes include mods to digital-to-analog instrumentation & reactor vessel ref water level,per 821005 meeting Revisions supersede 790531 revisions EURY.L W Carolina Power & Light Co 82/12/13 VASSALLO, Deprating Reactors Branch 2 3pp 16454 154 24X Fiche 50-324, 82/12/13,821≥170338 VASSALI (I. D. D.
- --8212170343 Proposed Tech Spec pages including mods to digital-to-analog instrumentation, reactor vessel ref water level special test exception for core spray sys, administrative controls & safety/relief valve challenges * Carclina Power & Light Co 82/12/13 287pp 16454 157 24x Fiche 50-324,82/12/13.8212170338
- -- 92:2170350 "Brunswick Steam Electric Plant Offsite Dose Calculation Manual (ODCM) " * Carolina Power & Light Co 82/12/13 190pp 16455 084 24X
- Fiche 50-324, 82/12/13, 8212170338
- --8212170354 "Brunswick Steam Electric Plant Process Control Program (PCP) * Carolina Power & Light Co 82/12/13 5pp 16455 274 24X Fiche 50-324/82/12/13/8212170338
- 8212210004 Application for amends to Licenses DPR-62 & DPR-71, correcting administrative inconsistency re min number of operable channels per trip sys requirements for certain HPCI & RCIC sys instruments

 EURY, L W Carolina Power & Light Co 82/12/13 VASSALLO, D Operating Reactors Branch 2 4pp 16485 262 24X

 Fiche 50-324, 82/12/13,8212210004 VASSALLO, D. B.
- --B212210006 Proposed Tech Apec revisions correcting administrative inconsistency re min number of operable channels per trip sys requirements for certain HPCI & RCIC sys isolation actuation instruments * Carolina Power & Light Co 82/12/13 10pp 16485 266 24X Fiche 50-324,82/12/13 B212210004
- G212170210 Commits to perform qualification testing of certain Raychem radiation cross-linked polyethylene cable having combined insulation thickness of 120 mils or greater Proposed cable qualification program forthcoming Qualification program forthcoming UTLEY.E E Carolina Power & Light Co 82/12/15 VASSALLO.D B Operating Reactors Branch 2 1p 16459 362 24X Fiche 50-324,82/12/15.8212170210
- B212300145 Forwards two supplemental repts to B20808 Franklin Research (tr rept re environ qualification of safety-related electrical equipment submitted on B21220 w/evaluation Space charges phenomenon valid concern W/o encl VASSALLO, D B Operating Reactors Branch 2 62/12/23 UTLEY, E E Carolina Power & Light Co 3pp 16624 188 24X fiche 50-324,82/12/23.8212300145
- @ Imspection reports: IE Bulletins & correspondence
- 82/08190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter: Stainless Steel, Recirculation Sys Piping at BiR Plants "Syc list encl
 DEYGUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Ins
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl CODB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8209190245
- 8212090273 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 VERRELLI.D H Division of Project & Resident Programs 82/11/16 UTLEY.E E Carolina Power & Light Co 1p 16365 289 24% Fiche 50-324.02/11/16.8212090273
- --8212070287 Responds to NRC 821006 itr re violations noted in IE Insp Repts 50-324/82-37 & 50-329/82-37 Corrective actions eight add1 spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current DIET2, C.R. Carolina Power & Light Co. 82/10/27 O'REILLY, J.P. Region 2, Office of Director. Spp. 16365-270 24X Fiche 50-324,82/11/16,8212070273
- --8212090299 Forwards IE Insp Repts 50-324/82-37 & 50-328/82-37 on 820907-10 & notice of violation, LEWIS.R C Division of Project & Resident Programs 82/10/05 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X Fiche 50-324,82/11/16,8212090273

- --8212070307 Notice of violation from insp on 820707-10 * Division of Project & Resident Programs 82/10/06 2pt 16365-295 24X Fiche 50-324,82/11/16,8212070273
- --B212090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on B20907-10
 Noncompliance noted failure to train all personnel required
 to use respirator protection properly & to have adequate
 number of spare air cylinders available
 MILLER.W H , CONLON.T E Division of Engineering & Technical
 Programs 82/09/28 Bpp 16365 297 24X Fiche 50-324.82/11/16,
 8212090273
- 82/08/190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAM: E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24 Fische 50-000.82/11/18.8208/90251
- B212090111 Forwards summary of B21110 meeting w/util in Atlanta.GA reactions taken by util to improve overall performance D*REILLY.JP Region 2. Office of Director B2/11/24 UTLEY.C E Carolina Power & Light Co 3pp 16357 242 24X Fiche 50-324, 82/11/24, 8212090111
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190296
- 8.708190257 JE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L [Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 90-000,82/11/30,8208190257
- BC:12090375 Advises that stress rule index & carbon content adopted as criteria for weld sample selection per MAREO-0313, Revision i Info required by Item 4 of IE Bulletin 82-03, Revision i will be provided by 821217
 HOME, P N Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Office of Director ip 16365-056 24X
 Fiche 50-324, 82/11/30, 8212090375
- 82)2090129 Forwards summary of 821117 meeting at site re integrated & local leav test programs & cracked weld in RHR shutdown cooling suction piping per IE Insp Rept 50-324/82-41
 O'REILLY.J P Region 2. Office of Director 82/12/02 UTLEY.F E Carolina Power & Light Co 3pp 16357 322 24X
 Fiche 50-324,82/12/02,8212090129
- 6: 08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUND; R C Director's Office, Office of Inspection and Fnforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8:/08170261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JORDAN, EL Bivision of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24 Fiche 50-000, 82/12/03, 8208170261
- 8208190267 [E Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG: R C Director's Office Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.62/12/16.8208190267
- BPOB190248 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc! JORDAN,E L. Division of Engineering & Guality Assurance. B2/12/20 Consolidated Edison Co of New York, Inc. 108pp. 16628 293 24: Fiche 50-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- 82:12100241 Forwards monthly operating repts for Nov 1982 BIETZ.C.R. Carolina Power & Light Co. 82/12/06 DEYOUNG.R.C Director's Office, Office of Inspection and Enforcement , 1p 16376 050 24x Fiche 90-324.82/12/06.8212100241
- --B212100250 Monthly operating repts for Nov 1982 HARRISON,F Carolina Power & Light Co 82/12/01 13pp 16376 051 24X Fiche 50-324,82/12/06.8212100241

- S Reportable occurrences, LERs & related correspondence
- 9212020273 Forwards LER 82-126/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16279 138 24X Fiche 50-324,82/11/23,8212020273
- --82i2020297 LER 82-126/03L-O on 82i024. standby liquid control sys pipin heat tracing on lines between sys accumulators 2-641-A003A & B & common discharge line found inoperable Caused by electrical failure Tracing section Model FP-10 replaced PASTVA.M J Carolina Power & Light Co 82/11/23 Region 2. Office of Director ip 16279 139 24X Fiche 50-324.82/11/23, 8212020293
- 8212020315 Forwards LER 82+125/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/23 Q'REILLY.J P Region 2. Office of Director 1p 16279 200 24Y Fitche 50-324, 82/11/23, 8212020315
- --B212020319 LER 82-129/OSL-O on B21024, during steady-state plant operation, reactor recirculation gump 2A tripped w/receipt of ATMS high reactor pressure/low level trip annunciator Caused by setpoint drift instrument calibr & returned to svc PASTVA:M J Carolina Power & Light Co 82/11/23 Region 2, Ofrice of Director 2pp 16279 201 24% Fiche 50-324,82/11/23,8212020315
- 8212020362 Forwards LER 82-113/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/23 O'REILLY, J P Region 2, Office of Director 1p 16278 182 24X Fiche 50-324 82/11/23.8212020362
- --8212020365 LER 82-117/03L-0 on 821026, fire watch patrol not posted during removal of five fire barrier ponetration seals in control bldg Caused by unfamiliarity w/limiting conditions for operation & fire watch requirements
 PASTVA, M J Carolina Power & Light Co 82/11/23 Region 2.
 Office of Director ip 16278 183 24X Fiche 50-324, 82/11/23, 8212020362
- B?1202006B Forwards LER B2-09B/03L-0 DIETZ.C R Carolina Power & Light Co B2/11/24 O'REILLY, J P Region 2. Office of Director 1p 16272 004 24X Fiche 50-324, 82/11/24, 821202006B
- --B2120200B3 LER 82-078/03L-0 on 821027, measured vibration reading of 28 RNR svc water pump exceeded 1 5 mils vibration Caused by failed gasket at pump rear bearing housing allowing loss of casing oil, resulting in increased operating temp PASTVA.M J. Carolina Power & Light Co. 82/11/24 Region 2, Office of Director ip 16272-005 24X Fiche 50-324,82/11/24,8212020068
- 87)2020152 Forwards LER 82-127/03L-0 DIETZ,C R Carolina Power & Light Co 82/11/24 O'REILLY, J P Region 2. Office of Director 1p 16274 170 24X Fiche 50-324, 82/11/24, 8212020152
- --B212020161 LER 82-129/03.-0 on B21028, while verifying rod drivu coupling for rad 18-07, and overtravel annunciator received Cause unknown Rod will be inspected for irregularities during next scheduled control rad drive rebuilding outage PASTVA.M J Carolina Power & Light Co 82/11/24 Region 2. Office of Director 1p 16274 171 24X Fichs 50-324,82/11/24.8212020152
- BP12070273 Forwards LER 82-128/03L-0 DEETZ.C R Carolina Power & Light Co 82/11/24 O'REILLY, J P Region 2. Office of Director 1p 16339 073 24X Fiche 50-324, 82/11/24, 8212070273
- --8212070275 LER 82-128/03L-0 on 821025, instrument recorder 2-CAC-AR-10, showed downscale indication of primary containment atmosphere hydrogen & oxygen concentration Gaused by failed recorder print drive motor Drive motor replaced PASTVA, M J. Carolina Power & Light Co. 82/11/24 Region 2, Office of Director ip 16339 074 24X Fiche 50-324,82/11/24, 8212070273
- BP12070295 Part 21 rept re discrepancies between orientation of snubbers as shown on pipe support details & orientation as used in analysis of record Review of supports design & issue of any fixes scheduled for completion by B21201 for Unit 1 BARSTEN.O E United Engineers & Constructors, Inc. (subs of Raytheon Co) B2/11/30 Director's Office, Office of Inspection and Enforcement 2pp 14339 044 24X Fiche 50-324,82/11/30, B212070295

- 6212090314 Forwards LER 62-124/01T-O Detailed event analysis and DIETZ.C R Carolina Power & Light Co 82/12/03 (FREILLY, J P Region 2. Office of Director 2pp 16365 120 24X Fiche 50-324.82/12/03.8212090314
- --8212070318 LER 82-124/01Y-0 on 821121, quick start testing of diesel generators 1,2 & 4 not performed within required 2-h period Caused by misinterpretation of plant standing instructions Quick starts performed instructions revised PASTVA.M J Carolina Power & Light Co 82/12/03 Region 2. Office of Director 1p 16365 122 24X Fiche 50-324,82/12/03,8212903344
- 8212300067 RO 2-82-139 on 821216 reactor water cleanup sys high differential flow isolation instrumentation declared inoperable due to erratic flow transmitter Caused by personnel error Instrumentation repaired & restored to syc BIETZ-C R Carolina Power & Light Co 82/12/17 O'REILLY, J P Region 2. Office of Director 2pp 16598 202 24X Fiche 50-324-82/12/17,8212300067
- B212280278 PND-II-82-137 on 821213, maifunctioning delta flow instrument on reactor water cleanup sys identified On 821216 operability of isolation instrumention questioned Sys isolated Investigation of circumstances ongoing HARDIN, A.K., VERRELLI.D.M. Region 2, Office of Director 82/12/20 2pg 16561 228 24x Fiche 30-324,82/12/20,8212280278
- DOCKET SO-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8212090273 Ack receipt of B21027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 VERRELLI,D M Division of Project & Resident Programs B2/11/16 UTLEV,E E Carolina Power & Light Co ip 16345 287 24X Fiche 50-324,82/11/14.9212090273
- --0212090209 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-324/02-37 & 50-325/02-37 Corrective actions eight add1 space cylinders purchased & weekly review to be conducted to ensure fire brigade training current DIEYZ,C R Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2. Office of Director 3pp 16365 290 24X Fiche 50-324,02/11/16/8212090273
- --B212070299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820707-10 & notice of violation LEHIS.R C Division of Project & Resident Programs 82/10/06 JUNES.J A Carolina Power & Light Co 2pp 16365 293 24X Fiche 50-324.82/11/16.8212090273
- --B212090309 Notice of violation from insp on 820907-10 * Division of Project & Resident Programs 82/10/06 App 16365-295 24X Ficho 50-324,82/11/16.8212090273
- --8218090321 IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10 Noncompliance noted failure to train all personnel required to use respirator protection properly & to have adequate number of spare air cylinders available MILLER.H H Division of Engineering & Technical Programs 82/09/28 8pp 16365 297 24X Fiche 50-324,82/11/16,82180902/3
- 8P12100032 Forwards info re emergency operations facility in response to NRC 821202 verbal request & Generic Ltr 81-10 Info based on util understanding of SECY-82-111
 ZIMMERHAN, 8 R Carolina Power & Light Co. 82/12/06 VASSALLO. D B Operating Reactore Branch 2 2pp 16379 033 24X
 Fiche 50-324,82/12/06,8212100032
- P Operating license stage documents & correspondence
- GP11230066 Generic Ltr 82-27 to all BMR licenses of operating reactors except LACEMR, Big Rock Point Dresden 1. Humboldt Bay, applicants for OL & helders of CP re transmittal of NUREO-0783 & NUREO-0783 Svc list encl W/o stated encl EISENNUT, D 0 Division of Excensing B2/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24% Fichs 50-000.82/11/15,6211230066
- BP12060160 Forwards request for add1 info to complete review of NUREG-0737.Action Items I A 2 I 4. "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B. 4. "Training to Nitigate Core Damage " Response requested within 40 days VASSALLO.D B. Operating Reactors Branch 2. 82/11/16 UTLEY.E E Carolina Power & Light Co 2pp 16325 246 24X Fiche 50-324.82/11/16.8212060160

- BP[2060fil Forwards safety evaluation re NUREO-0737, Item II F 1 3. "Add! Accident Monitoring Instrumentation," in response to 810630 & 820804 submittals Licensee proposed calibr procedures acceptable VASSALLO.D B Operating Reactors Branch 2 82/11/22 UTLEY, E Carolina Power & Light Co 3pp 16323 013 24X Fichs 50-324, 82/11/22, 8212060111
- 62:12070307 Endorses BNR owners group 8:0522 & 0721 repts re NUREG-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals " Loss of ac power will not significantly degrade recirculation pump seals IMMERMAN.5 R Carolina Power & Light Co 82/12/06 VASSALLO, D 8 Operating Reactors Branch 2 2pp 16965 127 24X Fiche 50-324.82/12/06.8212070307
- 8212140250 Forwards supplemental info re status of selected NUREG-0/37 requirements covered by Generic Ltrs 82-05 & 82-10, in response to NRC 820317 & 0505 requests UTLEY/E E Carolina Power & Light Co 82/12/04 EISENHUT, D 0 Division of Licensing 3pp 16407 327 24X Fiche 50-324, 82/12/06, 8212140250
- 8212140255 Request for amend to Licenses DPR-71 & DPR-62, revising, clarifying & providing editorial corrections to Tech Specs re ATWS
 EURY, L W Carolina Power & Light Co 82/12/06 VASSALLO, D B Operating Reactors Branch 3 2pp 16401 332 24X
 Fiche 50-324, 92/12/06, 8212140255
- ~-B212140297 Proposed Tech Specs for Licenses DPR-71 & DPR-62, revising, clarifying & providing editorial corrections re ATMS
 * Carolina Power & Light Co 82/12/06 22pp 16401 334 24X
 Fiche 50-324.82/12/06.8212140255
- BEL2170355 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs to incorporate organization changes Revisions suppl 810728 submittal EURY, L W Carolina Power & Light Co 82/12/10 VASSALLO. D B Operating Reactors Dianch 2 2pp 16456 053 24X Fishe 50-324, 82/12/10, 8212170355
- --8212170363 Proposed Tech Spec changes re administrative controls * Carolina Power & Light Co 82/12/10 56pp 16456 085 24X Fiche 50-324.82/12/10.8212170355
- 821217033B Supplemental application for amend to Licenses DPR-71 & DPR-52 Changes include mods to digital-to-analog instrumentation & reactor vessel ref water level, per 821005 meeting Revisions supersede 790531 revisions EURY, L N Carolina Power & Light Co 82/12/13 VASSALLO, D D Operating Reactors Branch 2 3pp 16454 154 24X Fiche 50-324,82/12/13,8212170338
- --8212170343 Proposed Tech Spec pages including mode to digital-to-analog instrumentation, reactor vessel ref water level, special test ecception for core spray sys. administrative controls & safety/relief valve challenges * Carolina Power & Light Co 82/12/13 287pp 16454 157 24% Fiche 50-324,82/12/13,8212170338
- --8212170350 "Brunswick Steam Electric Plant Offsite Dose Calculation Manual (DDCM)"

 Carolina Power & Light Co 82/12/13 190pp 16455 084 24% Fiche 50-324,82/12/13,8212170338
- --8212170356 "Brunswick Steam Electric Plant Process Control Program (PCP) "

 * Carolina Power & Light Co 82/12/13 5pp 16495 274 24X Fiche 50-324,82/12/13,8212170338
- SP12210004 Application for amends to Licenses DPR-62 & DPR-71, correcting administrative inconsistency re min number of operable channels per trip sys requirements for certain HPC1 & RCIC sys instruments
 EVRY, L W Garolina Power & Light Co B2/12/13 VASSALLO, D D Uperating Reactors Branch 2 App 16465 262 24X
 Fiche 50-324, 82/12/13, 8212210004
- -- 8212210006 Proposed Tech Spec revisions correcting administrative inconsistency remin number of operable channels per trip sys requirements for centain HPCI & RCIC sys isolation actuation instruments

 * Carolina Power & Light Co 82/12/13 10pp 16485 266 247 Fiche 50-324,82/12/13.8212210004
- 8212170210 Commits to perform qualification testing of certain Raychem radiation cross-linked polyechylene cable having combined insulation thickness of 120 mils or greater Proposed cable qualification program forthcoming

 UTLEYLE E Carolina Power & Light Co 82/12/15 VASSALLO,D B

 Operating Reactors Branch 2 1p 16459 362 24X

 Fiche 50-324,82/12/15,8212170210

DOCKETED ITEMS

- 32;2300145 Forwards two supplemental repts to 820808 Franklin Research Ctr rept re environ qualification of sefety-related electrical equipment submitted on 821220 w/eveluation Space rharges phenomenon valid concern W/o encl VASSALLO, D. 8 Operating Reactors 8ranch 2 82/12/23 UTLEY, E. Carolina Power & Light Co. 3pp. 16624 188 24X Fiche 50-324, 82/12/23, 8212300145
- u Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Svc list encl DEYDUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24x Fiche 50-000, 82/10/28, 8208190240
- 8;08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Syc list cncl
 CD88,L I Division of Fuel Facilities, Materials & Safeguards
 E2/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fichs 90-000, 82/11/05 8288190245
- 8/12070273 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 VERRELLI, D M Division of Project & Resident Programs 82/11/16 UTLEY, E Carolina Pauer & Light Co ip 16365 289 24X Fiche 50-324,82/11/16,8212070273
- --G212090289 Responds to NRC 821006 ltr re violations noted in IE Insp Repts 50-324/82-37 & 50-325/82-37 Corrective actions eight add1 spare cylinders purchased & weekly review to be conducted to ensure fire brigade training current DIETZ.C R Carolina Power & Light Co 82/10/27 O'REILLY, J P Region 2. Office of Director 3pp 16365 290 24X Fiche 50-324, 62/11/16, 8212090273
- -8212090299 Forwards IE Insp Repts 50-324/82-37 & 50-325/82-37 on 820907-10 & notice of violation LEMIS.R C Division of Project & Resident Programs 92/10/04 JONES, J A Carolina Power & Light Co 2pp 16365 293 24X Fiche 50-324, 82/11/16, 8212090273
- --8212090309 Notice of violation from inap on 820907-10 * Division of Project & Resident Programs 82/10/06 2pp 16365 295 24X Fiche 50-324, 82/11/16, 8212090273
- --B21209032: IE Insp Repts 50-324/B2-37 & 50-325/B2-37 on B20907-10
 Noncompliance noted failure to train all personnel required
 to use respirator protection properly & to have adequate
 number of spare air cylinders available
 MILLER.W H , CONLON.T E Division of Engineering & Technical
 Programs B2/09/28 Bpp 16365 297 24X Fiche 50-324, B2/11/16,
 B212090273
- 87/08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fithe 50-000,82/11/18,8208190251
- SEI2090111 Forwards summary of 821110 meeting w/util in Atlanta.9A re actions taken by util to improve overall performance O'REILLY.JP Region 2. Office of Director 82/11/24 UTLEY.E F Carolina Power & Light Co 3pp 16357 242 24X Fiche 50-324.82/11/24.8212090111
- 8POB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl UEVOUND,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 14411 045 24X Fiche 50-000.82/11/26.8208190256
- 82:08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82:11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 Each Fiche 50-000.82/11/30,8208190257
- 82:12070375 Advises that stress rule index & carbon content adopted as critaria for weld sample selection per NUREO-0313, Revision 1 Info required by Item 4 of IE Bulletin 82-03, Revision i will be provided by 82:217
 HOME.P W Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2, Ofrice of Director 1p 16365 056 24X
 Fiche 50-924, 82/11/30,8212070375

- 8212070129 Forwards summary of 821117 meeting at site re integrated & local leak test programs & cracked weld in RNR shutdown cooling suction piping per IE Insp Rept 50-324/82-41
 O'REILLY, J P Region 2, Office of Director 82/12/02 UTLEY, Ef-Carolina Power & Light Co. 3pp. 16357-322 24X
 Fiche 50-324, 82/12/02, 8212070129
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 133p 16411 317 24X Fichs 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets "Evo list and JGRDAN,E L. Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND:R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16:8208190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- 82:2100241 Forwards monthly operating repts for Nov 1782 DIETZ.C R Carolina Power & Light Co 92/12/06 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 1p 16376 050 24X Fishe 50-324,82/12/06,8212100241
- --B212100250 Monthly operating repts for Nov 1982 MARRISON.F Carolina Power & Light Co 82/12/01 13pp 16376 051 24X Fiche 50-324, 82/12/06, 8212100241
- S Reportable occurrences. LERs & related correspondence
- G212020306 Forwards LER 82-116/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/23 O'REILLY. J P Region 2. Office of Director 1p 16277 334 24X Fithe 50-325, 82/11/23.8212020306
- --8212020312 LER 62-116/03L-0 on B21027, RHR sys discharge valves to radwaste sys 1-Ei1-F040 & F047 found not fully closed Cause under investigation Supplemental rept outlining cause & corrective actions will be submitted PASTVA,M J Carolina Power & Light Co 82/11/23 Region 2, Office of Director 1p 16277 335 24X Fiche, 50-325, 82/11/23, pp:)2020304
- 82:12070008 Forwards LER 82-118/03L-0 DIETZ,C R Carolina Power & Light Co 82/11/24 O'REILLY,J P Region 2, Office of Director 1p 16327 238 24X Fiche 50-328.82/11/24.8218070008
- --8212070012 LER 82-118/03L-0 on 821026.RT0B narrow & wide-range instruments showed suppression pool level of -27 inches while actual level -26 5 inches Caused by instrumentation inaccuracies Instrumentation recallibr & pool level restored PABTVA:M J Carolina Power & Light Co 82/11/24 Region 2. Office of Director 1p 16327 239 24X Fiche 50-325.82/11/24.8212070008
- BP12070112 Forwards LER 02-106/03L-0 DIET7.C 8. Carolina Power & Light Co 82/11/24 D'REILLY, J P Region 2. Office of Director ip 16329 328. 24X Fiche 50-325.82/11/24.8212070112
- --8212070118 LER 82-106/03L-D on 821026, primary containment oxygen analyzer i-CAC-AT-1263-2 indicated drywell oxygen concentration 3% less than indicated by redundant analyzer i-CAC-AT-1257 Caused by instrument output shift PASTVA:NJ Carolina Power & Light Co 82/11/24 Region 2. Office of Director ip 16327 327 24% Fiche 50-325, 82/11/24, 8212070112
- 871207020B Forwards LER 82-117/03L-0 DIETZ,C R Carolina Power & Light Co 82/11/24, O'REILLY, J P. Region 2. Office of Director ip 16335 113 24X Fiche 50-325.82/11/24,8212070208

- --8212070214 LER 82-117/03L-0 on 821026, indicators 1-CAC-LI-2601-1 & 3 & 1-CAC-LR-2602 showed level indication of -29 inches, exceeding Tech Spac limit Caused by instrument drift Trickle flow adjusted & indicator recallbr PASTVA.M J Carolina Power & Light Co 82/11/24 Region 2. Office of Director 2pp 16335 114 24X Fiche 50-325, 82/11/24, 8212070208
- B212090167 Forwards LER 92-120/03L-0 DIETZ/C R Carolina Power & Light Co 82/11/29 O'REILLY/J P Region 2. Office of Director ip 16359 234 24X Fiche 50-325, 82/11/29, 9212090167
- --8212090173 LER 82-120/03L-0 on 821030; turbine control valve fast closure control oil pressure low switch EHC-PSL-1759 failed to actuate Cause could not be determined Switch exercised to ensure proper operation PABTVA; M J Carolina Power & Light Co 82/11/29 Region 2, Office of Director 1p 16359 239 24X Fichs 50-325, 82/11/29, 8212090167
- G212090535 Forwards LER 82-122/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/29 O'REILLY, J P Region 2. Deffice of Director ip 16366 025 24X Fiche 50-325, 62/11/29, 8212090535
- --8212090542 LER 62-122/03L-0 on 821030 & 1104, IA pump tripped On 821101 & 04, IB pump tripped Tripping concurrent w/receipt of ATWS high reactor pressure/low level trip annunciation Caused by actuation of ATWS due to electrical shorting PASTVA.M J Carolina Pawer & Light Co 82/11/27 Region 2, Office of Director 1p 16364 026 24X Fiche 50-325, 82/11/29, 8212090535
- 82:12090543 Forwards LER 82-124/03L-0 DIETZ.C R Carolina Power & Light Co 82/11/29 O'REILLY, J P Region 2. Office of Director 1p 16366 340 24X Fiche 90-325, 82/11/29, 82:12090543
- --8212090550 LER 82-124/03L-0 on 821030 primary containment atmosphere oxygen analyser 1-CAC-AT-1259-2 falsely indicated sudden downscale indication of drywell oxygen concentration Caused by shift in calibr setpoint due to moisture in lines PASTVA: M J Carolina Power & Light Co 82/11/29 Region 2, Dffice of Director 1p 16366 341 24X Fiche 50-325,82/11/29,8212090543
- BP12070295 Part 21 rept re discrepancies between orientation of snubbers as shown on pipe support details & orientation as used in analysis of record Review of supports design & issue of any fixes scheduled for completion by 821201 for Unit 1 SARSTEN.GE United Engineers & Constructors. Inc (subs of Raytheon Co) 82/11/30 Director's Office, Office of Inspection and Enforcement 2pp 16339-064 24X Fiche 50-324,82/11/30, 1010070998
- 82:2090100 Forwards LER 82-123/03L-0 DIETZ,C R Carolina Power & Light Co 82/12/01 O'REJLLY,J P Region 2. Office of Director 1p 16/357 309 24X Fiche 50-325,82/12/01.8212090100
- --B212090105 LER 82-123/03L-0 on 821101, performance of suppression pool level indicator operability test revealed remote shutdown panel instrument I-CAC-LI-3342 indicated incorrect level Caused by change in trickle flow to wet ref leg PASTVA:M J Carolina Power & Light Co B2/12/01 Region 2, Office of Director 2pp 16357 310 24X Fiche 50-325.82/12/01.8212090100
- 8212090135 Forwards LER 82-128/03L-0 DIETZ.C R Carelina Power & Light Co 82/12/03 O'REILLY, J P Region 2, Office of Director 1p 16359 177 24X Fich* 50-328, 82/12/03, 8212090135
- --B212090137 LER B2-128/O3L-0 on B21103.primary containment atmosphera organ analyzer 1-CAC-1259-2 tripped & could not be restarted Caused by failed low sample flow relay in instrument photohelic unit Photohelic unit replaced PASTVA:K J Carolina Power & Light Co B2/12/O3 Region 2, Office of Director 1p 16359 178 24% Fiche 50-325, B2/12/O3, B212090135
- 0212090147 Forwards LER 82-132/03L-0 DIETZ, C.R. Carolina Power & Light Co 88/12/03 O'REILLY, J.P. Region 2. Office of Director 1p 16359 167 24X Fiche 50-325, 62/12/03, 8212090147

- --8212090152 LER 82-132/03L-0 on 821105, routine surveillance revealed lack of position indication for PCIV 1-832-F0428 located at RIP-X-243A Caused by blown valve operator solenoid power supply fuse Fuse replaced PASTVA,M J Carolina Power & Light Co 82/12/03 Region 2, Office of Director 1p 16359 168 24X Fiche 50-325,82/12/03.
- GP12090453 Forwards LER 82-129/03L-0 DIETT, C R Carolina Power & Light Co 82/12/03 O'REILLY, J P Region 2, Office of Director ip 14363 247 24X Fiche 50-225, 82/12/03, 8212090453
- --8212090463 LER 82-129/03L-O on B21103 suppression chamber water trmp recorder 1-CAC-TR-778 on remote shutdown panel showed indications of temps but did not record Caused by worn print ink wheel not advancing due to adjustment problems PASTVAM J Carolina Power & Light Co 82/12/03 Region 2, Office of Director 1p 16363 248 24X Fiche 50-325, B2/12/03, B2(1290454)
- GP12140153 Forwards LER B2-130/03L-0 DEETZ.C R Carolina Power & Light Co B2/12/06 D'REILLY, J P Region 2. Office of Director 1p 16409 348 24X Fiche 50-325, B2/12/06, 8212140153
- --8212140159 LER 82-130/03L-0 on 821104, instrument isolation valve 1-821-F042A, located at RIP X-82B, automatically closed Caused by leakage through ref leg manifold isolation valves Valves will be repaired during next outage FASTVAM J Carolina Power & Light Co 82/12/04 Region 2, Office of Director 2pp 16409 349 24X Fiche 50-325, 82/12/04, 8212140153
- 82:2140196 Forwards LER 82-133/03L-0 PIETZ, C R Carolina Power & Light Co 82/12/06 O'REILLY, J P Region 2. Office of Director ip 16409 338 24X Fiche 50-325,82/12/06,8212140196
- --B212140202 LER B2-133/03L-0 on 821105 & 07, diesel low oil pressure tip occurred Caused by intermittent failures of diesel low lube oil pressure start time relay Relay replaced & generator quick started PASTVAM J Carolina Power & Light Co B2/12/06 Region 2, Office of Director 2pp 16409 339 24% Fiche 50-325,82/12/06, 8212140196
- 8212150112 Forwards LER 82-137/03L-0 DIETZ, C R Carolina Power & Light Co 82/12/08 O'REILLY, J P Hagion 2. Office of Director 1p 16430 347 24X Fiche 50-325.82/12/08,8212150112
- --8212150114 LER 82-137/03L-0 on 821111, routine surveillance revealed that indication of drywell oxygen concentration increased abruptly from 1 2 to 3 1% Caused by failure of atmosphere analyzer 1-CAC-AT-1263-2 due to zero shift Unit recalibr PASTVA, M J Carolina Power & Light Co 82/12/08 Region 2. Office of Director 1p 16430 348 24% Fiche 50-325,82/12/08,8212150112
- 8P12170141 Forwards LER 8R-139/03L-0 DIETZ, C R Carolina Power & Light Co 82/12/10 O'REILLY, J P Hagion 2. Office of Director 1p 16450 226 24X Fiche 50-325.82/12/10.8212170141
- -- G212170154 LER 82-139/03L-O on 821114.HPCI sys rendered inoperable when HPCI steamline flow high channel B isolation occurred during operability test Caused by shorted positioning coil in HPCI speed control electrohydraulic governing regulator actuator PASTVA, M J Carolina Power & Light Co G2/12/10 Region 2, Office of Director 2pp 16450 227 24X Fiche 50-325,82/12/10, G2/2170141
- BP12170216 RB on 821209, while performing corrective maint on main steam line high flow isolation instrument Group I isolation signal mistakenly reset Placement of jumpers in control logic allowed resetting of isolation Signal reinserted DIETZ, C R Carolina Power & Light Co 82/12/10 O'REILLY, J P Region 2, Office of Director 2pp 16459 352 24X Fiche 50-325, 82/12/10, 8212170216
- 8212210399 Forwards LER 82-138/03L-0 DIETZ, C R Carolina Power & Light Co 82/12/13 O'REILLY, J P Region 2. Office of Director ip 16493 035 24X Fiche 50-325, 82/12/13, 8212210399
- ~~B212210405 LER 62-138/03L-O on 821114, primary containment atmosphere oxygen analyzer 1-CAC-AT-1259-2 showed sudden unexpected upscale indication of drywell oxygen concentration Caused by moisture accumulation in sample lines Accumulation removed PASTVA:M J Carolina Power & Light Co 82/12/13 Region 2, Office of Director 1p 16493 056 24x Fiche 50-325,82/12/13, 6212210399

- 8:12210152 Forwards LER 82-119/03L-0 PIETZ.C R Carolina Power & Light Co 82/12/14 D'REILLY, J P Region 2. Office of Director 1p 16485 159 24X Fiche 30-325.82/12/14.8212210152
- --8212210159 LER 82-119/03L-0 on 821120, average power range monitor F declared inoperable due to erratic output signal from input local power range monitor 28-21C Cause undetermined Spare monitor installed PASTVA.M J Carolina Power & Light Co 82/12/14 Region 2, Office of Director 1p 16485 160 24X Fiche 50-325,82/12/14, page 20152
- 8.212210030 Forwards LER 82-141/03L-0 DIETZ.C R Carolina Power & Light Co 82/12/15 O'REILLY.J P Region 2. Office of Director 1p 16485 358 24x Fiche 50-325,82/12/15,8212210030
- --B212210032 LER 82-141/03L-O on 821124, post-accident noble gas radiation detection instrument 1-CAC-AT-1261-3 indicated downscale Caused by moisture accumulation on photomultiplier tubes due to dacaged mylar detector window Window replaced PASIVA.M J Carolina Power & Light Co 82/12/13 Region 2. Office of Director 2pp 16485 359 24X Fiche 50-325.82/12/15, 8212210030
- GP12220488 Forwards LER 82-142/03L-0 BIETZ,C R Carolina Power & Light Co 82/12/17 O'REILLY,J P Region 2. Office of Director 1p 16503 242 24X Fiche 50-325.82/12/17.8212220488
- --8212220493 LER 82-142/03L-0, on 821121, standby gas treatment train ill stopped running Caused by moisture intrusion in train local control panel Train ill dried & cleaned & control logic relays replaced PASTVA.M J. Carolina Pawer & Light Co. 82/12/17 Region 2, Diffice of Director 2pp. 16503 243 24X Fiche 50-325,82/12/17,8212220488
- GP12220496 Forwards LER 82-143/03L-0 DIETZ.C R Carolina Power & Light Co 82/12/17 D'REILLY, J P Region 2, Office of Director ip 16503 256 24X Fiche 50-325, 82/12/17, 82182820496
- B212220504 LER 82-143/03L-0 on B21123, innor doors of personnel secondary containment personnel airlocks discovered inoperable Caused by excessive leakage around seal Outer doors sealed & inner doors adjusted PASTVA.M J Carolina Power & Light Co B2/12/17 Region 2, Office of Director 1p 16503 257 24X Fiche 50-325,82/12/17.B212220496
- B2:2280383 Forwards LER 82-140/03L-0 BLETZ.C R Carolina Power & Light Co 82/12/18 O'REILLY, J P Hegion 2: Office of Director Ip 16557 001 24x Fiche 50-325, 62/12/18, 8212280383
- --B212280397 LER B2-i40/03L-0 on B21202, determined that min channels required operable for HPCI & RCIC isolation instruments identified in Tech Specs incorrect Caused by administrative error Tech Spec change submitted PQULK, R M Carolina Power & Light Co B2/12/18 Region 2, Office of Director 2pp 16559 002 24X Fiche: 50-325,82/12/18,82/1280383
- BP12300229 RD 1-82-154 on B21214, while detensioning reactor vessel head operational Mode 5 entered w/a meeting Tech Spec 3 O 4 requirements Investigation underway & Mode 5 requirements under review DIETZ.C R Carolina Power & Light Co B2/12/20 O'RETLLY, J P Region 2. Office of Director 2pp 16598 O31 24X fiche 50-325.82/12/20.8212300229
- 02:12300256 Forwards LER 82-144/03L-0 DIETZ.C R Carolina Power & Light Co 82/12/21 D'REILLY, J P Region 2. Office of Director ip 16575 260 24x Jiche 50-325, 82/12/21, 8212300256
- --3212300259 LER 82-144/03L-0 on 821127, suppression chamber water temp recorder i-CAC-TR-778, located on remote shutdown panel, perioditally failed to record Caused by recorder print mechanism relay K3 out of adjustment Relay adjusted PASTVA:N J Carolina Power & Light Co 82/12/21 Region 2. Bfice of Director 2pp 16595 261 R4X Fiche 50-325,82/12/21, 8212300256
- 8:12300307 Forwards LER B2-131/03L-0 DIETZ-C R Capolina Power & Light Co 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16594:218 24X Fiche 50-325, 82/12/21, 8212300307

- --B212300309 LER 82-\$31/03L-0 on 821127, surveillance revealed output voltage of battery charger for Div II battery 181 offscale high & charger capacitor on fire Caused by defective electrical resistor R5 on charger amplifier PASTVA, H J Carolina Power & Light Co B2/12/21 Region 2, Office of Director 1p 16594 219 24X Fiche 50-325, 82/12/21, 8212303030
- 8212300360 RO 1-82-154 an 821222, review revealed Mode 5 entered w/o meeting Tech Spec requirements Average power range monitors & bildy ventilation radiation monitors not verified operational Mode switch not locked in refuel position DIETZ.C R Carolina Power & Light Co 82/12/22 O'REILLY, J P Region 2, Office of Director 2pp 16594 241 24X Fiche 50-328, 82/12/22,8212300340
- 82:12300221 Forwards updated LFR 82-127/01T-1 DIETZ.C R Caroline Power & Light Co 82/12/23 O'REILLY.J P Region 2. Office of Director 1p 16598 036 24X Fiche 50-325, 82/12/23, 8212300221
- -- B212300225 Updated LER B2-127/017-1 on B21103.quick start testing of diesel generators 2,3 & 4 not performed for 12 h period per Tech Spec Caused by failure to enter requirement into daily surveillance rept on 821102 Testing performed PABTVA.M J Carolina Power & Light Co 82/12/23 Region 2, Office of Director 2pp 16578 037 24X Fiche 50-325,82/12/23,821230022;
- 0212300257 Forwards LER 82-147/01T-0 DIET7.C R Carolina Power & Light Co 62/12/23 O'REILLY, J P Region 2. Office of Director ip 16595 257 24X Fichs 50-325, 82/12/23,8212300257
- --B212300262 LER 82-149/01T-0 on 821209. limiting conditions for operation initiated on primary containment isolation sys instrument 1-B21-PDTM-N006-D-i due to downstale indications Caused by operator error Signal reinserted PASTVA: M J Carolina Power & Light Co 82/12/23 Region 2. Office of Director 2pp 16595 258 24X Fiche 50-325,82/12/23. 8212300257
- 82:2300316 Forwards updated LER 82-(10/03L-1 DIETZ.C R Carolina Power & Light Co 82/12/23 O'REILLY.J P Region 2. Office of Director 1p 16594 210 24X Fithe 50-325, 82/12/23,821230316
- B212300317 Updated LER 62-110/03L-1 on 821019, four suppression pool level indicators exceeded Tech Spec value during operability test Caused by incorrect input signal due to change in trickle flow to wet ref leg transmitter PASTVA.M J Carolina Power & Light Co 82/12/23 Region 2, Office of Director 2pp 16594 211 24 X Fiche 30-325,82/12/23,821200316
- 8212300331 Forwards supplemental LER 82-135/03L-1 DIETZ,C R Carolina Power & Light Co 82/12/23 O'REILLY,J P Region 2. Office of Director ip 16594 238 24X Fiche 50-325, 82/12/23,821230031
- --B212300334 Supplemental LER 82-135/03L-1 on B21019.1 5-inch discrepancy noted between narrow & wide range instruments Caused by inoperable RTGB level instruments Plant mod package developed to increase accuracy PASTVA.N J Carolina Power & Light Co 82/12/23 Region 2. Office of Director 2pp 16594 239 24X Fiche 50-325,82/12/23,8212300331
- DOCKET 90-327 SEQUOYAH AUGLEAR PLANT, UNIT 1

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212060033 Forwards draft supplemental SER (NUREO-001; Suppl 6), addressing review of permanent hydrogen mitigation sys Final draft will be available for review by 821206 NOVAK, TM Assistant Director for Licensing 82/11/30 FRALEY, R ACR8 - Advisory Committee on Reactor Safeguards 59pp 16325 265 24X Fiche 50-327, 82/11/30; 8212060033
- B212130339 Forwards proposed suppl to BER, updating NRC evaluation of issues re hydrogen mitigation sys License condition on hydrogen control provisionally resolved DIRCKS, N J. Office of the Executive Director for Operations 82/12/08 PALLADINO, N J., QILINSKY, V., AHEARNE, J. Commissioners 92pg 16412 214 24X Fiche 50-327, 82/12/08, 8212130339

- f Security, medical, emergency & fire protection plans
- GP12070180 Forwards add1 info.in response to NRC 821112 ltr.ltem 4.re fire protection program MILLB.C. H Tennessee Valley Authority 82/12/02 ADENSAM.E Licensing Branch 4 Spp 16034 294 24X Fiche 50-327,82/12/02, 8212070180
- 8212170229 Provides implementation schedule for generic security training & qualification plan Public safety employees have completed initial training Training per 10CFR50 54(p) will be completed by 830801

 MILLS, L M Tennessee Valley Authority 82/12/13 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 2pp 16462 020 24X Fiche 50-000-82/12/13.8212170229
- SP12170259 Notifies that required audit & Insp of fire protection & loss prevention program will be completed by 830917
 HILLS.L M Tennesses Valley Authority 82/12/14 ADENSAM.E
 Licensing Branch 4 1p 16456 206 24X Fishe 50-327,82/12/14,
 B212170259

H General correspondence

- 8212140478 Forwards missing Pages 63 & 66 of EIA re low level radwaste storage for Browns Ferry Nuclear Plant & SER & EIA on lowel radwaste storage facility at Sequoyah Nuclear Plant M/o enci LOYSEN.P Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 DREY.L A Affiliation Unknown 1p 16431.321 24X Fiche 50-000.82/11/23,8212140478
- ---8212140486 Requests missing pages to EIA on low level raduaste storage at Browns Ferry Nuclear Plant & copies of SER & EIA for Sequeyah Nuclear Plant DREY.L A Affiliation Unknown 82/11/08 Office of Nuclear Material Safety & Safeguards, Director 1p 16431 031 24X Fiche 50-000.82/11/23.8212140478

J Insurance & indemnity information

- 8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies PUCK, J.R. Harsh & McLennan, Inc. H. & M. Nuclear Consultants, Inc. Div. 82/11/18 HAINES, H.L. American Nuclear Insurers ip 16288 356 24X Fiche 50-000,82/11/18,8212020269
- B212290150 Forwards Endorsements 1,2 & 3 to NELIA Certificate N-64, Endorsements 1 & 2 to NELIA Certificate N-75.Endorsements 1, 2 & 3 to MELU Certificate M-66 & Endorsements 1 & 2 to MELU Certificate H-75

 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 35pp 16583 066 24X Fiche 50-327, 02/12/21, 0212270150
- 8212300109 Forwards Endorsement 29 to NELIA Policy NF-247 & Endorsement 24 to MAELU Policy NF-602 DUCK, J R Marsh & McLennan, Inc. M & M Nuclear Consultants, Inc. Div 82/12/21 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16598 253 24X Fiche 50-327,82/12/21,8212300109

O Advisory Committee on Reactor Safeguards reports & correspondence

- 6212270418 Responds to FDIA request for documents re proposed revision k/or update to reactor safety study referred to in NURCO-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON J H. Division of Rules and Records 82/11/26 SHOLLY, S C Union of Contened Scientists 3pp [6549 233 24x Fichs 50-000, 82/11/26, 8212270418
- --8212270466 Discusses feed & bleed DHR for facilities Using PORVs & high pressure injection pumps. We can heat could be removed w/o relying on secondary sys
 YOUNG.0 G ABBOTT.E C ACRS Advisory Committee on Reactor Safeguards 80/02/14 CARBOTN W ACRS Advisory Committee on Reactor Safeguards 80p 16549 266 24X Fiche 50-000,82/11/26.
 8212270418

P Operating license stage documents & correspondence

B212060061 Forwards response to 821117 verbal request for addl info re equipment survivability info supple 821101 response re hydrogen combustion & control for the condenser plants MILLS.L.H. Tennessee Valley Authority 82/11/27 ADENSAM.E. Licensing Branch 4 2pp 16314 012 24X Fiche 50-327.82/11/29, 8212060061

- B212060023 informs that util will upgrade emergency operating instructions (EDIs) as required by NUREQ-0737. Item I C 1 EDIs will follow generic guidelines developed by Westinghouse owners group NILLS.L M Tennessee Valley Authority 82/11/30 ADENSAM. E Licensing Branch 4 2pp 16313 327 24% Fiche 50-327, 82/11/30, 8212060023
- 8212060076 Forwards completed questionnaire in response to Generic Ltr 82-22 re steam generator tube integrity Info verbally provided to C Stable in 821130 telcon MILLS.L M Tennessee Valley Authority 82/11/30 ADENSAM.E Licensing Branch 4 2pp 16316 104 24X Fiche 50-327,82/11/30-B212060076
- B212070176 Forwards responses to NRC verbal questions on util B2091/ proposed Tech Spec change re degraded voltage relaying MTLLS.L M Tennessee Valley Authority 62/12/01 ADENSAM.E ticensing Branch 4 11pp 16334 314 24X Fiche 50-327.62/12/01. 8212070176
- B2:12080373 Requests relief from ASME Section XI requirement to hydrostatically pressure test replacement piping of essential raw cooling water sys Justification for deferral & one oversize drawing entl Aperture card is available in PDR MILLS.L M Tennessee Valley Authority 82/12/03 ADEMSAM.E Licensing Branch 4 3pp 16352 066 24X Fiche 50-327,82/12/03,8212050373
- 8208190263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISCHMUT, D G Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 29pp 16629 247 24X Fiche 50-000, 82/12/09, 8208190263
- 8212150010 Forwards addl info re equipment survivability per 821209 telcon request, revising 821129 submittal Core exit thermotouples located within pressure vessel & not exposed to hydrogen burning MAMMER, D S Tennessee Valley Authority 82/12/09 ADENBAM, E Licensing Branch 4 2pp 16421 176 24X Fiche 50-327, 62/12/09, 8212150010
- 8212140103 Generic Ltr 82-28 to all licensess of operating Westinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onefre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENHUT, D © Division of Licensing 82/12/10 Yankse Atomi Electric Co 27pp 16690 035 24X Fiche 50-000,82/12/10,82/12/40103
- BP12170236 Forwards add1 info re proposed change in instrument surveillance requirement test frequency of Tables 4 3-1 & 4 3-2 & thermal/hydraulic design parameters for Unit 1 reload safety evaluation NILLS.L M Tennessee Valley Authority 82/12/13 ADENBAM.E Licensing Branch 4 6pp 16459 337 24% Fiche 50-327.82/12/13.6212170236
- BP12170239 Requests proposed Tech Spec change for containment ventilation sys not be considered in review of 820917 reload safety evaluation MICLS.L if Tennessee Valley Authority 82/12/13 ADENSAM.E Licensing Branch 4 ip 16459 335 24X Fiche 50-327, 82/12/13, 3212170239
- B212290356 Notifies that util agrees to comply w/igniter operational temp limit of 1,700 F for permanent hydrogen mitigation sys, per B21223 telcon Tamp should be reconsidered upon completion of addl spray tests
 MILLS.L M Tennessee Valley Authority B2/12/23 ADENSAM.E
 Licensing Branch 4 1p 16586 223 24X Fiche 50-327.82/12/23, B212290356
- B212300351 Application for amend to Licenses DPR-77 & DPR-79, consisting of proposed changes to Tech Spec 4 8 1 1 2 d if re surveillance requirement for ac sources for electrical power sys.

 MILLS.L. H. Tennessee Valley Authority B2/12/23 ADENSAM.E
 Licensing Branch 4 2pp 16594 260 24X Fiche 50-327.82/12/23.

 B212300351
- --8212300355 Proposed changes to Tech Spec 4 8 1 1 2 d ii re surveillance requirement for ac sources for electrical power sys = Tennessee Valley Authority 82/12/23 4pp 16594 262 24X Fiche 50-327, 82/12/23,8212300351

- 9212300357 Application to amend Licenses DPR-77 & DPR-79, changing surveillance requirements for emergency gas treatment sys cleanup subsystems
 MILLS-L M Tennessee Valley Authority B2/12/23 ADENSAM, E
 Licensing Branch 4 2pp 16594 254 24X Fiche 50-327, B2/12/23, B2/2300357
- --B212300359 Proposed Tech Specs for Licenses DPR-77 & DPR-79 re surveillance requirements for emergency gas treatment sys cleanup subsystems Justification to support changes encl • Tennessee Valley Authority 82/12/23 4pp 16594 256 24X Fiche 50-327,82/12/23,8212300357
- 6:12300293 Forwards 16 proprietary figures referenced in GL amend request for vol reduction sys Figures withheld (ref 10CFR2 790) Affidavit encl NILLS.1 M Tennesses Valley Authority 82/12/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 16895 119 24X Fiche 50-327, 82/12/27, 8212300293
- G Inspection reports: IE Bulletins & correspondence
- B./UB190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall. Large-Diemeter: Stainless Steel. Recirculation Sys Piping at BMR Plants "Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Laforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000. B2/10/28. B208190240
- 8P12070486 Forwards IE Insp Repts 50-327/82-R3 & 50-328/82-R3 on 821005-08 & 18-22 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/11/02 PARRIS,H 0 Tennessee Valley Authority 2pp 16365-356 247 Fache 50-327,82/11/02,8212090486
- --B212090493 IE Insp Repts 50-327/82-23 & 50-328/82-23 on 821005-08 & 18-22 No noncompliance noted Major areas inspected refueling activities & plant bour THOMAS,M . JAPE,F Division of Engineering & Technical Programs 82/11/01 5pp 16345 358 24X Fichs 50-327,82/11/02,8212090486
- 8:06190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 t Model 802 Thermoluminescent Dosimeters " Svc list tricl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolisated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Frencise Requirements" Svc list encl JORDAN, E.C. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- G:'08190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list enc! IEFOUNIO, C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Isia 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208170256
- GPO8190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl "Syc list encl COSB.L I Division of Fuel Facilities, Materials & Safequards G2/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- G212090354 Ack receipt of B21108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-20 & ti0-328/82-20 VERRELLI,D M Division of Project & Resident Programs 82/11/30 PARRIS,H G Tennesses Vailey Authority Ip 16364 179 247 Fiche 50-327,82/11/30,8212090354
- --8212090365 Responds to NRC 821007 ltr re violations noted in IE Insp Repts 50-327/82-20 & 50-328/82-20 Corrective actions boric actd storage tank ventilation sys temporarily modified to prevent release of radioactive mabls to auxiliary bldg MILLS,L H Tennessee Valley Authority 82/11/08 0'REFLLY,J P Region 2, Office of Director 2pp 16364 180 24X Fishe 50-327,82/11/30.8212070354
- --8212090370 Forwards IE Insp Repts 50-327/82-20 & 50-328/82-20 on 820806-090\$ & notice of violation VERRELLI, D M Division of Project & Resident Programs 82/10/07 PARKIS, H 0 Tennessee Valley Authority 2pp 16364 182 24X Ficha 50-327,82/11/30,8212090354
- --G212070378 Notice of violation from insp on G20806-0905 * Division of Project & Resident Programs 82/10/07 16364 184 24% Fiche 50-327, 82/11/30.8212090354

- --8212090384 IE lnsp Repts 50-327/82-20 & 50-328/82-20 on 820806-0905 Noncompliance noted failure to post airborne radioactivity area FORD.C J. BUTLER.S D. QUICK.D R. Division of Project & Resident Programs 82/10/06 5pp 16364 185 24X Fiche 50-327.82/11/30, 82/2090354
- BPOB190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8708190261 IE Info Notice 82-48, "Failures of Agestat CR 0075 Relay Sockets" Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X
 Fiche 50-000,82/12/03,8208190261
- 82;2170318 Forwards add1 info relice condenser door surveillance inspresults Info supple 820729 & 0812 submittals
 MILLS.L M Tennessee Valley Authority 82/12/13 ADENSAM, E
 Licensing Branch 4 2pp 16456 156 24X Fiche 90-327, 82/12/13,
 8212170318
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000,82/12/16,8208170267
- GPOB19026B IE Info Notice 82-50, "Mod of Solid State AC Undervoitage Kelays Type ITE-27" Syr list encl JORDANIE L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190269
- R Periodic operating reports & related correspondence
- GP12290139 Forwards monthly operating repts for Oct 1982
 MABCH C C Southern California Edison Co B2/11/12 Division of
 Data Automation & Management Information 1p 16582 203 24X
 Fiche 50-327, 82/11/12, 8212290159
- --8212270164 Monthly operating repts for Oct 1982 MASON.C C . EDDINGS.M . JORDAN.M Tennessee Valley Authority 82/11/07 15pp 16982 204 24X Fiche 50-327.82/11/12.8212290159
- 8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982 MILLS.L.M. Tennessee Valley Authority 82/11/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000,82/11/30,8212030071
- 8012170388 Forwards "Annual Environ Operating Rept.810301-820914," per ETS Section 5 4 1 Future reporting periods will be for period beginning on Sept 15 & ending on Sept 14 of following yr MILLS.L M Tennessee Valley Authority 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16453 011 24X Fiche 50-327.82/12/07.8212170388
- --8212170390 "Amnual Environ Operating Rept.810301-820914"
 # Tennessee Valley Authority 82/12/07 178pp 16453 012 24X
 Fiche 50-327,82/12/07.8212170388
- S Reportable occurrences, LERs & related correspondence
- 8212030086 Forwards LER 82-130/03L-0 QREEN.H J Tennessee Valley Authority 82/11/29 D'RETLLY, J P Region 2, Office of Director 1p 16304 297 24X Fiche 90-327, 82/11/29, 8212030086
- ~-8212030092 LER 82-130/03L-0 on 820928 during routing performance of surveillance instruction 106, group 1 rows 1 & 2 min average ice weight less than required Caused by sublimation of ice in crane wall area Ice added CARVER.A M , HARDING M R. Tennessee Valley Authority 82/11/29 Region 2, Office of Director 1p 16304 260 24X Fiche 50-327, 82/11/29,8212030086
- 8P12140P41 Forwards LER 82-131/03L-0 GREEN.H J Tennessee Valley Authority 82/12/07 Q, REILLY, J P Region 2. Office of Director 1p 16409-300 24x Fiche 50-327, 82/12/07,8212140241

- --8212140247 LER 82-131/03L-0 on B21109, during Mode 6, nuclear instrumentation sys source range detector N-32 declared inoperable due to spiking Caused by heat gun used in work on penetration junction boxes Penetration work suspended ROSERS.H R , HARDINO.M R Tennessee Valley Authority 82/12/07 Region 2, Office of Director ip 16409 301 24X Fiche 50-327,82/12/07,8212140241
- 0/12280111 Forwards LER 82-135/03L-0 OREEN.H J Tennessee Vailey Authority 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16564 181 24X Fiche 50-327, 82/12/21, 8212280111
- --82:2280:16 LER 82-335/03L-O on 82:122, during Mode 5, three of four level switches on upper head injection sys found out of tolerance Caused by instrument drift Switches calibr & returned to svc LUDHIO,H C , HARDING:M R Tennessee Valley Authority Region 2. Office of Director ip 16564 182 24X Fiche 50-327, 02/12/21.821228011! 82/12/21

T Hearing transcripts on non-antitrust matters

- G212090182 Transcript of 821207 hearing in Washington, DC Pp 1-313
- Viewgraphs enci

 # ACR8 Advisory Committee on Reactor Safeguards 82/

 # ACR8 Advisory Committee on Reactor Safeguards 82/

 # ACR8 Advisory Committee on Reactor Safeguards 82/
- B212220550 Unofficial transcript of Commission B21215 discussion & possible vote in Washington.DC re hydrogen control Pp 1-90 Viewgraphs & BER (NUREG-0011, Suppl 4) entl * Commissioners B2/12/15 225pp 16540 0D1 24% Fiche 50-327,82/12/15,8212220550
- DOCKET 50-320 SEGUDYAH NUCLEAR PLANT, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 9712060033 Forwards draft supplemental SER (NUREG-0011, Suppl 6), addressing review of permanent hydrogen mitigation sys final draft will be available for review by 821206 NOVAK.T H Assistant Director for Licensing 82/11/30 FRAL ACRB Advisory Committee on Reactor Safeguards 59pp 16325 24X Fiche 50-327, 82/11/30, 8212060033 FRALEY. R 16325 269
- 8212130339 Forwards proposed supple to SER. updating NRC evaluation of issues religions mitigation systicanse condition on hydrogen control provisionally resolved DIRCKS.W J. Office of the Executive Director for Operations 82/12/08 PALLADINO, N J. GILINSKY, V. AHEARNE, J. Commissioners 92pp 16412 214 24X Fiche 50-327,82/12/08.8212130339
- F Security, medical, emergency & fire protection plans
- 8212070180 Forwards addl info.in response to NRC 821112 ltr, Item 4.re fire protection program
 MILLS.L M Tennessee Valley Authority 02/12/02 ADENSAM.E.
 Licensing Branch 4 5pp 16334 294 24% Fiche 50-327, 82/12/02
- 8212170227 Provides implementation schedule for generic security training & qualification plan Public safety amployees have completed initial training Training per IOCFR50 54(p) will be completed by 803801

 MICLS, LM Tennessee Valley Authority 82/12/13 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 2pp 16462 020

 P4X Fiche 50-000,82/12/13,8212170229
- B212170259 Notifies that required audit & insp of fire protection & loss prevention program will be completed by B30917 MLLS.L M Tennessee Valley Authority. B2/12/14 ADENSAM.E Licensing Branch 4 1p 16456 206 24X Fiche 50-327, B2/12/14, G212170259

H General correspondence

orwards missing Pages 65 & 66 of EIA re low level radwacte r Browns Ferry Nuclear Plant & 5ER & EIA on radwaste storage facility at Beguoyah Nuclear Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 Affilation Unknown 1p 16431:321 24% 05.82/11/23.8212140478

FIA on low level raduasts storage pies of SER & EIA for

Office of Nuclear 16431-031 24X 82/11/08 ī p

- J Insurance & indomnity information
- 8212020267 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liebility insurance facility form polities DUCK, J.R. Marsh & McLennan, Inc., M.&.M. Nuclear Consultants, Inc. Usv. 82/11/18 HAINES, H.L. American Nuclear Insurers ip 16288 356 24X Fiche 50-000, 82/11/18, 8212020269
- 8212290150 Forwards Endorsements 1,2 & 3 to NELIA Certificate N-66.
 Endorsements 1 & 2 to NELIA Certificate N-75, Endorsements 1,
 2 & 3 to MAELU Certificate M-66 & Endorsements 1 & 2 to
 MAELU Certificate M-75
 BUCK, J R Marsh & McCennan, Inc., M & M Nuclear Consultants, Inc. Div
 82/12/21 SALTZMAN, J Assistant Director for State & Licensee
 Relations 35pp 16583 066 24X Fiche 50-327,82/12/21,8212290150
- 8212300109 Forwards Endorsement 29 to NELIA Policy NF-247 &
 Endorsement 24 to MAELU Policy MF-102
 BUCK, J R Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div
 82/12/21 SALTYMAN, J Assistant Director for State & Licensee
 Relations 3pp 14598 253 24X Fiche 50-327,82/12/21,8212300109
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8212270418 Responds to FOIA request for documents re proposed revision A/or update to reactor safety study referred to in NUREO-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists Spo 16549 233 24X [iche 50-000, 82/11/26, 8212270418
- --B212270466 Discusses feed & bleed DHR for facilities Using PORVs & high pressure injection pumps, decay heat could be removed w/o relying on secondary sys YOUNG, G G. ABDOTT, E C. ACRS -- Advisory Committee on Reactor Safeguards 80/02/14 CARBON, H & ACRS -- Advisory Committee on Reactor Safeguards 80p 16547 266 24X Fiche 50-000.82/11/26, 801270448
- P Operating license stage documents & correspondence
- 8212060061 Forwards response to 821119 verbal request for addl info re equipment survivability Info suppls 821101 response re hydrogen combustion & control for ice condenser plents MILLS.L M Tennessee Valley Authority 82/11/29 ADENSAM.E Licensing Branch 4 2pp 16314-012 24X Fiche 50-327,82/11/29,6212060061
- 8212060023 Informs that util will upgrade emergency operating instructions (EOIs) as required by NUREG-0737. Item I C 1 EOIs will follow generic guidelines developed by Westinghouse owners group MiLLS.L.M Tennessee Valley Authority 82/11/30 ADENSAM.E Licensing Branch 4 2pp 1e313 327 24X Fiche 50-327.82/11/30. 8212060023
- 8212060076 Forwards completed questionnaire in response to Generic & tr B2-22 re steam generator tube integrity Info verbally provided to C Stable in 821130 telcon MILLS.L.M. Tennessee Valley Authority B2/11/30 ADENSAM.E Licensing Branch 4 2pp 16316-104 24X Fiche 50-327,82/11/30, B212060076
- 8212070176 Forwards responses to NRC verbal questions on util 82091/ proposed Fech Spec change re degraded voltage relaying MILLS,L M Tonnesses Valley Authority 82/12/01 ADENSAM.E Licensing Branch 4 11pp 16334 314 24X Fiche 50-327.82/12/01. 8212070176
- B2:12080373 Requests relief from ASME Section XI requirement to hydrostatically pressure test replacement piping of sesential raw cooling water sys Justification for deferral & one oversize drawing and! Aperture card is available in PDR MILLS.L M Tennessee Valley Authority 82/12/03 ADENSAM.E Licensing Branch 4 3pp 16352 066 24X Fiche 50-327,82/12/03,8212080373
- 83/08190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re sub, requirements Comments requested within 30 days of ltr Svc list encl ETSENNUT, D 0 Division of Licensing 82/12/07 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09, 82/8190263

- 8212150010 Forwards add1 info re equipment survivability per 821209 telcon request, revising 821129 submittal Core exit thermotouples located within pressure vessel & not exposed to hydrogen burning KAMMER. D.S. Tennessee Valley Authority 82/12/09 ADENSAM, E. Licensing Branch 4. 2pp. 16421 176 24X Fiche 50-327, 82/12/09, 8212150010
- GP: 12140103 Generic Ltr 92-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EISENHUT.D G Division of Licensing 82/12/10 Yankee Atomic Eisectric Co 27pp 16690 035 24X Fiche 50-000.82/12/10, 82/12/40103
- 8:12:70236 Forwards add1 info re proposed change in instrument surveillance requirement test frequency of Tables 4 3-1 & 4 3-2 & thermal/hydraulic design parameters for Unit 1 isload safety evaluation MILLS.L K Tennessee Valley Authority 82/12/13 ADENSAM.E Licensing Branch 4 6pp 16459 337 24X Fiche 50-327.82/12/13.82/12/130236
- 82/12/370239 Requests proposed Tech Spec change for containment ventilation sys not be considered in review of 820917 reload safety evaluation HILLS, L K Tennessee Valley Authority 82/12/13 ADENSAM, E Licensing Branch 4 [p 16439 335 24X Fiche 50-327, 82/12/13, 8212170239
- O:12270356 Notifies that util agrees to comply w/igniter operational temp limit of 1,700 F for permanent hydrogen mitigation sys, per 821223 telcon Temp should be reconsidered upon completion of addl spray tests
 HILLS, L M Tennessee Valley Authority 82/12/23 ADENSAM.E
 Licensing Branch 4 ip 16586 223 24% Fiche 50-327,82/12/23,825229035A
- BD12200351 Application for amend to Licenses DPR-77 & DPR-79, consisting of proposed changes to Tech Spec 4 B 1 1 2 d 11 re surveillance requirement for ac sources for electrical power rys MILLS.L M Tennessee Valley Authority 82/12/23 ADENSAM.E Licensing Branch 4 2pp 16574 260 24X Fiche 50-327,82/12/23,82/12/200351
- --B212300355 Proposed changes to Tech Spec 4 8 1 1 2 d 11 re surveillance requirement for ac sources for electrical power sys * Tennessee Valley Authority B2/12/23 4pp 16594 262 24X F[che 50-327, 82/12/23, 82;230035]
- SE12300357 Application to amend Licenses DPR-77 & DPR-77, changing surveillance requirements for emergency gas treatment sys cleanup subsystems MILLS-L II Tennessee Valley Authority 82/12/23 ADENSAM.E Licensing Branch 4 2pp 16594 294 24X Fishe 50-327,82/12/23, pp. 1230057
- U212300359 Proposed Tech Specs for Licenses DPR-77 & DPR-79 resurveillance requirements for emergency gas treatment syscleanup subsystems Justification to support changes encl * Tennessee Valley Authority 82/12/23 4pp 16594 286 24X Fiche 50~327,82/12/23-8212300357
- G:12300293 Forwards 16 proprietary figures referenced in OL amend request for vol reduction sys Figures withheld (ref IOCFR2 790) Affidavit encl MILLS:C M Tennessee Valley Authority 82/12/27 DENTON:H R Office of Nuclear Reactor Regulation, Director 9pp 16595 119 24% Fiche 50-327,82/12/27,8212300293
- Q Inspection reports, IE Bulletins & correspondence
- B:08190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel.Recirculation Sys Piping at BMR Plants " Syc list encl
 DEYOUNG.R C Director's Office, Office of Inspection and
 Enforcement B2/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000, B2/10/28, 8208190240
- 8212090486 Forwards IE Insp Repts 50-327/82-23 & 50-328/82-23 on B21005-08 & 18-22 No noncompliance noted VERRELL1.D M Division of Project & Resident Programs 82/11/02 PARRIS.H 0 Tennessee Valley Authority 2pp 16365 356 24X Fiche 50-327.82/11/02.8212090486
- ---8212070493 IE Insp Repts 50-327/82-23 & 50-328/82-23 on 821005-08 & 18-22 No noncompliance noted Major areas inspected refueling activities 5 plant tour THOMAS.M. JAPE,F Division of Engineering & Technical Programs 62/11/01 5pp 16365 358 24X Fiche 50-327, 82/11/02, 8212090486

- 8/08190245 (E Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolominescent Dosimeters " Svc list cnc!

 COBB.t. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- 8P08190251 IE info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8208190254 IR Info Notice 82-44, "Defective & Obsolete Combination Padlocks " Svc list enci BEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 1641: 065 24X Fiche 50-000, 82/11/26, 8208190256
- 87/08190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8212070354 Ack receipt of 821108 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-20 & 50-328/82-20
 VERRELLI.D M Division of Froject & Resident Programs 82/11/30
 PARRIS.H G Tennesses Valley Authority ip 16364 177 24X
 Fiche 50-327, 82/11/30.8212070354
- --8212070365 Responds to NRC 821007 ltr re violations noted in IE Insp Repts 50-327/82-20 & 50-328/82-20 Corrective actions buric acid storage tank ventilation sys temporarily modified to prevent release of radioactive matls to auxiliary bldg MILLS,L N Tennessee Valley Authority 82/11/08 O'REJLLY, J P Region 2: Optics of Director 2pp 16364 180 24X Fishe 50-327.82/11/30,8212090354
- --8212090370 Forwards IE Insp Repts 50-327/82-20 & 50-328/82-20 un 820806-0905 & notice of violation VERRELLI.D M Division of Project & Resident Programs 82/10/07 PARRIS.H Q Tennessee Valley Authority 2pp 16364 182 24X Fiche 50-327, 82/11/30, 8212090354
- --B212090378 Notice of violation from insp on 820806-0905 * Division of Project & Resident Programs B2/10/07 ip 16364 184 24X Fiche 50-327, 02/11/30/8212090354
- --8212090384 IE imap Repts 50-327/82-20 & 50-328/82-20 on 820806-0905 Noncompliance noted failure to post airborne radioactivity area FORD, E.J., BUILER, S.D., QUICK, D.R. Division of Project & Residont Programs 82/10/06 5pp 16364-185 24X Fiche 50-327,82/11/30,8212070354
- B:/OB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24% Fiche 50-000.82/12/03.8208190259
- BP08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Svr list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 P4X Piche 50-000, 82/12/03,8208190261
- 8212170318 Forwards add1 info relice condenser door surveillance inspresults Info supple 820729 & 0812 submittals
 MILLS.L M Tennessee Valley Authority 82/12/13 ADENSAM.E
 Licensing Branch 4 2pp 16454 156 24X Fichs 50-327,82/12/13,821270318
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- BPOB19024B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628, 293 24x Liche 50-000, 82/12/20, 8208170268

- R Periodic operating reports & related correspondence
- 8212290159 Forwards monthly operating rapts for Oct 1982 MASON C C Southern Californía Edison Co 82/11/12 Division of Data Automation & Management Information 1p 16882 203 24X Fiche 50-327,82/11/12,8212290159
- --8212290164 Monthly operating repts for Oct 1982 MASON, C.C., EDDINOS, M., JORDAN, M. Tennessee Valley Authority 82/11/07 15pp 16582 204 24% Fiche 50-327.82/11/12,8212290159
- 8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
 MILLS.L M Tennessee Valley Authority 82/11/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16304 210
 24X Fiche 50-600, 82/11/30, 8212030071
- S212170388 Forwards "Annual Environ Operating Rept.8:0301-820914," per ETS Section 5 4 1 Future reporting periods will be for period beginning an Sept 15 & ending on Sept 14 of following yr MILLS, L H Tennessee Valley Authority 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16453 011 24 fiche 50-327,82/12/07,8212170388
- --8212170390 "Annual Environ Operating Rept.810301-820914 " * Tennesse Valley Authority 82/12/07 178pp 16453 012 24X Fiche 50-327.82/12/07.8212170388
- S Reportable occurrences, LERs & related correspondence
- 8P12020179 Forwards LER 82-125/03L-0 GREEN H J Tennessee Valley Authority 82/11/23 O'REILLY, J P Region 2: Office of Director 1p 16274 107 24X Fiche 50-320 82/11/23 8212020179
- --8212020191 LER 82-129/031-0 on 821029.essential raw cooling water effluent line radiation monitor O-RM-90-134/141 found inoperable due to sample flow loss Caused by normal wear of motor coupling in monitor pump Coupling replaced, ROOZRS, H.R., HARDINO, M.R. Tennessee Valley Authority 82/11/20, Region 2, Office of Director 1p 16274 108 24X Fiche 50-328,82/11/23,8212020179
- 8:12070097 Seventh interim deficiency rept re retrievable info from valve tag numbers initially reported on 801212 Design personnel awaiting approval of design change request to revise drawings Final rept will be issued by 830420 MILLS.L M Tennessee Valley Authority 82/11/30 D'REILLY.J P Region 3. Office of Director ip 16357 312 24X Liche 50-328.82/11/30.8212090099
- 3212070551 Forwards LER 92-132/03L-0 GREEN.H J Tennessee Valley Authorsty 82/12/01 O'REILLY, J P Region 2. Defice of Director 1p 16366 342 24X Fische 50-328,82/12/01.8212070551
- -8212090556 LER 82-132/03L-0 on 821103.one RHR pump declared inoperable due to discharge flow switch failure to actuate Caused by failure of contacts to close due to faulty actuating cam Flow switch repaired & recalibr ROGERS.H R Tennessee Valley Authorsty 82/12/01 Region 2. Office of Director ip 16366 343 24X Fiche 50-328.82/12/01. 8212090551
- '12070174 Forwards LER 82-129/03L-0 GREEN.H J Tennesses Valley Authority 82/12/02 O'REILLY, J P Region 2. Office of Director 1p 16359 219 24X Fiche 50-328, 82/12/02, 8212070174
- 8212070178 LER 82-129/03L-0 on 821103, letdown orifice containment isolation valve 2-FCV-62-73 failed shut Caused by control fuses failing due to shorted coil in relay 8149AX Coil & fuses replaced. Valve tested & returned to svc on 821104 ROMINE.W D . HARDING.M R Tennesse Valley Authority 82/12/02 Region 2. Office of Director ip 16359 220 24X Fiche 50-328,82/12/02,8212090174
- 12140198 Forwards LER 82-133/03L-0 3REEN.H J Tennessee Valley Authority 82/12/08 O'REILLY, J P tegion 2. Office of Director 1p 16409 330 24% Tiche 50-328, 82/12/08, 8212140198
- 3212140207 LER 82-133/03L-0 on 821109, steam generator 4 level channe)
 LT-3-110 declared inoperable due to failing high while in
 Mode 1 Caused by faulty transistor Transistor replaced
 ROCERS.H R . HARDING.M R Tannessee Valley Authority 82/12/08
 Region 2. Office of Director. 1p 16409 331, 24X
 Ficha 50-328,82/12/08,8212140198

- G212210095 Forwards LER 82-136/03L-0 GREEN.H J Tennessee Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director ip 16491 080 24X Fiche 50-328.82/12/14.8212210095
- --82;22:10:100 LER 82-136/03L-0 on 82:115, inleakage found to be 340 cubic ft per minute to annulus during performance of Surveillance Instruction 264 Caused by numerous leaks found through personnel access & squipment doors & other areas CARVER.A M , HARDINO.M R Tennessee Valley Authority 82/12/14 Region 2. Office of Director 2pp 16491 081 24X Fiche 50-328,82/12/14,82:122:10075
- GP122B0133 Forwards LER 82-137/03L-0 GREEN.H J Tennessee Valley Authority B2/12/21 O'REJLLY, J P Hegion 2. Office of Director 1p 16563 183 24X fiche 50-328, 82/12/21, 82122B0133
- --B212280136 LER 82-137/03L-0 on B21122.during Mode 5, four upper head injection switches found out of talerance & one of four valves failed to close Gaused by broken micro switch & instrument drift Valve failure caused by faulty hydraulics LUDNIO.W C , HARDING.M R Tennessee Valley Authority 82/12/21 Region 2. Office of Oirector 2pp 16563 184 24X Fiche 50-328,02/12/21.8212280133
- 7 Hearing transcripts on non-antitrust matters
- Bi12090182 Transcript of 821207 hearing in Washington BC Pp 1-313
 Viewgraphs encl
 ACRS ~ Advisory Committee on Reactor Safeguards 82/12/07
 501pp 14359 248 24X Fiche 50-327, 82/12/07, 8212090182
- G/12220550 Unofficial transcript of Commission 821215 discussion & passible vote in Washington.DC re hydrogen control Pp 1-80 Viewgraphs & SER (NUREO-0011.Suppl 6) encl # Commissioners 82/12/15 225pp 16540 001 24X | teche 50-327.82/12/15.8212220550
- DOCKET 50-329 HIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B?:12010035 Forwards SEW 821107 response to question re jobs undertaken on behalf of util & security holdings Two I imited assignments unrelated to soil activities undertaken No stock holdings indicated BRUNNER. J E Consumers Power Co 62/11/15 PATON, N D Office of the Executive Legal Director 5pp 16260 341 24X Fiche 50-327. B2/11/15. 8212010035
- 82:12030269 Board Notification 92-117 forwards RH Engelken 82:1108 memo to DD Eisenhut re welding-related allogations made by former Bechtel employes W/o encl NDVAK.T H Assistant Director for Licensing 82:11:117 Atomic Safety and Licensing Appeal Panel 3pp 16316-323 24X Fiche 50-000.62:11:17.82:12030269
- GP12020210 Surmary of B21105 meeting w/util.68W.Parsons.Brinckerhoff & Govt Accountability Project in Bethesda.MD re independent assessment of auxiliary bldg underpinning HOOD.D Licensing Branch 4 82/11/22 Licensing Branch 4 1.7pp 16302 324 24X Fiche 50-329,82/11/22.8212020210
- 82/12270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREC-0784, Chapter 10 as R6 II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Divisson of Rules and Records 82/11/26 SHOLLY, S C. Union of Concerned Scientists 3pp 16549 233 24X Jiche 50-000, 82/11/26, 8212270418
- --82:1050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK, TM Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000, 82/11/26, 8212270418
- 82:2060399 Sunmary of 82:1109 meeting w/util in Rethesda, MD re preliminary results of seismic margins analysis for svc water pump structure t borated water storage tank HOOD.D 5 Licensing Branch 4 82/31/29 Licensing Branch 4 40pp 16:325 075 24X Fiche 50-329, 82/11/29, 82:2060389

- G:12280494 Notification of contract execution. Mod 4 to "Foundations & Underpinning Review of Remedial Heasures for Structures on Fill For Midland Plants 1 & 2 " Contractor Gentechnical figineers. Inc 1 ELDS. J A Technical Assistance Contracts Branch FIN 8-8035 H2/11/29 VOLLMER.R H Division of Engineering KANE. J NRC Nu Defailed Affiliation Given 1p 16590 139 24X Fiche 50-329.82/11/29.0218280494
- --U212280501 Mod 4.increasing total Funds deobligated to "Foundations b Underprinting Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2"

 Geotechnical Engineers Inc HAGAN.T F Division of Contracts
 FIN 3-8035 82/11/29 ip 16590 140 24X Fiche 50-329,82/11/29,
- Gf/12030275 Board Notification 82-117 forwards RH Engelken 821108 memo to GO Eisenhut re welding-related allegations made by former Bechtel employee W/o enc! NOVAK, T II Assistant Director for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316 315 24X Fiche 50-000.82/11/30.8212030275
- G:12080392 Proposes changes to independent review program submitted at E21005 meeting & discussed in 821025 & 1108 meetings w/TERA & High Analysis Co (OCK, J & Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Repulation, Director KEPPLER, J G Region 3, Office of Darector 4pp 16352 307 24x Fiche 50-329, 82/12/03,8212080392.
- GP12090056 Forwards Revision 1 to GA Dept Procedure B-3M-1,
 "Qualification & Certification of Insp & Test Personnel"
 Responses to requests for add1 info provided
 COCA,J W Consumers Power Co 82/12/03 DENTON,H R Office of
 Nuclear Reactor Regulation, Director 4pp 16359 062 24X
 1 iche 50-329, B2/12/03, B212090066
- -H212090069 Revision i to OA Dept Procedure B-3M-1, "Qualification & Certification of Insp & Test Personnel" + Consumers Pawer Co 82/10/25 20pp 16359 066 24% Fichs 50-329, 82/12/03,8212090066
- 8:/12160161 Authorizes remedial soils work activities for Dec 1982 Batails requested SHAFER, W D Region 3, Office of Director 82/12/07 MILLER, D D Consumers Fower Co 3pp 16373 355 24X Fiche 50-327, 82/12/07, (212100161
- Gf-12140253 Forwards corrected Page 1 to util 821203 ltr re qualification of insp.exam & testing & audit personnel Correction changes 820201 date in first paragraph to 830201 RICHARDS.L. NRC - No Detailed Affiliation Given 82/12/09 NRC -No Detailed Affiliation Given 1p 16401 356 24X [iche 50-327,82/12/09.8212140253
- -- H212140254 Corrected Page 1 to util 821203 ltm re qualification of image exam % testing % audit personnel

 ** Consumers Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16401 357 24% Fiche 50-329, 82/12/09, 8212140253
- G:12140361 Lists remedial soils work activities authorized for implementation on Piers 12 East & 12 West under turbine bldg.per 821206 request MARNICK.R F Region 3. Office of Director 82/12/09 COOK, J W Consumers Power Co 2pp 16418 279 24X Fiche 50-329,82/12/09,0212140361
- --U212140367 Requests authorization to resume const of remedial soils project on Piers 12 East & 12 West Commitments listed in util 820917 ltr implemented COCK.J N Consumers Power Co 82/12/06 KEPPLER.J o Region 3. Office of Director 4pp 16418 281 24X Fiche 50-329, 82/12/09, 8212140361
- S. 12170144 Advises that Revision 9 of Drawing 7220-C-45 resolves four NRC Items of concern identified in Encl 7 of 820525 ltr No Selamic Category I utils located outside G-listed areas thown on drawing (OGK, J W Consumers Power Co 62/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16450 271 248 liche 50-329, 82/12/10, 6212170144
- G212210309 Forwards Revision 1 to 820430 "Environ Qualification Rept," Vols 1 & 2 Revision reflects changes in regulatory requirements
 COCK-J W Consumers Power Co 82/12/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 16601 343 24X [iche 50-329, 62/12/13, 6212210309]
- \$212300149 Revision 1 to "Environ Qualification Rept." Vols 1 & 2 4 Consumers Pauer Co 82/12/31 1:207pp 16601 347 24X Fiche 50-329.82/12/13.8212210309

- 8/12/20440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 14523 135 24X Fich 50-000 82/12/14,8212220440
- 8712290508 Notification of 830208 meeting w/util & Bechtel in Bethesda, MD to discuss seismic/dynamic equipment qualification status & application of seismic margin study results to program HERNAN, B W Licensing Branch 4 82/12/16 ADENSAME G Licensing Branch 4 4pp 16593 359 24X Fishe 50-329.82/12/16,8212290508
- BP12300185 Summary of 821022 meeting w/util in Bethesda, MD re util proposal to qualify operators on both Units 1 & 2 Viewgraphs encl HERNAN, R W. Licensing Branch 4 82/12/16 Licensing Branch 4 25pp 16612 277 24X Fiche 50-329.82/12/16,8212300185
- GP12270203 Forwards Amend 111 to application for OL.consisting of Revision 14 to responses to requests replant fill COOK.JW Consumers Power Co. 82/12/17 DENTON.HR Office of Nuclear Reactor Regulation. Director 2pp 16578 203 24X Fiche 50-329: 82/12/17.8212290203
- -82:229020B Amend iii to application for OL, consisting of Revision 14 to responses to requests re plant fill COOK, J W Consumers Power Co 82/12/20 407pp 16578 204 24x Fiche 50-329,82/12/17.82:2290203
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 6112070356 Summary of 821122 meeting w/util in Bethosda.MD re acceptability of environ protection plan in FES Minor changes suggested to improve clarity IERNAN.R W Licensing Branch 4 82/12/01 Licensing Branch 4 19pp 16356 227 24X Fiche 50-329.82/12/01.8212070356
- Sti2280207 Outlines characteristics of effluent discharges from Dow Chemical tertiary treatment pend to Tittabawasse River during 801221-821120, per 821215 telcon & FES Assumptions used reasonable (COK, J W Consumers Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16562 107 24X Fiche 50-329, 82/12/21,8212280207
- [NRC Safety Evaluation Report (SER), suppls & correspondence
- BP12100409 Forwards request for add1 info on SER outstanding items revessel head vent & locked rotor accident Response due within 30 days
 ADENBAM, E 0 Licensing Branch 4 B2/12/07 COOK, J W Consumers
 Power Co 5pg 16389 077 24x Fiche 50-529, 82/12/07, 82/2100409
- G?i2170074 Summary of 821014 & 20 meetings w/util & Summit Nuclear Resources in Bethesda, MD re util proposal to establish independent safety engineering group per NUREG-0737, Item I B i 2 & SER IKERNAH, R W Licensing Branch 4 82/12/13 Licensing Branch 4 Spp 14480 355 24% Fiche 50-329,82/12/13,8212170074
- 69/12/20549 Notification of 830111-14 meetings w/util & Bechtel in Ann Anbor.MI & 630113 site visit to conduct audit of environ equipment qualification program, as discussed in Section 3 11 of SER HERNAM & Licensing Branch 4 82/12/16 ADENSAM & Cicensing Heanch 4 9pp 16523 352 24% Fiche 50-329,82/12/16,8212220548
- SP12290475 Summary of S21123 meeting w/util, NUS & Stoner Associates in Sethesda. MD renatural gas pipeline issue, SER Outstanding (Spen Item I IERNAM, R W Licensing Branch 4 S2/12/16 Licensing Branch 4 Spp 16606 040 24X Fiche 50-327, 82/12/16, 8212290475
- BP12280513 Summary of 821222 meeting w/util, Bechtel, B&W & NUS in Uethesda. MD re-resolution of SER open items concerning fire protection
 HERNAN, R W Licensing Branch 4 82/12/22 Licensing Branch 4 17pp 16572 132 24% Fiche 50~327, 82/12/22, 8212280513
- B212280516 "Resolution of NRC Staff Concerns of Midland Fire Protection Program"
 NRC - No Detailed Affiliation Given B2/04/02 34pp 16592 149 24X Fiche 50-329, B2/12/22, B212280513

- F. Security medical, emergency / fire protection plans
- S:12010506 Forwards request for add1 info L guidance on associated circuits re fire protection safe shutdown ADENSAM.E O Licensing Bianch 4 82/11/26 CODK.J N Consumers Power Co 12pp 16270 197 24X Fiche 50-329.82/11/26,0212010506
- 8: 12070300 Documents 821202 telcon re emergency operations facility Facilities for four plants completed Table encl VANDEUALLE.D J Consumers Power Co 82/12/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16343 156 24% (1che 50-000:82/12/03,8212070300
- 8212220304 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility

 KEPPLERIJO Region 3. Office of Director 82/12/16

 Connormealth Edison Co. 3pp. 16503 351 24X Fiche 50-000,82/12/16.

 KEP22020304
- G/1P280225 Advises that util will submit milestone schedule on 830201 to identify when util responses to NRC 821126 request for info re fire protection shutdown associated circuits will be provided COCK.J W. Consumers Power Co. 82/12/17 DENTON.H R. Office of Nuclear Reactor Regulation. Director 2pp 16562 177 24X Liche 50-327,82/12/17.6212280225
- 3212280513 Summary of 821222 neeting w/util, Bechtel, D&H & NUS in Pethesda, MD re resolution of SER open items concerning fire protection HERNAN, R W | Licensing Branch 4 82/12/22 | Licensing Branch 4 17pp | 16592 | 32 | 24% Fische 50-327, 82/12/22, 8212280513
- --0212280516 "Resolution of NRC Staff Concerns of Hidland Fire Protection Program" + MRC - No Detailed Affiliation Given 82/04/02 34pp 16592 149 24% Fiche 50-329, 82/12/22, 8212280513
- & Adjudicatory correspondence
- EP11080148 Forwards Rulemaking RM-50-3, "Licensing & Regulatory Policy & Procedures to Environ Protection.U Fuel Cycle Impacts "
 Certificate of Svc enc! PATOU.N D Hearing Branch 2 82/11/05 BECHHOEFER.C , COMAN, F P , HARBOUR.J Atomic Safety and Licensing Board Panel 6pp 15993 219 24X Fiche 50-329, 82/11/05, 8211080148
- 8:12020343 Interrogatories & request for production of documents on Stampris cost/benefit contention, per ASLB 821029 memorandum & order Related correspondence STAMIRIES B Stampriss B 82/11/26 Office of the Executive Legal Director App 16277 314 24% Fiche 50-327.82/11/26.8212020343
- 8212020345 Interrogatories A request for production of documents on Stamuris cost/benefit contention.per ASLR 821029 memorandum b order Related correspondence STAMIRIS.8 Stamuris B 82/11/25 Consumers Power Co 4pp 16277 310 24x Fiche 50-327.82/11/26.8212020345
- Bri2100075 Interrogatories re nonfuel operation & maint cost considerations Related correspondence STAMIRIG. B Stamiris B 82/12/02 Office of the Executive Lagal Director 2pp 16379 189 24X Fiche 50~327,82/12/02.82(2100075
- BP12060014 Advises that NRC intends to respond voluntarily to N Staminis 821201 interrogatories WRIGHY.N A Hearing Branch 2 82/12/03 BECHHOEFER.C., COWAN.F.P., HARBOUR.J. Atomic Safety and Licensing Board Panel 2pp 16313 334 24% Fiche 50-329,82/12/03,8212060014
- B?12070164 Order denying NRC request to postpone B21206-11 hearings festimony presented at hearings will be subj to re-eramination if any Region 3 investigative findings islevant BECHHOEFER.C. Atomic Safety and Licensing Board Panel B2/12/03 Uffice of the Executive Legal Director ip 16335-315 24X liche 50-329, B2/12/03, B212070164
- 89:12070174 Order extending time until 82:223 for Commission to act to review ALAB-691
 CHILK, 9 J Office of the Secretary of the Commission 82/12/03
 Commissioners ip 16334 330 24X Fiche 50-329,82/12/03, 0212070174
- 9P12140397 Objections to 820920 interrogatories to util on ZACK issues Interrogatory issues subj of independent investigation by Region 3 W/Certificate of Svc Related correspondence STAHL, D.M. Consumers Power Co. STAHL, D.M. Isham, Lincoln & Beale 82/12/10. Sinclair, M. 175p. 16401 288 24% Fiche 59-329, 82/12/10, 8212140387.

- BJ12210314 Forwards nonconformance repts re grinding wheels & G-listing of certain equipment components in diesel generator blidg, per util prior commitments Related correspondence IRUNNER. J E Consumers Power Co 82/12/14 BECHMORFER. C Atomic Safety and Licensing Board Panel 6pp 16497 121 24X (iche 50-329.82/12/14,8212210314
- 8P12220197 Requests info re exemption of facility from 1975 safety rules.compliance w/safety rules & regulations & time interval between accident & automatic closing of containment to seal shut & airtight condition MAREMALL.W H Mapleton Intervenors 82/12/14 Office of Nuclear Reactor Regulation, Director 2pp (6503-333-24X Fiche 80-329, 82/12/14, 8212220197
- S212230350 Notice of appearance in proceeding Certificate of Svc encl BARTH.D E Consumers Power Co 82/12/15 3pp 1651t 128 24X Fiche 50-329.82/12/15, 821230350
- BP12270005 Advises that NRC will voluntarily respond to B Stamiris
 B21202 interrogatories after requests reviewed No
 objections waived
 WRIOHI.N A Hearing Branch 2 B2/12/22 BECHHOEFER.C. COMAN.F.P.,
 HARBOUR.J Atomic Safety and Licensing Board Panel 2pp
 16538 298 24X Fiche 50-327,82/12/22.8212270005
- 8212300026 Grants extension until 830128 for Commission to act to leview ALAB-691 CHICK'S J Office of the Secretary of the Commission 82/12/23 Commissioners Ip 16598 311 24X Fiche 50-327.62/12/23,
- D Advisory Committee on Reactor Safeguards reports & correspondence
- B212010512 Summary of 264th ACRS meeting on B20403-05 in Washington, DC re Midland DL review reactor vessel integrity, seismic events in emergency planning & control room habitability e ACRS Advisory Committee on Reactor Safeguards B2/11/26 ACRS Advisory Committee on Reactor Safeguards 255pp 16293 236 24X Fiche 50-329,62/11/26,6212010512
- Q Inspection reports: IE Bulletins & correspondence
- Bf'0B190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants "Svc list encl
 BEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fishe 50-000.82/10/28, 8208190240
- 8/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Hodel BOI & Model 802 Thermoluminescent Dosimeters " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fichs 50-000.82/11/05.8208190245
- 8./08190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X fichs.50-000.82/11/18.8208190251
- 870819025& IE Info Notice 82-4&, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 62:08190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Mati " Svr list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82:711/30 Consolidated Edison Co of New York, Inc 356pp 16:387 028 24X Fishe 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24 Fiche.50-000.82/12/03,8208190261

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190248 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp. 16628 273 243 Fiche 50-000, 82/12/20, 8208190268

A Periodic operating reports & related correspondence

- 8P12070017 Forwards nonconformance ropts for Qct 1982.per Memorandum & Order ALAB-104 & Amend I to CPPR-81 & CPPR-82 CODX.J W Consumers Power Co 82/11/24 DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 1,240pp 14330 001 24% Fiche 50-329.82/11/24.8212070017
- S Reportable occurrences, LERs & related correspondence
- 82:12020313 Third interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys Initially reported on 820625 Corrective actions to be implemented by Bechtel listed Next rept will be submitted by 830214 COOK, J W Consumers Power Co. 82/11/22 KEPPLER, J G Region 3, Office of Director 9pp 16279 203 24X Fiche 50-329, 82/11/22,
- 87:2060112 PNO-III-82-130 on B21130,all safety-related welding on HVA(
 stopped after licenses determined QA program for welder
 certification & procedure qualification inadequate Photon
 Testing removed from list of approved vendors
 GARDNER, R, SHAFER, W, WARNICK, R Region 3. Office of Director
 B2/12/01 | p 16316 102 24x Fiche 50-329,82/12/01,8212060112
- B212100237 Final deficiency rept re cable substitutions on four Class IE cables not sized per design requirements Initially reported on 821028 Verification of correct cable type included as part of cable routing reinsp plan COUK, J W Consumers Power Co 82/12/01 KEPPLER, J Q Region 3, Office of Director App 16376 105 24X Fiche 50-329,82/12/01,8212100237
- BP12080416 PND-III-82-131 on 821202.util notified Region 3 of substantial reductions in safety-related work Total of 4,000 personnel remain Engineering & const teams will be responsible for completion of one or more safety sys
 BHAFER.W. HARNICK.R F. DAVIS, A B Region 3. Office of Director 62/12/03 3pp 16352 265 24X Fiche 50-329,82/12/03.8212080416
- 0212:00273 Interim deficiency rept re-potentially insufficient design of steel embedments in concrete using shear lugs located in tension zones Initially reported on 82:105 Review criterion being developed Neit rept will be submitted by 830301 CODEN, JW Consumers Power Co 82:12:03 KEPPLER, J G Region 3, 01:fice of Director 6pp 16376 139 24X Fiche 50-329,82/12/03,8212100273
- 8212280046 Board Notification 82-126 forwards Warnick 621201 & 03 memon re adequacy of welder qualifications & weld procedures at sites & reduction of safety-related work in progress imposed by util NOVAK, T.M. Assistant Director for Licensing 62/12/07 Atomic Safety and Licensing Board Panel 5pp 16593 011 24X Fiche 50-329, 82/12/07. 8212280046
- --8212280050 Recommends ASLB be notified of encl PNO re adequacy of welder qualifications & weld procedures at site WARNICK, R F Region 3. Office of Director 82/12/01 EISENHUL, D Division of Licensing 1p 16593 013 24X Fiche 50-327, 82/12/07,8212280046
- --B212280054 Forwards PNO re substantial reduction in amount of safety-related work at site for board notification WARRICK,R F Region 3, Office of Director B2/12/03 EISENHUT, D 9 Division of Licensing 1p 16593 017 24X Fiche 50-329,82/12/07.8212280046
- BP12210154 Interim deficiency rept re possibility of fraif1 ice formation in syc water intake structure Initially reported on B2112 Possible corrective actions under evaluation COCK, J W. Consumers Power Co. 82/12/12 KEPPLER, J Ø Region 3, Office of Director Spp. 16485-151 24X Fiche 50-329.82/12/12, 8212210156

- 6/12210314 Forwards nonconformance repts re granding wheels & G-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence URUNNER, J. E. Consumers Power Co. 82/12/14 BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 6pp. 16497-121 24x Liche 50-329, 92/12/14, 9212210314
- 8212280320 Interim deficiency rept rellack of overpressurization protection on piping Initially reported on 821116 Investigation & review continuing Next rept will be submitted by 830310 COOK.J W Consumers Power Co 82/12/14 KEPPLER.J G Region 3 Office of Director 7pp 16561 068 24X Fiche 50-329.82/12/14.8212280320
- B/12270126 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations SAR Change Notice 2648 incorporated in FSAR Revision 41 Next rept will be sent by 830318 CCOK.J N Consumers Power Co 82/12/17 KEPPLER.J G Region J. Office of Director 5pp 16538 152 24X Fiche 50-329.82/12/17. 821277019A

7 Hearing transcripts on non-antitrust matters

- 82:12090188 Forwards RB Peck revised testimony Centificate of Svc encl LAUER,R J Isham, Lincoln & Beate LAUER,R J Consumers Power Co 827/12/06 Atomic Safety and Licensing Board Panel 3pp 16362 001 24% Fiche 50-329,827(2706.8212090188
- --B212090194 Revised testimony of RB Peck Surcharge program at diesel generator bldg eliminated potential future settlement problems due to compressibility of plant fill math & lack of homogeneity PECK.R B Consumers Pawer Co 82/12/06 275pp 16362 004 24) Fiche 50-329,82/12/06.8212090188
- 8212100030 Transcript of 821206 hearing in Midland MI Pp 10,149-10,345 bupporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/06 121pp 16377 277 24X Fishe 50-329,82/12/06.8212100030
- 8212140044 Transcript of 821207 hearing in Midland, MI Pp 10, 346-10, 597 * Atomic Safety and Licensing Board Panel 82/12/07 256pp 16409 005 24X Fiche 50-329, 82/12/07, 8212140044
- Bi1210004B Forwards corrected Pages 8548-A.8628.8629 & 9194-B to transcripts of 821115 & 18 evidentiary hearings in Midland. HI MURPHY, B M. Alderson Reporting 82/12/08 MCMAMARA, A. NRC No Detailed Affiliation Given ip 16379 072 24X [1che 50-329.82/12/08.821210004B
- 8212100056 Corrected Pages 8548-A.8628 & 8629 to transcript of 821115 evidentiary hearing in Midland/HI * Atomic Bafety and Licensing Board Fanel 82/11/15 3pp 14379 073 24X Fiche 50-329, 82/12/08/8212100048
- U212100077 Corrected Page 9194-B to transcript of 921118 evidentiary hearing in Midland.MI * Atomic Safety and Licensing Board Panel 92/11/18 ip 16379 076 24X Fiche 50-329.82/12/08.8212100048
- B212140106 Transcript of 821208 hearing in Midland, MI Pp 10, 598-10, 80's Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/08 290pp 16407 236 24X Fiche 50-329, 82/12/08, 8212140106
- 0212150002 Transcript of 821209 hearing in Midland, MI Pp 10, 804-11, 007 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/09 323pp 16421 331 24% Fiche 50-329, 82/12/09, 8212150002
- BP12150006 Transcript of B21210 evidentiary hearing in Midland, MI Pp 11,008-11,228 Supporting documentation encl * Atomic Safety and Licensing Board Panel B2/12/10 352pp 16425 247 24% Fiche 50-329,82/12/10,8212150006

U Congressional/Executive Correspondence

GP12100042 Responds to 821103 ltr expressing concern re implementation of GA programs Special measures taken to munitor activities Gails settlement problem focused NRC attention Problems must be resolved before GL issued DIRCKS, WJ Office of the Executive Director for Operations 82/12/07 LEVIN.C Senate lipp 16399 346 24X Fiche 50-329, 82/12/07, 8212100042

- -- 8212100045 Expresses concern re implementation of QA programs Info re discussions w/J Reppler requested LEVIN.C Senate 82/11/03 DENYON.H Office of Nuclear Reactor Regulation, Director 3pp 18399-357 24% Fiche 80-329,82/12/07. 9212100042
- 2 TIMU THAIR DWALDIN OCC-08 TENDOD
- A Application/construction stage documents & correspondence
- BP12010035 Forwards SAH 821109 response to question re jobs undertaken on behalf of util & security holdings Two limited assignments unrelated to soil activities undertaken No stock holdings indicated BRUNNER, J E Consumers Power Co 02/11/15 PATON, W D Office of the Executive Logal Director 5pp 16260 341 24% Fiche 30-329, 82/11/15,8212010035
- 8212030269 Board Notification 82-117 forwards RM Engelken 821108 memo to DB Eisenhut re welding-related allegations made by former Bechtel employee W/o encl NDVAK.T M Assistant Director for Licensing 82/11/17 Atomic Safety and Licensing Appeal Panel 3pp 16316 323 24X Fiche 50-000,82/11/17.8212030269
- 8212020210 Summary of 821105 meeting w/util, S&W. Parsons, Brinckerhoff & Govt Accountability Project in Bethesda, MD re independent assessment of auxiliary bidg underpinning HOOD, D Licensing Branch 4 82/11/22 Licensing Branch 4 12pp 16302 324 24x Fiche 50-329, 82/11/22, 8212020210
- 6212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREQ-0784. Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON. J M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3 pp 16549 233 24X highes 50-000, 82/11/26,8212270418
- ~B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK,T M Assistant Director for Licensing 82/09/24 Division of Licensing Ip 16549 278 34X Fiche 50-000.82/11/26, 8212270418
- 8212060389 Summary of B21109 meeting w/util in Bethesda, MD re preliminary results of seismic margins analysis for svc water pump structure & borated water storage tank MOOD, D S Licensing Branch 4 82/11/29 Litensing Branc 40pp 16325 075 24% Fiche 50~329.82/11/29,8212060389 Licensine Beauch 4
- 8212280474 Notification of contract execution.Mod 4 to "Foundations & Underpinning Review of Ramedial Measures for Structures on Fill for Midland Plants 1 & 2 " Contractor Geotechnical Fill for Midland Plants 1 & 2 " Contractor Gootechnical Engineers, Inc FIELDS, J A Technical Assistance Contracts Branch FIN 8 82/11/29 VOLLMER/R H Division of Engineering MANE, J Detailed Affiliation Given 1p 16590 (39 24% Fiche 50-329, 82/11/29, 8212280494 FIN #-8035
- --8212280501 Mod 4 increasing total funds deabligated to "Foundations & Underpinning Review or Remedial Measures for Structures on Fill for Midland Plants 1 & 2 " HAGAN, TF Division of Contract Ocotechnical Engineers.Inc HAGAN.TF Division of Contracts N 8-8035 82/11/29 1p 16590 140 24% Fiche 50-329.82/11/29.
- 82:2030275 Board Motification 82-117 forwards RH Engelken 82:108 memo 2:12030273 Board Notification B2-117 forwards RH Engelken B211 to DG Eisenhut re welding-related allegations made by former Rechtel employee W/o entl NOVAK.T H Assistant Director for Licensing 82/11/30 Bafety and Licensing Board Panel 5pp 16316.315 24X Fiche 30-000.82/11/30.8212030275
- 8212080392 Proposes changes to independent review program submitted at B21005 meeting & discussed in 821028 & 1108 meetings w/TERA & Mgt Analysis Co COCK, J Consumers Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director KEPPLER, J G Region 3, Office of Director 4pp 16352 307 24X Fiche 50-329,82/12/03,8212080392
- G212090066 Forwards Revision 1 to GA Dept Procedure B-3M-1,
 "Qualification & Certification of Insp & Test Personnel"
 Responses to requests for addl info provided
 COOK.J W Consumers Power Co 82/12/03 DENTON, H R Office of
 Nuclear Reactor Regulation. Director 4pp 16359 062 R4X
 Fichs 50-308.82112/03.821200036 Fiche 50-329, 82/12/03, 8212090066
- --8212070069 Revision 1 to QA Dept Procedure 8-3M-1, "Qualification & Certification of Insp & Test Personnel" * Consumers Power Co 82/10/25, 20pp 16359 066 24% Fiche 50-329,82/12/03,8212090066

- 8212100161 Authorizes remedial soils work activities for Dec 1982 Details requested SMAFER, N D Region 3, Office of Director 82/12/07 MILLER, D D Consumers Power Co 3pp 16373 355 24X Fiche 50-329, 82/12/07, 8212100161
- 8/12140253 Forwards corrected Page 1 to util 821203 ltr re qualification of insprexam 5 testing & audit personnel Correction changes 820201 date in first paragraph to 830201 RICHARDS, L NRC No Detailed Affiliation Given 62/12/09 No Detailed Affiliation Given 1p 16401 336 24X Fiche 50-329, 82/12/09, 8212140253 MOC -
- 8212140256 Corrected Page 1 to util 821203 ltr re qualification of insp. exam & testing & audit personnel
 + Consumers Power Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16401 357 244
 Fiche 50-329, 82/12/09, 8212140253
- 8212140361 Lists remadial soils work activities authorized for implementation on Piers 12 East & 12 Hest under turbine bidg, per 821204 request WARNICK.R F Region 3, Office of Director 82/12/09 CODK, J W Consumers Power Co 2pp 16418 279 24X Fiche 50-329,82/12/09,0212140341
- --8212140347 Requests authorization to resume const of remedial soils project on Piers 12 East & 12 West Commitments listed in util 820917 Its implemented COGM-J W Consumers Power Co 82/12/06 KEPPLER. J G Region 3. Office of Director 4pp 16418 281 24X Fiche 50-329,82/12/09,82112/094 62121403A1
- 8P12170144 Advises that Revision 9 of Drawing 7220-C-45 resolves four NRC items of concern identified in Encl 7 of 820525 ltr No Beismac Category I utils located outside G-listed areas shown on drawing COOK, J W Consumers Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 14450 271 24X fiche 50-329, 82/12/10, 8212170144
- B212210307 Forwards Revision 1 to 820430 "Environ Qualification Rept," Please SUP-329, 82/12/13,8212210309 Penviron Qualification Rep Vols I & Revision reflects changes in regulatory requirements COOK, J & Consumers Power Co. 82/12/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director App. 16601 343 24X Fiche 50-329, 82/12/13,8212210309
- 8212300147 Revision 1 to "Environ Qualification Rept," Vols 1 & 2 * Consumers Power Co 82/12/31 1,207pp 16601 347 24X Fiche 50-327,82/12/13,8212210307
- 82:12220440 Board Notifications 82-125 & 82-125A forwards into re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on matural circulation NOVAK.TM Assistant Director for Licensing 82/12/14 Safety and Licensing Board Panel 5pp 16523 135 24x Fiche 50-000, 82/12/14,8212220440 82/12/14
- 8;12290508 Notification of 830208 meeting w/util & Bechtel in Bethesda, MD to discuss seismic/dynamic equipment qualification status & application of seismic margin study results to program HERRANAR W Licensing Branch 4 82/12/16 ADENSAM, E © Licensing Branch 4 4pp 16593 359 24% Fiche 50-329,82/12/16,8212270506
- GR12300185 Summary of 821022 meeting w/util in Bethesda, MD re util proposal to qualify operators on both Units 1 & 2 Viewgraphs encl HERNAN, R W R W Licensing Branch 4 82/12/16 Licensing Branch 4 16612 277 24% Fiche 50-329.82/12/16.8212300185
- 8212290203 Forwards Amend 111 to application for OL consisting of Revision 14 to responses to requests replant fill CODK, J.W. Consumers Power Co. 82/12/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16578 203 24X Fiche 50-329, 82/12/17, 8212290203
- ~-8212290208 Amend 111 to application for OL. consisting of Revision 14 to responses to requests re plant fill CODK.J W Consumers Pewer Co. 82/12/20 407pp 16578 204 24X Fiche 50-329, 82/12/17, 8212290203
- D NRC Draft/Final Environmental Statements, supple & correspondence
- B212070356 Summary of 821122 meeting w/util in Bethesda, MD re acceptability of environ protection plan in FES Minor changes suggested to improve clarity HERNAN, R W Licensing Branch 4 82/12/01 Licensing Br 19pp 16356, 227 24X Fiche 50~329, 82/12/01, 8212070356 Licensing Branch 4

1

- 821228020/ Gutlines characteristics of effluent discharges from Dow Chemical tertiary treatment pond to Tittabawassee River during 801221-821120, per 821215 telcon & FES Assumptions used reasonable CODK. J W Consumers Power Co 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16562 107 24X Nuclear Reactor Regulation, Director Fighe 50-329, 82/12/21,8212280207
- E MRC Safety Evaluation Report (SER), suppls & correspondence
- B012100409 Forwards request for add) info on SER outstanding items re vessel head vent & locked rotor accident Response due within JO days ADENBAM, E 0 L Licensing Branch 4 82/12/07 COOK, J W Consumer p 16389 077 24X Fiche 50-329,82/12/07,8212100409 Power Co
- G212170074 Summary of 821014 & 20 meetings w/util & Summit Nuclear Resources in Bethesda.MO re util proposal to establish independent safety engineering group per NUREG-0737.Item 1 2 % SER
 - i 2 % 56K AN.R W Litensing Branch 4 82/12/13 Licensi 16480 355 24X Fiche 30-329,82/12/13,8212170074 Licensing Branch 4
- G:12220548 Notification of 830111-14 meetings w/util & Bechtel in Ann Arbor.MI & 830113 sits visit to conduct audit of environ equipment qualification program, as discussed in Section 3 11
 - of SER MERNAN.R W Licensing Branch 4 82/12/16 ADENBAM.E G Licensing Branch 4 5pp 16523 352 24% Fiche 50-327.82/12/16.8212220548
- G212290475 Summary of 821123 meeting w/util, NUS & Stoner Associates in Bethesda, MD re natural gas pipeline issue, SER Outstanding Licensing Branch 4
- Bethesses, rn. 1200-1-200 Open I tem (HERNAN, R W Licensing Branch 4 82/12/16 Licensing Annual 1606 040 24X Fiche 50-329,82/12/16,8212290475
- GP12280513 Summary of 821222 meeting w/util.Bechtel.B&W & NUS in Bethesda.MD re resolution of SER open items concerning fire protection I.R.W. Licensing Branch 4 82/12/22 Licensing Branch 4 16592 132 24X Fiche 50-329,82/12/22,8212280513
- [Security, medical, emergency & fire protection plans
- G:12010506 Forwards request for addl info & guidance on associated circuits re fire protection safe shutdown
 ADENSAM.E O Licensing Branch 4 82/11/26 COOK.J W Consumers
 Power Co 12pp 16270 197 24X Fiche 50-329.82/11/26.8212010506
- 8212070390 Documents 821202 telcon re emergency operations facility lacilities for four plants completed Table encl VANDEMALLED J Consumers Pawer Co 82/12/03 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16343 156 24X Fische 50-000, 82/12/03, 8212070300
- 5712220306 Discusses layout of communications equipment required in rickerson bisturges layout of communications equipment required in control room, onsite technical support ctr & near-site cmergency operations facility KEPPLER, J G Region 3, Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000,82/12/16,8212220306
- GP12280R25 Advises that util will submit milestone schedule on 830201 to identify when util responses to NRC 821126 request for info re fire protection shutdown associated circuits will be provided COCK.J.W Consumers Power Co 82/12/17 DENTON.HR Office of Nuclear Reactor Regulation, Director 2pp 16862 177 24X Fiche 30-329, 82/12/17,8212280225
- GP18280513 Summary of 821222 meeting w/util, Bechtel, B&N & NUB in Nethesda, MD re resolution of SER open items concerning fire protection HERNAN, R W Licensing Branch 4 82/12/22 Licensing Branch 17pp 16592 132 24X Fichs 50-329, 82/12/22, 8212280513 Licensing Branch 4
- --8212280514 "Resolution of NRC Staff Concerns of Midland Fire Protection Program" * NRC No Detailed Affiliation Given 82/04/02 34pp 16592 149 24X Fiche 80-329, 82/12/22, 8212280513
- & Adjudicatory correspondence
- BP11080148 Forwards Rulemaking RM-50-3, "Licenting & Regulatory Policy & Procedures fo Environ Protection.U Fuel Cycle Impacts "
 Certificate of Svc encl
 PATON.W D Hearing Branch 2 82/11/05 BECHHUEFER,C, COWAN,F,P,
 HARBOUR,J Atomic 8afety and Licenting Board Panel 6pp
 13993 219 24X Fiche 50-329.82/11/05.8211080148,

- 8212020343 Interrogatories & request for production of documents on Stamiris cost/benefit contention.per ASLB 821029 memorandum & order Related correspondence STAMIRS. B Stamiris. B 82/11/26 Office of the Executive Lega) Director 4pp 16277 314 24% Fiche 50-329,82/11/26,8212020343
- 8212020345 Interrogatories & request for production of documents on Stamiris cost/benefit contention.per ASLB 821027 memorandum & order Related correspondence STAMIRIS.B Stamiris. B 82/11/26 Consumers Power Co 4pp 16277 310 24X Fiche 50-329,82/11/26,8212020345
- B212100095 interrogatories re nonfuel operation & maint cost considerations Related correspondence STAMIRIS, B Stamiris, B 82/12/02 Office of the Executive Legal Director 2pp 16379 189 24X Fiche 50-329,82/12/02,8212100095
- B212060014 Advises that NRC intends to respond voluntarily to

 R Stamiris B21201 interrogatories
 WRIGHT.N A Hearing Branch 2 S2/12/03 BECHHOEFER.C , COWAN.F P ,
 HARBOUR.J Atomic Safety and Licensing Board Panel. 2pp
 16313 334 24X Fiche 50-329,82/12/03.8212060014
- 8212070164 Order denying NRC request to postpone 821206-11 hearings Testimony presented at hearings will be subj to re-examination if any Region 3 investigative findings ...a Panel 82/12/03 16335 315 24V ı elevant relevant
 BECHHOREER.C Atomic Bafety and Licensing Board Panel
 Office of the Executive Legal Director ip 16335 315
 Fiche 50-329, 82/12/03, 8212070164
- BP12070174 Order extending time until 821223 for Commission to act to review ALAB-691 CHILK, 8 J Defice of the Secretary of the Commission 82/12/03 Commissioners ip 16334 330 24X Fiche 50-329,82/12/03,4212070174
- B2121403B7 Objections to 820720 interrogatories to util on ZACK issues Interrogatory issues subj of independent investigation by Region 3 W/Certificate of Svc Related correspondence STAHL:D M Consumers Power Co STAHL:D M Isham, Lincoln & Beale 827(27/10 Sincleir, M 17gp 16401 288 24X 6:10he 50-329, 82/12/10, 82121403B7
- B212210314 Forwards nonconformance repts re grinding wheels & G-listing of certain equipment components in diesel generator bldg, per util prior commitments Related correspondence RRUNNER.J E Consumers Power Co 62/12/14 BECHHOEFER.C Atomic Gafety and Licensing Board Panel 6pp 16497 121 24X Fiche 50-329, 82/12/14, 8212210314
- GP12220197 Requests info re exemption of facility from 1975 safety rules.compliance w/safety rules & regulations & time interval between accident & automatic closing of containment to seal shut & airtight condition MARSHALL,W H Kapleton Intervenors 82/12/14 Dffice of Nuclear Reactor Regulation. Director 2pp 16503 333 24x Fiche 50-329, 82/12/14,8212220197
- GC/12230350 Notice of appearance in proceeding Certificate of Svc encl BARTH, D E Consumers Power Co 82/12/15 3pp 16511 128 24X Fiche 50-329, 82/12/15, 8212230350
- B212270005 Advises that NRC will unluntarily respond to B Stemiris B21202 interrogatories after requests reviewed No Discritions waived WRIGHT: N A Hearing Branch 2 82/12/22 BECHHOEFER, C. COMAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 16538 298 24% Fiche 50-329, 82/12/22, 8212270005
- B212300026 Grants extension until 830128 for Commission to act to seview ALAB-691 review ALAUTOVI CHILK, S J Office of the Secretary of the Commission BZ/ Commissioners Ip 16598 311 24X Fiche 50-327,82/12/23, 920005812B
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B212010512 Summary of 264th ACRS meeting on 820603-05 in Washington, DC re Midland OL review, reactor vessel integrity, seismic events in emergency planning & control room habitability # ACRS - Advisory Committee on Reactor Bafeguards B2/11/26 ACRS - Advisory Committee on Reactor Safeguards 255pp 1629 P4X Fiche 30-329.82/11/26.8212010512 16293 236

O Inspection repurts. IE Bulletins & correspondence

- 8208;90240 IE Bulletin 82-03. Revision 1, "Stress Cracting in Thick-Hall. Large-Diameter. Stainless Steel. Recurculation Sys Piping at BUR Plants "Svc list encl
 DEYQUNG.R C Director's Office, Office of Inspection and
 Enforcement 82-10/28 Consolidated Edison Co of New York. Inc
 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 820B190245 IE Info Natice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolominescent Dosimeters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fishe 50-600, 82/11/05, 820B190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidates Edison Ca of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiotts " Svt list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24x Fiche 50-000.82/11/26.8208190256
- 82.08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati " Svc list enc! COSB.L I Division of Foel Facilities, Materials & Eafeguards 62/11/30 consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Frimary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNGE C Director's Office Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B208190261 IE Info Notice 82-AB, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDANE L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pg 16462 064 24) Fiche 50-000, 82/12/03, 8208190261
- 620B190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl
 DEYOUND.R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Conspillated Edjaron Co of New York, Inc
 127pp 16428 191 24X Fiche 50-000.82/12/16,820B190267
- B208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JBRDAN.E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24x Fiche 50-000.82/12/20.8208190268
- R Persodic operating reports & related correspondence
- GRI2070017 Forwards nonconformance repts for Dct 1982,per Hemorandum & Order ALAB-108 & Amend 1 to CPPR-81 & CPPR-82 COOK. J W Consumers Power Co 92/11/24 DEYDUNG.R C Director's Office, Office, of Inspection and Enforcement 1.260pp 16330 001 24X Fiche 50-329,82/11/24.82;2070017
- S Reportable occurrences. LERs & related correspondence
- 8012020313 Third interim deficiency rept re G-related equipment cooled by non-Q MVAC sys Initially reported on 820625 Corrective actions to be implemented by Bechtel listed Next rept will be submitted by 830214 COOK-J N Consumers Power Co 82/11/22 KEPPLER. J O Region 3. Office of Director 9pp 16279 203 24x Fiche 50-329, 82/11/22, 8212020313
- BP12060112 PNO-III-82-130 on 821130,all safety-related welding on HVAC, stopped after licenses determined OA program for welder certification & procedure qualification inadequate Photon Testing removed from 11st of approved vendors GARDMER.R . SMAFER.W . WARNICK, R . Region 3. Office of Director 82/12/01 ip 16316-102 24% Fiche 50-329,82/12/01.8212060112
- B2:2100237 Final deficiency rept re-cable substitutions on four Class IE cables not sized per design requirements Initially reported on B2:028 Verification of correct cable type included as part of cable routing reinsplain GOOK, J. H. Consumers Power Co. B2:12:01 KEPPLER, J. O. Region 3, Office of Director Opp. 16376 105 24X Fichs 50-329, 82:12:001

- 8212100273 Interim deficiency rept re-potentially insufficient design of steel embedments in concrete using shear lugs located in tension iones Initially reported on 821105 Review criterion being developed Next rept will be submitted by 830301 COOK.J W Consumers Power Co. 82/12/03 KEPPLER.J G Region 3, Office of Director. App. 16376-139 24X Fiche 50-329.82/18/03, 0212100273
- 8212280046 Board Notification 82-126 forwards Harnick 821201 t 03 memos re adequacy of welder qualifications t weld procedures at sites to reduction of safety-related work in progress imposed by vii

 NOVAK,T M. Assistant Director for Licensing 82/12/07. Atomic Safety and Licensing Board Panel 5pp 16573 011 24X

 Fishe 50-329,82/12/07,8212280046
- --8212280050 Recommends ASLB be notified of encl PNO re adequacy of welder qualifications & weld procedures at site MARNICK, F Region 3. Office of Director 82/12/01 EIBENIUT. Division of Licensing ip 16593 015 24% Fiche 90-329, 82/12/07,8212280046
- --8212280054 Forwards PNO re substantial reduction in amount of safety-related work at site for board notification MARNICK.R F Region 3, Office of Director 82/12/03 EISENHUT.D 0 Division of Licensing ip 16593 017 24X Fiche 50-329, 82/12/07.8212280044
- 8212210196 Interim deficiency rept re possibility of frazil ice formation in svc water intake structure Initially reported on 821112 Possible corrective actions under evaluation CODM.J W Consumers Power Co 82/12/12 KEPPLER, J Q Rogion 3, Office of Director 8pp 16485 151 24X Fiche 50-229,82/12/12, 82/22/15/4
- B/12210314 Forwards nonconformance repts re grinding wheels & G-listing of certain equipment components in diesel generator bldg. per util prior commitments Related correspondence BRUNNER, J E Consumers Power Co 82/12/14 BECHMORFER, C Atumic Safety and Licensing Board Panel 6pp 16497 121 24X Fiche 50-329.82/12/14,8212310314
- G212280320 Interim deficiency rept re lack of overpressuritation protection an piping Initially reported on G21116 Investigation & review continuing Next rept will be submitted by G30310 CGCK, J. W. Consumers Power Co. G2/12/14 KEPPLER, J. O. Region 3 Office of Director 7pp 16561 068 24X Fishe 50-329, 62/12/14.
- 8212270126 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations SAR Change Notice 2648 incorporated in FSAR Revision 41 Next rept will be sent by 830318 COOK. J W Consumers Power Co 82/12/17 KEPPLER, J G Region 3, Office of Director 5pp 16538 132 24X Fiche 50-329, 82/12/17. 8212270126
- 1 Hearing transcripts on non-antitrust matters
- 8P1209018B Forwards RB Peck revised testimony Certificate of Svt pnrl LAUER, R J Isham, Lincoln & Beale LAUER, R J Consumers Power to 82/12/06 Atomic Safety and Licensing Board Panel 3pp 16362 001 24X Fiche 50-327, 82/12/06, 8212090188
- --8212090194 Revised testimony of RB Peck Surcharge program at digspl generator bldg eliminated potential future settlement problems due to compressibility of plant fill matl & lack of honogeneity PECK:R B Consumers Power Co 82/12/06 275pp 16362 004 114X Fiche 50-329,82/12/06.8212090188
- 8212100030 Transcript of 821206 hearing in Midland, MI Pp 10, 149~10, 345 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/06 12ipp 16377 277 24X Fiche 50-329, 82/12/06, 8212100030
- 8212140044 Transcript of 821207 hearing in Midland, MI Pp 10, 346~ 10, 397 * Atomic Safety and Licensing Board Panel 82/12/07 256pp 16409 005 24X Fiche 50-327, 82/12/07, 8212140044
- B212100D48 Forwards corrected Pages 8548-A, 8628, 8629 & 9194-D to transcripts of 821115 & 18 evidentiary hearings in Midland, MI MURPHY, B M Alderson Reporting 82/12/08 MCNAMARA, A NRC No Detailed Affiliation Given 1p 16379 072 24X

- --8212100077 Corrected Page 9194-B to transcript of 821118 evidentiary hearing in Midland.MI + Atomic Safety and Licensing Board Panel 82/11/18 ip 16379 076 24X Fiche 50-329:82/12/08.8212100048
- 8212140106 Transcript of 821208 hearing in Midland.MI Fp 10,598-10,803 Supporting documentation enci * Atomic Safety and Licensing Board Panel 82/12/08 290pp 16407 236 24X Fiche 50-329,82/12/08,8212140106
- GZ12150902 Transcript of 821209 hearing in Midland, MI Pp 10, B04-11, 007 Supporting documentation encl * Atomic Safety and Licensing Board Panel 82/12/09 323pp 16421 331 24% Fiche 50-329, B2/12/09, B212150002
- S2:12150006 Transcript of 82:1210 evidentiary hearing in Midland, MI Pp 11,008-11, 228 Supporting documentation encl * Atomic Safety and Licansing Board Panel 82/12/10 352pp 14425 249 24X Fiche 50-327, 82/12/10, 82:12150006
- U Congressional/Executive Correspondence
- GF12100042 Responds to 821103 ltr expressing concern re implementation of GA programs Special measures taken to monitor activities Soils mettlement problem focused NRC attention Problems must be resolved before OL issued

 DIRCKS.N J Office of the Executive Director for Operations

 B2/12/07 LEVIN.C Senate lipp 16399 346 24X

 Fiche 50-329, 82/12/07, 8212100042
- --B212100045 Expresses concern re implementation of QA programs Info re discussions w/J Keppler requested LEVIN.C Senate B2/11/03 DENTON:H Defice of Nuclear Reactor Regulation. Director 3pp 16399-357 24X Fiche 50-329.82/12/07. B212100042

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

- I Security, medical, emergency & fire protection plans
- Bil2090337 Submits info on emergency operations facility (EDF) per F Apscella request EOF established in tower at util carporate ofcs located more than 10 miles from facility per NUREO-0676
 ROOTLD lowa Electric Light & Power Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 16365 088 24X Fiche 50-331.82/12/03.8217090337
- DP12170193 Forwards revision to modified amended security plan
 Revision withheld (ref 10CFR73 21)
 RODTL D lows Electric Light & Fower Co 82/12/10 DENTON.H R
 Office on Nuclear Reactor Regulation, Director 1p 16462 022 24X
 Ciche 50-331.82/12/10.8212170193
- 02:12230359 Releases public version of special orders re communication w//RC. state & local authorities during unusual events.alerts & emergencies
 FELTON, J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16544 059 24X Fiche 50-331.82/12/15.
- --G212230374 Forwards public version of Special Orders 519 re communication w/NRG state & local authorities during unusual events; alerts, embrgencies & significant events & 522 re emergency response organization notification list MEYER.K A lowa Electric Light & Power Co 82/12/07 DENTON; H R Office of Nuclear Reactor Regulation, Director ip 16544 062 24% Fiche 50-331.82/12/15.8212230369
- --8212230377 Public version of Special Orders 519 re communication w/ NRC, state & local authorities during unusual events, alerts, emergencies & significant events & 522 re emergency response organization notification list MEYER,K A lowa Electric Light & Power Co 82/12/07 32pp 16544 063 24% Fiche 50-331,82/12/15.8212230369
- G.!12220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site omergency operations facility KEPPLER.J G Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50~000,82/12/16.8212220306

- 8P12270168 Application to amend License DPR-49. modifying Tech Specs re Mark I containment nod program, compliance w/ANSI-N18 7, safety committee quorum & frequency of audits of emergency & security plans ROOT.L D Iowa Electric Light & Power Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16538 033 24X Fiche 50-331.82/12/20.8212270168
- --B212270176 Proposed Tech Specs re Mark I containment mod program, compliance w/ANSI-N18 7, safety committee quorum & frequency of audits of emergency & security plans

 * Ioua Electric Light & Power Co 82/12/20 8pp 16538 035 24X Fiche 50-331,82/12/20,8212270168
- J Insurance & Indemnity information
- B:12150132 Applies for pro-rata refund due to reduction of indemnity fee to min re licensing of BOth unit SECKMAN.PE I lows Electric Light & Power Co 82/12/10 SALTZMAN.J Antitrust & Economic analysis Branch (Utility Finance) 1p 16425 228 24X Fiche 50-331.82/12/10.8212150132
- ${\cal P}$ -Operating license stage documents & correspondence
- 8P11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden I, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0755 & NUREO-0755 wc list encl W/n stated encl LISENHUT, D G Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16397 004 24X Fiche 50-000, 82/11/15, 8211230066
- 8212020007 Forwards SER & technical evaluation regt re TMI Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage " Items considered resolved VASBALLO, D B Operating Reactors Branch 2 82/11/23 ARNOLD, D Ioua Electric Light & Power Co Bpp 16308 303 24X Fiche 50-331,82/11/23,8212020007
- --8208310315 "Improvements In Training & Requalification Programs As Required By TMI Action Items IA 2 1 & Il B 4 for Duane Arnold Energy Ctr." technical evaluation rept Science Applications, Inc. NRC-03-82-096 SAI-186-029-35 82/08/26 NRC No Detailed Affiliation Givon 15pp 16308 312 24X Fiche 50-331.82/11/23.8212020007
- B212100278 Application to amend License DPR-49 revising App A Tech Specs to incorporate changes to surveillance requirements for functional testing of mechanical snubbers ROOT.L D Towa Electric Light & Power Co 62/11/24 DENTON.H R Uffice of Nuclear Reactor Regulation. Director ip 16377-052 24X Fiche 50-331.02/11/24/8212100278
- ---8212100284 Proposed Tech Specs re surveillance requirement for functional testing of mechanical snubbers * Iowa Electric Light & Power Co 82/11/24 3pp 16377 033 24X Fiche 50-331,82/11/24,8212100278
- BP12070216 Forwards Class III amend fee for review of definition of "inoperable." in response to NRC 821110 ltr Protests fee classification ROOT:L D lowa Electric Light & Power Co BZ/11/29 MILLER,W D License Fee Management Branch 2pp 16329 357 24X Fiche 50~331. BZ/11/29, BZ12070216
- BP12130280 Forwards safety evaluation of BWR owners group 810522,0721 & 820902 responses to NUREO-0737, Item II K 3 25, "Effect of Loss of AC Power on Pump Seals" Responses acceptable VABSALLO,D B Operating Reactors Branch 2 82/12/01 ARNOLD,D lowa Electric Light & Power Co 7pp 16418 234 24x Fiche 50-331,82/12/01.8212130280
- 8212070308 Suppls util 811215 rept on NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants," in response to Franklin Resparch Ctr draft technical evaluation rept dtd 811023 HODTIL D lowa Electric Light & Power Co 82/12/02 BENTON.H R Office of Nuclear Reactor Regulation, Director 6pp 16343 162 24% Fiche 50-331.82/12/02.8212070308
- 8212070463 Authorizes refund of duplicate fee submitted for amend request re plan for integrated scheduling of plant mods MILLER.W O License Fee Management Branch 82/12/03 BATIE.D lows Electric Light & Power Co ip 16398 318 24% Fiche 50-331, B2/12/03, 8212070463

- 8212090322 Application to amend License DPR-49 revising App A Tech Specs to clarify conditions under which refueling operations may continue concurrent w/torus water level below min Tech Spec vol Class III amend fee enc!
 RDDT, L D Towa Electric Light & Power Co 82/12/06 DENTON.H
 Office of Nuclear Reactor Regulation. Director 2pp 16365 115
 24x Fiche 50-331,82/12/06.8212090322
- --8212090328 Proposed Tech Specs re surveillance requirement for core & containment cooling subsystem condensate storage tank during refueling operations

 * Ioua Electric Light & Power Co 82/12/06 3pp 16365 117 244 Fiche 50-331,82/12/06,8212090322
- 8/12270525 Forwards Amend 79 to License DPR-49, & notice of issuance & availability Amend changes limiting conditions for operation & surveillance requirements for reactor protection sys power conitoring sys VASSALLO, D.B. Operating Reactors Branch 2 82/12/06 ARNOLD, D. Ioua Electric Light & Power Co. 3pp. 16551 006 24X Fiche 50-331, 82/12/06.8212270525
- --8212270532 Amend 79 to License DPR-49, changing limiting conditions for operation & surveillance requirements for reactor protection sys power monitoring sys VASSALLO,D B Operating Reactors Branch 2 82/12/06 5pp 16551 009 24X Fiche 50-331,82/12/06/8212270525
- --8212270536 Notice of issuance & availability of Amend 79 to License DRR-49
 VASSALLO,D B Operating Reactors Branch 2 82/12/06 2pp. 18551 014 24% Fiche 50-331,82/12/06,8212270825
- 8212130350 Advises that since facility venting capability is acceptable. TMI I tom II B i re RCS high point vents is resolved Review did not evaluate 10CFRSO 44 compliance or automatic depressuritation sgs valve accumulator capacity VASSALLO, D B Operating Reactors Branch 2 82/12/07 ARNOLD, D lous Electric Light & Power Co 3pp 16412 091 24X Fishe 50-331, 82/12/07, 8212130350
- ---B209220453 "Operating Reactors TMI Lessons Learned NUREQ-0737 Response Evaluations (Program II), Project 1 RCS vents (Item II B 1), "final technical evaluation rept for Duane Arnold 4 Energy Incorporated FIN A-0246-2 82/07/01 BUTCHER, E Division of Licensing 4pp 16412 094 24X Fiche 50-331.
- --8209220450 Advises that plant venting capability acceptable if confirmatory items satisfactorily resolved SPEIS.T P Assistant Director for Reactor Safety 82/08/31 LAINAS.G C Assistant Director for Operating Reactors 2pp
- 82:12130365 Advises that fundamental changes in radiological effluent Tech Specs unacceptable Tech Specs must include listed requirements Detailed discussion of unresolved items enci Kesponse due in 60 days VASSALLG.D B Operating Reactors Branch 2 82/12/07 ARNOLD, D lowa Electric Light & Power Co 9pp 16413 235 24X Jiche 50-331, 92/12/07. 8212130365
- GD12150070 Forwards Revision 4 to ASME Inservice Testing Program ION-45-201 for pumps & valves for Jan 1983-May 1984 Revision written & implemented per 1980 edition.including 1980 addenda of ASME Section XI ROOT.L D. Towa Electric Light & Power Co. 82/12/08, DENTON.H R Office of Nuclear Reactor Regulation, Director. ip. 16430-010 24 Fiche 50-331,82/12/08,8212150070
- --8212150072 Revision 4 to ASME Inservice Testing Program IOW-45-201 for pumps & valves for Jan 1983 May 1984
 KIN.J W., PICKENS,T A., GAVULA,J J. NUTECH (Nuclear Technology, Inc.) 82/10/22 139pp 16430 011 24X Fiche 50-331,82/12/00,8212150070
- B2:22:03:5 Application to amend License DPR-49, changing Tech Specs to incorporate common ref level for reactor vessel water level instrumentation ROOT.L D lows Electric Light & Power Go 82/12/13, DENTON.H R Office of Nuclear Reactor Regulation. Director ip. 16496'295 24X Fiche 50-33: 82/12/13.82122:03:15
- --8212210316 Proposed Tech Spec changes, incorporating common ref level for reactor vessel water level instrumentation * Iowa Flectric Light & Power Go 62/12/13 13pp 16496-296 24% Fiche 50-331,82/12/13,8212210315

- 8212170308 Forwards response to 820728 request for add1 info re NUREQ-0737. Item II D 1, "Relief & Safety Valve Test" No functional valve deficiencies or anomalies experienced during Wyle Lab testing ROBT, L D Towa Electric Light & Power Co 62/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 16456 139 24X Fiche 50-331,82/12/14.8212170308
- 8212170311 "Operability Test Rept for Target Rock Three Stage Svc for Low Pressure Water Tests for GE" MILSAP,L. J. DALEY, C. MDBLY, T. Wyle Laboratories 82/12/14 3pp 16456 150 24x Fiche 50-331,82/12/14,8212170308
- BP:12270168 Application to amend License DPR-49, modifying Tach Specs re Mark I containment mod program, compliance w/ANSI-#118 7, safety committee quorum % frequency of audits of emergency & security plans RDOT.L D Iowa Electric Light & Power Co 82/12/20 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 2pp 16538 033 24X Fichs 50-331.82/12/20.8212270168
- 8212270176 Proposed Tech Specs re Mark I containment mod program, compliance w/ANSI-N18 7, safety committee quorum & frequency of audits of emergency & security plans
 Iowa Electric Light & Power Co 82/12/20 8pp 16538 035 24X Fiche 50-331,82/12/20,8212270168
- 6212280065 Forwards response to request for addl info re NUREO-0313. "Technical Rept on Matl Selection & Processing Ouidelines for BMR Coolant Pressure Boundary Piping "
 RODT, L D I lowe Electric Light & Power Co 62/12/21 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 130pp 16564 292
 24X Fiche 50-331,82/12/21,8212260065
- O Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syr list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- BEIOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model BO2 Thermoluminescent Dosimeters " Svc list encl COBB, L. I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000, 82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list enc! JORDAN-E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 247 Fiche 50-000, 82/11/18,8208190251
- 8/08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Syc list encl
 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Cansolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8212040318 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-331/82-04 NORELIUS, C E Division of Engineering & Technical Programs 82/11/30 ARNOLD, D Iowa Electric Light & Power Co ip 16312 090 24% Fiche 50-331,82/11/30.8212040318
- --8212060324 Responds to NRC 821005 ltr re violations noted in iE Insp Rept 50-331/82-04 Corrective actions audits for scope & schedular requirements & safety committee review of GA audit violations completed ROOT, L D Iowa Electric Light & Power Co 82/11/19 KEPPLER, J O Region 3, Office of Director 16pp 16312 091 24X Fiche 50-331.82/11/30.8212060318
- GP12100275 Forwards response to Revision 1 to IE Bulletin B2-03 re stress corrosion cracking in thick wall, large diameter, stainless steel recirculation sys piping at BMRs Addi info to be developed during Cycle 7 outage scheduled for B30211 ROOT.L D lowe Electric Light & Power Co B2/12/01 KEPPLER.J G Region 3. Office of Director 14pp 16374 302 24X Fiche 50-331,62/12/01.8212100295

- 8212100303 "Stress Corrosion Cracking Evaluation Program. Duane Arnold Energy Ctr " MARTIN, J B , SULLIVAN, M D , RICCARDELLA, P NUTECH (Nuclear Technology, Inc) 80/04/23 75pp 16376 316 24X Fiche 50-331.82/12/01.8212100295
- 82120B0274 Responds to B20930 ltr re regulatory improvement program frogram acceptable
 KEPPLER.J 0 Region 3. Office of Director B2/12/02 ARNOLD.D loua Electric Light & Power Co 1p 16354 240 24X
 Fiche 50-331.B2/12/02.B212080274
- 87/08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG,R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- BPOB190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svr list encl JORDAK.E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 87:12270278 Provides clarification for util commitments re IE Insp Repts 50~331/81~03 Item 48 & 50~331/81~13 Item 2 Commitment to revite emergency & plant operating instructions changed to Cycle 8 refueling outage ROOT.L D Iowa Electric Light & Power Co 82/12/03 KEPPLER.J G Region 3. Office of Director 2pp 16530 172 24X Fiche 50~331.82/12/03,8212270298
- 8708190267 IE Info Notice 92-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVOUNO,R C Director's Office. Office of Inspection and Enforcement 22/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8:'08190248 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JCRDAN,E L. Division of Engineering & Quality Assurance 82/12/70 Consolidated Edison Co of New York, Inc 108pp 16628 293 2/4X Fiche 50-000, 82/12/20, 8208190268
- & Periodic operating reports & related correspondence
- G.*12140134 Corrects error discovered in semiannual rept
 for Jan-June 1979 in values reported for Sr-89 & Sr-90 for
 liquid effluents Caused by conversion error
 MINECK.D L. Jowa Electric Light & Power Co. 82/11/17 Director's
 Office, Office of Inspection and Enforcement 1p 14408 235 24X
 (ische 50-331,82/11/17.8212140134
- G?12210209 Forwards monthly operating rept for Nov 1982 MINECK, D.L. lowa Electric Light & Power Co. B2/12/15 Director's Office, Office of Inspection and Enforcement 1p 16484, 358 24X Fiche 50-331, 82/12/15, 8212210209
- --G212210210 Monthly operating rept for Nov 1982 WATSON, M I lowa Electric Light & Power Co 82/12/15 App 16484 359 24X Fiche 50-331,82/12/15,8212210209
- 5 Reportable occurrences, LERs & related correspondence
- GP12060221 Forwards LER 62-073/03L-0 MINECK,D L Iowa Electric Light & Power Co 82/11/24 KEPPLER,J Q Region 3, Office of Director 1p 16313 187 24X Fiche 50-331, 62/11/24, 8212060221
- --B212060224 LER B2-073/03L-0 on B21102.monthly surveillance test of standby diesel generator fuel oil not performed in prescribed time for Oct Caused by personnel error Responsible personnel disciplined HTLL.K L lows Electric Light & Power Co 82/11/24 Region 3. Office of Director 1p 16313 188 24X Fiche 50-331,82/11/24. R912060221
- 97]2140142 Forwards LER 92-074/03L-0 MINECK,D L Iowa Electric Light & Power Co 82/12/03 KEPPLER.J G Region 3, Office of Director Ip 16408 178 24X Fiche 50-331.82/12/03.8212140142
- --B212140147 LER 82-076/03L-0 on 82110B, during shutdown surveillance testing, drywell pressure switch PS-4310C tripped at 2 2 psig instead of Tech Spec setpoint of 1 5 plus/minus 0 B psig increasing Caused by setpoint drift Switch recalibr HILL.K L Iowa Electric Light & Power Co 82/12/03 Region 3, Office of Director 1p 1640B 179 24X Fiche 50-331.82/12/03, 6212140142

- 8212140332 Forwards LER 82-075/03L-0 NINECK.D L Inwa Electric Light & Power Co 82/12/03 KEPPLER.J G Region 3. Office of Director ip 16401 361 24X Fiche 50-331, 82/12/03, 8212140332
- --8212140338 LER 82-075/03L-0 on 821105, during shutdown, drywell purge, PDIS-4305 opened drywell to suppression chamber vacuum breaker CV-4305 conservatively & would not reset to close Caused by instrument drift Switch recalibr HILL, K L flows Electric Light & Power Co 92/12/03 Region 3, Office of Director ip 16401 362 24X Fiche 50-331,82/12/03, R21240332
- G212210033 Forwards LER 62-061/03L-0 MINECK.D L lows Electric Light & Power Co 62/12/10 KEPPLER.J G Region 3. Office of Director 1p 16485 356 24X Fiche 50-331. 82/12/10. 8212210033
- --8212210034 LER 82-081/03L-0 on 821123, standby filter unit heater B tripped on overtemp Caused by inoperable controller EC-7304B due to failure of operable amplifier in controller circuitry Operable amplifier replaced HILL, K. L. Iowa Electric Light & Power Co. 82/12/10 Region 3, Office of Director ip 16485-357 24X Fiche 50-331,82/12/10, 021210020
- 8212210070 Forwards LER 82-079/03L-0 NINECK.D L. Iowa Electric Light & Power Co 82/12/10 KEPPLER.J 0 Region 3. Office of Director 1p 16492 276 24X Fiche 50-331, 82/12/10,8212210070
- --B212210074 LER B2-079/03L-0 on B21117.B core spray sys header to top of core plate high differential pressure switch tripped at 2 1 psid Caused by instrument drift Switch recalibr & tested satisfactorily
 HILL, K. L. Iowa Electric Light & Power Co. 82/12/10. Region 3, Office of Director 1p. 16492-277. 24X Fiche 50-331,82/12/10, 0210710070.
- 82:12210352 Forwards LER 82-077/03L-0 MINECK.D L Iowa Electric Light & Power Co 82/12/10 KEPPLER.J 6 Region 3. Office of Director Ip 16495 169 24X Fiche 50-331. 82/12/10.8212210352
- 8212210358 LER 82-077/03L-0 on 821116, during surveillance testing, RHR svc water pump 1P-22D failed to meet Tech Spec requirements Caused by Loose impeller on shaft Cause under investigation Pump rebuilt
 HILL, K L. Iowa Electric Light & Power Co. 82/12/10 Region 3, Office of Director 1p. 16495 170. 24% Fiche 50-331, 82/12/10, 8212210352
- 82:12280454 Forwards LER 82~080/03L~0 MINECK,D L. Iowa Electric Light & Power Co 82/12/17 KEPPLER,J 8 Region 3, Office of Director 1p 16556 031 24X fiche 50~331.82/12/17,8212280454
- --B212280457 LER 82-080/03L-0 on B21122.wash pump IP-112B had discharge head of approx 33 psig instead of required 60 psig Caused by slippage of coupling between motor & pump on motor shaft Pump & motor aligned & set screws tightened HILL.K L. Iowa Electric Light & Power Co. B2/12/17 Region 3. Office of Director ip 16556 032 24X Fiche 50-331.82/12/17.8212280454
- 0212300327 EN-02-037A on 821227.notice of proposed imposition of civil penalty in amount of 440,000 issued Action based on violation of fech Spec in which one emergency diesel generator could not be started within design requirements BARBERS 6. AXELRAD. J Director's Office Office of Inappetion and Enforcement 82/12/27 ip 16574 267 24% Fiche 50-331,82/12/27,8212300327

V Operator Examinations

- 3212020007 Forwards SER & technical evaluation rept re TMI Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage" Items considered resolved VASSALLO, D B Operating Reactors Branch 2 92/11/23 ARNOLD, D lows Electric Light & Power Co 8pp 16308 303 24% Fische 50-331, 82/11/23, 8212020007
- --B208310315 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 1 & II B 4 for Duane Arnold Energy Ctr," technical evaluation rept # Science Applications, Inc. NRC-03-B2-096 SAI-186-029-35 B2/08/26 NRC No Detailed Affillation Given 15pp 16308 312 24% Fiche 50-331,82/11/23,8212020007

- DOCKET 50-332 BARNWELL REPROCESSING PLANT
- Q Inspection reports. IE Bulletins & correspondence
- G212090447 Forwards IE Insp Rept 50-332/82-03 on 821026-29 No noncompliance noted G1850N.A F Division of Engineering & Technical Programs 82/11/05 BUCKHAM.J A Allied General Nuclear Services 200 16363 260 24X Fiche 50-332,82/11/05,8212090447
- --8212090451 IE Insp Rept 50-332/82-03 on 821026-29 No moncompliance noted Major areas (respected procedural control, internal review, audit safety committees, facility status & independent effort CORYELL OP, MCALPINE. E J Division of Engineering & Technical Programs 82/(1/04 4pp 16263 262 24X Fiche 50-332,82/11/05,8212090447
- 8P12090405 Ack receipt of IE Insp Rept 50-332/82-03 No proprietary info BUCKHAM.J A Allied General Nuclear Services 82/11/17 GIBSON,A F Division of Engineering & Technical Programs ip 16364 251 24% Fiche 50-332,82/11/17,8212090405
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT
 F Security, medical, emergency & fire protection plans
- GP12140225 Ack receipt of 821102 ltr requesting extension of completion date for radiation protection procedures per IE Health Physics Appraisal Rept 50-333/80-20 Revised date of 821231 acceptable for rept Items E 1.E 2.D 2.D 5 & D 8 MARTIN.T T Division of Engineering & Technical Programs 82/12/09 MCNEILL.C A Power Authority of the State of New York 2pp 16408 355 24X Fishe 50-333/82/12/09/8212140225
- --8212140236 Suppls 820430 response to NRC 820120 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Requests completion date for radiation protection procedures be extended to 821231 MCMEILL.C A Power Authority of the State of New York 82/11/02 MARTIN.T T Division of Engineering & Technical Programs 2pp 16408 357 24X Fiche 50-333, 82/12/09, 8212140225
- B2)2140294 Submits requested info from 821202 telcon re emergency operations facilities (EOF) Util in process of converting bldg to serve as alternate EOF BAYNE. J P Fower Authority of the State of New York B2/12/09 VASSALCD.0 D Operating Reactors Branch 2 Jpp 16402 082 24X Fiche 50-333, B2/12/09,8212140294
- 8P12150121 Ack receipt of 821129 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-333/80-20

 HARTIN: T T Division of Engineering & Technical Programs 82/12/10 MCNEILL: C A Power Authority of the State of New York 1p 16430 195 24X Fiche 50-233,82/12/10,8212150121
- --B212150126 Responds to NRC B21101 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions offgas sys undergoing testing & repair Next status rept will be filed by 830201 MCMEILL.C A Power Authority of the State of New York 82/11/29 MARTIN-T T Division of Engineering & Technical Programs 2pp 16430 196 24X Fiche 50-333.82/12/10.8212150121
- B212210177 Provides add1 info to assist shift crews making telephone repts via NRC emergency notification sys Bample event notification form used by NRC duty officer encl STAROSTECKI.R Division of Project & Resident Programs B2/12/16 MCNEILL, CA Power Authority of the State of New York 6pp 16484 243 24X Fiche 50-333,82/12/16.8212210177
- SF12220452 Submits clarification of dc power & control circuit definitions telecopied to NRC on 821207.per App R fire protection conformance requirements
 BAYNE, J.F. Power Authority of the State of New York 82/12/17
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 16504 261 24X Fiche 50-333,82/12/17.8212220452
- P Operating license stage documents & correspondence
- 8RI 1230066 Ceneric Ltr 82-27 to all BWR licensess of operating reactors except LACBUR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmitted of NUREO-0763 & NUREO-0763 Swc list encl W/o stated encl EIBENNUT, D C Division of Licensing B2/11/15, General Public Utilities OPU Service Corp 22pp. 16387 004 24X Fiche 30-000, 82/11/15, 8211230066

- BP12130277 Forwards safety evaluation of BWR owners group B10522,0921 & B20902 responses to NUREO-0737. Item II K 3 25. "Effect of Loss of AC Power on Pump Seals "Responses acceptable VASSALLO.D B Operating Reactors Branch 2 B2/12/01 SINCLAIR, L H Power Authority of the State of New York 7pp 16418 227 24% Fiche 50-333,82/12/01.8212130277
- 8P12270175 Forwards revised schedule for post-TMI requirements (Generic Ltr 82-03).NUREO-0737.Items II B 3 2 re post-accident sampling mod. II F 1 6 re containment hydrogen concentration monitor & III A 2 2 re meteorological data
 BAYNEJ P Power Authority of the State of New York 82/12/23
 VASSALLO.D B Operating Reactors Branch 2 3pp 16578 045 24X
 Fiche 50-333.82/12/23.8212290175
- & Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter: Stainless Steel, Recirculation Bys Piping at BRR Plants "Svc list encl.
 UEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112p 16462 163 24x Fichs 50-000, 82/10/28, 8208190240
- 82/09/90245 IE Info Notice 82-42, "Defects Observed in Panasonic Modil 801 & Model 802 Thermoluminescent Dosimeters "Svc list enc! COBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,82/08/190245
- 8208190251 IE Ipfo Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 74X Fiche 50-000, 82/11/18,8208190251
- BRI2030065 Forwards IE Insp Rept 50-333/82-22 on 821001-31 % notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/11/16 MCNEILL.C A Power Authority of the State of New York 2pp 16304-192 24X Fiche 50-333,82711/168.8212030065
- --8212030070 Notice of violation from insp on 821001-31 * Division of Project & Resident Programs 82/11/18 1p 16304 174 24X Fiche 50-333, 82/11/18,8212030065
- --8212030078 IE Insp Rept 50-333/82-22 on 821001-31 Noncompliance noted failure to simulate low condensate storage tank level at lavel switches 13-L5-76A & 13-L5-77B during performance of F-ST-24D
 LINVILLE, J C , DOERFLEIN, L T , BAUNACK, W H Division of Project & Resident Programs 82/11/16 15pp 16304 195 24X
 Fiche 50-333,82/11/18,8212030055
- B212080374 Responds to IE Bulletin 81-02. Suppl 1, "Failure of Gate type Valves to Close Against Differential Pressure " Valves listed are not installed at facility MCNEILL, C A Power Authority of the State of New York 82/11/18 HAYNES.R C Region 1. Office of Director ip 16353 319 24% Fiche 50-333.82/11/18.8212080374
- BYOB190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 UEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Concollabete Edison Co of New York, lice 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 870B190257 IE Info Notice 92-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! CDB0,L I Division of Fuel Facilities, Materials & Gafeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24x Fiche 50-000,82/11/30,8208190257
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNDIR C Director's Office of Defice of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- BP08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14442 044 Fiche 50-000, 82/12/03, 8208190261

ŗ

- BE12140225 Ack receipt of 821102 ltr requesting extension of completion date for radiation protection procedures per IE Health Physics Appraisal Rept 50-333/80-20 Revised date of 821231 acceptable for rept Items Ei.E.2.D.R.D 5 & D.8 MARTIN.T T Division of Engineering & Technical Programs 82/12/09 MCNETILL.C A Power Authority of the State of New York 2pp 16408 355 24X Fiche 50-933.82/12/09.8212140225
- --B212140236 Suppls 820430 response to NRC 820120 ltr re violations noted in IE Health Physics Appraisal Rept 80-333/80-20 Requests completion date for radiation protection procedures be extended to 821231 MARTIN, T T Division of Engineering & Technical Programs 2pp 16408 357 24X Ficho 50-333,82/12/09,8212140225
- 82:12:9012: Ack receipt of 82:129 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50:33:780-20 MARTIN. IT Division of Engineering & Technical Programs (MCNEILL, CA Power Authority of the State of New York 19 16430 195 24X Fiche 50-333,82/12/10.8212150121
- 8212150126 Responds to NRC 821101 ltr re violations noted in IE Health Physics Appraisal Rept 50-333/80-20 Corrective actions ofrgas sys undergoing testing & repair Next status rept will be filed by 830201 MCNEILL, C A Power Authority of the State of New York 82/11/29 MARTIN, T T Division of Engineering & Technical Programs Ppp 16430 196 24X Fiche 50-333, 82/12/10, 6212150121
- 8208190267 IE Info Notice 82~49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG,R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 171 24X Fiche 50~000,82/12/16,8208190267
- GP12220417 Forwards list of topic areas for discussion at upcoming Region 1/licensee meeting on drug & alcohol abuse programs, as discussed in IE info Notice 82-03 & NUREG-0903 Meeting as obtussed in it into Notice 82-05 & NonEco-0703 meeting date & time to be arranged STARDSTECKI.R Division of Project & Resident Programs 82. MCNEILL.C A Power Authority of the State of New York 4pp 16503 264 24X Fichs 50-333.82/12/16.8212220417
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 ' Svc list encl
 JORDAN. E.L. Division of Engineering & Guality Assurance 82/12/20
 Consolidated Edison Co. of New York, Inc. 108pp 16628 293 24:
 Fiche 50-000.82/12/20,8208190268
- N Periodic operating reports & related correspondence
- 8Pi2130081 Forwards monthly operating rept for Nov 1982 MONETLU.C A Power Authority of the State of New York Director's Office, Office of Inspection and Enforcement 16390 188 24X Piche 50-333.82/12/07.8212130081 82/12/07 Spp
- -- 4212130084 Monthly aperating rept for Nov 1982 CORX.J Power Authority of the State of New York 16370 189 24X Fiche 50-333.82/12/07.8212130081 8**թ** թ 82/12/07
- 5 Reportable occurrences, LERs & related correspondence
- GF:12040272 Forwards LER 82-049/03L-0 NCNEILL.C A Power Authority of the State of New York 62 HAYNES.R C Region 1. Orfice of Director ip 14312 043 Fiche 50-333.82/11/23.82/2060272 62/11/23
- ~-8212060296 LER 82~049/03L~0 on 821027, during Tech Sper surveillance 112060296 LER 82-049/03L-0 on B21027, during fech Sper surviv requirement review scram discharge vol vents & drains not cycled on quarterly basis Caused by supervisory personnel error Addi surveillance procedure developed LISENDR. Power Authority of the State of New York 82/1 Region i, Office of Director 2pp 16312 064 24X Fishe 90-333.89/11/23.82120A0092 82/10/23 Fiche 50-333, 82/11/23, 8212040292
- GP12060091 Forwards LER 82-051/03L-0 MCNEILL, C A Power Authority of the State of New York 82/ HAYNES, R C Region 1, Office of Director 1p 16316 075 fiche 50-333, 82/11/24,8212060091 82/11/24
- --B212060101 LER 82-051/03L-0 on B21109, setpoint on reactor low water level scram switch 02-3-LIS-1010 less conservative than required Caused by instrument drift Set readjusted & test frequency for trend observation increased

 # Power Authority of the State of New York B2/11/24 Region
 1. Office of Director 19 16316 076 24X Fiche 50-333, 82/11/24, 8212060091

- G?12060223 Forwards LER 82-052/03L-0 MCNEILL.C A Power Authority of the State of New York B2 HAYNES.R C Region 1. Office of Director 1p 16312 239 Fiche 50-333. B2/11/24. B212060223 B2/11/24
- --8212060231 LER 82-052/05L-0 on 821110. HPCI turbine high exhaust diaphragm pressure switch 23-PS-868 setpoint found to be less conservative than required setting Caused by instrument drift Switch setpoint adjusted within Tech Spec Immit

 * Power Authority of the State of New York 82/11/24 Region 1, Office of Director 1p 16312 240 24X Fiche 50-333,82/11/24,8212060223
- BP12080394 Forwards LER 82-050/03L-0 MCNEILL.C A Power Authority of the State of New York B2 HAYNES.R C Rogion 1, Office of Director 1p 16352 277 Fiche 50-333, 82/12/01.8212080394 82/12/01
- --8212080406 LER 82-050/03L-0 on 821109, scram discharge vol rod block 2:1208406 LER 82-050/03L-0 on 82:1109.scram distharge vol rod level surveillance test not performed within 7 days of reactor startup.per Tech Spec Caused by failure to enter frequency statement in procedure during review of Amend 62 Power Authority of the State of New York 82/12/01 1, Office of Director 2pp 16352 278 24X Fiche 50-333. Region 62/12/01,8212080394
- 8212210268 Forwards updated LER 82-051/03L-1 MCNEILL.C A Power Authority of the State of New York 82 HAYNES,R C Region 1, Office of Director 1p 16483 251 I iche 90-333,82/12/09.8212210268 82/12/09
- G212210274 Updated LER 82-051/03L-1 on 821109, while conducting surveillance testing on reactor low water scram switch 02-3-LIS-101D, sotpoint found less conservative than required Caused by Instrument drift Setpoint adjusted KEITH, H Power Authority of the State of New York 82/12/07 Region i. Office of Director 2pp 16483 252 24X Fiche 50-333,82/12/09.821221026B rk 82/12/07 24X
- 0212210415 Forwards updated LER 02-030/03L-1 MCNEILL.C A Power Authority of the State of New York BE HAYNES.R C Region 1. Office of Director ip 16493 103 Fiche 50-333,82/12/13.8212210415 82/12/13
- --8212210425 Updated LER 82-030/03L-1 on 820707.rod block monitor B found out of calibr Causes by instrument drift Monitor recalibr & returned to svc Surveillance calibr test frequency Thereased to once per month
 KEITH.H Power Authority of the State of New York
 Region I. Office of Director 2pp 16493 104 2
 Piche 50-333.82/12/13.8212210415 rk 82/12/13 24X
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 Security, medical, emergency & fire protection plans
- G212100038 Ack receipt of 921115 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Rept b0-334/82-15
 MARTIN: T T Division of Engineering & Technical Programs 62/12/06 CAREY, J J Duquesne Light Co 2pp 16379 046 24X
 Fiche 50-334, 82/12/06, 8212100038

- --B212100041 Responds to NRC B20727 ltr re violations noted in IE
 Emergency Preparedness Rept 50-334/82-15 Corrective actions
 line level of radio base stations turned up.ensuring sys
 activation 1 control sys tested monthly
 CAREY, J. Duquesne Light Co. B2/11/15 HAYNES, R. C. Region 1.
 Office of Director 2pp 16379 048 24X Fiche 50-334,82/12/04, 8212100038
- SPI2170200 Summaries S21130 meeting w/NRC & documents understanding mutually Agreed upon re App R fire protection rule Finalized tesponses to S21118 questions encl CAREY, J J Duquesne Light Cn S2/12/10 VARGA, S A Operating Reactors Branch 1 112pp 16450 012 24X Fiche 50-334,82/12/10. 8212170200
- 8212170032 Responds to 820920 1tr re changes to guard training & qualification plan Proposed changes acceptable Final determination cannot be made until listed changes implemented into plan
 VARCA, 8 A Decrating Reactors Branch 1 82/12/13 CAREY, J J
 Duquesne Light Co ip 16480 361 24X Fiche 50-334, 82/12/13, 82/12/032

- 82:12210334 Provides add1 info to better prepare shift crews operating nuclear power plants for questions NRC duty officer may ask during telephone notifications Revised event notification form encl STARDSTECKI.R Division of Project & Resident Programs 82/12/16
- Form entl
 STARDSTECKI,R Division of Project & Resident Programs 82/12/16
 CAREV,J J Duquesne Light Co 6pp 16496 322 24X
 Fiche 50-334,82/12/16,8212210334
- 8212300107 Forwards add1 info to clarify & substantiate 820630 request for exemption from App R to 1005R50 re control room & primary auxiliary bldg CAREY, J D Buquesne Light Co 82/12/21 VARDA, S A Operating Reactors Branch I 15pp 16598 234 24X Fiche 50-334,82/12/21, pagestors Branch I 15pp 16598 234 24X Fiche 50-334,82/12/21,

P Operating license stage documents & correspondence

- 9212030142 Responds to 920927 Question 7 re two loop operation Revised table of sequence of events for major rupture of main steam pipe encl
 CAREY, J J Duquesne Light Co 92/11/22 VARGA, S A Operating Reactors Branch 1 3pp 16303 022 24X Fiche 30-334, 82/11/22, 82/2030142
- 8212020078 Forwards application for amend to License DPR-66.permitting operation if second licensed reactor operator on shift unavailable due to conflicts between requirements for min shift crew composition & NRC policy statement on overtime CAREY. J. J. Duquesne Light Co. 82/11/23 VARGA, S. A. Operating Reactors Branch (2pp. 16272 014 24x Fiche 50-334,82/11/23,82/12/20078
- --8212020084 Application for emend to License DPR-66, permitting operation if second licensed reactor operator on shift unavariable due to conflicts between requirements for min shift crew composition & NRC policy statment on overtime CAREY, J. Duquesne Light Co. 82/11/23 ip 16272 016 24X Fiche 50-334,82/11/23,8212020078
- 8212020089 Proposed Tech Spec Page 6-4 re min shift crew composition # Duquesne Light Co 82/11/23 4pp 16272 017 24X Fiche 50-334,82/11/23,8212020078
- G212080474 Forwards application for amend to License DPR-66, revising Tables 3 7-4a & 3 7-4b re safety-related hydraulic & mechanical snubbers CAREY, J Duquesne Light Co. 82/11/23 VARGA-S A Operating Reactors Branch I, ip 16352 152 24X Fiche 50-334.82/11/23, B212080474
- --8212080480 Application to amend License DPR+66.revising Tables 3 7-4n & 3 7-4n re-safety-related hydraulic & mechanical snubbers CAREY.J J Duquesne Light Co. 82/11/23 2pp 16352 153 24X Fiche 50-334,82/11/23.8212080474
- --8212080484 Proposed Tech Spec change revising Table 3 7-4a & 3 7-4b re safety-related hydraulic & mechanical snubbers + Duquesne Light Co 82/11/23 8pp 16352 155 24X Fiche 50-334.82/11/23.8212080474
- 87:203014B Forwards completed questionnaire re steam generator tube integrity, in response to Generic Ltr 82-22. "Request for Info re Steam Generator Tube Integrity "GAREY, J J Duquesne Light Co. 82/11/24 EISENHUT, D O Division of Licensing Spp 16303 003 24X Fiche 50-334, 82/11/24, 821203014B
- 0212070520 Forwards revision to "Beaver Valley Unit 1 Offsite Dose Calculation Manual." supporting 021022 Revision 3 to proposed Tech Spec Change 36 Revisions to Section 2 2 2, deleting refs to food 8 ground pathways.forthcoming CAREY.J J Duquesne Light Co 82/12/01 VARGA.S A Operating Reactors Branch 1 Lp 16366 132 24X Fiche 50-334.82/12/01, 02:2070520
- --8212070526 Revision to "Beaver Valley Unit 1 Offsite Dose Calculation Manual" + Duguesne Light Co 82/11/17 157pp 16366 133 24X Fiche: 50-334, 82/12/01, 8212070520
- 8212130243 Forwards application to amend License DPR-66, consisting of Proposed Change Request 83 revising Section 6 Tech Specs re obsite safety committee & offsite review committee membership & responsibilities, per Generic Ltrs 82-17 & 23, CAREY, J J Duquesne Light Co 82/12/06 VARGA, S A Operating Reactors Branch | 1p. 16396 254 24X Fiche 50-334,82/12/06, 8212130243

- --8212130248 Application to amend License DPR-66, consisting of Proposed Change Request 83 revising Section 6 Tech Specs re onsite safety committee & offsite review committee membership & responsibilities
 CAREY, J Duquesne Light Co 82/12/06 Ip 16376 255 24% Fiche 50-334,82/12/06.8212130243
- --B212130264 Proposed changes to Section 6 Tech Specs re onsite safety committee & offsite review committee membership & responsibilities * Duquesne Light Co B2/12/06 Spp 16376 256 24X Fiche 50-334,82/12/06,8212130243
- BB12220373 Forwards fee for 821123 Tech Spec Change Request 82 SIEBERJ D Duquesne Light Co 82/12/06 License Fee Management Branch 1p 16517 150 24X Fiche 50-334, 82/12/06, 8212220373
- 8212220425 Forwards Class III license fee for 821123 Tech Spec Change Request 78 SIEBER, J. D. Duquesne Light Co. 82/12/06 License Fee Management Branch ip 16503 286 24% Fiche 50-334, 82/12/06, 8212220425
- BP12130242 Forwards Procedure Q, "Response to Void in Reactor Vesset," per NUREG-0737, Item II B I CAREY, J J Duquesna Light Co 82/12/07 VARGA.S A Operating Reactors Branch I 2pp 16376 220 24X Fiche 50-334, 82/12/07, 82
- --8212130245 Procedure G. "Response to Void in Reactor Vessel "

 4 Duquesne Light Co 82/12/07 8pp 16376 222 24X
 Fiche 50-334, 82/12/07, 8212130242
- GP12160339 Forwards "Analog Rod Position Indication Sys Special Rept." based on mat1 presented at 821014 meeting by util 4. Westinghouse Analog or digital indicators in Modes 3.4 & 5 should have no accuracy requirements CAREV.J J Duquesne Light Co 82/12/08 VARQA, S A Operating Reactors Branch i 2pp 16442 274 24X Fiche 50-334,82/12/08,8212160339
- --8212160346 "Analog Rod Position Indication Sys Special Rept" * Westinghouse Electric Corp 82/12/00 23pp 16442 296 24X Fiche 50-334, 82/12/08, 8212160337
- 8212220409 Forwards Class II license fee for 821206 Tech Spec Change Request 63 SIEBER, J D Duquesne Light Co 82/12/08 License Fee Management Branch 1p 16504 281 24% Fiche 50-334,82/12/08,8212220409
- BirOB190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT.D 0 Division of Licensing B2/12/09 Consolidated Edison Co of New York Inc 27pp 16627 247 24X Fiche 50-000, 82/12/09, 8208170263
- G.12270155 Forwards amended application for amend to License DPR-66, revising Tech Spec 6 2-1, "Min Shift Crew Composition "CAREY, J Duquesne Light Co 82/12/15 VARGA, 9 A Operating Reactors Branch I ip 16538 054 24X Fiche 50-334.82/12/15, reconstructions
- --8212270361 Amended application to amend License DPR-66, revising Tech Spec 6 2-1. "Min Shift Crew Composition" CAREY, J. J. Duquesne Light Co. 82/12/16 2pp. 16538 055 24X Fiche 50-334.82/12/15.8212270155
- --8212270163 Proposed Tech Spec 6 2-1, "Min Shift Crew Composition "
 # Duquesne Light Co 82/12/15 3pp 16538 057 24X
 Fiche 50-334.82/12/15.8212270155
- 8212270201 Forwards application for amend to License DPR-66, reducing to 50% number of income movemble detector thimbles required for sys to be operable CAREV. J J Duquesne Light Co 82/12/16 VARQA, S A Operating Reactors Branch 1 ip 16535 122 24X Fiche 50~334, 82/12/16, 8312270201
- --B212270207 Application for amend to License DPR-66, reducing to 507 number of incore moveable detector thimbles required for systobe operable CAREY, J. Duquesne Light Co. 82/12/16 2pp 16535 123 247 Fiche 50-334, 82/12/16, 8212270201
- --B212270209 Proposed Tach Specs re number of incore moveable detector thimbles required for sys to be operable * Duquesne Light Co 82/12/16 10pp 16535 125 24X Fichs 50-334.82/12/16,8212270201

G Inspection reports, IE Bulletins & correspondence

8008190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list end!

DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

- S2:08190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters " Svc list incl
 COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000.82/11/05.8208190245
- BP08190251 IE Info Notice 82-44. "Clarification of Emergency Plan fiercise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199—24: Tiche 50-000.82/11/18.8208190251
- 81/08170256 IE lnfo Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl BEYGUNG.R C Director's Office, Office of Inspection and Entorcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26.8208170256
- 8:08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl (088.L I Division of Fuel Facilities, Materials & Bafeguards 32/11/30 Consolidated Edison Co of New York, Inc 356pp 14:397 028 24X Fichs 50-000,82/11/30,8208190257
- G:12140150 Forwards IE Insp Rept 50~334/82~25 on 820928-1025 & notice of violation 5TAROSTECKI:R Division of Project & Resident Programs 82/11/30 CAREY, J J Duquesne Light Co 2pp 16410 178 24X Fishe 50-334, 82/11/30, 8212140150
- 9212140154 Notice of violation from insp on 820928-1025 * Division of Project & Resident Programs 82/11/30 2pp 16410 180 24X Fishe 50-334, 82/11/30, 8212140150
- --B212140160 IE Insp Rept 50-334/82-25 on 820928-1025 Noncompliance noted failure to follow nuclear safety procedures & review & approve control room tank curve procedures & failure to implement radiation work permit TROSMOSKI.W M . LAZARUS.W . TRIPP.L E Division of Project & Resident Programs 62/11/26 15pp 16410 182 24X Fiche 50-334,82/11/30,82(2140150
- 8P08190259 IE Bulletin 62-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 60:08190261 IE Info Notice 92-48, "Failures of Agastat CR 0095 Relay Sockets" Sic list encl JORDANIE L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462-064-24; Liche 50-000, 82/12/03, 8208190261
- G? 12100038 Ack receipt of B21115 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Rept to -334/82-15
 MARTIN.T T Division of Engineering & Technical Programs 62/12/06
 CAREY.J J Duquesne Light Co 2pp 16379 046 24X
 Fiche 50-334.82/12/06.8212100038
- --B212190041 Responds to NRC 820727 ltr re violations noted in IE
 Emergency Preparedness Rept 50-334/82-15 Corrective actions
 line level of radio base stations turned up ensuring sys
 activation & control sys tested monthly
 CARE\.J J Duquesne Light Co 82/11/15 HAYNES,R C Region 1,
 Office of Director 2pp 16379 048 24X Fiche 50-334, 82/12/06,
 8212100038
- BP08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYOUND.R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8P12220490 Advises of upcoming meeting to discuss IE Info Notice 82-05, "Increasing Frequency of Drug-Related Incidents " Info notice, list of topics to be covered at meeting & NUREO-0903 racl W/O NUREO STAROSTECKIR Division of Project & Resident Programs 82/12/16 CAREY, J J Duquesne Light Co Spp 16503 252 24X fiche 50-334,82/12/16,8212220490

- 8./08190268 IE Info Notice 82-50, "Mod or Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 P4X Fighe 50-000. 82/12/20, 82/8190248
- 9P12290280 Ack receipt of 821123 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/82-22 STAROSTECKIR Division of Project & Resident Programs 82/12/22 CAREY, J Duquesne Light Co. 2pp 16581 067 24X Fiche 50-334, 82/12/22.8212290280
- --8212270287 Responds to NRC 821022 ltr re violations noted in IE Insp Rept 50-334/82-22 Corrective actions revision will be made to startup checklist Drawings & status boards corrected to reflect current plant conditions CAREY. J J Duquesne Light Co 82/11/23 STAROSTECKI.R Division of Project & Resident Programs Spp 16581 069 24X Fiche 50-334.82/12/22.8212270280

R Periodic operating reports & related correspondence

- B212270225 Forwards monthly operating rept for Oct 1982 CAREY, J J Duquesne Light Co 82/11/08 Management Information Branch 1p 16578 063 24% Fiche 50-334, B2/11/08, B212290225
- B212070204 Forwards 821129 itr to PA Bureau of Water Quality Mgt advising that NPDES monthly rept for facility unavailable at present time FEITKNECHT.C Duquesne Light Co 82/11/29 REID.R W Operating Reactors Branch 4 2pp 16335 116 24X Fiche 50-334.82/11/29. G212070204
- S Reportable occurrences. LERs & related correspondence
- 6212080419 Forwards updated LER 81-078/03X-1 LACEY,W S Duquesne Light Co 82/11/26 HAYNES,R C Region 1, Uffice of Director 2pp 16352 108 24X Fichs 50-334,82/11/26, 8212080419
- --B212080440 Up dated LER 61-078/03X-1 on 810823, discovered leakage through containment airlock inner door seals Inner door sealing surfaces & O-rings wiped down & regreased Design change procedure approved on 820605

 * Duquesne Light Co 82/11/18 Region 1, Office of Director 2pp 16352 110 24X Fiche 50-334,62/11/26,8212080419
- BP12080451 Forwards updated LER 81-077/03X-1 LACEY,N S Duquesne Light Co 82/11/26 HAYNES,R C Region J. Office of Director 2pp 16382 164 24X Fiche 50-334,82/11/26, 6212080451
- --B212080497 Updated LER 81-077/03X-1 on 810817, increased radiation levels in auxiliary bldg discovered Caused by crack in welded pipe connection joining two 1A degassifier recovery HX Crack due to thermal stress fatigue + Duquesne Light Co 82/11/26 Region 1, Office of Director 2pp 16352 166 24X Fiche 50-334,82/11/26,8212080451
- GP12080526 Forwards LER 82-051/03L-0 LACEY, H S Duquesne Light Co 82/11/26 HAYNES, R C Region 1. Office of Director 2pp 16352 052 24X Fiche 50-334,82/11/26, 8212080526
- --8212080530 LER 82-051/03L-0 on 821104.while performing routine surveillance, area radiation monitor RIS-RM207 failed off scale jow Caused by multiple electrical component failures Faulty parts replaced & monitor returned to svc on 821117 ** Duquesne Light Co 82/11/05 Region 1. Office of Director 2pp 16352 054 24X Fiche 50-334,82/11/26.8212080524
- 8212140174 Forwards LER 82-049/03L-0 LACEY, W 8 Duquesne Light Co 82/11/26 HAYNES, R C Region 1. Office of Director 2pp 16409 351 24X Fiche 50-334,82/11/26, 6212140174
- --B212140191 LER 82-049/03L-0 on B21111.containment vacuum pump 1A observed not rotating Caused by binding between pump rotor & vanes due to corrosion buildup Pump shaft manually rotated & freed Design change being investigated

 ** Duquesne Light Co 82/11/19 Region 1, Office of Director 2pp 16409 353 24X Fiche 50-334,82/11/26.8212140174

- 8212150020 Forwards LER 82-053/03L-0 LACEY, W.S. Duquesne Light Co. 82/12/02 HAYNES, R.C. Region 1. Office of Director 2pp. 16421 214 24X Fiche 50-334,82/12/02, 82(2)50020
- --8212150025 LER 82-033/03L-0 on 820716, chemistry personnel failed to obtain boron sample of safety injection accumulator IA during two sampling periods in 1981 Caused by misunderstanding among chemists over sampling frequency LACEY, H S Duquesne Light Co 82/12/03 Region I. Office of Director 2pp 16421 216 24X Fiche 50-334.82/12/02.8212150020
- G212[50075 Forwards LER 82-052/03L-0 LACEY.N B Duquesne Light Co 82/12/02 HAYNES.R C Region L Office of Director 2pg 16431 015 24X Fiche 50-334,62/12/02, 62/218075
- --8212150078 LER 82-052/03L-0 on 821105, leaking fire hydrant reported in southeast yard Cause not stated Leak isolated & temporary fire hose installed in fuel bldg to insure adequate fire protection LACEY.W S Duquesne Light Co 82/12/02 Region 1, Office of Director 2pp 16431 017 24X Fiche 50-334,82/12/02.8212150075
- 9212290339 Forwards LER 82-054/04L-0 LACEY, W 8 Duquesne Light Co 82/12/13 HAYNES, R C Region 1. Office of Director 2pp 16586-227 24X Fiche 50-334, 82/12/13, 8212290339
- --B212270340 LER 82-054/04L-0 on 820929, continuous chlorination of circulating water sys occurred over 7-h period Highest free chlorine residual measured 0 45 mg/l Caused by personnel error Sys given to chemistry group & will be automated Duquesne Light Co 82/12/06 Region 1, Office of Director 2pp 16586 229 24X Fiche 50-334, 82/12/13,8212270337
- 8212290373 Forwards LER 81-105/03L-1 LAREY.N S Duquesne Light Co 82/12/15 HAYNES.R C Region 1, Uffice of Director 2pp 16586 266 24X Fiche-50-334.82/12/15, 8212270373
- --B212270382 LER B1-105/03L-1 on B11223 during surveillance test on HY-RT-18 preheater discharge air temp failed to reach required temp in specified time Caused by everpowering of two resistors in temp control unit Resistors replaced a Duquesne Light Co 82/12/13 Region I. Office of Director 2pp 16586 268 24X Fiche 50-334.82/12/15.8212290373
- 8212270404 Forwards updated LER 82-012/01x-1 LACEY,N 8 Duquesne Light Co 82/12/19 HAYNES,R C Region 1, Defice of Director 2pp 16886-195 24X Fiche 50-334.82/12/15, 6212270404
- --8212270411 Updated LER 82-012/01X-1 on 820416, total of seven overstressed pipe supports found upstream of main steam line containment isolation valves Caused by failure to include branch line loading in calculations

 * Duquesne Light Co 82/12/15 Region I. Office of Director 2pp 16586 157 24X Fiche 50-334,82/12/15,8212270404
- Eg12290437 Forwards LER 82-056/03L-0 LACEY.W 8 Duquesne Light Co 82/12/15 HAYNES.R C Region 1. Office of Director 2pp 16585 228 24X Fichs 50-334,82/12/15. R212290439
- --8212270448 LER 82-055/03L-0 on 821125, during normal power operation, hydrogen recombiner 18 failed surveillance test 1 45 4 due to inability to achieve acceptance criteria temp of 700 F Caused by design problem w/resistors in temp cantrol unit * Duquesne Light Co 82/12/06 Region 1, Office of Director 2pp 16585 230 24X Fiche 60-334,82/12/15,8212290439

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

- F Security, medical, emergency & fire protection plans
- SPI2090017 Notification of SPI213 meeting w/util in Bethesda.MD to discuss fire protection plan & factor mutual test programs SELLS.D E Operating Reactors Branch 3 82/12/06 CLARK.R A Operating Reactors Branch 3 2pp 16379 355 24X Ficher 50-335. 82/12/06.8212090017
- SPI2170053 Releases public version of revised offnormal & emergency operating procedures
 FELIDN.J M Division of Rules and Records 82/12/10 Document Management Branch ip 16480 339 24X Fiche, 50-335, 82/12/10, 200170083

- --8212170060 Forwards public version of Revision 2 to Offnormal & Emergency Operating Procedure 1-0510030. "Uncontrolled Release of Radioactive Liquids" & Revision 1 to 1560030. "Primary Water Sys Offnormal Operation "
 WETHY.C M Florida Power & Light Co 82/12/01 Director's Office, Office of Inspection and Enforcement 1p 14480 340 24% Fiche 50-335, 82/12/10, 8212170053
- --8212170045 Public version of Revision 2 to Offnormal & Emergency Operating Procedure 1-0510030, "Uncontrolled Release of Radioactive Liquids" & Revision 1 to 1560030, "Primary Water Sys Offnormal Operation "

 * Florida Power & Light Co 82/11/27 7pp 16480 341 24X Fiche 50-338,82/12/10.8212170053
- 8212270357 Application to amend App A to License DPR-67 in response to NRC 821027 ltr re add! Tech Spec fire protection items No amend fee required per 810204 ltr UHRIG.R E Florida Power & Light Co 82/12/22 EISENHUT.D G Division of Licensing 2pp 16586 244 24X Fiche 50-335,82/12/22.
- --8212290361 Proposed Tech Spec changes to App A re fire protection items UHRIQ.R E Florida Power & Light Co 82/12/22 10pp 16586 246 244 Fiche 50-335.82/12/22,82(2290357

J Insurance & indemnity information

- 8212300294 Forwards Endorsements 1,2 & 3 to NELIA Certificate N-59 & MAELU Certificate M-59 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Day 82/12/27 SALTZMAN, J Assistant Director for State & Licensee Relations 19pp 16594 271 24X Fiche 50-335,82/12/27,8212300294
- P Operating license stage doruments & correspondence
- 8P12090030 Forwards Amend 54 to License DPR-67, safety evaluation & notice of issuance & availability Amend reviews Tech Specs to reflect new UMS flow barrier configuration & deletes max water temp limitation
 WAGNER, D H Operating Reactors Dranch 3 82/12/03 UHRIO, R E Florida Power & Light Co. 3pp. 16385 182 24X
 Fiche 50-335, 82/12/03, 8212090030
- --8212090033 Amend 54 to License DPR-67, revising Tech Specs to reflect new UHS flow barrier configuration & doleting max water temp limitation CLARKIR Operating Reactors Branch 3 82/12/03 7pp 16385 JBS 24% Fiche 50-335,82/12/03,8212090030
- --8212070035 Safety evaluation supporting Amend 54 to License DPR-6/
 * Office of Nuclear Reactor Regulation, Director #2/12/03 Upp
 16385 192 24% Fiche 50-335,82/12/03,8212070030
- --B212070037 Notice of issuance & availability of Amond 54 to License DPR-67 CLARK, R Operating Reactors Branch 3 B2/12/03 2pp 16385 175 24x Fiche 50-335.82/12/03.8212090030
- 8P1215006B Forwards responses to NRC 820713 ltr re NUREG-0737. Item II B 3. "Post-Accident Sampling Sys " W/three oversize drawings Aperture cands are available in PDR URRIO.R E Florida Power & Light Co 82/12/06 CLARK.R A Operating Reactors Branch 3 13pp 16429 089 24X Fiche 50-335.82/12/06.821215004B
- B:08190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl LISENHIUT,D G Division of Licensing B2/12/09 Consolidated Edison Co of New York, Inc 29pp 16629 247 24X Fitche 50-000, 82/12/09, 8208190263
- 8212140103 Generic Ltr 82-28 to all licensess of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re insadequate core cooling instrumentation sys. Svc list encl.

 LISENHUT, D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16670 035 24X Fiche 50-000, 82/12/10. 82/12/40103
- BP12170127 Application for amend to App A of License DPR-67 providing Fech Specs on undervoltage relays for degraded grid conditions. UHRIG.R E Florida Power & Light Co 82/12/10 EISENHUT, D. G. Division of Licensing Rpp 16452 355 24X Fiche 50-335, 82/12/10, B21270127.

- -- 4212170129 Proposed Tech Specs re undervoltage relays for degraded grad conditions Fiche 50-335, 82/12/10, 8212170127
- 8,12170274 Forwards responses to 820913 request for add1 info re degraded grid voltage protection. Questions ind Proposed Tech Spec change to verify load shedding of emergency busses not Spec change to verify load shedding or emergency out-warranted since present test adequate UHR10.R E Florida Power & Light Co #2/12/10 CL/ Uperating Reactors Branch 3 18pp 16458 052 24X Fiche 50-335.82/12/10.812170274 CLARK, R A
- GP:12220551 Concurs w/util postponed installation of auxiliary feedwater sys logic cabinet until Fall 1984 refueling outage Application for Tech Sper changes should provide summary of testing & trouble shooting experience from Unit 2 CLARK, R A Operating Reactors Branch 3 82/12/13 UHRIG.R E Florida Power & Light Co 2pp 16523 347 24X Fichs 50-335,82/12/13,8212220551
- B.'t2270496 Forwards Amend 55 to License DPR-67 & notice of issuance & availability Amend updates Tech Specs re offsite & facility organization & membership of review board CLARK, R A Operating Reactors Branch 3 B2/12/14 UHRIG, R E Florida Power & Light Co 4pp 16605 166 24X Fische 50-335, 82/12/14,8212290496
- -- G212270499 Amend 55 to License DPR-67 updating offsite & facility organization figures & membership of nuclear review board in administrative controls section of Tech Spacs CLARK.RA Operating Reactors Branch 3 82/12/14 9pp 16605 170 24X Fiche 50-335,82/12/14,8212270496
- --B21229050: Notice of issuance & availability of Amend 55 to License DPR-67 DANGER OF THE STATE OF THE STAT
- 8212290357 Application to amend App A to License DPR-67 in response to NRC 621027 ltr re addl Tech Spec fire protection items No amend fee required per 810204 ltr
 UHRIGA RE Florida Power & Light Co 82/12/22 EISENHUT.D 9
 Division of Licensing 2pp 16586 244 24X Fiche 50-335.82/12/22,
- --8212290041 Proposed Tech Spec changes to App A re fire protection UHRIG.R E Florida Power & Light Co 82/12/22 10pp 16586 246 24(Fiche 50-335.82/12/22,8212290357
- GF:12270359 Responds to Generic Ltr 02-16 re Tech Specs for NUREO-0737 items Existing Tech Specs adequately cover anticipatory reactor trip on turbins trip UHRIG.R & Florida Power & Light Co 82/12/22 EISENHUT.D 0 Division of Licensing 3pp 16586 165 24X Fiche 50-335.82/12/22, G212290350 GZ12290389
- Inspection reports, IE Bulletins & correspondence

6212270357

- 8:'08190240 (E Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainloss Steel, Recirculation Sys Piping at BNR Plants " Syc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 1:2pp 16462 163 24X Fiche 50-000, 82/10/28, 8208170240
- Gui2090332 Forwards IE Insp Repts 50-335/82-35 & 50-389/82-80 on H21019-22 No noncompliance noted DANCE: H C Division of Project & Resident Programs 82/11/02 UMRIGA E Florida Power & Light Co 2pp 14345 171 24X Fiche 50-335
- B21209030B IE Insp Repts 50-335/B2-35 & 50-3B9/B2-50 on 821019-22 Nu noncompliance noted Major areas inspected IE Circular 81-08, previous insp findings & quality records for foundations LEMAHAM, J J . CONLON T E Division of Engineering & Technical Programs B2/11/01 4pp 16365 173 24X Fiche 50-335,82/11/02,6212090302
- 8.12090531 Forwards IE Insp Repts 50-335/82-32 & 50-389/82-44 on B20911-1010 No noncompliance noted DAKCE-R C Division of Project & Resident Programs 82/11/02 UHRIG-R E Florida Power & Light Co 2pp 16367 001 24X Fiche 50-335, 62/11/02, 6212070531

- --8212090537 IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No oncompliance noted Major areas inspected maint & surveillance noted Major areas inspected maint & surveillance noted Major areas inspected maint & surveillance observation, operational safety verification, bulletins.circulars,inro notices & preoperational testing ELROD, S A , BIBB, H E , JULIAN, C A Division of Project & Resident Programs 82/11/02 11pp 14347 003 24% Fichs 50-335,82/11/02,8212090531
- 86'08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list
- COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 24% Fiche 50-000.82/11/05.6208190245 82/11/05
- BP12090553 Ack receipt of B21103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/82-29 & 50-389/82-39 DANCE, H C Division of Project & Resident Programs 82/11/17 UMRIO, R E Florida Power & Light Co ip 16367 038 24X Fiche 50-339, 82/11/17, 8212090553
- --8212090559 Responds to NRC 821005 ltr re violations noted in IE Insp Repts 50-335/82-29 % 50-389/82-39 Corrective actions clearance orders corrected & personnel reinstructed re need to designate "locked open" or "locked closed" on orders UHRIG.R E Florida Power & Light Co 82/11/03 G'REILLY, J P Region 2, Dfrice of Director 2pp 16367 039 24X Fiche 50-335,82/11/17,8212090553
- --8212090561 Forwards IE Imsp Repts 50-335/82-29 & 50-389/82-29 on 212090561 Forwards IC Linky Replace 5888081-0910 & notice or violation DANCE/H C Division of Project & Resident Programs 82/10/05 UHRIG.R E Florida Power & Light Co 2pp 16367-041 24X Fiche 50-335, 82/11/17, 8212090553
- --8212090563 Notice of violation from insp on 820811-0910 * Division of Project & Resident Programs 82/10/05 16367 043 24X Fiche 50-335,82/11/17,8212090553
- --8212070564 IE Insp Repts 50-335/82-27 & 50-389/82-39 on 820811-0910 ≥12070304 It Insp Repts 50-335/82-27 & 50-387/82-39 on 820811-0910 Noncompliance noted failure to implement procedure for locking safety-related valves in required position ELROD.S A · BIBB.H E · JULIAN.C A Division of Project & Resident Programs 82/10/04 13pp 16367 044 24% Fiche 50-335.82/11/17, 8212090553
- 8708190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199—14 Fiche 50-000.82/11/18.8208190251
- B20B190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, B2/11/26, B20B190256
- BP12090544 Ack receipt of BP0907 & 1015 ltrs informing NRC of steps 12090514 Ack receipt of BR0907 & 1015 Itrs informing NRC of s taken to correct violations noted in IE Insp Rept 50-335/82-22 0'REILLY, J P Region 2, Office of Director 82/11/27 UHRI Florida Power & Light Co ip 16366 315 24X Fiche 50-335, 82/11/29.8212090544 UHRIGIRE
- --8212070549 Updates 820907 response to NRC 820805 ltr re violations noted in IE Insp Rept 80-335/82-R2 Corrective actions more specific signs installed on shield bldg access doors & personnel reinstructed URRIG.R E Florids Power & Light Co 82/10/15 O'REILLY, J P Region 2, Office of Director 1p 16366 316 24X Fiche 50-335,82/11/29.8212090544
- --8212090554 Reaponds to NRC 820805 ltr re violations noted in IE Insp Rept 50-335/82-22 Corrective actions door shut, signs installed & personnel instructed UHRIO.R E Florida Power & Light Co 82/09/07 O'REILLY, J P Region 2. Diffice of Director 2pp 16366 317 24X Fiche 50-335,82/11/27,8212090544
- --8212090558 Forwards IE Insp Rept 50-335/82-22 on 820527-0610 & notice of violation O'MEILLY.J P Region 2. Office of Director 82/08/05 UHRIG.R E Florida Power & Light Co 2pp 16366 319 24X Fiche 50-335,82/11/29,8212090544
- --B212090560 Notice of violation from insp on 820527-0610 * Region 2. Office of Director 82/08/05 1p 16366 321 24% Fiche 50-335,82/11/29.8212090544

- -8212090562 IE Insp Rept 50-335/82-22 on 820527-0610 Noncompliance noted on 820524, shield bldg integrity not maintained as plact entered Mode 2 from Mode 3 due to tied open door ELROD, S A. 8188 H E. JULIAN, C A. Division of Project & Resident Programs 82/08/02 3pp 16366 322 24X Fiche 50-335,82/11/29,8212090544
- 8,'08190257 IE Info Notice 82~47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syr list encl COUG.L (Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc. 356pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- 8P:08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUYOR C Director's Diffice, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24* Fiche 50-000.82/12/03.8208190259
- GP08190261 IC Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list enc!
 JCRDAN.E L Division of Engineering & Quality Assurance B2/12/03
 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24) tiche 50-060, 82/12/03.8208190261
- GP12220505 Requests written statement within 30 days of ltr re use or disposition of Raychen-Flamtrol cables Generic qualification tests for cables no longer acceptable JORDAN,E L Division of Engineering & Quality Assurance 82/12/10 UHRIO,R E Florida Power & Light Co 2pp 16523 100 24% fishe 50-335,82/12/10,8212220505
- 8, 08190267 IE Into Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc]ist enc]
 IEYDUNG:R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- & Periodic operating reports & related correspondence
- Gi-12290153 Forwards monthly operating repts for Oct 1982 WIKLIAMS.J W Florida Power & Light Co 82/11/15 Office of Resource Management Director 1p 16582 226 24x I iche 50-000.82/11/15,8212290153
- --8212270169 Monthly operating repts for Qct 1982 PACE.P Florada Power & Light Co 82/11/15 12pp 16582 227 24x Fiche 50-000, 82/11/15, 8212270153
- S Reportable occurrences. LERs & related correspondence
- 9711040086 Forwards LER 92-043/03L-0 WILLIAMS.J.Y Florida Power & Light Co 82/10/25 O'REYLLY.J.P. Region 2. Office of Director 1p 15927 036 24X Fiche 50-335.82/10/25.8211040086
- -8211040070 LER 82-043/03L-0 on 820923, at 100% power. That input to subcooled margin monitor became erratic, giving false indication & alarns Cause undetermined Malfunction cleared when cover of junction but removed GREEN.P % Florida Power & Light Co 82/10/25 Region 2, Office of Director ip 15927-037 24% Fiche 50-335.82/10/25, 62/1040086
- G212020369 Forwards LER 82-051/03L-0 WILLIAMS.J W Florida Pover & Light Co B2/11/23 D'REILLY.J P Region 2. Office of Director 1p 16278 145 24x [Liche 50-335, 82/11/23,8212020369
- --9212020371 LER 82-051/03L-0 on 821024, while moving control rods during ascent to full power control element assembly 40 dropped to full insertion Cause undetermined Control element assembly recovered flant operation resumed LAUR.S Florida Power & Light Co. 62/11/23 Region 2, Office of Director 1p. 16278 146 24X Fiche 50-335, 82/11/23,
- 8.712090403 Forwards LER 82-052/03L-0 WILLIAMS.J (I Florida Power & Light Co 82/12/01 O'REILLY, J P Kegion 2. Office of Director ip 16364 352 24X Fiche 50-335,82/12/01.8212090403
- --8212090410 LER 82-052/03L-O on 821101.during test to check ability of it auxiliary feedwater pump to take suction.condensate storage tank NV-09-11 failed to open Caused by torque limiter suitch malfunction Suitch readjusted BRANNIN.J P Florida Power & Light Co 82/12/01 Region 2. Office of Director 1p 16364 353 24% Fiche 50-335.82/12/01, 5212090403

- B212200071 Forwards LER 82-053/03L-0 WILLIAMS.J W Fibrida Power & Light Co B2/12/08 O'REILLY.J D Region 2. Office of Director ip 16470 023 24X Fiche 50-335.82/12/08.8212200071
- --8212200085 LER 92-053/03L-0 on 82110B, while performing post-maint surveillance test of iC steam driven suxiliary feedwater pump, steam supply valve from 1A steam generator failed to apper Caused by failure of contact in switch BRANNIN, J P Florida Power & Light Co 82/12/08 Region 2. Office of Director IP 16470 024 24X Fiche 50-335,82/12/08,8212200071
- 02:2150156 Forwards LER 82~055/03L-0 WILLIAMS J W Florada Power & Light Co 82/12/09 D'REILLY, J P Region 2. Office of Director 1p 16430 185 24X Fiche 50-335/82/12/09,8212150156
- ---B212150158 LER 82-055/03L-0 on 921107, control element assembly motion inhibit circuit for control element assembly out of sequence deviation scanner failed Caused by Pailure of relay in out of sequence circuitry Relay replaced ROTELLA:TS Florida Power & Light Co 82/12/09 Region 2. Office of Director ip 14430 186 24% Fiche 50-335,82/12/09, 8212150156
- G212210389 Forwards LER 82-056/03L-0 WILLIAMS, J W. Florida Power & Light Co. 82/12/13 O'REILLY, J P Region 2, Office of Director 1p 16494 300 24X Fiche 50-335.82/12/13,8212210389
- --8212210396 LER 82-052/03L-0 on 821111.control element assembly motion inhibit circuit for out-of-sequence deviation scanner failed Caused by loose relay socket in circuitry Relay reseated & circuitry returned to svc
 ROTELLA,T S florida Power & Light Co 82/12/13 Region 2, Office of Director 1p 16494 301 24X Fiche 50-335,82/12/13, R21210389
- 8218210175 Forwards LER 82-057/03L-0 WILLIAMS U Fibrida Power & Light Co 82/12/14 D'REILLY U P Region 2. Office of Director 1p 16484 342 24X Fiche 50-335.82/12/14.8212210175
- --8212210186 LER 82-057/03L-0 on 821114, dose equivalent I-131 exceeded Tech Spec 3 4 8 a limit after reactor trip Caused by iodine buildup in primary coolant due to power transient after operation u/nominal fuel leakage ROTELLATS Florida Power & Light Co 82/12/14 Region 2. Office of Director 4pp 16484 343 24X Fiche 50-335,82/12/14. 8212210175
- 9P12220441 Forwards LER 82-058/03L-0 WILLIAMS, J N Florida Power & Light Co 82/12/17 O'REILLY, J P Region 2. Office of Director 1p 16503 331 24X Fiche 50-335.82/12/17,8212220441
- --B212220442 LER 82-058/03L-0 on 821117, during full power operation, containment escape lock mechanical interlock failed during Surveillance Test 4 6 i 3 C Caused by misaligned locking mechanism mechanism readingmed ROTECLA: T 5 Florida Power & Light Co 82/12/17 Region 2, Office of Director ip 16503 332 24X Fiche 50-335,82/12/17,8212220441
- 8:12280359 Forwards LER 82-060/03L-0 WILLIAMS,J () Floride Power & Light Co 82/12/17 O'REILLY,J P Hegion 2, Office of Director 1p 16559 004 24X Ficher 50-335, 82/12/17, 8212280359
- --B2122B0366 LER 82-060/O3L-O on 82i117. during full power operation, auxiliary feedwater flow recorder 18 % sigma indicated flow when actual flow zero Caused by defective force motor internal to transmitter replaced ROTELLA, T 8 Florida Power & Light Co 82/12/17 Region 2, Office of Director 1p 16559 005 24X Fiche 50-335,82/12/17,82122B0359
- 8212280#18 Forwards LER 82-059/03L-0 WILLIAMS, J H Florida Power & Light Co 82/12/17 Q'REILLY, J. P Region 2. Dffice of Director ip 16560 026 24X Fiche 50-335, 62/12/17, 8212280418
- --8212280425 LER 82-059/03L-0 on 821117.during surveillance testing of diesel generator IB. solenoid operated fill valve for engine mounted fuel oil tank failed to open Gaused by stuck level float switch Switch moved.cleaned & satisfactorily tested. ROTELLA.T S Florida Power & Light Co 82/12/17 Region 2, GPfice of Director 1p 14560 027 24X Fiche 50-335.82/12/17.

- 1,2306061 Forwards LER 82-054/03L-0 | #3500001 | Ferwards | Let 82-034/03L-0 | #1LL1AMS, J W | Florida Fower & Light Co | 82/12/22 | O'REILLY, J P | Region 2, Office of Director | 1p | 16598 204 | 24x | Fiche 50-335, 82/12/22, 8212300061
- @212300065 LER 82-054/03L-0 on 821123.DD#S declared inoperable during 212300005 Let 82-094/03-0 on adil21,0345 declared inoperable our normal operation, resulting in loss of control element assembly pulse counting backup position indication & linear heat rate nonitor Loss of DDPS software related BRANNIU. J Filorida Power & Light Co 82/12/22 Region & Office of Director 1p 16998 205 24X Fiche 50-335.82/12/22
- CKET 50-336 MILLETONE NUCLEAR POWER STATION, UNIT 2 Security, medical, emergency & fire protection plans
- 12030167 Forwards 1E Safeguards insp Rept 50-336/82-21 on 820928-29 No noncompliance noted
 NARTHALT Division of Engineering & Technical Programs
 COUNSIL.N G Northeast Nuclear Energy Co (subs of North Northeast Nuclear Energy Co (subs of Northeast 2pp 16304 001 24x Fiche 50-336,82/11/17,8212030167
- D212030177 IE Safeguards Insp Rept 50-336/82-21 on 820928-29 No ANOUNTY LE Safeguages inspired to the control of the control of the control of the countries of the control of the countries of the countries
- I 2070124 Forwards proposal for revision to modified amended security plan Proposal withheld (ref 10CFR73 21)
 COUNSIL.W G WERNER R P Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 82/11/18
 CLARK.R A Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16329 341 24X Fiche 50-245,82/11/18. Meactors Branch 5 [4212070124
- *12070i14 Responds to Generic i.tr 82-25 re BNL request for assistance in field testing new measurement equipment & inventory techniques developed to aid in strengthening IAEA safeguards Add1 info available should be sent expeditiously COUNSIL.N G Connecticut Yankee Atomic Power Co COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/30 E1SENRUT.D G Division of Licensing ip 16057 272 24X Fiche 50-000, 82/11/30, 82/12090114
 - Insurance & indomnity information
- :12280063 Forwards Endorsement 83 to NELIA Policy NF-173 &
 Endorsement 75 to MAELU Policy NF-52
 SINISI, J M Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc
 Div 82/12/21 SALTZMAN, J D Assistant Director for State &
 Licensee Relations 3pp 16564 276 24X Fiche 90-245,82/12/21,
 2212280063
- Operating license stage documents & correspondence
- *12170321 Application to amend Licenses DPR-21 & DPR-65 by incorporating radiological effluent Tech Specs into safety Tech Specs
 CDUNSIL-W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W 9 Northeast Utilities 82/11/22 CLARK-R 4 Operating Reactors Branch 3 3pp 16453 280 24X Fiche 50-245, 82/11/22, 8212170321
- -92:2170322 Proposed radiological effluent Tech Specs for incorporation into safety Tech Specs * Northwast Nuclear Energy Co (subs of Northeast Utilitzes) 62/11/30 | 114pp 16493 283 24X Fiche 50-245.82/11/22, 82:2170321
- ~8212170323 Radiological effluent monitoring & persite dose calculation manual e Northeast Utilities 82/11/30 117pp 16454 037 24X Fiche 50-245.82/11/22.8212170321
- *12060157 Responds to Generic Ltr 82-22 re steam generators Haddam Neck steam generator performance excellent Max of 21 tubes replaced since 1979 Milistone Unit 2 replaced max of 429 Radiation protection grogram established COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W O Northeast Uttlities 82/11/29 EISENNUT, D O Division of Licensing 3pp 16313 117 24X Fiche 30-000,82/11/29.8212060157

- 8212140144 Forwards addl ree for Class [I changes re large & small break LOCA evaluations.per NRC 82111B request (OUNSIL, N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, H 0 Northeast Utilities 82/12/06 DIGGS, N License Fee Management Branch 2pp 16408 174 24X Fiche 50-336, 82/12/06,8212140144
- 82:12:50:28 Forwards application for amend of Licenses DPR-21 & DPR-65, reflecting merger of CT Light & Power Co & Hartford Liectric Co Class I & II fees enci Liectric Co Class I & II Pees enct COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 82/12/08 CLARK,R A Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 16425 229 24X Fiche 50-245,82/12/08, 8212150128
- ~-8212150142 Application for amend of Licenses DPR-21 & DPR-65, reflecting merger of CT Light & Power Co & Hartford Electric Co * Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/08 7pp 16425 231 24X Fiche 50-245, 82/12/08, 8212190128
- 82/2170199 Application to amend Licenses DPR-21 & DPR-65, reflecting merger of Hartford Electrical Light Co w/CT Light & Power COUNSIL.WG Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.WG Northeast Utilities 82/12/08 CLARK,R A Operating Reactors Branch 3 CRUTCHFIELD,D Operat Reactors Branch 5 9pp 16450 144 24X Fithe 50-245.82/12/08.
- 8908190243 Generic Ltr 82-32 to all PWR licensees re potential steam "OBJUZES Generic Let M2-32 to all PMK licensees re potent generator-related generic requirements forwards Science Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list enc! EIGEN-UT.D O Division of Licensing 82/12/09 Conso Edison Co of New York, Inc 29pp 16629 247 24X (iche 50-000, 82/12/09, 8208190263
- G2/12/140103 Generic Ltr 92-28 to all licensees of operating Hostinghouse & C-E PNRs (except Arkansas Nuclear One Unit 2 & San Gnofre 2 x 3) re inadequate core cooling instrumentation sys Suc list encl EIBENNJT.D 0 Division of Licensing 82/12/10 Yankee A Clectric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 82/12/40103 Yankee Atomic
- B21221012) Submits results of discharge piping analyses in response to NUREO-0737. Item II D 1, "Performance Festing of PMR Relief COUNSIL. H C Connecticut Yankee Atomic Power Co COUNSIL. H C Northeast Nuclear Energy Co (subs of Northeast Utilities)
 COUNSIL. H C Northeast Utilities E2/12/15 EISENRUT. D C Division of Licensing App 14485 084 24X Fiche 50-000.02/12/15, 8212210121
- @ Inspection reports, IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03, Revision I. "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermaluminescent Dosineters " Syc list enc1 COBB.L I Division of Fuel Facilities, Naterials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16/372 142 24X Fichs 50-000, 62/11/05, 82081 90245 COBB. L I
- 8212030167 Forwards IE Safeguards Insp Rept 50-336/82-21 on 820928-29 No noncompliance noted
 MARTIN T Division of Engineering & Technical Programs 82/11/17
 COUNSIL W G Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 2pp 16304 001 24X Fichs 50-336.82/11/17.8212030167 82/11/17
- --B212030177 IE Safeguards Insp Rept 50-336/82-21 on B20928-29 No noncompliance noted Major areas inspected BNN control & accounting, facility organization & operation, shipping & receiving, storage & internal control HOLTNER, E. GODY, A.T. Division of Engineering & Yechnical Programs 82/10/22 Spp 16304 003 24X Fiche 50-336,82/11/17,8212030167
- 8208190251 IE Info Nobice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24; Fiche 50-000, 82/11/18, 8208190251

- B212030045 Forwards IE Insp Rept 50-336/B2-23 on 821019-21 No moncompliance noted MARTIN:T T Division of Engineering & Technical Programs B2/11/12 CGUNSIL:W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16307 073 24X Fiche 50-336/82/11/19.8212030045
- ~~B212030031 IE Insp Rept 50-336/82~23 on 821019-21 No noncompliance noted Major areas inspected followup on 810102 loss of dc power event & review of diesel generator trip design & design changes

 EAPEN, P. K. BETTENHAUSEN, L. Region (, Office of Director B2/11/17 5pp 16307 075 24X Fiche 50-336/82/11/19,8212030045
- 620B190256 IE Info Notice 62-46, "Defective & Obsolete Combination Padlocks " Svc | list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 62/11/26 Consolidated Edison Co of New York, lnc 127pp 16411 045 24X Fische 50-000.82/11/26,820B190256
- 8208190257 IE Info Notice 92-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C080.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24x Fiche 50-000.82/11/30,8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYCUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 164t1 317 24X Fiche 50-000.82/12/03.8208190259
- 9208190261 IE Info Notice 82-48. "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24: Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,9208190267
- 82-08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage fielays Type ITE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp 16628-293 24X Fiche 50-000,871972A
- R Periodic operating reports & related correspondence
- 8212290139 Forwards monthly operating rept for Oct 1982 MRGCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) NRGCZKA.E J Northeast Utilities 82/11/12 Offic of Resource Management, Director Ip 16583 059 24X Fiche 50-336.822/11/12.8212270139
- --8212270142 Monthly operating rept for Oct 1782 61B5D14.J Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/12 App 16583 060 24X Fiche 50-336, 82/11/12,8212270139
- 9 Reportable occurrences, LERs & related correspondence
- BP12030201 Forwards LER 82-045/03L-0 MR0CZKA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MR0CZKA:E J Northeast Utilities 82/11/24 HAYKES:R C Region 1, Office of Director 1p 16304 097 24X Fiche 50-336
- --8212030204 LER 82-045/03L-0 on 821027.at 100% power.control room air conditioning sys I was lost Caused by broken were which shifted shortfung power supply due to personnel error Wire repaired & air conditioning sys returned to syc FILBURN.T Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1. Office of Director ip 16304 098 24% Fiche 50-336,82/11/24,8212030201
- BP12030227 Forwards LER 82-043/03L-0
 MR0CZKALE J Northeast Nuclear Energy Co (subs of Northeast Utilities) MR0CZKALE J Northeast Utilities B2/11/24
 MAYNES.R C Region i. Office of Director ip 16307 065 24X
 Fiche 50-336,82/11/24,8212030227
- --8212030234 LER 82-043/03L-0 on 821102, broken i 1/4-inch hydraulic snubber stud discovered & traced to hanger 490001 on one main steam lead to high pressure turbine Caused by constant high vibration & increased loads during plant trips STADNICK. & Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/11/24 Region 1. Office of Director ip 16307 066 24% Fiche 50-336.82/11/24.8212030227

- --8212080415 LER 82-044/03L-0 on 821105.while performing in-core detector alarm update, alarm values updated incorrectly, resulting in nonconservative values Caused by calorimetric being temporarily out of svc Personnel reinstructed in procedures BORCHERT, R Northeast Nuclear Energy Co (subs of Northeast Utilities) 82/12/03 Region 1. Office of Director ip 16352 269 24X Fiche 50-336, 82/12/03,8212080414
- GP12210227 Forwards updated LER 82-044/03X-1
 MRDC2KA.E J Northeast Nuclear Energy Co (subs of Northeast
 Utilities) MRDC2KA.E J Northeast Utilities 82/12/10
 MAYNES.R C Region 1. Office of Director 1p 16483 357 24X
 Fiche 50-336, 82/12/10, 8212210229
- --B212210233 Updated LER B2-044/03X-1 on B21104, while performing in cole detector alarm update, alarm values updated incorrectly, resulting in nonconservative alarm values for in-core detectors Caused by plant calorimetric out-of-sec BURCHERT. R Northeast Nuclear Energy Co (subs of Northeast Utilities) B2/12/03 Region 1. Office of Director 1p 16483 358 24X Fiche 50-336,82/12/10.8212210229
- DOCKET 50-338 NORTH ANNA POHER STATION, UNIT 1

 F Security, medical, energency & fire protection plans
- 8P12070195 Forwards IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted BANCE.H C Division of Project & Resident Programs 82/12/02 STEMART.W L Virginia Electric & Power Co 2pp 16335 011 247 Fiche 50-338, 82/12/02,812/2070175
- --8212070206 IE Bafeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted Major areas inspected security plan & implementing procedures, organization, audit & power supply Details withheld (ref 10CFR73 21) STANSBERRY, W W . MCGUIRE, D R Division of Engineering & Technical Programs 82/12/01 1p 16335 013 24X Fiche 50-338,82/12/02,8212070195
- 82/12090419 Forwards addl info re status of emergency response facilities locations & construpplementing 810401 & 820408 responses to Generic Ltr 81-10 transmitting NUREO-0696, per request STEWART. N L Virginia Electric & Power Co 82/12/06 DENTON, N R Office of Nuclear Reactor Regulation, Director 2pp 16364 2/6 247 Fiche 50-000, 82/12/06, 8212090419
- G./12150059 Forwards revised security drawings Drawings withheld (ref 10CFR2 790)
 STEMART.H L Virginia Electric & Power Co 82/12/09 DENTON.H R Diffice of Nuclear Reactor Regulation, Director VARGA,S A Operating Reactors Branch 1 ip 16427 362 24X Fiche 50-000,82/12/09,8212150059
- GP12170024 Forwards request for add1 info re security training & qualification plans, per util 820717 ltr CLARK, R A Operating Reactors Branch 3 82/12/13 STEWART, W L Virginia Electric & Power Co 4pp 16480 335 24X Fiche 50~000, 82/12/13, 8212170024
- G212270179 Informs that although 821209 itr forwarding security drawings failed to contain safeguards statement drawings were properly secured, marked & identified as safeguards info STEWART. H L. Varginia Electric & Power Co. 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch I ip 16539 010 24X Fiche 30-000.82/12/20,8212270179
- 9 Adjudicatory correspondence
- B212070137 Notice of B30216 special prehearing conference in Bethesda, MD to permit key issue identification to consider intervention petitions & to establish schedule for further actions MDLEE,8 J Atumic Safety and Licensing Board Panel 82/12/03 Upp 16327 023 24X Fiche 50-338,82/12/03,8212070137
- EP12070147 Notice of 820216 special prehearing conference in Betheada, ND to permit key issue identification, to consider intervention petitions & to establish schedule for further actions WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/03 Spp 16527 074 24X Fiche 50-338,82/12/03,8212070147

- 8P12070236 Memorandum memorializing 821202 tolcon w/util.Concerned Citizens of Louisa County.Louisa County & Board of Supervisors & NRC re scheduling special prehearing tonference
 - Supervisors o Rac re-sineguing special prenearing tronference
 WOLFE.S J Atomic Safety and Licensing Board Panel 82/12/03 4pp
 16329 313 24X Fiche 50-338, 82/12/03, 8212070236
- GP:2100104 Objects to 830117 deadline for submittal of contentions

 Beadline hampers identification of valid contentions &
 increases livelihood of burdening proceeding due to
 submittal of unreviewed contentions

 COLEMAN, J ff Severidge, Fairbanks & Diamond COLEMAN, J M Louisa
 (ounty, VA 82/12/07 MOLEF, S J Atomic Safety and Licensing Roard
 Panel 3pp 14379 113 24% Fiche 50-338,82/12/07,8212100104
- GP12140245 Motion to stay proceedings on applications for license amends to allow receipt & storage of Surry spent fuel Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl COLEMAN, J M Louisa County, VA COLEMAN, J M Reveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 14409 314 24X (iche 50-339.82/12/10.8212140245
- Girl2140249 Motion to stay proceedings on applications for license amends to expand spent fuel pool Proceeding should be stayed until Commission: completes waste confidence proceeding Certificate of Svc encl (GLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Dianond 82/12/10 Commissioners Spp 14409 308 24Y [iche 50-338,82/12/10,8212140249]
- GP12280122 Answer in opposition to Louisa County, VA 821210 motion for stay of proceeding until completion of waste confidence in Jenaking Delay would be inconsistent w/NRC regulations & would prejudice util Centificate of Svc encl MALPIN, M W. Virginia Electric & Power Co. 82/12/22 Commissioners 10pp 16564-124 24X Fiche 50-338.82/12/22, (2010) 100-2011
- --8212280130 Affidavit of ML Smith re transhipment of spent fuel Unless VEPCO can secure addl storage space for Surry spent fuel.

 Surry will lose full discharge capability
 SMITH.M L Virginia Electric & Power Co 82/12/21 App
 16564 134 24% Fiche 50-338.82/12/22.8212280122
- Orignol35 Answer in opposition to Louisa County, VA B21210 motion for stay of proceeding until completion of waste confidence indending belay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl MAUPIN, M W Virginia Electric & Power Co B2/18/22 Commissioners 10pp 16555 117 24X Fiche 50-338, 82/12/22, M212280135
- 8P12E90001 Response in apposition to Louisa County, VA motions to stay proceedings until confletion of waste confidence rulemaking Delay would be inconsistent w/RC regulations & would prejudice util Certificate of Svc encl
 1REBY, S A Hearing Branch | 82/12/27 Atomic Bafety and Licensing Board Panel 5pp 16583 248 24X Fiche 50-338,82/12/27, 6216290001
- P Operating license stage documents & correspondence
- 69/12020391 Forwards requests for add1 info re NUREG-0737. Items II F 1 4.5 % 6 concerning containment pressure, water level & hydrogen monitors Response requested within 30 days (LARK.R A Operating Reactors Branch 3 82/11/12 STEWART. W L Virginia Electric & Power Co 9pp 16308 134 24X [iche 50-338,82/11/12,8212020391
- 82:12010370 Informs that Class II fee appropriate for review of 821108 application for Amend 44 to GL changing Type C testing of 1solation valves Refund forthcoming BYGGS:R II License Fee Management Branch 82/11/23 STEMART.W L Virginia Electric & Power Co 1p 16271 097 24X Fishe 50-338.82/11/23,8212010370
- Gi'120&0134 Forwards response to NRC 821026 questionnaire re steam question tube integrity Data for each facility compiled in separate sections
 STEMARTIN L Virginia Electric & Power Co 82/12/01 DENTON, H R Uffice or Nuclear Reactor Regulation, Director EISENHUT, D 0 Division of Licensing 5pp 16314 070 24X Fiche 50-000, 82/12/01, 8212060134
- 8.712040284 Notifies that neither facility has add1 Tech Specs to be submitted, in response to Generic Ltr 82-16 re status of NUREO-0737 items STEWART, W.L. Virginia Electric & Power Co. 62/12/01 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing Ip. 16312-058 24X Fiche 50-000,82/12/01,103120-0584

- G/12130326 Lists as-found ring settings & EPRI as-left ring settings for plant relief & safety valves As-found settings will provide acceptable performance As-left settings add increased conservatism to valve performance STEMARTH L Virginia Electric & Power Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D 0 DLyision of Licensing 2pp 16389 327 24X Fiche 50-338.82/12/07, 8212130326
- 8/12/30319 Advises that util intends to terminate hydrogen monitoring program Parameters of data received impossible to control in power plant environ to degree necessary to perform accurate & meaningful interpretation of collected data STEMART.W L. Virginia Electric & Power Co. 62/12/08 DENTON,H R. Office of Nuclear Reactor Regulation. Director CLARK,R A. Operating Reactors Branch 3 ip. 16389-332 24X Fiche 90-338,62/12/08,6212130319
- 8./[2150048 Application to amend Licenses NPF-4 & NPF-7, allowing optimization of core loading patterns & providing add1 operating flexibility STEWART.U L Virginia Electric & Power Co 82/12/08 DENTON, H ft Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 9pp 16422 294 24X Fiche 50-338, 82/12/08, 8212150048
- --8212150052 Proposed Tech Spers allowing optimization of core loading patterns & providing addl operating flexibility * Virginia Electric & Power Co 82/12/08 21pp 16422 302 24X Fiche 50-338,82/12/08,8212150048
- 8//08190263 Generic Ltr 82-32 to all PWR licenses re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rept re subj requirements Comments requested uithin 30 days of ltr Svc list encl EISEMHUT.D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc. 27pp 16627 247 24X Fiche 50-000.82/12/09.8208190263
- 02:12140303 Generic Ltr 82-29 to all licensees of operating Westinghouse A C-E PWRs (except Arkansas Nuclear Cne, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl CIBENHUT, D 9 Division of Licensing 82/12/10 Yankee Atomic Liectric Co 27pp 16690 035 24X Fiche 50-000.82/12/10, 8212140103
- BF12210187 Responds to NRC comments on conclusions & recommendations re NUREG-0612. "Control of Heavy Loads." per 821022 telcon STEMART W. L. Virginia Electric & Power Co. 82/12/15 DENTON.H W. (Affice of Muclear Reactor Regulation, Director CLARK.R A. (Operating Reactors Branch 3 App. 16484-347 24X Fichs 50-338, 82/12/15, 8212210187
- 9212270407 Trip rept of 921127 visit to Region 2 ofc re investigation into latest Westinghouse main transformer fault to occur at facility ENGLE,L B Operating Reactors Branch 3 92/12/17 CLARK,R H Uperating Reactors Branch 3 5pp 16555 353 24X Fiche 50-338, 82/12/17, 8212270407
- G212270490 Trip rept of G21207 briefing at site re B21205 main transformer fault.resulting in turbine & reactor trip Cause undetermined Plant extensively damaged Task force organized to monitor util investigations LNGLE.L B Operating Reactors Branch 3 B2/12/17 CLAR.R A Operating Reactors Branch 3 16951 056 24X Fiche 50-338.82/12/17.8212270490
- 80:12290248 Application to amend Licenses NPF-4 & NPF-7 changing radiological effluent Tech Specs to delete radiological sampling monitoring & reporting Yequirements in accordance U/NURCHO-0472, Revision 3

 STEWART, U. Virginia Electric & Power Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 16588 034 24%

 Fiche 50-339, 82/12/17, 8212270248
- ~-G212270252 Proposed Tech Spec changes re sampling frequency of wasty decay tank enci Justifications for deviations from NUREG-0472. Revision 3 enci * Virginia Electric & Fower Co. 82/12/17 252pp 16588-037 24X Fiche 50-338,82/12/17,8212270248
- --8212290255 Offsite dose calculation manual * Virginia Electric & Power Co 82/12/17 166pp 16588 289 24% Fiche 50-330,82/12/17,8212290248
- --8212270256 Process control program * Virginia Electric & Power Co 82/12/17 30pp 16587 095 24X Fiche 50-338,82/12/17,8212290248

- B-12280201 Forwards addl info re NUREG-0737, Items II F 1 4, II F 1 5 & //12280201 Forwards addl info re NUREG-073/, Items II F 1 4, II F 1 : II F 1 6 concerning accuracies & time responses of containment post-accident monitoring equipment & placement of hydrogen monitor intake ports, per 821112 request STEMART.W L Virginia Electric & Power Co 82/12/21 DENTON, H Olfice of Nuclear Reactor Regulation, Director 8pp 16562 096 24X Fiche 50-338,82/12/21,8212280201
- B/12280257 Forwards remittance for Invoice B-0063 for review of Amend 4 to Topical Rept VEP-1. "OA Program Operations Phase." submitted on 820921 & approved on 821006 STEWART.H L Virginia Electric & Power Co 82/12/22 DENTON.H R Office or Nuclear Reactor Regulation. Director BARRY,L W Division of Accounting 1p 16561 269 24X Fiche 50-000.82/12/22. ecion, Director BARRY, L W Division 24X Fiche 50-000,82/12/22 of Accounting 8212280257
- G. Inspection reports. IE Builetins & correspondence
- B20B190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall Large-Diameter: Stainless Steel, Recirculation Sys Piping of BRR Plants "Syc list enci DEVOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consuldated Edison Co of New York, Inc 112pp 14462 163 24% Fishe 50-000, 82/10/28, 820B190240
- 8/12090285 Advises that SALP Repts 50-280/82-19.50-281/82-19.
 50-338/82-24 & 50-339/82-24 have been reviewed & approved diverall performance adequate No reply required O'REILLY.J P Region 2, Office of Director 82/11/03 LEASBURD.R H Virginia Electric & Power Co 2pp 16365 208 24X fiche 50-000.82/11/03.8212090285
- --B212090298 Forwards SALP Repts 50-280/82-19.50-281/82-19.50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 LEMIS, R. C. Division of Project & Resident Programs 62/08/04 LEASBURG, R. H. Virginia Electric & Power Co. 2pp. 16365 210 24X Fiche 50-000, 82/11/03, 8212090285
- --8212090306 SALP Repts 50-220/82-19,50-281/82-19,50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 Increased mgt attention should be directed towards plant operations & operational OA Region 2, Office of Director 82/08/04 31pp 16365 212 24X Fiche 50-000.82/11/03.8212090285
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thernoluminescent Dosimeters " Svc list

encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 02/11/05 Consolidated Edison Co of New York, Inc. 110pp 14372 142 24x Fiche 50-000, 82/11/05, 82081 90245

- 6:12090515 Forwards IE Insp Repts 50-338/82-36 * 50-339/82-36 on
- -8212090521 IE Insp Repts 50-338/82-34 & 50-339/82-36 on 821018-22 No noncompliance noted Hajor areas inspected QC & confirmatory measurements, including lab QC program chemical & commenced to the program chemical procedures & airborne effluent sempling EVANS.C D MONTGOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/08 9pp 16366 274 24X Fiche 50-338,82/11/09,8212090515
- GP12090478 Ack receipt of 821103 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-32 & 50-338/82-32 & DANCE, H C Division of Project & Resident Programs 82/11/12 SIEMART, H L Virginia Electric & Power Co ip 16365 314 24X Fiche 50-338, 82/11/12, 8212070478
- --8212070485 Responds to NRC 821005 ltr re violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32 Corrective actions chemistry periodic test for dose equivalent I-131 level revised to require deviation rept if limit exceeded STEWART.W L Virginia Electric & Power Co. 82/11/03 O'REILLY, J.P. Region 2, Office of Director. 3pp. 16365-315 24X Fiche 50-338,82/11/12.8212090478
- --8212090491 Forwards IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 & notice of violation DANCE.H C Division of Project & Resident Programs 82/10/05 LEASBURG.R H Virginia Electric & Power Co 2pp 16365 318 Fiche 50-338,82/11/12,8212090478
- --B212070496 Notice of violation from inspin 820713-17

 * Division of Project & Resident Programs 82/10/16365 320 24% Fiche 50-338,82/11/12,8212070478 62/10/05

- --B212090505 IE Insp Repts 50~338/82-32 A 50-339/82-32 on 820913-17 212090505 IE Insp Repts 20-338 82-32 & 50-339788-32 on days on Noncompliance noted failure to rept reactor coalant dose equivalent I-131 level in excess or Tech Spec limit WRAY, JR, BARR, KP Division of Engineering & Technical Programs (B2/10/04 6pp 16365 321 24% Fiche 50-336, 82/11/12, 8212070478
- BP08190251 IE Info Notice B2-44, "Clarification of Emergency Plan (sercise Requirements " Svc list encl JORDAN,E L Division or Engineering * Quality Assurance 82/11 Consolidated Edison Co of New York, Inc. 107pp 164t1 179 (sche 50-000, 82/11/18, 8208190251
- G212090161 Confirms 821129 meeting w/util in Atlanta. GA to discurs issults or investigation re causes of repeated main electrical output transformer failures Proposed agenda encl O'REILLY, J.P. Region 2. Office of Director 92/11/24 STEWART, Virginia Electric & Power Co. 2pp. 16359 OFB. 243 Fiche 50-338. 82/11/24. 8212090161 STEMARY, U. I.
- By08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYBUND, R C Director's Office of Inspection and
 Inforcement B2/11/26 Consolidated Edison Co of New York, Nic
 127pp 16481 065 24X Fiche 50-000,82/11/26,8208190256
- 82/08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities, Materials & Sareguards 02/11/30 Consolidated Edison Co of New York, Inc 354pp 16587 028 24% Fiche 50-000.82/11/30.8208190257
- B0712702 16335 011
- --8212070206 IE Safeguards Insp Repts 50-338/82-38 % 50-339/82-38 øw Programs B2/12/01 ip 16335 013 24X Fiche 50-338,82/12/0/.
- 8:08190259 IE Sulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUMO,R C Director's Office, Office of Inspection and Inforcement 82/12/03 Consolidated Edison Co of New York, lic Il3pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- GPOB190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list ancl JCRDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000.82/12/03.8208190261
- GPOB190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, lnc 127pp 16628 191 24X Fiche 50-000, 82/12/16.8208190247
- BPOB19026B IE Info Notice B2-50, "Mod of Solid State AC Undervoitage Relays Type ITE-27" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance B2/12/70 Consolidated Edison Co. of New York, Inc. 108pp 1662B 290 24X Fiche 50-000, B2/12/20, 820B19026B
- R Periodic operating reports & related correspondence
- GP12290317 Forwards monthly operating repts for Oct 1982 STEMART, W.L. Virginia Electric & Power Co. 82/11/10 M Uffice of Resource Management, Director ip 16589 143 Fiche 50-338, 82/11/10, 8212290317 HALLER, N. N.
- --8212290318 Monthly operating repts for Oct 1982 SCHMITENDORF, G Virginia Electric & Power Co 16587 144 24X Fiche 50-338,82/11/10,8212290317 82/11/01 1000
- S Reportable occurrences, LERs & related correspondence
- 87:2090112 Forwards LER 82-048/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 82/11/30 O'REILLY, J P Region 2, Office of Director 1p 16357 274 Fiche 50-338, 82/11/30, 8212090112

```
#212090115 LER 82-069/03L-0 on 821102 charging pumps & boric acid
                                                                                                                                                                                                                              --8212210147 LER 82-073/03L-O on 821118,B reactor trip breaker failed to auto open on simulated reactor signal Caused by stuck undervoltage tripping mechanism Device removed, cleaned, lubricated & reinstalled CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/13 Region 2. Defice of Director 2pp. 16485-173 24X Fiche 50-338, 22/14/18 03/1820147.
           2) 2090;15 LER 82-065/04.-0 on 82102-charging pumps & boric at 
floupaths rendered inoperable Caused by maint on charging 
pump C normal suction valve MGV-1270A which required removal 
of alive bonnet Valve bonnet replaced 
CARTHRIGHT.NR Virginia Electric & Power Co 82/11/30 
2) Orfice or Director 2pp 16357 277 24X Fiche 50-338. 
82/11/30, 8212090112
                                                                                                                                                                                                                                           82/12/13,8212210137
12090353 Forwards LER 82-072/03L-0
CARTURIGHT.N R Virginia Electric / Power Co 82/12/01
O'REILLY, J P Region 2. Office of Director 1p 16357 348
Fiche 50-338,82/12/01.8212090063
                                                                                                                                                                                                                              SP12210163 Forwards LER 82-077/03L-0
CARTWRIGHT.W R Virginia Electric 5 Power Co 82
U'REILLY,J P Region 2. Office of Director 1p
Liche 50-038.82/12/13.8212210163
                                                                                                                                                                                                                                                                                                                                                                           62/12/13
 3212090044 LER 82-072/03L-0 on 821115. while testing heat detectors,
                                                                                                                                                                                                                              --B212210171 LER 82-077/03L-0 on 821119.MOV-1536 could not be opened after period test Caused by loose control cable connection at motor operator Loose connection tightened CARTHRIGHT.WR Virginia Electric & Power Co. 82/12/13 Reg. 2. Office of Director 2pp 16484 306 24X Fiche 50-338.
          212090064 LER 82-072/03L-0 on 821115 while testing heat detering high pressure carbon dioxide sys automatic actuation valves failed to operate Caused by preumatic actuation devices being mechanically bound Devices closned CARTHRIGHI, W.R. Virginia Electric & Power Co. 82/12/01 & 0.00 prector gpp. 16057 049 24% Fiche 50-33B, 82/12/01.8212090063
                                                                                                                                                                                                                                                                                                                                                                                                                        Region
                                                                                                                                                                                      Region
                                                                                                                                                                                                                                           82/12/13, 8212210163
                                                                                                                                                                                                                              87/12220244 Forwards LER 92-078/03L-0
GARTWRIGHT, W R Virginia Electric & Power Co 82
O'REILLY, J P Region 2, Office of Director (p
Fiche 50-038, 82/12/15, 8212220244
 12090527 Forwards LER 82-071/031-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/01
O'REILLY, J.P. Region 2, Defice of Director. 1p. 16366-129
                                                                                                                                                                                                                                                                                                                                                                            82/12/15
 rehe 50-338,82/12/01,8212090527
                                                                                                                                                                                                                                          ...EEEUZOO LEN M2-0/B/O3L-O on 821125, in Mode 3,120-volt ac vital bus 1-1V lost voltage Caused by failure of normal power supply inverter 1-VD-1-04 dus to failed oscillator board, transformer & fuse Parts replaced & snverter tested CARTHRIGHT NR Virginia Electric & Power Co 82/12/15 Regian 2, Office of Director 1p 14517 193 24X Fiche 50-338,82/12/15,8212220244
                                                                                                                                                                                                                               --8212220268 LER 82-078/03L-0 on 821125, in Mode 3,120-volt at vital bus
 #212090538 LER 82-071/03L-0 on 821105.8 inside recirculation spray
           pump (1-RS-P-1B) did not operate within required time during functional testing Caused by drift in actuation timer
           setting Tiner readjusted & refested
CARTHRIGHT.W R Virginia Electric & Power Co 82/12/01
2. Office of Director 2pp 16366 130 24X Fishe 50-338.
                                                                                                                                                                                                                                                                                                                                                                                                                       Region
           FIZ/12/01, 8212090527
                                                                                                                                                                                                                              B:12220399 Forwards LER 82-079/00L-0
CARTWRIGHT, W R Virginia Electric & Power Co 62/12/15
O'REILLY.J P Region 2. Office of Director 19 16504 285
fiche 50-338, 82/12/15,8212220399
  12150191 PNO-11-82-132 on 821205, main transformer 8 found leaking
 1 21 30131 FRO-11-02-132 on occasion, main transformer brown teating of 11-resoluting in severe mechanical damage to transformer case & melting of neutral bus duct Cause under investigation Transformers will be replaced JULIAN, C A. DANCE, H C. Region 2. Office of Director 82/12/06 Ppp 16425 226 24X Fiche 50-338, 82/12/06, 8212150151
                                                                                                                                                                                                                               --B212220408 LER 82-079/03L-0 on 821126, in Mode 3, flow path from boric
                                                                                                                                                                                                                                         212220408 LER 82-01703.-0 oh 821126. In Nooe 3.flow path from acid tanks to RCS inoperable Caused by ruptured disphragm or borst acid transfer pump suction header isolation valve 1-CH-60 Valve diaphragm replaced CARTHRIGHT.H R Virginia Electric & Power Co 82/12/15 2. Office of Director 2pp 16504 286 24% Fiche 50-338. 82/12/15.8212220377
 | ≥ 100020 rorwards LER 82-074/03L-0

CARTHRIGHT W R Virginia Electric & Power Co 82/12/08

D'REILLYJ P Region 2, Office of Director ip 16421 007

Fiche 50-338, 82/12/08.8212130029
  12150026 Forwards LER 82-074/03L-0
                                                                                                                                                                                                                                                                                                                                                                                                                       Region
     1 che 50-338, 82/12/08, 8212150028
 B212150034 LER 82-074/03L-0 on 821117 protection Channel I overtemp
delta T 'c overpower delta T placed in trip rendering channel
inoperable Caused by T-hot NRA card (TM-412M) failure
                                                                                                                                                                                                                              GPI2220410 Forwards LER 82-070/03L-0
CARTHRIGHT.W R Virginia Electric & Power Co 82/12/16
U'REILLY, J P Region 2. Office of Director 1p 16503 245
Fiche 50-338, 82/12/16, 8212220410
           Channel recalibr
CARTURIGHT, W.R. Virginia Electric & Power Co. 82/12/08 Region
2. Office of Director (p. 1642) 008 24% Fiche 50-338,82/12/08.
                                                                                                                                                                                                                              --8212220416 LER 82-070/03L-0 on 821116 & 28. head tracing circuits ET-117N & ET-116N failed reducing piping temp below 149 F Cause of 921116 event not stated Failure on 821128 caused by loose insulation failed channel replaced & insulation added CARTMRIGHT, W.R. Virginia Electric & Power Co. 82/12/16 Rt. 2. Dffice of Director 2pp. 16503 246 24X Fiche 50-338, 82/12/16,8212220410
 J 2150074 Forwards LER 82-075/03L-0

CARTKRIGHT, WR Virginia Electric & Power Co 8

1 TREILLY, J P Region 2, Office of Director 1p

1 iche 50-338, 82/12/08, 82(2150074
                                                                                                                                        82/12/09
                                                                                                                                                                                                                                                                                                                                                                                                                    Region
                                                                                                                                                  16430 352
#3212150076 LER 82-075/03L-0 on 821117, individual rod position indicator for rods 8-10 in control bank A.D-4 in control bank C & N-7 in shutdown bank A deviated from group demand position w/no rod motion Caused by instrument drift Channels recalibr CARTHRIGHT, W R Virginia Electric & Power Co 82/12/08 Region 2. Office of Director 2pp 16430 353 24X Fiche 50-338, 62/12/08.8212150074
                                                                                                                                                                                                                             BP12300126 Forwards LER 82-080/03L-0
CARTWRIGHT.W R Virginia Electric & Power Co 82/12/20
O'REILLY, J P Region 2. Office of Director 1p 16598 257
                                                                                                                                                                                                                                    Fiche 50-338, 82/12/20, 8212300126
                                                                                                                                                                                                                              --8212300130 LER 82-090/03L-D on 821128.while in Mode 3.containment
                                                                                                                                                                                                                                         electrolido Lek W2-090/05-0 on Bellad, unile in moce 3, contain isolation syr air valve found open & unattended Cause unknown Valve closed & locked investigation underway CARTWRIGHT. W R Virginia Electric & Power Co 82/12/20 2, Office of Director 3pp 16598 258 24X Fiche 50-338, 82/12/20, 8212300126
 J 2200027 Forwards LER 82-069/03L-0
CARTERIGHT. W R Virginia Electric & Power Co 8:
O'REILLY, J P. Region 2. Office of Director 1p
                                                                                                                                                                                                                                                                                                                                                                                                                       Region
                                                                                                                                          82/12/09
                                                                                                                                                 16474 034
                                                                                                                                                                                                                             82:12300217 Forwards LER 82-082/01T-0
CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/20
O'REILLY, J.P. Regian 2. Office of Director 1p. 16597 353
Ficha 50-338, 82/12/20, 8212300217
 □⊇12200037 LER 82-069/03L-0 on 821110, in Mode 5, pressurizer PORV
         Previously blocked open found closed Caused by PDRV block
not adequately secured during installation Block
Teinstalled
CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/09
22. Office of Director 4pp. 16474-039 24X Fiche 50-338,
62/12/09.8212200027
                                                                                                                                                                                                                              --8212300220 LER 82-082/01T-0 on 821206, both trains of automatic safety injection blocked for 22 h & 30 minutes following inadvertent safety injection Caused by emergency procedure which misled operators Procedure revised CARTWRIGHT, W R Virginia Electric & Power Co 82/12/20, Region 2, Office of Director 3pp 16597 354 24X Fiche 50-338, 82/12/20,82/32002/2
 12150103 PND-11 82-132A updates 821205 failure of main transformer
Extensive damage occurred in main generator Generator

Si tassembled for detailed insp Stator winding damage

Si tassembled for detailed insp Stator winding damage

Si tassembled for Region 2. Offsce of Director

B2/12/10

PP 16430 358 24X Fiche 50-338, 82/12/10,8212150103
                                                                                                                                                                                                                                          62/12/20.8212300217
                                                                                                                                                                                                                             8212300171 Forwards LER 82-081/03L-0
CARTWRIGHT, W R Virginia Electric & Power Co B2
O'REILLY, J P Region 2, Office of Director ip
Fiche 50-338,82/12/21.8212300171
                                                                                                                                                                                                                                                                                                                                                                            82/12/21
                                                                                                                                                                                                                                                                                                                                                                                    14598 092
                                                                                                                                                                                                                                                                                                                                                                                                                       24X
 토론10137 Forwards LER 82-073/03L-0
 CARTHRIOHT.W R Virginia Electric & Power Co Bi
CARTHRIOHT.W R Virginia Electric & Power Co Bi
REILLY, J P Region 2. Office of Director ip
1 che 50-338,82/12/13,8212210137
```

82/12/13

16485 172 24X

- --8212300177 LER 82-081/03L-0 on 821203.svc water supply header A to Units 1 & 2 charging pump lube oil coolers & air compressors isolated to repair pinhole leak Caused by corrosion Affected piping cut out % replaced CARTHRIGHT.NR Virginia Electric & Power Co 82/12/21 Region 2: Office of Director 3pp 16598 D93 24X Fiche 50-338, 82/12/21.8212300171
- 8212300313 Forwards LER 82-090/03L-0 CARTWRIGHT.H R Virginia Electric & Power Co 82/12/21 O'REILLY, J P Region 2, Office of Director 1p 16594 213 24X Fiche 50-338,82/12/21,5212300313
- --0212300315 LER 82-090/03L-0 on 821205.3A auriliary feedwater pump removed from svc to determine cause of overcurrent flag drops on A & C phase Cause not determined Flags reset & mator bridged & meggered w/o discrepancies CARTWR18HT.W R Virginia Electric & Power Co 82/12/21 Region 2. Office of Director 2pp 16594 214 24X Fiche 50-338, 82/12/21,8212300313
- 8212300232 Forwards LER 82-084/09L-0 CARTHRIGHT, W R Virginia Electric & Power Co 82/12/22 O'REILLY, J P Region 2, Office of Director 1p 16598 018 24X Fische 50-338, 82/12/22,8212300232
- --8212300238 LER 82-084/03L-0 on 821205, at 20% power, channels FI-1475 & FI-1485 for steam generators A & B steam flow showed below actual flow Caused by transmitter for FI-1475 & multiplier/divider/square root for FI-1485 being out of callbr CARTHRIGHT. WR Virginia Electric & Power Co 82/12/22 Region 2, Diffice of Director ip 16598 019 24% Fiche 50-338,82/12/22,8212300232
- E212300245 Forwards LER 82-087/03L-0 CARTMRIGHT, W R Varginia Electric & Power Co 82/12/22 D'REILLY, J P Region 2. Office of Director 1p 16595 244 24X Fiche 50-338,62/12/22,8212300245
- --B212300247 LER 82-087/03L-0 on 821205, during Mode 1, individual RPI for rod M-02 in control bank D deviated from group demand position by greater than 12 steps w/no rod motion Caused by instrument drift RPI channel recalibr & returned to svc CARTWRIGHT, W R Virginia Electric & Power Co 82/12/22 Region 2. Defice of Director 2pp 14575 245 24X Fiche 50-338, 82/12/22,8212300249
- 0212300261 Forwards LER 02-071/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 02/12/22 O'REILLY,J P Region 2. Office of Director ip 16595 208 24X Liche 50-338, 02/12/22, 0212300261
- --8212300267 LER 82-091/03L-0 on 821207, during Mode 4, pressure in nitragen reservoir 8 for pressuriter PORV (PCV-1455C) dropped below min Caused by excessive nitragen leakage through nitragen reservoir 8 relief valve Valve repaired CARTHRIGHT. W R Virginia Electric & Power Co 82/12/22 Region, 2, Office of Director 2pp 16975 207 24% Fiche 50-338, 82/12/22, 8212300261
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- GP12070195 Forwards IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-39 on 821108-10 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 82/12/02 STEMATIN L Virginia Electric & Power Co 2pp 16335 011 24X Fichs 50-338,82/12/02,8212070195
- --8212070206 IE Safeguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted Major areas inspected security plan & implementing procedures organization, audit & power supply Details withheld (ref 10CFR73 21) STANSBERRY, W W Division of Engineering & Technical Programs 82/12/01 ip. 16335 013 24X Fiche 50-338,82/12/02,8212070195
- BP12090419 Forwards add1 info re status of emergency response Facilities locations & const. supplementing 810401 & 820408 ic it # 81-10 transmitting NUREG-0496, per
 - ic & Power Co 82/12/06 DENTON, H R Plation, Director 2pp 16364 276 190419
 - y drawings Drawings withheld
 - _ Power Co 82/12/09 DENTON, H R ition: Director 1p 16427 362 24

- SPJ21700R4 Forwards request for add1 info re security training & qualification plans.per util 820917 ltr
 CLARK.R A Operating Reactors Branch 3 82/12/13 BTEWART.W L
 Virginia Electric & Power Co 4pp 16480 335 24X
 Fiche 50-000, 82/12/13, 8212170024
- E2/2270179 informs that although 82:209 ltr forwarding security drawings failed to contain safeguards statement drawings were properly secured marked & identified as safeguards info STEMART. W.L. Virginia Electric & Power Co. 82/12/20 DENTON.H & Office of Nuclear Reactor Regulation, Director ip 16539-010-21% (sich 50-000, 82/12/20, 82/2270179
- 9 Adjudicatory correspondence
- B212070139 Notice of B30216 special prehearing conference in Bothesda. ND to permit key issue identification, to consider intervention petitions & to establish schedule for further actions
 WOLFE, S. J. Atamic Safety and Licensing Board Panel B2/12/03 bp. 16327 023 24X Fiche 50-338, 82/12/03, 8212070139
- G2]2070147 Notice of 820216 special prehearing conference in Bethesda, HD to permit key issue identification to consider intervention petitions & to establish schedule for further actions WDLFE.8 J Atomic Safety and Licensing Board Panel 82/12/03 5pp 16327 074 24X Fiche 50-338, 82/12/03.8212070147
- B212070236 Memorandum memorializing B21202 telcon w/util, Concerned Citizens of Louisa County, Louisa County & Board of Eurpervisors & NRC re-scheduling special prehearing conference WOLFE, B J Atomic Safety and Licensing Board Panel 82/12/03 4pp 16329 313 24X Fiche 50-338.82/12/03.8212070236
- BP12100104 Objects to B90117 deadline for submittal of contentions Deadline hampers identification of valid contentions A increases likelihood of burdening proceeding due to submittal of unreviewed contentions COLEMAN, J M Beveridge, Fairbanks & Diamond COLEMAN, J M Louiza County, VA 82/12/07 MOLFE, S J Abomic Safety and Licensing Board Panel 3pp 16379 113 24% Fiche 50-338, 82/12/07, 8212100104
- B212140245 Motion to stay proceedings on applications for license amends to allow receipt & storage of Surry spent fuel Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc encl COLEMAN, J M Louisa County, VA COLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 316 24X Fiche 50-336, 82/12/10, 8212140245
- B:/12140249 Motion to stay proceedings on applications for license amends to expand spent fuel pool Proceeding should be stayed until Commission completes waste confidence proceeding Certificate of Svc ancl CQLEMAN, J M Beveridge, Fairbanks & Diamond 82/12/10 Commissioners 8pp 16409 308 24% Fiche 50-338, 82/12/10, 8218140249
- G212280122 Answer in opposition to Louisa County, VA 821210 motion for stay of proceeding until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc encl MAUPILM M Virginia Electric & Power Co. 82/12/22 Commissioners 10pp 16564 124 24X Fiche 50-338,82/12/22, B212280122
- --0212280130 Affidavit of ML Smith re transshipment of spent fuel Unless VEPCO can secure addl storage space for Surry spent fuel. Surry will lose full discharge capability SMITH.M.L. Virginia Electric & Power Co 82/12/21 App 16544 134 24X Fiche 50-338,82/12/22,8212280122
- G:12280135 Answer in opposition to Louisa County, VA 821210 motion for stay of proceeding until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice witl Certificate of Svc encl MAUPIN.M W Virginia Electric & Power Co 82/12/22 Commissioners 10pp 16556 117 24% Fiche 50-338,82/12/22, 8212280135

т 4

8212270001 Response in opposition to Louisa County, VA motions to stay proceedings until completion of waste confidence rulemaking Delay would be inconsistent w/NRC regulations & would prejudice util Certificate of Svc enc!
TREBY, 8 A Hearing Branch I 82/12/27 Atomic Safety and Licensing Board Panel Spp 16583 248 24X Fiche 50-338,82/12/27,8212270001

- P Operating license stage documents & correspondence
- 0212020391 Forwards requests for add1 info re NUREQ-0737. Items
 11 F 1 4.5 & 6 concerning containment pressure, water level &
 hydrogen monitors Response requested within 30 days
 CLARK.R A Operating Reactors Branch 3 82/11/12 STEWART. W L
 Virginia Electric & Power Co 9pp 16/308 134 24X
 Fiche 50-338.82/11/12.8212020391
- GP12060284 Notifies that neither facility has add1 Tech Specs to be submitted in response to Generic Ltr 82-16 re status of NUREO-0737 Items
 STEWART IL Virginia Electric & Power Co 82/12/01 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 1p 16312 058 24X Fiche 50-000, 82/12/01, 8212060284
- 0212130326 Lists as-found ring settings & EPRI as-left ring settings for plant relief & safety valves As-found settings will provide acceptable performance As-left settings add increased conservatism to valve performance STEMART.W L Virginia Electric & Power Co 82/12/07 DENTON.H R Office of Nuclear Reactor Regulation, Director E EISENHUT,D G Bivision of Licensing 2pp 16387 327 24X Fiche 50-338.82/12/07, 8312130324
- 8./1215004B Application to amend Licenses NPF-4 & NPF-7.allowing optimisation of core loading patterns & providing additionable to the state of the
- --6212150052 Proposed Tech Specs allowing optimization of core loading patterns & providing additoperating flexibility * Virginia Electric & Power Co 82/12/08 21pp 16422 302 247 Fiche 50-338.82/12/08.8212150048
- GPOB190263 Generic Ltr B2-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science
 Applications inc draft rept re subj requirements Comments squested within 30 days of itr Svc list encl
 EISEM-UT, D G Division of Licensing 62/12/09 Consolidated
 Ldison Co of New York, Inc. 29pp 16629 247 24X
 fiche 50-000, 82/12/09,8208190263
- 8/12140103 Generic Ltr 82-28 to all licensees of operating Hestinghouse & C-E PHRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl LISENHUT, D G Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000, 82/12/10, 82/12/40103
- 8:/12210187 Responds to NRC comments on conclusions & recommendations re NUREG-0612, "Control of Heavy Loads," per 821022 telcon 5TEWART. W.C. Virginia Electric & Power Co. 82/12/15 DENTON, H.R. Uffice of Nuclear Reactor Regulation, Director CLARK, R.A. (Iperating Reactors Branch 3 4pp 16484 347 24% [1che 50-338,82/12/15,8212210187]
- 8212270407 Trip rept of 821129 visit to Region 2 ofc re investigation into latest Hestinghouse main transformer fault to occur at facility LNGLE.L 3 Operating Reactors Branch 3 82/12/17 CLARK.R H Uperating Reactors Branch 3 5pp 16555 353 24X Fiche 50-338.82/12/17.8212270407
- 8/12270490 Trip rept of 821209 briefing at site re 821205 main transformer fault resulting in turbine & reactor trip (ause undetermined Plant extensively damaged Task force organized to monitor util investigations

 LNOLE.L B Operating Reactors Branch 3 82/12/17 CLAR,R A Operating Reactors Branch 3 12/12/17 Branch 3 12/12/17, 8212270490
- 8:12290248 Application to amend Licenses NPF-4 & NPF-7 changing radiological effluent Tech Specs to delete radiological sampling monitoring & reporting requirements in accordance w/NUMES-0472, Revision 3 STEWART.W L Virginia Electric & Power Co 82/12/17 DENTON.H & Uffice of Nuclear Reactor Regulation, Director CLARK,R A Uperating Reactors Branch 3 3pp 16588 034 24% Fiche 50-338,82/12/17,8212270248

- --8212290252 Proposed Tech Spec changes re sampling frequency of waste decay tank encl Justifications for deviations from NUREO-0472. Revision 3 encl

 * Virginia Electric & Power Co 82/12/17 252pp 16588 037 24% Fiche 50-338.82/12/17.8212270248
- U212290256 Process control program
 # Virginia Electric & Power Co #2/12/17 30pp 16589 095 24X
 Fiche 50-338,82/12/17,8212290249
- 8212280201 Forwards add1 info re NUREG-0737. Items II F 1 4, II F 1 5 & II F 1 6 concerning accuraties & time responses of containment post-accident monitoring equipment & placement of hydragen monitor intake ports, per 821112 request STEWART. W L Virginia Electric & Power Co 62/12/21 DENTON. H Office of Nuclear Reactor Regulation. Director 8pp 16562 096 24X Fiche 50-338,82/12/21,8212280201
- SHI2280259 Comments on second analysis of safety valve loop smals due to potential operability problems posed by draining scals per 820701 ltr Engineering & required mots on unit planned based on retention of safety valve loop scals STEMART, N.L. Virginia Electric & Power Co. 82/12/21 DENTON, H. R. Office of Noclear Reactor Regulation, Director EISENHUT, D.O. Division of Licensing 1p 16561 249 24% Fiche 50-339,82/12/21,8212280259
- BP12280257 Forwards remittance for Invoice B-0063 for review of Amend 4 to Topical Rept VEP-1. "GA Program Operations Phase." submitted on B20721 & approved on B21006 STEWART, M L. Virginia Electric & Power Co. B2/12/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip 16561 249 24X fiche 50-000, 82/12/22, 8212280257
- O Inspection reports. IE Bulletins & correspondence
- 87-0819-0240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel. Recirculation Sys Piping at BNR Plants "Syc list encl
 DEYDUNG. R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fichs 50-000, 82/10/28,8208190240
- 8212070285 Advises that SALP Repts 50-280/82-19, 50-281/82-19, 50-338/82-24 & 50-339/82-24 have been reviewed & approved Overall performance adequate No reply required O'REILLY, J.P. Region 2, Office of Director 82/11/03 LEASBURG, R.H. Virginia Electric & Power Co. 2pp. 16365-208 24X Jiche 50-000, 82/11/03, 8212070285
- --8212090298 Forwards SALP Repts 50-280/82-19,50-281/82-19,50-338/82-24 & 50-339/82-24 for Jul 1980-June 1981 LEWIS.R C Division of Project & Resident Programs 82/08/04 LEASBURG.R H Virginia Electric & Power Co 2pp 16365 210 24X Fichs 50-000,82/11/03,8212090285
- --8212070306 SALP Repts 50-280/82-17,50-281/82-17,50-338/82-24 & 50-337/82-24 for Jul 1780-June 1781 Increased mgt attention should be directed towards plant operations & operational OA Region 2, Office of Director 82/08/04 31pp 16365 212 24X Fiche 50-000,82/11/03,8212070285
- 82/08/90245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list onc!

 CORB.L. I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50-000.82/11/05.8208190245
- 8212090818 Forwards IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/11/09 LEASBURG.R H Virginia Electric & Power Co 2pp 16366 292 24X Fiche 50-338.82/11/09.8212090515
- --8212090521 IE Insp Repts 50-338/82-36 & 50-339/82-36 on 821018-22 No noncompliance noted Major areas inspected GC & confirmatory measurements, including lab GC program, chemical & radiochemical procedures & airborne effluent sampling EVANS.C D . MONTOOMERY, D M Division of Emergency Preparedness & Operational Support 82/11/09 9pp 16366 294 24% Fiche 50-338,82/11/09.8212090515

- 8212090478 Ack receipt of 821103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32
- DANCE H C Division of Project & Resident Programs 82/11/12 STEWART, W L Virginia Electric & Power Co 19 16365 314 24X Fiche 50-338, 82/11/12, 8212070478
- --8212070485 Responds to NRC B21005 itr re violations noted in IE Insp Repts 50-338/82-32 & 50-339/82-32 Corrective actions chemistry periodic test for dose equivalent I-131 level revised to require deviation rept if limit eiceded STEMART.H L Virginia Electric & Pouer Co B2/11/03 0'REILLY, J P Region 2, Office of Director 3pp 16365 315 24X Fiche 50-338.82/11/12.8212070478
- --8212090491 Forwards IE Insp Repts 50-338/82-32 & 50-339/82-32 on 820913-17 & notice of violation DANCE.H C Division of Project & Resident Programs 82/10/05 LEASBURG.R H Virginia Electric & Power Co 2pp 16365 318 24x Fiche 50-338.82/11/12.8212090478
- --8212090496 Notice of violation from insp on 820913-17 • Division of Project & Resident Programs 82/10/05 1 16365 320 24x Fiche 50-338.82/11/12-8212090478
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc 1:st encl JORDAN, E. E. Division of Engineering & Quality Assurance 82/11/18 Consolidates Edison Co of New York, Inc. 109pp 16411 199 24: Fiche 50-000, 82/11/18,8208190251
- 8212090161 Confirms 821129 meeting w/util in Atlanta.0A to discuss results of Investigation re causes of repeated main electrical output transformer failures Proposed agenda encl O'REILLY, J P Region 2. Office of Director 82/11/24 STEWART, W L Virginia Electric & Power Co 2pp 16359 098 24X Fiche 50-338.82/11/24.8212090161
- B20B190254 IE Info Notice 82-44. "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2711/24 Consolidated Edison Co of New York, Inc 127pp 14411 045 24X Fiche 50-000 B2/11/26.8208190254
- 82/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L 1 Division of Fvel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York. Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8212070195 Forwards IE Safaguards Insp Repts 50-338/82-38 & 50-339/82-38 on 821108-10 No noncompliance noted DANCE-N C Division of Project & Resident Programs 82/12/02 STEMART.N L Viginia Electric & Power Co 2pp 16335 011 24) Fiche 50-338,82/12/02.8212070195
- --B212070206 IE Safeguards Insp Repts 50-338/82-38 t 50-339/82-38 on 821108-10 No noncompliance noted Major areas inspected security plan & implementing procedures, organization, audit & power supply Details withheld (ref 10CPR73 21) STANSBERRY, M W. MCQUIRE, D R Division of Engineering & Technical Programs 82/12/01 1p 16335 013 24x Fiche 50-338,82/12/02,8212070195
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Bvc list encl DEYQUNO, R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Societs " Svc list enci JORDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidates Edison Co of New York, Inc. 110pp 16462 064 24x Fiche 50-000,82/12/03.8208190261
- BE08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267

- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Bivision of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Ciche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- G212270G17 Forwards monthly operating repts for Oct 1982 BTEMART,W L. Virginia Electric & Power Co. 62/11/10 HALLER.N M Office of Resource Management, Director 1p 16589 143 24X Fiche 50-338, 62/11/10, 8212270317
- --8212290318 Monthly operating repts for Oct 1982 86MMITEMODRE, G. Virginia Electric & Power Co. 82/11/01 10pp 16589 144 24X Fiche 50-338,82/11/10.8212290317
- S Reportable occurrences, LERs & related correspondence
- 8212090102 Forwards LER 82-072/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 82/11/29 O'REILLY, J F Region 2, Office of Director 1p 16357 307 4/1X Fiche 50-339, 82/11/29, 8212070102
- --B212090107 LER B2-072/03L-0 on 821105.blowdown trip valve TV-BD-2006 would not remain closed when manually closed Caused by closed position limit switch out of adjustment Limit switch can repositioned CARTHRIGHT, W.R. Virginia Electric & Power Co. B2/11/29 Region 2, Office of Director Ip 16357 308 24X Fiche 50-339,82/11/29.
- Bp12090067 Forwards LER 82-073/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 82/12/01 D'REILLY,J P Region 2, Office of Director 1p 16359 087 24X Fiche 50-339, 82/12/01,8212090067
- --8212090072 LER 82-073/03L-0 on 821108, channel A RCS subcooling monitor declared inoperable after erroneous readings observed Cause not determined Monitor reset & functioned property CARTHRIGHT. W R Virginia Electric & Power Co 82/12/01 Region 2, Office of Director 2pp 16357 088 24X Fiche 50-337, 82/12/01.8212090067
- 8P12090272 Forwards updated LER 82-013/03X-1 CARTWRIGHT,N R Virginia Electric & Power Co 82/12/01 O'REILLY,J P Region 2. Office of Director 1p 16365 305 24X Fiche 50-339, 82/12/01.8212090272
- --B2120902B7 Updated LER 92-013/03X-1 on 82030B, during periodic surveillance test, one diesel generator & one offsite power supply for emergency bus 2H became temporarily inoperable Caused by deficiency in procedure Periodic test changed CARTWRIGHT, W R Virginia Electric & Power Co B2/12/01 Repions 2, Offsice of Director 3pp 16365-306 24X Fiche 50-339, B2/12/01.82/32082372
- G212210254 Forwards LER 82-074/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 82/12/13 U'REILLY,JP Region 2. Office of Director 1p 16483 311 24X Fiche 50-339, 82/12/13.8212210254
- --8212210269 LER 82-074/03L-0 on 821122.during Mode 1.RP1 for rod C-7 in shutdown bank A deviated from group demand position by greater than 12 steps w/no rod motion (In 821123.similar event occurred on rod B-8 Caused by instrument drift CARTHRIGHT.WR Virginia Electric & Pawer Co 82/12/13 Region 2. Office of Director 2pp 14483 312 24X Fiche 50-339, 82/12/13.8212210254
- 8±12220387 Forwards LER 82-075/03L-0 CARTWRIGHT.N R Virginia Electric & Power Co 82/12/15 O'REILLY.J P Region 2. Office of Director 1p 16517 228 24x Fiche 50-339,82/12/15,8212220387
- --8212220391 LER 82-075/03L-0 on 821123, deita flux momentarily exceeded 3/ target band during performance of control rod operability periodic test Caused by movement of control rods into core 18 steps for control rod operability test CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/15. Rugion 2, Office of Director 2pp 16517 229 24X Fiche 50-339, 82/12/15,8212220387
- 8212220392 Forwards LER 82-081/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 82/12/15, O'REILLY,J P Region 2, Office of Director 1p 16504 288 24X Fiche 50-339,82/12/15,8212220392

- --B212220397 LER 82-081/03L-0 on 821206, breaker for MOV-SW-2010 discovered open Caused by inadvertent opening of circuit breaker perhaps due to narrow passage Breaker closed & valve control power verified CARTWRIGHT, W R Virginia Electric & Power Co 82/12/15 Region 2, Office of Director 2pp 16504 289 24X Fiche 50-339, 82/12/15,821220392
- G:12220364 Forwards LER 82-077/01T-0 CARTWRIGHT, W.R. Virginia Electric & Power Ca 82/12/16 O'REILLY, J.P. Region 2, Office of Director 1p 16517 170 24X Fiche 50-339, 82/12/16 8212220364
- --821222036B LER 82-077/01T-0 on 821206.monthly surveillance tests for power range channels discovered missing Caused by tests being indivertently marked off by instrument supervisor Tests completed satisfactorily CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/16 Region 2, Office of Director 2pp. 16517-171 24X Fiche 50-339, 82/12/16.8212220364
- --B212300241 LER 82-078/03L-0 on B21205, during Mode 1, containment average air temp exceeded 105 F Caused by temp increase of chilled water to containment air recirculation cooling coils due to temporary inoperability of mechanical refrigeration unit CARTWRIGHT, W R Virginia Electric & Power Co 82/12/21 Region 2, Office of Director 2pp 16575 278 24X Fiche 50-337, 82/12/21,8212300237
- UP12300099 Forwards LER 82-079/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 82/12/22 B'REILLY,J P Region 2, Office of Director 1p 16598 229 24X Fishe 50-339 82/12/22 8212300099
- --9212300104 LER 82-079/03L-0 on 821206.axial flux difference went less than 5% from target band for duration of 2 minutes Caused by personnel error during power increase from 30% to 60% Rods withdrawn 5 difference restored to within limits CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/22 Region 2. Office of Director ip 16578 230 24% Fiche 50-339.82/12/22, 8212300099
- 9212300251 Forwards LER 82-080/031-0 CARTWRIGHT, W.R. Virginia Electric & Power Co. 82/12/22 O'REICLY, J.P. Region 2, Office of Director. 1p. 16595-263 24X fiche 50-337, 82/12/22, 8212300251
- ~-0212300255 LER 82-080/03L-0 on 821206, during Mode 1, individual RPI for rod H-02 in control bank D deviated from group demand position by greater than 12 steps w/no rod motion Caused by instrument drift RPI channel recalibr & returned to svc CARTHARIOHT.W R Virginia Electric & Power Co 82/12/22 Region 2, Office of Director 2pp 16595 264 24X Fiche 50-339, 82/12/22,8212300251
- G:12300286 Forwards LER 82-082/03L-0 CARTWRIGHT, W Virginia Electric & Power Ca 82/12/22 D'REILLY, J P Region 2, Office of Director 1p 16594 220 24X Fishe 50-039, 82/12/22, 8212300286
- ---8212300291 LER 82-082/03L-0 on 821213, fire door 871-18 between 2H emergency diesel generator room & turbine bldg failed to latch & lock Caused by latch sticking Latch adjusted & lubricated Design mods pursued CARTHARIGHT, W.R. Virginia Electric & Power Co. 82/12/22 Region 2, Office of Director ip 16594 221 24X Fiche 50-337,82/12/22, 8212300286
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 95:11230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBHR. Big Rock Point. Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Swc list encl W/o stated encl EIBENHUT, D G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X fiche 50-000. 82/11/15, 8211230066
- B\$/12010147 Forwards Amend 45 to amended & substituted application for OL.consisting of Amend 45 to FSAR LANDGRAFIL C LeBosuf, Lamb. Leiby & MacRae 82/11/30. DENTIN, H R OFFIce of Nuclear Reactor Regulation, Director 1p 16858 203 24X Fiche 50-341.82/11/30.8212010147

- --8212010154 Amend 45 to amended & substituted application for OL, consisting of Amend 45 to FSAR HEIDEL, C.M. Detroit Edison Co. 82/11/24 ip. 16258 204 24X Fiche 50-341, 82/11/30. 8212010147
- BP12170042 Forwards Amend 2 to CPPR-B7.safety evaluation & notice of issuance & availability Amend reflects merger of MI Electric Cooperative, Inc into Wolverine Electric Cooperative, Inc EISEMHUT, D G Division of Licensing 82/12/01 TAUBER.H Detroit Edison Co Gpp 16478 013 24X Fiche 50-341.82/12/01.8212170042
- --8212170057 Amand 2 to CPPR-87, reflecting merger of MI Electric Cooperative, Inc. into Wolverine Electric Cooperative, Inc EISENMUT. D 0 Division of Licensing 82/12/01 2pp 16478 016 24% Fiche 50-341,82/12/01.8212170042
- -- B212170076 Safety evaluation supporting Amend 2 to CPPR-87 * Office of Nuclear Reactor Regulation, Director 82/11/26 Zpp 16478 018 24X Fich 50-341.82/12/01.8212170042
- --8212170084 Nutice of issuance & availability of Amend 2 to CPPR-87 YOUNGBLOOD, 8 J. Licensing Branch | B2/11/26 3pp 16478 020 24% Fiche 50-341,82/12/01.8212170042
- BP12100267 Submits table clarifying reactor bldg basemat capacity for torus uplift, por 821118 telcon Listed basemat capacity max for torus uplift after subtraction for hydrostatic & normal foundation loads W/o stated encl
 TAUBER, H Detroit Edison Co 82/12/03 KINTNER, L Division of Licensing ip 16376 145 24X Fiche 50-341,82/12/03,8212100267
- BP12100166 Forwards approved scope of independent design verification program, per B21029 request Cygna Energy Svcs program plan for independent design verification will be submitted on or before S21215 Approval of plan requested by B21222 TAUBER: H Detroit Edison Co B2/12/07 RISENMUT.D C Division of Licensing 15pp 16373 333 24X Fiche 50-341.82/12/07.8212100166
- BD12130303 Forwards Certificate of Svc certifying distribution of Amend 45 to DL application to listed officials & agencies on 821206 MATERS.B R Detroit Edison Co 82/12/09 Office of Nuclear Reactor Regulation, Director 3pp 16389 324 24X Fiche 50-341.82/12/09.6212130303
- G212270046 Summary of B21118 meeting w/util & NUS re environ qualification of safety-related electrical equipment KINTNER,L L Licensing Branch 1 82/12/13 Licensing Branch 1 18pp 16553 162 24% Fithe 50-341,82/12/13,8212270046
- GP12300311 Forwards "Independent Design Verification Program," per 821207 ltr Meeting w/Cygna.util & NRC scheduled for 821220 TAUBER.H Detroit Edison Co 82/12/14 EISENHUT.D 0 Division of Licensing ip 16594 308 24X Fiche 50-341,82/12/14.8212300311
- 8212300312 "Independent Design Verification Program" * Cygna Energy Services 82/12/14 114pp 16594 309 24X Fiche 50-341,82/12/14-8212300311
- 8;12290510 Bummary of 821201 meeting w/util re independent design verification program Util proposed verification of design of HKR sys, including svc water Schedule acceptable Viewgraphs encl KINTI(ER.L. Licensing Branch 1 82/12/15 Licensing Branch 1 18pp 16593 327 24X Fiche 50-341.82/12/15.8212290510
- 8P12270031 Trip rept of 820824-26 caseload forecast panel site visit re observation of status of const & util basis for currently scheduled completion date KINTRER.L. L. Licensing Branch 1 82/12/16 Licensing Branch 1 17pp 16553 165 24X Fiche 50-341.82/12/16.8212270031
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8P12090061 Discusses 820115 ltr re channel box deflection concern Previous commitment indicated in SER Suppl 2 will be modified to adopt Licensing Review Group II position w/ simpler method of friction testing Details encl TAUSER.H Detroit Edison Co 82/12/03 KINFRER.L Division of Licensing 3pp 16357 352 24X Fiche 50-241.82/12/03.8212090061
- F Security, medical, emergency & fire protection plans
- 8212220460 Informs that no changes to comments for individual emergency action levels under each emergency classification required Both sets of emergency action levels identical MARTIN. J B astelle Memorial Institute, Pacific Northweat Laboratory 82/11/08 KANTOR.F Emergency Preparedness Licensing Br (after 8011f 9 set IKE) ip 16504 237 24X Fiche: 50-341.82/11/08.8212220460

- G210150165 Forwards review of emergency action levels for Enrico Fermi nuclear power station MARTINI B gattelle Memorial Institute, Pacific Northwest Laboratory 82/10/05 PAGANG.F G EP Licensing Branch 15pp 16504 238 24X Fiche 50-341.82/11/08.8212220460
- 8.12140375 Forwards info re emergency operations facilities (EOF).per LL Kintner 821202 request Const of permanent primary EOF tamplete TAUBER.H Detroit Edison Co 82/12/06 YOUNGBLOOD.B J Licensing Branch 1 2pp 16401 008 24X Fiche 50-244:82/12/06.82/2140375
- S212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site (mergency operations facility NEPPLER. J G Region 3, Diffice of Director S2/12/16 (Componwealth Edison Co 3pp 16503 351 24X Fiche 50-000, B2/12/14, B2) 220306

6 Adjudicatory correspondence

- 8012020353 Appeals portion of ASLB 821027 initial decision denying Monroe County,MI 820827 petition to intervene Appeal made under 10CFR2 714(a), since extent of County appeal rights per 10CFR2 762 unclear MESTGVER, A T Monroe County, MI 82/11/08 Atomic Safety and Lizensing Board Panel Spp 162/8 010 24X Fiche 50-341.82/11/08, 6212020353
- 8d12010191 Disagrees w/NRC decision to treat Monroe County, HI 821108 Itr as appeal under 10CFR2 710a rather than under 2 762 NRC does not have authority to decide issues for ASLAB HILOCK.J R Minock.J MINDCK.J R Citizens for Energy & Lmployment 82/11/26 EILPERIN.S., MODRE.T S. & DITCHY, R.L. Atomic Safety and Licensing Appeal Panel 2pp 16258 109 24X Fiche 50-341,82/11/26.8212010191
- Bir12010207 Order directing D Hawall & persons from Citizens for Employment & Energy who dealt w/Howell to file affidavits on organization representation Affidavits due B21210 Time for util & NRC responses to show cause order extended SHBEMAKER.C J Atomic Safety and Cicensing Appeal Panel Citizens for Emergy & Employment 2pp (4258 001 24X Fiche 50-341.82/11/30.8212010207
- 8.12010216 Order granting Citizens for Employment & Energy 10 days after issuance of order to file brief supporting Monroe County, MI intervention appeal Monroe County request for extension of time to file exceptions denied 6HOEMAKER.C J Atomic Safety and Licensing Appeal Panel 82/11/30 Sp. 1638 007 244 Fiche 50-341.82/11/30 8212010216
- GF12070234 Erratum to ASLB 821029 initial decision Name of Voight should be changed to Voigt in cover page list of appearances t in Line 8 of Paragraph 80 MICHGLLIN.0 L Acomic Safety and Licensing Board Panel 82/12/03 p 16329 320 24X Fiche 50-341.82/12/03.8212070234
- BP12140377 Arfidavit of DE Howell re employment by & representation of Citizens for Employment & Energy Decision not to file proposed rindings of fact & conclusions of law made jointly w/KA Stegfried Certificate of Svc enc! MCMRLL.D E Citizens for Energy & Employment B2/12/08 App 16401 306 24X Fiche 50-341.82/12/08.9212140377
- G?'12140460 Affidavit of KA Siegfried D Howell had full authority from affiant & Citizens for Employment & Energy to make decisions ie legal representation of organization SIEGFRIED, A Citizens for Energy & Employment B2/12/08 fp 16405 030 24X Fiche 50-341,82/12/08,8212140460
- G2:12:40428 Response supporting Monroe County, MI appeal of ASLB 82:1029 memorandum & order denging County petition to intervene Good cause shown No other means of protecting County interest exists Certificate of Svc encl MINOCK, JR Citizens for Energy & Employment MINOCK, JR Ninock, J 82:712:710 Atomic Safety and Licensing Appeal Panel 12pp 16405 198 24X Fiche 50-341,82/12/10,82:12:40428
- 8212230211 Order rendering ASLB 821029 decision authorizing NRR to issue OL effective Full power license will not be issued until remaining unontested issues resolved CHILK, S.J. Office of the Secretary of the Commission 82/12/20 Epp 14511 030 24X Fiche 50-341,82/12/20,8212230211
- Bill 2230355 Response in opposition to Citizens for Employment & Energy response to ASLB S21122 order to show cause why appeal from S21029 initial decision should not be summarily dismissed for failure to file proposed findings W/Certificate of Svc VOIQT.H E Detroit Edison Co S2/12/22 Atomic Safety and Licensing Appeal Panel 9pp 16511 152 24X Fiche 50-341.82/12/22, S212230355

- 8/12280139 Response in opposition to Citizens for Employment & Energy CCEE 8/21121 answer to ABLAB 8/21112 order to show cause why CEE 8/21108 appeal to ASLB 8/21029 order should not be dismissed Certificate of Svc encl WOODHEAD.C P Hearing Branch 1 82/12/23 Atomic Safety and Licensing Appeal Panel 12pp 14563 191 24X Fiche 50-341, 9/2/12/23,8212280139
- 8212280191 Forwards ALAB-707, denying Monroe County, MI intervention petition & requiring NRR Director to consider petition as request for action under 10CFR2 204 MOODHEAD, CP Hearing Branch 1 82/12/27 PERRY, 8 Federal Emergency Management Agency 1p 16564 019 24X Fiche 50-341,82/12/27,8212280151
- ~-8212280156 Decision ALAB-707, denying Monroe County, MI intervention petition & requiring NRR Director to consider petition as request for action under 10CFR2 206 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 82/12/21 15pp 16564 020 24X Fiche 50-341, 82/12/27, 8212280151
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8212010147 Forwards Amend 45 to amended & substituted application for DL.consisting of Amend 45 to FSAR LANDRAFI. C LeBoeuf, Lamb. Leiby & MacRae 82/11/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 16258 203 2/4X Fiche 50-341.62/11/30.8212010147
- --8212010156 Amend 45 to amended & substituted application for OL, consisting of Amend 45 to FSAR HEIDEL, C M Detroit Edison Co 82/11/24 ip 16258 204 24X Fiche 50-341,82/11/30,8212010147
- --G212010163 Amend 45 to FSAR * Datroit Edison Co 82/11/30 408pp 14258 205 24X Fiche 50-341,82/11/30,8212010147
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel. Recirculation Sys Piping at BNR Plants " Syc list entl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24x Fiche 50-000.82/10/28, 8208190240
- 82/08/190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BO1 & Model BO2 Thermoluminescent Dosimeters " Svc list cnc! COBB.L I Division of Evel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000.82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Liercise Requirements " Svc list encl JARDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24: Fiche 50-000.82/11/18.8208170251
- BP12100198 Forwards IE Insp Rept 50-341/82-18 on 820901-1031 No noncompliance noted KNDP,R C Divysion of Project & Resident Programs 82/11/24 WELLS D A Detroit Edison Co 2pp 16376 204 24X Fiche 50-341,82/11/24,8212100198
- --8212100203 IE (nsp Rept 50-341/82-18 on 820901-1031 No noncompliance noted Major areas inspected licensee action on previous items, electrical conduit installation & insp activities, NRC/licensee mgt meeting, OL issuance & site visits LITTLE, B H , BYRON, P M , KONKLIN, J E Division of Project & Resident Programs B2/11/22 opp 16376 206 24% Fiche 50-341,82/11/24.8212100198
- B208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " 8vc list encl DEYOUNO,R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl. COBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYUUNO.R C Director's Office Office of Inspection and Enforcement 88/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche.50-000,82/12/03,8208190259

- 8208190241 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JCRDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Ca of New York, Inc 110pp 14462 064 24y Fiche 50-000, 82/12/03, 8208190261
- 8212170244 Forwards IE Insp Rept 50-341/82-14 on 820908-10 & notice of violation LITTLE, W 5 Division of Engineering & Technical Programs 82/12/03 WELLS D A Detroit Edison Co 2pp 16459 205 24X Fiche 50-341,82/12/03,8212170244
- 8212170247 Notice of violation from insp on 820908-10 LITTLE, H S Division of Engineering & Technical Programs 82/12/03 4pp 16459 207 24X Fiche 50-341,82/12/03,8212170244
- --8212170253 IE Insp Rept 50-341/82-14 on 820908-10 Noncompliance noted failure to follow procedures, establish & use deviation disposition requests & to take corrective actions NAIDU, K R . LITTLE, B H . WILLIAMS, C C Division of Engineering & Yechnical Programs 82/10/25 7pp 16459 211 24X Fiche 50-341,82/12/03,8212170244
- B&12170105 Confirmatory action ltr re deficiencies identified during review of large bare hangers previously installed & accepted by GC site contractors, per 821210 telcon Independent engineering organization will evaluate all deficiencies NDRELIUS, C E Division of Engineering & Technical Programs 82/12/10 WELLS, D A Detroit Edison Co 2pp 16452 334 24% Fiche 50-341, 82/12/10, 8212170105
- 8212230309 Notifies that listed drawings have been sent to G Hammer of Mechanical Engineering Branch & T Cook of EG&O to support review of inservice insp program for pumps & valves LUSIS.E Detroit Edison Co 82/12/15 LYNCH.D Office of Nucleur Reactor Regulation. Director ip 16511 124 24X Fiche 50-341.82/12/15.8212230309
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND, R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208170268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITC-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24x Fishe 50-000, 82/12/20, 8208170268
- S Reportable occurrences. LERs & related correspondence
- 8212210443 Interim Deficiency Rept 74 re sway strut paddic clamped rigid Initially reported on 820702 Training session conducted for QC & craft supervisory personnel revised Next rept will be sent by 830324 WELLS D A Detroit Edison Co 82/11/24 KEPPLER.J G Region 3, Office of Director 2pp 16489 200 24X Fiche 50-341,82/11/24,8212210443
- B212270359 Interim deficiency rept re frozen reactor mode switch 73 & failure of contacts to maintain position during operation Initially reported on 820701 Switch modified Qualification work for switch handle in progress Next rept due by 830324 WELLS:D A Detroit Edison Co 82/11/24 KEPPLER.J G Region 3, Office of Director 2pp 16530 008 24x Fiche 50-341,82/11/24. 8212270359
- 8212270362 Interim deficiency rept re linear indications noted on Class I 5/8-inch stainless steel tee 50 fittings w/heat numbers 19 F & 43 F Initially reported on 820210 Tees removed & replaced Next rept will be submitted by 830325 HELLS, D A Detroit Edison Co 82/11/24 KEPPLER, J G Region 3, Office of Director 2pp 16530 010 24X Ficher 50-341,82/11/24,8212270360
- DOCKET 50-344 TROJAN NUCLEAR PLANT
- F. Security, medical, emergency & fire protection plans
- 8212140R80 Forwards 1982 radiological emergency plan exercise objectives & limitations BRUEHL,D J Portland General Electric Co 82/10/20 GRIMES,B K Division of Emergency Preparedness 6pp 16402 098 24X Fiche 30-344,82/10/20,8212140280
- 8212060384 Forwards 1E Insp Rept 50-344/82-30 on 821004-29 No noncompliance noted. STERNERO,D M Division of Resident, Reactor Project & Engineering Programs 82/11/15. WITHERS,B D Portland General Electric Co 4pp 16311 070 24X Fiche 50-344,82/11/15,8212060384

- --821206039: IE insp Rept 50-344/82-30 on 821004-29 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, security, environ monitoring & followup on LERs MALMROS, M H., DDDDS, R T. Division or Resident, Reactor Project & Engineering Programs 82/11/12 5pp 16311 074 24X Fiche 50-344,82/11/15.8212060384
- 8212140349 Requests NRC determination that records storage yault in technical support ctr may be used as security storage container for safeguards info documents CULP.0 H Portland General Electric Co 82/11/19 KASUN.D J Physical Security Licensing Branch 6pp 16401 026 24X Fiche 50-344.82/11/19.8212140349
- 8712210180 Forwards IE Emergency Preparedness Appraisal Rept 50-344/82-06 on 820222-0304 No noncompliance noted List of areas needing improvement encl ENGELKEN R H Region 5, Office of Director 82/12/02 WITHER's N D Portland General Electric Co 3pp 16485 032 24X Fiche 50-344.82/12/02.8212210180
- --8212210185 IE Emergency Preparedness Appraisal Rept 50-344/82-06 un 820222-0304 No noncompliance noted Major areas inspected administration of emergency preparedness emergency organization, training & retraining facilities & equipment FISH.R F , SCOKN.K , HANCHETT.J O Division of Radiological Safety & Safeguands Program 62/11/JO 39pp 16485 035 24X Fiche 50-344.82/12/02,8212210180
- 8212100399 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 82/12/07 Document Hanagement Branch ip 16389 197 24X Fithe 50-344.82/12/07. G212100399
- --B2121004i1 Public version of revised emergency plan implementing procedures; including Procedures EP-19 2 re operation of dedicated telephone sys & EP-29 1 re instructions for use of computer terminal YVMOTIC P Portland General Electric Co 82/11/18 20pp 16389 200 24X Fiche 50-344, B2/12/07, B212100379
- 8212170304 Forwards IE Safeguards Insp Rept 50-344/82-31 on 821129-1203 No noncompliance noted Rept withheld (ref IOCFR73 21)
 NORDERHAUG, L.R. Division of Radiological Safety & Safeguards
 Program 82/12/09 UITHERS, B. Portland General Electric Co
 Rpp 16456 129 24% Fiche 50-344,82/12/09,8212170304
- BP12210301 Forwards replacement Page 5-6a to security plan Section 5 2 1 2 1 Page withheld (ref 10CFR73 21) WITHERS B D Portland General Ejectric Co B2/12/13 CLARK, R A Operating Reactors Branch 3 1p 16484 337 24X Fiche 50-344,82/12/13,8212210201
- 8212270483 Forwards exemption from requirements of IOCFR50 48 & App R of IOCFR50 re fire protection for equipment important to safe shutdown & emergency lighting Safety evaluation supporting exemption encl CLARK.R A Operating Reactors Branch 3 82/12/14 WITHERS.B D Portland General Electric Co 4pp 16549 305 24X Fichs 50-344.82/12/14.8212270483
- --B212270486 Exemption from requirements of lOCFR30 4B & App R of lOCFR30 re fire protection for equipment important to safe shutdown & emergency lighting EISENKUT,D 0 Division of Licensing 82/12/14 Portland General Electric Co 13pp 16549 309 24% Fiche 50-344, 82/12/14.8212270483
- --8212270488 Safety evaluation supporting examption from 10CFR50.App R requirements
 * Office of Nuclear Reactor Regulation, Director 82/12/14
 21pp 16549 322 24X Fiche 50-344.82/12/14.8212270483
- --B206100047 Discusses request for exemption from requirements of Section III 0 2 of App R to 1GCFRSQ re intake structure, fuel bldg, auxiliary bldg, turbine bldg & cable penetration area outside containment COHN.8 M Gage-Babcock Associates. Inc 81/11/20 BENARGYA, V Chemical Engineering Branch, 10pp 16547 343 24X Fishe 50-344,82/12/14,8212270483

- P Operating license stage documents & correspondence
- G:/12030027 Forwards completed steam generator questionnaire.per 821026 request Outages, solely for steam generator-related maint, gccurred in 1979 & 1981 Remaining maint performed during scheduled refueling outages
 WITHERS.B D Portland General Electric Co 82/11/24 EISENHUT.D 0
 Division of Licensing App 16304 334 24X Fiche 50-344,82/11/24, 8212030027
- Officorogic Forwards "Trojan Nuclear Plant Cycle 5 Startup & Power (scalation Physics Testing Rept" WITHERS: B D Portland General Electric Co 82/11/30 ENGELKEN, R H Region 5, Office of Director ip 16337 074 24X (iche 50-344, 82/11/30, 9212070316
- --8212070319 "Trojan Muclear Plant Cycle 5 Startup & Power Escalation Physics Testing Rapt " * Portland General Electric Co POE-1035 82/11/30 58pp 16337 075 24X Fiche 50-344,82/11/30.8212070316
- Gi/12100044 Forwards add1 info requested on 821007 re inservice testing relief requests for pumps & valves
 WITHERS: B D Portland General Electric Co 82/12/03 CLARK, R A Operating Reactors Branch 3 21pp 16379 050 24X
 Fiche 50-344, 82/12/03. 8212100044
- B?:2130356 Forwards Amend 78 to License NPF-1, safety & technical evaluations & notice of issuance & availability Amend adds operability & surveillance requirements for reactor coolant overpressure mitigation sys CLARK, R A Operating Reactors Branch 3 82/12/06 WITHERS, B D Portland General Electric Co 3pp (6412 102 24X Fiche 50-344, 82/12/06, 8212130366
- --B212133367 Amend 78 to License NPF-1, adding operability & surveillance requirements for reactor coolant overpressure mitigation sys CLARK, R A Operating Reactors Branch 3 B2/12/06 17pp 16412 105 24X Fiche 50-244, 82/12/06.8212130366
- --G212130369 Safety evaluation supporting Amend 78 to License NPF-I * Office of Nuclear Reactor Regulation. Director 82/12/06 12pp 16412 122 24x Fiche 50-344.82/12/06.8212130368
- --8212(30370 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Low Temp Overpressure Protection Sqs for Trojan Nuclear Power Plant"

 LATORRE.V R. VICTOR.R A Lawrence Livermore Laboratory FIN A-0231 UCID-18670 80/06/30 NRC No Detailed Affiliation Given 26pp 16412 134 24X Fiche 50-344.82/12/06.8212130366
- --9212130372 Notice of Issuance & availability of Amend 78 to License NPF-1 CLARK, R.A. Operating Reactors Branch J 82/12/06 2pp 16412 159 24X Fichs 50-344, 82/12/06, 8212130366
- GP/08190263 Generic Ltr B2-32 to all PWR licensees re-potential steam generator-related generic requirements Forwards Ectence Applications, Inc draft rest re-sub, requirements Comments requested within 30 days of ltr Svc list encl EISEMHUT, D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 29pp 16629 247 24% Liche 50-000.82/12/09, 8208190263
- G:12140103 Generic Ltr 62-28 to all licensees of operating
 Westinghouse & C-E PWRs (except Arkansas Nuclear Dne:Unit 2
 & San Gnofre 2 & 3) re inadequate core cooling
 instrumentation sys Svc list encl
 EISE(MJT.D O Division of Licensing 82/12/10 Yankee Atomic
 Electric Co 27pp 16690 035 24x Fiche 50-000,82/12/10,
 62:2140103
- GP12280283 Forwards exceptions taken to NUREO-0737 requirements recontainment pressure monitors, water level monitors & hydrogen monitors, in response to 821112 request for additute.

 WITHERS, B D Portland General Electric Co 82/12/17 CLARK, R A Operating Reactors Branch 3 15pp 16561 312 24X

 Fiche 50-344, 82/12/17, 8212280283
- 82/12280410 Forwards SER & technical evaluation repts supporting environ qualification of safety-related equipment Plans for qualification or replacement of equipment in Categories 1 B. II A & II B should be submitted in 90 days CLARK.R A Operating Reactors Branch 3 82/12/17 WITHERS, B D Portland General Electric Co 3pp 16574 001 24X Fiche 50-344.82/12/17.8212280410

- --8212280419 SER supporting environ qualification of safety-related electrical equipment

 Defice of Nuclear Reactor Regulation, Director 82/12/17 5pp 16574 004 24X Fiche 50-344.82/12/17.8212280410
- --8210250187 "Review of Licensees Resolution of Outstanding Issues From MRC Equipment Environ Qualification SERs (F-11 & B-60), Trojan Nuclear Plant." final technical evaluation rept Proprietary info deleted PANDEY, S. Franklin Institute/Franklin Research Center NRC-03-79-116 TER-05257-485 82/10/19 LE.N B NRC No Detailed Affiliation Given 351pp 16574 009 24X Fichs 50-344,82/12/17.8212280410
- 8212280470 Forwards info re NUREO-0737, Items II D 3, "Post-Accident Sampling Capability" & III D 3 4, "Control Room Habitability," in response to NRC 820630 request W/seven oversize drawings Aparture cards are available in PDR WITHERS, B D Portland Goneral Electric Co 82/12/17 EISENHUT, D G Division of Licensing 25pp 16556 071 24X Fiche 50-344. 62/12/17,8212280470
- 6212270368 Forwards responses to NUREO-0737. Items II E 4 2 7, II K 2 10. II K 3 3, II K 3 12 & I A 1 3, per Generic Ltr 82-16 No add 1 Tech Specs requested HITHERS, B D Portland General Electric Co 82/12/21 EISENHUT, D G Division of Licensing 3pp 16530 046 24% Fiche 50-344,82/12/21, E01037036
- @ Inspection reports, lE Bulletins & correspondence
- 8:/08190240 IE Bulletin BR-O3, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/29 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 50-000, 82/10/28,8208190240
- 8708190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encil COB.L. I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000,82/11/05,8208170245
- B?120403B4 Forwards IE Insp Rept 50-344/B2-30 on B21004-29 No noncompliance noted STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 82/11/15 WITHERB, B D Portland General Electric Co 4pp 16311 070 24X Fiche 50-344.82/11/15.82120603B4
- --8212060391 IE Insp Rept 80-344/82-30 on 821004-29 No noncompliance noted Major areas inspected plant operations, surveillance testing, naint, security, environ monitoring & followup on LERs
 MALMROS, M H , PODDS, R T Division of Resident, Reactor Project & Engineering Programs 82/11/12 Spp 16311 074 24X
 Fiche 30-344,82/11/13.8212060384
- BP08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Liercise Requirements " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " 8vc list encl DEYGUND.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York. Inc 127p. 14411
- B:08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24% Fiche 50-000,82/11/30,8208190257
- 8212210180 Forwards IE Emergency Preparedness Appraisal Rept 50-344/82-05 on 820222-0304 No noncompliance noted List of areas needing improvement encl ENGELKEN.R H Region 5, Office of Director 62/12/02 WITHERS, B. D Portland General Electric Co 3pp 16485-032 24X Fiche 50-344.82/12/02.8212210180
- --8212210185 IE Emergency Preparedness Appraisal Rept 50-344/82-05 on 820222-0304 No noncompliance noted Major areas inspected. administration of emergency preparedness, emergency organization, training & retraining facilities & equipment FISH, R F , SCOWN, K , HANCHETT, J O Division of Radiological Safety & Safeguards Program 82/11/20 39pp 16485 035 24X Ficha 50-344,82/12/02.8212210180

- 8208190259 IE Builetin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 87/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000, 82/12/03, 8208190261
- 8212170304 Forwards IE Safeguards Insp Rept 50-344/82-31 on 821129-1203 No noncompliance noted Rept withheld (ref 10CFR73 21)
 NORDERHAUD.L R Division of Radiological Safety & Safeguards
 Program 82/12/079 WITHERS, B D Portland General Electric Co
 2pp 16456 129 24X Fiche 50-344,82/12/09,8212170304
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Cas Monitoring " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20,8208190268
- R Periodic operating reports & related correspondence
- SE12070343 Forwards monthly operating rept for Jul 1982 YUNDT, C.P. Portland General Electric Co. 82/08/05 - Office of Management and Program Analysis ip 16343 199 24X Fiche 50-344, 82/08/05, 8212070343
- --0212070346 Monthly operating rept for Jul 1982 NICHDL80N.W D Portland General Electric Co 02/08/04 4pp 16343 290 24X Fiche 50-344, 82/08/05, 8212070343
- GP:12290201 Forwards monthly operating rept for Oct 1982 YUNDT, C.P. Portland General Electric Co. 82/ii/03 Office of Resource Management, Director 1 19 16578 185 24X Fiche 50-344, 82/11/03, 8218290201
- --8212270204 Monthly operating rept for Oct 1982 NICHOLSON,W O Portland General Electric Co 82/11/03 4pp £6578 186 24X Fiche 50-344,82/11/03,8212270201
- 9 Reportable occurrences, LERs & related correspondence
- 8P1203001i Forwards LER 82-020/03L-0 Detailed event analysis encl YUNDT,C P. STEELE,R L. Portland General Electric Co 82/11/10 ENGELKEN.R H. Region 5. Office of Director 3pp 16304 234 24X Fiche 50-344, 82/11/10, 8212030011
- --B212030017 LER B2-020/03L-0 on B21013,manual filter inlet damper on train A control room emergency ventilation sys found closed, isolating fan VC-142A suction path from control room Caused by loose setscrew Improved attachment method implemented BAIR.0 0 Portland General Electric Co B2/11/10 Region 5. Office of Director ip 16304 237 24X Fiche 50-344.82/11/10, B212030011
- 8212140346 Forwards LER 82-021/03L-0 Detailed event analysis encl VUNDT, C.P. Portland General Electric Co. 82/11/30 ENGELKEN, R.H. Region 5, Office of Director 3pp 16401 021 24X Fiche 50-344, 82/11/30, 8212140346
- --8212140355 LER 82-021/03L-0 on 821101, pressurizer level transmitter LT-461 found out of calibr Setpoint for high pressurizer level reactor trip exceeded max value Caused by setpoint drift Instrument recalibr & returned to svc BAIR.9 9 Portland General Electric Co 82/11/30 Region 5, Office of Director 1p 16401 024 24X Fiche 50-344,82/11/30, 8212140346
- G212280421 PNS-V-82-005 on B21217, bumb threat received from unidentified male Plant search quelled negative results SCHWAN, C A. BCHUSTER, M D. Region 5. Opfice of Director 82/12/17 ip 14540 028 24% Fiche 50-344, 82/12/17, B212280421
- SEI2280190 Forwards response to request for add1 info re resolution of LER 79-15 per B20929-30 meeting in San Francisco, CA w/util & Bechtel Need for add1 tornado missile barrier at fuel bldg eliminated Meeting agenda encl WITHERS: B D Portland General Electric Co 82/12/22 CLARK.R A Operacting Reactors Branch 3 7pp 16562 296 24X Fiche 50-344, 82/12/22, 8212280190

- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B212020270 Notifies that alternate dedicated svc water sys will be installed within 30 months of NRC 820402 acceptance date, per 10CFR50 48(c)(4)
 CROUSE, R P Toledo Edison Co 82/11/23 STOLZ, J F Operating Reactors Branch 4 1p 14279 353 24% fiche 50-344,82/11/23, 231202777
- 8.12080643 Forwards safety evaluation % notice of elemption from certain technical requirements of App R to 100FR50.per util 820429 request tiseNHVT.D G Division of Licensing 82/11/23 CROUSE, R P Tolido Eddson Co 4pp 16372 352 24X Fiche 50-346, 82/11/23, 8212080643
- --8212080649 Safety evaluation supporting exemption from certain requirements of App R to 100FR30

 * Office of Nuclear Reactor Regulation, Director 82/11/23 Spp 16372 356 24% Fiche 50-346,82/11/23.8212080643
- --8212080652 Notice of exemption from certain requirements of App K to 10CFR50 STOLZ, J F Operating Reactors Branch 4 82/11/23 2pp 14372 361 24X Fiche 50-346,82/11/23,8212080643
- 8:12100255 Forwards IE Insp Rept 50-346/82-31 on 821003-30 & notice of violation BPESSARD.R L. Division of Project & Resident Programs 82/11/26 CRGUSE.R P. Toledo Edison Co. 2pp. 16376 159 24x Fiche 50-346.82/11/26.8212100255
- 8212100287 Notice of violation from insp on 821003-30 SPESSARD, R L Division of Project & Resident Programs 82/11/26 1p 16376 161 24% Fiche 59-346.82/11/26.8212100255
- --9212100263 IE Insp Rept 50-346/82-31 on 821003-30 Noncompliance noted repair of buried fire piping accomplished winadequate procedures, as requirement for restoring backfill to original spec omitted PEEBLES: T A . ROGERS.W 0 . BYRDN.P M Division of Project & Resident Programs 82/11/24 8pp 16376 162 24x Fiche 59-346.82/11/26.8212100255
- 8212040074 Forwards IE Safeguards Insp Rept 50-346/82-30 on 821025-29 to notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)

 NORELIUS.C E Division of Engineering & Technical Programs
 82/11/29 CROUSE, R P Toledo Edison Co 2pp 14314 358 24X
 (ithe 50-346.82/11/29,8212060074
- --B212060080 IE Safeguards Insp Rept 50-346/82-30 on 821025-29
 Noncompliance noted security organization mgt.personnel & response-records & repts, testing & maint & physical barriers Details withheld (ref 10CFR73 21)
 PIRTLE.O L., KNICELEY, J. R., CREED, J. R. Region 3, Office of Director B2/11/23 2pp 16314 360 24X Fiche 50-346.82/11/29, 8212060074
- 8212130132 Releases public version of list of effective pages to emergency plan manual FELTON, J M Division of Rules and Records 82/12/03 Document Management Branch 1p 16410 325 24X Fiche 50-346, 82/12/03. 82/03/03/03
- --8212130137 Forwards public version of list of effective pages to emergency plan manual & Figure 5-2 re facility organization * Toledo Edison Co 82/10/06 Office of Nuclear Reactor Regulation, Director ip 16410 327 24X Fiche 50-346.82/12/03,8212130132
- --8212130144 Public version of list of effective pages to emergency plan manual & Figure 5-2 re facility organization (MURRAY.T D Totedo Edison Co 82/09/29 4pp 16410 328 24/ Fiche 50-346.82/12/03.8212130132
- 8212100231 Forwards proposed revision to industrial security plan Revision withheld (ref 10CFR73 21) CROUSE: R P Toledo Edison Co 82/12/06 DENTON: H R Office of Nuclear Reactor Regulation: Director Ip 16376 191 24X Fiche 50~346,82/12/06,8212100231
- 8212(5030) Releases public version of revision to emergency plan supporting procedures revision index FELTON.J M Division of Rules and Records 82/12/08 Document Management Branch ip 16446 264 24X Fiche 50-346,82/12/08,82

- GF12160091 Releases public version of revised emergency plan implementing procedure FELTON.J B Division of Rules and Records 82/12/08 Docum Hanagement Branck ip (5447 209 24X Fiche 50-346,82/12/08, 0212160091
- -0212160098 Forwards public version of Revision 4 to Emergency Plan Implementing Procedure EJ 1300 01. "Emergency Plan Activation" Receipt form enci Toledo Edsson Co 82/11/19 NRC ~ No Detailed Affiliation Given 1p 16447 210 24 (Fishe 50-346.82/12/08.8212160091
- --8212160107 Public version of Revision 4 to Emergency Plan Implementing Procedure &I 1300 01, "Emergency Plan Activation" Revision index encl inder enci inderA, T D , BEVER, B D , BRIDEN, D W Tolede Edison Co 39pp | 16447 211 24X Fiche 50-246,82/12/08,8212140091
- Ball 222029B Releases public version of revised emergency plan PAGE 2027B Integrated index to the portion of Rules and Records B2/12/10 Document Management Branch ip 16523 255 24% Fiche 50-346,82/12/10, U212220278
- --9212220302 Forwards public version of Revision 158 to emergency plan supporting procedures index Receipt form encl 4 Toledo Edison Co 82/12/03 NRC No Detailed Affiliation Given 1p 16523 256 24X Fiche SO-346,82/12/10.8212220298
- --B212220308 Public version of Revision 158 to emergency plan supporting procedures index * Toledo Edison Co 82/12/31 ip 16523 257 24X Fiche 50-346 82/12/10,8212220298
- G212300193 Responds to util B21123 schedule for completing mods to provide alternate svc water capability, required by App R to 100FRS9 Hods must be completed in accordance w/schadule for alternative shutdown capability, not dedicated shutdown STOLZ-JF Operating Reactors Branch 4 B2/12/14 CROUSE-R P Toledo Edison Co 2pp 16512 331 24X Fiche 50-346-82/12/14, H212300193
- 8./12220306 Piscusses layout of communications equipment required in control room ensite technical support of & near-site emergency operations facility KEPPLER. J C. Region 3. Office of Director 82/12/16 Communication Co. 3pp 16503 351 24X Fishe 50-000.82/12/16.
- GF12290026 Responds to 821012 ltr re changes to physical security plan Changes acceptable Requests administratively correct plan pages be submitted STOLZ. J Operating Reactors Branch 4 82/12/16 CROUSE.R D Toledo Edison Co 8212270026
- M Antitrust correspondence
- BP12150012 Requests NRC review of Cleveland Electric Illuminating Co 821119 Filing w/FERC for increase in rates for firm power svc Also requests NRC consideration of petition to intervene in matter
 PANDY. J Cleveland, OH 82/12/02 TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 37pp 16421 139
 Fiche 50-000. 92/12/02. 8212150012
- P Operating license stage documents & correspondence
- 89:12:30:11 Forwards Amend 49 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes Tach Spec Table 3 7-3 re safety-related hydraulic snubbers. DEAQAZIO.A W Operating Reactors Branch 4 82/11/23 CROUSE, Tolledo Edison Co. 3pp 16418 OD7 24X Fiche 50-346.82/11/23, CROUSE, R. P. Toledo Edison Co. 3pp
- --B212130117 Amend 49 to License NPF-9, changing Tech Spec Table 3 7-9 re safety-related hydraulic snubbers. STOLZ, J.F. Operating Reactors Branch 4 B2/11/23 7pp 16418 010 24X Fiche 50-346,82/11/23,8212130111
- --B212130121 Safety evaluation supporting Amend 49 to License NPF-3 * Office of Nuclear Reactor Regulation, Director B2/11/23 16418 017 24% Fiche 50-346,82/11/23,8212130111

- -- 8212130124 Notice of issuance & availability of Amend 49 to Lacense NPF-3 STOLZ.J F Operating Reactors Branch 4 82/11/23 2pp 16418 019 24X Fiche 50-346,82/11/23,8212130111
- BC12100040 Responds to 821013 1tr re Tech Specs for snubber surveillance All snubbers defined in ANSI/ASME OM-4 Std wil be listed in Tech Spec tables in manner similar to current table on hydraulic snubbers
 CROUSE.R P folede Edison Co 82/11/24 STOLZ.J F Operating
 Reactors Branch 4 2pp 16379 041 24X Fiche 50-346.82/11/24. R212100040
- GP12020205 Forwards temporary mods to facility procedures re reactor/turbine trip, auxiliary feedwater sys, station & instrument air, makeup & purification sys & plant startup SYRDNSXI.J H Tolado Edison Co 82/11/29 MAINES.R NRC Detailed Affiliation Olven 6pp 16274 096 24X Fiche 50-346.82/11/29,8212020205 NRC - Na
- GP12030337 Requests confirmation of schedule for resolution of items discussed in B21115 telcon re NUREQ-0612. "Control of Heavy Loads at Nuclear Power Plants " Response should be provided By 82/210 SYDLZ.J F Operating Reactors Branch 4 82/11/30 CROUSE.R D Toledo Edison Co 3pp 16316 326 24X Fiche 50-346.82/11/30. 8212030337
- 8212040158 Updates util 820917 ltr re NUREO-0737, Item II B 3, "Post-Accident Sampling " Util commits to revised completion date of Dec 1983 for installation of RCS sample panel & containment air monitor grab sample due to vendor problems CROUSE.R P Toledo Edison Co 82/11/30 STOLZ, J F Operating Reactors Branch 4 2pp 16313 115 24X Fiche 50-346.82/11/30.8313940159 CROUSE, R P Toled Reactors Branch 4 8212060158
- 8212100414 Forwards Amend 50 to License NPF-3, safety evaluation & notice of issuance & availability Amend changes Tech Spec Survaillance Requirement 4 6 I 5 re arithmetic averaging of injet temp to containment air coolers STOLZ, J.F. Operating Reactors Branch 4 82/11/30 CROUSE, R.P. Toledo Edison Co. Opp. 16389 061 24X Fiche 50-346,82/11/30, 8212100414
- --B212100453 Amend 50 to License NPF-3 changing Tech Spec Surveillance Requirement 4 6 ! 5 rs arithmetic averaging of inlet temp to containment air coolers STGLZ, JF Operating Reactors Branch 4 82/11/30 7pp 16387 064 24X Fiche 50-346,82/11/30,8212100414
- --B212100474 Safety evaluation supporting Amend 50 to License NPF-3 * Office of Nuclear Reactor Regulation, Director B2/11/30 16387 071 24X Fiche 30-346, B2/11/30, B212100414
- --B2121004B1 Notice of issuance & availability of Amend 50 to License NPF-3 STOLZ,JF Operating Reactors Branch 4 82/11/30 2pp 14389 075 24% Fiche 50-346,82/11/30,8212100414
- 8212070459 Forwards request for add1 info re NUREG-0737. Item II B 4:
 "Training for Mitigating Core Damage" Response requested
 no Later ther 821231
 STOLZJ F Operating Reactors Branch 4 82/12/01 CROUSE, R P
 Toledo Edison Co 3pp 16355 329 24X F; che 50~346.82/12/01. 8212070459
- GP12:3005: Requests modified responses to recommendations in NRC status rept re NUREQ-0737. Item II E 1 i, "Auxiliary Feedwater Sys Evaluation " Response to unresolved concerns requested by 821217 821217 STOLZ, J. F. Operating Reactors Branch 4 82/12/01 CROUSE, R. P. Toledo Edison Co. 3pp. 16417, 046 24X Fiche 50-346, 82/12/01, 6212130051
- 82J2070292 Discusses disposal of meteorological data strip charts Space considerations necessitate destroying charts in Dec 1983 Data on megnetic tape will be retained & stored consistent
- 82:2070040 Forwards SER for containment purging & venting during normal operation per Generic Item B-24 & NUREG-0737, Item If E 4 2 Purge sys design & operating practices acceptable except for two listed items STOLZ.JF Operating Reactors Branch 4 82/12/03 CRGUSE.R P Taledo Edison Co 7pp 16384 247 24X Fiche 50-346.82/12/03, RECEDENCE.

- --8212070043 SER for containment purging & venting during normal operation Debris screens should be installed & leakage integrity tests performed regularly Interim position encl a Operating Reactors Branch 4 82/12/03 App 16384 254 24X Fiche 50-346,82/12/03,8212070040
- B212130090 Endorses B&W Topical Repts BAW-10154P, "B&W Smel) Break LOCA ECCB Evaluation Model" & BAW-10072P, Revision 3, "CRAFT-2," in effort to complete small break LOCA methods program response to NURSO-0737, Item II K 3 30 CROUSE, R P Toledo Edison Co B2/12/07 STOL7, J F Operating Reactors Branch 4 1p 16389 315 24X Fiche 50-346,82/12/07, H212130090
- GP1213008B Forwards 821206 affidavit of JH [autor requesting proprietary classification of BAM-1719. "Fracture Toughness Test Results From Capsule TEt-f." reactor vessel mati surveillance program CRDUSE: PP Toledo Edison Co 82/12/08 STDLZ.J F Operating Reactors Branch 4 8pp 16390 197 24X Fiche 50-346.82/12/08.621213008B
- 8:08190263 Generic Ltr 82-32 to all PWR licenseus re potential steam generator-related generic requirements Forwards Science Applications, inc draft rept re subj requirements Comments requested within 30 days of itr 8xc list encl LISENHUT.D 0 Division of Licensing 82/12/09 Consolidated Edison Co of New York, Inc. 29pp 16627 247 24X fiche 50-000,82/12/09.8208190263
- 8212170372 Advises that anticipatory reactor trip sys main feedwater trip bypass alarm. described in util 820727 ltr. represents acceptable alternative to automatic bypass removal 8TOLZ. J. F. Operating Reactors Branch 4 82/12/10 CRGUSE.R P Toledo Edison Co. 2pp. 16478 165 24X Fiche 50-346,82/12/10,82/12/70372
- G212270363 Forwards order for license mod requiring installation of inadequate core couling sys which conforms to design parameters specified in NURGE-0737, Item II F 2 "Detection of Inadequate Core Cooling "EBCAMUTO D Division of Licensing B2/12/10 CROUSE, R P Tole Ldison Co Spp 16566 215 24% Fiche 50~346, 82/12/10, 8212270363
- --8212270370 Order for mod of License NPF-3 re NUREO-0737, Item II F 2, "Detection of Inadequate Core Cooling " Checklist for plant specific review of inadequate core cooling instrumentation sys encl EISETHUT. D O Division of Licensing 82/12/10 Toledo Edison Co 11pp 16566 218 24X Fiche 50-346, 82/12/10, 8212270363
- BP12280069 Forwards Amend 51 to License NPF-3 & notice of issuance & availability Amend proposes license conditions re sys integrity measurements program & improved fodine monitoring program DEAGAZIO. A W Operating Reactors Branch 4 82/12/10 CROUSE, R P Toledo Edison Co 3pp 16593 076 24X Fiche 50-346, 82/12/10, 82/1280069
- --B2122B007i Amend 51 to License NPF-3, adding license conditions re sys integrity measurements program & improved iodine manitoring program STGLZ.J F Operating Reactors Branch 4 B2/12/10 5pp 16593 079 24X Fiche 50-346, 82/12/10,82122B0069
- --8212280074 Notice of issuance & availability of Amend 51 to License NAF-3 BTOLZ.JF Operating Reactors Branch 4 82/12/10 2pp 16593 085 24X Fiche 50-346, 82/12/10, 8212280069
- 8212210072 Responds to 821130 ltr concerning response to draft technical evaluation rept re control of heavy loads Util reviewing request to submit Phase II rept Response will be provided 830131 CROUSE.R P Toledo Edison Co 82/12/14 STOLZ, J.F. Operating Reactors Branch 4 1p 16473 015 24X Fiche 50-346,82/12/14, 8212210092
- 8212220273 Requests relief from Class 2 valve testing requirements of ABME Section XI IWV.MSIV MS-100 & MS-101 Permission to perform subj test in lieu of full stroke test at cold shutdown requested Modified code relief Request 1 encl CROUSE.R P Toledo Edison Co B2/12/14 STOLZ,J F Operating Reactors Branch 4 5pp 16518 026 24X Fiche 50-346,62/12/14, 62/12220273.

- BP12270210 Responds to NRC BR1201 ltr re NUREG-0737. Item II E 1 1.

 "Auxiliary Feedwater Sys Reliability Evaluation" & request for util commitment to Recommendation GS-6 Suggested changes to Tech Specs not warranted CROUSE.R P Toledo Edison Co BR212/15 STGLZ.J F Operating Reactors Branch 4 3pp 16535 001 24X Fishe 50-346.82/12/15.
- 89/12270205 Advises that final avaluation re EPRI relief & safety valve testing per NUREG-0737. Item II D 1. "Reliability Engineering," will not be submitted until 930131 Summary of evaluation submitted CRCUSE.R P Toledo Edison Co 82/12/17 STOLZ.J F Operating Reactors Branch 4 2pp 16534 354 24% Fiche 50-346,82/12/17,8212270205
- & Inspection reports. IE Bulletins & correspondence
- 8,08190240 IE Bulletin 82-03.Revision i. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/2B Consolidated Edison Co of New York, list 112pp 16462 163 24X Fiche 50-000.82/10/28,8208190240
- GEOB190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl COBO.L. I Division of Fuel Facilities, Materials & Sareguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 24X Fichs 50-000, 82/11/05, 8208190245
- 82/08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 243 Fiche 50-000, 82/11/18, 8208190251
- 8/08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNG,R C Director's Office. Office of Inspection and Enforcement 82/11/26 Congolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000, 02/11/26, 8208190256
- 8212100255 Forwards IE Insp Rept 50-346/82-31 on 821003-30 & notice of violation SPESSARD,R L Division of Project & Resident Programs 82/11/26 CROUSE,R P Toledo Edison Co 2pp 16376 159 24X Fiche 50-346,82/11/26,8212100255
- --8212100257 Notice of violation from insp on 821003-30 SPEBSARD,R L Division of Project & Resident Programs 82/11/24 1p 16376 161 24% Fiche 50-346,82/11/26,8212100255
- --8212100263 IE Insp Rept 50-346/82-31 on 821003-30 Noncompliance noted repair of buried fire piging accomplished w/inadequate procedures as requirement for restoring backfill to original spec omitted PEEBLES.TA. ROGERS.W G. BYRON.P M Division of Project & Resident Programs 82/11/24 Bpp 16376 162 24X Fiche 30-346,82/11/26.8212100255
- 8P12060074 Forwards JE Safeguards Insp Rept 50-346/82-30 on 82:025-29 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21)
 NORELIUS, C E Division of Engineering & Technical Programs
 82/11/29 CROUSE, R P Toledo Edison Co 2pp 16314 358 24X
 Fiche 80-346/82/11/29,82:2060074
- --8212060080 IE Bafeguards Insp Rept 50-346/82-30 on B21025-29
 Noncompliance noted security organization mgt.personnel & response, records & repts.testing & maint & physical barriers Details withheld (ref 100FR73 21)
 PIRTLE, Q L , KNICELEY, J R , CREED, J R Region 3, Office of Director 82/11/23 2pp 16314 360 24X Fiche 50-346,82/11/29,8212060074
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl." Svc list enc!
 CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- B20B190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259

- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYDUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 80-000.82/12/16.8208190267
- 8212210351 Ack receipt of 821209 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 30-346/82-29 STREETER. J F Division of Project & Resident Programs 82/12/16 CROUSE. R P Toledo Edison Co ip 16493 100 24% Fiche 50-346, 82/12/16,8212210361
- --8212210368 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-346/82-29 Corrective actions reactor theory requalification exam reviewed per Administrative Procedure AD 1818 15 4 responsible personnel counseled CROUSE: R P Toledo Edison Co 82/12/09 STREETER, J F Division of Project & Resident Programs 2pp 16493 (O) 24X Fiche 50-346, 82/12/16, 8212210361
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24 Fiche 50-000.82/12/20.8208190268
- 82:2290224 Responds to IE Bulletin 82-0; Revision 1, Suppl 1 re alteration of radiographs of welds in piping subassemblies supplied by ITT Grinnell Industrial Piping. Inc No alteration CROUSE, R P Toledo Edison Co Ø2/12/21 KEPPLER, J Q Region 3 Office of Director 2pp 16578 070 24X Fiche 50-346,82/12/21, B212270226
- BP12290449 Ack receipt of 821206 itr informing NkC of steps taken to correct violations noted in IE Insp Rept 50-346/82-27 Corrective actions delineated in LER 82-44 will be implemented to correct noncompliance STREFTER. JF Division of Project & Resident Programs 82/12/23 CROUSE. R P Toledo Edison Co 1p 16585 213 24X Fiche 50-346, 82/12/23,8212270449
- --8212270455 Responds to NRC 821104 ltr re violations noted in ik Insp Rept 30-346/82-27 Corrective actions Special Order 99 distributed to clarify requirements of Yech Specs re consequences of failure to perform surveillance requirement CROUSE.R.P. Toledo Edison Co. 82/12/06 SPESSARD.R.L. Division of Project & Resident Programs 3pp 16585 214 24X Fiche 50-346,82/12/23,8212290449
- R Periodic operating reports & related correspondence
- 82:12290307 Forwards monthly operating rept for Oct 1982 MURRAY.T D foledo Edison Co 82/11/07 HALLER.N Office of Resource Management, Director 1p. 16588 018 24K Fiche 50-346, 82/11/09,8212290307
- --8212290309 Monthly aperating mept for Oct 1982 SARSOUR, B Toledo Edison Co 82/11/09 8pp 16588 019 24X Fiche 50-346.82/11/09.8212290307
- S Reportable occurrences, LERs & related correspondence
- 8212100229 Forwards LER 82-056/03L-0 MURRAY, T D Toledo Edison Co 82/12/02 KEPPLER, J Q Region Office of Director 1p 16976 188 24X Fiche 50-346, 82/12/02,
- --8212100239 LER 82-056/03L-0 on 821104, breaker 8FI14 tripped, causing loss of power to F12 series motor control ctrs Caused by ground in Jackey fire pump motor when pump seized Pump rebuilt & motor replaced LCNO.J Toledo Edison Co 82/12/02 Region 3, Office of Director 2pp 16376 189 24X Fiche 50-346,82/12/02.8212100229
- 8212100325 Forwards LER 82-057/03L-0 MURRAY.T D Toledo Edison Co 82/12/02 KEPPLER.J & Region 3, Office of Director 1p 16377 060 24X Fiche 50-346,82/12/02, 8212100325
- --8212100332 LER 82-057/03L-0 on 821105, found door 400 not completely closed & latched Caused by personnel error Personnel to receive additional in basic security RICHTER.L. Toledo Edison Co 82/12/02 Region 3, Office of Director 3pp, 16377 061 24X Ficher 50-346, 82/12/02, 8212100325

- 8P12100281 Forwards LER 82-058/03L-0 MURRAY, T D Toledo Edison Co 82/12/03 KEPPLER, J G Region 3, Office of Director 1p 16377 142 24X Fiche 50-346, 82/12/03,
- --8212100287 LER 82-058/03L-0 on 921106, while performing ST 5032 01, setpoints for containment post-accident radiation monitor RE 45978A found drifted rendering monitor inoperable Caused by component failure Microprocessor boards replaced ELDRED, D T Toledo Edison Co 82/12/03 Region 3, Office of Director 2pp 16377 143 24x Fiche 50-346,82/12/03,8212100281
- 8212170282 Forwards LER 82-059/03L-0 MURRAY. T D Toledo Edison Co 82/12/08 KEPPLER, J C Region 3, Office of Director 1p 16461 154 24X Fiche 50-346, 82/12/08,
- --8212170285 LER 82-059/03L-0 on 821108, containment post-accident radiation monitor, channel 2 read low On 821116 & 22 equipment fail alarm received Caused by failed high voltage power supply board Board replaced & declared operable ELDRED, D T Toledo Edison Co 82/12/08 Region 3, Office of Director 3pp 16461 155 24X Fiche 50-346,82/12/08,8212170282
- 8912170178 Forwards LER 82-060/031-0 MURRAY, T D Toledo Edison Co 82/12/09 KEPPLER, J G Region Office of Director (p 16450 137 24X Fiche 50-346, 82/12/09,

1

- --8212170187 LER 82-060/03L-0 on 821111.during performance of \$7 5031 13. discovered ventilation duct chase 48 power supply in steam a feedwater rupture control sys channel 2 failing at I-volt/h Caused by component failure Channel 2 de-energized YARGER.K Taledo Edison Co 82/12/07 Region 3, Office of Director 2pp 14450 138 24X Fiche 50-344,82/12/09,8212170178
- 8712280247 Forwards LER 82-061/03L-0 MURRAY, T D Toledo Edison Co 82/12/19 KEPPLER, J G Region 3, Office of Director 1p 16361 274 24X Fiche 50-346,82/12/15,
- --8212280280 LER 82-061/03L-0 on 821116, fire door 509 (control room access door) & door 512 (control alarm station door) declared monfunctional due to improper fire rating labels Caused by design error Duors will be replaced HART, T. RICHTER, L. Toledo Edison Co. 82/12/15 Region 3, Office of Director 3pp 16561 275 24X Fiche 50-346, 82/12/15, 8212302347
- 8/12/280281 Forwards revised LER 82-059/03T-1 MURRAY.T D Toledo Edison Co 82/12/15 KEPPLER.J G Region 3. Office of Director 1p 14541 140 24% Fiche 50-346,82/12/15.
- --B212280240 Revised LER 82-059/03T-1 on B2110B.containment post-accident radiation monitor RE 4597AA Channel 2 discovered reading low On B21116 & 22.equipment fail alarm received on RE 4597AA Caused by failed high voltage power supply board ELDRED, D T Toledo Edison Co 82/12/15 Region 3. Office of Director 3pp 16561 141 24X Fiche 50-346.82/12/15.8212280281
- 8212270151 PNO-III-82-137 on 821216.unusual event declared after gasoline truck collided websto 1/2 mie south of plant site, spilling approx 4,000 gallons of fuel Casoline contained in surrounding ditches Unusual event terminated \$21217 PEEBLES, T. REYEG, L. SIRETERJ, J. Region 3, Office of Director 82/12/17 1p 16538 341 24% Fiche 50-346,82/12/17,8212270151
- 8212280075 Forwards LER 82-062/03L-0 MURRAY, T D Toledo Edison Co 82/12/17 KEPPLER, J Q Region 3. Diffice of Director 1p 16565/133 24% Fiche 50-346, 92/12/17,
- --8212280077 LER 62-062/03L-0 on 821117.discharge check valve CV-186 stuck during 6T 5065 02.rendering hydrogen dilution blower 1-4 inoperable Caused by design/fabrication error New valve THOMPSON, T Tolsdo Edison Co 82/12/17 Region 3, Office of Director 2pp 16565 134 24% Ficher 50~346,82/12/17,8212289075
- 8712280234 Forwards LER 82-063/03L-0 MURRAY.T D Toledo Edison Co 82/12/17 KEPPLER, J O Region Office of Director ip 16562 175 24X Fiche 50-346, 82/12/17. 8212280234
- ~B2[2280239 LER 82-063/03L-0 on B2[1]8, offsite ac source operability not demonstrated within 1 h after emergency diasel generator 1-1 taken out of avc for periodic maint Caused by personnel error Personnel counseled LDNG.T Toledo Edison Co B2/12/17 Region 3, Office of Director 3pp 16362 196 24X Fiche 80-346,82/12/17,8212280234

- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8212100070 Submits permanent, backup, interim primary & interim backup emergency operations facilities (EOF) info per 821202 verbal request EOF completed & occupied in Oct 1982 CLAYTON.F L Alabama Power Co 82/12/03 VARQA.8 A Office of Nuclear Reactor Regulation, Director 3pp 16375 359 24X Fiche 50-348,82/12/03,8212100070
- J Insurance & indemnity information
- 82:12280223 Forwards Endorsement 48 to NELIA Policy NF-238 & Endorsement
 - **/220243 Forwards Endorsement 49 to NELIA Policy NF-238 & Endorsement 40 to MAELU Policy MF-93
 DUCK J R Marsh & McLennan. Inc. N & M Nuclear Consultants. Inc. Div. B2/12/20
 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16562 276 24X Fiche 50-348.82/12/20,8212280223
- 8212280348 Forwards Certificates of Insurance N-62 & N-73 for Endorsements 1.2 & 3 to NELIA Policy NF-238 & Certificates of Insurance M-62 & M-73 for Endorsements 1.2 & 3 to MAELU
 - of Insurance m-oz d in 3.50 and 5.50 an
- P Operating license stage documents & correspondence
- 82:2020130 Informs that info requested in Generic Ltr 82-22 re steam enzululu intorms that info requested in Generic Ltr 82-22 r generator tube integrity, maint, repair & worker exposures submitted via annual CFR repts & util 820412 ltr CLAYTGN.F L Alabama Power Co 82/11/24 EIBENHUT.D & of Licensing 2pp 16272 037 24X Fichs 50-340,82/11/24, 8212020130 Divisian
- 8208170263 Ceneric Ltr 82-32 to all PWR licensees re potential steam evervozed Generic Ltr Na-32 to all MMK licensees re potenti generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of itr Bvc list encl EISERHUT.D 0 Division of Licensing B2/12/09 Consol Edison Co of New York. Inc. 29pp 16629 247 24X Fiche 50-000, B2/12/09, B208190263 Consolidated
- 82:12280280 Requests approval by 830701 of 820810 ltr re RCS pressure scheduling of next refueling to support planning & scheduling of next refueling outage

 CLAYTON,F L Alabama Power Co 82/12/23 VARGA: S A Office of Nuclear Reactor Regulation. Director 1p 16561 243 24X Fiche 50-348,82/12/23,8212280280
- **Q** Inspection reports, IE Bulletins & correspondence
- 8:08190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants" Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs 50-000, 82/10/28, 8208190240
- 9212090362 Advises that provisions of IE Bulletin Bi-O3, [tem 4 B met, following extensive insp & cleaning of various safety-related & nonsafety-related HX CLAYTON.F.L. Alebama Power Co. 82/10/29 O'REILLY.J.P. Region Office of Director 4pp 16345 160 24X Fiche 50-348,82/10/29,
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Hodel 801 & Model 802 Thermoluminescent Dosimeters " 8vc list
- CDBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp. 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8P12090412 Advises that IE Bulletin 82-01, Revision 1. Suppl 1. review of radiographs furnished by ITT Grinnell for piping assemblies, revealed too assemblies w/altered radiographs on total of three welds Penetrameter image darkened CLAYTON, FL Alabama Power Co 82/11/09. D'REILLY, J P Region 2. Orfice of Director 2pp 16365 042 24X Fiche 50-348,82/11/09, 8313700419
- 9212090511 Forwards IE Insp Repts 50-348/82-25 & 50-344/82-24 on B20914-1022 No noncompliance noted
 VERRELLI, PM Division of Project & Resident Programs B2/11/17
 MCDDNALD, R P Alabama Power Cb 2pp 16367 014 24X Fiche 50-348, 82/11/17, 8212090511

- --8212070519 iE Insp Repts 50-348/82-25 & 50-364/82-24 on 820916-1022 No noncompliance noted Major areas inspected monthly surveillance observation, monthly maint observation & survelliance observation, monthly maint observation & operational safety verification BRADFORD,W H. CANTRELL,F Division of Project & Resident Programs 82/11/17 8pp 16367 016 24X Fiche 50-348,82/11/17,8212090511
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl ROBIPO296 IE Info Notice Decision Decision of Inspection and Padlocks "Svc list encl DeryOUND.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pg 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8212090432 Confirms 821123 telcon re 821214 mgt meeting in Birmingham. AL to review results of first phase of annual appraisal of regulatory performance Proposed agenda encl LEWIS.R C Division of Project & Resident Programs 82/11/29 MCDONALD.R P Alabama Power Co 3pp 16364 271 24X Fiche 50-348.82/11/29.8212090432
- 82:08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche \$0-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 16411 317 24% Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN:E L Division of Engineering & Quality Assurance 82/12/0 Consolidated Edison Co of New York, Inc 110pp 16462 064 : Fiche 50-000:82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEYOUNG.R C Director's Office of Pfice of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50. "Hod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN:E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24 Fiche \$0-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- BP12170197 Forwards monthly operating rept for Nov 1982 CLAYTON.F L Alabama Power Co B2/12/13 Division of Data Automation & Management Information 1p 16461 302 24X Fiche 50-34B.82/12/13.8212170197
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8210040239 Forwards Amend 39 to application for OL (filed in PDR in Category A)

 BRADLEV.E J Philadelphia Electric Co E2/09/30 DENTON.H R

 Office of Nuclear Reactor Regulation, Director App 15589 170

 24X Ficha 50-352,82/09/30,8210040239
- --B210040253 Amend 39 to application for DL, consisting of Revision 10 to FSAR, proprietary & nonproprietary Revision 1 to design assessment rept & Revision 4 to environ rept Certificate of Svc encl Proprietary design rept withheld tref 10CFR2 790; BOVER, V. 8 Philadelphia Electric Co 82/09/28 7pp 15589, 176 P4K Fiche 50-352, 82/09/30, 8210040239
- --8210040272 Revision 1 to nonproprietary design assessment rept * Philadelphia Electric Co 82/09/30 228pp 15590 286 Fiche 50-352,82/09/30,8210040239

- B212060077 Forwards request for add1 aussliany sys info re Revision 10 to FSAR Response should be provided within 7 days SCHNENCER. A. Licensing Branch 2 82/11/17 BAUER. E G Philadelphia Electric Co 4pp 16323 016 24% Fiche 50-352, 82/11/17, 8212060097
- B212050118 Forwards request for add1 info as result of concerns raised during hearing session on Point Pleasant Diversion Project SCHWENCER.A Licensing Branch 2 82/11/18 BAUER.E 9 Philadelphia Electric Co 4pp 16323 007 24X Fiche 50-352, 82/11/18, 8212060118
- 8212060510 Notification of 921217 meeting w/util at Limerick Info Ctr to discuss mgt structure & technical resources audit ABELSON,H Licensing Branch 2 62/11/23 BCHMENCER,A Licensing Branch 2 4pp 16344 016 24X Fiche 50-392,92/11/23,8212060810
- 8212080015 Notification of cancellation of 821217 meeting w/util st site to discuss plant mgt structure & technical resources audit Meeting will be rescheduled ABELSON: H Licensing Brench 2 82/11/23 SCHWENCER. A Licensin Branch 2 4pp 16347 173 24X Fiche 50-352,82/11/23,8212080015
- 8212010470 Confirms 881214-17 mgt structure & technical resources audit Agende encl
 SCHWENCER. A. Licensing Branch 2 82/11/24 BAUER, E. G. Philadelphia Electric Co. Spp. 16270 215 24X
 Fiche SO-382.892/11/24.8212010470
- B212010513 Forwards Ed&G draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants.Limerick Generating Station Units 1 & 2." for comment SCHWENGER.A Licensing Branch 2 82/11/24 PAUER.E G Philadelphia Electric Co 3pp 16268 168 24X Fiche 50-352,82/11/24,82120105(3
- --8212010519 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units i & 2" MARINGAS, N , STICKLEY, T H EG&G, Inc 82/11/30 NRC - No Detailed Affiliation Given 30pp 16268 171 24X Fiche 50-352,82/11/24,8212010513
- 8212060393 Summary of 820903 meeting w/util.GE.Fauske & Associates,Inc, BNL.NVS.Science Applications.Inc.Commonwealth of PA. Limerick Ecology Action & applicant counsel in Bethesda,ND re PRA ABGLSON,H Licensing Branch 2 82/11/29 Licensing Branch 2 47pp 16323 021 24X Fiche 50-352,82/11/29,8212060393
- 8212060378 Summary of 820722 meeting w/util, NUTECH & BMML in Bethesda, MD re-present & future corp & plant mgt structure, staffing, training plans & safety review groups
 ABELSON: H Licensing Branch 2 82/11/29 Licensing Branch 2
 17pp 16322-318 24X Fiche 50~352, B2/11/27, 8212060398
- 8212030122 Forwards Amend 42 to application for DL Amend revises FSAR in response to NRC 820809 ltr Certificate of Svc enc! BRADLEV.E.J Philadelphia Electric Co 82/11/30 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 16303 283 24X Fiche 50-352.82/11/30.8212030122
- --82(2030132 Amend 42 to application for OL revising FSAR BOYER VS Philadelphia Electric Co 82/11/27 3pp 16303 288 24X Fiche 50-332,82/11/30,8212030122
- 8212070493 Notification of 821215 meeting w/u til & SNL in Bethesda.MD to discuss questions generated during review of BNL draft rept on PRA Meeting agenda wnc!
 ABELSDN:H Licensing Branch 2 82/12/01 SCHWENCER, A Licensing Branch 2 4pp 16351:355 24X Fiche 50-352,82/12/01,8212070493
- 8212070025 Forwards agreement w/ARCO Pipeline Co prohibiting shipping propana through ARCO pipeline.per C Ferrell concern from Aug 1982 environ site visit BRADLEY.E.J Philadelphia Electric Co 82/12/03 SCHWENCER.A Licensing Branch 2 5pp 16327 347 24X Fiche 50-352,82/12/03,8212070028.
- 8212080446 Forwards draft response to NRC 820901 request for add1 info to aid E Pedersen audit of util organization BRADLEY,E J Philadelphia Electric Co 82/12/03 SCHWENCER,A Licensing Branch 2 71pp 16352 180 24X Fiche 50-352,82/12/03, B212080446
- 8212160747 Forwards request for add1 info re pump house noise Corrected numbers for previously submitted E290 series questions resubmitted Response requested within 7 days of ltr receipt SCHWENCER. A Licensing Branch 2 82/12/08 BAUER. E Q Philadelphia Electric Co 4pp 16466 001 24X Fiche 50-352.82/12/08,8212160747

- 8212220541 Requests tost case calculation for radiological risk be provided to facilitate review of PRA Case should be calculated w/version of CRAC computer code used in plant PRA SCHWENCER, A Licensing Branch 2 82/12/13 BAUER, E G Philadelphia Electric Co 3pp 16523 357 24X Fiche 50-352, 82/12/13, 8212220541
- 8212210402 Advises that actual scram valve characteristics will be used in preparing analysis of control rod drive sys hydrodynamic loads Analysis & complete response will be provided by 830319

 BRADLEY, & J Philadelphia Electric Co 82/12/16 SCHWENCER, A Licensing Branch 2 2pp 16494 310 24X Fiche 50-352, 82/12/16. 8212210402
- 8212210491 Forwards Amend 43 to license application (filed in PDR Category A)
 BRADLEYE J Philadelphia Electric Co 82/12/17 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 1p 16486 048 24X
 Fiche 50-352,82/12/17,8212210491
- --B212210495 Amend 43 to license application consisting of Revision 8 to environ rapt & Revision 14 to FSAR BOYER.V 5 Philadelphia Electric Co 82/12/15 App 16486 050 24X Fiche 50-332,82/12/17,8212210491
- 8212220097 Forwards DDI 821206 ltr transmitting Fish & Mildlife Svc correspondence re Point Pleasant diversion Info relates to testinony before ASLB HODODON A P Hearing Branch 2 82/12/20 BRENNER.L., MORRIS.P A. COLE.R F Atomic Safety and Licensing Board Panel lipp 16516 105 24X Fiche 50-352.82/12/20.8212220097
- 8212270141 Forwards summary of loss of offsite power comments presented at 821215 meeting.compilation of requests for addlinfo for BNL re PRA review & summary of comments on remaining issues BDYER, V S Philadelphia Electric Co 82/12/22 EISENHUT, D Ø Division of Licensing 23pp 16538 312 24X Fiche 50-352.82/12/22, 8212270141
- 8212280209 Forwards responses to Auxiliary Sys Branch Questions 410 94 through 410 99 re spent fuel storage, transmitted by 821122 ltr Responses will be incorporated in FSAR revision scheduled for Jan 1983 BRADLEY, E. J. Philadelphia Electric Co. 82/12/22 SCHWENCER, A Licensing Branch 2 10pp 16562 110 24X Fiche 50-352, 82/12/22, 8212280209
- C Utility Environmental Report (ER), amends & correspondence
- B210040239 Forwards Revision 6 to environ rept (Piled in PDR in Category C) BRADLEY,E J, Philadelphia Electric Co B2/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 15589 170 24X Fichs 50-352,82/09/30,8210040239
- --8210040278 Revision & to environ rept

 * Philadelphia Electric Co 82/09/30 20ep 15591 154 24X
 Fiche 50-352,82/09/30,8210040239
- 8212100274 Advises that response to Siting Analysis Branch Question E310 10 will be provided via environ rept revision in Feb 1983 BRADLEY, E. J. Philadelphia Electric Co. 82/12/07 SCHWENCER, A. Licensing Branch 2 2pp 16376 147 24X Fiche 50-352,82/12/07.8212100274
- B212210491 Forwards Revision 8 to environ rept (filed in PDR Category C)
 BRADLEYE J Philadelphia Electric Co 82/12/17 DENTON H R
 Office of Nuclear Reactor Regulation, Director Ip 16406 048 24X
 Fiche 50-352, 82/12/17, 8212210491
- --8212210498 Revision 8 to environ rept * Philadelphia Electric Co 82/12/31 23pp 16486 207 24X Fiche 50-352, 92/12/17, 8212210491
- F Security, medical, emergency & fire protection plans
- 821207013B Advises that revised fire protection evaluation rept due by Nov 1982, per 820901 commitment, delayed until Jan 1983 Delay due to substantial, unanticipated addl effort required to upgrada rept per NRC 82072B itr IRADLEY, E. J Philadelphia Electric Co 82/12/03 SCHWENCER, A Licensing Branch 2 2pp 16327 032 24X Fithe 50-352, 82/12/03, 821207013B

- BB12100090 Submits info per 821203 telcon request re emergency operations facility (EDF) Response to Generic Ltr 81-10 submitted 810320 EDF const will be completed by Sept 1983 KEMPER, J 5 Philadelphia Electric Co B2/12/06 SCHMENCER, A Licensing Branch 2 Jpp 16379 240 24X Fiche 50-352,82/12/06,8212100090
- B21221037B Forwards draft FSAR page changes & responses to QA Branch B20713 request for add1 info Sixteen oversize drawings encl Aperture cards available in PDR BRADLEY. E. J. Philadelphia Electric Co. B2/12/17 SCHWENCER. A. Licensing Branch 2 92pp 16489 324 24X Fiche 50-352, 82/12/17, 821221037B
- 89:12270144 Forwards response to NRC comments on physical security plan Response withheld (ref 10CFR2 790 & 10CFR73 21) BRADLEY,E J Philadelphia Electric Co 82/12/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 16538 128 94X Fiche 50-352,82/12/17,8212270144

G Adjudicatory correspondence

- B212020330 Reply findings of fact & conclusions of law in form of initial decision CDINER, T B Philadelphia Electric Co CDNNER, T B Conner & Hetterhahn 82/11/30 21pp 16277 279 24X Fiche 50-352, B2/11/30, 0310202020
- --8212020339 Reply to Del-Aware 821117 response to ASLB request for info re flow in Bchuylkill River Response inaccurate & exceeds scope of ABLB limited inquiry Del-Aware is cluttering record w/erroneous & irrelevant matl W/Centificate of Svc CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn 82/11/29 10pp 16277 300 24X Fiche 50-352.82/11/30.8212020330
- 9212130358 Notifies that 920702 petition on behalf of Del-Aware Unlimited to suspend or revoke CPs has been denied Decision encl
 DENTON H R Office of Nuclear Reactor Regulation, Director B2/12/07 BUGARMAN, R J Sugarman, R J 3pp 16413 008 24) Fiche 50-392, 82/12/07, 8212130358
- ~-B212130359 Director's Decision DD-B2-13 denying Del-Aware Unlimited petition to suspend & revoke CPs No major changes in facts mat! to resolution of environ issues presented DENTON.H R , CASE.E G Office of Nuclear Reactor Regulation, Director B2/12/07 42pp 16413 011 24X Fiche 50-352,82/12/07, B212130358
- ~-B212130361 Notice of denial of Del-Aware Unlimited petition to suspend & revoke CPs CASE.E G Office of Nuclear Reactor Regulation, Director B2/12/07 3pp 16413 094 24X Fiche 50-352,82/12/07,8212130358
- 82:12140034 Forwards NRR Director 82:1207 denial of Del-Aware Unlimited request for suspension or revocation of CPs per 10CFR2 202 & 206 t/to encl HOD9DON,A P Hearing Branch 2 82/12/10 BRENNER,L, MORRIS,PA, COLE,R F Atomic Bafety and Licensing Board Panel 2pp 16409 293 24X Fiche 30-352,82/12/10,8212140036
- B212160304 Requests encl DOI B21207 ltr to ASLB be served on parties LANE.V M Atomic Bafety and Licensing Board Panel B2/12/14 GTUCKY.S Docketing & Services Branch ip 16446 039 24X Fiche 50-352.82/12/14/8212160304
- --8212160316 Forwards pages from "Design of Water Intake Structures for Fish Protection." re velocity difference across intake & potential for biofouling even in fresh water MCCOY.R W Interior.Dept of. Fish & Wildlife Service. 82/12/07 BRENNER,L Atomic Bafety and Licensing Board Panel 8pp 16446 040 24% Fiche \$0-352.82/12/14/8212160304
- B212200114 Advises that correspondence re Miller & McCoy testimony in OL proceeding sent to ASLB Portions of transcripts where Miller & McCoy testimony appears or is discussed encl W/o encl HODGDDN, A P Hearing Branch 2 82/12/17 CONTE, A R Interior, Dept of 1p 16470 184 24% Fichs 50-352,82/12/17,6212200114
- 8212230327 Advises of State court 821216 decision reversing Public Utils Commission 820827 order re Unit 2 financing Del-Aware Unlimited Inc preliminary injunction to enjoin work on Point Pleasant Diversion Project denied on 821215 CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co 82/12/17 BRENNER, L. COLE, R F., MORRIB, P A Atomic 8afety and Licensing Board Panel 2pp 16505 136 24% Fiche 50-352,82/12/17, 8212230327

- 8212230352 Informal discovery re Friends of the Earth/RL Anthony Contentions V-3a & V-3b admitted by ASLB on 821122 ANTHONY: R L ANTHONY: R L Friends of the Earth 82/12/17 Athony: R L ANTHONY: R L Friends of the Earth 1651 196 24X Fiche 50-352:82/12/17.8212230352
- B2;2230356 Response to ASLB B21122 order re Friends of the Earth proposed contentions on hazards from industrial activities & motion to reconsider admission of Contentions 1,24,6 B & 9
 ANTHONY, R L Anthony, R L ANTHONY, R L Friends of the Earth B2/12/19 Atomic Bafety and Licensing Board Panel 3pp
 16511 162 24X Fiche 50-352,82/12/19,8212230356
- 8212220097 Forwards DOI 821206 ltr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion Info relates to testimony before ASLB HODGDON, A P Hearing Branch 2 82/12/20 BRENNER, L, MORRIS, PA, COLE, RF Atomic Safety and Licensing Board Panel 11pp 16516 105 24X Fiche 50~352,62/12/20,6212220097
- 8212220126 Advises that NRC will not respond to Del-Aware Unlimited B21201 request for leave to respond to applicant reply on flows in Schuylkill River re need for supplemental cooling water for one unit vs two units HODODON.A P Hearing Branch 2 82/12/20 BRENNER.L, HORRIS, P A COLE.R F Atomic Safety and Licensing Board Panel 3pp 16503 02 24% Fiche 50-352.82/12/20,8212220126
- 8P12270216 Notice re contract award & const starting date Mergentime.
 Inc awarded contract on 921215 to construct Point Pleasant
 intake Non-contention work will begin on 830107 Certificate
 of 8vc & VS Boyer affidavit encl.
 CONNER.T B Philadelphia Electric Co CONNER.T B Conner &
 Wetterhahn 82/12/21 7pp 16536 196 24X Fiche 50-352,82/12/21,
- BP12280185 Forwards US District Court for Eastern District of PA 821217 order dismissing Del-Aware, Inc. claims under Rivers & Harbors Act for lack of jurisdiction
 CONNER, T.B. Conner & Hetterhahn CONNER, T.B. Philadelphia Electric
 Co. 82/12/23 GRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel 4pp. 16556-142 24X Fiche 80-352,82/12/23,8212280185
- B212300187 Response in opposition to Friends of the Earth 821219 motion to reconsider ASLB 821122 order ruling on proposed contentions on hazards from industrial activities near site instant request clearly too late Certificate of Bvc encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn 82/12/28 Atomic Safety and Licensing Board Panel Bpp 16597 330 24% Fiche 50-352,82/12/28,8212300187

K Utility Final Barety Analysis Report (FSAR) & amends

- 8P10040239 Forwards Amend 39 to application for DL (filed at PDR in Category A), consisting of Revision 10 to FSAR (Category K). Revision 6 to environ rept (Category C) & Revision 1 to design assossment rept (Category A)

 BRADLEY,E.J. Philadelphia Electric Co 82/09/30 DENTON,H R

 Office of Nuclear Reactor Regulation, Director App 15589 170

 24X Fichs 50-352,82/09/30,8210040239
- --8210040267 Revision to to FSAR
 * Philadelphia Electric Co 82/09/30 464pp 15889 183 24X
 Fiche 50-352,82/09/30,8210040239
- 8212130341 Forwards Affidavit of Svc re distribution of Revision 13 to FSAR per DG Eisenhut 810706 ltr
 BRADLEY/E J Philadelphia Electric Co 82/12/10 DENTON.H. R
 Office of Nuclear Reactor Regulation, Director 3pp 16387 282
 24% Fiche 50-352,82/12/10.8212130341
- 8212210491 Forwards Amend 43 to license application (filed in PDR Category A).consisting of Revision 8 to environ rept (filed in PDR category C) & Revision 14 to FBAR (filed in PDR Category K) Certificate of Svc encl BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16486 048 24X Fiche 50-352,82/12/17.8212210491
- ~-8212210499 Revision 14 to FSAR * Philadelphia Electric Co 82/12/31 151pp 16486 056 24X Fiche 50-352,82/12/17,8212210491
- 9 Inspection reports. IE Bulletina & correspondence
- 8208190240 IE Bulletin 62-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Strel.Recirculation Sys Piping at BHR Plants "Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28,8208170240

- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list while CGBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/05 consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- 8212070264 Forwards IE Insp Rept 50-352/82-13 on 821004-1114 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/11/23 KEMPER, J S Philadelphia Electric Co 2pp 16339 141 24X Fiche 50-352, 82/11/23, 8212070264
- --8212070265 Notice of violation from insp on 821004-1114 * Division of Project & Resident Programs 82/11/23 ip 16339 143 24% Fiche 50-352,82/11/23,8212070264
- --8212070269 IE Insp Rept 50-352/82-13 on 821004-1114 Noncompliance noted design Drawing OBB-102-H1 revised on 820930 w/o incorporating Field Change Requests M-11 559F & M-11 939F CHAUDHARY.5 X , GRAY.E H , MCCABE.E C Division of Project & Resident Programs 82/11/17 pp 16339 144 24X Ficher 50-352,82/11/23,8212070264
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list and BEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche: 50-000, 82/11/26,8208190256
- 8208190257 [E Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc.! COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bullstin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list enc! DEYOUNG.R C Director's Office Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JORDAN EL Division of Engineering & Quality Assurance, 82/12/03 Consulidated Edison Co of New York, Inc 110pp 16462 064 24; Fiche 50-800,82/12/03,8208190261
- 8208190267 JE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYOUND: R C Director's Office Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000, 82/12/16, 8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edition Co of New York, Inc 108pp 16628 293 24x Fiche 50-000.82/12/20.8208190268
- R. Periodic operating reports & related correspondence
- 8212270276 Reviess 820921 Itr re const completion date.per NRC 810811 request for quarterly updates Const & engineering efforts support earlier const & fuel load date of Aug 1984 BRADLEY.E J Philadelphia Electric Co 82/12/27 EISENHUT.D C. Division of Licensing 2pp 16581 064 24X Fichs 50-052.82/12/27, 8212270276
- 8 Reportable occurrences, LERs & related correspondence
- 8212280363 Interim deficiency rept re inadequate pressure transducers/
 transmitters mounted on post-LOCA hydrogen recombiners
 initially reported on 821117 Final rept will be submitted by
 830211 Also reported per Part 21
 MANNO, 6 F Niagara Mohauk Power Corp 82/12/14 STAROSTECKI,R.
 Division of Project & Resident Programs 2pp 16560.058 24X
 Fichs 50-000,82/12/14,8212280363

- --8212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LBCA hydrogen recombiners Transducers should be replaced w/muclear rated transducers Engineering field bullatin to be issued by 821029 EMPEY, D C Rockwell International Corp 82/10/21 COLLINS, J Region 4. Office of Director 2pp 16560 060 24X Fiche 50-000.82/12/14.8212280363
- T Hearing transcripts on non-antitrust matters
- B212080476 Transcript of 820818 public meeting in Pottstown.PA re environ review Pp 1-132 Supporting documentation encl * NRC - No Detailed Affiliation Given 82/08/18 275pp 1633 035 24% Fiche 50-352.82/08/18.8212080496
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- G210040239 Farwards Amend 39 to application for OL (filed in PDR in Category A)
 BRADLEY, E J Philadelphia Electric Co B2/09/30 DENTON, H R
 Defice of Nuclear Reactor Regulation, Director 6pp 15589 170
 24% Fiche. 30-332, B2/09/30, B210040239
- --8210040253 Amend 37 to application for QL, consisting of Revision 10 to FSAR, proprietary & nonproprietary Revision 1 to design assessment rept & Revision 6 to environ rept Centificate of Evc encl Proprietary design rept withheld (ref 100FR2 770) BOYER, V S Philadelphia Electric Co 82/09/28 7pp 15589 174 244 Fiche 50-352,82/09/30,8210040239
- --8210040272 Revision 1 to nonproprietary design assessment rept
 # Philadelphia Electric Co 82/09/30 228pp 15590 286 24X
 Fiche 90-332, 82/09/30, 8210040239
- BP12050077 Forwards request for add1 auxiliary sys info re Revision 10 to FSAR Response should be provided within 7 days SCHNENCER: A Licensing Branch 2 82/11/17 BAUER: E 9 Philadelphia Electric Co 4pp 16323 016 24X Fiche 50-352. 82/11/17. 8212060077
- B2120&0118 Forwards request for addl info as result of concerns raised during hearing session on Point Pleasant Diversion Project SCHWENCER, A Licensing Branch 2 82/11/18 BAUER, E Q Philadelphia Electric Co 4pp 16323 007 24% Fiche 50-352, 82/11/18, 82120&0118
- 8212040510 Notification of 821217 meeting w/util at Limerick Info Ctr to discuss mgt structure & technical resources audit ABELSON.H Licensing Branch 2 82/11/23 SCHMENCER, A Licensing Branch 2 4pp 14344 014 24X Fichs 50-352,82/11/23,8212040510
- B2J2080015 Not: fication of cancellation of 821217 meeting w/vt:1 at site to discuss plant mgt structure & technical resources audit Meeting will be rescheduled ABELSON:H Licensing Branch 2 B2/11/23 SCHWENCER, A Licensing Branch 2 4pp 16367 173 24X Fiche 50-352,82/11/23,8212080015
- 8212010470 Confirms 821214-17 mgt structure & technical resources audit Agenda encl SCHWENCER.A Licensing Branch 2 82/11/24 BAVER,E 0 Philadelphia Electric Co 5pp 16270 215 24X Fiche 50-352. 82/11/24.8212010470
- G212010513 Forwards EO&O draft technical evaluation rept, "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units 1 & 2." for comment SCHMENCER.A Licensing Branch 2 82/11/24 BAVER, E 0 Philadelphia Electric Co 3pp 16268 168 244 Fiche 50-352, 82/11/24, 8212010513
- --8212010519 "Control of Heavy Loads at Nuclear Power Plants, Limerick Generating Station Units I & 2 " MARINGAS: R , STICKLEY, T H ECRO, Inc 82/11/30 NRC - No Betailed Artijation Given 30pp 16268 171 24X Fiche 50-352,82/11/24,8212010513
- 8212060393 Summary of 820903 meeting w/util, QE, Fauske & Associates, Inc. BNL, NUS. Science Applications. Inc. Commonwealth of PA. Limerick Ecology Action & applicant counsel in Bethesda, MD re PRA ABELSON. H Licensing Branch 2 82/11/29 Licensing Branch 2 47pp 16323 021 24X Fiche 50-352, 82/11/29, 8212060393
- 8212040398 Summary of 820922 meeting w/util.NUTECH & BMNL in Bethesda. MD re present & future corp & plant mgt structure.staffing, training plans & safety review groups ABEL80N:H Licensing Branch 2 82/11/29 Licensing Branch 2 17pp 14322 318 24X Fiche 50-352,82/11/29,8212040398

- 8212030122 Forwards Amend 42 to application for OL Amend revises FSAR in response to NRC 820809 ltr Certificate of 8vc encl BRADLEY.E J Philadelphia Electric Co 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 5pp 16303 283 24X Fiche 50-352.82/11/30.8212030122
- --8212030132 Amend 42 to application for OL, revising FSAR BDYER, V S Philadelphia Electric Co 82/11/29 3pp 16303 288 24X Fiche 50-352,82/11/30,8212030122
- 8212070493 Notification of 821215 meeting w/util & BNL in Bethesda, MD to discuss questions generated during review of BNL draft rept on PRA Heeting agenda encl ABELSON, H Licensing Branch 2 82/12/01 SCHWENCER, A Licensing Branch 2 4pp 16351 355 24% Fiche 50-352,82/12/01,8212070493
- 8212070025 Forwards agreement w/ARCO Pipeline Co prohibiting shipping propane through ARCO pipeline.per C Ferrell concern from Aug 1982 environ site vists
 BRADLEY.E J Philadelphia Electric Co 82/12/03 SCHWENCER.A
 Licensing Branch 2 5pp 16327 349 24X Fiche 50-352,82/12/03.
 8212070025
- 8212080446 Forwards draft response to NRC 820901 request for add1 info to aid E Pedersen audit of util organization BRADLEY.E J Philadelphia Electric Co 82/12/03 SCHWENCER.A Licensing Branch 2 71pp 16352 180 24X Fiche 50-352,82/12/03, 8212080446
- 8212160747 Forwards request for add1 info re pump house noise Corrected numbers for previously submitted E290 series questions resubmitted Response requested within 7 days of 1tr receipt SCHMENCER.A Licensing Branch 2 B2/12/08 BAVER.E G Philadelphia Electric Co 4pp 16466 001 24X Fiche 50-352,82/12/08,8212160747
- 82:222054: Requests test case calculation for radiological risk be provided to facilitate review of PRA Case should be calculated w/version of CRAC computer code used in plant PRA SCHWENCER.A Licensing Branch 2 82/12/13 BAUER.E 9 Philadelphia Electric Co 3pp 16523 337 24X Fiche 50-352, 82/12/13, 82:222054:
- 8212210402 Advises that actual scram valve characteristics will be used in preparing analysis of control rod drive sys hydrodynamic loads Analysis & complete response will be provided by #30315

 BRADLEY,E J Philadelphia Electric Co 82/12/16 SCHWENCER, A Licensing Branch 2 2pp 16494 310 24X Fiche 50-332,82/12/16,8212210402
- 821221047| Forwards Amend 43 to license application (filed in PDR Category A)
 BRADLEY, E J Philadelphia Electric Co 82/12/17 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 16486 048 24)
 Fiche 50-332, 82/12/17, 8212210491
- --8212210475 Amend 43 to license application consisting of Revision 8 to environ rept & Revision 14 to FSAR BOYER.V S Philadelphia Electric Co 82/12/15 6pp 16486 050 24% Fiche 50-302.82/12/17.8212210491
- 87:2220097 Forwards DOI 82:206 itr transmitting Fish & Wildlife Svc correspondence re Point Pleasant diversion Info relates to testinony before ASLS
 HODODON P Hearing Branch 2 82/12/20 BRENNER, L Atomic Safety and Licensing Board Panel i ipp 16516 105 24X
 Fiche 50-382.82/12/20.82:2220097
- B2:2270141 Forwards summary of loss of offsite power comments presented at 82:1215 meeting, compilation of requests for add1 info for BNL re PRA review & summary of comments on remaining issues BOVER, V S Ph(ladelphia Electric Co 82/12/22 EISENHUT, D. O Division of Licensing 83pp 16538 312 24X Fiche 90-352,82/12/22,821227014;
- 8212280209 Forwards responses to Auxiliary Sys Branch Questions 410 94 through 410 99 re spent fuel storage, transmitted by 821122 1tr Responses will be incorporated in FSAR revision scheduled for Jan 1983 BRADLEY, E. J. Philadelphia Electric Co. 82/12/22 SCHWENCER, A Licensing Branch 2 10pp 14562 110 24X Fiche 50-352, 82/12/22, 8212280209
- C Utility Environmental Report (ER), amends & correspondence
- E210040239 Forwards Revision 6 to environ rept (filed in PDR in Category C)
 BRADLEY.E J Philadelphia Electric Co 82/09/30 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 6pp 15589 170
 24X Fiche 50-352.82/09/30.8210040239

- --8210040278 Revision 6 to environ rept

 * Philadelphia Electric Co 82/09/30 20pp 19591 154 24%
 Fiche 50-352, 82/09/30.6210040239
- 8212100274 Advises that response to Siting Analysis Branch Question E310 10 will be provided via environ rept revision in Fab 1983 BRADLEY.E.J. Philadelphia Electric Co. 82/12/07 SCHHENCER.A Licensing Branch 2 2pp 14376 147 24X Fiche 50-352,82/12/07, 8212100274
- 8212210491 Forwards Revision 8 to environ rept (filed in PDR Category C)
 BRADLEY,E J Philadelphia Electric Co 92/12/17 DENTON,H R
 Office of Nuclear Reactor Regulation. Director ip 16486 048 24X
 Fiche 50-352,92/12/17.8212210491
- --8212210498 Revision 8 to environ rept

 * Philadelphia Electric Co 82/12/31 23pp 16486 207 24x
 Fiche 50-352,82/12/17,6212210491
- F. Security, medical, emergency & fire protection plans
- 8212070138 Advises that revised fire protection evaluation rept due by Nov 1982,per 820901 commitment, delayed until Jan 1983 Delay due to substantial, unanticipated addl effort required to upgrade rept per NRC 820728 ltr

 BRADLEY.E J Philadelphia Electric Co 82/12/03 8CHMENCER.A Licensing Branch 2 2pp 16327 032 24X Fiche 50-352,82/12/03,8212070138
- 8212100070 Bubmits info per 821203 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 submitted 810320 EOF const will be completed by Bept 1783 KEMPER.J 5 Philadelphia Electric Co 82/12/06 SCHWENCER, A Licensing Branch 2 3pp 16379 240 24X Fithe 50-352,82/12/06,8212100070
- 8212210398 Forwards Graft FSAR page changes & responses to GA Branch 820713 request for addl info Sixteen oversize drawings enc1 Aperture cards available in FDR BRADLEY.E J Philadelphia Electric Co 82/12/17 8CHHENCER, A Licensing Branch 2 92pp 16489-324 24X Fiche 50-352,82/12/17, 82(22)0398
- 8212270144 Forwards response to NRC comments on physical security plan Response withheld (ref 10CFR2 790 & 10CFR73 21) BRADLEY.E J Philadelphia Electric Co 82/12/17 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 14538 128 24% Ficae 50-352,82/12/17,8212270144
- O Adjudicatory correspondence
- B212020330 Reply findings of fact & conclusions of law in form of initial decision
 CONNER, T B Philadelphia Electric Go CONNER, T B Conner & Wetterhahn B2/11/30 2ipp 16277 279 24X Fiche 50-352,82/11/30, B212020330
- --B212020339 Reply to Del-Aware B21117 response to ASLB request for info re flows in Schuylkill River Response inaccurate & exceeds scope of ASLB limited inquiry Del-Aware is cluttering record w/erroneous & irrelevent mati W/Certificate of Svc CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn. 82/11/29 10pp 16277 300 24x Ficha 50-352,82/11/30.8212020330
- BRI2130358 Notifies that B20702 patition on behalf of Del-Aware Unlimited to suspend or revoke CPs has been denied Decision enc!

 DENTON: HR Office of Nuclear Reactor Regulation, Director 82/12/07 SUGARMAN: R J Sugarman: R J 3pp 14413 008 24X Fiche 50-352.82/12/07.8212130358
- --B212130359 Director's Decision DD-B2-i3 denying Del-Aware Unlimited patition to suspend & revoke CPs No major changes in facts math to resolution of environ issues presented DENTON.H R , GABE, E G Office of Nuclear Reactor Regulation, Director 82/12/07, 42pp 16413,011 24X Fiche 50-352, B2/12/07, 8212130358
- --B212130351 Notice of denial of Del-Aware Unlimited petition to suspend & revoke CPs CASE,E 0 Office of Nuclear Reactor Regulation, Director B2/12/07 3pp 16413 054 24X Fiche 50-382,82/12/07,8212130358

- 8212140036 Forwards NRR Director B21207 denial of Del-Aware Unlimited request for suspension or revocation of CPs per 10CFR2 202 & 2 206 W/o encl HODGDON, A P Heating Branch 2 82/12/10 BRENNER, L, MORRIS, P.A., COLE, R.F. Atomic Bafety and Licensing Board Panel 2pp 16409 293 24X Fiche 50-352.82/12/10.8212140036
- 8212160304 Requests encl DOI 821207 ltr to ASLB be served on parties LANE-V N Atomic Sefety and Licensing Board Panel 82/12/14 BTUCKY.S Docteting & Services Branch 1p 16446 039 24X Fiche 50-352.82/12/14.8212160304
- --B212160316 Forwards pages from "Design of Water Intake Structures for Fish Protection," re velocity difference across intake & potential for biofoulling even in fresh water MCCOY.R W Interior.Dept of, Fish & Wildlife Service 82/12/07 BRENNER.L. Atomic Safety and Licensing Board Panel 8pp 16446 040 24X Fiche 50-352,82/12/14,8212160304
- 8212200114 Advises that correspondence re Miller & McCoy testimony in OL proceeding sent to ASL® Portions of transcripts where Miller & McCoy testimony appears or is discussed encl W/o encl HODODON, A P Hearing Branch 2 82/12/17 CONTE, A R Interior, Dept of ip 16470 184 24X Fiche 50-352,82/12/17,8212200114
- B212230327 Advises of State court B21216 decision reversing Public Vtils Commission 620827 order to Unit 2 financing Del-Aware Unlimited Inc preliminary injunction to enjoin work on Point Fleasant Diversion Project denied on 82/215.

 COMNER.T.B. Conner & Hetterhahn CONNER.T.B. Philadelphia Electric Co. 62/12/17 BRENNER.L., CDLE.R.F., MORRIS.P.A. Atomic Safety and Licensing Board Panel. 2pp. 16505 136 24X Fache 50-392,82/12/17,8212230327
- 8212230352 Informal discovery re Friends of the Earth/RL Anthony Contentions V-3a & V-3b admitted by ASLB on 821122 ANTHONY.R L Anthony. R L ANTHONY.R L Friends of the Earth 82/12/17 Atomic Safety and Licensing Beard Panel Ip 16511 176 24X Fiche 50-352.82/12/17.8212230352
- 8212230356 Response to ASLB 821122 order re Friends of the Earth proposed contentions on hazards from industrial activities & motion to reconsider admission of Contentions 1,2,6,8 & 9 ANTHONY.R L Anthony, R L ANTHONY.R L Friends of the Earth 82/12/19. Atomic Safety and Licensing Board Panel Spp 16511 162 24% Ficher 50-352.82/12/19.8212200356
- 8212220077 Forwards DOI 821206 ltr transmitting fish & Wildlife Svc correspondence re Point Pleasant diversion Info relates to testimeny before ASLB HDDGBON.A P Hearing Branch 2 82/12/20 BRENNER, L, MDRRIB.PA, GOLE-R F Atomic Safety and Licensing Board Panel 11pp 16516-105 24X Fiche 50-352,82/12/20.8212220097
- B212220126 Advises that NRC will not respond to Del-Award Unlimited B21201 request for leave to respond to applicant reply on flows in Schuylkill River re need for supplemental cooling water for one unit vs two units HDD9DDN:A P Hearing Branch 2, 82/12/20 BRENNER.L., MORRIS.P. A. COLE.R.F. Atenic Safety and Licensing Board Panel 3pp 16503-022 24X Ficha 50-352,82/12/20,8212220126
- 8212270216 Notice re contract award & const starting data Hargentime, Inc awarded contract on 821215 to construct Point Pleasant intake Non-contention work will begin on 830107 Certificate of 8vc & VS Bayer affidavit encl CONNER, T. B Philadelphia Electric Co CONNER, T. B Conner & Westerhahn. 82/12/21. 7pp 16536 196 24X Fiche 50-352,82/12/21,8212270216
- B212280165 Forwards VS District Court for Eastern District of PA 821217 order dismissing Del-Aware Inc claims under Rivers & Harbors Act for lack of jurtsdiction CONNER.T. B Conner & Hetterhahn CONNER.T. B Philadelphia Electric Co. 82/12/23 BRENNER.L. COLE.R.F., MORRIS.P.A. Atomic Safety and Licensing Board Panel 4pp 14596-142 24X Fiche 50-352,82/12/23,8212280185
- 8212300187 Response in apposition to Friends of the Earth 821219 motion to reconsider ABLB 821122 order ruling on proposed contentions on hazards from industrial activities near site, instant request clearly too late Certificate of Svc encl, CONNER.T B. Philadelphia Electric Co. CONNER.T B. Conner & Wetterhabn. 82/12/28. Atomic Sefety and Licensing Board Panel Spp. 16597-330. 24X Fichs 80-352.82/12/28.8212300187

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8210040239 Forwards Amend 39 to application for OL (filed at PDR in Category Al. consisting of Revision 10 to FBAR (Category K), Revision 6 to environ rept (Category C) & Revision 1 to design assessment rept (Category A)

 BRADLEY,E J Philadelphia Electric Co 82/09/30 DENTON.H R

 Office of Nuclear Reactor Regulation, Director 6pp 15589 170
 24X Fiche 30-352,82/09/30,8210040239
- --B210040267 Revision 10 to F5AR

 + Philadelphia Electric Co B2/09/30 464pp 19589 183 24X
 F1chs 50-352,82/09/30,8210040239
- 6212130341 Forwards Affidavit of Svc re distribution of Revision 13 to FSAR per DG Eisenhut 810706 ltr BRADLEY,E J Philadelphia Electric Co 82/12/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 16389 282 24X Fiche 50-352,82/12/10,8212130341
- 8212210491 Forwards Amend 43 to license application (filed in PDR Category A).commisting of Revision 8 to environ rept (filed in PDR Category C) & Revision 14 to FSAR (filed in PDR Category K) Certificate of Byc encl
 BRADLEY.E J Philadelphia Electric Co 82/12/17 DENTON.H R
 Office of Notlear Reactor Regulation, Director 1p 14484 048 24x
 Fiche 50-352,82/12/17,8212210491
- --8212210499 Revision 14 to FSAR
 # Philadelphia Electric Co 82/12/31 151pp 16486 056 24x
 Fiche: 50-352, 82/12/17, 8212210491
- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel. Recirculation Sys Piging at BRR Plants "Syr list encl
 DEYGUNO, R C Director's Office. Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 143 24X Fichs 50-000.82/10/28, 8208190240
- B20B190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters" Svc list enc!

 CORB.L. I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fishs 30-000.82/11/05.8208190245
- 8208190251 JE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " 8vc list enc! DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Ca of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8206190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COSB. L I Division of Fuel Facilities: Materials & Safeguards 82/11/30 Consolidated Edison Co of New York. Inc 356pp 16387 028 24X Fiche 50-000. 82/11/30, 8208190257
- 820Bi90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement, 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411-317 24X Fiche 50-000.82/12/03.8208190259
- B208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000:82/12/03.8208190261
- B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc. 127pp. 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 820B19026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20,820B190268

S Reportable occurrences. LERs & related correspondence

- B212280363 Interim deficiency rept re inadequate pressure transducers/ transmitters mounted on post-LOCA hydrogen recombiners Initially reported on 821117 Final rept will be submitted by B30211 Also reported per Part 21 MANNO,S F Niagara Mohawk Power Corp 82/12/14 STAROSTECKI.R Division of Project & Resident Programs 2pp 16560 058 24X Fiche 50-000.82/12/14,8212280363
- --B2122B0373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029 EMPEY.D C Rockwell International Corp 82/10/21 COLLINS, J Region 4. Office of Director 2pp 16560 060 24X Fithe 50-000, B2/12/14, 82122B0363

T Rearing transcripts on non-antitrust matters

9212080496 Transcript of 820818 public meeting in Pottatown, PA re environ review Pp 1-132 Supporting documentation encl 8 NRC - No Detailed Affiliation Given 82/08/18 275pp 16353 035 24X Fiche 50-352,82/08/18.8212080496

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

- 9212300072 Notification of B30104 significant licensee meeting w/util for presentation of GA organizational & functional changes TRIPP.L E Division of Project & Resident Programs B2/12/21 Division of Project & Resident Programs 2pp 14624 280 24X Fiche 50-000, B2/12/21, B212300072
- 8212270135 Advises that Rept 82-138, "Hope Creek Generating Station Recirculation Sys Crack Stability/LLB," contains no proprietary info PARIS,P C Fracture Proof Design Corp 82/12/22 WAGNER, D, Licensing Branch 2 ip 16538 016 24X Fiche 50-354,82/12/22,8212270135
- C Utility Environmental Report (ER), amends & correspondence
- 6212010349 Notification of 821202 meeting w/util.Bechtel & Fracture Proof Design Corp in Bethasda.MD to discuss drywell jet impingement barriers & alternatives re OL environ rept Agenda encl
 MAGNER.D Licensing Branch 2 82/11/26 8CHWENCER.A Licensing Branch 2 4pp 16271 329 24x Fiche 50-354,82/11/26,8212010349.

G Adjudicatory correspondence

- 9212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of 8vc encl.

 JDHNSRUD. JH Environmental Coalition on Nuclear Power 82/12/08
 Commissioners 4pp 16403 167 24% Fiche 50-000,82/12/08, 82/12440186
- BP12140438 Order extending time until B21227 for TM1 & Peach Bottom intervenors to file petition for review of ALAB-701 CMILK.S J Office of the Secretary of the Commission 62/12/13 Environmental Coalition on Nuclear Power 1p 16404 360 24X Fiche 50-000, 82/12/13, 8212140438
- 8312216009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed BORDENICK, B M Hearing Branch 3 82/12/16 JOHNBRUD, J Affiliation Unknown 2pp 16486 005. 24X Fiche: 50-000, 82/12/16, 82
- B212300134 Patition for review of consolidated radon proceedings Commission should grant financial assistance to intervenors, should reopen record on all issues & remand tase for full consideration Certificate of Svc and JOHNSRUD, J H Environmental Coalition on Nuclear Power. 82/12/27 Commissioners. 15pp 16598.112 24X Fiche 50-000.82/12/27, 8212300134

O. Inspection reports, IE Bulletins & correspondence

8208190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Syc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svt list encl
 COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fithe 50-000, 82/11/05, 8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 62/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-00D, 82/11/18,8208190251
- 8212020051 Natification of contract elecution. Task Order 27 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents." awarded to Parameter. Inc WOLLETT. B. Research Contracts Branch FIN 8-1302 82/11/18 BLAHA-J Director's Office, Office of Inspection and Enforcement LOFY.R. NRC No Detailed Affiliation Given 1p 16317 091 24X Fiche 50-354.82/11/18.8212020051
- --8212020057 Ltr contract issuing Task Order 27 to. "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " GUSTAVE.R P. Research Contracts Branch FIN 8-1302 82/11/10 LOFY.R A Parameter, Inc. 4pp 16317 092 24X Fichs 50-35482/11/18-8212020051
- B212020006 Notification of 821207 significant licensee meeting w/util in Hancocks Bridge, NJ to discuss SALP TRIPP.L E Region 1, Office of Director 82/11/19 Region 1, Office of Director. 19 16308 362 24X Fiche 80-354,82/11/19, B212020004
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/20 Consolidated Edism Co of New York, Inc 39App 16387 028 24% Fiche 50-000.82/11/30.8208190257
- B2:12:160024 Responds to IE Bulletin 8:-02. Suppl 1: "Failure of Gate Type Valves to Cluse Against Differential Pressure " All vendors, including NSES supplier confirm that no Westinghouse gate valves used in safety-related applications at facility MARTIN.T J Public Service Electric & Gas Co of New Jersey 82:/12/01 MAYNES, R C Region 1. Dffice of Director 3pp 16446 216 24% Fiche 50-354.82/12/01.82:2160024
- B20B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG:R C Director's Office Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Ficha 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets" Syc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x
 Fiche 50-000, 82/12/03, 8208170261
- S208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enci DEYOUNG.R.C Director's Office. Office of Inspection and Enforcement. S2/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191. 24X Fiche: 50-000, 82/12/16, 8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid Btate AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 243 Fiche 50-000, 82/12/20, 8208190268
- 8212290436 Ack receipt of 821201 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/82-12 STAROBECKIR Division of Project & Resident Programs 82/12/22 MARTIN. T J Public Service Electric & Oas Co af New Jersey 1p 14585 197 24% Fiche 50-354,82/12/22.8212290436
- --8212290444 Responds to NRC 821105 ltr re violations noted in IE Insp. Rept 50-354/82-12 Corrective actions Varglass tie wraps replaced w/Tefzel wraps & motor control ctrs cleaned, removing cut Varglass wraps & strands MARTIN.T.J Public Service Electric & Gas Co of New Jersey 82/12/01 HAVNES.R C Region 1. Office of Director. 3pp. 16585 198 24X Fiche 50-354.82/12/22.8212290436

- R Periodic operating reports & related correspondence
- 8212280067 Advises that const progress approx 58% complete as of Nov 1982 Fuel load date scheduled for Jan 1986
 LANDRIEU.P R Public Service Electric & Gas Co of New Jersey
 82/12/15 TRIPP.L E Division of Project & Resident Programs
 16564 234 24x Fiche 30-354.82/12/15.8212280067
- S Reportable occurrences, LERs & related correspondence
- 8212080502 Deficiency rept re significant const deficiency underestimated annulus pressuritation loads Initially reported on 821028 Independent technical review of design MARTIN T J Public Service Electric & Qas Co of New Jersey 82/11/27 HAYNES, R C Region 1. Office of Director. 2pp 16352 120 24% Fichs 50-334/82/11/27,8212080502
- DOCKET 50-358 HOPE CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8212270135 Advises that Rept 82-138, "Hope Creak Generating Station Recirculation Sys Crack Stability/LLB." contains no proprietary info.

 PARIS.P C Fracture Proof Design Corp 82/12/22 MAGNER.D

 Licensing Branch 2 tp. 16538 016 24X Fiche 30-354,82/12/22,82/12/23
- C Utility Environmental Report (ER), amends & correspondence
- 8212010349 Notification of 821202 meeting w/util.Bechtel & Fracture Proof Design Corp in Bethesda.MD to discuss drywell jet impingement barriers & alternatives re OL environ rept Agenda ent! #AGNER.D. Licensing Branch 2 82/11/26 SCHWENCER.A Licensing Branch 2 4pp 16271-329 24X Fiche 50-354.82/11/26,8212010349
- O Adjudicatory correspondence
- 8212140186 Request for extension of time until 821224 to file petition for review of ALAB-701 Time necessary due to holidays, sickness & vacations Certificate of Byc engl JUNSRUD, JH Environmental Coalition on Nuclear Power 82/12/08 Commissioners 4pp 16403 [67 24X Fiche 50-000,62/12/08, G212140186
- 80:2140438 Order extending time until 82:227 for THI & Peach Bottom intervenors to file petition for review of ALAB-70: CHILK:S J Office of the Secretary of the Commission 82/12/13 Environmental Coalition on Nuclear Pawer Ip 16404 360 24X Fiche. 50-000. 82/12/13.82:2140438
- 8212210009 Advises that intervenor petition for review of ALAB-701 should be served on NRC when filed BORDENICK.B.M. Hearing Branch 3 82/12/16 JOHNSRUD, J Affiliation Unknown. 2pp 16486 005 24X Fishe 50-000.82/12/16. Affiliation Unknown.
- 8212300134 Petition for review of consolidated radon proceedings Commission should grant financial assistance to interveners, should reopen record on all issues & remand case for full consideration Certificate of Svc encl. JOHNSRUD.J H Environmental Coslition on Nuclear Power. 82/12 Commissioners. 13pp 16593.112 24X Fiche 50-000,82/12/27. 8212300134
- G. Inspection reports. IE Bulletins & correspondence
- BR09190240 IE Bulletin B2-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel. Recirculation Sys Piping at BWR Plants." Byc list encl DEYOUND. R G Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000. B2/10/28. 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters." Svc list
- COBB.L I Division of Fuel Facilities, Materials & Bafeguards B2/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142. 24X Fiche-50-000, B2/11/05, B208190845
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance. 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199. 24) Fiche 50-000, 82/11/18, 9208190251.

- B20B190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24x Fiche 50-000,82/11/26,8208190256
- 820B190287 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl ^ Svc list encl COBB.L.1 Division of Fuel Facilities, Materials & Gafeguards 82/11/30 consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fichs 50-000,82/11/30,8208190257
- 8P12160024 Responds to IE Bulletin 81-02. Buppl 1, "Failure of Gate Type Valves to Close Against Differential Pressure " All vendors, including N858 supplier confirm that no Westinghouse gate valves used in safety-related applications at Pacility MARTIN, T J Public Service Electric & Gas Co of New Jersey 82/12/01 HAYMESR C Region 1, Office of Director 3pp 16446 216 24X Fiche 50-354,82/12/01.8212160024
- 8208190259 RE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Bvc list and DEYQUNO, R C Director's Office Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E. L. Division of Engineering & Quelity Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000.82/12/03,8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYDUNG:R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24% Fiche 50-000,82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Tupe ITE-27 " Svc list encl
 JORDAN,E L Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190248
- 8 Reportable occurrences. LERs & related correspondence
- 8212080502 Deficiency rept re significant const deficiency underestimated annulus pressurization loads Initially reported on 821028 Independent technical review of design calculations performed

 MARTHUT J Public Service Electric & Gas Co of New Jersey

 82/11/29 HAYNES,R C Region 1, Defice of Director 2pp

 16352 120 24% Fiche 50-354,82/11/29,8212080502
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR Q Inspection reports, IE Bulletins & correspondence
- 8212140396 Forwards IE Safeguards Insp Repts 50-151/82-01,50-356/82-02 & 70-0258/82-01 on 621117-19 & notice of violation Insp rept details withheld fref 10CFR2 790; MILLER, J R Division of Engineering & Technical Programs 82/12/09 MILEY, O H Illinois, Univ of, Urbana-Champaign 2pp 16404 344 24X Fiche 50-151,82/12/09,8212140396
- --8212140399 Notice of violation from insp on 821117-19 MILLER, J R Division of Engineering & Technical Programs 82/12/09 1p 16404 346 24X Fiche 50-151,82/12/09,8212140396
- --8212140414 IE Safeguards Insp Repts 50-151/82-01.50-356/82-02 & 70-0258/82-01 on B2117-17 Noncompliance noted failure to include items containing BNN on annual inventory & to submit 742 forms Details withheld (ref 10CFR2 790) MADEDA: T J . CREED. J R Division of Engineering & Technical Programs 82/12/06 ip 16404 347 24% Fiche 50-151,82/12/09,8212140396
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 82i1230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBWR, Big Rock Point Dresden i. Humboldt Bau, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 & VC list encl W/o stated encl EISENHUT, D Ø Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16/387 004 24X Fiche 50-000, 82/11/15, 8211230066

- 8012010089 Application to amend CPPR-88, extending const completion date to 841231 to permit resolution of quality confirmation program deficiencies noted in 810408 immediate action ltr & 811124 notice of violation & to resolve mpd & 80 concerns BORGMANN, E A Cincinnati Gas & Electric Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 16260 272 24X Fiche 50-358.82/11/24,8212010089
- 8212010530 Staff requirements memo re Commissioners 821123 affirmation/discussion & vote in Washington.DC on 8ECY-82-449 & SECY-82-425 Petition to disqualify NRC atty from Zimmer proceeding denied CMILK.S J Office of the Secretary of the Commission 82/11/24 Office of the Secretary of the Commission 2pp 16270 268 24X Fiche 50-358.82/11/24.8212010530
- B212020004 Summary of B21103 meeting w/util in Bethesda.MD re environ qualification rept for Class IE equipment NRC requested conditionally qualified equipment be qualified XINTNER.L L. Licensing Branch 1 B2/11/24 Licensing Branch 1 App 16317 085 24X Fiche 50-358.82/11/24.8212020004
- 8012030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to BO Eisenhut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT, D O Division of Licensing 82/11/24 PALLADING, N J Commissioners 2pp 16316 240 24X Fiche 50-000,82/11/24,8212030953
- --B212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations usil assist in evaluation VOLLMER.R H Division of Engineering B2/09/30 EISENHUT.D Q Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24,82/2030253
- SP12070458 Forwards request for addl info to be submitted to Mechanical Engineering Branch in form of revision to FSAR & to Equipment Qualification Branch in form of revision to 820716 environ qualification rept Response due in 7 days YOUNGBLOOD, B J Licensing Branch 1 82/11/29 BDRGMANN, E A Cincinnati Qas & Electric Co Spp 16355 348 24% Fiche 50-358, 82/11/29, 8212070458
- 8P12020256 Forwards 50 oversize P&ID drawings.per Revision 89 of FSAR, scheduled for submittal on 821203 Drawing revision list encl Aperture cards are available in PDR ARHONDI.P J Sargent & Lundy, Inc. 82/11/30 DICK.0 NRC No Detailed Affiliation Given 5pp 16279 133 24% Fiche 50-358,82/11/30,8212020256
- 9212140335 Responds to 921118 ltr & 921122 revision requesting concurrence prior to performing 16 activities Clarifies activities considered nonsafety-related & others needing approval on case-by-case basis XEPPLER.JO Region 3. Office of Director 82/11/30 BORGMANN.E A Cinctineati Gas & Electric Co 3pp 16402 001 24X Fiche 50-358.82/11/30.8212140335
- --B212140340 Requests concurrence prior to performance on nonconst items under B21i12 show cause order for immediate suspension of essential const DDROMANN.E A Cincinnati Gas & Electric Co B2/11/18 KEFFLER, J O Region 3, Office of Director 2pp 16402 004 24X Fiche 50-358,82/11/30,8212140335
- ~-B212140342 Requests deletion of Items 9 & 15 from B21118 ltr as items do not constitute physical const as covered by show cause order BOROMANN.E A Cincinnati Gas & Electric Co B2/11/22 KEPPLER.J O Region 3, Office of Director 2pp 16402 006 24X Fiche 50-358,82/11/30,8212140335
- 8212090094 Amend 142 to DL application, consisting of Revision 89 to FSAR
 BORGMANN, E.A. Cincinnet: Gas & Electric Co. 82/12/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 16358 001 24X fiche 50-358, 82/12/03, 8212090094
- BP12170080 Forwards Certificate of Byc of Amend 142 to DL application, in form of Revision 87 to FSAR
 BORGMANN,E A Cincinnati Qas & Electric Co 82/12/10 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 2pp 14453 009
 24X Fichs 50-358,82/12/10,8212170080
- 8212270424 Forwards comments on Bechtel 821123 proposal to perform independent review of util mgt required by Commission G21112 Order CLT-82-33 EISENHUT, D.G. Division of Licensing 82/12/16 KEPPLER, J.G. Region 3. Office of Director 3pp 16589 297 24X Fiche 50-358, 82/12/16,8212270424

- --8212270429 Requests comments on util 821126 request for approval of Bechtel as independent reviewer to fulfill requirements in Commission 821112 show cause order KEPPLER. J Ø Region 3. Office of Director 82/12/02 CUNNINOHAM. O K Office of the Executive Legal Director DENTON. H R Office of Nuclear Reactor Regulation, Director DEYOUND. R C Director's Office, Office of Inspection and Enforcement ip 16589 300 24X Fiche 50-338,82/12/16.8212270424
- --8212270434 Proposes Rechtel as independent reviewer per Commission 821112 show cause order requirements & transmits program for independent review of mgt DICKHONER. H H Cincinnati Gas & Electric Co 82/11/26 KEPPLER. J G Region 3. Office of Director 64pp 16587 301 24X Fiche 50-358, 82/12/16, 8212270424
- B212290420 Responds to B21012 ltr re position on conduct of selfinitiated audit of engineering & const programs Details of audit plan in lieu of self-initiated glan requested WARNICK,R F Region 3. Office of Director 82/12/27 BOROMANN,E A Cincinnati Oas & Electric Co 2pp. 16585 192 24X Fiche 50-358, 62/12/27, 8212290420
- --8212290425 Informs that INPO self-initiated audit will not be conducted at facility Double insp & in-house audits planned BORDMANN.E A Cincinnati Gas & Electric Co 82/10/12 KEPPLER.J Q Region 3. Office of Director ip 18585 174 24X Fiche 50-358,82/12/27.8212290420
- F Security, medical, emergency & fire protection plans
- 82:2070027 Releases public version of revised emargency plan & revision to "Design Submittal Emergency Response Factilities"

 FELTON, J M Division of Rules and Records 82/12/02, Document Management Branch 1p 16385 197 24X Fiche 50-358, 82/12/02, 82/12/00027
- --B212070028 Forwards public version of Revision 2 to emergency plan & Revision 1 to "Design Submittal Emergency Response Facilities"

 BGROMANN-E A Cincinnati Gas & Electric Co B2/11/19
 DENTON-H R Office of Nuclear Reactor Regulation, Director App 16395 198 24X Fiche 50-358, 82/12/02,8212070027
- --8212090031 Public version of Revision 2 to emergency plan * Cincinnati Gas & Electric Co 82/11/30 397pp 16385 202 24x Fiche 50-358.82/12/02.8212090027
- --8212090034 Public version of Revision 1 to "Design Submittal ~ Emergency Response Facilities "
 * Cincinnati Cas & Electric Co * Columbus & Southern Ohio Electric Co * Dayton Power & Light Co 82/08/31 125pp 16386 239 24X Fiche 50-358,82/12/02.8212090027
- 8212080472 Confirms 821202 telcon to L Kintner re emergancy preparedness review Response to Deneric Ltr 81-10 sent on 810612 Permanent primary emergency operations facility described BORGMANN.E A Cincinnati Gas & Electric Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 16352 256 24X Fithe 50-358, 82/12/03, 8212080472
- 8212080001 Forwards Meterology & Effluent Treatment Branch request for add1 info re gaseous effluent transport to continue OL application review FBAR amend requested by 830601 YOUNGBLOOD, B J Licensing Branch 1 82/12/06 BORGMANN, E A Cincinnati Oas & Electric Co 4pp 16368 302 24% Fiche 50-358, 82/12/06, 82120800001
- B21221054: Releases public version of Revision 2 to emergency plan & Revision 1 to "Design Submittal Emergency Response Facilities"

 FELTON.J M Division of Rules and Records B2/12/10 Document Management Branch 1p 16502 270 24X Fichs 50-358, 82/12/10.
 B212210541
- --B212210545 Forwards public version of Revision 2 to emergency plan & Revision 1 to "Design Criteria Emergency Response Facilities " W/o encl BOROMANN.E A Cincinnati Oas & Electric Co B2/11/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp. 16502, 271 24% Fiche 50-358, B2/12/10, 8212210541
- B212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J. & Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000,82/12/16.
 821220306

G Adjudicatory correspondence

- B212010040 Ack receipt of 821103 itr estimating completion date of FEMA final finding per 44CFR350 Ltr forwarded to ASLB & parties Estimate of interim findings of sufficient finality requested TREBY. B A Hearing Branch | B2/11/30 CASSIDY. B Federal Engagement Agency | 10 16260 333 24X Fiche 50-358. B2/11/30. B212010040
- G212020362 Response supporting Zigmer Area Citizens Zigmer Area Citizens of KY & City of Mentor, KY 821117 petitions for appointment of consultant to monitor third party audit & for public participation procedures Certificate of Svc enci DEVING, T. BERNASEI. L. Miami Valley Power Project 82/11/30 Commissioners 9pp 16278 104 24X Fiche 50-358,82/11/30, B212020382
- 8212070184 Resolution of City of Mentor, KY in support of ZAC/ZACK & City of Mentor 821119 joint intervention petition Public participation necessary ingredient in maningful attempt to resolve difficulties Certificate of Svc encl STRASINGER.R. YOUNG, G Mentor, KY 82/12/02 3pp 16335 259 24% Fiche 30-350.82/12/02.8212070184
- 6212080288 Answer opposing Zimmer Area Citizens/Zimmer Area Citizens of KY 821119 petition for appointment of consulting firm to review & manitor third-party audit Commission considered same grounds in issuing CLI-82-38 M/Certificate of Svc METTERNAHINH J Cancinnati Oas & Electric Co METTERNAHINH J Connex & Metterhalm 82/12/06 Commissioners 12pp 16354 213 24X Fiche 50-358.82/12/06,8212080288
- B212090073 Answer consenting to Commission B21112 show cause order a order immediately suspending const Consent should not be taken as admission of truth of factual assertions or conclusions in order Certificate of Svc enci
- 8212090222 Response to applicant brief supporting applicant revised escaptions ASLB erred in determining further proceedings of evacuation of schools in Clermont & Campbell Counties necessary Certificate of Sev and BARTH.C A Hearing Branch I 82/12/08 Akomic Safety and Licansing Appeal Panel 42pp 16363 037 24X Fiche 50-358, 82/12/08, 8212090222
- B212140205 Memorandum supporting Zimmer Area Citizens-Zimmer Area Citizens of KY & City of Mentor KY B21119 petition for appointment of consulting firm to review & monitor third-party audit Certificate of Svc enc. | HOLIVER.J Frankhauser.D D HOLIVER.J Holiver.J D 82/12/10 Commissioners 4pp 16408 332 24X Fiche 50-358,82/12/10,
- B212130032 Order scheduling B30110 oral argument on applicant appeal from ASL8 B20-21 initial decision & from B20824 memorandum & order in Bethasda: MD Each side allocated 90 minutes BHOEMAKER.C J Atomic Bafety and Licensing Appeal Panel B2/12/13 Jpp 16421 243 24X Fichs 50-358.82/12/13.8212150032
- 82(2)60241 Errata to NRC response to applicant brief supporting applicant exceptions Certificate of Svc encl BARTH, C.A. Hearing Branch 1 82/12/15 Atomic Bafety and Licensing Appeal Panel 3pp 16446-126 24X Fiche 50-358,82/12/15, B212160241
- 8212200089 Answer opposing Himmi Valley Power Project 821130 petition to establish detailed structure for public participation through audit Intervenor fails to demonstrate process necessary to carry out NRC goals Certificate of Svc encl METTERHANN, N. J. CINCINNATI Gas & Ejectric Co. METTERHANN, M. J. Conner & Metterhahn. 82/12/16. Commissioners. 7pp. 16473 297 24X Fichs 50-358,82/12/16,8212200089
- B212230357 Notice of oral argument on application for appeal from ASLB B20521 initial decision & 820524 memorandum & order Argument will be heard on 830110 in Bethesda, MD SHDEHAKER, C.J. Atomic Safety and Licensing Appeal Panel 82/12/21 is 16511 203 24X Fiche 50-358.82/12/21, 8212230367
- 8212280[9] Advises that M Sinclair will not respond to applicant 821210 objections to interrogatories prior to completion of NRC investigation of Zimmer Area Citizens of KY issues BISHOP.L L Harmon & Weiss BISHOP.L L Sinclair, M 82/12/21 BECHMOEFER.C , HARBOUR.J , COMAN.F.P Atomic Safety and Licensing Board Panel ip 16562 303 24X Fichs 50-338,82/12/21,8212280191

- 8212300244 Staff requirements memo summariting 821216 affirmation/discussion & vote in Washington.DC re-citizens petition for consulting firm svcs to monitor procedures instituted per show cause order Petition denied CHTLK.5 J Office of the Secretary of the Commission 82/12/22 Office of the Secretary of the Commission 82/12/22 Fiche 50-358.82/12/22.9212300244
- 8212270241 Order CLI-82-40, denying Zimmer Area Citizens/Zimmer Area Citizens of KY 821119 motion to have util provide svcs of consulting firm to monitor procedures per Order CLI-82-33 & motion for review of independent antity selection CHILK, 8 J Office of the Secretary of the Commission 82/12/23 Zimmer Area Citizens 2 Ky 5pp 1653/15/24X Fiche 50-358,82/12/23.8212270241
- 8212280129 Supplemental memorandum in support of Miami Valloy Power Project 820820 petition for reconsideration of Commission 820730 order & motion for notification of all future third-party communications Certificate of Svc encl DEVINC. T B. 8ERNABEL: L. Miami Valley Power Project DEVINE, T B. 9overnment Accountability Project 82/12/23 Commissioners 24pp 16564 035 24X Fiche 50-358.82/12/23,8212280128
- H General correspondence
- 8212270315 Add1 response to FOIA request for tape recordings of interviews w/F Dit: on 810225 & OSDA & any other recordings re facility investigation forwards Magnaflux Corp tape & disclaimer re Applegate/Alldredge side of tape W/o encls FELTON.J M Division of Rules and Records 82/11/16 HICKEY, J P Bhaw. Pittman. Potts & Troubridge 1p 15555 321 24x Fiche 50-358.82/11/16.8212270315
- J Insurance & Indomnity information
- 8212280205 Forwards Endorsement 21 to NELIA Policy NF-247 BUCKLES, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 82/12/20 SALTZMAN, J. Office of State Programs, Director 2pp 16562 287 24X Fiche 50-358,82/12/20,8212280205
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8212070074 Amend 142 to OL application, consisting of Revision B9 to FBAR BOROMANN,E A Cincinnati Ques & Electric Co. 82/12/03 DENTON-H R Office of Nuclear Reactor Regulation, Director 2pp 16398 001 24X Fiche 50-358,82/12/03,8212070074
- --8212090096 Revision 89 to FSAR d Cincinnati Oas & Electric Co 82/12/31 167pp 16358 003 24X Fiche 50-358,82/12/03,8212090094
- 8212170080 Forwards Certificate of Svc of Amend 142 to DL application, in form of Revision 89 to FBAR
 BOROMAN,E A Cincinnet(20% Electric Co 82/12/10 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16453 009
 24X Fiche 50-388,82/12/10,8212170080
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 62-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNGR C Director's Office Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- B20B190245 IE info Notice B2-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encil COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 24X Fiche 50-000, 82/11/05, 820B190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199, 24X Fiche 50-000, 82/11/18, 8208190251
- 8212010089 Application to amend CPPR-BB, extending const completion date to 841231 to permit resolution of quality confirmation program deficiencies noted in 810408 immediate action it & 811124 notice of violation & to resolve mpt & GA concerns BORGMANN, E A Cincinnati Gas & Electric Co 82/11/24 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 16260 272 24X Fiche 50-358,82/11/24,8212010089

1

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000,82/11/26,8208190256
- 8708190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COB8.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8212040025 Ack receipt of 820721 & 0816 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 30-398/82-05 MARNICK, R F. Region 3, Office of Director 82/11/30 BORGHANN, E.A. Cincinnati Gas & Electric Co. 1p 16313 327 24X Fiche 50-358, 82/11/30. 8212060025
- --8212060030 Responds to NRC 820701 ltr reviolations noted in IE Insp Rept 50-358/82-05 Corrective actions notification of potentially reportable item forms received prior to violation reviewed & 64 procedures revised BORGMANN.E A Cincinnati Oas & Electric Co 82/07/21 KEPPLER. J O Region 3. Office of Director 2pp 16313 330 24X Fiche 50-358,82/11/30,8212060025
- --8212060037 Supple 820721 response to NRC 820701 ltr re violations noted in IE Insp Rept 50-358/82-05 Addl training will be provided for site personnel re reporting requirements of 10CFRSO 55(e) Training to be completed by 820930 BORGMANN. E A Cincinnati Oas & Electric Co 82/08/14 KEPPLER. J G Region 3, Office of Director 2pp 16313 332 24X Fiche 50-358,82/11/30,8212040025
- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEVDUNO,R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- BROBI90261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " 8vc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24; Fiche 50-000, 82/12/03, 8208190261
- 8212210027 Ack receipt of 820506 ltr supplementing 800506 response to IE Insp Rept 50-358/80-05 All required GC insps & evaluations/dispositions must be completed prior to initiating design document change NCRELIUS.C E Division of Engineering & Technical Programs 82/12/15 BORGMANN.E A Cincinnati Gas & Electric Co 2pp 14486 001 24X Fiche 50-358/82/12/15/8212210027
- --B212R10031 Supple 800506 ltr responding to violations noted in IE Insp Rept 50-358/80-09 All design document changes will receive B&L Engineering site approval under existing procedures prior to final acceptance BORGMANN.E A Cincinnati Qas & Electric Co 82/05/06 KEPPLER, J O Region 3. Office of Director 2pp 16486 003 24X Fiche 50-358, 82/12/15.821221002F
- 8208190268 IE Info Notice 92-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- 8212280166 Notifies that use of generic nonconformance repts conforms w/820929 commitment to perform 100% review of surveillance & nonconformance repts written by contractor Evaluations of exception correction notices ensure initiation of repts WARNICK, R F Region 3, Office of Director 82/12/23 BORGMANN, E. A Cincinnati Cas & Electric Co 2pp 16563 332 24% Fiche 50-358, 82/12/23, 8212280166
- --8212280171 Submits summary of 820702 agreements re document reviews Quality confirmation program personnel should perform review after NJ Kaiser review of action items Quality confirmation personnel will review correction notices ROROMANNE A Cincinnati Gas & Electric Co 82/09/29 KEPPLER. J O Region 9. Office of Director 1p 16569 334 24X Fichs 50-358,82/12/23,8212280166

- 8212290341 Ack receipt of 820812 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-03 WARNICK.R F Region 3. Office of Director 82/12/27 BOROMANN.E A Cincinnati Cas & Electric Co 1p 16586 184 24X Fiche 50-358. 82/12/27.8212290341
- --B212270343 Responds to IE Imsp Rept 50-358/82-03 Completion dates for committed actions clarified & supplemental info provided BOROMANN.E A Cincinnati Oas & Electric Co 82/08/12 KEPPLER.J O Region 3. Office of Director 3pp 16586 185 24x Fiche 50-358,82/12/27,8212270341
- 8212290381 Ack receipt of 820804 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-358/82-01 MARNICK,R F Region 3, Office of Birector 82/12/27 BORGMANN,E A Cincinnati Gas & Electric Co 2pp 16585 158 24X Fiche 50-358,82/12/27.8212290381
- --8212290429 Documents 620721 telcon re response to 1E lnap Rept 50-358/82-01 Response will be submitted by 820806 per agreement w/NRC Delay needed due to extensive evaluation required to address Commission concerns BOROMANN, E. A. Cincinnati Gas & Electric Co. 82/08/02 KEPPLER, J. G. Region 3, Office of Director 1p 14585 160 24X Fiche 50-358,82/12/27,8212290381
- --8212270454 Responds to NRC 820624 ltr re violations noted in IE Insp. Rept 50-358/82-01 Corrective actions GA job descriptions re-evaluated & qualifications & procedures for cable pulling & wire termination insps revised BORGMANN.E A Cincinnati Gas & Electric Co 82/08/04 KEPPLER.J 9 Region 3 Office of Director 16pp 16585 161 24X Ficha 50-358.82/12/27.8212290381
- R Periodic operating reports & related correspondence
- 8212170107 Advises that project is 98 27 complete as of 820928 Actual dates & activity status encl
 BURGMANN.E A Cincinnati Gas & Electric Co 82/10/26 KEPPLER.J G Region 3. Office of Director App 16450 305 24X
 Fiche 50-358
- 8212170191 Advises that project considered 98 3% complete as of 821026 Actual dates & activity status encl BOROMANN.E A Cincinnati Gas & Electric Co 82/11/09 KEPPLER.J G Region 3, Office of Director 6pp 16450 178 24% Fiche 50-358.82/11/09.8212170191
- 8212080595 Forwards monthly status rept for Oct 1982 DIRCKS,W J. Office of the Executive Director for Operations 82/12/03 PALLADINO,N J. Commissioners ip 16372 259 24X Fiche: 30-385, 82/12/03, 8212080593
- --8212080597 "Zimmer Monthly Status Rept." Oct 1982 # Region 3. Office of Director 82/10/31 37pp 16372 260 24X Fiche 50-358,82/12/03,8212080595
- S Reportable occurrences. LERs & related correspondence
- B212020367 Interim deficiency rept re failure of fusible links in fire dampers mfg by Air Balance. Inc Initially reported on 821029 Engineering evaluation continuing Next rept will be submitted by 830131
 BORGMANN. E A Cincinnati Oas & Electric Co 82/11/16 KEPPLER. J G Region 3. Office of Director 2pp 16278 140 24X
 Fiche 50-358, 82/11/16.8212020367
- B212020225 Interim deficiency rept re discrepancies in dynamic analysis in small bore piping Initially reported on 821026 Audit of simplified dynamic analysis procedures continuing Next rept will be submitted by 830228
 BQROMANN.E A Cincinnati Gas & Electric Co 82/11/19 KEPPLER, J. G Region 3. Office of Director 2pp 16274 092 24X
 Fiche 50~358,82/11/19,8212020225
- B212020257 Interim deficiency rept re seismic clearance Initially reported on 821029 Insp procedure for pipe support istallation does not contain proper seismic clearance criteria Walkdown to be performed Next rept due by 830731 BOROMANN.E A Cincinnati Oas & Electric Co 82/11/19 KEPPLER.J.O Region 3. Office of Director. 2pp 16279.319 24% Fiche 50-358.82/11/19.8212020257
- B21R030111 Interim deficiency rept re GE panel installations Condition not reportable per 10CFR50 55(e) or Part 21 Plant safety not compromised. Separation requirements not necessary Final rept expected by 830117
 BORGMANN.E A. Cincinnati Oas & Electric Co 92/11/19 KEPPLER. J Q Region 3, Office of Director 2pp 16303 025 24% Fiche: 50-358, 82/11/19.8212030111.

- 8212020320 Interim deficiency rept re failure to provide procedures for installation of non-Class IE cables in panels Initially reported on 821027 Stop work order issued & procedures will be revised Next rept expected by 830131 BORGMANN.E A Cincinnati Cas & Electric Co 82/11/24 KEPPLER, J G Region 3, Office of Director 2pp 16279 196 24X Fiche 50-358, 82/11/24, 8212020320
- 82:2170260 Interim deficiency rept re lack of pipe bend qualifications Initially reported on S21:09 HJ Kaiser mechanical const procedure revised to allow requalification of bending operations final rept by 830:31

 BORGMANN, E A Cincinnati Ons & Electric Co 82/12/09 KEPPLER, J G Region S. Office of Director 2pp 16456 204 24X

 Fiche 50-358.82/12/08.8212170260
- 8212270190 Interim deficiency rept relact of insprecords for Nelson stude investigation re-structurel adequacy of stude used on installed cable tray supports almost complete Rept detailing glans for verification of support integrity due by 821222 BOROMANN.E A Cincinnati Cas & Electric Co 82/12/15 KEPPLER.J Q Region 3, Office of Director 1p 16539 302 24X Fiche 50-358,82/12/15,8212270190
- 8212290277 Followup to finel deficiency rept re svc water sys mode Due to delay at vendor facility.pump will not be returned to site until 830331 BDROMANN.E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER, J & Region 3, Defice of Director I p 16581 066 24X Fiche 50-258, 82/12/20, 8212290277
- 8212290364 Deficiency rept re M-71 work package control Initially reported on 821126 Condition determined not reportable under 10CFR50 55(e) as communicated in 821220 telcon Add1 info available in GA dept.
 BURGMANN.E A Cincinnati Gas & Electric Co 82/12/20 KEPPLER.J O Region 3. Office of Director ip 16586 164 24X Fiche 50-358.82/12/20.6212290364.
- 8212290397 Interim deficiency rept to potential M-50 masking of rejectable discontinuities in radiographs of weldments by as-welded surface conditions Radiographs will be reviewed for proper quality & interpretation by 830331 BOROMANNE A Cincinnati Cas & Electric Co 82/12/20 KEPPLER, J G Region 3. Office of Director ip 16586 271 24X Fiche 50-358.82/12/20.8212290397
- 8212290438 Supplemental final deficiency rapt re potential overpressurization of RHR sys piping inboard & outdoard isolation valves.previously submitted in 820525 ltr Valvauill be delivered by 830401 & work completed by 830430 BOROMANNE A Cincinnati Cas & Electric Co 82/12/20 KEPPLER.J G Region 3. Office of Director 2pp 14585 177 24X Fiche 50-358.82/12/20.8212290438
- 8212290467 Final deficiency rept re discrepancies in simplified dynamic analysis of small hore piping const fritially reported on 821026 Corrective actions verified & accepted Final designs found within allowable limits BORGMANN.E A Cincinnati Oas & Electric Co 82/12/20 KEPPLER, J G Region 3, Office of Director 2pp 16585 217 24X Fiche: 50-358, 82/12/20.8212290467
- 8212290493 Interim deficiency rept re seismic qualification of essential HVAC damper mounting brackets American Warming & Ventilation Co resubmitted modified Sergent & Lundy design drawings, Followup rept will be submitted by 630228 BDRCMANN, E A. Cincinneti Ges & Electric Co 82/12/20 KEPPLER. J G Region 3. Office of Director 2pp 16593 253 24X Fiche 30-358, 82/12/20, 8212290483
- 8212290342 Interim deficiency rept re lack of insp records for Nelson studs Small base metal defect in embed plate discovered Random studs will receive test loading which will exceed AWS DI I requirements. NRC approval for testing anticipated BORRMANN.E A Cincinnati Gas & Electric Co 82/12/21 KEPPLER.J G Region J. Office of Director 2pp 16586 234 24X Fiche 50-358,82/12/21,8212270342
- 8212290285 Interim deficiency rept re GA program When NRC approval obtained to perform mgt reviews & when const & GA mgt recommendations accepted, definite schedule for quality confirmation program completion will be submitted BORGMANN.E A Cincinnati Gas & Electric Co. 82/12/23 KEPPLER, J G Region J, Dffice of Director. 10. 16581 114 24X Fiche 50-358, 82/12/23, 8212290285
- T Hearing transcripts on non-antitrust matters
- 8212020226 Unofficial transcript of 821123 affirmation/discussion & vote in Washington.DC re SECY-82-425 & SECY-82-449 e Commissioners 82/11/23 8pp 14308 193. 24x Fichs 50-000.82/11/23,8212020226

- 8212290254 Unofficial transcript of Commission 821216 affirmation/ discussion & vote in Washington.DC on SECY-82-474A re independent review of facility Pp 1-9 • Commissioners 82/12/16 10pp 16606 266 24X Fiche 50-358.82/12/16.8218290254
- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located sub. It a Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 62/11/03 GALLO, J Itham. Lincoln & Beate 2pp 16433 354 24% Fiche 50-000, 82/11/03, 8212140001
- --7912170426 Notifies of info required from applicant re independent confirmatory piping analysis BOSNAK R J Mechanical Engineering Branch 79/12/06 RUBENTEIN. L Light Water Reactors Branch 4 2pp 16435 014 24X Fiche 50-000
- --8003310092 Suggests review of existing high resolution seismic profiling to define possible Christianitos-Offshare Deformation Zone USGC to assist JACKSGN.R E Geosciences Branch 80/03/18 KNIGHT J P Assistant Director for Engineering Ip 16434 258 24X Fiche 50-000.82/11/03.8212140001
- --8005050726 "Vertical Spectra from 1979 Imperial Earthquake " * Southern California Edison Co 80/03/31 24pp 16435 021 24% Fiche 50-000.82/11/03.8212140001
- --8007180114 Forwards NRC formal question, requesting that util perform symbol of estimated earthquake ground motion for Unit 1 based on deterministic modeling & ground motion for Units 2 & 3. based upon ampirical evaluation GARDONE. A T Quesciences Branch 80/06/11 DAVIS. J California. State of 1p 16434 257 24X Fiche 50-000, 82/11/03, 8212140001
- --8007230260 Forwards transcripts of 800520-21 meetings w/licensee reneed for addl offshore seismic profiles W/o and CARDONE.A T Geosciences Branch 80/06/04 AMIMOTO.P California, State of 1p 16435 052 24% Fiche 50-000.82/11/03.8212140001
- --8010150236 Request for procurement NRR-80-143 to award sole source contract to JE Luco for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station"

 VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04
 7pp 16435 087 24% Fiche 50-000.82/11/03,8212140001
- --8010150242 Requests for procurement NRR-80-145 to award sole source contract to R Hermann for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station"

 VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04

 7pp 16435 065 24X Fiche 50-000, 82/11/03, 8212140001
- --8010150246 Request for procurement NRR-80-144 to award sole source contract to K Aki for "Followon to Bimulation of Earthquake Oround Motions for San Onefre Nuclear Generating Station VOLLMER, R H Division of Engineering FIN 8-6898-0 80/08/04 7pp 16434 247 24X Fichs 80-000.82/11/03.8212140001
- F. Security, medical, emergency & fire protection plans
- 8212210197 Forwards JE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No nancompliance noted BISHOP.T W Division of Resident. Reactor Project & Engineering Programs 82/12/02 PAPAYL. T Southern California Edison Co 2pp 16484 317 24X Fichs 50-361.82/12/02.8212210197
- --8212210204 IE Insp Repts 50-361/82-36 & 50-362/82-27 on 821101-05 No noncompliance noted. Major areas inspected fire protection/ prevention program & program inplementation SCOWN.K.M., ZMETZIO.6 B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fichs 50-361,82/12/02,8212210197
- 8212060228 Forwards IE Safeguards Insp Rept 50-361/82-35 on 820907-1103 & notice of viplation Encls withheld (ref 10CFR2 790) NORDERHAUD, L R Division of Radiological Safety & Safeguards Program 82/12/03 PAPAY.L T Southern California Edison Co 2pp 16312 178 24X Fiche 50-361.82/12/03.8212060228

- B212070532 Forwards IE Safeguards Insp Repts 50-206/82-29 & 50-361/82-27 on 821031-1105 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790) NORDERHAUG, L.R. Division of Radiological Safety & Safeguards Program 82/12/06 PAPAY, L.T. Southern California Edison Co. 2pp 16366 106 24% Fiche 50-206.82/12/06.8212070532
- B2:2:7020B Advises that emergency support facilities are operational Red & green phones will not be operational in emergency operations facility until 830:26
 BASKIN.K F Bouthern California Edison Co 82/12/15 KNIGHTON.Q W

G Adjudicatory correspondence

- 8212070007 Confirms 821203 telcon w/Freeman rescheduling meeting to 821215 CHANDLER, L. J. Hearing Branch 2 82/12/06 NESBITT, W. Affiliation Unknown to 16327 237 24X Fiche 50-361.82/12/06.8212070007
- 8212090199 Confirms 821213 meeting in Houston, TX to discuss possibility of participation in hearing re-medical svcs to treat radiological contamination & exposure CHANDLER, L. J. Hearings Division 82/12/08 COLLINS, V.P. Affiliation Unknown Ip 16363 356 24X Fiche 50-361,82/12/08,82120,90199

H General correspondence

B212290007 Final response to FOIA request for SECY-B1-600A.

SECY-B1-622A.SECY-B2-23.SECY-B2-42.SECY-B1-134.SECY-B2-137.

SECY-B2-197A & B.SECY-B2-286 & SECY-B2-315 SECY-B1-622A & SECY-B2-197A & B. SECY-B1-622A & SECY-B1-62A & SECY-B1-622A & SECY

J Insurance & indomnity information

- B212270171 Forwards Endorsements 89 & 90 to NELIA Policy NF-146.
 Endorsements 77 79 to MAELU Policy MF-79, Endorsement 35 to
 NELIA Policy NF-282, Endorsement 1 to NELIA Binder EB-87 &
 Endorsement 1 to MAELU Binder XB-87
 ROCCO, J Bouthern California Edison Co 82/12/20 DINITZ. I.
 Antitrust & Economic analysis Branch (Utility Finance) 19pp
 16538 347 24X Fiche 50-206,82/12/20,8212270171
- P Operating license stage documents & correspondence
- 8912140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 QALLO, J Isham Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- ---B203310470 Forwards BEP seismic completion plan to perform review parallel w/license efforts to complete BEP Topic III-6, seismic design considerations, for Group II plants HERMANN, R Systematic Evaluation Program Branch B2/03/08 RUSSELL, W T Systematic Evaluation Program Branch 5pp 14434 276 24X Fiche 50-000, 82/11/03, 8212140001
- 8212030269 Board Notification 82-117 forwards RH Engelken 921108 memo to BS Elsenbut re welding-related allegations made by former Bechtel employee W/o encl NOVAK.T M Assistant Director for Licensing 92/11/17 Atomic Safety and Licensing Appeal Panel 3pp 16316 323 24X Fiche 50-000,82/11/17,8212030269
- BR12030253 Board Notification 82-105 forwards RH Vollmer 820730 memo to DC Eisenhot re alleged design deficiency in ASME Code Class I piping Effects of local pips wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT.D 0 Division of Licensing 82/11/24, PALLADIND.N J., GLINRSKY,V. A.HEARNE, J.F. Commissioners 2pp 16316 240 R4X Fiche 50-000, 82/11/24, 8212030253
- --8212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/sipe support-sipe interface design issue would be serious matter if substantiated Ofc of investigations will assist in evaluation VOLLMER.R H Division of Engineering 82/09/30 EISENHUT.D Q. Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24,8212030253

- B212010171 Responds to NRC 821026 Itr re Congressional request for info on steam generator tube integrity Due to recent receipt of OLs.operating history does not provide meaningful info DIETCH, R Bouthern California Edison Co 82/11/29 EISENHUT, D G Division of Licensing ip 16258 082 24X Fiche 50-361,82/11/29, 8212010171
- 8212010319 Staff requirements memo re Commission 821118
 affirmation/discussion & vote on SECYs 82-439 & 82-438
 CHILK, 8 J Office of the Secretary of the Commission 82/11/30
 DIRCKS, N J Office of the Executive Director for Operations
 BICKHIT, L Office of the Ceneral Counsel 2pp 16271 282 24X
 Fiche 50-361, 82/11/30, 8212010319
- 8212020373 Forwards changes to post-accident sampling descriptions per NUREG-0737, Item II B 3 & 821112 meeting Changes will be incorporated in FSAR amend to be submitted late Dec 1982 BASKIN, K P Southern California Edison Co 82/11/30 KNIGHTON, 0 will Licensing Branch 3 7pp 16290 318 24X Fiche 80-361, 82/11/30, 8212020373
- 8212030275 Board Notification 82-117 forwards RH Engelken 821108 memo to D0 Eisenhut re welding-related allegations made by former Hechtel employee W/o encl NOVAK:T M Assistant Birector for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316 315 24X Fiche 50-000, 82/11/30, 8212030275
- 8212030157 Forwards Amend Application 15 to License NPF-10, consisting of Proposed Changes 10 & 21 Changes would increase ESF response time limits for auxiliary feedwater delivery & minimize Tech Spec differences between units DIETCH, R Southern California Edison Co 82/12/01 DENTON, H R. Office of Nuclear Reactor Regulation. Director 19 14304 309 24; Fiche 50-341.82/12/01.8212030157
- --B212030168 Amend Application 15 to License NPF-10, revising Tech Specs 3 3 2 (Table 3 3-5) & 4 7 1 2 1 a Proposed changes increase ESF response time limits for auxiliary feedwater delivery DIETCH, R Southern California Edison Co COTTON, O D San Diego Oas & Electric Co HOYT, O W Anaheim CA 82/12/01 7pp 16306 310 24X Fiche 50-361, 82/12/01,8212030157
- --B212030250 Proposed Tech Spec changes, increasing ESF response time limits for auxiliary feedwater delivery * Southern California Edison Co B2/12/01 96pp 16306 317 24X Fiche 50-361.82/12/01.8212030157
- 82121703Bi Notification of 821207 meeting w/util in San Clemente, CA to discuss rapid depressurization & DHR capability & inadequate core cooling instrumentation RODD. H Licensing Branch 3 82/12/01 KNIGHTON, 0 W Licensing Branch 3 5pp 16478 090 24X Fiche 50-361,82/12/01,8212170381
- B212070190 Forwards proposed Tech Spec changes re turbine overspeed protection Proposed change will be detailed in formal OL amend request to be submitted during who 6 821220
 BABKIN, KP Bouthern California Edison Co B2/12/03 KNIGHTON, W Licensing Branch 3 3pp 16334 354 24X Ficher 50-361, 82/12/03, 8212070190
- --8212070193 Proposed Tech Spec Page 3/4 3-75 re turbine overspeed protection * Southern California Edison Co 82/12/03 5pp 16334 357 24X Fithe 50-361,82/12/03,8212070190
- 8212070376 Forwards amend fee for Items 2 & 3 per NRC 821018 ltr re Amends 4.6 & 7 to License NPF-10 Disagress w/fees applicable for Item 1(6) re license condition for environ qualification program BASKIN.K.P Southern California Edison Co 82/12/03 MILLER.W G License Fee Nanagament Branch 2pp. 16365 053 24X Fiche 50-361,92/12/03.8212070376
- B212090176 Amends wtil B21028 ltr summarising status of electrical equipment environ qualification program Review & determination of acceptability of as-installed condition will be completed by B21215
 BABKIN, K P Southern California Edison Co B2/12/07 XNIOHTDN.O.W Licensing Branch 3 6pp 16359 213 24X Fiche 50-361, B2/12/07, B212090176
- B212090179 Forwards Affidavit of 8vc affirming that distribution of Amend 15 to License NPF-10 has been completed MEDFORD, M.O. Bouthern California Edison Co. 82/12/07 KNIGHTON, & W. Licensing Branch 3. 4pp. 16359,207. 24X Fiche 50-361,82/12/07,8212090179

- 82:2090514 Responds to Generic Ltr 82-16. "Clarification of TMI Action Plan Requirements" Comparison of Tech Specs for both units vs NUREG-0737 requirements encl BASKIN-K P Southern Galifornia Edison Co 82/12/07 KNIGHTON-G W Licensing Branch 3 12pp 16366 013 24X Fiche 50-361.82/12/07. B212090514
- B212130161 Forwards Amend 11 to License NPF-10, safety evaluation & notice of issuance & availability Amend changes Tech Spec 3 3 4 specifying at least one operable turbine overspeed protection sys MXIGHTON, O W. Licensing Branch 3 B2/12/07 DIETCH.R Southern California Edison Co COTTON, O D. BERNATH, L San Biego Gas & Electric Co 3pp 16376 056 24% Fiche 50-361,82/12/07.8212130161
- --B212130162 Amend 11 to License NPF-10-changing Tech Spec 3 3 4 specifying at least one operable turbine overspeed protection sys MXIOMITON 0 H Licensing Dranch 3 82/12/07 5pp 16396 060 24X Fiche 50-361,92/12/07.8212130161
- ~-B212130164 Bafety evaluation supporting Amend 11 to License NPF-10 * Office of Nuclear Reactor Regulation, Director B2/12/07 3pp 16396 065 24X Fiche 50~361.82/12/07.8212130161
- --8212130168 Notice of issuants & availability of Amend 11 to License NFF-10 KNIGHTON 0 W Licensing Branch 3 82/12/07 3pp 16396 068 24% Fiche 50-361 82/12/07 9212130161
- B20Bi90263 Generic Ltr 82-32 to all PWR licensees re potential steam generator-related generic requirements Forwards Science Applications. Inc draft rept re subj requirements Commants requested within 30 days of itr Svc list encl EISENHUT.D 9 Division of Licensing 82/12/09 Consolidated Edison Co of Neu York Inc 29pp 16629 247 24X Fiche 50-000.82/12/09.820Bi90263
- 8212220061 Requests remittance of Class III fees per 820816 Tech Spec change request re condensate storage tank & 820930 application to allow Mode 2 & 3 operation w/turbine overspeed protection sys inoperable DIGOS.R M License Fee Management Branch 82/12/10 DIETCH.R Southern California 801son Co 1p 16525 362 24X Fiche 50-361.82/12/10.8212220061
- 82:12220434 Board Notifications 82-125 & 82-125A forwards info re flow blockage during natural circulation All concerns re phenomena of natural circulation flow blockage previously identified by NRC & provided to Commission EISENHUT, D 0 Division of Licensing 82/12/14 PALLAPINO, N J , OILLINERY, V , AHEARNE, J Commissioners 4pp 16523 103 24X Fiche 50-000, 82/12/14, 8212220434
- 8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NOVAN. T M Assistant Director for Licensing 82/12/14 Atomic Bafety and Licensing 8007 Panel 5pp 16523 135 24X Fiche 50-000.82/12/14,8212220440.
- B212220461 Board Notification 82-124 forwards RJ Mattson 821123 mamo re Semiscale S-UT-8 test results Phenomena of core level degression & loop seal clearing may be more compler than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Bafety and Licensing Board Panel 7pp 16523 169 24x Fiche 50-000.82/12/14.8212220461
- 8212220482 Board Notification 82-124 forwards RJ Mattson 821123 memb re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed EISENNUT, D 0 Division of Licensing 82/12/14 PALLADINO, N J . QILINSKY, V AREARNEL, F Commissioners 4pp 16523 199 24X Fiche 30-000, 82/12/14, 8212220482
- 8212230291 Forwards table of all ESF actuation sys subgroup relays categorised per NRC 821007 request ESF actuation trains not defeated for testing subgroup relays Procedure considered unsafe operating practice

 BASKIN.K P Southern California Edison Co 82/12/17 KNIGHTON.G W Licensing Branch 3 26pp 16507 321. 24X Fiche 50-361.82/12/17.8212230291
- 9212230260 Provides results of review of Rosemount transmitters & resistance temp detectors tested w/terninal head areas sealed from abnormal environ atmosphere BASKINAK P Bouthern California Edison Co 82/12/21 XNIGHTON, G W Licensing Branch 3 4pp 16508/184 24X Fiche 50-361, 82/12/21, B212230260.

- 8212230325 Supple 821220 ltr re proposed change to License NPF-10 Component Cooling water sys adequate to simultaneously serve all essential & nonessential loads except shutdown cooling HX Safety analyses not affected by change BASKIN,X P Southern California Edison Co 82/12/21 KNIGHTON & Licensing Branch 3 1p 16507 309 24X Fiche 50-361,82/12/21.
- B212230349 Comments on NRC safety evaluation re Amend 8 to License NPF-10 Amend changed date for operability of post-accident sampling sys Plant expected to return to power by early Jan 1983
 BASKIN, K P Southern California Edison Co 82/12/21 KNIGHTON, G W Licensing Branch 3 2pp 16511 264 24X Fiche 50-361,82/12/21, 8212230349
- O Inspection reports. IE Bulletins & correspondence
- G2(2290023 FOIA request for documents re EE Kent a)legations concerning facilities
 COHEN,E M , CARPENTER,T , JACOBSON,J Orange County Alliance for Survival 82/10/27 FELTON,J M Division of Rules and Records
 19 16607 055 24X Fiche 50-204,82/10/27,82(2290023
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list enc! COBB.L I Division of Fuel Facilities, Materials & Safequerds 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50-000-82/11/05, 8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolydated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000,82/11/18.8208190251
- B212060154 Forwards IE Insp Rept 50-361/B2-32 on 621025-29 No noncompliance nated BISHOP: TW Division of Resident, Reactor Project & Engineering Programs 82/11/19 PAPAV.L T Southern California Edison Co 2pp 16313 135 24X Fiche 50-361.82/11/19.8212060154
- --8212060169 IE Insp Rept 50-361/82-32 on 821025-29 No noncompliance noted Major areas inspected audit implementation, training & requalification training program MENDONCA-M M , KIRSCH, D F Division of Resident, Reactor Project & Engineering Programs 82/11/19 3pp 16313 137 24X Fichy 50-361,82/11/19,8212060154
- 8212040156 Forwards IE Insp Repts 50-206/82-33 & 50-361/82-33 on B21025-28 & notice of violation BOOK: H E Region 5, Office of Director 82/11/19 PAPAY, L T Southern Galifornia Edison Co 4pp 16313 120 24X Fiche. 50-206, 82/11/19: 8212060156
- --8212060161 Notice of violation from insp on 821025-28 * Region 5. Office of Director 82/11/19 4pp 16313 122 24% Fiche 50-206.82/11/19.8212060156
- --BR12060168 IE Insp Repts 50-206/82-33 & 50-361/82-33 on 821025-28
 Noncompliance noted failure to post notice to workers,
 described in 10CFR19 11, Paragraph 3
 YUMAS, 0 F , MENSLAWSKI, F A , BODK, H E Division of Radiological
 Safety & Safeguards Program 82/11/18 9pp 16313 126 24X
 Fiche 50-206,82/11/19,8212060156
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNGER C Director's Office. Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-fissile Radiosctive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York
- 8212170369 Forwards IE Insp Repts 50-206/82-31,50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 82/11/30 PAPAY, L T Southern California Edison Co 4pp 16455,279 24X Fiche 50-206,82/11/30,8212170369
- ~-8212170376 IE Insp Repts 50-206/82-31,50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted Hajor areas inspected—allegations re design inndequacies & deficiencies in implementation of welding codes & std:
 HERNANDEZ,O , WAONER,W J , KIRSCH,D F Division of Resident.
 Reactor Project & Engineering Programs 82/11/30 43pp
 16455 283 24X Fiche 50-206,82/11/30.8212170369

- --8212170383 Requests notification if list of items to be submitted by 821103 re welding code requirements not correct ENDELKEN.R H Region 5, Office of Director 82/10/27 PAPAY,L T Southern California Edison Co ip 16455 326 24% Fiche 50-206.82/11/30.8212170369
- --8212170384 Responds to NRC 821029 ltr re allegations concerning const quality & welding code requirements PAPAY, L T Southern California Edison Co 82/11/03 ENGELKEN, R H Region 5, Office of Director 11pp 16455 327 24X Fiche 50-206.82/11/30.8212170369
- --8212170386 Forwards Bechtel 821027 response to allegations re const quality, per request made at 821103 site meeting CURRAN.J M Southern California Edison Co 82/11/03 KIRSCH.D F Region 5. Office of Director 37pp 16455 338 24X Fiche 50-204,82/11/30.8212170369
- --8212080291 Transmits reply to 821027 request for technical assistance in evaluating EE Kent Allegation Items 2,5.4 & 8 Evaluation concludes allegations unsubstantiated EISENHUT, D 0 Division of Licensing 82/11/30 CREMS, J L Division of Resident, Reactor Project & Engineering Programs IP 18456 013 24X Fiche 50-206, 82/11/30/8212170369
- --82:1270023 Forwards safety evaluation of E Kent allegations reweldments at plants Allegations have no merit & no further action should be taken

 JOHNSTON.W V Assistant Director for Materials & Qualifications
 Engineering 82/11/17 NOVAK.T M Assistant Director for
 Licensing 14pp 16456 014 24X Fiche 50-206.82/11/30.
 8212170367
- 8212210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on fi21101-05 No noncompliance noted HIBHOP:T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY.L T Southern California Edison Co 2pp 16484 317 24X Fiche 50-361/82/12/02/8212210197
- --B212210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompliance noted Major areas inspected fire protection/ prevention program 5 program implementation SCOWN.K M . ZWETZIG 6 B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fische 50-361.82/12/02.8212210197
- BPOB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000,82/12/03,8208190261
- B212060228 Forwards IE Safeguards Insp Rept 50-361/82-39 on 920907-1103 & notice of violation Encls withheld (ref 10CFR2 790)
 NORDERHADO,L R Division of Radiological Bafety & Safeguards
 Program 82/12/03 PAPAY,L T Southern California Edison Co 2pp
 16312 178 24X Fiche 50-361,82/12/03.8212060228
- BR12170391 Forwards IE Insp Rept 50-361/82-41 on B21110-11 & notice of violation BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/12/03 PAPAY.L T Southern California Edison Co 2pp 16459 168 24X Fiche 50-361,82/12/03,8212170391
- --8212170394 Notice of violation from insp on 821110-11 YOUNG.T Division of Resident, Reactor Project & Engineering Programs 82/12/03 ip 16459 170 24X Fiche 50-361.82/12/03, 8212170391
- --8212170397 IE Insp Rept 50-361/82-41 on 821110-11 Noncompliance noted failure to maintain open, continuous communication channel w/RRC operations ctr
 YOUNG.T. JOHNSON, P. H. KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 82/12/03. Spp 16459 171 R4X Fiche 50-361, 82/12/03, 8212170371
- 8212270030 Partial response to FOIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1, 2, 4, 7, 10, 15 & 16 listed in App A Remaining documents will be released when inspirely issued Tapes available in FDR FELTON. J M Division of Rules and Records 82/12/03 CARPENTER, T Drange County Alliance for Survival 3pp 16607 056 24X Fiche 50-206, 82/12/03, 8212270030

- --8212270035 Summarizes 821006 telron w/J O'Dell (LA Times) re EE Kont allegations concerning welding practice at facilities KIRSCH.D F Division of Resident, Reactor Project & Engineering Programs 82/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16407 077 24X Fiche 50-206,82/12/03, 8212270030
- ---B212270038 Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities CURRAN.J M Bouthern California Edison Co 82/10/07 KIRBCH.D F Region 5. Office of Director 48pp 16607 079 24X Fiche 50-206, 82/12/03, 8212270030
- --8212290042 Lists EE Kent concerns re facilities, per 821022 discussions w/Kent KIRSCH, D.F. Division of Resident. Reactor Project & Engineering Programs 82/10/22 CURRAN, J. Southern California Edison Co ip 16607 127 24X Fiche 50-206.82/12/03,8212290030
- --B212270049 Figure NB-4250-1. "Welding End Transitions Max Envelope," w/annotation "Example of Approx Slopes Discovered 821025 at San Onofre Nuclear Generating Stations " Charts re welding & pipe support enc!
 KENT.E E Affiliation Unknown 82/11/12 3pp 16607 129 24X Fiche 50-204, 82/12/03, 8212290030
- 8212090532 Forwards IE Safeguards Insp Repts 50-206/82-29 & 50-361/82-29 on 821031-1105 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 790) NORDERHAUGL R Division of Radiological Bafety & Safeguards Program 82/12/06 PAPAYL T Southern California Edison Cu 2pp 16366 106 24X Fiche 50-206,82/12/06.8212090532
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Syc list encl DEYOUNG: R C Director's Office of Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16.8208190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 ' Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- G212290176 Forwards monthly operating rept for Oct 1982 RAY,H B Southern California Edison Co G2/11/15 Division of Data Automation & Management Information ip 16578 039 24X Fiche 50-361, G2/11/15, G212290176
- --82:2290181 Monthly operating rept for Oct 1982 IYER.J S Bouthern California Edison Co 82/11/15 Spp 16578 040 24% Fiche 50-361:82/11/15.8212290176
- B Reportable occurrences, LERs & related correspondence
- B212070225 Forwards LER 82-131/03L-Q Detailed event analysis submitted RAY, H B Southern California Edison Co 82/11/18 ENGELKEN, R H Region 5, Office of Director 200 16329 349 24X Fiche 50-361, 82/11/18, 8212070225
- --8212070231 LER 82-131/03L-0 on 821020, auxiliary feedwater pump 2P-141 declared inoperable Caused by dirt on oil filter preventing valve 2MV4731 from stroking fully open Oil filter replaced & valve tested successfully RAY.H 8 Southern California Edison Ca 82/11/18 Region 5. Office of Director 1p 16327-351 24X Fiche 50-361,82/11/18,8212070225
- 8212070252 Forwards LER 82-135/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co B2/11/18 ENGELKEN, R H Region 5. Office of Director 200 16339 124 24X Fiche 50-361, 82/11/18, 8212070252
- --8212070259 LER 82-135/03L-0 on 821018 during change from Mode 4 to Mode 3, one train of component cooling water improperly aligned rendering smergency chiller E-335 inoperable Caused by improper documentation Personnel reinstructed RAY,H B Southern California Edison Co. 82/11/18 Region 5, Office of Director. 1p 16339 126 24X Fiche 50-361,82/11/18,8210770282
- 82:2070383 Forwards LER 82-128/03L-0 Detailed event analysis submitted RAY, H. B. Southern California Edison Co. 82/11/18 ENOELKEN, R. H. Region 5, Office of Director. 2pp. 16336-336 24X Fiche 50-361, 82/11/18.8212070383

- --8212070399 LER 82-128/03L-0 on 821021, while in Mode 2, control element assembly slipped & dropped in excess of 7 inches Caused by slow operation of grippers Oripper actuation voltage & duration of application increased Sys tested successfully RAY.H B Southern California Edison Co 82/11/18 Region 5, Office of Director ip 16336 338 24% Fiche 50-361,82/11/18,8212070383
- 6212070281 Forwards LER B2-137/03L-O Detailed event analysis submitted RAY, H B Southern California Edison Co 82/11/19 ENGELKEN.R H Region 5. Office of Director 2pp 14343 191 24X Fiche 50-361.82/11/19.8212070281
- --8212070294 LER 82-137/03L-0 on 821020. while in Mode 3. absence of chemical & vol control sys jetdown flow & decreasing vol control tank level revealed Caused by sticking relief valve Investigation angoing Revised LER will be provided RAY.H # Southern California Edison Co 82/11/19 Region 5, 0ffice of Oirector 19 16343 193 24X Fiche 50-361,82/11/19,8212070281
- 8212070283 Forwards LER 92-133/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/11/19 ENGELKEN, R H Region 5, Office of Director 2pp 16339 110 24X Fiche 50-361, 82/11/19, 8212070283
- --8212070287 LER 82-133/03L-0 on 821021. during Mode 2. hot leg sample isolation valve 2HV-0509 observed w/simultaneous open & closed position indication when actually closed Caused by loose actuator bar on limit switch assembly Bar tightened. RAY.H B Southern California Edison Co 82/11/19 Region 5. Office of Director 1p 16339 112 24X Fiche 50-361.82/11/19. 82/2070/983
- 8212070290 Forwards LER 82-134/03L-0 Detailed event analysis submitted RAY.H B Southern Callfornia Edison Ca 82/11/19 ENGELKEN,R H Ragion 5, Office of Director 2pp 16339 017 24X Fiche 50-361,82/11/19,8212070290
- --8212070273 LER 82-134/03L-0 on 821024, during Made 1, containment airborns monitor 287-7804-1 failed to meet surveillance requirements of Tech Specs Caused by instrument drift in sample pump flow controller Controller adjusted RAY,H 8 Southern California Edison Co 92/11/19 Region 5. Office of Director ip 16337 019 24X Fiche 50-361,82/11/19. 8212070270
- 8212070379 Forwards LER 82-132/03L-0 Detailed event analysis submitted RAY.H 8 Southern California Edison Co 82/11/19 ENGELKEN.R H Region 5. Office of Director 2pp 16336 339 24X Fiche 50-361.82/11/19.8212070379
- ~~8212070388 LER 82-132/03L-0 on 621023.during turbine generator voltage regulator testing, turbine stop valve 20V-2200E failed to close Caused by faulty electro-hydraulic servo-mechanism which controls valve actuation Assembly replaced RAY.H B Southern California Edison Co 82/11/19 Region 5. Office of Director ip 16336 341 24X Fiche 50-361.82/11/19. 6212707779
- 8212070406 Forwards LER 82-125/03L-0 Detailed event analysis submitted RAY,H B Southern California Edison Co 82/11/22 ENGELKEN,R H Region 5. Office of Director 2pp 16336 344 24X Fiche 50-361-82/11/22.8212070406
- --8212070412 LER 82-j25/03L-0 on 821001, shutdown cooling sys declared inoperable when pre-existing tube leat in Train A component cooling water sys HX aggravated Caused by surge tank filled w/solid due to faulty level control switch 2LSN-6498 RAY, H B Southern California Edison Co 82/11/22 Region 5, Office of Director. ip 16336-346 24X Fiche 50-361,82/11/22, 8212070406
- 8212070324 Forwards LER 82-141/03L-0 Detailed event analysis submitted RAY,N B. Bouthern California Edison Co 82/11/24 ENGELKEN,R H Region 5. Office of Director 2pp 16343,139 24X Fiche 50-361.82/11/24.8212070324
- --8212070329 LER 82-141/03L-0 on 821027, during Made 2, condensate storage tank T-120 water fell below Tech Spec limit Caused by inadequate makeup water control to tank due to misalignment of valves Engineering evaluation underway RAY-H B Southern California Edison Ca 82/11/24 Region 5, Office of Director ip 16343 161 24X Fiche-50-361, 82/11/24, 2113/7824
- 8212070390 Forwards LER 82-138/01T-0 Detailed event analysis submitted RAY.H B. Southern California Edison Co. 82/11/24 ENGELKEN,R H Region 5. Office of Director 3pp. 16337 216. 24X Fichs. 50-361. 82/11/24,8212070350.

- ~-B212070360 LER 82-138/01T-0 on 82(107, during momentary loss of power to feedwater control systreactor manually tripped & ECCS automatically initiated Caused by dislodging of power cord Control cabinets secured w/tie wraps & training updated RAY.H B Southern California Edison Co 82/11/24 Region 5, Office of Director 1p 16337 217 24X Fiche 90~361,82/11/24, 8212070350
- 0212070369 Forwards LER 02-140/03L-0 Detailed event analysis submitted RAY, H B Southern California Edison Co 82/11/24 ENGELKEN, R H Region 5, Office of Director 2pp 16336 333 24X Fiche 50-361, 82/11/24, 8212070369
- --8212070374 LER 82-140/03L-0 on 821029, mismatch in power indication found between channel B & channels A.C & D indicating circuitry failure associated w/channel B calculation Caused by gain drifting in linear amplifier Board replaced RAY.H B Southern California Edison Co 82/11/24 Region 5, Office of Director ip 16336 335 24X Fiche 50-361,82/11/24,8212070367
- 8212140035 ROS 82-142 & 82-001 on 821124 & 29.CREACUS Train A declared inoperable due to charcoal filter replacement on cooling unit E-418 & emergency chiller E-335 inoperable due to high motor winding temp trip Cooldown initiated RAY,H B Southern California Edison Co 62/11/30 ENGELMEN.R H Region 5. Office of Director 2pp 16409 271 24X Fiche 50-361.82/11/30.8212140035
- 8212140265 Forwards LERs 82-094/03L-1 & 82-103/03L-1 Detailed event analyses submitted RAY, H B Southern California Edison Co 82/11/30 ENGELKEN, R H Region 5, Office of Director 2pp 16402 115 24X Fiche 50-361, 82/11/30, 8212140265
- --8212140270 LER 82-094/03L-1 on 820808, stroke time for hot leg sample isolation valve 2MV-0317 could not be measured due to simultaneous indication of valve open & closed positions Caused by loose limit switch Switch tightened RAV-H B Southern California Edison Co. 82/11/30 Region 5, Office of Director Ip 16402 117 24X Fiche 50-361.82/11/30, R912140265
- --8212140272 LER 82-103/03L-1 on 820825 during ESF subgroup relay testing hot leg sample isolation valve 2HV-0517 breaker 28J-23 tripped on overload while attempting to close valve Caused by burned out motor on operator Motor replaced RAY. H # Southern California Edison Co 82/11/30 Region 5, Office of Director Ip 16402 118 24X Fiche 50-361, 82/11/30, 8212140265
- 82:2140398 Forwards LER 82-143/03L-0 Detailed event analysis submitted RAY,H B Bouthern California Edison Co 82/12/01 ENGELKEN,R H Region 5, Office of Director 2pp 16403 360 24X Fiche 30-361,82/12/01,8212140398
- --8212140405 LER 82-143/03L-0 on 821101, auxiliary feedwater pump 2P-140 declared inoperable Caused by introduction of air into electro-hydraulic actuator by low hydraulic ail level condition resulting in slow response of governar valve RAV.H B Southern California Edison Co 82/12/01 Region 2. Office of Director 1p 14403 362 24X Fiche 50-361,82/12/01,8212140378
- 8212170281 PMG-V-92-050 on 821212 reactor tripped due to low DNBR signal Caused by generation of false rod control element position penalty by protection sys due to improper filtering of fluctuating rod position reed switch input signal ECKHARDT.J. BISHOP. TW Region 5. Office of Director 82/12/13 p 16461 182 24X Fiche 50-361.82/12/13,8212170281
- 8212290413 Discusses ESF actuation sys 821217 event & short-term actions taken to reduce probability of recurrence NRC concurrence w/Unit 2 power operation & continuation of Unit 3 startup test program requested DIETCH.R Southern California Edison Co 82/12/28 EISENHUT.D C Division of Licensing 6pp 16597 093 24X Fiche 50-361,82/12/28,8212290413
- DOCKET 50-362 BAN ONDERE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- BR12140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J Isham, Lincoln & Beale, 2pp 14433 354 24X Fiche 50-000, 82/11/03, 8212140001

- --7912190426 Natifies of info required from applicant re independent confirmatory piping analysis BOSNAK, R. J. Mechanical Engineering Brench 79/12/06 RUBENSTEIN. L. Light Mater Reactors Branch 4 2pp 16435 014 244 Fiche 50-000.82/11/03.8212140001
- --B003310092 Suggests review of existing high resolution seismic profiling to define possible Christianitos-Offshore Deformation Zone USGC to assist JACKSON, R E Geosciences Branch 60/03/18 KNIGHT, J P Assistant Director for Engineering Ip 16434 258 24X Fiche 50-000,82/11/03.8212140001
- --8000099726 "Vertical Spectra from 1979 Imperial Earthquake" * Southern California Edison Co 80/03/31 24pp 16435 021 24x Fiche 50-000,82/11/03,8212140001
- --8CO718D114 Forwards NRC formal question, requesting that util perform evaluation of estimated earthquake ground motion for Unit 1 based on deterministic modeling & ground motion for Units 2 & 3. based upon empirical evaluation CARDOME, A T Geosciences Branch 80/06/11 DAVIS, J California, State of 1p 16434 259 24X Fiche 50-000, 82/11/03, 8212140001
- -8007230260 Forwards transcripts of 800520-21 meetings w/licensee reneed for addit offshore seismic profiles W/o and CARDENE, A Togosciences Branch 80/06/04 AMIMOTO, P. California, State of 1p 16435-052 24X Fiche 50-000.82/11/03, 62(214000)
- --8010150236 Request for procurement NRR-60-143 to award sole source contract to JE Luco for "Followon to Simulation of Earthquake Ground Motion for San Onofre Nuclear Generating Station "
 VOLLMER, R H Division of Engineering FIN D-6898-0 80/08/04
 7pp 16425 057 24X Fiche 50-000.82/11/03.8212140001
- --B010150242 Requests for procurement NRR-80-145 to award sole source contract to R Herrnann for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " VOLLMER,R H Division of Engineering FIN 8-6898-0 80/08/04 7pp 16435 065 24X Fiche 50-000.82/11/03.8212140001
- --B010150246 Request for procurement NRR-B0-144 to award sole source contract to K Aki for "Followon to Simulation of Earthquake Ground Motions for San Onofre Nuclear Cenerating Station VOLLMER, R H Division of Engineering FIN B-6898-0 B0/08/04 7pp 16434 247 24X Fiche 50-000, B2/11/03, B212140001
- --0203310670 Forwards SEP seismit completion plan to perform review parallel U/license efforts to complete SEP Topic III-6, seismic design considerations, for Group II plants
 HERMANN.R Systematic Evaluation Program Branch 82/03/08
 RUSSELL.H T Systematic Evaluation Program Branch 5pp
 16434 276 24X Fiche 50-000, 82/11/03, 8212140001
- D21223029: Forwards table of all ESF actuation sys subgroup relays categorized per NRC 821007 request ESF actuation trains not defeated for testing subgroup relays Procedure considered unsafe operating practice
 BASKIN, K P Southern California Edison Co 82/12/17 KNIGHTON, C & Licensing Branch 3 26pp 16507 321 24X Fiche 50-361, 82/12/17, 8212230291
- 82:12230260 Provides results of review of Rosemount transmitters & resistance temp detectors tested w/terminal head areas sealed from abnormal environ atmosphere BASKIN.K P Southern California Edison Co 82/12/21 KNIOHTON.G W Licensing Branch 3 4pp 16508 184 24X Fiche 50-361.82/12/21, 8212230260
- F Security, medical, emergency & fire protection plans
- 8P12210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on 621101-05 No noncompliance noted IIISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY.L T Southern California Edison Co 2pp 16494 317 24X Fiche 50-361.82/12/02.8212210197
- --8212210204 IE Insp Repts 50-361/82-36 & 50-362/82-29 on 821101-05 No noncompilance noted Major areas inspected fire protection/ prevention program & program implementation SCOWN,K M Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fichs 50-361,82/12/02,8212210197

- 8212210362 Forwards IE Safeguards Insp Rept 50-362/82-22 on 821005-08 & notice of deviation Rept & notice of deviation withheld (ref 10CFR2 790)
 NGRDERHAUG.L R Division of Radiological Safety & Safeguards
 Program 82/12/14 PAPAY.L T Southern California Edison Co 2pp 16475 159 24X Fichs 50-362, 82/12/14, 8212210362
- 8212170208 Advises that emergency support facilities are operational Red & green phones uill not be operational in emergency operations facility until 830126

 BASKIN.K P Southern California Edison Co 82/12/15 KNIGHTON,8 W Licensing Branch 3 2pp 16459 345 24X Fiche 50-361,82/12/15,8212170208

O Adjudicatory correspondence

- B212070007 Confirms B21203 telcon w/Freeman rescheduling meeting to 821215
 CHANDLER, L J Hearing Branch 2 82/12/06 NESBITT, W Affiliation Unknown is 16327 237 24% Fiche 50-361.82/12/06.8212070007
- 8212090199 Confirms 821213 meeting in Houston, TX to discuss possibility of participation in hearing re-medical sycs to treat radiological contamination & exposure CHANDLER, L.J. Hearings Division B2/12/08 COLLINS, V.P. Affiliation Unknown ip 16363-356 24X Fichs 50-361,82/12/08,8212090199

H General correspondence

- J Insurance & indemnity information
- B212130039 Forwards Amend 17 to Indemnity Agreement B-31, reflecting issuance of License NPF-15, per NRC 821115 request BASKIN, K P Southern California Edison Co 82/12/17 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16389 308 24X Fiche, 50-362, 82/12/17, 8212130039
- B212270171 Forwards Endorsements B9 & 90 to NELIA Policy NF-146, Endorsements 77 79 to MAELU Policy MF-79, Endorsement 35 to NELIA Policy NF-282. Endorsement 1 to NELIA Binder ED-87 & Endorsement 1 to MAELU Binder XB-87 ROCCO. J Southern California Edison Co 82/12/20 DINITZ. I Antitrus & Economic analysis Branch (Utility Finance) 19pp 16538 347 24X Fiche 50-206, 82/12/20, 8212270171
- P Operating license stage documents & correspondence
- 8212030269 Soard Notification 82-117 forwards RH Engelken 821108 memo to DO Eisenhut re welding-related allegations made by former Bechtel employee W/o encl. NOVAK.T M Assistant Director for Licensing 82/11/17 Atumic Bafety and Licensing Appeal Panel 3pp 16316-323 24X Fiche 50-000, 82/11/17, 8212030269
- 8212010409 Submits daily highlight Fuel load completed 821121 ROOD,H Litersing Branch 3 82/11/23 DENTON,H R. CASE,E G. CARTER, J. Office of Nuclear Reactor Regulation, Director lp 16271 077 24X Fiche 50-362,82/11/23,8212010409
- 8812030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DO Eisenbut re alleged design deficiency in ASME Code Class 1 piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not evaluated properly EISENHUT.D 0 Division of Licensing 82/11/24 PALLADING.N J. ROBERTS.T F. ASSELSTINE.J K. Commissioners 2pp 16316-240 24X Fiche 50-000.82/11/24,82120330253
- ---8212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation VOLLMER.R H Division of Engineering B2/09/30. EISENHUT.D G Division of Licensing 5pp 16316 247 24X Fiche 50~000, 82/11/24,8212030253
- BP12010171 Responds to NRC 821026 ltr re Congressional request for info on steam generator tube integrity Due to recent rectit of Ols.operating history does not provide meaningful info DIETCH: R Southern California Edison Co. 82/11/29 EISENHUT.D G Division of Licensing Lp 16258 0B2 24X Fiche 50-361,82/11/29, 8212010171

- 8212010319 Staff requirements mamo re Commission 821118
 affirmation/discussion & vote on SECVs 82-437 & 82-438
 CHILK.S J Office of the Secretary of the Commission 82/11/30
 DIRCKS.W J Office of the Executive Director for Operations
 BICKKIT.L Office of the General Counsel 2pp 16271 282 24X
 Fiche 50-361,82/11/30.8212010319
- 9212020373 Forwards changes to post-accident sampling descriptions per NUREO-0737. Item II B 3 & 821112 meeting Changes will be incorporated in FSAR amend to be submitted late Dec 1982 BASKIN. K P Southern California Edison Co 82/11/30 KNIGHTON, G W Licensing Branch 3 7pp 16290 318 24X Fiche 50-361,82/11/30, 8212020373
- 3212030275 Board Notification 82-117 forwards RH Engelken 821108 memo to DG Eisenhut re welding-related allegations made by former Bechtel employee W/o encl NDVAK, TM Assistant Director for Licensing 82/11/30 Atomic Safety and Licensing Board Panel 5pp 16316-315 24% Fiche 50-000.82/11/30.8212030275
- 3P12080540 Advises that License NPF-15 amended per 821119 ltr & telion Listed footnote should be added to Tech Spec 3 9 8 2 Amend allows removal of cooling trains for up to 1-h per 8-h period during performance of core alterations NOVAK, T M Division of Licensing 82/11/30 DIETCH, Southern California Edison Co COTTON. 0 D. DERNATH, L. San Diego Gas & Electric Co 3pp 16370 (85 24X Fiche 50-362,82/11/30,8212080540
- 212140492 TECHNICAL SPECIFICATIONS FOR SAN ONOFRE NUCLEAR GENERATING STATION UNIT NO. 3 Docket No. 50-362 (Southern California Edison Company)
 BRINKMAN D Office of Nuclear Reactor Regulation, Director NUREO-0952 82/11/30 454pp 16431 340 24X Fiche 50-36 82/11/30, 8212140482
- 212170381 Notification of 821207 meeting w/util in San Clemento,CA to discuss rapid depressurization & DHR capability & inadequate core cooling instrumentation RODD.H Licensing Branch 3 82/12/01 KNIOHTON.O W Licensing Branch 3 5pp 16478 070 24X Fiche 50-361.82/12/01.8212170381
- 212090176 Amends util 821028 ltr summarizing status of electrical equipment environ qualification program Review & determination of acceptability of as-installed condition wevermination of acceptability of as-installed condition will be completed by 821215
 BASKIN K F Southern California Edison Co 82/12/07 KNIGHTON, 6
 Licensing Branch 3 6pp 16359 213 24X Fiche 50-361, 82/12/07, 8212090176 82/12/07 KNIGHTON G W
- P12090514 Responds to Opneric Ltr 82-16, "Clarification of TMI Action Plan Requirements " Comparison of Tech Specs for both units vs NUREG-0737 requirements encl BASKIN K P Southern California Edison Co 82/12/07 KNIGHTON 6 W Licensing Branch 3 12pp 16366 013 24X Fiche 50-361.82/12/07.
- Licensing Branch 3 G212070514
- *08190263 Generic Ltr 82-32 to all PWR licensees no potential steam generator-related generic requirements Forwards Ecsence Applications, Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISE(HMUT.D 9 Division of Licensing 82/12/09 Consolidated Edison Co of New York. Inc 29pp 16629 247 24X Fiche 50-000, 82/12/09. 8208[90263
- '12130188 Forwards Amend Application 1 to License NPF-15, consisting of proposed Change NPF-15-2 to Tech Spec 2 9 8 2 to allow shutdown cooling trains to be removed from operation to facilitate fuel movement & core alterations DIETCH, R. Southern California Edison Co. 82/12/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 16376-120 24% Fiche 50-362, 82/12/09, 82/2130188
- 8212130193 Amend Application 1 to License NFF-15, allowing both shutdown cooling trains to be removed from operation to facilitate fuel movement & core alteration in vicinity of reactor pressure vessel hot legs
 DIETCH: R Southern California Edison Co 82/12/09 5pp
 16396 121 24X Fiche 50-362, 82/12/09, 8212130188
- B212130198 Proposed Change NPF-15-2 to Tech Spec 3 9 8 2, allowing both shutdown cooling trains to be removed from operation to facilitate fuel movement & core alteration in vicinity of reactor prossure vessel hot legs * Bouthern California Edison Co Fiche 50-362,82/12/07,8212130188 82/12/09 3pp [6396 [26 24X
- 12220434 Board Notifications 82-125 & 82-125A forwards info re flow laxious control notifications named a partial a remains in ileckage during natural circulation All concerns re phenomena of natural circulation flow blockage previously Identified by NRC & provided to Commission
 IJEENHUT, D G Division of Licensing 82/12/14 PALLADINO, N J.
 IDERTS, T . ASSELSTINE, J K Commissioners 4pp 16523 103 2.
 Tache 50-000, 82/12/14,8212220434 16523 103 24X

- 8212220440 Board Notifications 82-125 & 62-125A forwards info re
 H Etherington evaluation of flow blockage during natural
 circulation of PWRs Results do not adversely impact present
 position on reliance on natural circulation
 NOVAK.T M Assistant Director for Licensing 82/12/14 At
 Safety and Licensing 80ard Panel 5pp 16523 135 24X
 Fiche 50-000, 82/12/14, 8212220440 Atomic
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 5-VT-6 tost results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NDVAK.T.M. Assistant Director for Licensing 82/1 Safety and Licensing Board Panel 7pp 16523 169 Liche 50-000, 82/12/14.8212220461
- 8912220482 Beard Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed EISENRUT, D.G. Divis PREVIOUSLY SUPPOSED EISENHUT.D G Division of Licensing 82/12/14 PALLADING.N J ROBERFS.T , ASSELSTINE.J K Commissioners 4pp 16523 199 2 Fiche 50-000, 82/12/14, 82122R0482
- @ Inspection reports, IE Bulletins & correspondence
- 8212290023 FOIA request for documents re EE Kent allegations concerning facilities
 COMEN, E M Orange County Alliance for Survival 82/10/27
 FELTON, J M Division of Rules and Records Ip 16607 055 24X
 Fiche 50-362, 82/10/27, 8212290023
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thirk-Wall, Large-Diameter, Stainlass Steel, Recirculation Sys Piping at 8MR Plants "Syc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 62/10/28, 8208190240
- 82/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list
 - COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05.8208190245 82/11/05
- BROB190251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/11 Consolidated Edison Co of New York, Inc. 109pp 16411 199 Fishe 50-000.82/11/18:8208190251
- B212060166 Forwards IE Insp Rept 50-362/82-24 on 821012-29 No nenconplience noted
 BISHOP, T W Division of Resident, Reactor Project & Engineering
 Programs 82/11/18 PAPAY, L T Southern California Edison Co
 Ppp 16313 090 24X Fiche 50-362, 02/11/18, 8212060166
- --9212040170 IE Insp Rept 50-342/82-24 on 821012-29 No noncompliance eizowurvu IE insp Rept 50-362/82-24 on 821012-29 No noncompliance noted Major areas inspected preoperational test program, including test procedure verification evaluation of test results & monroutine event followup
 STEWART, J.P., KIRSCH.D.F. Division of Resident, Reactor Project & Engineering Programs 82/fi/17 9pp 16313 092 24X
 Fiche 50-362,82/11/18,8212040166
- 81'08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocts "Svc list enc!

 DEYOUNG: R C Director's Office, Office of Inspection and

 Enforcement 82/11/26 Consolidated Edison Co of New York, Inc.

 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- BP12130263 Forwards 1E Insp Rept 50-362/82-30 on 821025-29 No **12130263 Forwards IE Insp Rept 50-362/82-30 on 821025-29 No monconpliance noted BISHQP.T W Division of Resident, Reactor Project & Engineering Programs B2/11/29 PAPAYL T Southern California Edison Co 2pp 16396 247 24X Fiche 50-362.82/11/29,8212130263
- --B212130265 IE Insp Rept 50-362/82-30 on 821025-29 No noncompliance exisused le Insp Rept 50-362/82-30 on 821025-29 No noncompliance noted Major areas inspected const of installed instrumentation & electrical components & onsite design change program ECKHARDT. J H . KIRSCH. D F Division of Resident, Reactor Project & Engineering Programs 82/11/24 App 16396 249 24X Fiche 50-362,82/11/29.8212130263
- 62°08190257 IE info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl "Svc list encl COBB.L 1 Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000, 82/11/30 6808190257

- 8212170369 Forwards IE Insp Repts 50-206/82-31,50-361/82-31 & 50-362/82-27 on 821015-1115 No noncompliance noted BISHOP, F W Division of Resident, Reactor Project & Engineering Programs 82/11/30 PAPAYL T Southern California Edison Co 4pp 16455 279 244 Fiche 50-206.82/11/30.8212170369
- --B212170376 IE Insp Repts 50~206/82~31.50~361/82~31 & 50~362/82~27 un 821015~[115 No noncompliance noted Major areas inspected allegations re design inadequacies & deficiencies in implementation of welding codes & stds HERNANDEZ. G. HAGNER, W.J. KIRBCH.D F. Division of Resident, Reactor Project & Englineering Programs 82/11/30 43pp 16455 283 24X Fiche 50~206.82/11/30.8212170369
- --B2121703B3 Requests notification if list of items to be submitted by B21103 re welding code requirements not correct ENCELKEN,R H Region 5, Office of Director B2/10/29 PAPAY,L T Bouthern California Edison Co 1p 16455 326 24X Fiche 50-206.82/11/30.8212170369
- --B212170384 Responds to NRC B21029 ltr re allegations concerning const quality & welding code requirements PAPAYL T Southern California Edison Co B2/11/03 ENGELKEN, R H Region 5, Office of Director 11pp 16455 327 244 Fishe 50-206, B2/11/30, B212170369
- --8212170386 Forwards Bechtel 821029 response to allegations re const quality, per request made at 821103 site meeting CURRAN. J H Southern California Edison Co 82/11/03 KIRSCH. D F Region 5. Office of Director 37pp 16455
- --B2(208)291 Transmits raply to 821029 request for technical assistance in evaluating EE Kent Allegation Items 2,5,6 % 8 Evaluation concludes allegations unsubstantiated EISEMHUT,D 0 Division of Licensing 82/11/30 CREWS,J L Division of Resident, Reactor Project & Engineering Programs 1P 16455 013 24X Fiche 50-206,82/11/30,8212170369
- --G211290023 Forwards safety evaluation of C Kent allegations rewoldments at plants Allegations have no merit & no further action should be taken JOHNSTON, H V Assistant Director for Materials & Qualifications Engineering 62/11/17 NOVAK, T M Assistant Director for Licensing 14pp 16456 014 24X Fiche 50-206, 82/11/30, 8212170369
- 8:12210197 Forwards IE Insp Repts 50-361/82-36 & 50-362/82-29 on H21101-05 No noncompliance noted BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 82/12/02 PAPAY.L T Southern California Edison Co 2pp 16484 317 24X Fiche 50-361.82/12/02.8212210197
- --B212210204 IE Insp Repts 50~361/82-36 & 50~362/82-29 on B21101~05 No noncompliance noted Major areas inspected fire protection/ prevention program & program implementation SCCAN.K M , ZWETZIG,0 B Division of Resident, Reactor Project & Engineering Programs 82/12/01 9pp 16484 319 24X Fiche 50~361.82/12/02.8218210197
- 8:08190289 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEVOUND.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc t13pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- Bi:08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay fackets" Syc list encl
 JORDANA E L Division of Engineering & Quality Assurance 82/12/03
 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x
 Fiche 50-000, 82/12/03, 8208190261
- 97:2290030 Partial response to FOIA request for documents re EE Kent allegations concerning facilities Forwards Documents 1.2.4.
 7.10.15 & 16 listed in App A Remaining documents will be released when inspired in saved Tapes available in FOR FELTON.J M. Division of Rules and Records 82/12/03 CARPENTER.T Drange County Alliance for Burvival 3pp 16607 056 24X Fiche 50-362,82/12/03,82/1229030
- --0212290035 Summarizes 821006 telcon w/J D/Dell (LA Times) re EE Kent allegations concerning welding practice at facilities KIRSCH DF Division of Resident, Reactor Project & Engineering Programs 82/10/06 Division of Resident, Reactor Project & Engineering Programs 2pp 16607 077 24X Fiche 50-362,82/12/03,8212270030
- --821227003B Forwards util/Bechtel QA audit package re EE Kent allegations concerning facilities CURRAN-J M Bouthern California Edison Co 82/10/07 KIRSCH, D F Region 5, Office of Director 48pp 16607 079 24X Fiche 50-362,82/12/03,8212270030

- --8212290049 Figure NB-4250-1, "Welding End Transitions Max Envelope, W/annotation "Example of Approx Slopes Discovered 821025 at San Onofre Nuclear Generating Stations "Charts re welding & pipe support entl KENI,E E Affiliation Unknown 82/11/12 3pp 14607 129 24X fiche 50-342,82/12/03,8212290030
- B212210362 Forwards IE Safeguards Insp Rept 50-362/82-22 on B21005-08 & notice of deviation Rept 3 notice of deviation withheld (ref 10CFR2 790)
 NORDERHAUG,L R Division of Radiological Safety & Safeguards
 Program B2/12/14 PAPAY,L T Southern California Edison Co 2pp 16495 159 24X Fiche 50-362,82/12/14,8212210362
- 8POB190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Munitoring " Svc list encl
 DEYOUND, RC Director's Office Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24x Fiche 50-000,82/12/16.8208190267
- 8708170268 IE Info Notice 82-50, "Mod of Splid State AC Undervoltage Relays Type ITE-27" Svc list enc! JORDAN.E.L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208170268
- S Reportable occurrences. LERs & related correspondence
- B212040012 Deficiency rept re Stewart-Stevenson governor output voltage erratic behavior causing momentary speed changes of diesel generator 36002 Initially reported on B21021 Evaluation being performed CURRAN, J M Southern California Edison Co B2/10/22 ENGELKEN, R H Region 5, Office of Director ip 16313 326 24% (1che 50-362, 82/10/22, 8212040012
- BP12140035 ROs 82-142 & 82-001 on 821124 & 28.CREACUS Train A declared inoperable due to charcoal filter replacement on cooling unit E-418 & emergency chiller E-335 inoperable due to high motor winding tenp trip Cooldown initiated RAY. H B Southern California Effson Co 82/11/30 ENGELKEN. R H Region 5, Orfice of Director 2pp 16409 291 24X Fishe 50-361,82/11/30,8212140035
- 8212290413 Discusses ESF actuation sys B21217 event & short-term actions taken to reduce probability of recurrence NRC concurrence w/Unit 2 power operation & continuation of Unit 3 shartup test program requested DIETCH.R Southern California Edison Co 82/12/28 EISENHUT.D O Division of Licensing 6pp 16587 093 24X Fiche 50-361,82/12/28,8212290413

DUCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT R F Security, medical, energency & fire protection plans

- OP12100070 Submits permanent backup, interim primary & interim backup emergency operations facilities (EOF) info per 821202 verbal request EOF completed & occupied in Oct 1982
 CLAYTON,F L Alabama Power Co 92/12/03 VARGA,S A Office of Nuclear Reactor Regulation, Director 3pp 16375 359 24X Fiche 50-348,82/12/03.0212100070
- J. Insurance & indemnity information
- 8:12280223 Forwards Endorsement 48 to NELIA Policy NF-238 & Endorsement 40 to MAELU Policy MF-93 DUCK, J R Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 16582 276 24X Fiche 50-348,82/12/20,8212280223
- 6212280348 Forwards Certificates of Insurance N-62 & N-73 for Endorsements 1.2 & 3 to NELIA Policy NF-238 & Certificates of Insurance M-62 & M-73 for Endorsements 1.2 & 3 to MAELU Policy MF-93

 DVCK, J R Marsh & McLennan, Inc. 1 M & M Nuclear Consultants, Inc. Div 82/12/20 SALTZMAN, J Assistant Director for State & Licensee Relations 35pp 16561 146 24X Fiche 50-348, 82/12/20, 8212280348

P Operating license stage documents & correspondence

- B212020108 "SER of Pump & Valve Inservice Testing (IST) Program Submitted by AL Power Co for Joseph & Farley Nuclear Plant, Unit 2," interim rept COOK, T L , HUBBLE, H H , ROCKHOLD, H C EG&G. Inc FIN A-6430 8212020108 8210/31 HAMMER, C G Division of Engineering 141pg 16309 252 24% Fiche 50-364,82/10/31,8212020108
- 8212020130 Informs that info requested in Generic Ltr 82-22 re steam generator tube integrity, maint, repair & worter exposures submitted via annual CFR repts & util 820412 ltr CLAYTON,F t. Alabama Power Co. 82/11/24 EISENHUT, D. G. Division of Licensing 2pp 14272 037 24X Fichs 50-348,82/11/24.
- 8212080060 Forwards Amend 20 to License NPF-8, safety evaluation & notice of issuance & availability Amend modifies valve
- VAROA: B A Operating Reactor: Branch 1 82/11/24 CLAYTON: F L Alabame Power Co 3pp 16367 200 24% Fiche 50-364.82/11/24.
- --8212080077 Amend 20 to License NPF-8, modifying valve leakage test criteria on one-time basis for startup from first refueling outage only

 VARGA-S A Operating Reactors Branch 1 82/11/.
 16367 203 24X Fiche 50-364,82/11/24.8212080060 82/11/24 Apr
- --8212080080 Safety evaluation supporting Amend 20 to License NPF-8 * Office of Nuclear Reactor Regulation, Director 82/11/24 (14367-209 24X Fiche 50-364,82/11/24,8212090060
- --8212060083 Notice of issuance & availability of Amend 20 to License NPF-B VARGA, S.A.
 - Operating Reactors Branch 1 82/11/24X Fich 50-364,82/11/24.8212080060 82/11/24 2pp
- 8212/80033 Advises that all portions of post-accident sampling sys, including containment atmosphere & vent stack ac-powered solenoids operational (ref NURES 0737, Item II B 3) Solenoids mistakenly installed utilizing dc power CLAYTON, F L Alabama Power Co. 82/11/30 VARGA. S A Office of Nuclear Reactor Regulation, Director ip 16421 242 24% Fiche 50-364, 82/11/30, 8212150033
- 8P12160568 Forwards Amend 21 to License NPF-B.safety evaluation & notice of issuance & availability Amend extends time to complete mod to safety-related mesonry wail REEVES.E A Operating Reactors Branch ! 82/12/02 CLAYION.F L Alabara Power Co 2pp 16466 179 24X Fiche 50-364.82/12/02.8212160368
- --B212160978 Amend 21 to License NPF-B, extending time scheduled to complete mod to safety-related masonry wall until second refueling outage or until NRC accepts energy balance technique showing no mod needed VAROA. S A Operating Reactors Branch 1 82/12/02 2pp 18466 181 247 Fiche 50-364, 82/12/02,8212160568
- --8212160581 Bafety *valuation supporting Amend 21 to License NPF-8

 * Office of Nuclear Reactor Regulation. Director 82/12/02 :
 16466 183 247 Fiche 50-364.82/12/02.8212160368
- -8212160596 Notice of issuance & availability of Amend 21 to License NPF-B VAROA.6 A Operating Reactors Branch 1 82/12/ 16466 186 24x Fiche 50-364,82/12/02,8212160568 82/12/02 250
- 208190263 Generic Ltr 82-32 to all PWR licensess re potential steam generator-related generic requirements Forwards Science Applications, Inc draft rapt re sub; requirements Comments requested within 30 days of its St. 1ist encl EEGENRUT, D. 0. Division of Licensing 82/12/09 Consolidated Edison Co. of New York, Inc. 29pp. 16629 247 24X Fichs 50-000, 82/12/09, 8208190263
- 212140103 Generic Ltr B2-2B to all licensees of operating Hestinghouse & C-E PMRs (except Arkansas Nuclear One, Unit 2 & San Onofre 2 & 3) re inadequate core cooling instrumentation sys Svc list encl EIBENHUT, D 0 Division of Licensing B2/12/10 Yankee Atomic EIBENHUT, D 0 27pp. 16670 035 24X Fiche 50-000,82/12/10, B212140103
- 112170234 Clarifies 821008 proposed Tech Spec change to delete turbine valve testing requirements. Proposed change not inconsistent w/WCAP-1016 conclusions Expedited review requested Hestinghouse draft 821210 ltr encl CLAYTON.F.L. Alabama Power Co 62/12/10 VARGA.S.A. Office of Nuclear Reactor Regulation, Director 5pp 16489 357 24X Fiche 50-364, 82/12/10, 8212170234.

- 82(2210)30 Request for amond to License NPF-8, deleting eight nonsafety-related snubbers from Tech Spec Table 3 7-4a Safety evaluation encl CLAYTON:F L. Alabama Power Co. 82/12/10 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 3pp. 16485-078 24X Fiche 50-364, 82/12/10, 82(22)10(3)
- --8212210132 Processed Tech Spec Table 3 7-4a, deleting eight nonsafeturelated snubbers Co 82/12/10 3pp 16485 OS1 24x Fichs 50-364, 82/12/10, 8212210130
- 8212280280 Requests approval by 830701 of 820810 ltr re RCS pressure isolation valve leak testing to support planning & scheduling of next refueling outage CLAYTON: FL Alabama Power Co 82/12/23 VAROA. S A Office of Nuclear Reactor Regulation. Director 1p 16561 243 24X Fiche 50-348, 82/12/23, 8212280280
- Q Inapection reports, IE Bulletins & correspondence
- 8208190240 IE Builetin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants "Syc List encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/20 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list conclude the concluded of the conc
- 8P12070412 Advises that IE Bulletin 82-01, Revision 1, Suppl 1, review of FIGURE ADVISES THAT IE Bulletin 82-01, Revision 1, Suppl 1, review radiographs furnished by ITT Grinnell for piping assemblies, revealed two assemblies wellstred radiographs on total of three welds Penetrameter image darkened CLAYTON-F L Alabama Power Co 82/11/09 D'REILLY, J P Region Office of Director 2pp 14365 042 24X Fiche 50-348, 82/11/09, 8212090412
- 8212070435 Confirms 821108 telcon re enforcement conference scheduled for 821117 in Atlanta, OA Circumstances surrounding inoperable containment spray say will be discussed D'REILLY, J P Region 2: Office of Director 82/11/12 MCDONALD, R P Alabema Power Co 2pp 16363 266 24X Fiche 50-364, 82/11/12, 8212090435
- 8212090511 Forwards IE Insp Repts 50-348/82-25 & 50-344/82-24 on 820916-1022 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 82/11/17 MCDGMALD R P Alabama Power Co 2pp 16367 014 24X Fiche 50-348, 82/11/17, 8212090511
- --8212070517 IE Imag Repts 50-348/82-25 & 50-344/82-24 on 820914-1022 No noncompliance noted Major areas inspected monthly surveillance observation to surveillance operational safety verification

 BRADFORD.W H , CANTRELL.F Division of Project & Resident

 Program 82/11/17 8pp 16367 016 24X Fiche 50-348.82/11/17,
 8212090511
- 820B190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000.82/11/18.8208190251
- B208190236 IE Info Notice B2-46, "Defective & Obsolete Combination Padlocks" Bvc list encl
 DEYOUNG, RC Director's Office, Office of Inspection and Enforcement, B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411
- 8212090432 Confirms 821123 telcon re 821214 mgt meeting in Birmingham, AL to review results of first phase of annual appraisal of regulatory performance Proposed agenda encl LEWIS.R C Division of Project & Resident Programs 82/11/29 MCDONALD.R P Alabama Fower Co 3pp 16364 271 24X Fiche 50-348, 82/11/29, 8212090432
- 820B190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! CDBB-L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 02B 24X Fiche 50-000,82/11/30,8208190257

- 8212070336 Submits info per IE Bulletin 80-11. "Masonry Walls." re concrete block wall 2CBH-34 Motor control ctr can be supplied by power feed from Unit i within 2-h.;f seismic event occurred & power supply lost CLAYTON.F L. Alabama Power Co. 82/12/01 VARGA.S A. NRC No Detailed Affiliation given ip 16343 204 24X Fiche 50-364.82/12/01.8212070336
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 820819026; IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAK; E.C. Divisson of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000: 82/12/03:8208190261
- 82/08/190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNO, R C Director's Office Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208;90268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000,82/12/20,8208190268
- R Periodic operating reports & related correspondence
- G212170297 Forwards monthly operating rept for Nov 1982 CLAYTOV.F L Alabama Power Co 82/12/13 Office of Management and Program Analysis Ip 16453 215 24X Fiche 50-364.82/12/13. 8212170297
- --8212170302 Monthly operating rept for Nov 1982 HAIRSTON.W G Alebama Power Co 82/12/04 Bpp 16453 216 24X Fiche 50-364.82/12/13.8212170277
- S Reportable occurrences, LERs & related correspondence
- G212090295 Forwards LER 82-046/03L-0 CLAYTON, F L Alabama Power Co 82/12/01 O'REILLY, J P Region 2 Office of Director 1p 14365 131 24X Fiche 50-364, 82/12/01, G212090295
- --BR12070312 LER 82-046/03L-0 on 821028, snubber 2RG-RB0A determined to be inoperable when found w/damaged & leaking O-ring Snubber rebuilt, satisfactorily tested & reinstalled No evidence of damage to piping supports or restraints near snubber HAIRSTON, W G Alabama Power Co 82/12/01 Region 2, Office of Director ip 16365 132 24X Fiche 50-364, 82/12/01.8212090275
- B212300216 Forwards LERs 82-047/03L-0.82-048/03L-0.82-049/03L-0 & 62-050/03L-0 CLAYTON,F L Alabama Power Co 82/12/23 Region 2, Office of Director ip 16598 107 24X Fiche 50-364,82/12/23,8212300214
- --8212300223 LER 82-047/03L-0 on 821124. during surveillance test review, air temp nonitoring not performed within required time interval Caused by personnel serior Requirement (FNP-2-STP-63 O) revised to include performance of air temp monitoring HALRSTON. W Q Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 108 24x Fiche 50-364, 82/12/23, 8212300216
- --9212300227 LER 82-048/03L-0 on 821127, source range channel N-32 declared inoperable due to loss of detector voltage Caused by faulty high voltage connector Connector replaced HAIRSTON,N G Alabama Power Co 82/12/23 Region 2, Office of Director ip 16598 109 24X Fiche 50-364,82/12/23,8212300216
- --8212300231 LER 82-049/03L-0 on 821201, containment atmosphere activity monitors R-ii (particulate monitor) & R-12 (gaseous monitor) declared inoperable when vacuum pump tripped due to erroneous high flow signal Caused by faulty high flow relay HAIRSTON,W 0 Alabama Power Co 82/12/23 Region 2, Office of Director 1p 16598 110 24X Fithe 30-364,82/12/23,8212300216
- --B212300236 LER 82-050/03L-0 on 821124, source range channel N32 declared inoperable due to erratic readings Caused by faulty detector on N31 & faulty high voltage power supply cable connector on N32 Detector & cable connector replaced HAIRSTON, 0 Alabama Power Co 82/12/23 Region 2, Office of Director ip 16398 111 24X Fiche 50-364,82/12/23,8212300216

- DDCKET 50-366 EDMIN I HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 82:2150009 Confirms telcon re emergency facility status per Generic Ltr 82-10 Structure complete & habitable Info equipment not completely installed but facility operable BECKHAM, J T Georgia Power Co 82/12/08 Office of Nuclear Reactor Regulation. Director ip 16421 138 24X Fiche 30-321.82/12/08.8212180009
- J Insurance & indemnity information
- 8212280369 Forwards Endorsement 74 to NELIA Policy NF-215 & Endorsement 60 to MAELU Policy MF-78

 DUCK, J. R. Harsh & McLenhan, Inc., M. & M. Nuclear Consultants, Inc. Div. 82/12/20

 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 16560-047 24X Fiche 50-321.827.12/20.821809369
- P Operating license stage documents & correspondence
- B212100393 Requests verification that encl acceptance criteria for NUREO-0737.15em II K 3 22. "Automatic Switchover of RCIC Bys Suction." satisfied Response requested within 30 days STOLZ.J F Operating Reactors Branch 4 82/08/04 BECKHAM, J. T Georgia Power Co 4pp 16389 220 24X Fiche 50-321,82/08/04, 821210393
- 8211230066 Generic Ltr 82-27 to all BWR licensess of operating reactors except LACBWR. Big Rock Point, Dresden L. Humboldt Bay, applicants for DL & holders of CP re transmittel of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT.D 0 Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/19, 8211230066
- 8912170246 Advises that specific containment & purge valves identified in NRC 821110 ltr are not applicable to facilities Meeting requested to determine status of remaining issue re purging & venting BECKHAHLJ T Georgia Power Co 82/12/13 Office of Nuclear Reactor Regulation, Director ip 16457 178 24X Fiche 50-321,82/12/13,8212170246
- 8212290450 Informs of post-implementation review of NUREG-0737. Items II F 1 4.11 F 1 5 & II F 1 6 re containment pressure, water level & hydrogen monitors Add1 info & guidance for answering questions encl
 STGLZ.J F Operating Reactors Branch 4 82/12/17 BECKHAM. J T Georgia Power Co 10pp 16406 074 24X Fiche 50-321.82/12/17, 6212290450
- B212290151 Revises estimated completion date for implementation of NUREO-0737. Item II B 3 to 830401. in response to Generic Ltr 82-05 Interim sampling capabilities per NUREG-0578 provided in 820407 ltr GUCWA, L T Georgia Power Co 82/12/20 Office of Nuclear Reactor Regulation. Director 1p 16582 239 24X Fiche 50-321.82/12/20. 82/220151
- G Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants "Svc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fichs 50-000,82/10/28,8208190240
- B208170245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Byc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp. 14372 142 24X Fiche 50-006-82/11/05,8298190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 107pp 16411 199 24x Fiche 50-000, 82/11/18, 8208190251

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svr list enc) DEYOUND,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 055 24% Firms 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radigactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Fichs 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYDUNG, RC Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X fiche 50-000, 82/12/03, 8208190259
- B208[9026] IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc][st enc! JGRDAN.E L Division of Engineering & Quality Assurance B2/12/03 Consolidated Edison Co of New York, Inc | 110pp | 18462 064 | 24 Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list enc!

 DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consplidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 [E Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 28% Fiche 50-000, 82/12/20, 9208190268
- 8212300189 Advises that NRC has no objection to use of 1980 Edition of ASME Section XI & addenda through Winter 1980 for inservice insp of Category B-H welded supports in response to 820830 request for relief from 1974 Edition requirements STOLZ. J F Decreting Reactors Branch 4 82/12/20 BECKHAM. J T Georgia Power Co 2pp 18624 034 24X Fiche 50-321,82/12/20, 8212300189
- R Periodic operating reports & related correspondence
- B212170353 Forwards monthly operating repts for Nov 1982 NIX.H C Georgia Power Co B2/12/07 Director's Office Office of Inspection and Enforcement 1p 16459 191 24X Fiche 50-321.82/12/07.8212170353
- --8212170359 Monthly operating repts for Nov 1982 SMITH.A Georgia Power Co 82/12/07 10pp 16459 192 24X Fiche 50-321.82/12/07.8212170353
- S Reportable occurrences. LERs & related correspondence
- 82:2020292 Forward: LER 82-120/03L-0
 NIX.H C Georgia Power Co 82/11/19 O'REILLY, J.P. Region 2,
 Office of Director 1p 16279 140 24X Ficha 50-366, 82/11/19,
 G2:2020292
- --8212020295 LER 82-120/03L-0 on 821022.berrier adjacent to silicone foam fire barrier in cable spread room found breached Caused by penetration left unsealed after installation of conduit Maint request initiated Seal repaired on 821102 SUMNER.H L Georgia Fower Co. 82/11/19 Region 2. Office of Director ip 16279 141 24X fiche 50-366.82/11/19.8212020292
- BP12090142 Forwards updated LER 78-057/03X-1 NIX-H C Georgia Power Co B2/11/23 D/REILLY, J.P. Region 2, Office of Director 1p 16359 172 24X Fiche 50-366, 82/11/23, 6212070142
- --8212090149 Updated LER 78-059/03X-1 on 781026.during review of HNP-832 limiting conditions for operation instrument data sheets.

 32 instruments exceeded calibr interval Caused by oversight Instruments calibr Personnel counseled re recordkeeping.

 TIPPS 8 8 Georgia Power Co 82/11/23 Region 2. Office of Director Ip 16359 173 24X Ficha 50-366.82/11/23.8212090142
- 8212090247 Forwards LER 82-129/03L-0 NIX.H C Georgia Power Co. 82/11/23 O'REILLY.J P. Region 2. Office of Director 1p 16361 349 24X Fiche. 50-366, 82/11/23, 8212090247

- --B212090254 LER 82-123/03L-0 on 821030, during insertion of control rods for reactor shutdown reed switch position indicators for control rods 14-07 & 34-43 found inoperable Caused by component failure Indicators will be repaired TIPPS:SB Georgia Power Co 82/11/23 Region 2, Office of Director ip 16361 350 24X Fiche 50-366,82/11/23,8212090247
- 8212090391 Forwards updated LER 80-097/03X-1 NIX.H C Georgia Power Co 82/11/23 D'REJLLY, J P Region 2, Office of Director 1p 16365 040 24X Fiche 50-366.82/11/23, 8212090381
- --8212090388 Updated LER 80-097/03X-1 on 800625, while performing HPC1 steam line dolta P instrument FT&C procedure, flow switch MO04 setpoints found to be out of tolerance Gaused by setpoint drift Switch calibr, tested & returned to svc TIPPS, S B Georgia Power Co 82/11/23 Region 2, Dffice of Director ip 16365 041 24% Fiche 50-366, 82/11/23, 8212090381
- BD12090386 Forwards updated LER 80-019/03X-1 NIX,H C Georgie Power Co 82/11/23 O'REILLY,J P Region 2, Office of Director 1p 16364 193 24X Fiche 50-366,92/11/23, 8212090386
- --0212070391 Updated LER 80-019/03X-1 on 800227, erroneous reading on drywell hydrogen dioxide analyzer A recorder disclosed Caused by diaphragm farlure in analyzer vacuum pump Diaphragm replaced Analyzer calibr & functionally tested TIPPS S B Georgia Power Co 02/11/23 Region 2, Office of Director 1p 16364 194 24X Fiche 50-366,82/11/23,8212090386
- 8212090121 Forwards LER 82-125/03L-0 NIX.H C Georgia Power Co 82/11/30 D'REILLY, J P Region 2 Office of Director 19 16357 325 24X Fiche 50-366.82/11/30. 6212090121
- --8212070126 LER 82-125/03L-0 on 821103, w/reacter protection sys (RPS) alternate supply out of svc for maint.RPS supply over voltage relay discovered out of calibr Caused by component failure due to setpoint drift Relay recalibr TIPPS.S B Georgia Power Co. 82/11/30 Region 2. Office of Director ip 16357 326 24X Fiche 50-366.82/11/30,8212070121
- 8212090329 Forwards updated LER 81-084/03X-1 NIX.H C Ocorgia Power Co 82/11/30 O'REILLY, J P Region 2-Office of Director 1p 16365 079 24X Fiche 50-366.82/11/30-8212090329
- --B212090335 Updated LER 81-084/03X-1 on B10903,N005 HPC1 steam line delta P suitch found to actuate at 204 5 inches water Caused by setpoint drift Barton Model 288A switch recalibr, tested & returned to svc TIPPS-8 B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16365 080 24X Fiche 50-366,82/11/30,8212090329
- G212070389 Forwards LER 82-124/03L-0 NfX.H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2) Office of Director 1p 16364 249 24X Fiche 50-366, 82/11/30, G212090389
- --8212090399 LER 82-124/03L-0 on 821102, during administrative review, temporary changes made to arm calibr procedure not reviewed & signed within required 14 days Caused by personnel error One dept assigned responsibility for tracking changes TIPPS:8 B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16364 250 24X Fiche 50-366,82/11/30,8212090389
- SP12090437 Forwards updated LER 80-100/01X-1 NIX.H C Georgia Power Co 82/11/20 0'RELLLY.J P Region 2. Office of Director 1p 16364 176 24X Fiche 50-366.82/11/30. S212090437
- --B212070446 Updated LER 80-100/01X-1 on 800702, during testing, switches NDC2A D & NO11A D actuated above Tech Spers limit of plus/sinus 2 psig Caused by setpoint drift Bwitches recalibr, tested & returned to svc
 TIPPS.S D Georgia Power Co B2/11/30 Region 2, Office of Director 2pp 16364 177 24X Fiche 50-366, 82/11/30, 8212090437
- 8212100264 Forwards updated LER 80-141/03X-1 NIX.H C Georgia Fower Co 82/11/30 O'REILLY.J P. Region 2. Office of Director 1p 16377 050 24X Fiche 50-366.82/11/30. 8212100264
- --8212100279 Updated LER 80-141/03X-1 on 801014, while making power changes from 2,180 to 1,980 MHt,N004 HPCI steam line dp switch found to actuate at 198 inches water Caused by setpoint drift Switch recalibr TIPPS, 8 B Georgia Power Co 82/11/30 Region 2, Office of Director 1p 16377 051 24X Fiche 50-366,82/11/30,8212100264

- 8212100282 Forwards updated LER 80-103/01X-1 NIX,H C Deorgia Power Co 82/11/30 O'REILLY,J P Region 2. Office of Director 1p 16377 146 24X Fiche 50-366,82/11/30. B212100882
- --B212100P86 Updated LER 80-103/01X-1 on 800709, at 97% power, high drywell pressure switches NOiOA D actuated at 2 21, 2 34, 2 27 & 2 47 psig, respectively; above Tech Spec limit of plus/minus 2 psig Caused by setpoint drift Switches recalibr & tested TIPPS-S B Georgia Power Co B2/11/30 Region 2, Office of Director 2pp 16377 147 24% Fiche 50-366, 82/11/30, 8212100282
- 82121003(1 Forwards updated LER 81-121/03X-1 NIX.H C Oeorgia Power Co 82/11/30 O'REILLY, J P Region 2, Office wf Director 1p 16376 279 24X Fithe 50-366, 82/11/30, 8212100311
- --B212109314 Updated LER B1-121/03X-1 on B11207, at 2.402 MHt,N004 HPCI steam line dp switch actuated at 207 5 inches below Tech Spec limit of plus/ninus 3007 rated flow Caused by setpoint drift Switch recalibr, tested & returned to svc TIPPS, S B Georgia Power Co B2/11/30 Region 2, Office of Director 1p 16376 280 24X Fichs 50-366, 82/11/30, 8212100311
- 8P12140421 Forwards updated LER 80-076/03X-1 NIX.H C Georgia Power Co 82/11/30 D'REILLY, J P Region 2, Diffice of Director 1p 16404 197 24X Fiche 50-366, 82/11/30, 8212140421
- --8212140429 Updated LER 80-076/03X-1 on 800429.61 of 137 control rod driveline hydraulic control unit pressure switches found to have setpoints greater than Tech Spec limit Caused by instrument drift Switches recalibr & returned to svc TIFPS.S B Georgia Power Co 82/1/30 Region 2, Office of Director 1p 16404 198 24X Fiche 50-346,82/1/30,8212140421
- BP12140433 Forwards updated LER 79-124/03X-1 NIX-H C Georgia Power Co 82/11/30 O'REILLY, J P Region 2. Office of Director Ip 16404 361 24X Fiche 50-366,82/11/30, 8212140433
- --8212140436 Updated LER 79-124/03X-1 on 791120, vacuum breaker E failed to open per Tech Specs Caused by stuck valve operator Valve operator freed & repaired Torus/drywell vacuum breaker E satisfactorily tested & returned to svc TIPPS,S B Georgia Power Co 82/11/30 Region 2, Office of Director ip 16404 362 24X Fiche 50-366,82/11/30,8212140433
- 8P12090190 Forwards updated LER 82-112/01X-2 NIX.H C Georgia Power Co 82/12/02 O'REILLY, J P Region 2, Office of Director 1p 16361 295 24X Fiche 30-366, 82/12/02, n212090190
- --B212090193 Updated LER 82-112/01X-2 from B21009-1116 inadequacies discovered in test procedures for automatic initiation logic of listed plant sys Caused by failure to test relay &/or continuity of one or more sets of contacts SUMNER, H L Quergia Power Co B2/12/02 Region 2, Office of Director 2pp 16361 296 24X Fiche 50-366. B2/12/02, 8212090190
- B212170155 Forwards LER 82-126/03L-0 NIX.H C Ceorgia Power Co 82/12/03 O'REILLY, J P Region 2, Office or Director 1p 16450 298 24X Fiche 50-366,82/12/03, 8212170155
- --8212170165 LER 82-126/03L-0 on 821105, post-accident high drywell pressure alarm failed to actuate during quarterly surveillance test Caused by erroneous wiring of drywell & torus pressure recorder Wiring erron corrected TIPPS.5 9 Georgia Power Co. 82/12/03 Region 2, Office of Director 1p 16450 299 24X Fiche 50-366,82/12/03,8212170155
- G212140115 Forwards updated LER 81-116/03Y-1 NIX.H C Georgia Power Co 82/12/07 O'REILLY.J P Region 2. Office of Director 1p 16408 245 24X Fiche 50-366.82/12/07. G2[2140115
- ~-B212140123 Updated LER B1-116/03X-1 on B11125.NO04 HPCI steam line differential pressure switch actuated above Tech Spec limits during performance of steam line Instrument FT & C procedures Caused by setpoint drift Switch recalibr TIPPS.5 B Georgia Power Co 62/12/07 Region 2, Office of Director 1p 16408 246 24X Fiche 50-366.82/12/07.8212140115
- 8212210446 Forwards LER 92-127/03L-0 NIX.# C Ocorgia Power Co 82/12/07 O'REILLY, J P Region 2. Office of Director 1p 16489 194 24X Fiche 50-366,82/12/07, 8212210446

- --B212210452 LER 82-127/03L-0 on 821113, during hydrogen & oxygen analyser FT & C procedure, A drywell analyser found inoperable Caused by component failure, due to loose connection Connection repaired & component returned to evc
 TIPPS, S B Georgia Power Co 82/12/07 Region 2, Office of Director 1p 16489 195 24% Fiche 50-366, B2/12/07, B212210446
- 8212150070 PND-II-82-134 on 821208.bomb threat received while in final preparation for full scale emergency drill Security determined call came from security guard posted at entry gate to owner controlled area Guard fired & arrested IILLMAN.A. MCGUIRE. DR Region 2. Office of Director 82/12/07 2pp 16430 187 24X Fiche 50-021.82/12/09.8212150070
- 8212280157 Forwards LER 92-122/03L-0 NIX.H C Georgia Power Co 82/12/16 O'REJLLY, J P Region 2, Office of Director Ip 16556 133 24X Fiche 50-366,82/12/16, 8212280157
- --8212280161 LER 82-122/03L-0 on 821123, during Mode 1 at 2,417 MWt, fire datector surveillance safety-related areas procedure not completed by latest possible date (821123) Caused by personnel oversight Personnel counselled TIPPS.8 8 Georgia Power Co 82/12/16 Region 2, Office of Director 1p 14556 134 24X Fiche 50-366,82/12/16,8212280159
- B21230005B Forwards updated LER 82-043/03X-1 NIX.H C Georgia Power Co B2/12/16 O'REJLLY, J P Region 2, Office of Director 1p 16598 206 24X Fiche 50-366, 82/12/16, B21230005B
- --8212300063 Updated LER 82-043/03X-1 on 820428, w/plant in refueling outage, delta pressure switch NO04 actuated above Tech Spec limit Caused by setpoint drift Switch recalibr TIPPS B Georgia Power Co 82/12/16 Region 2. Office of Director 1p 16598 207 24X Fiche 50-366,82/12/16,8212300058
- 8212300284 Forwards updated LER 81-102/03X-1 NIX.H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2. Office of Director ip 16594 073 24X Fichs 50-366, 82/12/16, 8212300284
- --8212300290 Updated LER 81-102/03X-1 on 811026.P0018 primary containment hydrogen peroxide analyser declared inoperable due to erratic operation Caused by worn pump head valve body Pump repaired & analyser returned to svc
 TIPPS.8 B Georgia Power Co 62/12/16 Region 2, Office of Director 1p 6594 076 24X Fiche 50~366.82/12/16.8212300284
- B212300285 Forwards updated LER 80-109/03X-1 NIX.H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 16575 117 24X Fiche 50-366, 82/12/16, 8212300285
- ---B212300292 Updated LER B0-109/03X-1 on 800809, during HPCI valve operability procedure. HPCI suppression chamber suction valve failed when cycled to check battery ground Caused by motor winding failure due to humid temp Valve motor repaired TIPPS. B B Georgia Power Co B2/12/16 Region 2, Office of Director ip 16995 118 24X Fiche 50-366, B2/12/16, B212300288
- 8212300275 Forwards updated LER 81-115/03X-1 NIX.H C Georgia Power Co 82/12/14 O'REILLY, J P Region 2, Office of Director 1p 16594 290 24X Fiche 50-366, 82/12/16, 6212300295
- --B212300298 Updated LER Bi-115/03X-1 on B21123 during performance of HPCI turbine exhaust diaphrogm pressure instrument FT&C procedure, pressure switch NOI2A actuated above Toch Spec limit Caused by setpoint drift Switch calibr TIPPS.S B Georgia Power Co 82/12/16 Region 2. Office of Director ip 16594 271 24X Fiche 50-366.82/12/16.8212300295
- 8212300323 Forwards updated LER 80-124/03X-1 NIX.H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, Office of Director, ip 16594 082 24X Fiche 50-366, 82/12/16, 321230323
- --8212300325 Updated LER 80-124/03X-1 on 600813 & 27. during surveillance of torus/drywell vacuum breakers. J & I breakers failed to give proper light indication Caused by air control valves being out of adjustment Valves adjusted & breakers tested TIPPS & B Georgia Power Co 82/12/16 Region 2, Uffice of Director ip 16594 083 24X Fiche 50-366.82/12/16.8212300323
- B212300340 Forwards updated LER 80-101/03X-1 NIX:H C Qeorgia Power Co 82/12/16 O'REILLY, J P Region 2. Office of Director 1p 16594 223, 24X Fiche 50-366,82/12/16, B212300340

- --8212300345 Updated LER 80-101/03X-1 on 800711.HPCI sys failed to manual start due to failure of FOOG HPCI injection valve Caused by motor unnding failure due to design problem Motor replaced Valve tested & returned to svc TIFPS.5 B Georgia Power Co 80/12/16 Region 2, Office of Director 1p 14594 224 24X Fichs 50-366.82/12/16.8212300340
- 0212300344 Forwards updated LER 80-129/03/-1 NIX.H C Georgia Power Co 82/12/16 O'REILLY, J P Region 2, DFFire of Director 1p 16594 227 24X Fiche 50-366.82/12/16, 8212330244
- -- B212300346 Updated LER 80-129/03X-i on 800918, torus/drywell vacuum breaker 0 failed to open upon actuation of test switch Caused by air control valve out of adjustment Valve adjusted & breaker satisfactorily bested & returned to svc on 800929 TIPPS.8 8 Georgia Power Co 82/12/16 Region 2. Office of Director ip 16594 228 24X Fiche 50-366.82/12/16.8212300344
- 8212300098 Forwards LER 82-128/03L-0 NIX.H C Georgia Power Co 82/12/21 O'REILLY, J P Region 2, Office of Director Ip 16598 129 24X Fishe 50-366, 82/12/21, 8212300098
- --8212300102 LER 82-128/03L-O on 821125 during power ascension. Core max fraction of limiting power density found greater than Tech Spec limit Caused by control rod movement in low xenon concentration producing higher power Monitor adjusted SUNNER.H L. Georgia Power Co. 82/12/21 Region 2, Office of Director 2pp 16598 130 24X Fishe 50-366.82/12/21,8212300098

DOCKET 50-367 BAILLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 86:11230064 Generic Ltr 82-27 to all BHR licenses of operating reactors except LACBHR, Big Rock Point, Dresden I. Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0783 Svc list encl 4/0 stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 163B7 004 24X Fiche 50-000, 82/11/15, 8211230066
- BP12160729 Forwards evaluation of util final rept re site restoration, per ASLB 820506 order Util has restored site per approved restoration plan SCHWENCER.A Licensing Branch 2 B2/12/13 SHORB,E M Northern Indiana Public Service Co 5pp 16466 008 24X Fiche 50-367, 82/12/13.6212160729
- Q Inspection reports: IE Bulletins & correspondence
- B212100195 Forwards IE Insp Rept 50-367/B2-02 on 821116 No noncompliance noted KNOP.R C Division of Project & Resident Programs 82/11/24 SHORB.E M Northern Indiana Public Service Co 2pp 16376 200 24X Fiche 50-367.82/11/24.82/2100195
- ~~8212100200 IE Insp Rept 50-367/82-02 on 921116 No noncompliance noted Major areas inspected site restoration activities PELKE.P R . KONKLIN.J E Division of Project & Resident Programs 82/11/24 2pp 16376 202 24% Fiche 50-367, 82/11/24, 8212100195

DOCKET 50-369 ARKANSAS NUCLEAR ONE, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8212070425 Responds to FDIA request for documents re 820807 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FDIA Exemptions 3, 5 & 7) FELTON. J M Division of Rules and Records 82/11/05 MCGARRY, J M Debevois & Liberman Spp 16355 003 24% Fiche 50-000, 82/11/05, 8212070425
- --B212070473 Concludes that all Region 4 licensees in compliance ω/B2020i deadlins for implementation of prompt notification sys COLLINS, U T Region 4, Office of Director B2/02/01 GRIMES, B K Division of Emergency Preparedness 2pp 16355 104 24X Fiche 50-000, B2/11/05, B212070425
- B212080074 Releases public version of revised emergency plan procedure FELTON, J M Division of Rules and Records B2/12/01 Document Management Branch ip 16367 185 24X Fiche 50-313,82/12/01, 8212080074

- --8212080082 Forwards public version of Revision 4 to Emergency Plan Procedure 1903 30. "Plant Evacuation" Receipt form encl * Ariansas Power & Light Co 82/11/12 NRC No Dotailed Affiliation Given 1p 16367 186 24X Fiche 50-313.82/12/01, 5012080074
- --8212080085 Public version of Revision 4 to Emergency Plan Procedure 1903 30, "Plant Evacuation" * Arkansas Power & Light Co 82/11/11 3pp 16367 187 24X Fiche 50-313, B2712/01, B212080074
- 8212090311 Forwards emergency operations facility (EOF) summary info, per 0 Vissing 821203 request & Generic Ltr 82-10 Const of permanent backup EOF completed MARSHALL, JR Arkansas Power & Light Co 82/12/06 STOLZ, JF Operating Reactors Branch 3 2pp 16365 127 24X Fiche 50-313,82/12/06.8212090311
- 8212150272 Releases public version of ack of receipt of licensee ltr transmitting amend to emergency plan FELTON.J M Division of Rules and Records 82/12/08 Document Management Branch 1p 16446 276 24X Fiche 50-313.82/12/08. 8212150272
- --8212150280 Submits public version of ack of receipt of licenses B20827
 1tr transmitting Amend 5 to emergency plan Info re
 compliance w/requirements of 10CFR50 54(t) re annual review
 & audits of emergency plan requested
 SEIDLE, W C Division of Resident. Reactor Project & Engineering
 Programs 82/11/24 CAVANAUOH, W Arkansas Power & Light Co
 2pp 16446 278 24X Fiche 50-313.82/12/09.8212150272
- --8212150288 Forwards public version of transmittal of Amend B to emergency plan; incorporating both State of AR & in-house comments W/o encl MARSHALL, J R Arkansas Power & Light Co 62/08/27 COLLINS, J Office of Nuclear Regulatory Research, Director DENTON, H R Office of Nuclear Resctor Regulation, Director Zpp 16446 280 24X Fiche 50-313,82/12/08,8212150272
- 8212160542 Forwards draft safety evaluations of util requests for exemptions from fire protection of safe shutdown capability & of safe shutdown capability in event of fire Proposed mode uill be reviewed in 1783 Confirmation of 821111 Itr needed CLARK,R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 BZ/12/08 CAVANAUGH,W Arkansas Power & Light Co 57pp 16447 125 24X Fiche 50-313,82/12/08,6212160542
- 8212280224 Discusses util 820701 response documenting results of review of fire iones for compliance w/100FR50 48 & App R Alternate shutdown capability would be provided by cross-feed between Units 1 & 2 Special entry for G valves will not be made.

 MARSHALL.J R Arkansas Power & Light Co 82/12/10 EISENHUT, D Ø Division of Licensing 1p 16562 176 24X Fiche 50-313,82/12/10,8212280224
- 8212230152 Releases public version of revised nuclear contingency plan procedure FELTON.J M Division of Rules and Records 82/12/15, Document Management Branch 1p 14543 279 24X Fiche 50-313,82/12/15, 201230152
- --8212230165 Forwards public version of Revision 1 to Nuclear Contingency Plan Procedure 9, "Emergancy Response Support " MARSHALL, J R Arkansas Power & Light Co BZ/12/10 COLLINS, J T. Region 4, Office of Director EISENHUT, D G Division of Licensing ip 16543 280 24X Fiche 50-313,82/12/15,8212230152
- --8212230172 Public version of Revision 1 to Nuclear Contingency Plan Procedure 7. "Emergency Response Support" 4 Arkansas Power & Light Co 82/11/15 86pp 16543.282 24X Fiche 50-313,82/12/15.8212230152
- P Operating license stage documents & correspondence
- 8212030169 Forwards info re NUREG-0737. Item II B.3. "Post-Accident Sampling Sys." in response to NRC 820701 request Grab sample sys utilized as backup to online sampling sys MARSHALL.U.R. Arkansas Power & Light Co. 82/11/24 CLARK.R.A. Operating Resctors Branch 3 870L7.U.F. Operating Resctors Branch 12pp 16306-254 24X Fiche 50-313.82/11/24,8212030169
- 6212060262 Requests extension until 930228 to respond to NRC 620921 request for Tech Spec revision re snubber surveillance. Extension needed to review implications of ANBI/ASME DM4-1982 MARSHALL, J.R. Arkaneas Fower & Light Co. 82/11/26 STOLZ, J.F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 2pp 16312 272 24X Fiche 50-313,82/11/26,8212060262.

- 8212060333 Requests extension to 830228 for submittal of App I revisions
 HARBHALL, J.R. Arkansas Power & Light Co. B2/11/30 BTQLZ, J.F.
 Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch
 3 2pp 16312 190 24X Fiche 50-313,82/11/30,8212060333
- 8212070284 Forwards summary of analysis of pressurizer safety & relief valve discharge piping, as required by NUREO-0737. Item II D i Piping stresses & support loads do not meet code, however, piping & valves will remain operable MAREHALL, JR Arkansas Power & Light Co 82/11/30 STCLZ, JF Operating Reactors Branch 4 CLARK, RA Operating Reactors Branch 3 4pp 16343 195 24X Fiche 50-313, 82/11/30, 8212070284
- 8212210013 Forwards SER on NUREG-0737. Item II A 2 1. "Upgraded Reactor Operator & Senior Reactor Operator Training" & Item II B 4. "Training for Mitigating Core Damage " Items resolved STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 82/12/01 CAVANAUGH, W Arkansas Power & Light Co Spp 16543 221 24X Fiche 50-313,82/12/01.8212210013
- 8208190263 Generic Ltr 82-32 to all PWR licensees re-potential steam 208190263 Generic Ltr B2-32 to all PMR licensees re potent generator-related generic requirements forwards Science Applications. Inc draft rept re subj requirements Comments requested within 30 days of ltr Svc list encl EISENHUT.D 0 Division of Licensing 82/12/09 Conso. Edison Co of New York. Inc 27pp 16627 247 24X Fiche 50-000.82/12/09,8208190263
- B212170215 Forwards proprietary & nonproprietary slides, "Fuel Shoulder Cap Mod," used at 821006 meeting re fuel shoulder gap problem Affidavit from C-E encl Blides withheld tref (00FR2 790) MARSHALL, J R Arkaneas Power & Light Co 82/12/10 CLARK, R A Operating Reactors Branch 3 5pp 16456 028 24X Fiche 50-368, 82/12/10, 8212170215
- 8212210039 Forwards response to 821119 request for info & clarification of 13 remaining open items re inservice test program MARBHALL.JR Arkansas Power & Light Co 82/12/10 CLARK,R A Operating Reactors Branch 3 4pp 16490 220 24X Fiche 50-368.82/12/10,8212210039
- 8212270421 Forwards order for mod of licenses, requiring installation of imadequate core cooling instrumentation sys conforming w/NUREO-0737, Item II F 2
 EIBENHUT, D 0 Division of Licensing 82/12/10 CAVANAUGH, H
 Arkansas Power & Light Co 2pp 16572,330 24X
 Fiche 50-313,82/12/10,8212270421
- ---B212270427 Order for mod of licenses requiring installation of inadequate core cooling instrmentation sys conforming w/ NUREG-0737. Item II F 2 Checklist for review of sys encl EISENHUT.D 0 Division of Licensing B2/12/10 Arkansas Light Co 11pp 16572 332 24% Fiche 50-313.82/12/10. Arkansas Power
- 8212270022 Responds to 821130 ltr requesting extension of response date re App I submittal to 830228 Delay acceptable CLARK.R A Operating Reactors Branch 3 BTDLZ.J F Operating Reactors Branch 4 82/12/14 CAVANAUGH H Arkansae Pawer & Light Co 2pp 16607.181 24X Fiche 50-313.82/12/14.8212290022
- E212280457 Informs of procurement of seismic instrumentation to augment & replace triaxial time-history accelerographs Changes to Yech Specs re new equipment will be submitted & will obviate request for deletion of monthly channel check requirement MARSHALLJR Arkenses Power & Light Co 82/12/20 CLARK.R A Operating Reactors Branch 3 2pp 16556 009 24X Fiche 50-368.82/12/20,8212280459
- Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at SWR Plants," Svc list encl.

 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp. 16462 163, 24X Fiche. 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" 8vc list
 - encl. COBS.L. I. Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372.142. 24X Fiche: 50-000,82/11/05.8208170245
- 82:2210245 Forwards IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No noncompliance noted.

 SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 82/11/05 CAVANAUOH,W Arkansas Power & Light Co 1

- --8212210250 IE Insp Repts 50-313/82-21 & 50-368/82-18 on 820802-06 No nancompliance noted Major areas inspected licensee action on previous insp findings, procedures review qualification & exposure control #APPSSURE CONTROL

 BAER.R. HILBORN.L. HOLLEY.H Division of Resident, Reactor

 Project & Engineering Programs 82/10/28 29pp 16483 317

 Fiche 50-313,82/11/05.8212210245
- B212140481 Forwards add1 info re IE Bulletin B2-02, clarifying B20929 commitments Results of mail review to determine number of leaks on bolted clasures listed MARSHALL, JR Arkansas Power & Light Co 82/11/08 COLLINS, J T Region 4, Office of Director 5pp 16403 355 24% Fiche 50-313, 82/11/08, 8212140481
- 8212140334 Responds to IE Bulletin 82-01, Revision 1, Suppl 1. "Alterations of Radiographs of Wolds in Piping
 Subassemblies " Listing of specific welds & action taken
 encl Actions indicate resolution of discrepancies
 MARSHALL.J R Arkansat Power & Light Co 82/11/11 COL
 Region 4. Office of Director 4pp 16401 284 24X
 Fichs 50-368.82/11/11/8212140334 COLLINS. J T
- 8212030184 Forwards IE Insp Rept 50-348/82-32 on 821025-29 No noncompliance noted SEIDLE,W C Division of Resident, Reactor Project & Engineering Programs 82/11/12 CAVANAUOH,W Arkansas Power & Light Co 2pp 16303 214 24% Fiche 50-368.82/11/12,8212030184
- --8212030192 IE Insp Rept 50-948/82-32 on 821025-29 No noncompliance noted Major areas inspected pipe hangers following licensee rept of numerous syc water sys deficiencies TUM-INBON.D P Region 4. Office of Director CUMMINS.J E . JOHNSON.W D Division of Resident, Reactor Project & Engineering Programs 82/11/05 4pp 16303 216 24X Fiche 50-948.82/11/12, 8212030184
- 8208190251 IE info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000,82/11/18.8208190251
- 8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 1641
- 8208190257 IE Info Notice 82-47, "Trensportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enci CO88-L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 820B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 80-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/0 Consolidated Edison Co of New York, Inc. 110pp 16462-064 (Fiche 50-000,82/12/03,820819026)
- 820B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! DEYGUNQ.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127gp 16628 191 24X Fiche 50-000,82/12/16.8208190267
- 8208190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl
 JORDAN E L Division of Engineering & Quality Assurance 82/1
 Consolidated Edison Co of New York, Inc 108pp 16628 273
 Fiche 30-000, 82/12/20, 8208170268
- 8212290192 Ack receipt of 821105 ltr informing NRC of steps taken to correct deviation noted in 1E Insp Repts 50-313/82-19 & 50-368/82-16 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/12/23, CAVANAUOH, W Arkanses Fower & Light Co ip 16578 132 24X Fiche 50-313,82/12/23.8212290192
- --B212290198 Responds to NRC B21007 ltr re deviation noted in IE Insp.
 Repts 50-313/82-19 & 50-368/82-16 Corrective actions environ
 qualification info submitted in B20729 & OBIG ltrs
 Commitment tracking sys implemented
 MARSHALL, J. R. Arkansas Power & Light Co. B2/11/05 SEIDLE, W.C.
 Division of Resident, Reactor Project & Engineering Programs 2pp
 16578 133 24X Fiche 50-313.82/12/23.8212290192

- R Periodic operating reports & related correspondence
- 8212290168 Forwards suppl to "Annual Environ Monitoring Rept.1981" MARSHALL.JR Arkansas Power & Light Co 82/11/12 COLLINS.JT Region 4. Office of Director 1p 16582 181 24X Fiche 50-313,82/11/12.821229018
- --82[2290171 Suppl to "Annual Environ Monitoring Rept. 1981"

 * Ankansas Power & Light Co 82/11/12 15pp 16582 182 24X
 fiche 50-313,82/11/12,8212290468
- 8212290234 Forwards monthly operating rept for Oct 1982 MARSHALL, J R Arkansas Power & Light Co 82/11/15 HALLER, N M Management Information Branch 1p 16582 173 24X Fiche 50-368, 82/11/15,8212290234
- --9212290236 Monthly operating rept for Oct 1982 BRAMLETT.L S Artansas Power & Light Co 52/11/15 App 16582 174 24% Fiche 50-366, 82/11/15,8212290234
- S Reportable occurrences, LERs & related correspondence
- 8P12030066 Forwards LER 82-033/03L-0 MARSHALL J R Arkansas Power & Light Co 82/11/18 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs | Ip 16307 IS7 24X Fichs 50-368, 82/11/18, 82/2030066
- ~~8212030075 LER 82~033/03L-0 on 821018. while in Mode 6, safety injection check valve 281-130 stuct in open position when stroked by hand Caused by protruding valve disc stud Portion of protruding disc stud filed off RDDSERS.P Ariannas Power & Light Co 82/11/18 Region 4. Office of Director 2pp 16307 158 24X Fiche 50-368,82/11/18, pp 16307014.
- B212100254 PND-IV-82-044 on B21203 normal phone communication lost due to local flooding caused by heavy rains & severe weather Bactup radio communications feasible from elevated ground northwest of Little Rock Addl heavy rain possible SEIDLE.N C GAGLIARDO.J E Region 4, Office of Director 82/12/03 2pp 16376 127 24X Fiche 50-313,82/12/03,8212100254
- 8212210027 Forwards LER 82-038/03L-0 MARSHALL.J R Ariensas Power & Light Co 82/12/06 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 16483 361 24X Fiche 30-368, 82/12/06, 8212210027
- --8212210028 LER 82-039/03L-0 on 821111, emergency feedwater control valve 2CV-1076-2 found not wired per installation frawings Caused by installation oversight Circuitry for valve operators corrected to conform to electrical schematic ROBERS, P. Arkansas Power & Light Co. 82/12/07 Region 4, Office of Director ip 16485-362 24X Fiche 50-368,82/12/06, 82/2210027
- 8212210117 Forwards LER 82-034/03L-0
 MARSHALL, J R Arksnass Power & Light Co B2/12/07 SEIDLE, H C
 Division of Resident, Reactor Project & Engineering Programs Ip
 16485 125 24X Fiche 50-068, 82/12/07,8212210117
- --B212210120 LER B2-034/03L-0 on B21107, improper level indication observed on C safety injection tank Caused by water in safety injection tank saturated w/nitrogen, causing gas bubbles to develop in transmitter ref legs Legs vented MDEOGENBERG, D Arkansas Power & Light Co B2/12/07. Ragion 4, Office of Director 2pp 16485-126 24X Fiche 50-368,82/12/07,8212210117.
- BR12210193 Forwards LER 82-037/03L-0 MARSHALL J R Arkansas Power & Light Co 82/12/07 BEIDLE, W C Division of Resident. Reactor Project & Engineering Programs Ip 16484 354 24X Fishe 50-368.82/12/07.8212210193
- --B212210198 LER 82-037/03L-0 on B21110, during low power testing in Mode 2, breaker to operating charging pump 2F36A tripped Caused unknown Resistance checks of all motor leads & windings revealed no abnormalities

 MOEGGENBERG.D Arkanas Power & Light Co 82/12/07 Region 4, Dffice of Director Ip. 16484 335 24X Fiche 50-368, 82/12/07, 8212210193
- 8P12210257 Forwards LER 82-036/03L-0 MARSHALL, J R Artansas Power & Light Co 82/12/07 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs ip 16483, 299 24X Fiche 50-268, 82/12/07, 82/2210250

- --B212210260 LER B2-036/03L-0 on B2110B.during Mode 3.emergency feedwafer pump 2P-7A isolation valve 2CV-1062-2 failed to close Caused by changes in operating characteristics due to contact not being wired MOEGGEMBERG, D. Arkaness Power & Light Co. B2/12/07 Region 4. Office of Director 1p 14483 300 24X Fiche 50-368,82/12/07, S212210257
- 8212280072 LER 82-042/017-0 on 821210.power ascension testing revealed that values of shape annealing matrix for all four CPC channels improperly loaded into CPCs Caused not stated Correct matrix loaded within i h LEVINE.J M Arkansas Power & Light Co 82/12/10 CGLLINS.J Region 4, Office of Director 2pp 16565 074 24X Fiche 50-368,82/12/10,8212280072
- B21221020B PNO-IV-82-04B on 821211, unit tripped from 97% power due to dropped control element assembly (CEA) Caused by failure of upper gripper coil for part length CEA 26 JOHNSON, W D. CALLAN, L. J. Region 4, Office of Director 82/12/13 1p 16405 031 24% Fiche 50-368.82/12/13,8212210208
- 8212270189 Forwards LER 62-039/03L-0 MARSHALL, J R Arkansas Power & Light Co 62/12/13 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs Ip 16337 299 24X Fiche 50-368, 62/12/13, 6212270189
- --B212270194 LER 82-039/03L-0 on B21112.degraded fire barrier exists fire to unsealed piping penetrations Caused by personnel error arising from insufficient instruction on applicable design change documentation Penetrations sealed WADE.P B Arkansas Power & Light Co 82/12/13 Region 4. Office of Director 2pp 16539 300 24X Fiche 50-368,82/12/13, 8212270189
- 8212270212 Forwards LER 82-041/03L-0 MARSHALL, J R Arkansas Power & Light Co 82/12/13 BEIDLC, N C Bivision of Resident, Reactor Project & Engineering Programs | p 16578 196 24X Fiche 50-366, 82/12/13, 8212270212
- --8212290223 LER 82-041/03L-0 on 821124, isolation valve 2MS-0340 faller to close & steam leak discovered in emergency feedwater pump steam supply pressure transmitter 2PT-0340 Caused by stripped threads due to overborquing of tubing connector RODERS, P. Arkansas Power & Light Co. 82/12/13 Region 4, Office of Director 2pp. 16978 197. 24X Fiche 50-368,82/12/13, 821290212
- 8P12280142 Forwards revised LER 82-034/03L-1 MARSHALL.J R Arkansas Power & Light Co 82/12/15 SEIDLE.H C Division of Resident, Reactor Project & Engineering Programs to 1555 186 24X Fiche 50-36B, 82/12/15, 8212280142
- --9212280146 Revised LER 82-036/03L-1 on 821108 during Mode 3 emergency feedwater pump 2P-7A isolation valve 2CV-1026-2 failed to close following surveillance testing Caused by change in operating characteristics due to miswired contact MDEOGENBERG.D Arkansas Power & Light Co 82/12/07 Region 4, Office of Director 2pp 16563 187 24% Fiche 50-368,82/12/15, 8212280142
- BE12300052 Forwards LER B2-044/03L-0 MARSHALL.J R Arkansas Power & Light Co B2/12/21 SEIDLE.W C Division of Resident, Reactor Project & Engineering Programs I; 16578 191 24% Fiche 50-368, B2/12/21, B212300052
- ---8212300059 LER 82-044/03L-0 on 821206, control power fuse opened on charging pump 2P-036-C during pump startup while charging pump A (inoperable due to maint) Possibly caused by fuse fatigue or dragging contactor Fuse/motor contacts replaced WADE, P B Arkansas Power & Light Co 82/12/21 Region 4. Office of Director 1p 16598 192 24X Fiche 50-368, 82/12/21. 8212300052
- 8212300088 Forwards LER 82-042/01T-0 MARSHALL, J.R. Arkansas Power & Light Co 82/12/21 SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs Ip 16597 024 24% Fiche 50-368, 82/12/21, 8212300088
- --8212300090 LER 82-042/01T-0 on 821210, shape annealing matrix values for core protection calculators found improperly loaded Caused by personnel error due to inadequate labeling of matrix elements listed by SAM analysis code ROSERS, P. Arkansas Power & Light Co 82/12/21 Region 4, Office of Director 2pp 16599 030 24X Fiche 50-34B,82/12/21,8212300088
- 8212300057 Forwards LER 82-045/03L-0 MARSHALL, J R. Arkansas Power & Light Co 82/12/23 BEIDLE, W C Division of Resident. Reactor Project & Engineering Programs 1p 16598 188 24X Fichs 50-368,82/12/23,8212300057

- --B212300062 LER 82-045/03L-0 on 821129, slow decrease in pressurizer pressure noted w/both proportional & one backup heater banks energized Caused by three open fuses Fuses replaced MDEGGENBERG.D Arkansas Power & Light Co 82/12/23 Region 4 Office of Director 1p 16598 189 24X Fiche 50-368,82/12/23,8212300037
- 8212300182 PNO-IV-82-052 administrative measures taken to preclude potential problem w/single plant protection sys.including caution-tagged cabinets, shift supervisor briefing & operator review of San Onofre incident
 JAUDON, J.P., CALLAN, L.J. Region 4. Office of Director 82/12/2;

 p 16597 329 24X Fiche 50-346,82/12/27,8212300182
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8212130069 Forwards info on emergency offsite facilities (EDF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permenant primary & backup EDF completed TUCKER.H B Duke Power Co 82/12/03 DENTON.H R Dffice of Nuclear Reactor Regulation. Director 2pp 16390 186 24% Fiche 30-000.82/12/03.8212130069
- 8212070044 Reviews util 820417 & 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test STGLZ, J F Operating Reactors Branch 4 82/12/07 TUCKER, H B Duke Power Co 2pp 16384 244 24X Fiche 50-000, 82/12/07, 8212090044
- BP12230057 Releases public version of emergency plan implementing pracedures
 FELTON.J M Division of Rules and Records 82/12/14 Document Management Branch ip 16545 246 24X Fiche 50-369,82/12/14, 8212230057
- --B212230076 Forwards public version of emergency plan implementing procedures, including Procedure #P/0/0/1009/05 re first response evaluation of reactor coolent leak inside containment TUCKER.H D Duke Power Co 82/12/02 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM.E O Licensing Branch 4 2pp 16545 247 24X Fiche 50-369, 82/12/14, 8212230067
- --B212230083 Public version of emergency plan implementing procedures, including Procedure HP/O/B/1009/05 re first response evaluation of reactor conlant leak inside containment MCGREEN B . LEGNARD.J R Duke Power Co 82/11/23 84pp 14545 249 24X Fiche 50-369,82/12/14,8212230067
- 8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures FELTON.J M Division of Rules and Records 82/12/15 Document Management Branch Ip 16542 026 24X Fiche 50-000, 82/12/15, 8212230093
- --B212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures TVCKER.H B Duke Power Co B2/12/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16542 027 24X Fiche 50-000, 82/12/15, 8212230093
- --8212230124 Public version of Revision 7 to crisis mgt plan One oversize pemphlet encl Aperture cand available in PDR VAUGHN.R E Duke Power Co 82/11/29 9pp 16942 029 RAX Fiche 50-000, 82/12/18, 8212230093
- --8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 2 re crisis news group plan & 5 3 11 re McGuire crisis phone directory VAUGHIR E Duke Power Co 82/11/29 280pp 16542 038 24X Fiche 50-000, 82/12/15, 8212230093
- P Operating license stage documents & correspondence
- B212030002 Forwards "Reactor Containment Didg Integrated Leak Rate Test. Buppl 2 " TUCKER, H B Duke Fower Co 82/11/18 DENTON, H R Office of Nuclear Reactor Regulation, Director. ADENBAM, E G Licensing Branch 4 Ip 16304 216 24X Fiche 50-369, 82/11/16, 8212030002
- --8212030003 "Reactor Containment Bldg Integrated Leak Rate Test.Suppl 2"
 - * Duke Power Co 82/11/18 5pp 16304.217. 24X Fiche 50-369,82/11/18.8212030002

- 8212040244 Application to amend License NPF-9, revising App A Tech Specs to reduce measurement uncertainty for total RCS flow Tech Spec, justification & safety analysis withheld (ref iOCFR2 790)
 TUCKER, H B Duke Power Co 82/11/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 3pp 16312 159 24% Fiche 50-369,82/11/23,8212060244
- --8212060245 Requests withholding of proprietary matl re RCS total flowrate vs R1 & R2 four loops in operation (STS), per enc1 Affidavit AM-76-60 MIESEMANN, R A Westinghouse Electric Corp 82/11/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 Spp 16312 162 24X Fiche 50-369,82/11/23,8212040244
- 8212010286 Submits list of outstanding items requiring responses by 821217 to complete review of DL application ADENSAME 0 Licensing Branch 4 82/11/24 TUCKER, H B Duke Power Co. 2pp 16271 254 24X Fichs 50-369,82/11/24,8212010286
- 8212070341 Forwards responses to NUREO-0737. Item II B 3. "Post-Accident Sampling Sys " H/14 oversize drawings Aperture cards are available in PDR TUCKER. H B Duke Power Co. 82/12/01 DENTON, H R Office of Nuclear Reactor Regulation. Director 32pp 16340 252 24X Fiche 50-269.82/12/01.8212070341
- --8212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys" DEAK.A M : MCCONNELL-T. Duke Power Co 82/05/17 18pp 16340 305 24% Fiche 50-269, 82/12/01.8212070041
- 8212140390 Forwards fee for Class III amend re requests for relief from hydrostatic testing requirements on feedwater sys to steem generators & safety injection sys TUCKER.H B Duke Fowar Co. 82/12/03 DENTON.H R Deffice of Nuclear Reactor Regulation. Director ADENSAM, E. 0 Licensing Branch 4 2pp 16401 032 24X Fiche 50-369,82/12/03,8212140390
- 8212140103 Generic Ltr 82-28 to all licensees of operating Westinghouse & C-E PWRs (except Arkansas Nuclear One, Unit 2 & San Gnofre 2 & 3) re inadequate core cooling instrumentation sys Svc list entl EISENMUT.D 0 Division of Licensing 82/12/10 Yankee Atomic Electric Co 27pp 16690 035 24X Fiche 50-000.82/12/10.82/12/40103
- 821215017B Notification of 821216 meeting w/util in Bethesda.MD to discuss independent design verification program BIRKEL.R A Licensing Branch 4 82/12/10 ADENBAN.E G Licensing Branch 4 3pp 16437 350 24X Fiche 50-369.82/12/10.8212150178
- 8212160249 Forwards responses to questions re standby shutdown sys per NRC 821203 request TUCKER. H B Duke Power Co 82/12/14 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch 4 16pp 16446 100 24X Fiche 50-369.82/12/14.8212160249
- 8212170290 Forwards justification for addl 30-day operation of steam generators at 75% power, based on enci results of recent eddy current tests Mod scheduled for mid-Jan 1983 Concurrence requested TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Dffice of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 (1pp 16456.166 24% Fiche 50-369.82/12/15,8212170290
- BRI2210419 Forwards Amend 70 to application for DL.consisting of Revision 44 to FSAR TUCKER.H B Date Power Co 82/12/15 DENTON, H R Dffice of Nuclear Reactor Regulation, Director ADENBAM, E O Licensing Branch 4 2pp 16490 056 24X Fiche 50-370, 82/12/15, 8212210419
- 8212270232 Requests exemption from 10CFR50,71(e) requirements to FBAR update initiated within 24 months of 800722 or OL issuence, whichever is later Updated FBAR will be submitted 12 months after issuance of OL for Unit 2
 TUCKER.H 8 Dute Power Co. 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licesing Branch 4 ip. 16378 079 24% Fiche 50-369,82/12/22,8212270232
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision I. "Stress Cracking in Thick-Wall, Large-Diamator, Stainless Steel, Recirculation Sys Piping at BWR Plants." Swc list encl DEYOUNO, R.C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462-163 24X Fiche 50-000, 82/10/28, 8208190240

- 8212070373 Forwards IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No nancompliance moted BANCE.H C Division of Project & Resident Programs 82/11/04 TUCKER H B Dute Power Co 2pp 16365 057 24X Fiche 50-369. 82/11/04. 8212090373
- --8212090380 IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted Major areas inspected maint. surveillance, hot functional testing, sys operational safety verification, plant trips.LERs & NUREO-0737 items NOPKINS.P., BRYANT.J. C Division of Project & Resident Programs 82/11/04 9pp 16365 059 24X Fichs 50-369.82/11/04.8212090373
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 CDBh.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Commoliated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000.82/11/05.8208190245
- 8212090250 Responds to IE Bulletin 82-01, Revision 1, Suppl 1 Total radiographic film review revealed no film alterations & required penetrameter sensitivities were clear TUCKER. H B Duke Power Co 82/11/10 0'REILLY.J P Region 2, Office of Director 1p 16361 352 24% Fiche 50-369, 82/11/10.
- 8212090401 Ack receipt of IE Insp Repts 50-369/82-36 & 50-370/82-30, No proprietary info TUCKER, H 8 Date Power Co 82/11/12 O'REILLY, J P Region 2, Defice of Director 1p 16364 261 24X Fiche 50-369,82/11/12, parapol/401
- B20B190251 IE Info Notice B2-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Pavision of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche. 50-000. 82/11/18. 8208190251
- 8212090187 Act receipt of 821105 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/82-35 DANCE. H C Division of Project & Resident Programs 62/11/19 TUCKER. H B Duke Power Co ip 16361 285 24X Fiche 50-369.82/11/19.8212090187
- --8212070192 Responds to NRC 821007 ltr re violations noted in 1E Insp Rept 50-369/82-35 Corrective actions add1 training given to staff devaloping exposure folders & random file auditing initiated TUCKER: H 8 Duke Power Co 82/11/05 O'REILLY, J P Region 2, Office of Director 2pp 16361 286 24X Fiche 50-369, 82/11/19, 8212090187
- --8212090197 Forwards IE Insp Rept 50-369/82-35 on 820913-17 & notice of violation
 DANCE.H C Division of Project & Resident Programs 82/10/07
 TUCKER.H B Dute Power Co. 2pp 16361 288 24X
 Fiche 50-369, 82/11/19, 8212090187
- --8212090198 Notice of violation from insp on 820913-17 * Division of Project & Resident Programs 82/10/07 ip 16361:290 24X Fiche 50-369,82/11/19,8212090187
- --8212070204 IE Insp Rept 50-349/82-35 on 820913-17 Nancompliance noted wrong exposure credited to individual when record of individual exposure not available ALBRIGHT,R H . BARR.K P Division of Engineering & Technical Programs 82/10/01 4pp 16361 291 24X Fiche 50-369.82/11/19, 8212090187
- B212090339 Ack receipt of IE Insp Repts 50-349/82-34 & 50-370/82-29 No proprietary info TUCKER. H B Duke Power Co 82/11/19 O'REILLY, J P Region 2, Office of Director 1p 16365 138 24X Fiche 50-369, 82/11/19, B212090339
- 8208190255 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocks." Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 30-000,82/11/26,8208190256
- 8208190297 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fibrile Radioactive Hatl " Svc list encl COBS.L I Division of Fuel Facilities, Materials & Safeguards 92/11/30 consolidated Edison Co of New York, Inc 35/pp 16/387 028 24X Fichs 50-000,82/11/30,8208190257

- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNO,R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- BPOBI90261 IE Info Notice 82-48, "Failures of Agastat CR 0098 Relay Sockets" Byc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Oas Monitoring " Evc list encl DEYOUNG: C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list encl JORDÁN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- R Periodic operating reports & related correspondence
- B212210060 Forwards monthly operating rept for Nov 1782 TUCKER.H B Duke Power Co 82/12/15 Director's Office, Difice of Inspection and Enforcement 1p 16492 269 24X Fiche 50-369, 82/12/15,8212210060
- --8212210065 Monthly operating rept for Nov 1982 REAVIS.J A Duke Power Co 92/12/15 App 16492 264 24X Fiche 50-369,82/12/15.8212210060
- S Reportable occurrences. LERs & related correspondence
- 8212140425 Forwards LER 82-074/03L-0 Detailed event analysis encl TUCKER,H B Duke Pawer Co 82/11/30 O'REILLY,J P Region 2, Office of Director 4pp 14404 181 24X Fiche 50-369,82/11/30, 8212140425
- --8212140434 LER 62-074/03L-O on 621014, 19, 25 & 28, various door seals failed on both upper & lower personnel air locks Caused by door out of alignment, seals inflated while door open & surface of seal peeled off Seals replaced NARDOCLP B Duke Power Co 82/11/30 Region 2, Office of Director 1p 16404 185 24X Fiche 50-369, 82/11/30, 8212140425
- 8212140171 Forwards LER 82-076/03L-0 TUCKER: H B Duke Power Co 82/12/03 D'REILLY. J P Region 2: Office of Director 1p 16409 355 24X Fiche 50-369,82/12/03: 0212140171
- --8212140176 LER 82-076/03L-O on 821104, while in Mode 1, power supply to main fire pump C lost for approx 2-h & 25 minutes making main fire pumps 2 & 3 inoperable Caused by power loss from broken insulator damaged by lightning Insulator replaced.

 NARDDCLP B Duke Power Co. 82/12/03 Region 2, Office of Director ip 16409 356. 24% Fiche 50-369,82/12/03,8212140178
- 9212200005 Forwards LER 92-077/03L-0 TUCKER.H B Duke Power Co 82/12/03 D'REILLY, J.P. Region 2: Office of Director Ip 16474 040 24X Fiche 50-349, 82/12/03. 8212200005
- --8212200012 LER 82-077/03L-0 on 821105, eight procedure change cards of each reactor protection sys channel omitted from overlap testing Caused by inadequate procedures Omitted cards calibr & procedurel changes approved NARDOCIP B Duke Power Co 82/12/03 Region 2, Office of Director ip 16474 041 24% Fiche 50-369, 82/12/03, 8212200005
- 8212210145 Forwards LER 82-078/03L-0 TUCKER.H B Duke Power Co 82/12/08 D'REILLY, J.P. Region 2, Office of Director ip 16485 167 24X Fiche 50-369,82/12/08, 8212210145
- --8212210154 LER 82-078/03L-O on 821108, during draining of RCS, both cantrifugal charging pumps inoperable Caused by confusing statement in draining procedure allowing both breakers to be racked out & tagged Procedure revised & personnel counseled NARDOCI.P B Duke Power Co 82/12/08 Region 2, Office of Director ip 16485 168 24X Fiche 50-369,82/12/08,8212210145
- 8212280380 Forwards LER 82-079/03L-0 TUCKER, H B Duke Power Co 82/12/15 O'REILLY, J P Region 2: Defice of Director ip 16560 056 24X Fiche 50-369, 82/12/15, 8212280380

- --8212283394 LER 82-079/03L-0 on 821118, centrifugal charging pump 1A declared inoperable when excessive leakage from pump seals noted Caused by pump shaft slinging water out of seal leakage basin Drain line cleared & pump returned to svc NARDOCI.P 8 Duke Power Co 82/12/15 Region 2, Office of Director Ip 16560 057 24X Fiche 50-367,82/12/15,8212280380
- 8212300093 Forwards LER 82-080/03L-0 TUCKER.H B Duke Power Co 82/12/22 O'REILLY, J P Region 2, Office of Director 1p 16599 034 24X Fiche 50-369,82/12/22, 8212300093
- --B212300094 LER 82-080/03L-0 on 821122, discrepancies discovered in intermediate range internal picoampere source & LOG current amplifier callibr procedures Caused by improper procedure options Channels recallibr & procedures revised NARDOCI.P B Duke Power Co 82/12/22 Region 2, Office of Director ip 16597 035 24X Fichs 50-367:82/12/22,08212300093
- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8212010286 Submits list of outstanding items requiring responses by B21217 to complete review of OL application
 ADENSAM.E G Licensing Branch 4 82/11/24 TUCKER.H B Duke Power Co 2pp 16271 254 24X Fiche 50-365.82/11/24.8212010286
- G212070341 Forwards responses to NUREG-0737. Item II B 3, "Post-Accident Bampling Sys " W/14 oversize drawings Aperture cards are available in PDR TUCKER. H B Dute Power Co B2/12/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 16340 252 24X Fithe 50-267. B2/12/01. B212070341
- ~-B212070353 "Operating Procedure for Operation of Post-Accident Liquid Sample Sys " DEAK.A M. MCCONNELL.T Duke Power Co 82/05/17 18pp 18340 305 24X Fiche 50~269, 82/12/01,8212070341
- B212140390 Forwards fee for Class III amend re requests for relief from hydrostatic testing requirements on feedwater sys to steam generators & safety injection sys TUCKER.H B Duke Power Co B2/12/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBAM,E 0 Licensing Branch 4 2pp 16401 032 24% Fiche 50-369,82/12/03,8212140390
- B212150178 Notification of B21216 meeting w/util in Bethesda, MD to discuss independent design verification program DIRKEL, R A Licensing Branch 4 B2/12/10 ADENSAM, E.G. Licensing Branch 4 3pp 16437 350 24X Fiche 50-367, B2/12/10, B212150178
- B212160249 Forwards responses to questions re standby shutdown sys per NRC 821203 request TUCKER: H B Duke Fouer Co B2/12/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 16pp 16446 100 24X Fiche 50-369,82/12/14.8212160249
- B212210419 Forwards Amend 70 to application for OL.consisting of Revision 44 to FBAR TUCKER.H B Duke Power Co 82/12/15 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E 0 Licensing Branch 4 2pp 16490 056 24X Fiche 50~370,82/12/15,8212210419
- 8212290232 Requests examption from 10CFR50 71(e) requirements re FBAR update initiated within 24 months of 800722 or DL issuance, whichever is later Updated FSAR will be submitted 12 months after issuance of DL for Unit 2
 TUCKER, H B Duke Power Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licansing Branch 4 1p 16578 079 24X Fiche 50-367, 82/12/22, 8212240232
- F Security, medical, emergency & fire protection plans
- 8212130069 Forwards info on emergency offsite facilities (EOF).per R Birkel 821203 request & Generic Ltr B1-10 Const of permanent primary & backup EOF completed TUCKER.H B Duke Power Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16370 186 24X Fiche 50-000, 82/12/03, 8212130069
- 8212090044 Reviews util 820419 & 0727 ltrs re security personnel requalification requirements Annual supervisor observation considered sufficient requalification test STOL2.J F Operating Reactors Branch 4. 82/12/07 TUCKER.H.B Duke Power Co 2pp 16384 244 24X Fiche 50-000,82/12/07,82120700044

- 8212230067 Releases public version of emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 62/12/14 Document Management Branch 1p 16545 246 24X Fiche 50-369,82/12/14, 8212230067
- --8212230076 Forwards public version of emergency plan implementing procedures, including Procedure HP/D/B/1009/05 re first response evaluation of reactor coolant leak inside containment TUCKER.H B Duke Power Co 82/12/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBAM,E 0 Licensing Branch 4 2pp 16545 247 24X Fiche 50-369,82/12/14,8212230067
- --8212230083 Public version of emergency plan implementing procedures, including Procedure tP/O/B/1009/05 re first response evaluation of reactor coolant leak inside containment MCCREF, M. B. LEONARD, J. R. Duke Power Co. 82/11/23 84pp 16545 249 24% Fiche 50-369, 82/12/14, 8212230067
- 8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures FELTON.JM Division of Rules and Records 82/12/15 Document Management Branch ip 16542 026 24K Fiche 50-000,82/12/15, 301220093
- --8212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures
 TUCKER.H B. Duke Power Co. 82/12/02 DENTON.H R. Office of
 Nuclear Reactor Regulation, Director 2pp 16542 027 24X
 Fiche 50-000.82/12/15.8212230093
- --B212230124 Public version of Revision 7 to crisis mgt plan One oversise pamphiet encl Aperture card available in PDR VAUGHN.R E Duke Power Co 82/11/29 9pp 16542 027 24X Fiche 50-000.82/12/15.8212230093
- --8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 2 re crisis news group plan & 5 3 11 re McQuire crisis phone directory VAUGHIN R E Duke Power Co 82/11/29 280pp 16542 038 24X Fiche 50-000,82/12/15.8212230093
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8212210419 Forwards Amend 70 to application for OL, consisting of Revision 44 to FSAR
 TUCKER, H B Duke Power Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 16490 056 24X Fiche 50-370, 82/12/15, 8219210419
- --8212210423 Revision 44 to FBAR Work oversize drawing Aperture card is available in PDR
 Duke Power Co 82/12/15 65pp 16490 058 24X
 Fiche 50-370, 82/12/15. 8212210419
- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision i. "Stress Cracking in Thitk-Wall. Large-Diameter. Stainless Steel, Recirculation Gys Piping at BWR Plants "Svc list end!
 BEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inspection 16462 163 24X Fishe 50-000. 82/10/28. 8208190240
- 8212090373 Forwards IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted DANCE.N C Division of Project & Resident Programs 82/11/04 TUCKER.H B Duke Power Co 2pp 16365 057 24X Fiche 50-369. 82/11/04.8212090373
- --8212090390 IE Insp Repts 50-369/82-38 & 50-370/82-33 on 820918-1020 No noncompliance noted Major areas inspected maint, surveillance, hot functional testing, sys operational safety verification, plant trips, LERs & NUMEG-0737 items HOPKINS,P : BRYANT, J C Division of Project & Resident Programs 82/11/04 9pp 16365 059 24X Fiche 50-369, 82/11/04, 8212090373
- 820Bi90245 IE Info Notice 82-42, "Defects Observed in Penasonic Model BO2 Thermoluminescent Dosimbters " Svc list encl COBB.L I. Division of Fuel Facilities, Materials & Safeguards S2/11/05 Consolidated Edison Co of New York, Inc 110pp 16372.142 24X Fiche 50-000, 82/11/05, 820Bi90245
- B212090250 Responds to IE Bulletin 82-01, Ravision 1.8uppl 1 Total radiographic film review revealed no film alterations & required penetrameter sensitivities were clear TUCKER. H B Duke Power Co 82/11/10 O'REILLY, J P Region 2, Office of Director 19 16361 352 24X Ficher 50-369, 82/11/10, 8212090250

- B212070401 Ack receipt of IE Insp Repts 50-369/02-36 & 50-370/82-30 No proprietary info TUCKER-H B Duts Power Co B2/11/12 O'REILLY, J P Region 2, Office of Director ip 16364 261 24X Fiche 50-369, 82/11/12, H212070401
- 82)2070262 Forwards IE Insp Rept 50-370/B2-34 on 821101-04 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/11/17 TUCKER.H B Duke Power Co 2pp 16362 332 24X Fiche 50-370,82/11/17.8212090262
- --B212090271 IE Insp Rept 50-370/82-34 on 821101-04 No noncompliance noted Major areas inspected preoperational test procedure review preoperational test witnessing & preoperational test results review THOMAS.H., JAPE.F. Division of Engineering & Technical Programs 82/11/15 3pp 16362 334 24X Fiche 50-370,82/11/17,8212090262
- 8208190281 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Comsolidated Edison Co of New York, Inc 109ap 16411 199 24: Fiche 50-000.82/11/18.8208190251
- 8212090339 Ack receipt of IE Insp Repts 50-369/82-34 & 50-370/82-29 No proprietary info TUCKER,H B Dute Power Co 82/11/19 O'REILLY,J P Region 2, Office of Director ip 16365 (38 24X Fiche 50-369, 82/11/19, 8212090339
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocks " Svc Isst encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- B20B190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc Jist encl COBB.L I Division of Fuel Facclities, Materials & Bafeguards B2/11/30 Consolidated Edison Co of New York
- B208190289 IE Bullstin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list which DEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Gaison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svr list encl JORDAN, E L Division of Engineering & Guality Assurance 82/12/03 Cansolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- B208190268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list enc! JURDAN.E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24; Fiche 50-000, 82/12/20, 8208190268

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

1

- F Security, medical, emergenty & fire protection plans
- B212060041 Forwards Revision 13 to modified amended security plan Revision withheld (ref 10CFR73 21) DELOCORDEL C Commonwealth Edison Co 82/11/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16313 270. 24X Fiche 50-373, 82/11/29, 8212060041
- 8212090383 Forwards info re amargancy operations facilities per 821122 & 1202 requests Info previously submitted by telcon Request for written response unnacessary burden on licensee DELOEDROE.L. O Commonwealth Edison Co 82/12/03 EISENNUT. D O Division of Licensing 2pp 16365 051 24X Fiche 50-000,82/12/03,8212090383
- B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"

 FELTON.J M Division of Rules and Records 82/12/07, Document Management Branch ip 16417 062 24X Fiche 80-000,82/12/07, '2130017

- --8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Offsite Honitoring Locations (Maps) " Revised table of contents encl PAJONSKI, J Commonwealth Edison Ca 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417 063 24X Fichs 50-000, 82/12/07.8212130017
- --8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EQ-2, "Pre-Established Onsite & Offsite Monitoring Locations (Mags)"
 PAJONSKI, J E Communuealth Edison Co 82/11/29 4pp 16417 065 244 Fiche 50-000.82/12/07.8212130017
- 8212130093 Requests exemption from 10CFR50 44 requirements extending initial startup test program beyond 6 months following initial criticality per Tech Specs 3 6 6 2 & 3 10 5 Approval required by 821220 SCHROEDER.C W Commonwealth Edison Co 82/12/07 SCHHENCER.A Licensing Branch 2 6pp 16390 176 24X Fiche 50-373,82/12/07,8212130093
- 8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMM.T.R. Commonwealth Edison Co. 82/12/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000, 82/12/07, 8212140243
- 8212220175 Releases public version of revised generating station emergency plan implementing procedures FELTON.J M Division of Rules and Records 82/12/10 Document Hanagement Branch 1p 16529 029 24% Fiche 50-000.82/12/10.8212220175
- --8212220190 Forwards public version of revised generating station emergency plan implementing procedures including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJUNSKI.J E Commonwealth Edison Co 82/11/15 DENTON, H R Office of Muclear Reactor Regulation. Director 1p 16529 030 24X Fiche 50-000.82/12/10.8212220175
- --8212220202 Public version of revised generating station emergency plan implementing procedures including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI. A Commonwealth Edison Co 82/10/13 48pp 16529 031 24% Fiche 50-000, 82/12/10.8212220175
- B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPPLER. J 0 Region 3. Office of Director 82/12/16 Commonwealth Edison Co. 3pp 16503 391 24X Fiche 50-000,82/12/16,8212220306
- 8212300167 Releases public version of revised generating station emergency plan telephone directory FELTON-J M Division of Roles and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000,82/12/20, 8212300167
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory MORE, R DENTON, H R Diffice of Nuclear Reactor Regulation, Director ip 16612 216 24X Fiche 50-000, 82/12/20, 8212300167
- --B212300197 Public version of revised generating station emergency plan telephone directory GALLELD P Commonwealth Edison Co B2/11/05 60pp 16612 217 24% Fiche 50-000, B212120, B212300167
- H General correspondence
- 8212200099 Submits petition to revoke OL until main recirculation pumps & all other parts of RCS are capable of operating at full power & order investigation & open public hearing into causes of stuck discharge valve on recirculation pump A ODODL. E Citizens Against Nuclear Power 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16470 138 24X Fiche SO-373, 82/12/15, 8212200099
- B212280176 Notifies of change in mailing address for NRC licensing mat1 MRIGHT, O.N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D 0 Division of Licensing Ip 16356 135 24X Fiche 50-000, 82/12/20, 8212280176

- K. Utility Final Safaty Analysis Report (FSAR) & amends
- 8212210463 Forwards Amend 61 to FBAR, updating baseline record & incorporating as-built & as-tested configuration SCHARDERROW Commonwealth Edison Co 82/12/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 16486 276 24X Fighs 50-373, 82/12/13, 8210910463
- --8212210466 Amend 61 to F8AR

 * Commonwealth Edison Co 82/12/31 299pp 16486 279 24X
 Fiche 50-373,82/12/13,8212210463
- 8212280341 Forwards affidavit confirming distribution of FBAR.Amend 61 SCHROEDER.C W Commonwealth Edison Co 82/12/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 16560 092 24X Fiche 50-373.82/12/23.8212280341
- P Operating license stage documents & correspondence
- B2i1230046 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBUR, Big Rock Point Dresden i, Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREG-0763 & NUREG-0789 Svc list enc! W/o stated enc! ETSENHUT.D @ Division of Licensing 93/11/15 General Public Utilities 0PU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066
- G212080462 Forwards add1 mat1 tests received on 821119 from Region 3 supplementing mat1 addressed in "Independent HVAC Review Final Rept." Oct 1982 Data reviewed by welding & mat1 specialists Comments encl XEMPIAX.A J C F Braun & Co 82/11/24 SHELTON. # R Commonwealth Edison Co 3pp 16372 324 24X Fiche 50-373.82/11/24, B212080662
- --B212080664 Forwards add1 data obtained as part of mat1 sampling program
 re HVAC in addition to data provided on B21007
 NORELIUS.C E Region 3, Office of Director B2/11/19
 STIEBE.W L C F Braun & Co 11pp 16372 327 24X
 Ficha 50-373, 82/11/24, 8212080662
- --8212080668 Discusses hardness tests performed to determine whether matl samples which meet chemical requirements for A36 also meet tensile requirements Specimens meet specs SHACK.W J Argonne National Laboratory 82/08/06 LANKSBURY, R Region 3. Office of Director 2pp 16372 338 24X Fiche 50-373,82/11/24.8212080662
- --8212080670 Discusses hardness tests performed to determine whether matl samples met mechanical requirements of appropriate ASTM spec Nut meets hardness spec Calculated flow stress consistent w/proof load stress SHACK.W J Argonne National Laboratory 82/09/22 LANKEBURY, R Region 3, Office of Director 3pp 16372 340 24x Fiche 50-373,82/11/24,8212080662
- --8212080673 Discusses hardness tests performed on three bolts (1/2.3/8, 1/4-inches) & corresponding nuts to find if bolts conform to appropriate ABTM spec Results of test summarized Specimens meet required specs SMACK.W J Argonne National Laboratory 82/10/07 LANKSBURY, R Region 3. Office of Director 3pp 16372 343 24X Fiche 50-373,82/11/24,8212080662
- B212060381 Notification of 821201 meeting w/util.CF Braun & Govt Accountability Project in Bethesda.MD to discuss independent review of HVAC sys BOURITA.A Licensing Branch 2 82/11/26 SCHWENCER.A Licensing Branch 2 3pp 16323 324 24X Fiche 50-373,82/11/26.8212060381
- 82:12020398 Submits recommendations re proposed issuance of full power GL, based on review of CF Braun & Co 82:1027 rept & witness analysis of Zack Co 9A breakdown in area of HVAC sys Heaknesses in rept preclude issuance pending further review DEVINE.T. GARDE.8 P Institute for Policy Studies 82/11/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 20pp 16270 345 24X Fiche 50-373,82/11/30,8212020398
- G212100361 Authorizes operation of facility above 50% power Safety evaluation of licenses 821027 independent HVAC review final rept on Project 6356-N b FR notice encl Measures to correct discrepancies in rept requested EISENHUT, D Q Division of Licensing 82/12/03 REED, C Commonwealth Edison Co 5pp 16398 307 24X Fiche 50-373,82/12/03,821210034
- ~-B212100368 Bafety evaluation of independent HVAC review final rept on Project 6356-N HVAC review provides reasonable assurance that sys acceptable for power operation above 50%.
 * NRC No Detailed Affiliation Given 82/12/03, 19pp 16398 312 24X Fiche 50-373, 82/12/03, 8212100361

- --8212100372 Notice of authorization of operation above 50% pawer SCHWENCER.A Licensing Branch 2 62/12/03 4pp 16398 331 243 Fiche 50-373, 82/12/03.8212100361
- B212130151 Submits daily highlights rept for B21206 Restriction to 50% power removed as result of acceptable independent review findings
 BOURNIA. A Licensing Branch 2 82/12/06 DENTON, H R, CASE, D Q, CARTER, J Office of Nuclear Reactor Regulation, Director 1p 16410 316 24% Fichs 50-373, 82/12/06, 82/2130151
- 821214006B Forwards application for amend to License NPF-11.allowing plant operation w/one recirculation loop out of svc SCHROEDER.C W Commonwealth Edison Co 82/12/06 SCHWENCER.A Licensing Branch 2 2pp 1640B 316 24X Fiche 50-373,82/12/06.8212140068
- --8212140072 Application for amend to License NPF-11.allowing operation w/one rectrculation loop out of svc # Commonwealth Edison Co 82/12/06 3pp 16408 318 24X Fichs 50-373,82/12/06.8212140068
- 8212130093 Requests exemption from 10CFR50 44 requirements, extending initial startup test program beyond 6 months following initial criticality per Teth Specs 3 6 6 2 & 3 10 5 Approval required by 821220
 SCHROEDER, C W Commonwealth Edison Co 82/12/07 SCHWENCER, A Licensing Branch 2 App 16390 176 24% Fiche 50-373,82/12/07,8212130093
- G212140402 Responds to S21207 request to specify implementation data of mod for License Condition 1 C (17) Bince current outage allows for mod installation.820818 Tech Spec change request should be approved to be effective as of B21209 SCHROEDER.C W Commonwealth Edison Co 92/12/08 SCHWENCER.A Licensing Brench 2 2pp 16404 358 24X Fiche 50-373.82/12/08.6212140402
- 8P12170013 Forwards Amend 10 to License NPF-11, safety evaluation & notice of issuance & availability Amend changes Tech Specs as result of hardware mods to satisfy License Condition 2 C (17)
 EISENHUT, D G Division of Licensing 82/12/09 DELGEORGE, L D Commonwealth Edison Co 2pp 16480 304 24X Fiche 50-373,82/12/09,
- --B212170016 Amend 10 to License NPF-11.changing Tech Spec as result of hardware mods to satisfy License Condition 2 C (17) EISENHUT.D Q Division of Licensing 82/12/09 4pp 16480 306 24% Fiche 50-373 82/12/09, 8212170013
- --8212170030 Safety evaluation supporting Amend 10 to License NPF-11
 * Office of Nuclear Reactor Regulation Director 82/12/09
 13pp 16480 310 24X Fiche 50-373,82/12/09,8212170013
- --0212170034 Notice of issuance & availability of Amend 10 to License NPF-11 SCHWENCER,A Licensing Branch 2 02/12/09 4pp 16480 323 24X Fiche 50-373,82/12/09,8212170013
- 8212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations" SMARTI,E D Commonwealth Edison Co 82/12/14 HAASS,W P Quality Assurance Branch 1p 16518 007 24X Fiche 50-000,82/12/14,
- --8212220231 "QA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co GE-1-A R22 82/11/01 17pp 14518 007 24X Fiche 50~000.82/12/14.8212220212
- 8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment SWARTZ.E D Commitment Communication Co. 62/12/22 EISENHUT, D Q Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212340212
- 8212280298 Forwards info on 821201 meeting re Govt Accountability
 Project repts & discussions of corrective actions for
 FC Braun Observation GC-2-53, GA review & Unit 2 HVAC, per NRC
 G21203 request
 REED, C Commonwealth Edison Co 82/12/22 EISENHUT, D G Division
 of Licensing 34pp 16561 097 24X Fiche 30-373, 82/12/22,
 83129200298

- O Inspection reports, IE Bulletins & correspondence
- B20B190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick" Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping Mail-Large-Diameter, Staliness Scentification by Figing at BMR Plants " Stylist and EMR Plants " Stylist and EMR Plants" Stylist and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs 50-000,82/10/28,8208170240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolyminescent Dosimeters " Svc list GOBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/03 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 820Bi9025i IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/11 Consolidated Edison Co of New York, Inc 109pp 16411 199 Fiche 50-000.02/11/18.820819025i
- 8212030021 Forwards IE Insp Repts 50-373/82-49 & 50-374/82-15 on 821001-29 No noncompliance noted STREETER, J.F. Division of Project & Resident Programs 82/11/18 REED.C. Commonwealth Edison Co. 2pp 16304 316 24X Fiche 50-373,82/11/18.8212030021
- --B212030028 IE Insp Repts 50-373/82-49 & 50-374/82-15 on 821001-29 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification & monthly surveillance observations
 GULDEMOND. W., WILLIAMS. D., MADISON. A. Division of Project & Resident Programs 82/11/18 12pp 16304 318 24X
 Fiche 50-373,82/11/18,8212030021
- 8212140326 Forwards final SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 No response required KEPPLER.J O Region 3. Office of Director 82/11/23 REED, C Commonwealth Edison Co 3pp 16402 012 24X Fiche 50-373,82/11/23,8212140326
- --8212140329 SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 Deficiency noted in conducting tests w/o adequate procedures * Region 3, Office of Director 82/05/30 39pp 16402 015 24X Fiche 50-373,82/11/23,8212140326
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padjocks "Svc list encl
 DEYQUNO.R C Birector's Office. Office of Inspection and
 Enforcement 82/11/26 Consolidated Edison Co of New York. Inc
 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 82/81/90257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consulidated Edison Co of New York
- 8212170077 Forwards IE Insp Repts 50-373/82-53 & 50-374/82-21 on 821101-05 & 08 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/12/01 REED. Commonwealth Edison Co 2pp 16450,354 24X Fiche 50-373,82/12/01.8212170077
- --8212170079 IE Insp Repts 50-373/82-53 & 50-374/82-21 on 821101-05 & 08 No noncompliance noted Major areas inspected radiological environ protection, including program mgt, QC & implementation
 - 3190257 IE Bulletin 82-04. "Deficiencies in Primary Containment lectrical Penetration Assemblies " Svc list encl Director's Office Office of Inspection and offorcement 82/12/03 Consolidate Edison Co of New York, Inc 13pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208170261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay 200170201 It into notice dering. Failures of hypersol on 0070 heley Sockets "Syc list encl JORDAN:EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fichs 50-000, 82/12/03, 8208190261
- 8212140224 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-45 SPESSARD, RL Division of Project & Resident Programs 62/12/09 REED. C Commonwealth Edison Co 1p 16408 339 24X Fiche 50-373, 82/12/09, 8212140224

- --8212140231 Responds to NRC 821104 ltr re violations noted in IE Insp Repts 50-373/82-45 & 50-374/82-13 Corrective actions flow controller returned to panel & station procedures revised to include leakage compensation DELOEDROEL C Commonwealth Edison Co 82/12/02 KEPPLER J O Division of Project & Resident Programs 3pp 16408 340 24X Fiche 50-373,82/12/09.8212140224
- 8212140289 Forwards re-evaluation of safety-related concrete massury walls per IE Bulletin 80-11 Requests NRC review be concluded by June 1983 SCHROEDER: C W Commonwealth Edison Co 82/12/09 SCHMENCER. A Licensing Branch 2 2pp 16402 085 24X Fiche 50-373.82/12/09.
- ---8212140292 "Re-evaluation of Safety-Related Concrete Masonry Walls at LaSalis County Station "

 * Commonwealth Edison Co 82/11/19 11pp 16402 087 24X Fiche 50-373, 82/12/09, 8212140289
- 8212210104 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 50-373/82-46 & 50-374/82-19
 NORELIUS, C E Division of Engineering & Technical Programs 82/12/13 REED, C Commo
- --821221010B Responds to NRC 82110B ltr re violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19 Corrective actions Morrison Const Co SDP PC-2 welding matls control procedure reworded to avoid internal procedure conflict DELOGOROE. L O Commonwealth Edison Co 82/12/02 KEPPLER, J O Region 3, Office of Director 3pp 16491 043 24X Fiche 50-373,82/12/13,8212210104
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNO,R C Director's Dffice. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 1270p 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage 2001/0/26M IE Info Notice 92-30, "Non or Solid State AC Undervoit Relays Tupe 17E-27" Svc list encl JORBAN.E L Division of Engineering & Quality Assurance 82/1 Consolidated Edison Co of New York. Inc 108pp 16628 293 Fiche 50-000, 82/12/20, 8208170268
- 8212270178 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09
 STREETER.J F Division of Project & Resident Programs 82/12/20
 REED.C Commonwealth Edison Co ip 16535 151 24X
 Picks 30-373,82/12/20.8212270198
- --8212270223 Responds to NRC B21007 ltr re violations noted in 1E Insp. Repts 50-373/82-41 & 50-374/82-09 Corrective actions operator trainee functioning directly under unit operator & guidelines for control room trainees drafted DELOECROE. O Commonwealth Edison Co 82/11/05 KEPPLER, J Q Region 3, Office of Director 3pp 16535 152 24X Fiche 50-373,82/12/20,8212270198
- R Periodic operating reports & related correspondence
- 8212130175 Forwards monthly operating rept for Nov 1982 DIEDERICH 0 J Commonwealth Edison Co 82/12/06 Resource Management, Director 1p 16396 072 24X Fiche 50-373, 82/12/06, 8212130175
- --8212130177 Monthly operating rept for Nov 1982 ULLRICH,J Commonwealth Edison Co 82/12/06 16pp 16396 073 24X Fiche 50-373,82/12/06,8212130175
- B Reportable occurrences, LERs & related correspondence
- B212020274 Forwards NPDES noncompliance notification DIEDERICH, 0 J Commonwealth Edison Co 82/11/23 KEPPLER. J G Region 3, Office of Director 2pp 16288 353 24X Fiche 50-373.82/11/23.8218020274
- --B212020282 NPDES noncompliance notification on B21029, iron concentrations of 41 3 mg found in regenerated waste solids discharge tank Caused by addition of const wastes from Unit 2 condensate polishing sys Treatment mod initiated * Commonwealth Edison Co 82/11/12 ip 16288 355 24X Ficha, 50-373, 82/11/23, 82/2020274
- 8212020294 Forwards LER 82~138/03L-0 DIEDERICH,0 J Commonwealth Edison Go 82/11/23 KEPPLER,J 0 Region 3, Office of Director ip 16277 359 24X Fiche.50-373,82/11/23,8212020294

- ---9212020301 LER 82-138/03L-0 on 821026, LIT5-1821-N026A level switch failed to perform design function Caused by misalignment of micro switch w/actuating device preventing proper operation Buttch realigned HQUSTON, R W Commonwealth Edison Co 82/11/22 Region 3, Office of Director 2pp 16277 360 24X Fiche 50-373,82/11/23,82320294
- B212020305 Forwards LER B2-137/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/11/24 KEPPLER, J 0 Region 3, Office of Director 1p 16277 270 24X Fishe 50-373, 82/11/24, 8219020305
- --8212020327 LER 82-137/03L-0 on 921026, both reactor recirculation pumps received downshift signal Pump 1A downshifted, but pump 1B did not pick up in slow speed & drifted to stop, resulting in tripping of pump 1A Caused by feedwater low flow transient HIETELA, J Commonwealth Edison Co 82/11/24 Region 3, Office of Director 2pp 16277 271 24% Fiche 50-373,82/11/24, 8212020305
- 0212080400 Forwards LER 02-140/03L-0 DIEDERICH,0 J Commonwealth Edison Co 02/11/29 KEPPLER.J 0 Region 3, Office of Director ip 16352 273 24X Fiche 50-373.02/11/29.021000400
- --B2120B0410 LER B2-140/O3L-O on B21030, affgas pretreatment munitor became inoperative Caused by loss of flaw due to water in sample line Sample line drained Purge valve installed to allow proper flow LUETT, W.R. Commonwealth Edison Co. 82/11/29, Region 3, Office of Director 3pp 16352 274 24X Fiche 50-373, B2/11/29, B2330B0400
- B212080308 Forwards LER 92-142/03L-0 DIEDERICH, G J Commonwealth Edison Co 82/11/30 KEPPLER, J G Region 3, Office of Director 1p 16393 353 24X Fiche 50-373, 62/11/30, 8212080308
- --B212080317 LER B2-142/03L-0 on B21102, radwaste valve DWL067 did not fully close when tripped w/simulated radwaste discharge hi-hi trip signal Caused by fouling of valve internals w/foreign matls Valve cleaned ARANO.J Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16353 354 24X Fiche 50-373,82/11/30,8212080308
- B2120B0412 Forwards LER B2-139/03L-0 DIEDERICH, G J Commonwealth Edison Co 82/11/20 KEPPLER, J G Region 3, Office of Director 1p 16352 270 24X Fiche 50-373, 82/11/30, 82120B0412
- --B212080413 LER 82-139/03L-0 on 821030.Div 11 oxygen channel was reading erratically Caused by moisture buildup in oxygen sample flowmeter Moisture removed & instrumentation recallbr DUS.R Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16352 271 24X Fiche 50-373.82/11/30.8212080412
- \$212080508 Forwards LER 82-143/03L-0
 DIEDERICH O J Commonwealth Edison Co 82/11/30 KEPPLER, J G
 Region 3, Office of Director 1p 16352 069 24X
 Fiche 50-373,82/11/30,8212080508
- --8212080524 LER 82-143/O3L-O on 821102.offgas pretreatment monitor inoperable Caused by loss of flow due to water in sample line drained Temporary heat trace installed to keep gas at higher temp Mod M-1-1-82-227 written LUETT.W Commonwealth Edison Co 82/11/30 Region 3, Office of Director 2pp 16352 070 24X Fiche 50-373,82/11/30.8212080508
- 8212080318 Forwards LER 82-141/03L-0 DIEDERICH.O J Commonwealth Edison Co. 82/12/01 KEPPLER, J 6 Region 3. Office of Director ip 16353 344 24X Fiche 50-373,82/12/01,8212080318
- --8212080332 LER 82-141/03L-0 on 821102,RCIC inboard testable check valve IE51-F066 failed to indicate closed Cause still under investigation byvendor Alternative limit switch configurations being evaluated HGUSTON,R W Commonwealth Edison Co 82/12/01 Region 3, Office of Director 2pp 16353 345 24X Fiche 50-373,82/12/01,8212080318
- 9212100272 Forwards NPDES noncompliance notification DIEDERICH, O J Commonwealth Edison Co 82/12/02 KEPPLER, J & Region 3, Office of Director in 16377 087 24X Fiche 50-373, 82/12/02, 8212100272
- --9212100275 NPDEB noncompliance notification on 821105, temporary hydrogen peroxide sys not injecting hydrogen peroxide Injection pump repaired * Commonwealth Edison Co 82/11/13 2pp 16377 088 24X Fiche 50-373,82/12/02,8212100272

- B212100261 FND-111-82-133 on 821205 during hot shutdown, discharge valve in recirculation loop A could not open beyond 207 Vendor representative will attempt in-place repairs Unit placed in cold shutdown WALKER, R., OULDEMOND, W., STREETER, J. Region 3, Defice of Director 82/12/06 ip 16376 146 24X Fiche 50-373,82/12/06,8212100261
- 8P12140067 Forwards LER 82-144/03L-0 DIEDERICH 0 J Commonwealth Edison Co 82/12/06 KEPPLER, J C Region 3, Office of Director 1p 16408 313 24X Fiche 50-373, 82/12/06. 8212140067
- --B212140095 LER 82-144/03L-0 on B21107.Div 1 battery charger doclared inoperable due to defective dc output breaker Battery also out due to prolonged discharge w/specific gravities exceeding min value Caused by poor connections
 HIETALA.J Commonwealth Edison Co B2/12/06 Region 3, Office of Director 2pp 16408 314 24X Fiche 50-373,82/12/06,8212140067
- 8212140119 Forwards LER 82-145/03L-0 DIEDERICH.0 J Commonwealth Edison Co 82/12/06 KEPPLER.J 0 Region 3. Office of Director 1p 16408 201 24X Fiche 50-373-82/12/06.8212140119
- --821214012B LER 82-145/03L-O on 821107.chlorine & ammonia detector B alarmed & would not reset Caused by dirty lens Lens cleaned & detector returned to syc KAY,D L. Commonwealth Edison Co 82/12/06 Region 3, Office of Director 2pp 16408 202 24X Fiche 50-373,82/12/06,8212140119
- G212270354 Forwards LER 82-155/03L-0 Detailed event analysis encl DIEDERICH, 0 J Commonwealth Edison Co 62/12/06 KEPPLER, J 0 Region 3, Office of Director 2pp 16530 012 24X Fiche 90-373, 62/12/06, 8212270354
- --8212270356 LER 82-195/03L-0 on 921118, secondary containment violated in reactor bldg at 761-ft elevation due to doors 418 & 285 opening simultaneously Caused by malfunctioning latch bolt due to electric strike out-of-adjustment at door 285 KAY.D L Communumenth Edison Co 82/12/03 Region 3, Office of Director ip 16530 014 247 Fiche 50-373,82/12/06.8212270354
- 8912170159 Forwards LER 82-146/03L-0 DIEDERICH, 0 J Commanwealth Edison Co 82/12/09 KEPPLER, J G Region 3. Office of Director 1p 16462 030 24X Fiche 50-373, 82/12/09, 8212170159
- --B212170176 LER 82-146/03L-0 on 821111.div II.1D18-N009C monitor discovered drifting high Caused by failed Geiger-Muller tube Tube replaced KAY.D L. Commonwealth Edison Co. 82/12/10 Region 3, Office of Director 2pp 16462 031 24X Fiche 50-373,82/12/09,8212170159
- 8912170184 Forwards LER 82-148/03L-0 DIEDERICH,O J Commonwealth Edison Co 82/12/09 KEPPLER.J @ Region 3. Office of Director 1p 16462 061 24X Fiche 50-373.82/12/09.8212170184
- 8212170174 LER 82-14B/O3L-O on 821112.Div 11 post-LDCA oxygen channe) indication drifted down to 4% Caused by instrument drift, resulting in false indication Adjustments made to sample flows & calibr performed DUS.R Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16462 062 24x Fichs 50-373,82/12/09,8212170184
- 0212170233 Forwards LER B2-147/03L-0 DIEDERICH,O J Commonwealth Edison Co B2/12/09 KEPPLER,J O Region 3, Office of Director ip 16459 332 24X Fiche 50-373,82/12/09,8212170233
- --8212170238 LER 82-147/03L-0 on 821111, offgas B train hydrogen analyzer began operating erratically Caused by moisture entering sensitive hydrogen sensors in units Hydrogen sensors removed, dried out & replaced HOUSTON, R Commonwealth Edison Co 82/12/10 Region 3, Office of Director 2pp 16459 333 24X Fiche 50-373, 82/12/09, 8212170233
- B212170123 Forwards LER 82-149/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/12/10, KEPPLER, J Q Region 3, Office of Director 1p 16452 349 24x Fiche 50-373, 82/12/10, 8212170123
- --8212170126 LER 82-149/03L-0 on 821112, lake blowdown flow recorder discovered giving incorrect readings Caused by algae buildup on instrument probe Probe cleaned & weekly functional test will be performed WATFORD, P.S. Commonwealth Edison Co. 82/12/10 Region 3, Office of Director 2pp. 16452 350 24% Fiche 50-373,82/12/10,8212170123

- 8212170211 Forwards NPDES noncompliance for Permit IL0048151, per App B, Section 3 2 of License NPF-11 DIEDERICH: 0 J Commonwealth Edison Co 82/12/10 KEPPLER, J G Region 3, Office of Director 1p 16459 349 24X Fiche 50-373, 82/12/10, 8212170211
- --B212170214 NPDES noncompliance notification on 821112 discharge from low vol waste wastewater treatment facility contained 115 6 mg/l oil & grease Cause not stated Discharge stopped, tank taken out of svc & oil soak bags placed in tank DEEDERICH, & J Commonwealth Edison Co 82/11/24 2pp 16459 350 24% Fiche 50-373, 82/12/10,821217021;
- 8212170264 Forwards LER 82-150/03L-0 DIEDERICH 0 J Commonwealth Edison Co 82/12/10 KEPPLER J G Region 3, Office of Director 1p 16456 201 24X Fishe 50-373, 82/12/10, 8212170264
- ~-8212170270 LER 82-150/03L-O on 821111.RCIC flow controller failed to control RCIC sys flow during performance of BTP-14 Caused by loose leads at square root converter 1851-K601 Leads tightened RCIC sys successfully run HOUSTON.R W Commonwealth Edison Co 82/12/10 Region 3. Office of Director 2pp 16456 202 24X Fiche 50-373,82/12/10. RP121702A4
- 8212270140 Forwards LER 82-152/03L-0 DIEDERICH, O J Commonwealth Edison Co. 82/12/13 KEPPLER, J G. Region 3. Office of Director 1p 16538 (31 24% Fiche. 80-373, 82/12/13, 8212270140
- --0212270148 LER 82-132/03L-0 on 821115 during performance of LIS-RI-01, differential pressure indicating switch 1E31-N007A setpoint found out of talerance in ponconservative direction per Tech Spec 3 3 2 Cause unknown Switch recalibr HOUSTON,R W Commonwealth Edison Co 82/12/13 Region 3, Office of Director. 2pp 16538 132 24X Fishe 50-373,82/12/13, 8212270140
- 8212270162 Forwards NPDES noncompliance rept for 821116 DIEDERICH OJ Commonwealth Edison Co 82/12/13 KEPPLER J G. Region 3, Office of Director 2pp 16539 007 24X Fiche 50-373, 82/12/13, 8212270162
- --8212270170 NPDES noncompliance rept on 821116, emulsified oil in equalization tank reduced flocculation to filtration efficiency Cause not stated Plant discharge stopped & all treated water returned to equalization tank & Commonwealth Edison Co 82/12/13 Ip 16939 009 24X Fiche 50-373,82/12/13,8212270162
- 8212280363 Interim deficiency rept to inadequate pressure transducers/
 transmitters mounted on post-LDCA hydrogen recombiners
 Initially reported on 821119 Final rept will be submitted by
 830211 Also reported per Part 21
 MANNO.S F Niggars Mohawk Power Corp 82/12/14 BTAROSTECKI,R
 Division of Project & Resident Programs 2pp 16560 058 24X
 Fiche 50-000.82/12/14.8212280363
- --8212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LOCA hydrogen recombiners Transducers should be replaced w/nuclear sated transducers Engineering field bulletin to be issued by 821027

 EMPEY, D. C. Rockwell International Corp. 82/10/21 COLLING, J. Region 4. Defice of Director. 2pp. 16560-060 24X

 Fiche 50-000, 82/12/14, 8212280363
- B2:2270175 Forwards LER 82-151/03L-0 DIEDERICH 0 J Commonwealth Edison Co 82/12/15 KEPPLER, J G Region 3: Office of Director 1p 16538 020. 24X Fiche 50-373. 82/12/15.8212270175
- --8212270180 LER 82-151/O3L-0 on 821117, emergency makeup control room ventilation fan 8 failed to start Caused by bent outlet damper shart to 8 train & broken bearing housing cap Linkage misaligned when installed initially Damper repaired, HITTENSURG, K. Commonwealth Edison Co. 82/12/15 Region 3, Office of Director 2pp 14538 021 24% Fiche 50-373,62/12/15,6212270175
- G212280447 Forwards LER 82-153/03L-0 DIEDERICH.O J Commonwealth Edison Co 82/12/16 KEPPLER.J 9 Region 3. Office of Director 1p 14556 001 24X Fiche 50-373, 82/12/16.8212280447
- ~-8212280449 LER 82-153/03L-0 on 821118, steam & water leak discovered on regenerative HX shell side relief line to HX socket weld junction Cause not determined Reactor water cleanup systicolated whoth HX off HX off WINTERNOFF, D. Commonwealth Edison Co. 82/12/15 Region 3, Office of Director 2pp 14556 002 R4X Fiche 50-373, 82/12/16, 8212280447

- 8212280483 Forwards LER 82-154/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/12/16 KEPPLER, J G Region 3. Office of Director 1p 16556 006 24X Fiche 50-373, 82/12/16.8212280483
- --8212280487 LER 82-156/03L-0 on 821119, while performing STP-23A. reactor coolant conductivity exceeded limit Caused by personnel error Personnel advised that startup test insufficient reason to bupass condensate polishers
 WITTENBURG. K. Commonwealth Edison Co. 82/12/16 Region 3, Office of Director 2pp 16556 007 24X Fiche 50-373.82/12/16, 8212280483
- 8212280195 Forwards LER 82-158/03L-0 DIEDERICH O J Commonwealth Edison Co 82/12/20 KEPPLER J G Region 3. Office of Director ip 16556 158 24X Fiche 50-373,82/12/20.8212280195
- --8212280215 LER 82-158/03L-0 on 821122.drain valve 1821-F016 would not seal in close direction Caused by dirty contacts in closing torque switch Torque switch contacts cleaned & settings verified DUS.R Commonwealth Edison Co 82/12/20 Region 3, Office of Director 2pp 14554 159 24X Fiche 50-373.82/12/20,8212280195
- B212280229 Forwards LER 82-157/03L-0 DIEDERICH, 0 J Commonwealth Edison Co 82/12/20 KEPPLER.J G Region 3, Office of Director 1p 16862 273 24X Fiche 50-373, 82/12/20, 8212280229
- --8212280231 LER 82-157/03L-0 on 821121.9A control room HVAC ammonia detector failed Caused by broken paper tape in detector Tape replaced HATFORD.P S Commanwealth Edison Co 82/12/20 Region 3. Office of Director 2pp 16562
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR. Big Rock Point, Dresden 1. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0783 Svc list encl W/o stated encl EISEMHUT, D 9 Division of Licensing 62/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15,8211230066
- 82120603B! Notification of 821201 meeting w/util, CF Braun & Govt Accountability Project in Bethesda.MD to discuss independent review of HVAC sys BOURNIA.A Licensing Branch 2 82/11/26 SCHWENCER, A Licensing Branch 2 3pp 16323 324 24X Fiche 50-373.82/11/26,8212060381
- B212220212 Forwards Revision 22 to CE-1-A, "GA Program for Nuclear Congrating Stations" SWART, E.D. Commonwealth Edison Co. 62/12/14 HAASS, W.P. Quality Assurance Branch 1p 16518 007 24X Fithe 50-000,82/12/14,
- --8219220231 "QA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000,82/12/14.8212220212
- B£12280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment SHARTY. E.D. Commonwealth Edison Co. 82/12/22 EISENHUT, D.G. Division of Licensing 18pp 16556 161 24X Fiche 50-000, 82/12/22, 8212280212
- 8212280298 Forwards info on 821201 meeting re Oovt Accountability
 Project repts & discussions of corrective actions for
 CF Braun Observation OC-2-53, GA review & Unit 2 HVAC, per NRC
 821203 request
 REED.C Commonwealth Edison Co 82/12/22 EIGENHUT, D @ Division
 of Licensing 34pp 16561 099 24X Fiche 50-373,82/12/22,
- F Security, medical, emergency & fire protection plans
- BD12060041 Forwards Revision 13 to modified amended security plan Revision withheld (ref 10CFR73 21) DELOEGRGE, L C Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16313 270 24X Fiche 50~373,82/11/29,8212060041

- S212090383 Forwards info re emergency operations facilities per B21122 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee DELOEURGE.L O Commonwealth Edison Co 82/12/03 EISENHUT, D 9 Division of Licensing 2pp (6365-051 24X Fichs 50-000-82/12/03, 8212090363
- BP12130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "FELTON J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 90-000, 82/12/07, 8212130017
- --B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EO-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "Revised table of contents encl PAJOHSKI.J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000, B2/12/07, B212130017
- ~-8212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Unsite & Offsite Monitoring Locations (Maps)"

 FAJUMSKI, J E Commanwealth Edison Co 82/11/29 4pp 16417 068 244 Fiche 50-000, 82/12/07, 8212130017
- 87:12140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMILT Commonwealth Edison Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50-000.82/12/07.8212140243
- 6212220175 Releases public version of revised generating station emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 82/12/10 Documen Management Branch ip 16527 027 24X Fiche 50-000, 82/12/10, 8212220175
- -- 8212220170 Forwards public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request PAJONSKI.J E Commonwealth Edison Co 82/11/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16527 030 24X Fiche 50-000,82/12/10,8212220175
- --82122P0202 Public version of revised generating station emergency plan implementing procedures, including Procedures ED-3 re demand polling of meteorological data & ED-20 re emergency forecast request LITERSKI, L A Commonwealth Edison Co 82/10/13 48pp 16529 031 24X Fiche 50-000,82/12/10,8212220175
- B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site remergency operations facility KEPPLER. J 0 Region 3. Office of Director B2/12/16 Commonwealth Edison Co. 3pp. 14503-351 24X Fiche 50-000,82/12/16. M212220306
- B212300167 Releases public version of revised generating station emergency plan telephone directory FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Fiche 50-000, 82/12/20, 8212300167
- B212300179 Forwards public version of revised generating station emergency plan telephone directory MUDRE.R D Commonwealth Edison Co B2/12/02 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 14612 216 24X Fiche 50-000, 82/12/20, 8212300167
- --B212300199 Public version of revised generating station emergency plan telephone directory GALLE,D P Commonwealth Edison Co B2/11/05 60pp 16612 21/ 244 Fiche 50-000, B2/12/20, B212300167
- H General correspondence
- 8:12280176 Notifies of change in mailing address for NRC licensing mat! WRIGHT, C N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D C Division of Licensing, ip 16556 135 24X Fiche \$0

- K Utility Final Bafety Analysis Report (FSAR) & amends
- B212210463 Forwards Amend &1 to FSAR, updating baseline record & incorporating as-built & as-tested configuration SCHROEDER,C W. Commonwealth Edison CO. B2/12/13 DENTON,H R. Office of Nuclear Reactor Regulation. Director 3pp 16496-276-24X Fiche 50-373,82/12/13.8212210463
- --G212210466 Amend 61 to FSAR * Commonwealth Edison Co 82/12/31 299pp 16486 277 24X Fiche 50-373,82/12/13,8212210463
- B212280341 Forwards affidavit confirming distribution of FSAR.Amend 61 8CHROEDER.C W Commonwealth Edison Co B2/12/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16560 092 44X Fiche 50-073.82/12/23.8212280341
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision i, "Btress Cracking in Thick-Wall, Large-Diameter, Btainless Steel, Recirculation Sys Piping at BHR Plants "Svc list encl
 DEYQUNO, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24x Fichs 50-000, 82/10/28, 8208190240
- G208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consultdated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 82081-90245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JRDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24x Fiche 50-000, 82/11/18, 8208190251
- 8212030021 Forwards IE Insp. Repts 50-373/82-49 & 50-374/82-15 on B21001-29 No noncompliance noted STREETER, J.F. Division of Project & Resident Programs 82/11/18 REED, C. Commonwealth Edison Co. 2pp. 16304-316 24X Fiche 50-373, 82/11/18, 8212030021
- --B212030028 IE Insp Repts 50-373/82-49 & 50-374/82-15 on B21001-29 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational safety verification & monthly surveillance observations
 GULDEMOND, N , WILLIAMS, D , MADISON, A Division of Project & Resident Programs 82/11/18 12pp 14304 318 24X
 Fiche 50-373,82/11/18,8212030021
- B212140326 Forwards final SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 No response required KEPPLER, J O Region 3. Office of Director 82/11/23 REED, C Commonwealth Edison Co 3pp 16402 012 24X Fiche 50-373, 82/11/23, G212140326
- --B212140327 SALP Repts 50-373/82-38 & 50-374/82-08 for Jul 1980-Dec 1981 Deficiency noted in conducting tests w/o adequate procedures * Region 3, Office of Director 82/05/30 37pp 14402 015 24X Fiche 50-373,82/11/23,8212140326
- 6208190256 IR Info Notice 92~46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc. 127pp 16411 065 24X Fithe 50-000.62/11/26,8208190256
- 8208190257 IE info Notice 82-47. "Transportation of Tupe A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York
- B212170077 Forwards 1E Insp Repts 50-373/B2-53 & 50-374/B2-21 on B21101-05 & 08 No noncompliance noted PAPERIELLO,C J Division of Emergency Preparedness & Operational Support 82/12/01 REED.C Commonwealth Edison Co 2pp 16450 354 24X Fiche 50-373,82/12/01,8212170077
- --8212170079 IE Insp Repts 50-373/82-53 & 50-374/82-21 on flip101-09 & 08
 No noncompliance noted Major areas inspected radiological
 environ protection, including program mgt, GC &
 implementation
 JANUSKA, A C , CESTMANN, M J , SCHUMACHER, M C Division of Emergency
 Preparedness & Operational Support 82/11/29 8pp 16450 356
 24X Fiche 50-373, 82/12/01, 8212170077

ļ

- B208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Editon Co of New York, Inc Ilap 16401 317 24% Fiche 50-000. 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Sve list enci JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000, 82/12/03, 8208190261
- 8212140224 Act receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropt 50-373/82-45 SPESSARD, R L Division of Project & Resident Programs 82/12/09 REED. C Commonwealth Edison Co 1p 16408 339 24X Fiche 50-373, 82/12/09, 8212140224
- --8212140231 Responds to NRC 821104 ltr re violations noted in IE Insp Repts 90-373/82-45 & 50-374/82-13 Corrective actions flow controller returned to panel & station procedures revised to include leakage compensation DELOEORGE, L.O. Commonwealth Edison Co. 82/12/02 KEPPLER, J.G. Division of Project & Resident Programs. 3pp. 16408-340. 24X Fiche 50-373,82/12/09.6212140224
- 8212140287 Forwards re-evaluation of safety-related concrete masonry walls per IE Bulletin 80-11 Requests NRC review be concluded by June 1983
 SCHROEDER, C M Commonwealth Edison Co 82/12/07 SCHHENCER, A Licensing Branch 2 2pp 16402 085 24X Fiche 50-373,82/12/07,8212140287
- --8212140292 "Re-evaluation of Safety-Related Concrete Masonry Walls at LaSalle County Station " * Gommonwealth Edison Co 82/11/19 11pp 16402 087 24X Fiche 50-373,82/12/09.8212140289
- 8212210104 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 50-373/82-46 & 50-374/82-19
 NGRELIUS, C E Division of Engineering & Technical Programs 82/12/13 REED.C Commonwealth Edison Co Ip 16491 042 24X Fichs 50-373.82/12/13.8212210104
- --B21221010B Responds to MRC 82110B ltr re violations noted in IE Insp Repts 50-373/82-46 & 50-374/82-19 Corrective actions Morrison Const Co SOP PC-2 welding metls control procedure reworded to avoid internal procedure conflict DELOGORGE.L O Commonwealth Edison Co 82/12/02 KEPPLER.J G Region 3, Office of Director 3pp 16491 043 24X Fiche 50-373,82/12/13,8212210104
- 820B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYGUND,R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- BP12270198 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-373/82-41 & 50-374/82-09
 STREETER. J F Division of Project & Resident Programs 82/12/20
 REED. C Commonwealth Edison Co ip 16535 151 24X
 Fiche 50-373.82/12/20.8212270198
- --8212270223 Responds to NRC 821007 ltr re violations noted in IE Insp Repts 50-373/82-41 & 50-374/82-09 Corrective actions operator trainee functioning directly under unit operator & guidelines for control room trainees drafted DELOECRES, L O Commonwealth Edison Co 82/11/05 KEPPLER, J O Region 3. Office of Director 3pp 16535 152 24X Fische 50-373,82/12/20,8212270198
- 8212290337 Forwards addit copies of inservice inspiplan in response to NRC request & per requirements of Deneric Ltr 82-14 Suggests alternative to requirements contained in itr SCHROEDER.C W Commonwealth Edison Co 82/12/21 SCHWENCER.A Licensing Branch 2 2pp 16587 124 24X Fiche 50-374,82/12/21,8212390337

- S Reportable occurrences. LERs & related correspondence
- 8P12270162 Forwards NPDES noncompliance rept for 821116 DIEDERICH, 0 J Commonwealth Edison Co 82/12/13 KEPPLER, J G Region 3, Office of Director 2pp 16539 007 24X Fiche 50-373, 82/12/13, 8212270162
- --8212270170 NPDES noncompliance rept on 821116, emulsified oil in equalization tank reduced flocculation & filtration efficiency Cause not stated Plant discharge stopped & all treated water returned to equalization tank & Commonwealth Edison Co. 82/12/13 ip 16939 009 24X Fiche 50-373,82/12/13,8212270162
- 8212280363 Interim deficiency rept re inadequate pressure transducers/ transmitters mounted on post-LOCA hydrogen recombiners Initially reported on 821119 Final rept will be submitted by 830211 Also reported per Part 21 MANNO.S F Niagara Mohawk Power Corp 82/12/14 STAROSTECKI.R Division of Project & Resident Programs 2pp 16560 098 24X Fiche 50-000,82/12/14,8212280363
- --B212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LCCA hydrogen recombiners Transducers should be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029 EMPEY, D C Rockwell International Corp 82/10/21 CULLINS, J Region 4, Office of Director 2pp 16560 060 24% Fiche 50-000, 82/12/14, 8212280363

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

- W Decommissioning Stage Documents & Correspondence
- 8P12210110 Discusses 800310 application to authorize dismantling of L-85 facility.License R-118 Physical changes in facility have resulted in preparation of revised supporting statement for dismantling facility Statement encl REMLEY.M E Rockwell International Corp 82/12/14 THUMAS.C D Stendardisation & Special Projects Branch 8pp 16491 033 24X Fiche 50-375.82/12/14.8212210110
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8212090429 Forwards 821102 meeting summary re activities authorized by Licenses NPF-13 & CPRR-13 Meeting beneficial & provided better understanding of issues W/o encl O'REILLY,JP Region 2, Office of Director 82/11/15 LEWIS,F W Middle South Utilities, Inc - Middle South Energy, Inc 2pp 16384 274 24X Fiche 50-000,82/11/15,8212090429
- B212270418 Responds to FOIA request for documents re proposed revision %/or update to reactor safety study referred to in NUREO-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, S (Union of Concerned Scientists 3pp 16547 233 24% Fiche 50-000, 82/11/26, 8212270418
- c-8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o enc!
 NOVAK.T M Assistant Director for Licensing 62/09/24
 Division of Licensing ip 16549 278 24X Fiche 50-000.82/11/26, 8212270418
- BRI2100002 Informs of revisions inadvertently excluded from F5AR Amend 29 Info uill be incorporated in F8AR Amend 30.currently scheduled for submittal in early Dec 1982 MAURIN.L V Louisiana Power & Light Co 82/12/07 NOVAK,T M Assistant Director for Licensing 5pp 16377 272 24X Fiche 50-382,82/12/07,8212100002
- 8P12220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NOVAK.T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000,82/12/14,8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memd re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M. Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000:82/12/14.8212220461

- 8212300162 Provides status of commitments re recruiting & upgrading total corporate capability
 MAURIN.L V Louisiana Power & Light Co 82/12/17 WILSON, J NRC -No Detailed Affiliation Given Sap 16598 020 24X
 Fiche 50-382, 82/12/17, 8212300162
- 82/12270160 Confirms B21215 telcon re equipment qualification audit Agreements & commitments documented MAURIN,L V Louisiana Power & Light Co 82/12/20 NOVAK,T M Assistant Director for Licensing 2pp 16538 044 24X Fiche 50-382,88/12/20,8218270160
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 97:20:0175 Forwards Suppl 4 to SER W/o encl KNIGHTON.9 W Licensing Branch 3 82/10/29 MAURIN.L V Louisiana Fower & Light Co 2pp 16290 293 24x Fiche 50-382,82/10/29, 82120:10/75
- F Security, medical, emergency & fire protection plans
- 8212010411 Requests add1 info re emergency action levels in facility radiological emergency plan Response to encl comments should be pravided within 15 days KNIGHTON & W. Licensing Branch 3 82/11/19 MAURIN, L. V. Louisiana Fower & Light Co. Bpp. 16271 069 24X Fichs 50-382, 82/11/19, 8212010411
- GP)2090203 Confirms 821202 telcon re 820128 response to Generic Ltr 81-10 re permanent backup & interim emergency operations facilities (EDF) Interim EDF approved in NRC 820202 ltr MAURIN, L V Lauisiana Power & Light Co 82/12/03 NDVAK, T M Assistant Director for Licensing 3pp 16361 333 24X Fiche 50-382,82/12/03,8212090203
- GP12200121 Forwards GL Madsen 821014 ltr transmitting SALP Rept 50-382/82-20 for Jul 1981 June 1982 & util 821108 & 16 corments on rept COLLEMS.J T Region 4. Office of Director 82/12/03 MAURIN, L V Louisiana Power & Light Co 2pp 16470 100 24X Fiche 50-362.82/12/03.8212200121
- --9212200126 SALP Rept 50-382/82-20 for Jul 1981 June 1982 Addl inspeffort should be continued until const program completed & throughout preoperational testing phase or until licensee demonstrates improvement in mot controls in weak areas CROSBMAN.H A. MADSEN.C.L. Division of Resident. Reactor Project & Engineering Programs 82/10/13 20pp 16470 104 24X Fiche 50-382,82/12/03.8212200121
- --4212200127 Forwards comments on SALP Rept 50-382/82-20 for Jul 1781 June 1782 Agrees w/NRC findings.conclusions &
 recommendations Corrective measures in weak areas initiated
 MAURIN.L V Louisiana Power & Light Co 82/11/08 MADSEN.0 L
 Division or Resident. Reactor Project & Engineering Programs 9pp
 16470 124 24X Fiche 50-382.82/12/03.8212200121
- 8:112150042 Forwards fire protection training program & fire protection program
 ANURINIL V Louisiana Power & Light Co 82/12/07 NOVAK,T M
 Assistant Director for Licensing ip 16425 060 24X
 Fiche 50~382,82/12/09,8212150042
- --8212150047 Fire protection program
 # Louisiana Power & Light Co PMD-PE-010 R00 82/05/17 51pp
 16425 061 24X Fiche 50-382, 82/12/09, 8212150042
- --8212190050 "Program Description for Fire Protection Training "
 Louisiana Power & Light Co 82/02/17 36pp 16425 112 24X
 Fiche 50-382,82/12/09,8212150042
- G7:12150140 Requests deficiencies noted in 820331 interim findings of offsite emergency preparedness be remedied Future interim the final findings should include FEMA headquarter concurrence GRIMES.8 K Division of Emergency Preparedness 82/06/11 KRIMM.8 W Federal Emergency Management Agency 1p 16429 109 24X Fiche 50-382.82/12/14.8212150131
- &P12270013 Releases public version of comments on BNWL/NRC review of emergency action levels FELTON. J M Division of Rules and Records 82/12/16 Document Management Branch 1p 16551 290 24X Fiche 50-382,82/12/16, 8212270013
- ~-8212270015 Forwards public version of BNWL/NRC review of emergency action levels for radiological emergency plan MAURIN, L V Louistana Power & Light Co 82/12/10 NOVAK, T M Assistant Director for Licensing 1p 16551 291 24X Fiche 50~382,82/12/16,8212270013

- --B212270017 Public version of comments on BNWL/NRC review of emergency action levels for radiological emergency plan * Louisiana Power & Light Co. B2/12/10 17pp 16551 292 24X Fiche 50-38g, 82/12/16, 8212270013
- G Adjudicatory correspondence
- 82:12020355 Response opposing applicant 82:112 motion for reconsideration & clarification of certain rulings in ASLB 82:103 partial initial decision on conditions for evacuation & itrs of agreement GROESCH, & L. Joint Intervenors-Waterford 82:11/27 Atomic Safety and Licensing Board Panel 3pp 16278 015 24X Fiche 50-382,82:11/27,82:2020355
- 8212020374 Memorandum & order denying Joint Intervenors 820612 motion for reconsideration of ASLB 790913 order & 790912 ruling Balance of State of LA 820721 petition to intervene denied in light of Court of Appeals decision, NROC vs NRC MOLFE.8 J Atomic Bafety and Licensing Board Panel 82/11/30 Joint Intervenors-Waterford 7pp 16278 092 24X Fiche 80~382,82/11/30.8212020374
- BZ12020342 Order scheduling 830111-14 evidentiary hearing in New Orleans: LA Record reopened solely to receive evidence on adequacy of applicant revised pre-emergency public info-brochure MQLFE, S J Atomic Safety and Licensing Board Panel 82/12/01 2pp 16279 147 24X Fiche 50-382,82/12/01.8212020342
- 821206008B Advises that Judge Jordan should be served at address in Pumpano Beach, FL during 821218-830131 WOLFE, 8 J Atomic Safety and Licensing Board Panel 82/12/01 Uffice of the Executive Legal Director 1p 16314 279 24X fiche 50-382, 82/12/01,8218060088
- BP12060007 Response supporting applicant 821112 motion for reconsideration or clarification of ASLB 821103 partial initial decision Need to satisfy four conditions to receive low power OL should be clarified Certificate of Svc encl TURK, S.E. Hearing Branch i 82/12/02 Atomic 8afety and Licensing Board Panel 8pp 14313 302 24X Fiche 50-382,82/12/02, 8212060007
- B2:12080260 Response opposing Joint Intervenors 82:130 motion to extend time to file direct testimony & to reschedule hearing on emergency brochure intervenors fail to explain witness unavailability Certificate of Byc encl
 1URK:8 E Hearing Branch 1 82/12/07 Atomic Safety and
 Licensing Board Panel 6pp 16354 111 24X Fiche 50-382:82/12/07,
 82:12080260
- 8212100098 Memorializes 821012 telcon w/ASLB, applicant, Joint Intervenors, NRC & FEMA re ASLB rulings on applicant 820923 filling & Joint Intervenor 820927 motions Svc list encl CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Louisians Power & Light Co 82/12/07 WOLFE, S J , FOREMAN, H , JORDÁN, H Atomic Safety and Licensing Board Panel 5pp 16379 181 24X Fichs 50-382,82/12/07,8212100098
- 8712100100 Answer opposing Joint Intervenors 821130 motion to extend time for filing direct testimony & to reschedule hearing on emergency brochure Joint Intervenors fail to justify untimeliness of motion Certificate of Svc encl CHURCHILL.B W Louisiana Power & Light Co CHURCHILL.B W Shaw, Pittman, Potts & Trowbridge 82/12/07 Atomic Safety and Licensing Board Panel 10pp 16379 116 24X Fiche 50-382,82/12/07,8212100100
- B212150035 Memorandum & order denying Joint Intervenors 821130 motion for indefinite extension of time to file direct testimony & request for rescheduling hearing Intervenors failed to show good cause in support of motion WOLFE, S J Atomic Safety and Licensing Board Panel 82/12/13 Joint Intervenors-Materford 6pp 16421 236 24X Fiche 50-382,82/12/13,8212150035
- BP12150131 Forwards listed correspondence between NRC & FEMA Some documents withheld (ref 10CFR2 790)
 TURK. S. E Hearing Branch 1 82/12/14 GROESCH. Q Affiliation
 Unknown 2p 16429 106 24% Fiche 50-392, 82/12/14, 9212150131
- --8212150137 Requests L Jones 820305 ltr to S Turk.NRC exhibit on potassium iodine & transcripts for 820506.07 & 12 CA861DY, B P Federal Emergency Management Agency 82/05/14 TURK.S Hearing Branch 1. ip 16429 108 24X Fiche 50-382.82/12/14.8212150131

- --82(2150140 Requests deficiencies noted in 820331 interim findings of offsite emergency preparedness be remedied Future interim & Final findings should include FEMA headquarter concurrence GRIMES, B K Division of Emergency Preparedness 82/06/11 KRIMM, R W Federal Emergency Management Agency 1p 16429 109 24X Fiche 50-382,82/12/14.8212150131
- --8212150148 Forwards NRC proposed findings of fact.supporting brief & motion to correct hearing transcript W/o encl
 TURK, S E Hearing Branch 1 82/07/16 CASSIDY, B P Federal
 Emergency Hanagement Agency ip 16429 110 24X
 Fiche 50-382,82/12/14.8212150131
- --B212150153 Requests ASLB order requesting further FEMA testimony on public info brachure & final FEMA testimony filed u/ASLB CASSIDY.B P Federal Emergency Management Agency 82/09/13 TURK.S E Hearing Branch I 1p 16429 111 24x Fiche 50-382.82/12/14.8212150131
- B212160354 Memorandum memorializing B21213 telcon w/applicant, NRC. FEMA & Joint Intervenors Joint Intervenors motion to extend time to fill direct testimony & reschedule hearing on emergency brochure denied MCLFE.S J Atomic Safety and Licensing Board Panel B2/12/14 App 16442 337 24X Fiche 50-382.82/12/14,8212160354
- 8212160503 Memorandum & order partially granting applicant 821112 motion for reconsideration or clarification of ASLB 821103 Partial Initial Decision LHP-82-100 Condition 2 reliefs of agreement w/support parishes modified WDLFE.S J Atomic Safety and Licensing Board Panel 82/12/14 Louisiana Power & Light Co 8pp 16442 122 24% Fiche 50-382, 82/12/14.8212160503
- 87:12:409:15 Order rejecting Joint Intervenors 82:212 request for full NRC investigation re-massive chemical fire at Union Carbide plant & relation to nuclear plant ASL8 not authorized to initiate or conduct investigation WOLFE:S J Atomic Safety and Licensing Board Panel 82/12/15 2pp 16442 117 24X Fiche 50-382:82/12/15,8212:605:15
- --9212160521 Notifies of massive chemical fire at Union Carbide plant & requests full NRC investigation re-nuclear plant FONTANA, L. Joint Intervenors-Waterford FONTANA, L. Fontana, L. 82/12/12 WOLFE, S. Atomic Safety and Licensing Board Panel 1p 16442 119 24X Fiche 50-282, 82/12/15, 8212160515
- B212230361 Motion for reconsideration of ASLB 821213 memorandum & order Due to ill health of E Duncan, 30-day extension requested in which to file direct testimony & commence hearings GROESCH, O L. Joint Intervenors-Waterford B2/12/17 Atomic Safety and Licensing Board Papel 4pp 16511 166 24X Fiche 50-382, 82/12/17, 8212230361
- 82:12270330 Forwards ASLAB 730731 Memorandum & Order ALAB-13B, affirming ASLB decisions to reopen hearing on fuel densification (saue & to permit operation during proceeding & reversing determination to reopen on four issues M/svc list PIZZUTO, C M Shaw, Pittman, Potts & Trombridge 82/12/21 GROESCH-0 Joint Intervenors-Waterford 10pp 15530 174 24% Fiche 50-382,82/12/21,8212270330
- 8212270184 Order rescheduling hearing Since record reopened to receive evidence re adequacy of public info booklet, hearing will be held on 80208-11 in New Orleans.LA HOLFELS J Atomic Safety and Licensing Board Panel 82/12/22 2pp 16539 011 24X Fiche 90-382,82/12/22,8212270184
- B212270247 Memorandum memorializing 821221 conference call w/FEMA, applicants & Joint Intervenors MULFE'S J Atomic Safety and Licensing Board Panel 82/12/22 4pp 16530 352 24X Fiche.50-382,82/12/22,8212270247
- B212280182 Exception to ASLB B21103 partial initial decision re Condition 2 Certificate of Svc encl CHURCHILL, B W Louisiana Power & Light Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 82/12/24 Atomic Safety and Licensing Appeal Panel App 16562 181 24X Fichs 50-382,82/12/24, B212280182
- @ Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin B2-03.Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Syc list encl BEYDUNG, R C Director's Office, Office of Inspection and Enforcement. 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche. 50-000, 82/10/28, 8208190240

- B20B190245 IE Info Natice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!

 COBB-L I Division of Fuel Facilities, Materials & Safeguards 82/11/05

 82/11/05 E0011dated Edison Co of New York, Inc 110pp 16372 142 244 Fiche 50-000, 82/11/05 8208190245
- 8P12070119 Forwards IE Insp Rept 50-382/82-23 on 820716-0915 No noncompliance noted MADSEN.6 L Division of Resident, Reactor Project & Engineering Programs 82/11/17 MAURIN.L V Louisiana Power & Light Co 2pp 16327 089 24X Fiche 50-382,82/11/17,8212070119
- --8212070123 IE Insp Rept 50-392/82-23 on 820716-09;5 No noncompliance noted Major areas inspected previously identified insp findings, preoperational test procedure review, preoperational test witnessing & site tour CONSTABLE, 0 L. CUMMINS, J E. JONES, W B Division of Resident, Reactor Project & Engineering Programs 82/11/10 10pp 16327 091 24X Fiche 50-382,82/11/17,8212070119
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDÁN.E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000,82/11/18.8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYDUNO.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8708190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safequards G2/11/30 Consolidated Edison Co of New York, Inc 356pp 16:387 028 24% Fiche 90-000, 82/11/30,8208190257
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYDUNG:R C Director's Office. Office of Inspection and Enforcement 62/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Evc list encl JORDAN-EL, Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8:12070223 Ack receipt of 821027 ltr in response to violations noted in lE Insp Rept 50-382/82-18 Add1 info re craft personnel training & completion of training requested MADSEN. 0 L Division of Resident, Reactor Project & Engineering Programs 82/12/03 MAURIN.(V Louisiana Power & Light Co 2pp 16327 352 24% Fichs 50-382,82/12/03.8212070223
- --8212070228 Responds to NRC 820930 ltr re violations noted in IL Insp Rept 50-382/82-18 Corrective actions Nonconformance Rept H3-4374 issued reporting lack of approved design & weld insp documentation on mod insp Procedure CP-17 revised MAURIN.L V Louisiana Power & Light Co 82/10/29 MADSEN.O L Division of Resident. Reactor Project & Engineering Programs 2pp 16329 354 24X Fiche 50-382,82/12/03,8212070223
- 8212200121 Forwards GL Madsen 821014 ltr transmitting SALP Rept 50-382/82-20 for Jul 1981 June 1982 & util 621108 & 16 comments on rept COLLINS.J T Region 4. Office of Director 82/12/03 MAURIN.L V Louisiana Power & Light Co 2pp 16470 100 24X Fiche 50-382,82/12/03,8212200121
- --B212200125 Forwards SALP Rept 50-3B2/82-20 for Jul 1981 June 1982
 Analyses & evaluation will be discussed in New Orleans, LA
 on 821020 Comments should be submitted within 20 days from
 date of meeting
 MADSEN, O L Division of Resident, Reactor Project & Engineering
 Programs 82/10/14 MAURIN, L V Louisiana Power & Light Co
 2pp 16470 102 24X Fiche 50-3B2, 82/12/03, 8212200121
- --8212200126 SALF Rept 50-382/B2-20 for Jul 1981 June 1982 Addl inspeffort should be continued until const program completed & throughout prepaperational testing phase or until licensee demonstrates improvement in mgt controls in weak areas CROSSMAN & A , MADSEN O L Division of Resident, Reactor Project & Engineering Programs 82/10/13 20pp 16470 104 24% Fiche 50-382,82/12/03,8212200121

- --8212200127 Forwards comments on SALP Rept 50-382/82-20 for Jul 1981 -June 1982 Agrees w/NRC findings, conclusions &
 recommendations Corrective measures in week areas initiated
 MAURIN,L V Louisiana Power & Light Co 82/11/08 MADSEN,G L
 Division of Resident, Reactor Project & Engineering Programs 9pp
 16470 124 24X Fiche 50-382,82/12/03,8212200121
- --82:2200129 Clarifies 821108 comments on Item g of SALP Rept 50~382/62-20 for Jul 1981 June 1982 re instrumentation & controls sys MAURIN, L V Louisiana Power & Light Co 82/11/16 MADSEN, G L
 - sys MAURIN,L V Louisiana Power & Light Co 82/11/16 MADBEN.9 L Division of Resident: Reactor Project & Engineering Programs 2p; 16470 133 24X Fiche 50-382,82/12/03,8212200121
- 8212280374 Forwards IE Insp Rept 50-382/82-14 on 820516-0715 Notice of violation transmitted under separate cover MADSEN: 0 L Division of Resident. Reactor Project & Engineering Programs 82/12/06 MAURIN.L V Louisiana Power & Light Co 2pp 16559 078 24X Fiche 50-382,82/12/06,8212280374
- --8212280378 IC Insp Rept 50-382/82-14 on 820516-0715 Noncompliance noted failure to adequately control quality of sarety-related work CDNSTABLE 6 L , CUMMINS, J E , JONES, W B Division of Resident. Reactor Project & Engineering Programs 92/10/29 17pp 14559 080 24% Fiche 50-392,82/12/06,8212280374
- DP12280423 Discusses IE insp on 820516-0715 & forwards notice of violation & notice of proposed imposition of civil penalty COLLING, J T Region 4. Office of Director 82/12/06 MAURIN, L V Louisiana Power & Light Co 3pp 16559 028 24X Fiche 50-382, 82/12/06, 8212280423
- --8212280430 Notice of violation & notice of proposed imposition of civil penalty in amount of \$20,000 Noncompliance noted failure to adequately control activities affecting quality of safety-related work

 COLLINS.J T Region 4. Office of Director 82/12/06 3pp 16559 031 24X Fiche 50-382,82/12/06,8212280423
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/14 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- BPOBI9026B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl URDAN,E L Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000.82/12/20.8208190268
- 8212270245 Discusses augmented inservice insp program being implemented to comply w/requirements of SRP & & including Branch Technical Position ABB 3-1 re main steam & feedwater & safety injection piping MAURIN, LV Louisians Power & Light Co 82/12/22 NDVAK, T M Assistant Director for Licensing 3pp 16582 100 24X Fiche 50-382, 82/12/22, 8212270245
- 5 Reportable occurrences, LERs & related correspondence
- 8212219066 Fifth interim rept of Significant Const Deficiency 35 re mat1 properties of JC White Co tube track & welded fittings Carrective action will be completed by 830401 Final rept will be sent by 830508 HAURIN.t. V Louisiana Power & Light Co 82/11/15 CQLLINS, J T Region 4, Office of Director 2pp 16492 270 24X Fiche 50-382,82/11/15,82/2210066
- EM12210172 Seventh Interim Significant Const Deficiency Rept 40 re ITE-Goold starter coil failure in containment cooling fans Lab testing of six coils returned to vendor scheduled to be completed by 821210 Final rept will be submitted by 830110 MAURIN.L V Louisiane Power & Light Co 82/11/15 COLLINS, J T Region 4, Office of Director 1p 16484 256 24X Fiche 50-382, 82/11/15,8212210172
- Sti2210281 Final rept of Potential Reportable Deficiency 91 re operator base plate hubs for MSIVs made from alloy mail rather than carbon steel Initially reported on S21019 Safety function of MSIVs not affected Item reportable under 10CFR50 55(e) MAURIN. L V Louisiana Power & Light Co 92/11/15 COLLINS, J T Repion 4. Defice of Director 2pg 16483 019 24X fiche 50-382,82/11/15,8212210281
- B2:2030048 Final rept of Potentially Reportable Deficiency 92 re design of maint hatch shield door seal sys Initially reported on B2:019 Condition not reportable under 100FR90 55(e) because change initiated to upgrade sys to safety-related design MAURIN.L V Louisiana Power & Light Co 82/11/22 COLLING.J T Region 4. Office of Director 2pp 16304 141 24X Fiche 50-382.82/11/22,82:2030048

- BP12030036 Interim Significant Const Deficiency Rept 67 re failure of A500 Orade B tube steel to meet chemical/physical properties Initially reported on 821022 Physical property data needed to judge acceptability Next rept by B21219 MAURIN, L V Louisians Power & Light Co 82/11/23 COLLINS, J T Region 4, Office of Director 3pp 16304 131 24X Fiche 50-382,82/11/23,8212030036
- 8P12030055 Final deficiency mept me lack of DBA testing for Coating Sys MS-1 & MS-3 in meactor containment bldg Initially reported on 821023 Successful BBA tests conducted on Dimetcote E-2 Condition determined not reportable per 105FR50 55(e) MAURIN, L V Louisiana Power & Light Co 82/11/23 COLLINS, J T Region 4. Office of Director 2pp 16304 156 24X Fishe 50-382, 82/11/23, 8212030055
- 8212140395 Significant Const Deficiency Rept 50 re gossible malfunction in Agastat E7000 series time-delay relays Corrective actions complete Documentation being assembled by contractor for 0A review Final rept will be submitted by 820105 MAURIN, L V Louisiana Power & Light Co 82/11/30 COLLINS, J T Region 4, Office of Director 1p 14401 034 24X Fiche 50-382, 82/11/30, 8212140375
- 8212210230 Interim Significant Const Deficiency Rept 49 re Time-Trol. Inc heat trace panel malfunctions Defective modules still being replaced Final rept to be submitted by 830118 MAURIN, L V Louisiana Power & Light Co 82/11/30 COLLINS, J T Region 4, Office of Director 1p 14483 350 24X Fiche 90-382, 82/11/30, 8212210230
- 8212060329 EN-82-037 on 821206, notice of violation & notice of proposed imposition of civil penalty will be issued to util for violation of OA requirements CRAIG, J. AXELRAD, J. NRC No Detailed Affiliation Given 82/12/01 ip 16312 OS1 24X Fiche 80~392,82/12/01,8212060329
- 82:2270:30 Final Significant Const Deficiency Rept 42 re Type HMA auxiliary relays mfg from 1976-June 1981 Instially reported on 91:207 Corrective actions complete.per GE Svc Advice 721-PSM-166 1
 MAURIN, L V Louisiana Power & Light Co 82/12/14 COLLINS, J T Region 4, Office of Director 3pp 16538 146 24X
 Fiche 50-382,82/12/14,8212270130
- 8P12270138 Final Bignificant Const Deficiency Rept 38 re flooding of emergency diesel generator A high & low voltage control & relay panels Damaged relay panels replaced MAURIN, L V Louisiana Power & Light Co 62/12/15 COLLINS, J T Region 4, Office of Director 3pp 16538 134 24X Fiche 50-382, 62/12/15, 8212270138
- B212270166 Interim deficiency rept re incorrect atructural calculations used for holdup & boric acid makeup tanks Const completion date delayed so final rept will not be submitted until G3021
 MAURIN.L V Louisiana Power & Light Co 82/12/15 COLLINS, J. T Region 4. Office of Director ip 16538 043 24X
 Fiche 50~382,82/12/15.8212270166
- BP12270257 Final Significant Const Deficiency Rept 44 re LPSI pump section valves Initially reported on 820810 New 20-inch diameter check valves installed, butterfly valves locked open & 300 lb pressure class rating extended to suction line. MAURIAL V Louisiana Power & Light Co 82/12/15 CDLUNG. J T Region 4. Office of Director 3pp 16530 327 24% Fiche 50-382.82/12/15,8212270257
- 8212280169 Final rept of Significant Const Deficiency 52 re bimstallic penetration wolds w/o stress relief/post-welf heat treatment on containment penetration assemblies Replacement penetrations w/correct post-weld heat treatment installed MAURIN.L V Louisians Power & Light Co 82/12/15 COLLING, J T Region 4, Office of Director 3pp 16563 204 24% Fiche 50-382,82/12/15,8212280169
- BP12280203 Final rept of Significant Const Deficiency 34 re Buffalo Forge HVAC fan shrouds w/o capability to contain fan blade missiles Mods to fans completed on 821112 Reported by manufacturer under fart 21 MAURIN.L V Louisiana Power & Light Co 82/12/15 COLLINS, J T Region A. Office of Director 3pp 16562 104 24X Fiche 50-382.82/12/15.8212280203
- 8212280143 Final rapt of Significant Const Deficiency 48 radesign application of break flanges at elevated temps in RCS, safety injection & chemical & vol control sys Flanges w/matl not meeting ASME Code requirements replaced w/correct matl MAURIN, L V Louisiana Power & Light Co 82/12/17, COLLING, J T Region 4, Office of Director 2pp, 16563 189 24X Fiche 50-382,82/12/17,8212280143

- 8212300198 Potentially Reportable Deficiency 76 re inadequate shoulder sap for Satch C fuel assemblies Initially reported on Salif? Condition determined not reportable Mods to fuel assemblies uill be made by C-E prior to shipment MAURIN. L. U. Louisiana Power & Light Co 82/12/20 COLLINS, J T Region 4, Office of Director 2pp 14599 027. 24X Fiche 50-382,82/12/20,6212360198
- 8212300310 Final Significant Const Deficiency Rept 67 re failure of A500 Orade B tube stael to meet chemical/physical properties Properties within ASHE/ASTM code No degradation of safety-related sys occurred MAURIN. L V Louisiana Power & Light Co 82/12/20 COLLINS, J T Region 4, Office of Director 2pp 14594 214 24X Fiche 50-382,82/12/20,8212300310
- 8812300219 Final rept of Bignificant Const Deficiency 43 re main/
 emergency feedwater sys Internals of thect valves PFH-V828A
 & RFH-V8268 removed & two 4-inch 900 chect valves added
 downstream of each emergency feedwater flow transmitter
 MANRIN.L V Lovisiana Power & Light Co 82/12/21 COLLINS, J T
 Region 4, Office of Director 7pp 15597 357 24X
 Fiche 90-382,82/12/21,8212300219
- BD12300268 Final rept of Significant Const Deficiency 41 re unapproved welding Attachment weld removed & rewelded w/approved procedures Two temporary welds removed & base metal repaired & found acceptable HAURIN, L. V. Louisiana Power & Light Co. B2/12/2t COLLING, J.T. Region 4, Office of Director 3pp 16595, 128 24X Fiche 50-382, 82/12/21, 8212300288
- DUCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

 C. NRC Safety Evaluation Report (SER), supple & correspondence
- 8211090019 Updates 820827 response to SER Suppl 3. Section 3 10 2 2 re seismic & dynamic qualification Info completes SER action CURTIS.N W Pennsylvania Power & Light Co 82/11/04 SCHWENCER, A Licensing Branch 2. 2pp 16008 238 24X Fiche-50-387, 82/11/04, 8211090019
- F Security, medical, emergency & fire protection plans
- --8212030070 IE Safeguards Insp Rept 50-387/82-23 on 820816 No noncompliance noted Major areas inspected licenses actions re excessive alarms Safeguards info deleted (ref 100FR73 21) MADDEN, W J , DUNLAP, J M , 00DV.A T Division of Engineering & Technical Programs 82/11/19 2pp 16304 257 24X Fiche 50-387,82/11/19,8212030087
- B212070151 Forwards IE Insp Repts 50-387/B2-32 & 50-388/B2-05 on B20408-1019 & notice of violation BTAROSTECKI.R Division of Project & Resident Programs 82/11/23 MENYON.B D Pennsylvania Power & Light Co 2pp 16335 318 24X Fiche 50-387.82/11/23,8212070151
- --8212070154 Notice of violation from insp on 820908-1019 Safeguards info deleted (ref 100582 790) • Division of Project & Resident Programs. 82/11/23 2pp 16335 319 24% Fiche 50-387, 82/11/23, 8212070151
- --0212070158 IE Insp Repts 30-387/82-32 & 50-388/82-05 on 820908-1019
 Noncompliance noted security violation re vehicles in
 protected Area & requirements for operable fire protection
 equipment not met Safeguards info deleted (ref 10CFR2 790)
 RHOADS, 0 G . MCCANN, J F . CHUNG, J W Division of Project &
 Resident Programs 82/11/03 17pp 16335-321 24X
 Fiche, 50-387, 82/11/23, 8212070151
- 8212060140 Provides status of 820916 proposed improvements to security sys Improvement re info retrieval complete Mod re vital area portal hardware unnecessary CURTIS.N.W Pennsylvania Power & Light Co 82/11/30 SCHWENCER, A Licensing Branch 2 1p 16313 137. 24X Fiche 50-387, 92/11/30, 8212060140
- 8212220537 Notifies that 821025 amend request for License NPF-14 is consistent w/(0CFR50 54(p) & does not decrease effectiveness of physical security plan No fae required 8CHMENCER. A Licensing Branch 2 82/12/16 CURTIS, N W Pannsylvania Power & Light Co 2pp 16523 036 24X Fiche. 50-387. 82/12/16,8212220337

- B212300407 Releases public version of temporary change notices for emergency plan implementing procedures FELTON, J M Division of Rules and Records 82/12/22 Document Management Branch 1p 16613 179 24X Fiche 50-387, 82/12/22, 8212300407
- --8212300408 Forwards public version of temporary change notices for energency plan implementing procedures including Procedure EP-IP-034 re pharmacy bidg sample station owergency sampling

 * Pennsylvania Fower & Light Co 82/12/14 DENTON, H R NRC No Detailed Affiliation Given in 16613 180 24X
 Fiche 50-387, 82/12/22,8212300407
- --8212300410 Public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling RIZZD.J S Pennsylvania Power & Light Co 82/12/13 14pp 16613 181 24X Fiche 50-387, 82/12/22, 8212300407
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8P122(0450 Forwards Amend 53 to OL application containing Revision 32 to FSAR CURTIS,N W Pennsylvania Power & Light Co 82/12/17 SCHWCNCER,A Licensing Branch 2 11pp 16487 218 24X Fiche 50-387,82/12/17,02/12/10450
- P Operating license stage documents & correspondence
- B212010169 Board Notification 82-114 forwards Teledyne independent design review EISEMHUT,D & Division of Licensing 82/11/09 PALLADINO,N . OILINEKY,V . AHEARNE, J Commissioners Spp 16270 244 24X Fiche 50-387, 82/11/09,8212010169
- 8211230066 Generic Ltr 82-27 to all BMR licenses of operating reactors except LACBWR. Big Rock Point, Dresden 1. Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl Wo stated encl EISENHUT. D & Division of Licensing 62/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15,8211230066
- BP12010030 Informs of issuance of full power license amends on BP1112 Susquehanna i & Summer i issued 40-yr license expiring on P20717 & P20321.respectively Susquehanna i will operate w/low power limitation & Summer i at 50% power PERCH, R L Licensing Branch 2 KANE, W F Licensing Branch i B2/11/15 CASE, E. CARTER, J Office of Nuclear Reactor Regulation, Director EISENNUT, D Division of Licensing ip 16271 356 24x Fiche 50-000, 82/11/15,8212010030
- B212140494 Forwards containment dome shield bell descriptions.Figures 4 & 5
 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 82/11/23
 Advanced Fuel & Spent Fuel Licensing Branch 3pp 16431 336 24;
 Fiche 50-387, 82/11/23,8212140494
- --82:2140497 Advises that shield bell descriptions need no longer be withheld from public disclosure CURTIS.N W Pennsylvania Power & Light Co 82/11/11 SQUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 1p 16431 339 #4% Fiche 50-387,82/11/23.82:2140494
- 8212030253 Board Notification 82-105 forwards RH Vollmer 820930 memo to DG Eisenhut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loafs introduced by pipe clamps not evaluated properly EISENHUT, D 0 Division of Licensing 82/11/24 PALLADINO, N J . ROBERTS.T F . ASSELSTINE, J K . Commissioners 2pp 16316 240 24% Fiche 50-000, 82/11/24,8212030253
- --8212030265 Discusses alleged design deficiency in ASME Code Class I piping Failure to deal w/pipe support-pipe interface design issue would be serious matter if substantiated Dfc of Investigations will assist in evaluation VCLLMER.R H Division of Engineering 82/09/30 EISENHUF.D G Division of Licensing Spp 16316 247 24X Fiche 50-000, 82/11/24,8212030233
- B212060066 Informs of changes to be made to emergency svc water sys in order to resolve single failure concerns food changes appray pond bypass valve from normally closed valve to normally open valve CURTIS,N W Pennsylvania Power & Light Co 82/12/01 SCHWENGER, A Licensing Branch 2 ip 16314 321 24X Fiche 50-387,82/12/01. B212060066

- 8212070214 Suppls 821110 ltr describing nonconformance w/NUREG-0737, Item [1 E 4 2, "Containment Isolation Dependability" Upening logic for isolation valves modified to eliminate ganged-opening in more than one sys CURTIS, N W Pennsylvania Power & Light Co 82/12/07 SCHMENCER, A Licensing Branch 2 ip 16362 343 24X Fiche 50-387, 82/12/07, 82(2070214
- B212160417 Forwards "PA Power & Light Co Susquenhanna Steam Electric Station Unit 1 - Review of As-Built Reconciliation on Sample of 400 Pipe Supports & All Phase III (Large Pipe) Anchors " CURTIS, N W Pennsylvania Power & Light Co 82/12/07 SCHWENCER, A Licensing Branch 2 ip 16443 001 24X Fiche 50-387,82/12/07, G212160417
- --8212160419 "PA Power & Light Co Susquehanna Steam Electric Station Unit 1 - Review of As-Built Reconciliation on Sample of 400 Pipe Supports & All Phase III (Large Pipe) Anchors " SATTARLD, RHOMBES, W J Pennsylvania Power & Light Co 82/11/30 94pp 16443 002 24X Fiche 50-387,82/12/07.8212160417
- 82:12170271 Application for Amend 15 to License NPF-14, consisting of proposed changes to Tech Specs re administrative controls, special test exemption for oxygen concentration, leakage in RCS trefueling operations CURTIS, N W Pennsylvania Power & Light Co 82/12/10 SCHWENCER, A Licensing Branch 2 3pp 16456 177 24X Fishe 50-387, 82/12/10, 821270271
- --8212170272 Proposed Tech Spec changes re administrative controls, special test exemption for oxygen concentration, leakage in RCS & refueling operations a Pennsylvania Power & Light Co 82/12/10 10pp 16456 180 24X Fiche 50-387, 82/12/10, 8212170271
- 82:12160317 Provides justification for interim operation w/currently installed suppression pool temp monitoring sys (SPOTMOS) resistance temp detector device Multiple sensor failures disabling SPOTMOS unlikely to occur during normal operation CURTIS.N W Pennsylvania Power & Light Co 82/12/13 SCHWENCER.A Licensing Branch 2 3pp 16442 083 24X Fiths 50-387,82/12/13. 6212160317
- EP12220552 Forwards Amend 6 to License NPF-14, safety evaluation & notice of issuance & availability Amend changes surveillance requirements for vacuum breakers, establishes min discharge pressurs for LPCI pump & changes ECCS actuation values SCHWENCER. A Licensing Branch 2 B2/12/16 CURTIS, N W Pennsylvania Power & Light Co. 3pp. 16323 309 24X Fiche 50-387, 82/12/16, 92/220552
- --8212220554 Amend 6 to License NPF-14, changing surveillance requirements for vacuum breakers, establishing min discharge pressure for LPCI pump, changing ECCS actuation instrument setpoint values & applicability of safety relief values SCHMENCER, A Licensing Branch 2 82/12/16 28pp 16523 312 24% Fiche 50-387, 82/12/16, 8212220552
- --8212220556 Safety evaluation supporting Amend 6 to License NPF-14 • Office of Nuclear Reactor Regulation, Director 82/12/16 4pp 16523 340 24% Fiche 50-387,82/12/16,8212220592
- ---9212220557 Notice of issuance & availability of Amend 6 to License NPF-14 PERCH.R L Licensing Branch 2 62/12/16 3pp 16523 344 24X Fiche 50-387,62/12/16,9212220552
- 86:12270272 Provides complete description delineating interim gas line flow restrictions to 39m3 per second & procedures addressing sys configuration changes, per License Condition 2 C (13) CURTIS. N W Pennsylvania Power & Light Co 82/12/21 9CHWENGER. A Licensing Branch 2 2pp 16530.324 24X Fichs 50-387.82/12/21. 8212270272
- 8212280446 Advises that util response to questions re evaluation of hydrodynamic loads on control rod drive piping delayed until end of Second Quarter 1783, due to delay in receiving BWR owners group input CURTIS.N W Pennsylvania Power & Light Co 82/12/22, BCHWENCER, A Licensing Branch 2 ip 16556 022 24X Fiche 50-387, 82/12/22, 8212280446
- B212280347 Forwards revised "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4 " CURTIS.N W Pennsylvania Power & Light Co 82/12/23 SCHWENCER, A Licensing Branch 2 2pp 16561 043 24X Fiche. 50-387, 82/12/23, 6212280347
- --8212280354 Revision 1 to "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4 " WILLIAMSON 0 0 . TESKE M E . BILANIN A J Continum Dynamics, Inc 82-4 R01 82/09/30 6pp. 16561 045 24X Fiche 50-387,887/12/23, 8212280347

- @ Inspection reports. IE Bulletins & correspondence
- B208190240 IE Bulletin B2-03, Revision i, "Stress Cracking in Thick-Wall: Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl
 DEVOUND, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24X Fiche 50-000. 82/10/28. B208190240
- 8208190245 IE Info Natice 82~42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc! C08B:L I Division of Fuel Facilities, Natorials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05,8208190245
- 8708190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svr list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18, Consolidated Edison Co of New York, Inc. 109pp 16411
- 8212030087 Forwards IE Safeguards Insp Rept 50-387/82-23 on 820816 No noncompliance noted MARTIN,T T Bivision of Engineering & Technical Programs 82/11/19 KENYON,B D Pennsylvania Power & Light Co 2pp 16304 255 24X Fiche 50-387,82/11/19,8212030087
- --B212030090 IE Safeguards Insp Rept 50-387/82-23 on 920814 No noncompliance noted Major areas inspected licenses actions re excessive alarms Safeguards info deleted (ref 100FR73 21) MADDEN,W J , DUNLAP, J M . OGDY, A T Division of Engineering & Technical Programs 82/11/19 2pp 16304 257 24X Fichs 50-387, 82/11/19,8212030087
- 8P:2070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820708-1017 & notice of violation BTAROSTECKI.R Division of Project & Resident Programs 82/11/23 KENYON, 8 D Pennsylvania Power & Light Co. 2pp 16335 318 24X Fiche 50-387. 82/11/23.8212070151
- --B212070154 Notice of violation from insp on B2090B-1019 Bafeguards i deleted (ref 100FR2 790) e Division of Project & Resident Programs B2/11/23 2pp 16335 319 24X Fiche 50-387. B2/11/23,8212070151
- --8212070158 IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 Noncompliance noted security violation re vehicles in protected area & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790) RHOADS, 0 G, MCCANN, JF, CHUNG, JW Division of Project & Resident Programs 82/11/03 17pp 16335 321 24% Fiche 50-387,82/11/23,8212070151
- B20B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNO.R C Director's Office. Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24K Fiche 50-000.B2/11/26.B20B190256
- 8212100059 Forwards IE Insp Rept 50~387/82-41 on 821105-10, No noncompliance noted MARTIM: T Division of Engineering & Technical Programs 82/11/2 KENYON: B D Pennsylvania Power & Light Co 2pp 16377 149 24X Fiche 50~387, 82/11/26, 8212100059
- --8212100064 IE Insp Rept 50-387/82-41 on 821105-10 No noncompliance noted Major area inspected status of outstanding items concerning pipe hangers & restraints NARGHLL, DURK.JP Division of Engineering & Technical Program 82/11/24 4pp 16377 151 24X Fiche 50-387,82/11/26,821210005
- 8208190257 IE Info Notice \$R-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguards \$82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 R4X Fiche 50-000,82/11/30,8208190257
- 8212030093 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/82-39 MARTIN T Division of Engineering & Technical Programs 82/11/3 KENYON.B D Pennsylvania Power & Light Co 1p 14304 250. 24X Fiche 50-387, 82/11/30, 8212030093
- --B21203009A Responds to NRC 821019 ltr re violations noted in IE Ins Rept 50-387/82-39 Corrective actions Temporary Change 82-2232 issued requiring section heads to identify computer points & functions used for Tech 8pec KENYON, B D Pennsylvania Power & Light Co. B2/11/19 MARTIN, T. Division of Engineering & Technical Programs 4pp 16304 251 24% Fiche 50-387,82/11/30,8212030093

- 8208190289 IE Bull#tin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUND:R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411.317 24X Fiche 50-000.82/12/03,8208190259
- B208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp 16462 064 24 Fiche 50-000, 82/12/03, 8208190261
- 8212290463 Forwards IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/12/14 KENYON, B D Pennsylvania Power & Light Co 2pp 16585 138 24X Fiche 50-387.82/12/14.8212290463
- --8212270465 Notice of violation from insp on 821020-1201 * Division of Project & Resident Programs 82/12/19 ip. 16585 140 24X Fiche 50-387, 82/12/14,8212270463
- --8212290468 IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 Noncompliance noted failure to keep record of average suppression chamber water temp during RGIC sys testing RHOADS, 0 O , MCCANN, J F , CHUNG, J W Division of Project & Resident Programs 82/12/10 17pp 16585, 141 24X Fiche 50-387,82/12/14-8212290469
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8212220400 Ack receipt of 821203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/82-34 MARTIN, T T Division of Engineering & Technical Programs 82/12/16 KENYON, B D Pennsqlvania Poucr & Light Co Ip 16503 232 24X Fiche 50-387, 82/12/16,8212220400
- --8212220405 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 90-387/82-34 Corrective actions procedures revised to clarify & implement insp program for prefabricated hanger components Affidavit enc! KAUFFMAN. J T Pennsylvania Power & Light Co 82/12/03 MARTIN. T T Division of Engineering & Technical Programs Spp 14503 233 24% Fische, 50-397, 82/12/16-8212220400
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JURDAN,E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268

R Periodic operating reports & related correspondence

- 8212290115 Forwards monthly operating rept for Oct 1982 KENYON, B D Pennsylvania Power & Light Co 82/11/11 BEESE, M R. Hanagement Information Branch 1p 16582 245 24% Fiche 50-387, 02/11/11, 0212290115
- ~~8212270117 Monthly operating rept for Oct 1982 RUCZYNSKI.L A Pennsylvania Fower & Light Co 82/11/03 App 16582 246 24X Fiche 50~387.82/11/11.8212270115

S Reportable occurrences, LERs & related correspondence

- BB12030041 Forwards revised LER 82-026/D1T-1 KEISER.H W Pennsylvania Power & Light Co 82/11/19 HAYNES,R C Rejon 1. Office of Director 1p. 16304 138 24X Fiche: 50-387, 82/11/19, 8212030041
- --8212030047 Revised LER 82-026/01T-1 on 820717, review revealed certain cables discussed in Deficiency Rept 80-00-28 not flexed or grounded prior to fuel load Caused by failure to maintain control over FDDR KRI-607 during turnovar of const MITCHELLD 0, Pennsylvania Power & Light Co 82/11/19 Region 1, Défice of Director 2pp 18304 139 24X Fiche 50-387, 82/11/19.8212030041
- 0212030173 Forwards LER 82-045/03L-0 KEIBER: H N Pannsylvania Fower & Light Co. 82/11/24 HAYNEB: R C. Region 1. 07fice of Director 1p 14303 278 24X Fichs. 50-387: 62/11/24: 8212030173.

- --8212030179 LER 82-045/03L-0 on 821025.essential svc water pump failed to start. Cause could not be determined or reproduced Svc pump tested 5 times w/o recurrence of failure MITCHELL.D 0 Pennsylvania Power & Light Co 82/11/24 Region 1. Office of Pirector Ip 16303 279 24X Fiche 50-387.82/11/24, 8212030173
- B2120B0295 Forwards LER BR-046/03L-0 KEISER.H W Pennsylvania Power & Light Co 82/11/29 HAYNES,R C Region 1. Diffice of Director ip 16353 360 24X Fiche 50-387. 82/11/29. 82120B0295
- -B212080303 LER 82-046/03L-0 on 821031.0A reviewer determined five safety-related snubbers installed had not been determined operable by performing necessary surveillance Caused by oversights in turnover process List of snubbers verified MITCHELL-D 0 Pennsylvania Power & Light Co 82/11/29 Region 1.0 Office of Director 1p 16353 361 24X Fiche 50-387.82/11/29, 8212080295
- BPJ2080320 Forwards LER 82-044/03L-0 KEISER:H W Pennsylvania Fower & Light Co 82/11/29 HAYNES,R C Region 1. Office of Director ip 16353 342 24X Fiche 50-387, 82/11/29, 8212080320
- G2120B0333 Forwards LER 82-047/03L-0 KEISER: H W Pennsylvania Power & Light Co 92/11/29 HAYNES, R C Region 1, Office of Director 1p 16353 333 24X Fiche 50-387: 82/11/29, 82120B0333
- --8212080342 LER 82-047/03L-0 on 821027, during performance of dissel generator monthly operability test, diesel generator tripped on high vibration Caused by defective vibration switch & pressure regulator Components repaired KUCZYNSKI, L. A Pennsylvania Power & Light Co. 82/11/29 Region 1. Office of Director 1p. 16393-334 24X Fiche 50-387,82/11/29,8212080333
- BP12080362 Forwards LER 92-042/01T-0 KEIBER: H W Pennsylvania Power & Light Co 82/11/30 HAYNES: R C Region 1. Office of Director 1p 16352 271 24X Fiche 50-387, 82/11/30, 8212080362
- ~-8212080372 LER 82-042/017-0 on 821116, review of response to internal incident rept revealed that grab samples not taken at required frequency while RHR svc water sys monitor out of svc Caused by personnel error KUCZYNSKI, L. A. Pennsylvania Power & Light Co. 82/11/30. Region 1, Office of Director 1p. 16352-292. 24X Fiche 50-387, 82/11/30, 8212080340.
- 8212080369 Forwards LER 92-043/01T-0 KEISER, H W Pannsylvanta Power & Light Co 82/11/30 HAYNES, R C Region 1, Office of Director 1p 16353 314 24X Fiche 50-387, 92/11/30, 8212080369
- --B212080378 LER B2-043/01T-O an B21116, engineering review revealed failure of single component could defeat overload detection b protection devices for containment penetration carrying power cables for reactor recirculation pumps KUCZYMSKI.L A Pennsylvania Power & Light Co 82/11/30 Region in Office of Director Rpp 16353 315 24X Fiche 50-387. 82/11/30.8212080369
- 8212080382 Forwards LER 82-048/03L-0 KEIGER/H W Pennsylvania Power & Light Co 82/12/01 HAYNES,R.C Region 1. Office of Director 1p 16352 321 24X Fiche-50-387, 82/12/01,8212080382
- --B2120B03B6 LER 82-048/03L-0 on 921101.control rod position indication full-out position switch inoperable for one rod Caused by failed subcomponent on printed circuit board Board replaced MITCHELLO G Pennsylvania Power & Light Co B2/12/01. Region 1. Office of Director ip 16352 322 24X Fiche 50-387,82/12/01,8212080382
- 8212140182 Forwards LER 82-002/01T-1 KEISER,H W Pannsylvania Power & Light Co 82/12/01 HAYNES,R C Region 1, Office of Director 1p 16410 211 24X Fiche 50-387, 82/12/01,8212140182

- --B212140189 LER B2-002/01T-1 on 820721, review of pipe clamp anchors determined that Detail 600 anchors would not support axial loads as designed Caused by faulty documentation which allowed incorrect installation of anchors Anchors neworked MITCHELL.D 0 Pennsylvania Power & Light Co 82/12/01 Region 1. Office of Director 2pp 16410 212 24X Fiche 50-387.
- B212140135 Forwards LER 82~049/03L-0 #EISER: H W Pennsylvania Power & Light Co 82/12/03 HAYNES: R C Region 1, Office of Director 1p 16408 171 24X Fiche 50~387, 82/12/03. 6212140135
- --B21214013B LER B2-049/03L-0 on B21103, HPCI sys inoperable when input voltage to static inverter exceeded setpoint & tripped off inverter during statup test program Caused by exceeding trip setpoint Inverter reworked & setpoint raised MITCHELL.D @ Pennsylvania Power & Light Co B2/12/03 Region 1. Office of Director 1p 1640B 172 24X Fiche, 50-3B7, B2/12/03,
- B212140258 Forwards LER 82-050/03L-0 KEISER, H W Pennsylvania Power & Light Co 82/12/03 HAYNES, R C Region 1. Office of Director 1p 16401 330 24X Ficho 50-387, 82/12/03, 8212140258
- --8212140261 LER 82-050/03L-0 on 821105, diesel generator D failed to run during performance of surveillance test Caused by frequency sensitive relay Voltage regulator prepositioned until nonfrequency sensitive relay installed MITCHELL.D G Pennsylvania Power & Light Co 82/12/03 Region 1, Office of Director ip 16401 331 24X Fiche 50-387.82/12/03, 82/12/40288
- B&12140260 Forwards revised LER 82-031/03L-1 KEISER, H W Pennsylvania Power & Light Co 82/12/03 HAYNES, R C Region 1, Office of Director 1p 16401 004 24X Fiche 50-307, 82/12/03, 8212140260
- ---B212140325 Revised LER 82-031/03L-1 on B21002,1105,07,08 & 09. rone III of secondary containment showed indication of failure to maintain required vacuum Caused by wind turbulence External atmospheric sensor moved MITCHELL:D 0 Pennsylvania Power & Light Co 82/12/03 Region 1, Office of Director ip 16401 005 24X Fiche 50-387,82/12/03,82121402A8
- BP12210236 Forwards LER 82-05L/03L-0 KEISER, H W Pennsylvania Power & Light Co 82/12/07 HAYNES, R C Region 1. Office of Director 1p 16484 232 24X Fiche 50-387, 82/12/07, 8212210236
- --B212210241 LER 82-051/OSL-0 on 821107. during startup testing of RCIC sys. controller functioning but could not be transferred to automatic mode Caused by controller not being tuned at rated conditions Controller calibr & testing completed MITCHELL.D G Pennsylvania Power & Light Co 82/12/07 Region 1. Office of Director ip 16484 233 24X Fiche 50-387.82/12/07.821210336
- Bi:12210343 Forwards LER B2-052/03L-0 KETEER:H W Pennsylvania Power & Light Co 82/12/07 HAYNES,R C Region I. Office of Director 1p 16497 001 24X Fiche 50-387, 82/12/07, 8212210343
- ---B212210347 LER B2-052/09L-0 on B21107.during startup testing pressure instrumentation indicated Zone 1 of secondary containment not maintained at required vacuum Caused by high wind condition Zone III sensor separated & moved MITCHELL, D. G. Pennsylvania Power & Light Co. B2/12/07 Region 1. Office of Director ip 16497 003 24X Fiche 50-387.B2/12/07, B212210343
- GD12210052 Forwards LER 82-053/03L-0 KEI5ER:H W Pennsylvania Power & Light Co 82/12/10 HAYNES:R C Region 1. Office of Director 1p 16492 234 24X Fiche 50-387, 82/12/10, 8212210052
- --8212210057 LER 92-053/03L-0 on 921111.during startup testing program, control structure heating & ventilation sys chlorine detector determined inoperable Caused by clogged wick in chlorine detector Equipment repaired MITCHELL, D & Pennsylvania Power & Light Co 82/12/10 Region 1. Office of Director 2pp 16492 235 24% Fiche 50-387, 82/12/10, 8212210052
- BRIR280403 Forwards LER 82-055/03L-0 KEISER:H W Pannsylvania Power & Light Co 82/12/14 HAYNES,R C Hegion I: Office of Director 1p 16560 050 24X Fiche 50-387,82/12/14,8212280403

- --8212280417 LER 82-055/03L-0 on 821114, during startup testings, rod worth minimiter declared inoperable & removed from svc after locking up several times during rod movement Caused by defective reed switch Indication mechanism replaced MITCHELL, D & Pennsylvania Fower & Light Co 82/12/14 Region 1. Office of Director ip 16560 051 24X Fiche 50-387,82/12/14,8212280403
- 8212280465 Forwards LER 82-054/03L-0 KEISER: H W Pennsylvania Power & Light Co 82/12/14 HAYNES: R C Region 1, Office of Director 1p 16956 026 24X Fiche 50-387: 82/12/14.8212280465
- ~~B212280468 LER 82-054/03L-0 on B21115, due to drywell chiller tripping, drywell temp exceeded 135 F Caused by strainer blockage Strainer removed & design change to replace present strainer initiated MITCHELL, D Q Pennsylvania Power & Light Co 82/12/14 Region 1, Office of Director 2pp 16556 027 24% Fiche 50-387, 82/12/14, B212280465
- 8212280400 Final deficiency rept re failure to meet single failure criterion for medium voltage penetration Initially reported on 82117 Redundant Class IE overcurrent protection will be provided for assemblies Also reported per Part 21 CURIIS,N W Pennsylvania Power & Light Co 82/12/15 HAYNES,R C Region f. Office of Director 4pp 14556 138 24X Fiche 50-387,82/12/15.8212280400
- 8212270441 Forwards LER 82-057/03L-0 KEISER.H W Pennsylvania Power & Light Co 82/12/20 HAYNES.R C Region 1. Office of Director 1p 16585 217 24X Fiche 50-387,82/12/20.8212270441
- --8212290446 LER 82-037/O3L-O on 821120, during startup testing program, RCIC declared inoperable after ramp generator failed Cause undetermined Generator board inspected, cleaned & functionally checked No problems identified MITCHELL, D. O. Pennsylvania Power & Light Co. 82/12/20 Region 1, Office of Director ip 14585-220 24X Fiche 50-387,82/12/20,8212290441
- X Onsite Storage of Low Level Waste
- 8212290494 Advises that affidavit re 820923 application for buproduct matl license for low level radwaste storage must contain reason for usthholding info from public disclosure per 100FR2 770 ROUSE.1. C. Advanced Fuel & Spent Fuel Licensing Branch 82/10/27 CURTISEN W. Pennsylvania Power & Light Co. 2pp. 14605-181 24X Fiche 50-387.82/10/27.8212290494
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dreaden 1. Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 & VOLEG-0769 Svc list encl W/o stated encl EISENHVT, D G Division of Licensing B2/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24% Fiche 50-000. 82/11/15,8211230046
- 92/2140494 Forwards containment dome shield bell descriptions. Figures 4 & 5
 ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 92/11/23
 Advanced Fuel & Spent Fuel Licensing Branch 3pp 16431 336 24X
 Fiche: 50-387, 82/11/23, 82/2140494
- ~-8212140497 Advises that shield bell descriptions need no longer be withheld from public disclosure CURTIS.N.F Pennsylvania Power & Light Co 82/11/11 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch Ip 16431 339 24X Fiche 50-387,82/11/23.8212140494
- 8212030253 Board Notification 82-105 forwards RH Vollmer 820730 memo to DC Eisenbut re alleged design deficiency in ASME Code Class I piping Effects of local pipe wall stresses due to support loads introduced by pipe clamps not svaluated properly EISENHUT, D G Division of Licensing 82/11/24 PALLADINO, N J Commissioners 2pp 16316 240 24X Fiche 50-000,82/11/24, 8212030253
- --B212030265 Discusses alleged design deficiency in ABME Code Class I piping Failure to dual w/pipe support-pipe interface design issue would be serious matter if substantiated Ofc of Investigations will assist in evaluation VOLLMERR H Division of Engineering B2/09/30 EISENRUT.D O Division of Licensing 5pp 16316 247 24X Fiche 50-000, 82/11/24,8212030253

- 8012060066 Informs of changes to be made to bmergency svc water sys in order to resolve single failure concerns Mod changes spray pond bypass valve from normally closed valve to normally open valve CURTIS.N W Pennsylvania Power & Light Co 82/12/01 SCHWENCER.A Licensing Branch 2 1p 16914 321 24X Fiche 50-387.82/12/01.
- 8212210310 Provides justification for unnecessary documentation of Unit 2 seismic qualification review team & environ qualification audit Few equipment differences exist between Units 1 & 2 CURTIS.N W Pennsylvania Power & Light Co 92/12/17 SCHWENCER, A Licensing Branch 2 2pp 16496 320 24X Fiche 50-369,82/12/17, 8212210310
- 8212210450 Forwards Amend 53 to DL application containing Revision 32 to FSAR to FSAR CURTIS.N W Pennsylvania Power & Light Co 82/12/17 SCHWENCER.A Licensing Branch 2 lipp 16487 218 24X Fiche 50-387,82/12/17. 8212210450
- B212280446 Advises that util response to questions relevaluation of hydrodynamic loads on control rod drive piping delayed until rnd of Second Quarter 1983, due to delay in receiving BHR owners group input CURTIS.N W. Pennsylvania Power & Light Co. 82/12/22 SCHWENCER. Licensing Branch 2. Ip. 16556-022 24X Fische 50-387,82/12/22,122280446
- 8212280347 Forwards revised "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4 " CURTIS.N W Pennsylvania Power & Light Co 82/12/23 SCHWENCER.A Licansing Branch 2 2pp 16561 043 24X Fiche 50-307.82/12/23, 8212280347
- --8212280354 Revision I to "Mark II Primary Containment Vacuum Relief Valve Test Program Phase 4" WILLIAMSON, 6 0, TESKE, M E., BILANIN, A.J. Continum Dynamics, Inc 82-4 ROI 82/09/30 App. 16561 045 24X Fiche 50-387,82/12/23, 8212280347
- F Security, medical, emergency & fire protection plans
- 8212070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on B20908-1019 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 82/11/2 KENYON, B D Pennsqlvania Power & Light Co 2pp 16/335 318 24 Fiche 50-387, 82/11/23, 8212070151
- --8212070154 Notice of violation from insp on 820908-1019 Safeguards info deleted (ref 10CFR2 790) * Division of Project & Resident Programs 82/11/23 2pp 16335 319 24X Fiche 30-387.82/11/23.8212070151
- --B212070158 IE Insp Repts 50-387/B2-32 & 50-388/B2-09 on B20708-1019 Noncompliance noted tecurity violation re vehicles in protected area & requirements for operable fire protection equipment not met Safeguards info deleted (ref 10CFR2 790) RHOADB.6 G , MCCABE.E C Division of Project & Resident Programs 62/11/03 17pp 16338 321 24% Fiche 50-367.82/11/23,6212070151
- 8P12300407 Releases public version of temporary change notices for emergency plan implementing procedures FELTON, J.M. Division of Rules and Records 82/12/22 Documen Hanagement Branch ip 16613 179 24X Fiche 50-387, 82/12/22, 8212300407
- --8212300408 Forwards public version of temporary change notices for emergency plan implementing procedures including Procedure EP-IP-034 re pharmacy bidg sample station emergency sampling
 * Pennsylvania Power & Light Co 82/12/14 DENIGN, H R NRG No Detailed Affiliation Given 1p 15613 180 24X Fiche 50-387, 82/12/22, 8212300407
- --B212300410 Public version of temporary change notices for emergency plan implementing procedures, including Procedure EP-IP-034 re pharmacy bldg sample station emergency sampling RIZZOU S Pennsylvania Power t Light Co 82/12/13 14pp 14613 181 24X Fiche 50-387,82/12/22,8212300407
- O Inspection reports, IE Bulletins & correspondence
- B20B190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syx list encl DEYCUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 30-000.82/10/28.8208190240

- 8208190345 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Ca of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svr list encl JORDANIE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24x Fiche 50-000.82/11/18.8208190251
- 8212070151 Forwards IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 & notice of violation 8TAR08TECKI.R Division of Project & Resident Programs 82/11/23 KENYON, B D Pensylvania Power & Light Co 2pp 16335 318 24% Fiche 50-387.82/11/23.8212070151
- ~-8212070154 Notice of violation from insp on 820908-1019 Safaguards info deleted (ref 1002R2 790) * Division of Project & Resident Programs 82/11/23 2pp 16335 319 24X Fiche 50-387, 82/11/23, 8212070151
- --B212070158 IE Insp Repts 50-387/82-32 & 50-388/82-05 on 820908-1019 Noncompliance noted security violation re vehicles in protected area & requirements for operable fire protection equipment not met Bařeguards info deleted (ref 10CFR2 790) RHOADB.0 G , MCCANN.J F , CHUNO.J W Division of Project & Resident Programs 82/11/03 17pp 16395 321 24% Fiche 50-387,82/11/23,8212070151
- 8208190256 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " 8vc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- B20B190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDB.L I Division of Fuel Facilities, Materials & Bafeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257
- B208190259 IE Bullstin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYGUNO,R C Director's Offices Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc Idap 16411 317 24X Fichs 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fische 50-000, 82/12/03,8208190261
- 8212290463 Forwards IE Insp Repts 30-387/82-40 & 50-388/82-12 on 821020-1201 & notice of violation STAROSTECKI,R Division of Project & Resident Programs 82/12/14 KENYON,B D Pennsylvania Power & Light Co 2pp 14585 138 24% Fichs 50-387,82/12/14,8212290463
- --8212270468 IE Insp Repts 50-387/82-40 & 50-388/82-12 on 821020-1201 Noncompliance noted failure to keep record of average suppression chamber water temp during RCIC sys testing RMDADS,0 0 . MCCANN.JF . CHUNO.JW Division of Project & Resident Programs 82/12/10 17pp 16585 141 24X Fiche 50-387,82/12/14.8212270463
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list and DEYQUNOR C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191, 24X Fiche 50-000,82/12/16,8208190267.
- B20B19024B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc! URDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14428 273 24X Fiche 50-000, 82/12/20, 820B19024B
- 8 Reportable occurrences. LERs & related correspondence
- 8212280323 Final deficiency rept re nonconformance of Berhtel field welding Initially reported on 821115 Training sessions conducted re welding GC requirements & Procedures FP-Q-24 & FP-W-I will be revised Also reported per Part 21 CURTIS:N W Pennsylvenia Power & Light Ca 82/12/15 HAYNEB,R C Region 1, Office of Director 7pp. 16562 077 24X Fichs 50-988,82/12/15,8212280323

- 8212280346 Interim deficiency rept re design verification of max permissible lengths of wire in low voltage power & control circuits Caused by Bechtel failure to follow procedures final rept by 830415 Also reportable per Part 21 CURTIS.N W Pennsylvania Power & Light Co 82/12/15 HAYNES,R C Region 1. Office of Director 3pp 16561 038 24X Fiche 50-388,82/12/15,8212280346
- 8212280400 Final deficiency rept re failure to meet single failure criterion for medium voltage penetration Initially reported on 82117 Redundant Class IE overcurrent protection will be provided for assemblies Also reported per Part 21 CURTIS.N W Pennsylvania Power & Light Co 82/12/15 HAYNEB.R C Region 1. Office of Director 4pp 16556 138 24X Fiche 50-387.82/12/15.8212280400

X Onsite Storage of Low Level Waste

- 8212270474 Advises that affidavit re 820723 application for byproduct matl license for low level radwaste storage must contain reason for withholding info from public disclosure per 10CFR2 770
 ROUSELL C Advanced Fuel & Spent Fuel Licensing Branch 82/10/27 CURTIS.N W Pennsylvania Power & Light Co 2pp 16605 181 24X Fiche 50-387, 82/10/27.8212270494
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B212010439 Summary of 820831-0903 instrument & control site audit NERSES/V Licensing Branch 3 82/11/18 Licensing Branch 3 5pp 15267 280 24X Fiche 50-389, 82/11/18, 8212010439
- B212090002 Notification of 821130 meeting w/util in Bethesda, MD to discuss status of plant const completion NERSES: V Licensing Branch 3 82/11/22 KNIOHTON, O W Licensing Branch 3 3pp 16384 231 24V Fiche 50-389, 82/11/22, 8212090002
- 82:2100260 Notifies of Engineering Verification Program Review
 Committee 82:215 meeting in Bethesda, MD to discuss
 resolution of remaining discrepancies from design review
 phase & review mat1 to be included in final design rept
 CHRISTIAN, D L Florida Power & Light Co 82/12/07 EISENHUT, D G
 Division of Licensing 2pp 16376 044 24X Fiche 50-389, 82/12/07,
 82:12:00260
- 8P12150129 Forwards resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant.Unit 2 " Attachment updates 821110 submittal which had missing pages UHRIO.R F Florida Power & Light Co 82/12/07. EISENHUT, D 0 Division of Licensing 1p 16423 004 24X Fiche 50-389,82/12/07.
- --8212150134 Resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2" * Southwest Research Institute 82/07/31 234pp 16423 005 24X Fiche 50-387,82/12/07.8212150129
- BP12220153 Summary of S21130 meeting w/util in Bethesda, MD re status of plant const Implementation schedule for fire protection hardware items not approved NRC will suggest submittal date for results of independent design review NRRSES, V Licensing Branch 3 82/12/08 Licensing Branch 3 4pp 16525 382 24% Fiche 50-387,82/12/08,8212220153
- 8312140373 Forwards revision to 821008 ltr re post-accident sampling sys Completion date will be changed from "Prior to Exceeding SX Power" to "Prior to Initial Criticality"

 UHRIO.R E Florida Power & Light Co 82/12/09 EISENHUT, D. Q

 Division of Licensing 2pp 16401 006 24X Fiche 50-389, 82/12/09, 8212140373
- B212140461 Forwards response to request for analysis of limited small feedwater line break u/assumption of single failure & availability of offsite power, to verify that sys pressures will not exceed 120% of design pressure UHRIO.R O Florida Power & Light Co B2/12/09 EISENHUT, D O Division of Licensing 24pp 16404 023 24X Fiche 50-389,82/12/09,82112/044.
- 8212170269 Forwards responses to issues raised in Environ Qualification Branch review of program All safety-related equipment will be qualified per NUREO-0598 by first refueling UHRIG.R E Florida Power & Light Co 82/12/09 EISENHUT, D.G. Division of Licensing 314pp 16456 213. 24X Fiche 50-389, 82/12/09, 8212170269

- B212220200 Provides status of inadequate core cooling instrumentation package per TMI Item [I F 2 Sys wil] be fully operational by mid 1983 Mods to sys will be included in next revision to FSAR UHRIO.R E Floride Power & Light Co 62/12/14 EISENHUT.D G Division of Licensing Ip 16503 048 24% Fiche 50-389,82/12/14,8210202000
- 8212280333 Forwards minutes of 821207 meeting w/util & C-E task force managers in New York.HY re engineering verification program Results of onsite verification phases of program discussed BLODOETT,TH Ebasco Services, Inc (subs of Enserch Corp.) 82/12/22 EISENHUT.D & Division of Licensing 2pp 16560 090 24X Fichs 50-385,82/12/22,8212280333
- B212280405 Forwards minutes of engineering verification program review committee 821215 final meeting in Bethesda, MD Task force disbanded as of 821217 BLODOFTT, TH Ebasco Services, Inc. (subs. of Enserch Corp.) 82/12/22 EIBENHUTD Q Division of Licensing 2pp 16560 040 24X Fiche 80~389,82/12/22,8212280405
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212090211 Forwards IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/11/19 UHRIO.R. E Florida Power & Light Co 2pp 16361 336 24X Fiche 50-389.82/11/19.8212090211
- --B212090213 IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted Major areas inspected preoperational test program implementation & SER confirmatory items
 TAYLOR, P. XRVO. H. JAPE, F. Division of Engineering & Technical Programs B2/11/18 4pp 16361 338 24X Fichs 50-369.82/11/19, 8212090211
- 821221010: Forwards addl info re small feedwater line break analysis Info needed to close confirmatory issue addressed in Bection 15 10 2 of BER UHRIO.R E Florida Power & Light Co 82/12/14 EISENHVT.D O UVISION of Licensing 19pp 16491 061 24X Fiche 50-389.82/12/14, 6212210101
- B212270265 Advises that satisfactory reactor protection may power supply testing has been completed for ultra isolation transformers per SER Suppl 1. Section 7.2.5 Acceptance criteria met

 UHRIGAR E Florida Power & Light Co B2/12/22 EISENHUT, D. G.

 Division of Licensing 2pp 16582 035 24X Fiche 50-387, 82/12/22, 62/12/20265
- F Security, medical, emergency & fire protection plans
- 8212070268 Forwards IE Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/10/24 UHRIO.R E Florida Pawer & Light Co 2pp 16362 307 24X Fiche 50-389, 82/10/26, 8212090268
- --8212070275 IE Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted Major areas inspected fire protection MILLER, W H , CONLON, T E Division of Engineering & Technical Programs 62/10/22 5pp 16362 309 24X Fiche 50-389,822/10/26,8212090268
- BRI217040B Notification of 821214 meeting w/util in Dethesda, MD to review remaining licensing action re fire protection NERSES V Licensing Branch 3 82/12/07, KNIOHTON.0 W Licensing Branch 3 3pp 16478 192 24% Fiche 50-387, 82/12/07, 821217040B
- B212220153 Summary of 821130 meeting w/util in Bethesda. MD re status of plant const implementation schedule for fire protection hardware items not approved NRC will suggest submittal date for results of independent design review NERSES, V. Licensing Branch 3 82/12/08 Licensing Branch 3, 4pp 16525, 352 24% Fiche, 30-389, 82/12/08, 8212220153
- J Insurance & indemnity information
- 8312300294 Forwards Endorsements 1.2 & 3 to NELIA Certificate N-89 & MAELU Certificate M-59
 DUCK-J R. Harsh & McLennan Inc., M & M Nuclear Consultants, Inc. Div 82/12/27 8417MAN-J Assistant Director for State & Licensee Relations 19pp 16594 271 24X Fiche 50-335,82/12/27,8212300294,

M Antitrust correspondence

- 89;2010046 Informs that add1 antitrust advice received from atty general No antitrust hearing necessary on proposed amend to CP per 821025 itr TOALSTON A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 UDALL M K House of Rep , Interior & Insular Affairs ip 16271 345 24x Fiche 50-389,82/11/16.8212010046
- ~-8212010053 Advises that info submitted for antitrust review provides no basis to conclude that participation by util would create situation inconsistent w/antitrust laws No antitrust having necessary

 BAXTER, W.F. Justice, Dept of 82/10/25 CUNNINGHAM, G.H. Office of the Executive Legal Director ip 16271 346 24X

 Fiche 50-389, 82/11/16.8212010046
- 8212010288 Ack receipt of encl assistant atty general 821025 ltr providing add1 antitrust advice; per Atomic Energy Act of 1984. Section 105c No antitrust hearing necessary for proposed CP amend TOALSTON, A L. Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 SIMPSON, A Senate, Environment & Public Works 1p 16271 268 24X Fiche 50-389, 82/11/16, 8212010288
- --8212010270 Comments on proposed CP amend to allow util to become co-buner of facility No antitrust hearing necessary for proposed amend BAXTER, W F Usstice, Dept of, Attorney General's Office 82/10/25 CUNNINGHAH, O H Diffice of the Executive Legal Director 1627/ 267 24X Fiche 50-389, 82/11/16.8212010288
- B212010277 Ack receipt of encl assistant atty general B21025 ltr providing add1 antitrust advice.per Atomic Energy Act of 1994. Section 105: No antitrust hearing necessary for proposed CP amend TOALSTON. A L Antitrust & Economic anelysis Branch (Utility Finance) 82/11/16 OTTINGER, R L House of Rep. Energy & Cormerce 1p 16271 277 24x Fiche 50-389.82/11/16.8212010279
- 8212010272 Forwards assistant atty general 821025 ltr providing addl antitrust advice.per Atomic Energyy Act of 1954. Section 103c TOALSTON.A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/17 URRIGRE Florida Power & Light Co ip 16271 270 24x Fiche 50-389.82/11/19.8212010292

9 Inspection reports, IE Bulletins & correspondence

- 8212070268 Forwards IE Insp Rept 50-387/82-47 on 821004-08 No noncompliance noted DANCE H C Division of Project & Resident Programs 82/10/26 URRIO. R E Florida Power & Light Co 2pp 16362 307 24X Fiche 50-389, 82/10/26, 8212070268
- --8212090275 IE Insp Rept 50-389/82-47 on 821004-08 No noncompliance noted Major areas inspected fire protection MILLER, W H , CONLON, T E Division of Engineering & Technical Programs 82/10/22 Spp 16362 309 24X Fiche 50-389,82/10/26,8212090268
- 8208190240 IE Bulietin 82-03, Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc, 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- 8212090302 Forwards IE Insp Repts 50-335/62-35 & 50-389/62-50 on 821019-22 No noncompliance noted DANCE. H C Division of Project & Resident Programs 82/11/02 UHRIO.R E Florida Power & Light Co 2pp 16365 171 24X Fiche 50-335,82/11/02,8212090302
- --8212090308 IE Imsp Repts 50-335/82-35 & 50-389/82-50 an 821019-22 Np noncompliance noted Major areas inspected IE Circular 81-08, previous insp findings & quality records for foundations LENAHAN, J J , CONLON, T E Division of Engineering & Technical Programs 82/11/01 4pp 16365-173 24X Fiche 50-335,82/11/02,8212090302
- #212090331 Forwards IE Insp Rept 50-389/82-52 on #21019-22, No noncompliance noted DANCE, H. C. Division of Project & Resident Programs #2/11/02 UHR10.R E Florida Power & Light Co 2pp. 16365 091, 24X Fiche 50-389.82/11/02.8212090331

- --8212090336 IE Insp Rept 50-389/82-32 on 821019-22 No nancompliance noted Major areas inspected previous enforcement matters, reactor vessel installation, safety-related components. RCPD piping, safety-related piping & inspector followup items KLEINSOROE, W.P., BLAKE, J. Division of Engineering & Technical Programs 82/11/01 9pp 16365 093 24X Fiche 50-389,82/11/02,8212090331
- 8212090531 Forwards IE Insp Repts 50-385/82-32 & 50-389/82-44 on 820911-1010 No moncompliance noted DANCE.H C Division of Project & Resident Programs 82/11/02 UHRIO.R E. Florida Power & Light Co 2pp 16367 001 P4X Fiche 50-335,82/11/02.8212090531
- --8212090537 IE Insp Repts 50-335/82-32 & 50-389/82-44 on 820911-1010 No noncompliance noted Major areas inspected maint & surveillance observation, operational safety verification. bulletins, circulars, info notices & preoperational testing ELROD, 8 A, \$188, H E, JULIAN, C A Division of Project & Resident Programs 82/11/02, 11pp 16367 003 24X Fiche 50-335,82/11/02, 8212090531
- 82/2090353 Forwards IE Insp Rept 50-389/82-51 on 821018-22 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/11/03 URIO, R E Florida Power & Light Co 2pp 16365 072 24X Fiche 50-389,82/11/03,8212090353
- --B212070360 IE Insp Rept 50-389/82-51 on 821018-22 No noncompliance noted Major areas inspected preoperational test procedure review witnessing & implementation, hot functional test witnessing & inspector followup items
 TAYLOR, P. A. JAPE, F. Division of Engineering & Technical Programs
 82/11/01 4pp 16365 074 24% Fiche 50-389,82/11/03.8212090353
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Notel 801 & Model 802 Thermoluminescent Dosimeters" Syc list enc!
 COSB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of Neu York, Inc 110pp 16372 142 24x Fiche 50-000,82/11/05,8208190245
- 8212070404 Forwards IE Insp Rept 50-389/82-58 on 821025-27 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/11/09 UHRIGR E Floride Power & Light Co 2pp 16365 001 24X Fiche 50-389, 82/11/09, 8212090404
- ---8212090411 IE Insp Rept 50-389/82-58 on 821025-29 No nuncompliance noted Major areas inspected preoperational test procedure review & witnessing thermal expansion tasting performed during initial plant heatup WHITENER H L , JAPE F Division of Engineering & Technical Programs 82/11/08 5pp 14345 003 24% Fiche 50-389,82/11/09,8212090404
- 8212090553 Ack receipt of 821103 1tr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/82-29 & 50-369/82-39

 BANCE.H C Division of Project & Resident Programs 82/11/17

 URRIO.R E Florida Power & Light Co 1p 16367 038 24X

 Fiche 50-335.82/11/17,8212090553
- --B212090559 Responds to NRC 821005 ltr re violations noted in It Insp Repts 50-335/82-29 & 50-389/82-39 Corrective actions clearance orders corrected & personnel reinstructed re need to designate "locked open" or "locked closed" on orders UHRIG.R E Florida Fower & Light Co 82/11/03 O'REILLY, J P Region 2. Office of Director App 16367 039 24X Fiche 50-335, 82/11/17, 8212090553
- --8212090561 Forwards IE Insp Repts 50-335/82-29 & 50-389/82-29 on 820811-0910 & notice of violation DAKCE,H C. Division of Project & Resident Programs 82/10/08 UHRIG.R E Florida Power & Light Co 2pp 16367 041 24X Fichs 50-335,82/11/7,8212090553
- --B212090564 IE Insp Repts 50-335/82-29 & 50-389/82-39 on 820811-0910 Noncompliance noted failure to implement procedure for locking safety-related valves in required position ELROD.8 A: BIBB.H E: JULIAN.C.A Division of Project & Resident Programs 82/10/04. 13pp 16367 044. 24X Fiche 50-335.82/11/17,8212090553
- 820B190251 IE Info Notice 82-44, "Clarification of Emergancy Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quelity Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 1641; 199 24X Fiche-50-000, 82/11/18, 8208190281

- 8212090211 Forwards IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/11/19 UHRIG, R E Florida Power & Light Co 2pp 14341 334 24X Fiche 50-389,82/11/19,8212090211
- --8212090213 IE Insp Rept 50-389/82-54 on 821101-05 No noncompliance noted Major areas inspected preoperational test program implementation & SER confirmatory items
 TAYLOR.P., KRUG.H., JAPE.F. Division of Engineering & Technical Programs 82/11/18 4pp 16361 338 24X Fiche 50-389,82/11/19,821209021
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl DEVOUND, R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 14397 028 24X Fiche 50-000,82/11/30,8208190257
- BPOBI90259 IE Bulletin 82-04, "Deficiencies in Frimary Containment Electrical Penetration Assemblies " Svc list encl DEYQUMO.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 183pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 82:12:50:129 Forwards resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2 " Attachment updates 82:11:0 submittal which had missing pages UHRIO, R E Florida Power & Light Co 82:12/07 EISENHUT, D Q Division of Licensing ip 16423 004 24X Fiche 50-389, 82:12/07, 82:12:150:129
- --B212150134 Resubmittal of "Mechanized Preservice Exam of Selected Components of St Lucie Plant, Unit 2 " * Southwest Research Institute 82/07/31 234pp 16423 005 24x Fiche 50-389,82/12/07,8212150129
- B208190267 IE Info Notice B2-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl
 DEYQUNO.R C Director's Office. Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fichs 50-000, 82/12/16, 8208190267
- 8:'08:70268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JDRDAH,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628-273 24X Fithe 50-000.82/12/20.8208170268
- R Periodic operating reports & related correspondence
- BP12170243 Forwards joint Ebasco & C-E Task Force engineering verification program status summary for 2-wk period, 821122-1204
 BLODGETT,T H Ebasco Services, Inc (subs of Enserch Corp)
 82/12/09 E1SENHUT,O O Division of Licensing 5pp 14461:292
 24X Fiche 50-389,82/12/09,8212170243
- BP12280187 Forwards Joint Ebasco & C-E task force engineering verification program weekly status summary for 821213-17. BLODGETT.T H Ebasco Services, Inc (subs of Enserch Corp). 82/12/21 EISENHUT.D & Division of Licensing 5pp 14562:256 24X Fiche 50-389,82/12/21,8212280187
- 9 Reportable occurrences, LERs & related correspondence
- B212030216 Interim deficiency rept re fan belts on diesel generators 2A & 2R Initially reported on B20210 AddI mods needed to fully correct problem Final rept will be submitted by 330120 URRIGAR E Florida Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director 1p 16306 295 24X Fiche 50-389, 82/11/24, 8212030216

- 8212070215 Interim deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals Initially reported on 820430 Review continuing Next rept will be submitted by 830115
 UHRIGAR E Florida Power & Light Co 82/11/29 O'REILLY, J P Region 2. Defice of Director | p 16329 359 24X Fiche 50-389, 82/11/29, 8212070215
- BE12090200 Suppl to Bi0724 final deficiency rept re local centrol switches supplied by Gould Rundel Re-evaluation of switch proturberance indicated deficiency only in 88-6 switches UHRIG:R E Florida Power & Light Co 82/12/01 D'REILLY, J P Region 2. Office of Director ip 16362 360 24X Fiche 50-389, 82/12/01.0212090200
- 8212150074 Final Deficiency Rept 82-021 re incorrect reactor protective sys low flow input signals Initially reported on 821013 Wiring diagram & polarity of input signal cables corrected Deficiency not reportable per 10CFR50 55(e) UHRIGAR E Florida Power & Light Co 82/12/09 0'REILLY, J. P. Region 2. Office of Director 2pp 16431 013 24X Fiche 50-389, 82/12/09, 8212150074
- 6212150098 Final Deficiency Rept 82-024 re defective masonry walls Initially reported on 821110 During insp of as-built masonry walls, 31 contained less than required amount of rebar due to design misinterpretation Walls will be modified UHRIG.R E Florida Power & Light Co 82/12/09 0'REILLY, J P Region 2. Office of Director 2pp 16425 242 24X Fiche 50-389, 82/12/09, 8212150098
- 8212210348 Interim deficiency rept re insulation on Conax ring tongue connectors Initially reported on 821110 Investigation continuing Final rept will be submitted by 82128 URRIGARE Florida Power & Light Co 82/12/10 0'REILLY.J P Region 2. Office of Director 1p 16496 362 24X Fiche 50-387.82/12/10,8212210348
- 8212210354 Interim deficiency rept re micro-switch PTK selector switches Initially reported on 821110 Review continuing final rept will be submitted by 830110 URRIGHE Florida Power & Light Co 82/12/10 0'REILLY, J P Region 2. Office of Director 1p 16489.175 24X Fiche 50-389,82/12/10.8212210354
- 8212300252 Interim deficiency rept re lack of documentation on Class I & II bolts & nuts Initially reported on 821013 Final rept will be submitted by 830126 UHRIGAR E Florida Power & Light Co 82/12/20 O'REILLY, J P Region 2. Office of Director ip 16595 234 24X Fiche 50-389, 82/12/20, 8212300252
- U Congressional/Executive Correspondence
- B212010046 Informs that addl antitrust advice received from atty general No antitrust hearing necessary on proposed amend to GP per 821025 itr
 TOALSTON.A L Antitrust & Economic analysis Branch (Utility Finance) 82/11/16 UDALL.M K House of Rep. Interior & Insular Affairs ip 16271 345 24% Fiche 50-389,82/11/16,8212010046
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8212010117 Notifies that no requests received from public for hearing on extension of const completion dates
 KENYON,T J Licensing Branch 4 82/11/19 NOVAK,T M Assistant Director for Licensing ip 16290 230 24X Fiche 50-390,82/11/19,8212010117
- --8212010122 Notifies of extention of const completion dates to 840301 & 850801 for Units 1 & 2, respectively Order & safety evaluation encl ADENSAM, E 0 Licensing Branch 4. 82/11/19 PARRIS, H 0 Tennessee Valley Authority 1p 16270 231 24X Fiche 50-370, 82/11/19, 8212010117
- --8212010126 Order extending const completion dates for Units 1 & 2 to 840301 & 850801.respectively.
 EISENHUT, D 0 Division of Licensing. 82/11/19 Tennessee Valley Authority 2pp 16270 232 24X Fiche.50-370.82/11/19, 82(2010117
- --8212010127 Safety evaluation supporting request for extension of CPPR-91 & CPPR-92 to 840301 & 850801; respectively Extension acceptable
 * Division of Licensing 82/11/17 5pp 16290 234 24X Fiche 30-370, 82/11/19, 82/2010117

- 8212060081 Submits revised milestone schedules of prompt notification sys for design.const 2 field testing finish & inservice testing State of TN assumes sys on 830701 MILLS.L H Tennessee Valley Authority 82/11/30 ADENSAM, E Licensing Branch 4 ip 16316 107 24X Fiche 50~390,82/11/30, 8212040081
- B212070291 Responds to action items resulting from NRC B20922 geotechnical audit of plant Util action complete w/exception of analysis of actial attesses on buried pape which will be Provided by 830305
 MILLS.L H Tennessee Valley Authority 82/11/30 ADENSAM, E Licensing Branch 4 44pp 16337 020 24% Fichs 50-390,82/11/30. 82:2070291
- 8212070072 Requests add1 info re 820514 submittal on Branch Technical Position CSB 4-4. "Containment Purging During Normal Plant Operation " Info needed by 830115 ADENSAM, 6 0 Licensing Branch 4 82/12/01 PARRIS, H 0 Tennesses Valley Authority 3pp 16356 274 24X Fiche 50-370,82/12/01.
- 8212070186 Forwards add1 info to resolve concerns listed in NRC 820723

 1tr re Apr 1982 seismic qualification review team audit

 MILLS.L M Tennessee Valley Authority 82/12/01 ADENSAM.E

 Licensing Branch 4 127pp 16338 131 24X Fishe 50-390.82/12/01.

 8212070186
- 8212270287 Forwards "Liquefaction Evaluation of Essential Raw Cooling Hater Pipeline Route Task 9." per LM Mills 821116 ltr KAMKER.D S Tennessee Valley Authority 82/12/09 ADENBAM.E Licensing Branch 4 ip 16565 145 24X Fiche 50-390,82/12/09, 8212270287
- --8212270290 "Liquefaction Evaluation of Essential Raw Cooling Water Pipeline Route Task 9 " M/seven oversize figures Aperture cards are available in PDR
 * Woodward-Clyde Consultants, Inc. 82/11/30 79pp 16565-146-24X Fiche 50-390,82/12/09,8212270287
- 8212270262 Provides info to facilitate NRC use of computer card deck containing time histories of four artificial earthquakes used for facility MILLS.L H Tennessee Valley Authority 82/12/20 ADENSAN.E Licensing Branch 4 2pp 16530 330 24% Fiche 50-390.82/12/20, 6212270262
- 8212270355 Forwards status rept on proposed mods to model D steam generators to reduce flow-induced vibration & tube wear problems Rept specifying final resolution of issue will be provided in Jan 1983
 MILLS.L M Tennessee Valley Authority 62/12/20 ADENSAM.E Licensing Branch 4 2pp 16530 044 24% Fichs 50-390,82/12/20,8212270355
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8212060070 Forwards response to SER open Item 13 re quality classification of diesel generator auxiliary sys piping & components

 HILLS,L M Tennessee Valley Authority 82/11/27 APENSAM.E

 Licensing Branch 4 3pp 16314 296 24X Fiche 50-390.82/11/29.

 B212060070
- 8212210451 Forwards response to 820419 request for add1 info. Guestions 40 127 & 40 129 re diesel generators Info to resolve SER Open Item 14 re diesel generator operation w/o secondary coolant & expension tank location also encl MILLS.L.M. Tennessee Valley Authority 82/12/14 ADENSAM.E. Licensing Branch 4 lipp 16489 181 24X Fiche 50-390,82/12/14.8212210451.
- F Security, medical, emergency & fire protection plans
- 8212100046 Responds to R Heron 811202 telcon request re emergency operations facility (EOF) Response to Ceneric Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided KAMMER.D.S. Tennessee Valley Authority 82/12/06 APENSAM, E. Licensing Branch 4 1p. 16379 071 24X Fiche 50-000, 82/12/06. Licensing Branch 4 8212100046
- J Insurance & indemnity information
- 8212020269 Bubmits info re const & warehouse values located offsite as Page 100 to the const & warehouse values located offsit result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 DUCK, JR Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. 82/11/18 HAINES, H L. American Nuclear Insurers ip 16288; 24X Fiche 50-000,82/11/18.82(2020269

- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IF Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel, Recirculation Sys Piping et BNR Plants "Svc list encl DEYGUND. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000. 82/10/28, 8209190240
- 8212090400 Forwards IE Insp Repts 50-390/82-36 & 50-391/82-33 on PERIORATE IN No noncompliance noted VERRELLI, DN Division of Project & Resident Programs 82/11// PARRIS.H O Tennesses Valley Authority 2pp 16364 256 24% Fiche 50-390, 82/11/01, 8212090400 82/11/01
- -8212090407 IE Inap Repts 50-390/82-36 & 50-391/82-33 on 821012-15 No noncompliance noted Major areas inspected electrical cables & terminations, licensee identified items & independent insp GIBBGKS, T D , CONLOW T E Division of Engineering & Technical Programs 82/10/29 3pp 16364 258 24% Fiche 50-390,82/11/01,8212090400
- 8P12090497 Forwards IE Insp Repts 50-390/82-37 & 50-391/82-34 on P20723-1019 No noncompliance noted
 VERRELLI, D M Division of Project & Resident Programs 82/11/03
 PARRIS, H O Tennessee Valley Authority 2pp 16365 335 24X
 Fiche 5D-390.82/11/03.8212090497
- --8212090504 IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted Major areas inspected licensee action on previous insp findings, independent insp effort, followup on licensee identified items & worker allegations HEATHERLY, T L , GUICK, D R Division of Project & Resident Programs 82/11/03 7pp 16365 337 24X Fiche 50-390,82/11/03,8212090497
- 8208190245 IE 1nfo Notice 82-42, "Defects Observed in Panasonic Model GOI & Model GO2 Thermoluminescent Dosimeters" Svc list COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 820B190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411

Fiche 50-000, 82/11/18, 8208190251

- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks" Bvc list encl
 DEYDUNO, RC Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8212090334 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-390/81-26 & 50-391/81-24 VERRELLI,D M Division of Project & Resident Programs 82/11/29 PARRIS.H Q Tennessee Valley Authority ip 16365 089 24% Fiche 50-390,82/11/29,8212090334
- --B212070347 Submits supplemental response to NRC 8112R3 ltr reviolations noted in IE Insp.Repts 50-390/81-26 & 50-391/81-24 Corrective actions assessment of cleanliness of HVAC sys should be completed by 830201 MILLS.L.M. Tennessee Valley Authority 82/11/18 0'REILLY,J P. Region 2. Office of Director ip 16365 090 24X Fiche 50-390,82/11/29,8212090334
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactivo Matl " Svc list encl CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fichs 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24: Fiche 50-000,82/12/03,8208190261

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oss Monitoring " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000, 82/12/16, 8208190267
- B20B19026B IE Info Notics 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24) Fiche 50-000, 82/12/20, 920B19026B
- R Periodic operating reports & related correspondence
- 8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982
 MILLS.L M Tennessee Valley Authority 82/11/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16304 210
 24X Fiche 50-000, 82/11/30, 8212030071
- S Reportable occurrences, LERs & related correspondence
- 82:2020298 First combined interim deficiency rept re nonconformance in alternately analyzed piping program Util proceeding w/1007 reverification of alternate analyses Next rept will be submitted by 830426 MILLS.t. M. Tennessee Valley Authority 82/11/24 O'REILLY, J.P. Region 2. Office of Director 3pp 16277-354 24X Fishe 50-390.82/11/24.8212020298
- 8212020368 Final deficiency rept re unterminated cables associated w/control room isolation function of control bldg ventilation sys Initially reported on 820901 Cables terminated & inspected per as-constructed drawings MfLLS.L M Tennesses Valley Authority 82/11/24 0'REILLY, J P Ragion 2, Offices of Director 3pp 16278 142 24X Fiche 50-390, 82/11/24, 8212020368
- 8212030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys initially reported on 821026 Proposed disposition to replace Star Model GE sprinkler heads under review MiLLS, L M Tennesses Valley Authority 82/11/29 0'REILLY, J P Ragion 2. Office of Director 2pp 16304 212 24X Fiche 50-000, 82/11/29, 8212030001
- 8212070058 Second interim deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Sampling program still being conducted Next rept repected by 830223
 MILLS.I. M Tennessee Valley Authority 82/11/29 0'REILLY, J P Region 2. Office of Director ip 16327 335 24X
 Fiche 50-390.82/11/29.8212070058
- 8212070142 Sixth interim deficiency rept re diesel generator room enhaust fan mod Initially reported on 810831 Design mod in progress to provide structural stiffeners to reduce lateral vibration of fans Next rept will be submitted by 830225 MILLS.L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2. Office of Director ip 16327 073 24X Fiche 50-390, 82/11/29, 8212070142
- 8P12070267 Final deficiency rept re unauthorized conduit & cable rework Initially reported on 821015 Procedure WBNP-GCI-1 07 revised to clarify requirements when immediate documentation required for rework MELS,L M Tennesses Valley Authority 82/11/29 0'REILLY, J P Region 2. Office of Director 2pp 16039 071 24X Ficho 50-370,82/11/29,8212070267
- 8712070140 Third interim deficiency rept re incorrect seismic displacements & response spectra use Initially reported on 920430 Problems reanalyzed to determine final effect on piping & nozzle No other displacement errors occurred MILLS.L M Tennessee Valley Authority 82/11/30 0/REILLY.J P Region 2: Office of Director 2pp 16359 246 24% Fiche 50-390.82/11/30.8212090160
- 82:2070165 First interim deficiency rept re control of non-GA hex nuts laitially reported on 82:1021 Unqualified hex nuts used to install some hangers on safety-related upper head injection sys Investigation continuing MILLS.L M Tennessee Valley Authority 82/11/30 O'REILLY, J P. Region 2. Office of Director 2pp 16359 244 24X Fiche. 50-390, 82/11/30, 82:2090165
- B212090170 First interim deficiency rept re curtain-type fire dampers failing to close against normal operating air flow Initially reported on B21025 Std Spec MEB-SS-10 3 revised to include stainless negator closer springs MILLS.L M Tennesses Valley Authority 62/11/30 O'REILLY.J P. Region 2. Office of Director 2pp 16359 232 24X Fiche 50-390.62/11/30.8212070170

- 8212090541 Fourth interim rept re containment spray miniflow valve design error Initially reported on 820305 Possible breakdown in Westinghouse GA diagram being reviewed Also reportable per Part 21 Next rept expected by 830502 MILLS.L M Tennessee Valley Authority 82/12/01 0'REILLY, J R Region 2. Office of Director 2pp 16366 338 24X Fiche 50-390, 82/12/01,8212090541
- 8212070054 Fourth interim deficiency rept re excessive movement of containment penetration beliews Initially reported on B11204 Problem being reanalyzed interprotating correct operating temps Next rept to be submitted on B30520 MILLB.L M Tennessee Valley Authority 82/12/02 0'REILLY, J P Region 2. Office of Director 2pp 16357 346 24X Fiche 30-390, 82/12/02, 8212070054
- 8212090150 Tenth interim deficiency rept re improper design of steel containment penetration assemblies Initially reported on B01217 All affected piping evaluated & reanalyzed Piping can withstand extra pressures Next rept expected by 830318 MILLS.L M Tennessee Valley Authority 82/12/03 0'REILLY, J P Region 2. Office of Director 2 pp 16359 119 24%, Fiche 50-370, 82/12/03, 8212090150
- 8212100270 Fifth interim deficiency rept re lact of Div of Engineering design sys to ensure QA procedures issued before work begins initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects MILLS, L M Tennessee Valley Authority 82/12/06 0'REILLY, J P. Region 2. Office of Director ip 16377 136 24% Fiche 50-000, 82/12/06, 8212100270
- 8212140087 Fifth interim deficiency rept re incorrect thermal range analysis Initially reported on 821022 Upon closure of Engineering Change Notice 3210, support mod will be evaluated Next rept expected by 830527 MILLS.L M Tennessee Valley Authority 82/12/05 O'REILLY, J P Region 2, Office of Director ip 16408 255 24% Fiche 50-390, 82/12/06, 8212140087
- 8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 821109 Valves will be modified on site Next rept due 830607 Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 82/12/07 O'REILLY, J P Region 2. Office of Director 3pp 16408 166 24X Fiche 50-000, 82/12/07, 8212140141
- BP12140164 Second interim deficiency rept ra heat loss from Power Sys diesels Inftially reported on 820729 Evaluation of heat load test results underway to determine needed changes Next rept due by 830322 Also reportable per Part 21 MILLS.L.M. Tennessee Valley Authority 82/12/07 0/REILLY, J.P. Region 2. Office of Director 2pp 16409 344 24X Fiche 50-390.82/12/07,8212140164
- B212140376 Final deficiency rept re anchor soits not installed in accordance w/spacing space. Initially reported on B10331 Condition could not have adversely affected safe operation of plant Condition not reportable under 10CFR50 55(e) HILLB.L M Tennessee Valley Authority B2/12/07 0'REILLY, J P Region 2. Office of Director 2pp 16403 157 24X Fiche 50-390, B2/12/07, B212140376
- 8:12150136 Becond interim deficiency rept re inadequate QA program for masonry block work Initially reported on 820902 Areas where morter did not meet min compressive strength requirements acceptable Next rept due by 830825 MILLB.L M Tannessee Valley Authority 82/12/09 0'REILLY, J P Region 2. Office of Director 2pp 16425 238 24X Fiche 50-390, 82/12/09, 8212150136
- 8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No add1 info available until action team 821215 rept Next rept will be submitted by 830420 MILLS.L M Tennessee Valley Authority 82/12/13 O'REILLY. J P Region 2. Office of Director 1p 16473 362 24X Fiche 50-000, 82/12/13, 8212200001
- B212200017 Fifth interim deficiency rept re design review process interface coordination artivity Initially reported on B10717 Corrective action to be based on action team rept to be issued approx B21215 Next rept expected by B30422 MILLS, L.M. Tennessee Valley Authority 82/12/13 O'REILLY, J.P. Ragion 2, Office of Director 2pp 16473 085 24X Fiche 50-000, B2/12/13, 8212200017.
- 8212210356 Fourth interim deficiency rept re design of HVAC penetrations in containment Initially reported on 811224 Penetrations determined to be overstressed will be supported by hangers or stiffened Next rept expected by 830325 MILLS,L M Tennessez Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director ip 16495 171 24X Fithe. 50-390, 82/12/13, 8212210356

- 8212210445 Second final deficiency rept re improper weld attachment of shear lugs initially reported on 801030 New hanger installation procedure implemented Remaining corrective action on welds will be completed by 830131 MICLS.L.M. Tennessee Valley Authority 82/12/13 O'REILLY.J.P. Region 2. Diffice of Director 3pp 16489 197 24X Fiche 50-390.82/12/13.8212210445
- 8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates initially reported on 820412 Multiple supports attached to plates u/o design review of plate capacity Preliminary const spec issued Next rept by 830404 MILLSit M Tennesses Valley Authority 82/12/14 D'REILLY, J P Region 2. Office of Director 2pp 16485 260 24X Fiche 50-000.82/12/14.8212210026
- B212210217 Second interim deficiency rept re incorrect supports in analysis of 3-inch chemical & vol control sys line intitally reported on 820505 [n-line isolation valves reanalyzed Next rept expected by 830520 MILLS.L.M. Tennessee Valley Authority B2/12/15 O'REILLY, J.P. Region 2. Office of Director 2pp 16485 014 24X Fiche 50-170.82/12/15.8212210217
- 8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Vollow Creek & Hartsville deferred Nort rept will be sent by 830322 MILLS.L M Tennessee Valley Authority 82/12/15 D'REILLY, J P Region 2. Office of Director 2pp 16489 168 24X Fiche 50-000.82/12/15,8212210431
- 8212220485 Second interim deficiency rept re solid state protection systest procedures Initally reported on 820831 Mestinghouse proposal for procedural change rejected Util will implement own change Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/12/16 D'REILLY. J P Region 2. Office of Director 3pp 14504 015 24X Fiche 50-390.82/12/16.8212220485
- BR12220426 Seventh interim deficiency rept re rerouting of high pressure fire protection piping Initially reported on Bio(30 Intressing pipe head diameter to next largest size would eliminate deficiency Next rept due by B30622 HILLS, L N Tennossee Valley Authority B2/12/17 O'REILLY, J P Region 2, Office of Director 2pp 16503 287 24X Fiche 50-370.82/12/17, B212220426
- 8212280355 Second interim deficiency rept re unistrut clamps loaded in more than one direction for seismic supports Initially reported on 820708 Investigation continuing Next rept will be provided by 830211
 MILLS.L M Tonnessee Valley Authority 82/12/21 O'REILLY, J P Region 2. Office of Director 2pp 16360 100 24X
 Fiche 50-390,82/12/21.8212280355

DOCKET 50-391 MATTE BAR NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8212010117 Notifies that no requests received from public for hearing on extension of sonst completion dates KENYON-T J Licensing Branch 4 82/11/19 NOVAK,T M Assistant Director for Licensing ip 16290 230 24% Fiche 50-390,82/11/19,8212010117
- --8212010122 Notifies of extention of const completion dates to 840301 & 830801 for Units 1 & 2 respectively Order & safety evaluation encl ADENSAM, E G Licensing Branch 4 82/11/19 PARRIS, H G Tennessee Valley Authority 1p 16290 231 24X Fiche 50-390, 82/11/19, 8212010117
- --8212010126 Order extending const completion dates for Units 1 % 2 to 840301 & 850801: respectively EISENHUT. D 0 Division of Licensing 82/11/19 Tennessee Valley Authority 2pp 16290 232 24X Fiche 50-390, 82/11/19, 8212010117
- --8212010129 Bafety evaluation supporting request for extension of CPPR-91 & CPPR-92 to 840301 & 850801.respectively Extension acceptable a Division of Licensing 82/11/19 5pp 16270 234 24X Fiche 50-370,82/11/19.8212010117
- 8212060081 Submits revised milestone schedules of prompt notification sys for design const & field testing finish & inservice testing State of TN assumes sys on 830701 MILLS.L.M. Tennessee Valley Authority 82/11/30 ADENSAM.E. Licensing Branch 4 ip 16316 107 24X Fiche.50-390.82/11/30.8212060081

- 8212070291 Responds to action items resulting from NRC 820922 geotechnical audit of plant Util action complete w/exception of analysis of axial stresses on buried page which will be provided by 830305 MILLS.L M Tennessee Valley Authority 82/11/30 ADENSAM.E Licensing Branch 4 44pp 16339 020 24X Fiche 50-390.82/11/30.8212070291
- BP12070072 Requests add1 info re 820514 submittal on Branch Technical Position CSB 6-4. "Containment Purging During Normal Plant Operation "Info needed by 830115 ADENSAM.E O Licensing Branch 4 82/12/01 PARRIS.H G Tennessee Valley Authority 3pp 16356 274 24% Fiche 50-390,82/12/01. B212070072
- 8212070186 Forwards add1 info to resolve concerns listed in NRC 820923

 1tr re Apr 1982 seismic qualification review team audit

 MILLS: L M Tennessee Valley Authority 82/12/01 ADENSAM, E

 Licepsing Branch 4 127pp 16335 131 24% Fiche 50-390, 82/12/01,
 8212070186
- B212270287 Forwards "Liquefaction Evaluation of Essential Raw Cooling Mater Pipeline Route Task 9." per LM Mills 821116 ltr KAMMER.D 8 Tennessee Valley Authority 82/12/09 ADENSAM, E Licensing Branch 4 lp 16565 145 24X Fiche 50-390, 82/12/09. 8212270287
- ~-8212270290 "Liquefaction Evaluation of Essential Raw Cooling Water Pipeline Route Task 9 " W/seven oversize figures Aperture cards are available in PDR * Woodward -Clyde Consultants, Inc 82/11/30 79pp 16965 146 24% Fiche 50-590,82/12/09.8212270287
- 8212270R62 Provides info to facilitate NRC use of computer card dect containing time histories of four artificial earthquakes used for facility MILLS.I. M. Tennesses Valley Authority 62/12/20 ADENSAM.E Licensing Branch 4 2pp 16530 33C 24X Fiche 50-390,82/12/20, 8212270262
- 8212270355 Forwards status rept on proposed mods to model D steam generators to reduce flow-induced vibration & tube wear problems Rept specifying final resolution of issue will be provided in Jan 1983 MILLGL H Tennessee Valley Authority 82/12/20 ADENSAM. E Licensing Branch 4 2pp 16530 044 24X Fiche 50-390, 82/12/20, 2012/2020.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8212060070 Forwards response to SER open Item 13 re quality classification of diesel generator auxiliary sys piping & components
 MILLS.L. M. Tennessee Valley Authority 62/11/29 ADENSAM.E
 Licensing Branch 4 3pp 16314 296 24X Fiche 50-390, 82/11/29.
 8212060070
- 8212210451 Forwards response to 820419 request for add1 info.Questions
 40 127 % 40 128 re diesel generators Info to resolve SER
 Open Item 14 re diesel generator operation w/o secondary
 coolant & expansion tank location also encl
 MILLS.L M Tennessee Valley Authority 82/12/14 ADENSAM, E
 Licensing Branch 4 11pp 16489 181 24% Fishe 50-390, 82/12/14,
 8212210451

1

- F Security, medical, emergency & fire protection plans
- 6212100046 Responds to R Heran 611202 telcon request re emergency operations facility (£0F) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided KAMKER. D S. Tennessee Valley Authority 82/12/06 ADENSAM. E Licensing Branch 4 1p 16379 071 24X Fiche 50-000. 82/12/06. 8212100046
- J Insurance & indemnity information
- 8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 BUCK.J R Marsh & McLennan.Inc / M & M Nuclear Consultants.Inc Div 82/11/18 HAINES.H.L American Nuclear Insurers ip 16288 356

 24X Ficher 50-000, 82/11/18, 8212020269

@ Inspection reports, IE Bulletins & correspondence

- 8208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl
- Wall, Large-Diameter, Stainless Steel, Retirculation Sys Piping at BMR Plants " Syt list encl
 DEYGUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Int 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- BR12090400 Forwards IE Insp Repts 50-390/82-36 & 50-391/82-33 on
- RIZO00400 Forwards IE insp Repts 30-390/82-36 & 50-391/82-; BZZ(012-15 No noncompliance noted VERRELLID M Division of Project & Resident Programs (PARRIS, M G Tennessee Valley Authority 2pp 16364 256 Fichs 50-390, BZ/11/01, BZ12090400 62/11/01
- --8212070407 IE Insp Repts 50-390/82-34 & 50-391/82-33 on 821012-15 No ELECTIVATOR IE Insp Repts 50-390/82-34 & 50-391/82-33 on 821012-15 No noncompliance noted Major areas inspected electrical cables & terminations.licensee identified items & independent insp GIBBONS, T.D., CONLON, T.E. Division of Engineering & Technical Programs 62/10/29 3pp 14364-258 24X Fiche 50-390,82/11/01,8212090400
- 8212090497 Forwards IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/11 PARTIS.H O Tennessee Valley Authority 2pp 16365 335 24 Fiche 50-390, 62/11/03, 8212090497 82/11/03
- --B212090504 IE Insp Repts 50-390/82-37 & 50-391/82-34 on 820923-1019 No raduration is inspiring 50-340/82-37 and 30-341/82-34 bn 82028-31019 in oncompliance noted Major areas inspected licensee action on previous insp findings, independent inspected ficense action on licensee dentified items & worker allegations

 HEATHERLY, T. L., QUICK, D. R. Division of Project & Rusident

 Programs 82/11/03 7pp 16365-337 24X Fiche 50-370.82/11/03, 8212090497
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list
- GOBD.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245 82/11/05
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18,8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list and DEVOUND, R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc (27pp 1641
- SP12090334 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 VERRELLI.D M Division of Project & Resident Programs 82/11/29 PARRIS,H O Tennessee Valley Authority ip 16365 089 24X Fiche 50-390,82/11/29,8212090334
- --B212090347 Bubmits supplemental response to NRC B11223 ltr reviolations noted in IE Insp Repts 50-390/81-26 & 50-391/81-24 Corrective actions assessment of cleanliness of HVAC sys should be completed by 830201 MILLS.L M Tennessee Valley Authority 82/11/18 0'REILLY, J P Region 2. Office of Director ip 16365 090 24X Fiche 50-390.82/11/29.8212090334
- B208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 354pp 14387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list entl DEYQUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche, 50-000, 82/12/03, 8208170259
- 6208190261 IE Info Notice 82-49, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAH,E, L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24: Fiche 50-000, 82/12/03, 8208190261

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! DEYOUNG: R C Director's Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8212210360 Forwards "AGME Section XI Preservice Insp Program Technical Instruction TI-508: Revision 3 MILLS.L M Tennessee Valley Authority 82/12/16 ADENBAM.E Licensing Branch 4 1p 16495 172 24X Fiche 50-391,82/12/16,
- -8212210363 Surveillance Enstruction TI-508, "ASME Section XI Preservice Insp Program." Revision 3 DETULLIG. D. SWALLOWS. J H Tennessee Velley Authority 126pp 16495 173 24X Fiche 50-391.82/12/16.8212210360
- BP08190268 IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- R Periodic operating reports & related correspondence
- 8212030071 Forwards central emergency control ctr meteorological data availability statistics for Apr-Sept 1982 MILLS, L M Tennessee Valley Authority 82/11/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16304 210 24X Fiche 50-000.82/11/30,8212030071
- S Reportable occurrences, LERs & related correspondence
- 82:12020278 First combined interim deficiency rept re nonconformance in alternately analyzed piping program Util proceeding w/100% reverification of alternate analyses Next rept will be revenirication of alternate analyses Next rept will be submitted by 830426
 MILLS,L M Tennessee Valley Authority 82/11/24 O'REILLY, J P Region 2. Office of Director 3pp 16277 354 24X
 Fiche 50-390.82/11/24.8212020278
- 8212020348 Final deficiency rept re unterminated cables associated w/control room isolation function of control bldg ventilation sys Initially reported on 820901 Cables ventilated & inspected per as-constructed drawings NILLS.L M Tennessee Valley Authority 82/11/24 (Region 2. Office of Director 3pp 16278 142 24X Fiche 30-390, 82/11/24, 8212020368 O'REILLY, J P
- BP12030001 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on B21026 Proposed disposition to replace Star Kodel GE sprinkler heads under review MILLS.L M Tennessee Valley Authority 82/11/29 0'REILLY, J P Region 2. Office of Director 2pp 16304 212 24X Fiche 50-000, B2/11/29, B212030001
- 8212070058 Second interim deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Sampling program still being conducted Next rept expected by 830223
 NILLS, L. M. Tennessee Valley Authority 82/11/29 0'REILLY, J.P. expected by 830223 MILLS,L M Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2, Office of Director 1p 16327 355 24X Fiche 50-370, 82/11/29, 8212070058
- 8212070142 Bixth interim deficiency rept re diesel generator room exhaust fan mod Initially reported on 810831. Design mod in progress to provide structural stiffeners to reduce lateral vibration of fans Next rept will be submitted by 830225 MILLS, L. M. Tennessee Valley Authority 82/11/29 0'REILLY, J. Region 2. Office of Director 19 16327 073 24X Fiche 50-390, 82/11/29, 8212070142 27 O'REILLY, J P 24X
- B212090160 Third interim deficiency rept re incorrect seismic displacements & response spectra use Initially reported on 820430 Problems reanalyzed to determine final effect on piping & nozzle No other displacement errors occurred MILLB.L M Tennessee Valley Authority 82/11/30 O'REILLY, J P Region 2, Office of Director 2pp 16359 246 24X Fiche 50-390, 82/11/30, 8212090160
- 8212090170 First interim deficiency rept re curtain-type fire dampers failing to close against normal operating air flow Initially reported on 821025 Std Spec MEB-S5-10 3 revised to include reported on S21020 Sta aper Mean-San-10 3 revises to stainless negator closer springs MILLS.L M Tennessee Valley Authority 82/11/30 Region 2. Office of Director 2pp 16359 232 2: Fiche 50-390. 82/11/30.8212090170 D'REILLY, J P

- 82:2070541 Fourth interim rept re containment spray miniflow velve design error initially reported on 820305 Possible breakdown in Westinghouse GA diagram being reviewed Also reportable per Part 21 Next rept expected by 830502 HILLS, L M Tennessee Valley Authority 82/12/01 O'REILLY, J R Region 2. Office of Director 2pp 16366 338 24% Fiche 50-390.82/12/01,8212070541
- 8212070054 Fourth interim deficiency rept re excessive movement of containment penetration bellows Initially reported on Bi1204 Problem being reamalyzed incorporating correct operating tengs Next rept to be submitted on 830520 MILG.L M Tennessee Valley Authority 82/12/02 O'REILLY.J P Region 2. 0ffice of Director 2pp 16397 346 24% Fiche 50-370,82/12/02,3212070054
- BR12090150 Tenth interim deficiency rept re improper design of steel containment penetration assemblies Initially reported on G01217 All effected piping evaluated & reamalyred Piping can withstand extra pressures Next rept expected by B30318 HILLS, L.M. Tennessee Valley Authority B2/12/03 0'REFLLY, J.P. Region P. Office of Director 2pp 16359 119 24X Fiche 80-390, 82/12/03, 8212090150
- B212100270 Fifth interim deficiency rept re lact of Div of Engineering design sys to ensure QA procedures is sued before work begins Initially reported on B11020 Final rept will not be submitted until decision made on deferral of projects MILLS.L M Tennessee Valley Authority B2/12/06 O'REILLY, J P Region 2, Office of Director 19 16377 136 24X Fiche 50-000, 82/12/06.8212100270
- 9312140087 Fifth interim deficiency rept re incorrect thermal range analysis Initially reported on 821022 Upon closure of Engineering Change Notice 3210, support mod will be evaluated Next rept expected by 830527 MILS: L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2. Office of Director 1p 16408 255 24X Fiche 50-390,82/12/06,8212140087
- 821214014: First interim deficiency mept re Henry Pratt pneumatic authorfly valve actuator yoke failure Initially reported on B21109 Valves will be modified on site Next mept due 830607 Also reportable per Part 21 MILS.L M Tennessee Valley Authority 82/12/07 D'REJLLY, J P Region 2. Defice of Director 3pp 16408 166 24X Fiche 50-000, 82/12/07.8212140141
- 8212140164 Second interim deficienty rept re heat loss from Power Sys diseals Initially reported on 820729 Evaluation of heat load test results underway to determine needed changes Next rept due by 830322 Also reportable per Part 21 MILLS.L M Tennessae Valley Authority 82/12/07 0'REILLY, J P Region 2. Office of Director 2pp 16409 244 24% Fiche 50-390, 82/12/07, 8212140164
- 8212140376 Finel deficiency rept re anchor bolts not installed in accordance w/spacing specs Initially reported on 810331 Condition could not have adversely affected safe operation of glant Condition not reportable under 10CFR50 55(e) MILLS.L M Tennessee Valley Authority 82/12/07 0'REILLY, J P Region 2, Office of Director 20p 16403 157 24X Fiche 50-390, 82/12/07, 8212140376
- 8212150136 Second interim deficiency rept re inadequate 0A program for masonry black work Initially reported on 820702 Areas where morter did not meet min compressive strength requirements acceptable Next rept due by 830225 MILLS.L M Tennessee Valley Authority 82/12/09 0'REILLY, J P Region 2, 8ftce of Director. 2pp 16425 238 24X Fiche 50-370,82/12/09.8212150136
- 8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No add1 info available until action team 821215 rept Next rept will be submitted by 830420 MILLS.L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Ragion 2, Office of Director ip 16473 362 24X Fiche 50-000, 82/12/13, 8212200001
- 8212200017 Fifth interim deficiency rept re design review process interface coordination activity initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422 MILLS,L M Tennessee Valley Authority B2/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 30-000, 82/12/13, 8212280017
- 0212210356 Fourth interim deficiency rept re design of HVAC penetrations in containment Initially reported on Bit224 Penetrations determined to be overstressed will be supported by hangers or stiffened Next rept expected by 830325 HILLS.L M Tennessee Valley Authority 82/12/13 0'REILLY.J P Ragion 2. Office of Director ip 16495 171, 24X Fiche 50-390, 82/12/13, 8212210356

- B212210445 Second final deficiency rept re improper weld attachment of shear lugs [nitially reported on B01030 New hanger installation procedure implemented Remaining corrective action on welds will be completed by B30131 MICLS.L M Tennessee Valley Authority B2/12/13 O'REILLY.J P Region 2. Office of Director 3pp 16489 197 24X Fiche 50-390.82/12/13,8212210445
- 8212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next rept by 830404 MILLS, L M Tennessee Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director 2pp 16485 260 24% Fiche 50-000, 82/12/14, 8212210026
- SP12210217 Second interim deficiency rept re incorrect supports in analysis of 3-inch chemical & vol control sys line Initially reported on 820505 In-line isolation valves remailed Next rept expected by 830520
 MILLS.L M Tennessee Valley Authority 82/12/15 0'REILLY, J P Region 2. Office of Director 2pp 16485 014 24X
 Fiche 50-390, 82/12/15, 8212210217
- 8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MILLS.L M Tennessee Valley Authority 82/12/15 O'REILLY.J P Region 2. Office of Director 2pp 16489 168 24X Fiche 50-000,82/12/15,8212210431
- 8212220489 Second interim deficiency rept re solid state protection systest procedures Initially reported on 820831 Westinghouse proposal for procedural change rejected Util will implement own change Also reportable per Part 21 MILLS.L. M. Tennessee Valley Authority 82/12/16 O'REILLY, J.P. Region 2. Defice of Director 3pp 16504 015 24X Fiche 50-390, 82/12/16.8212220485
- 8212220426 Seventh interim deficiency rept re rerouting of high pressure fire protection piping Initially reported on G10130 Increasing pipe head diameter to next largest size would eliminate deficiency Next rept due by 830622 MILLS.L M Tennessee Valley Authority 62/12/17 G'REJLLY.J P Region 2, Office of Director 2pp 16503 287 24X Fiche 50-390.82/12/17,8212220426
- 8212280355 Second interim deficiency rept re unistrut clamps loaded in more than one direction for seismic supports Initially reported on 820708 Investigation continuing Next rept will be provided by 830211
 MILLS,L M Tennessee Valley Authority 82/12/21 D'REILLY, J P Region R. Office of Director 2pp 16560 100 24X
 Fiche 50-390, 82/12/21, 8212280355
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8211170238 Forwards NRC briefing package for meeting w/Commission on full power operation Matters raised in Commissioner Ahearne 82103 memo to be discussed DIRCKS.N J Office of the Executive Director for Operations 82/11/05 PALLADING.N J Commissioners 2pp 16155 272 24X Fiche 50-395.82/11/05.82/1170238
- 82:2070448 Forwards NUREG-0717, Suppl 5 to SER Copy also sent to LPDM W/o encl YOUN03LOOD, B J Licensing Branch I 82/11/29 DIXON, O W South Carolina Electric & Gas Co 3pp 16355 321 24x Fiche 50-395, 82/11/29, 8212070448
- F Security, medical, emergency & fire protection plans
- 8212070398 Forwards RC Lewis 820825 ltr & SALP rept for Sept 1980-Mar 1982 O'REILLY, J P Region 2, Office of Director 82/11/08 DIXON, O W South Carolina Electric & Gas Co 2pp 16363 268 24X Fiche 50-375, 82/11/08, 8212070398
- -8212070444 Forwards SALP rept for Sept 1980-Mar 1982 Meeting scheduled for 820831 to discuss results Comments re fine protection program & settlement of svc water pumphouse & piping deficiencies should be submitted within 20 days of meeting LEWIS:R C Division of Project & Resident Programs 82/08/25 DIXGN.O W South Carolina Electric & Gas Co 2pp 16363 270 24X Fiche 50-395.82/11/08.8212090398

- --8212090454 SALP rept for Sept 1980-Mar 1982 Add1 attention warranted in areas of fire protection program evaluation & settlement of svc water pumphouse & piping Region 2, Office of Director 82/08/25 14pp 16363-272 24X Fichs 50-375, 82/11/08, 8212090398
- 8212020340 Advises that util does not wish to participate in BNL exercise, in response to Generic Ltr 82-25, "Integrated IAEA Exercise for Physical Inventory of LWRs"
 DIADMO W South Carolina Electric Gas Co 82/11/29 DENTON.H R
 Office of Nuclear Reactor Regulation, Director ip 16277 269
 P4K Fiche 50-395,82/11/27,8212020340
- 9212100292 Forwards Amend 8 to physical security plan Amend withheld PIZIOUSY POWARDS AMEND OF COPHYSICAL SECURITY PIAN AMEND WITHING (Ref 10CFR2 790)

 BIXON,O W South Carolina Electric & Gas Co 82/11/29 DENTON

 Office of Nuclear Reactor Regulation, Director 1p 16376 272

 24X Fiche 50-095 South Carolina Electric & Gas Co 82/11/29 DENTON, H R
- 8P12100094 Forwards Amend 6 to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for independent review of emergency plan & implementing procedures once every 12 months YOUNGBLOOD, B J Licensing Branch 1 B2/11/30 DIXON, O W Gouth Carolina Electric & Oas Co 3pp 16399 009 24X Fiche 50-395, 82/11/30, 8212100094
- --8212100101 Amend & to License NPF-12 providing for independent review of emergency plan & implementing procedures at least once every 12 months per 10CFR50 54(t) Tech Spec changes encl YQUNQBLQOD.8 J Licensing Branch 1 82/11/30 4pp 16399 012 24% Fiche 50-395,82/11/30.8212100094
- --8212100106 Safety evaluation supporting Amend 6 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 82/11/30 5 16399 017 24X Fiche 50-395, 82/11/30, 8212100094
- -- 8212100110 Notice of issuance & availability of Amend 6 to License UPF-12 YOUNGBLOOD, B J Licensing Branch 1 82/11/30 3pp 16379 020 24% Fiche 50-395,82/11/30,8212100094
- 67:12070181 Suppl to 82:1008 application for amend to License NPF-12 re fire protection Info mistakenly omitted from original application
 DIGGLO W South Carolina Electric & Gas Co 62/12/01 DENTON.H
 Office of Nuclear Reactor Regulation. Director 12pp 16035 263
 P4X Fiche 50-095, 82/12/01.8212070181
- BP12070018 Ack receipt of 821119 ltr informing NRC of steps taken to correct violations noted in 16 Safeguards Insp Rept 50-395/82-53 LEWIS.R C Division of Project & Resident Programs 82/12/02 DIXDN.D W South Carolina Electric & Gas Co ip 16327 342 24X Fiche 50-375,82/12/02,8212070018
- --8212070026 Forwards response to NRC 821021 1tr re violations noted in IE Safeguards Insp Rept 50-395/82-53 Response withheld DIXON.O W South Carolina Electric & Oas Co 92/11/19 O'REILLY.J P Region 2. Office of Director 2pp 16327 343 24X Fiche 50-375, 82/12/02, 8212070018
- --8212070030 Forwards IE Safeguards Insp Rept 50-395/82-53 on 820920 & notice of violation Details & notice of violation withheld (ref 10CFR73 21) LEWIS.R C Division of Project & Resident Programs 82/10/21 DI(ON.D W South Carolina Electric & Gas Co 2pp 16927 346 24K Fiche 50-395,82/12/02,8212070018
- --8212070034 IE Safeguards Insp Rept 50-395/82-59 on 820920 Noncompliance noted failure to follow escort procedures Details withheld (ref 10CFR73 21) TYPE 1007RV3 21/ SKOLDS J L , MCGUIRE D R Division of Engineering & Technical Programs 82/10/20 ip 16327 348 24X Fiche 50-395.82/12/02, 6212070018
- GP:t2070128 Provides info re emergency operations facility per NRC request Facility is served by separate ventilation sys w/HEPA filters 82/12/03 DENTUN. 200 16327,085 DIKON.O W South Carolina Electric & Gas Co 82/12/C Office of Nuclear Reactor Regulation. Director 2pp P4X Fiche 50-495.82/12/03.8212070128 DENTON, H. R.
- 82:12:60322 Forwards corrected Pages 1 & 2 of table of contents to Amend 8 of physical security plan DIXON:0 W South Carolina Electric & Gas Co 82/12/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 16442 319 24X Fiche 50-395,82/12/13.8212160322

- --8212140329 Corrected Pages 1 & 2 of table of contents of Amend 8 of physical security plan * Bouth Carolina Electric & Gas Co 82/12/13 2pp 14442 320 24X Fiche 50-395.82/12/13.8212140322
- G Adjudicatory correspondence
- 8211150416 Order rendering ASLB 820720 & 0804 decisions immediately effective Order does not authorize issuance of full power OL since order does not deal w/uncontested issues considered separately by NRC & Commissioners CHILK-8 J Office of the Secretary of the Commission 82/11/10 2pp 16060 283 24X Fiche 30-395.82/11/10.8211150416
- P Operating license stage documents & correspondence
- 8212020076 "SER, Inservice Testing Program. VC Summer Nuclear Station," HUBBLE, W H , ROCKHOLD, H C E080, Inc FIN A-6430 B212020076 B2/10/31 HAMMER, 0 0 Division of Engineering 73pp 16309 001 24X Fiche 50-395, B2/10/31, B212020076
- B211170238 Forwards NRC briefing package for meeting w/Commission on full power operation Matters raised in Commissioner Ahearne B21103 memo to be discussed DIRCKB, M J Office of the Executive Director for Operations B2/11/05 PALLADING, N J Commissioners 2pp 14155 292 24X Fiche 50-398, 82/11/05, 8211170238
- 8212090398 Forwards RC Lewis 820825 1tr & SALP rept for Bept 1980-Mar 0'REILLY, J P Region 2, Office of Director 82/11/08 DIXON, O W Bouth Carolina Electric & Gas Co 2pp 16363 268 24X Fiche 50-375, 82/11/08, 8212090378
- --B212090444 Forwards SALP rept for Bept 1980-Mar 1982 Meeting scheduled for B20831 to discuss results Comments re fire protection program & settlement of svc water pumphouse & piping deficiencies should be submitted within 20 days of meeting LEMIS,R C Division of Project & Resident Programs 82/08/25 DIKON,O W South Carolina Electric & Gas Co 2pp 14343 270 24x Fiche 50-395,82/11/08,8212090398
- --B212070454 SALP rept for Sept 1980-Mar 1982 Add1 attention warranted in areas of fire protection program evaluation & settlement of svc water pumphouse & piping * Region 2. Office of Director 82/08/25 14pp 16360 272 24X Fiche 50-395.82/11/08.8212090398
- BD12010030 Informs of issuance of full power license amends on B21112
 Busquehanna i & Summer i issued 40-yr license expiring on
 220717 & 220321: respectively Susquehanna i will operate
 w/low power limitation & Summer i at 50% power
 PERCH.R L Licensing Branch 2 KANE.W F Licensing Branch 1
 B2/11/15 CASE.E . CARTER.J Office of Nuclear Reactor Regulation.
 Director EISENHUT.D Division of Licensing ip 16271 356 24X
 fiche 50-000, 82/11/15,8212010030
- BR12010526 Staff requirements memo re Commission B21112 discussion/possible vota in Washington.DC on full power OL Operation above 5% approved CHILK.S J Office of the Secretary of the Commission BR/11/26 DIRCKS.N J Office of the Executive Director for Operations 2pp 16270 266 24% Fiche 50-395.82/11/26.B212010526
- 8212270418 Responds to FOIA request for documents re proposed revision ELECTURED GREADURES to FULK request for Socuments re proposed revision &/or update to reactor safety study referred to in NUREO-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods. Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 8HOLLY, S C Union of Concerned Scientists 3pp 16549 233 24% Fiche 50-000, 82/11/26, 8212270418
- --8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued M/o encl NOVAK.T M Assistant Director for Licensing 82/09/24 Division of Licensing, ip 16549 278 24X Fiche 50-000,82/11/24,
- EP12100094 Forwards Amend & to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for independent review of emergency plan & implementing procedures once every 12 months YOUNOBLOOD, B J Licensing Branch 1 62/11/30 DIXON, 0 W South Carolina Electric & Gas Co 3pp 16399:009 24X Fiche 50-395.82/11/30.8212100094
- --8212100101 Amend & to License NPF-12.providing for independent review of emergency plan & implementing procedures at least once every 12 months per 10CFR50 54(t) Tech Spec changes encl yQUNQBLOOD, B U Licensing Branch 1 92/11/30 4pp 169 24% Fiche 50-395, 82/11/30, 8212100094 16399 012

- --8212100106 Safety evaluation supporting Amend & to License NPF-12 Office of Nuclear Reactor Regulation, Director 16399 017 24X Fiche 50-395, 82/11/30, 8212100094 82/11/30
- --9212100110 Notice of issuance & availability of Amend 6 to License RPF-12 YOUNGBLOOD, B J Licensing Branch 1 82/11/30 3pp 16399 020 24% Fiche 50-395, 82/11/30, 8212100094
- 8212070181 Suppl to 821008 application for amend to License NFF-12 refire protection Info nistakenly omitted from original application
 pIXON-0 H South Carolina Electric & Gas Co 82/12/01 DENION-H R
 Office of Nuclear Reactor Regulation, Director 12pp 14:335 263
 24X Fichs 50-395.82/12/01.8212070181
- 8212270067 Forwards Amend 7 to License NPF-12, safety evaluation & notice of issuance & availability Amend provides for range of hydrogen & oxygen content in std gas samples in channel DIXON DW South
- callor YOUNGBLOOD, B J Licensing Branch 1 82/12/06 DE Garolina Electric & Gas Co 3pp 16606 347 24X Fichs 50-399, 82/12/06,8212290067
- --8212290071 Amend 7 to License NPF-12.providing for range of hydrogen & oxygen in std gas samples used in hydrogen & uzygen monitor channel calibr YOUNGBLOOD B J Licensing Branch 1 82/12/06 5pp 16606 350 24Y Fiche 50-395,82/12/06.8212290067
- --8212290076 Safety evaluation supporting Amend 7 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 82/12/06 16606 355 24X Fiche 50-395,82/12/06,8212290067
- --8212290081 Notice of issuance & availability of Amend 7 to License YOW/0BL000:B J Licensing Branch I 82/12/06 3pp 16606 357 24X Fiche 50-395,82/12/06.8212290067
- 8212140103 Generic Ltr 82-28 to all licensess of operating Wastinghouse & C-E PWRs (except Ariansas Nuclear One, Unit 2 & San Onofre 2 & 3) re insadequate core cooling instrumentation sys Svc list encl EJSERMUT.D G Division of Licensing 82/12/10 Yenkee EJSERMUT.D G Division of Licensing 82/12/10 Yenkee 6212140103 Yankee Atomic
- 8P12170257 Provides add1 info on Operating License Condition 2 3 (14) re operations at 50% power Util intends to implement program addressed in Westinghouse rept on interim power evaluation South Carolina Electric & Gas Co 82/12/14 DENTON, Office of Nuclear Reactor Regulation. Director 2pp 16487 173 24% Fiche 50-375, 82/12/14, 8212170257 DENTON, H. R.
- 8212220440 Board Notifications 82-125 & B2-125A forwards info re High representations of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NOVAN.T M Assistant Director for Licensing 82/12/14 Safety and Licensing Board Pansl 5pp 16523 135 24X Fiche 50-000, 82/12/14, 8212220440
- G21222046: Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UY-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T H Assistant Director for Licensing 82/12/14, Safety and Licensing Board Panel 7pp 16523 169 24% Fiche 50-000,82/12/14,8212220461 Atomic
- 82:12230288 Application to amend License NPF-12 revising Tech Spec Figure 3 2-3 & Table 3 8-1 to add containment penetration Conductor overcurrent protective device for steam cleaning machine permanent power source

 DIXON.O H Bouth Carolina Electric & Gas Co 82/12/17 DENTON,HR

 Office of Nuclear Reactor Regulation, Director Spp 16507 347

 24% Fiche 50-395,82/12/17,8212230208
- --8212230294 Proposed Tech Spec Figure 3 2-3 & Table 3 8-1 re RCS flowrate & containment penetration conductor overcurrent flowrate & containment penetration conductor overcurrent protective device test setpoint criteria, respectively # South Carolina Electric & Cas Co 82/12/17 2pp 16507 350 24X Fiche 50-395,82/12/17,8212230288

- Q Inspection reports. IE Bulletins & correspondence
- 8/08/90240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BWR Plants " Svc list encl
 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208/90240
- 8212090392 Notifies that info necessary to close IE Bulletin 79-14, "Seismic Analysis of As-Built Safety-Related Piping Bys." to resolve issue re criteria for overlapping computer analysed piping math models will be provided by 830128 DIXON, O W South Carolina Electric & Gas Co 82/11/04 O'REILLV.J P. Region 2. Office of Director 2pp 16364 347 2-Fiche 50-375, 82/11/04, 8212090392 24 Y
- 8708170245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list concl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fichs 50-000, 82/11/05, 82081 90245
- 8212090398 Forwards RC Lewis 820825 1tr & SALP rept for Sept 1980-Mar 1704 O'RE(LLY, J P Region 2, Office of Director 82/11/08 DIXON, Ø W South Carolina Electric & Gas Ca 2pp 16363 268 24X Fiche 50-375, 82/11/08, 8212070398
- --8212070444 Forwards SALP rept for Sept 1980-Mar 1982 Meeting scheduled for 820831 to discuss results Comments re fire protection program & settlement of sec water pumphouse & piping deficiencies should be submitted within 20 days of meeting LEWIS.R C Division of Project & Resident Programs 82/08/28 DIXON.O W South Carolina Electric & Gas Co 2pp 16363 270 24% Fiche 50-395, 92/11/08.8212090398
- -8212090454 SALP rept for Sept 1980-Mar 1982 Addl attention warranted in erzovavoa SALP rept for Sept 1980-Mar 1982 Add1 attention warranted areas of fire protection program evaluation & settlement of svc water pumphouse & piping 8 Region 2, Office of Director 82/08/25 14pp 16363 272 24X Fiche 50-395.82/11/08.8212090398
- 8212090406 Confirms that requirements constraining power below 5% have been completed & util may proceed above 5% gower in accordance w/OL.

 O'REILLY.J P Region 2. Office of Director 82/11/10 DIXON.O W South Caroline Electric & Gas Co. Ip 16364 175 24% / iche 50-395.82/11/10.8212090406
- GPOB190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list end! JORDANN EL Division of Engineering & Quality Assurance G2/t1/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24x Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination POBIFO256 IE Info Notice be-no. Verbound Particle Info Notice be-no. Verbound Inspection and DEYOUND.R C Director's Office, Office of Inspection and DEYOUND.R C Director's Office, Office of Inspection and Lifercement 82/11/26 Consolidated Edition Co of New York, Inc. 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8P12090509 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-49 DANCE,H C Division of Project & Resident Programs 82/11/29 DIXON,D W South Carolina Electric & Gas Co ip 16367 024 24) Fichs 50-395,82/11/29.8212090509
- --8212090816 Responds to NRC B21019 ltr re violations noted in IE Insp Rept 50-395/82-49 Corrective actions operator logs revised to include syc water pond level requirements & clarifications made to Tech Spec surveillance requirements D1XDN,D W South Carolina Electric & Qas Co B2/11/18 D'KBILLY,J P Region 2, Office of Director 4pp 16367 025 241 Fiche 50-395,82/11/29,82/2090509 24x
- --8212090530 Forwards IE Insp Rept 50-395/82-49 on 820901-30 & notice of violation DANCE: HC Division of Project & Resident Programs 82/10/19 DI(ON: OW South Carolina Electric & Oas Co 2pp 16367 029 24% Fichs 50-395,82/11/29.8212090509
- --8212070534 Notice of violation from insp on 820701-30 * Division of Project & Resident Programs 82/10/19 ip 16367 031. 24X Fiche 50-395,82/11/29,8212090509

- --B212090545 IE Insp Rept 50-395/B2-49 on 820901-30 Noncompliance noted failure to follow procedures & failure to perform required surveillance for suc water pond level verification SKGLDS, U L BROWNLEE, V L Division of Project & Resident Programs 82/10/19 6pp 16367 032 24X Fichs 50-395, B2/11/29, B212090509
- 8:08170257 IE Info Notice 82~47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati' Svc list encl COBB:Ll I Division of Fuel Facilities, Materials & Safaguards 62/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- BP12070018 Ack receipt of B21119 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Ropt 50-395/82-53 LEMIS R C Division of Project & Resident Programs B2/12/02 DIXON. D N South Carolina Electric & Gas Co 1p 16327 342 24X Fishe 50-395, 82/12/02.8212070018
- --82:2070026 Forwards response to NRC 82:021 1tr re violations noted in IE Safeguards Insp Rept 50-375/82-53 Response withheld DIKON.O W South Carolina Electric & Oas Co 82/11/19 O'REILLY, J P Region 2. Office of Director 2pp 16327 343 24X Fiche 50-375,82/12/02.82:12070018
- --8212070030 Forwards 1E Safeguards Insp Rept 50~375/82-53 on 820920 & notice of violation Details & notice of violation withheld (rer 10CFR73 21)
 LEMIS.R C Division of Project & Resident Programs 82/10/21
 DIXON.D W South Carolina Electric & Gas Co 2pp 16327 346
 244 Fiche 50-395,82/12/02.8212070018
- ~-8212070034 IE Safeguards Insp Rept 50~395/82-53 on 820920 Noncompliance noted failure to follow escort procedures Details withheld (ref 10CFR73 21)
 SKOLDS, J L , MCOUIRE, D R Division of Engineering & Technical Programs 82/10/20 ip 16327 348 24% Fiche 50~395,82/12/02,8212070018
- BPOBI90259 IE Builatin B2-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies " Svc list ench BEYOUNG.R C Director's Office, Office of Inspection and Enforcement 62/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 244 Fiche 50-000, 82/12/03, 8208190259
- BrOB190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Speckets " Syc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp. 16462-064 24X [tche 50-000.82/12/03.8208190261
- 8;/08190267 |E Info Notice 82-49, "Correction for Sample Conditions for Air > Oas Monitoring " Svc list enc! BEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8P/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- S Reportable occurrences. LERs & related correspondence
- BP12030108 RO on 821110. Suring Mode 2 operation, radiation manitor RM-019C (main steam line C monitor) declared inoperable due to erratic indications Caused by moisture accumulation Honitor uill be changed prior to 830101 BIKON O W Bouth Carolina Electric to Oas Co 82/11/23 BYRELLEY, JP Region 2, Defrice of Director 2pp 16303 099 24X Fiche 50-395, 82/11/23, 8212030108
- EP12030188 Forwards LER 82-0P9/03L-0 Detailed event analysis entl DIXON O W South Carolina Electric & Gas Co 82/11/23 CIREILLY, J P Region 2: Office of Director 2pp 16306 266 24X fiche 50-395.82/11/23:8212030188
- --B212030199 LER B2-029/03L-O on B21025, during zero power testing, isolation amplifier resistor input on power range channel NI-44 found out of calibr tolerance Caused by instrument drift Channel removed from svc & calibr MCKINNEY, C. J. Sauth Carolina Electric & Oas Co. B2/11/23 Region 2, Office of Director. Ip. 16306 268 24% Fiche 50-395, B2/11/23, B212030188

- 8212030087 Interim deficiency rept re safety halard concerning undetectable failure which could exist in on-line circuits of solid state protection sys Westinghouse finalizing design mod package Final rept expected by 830201 DIAONO W South Carolina Electric & Oas Co 82/11/24 D'ÆELLY.J P. Region 2. Office of Director 2pp 14304 101 24% Fiche 80-395, 82/11/24.8212030089
- 8212030133 Forwards LER 82-030/03L-0 Detailed event analysis encl DIXON-0 W South Carolina Electric & Gas Co 82/11/24 O'REILLY, J.P. Region 2: Office of Director 2pp 16306 098 24X Fiche 50-395, 82/11/24, 8212030133
- --B212030139 LER 82-030/03L-0 on B21028. In Mode 2, svc water booster pump discharge check valve XVC-31398 found stuck in closed position Valve disassembled, inspected, lubricated, reassembled & tested satisfactorily FIELDS.H C South Carolina Electric & Oas Co 82/11/24 Region 2, Office of Director 1p 16306 100 24% Fiche 50-395.82/11/24, 8212030133
- G212030164 Forwards LER 82-031/03L-0 Detailed event analysis encl DIYON,O W South Carolina Electric & Oas Co 82/11/24 O'REILLY, J P Region 2. Office of Director 2pp 16307 080 24X Fiche 50-395, 82/11/24, 8212030164
- --8212030171 LER 82-031/03L-0 on 821030, w/plant in Mode 4, source range channel NI-32 failed low Caused by loose connection on dry butb voltage attenuator connector Connection repaired & channel operable by 821101 MCKINNEY.C J South Carolina Electric & Oas Co 82/11/24 Region 2, Office of Director 5p 16307 082 24X Fiche 50-395,82/11/24,8212030164
- GP12030186 Forwards LER 82-032/03L-0 Detailed event analysis encl DIMONO W South Carolina Electric & Gas Co 82/11/24 D'REILLY, JP Region 2, Office of Director 2pp 16303 211 24X Fiche 50-395, 82/11/24, 8212030186
- --8212030202 LER 82-032/03L-0 on 921029, auxiliary operator discovered nuclear blowdown monitor tank damaged Caused by distorted disphragm blocking tank overflow & vent paths Disphragm removed & tank repaired KOGN.A R South Carolina Electric & Oas Co 82/11/24 Region 2, Diffice of Director ip 16303 213 24X Fiche 50-395.82/11/24, 8212030186
- 8R12030060 Forwards LER 82-033/03L-0 Detailed event analysis encl DIADN.O W South Carolina Electric & Oas Co 82/ii/27 O'REILLY.J P Region 2. Office of Director 2pp 16304 187 24X Ficha 50-378.82/11/29.6212030060
- --9212030064 LER 82-033/03L-0 on 821031, during water pump test, speed switch XES-2003A failed in midposition during fast to slow speed transfer, rendering see water train A inoperable Caused by bad rolay contact on speed switch Rolay repaired MCKINNEY.C J Bouth Carolina Electric & Gas Co 82/11/29 Region 2, Office of Director ip 16304 189 24% Fiche 50-375,82/11/29,8212030060
- 8212090422 Forwards LER 82-034/03L-0 Detailed event analysis encl DIXON 0 U South Carolina Electric & Gas Co 82/12/01 O'REILLY, J P Region 2, Office of Director 2pp 16364 253 24X Fiche 50-375, 82/12/01.8212090422
- ---8212090438 LER 82-034/03L-0 on 821103, during Mode 4, radiation munitor RM-019C (main steam line C monitor) failed to high radiation alarm setpoint Caused by moisture penetration of cable connectors between detector & preamp Detector replaced FIELDS, H C South Carolina Electric & Gas Co 82/12/01 Region 2, Office of Director 1p 16364 255 24X Fiche 90-395,82/12/01.8212090422
- 8212070243 Forwards LER 82-036/03L-0 Detailed event analysis encl DIXON.O W South Carolina Electric & Oas Co B2/12/02 O'REILLY.J P Region 2, Office of Director 2pp 16361 353 24X Fiche 50-375,82/12/02.8212070243
- --B212090253 LER 82-036/03L-0 on 821103, plant entered Mode 3 w/control room evacuation panel pressurizer relief tank level indicator LI-470A inoperable Caused by level transmitter being out of calibr Transmitter calibr FIELDB, H C Bouth Carolina Electric & Oas Co 82/12/02 Region 2, Office of Director ip 16941 355 24X Fiche 50-995, 82/12/02, 22/2002034
- GP:2090449 Forwards LER 82-035/03L-0. Detailed event analysis encl DIACN.O W South Carolina Electric & Oas Co B2/12/02 D'REILLY.J P Region 2. Office of Director 2pp 16363.249 24X Fichs 50-395, 82/12/02, 8212090449.

- --8212090460 LER 82-035/03L-0 on 821103, plant entered Mode 3 w/boric acid tani B level instrument LT-163A inoperable Caused by instrument out of calibr due to zero shift on transmitter instrument recalibr KOON A R South Carolina Electric & Gas Co 82/12/02 Region 2. Office of Director 1p 16363 251 24X Fiche 50-375, 82/12/02. 8212090449
- 8P:2070366 Forwards LER 82-037/03L-0 Detailed event analysis encl DIXON-0 W South Carolina Electric & Gas Co 82/12/03 D'REILLY.JP Region 2. Office of Director 2pp 16365 068 24X Fiche 50-395, 82/12/03.8212090366
- --8212090372 LER 82-037/03L-O on 821104, steam generator blowdown radiation monitor (RM-L3) & steam generator blowdown discharge radiation monitor (RM-L10) taken out of svt Caused by insufficient sample flow Sys aligned for RM-L10 HARRIS.A B South Carolina Electric & Gas Co 82/12/03 Region 2, Office of Director in 16365 070 24X Fiche 50-395,82/12/03,8212090366
- GP12150077 Forwards LER 82-038/03L-0 Detailed event analysis encl DIXON.O W South Carolina Electric & Gas Co 82/12/08 O'REILLY.JP Region 2, Office of Director 200 16427 342 24X Fiche 50-395, 82/12/08, 8212150077
- --8212150081 LER 82-038/03L-0 on 821114, main control board indication for steam generator A steam flow (FT-474) failed to indicate sys flow Gaused by indicator needle sticking to lower stop Channel calibr performed MCKINNEY, C. J. South Carolina Electric & Gas Co. 82/12/08 Region 2, Office of Director 19 16427 344 24X Fiche 50-395, 82/12/08.8212150077
- 8212150089 Forwards LER 82~040/03L-0 Detailed event analysis encl DIXEM.O H South Carolina Electric & Oas Co 82/12/08 O'REILLY.J F Region 2. Office of Director 3pp 16431 027 24X Fiche 50-395. 82/12/08.8212150089
- --B212150091 LER 82-040/03L-0 on 821108. Tech Spec 3 3 2 had not been complied w/due to improper interpretation Caused by personnel error Ltr issued delineating correct interpretation of Tech Spec KOON. A R South Carolina Electric & Gas Co 82/12/08 Region 2. Office of Director 1p 16431 030 24X Fiche 50-395.82/12/08, 8212150089
- G212150097 Forwards LER 82-039/03L-0 Detailed event analysis encl D1XON-D W South Carolina Electric & Gas Co 82/12/08 O'REFLLY, J.P. Region 2, Office of Director 2pp 16430 349 24X Fiche 50-395, 82/12/08, 8212150097
- --8212150100 LER 82-037/03L-0 on 821108, steam generator steam flow transmitter (FT-476) power supply found defective Caused by failure on transmitter power supply (FGY-476) Channel placed in tripped condition Circuit board replaced & tested MCKINNEY.C J South Carolina Electric & Oas Co 82/12/08 Region 2, Office of Director ip 16430 351 24X Fiche 50-395,82/12/08,8212150097
- GP12150117 Forwards LER 82-041/03L-0 Detailed event analysis encl DIXON-0 W South Carolina Electric & Gas Co B2/12/09 O'REILLY.J P Region 2, Office of Director 2pp 16427 348 24X Fiche 50-395, 82/12/09.8212150117
- --8212150122 LER 82-041/03L-O on 821109.during Mode 2.rediation monitor RM-AI (control room isolation) failed surveillance Test Procedure 360 032 Caused by instrument drift Monitor calibr & returned to svc.

 KOON.A R South Carolina Electric & Gas Co 82/12/09 Region 2. Office of Director 1p 16427 350 24X Fichs 50-395.82/12/09, 82(2150117
- 82:2170287 Forwards LER 82-042/03L-0 Detailed event analysis encl DIXON, O W South Carolina Electric & Gas Co 82/12/10 O'REILLY, J P Region 2, Office of Director 2pp 16453 212 24X Fiche: 50-395, 82/12/10.8212170287
- --821217029(LER 82-042/03L-0 on 821110.RCS temp average decreased when control rods inserted Caused by samultaneous rod insertion & main steam dumping Control rods withdrawn & steam dump isolated to recover temp average FIELDS, H C Bouth Carolina Electric & Gas Co 82/12/10 Region 2. Office of Director 1p. 16453 214 24X Fiche 50-395,82/12/10.8212170887
- 0212210341 Final Part 21 rept re possible thermostatic valve malfunction fail-safe to "Full Cooling Position " Initially reported on 820525 All corrective actions completed MRIARTY. J M Colt Industries. Inc 82/12/10 KEPPLER. J G Region 3. Office of Director 1p. 16496 334 24% Fiche 50-395,82/12/10. 8212210341

- 8212200110 Forwards LER 82-043/03L-0 Detailed event analysis enci DIXON.O W South Carolina Electric & Oas Co 82/12/13 O'REILLY, J P Region 2. Office of Director 2pp 16470 149 24X Fiche 50-395, 82/12/13, 8212200110
- --B212200115 LER 82-043/03L-0 on 821113 nuclear instrumentation power range channel (N42) low-range trip setpoint found set at 50% instead of 25% of rated thermal power Caused by personnel error Lou-range trip setpoint reset MCMINNEY. C J South Carolina Electric & Gas Co 82/12/13 Region 2. Office of Director ip 16470 151 24% Ficha 50-395.82/12/13.8212200110
- 8212220374 Forwards LER 82-047/03L-0 Detailed event analysis encl DIXDM D W South Carolina Electric & Gas Co 82/12/16 O'REILLY, J.P. Region 2, Office of Director 2pp 16517 264 24X Fiche 50-395, 82/12/16, 8212220376
- --8212220384 LER 82-047/03L-0 on 821118 operations personnel failed to document Tavg on 30-minute basis greater than 551 degrees w/Tavg-Tref deviation alarm not reset Caused by failure of operator to recognize surveillance requirements MCKINNEY.C J South Carolina Electric & Oas Co 82/12/16 Region 2, Office of Director 1p 16517 266 24X Fiche 50-395,82/12/16,8212220376
- 8212220411 Forwards LER 82-046/03L-0 Detailed event analysis encl D1xDN,D W Bouth Carolina Electric & Gas Co 82/12/16 D'REILLY,J P Region 2. Office of Director 3pp 16503 248 24X Fiche 50-395,82/12/16,8212220411
- --8212220414 LER 82-046/03L-0 on 821117.main control board indication for steam generator feedwater flow read zero Caused by personnel leaving equalizing velves on transmitters open Valves closed & personnel indoctrinated MCKINNEY.C J Bouth Carolina Electric & Gas Co 82/12/16 Region 2. Office of Director ip 16503 251 24X Fiche 50-395,82/12/16.8212220411
- 8212220428 Forwards LER 82-045/03L-0 Detailed event analysis encl DIXON.D W South Carolina Electric & Gas Co 82/12/16 O'(REILLY.J P Region 2. Office of Director 2pp 16503 289 24X Fiche 50-395, 82/12/16, 8212220428
- --8212220462 LER 82-045/03L-0 on 821116.plant entered Mode 1 w/o performing surveillance Test Procedure 134 001 re shutdown margin calculation per Tech Specs Caused by personnel oversight Tech Specs reviewed Surveillance program revised FIELDS, H C Bouth Carolina Electric L Gas Co 82/12/16 Region 2, Office of Director 1p 16503 291 24X Fiche 50-395,82/12/16, 2013200439
- 8212220498 Forwards LER 82-044/01T-0 Detailed event analysis encl DIXDN,O W South Carolina Electric & Gas Co 82/12/16 O'KEILLY,J P Region 2, Office of Director 4pp 16503 259 24X Fiche 50-375.82/12/16.8212220498
- --8212220500 LER 82-044/01T-0 on 821202, surveillance test performed on 821005 for RMR pump A signed off approved when acceptance criteria not met Caused by personnel error due to lack of experience
 KGON, A R South Carolina Electric & Gas Co 82/12/16 Region 2, Defice of Director 1p 16503 263 24X Fiche 50-395,82/12/16,8212220498
- BR12220328 Forwards LER 82-049/03L-0 Detailed event analysis encl DIXON D W South Carolina Electric & Gas Co 62/12/17 O'REILLY, J P. Region 2. Office of Director 3pp 16517 177 24X Fiche 50-395, 82/12/17, 8212220328
- --8212220337 LER 82-049/03L-0 on 821118, Surveillance Requirement 4 7 9 1 1(e) not performed on fire suppression water sys Caused by fire protection group being unaware of Mode 6 restriction Personnel counseled & tracking program updated HCNINNEY, C J South Carolina Electric & Cas Co 82/12/17 Region 2, Office of Director 1p 18517 180 24X Fiche 50-395,82/12/17,8212220328
- 9212300035 Forwards LER 92-050/03L-0 DIXON.D H South Carolina Electric & Gas Co 82/12/21 O'REILLY.J P Region 2. Office of Director 3pp 16598 198 24X Fiche 80-395.82/12/21.8212300035
- --8212300042 LER 82-050/03L-0 on 821207, fire watch patrol not executed for Zone FF for 4 h while smoke detectors insperable Caused by breakdown in communications & absenteeism Personnel dismissed

 * South Carolina Electric & Gas Co 82/12/21 Region 2, Office of Director ip 14578 201 24X Fichs 50-395,82/12/21, 8212300035

- F. Hearing transcripts on non-antitrust matters
- B211180122 Unofficial transcript of 921112 public discussion/possible vote on full power QL in Washington, DC Pp 1-70

 * Cormissioners 82/11/12 94pp 16154 141 24X
 Fiche 50-395, 82/11/12, 9211180122
- DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR
- G Inspection reports, IE Bulletins & correspondence
- OPOB) 90240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BNR Plants "Svc list encl
 DEYOUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24% Fichs 50-000, 82/10/28, 8208190240
- DOCKET SO-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- B210270013 Forwards Revision 1 to "Plant Verification Rept." dtd (let 1982 BDUCHEY.O D Washington Public Power Supply System 82/10/22 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 15817 012 24X Fiche 50-397.82/10/22,8210270013
- --8210270016 Forwards Revision 1 to "Plant Verification Rept." dtd Oct 1982 GLASSCOCK.R B Washington Public Power Bupply System 82/10/22 ENGELKEN.R H Region 5. Office of Director ip 15817 014 24X Fiche 50-397.82/10/22.8210270013
- --8210270018 Revision I to "Plant Verification Rept," dtd Oct 1982 TIMMINS.D C. MATLOCK.R G., SHEN.P K. Washington Public Power Supply System 82/06/30 437pp 15817 015 24X Fiche 80-397.82/10/22,8210270013
- 6.11230066 Generic Ltr 82-27 to all BWR licenses of operating reacturs except LACBUR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0785 Svc list encl W/o stated encl EISENNUT.D G Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X [iche 50-000.82/11/15.8211230066]
- 8P12030260 Summary of 821110 meeting w/util in Bethesda, MD re review of GA program in light of deficiencies disclosed at other projects Viewgraphs encl AULUCK, R Licensing Branch 2 82/11/30 Licensing Branch 2 83pp 16317 231 24X Fiche 50-397.82/11/30,8212030260
- 8/12200047 Forwards one oversize design elementary diagram showing relaying stheme used to implement commitment to provide second level undervoltage protection for div I & II ESF buses Aperture card is available in PIR BOUCHEY, 6 D Washington Public Power Supply System 82/12/08 SCHWENCER: A Licensing Branch 2 1p 16470 185 24X Fiche 50-397, 82/12/08, 8212200047
- 80:12200074 Forwards summary info re containment vessel out-of-roundness issue raised during litigation following termination of Contract 206 per R Auluck request Out-of-roundness will have no detrinental effect on structural capacity GOUCHEY.9 D Washington Public Fower Supply System 82/12/08 SCHWENCER.A Licensing Branch 2 5pp 16470 025 24X Fiche 50-397, 82/12/08,8212200074
- 6:12170173 Responds to NRC Question 010 066 re pipe break in BWR scram sys (MUREO-0803) Response to Questions 010 067 010 074 will be submitted under separate cover during Dec 1982 BOUCHEV-0 D Washington Public Power Supply System 82/12/09 BCHWENCER, A Licensing Branch 2 13pp 16450 124 24X Fiche 50-397, 82/12/09, 82/12/70173
- 69:12170175 Responds to telephone request for info re analytical models used to predict forcing functions & response of drywell-to-wetwell vacuum breakers Final rept to be provided following completion of vacuum breaker mod 60UCHEV.0 D Washington Public Power Supply System 62/12/09 SCHMENCER.A Licensing Branch 2 1p 16462 060 24X Fiche 50-397.82/12/09.8212170175

- 8212170374 Forwards marked-up revision to FSAR Section 8 3 1 4 reflecting analysis justification for coll-to-contact relay isolation between redundant Class IE circuits & Revision 0 to "Electrical Separation Practices"

 BOUCHEY. 0 D Washington Public Power Supply System 82/12/09 SCHMENCER. A Licensing Branch 2 3pp 16453 226 24X Fiche 50-397. 82/12/09.8212170374
- --8212170379 Revision 0 to "Electrical Separation Practices" BRASTAD.0 H , MALLANDA.J J Washington Public Power Supply System 82/12/03 51pp 16453 229 24% Fiche 50-397.82/12/09, 8212170374
- G212220355 Forwards request for add1 info re review of safety-related equipment Responses needed by 930107
 SCHWENCER.A Licensing Brench 2 B2/12/09 FEROUSON, R L
 Washington Public Power Supply System 4pp 16523 244 24X
 Fiche 50-397, 82/12/09, 8212220355
- G212270159 Forwards revised organization & staffing announcement for operational GA program description.per G21215 telicon Infowall be included in FSAR revision to be filed early in 1963 GOUCHEY.60 D Washington Public Power Supply System 82/12/16 HAASS, H P Guality Assurance Branch Gpp 16538 046 24X Fiche 50-397, 82/12/16, G212270159
- B212230363 Trip rept of Commissioners Oilinsky & Abbott 821202 site visit Agenda & vieugraphs encl ABBOTT. EC Commissioners 82/12/17 Commissioners 26pp 16511 170 24X Fiche 50-397.82/12/17.8212230363
- 8212290241 Responds to NRC 820809 request for add1 info on fuel corrosion measures Factors attributed to corrosion fuel failures include fuel duty, cladding matl & reactor water environ
 BOUCHEY, O D Mashington Public Power Supply System 82/12/23 SCHVENCER, A Licensing Branch 2 2pp 16382 043 24x Fiche 50-397, 82/12/23, 8212270241
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8/12010024 Advises that recommendations re application for DL per 821013 ltr will be addressed in SER supplement to be issued in Dec 1982 000DMIN.E F Office of Nuclear Reactor Regulation, Director 82/11/12 FRALEY,R ACR8 Advisory Committee on Reactor Safeguards 3pp 16290 239 24X Fiche 5D-397,82/11/12,8212010024
- B212200093 Forwards sweepolet stress calculation per SER, NUREG-0892, Confirmatory Issue 6 & 820930 telcon BOUCHEY, 0 D Washington Public Power Supply Bystem 82/12/08 SCHMENCER, A Licensing Branch 2 Spp 16470 041 24X Fiche 50-397, 82/12/08, 8212200083
- B21217013B Forwards responses to NRC Questions 010 067 through 010 074 re internally generated missiles.per 821209 commitment Responses close out Outstanding Issue 2 in SER.NREC-0872 BOUCHEY. 6 D Washington Public Power Supply System 82/12/09 SCHWENCER. A Licensing Branch 2 9pp 16482 006 24X Fiche 50-397. B2/12/09. B21217013B
- F Security, medical, emergency & fire protection plans
- 8912100256 Forwards util 800616 & 1212 & 810320 & 0408 ltrs re emergency response facilities (ERF) in response to Generic Ltr 81-10, per NRC request Util does not plan to provide backup ERF Requested info provided HOUGHEY, 0 Washington Public Power Supply System 82/12/03 DENTON, HR Defice of Nuclear Reactor Regulation, Director 2pp 16376 149 24X Fiche 50-397.82/12/03.8212100256
- 8212270505 Notification of 830105 meeting w/util in Bethesda.MD to discuss request for limited exemption re prompt notification sys AULUCK.R Licensing Branch 2 82/12/23 SCHWENCER.A Licensing Branch 2 3pp 16593 346 24X Fiche 50-397.82/12/23.8212290505
- 6 Adjudicatory correspondence
- B212020350 Order scheduling 830119-20 prehearing conference in Richland, WA to discuss standing of parties, specific issues to be considered at evidentiary hearing, scheduling & possible consolidation OROSSMAN, H Atomic Safety and Licensing Board Panel 82/11/30 4pp 16278 001 24% Fiche 50-397, 82/11/30, 8212020350

DOCKETED ITEMS

- 8212140418 Motion for delay of 830119 t 20 prehearing conference Schedule burdensome due to two major holiday periods Four days of preparation lost Certificate of Svc encl MELLN Coalition for Safe Power 82/12/09 Atomic Safety and Licensing Board Panel 3pp 16403 312 24X Fiche 50-397.82/12/09, 8212140418
- B212200104 Order rescheduling B30119 & 20 prohearing conferences for B30106-27 Coalition for Safe Power allowed to file supply to requests for hearing no later than 15 days before conference GROSSMAN.H 2005/4AN.H Atomic Safety and Licensing Board Panel 82/12/15 2pp 16470 089 24X Fiche 50-397.82/12/15,8212200104
- 8212230314 Requests supplemental pleadings be served on applicant counsel in Hashington DC per ASLB 821215 order Pleadings expected by 830111 Pleadings served to util in Richland HA do not constitute svc in proceeding REYNOLDS NS Debevoise & Liberman REYNOLDS NS Washington Public Power Supply System 92/12/20 RDSGLIE & Coalition for Safe Fower ip 14507 027 24X Fiche 50-397.82/12/20.8212230314
- 8212270326 Response supporting Coalition for Safe Power 821207 mption for 1-wt delay of prehearing conference scheduled for 830119-20 Applicant does not concede that basis for request constitutes good cause Certificate of Svc enc!

 REYNOLDS.N S Washington Public flower Supply System REYNOLDS.N S
 Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Roard Panel 6pp 16530 190 24% Fiche 50-397.82/12/22.8212270326
- 8912280277 Forwards repsonses to petitioner motion for delay of 830119 & 22 prehearing conference, for inclusion in records Related correspondence Wo enci REYMOLDS, N S Debevoise & Liberman REYMOLDS, N S Hashington Public Power Supply System 82/12/22 GROSSMAN, H Atomic Safety and Licensing Deard Panel ip 16561 311 24X Fiche 50-397, 82/12/22, 8212280277
- 8212280145 Notice of appearance in proceeding Certificate of Svc encl PATON.W D. Hearing Branch 2 82/12/27 2pp 16563 122 24X Liche 50-397, 82/12/27, 8212280145
- If General correspondence
- 8212170314 Notifies that RL Ferguson, managing director of util, resigned on 821127, effective 830401, due to health reasons BOUCHEY, O D Washington Public Fower Supply System 82/12/08 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 14456 158 24X Fiche 50-397,82/12/08,8212170314
- R Utility Final Safety Analysis Report (FSAR) & amends
- 8212270180 Forwards App J to FSAR. "Shielding Evaluation Rept"
 DDUCHEY, 0 D Mashington Public Power Supply System 82/11/23
 SCHWENCER. A Licensing Branch 2 2pp 16580 096 24X
 Fiche 50-397, 82/11/23, 8212270180
- --8212290185 App J to FSAR, "Shielding Evaluation Rept "
 # Washington Public Power Supply System 82/09/30 310pp
 16580 098 24% Fiche 50-397, 82/11/23,8212290180
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8211100498 Summarizes ACRS 270th meeting on B21007-08 in Hashington, DC to review full-power OL for HPPSS Unit 2 & small break LOCA for 86H plants
 BHEHMON, P ACRS Advisory Committee on Reactor Safeguards
 B2/10/19 PALLADING N J Commissioners 2pp 66441 090 24X
 Fiche 50-397, 82/10/19, 821(100468
- 8212010024 Advises that recommendations re application for OL per 821013 itr will be addressed in SER supplement to be issued in Dec 1982 GOODNIN,E F Office of Nuclear Reactor Regulation, Director 82/11/12 FRALEY,R ACRS Advisory Committee on Reactor Safeguards 3pp 16290 239 24X Fiche 50-397,82/11/12,8212010024
- @ Inspection reports, IE Bulletins & correspondence
- 8200190240 IE Bulletin 82-03, Revision I, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Syc list encl DEYQUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Eduson Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240.

- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic File 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc1
 - CORB.L J Division of Fuel Facilities, Materials & Safeguards
 B2/11/05 Consolidated Edison Co of New York, Inc 110pg
 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8212040021 Advises that IE Bulletin 82-01, Suppl 1 re ITT Grinnell supplied matls, is not applicable to facility MATLOCK, R G Washington Public Power Supply System 82/11/12 ENGELKEN.R H Region 5. Office of Director 1p 16313 325 Fiche 50-397, 82/11/12, 8212060021
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/12 Consolidated Edison Co. of New York, Inc. 109pp 14411 fiche 50-000.82/11/18.8208190251
- 82/2060205 Forwards IE Insp Rept 50-397/82-24 on 821001-31 No moncompliance noted
 STERMOERG.D M Division of Resident, Reactor Project & Engineering
 Programs 82/11/22 MATLUCK,R G Washington Public Power Supply
 System 2pp 16312 241 24X Fiche 50-397,82/11/22,8212060205 STERNOLIGE Programs 82,
- --8212040208 IE Insp Rapt 50-397/82-24 on 821001-31 No noncompliance elaborous L imag kept 30-37/08-24 on 021001-31 ko noncomplation noted. Major areas inspected mechanical contractor records review program & corrective activities, work reverification program activities, RCPB piping & as-built configuration TOTN A D , FELL.R A , DODDS:R T Division of Resident, Reactor Propect & Engineering Programs 82/11/19 16pp 16312 243 241 Fiche 50-397, 82/11/22, 8212060205
- 8212220213 Forwards JE Insp Rept 50-397/82-19 on 820913-1008 No noncompilance noted STERNBERG, D M Div: noncompliance noted
 STERNBERG, D M Division of Resident, Reactor Project & Engineer; r;
 Programs 62/11/24 MATLOCK, R G Washington Public Power Supply
 System 2pp 16503 335 24x Fiche 50-397, 82/11/24, 9212220213
- --8212220218 IE Insp Rept 50-397/82-19 on 820913-1008 No nuncompliance cleaecast it insp Mept 50-39//82-19 on #20913-1009 No moncompliated noted Major areas inspected welding GC program radiograph reverification program, items reported by 10CFR50 55(e) notification & safesty-related piping sys, sizes & matls KERCH, M W, HARRIS,R H, CURR., P Region 1, Defice of Director 02/11/04 8pp 16503 337 24% Fiche 50-397,82/11/24,8212220210
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocis "Svc list end Padlocis "Svc list end DEYDUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 82/8190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl Division of Fuel Facilities, Materials & Safeguards 82/11/30 consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8212280443 Confirms 821123 telephone request for extension until #21203 to provide response to IE Insp Rept 50-397/82-21
 MATLOCK.R 0 Washington Public Power Supply System 82/12/02
 ENGELKEN.R H Region 5. Office of Director ip 16556 037
 Fichs 50-397, 82/12/02, 8212280443
- 9208190259 JE Bulletin 82-04, "Peficiencies in Primary Containment Electrical Penetration Assemblies " Svt list encl DEYDUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, I 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208170259 New York, Inc
- 8208190261 [E Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/12/(Consolidated Edison Co of New York, Inc 110pp 16462 064 : Fiche 50-000, 82/12/03,8208190261
- 8212210416 Forwards IE Insp Rept 50-397/82-26 on 821101-05 No noncompliance noted strangering of Resident, Reactor Project & Engineering STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 82/12/08 MATLOCK, R. G. Washington Public Power Supply Programs 82/12/08 02:2210416

- --R212210427 IE Insp Rept 50-397/82-26 on 821101-05 No noncompliance noted Major areas inspected preoperational test procedure program, followup of open items, IE bulletin/circular program, rollingup or upen trems, it deliberin/circular follows b independent insp HILLETT.D J. DODDS:R T Division of Resident, Reactor Project & Engineering Programs 82/12/08 3pp 16493 082 24X Fiche 50-37, 82/12/08.8212210416
- 8212170088 Forwards SALP rept for Jul 1981-Jul 1982 ENGELMEN.R H Region 5. Office of Director 82/12/10 FERGUSDN.R L Washington Public Power Supply System 16450 322 24% Fiche 50-397.82/12/10.8212170088
- ~-8212170091 SALP rept for Jul 1981-Jul 1982 Weaknesses noted design & installation of electrical sys & implementation of corrective actions in const deficiency repts a Region 5. Office of Director 82/12/10 21pp 16450 325 24X Fiche 50-397.82/12/10.8212170088
- --B212170:00 Responds to B21027 SALP rept Corrective actions task force established to revisit electrical separation & follow up surveillances on const deficiency repts incorporated into surveillances on to.... The project QA FERGUSON,R L Hashington Public Power Supply System 82/11/23 FERGUSON,R L Division of Resident, Reactor Project & Engineering Programs Spp 16450 346 24X Fiche 50-397, 82/12/10, 8212170088
- --8212170603 Notifies of weaknesses in specific areas identified in SALP rept Meeting scheduled for 821103 to discuss assessment STERNBERO.D M Region 5, Office of Director 82/10/27 MATLGCK.R G Washington Public Power Supply System ip 16450 351 24X Fiche 50-397,82/12/10,8212170088
- BP122B0023 Notifies that generic qualification tests of Raychem Flamtrol cables no longer applicable for all cables Certain Maychem-Flamtrol cables react adversely to space charges occurring during radiation crosslinking

 JORDAN,E L Division of Engineering & Quality Assurance B2, FERGUSON, R Mashington Public Power Supply System 4pp 14: 24X Fiche 50-397,82/12/10,8212280023 82/12/10
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list entl IEVOUNG.R C Director's Office. Office of Inspection and Inforcement B2/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24% Fiche 50-000, 82/12/16, 8208190267
- 8.º08190268 IE info Notice 82-50. "Mod of Solid State AC Undervoltage (lelays Type ITE-27" Svc list encl JURDAN: Et Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 273 24) Fiche 50-000.82/12/20.8208190268
- B21230039B Ack receipt of 821202 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-397/B2-21 50-397/82-21 BTERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 MATLOCK,R O Washington Public Power Supply System 1p 16594 292 24X Fiche 50-397,82/12/23,8212300308 BTERNUL... Programs Bi
- --8212300318 Responds to NRC 821025 ltr re violations & deviations noted in IE Insp Rept 50-397/82-21 Corrective actions electrical separation project engineering directives reviewed to identify cables affected by 6-1nch separation requirements CARLISLEIC S Washington Public Power Supply System 82/12/02 SYERMIERO, D M Division of Resident, Reactor Project & Engineering Programs 15pp 16994 293 24X Fiche 50-397,82/12/23,8212300308
- S Reportable occurrences, LERs & related correspondence
- 8212040179 Interim deficiency rept re voltage drop due to excessive cable length Initially reported on 820403 Control power transformer output increased Voltage no longer impeded & long cable used Next rept expected by 830222 MATLOCX.R 0 Washington Public Power Supply System 82/11/23 ENDELKON.R H. Region 5. Office of Director 2pp 16313 076 2/ Fiche 50-397, 82/11/23,8212040179
- BP12050289 Interim deficiency rept re controls for remote shutdown panel & pump discharge switch Initially reported on 820819 & 0820. respectively Switches & valves will be relocated Next rept will be submitted on 830288 MATLOCK.R 9 Washington Public Power Supply System 82/11/23 ENGELKEN.R H Region 5. Office of Director 4pp 16312 066, 24% Fiche 50-397, 82/11/23.8212060289
- 8212210396 Deficiency rept re Johnson Controls design issue Eight of 132 small bore lines did not meet min design criteria
 following thermal affects application
 MATLOCK:R 0 Washington Public Power Supply System 82/12/02
 ENGELERN,R H Region 5, Office of Director 2pp 16493 361 24X
 Fiche 50-397,82/12/02,8212210386

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1 A Application/construction stage documents & correspondence
- 8212130181 Forwards revised "Human Factors Design Evaluation Rept for Shearon Harris Unit 1 Control Room" MCDUFFIE.M A Carolina Power & Light Co 82/12/07 DENTON.H R Uffice of Nuclear Reactor Regulation, Darector (p. 16397-336 24X Fiche 50-400, 82/12/07, 8212130181
- --8212130185 Revised "Human Factors Design Evaluation Rept for Shearon Herris Unit 1 Control Room TALLEY, W T. HAHER, J. FABRY, J Essex Corp 82/09/16 165pp 16397 337 24X Fiche 50-400, 82/12/07. 8212120181
- C Utility Environmental Report (ER), amends & correspondence
- BP:12210422 Forwards Amend 5 to environ rept MCDUFFIE, M A Carolina Power & Light Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16494 001 24X Fiche 50-400, 82/12/15, 8212210422
- --8212210424 Amend 5 to environ rept

 * Carolina Power & Light Co 82/12/15 270pp 16494 003
 Fiche 50-400, 82/12/15, 8212210422 24 X
- 82:12280112 Forwards revised distribution list reflecting title, address & name changes for distribution of Amend 9 to environ rept Distribution made within 10 days after issuance of amend Distribution made within 10 days after issuance of amend
 Affidavit encl
 2IMMERMAN,8 R Carolina Power & Light Co 82/12/23 EISENHUT, D Q
 Division of Licensing 5pp 16564 183 24X Fiche 50-400,82/12/23,
 0212280112
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8212160036 Forwards addl info requested by NRC 821120 ltr re vol reduction sys info addresses all items necessary for DES input Renaining info will be submitted as available MCDUFFIE.M A Carolina Power & Light Co 82/12/13 DENTON, H R Office of Nuclear Results results on Director 9pp 16446 207 P4X Fiche 50-400,82/12/13,8212160036
- E NRC Safety Evaluation Report (SER), supply & correspondence
- BP12080558 Forwards request for add1 info re response to vol reduction sys for draft SER Response required by 821210 to complete safety review on schedule KNIOHTON.O W Licensing Branch 3 82/11/26 UTLEY, E Carolina Power & Light Co Spp 16368 355 24X Fiche 50-400. B2/11/26. Power & Light Co Spp 8212080558
- Q Adjudicatory correspondence
- B212020336 Order directing NRC & util to answer questions on document copies & cost to enable ASLB to rule on intervenor requests to reconsider order re svc of documents KELLEY. J. L. Atomic Safety and Licensing Board Panel 62/12/01 Office of the Executive Legal Director 2pp 16279 149 24X Fiche 50-400,82/12/01.8212020336
- B2J2100099 Advises that name will be added to applicant svc list for future filings Listed documents encl Svc list only encl BAXTER.T A Shaw Pittman, Potts & Trombridge BAXTER.T A Capolina Power & Light Co 82/12/07 LOTCHIN.P Affiliation Unknown Spp 16379 186 24X Fiche 50~400.82/12/07.8212100099
- BP12170073 Forwards Generic Ltr B2-14 setting forth schedule of number of copies of documents required to be submitted to NRC, in response to ABLB B21201 inquiry BARTH, C A Hearing Branch 1 82/12/14 KELLEY, J L, BRIGHT, C D, CARPENTER, J H Atomic Safety and Licensing Board Panel 19 16452-324 24X Fiche 50-400, B2/12/14, 8212170073
- 8212230366 Response to ASLB 821201 order seeking info on document capies & costs re serving documents on intervenors capies & costs re serving documents on intervenors Certificate of Svc enci Related correspondence JUNIONES, RE, FLYNN, SF Carolina Power & Light Co 82/12/Atomic Safety and Licensing Board Panel App 16511 197 Fiche 50-400, 82/12/15,8212230366 92/12/15
- 8P:12210222 Motion for codification of admitted contentions Request made for convenience of all parties & ASLB & in fairness to applicants who bear burden of proof re each contention admitted for litigation Certificate of Bvc encl
 O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 82/12/17. Atomic Safety and Licensing Board Panel 78pp 16484 101 24X Fichs 50-400,82/12/17, 8212210222

- 8212270222 Forwards Chapters 8 & 11 of environ rept, through Amend 5 Chapters cover benefits & costs & provide analysis of savings for utilizing plants from 1986 1995 Svt list encl BAXTER.T A Shaw, Pittman, Potts & Troubridge BAXTER.T A Carolina Power & Light Co 82/12/21 KELLEY.J L , BRIGHT.C D , CARPENTER.J H Atomic Safety and Licensing Board Panel 19pp 16535 097 24X Fiche 50-400.82/12/21.8212270222
- @ Inspection reports, IE Bulletins & correspondence
- 8212090183 Forwards IE Insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 62/10/26 UTLEY,E E Carolina Power & Light Co 2pp 16359 191 24X Fichs 50-400,82/10/26,8212090183
- --B212070186 IE Insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No noncompliance noted Major areas inspected safety-related piping for Unit 2 GOLEY.J.L. BLAKE.J J Division of Engineering & Technical Programs 82/10/21 4pp 16357 193 24X Fiche 50-400/82/10/26, 8212070183
- 8212090348 Forwards IE Insp Repts 50-400/82-34 & 50-401/82-34 on 821012-15 No noncompliance noted VERRELLI,D H Division of Project & Resident Programs 82/10/27 UTLEY,E E Cardina Power & Light Co 2pp 16365 081 24X Fiche 50-400,82/10/27.8212090348
- --9212090355 IE Insp Repts 50-400/82-34 & 50-401/82-34 on B21012-15 No noncompliance noted Major areas inspected electrical components & sys work & work activities, quality records & followp on previous insp stem
 MERRIWEATHER, N. CONLOW, T. E. Division of Engineering & Technical Programs 82/10/22 3pp 16365 083 24X Fiche 50-400,82/10/27,8212090348
- 8208190240 IE Bulletin 82-03. Revision i. "Stress Cracking in Thick-Wall-Large-Diameter. Stainless Steel. Recirculation Sys Piging at 8MR Plants " Svc list encl
 DEYGUNG. R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462-163 24X Fiche 50-000. 82/10/28. 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards
- COBB.L I Division of Fuel Faculities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000.82/11/05.8208190245
- 8212070229 Ack receipt of 821027 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/82-31 VERRELLI.0 M Division of Project & Resident Programs 82/11/10 VILEY, E E Carolina Power & Light Co ip 16363 079 24X Fiche 50-400, 82/11/10, 8212070229
- --8212090237 Responds to NRC 820928 itr re violations noted in IE Insp Rept 50-400/82-31 Corrective actions maint logs initiated for warehouse & walkdown of storage areas performed PARSONS.R M Carolina Power & Light Co. 82/10/27 O'REILLY, J P Region 2. Office of Director 3pp 16363 080 24x Fiche 50-400, 82/11/10.8212090229
- --8212090244 Forwards IE Insp Repts 50-400/82-31 & 50-401/82-31 on 820907-10 & notice of violation VERRELLI,D M Division of Project & Resident Programs 82/09/28 JONES,J A Carolina Power & Light Co 2pp 16363 083 24X Fiche 50-400.82/11/10.8212090229
- --8212070247 Notice of violation from insp on 820907-i0 # Division of Project & Resident Programs 82/09/28 ip 16363 085 24% Fiche 50-400,82/11/10,8212090229
- --8212090256 IE Insp Repts 50-400/82-31 & 50-401/82-31 on 820907-10 Noncompliance noted failed to follow storage procedures for electrical penetrations HUNT-M D Division of Project & Resident Programs, CONLON, T E Division of Engineering & Technical Programs, 82/09/21 App 16363-086 24X Fiche 50-400, 82/11/10-8212090229
- 8208190251 JE Info Notice 82~44, "Glamification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411-199, 24x Fiche 50-000,82/11/18.8208190251
- B208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " 8vc list encl. DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche, 50-000, 82/11/26, 8208190256

- 820B190257 IE Info Notice 82-47, "Transportation of Type A G.ar'itic of Non-Fissile Radioactive Matl " Svc list encl CO88.L [Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fichs 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Contairne "
 Electrical Penetration Assemblies " Svc list encl
 DEVOUNG.R C Director's Office. Office of Inspection and
 Enforcement 82/12/03 Consolidated Edison Co of New York "
 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 %****, Sockets "Svc list encl JORDAN, E.L. Byvision of Engineering & Quality Assurance C2 ... Consolidated Edison Co of New York, Inc. 110pp 14462 144 : Fiche 90-000, 82/12/03, 82/88190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions of Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York | 127pp 16628 191 24X Fishe 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Under.olisis Relays Type ITE-27" Svc list enc! JORDAN E L Division of Engineering & Quality Assurance 62/1d Consolidated Edison Co of New York, Inc 108pp 16628 293 .4 Fiche 50-000, 82/12/20, 8208190268.
- 5 Reportable occurrences, LERs & related correspondence
- 8912070043 Interim deficiency rept re balted connections w/ezcessi-m gaps & ASTM A325 nuts on ASTM A490 bolts Initially reported on 820618 Bolt-nut combination acceptable & nonreportable Each gap being evaluated individually Next rept by 830415 PARSONS,R M Carolina Power & Light Co 82/11/30 O'REILLY, J F Region 2, Office of Director 2pp 16329 347 24X Fiche 50-400, 82/11/30,8212070043
- B212070305 Interim deficiency rept re defective welding in auxiliar, relay cabinets supplied by Sys Control Corp Initially reported on 82:101 Vendor evaluating Next rept will be submitted by 830204 Also reportable per Part 2: PARSONS, R H Carolina Power & Light Co 82/11/30 O'REILLY, J'Region 2, Office of Director ip 14343 158 24X Fiche 50-400, 82/11/30, 82:12070305
- 8212170328 Third interim deficiency rept re failure of seismic Cate; , I pressure gauges supplied by Dresser Industries Initially reported on 810923 Gauges placed on QA hold pending test results Also reportable per 100FR21 PARSONS, R M Carolina Power & Light Co 82/12/09 O'REILLY, J P Region 2, Office of Director 4pp 16496 (15 24X Fiche 50-400, 82/12/09,8212170328
- B212170183 Interim deficiency rept re 480-volt switchgear design of secondary disconnects. Initially reported on B21102 Disconnects in breaker cradle will be replaced Final rept expected 830131 Also reportable per Part 21 PARSONS.R H Carolina Power & Light Co 82/12/10 O'REILLY, J P Region 2. Office of Director 4pp 16450 184 24X Fische 50-400, 82/12/10.8212170183
- 8212220345 Deficiency rept re welding deficiencies in chemical & volcontrol sys pump supports Initially reported on 821129 Item determined not reportable per (OCFRSO 55(e) & 10CFRS) CHIANGL,N J Carolina Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director ip 14517 152 24X Fiche 50-400, 82/12/14, 8212220345
- 8212220432 Supplemental deficiency rept requesting extension to 831143 to submit 10CFR50 55(e) & 10CFR21 repts re shop welding defects on seismic Class I cable trays PARSONS.R M Carolina Power & Light Co 82/12/14 O'REILLY. J P Region 2, Office of Director ip 16503 316 24X Fiche 50-400.82/12/14,8218220432
- 8212300326 Interim deficiency rept re welding deficiencies in reactor coolant pump motor frame Initially reported on 821202 Hestinghouse evaluation continuing Next rept will be submitted by 830311 PARSONS:R K Caroline Power & Light Co B2/12/23 O'REILLY. J P Region 2. Office of Director ip 16594 266 24x Fiche 30-400, 82/12/23, 8212300326

- DOCKET 50~401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- C Utility Environmental Report (ER), amends & correspondence
- 8P12210422 Forwards Amend 5 to environ rept MCDUFFIE.M A Carolina Power & Light Co 82/12/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16494 001 Pax Fiche 50-400.82/12/15.8212210422
- --82;2210424 Amend 5 to environ rept * Carolina Power & Light Co 82/12/15 270pp 16494 003 24X Fiche 50-400,82/12/15,8212210422
- BP12280112 Forwards revised distribution list reflecting title, address & name changes for distribution of Amend 5 to environ rept Distribution made within 10 days after issuance of amend Affidavit encl I IHMERMAN, S.R. Carolina Power & Light Co. 82/12/23 EISENHUT, D.G. Division of Licensing Spp. 14544 183 24X Fiche 50-400, 82/12/23, 82122801132
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 82:12160036 Forwards addl info requested by NRC 82:120 ltr re vol reduction sys Info addresses all items necessary for DES input Remaining info will be submitted as available MCDUFFIE.M A Carolina Power & Light Co 82/12/13 DENTON.H R OFfice of Nuclear Reactor Regulation. Director 9pp 16446 207 24X Fichs 50-400.82/12/13.8212160036
- E NAC Safety Evaluation Report (SER), supply & correspondence
- G21208055B Forwards request for addl info re response to vol reduction sys for draft SER Response required by 821210 to complete safety review on schedule KNIOKTON.0 W Licensing Branch 3 82/11/24 UTLEY.E E Carolina Power & Light Co 5pp 16368 355 24X Fiche 50-400.82/11/24. 8212080558
- G Adjudicatory correspondence
- S212020336 Order directing NRC & util to answer questions on document copies % cost to enable ABLB to rule on intervenor requests to reconsider order re svc of documents MELLEY, J L. Atomic Safety and Licensing Board Panel 82/12/01 Office of the Executive Legal Director 2pp 16277 149 24X fiche 90~400,82/12/01,8212020336
- BP12100099 Advises that name will be added to applicant syr list for future filings Listed documents encl 8vc list only encl MAXTER. I A Shaw. Pittman. Potts & Trowbridge BAXTER. I A Carolina Power & Light Go 82/12/07 LOTCHIN,P Affiliation Unknown 3pp 16379 186 24X Fiche 50-400.82/12/07.8212100099.
- BQ12170073 Forwards Generic Ltr 82-14 setting forth schedule of number of copies of documents required to be submitted to NRC.in response to ASLB 821201 inquiry BARTH.C A Hearing Branch 1 82/12/14 KELLEY.J L . BRIGHT.G D . CARPENTER.J H Atomic Safety and Licensing Board Panel 1p 16452 326 24X Fichs 50-400.82/12/14.8212170073
- 6212230366 Response to ASLB 621201 order seaking info on document copies & costs re serving documents on intervenors Certificate of Svr encl Related correspondence JONES.R E. FLYNN.S F. Carolina Power & Light Co. 62/12/15 Atomic Safety and Licensing Board Panel. Opp. 16511 197 24X Fishe 50-400.62/12/15.8212830366
- 8212210222 Motion for codification of admitted contentions Request made for convenience of all parties & ASLO & in fairness to applicants who bear burden of proof re each contention admitted for litigation Certificate of Stv encl
 D'NEJLL.J H Carolina Power & Light Co D'NEJLL.J H Shaw,
 Pittman. Potts & Trowbridge 82/12/17 Atomic Safety and
 Licensing Board Panel 78pp 16484 101 24X Fiche 50-400, 82/12/17, 8212210222
- 82/12270222 Forwards Chapters 8 & ii of environ rept. through Amend 5 Chapters cover benefits & costs & provide analysis of savings for utilizing plants from 1986 1995 Svc list encl BAXTER.T A Shaw, Pittman. Potts & Trowbridge BAXTER.T A Carolina Power & Light Co 82/12/21 KELLEY.J L , BRIGHT.C D . CARPENTER.J H Atomic Safety and Licensing Board Panel 19pp 16595 097 24X Fiche 50-400,82/12/21,8212270222

Q Inspection reports. IE Bulletins & correspondence

- 8212070183 Forwards IE Insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs B2/10/26 UTLEY, E E Carolina Power & Light Co Rpp 16359 191 24X Fiche 50-400, 82/10/24, 8212070183
- --8212070186 IE insp Repts 50-400/82-33 & 50-401/82-33 on 821004-05 No nancompliance noted Major areas inspected safety-related piping for Unit 2 COLEY, J L . BLAKE, J J Division of Engineering & Technical Programs 82/10/21 4pp 16359 193 24X Fichs 50-400, 82/10/26, 8212070183
- B212090348 Forwards IE 1nsp Repts 50-400/82-34 & 50-401/82-34 on B21012-15 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 82/10/27 UTLEY, E.E. Carolina Power & Light Co. 2pp. 16365 081 24X Fiche 50-400, 82/10/27, 8212070348
- --B212090355 IE Insp Repts 50-400/82-34 & 80-401/8R-34 on 821012-15 No noncompliance noted Major areas inspected electrical components & sys work & work activities, quality records & followup on previous insp item

 MERRIKEATHER, N. CONLON. T.E. Division of Engineering & Technical Programs 82/10/22 Spp 16365 089 24X Fichs 50-400, 82/10/27, 8212090348
- 8208190240 IE Bulletin BQ-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Bteel, Recirculation Sys Piping at BWR Plants " Byc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28.8208190240
- 8208190245 IE Info Notice B2-42. "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters" Byo list enc!

 COBB.t. I Division of Fuel Facilities. Materials & Safeguards 62/11/05 Consolidated Edison Co of New York. Inc 110pp 16372 142 24% Fiche 50-000.82/11/05.8208190245
- B212090229 Ack receipt of B21027 ltm informing NRC of steps taken to correct violations noted in IE Imsp Rept 50-400/82-31
 VERRELLI,D M Division of Project & Resident Programs B2/11/10
 UTLEY,E E Carolina Power & Light Co ip 16363 079 24X
 Fiche 50-400, 82/11/10, 8212090229
- --8212070244 Forwards IE Insp Repts 50-400/82-31 & 50-401/82-31 on 820907-10 & notice of violation VERRELLI,D M Division of Project & Resident Programs 62/09/28 JONES,J A Carolina Power & Light Co 2pp 16363 083 24X Fiche 50-400,82/11/10,8212090229
- --8212070249 Notice of violation from insp on 820907-10 * Division of Project & Resident Programs 82/09/28 ip 16363 085 24% Fiche 50-400, 82/11/10:8212090229
- ---B212090254 IE Insp Repts 50-400/B2-31 & 50-401/B2-31 on 820907-10 Noncompilance noted failed to follow storage procedures for electrical penetrations HUMT, M D Division of Project & Resident Programs CDNL-DN, T E Division of Engineering & Technical Programs 82/09/21 App 16363 086 24% Fiche 50-400, 82/11/10/B212090229
- B208190251 IE lnfo Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN:E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000, 82/11/18,8208190251
- 8POB190256 IE Info Notice 82~46. "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24x Fiche 50-000,82/11/26,8208190256.
- BEO8190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguerds, B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257
- 8208190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208170257

DOCKETED ITEMS

- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDÁN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp. 16462 064 24) Fiche 50-000,82/12/03.8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Qas Monitoring " 8vc list encl DEYOUNG.R C Director's Office of Inspection and Enforcement 62/12/16 Consolidated Edison Co of New York, Inc 127pp 14628 191 24X Fiche 50-000,82/12/16.8208190267
- 8208190268 IE Info Notice 92-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24: Fiche 50-000.82/12/20.8208190268
- S Reportable occurrences. LERs & related correspondence
- SRI2070043 Interim deficiency rept re boited connections of excessive gaps & ASTM A325 nuts on ASTM A490 boits Initially reported on B20618 Boit-nut combination acceptable & nonreportable Each gap being evaluated individually Next rept by 830415 PARSONS.R M Carolina Power & Light Co 82/11/30 O'REILLY.J P Region 2. Office of Director 2pp. 16329'347 24X Fithe.50-400,82/11/30,8212070043
- 8212070305 Interim deficiency rept re defective welding in auxiliary relay cabinets supplied by Sys Control Gorp Initially reported on 821101 Vendor evaluating Next rept will be submitted by 830204. Also reportable per Part 21 PARSONS.R M Carolina Power & Light Co 82/11/30 O'REILLY, J P Region 2. Office of Director 1p 16343 158 24X Fiche 50-400.82/11/30.8212070305
- 8212170183 Interim deficiency rept re 480-volt switchgoar design of secondary disconnects Initially reported on 821102 Disconnects in breaker cradle will be replaced Final rept expected 830131 Also reportable per Part 21 PARSONS:R M Carolina Power & Light Co 82/12/10 0/REILLY; J P Region 2. Office of Director 4pp 16450 184 24X Fiche 50-400,82/12/10,8212170183
- BP12220345 Deficiency rept re-welding deficiencies in chemical & volcontrol sys pump supports Initially reported on 821129 Item determined not reportable per IOCFR50 35(e) & 10CFR21. CHIANGI,N J Carolina Power & Light Co 82/12/14 8'REILLY, J P Region 2. Office of Director Ip 16517 152 24X Ficha 50-400,82/12/14,8212220345
- 8P12220432 Supplemental deficiency rept requesting extension to 831002 to submit 10CFR30 55(e) & 10CFR21 repts re shop welding defects on seismic Class I cable trays PARSONS,R M Carolina Power & Light Co 82/12/14. O'REILLY, J P Region 2. Office of Director Ip 16503 316 24X Fiche 50-400,82/12/14.8212220432
- 8212300326 Interim deficiency rept re welding deficiencies in reactor coolant pump motor frame Initially reported on 821202 Westinghouse evaluation continuing Next rept will be submitted by 830311 PARSONS.R M Carolina Power & Light Co 82/12/23 O'REILLY, J P Region 2. Office of Director ip 16594:266 24X Fiche 50-400, 82/12/23.8212300326
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- 8212090305 Provides final rept on resolution of issues re IE Bulletins 79-28. "Possible Maifunction of NAMCO Model EAIBO Limit Switches at Elevated Temps" & 80-23. "Failures of Sciencid Valves Mfg by Valcor Engineering Corp "
 SPENCER.W C Virginia Electric & Power Co 82/11/01 O'REILLY, J P Region 2. Office of Director 2pp 16365.133 24X
 Fichs.50-404.82/11/01.8212090305
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR
- F Security, madical, emergency & fire protection plans
- 8212060249 Forwards IE Insp Rept 50-409/82-06 on 820510-14 % notice of violation KEPPLER.J G Region 3. Office of Director 82/11/16 LINDER.F W Dairyland Fower Cooperative 3pp 16312 288 24X Fiche 50-409, 82/11/16, 8212060249

- --8212060250 Notice of violation from insp on 820510-14 KEPPLER, J O Region 3, Office of Director 82/11/16 3pp 16312 291 24X Fiche 50-409,82/11/16.8212060249
- --8212060252 IE Insp Rept 50-409/82-06 on 820510-14 Noncompliance noted imadequate shift staff augmentation capability & inadequate meteorological measurements procedures PAGLIARO, J A. ORANT, W B. AXELSON, W L. Division of Emergency Preparedness & Operational Support 82/11/10 16pp 16312 294 24% Fiche 50-409, 82/11/16,8212060249
- B212190015 Forwards IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted HIND J A Division of Emergency Preparedness & Operational Support 82/11/23 LINDER, F W Dairyland Power Cooperative 2pp 16421 181 24X Fiche 50-409.82/11/23.8212150015
- --8212150019 IE Emergency Plan Bafety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted Major areas inspected 820903 site emergency plan PAGLIARO. J A. AXELSON, W. L. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/11/18 31pp 16421 183 244 Fiche 50-409, 82/11/23, 82:2150015
- 8212070152 Forwards supplemental info re emergency offsite facility (EOF), per R Dudley 821202 telcon request EDF considered both interim & permanent facility LINDER, F Dairyland Power Cooperative 82/12/02 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 16326 224 24X Fiche 50-409, 82/12/02, 8212070152
- 8212080169 Forwards Amend 30 to License DPR-45 & notice of issuance Amend revises requirement to maintain guard training & qualification plan to be implemented within 60 days of approval & qualification of all security personnel CRUTCHFIELD. D Operating Reactors Branch 5 82/12/06 LINDER, F Dairylend Power Cooperative 4pp 16354 075 24X Fiche 50-407, 82/12/06, 8212080169
- --8212080174 Amend 30 to License DPR-45, including requirement to maintain guard training & qualification plan to be implemented within 60 days of issuance & requiring security personnel to be qualified within 2 yrs of approval CRUICHFIELD. Departing Reactors Branch 5 82/12/06 3pp 16384 080 24X Fiche 50-409,82/12/06.8212080169
- ---8212080178 Notice of issuance & availability of Amend 30 to License DPR-45 * Operating Reactors Branch 5 82/12/06 2pp 16354 083 24X fiche 50-409,82/12/06.8212080169
- 8212220315 Releases public version of radiological emergency response plan implementing procedure
 FELTON. JM Division of Rules and Records 62/12/10 Document Management Branch ip 16523 248 24X Fiche 50-409, 82/12/10.
- --B212220323 Forwards public version of Issue O to Radiological Energency Response Plan Implementing Procedure EFP-18, "Operation of Technical Support Ctr/Emergency Offsite Facility Data Acquisition Sys "
 LINDER,F Dairyland Power Cooperative 82/11/29 CRUTCHFIELD,D Operating Reactors Branch 5 p 16523 249 24X Fiche 50-409,82/12/10,8212220315
- ~-8212220331 Public version of Issue O to Radiological Emergency Response Plan Implementing Procedure EPP-18, "Operation of Technical Support Ctr/Emergency Offsite Facility Data Acquisition Sys." a Dairyland Power Cooperative 82/11/17 4pp 14523 251 24X Fiche 50-409,82/12/10,8212220315
- 8212210216 Forwards Amend 31 to License DPR-45, safety evaluation & notice of issuance & availability Amend approves revisions to physical security plan & safeguards contingency plan Encis withheld (ref 100FR73 21)
 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/14 LINDER, F Dairyland Power Cooperative 5pp 16485 009 24X
 Fiche 50-409.82/12/14,8212210216
- B212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J. G. Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000,82/12/16,821230304

- P Operating license stage documents & correspondence
- 8212020086 "SEP Topic VII-3.Electrical.Instrumentation & Control Features of Sys Required for Safe Shutdown LACOMR." Interim 1991 HAROLDSON, R O. FARMER, F Q EORG, Inc FIN A-6425 8212020086 82/10/31 SCHOLL, R F Office of Nuclear Reactor Regulation, Director 17pp 16309 063 24X Fiche 50-409.82/10/31,8212020086
- B212140001 Add1 response to FQIA request for five categories of documents re BEP Forwards documents listed in App A No documents iocated sub, to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON. J M Division of Rules and Records B2/11/03 GALLO, Jisham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000,82/11/03,6210140001
- ---7907180391 Submits results of numerical values for spectral ordinates for facility WIGHT.L H TERA Corp 79/07/11 REITER.L Geosciences Branch 7pp 16436 291 24X Fiche 50-000, 82/11/03, 8212140001
- --7908090435 Forwards individual plant summaries re seismic capability & recommended interim actions Oldar BEP plants have less inherent margins to withstand lateral dynamic loads DAVIS.D K Systematic Evaluation Program Branch (Pre 791030) 79706/18 VOLLMER.R H Assistant Director for Systematic Evaluation Program (Pre 791030) 5pp 16434 321 24X Fiche 50~000,82/11/03,8212140001
- --8002200975 Notifies that revipe & performance of audit calculations to be continued per contract & preliminary review work to be completed at LaCrosse Code used for reanalysis of piping sys requires benchmarking per code verification program SHAO, L. C. Assistant Director for Engineering Programs 79/10/30 EISENHUT. D. O. Division of Operating Reactors 1p. 16435 111 24X Fiche 50-000:82/11/03,8212140001
- --8003310489 Requests approval of proposed show cause order re seismic design changes Risk-benefit evaluation entirely appropriate for decisions MALSCH.M Q Office of the Executive Legal Director 80/02/19 AHEARNE.J F , GILINSKY, V , KENNEDY, R T Commissioners 2pp 16434 268 24X Fiche 50-000,82/11/03,8212140001
- --8009170164 Advises that util 800804 rept. "Seismic & Structural Analysis of LACBUR & Oenoa 3 Stacks." indicates that stack rests directly un foundation soil Info conflict w/740111 rest Factual determination should be obtained from util LEAR.0 & Hydrologic & Geotechnical Engineering Branch 80/09/08 CRUTCHFIELD,D Operating Reactors Branch 5 ip 16434 267 24X Fiche 50-000,82/11/03,8212140001
- ---B203310470 Forwards SEP seismic completion plan to perform review parallel u/license efforts to complete SEP Topic III-6, seismic design considerations for Group II plants HERMANN. R Systematic Evaluation Program Branch 82/03/08 RVSSELL. W T Gystematic Evaluation Program Branch 5pp 14434 276 24X Fiche 50~000.B2/11/03.B212140001
- B212140149 Discusses SEP site-specific spectra project Project in final stages Comments from Peer Review Orang & all other comments should be received by 791130 Listing of references re site-specific spectra (SEP Topic III-6) encl LEVIN:H A Systematic Evaluation Program Branch 79/11/13. EISENHUT, D O Division of Operating Reactors 4pp 16436 300 24X Fiche 50-000, 82/11/03, 8212140001
- 8212020328 Forwards final SER for SEP Hydrology Topics II-3 A.II-3 B, II-3 B 1 & II-3 C Development of emergency plans & Tech Specs for site flooding & low water level required to complement emergency svc water supply sys CRUTCHFIELD.D Operating Reactors Branch 5 82/II/12 LINDER, F Bairyland Power Cooperative 24pp 16278 185 24X Fiche 50-409, 82/II/12, 8212020328
- --8209290122 "Hydrological Considerations (BEP, II-3A, B, B, C) Dairyland Fower Cooperative, LACBWR, "technical evaluation rept SCHERRER, J S Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-427 82/09/27 STALEY, Q NRC No Detailed Affiliation Given 50pp 16278 208 24X Fiche 50-409, 82/11/12.8212020328
- 8212080228 Forwards "1982 Evaluation of LACBHR" for review TAYLOR, J Dairyland Power Cooperative 82/11/22 KEPPLER, J O Region 3, Office of Director in 16354 137 24X Fiche 50-409, 82/11/22, 8212080228
- --8212080250 "1982 Evaluation of LACBWR " * Institute of Nuclear Power Operations 82/10/31, 35pp 16354 138 24X Fiche 50-409,82/11/22,8212080228

- 8212030D24 Submits add1 info re draft technical evaluation rept for control of heavy loade.per 821116 telcon Diagram of load paths handled by reactor bldg ceans encl LINDER.F Dairyland Power Cooperative 82/11/24 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 16304 330 24X Fiche 50-409. 82/11/24.8212030D24
- 8212020245 Forwards final evaluation of SEP Topic III-4 A. "Tornado Missiles " Sys & components inadequately protected from tornado missiles CRUTCHFIELD. O Operating Reactors Branch 5 82/11/27 LINDER.F Dairyland Power Cooperative 16pp 16274 073 24X Fiche 50-407,82/11/27.8212020245
- B212070110 Submits add1 info on post-accident containment radiation dose, per B21201 telcon Electrical equipment requiring environ qualification located in containment bldg reviewed for beta radiation sensitivity
 LINDER, F Dairyland Fower Cooperative B2/12/02 CRUTCHFIELD, D Operating Reactors Branch 5 1p 16327 362 24X Fiche 50-409, 82/12/02, 8212070110
- 8212080169 Forwards Amend 30 to License DPR-45 & notice of issuance Amend revises requirement to maintain guard training & qualification plan to be implemented within 60 days of approval & qualification of all security personnel CRUTCHFIELD.D Operating Reactors Branch 5 82/12/06 LINDER.F Dairyland Power Cooperative 4pp 16354 075 24X Ficher 50-409, 88/12/06, 8212080169
- --B212080174 Amend 30 to License DPR-45, including requirement to mainta guard training & qualification plan to be implemented within 60 days of issuance & requiring security personnel to be qualified within 2 yrs of approval CRUTCHFIELD.D Operating Reactors Branch 5 82/12/06 3pp 14354 080 24x Fiche 50-409, 92/12/06, 9212080169
- --8212080178 Notice of issuance & availability of Amend 30 to License DPR-45 > Operating Reactors Branch 5 82/12/06 2pp 16354 083 24X Fichs 50-409.82/12/04.8212080169
- B212150115 Forwards draft evaluation of SEP Topic III-7 B re design codes/design criteria & load combinations Review should be conducted to determine applicability of codes & ability of structures to resist increased loads CRUTCHFIELD.D. Operating Reactors Branch 5 B2/12/09 LINDER, F Dairy land Power Cooperative | Itpp | 14429 114 24X Fiche 50-409, 82/12/09, 8212150115
- --8209230258 "Design Codes, Design Criteria, & Loading Combinations (SEP, III-78), LaCrosse (Genoa) Nuclear Generating Station, "technical evaluation rept STILKELL.T C Franklin Institute/Franklin Research Center NRC-03-79-18 TER-05257-328 82/09/20 PERSINKO, D NRC No Detailed Affiliation Given 244pp 16429 125 24X Fiche 50-409,82/12/09,8212150115
- 8212130154 Forwards BER of SEP Topic VI-4, "Containment Isolation Bys Four deviations from review guidelines identified Evaluation will be basic input to integrated safety assessment CRUTCHFIELD.D Operating Reactors Branch 5 82/12/09 LINDER, F Dairyland Power Cooperative 25pp 16423-242 24X Fiche 50-409, 82/12/09, 8212150154
- B212170204 Advises of plans to modify waste disposal bldg, due to need for greater flexibility in spent resin handling. FEB, NUREG-0191, Bection 3 6 4 should be revised to reflect mod. LINDER, F Dairyland Power Cooperative 82/12/10 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 16459 321 24X Fiche 50-409, 82/12/10, 82/2170204
- 8212180039 Forwards evaluation of SEP Topic III-3 A, "Effects of High Water Levels on Structures" Containment bldg will remain undamaged by design basis flood concurrent w/3-ft high wave CRUTCHFIELD, D Operating Reactors Branch 5 82/12/13 LINDER, F Dairyland Power Cooperative. 5pp 16421 325 24X Fiche 50-409, 82/12/13, 82(2)50039
- 8212210216 Forwards Amend 31 to License DPR-45, safety evaluation & notice of issuance & availability Amend approves revisions to physical security plan & safeguerds contingency plan Encls withheld (ref 10CFR73.21)
 CRUTCHFIELD.D Operating Reactors Branch 5 82/12/14 LINDER.F Dairyland Power Cooperative 5pp 16485 009 24X
 Fiche 50-409,82/12/14.8212210216

- 8212280059 Forwards Revisson I to "Belamic & Stress Analysis of LACBWR HPCS Discharge Line Piping Sys " Rept discusses discrepancies identified in RO 82-05 & noted between as-analysed & as-built conditions of piping sys LINDER, F Dairyland Power Cooperative 62/12/16 CRUTCHFIELD, D Operating Reactors Branch 5 12pp 16562 323 24X Fiche 50-409,82/12/16.8212280059
- --8212280061 "Seismic & Stress Analysis of LACBUR MPCS Discharge Line Piping Sys." Revision I DRLIGADD.A., HUSAIN. I Nuclear Energy Service, Inc. NES 81AD091 R01 77/05/10 138pp 16562 335 24X Fiche 50-409,82/12/16, 8212280059
- 8212280434 Board Notification 82-123 forwards USOS open file rept on "Probabilistic Estimates of Max Acceleration & Velocity in Rott in Contiguous US"

 MIRAGLIA.F J Assistant Director for Safety Assessment 82/12/17 Atomic Safety and Licensing Board Panel 3pp 16592 001 24X Fiche 50-409.82/12/17.8212280434
- --8212280438 Open File Rept 82-1033. "Probabilistic Estimates of Max Acceleration & Valocity in Rock in Continguous US " ALGERMISSEN.8., PERKINS.D M , THENHAUS.P C Interior, Dept of, Geological Survey 82-1033 82/12/31 113pp 14592 006 24X Fiche 50-409,82/12/17.8212280434
- 8212290320 Forwards BER & nonproprietary & proprietary versions of "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11.8-40)." Proprietary version withheld (ref 10CFR2 790) CRUTCHFIELD.B Operating Reactors Branch 5 82/12/21 LINDER.F Dairyland Power Cooperative. 3pp 16585 232 24X Fiche: 50-409.82/12/21,8212290320
- --B212290323 SER supporting util environ qualification of safety-related electrical equipment.

 4 Office of Nuclear Reactor Regulation, Director 62/12/21 Spp 16585-235 24X Fiche: 50-409, 82/12/21, 8212290320
- ---8207010410 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11,8-60)," technical evaluation rept CRANE, C J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-05257-464 82/06/25 LE,N B NRC No Detailed Affiliation Given 266pp 16586 001 24X Fiche 50-409,82/12/21.8212290320

Q Inspection reports. IE Bulletins & correspondence

- 8208190240 IE Builetin 92-03. Revision 1, "Btress Cracking in Thick-Wall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BUR Plants." Syc list enci DEYQUNG. R.C. Director's Office, Office of Inspection and Enforcement 92/10/28 Consolidated Edison Co of New York. Inc 112pp. 15462 163 24% Fichs 50-000, 82/10/28, 8208190240
- 8212060051 Forwards IE Insp Rept 50-409/82-17 on 821004-15 & notice of violation
 PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/11/01 LINDER.F.W Dairyland Power Cooperative 2pp 14314 080, 24x Fichs 50-409,82/11/01,8212060051
- --8212060055 Natice of violation from insp on 821004-15 PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 82/11/01 ip 16314-082 24X Fichs 50-409,82/11/01, 8212060051.
- --B212060062 IE Insp Rept 50-409/82-17 on 821004-15 Noncompliance noted failure to perform monthly strontium analysis of liquid waste water composite NICHOLSON, N. A., LYNCH, J. L., BCHUMACHER, M. C. Division of Emergency Preparedness & Operational Support. 82/10/28 11pp 16314 083 24X Fiche 50-409,82/11/01,8212060051
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters." Svc list enc!
 CO89.L. I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372:142 24X Fichs 50-000,82/11/05,8208190245
- 8212060249 Forwards IE Insp Rept 50-409/82-06 on 820510-14 & notice of violation KEPFLER. J. O Region 3. Office of Director. 82/11/16 LINDER. F. W Rairyland Power Cooperative 3gg 16312 288 24K Fichs 50-407.82/11/16.8212060249.
- --8212060250 Notice of violation from insp on 820510-14 KEPPLER, J. Q. Region 3. Office of Director. 62/11/16 3pp 16312 271 24X Fiche: 50-409, 62/11/16, 8212050249.

- ~-8212060292 IE Insp Rept 50-409/82-06 on 820510-14 Noncompliance noted inadequate shift staff augmentation capability & inadequate meteorological measurements procedures PAGLIARO, J A. ORANT, H B. AXELSON, W L. Division of Emergency Preparadness & Operational Support 82/11/10 16pp 16312 274 24% Fiche 50-409,82/11/16.8212060249
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance B2/11/18 Consultdated Edison Co of New York, Inc. 109pp 16411
- B212150019 Forwards IE Emergency Plan Safety Evaluation Rept 50-409/82-15 during Nov 1982 No noncompliance noted HIND J A Division of Emergency Preparedness & Operational Support B2/11/23 LINDER,F W Pairyland Power Cooperative 2pp 16421 181 24X Fiche 50-409.82/11/23.8212150015
- --B212150019 IE Emergency Plan Safety Evaluation Rept 50-409/02-15 durin Nov 1982 No noncompliance noted Major areas inspected 820903 site emergency plan PAGLIARO, J. A., AXELSON, W. L., PAPERIFLLO, C. J. Division of Emergency Preparedness & Operational Support 82/11/18 31pp 16421 183 24X Fiche 50-409, 82/11/23, 82(2150015
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocks " 8vc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000.82/11/26,8208190256
- B20B190257 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Metl " Svc list encl CD8B.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 820B190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYOUNG.R C Director's Office, Office of inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- BPD8190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8212090433 Ack receipt of 821115 itr providing info on NUREQ-0737. Test Action Item II F i I re SPING equipment as requested in IE Insp Rept 50-40782-14 PAUL, R A. Region 3. Office of Director 82/12/03. SHAFER.P W Dairyland Power Cooperative ip 16364 278 24X Fiche 50-409.82/12/03.8212090433
- --B212090440 Forwards info on NUREG-0737. Item II F 1 I re SPING equipment as requested in IE Insp Rept 50-409/82-14 SPING-3 moved to stack shack replacing SPING-4 as normal operations stack particulate I-i31 & nobis gas monitor SHAFER.P W Dairyland Power Cooperative 82/11/15 PAUL.R Region 3. Office of Director & SHAP 16364 279 24X Fiche. 50-409.82/12/03.8212090433
- 8212140410 Ark receipt of 821124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-17 PAPERIELLO.C J Division of Emergency Preparedness & Operational Support 82/12/08 LINDER,F W Darrylland Power Cooperative Ip 16404 330 24X Fiche 50-409.82/12/08.8212140410
- ---8212140417 Responds to NRC 821101 ltr re-violations noted in IE Insp. Rept 50-407/82-17 Corrective actions grevimetric strontium separation & analytical procedure replaced u/less complicated inn-exchange/gravimetric procedure LINDER.F Dairyland Power Cooperative 82/11/24 PAPERIELLO.C J Division of Emergency Preparadness & Operational Support 5pp 16404.331 24X Fiche 50-409.82/12/08.8212140410
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring," Svc list sncl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co, of New York, Inc 127pp 14628-191 24X Fiche 50-000, 82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27." Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268

- @212280091 Ack receipt of 821118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-16
 MILLER, J.R. Division of Engineering & Technical Programs 82/12/20
 LINDER, F.W. Dairyland Power Cooperative 2pp 16564 231 24X
 Fishe 50-409, 82/12/20, 8212280091
- --B212280095 Forwards response to NRC 821026 ltr re violations noted in IE Insp Rept 50-409/82-16 Response withheld (ref 10CFR73 21) LINDER,F Dairyland Power Cooperative 82/11/18 MILLER, J.R. Division of Engineering & Technical Programs ip 16564 233 24X Fichs 50-409, 82/12/20, 8212280091
- R Periodic operating reports & related correspondence
- G2:12290220 Forwards monthly operating rept for Oct 1982 LINDER, F Dairyland Power Cooperative 82/11/10 Management Information Branch 1p 14578 080 24Y Fiche 50-409, 82/11/10,
- --8212270222 Monthly operating rept for Oct 1782
 GABON, G R Dairyland Power Cooperative 82/11/10 Bpp
 16578 081 24X Fiche 50-409, 82/11/10, 8212270220
- S Reportable occurrences, LERs & related correspondence
- B::12280253 Forwards LER 82-020/03L-0 Detailed event analysis submitted LINDER.F Dairyland Power Cooperative 82/12/16 KEPPLER.J G Region 3, Office of Director ip 16561 181 24X Fithe 50-409.82/12/16.8212280283
- --8212280256 LER 82-020/03L-0 on 821117 & 20, vacuum pump which maintains isokinetic flow rate to stack activity monitors tripped Caused by overheating Air blower set up to cool motor ODODMAN,L S Dairyland Power Cooperative 82/12/14 Region 3, Office of Director 2pp 16561 182 24X Fiche 50-409,82/12/16,8212280253
- DECKET 50-410 NINE MILE POINT NUCLEAR STATION. UNIT 2
- A Application/construction stage documents & correspondence
- #3211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL 5 holders of CP re transmittal of NUREO-0753 & NOREO-0763 Svc list encl W/o stated encl EISEMHUT, D & Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 92/11/15, 9211230066
- B212100207 Clarifies position on implementation of NF-2130 rebulk mate certification Policy will be documented in PBAR amend

 DISE.D F Miagara Mohawk Power Corp B2/12/06 SCHWENCER, A Licensing Branch 2 ip 16376 215 24X Fiche 50-410.82/12/06.8212100207
- Ce Inspection reports, IE Bulletins & correspondence
- B£r08190240 IE Bulletin 82-03.Revision i. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation 948 Piping at 84R Plants "Svc list encl
 UEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 142p 16462 163 24X Fiche 50-000.82/10/28.8208190240
- B2*08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 % Model 802 Thermaluminescent Dosimeters " Svc list cnc! COSB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05,8208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Fiercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199, 24X Fiche 50-000, 82/11/18, 8208190251
- 8:'08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocks " Svc list encl Director's Dffice, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 1641 065 24X Fichs 50-000, 82/11/26, 8208190256

- 8212140490 Forwards IE Insp Rept 50-410/82-12 on 821012-1112 & notice of violation STAROSTECKI. R Division of Project & Resident Programs 82/11/27 KHODE. 0 K Niagara Mohawk Power Corp 2pp 16404 001 24X fiche 50-410.82/11/29.8212140490
- --8212140492 Notice of violation from insp on 821012-1112 * Division of Project & Resident Programs 82/11/29 1 16404 003 24% Fiche 50-410, 82/11/29, 8212140490
- --8212140495 IE Insp Rept 50-410/82-12 on 821012-1112 Noncompliance noted failure to submit planner package for safety-related piping to GC documentation supervisor for review & approval SCHULZ.R D , KISTER, H B Division of Project & Resident Programs 62/11/20 Gpp 16404 004 24X Fiche 50-410,82/11/29,8212140470
- BC:08190257 IE Info Notice 82-47, "Transportation of Type A Quantities or Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, B208190257
- B20B190259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list enct DEVOUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24% Fiche 50-000, 82/12/03, 820B190259
- BPOB190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000. 82/12/03. 8208190261
- GP:12190227 Notification of 821220 meeting w/util in Syracuse.NY to discuss SALP KISTER:H Division of Project & Resident Programs 82/12/09 Division of Project & Resident Programs 2pp 16446 361 24X Fiche 50-410.82/12/09.9212150227
- SPOB190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Oas Monitoring "Sec list encl Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co. of New York, Inc. 127pp 16428 191 24% Fichs 50-000.02/12/16.8208190267
- BP:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc!
 JURDANIE L Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x
 Fiche 50-000, 82/12/20, 8208190268
- B Reportable occurrences, LERs & related correspondence
- B212030166 Interim deficiency rept re ITT Orinnell Category II planner for Category I work Initially reported on 821026 Evaluation of effects of flooding due to failure in progress Final rept expected by 830114

 MANNO.5 F Niagara Mohawk Power Corp 82/11/24 STAROSTECKI,R

 Division of Project & Resident Programs 2pp 16306 102 24X

 Fithe 50-410, 82/11/24, 8212030166
- 82'12140093 Interim deficiency rept re issuance of planners by ITT Grinnell w/o prior approval by SEM Initially reported on H2[10] Work restarted as planners released by SEM Final rept will be submitted by 830131 MANNO.S F Niagara Mohauk Power Corp 82/12/01 STAROSTECKI,R Division of Project & Resident Programs 2pp 16408 271 24X Fiche 50-410,82/12/01,8212140073
- BP12140372 Interim deficiency rept re enhancement of ITT Grinnell weld radiographs per IE Bullotin 82-01. Revision 1. Suppl 1 Initially reported on 821108 Review of Grinnell site radiographs in progress Final rept expected by 830131 MANNO.S F Niagara Mohawk Power Corp 82/12/06 STAROSTECKI.R Division of Project & Resident Programs 2pp 16401 154 24X Fiche 50-410.82/12/06.8212140372
- B212280963 Interim deficiency rept to inadequate pressure transducers/ transmitters mounted on post-LOCA hydrogen recombiners Initially reported on 621119 Final rept will be submitted by B30211 Also reported per Part 21 MANNO.S F Niagara Mohauk Power Corp 62/12/14 STAROSTECKI.R Division of Project & Resident Programs 2pp 16560 058 24X Fiche 50-000.82/12/14.8212280363

--8212280373 Part 21 rept re inadequate pressure transducers/transmitters mounted on post-LGCA hydrogen recombiners Transducers showld be replaced w/nuclear rated transducers Engineering field bulletin to be issued by 821029

EMPEY.D C Roctuell international Corp 82/10/21 CDLLINS, J Region 4. Office of Director, 2pp 16560 060 24X Fiche 50-000,82/12/14.8212280363

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8212170410 Notification of 821208 meeting w/wtil in Bethenda.MD to inform applicant of project manager assignment in Licensing Branch 3 to fatility LAZO,L Licensing Branch 3 82/12/06 KNIOHTON, O W Licensing Branch 3 3pp 16478 155 24X Fiche 50-412.82/12/06.8212170410
- 8212220403 Forwards amend to application for OL, consisting of general info required by environ rept.FSAR & 100FR50 & 51 MODLEVER: E J Duquesne Light Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16504 291 24X Fiche 50-412.82/12/13.8212220403
- --8212220404 Amend to application for OL consisting of general info required by environ rept.FSAR & 100FRSO & 51 WGDLEVER.E J Duquesne Light Co 82/12/15 30pp 16504 293 24% Fithe 50-412, 82/12/15,8212220403

M Antitrust correspondence

- 8212220283 Forwards info for OL antitrust review per Generic Ltr 82-14 Encl submittal addresses questions in Reg Ouide 9 3 ac applicable to all facility owners for period since CP antitrust review WOOLEVER.E J Duquesne Light Co 82/12/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 128pp 16516 117 24X Fiche 50-412, 82/12/15, 8212220283
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Mall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants " Syc list and DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 30-000,82/10/28,8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list uncl COBS.L I Division of Fuel Pacilities, Materials & Safeguards 822/11/05 Consolidated Edison Co. of New York Inc 110pp 14372 142 4X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24) Fiche 50-000.82/11/18:8208190251
- 8212060189 Forwards IE Insp Rept 50-412/82-13 on 821004-1102 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 82/11/22 WD0LEVER.E J Duquesne Light Co 2pp 16313 066 24X Fiche 50-412,82/11/22,8212060189
- --8212060192 IE Insp Rept 50-412/82-13 on 821004-1102. No nencompliance noted Major areas inspected welding activities, nondestructive exams, piping support installation procedure review, site bours & unresolved items MALTON, G., TRIPP, L. Division of Project & Resident Programs 62/11/19 App. 16313-068 24X Fiche 50-412.82/11/22,8212060189
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYQUNO.R C Director's Office. Office of Inspection and Enforcement. B2/11/26 Consolidated Edison Co of New York, Inc 127pp 1641
- B208190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! CDB9rL 1. Division of Foeb Facilities, Materials & Bafeguards B2711/30 Consolidated Edison Co of New York, inc 355pp 14387.028 24X Fiche: 50-000,82/11/30,8208190257

- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYDUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 820B190261 IE Info Notice 82-40, "Failures of Agastat GR 0095 Relay Sockets "Svc list enc! JERDAN EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03,8208190261
- 8212140424 Ack receipt of 821020 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-412/82-09 STAROSTECKI, R Division of Project & Resident Programs 82/12/07 WOOLEVER, E J Duquesne Light Co 2pp 16404 013 24% Fiche 50-412, 82/12/07, 8212140424
- --B212140427 Responds to NRC 820914 ltr re violations noted in IE Insp Rept 30-412/82-D9 Corrective actions engineering evaluation of condition of affected seating will be performed & ESHC cards will be issued for valves requiring maint HOOLEVER.E. J. Duquesne Light Co. 82/10/20 STARDSTECKI, R Division of Project & Resident Programs 3pp 16404 015 24X Fiche 50-412,82/12/07,8212140424
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/12/20 Consolidated & Edison Co of New York, Inc 108pp 16628 273 24X Fichs 50-000, 82/12/20, 8208190268
- 8 Reportable occurrences, LERs & related correspondence
- 8212140043 PNO-1-82-078 on 821206, security guard caught w/marijuana cigarette & fired Resident inspector informed on 821208 No police charges filed NALTON, 0. LAZARUS, W. Region 1. Office of Director 82/12/09 lp 16408 278 24X Fichs 50-412,82/12/09,8212140043

DOCKET 50-413 CATAMBA NUCLEAR STATION: UNIT 1

- A Application/construction stage documents & correspondence
- 8212030080 Forwards info demonstrating compliance w/10CFR20.50 & 100 regulations in response to 821027 request TUCKER.H B Duke Power Co 82/11/30 DENTON, HR Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 33pp 16304 261 24% Fiche 50-413.82/11/30.8212030080
- 8212030049 Forwards responses & revised responses to F8AR open items TUCKER.H B Duke Power Co 82/12/01 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Dranch 4 82pp 16305 082 24X Fiche 50-413.82/12/01.8212030049
- B212130257 Forwards summary of B21103-04 meeting w/Mechanical Engineering Branch & BNWL in Charlotte,NC to discuss open items from provious meetings M/eight oversize drawings Aperture cards are available in PRR TUCKER.H B Duke Power Co B2/12/06 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 9 Licensing Branch 4 55pp 16481 011 24X Fiche 50-413.82/12/06.8212130257
- 8212140263 Forwards Westinghouse proprietary & nonproprietary versions of response to NRC request for addl info re improved thermal design procedures
 TUCKER: H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 2pp 16406 092 24% Fiche 50-413, 82/12/08, 8212140263
- --8212140312 Affidavit of RA Wiesemann re Westinghouse proprietary info in util submittal on improved thermal design procedures WIESEMANN.R A Westinghouse Electric Corp 82/12/02 7pp 14406 098 24X Fiche 50-413,82/12/08,8212140263
- --8212140318 Submits response to NRC request for addl info on improved thermal design procedures Nonproprietary version encl Proprietary version withheld THOOCO.F.J Westinghouse Electric Corp. 82/12/03 CANADY.K S. Duke Power Co. 51pp. 16406-102 24X Fiche S0-413,82/12/08,8212140263

- 8212140267 Requests Westinghouse proprietary matt in util submittal re improved thermal design procedures be withheld (ref IOCFR2 790) Affidavit ent WIEBEMANN:R A Westinghause Electric Corp 82/12/02 Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 1p 16406 094 24X Fiche 50-413,82/12/08.
- 8212160044 Forwards summary of 821116-18 meetings w/Westinghouse & NRC in BethesdaiMD re open items from previous meetings
 List of attendees encl
 TUCKER.H B Duke Power Co 82/12/08 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 lipp 16446 077 24X Fiche 50-413,82/12/08.8212160044
- GP12150232 Notification of B21214 meeting w/util in Bethesda.MD to discuss resolution of Reactor Sys Branch open items &
 - cancerns JABBCUR,K N Licensing Branch 4 82/12/09 ADENBAM,E Q Licen Branch 4 3pg 16446 356 24% Fiche 50-413,82/12/09,8212150232 Licensing
- 8212220015 Notification of 821215 meeting w/util & Westinghouse in Bethesda.MD to discuss resolution of Containment Sys Branch open items JABBOUR, K N Licensing Branch 4 82/12/07 ADENSAM.E 0 Licen Branch 4 3pp 16529 097 24X Fiche 30-413.82/12/09.8212220015 Licensina 24X Fiche 50-413, 82/12/09, 8212220015
- 8212290354 Forwards response to question re diesel generator operation during adverse environ conditions, per 821013 request Based on past 30 yrs of weather data, lowest recorded outside temp was -5 F
 TUCKER, H B Duke Power Co 82/12/09 DENTON, H R Office of
 - TUCKER, H B Duke Power Co 82/12/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing 4 7pp 16586 168 24% Fiche 50-413,82/12/09,8218290334 Licensing Branch
- 8212160345 Forwards responses or revised responses to open items of lighted technical review branches to facilitate completion of FISTER TECHNICAL FEVIEW Branches to Facility to Competition of FSAR review Responses to be included in FSAR Revision 7
 TUCKER.H B Duke Power Co 82/12/10 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 43pp 16442 040 24X Fiche 50-413,82/12/10,8212160345
- B212170422 Notification of 821213 meeting w/util in Dethesda,MD to discuss resolution of Reactor Sys Branch open items re safety valve sizing analyses JABBOUR.K N. Licensing Branch 4 82/12/10 ADENSAM,E 0 Licens Branch 4 20pp 16478 114 24X Fiche 50~413,82/12/10,8212170422
- E212270261 Transmits responses to open stems of listed technical review branches to complete FSAR review Responses will be included in FSAR Revision 7 H/23 oversize drawings Aperture cards are available in PDR Three drawings illegible TUCKER: H B Duke Power Co 62/12/15 DENTON: H R Office of Nuclear Reactor Regulation. Director ADENSAM. E 9 Licensing Branch 4 84pp 16533 314 24X Fiche 50-413.82/12/15.8212270261
- 8212220227 Forwards response to 821220 generic ltr re NUREG-0612, "Control of Heavy Loads," Section 2 2 for spent fuel pool areas & Section 2 4 for auxiliary bldgs Ice condenser bridge areas & Section 2 % For Substituting 2.103% fee Condenses Pringer crane design specs lisked
 TUCKER. H B Dute Power Co B2/12/16 DENTON. H R Office of Nuclear Reactor Regulation. Director ADEMSAM. E 0 Licensing 4 Bip 16518 Licensing Branch
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- BP12220093 Requests mgt review & comment on FEB scheduled for issuance on B30105 Comments & changes must be forwarded by noon on B21217 to allow time for final approval ADENSAM.E O Licensing Branch 4 B2/12/13 LEAR.G E Hydrologic & Gentechnical Engineering Branch BALLARD,R L Environmental Engineering Branch TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16526 346 24X
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- G212030317 Forwards, for review & comment, Reactor Sys Branch preliminary draft SER input Transmittal provides for identification & resolution of add1 analysis missing info clarification or other work necessary to resolve outstanding issues NOUVAK.T M Assistant Director for Licensing 82/11/30 TUCKER, H Duke Power Co 46pp 16316 169 24X Fiche 50-413.82/11/30. 8212030317

F Security, medical, emergency & fire protection plans

- B212130069 Forwards info on emergency offsite facilities (EDF), per R Birkel B21203 request & Generic Ltr B1-10 Const of germanent primary & bactup EDF completed TUCKER.H B Duke Power Co B2/12/03 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16370 186 24X Fiche 50-000, 82/12/03, 8212130069
- 8212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
 FELTON.J M Division of Rules and Records 82/12/15 Document
 Management Branch 1p 16542 026 24X Fiche 50-000.82/12/15,
 8212230093 Doc ument
- --8212230108 Forwards public version of Revision 7 to crisis mgt plan & Tevisions to crisis mot plan implementing procedures
 TUCKER.H B Duke Power Co 82/12/02 DENTON.H R Office of
 Nuclear Reactor Regulation, Director 2pp 16542 027 24X
 Fiche 50-000, 82/12/15, 8212230093
- --B212230124 Public version of Revision 7 to crisis mgt plan One oversize pamphlet encl Aperture card available in PDR VAUGHN.R E Duke Power Co 82/11/27 9pp 16542 029 24X Fiche 50-000,82/12/13,8212230093
- --8212230134 Public version of revised crisis mgt plan implementing procedures, including Procedures 9.3.2 re-crisis news group plan & 9.3.1 re-mcGuire crisis phone directory VAUGHN, R E Dute Power Co. 82/11/29 280pp 16542-038 24X Fiche 50-000,82/12/15.8212230093

O Adjudicatory correspondence

- 8212040135 Memorandum & order reflecting decisions made following 821007-08 second prehearing conference in Charlotte.NC Inpact of AKAB-637 on contentions determined & addl contentions re DES considered KELLEY.J L Atomic Safety and Licensing Board Panel 82/12/01 27pp 16314 040 24% Fiche 50-413.82/12/01.8212060135
- B212060243 Order extending time until 821210 for Commission to act to elections: although expending time until 821210 for commission to review ALAB-687
 CHILK.S J Office of the Secretary of the Commission 82. Commissioners ip 16312 236 24X Fiche 50-413,82/12/03,8212060243
- B21207017B Interrogatories & requests to produce re Carolina Environ Study Group Contention 19/Palmetto Alliance Contention 44 Certificate of Svc encl Related correspondence B Duke Power Co 92/12/03 Carolina Environmental Study Group 15pp 16334 299 24X Fiche 50~413,82/12/03.8212070178
- BP12100096 Response supporting NRC B21122 motion for sanctions against Palmetto Alliance for failure to comply w/ASLB ordered discovery or alternatively, for dismissal of Alliance Contentions 8.16 & 17 Certificate of Svc encl
 CARR, A V Duke Power Co 82/12/07 Atomic Safety and Licensing
 Board Panel 49pp 16379.191 24X Fishe 50-413.82/12/07.
- B212130362 Requests review of enc. ASLB 821201 memorandum & order, containing add1 info to ASLB views on what NRC comments should address Updates may be necessary ADENBAM.E G. Licensing Branch 4 82/12/08 LEAR.O E Hydrologic & Geotechnical Engineering Branch Engineering Branch BALLARD.R L Environmental Antitrust & Economic analysis Branch (Utility Finance) 2pp Fiche 50-413.82/12/08.8212130362
- GP12130230 Motion for resumption of discovery as listed Several discovery matters remain outstanding Certificate of Svc encl.Related correspondence MCOARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 82/12/09 Atomic Safety and Licensing Board Panel 5pp 16396 264 24% Fiche.50-413.82/12/09.8212130230
- B212130214 Order extending time until 821217 for Commission to act to review ALAB~487 CHILK, S. J. Office of the Secretary of the Commission 82/ Commissioners ip 16390 116 24X Fiche 50-413,82/12/10,8212130214 82/12/10
- 8212150127 Statement of position on applicability of Table 6-4 to transshipment of spent fuel from Oconee & McGuire to Catawba Environ impact of spent fuel transportation properly considered in OL hearings W/Gertificate of Svc JOHNSON O E. Hearing Branch 4 82/12/13 18pp 16430 320 24X Fiche:50-413,82/12/13,8212150127

- 8212160261 Position on consideration of Oconee & McGuire spent fuel transportation issues in proceeding Environ effects of transporting fuel to Catawba should not be litigated in instant proceeding Certificate of Svc encl MCGARRY, J M Dute Power Co MCGARRY, J M Debevoise & Liberman. 82/12/13 22pp 16446 173 24X Fiche 50-413.82/12/13.8212160261
- 8212150124 Forwards NRC first set of interrogatories & document production requests to replace lost copy Confirms stipulation reached in 821213 telcon that responses will be provided by 821228 JOHNSON 9 E Hearing Branch 4 82/12/14 PRESLER, H Charlotte-Mecklemberg Environmental Coalition 1p 16430 310 24X Fiche 50-413, 82/12/14, 8212150124
- 8212160235 Motion for protective order re listed Palmetto Alliance third set of interrogatories Interrogatories seek info which is irrelevant requires compilation of matls not readily available or is protected by work product doctrine JOHNSON, G. E. Hearing Branch 4 82/12/15 Atomic Safety and Licensing Board Panel 9pp 16443-101 24X Fiche 50-413, 82/12/15, 8212160235
- --8212160240 Response to third set of interrogatories & requests to produce re Palmetto Alliance Contentions 16 & 44 Prof qualifications & Certificate of Svc encl JUNNSON, 0 E Hearing Branch 4 82/12/15 Palmetto Alliance 163pp 16443 110 24X Fiche 50-413-82/12/15,8212160235
- 8212160256 Third set of interrogetories & document production requests Certificate of Svc encl JOHNSON O E Hearing Branch 4 82/12/15 Pelmetto Alliance 10pp 16445 163 24X Fiche 50-413,82/12/15,8212160256
- 82:2140303 Second set of interrogatories & document production requests Certificate of Svc encl
 JOHNSON, 9 E Hearing Branch 4 82/12/15 Carolina Environmental Study Group 10pp 14442.322 24X Fiche 50-413.82/12/15, B212140303
- 6212170180 Forwards RO Contains affidavit & second page of JJ Bury statement of prof qualifications, inadvertently omitted from NRC 621215 responses to Palmetto Alliance third set of interrogatories & requests to produce JOHNSON, G E Hearing Branch 4 82/12/16 GUILD, R Guild, R 4pp 16450 188 24X Fiche 50-413,82/12/16,8212170180
- 6212170185 Motion to compel full responses to NRC first set of interrogatories & document production requests to Palmetto Alliance on Contentions Tintervenor must answer contentions on factual & legal bases Certificate of Svc encl.

 JOHNSON G E Hearing Branch 4 82/12/16 Atomic Safety and Licensing Board Panel 10pp 16450 168 24X Fichs 50-413,82/12/16,8212170186
- 8P12210242 Order extending time until 821223 for Commission to act to review ALAB-687 CHILK S J Office of the Secretary of the Commission 82/12/17 Commissioners ip 16484 080 24% Fiche 50-413.82/12/17.8212210242
- 8212210317 Advises that NRC does not intend to file answer to util B21209 motion re discovery NRC already answered Palmetto Alliance Contention 44 & filed motion to compel answers to NRC interrogatories on Palmetto Contention 7
 JOHNSON.0 E Hearing Branch 4 B2/12/20 KELLEY, JL, FOBTER, RF. CALLIFMI, D Atomic Safety and Licensing Board Panel, ip 14496 290 24X Fithe 50-413,82/12/20.8212210317
- 821222032 Motion to compel Prairie Alliance answers to util interrogatories re Palmetto Alliance Contentions 6 & 7 or alternatively, to dismiss contentions Alliance fails to satisfy Commission rules & regulations
 MCGARRY, J M Duke Power Co MCGARRY, J H Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 32pp 16518 234 24x Fiche 50-413,82/12/20,8212220232
- --0212220239 Response opposing Palmetto Alliance motion for protective order from applicant discovery Alliance motion impermissibly vague & fails to demonstrate applicability of atty/cliant privilege or work product doctrine W/Certificate of Svc MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 14pp 16518; 266 24x Fichs 50-413.62/12/20.8212220232
- B212270244 Motion to compel Palmetto Alliance to respond further to interrogatories re Alliance Contentions & & 7 Discovery of bases for contentions permitted Contention 7 should be dismissed MCOARRY, J M Duke Power Co. MCGARRY, J M Debevoise & Liberman. B2/12/20 Atomic Safety and Licensing Board Panel 32pp 16537 166 24X Fiche 50-413.82/12/20.8212270244

- 821227032(Response opposing Palmetto Alliance 820428 motion for protective order re Contentions & & 7 Alliance has not demonstrated applicability of atty-client or work product privileges
 MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 12pp 16530 266 24X Fiche 50-413.82/12/20.8212270321
- 8212280132 Objections to ASLB 821201 order & motion for reconsideration or for certification Contentions 18 re emergency diesel generator operation & 17 re conticula infestation effect on cooling sys should be admitted Certificate of Svc encl GUILD, R Palmetto Alliance OUILD, R Carolina Environmental Study Group OUILD, R Ouild, R 82/12/20 Atomic Safety and Liconsing Board Panel 8pp 16563 212 24X Fiche 50-413,82/12/20.8312280132
- 8212280138 Comments on transshipment of spent fuel from Ocones & McQuire for storage at Cafamba Table 8-4 inapplicable Contentions DES 10 & DES 17 should be admitted GUILDR Palmetto Alliance GUILDR Carolina Environmental Study Group GUILDR Ouild R 82/12/20 Atomic Safety and Licensin Board Panel 5pp 14563 207 24X Fichs 50-413,82/12/20.8212280138
- 8212270224 Memorandum & order ruling on various disputes Palmetto Alliance waived all claims to privilege & thus must answer interrogatories Alliance 820830 motion for protective order & NRC motion for sanctions denied KELLY.J L Atomic Safety and Licensing Board Panel 82/12/22 Palmetto Alliance 93pp 16535 004 24x Fiche 50-413,82/12/22,8212270224
- 8212270251 Order establishing Commission review of ASLAB Decision ALAB-697 Commission will review issues re Atomic Energy Act. Section 1894 & definition of good cause for late filing Briefs due in 30 days & reply briefs in 50 CHILK, 8 J Office of the Secretary of the Commission 82/12/23 pp 16530 055 24% Fiche 50-413,82/12/23,8212270251
- 8212280174 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group objections to ASLB 821201 order & motion for reconsideration or certification GARRA V Duke Power Co 82/12/23 QUILD:R Quild: R RILEY, J L Affiliation Unknown Ip 16563 141 24% Fiche 50-413,82/12/23,82/12/801724
- 8212270002 Requests complete copy of Palmetto Alliance & Carolina Environ Study Group 821220 objections to ASLB 821201 order & motion for reconsideration or certification JOHNSON-0 E Hearing Branch 4 82/12/27 GUILD.R Palmetto Alliance GUILD.R Quild.R ip 16582 240 24X Fiche 50-413.82/12/27.8212290002
- B212300010 Serves Commission B21223 order & underlying decision ALAB-687 M/o encl STUCKY.S W Docketing & Services Branch B2/12/28 Natural Resources Defense Council 1p 16598 261 24X Fiche 30-413, 82/12/28, 8212300010
- Q Inspection reports: IE Bulletins & correspondence
- B208190240 IE Bulletin B2-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Sys list encl
 DEYQUNG.R C Director's Dffice, Office of Inspection and
 Enforcement B2/10/28 Consolidated Edison Co of New York, Inc.
 J12pp 16462 163 24X Fichs 50-000, 82/10/28, 8208190240
- 8212090482 Ack receipt of IK Insp Repts 50-413/82-24 & 50-414/82-22 No proprietary info TUCKER.H B Duke Power Co 82/10/28 D'REILLY, J P Region 2, Office of Director 1p 16363 286 24X Fiche 50-413,82/10/29, H212090482.
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list ent!
 COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372-142 24% Fiche 30-000,82/11/05,8208190245
- 8212090233 Advises that no piping subassemblies exist within scope of IE Bulletin 82-01, Revision 1, Suppl 1, in response to 820818 transmittal TUCKER, H B Duke Power Co 82/11/05 O/REILLY, J P Region 2, Office of Director 1p 16361 348 24X Fiche 50~413,82/11/05, 82/12/09233
- 8212070442 Ack receipt of IE Insp Repts 50-413/82-25 & 50-414/8R-23 No proprietary info TUCKER, H B. Dute Power Co 82/11/11 O'REILLY, J P Region 2, Office of Director 1p 16364 252 24X Fiche 50-413,82/11/11, 8212070442

- 8212090459 Forwards IE Insp Repts 50-413/82-28 & 50-414/82-26 on 821026-29 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/11/15 TUCKER.H B Duke Power Co 2pp 16363 357 24X Fishe 50-413, 82/11/15,8212090459
- ---8212090465 IE Insp Repts 50-413/82-28 & 50-414/82-26 on 8210R6-29 No noncompliance noted Major areas inspected instrumentation components & sys work activities (C records instrumentation cables & action on previous insp matters GIBBONS.T D , CONLON.T E Division of Engineering & Technical Programs 82/11/10 4pp 14363 359 24X Fiche 50-413.82/11/15, 8212090459
- B212090522 Ack receipt of IE Insp Repts 50-413/82-24 & 50-414/82-24 No proprietary info TUCKER.H B Duke Power Co 82/11/17 O'REILLY, J P Region 2, Office of Director ip 16366 362 24% Fiche 50-413, 82/11/17, B212090522
- B20819025; IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JQRDAN.E L Division of Engineering & Quality Assurance BQ/11/18 Consolidated Edison Co of New York. Inc 109pp 1645; 199 24) Fiche 50-000.BZ/11/18,820819025;
- BP12090232 Ack receipt of 821039 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-21 & 50-414/92-19 LEWIS.R C Division of Project & Resident Programs 82/11/18 TUCKER.H B Duke Power Co ip 16362 314 24X Fiche 50-413,82/11/18.8212090232
- --B212090239 Responds to NRC 820930 ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19 Corrective actions defective base metal indication in Class B weld repaired Clearance criteria added to Design Drawing IC9-A-20 4 TUCKER.H B Duke Pawer Co 82/10/29 O'REILLY.J P Region 2, Office of Director 4pp 16362 315 24X Fiche 50-413,82/11/18, 8212090232
- ---8212090246 Forwards IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0825 & notice of violation LEMIS.R C Division of Project & Resident Programs 82/09/30 TUCKER.H B Duke Power Co 2pp 16362 319 24x Fiche 50-413,82/11/18.8212090232
- --B212090251 Notice of Violation from insp on 820726-0825 * Division of Project & Resident Programs 82/09/30 Sp; 16362 321 24X Fiche 50-413,82711/18.8212090232
- --8212090261 IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0825 Nuncompliance noted failure to evaluate rejectable defect identified by radiography adequately & failure to include qualitative acceptance criteria in drawings VANDOURN.P K , BRYANT, J C Division of Project & Resident Programs 82/09/29 8pp 16362 324 24X Fiche 50-413.82/11/18, 8212090232
- 8212070317 Forwards IE Insp Repts 50-413/82-27 % 50-414/82-25 on 621026-29 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/11/19 TUCKER, H B Duke Power Co 2pp 16365 105 24X Fiche 50-413, 82/11/19, 8212090317
- --8212070324 IE Insp Repts 50-413/82-27 & \$0-414/8R-25 on 821026-27 No noncompliance noted Major areas inspected const progress, reactor vessel internals & licensee action on previous enforcement matters

 ECONOMOSIN, BLAKE, J. Division of Engineering & Technical Programs 82/11/12 App. 16365 107 24X Fiche 50-413,82/11/19,8212070317
- B*08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYCUNO.R C Director's Office. Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50~000,82/11/26.8208190256
- B:/08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CQBS.L I Division of Fuel Facilities, Materials 5 Safeguards G2/11/30 Consolidated Edison Co of New York. Inc 35App 143B7 028 24X Fiche 50-000.82/11/30.8208170257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list enc! DEYOUNO, R C Director's Office, Defice of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259

- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay bockets" 8vc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated & Gison Co. of New York, Inc. 110pp. 16462 064 24X Fiche 50-Q00, 82/12/03, 8208190261
- 820B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000, 82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24) Fiche 50-000, 82/12/20,8208190268

S Reportable occurrences. LERs & related correspondence

- 8212170256 Interim Significant Deficiency Rept SD 413-414/82-23 reviolation of approved const procedures for mixing & placing SikaTop 122 during drill hole repair Initially reported on 821108 Test program initiated Final rept due by 830506 TUCKER.H B Dute Power Co 82/12/08 O'REILLY, J P Region 2, Office of Director Spp 16457 170 24X Fiche 50-413.82/12/08.6212170256
- BR121500B6 PNO-II-82-135 on BR1209, contractor employee arrested & charged w/blackmail, including extortion & threat to kill, injure or intimidate Arrest followed 3 day investigation as result of bomb threats on BR1206.07 & 08 MOORE, D.E., BRYANT, J.G. Region 2. Office of Director 82/12/09 2pp 16431 024 24% Fiche 50-443.82/12/09.82121500B6
- 8212210231 Significant Deficiency Rept 8D 413-414/82-24 re ITT Barton Class IE transmitters exhibiting thermal non-repeatability Initially reported on 821112 Problem eliminated by addition of insulating spacers between potentiometers & brackets TUCKER.H B Duke Power Co 82/12/10 O'REILLY, J P Region 2, Office of Director App 16483 351 24X Fiche 50-413.82/12/10, 02/2210231

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8P12030080 Forwards info demonstrating compliance w/10CFR20, 50 & 100 regulations, in response to 821027 request TUCKER.H B Duke Power Co 82/11/30 DENTON,H R Diffice of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 4 33pp 16304 261 24X Fiche 50-413,82/11/30,8212030080
- B212030049 Forwards responses & revised responses to FSAR open items TUCKER.H B Duke Power Co B2/12/01 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 S2pp 16305 082 24X Fiche 50-415.82/12/01.8212030045
- 8212130257 Forwards summary of 821103-04 meeting w/Mechanical Engineering Branch & BNWL in Charlotte, NC to discuss open items from previous meetings W/eight oversize drawings Aperture cards are available in PDR TUCKER, H B Duke Power Co 82/12/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4 55pp 16411 011 24X Fiche 50-413,82/12/04,8212130257
- 8212140263 Forwards Westinghouse proprietary & nonproprietary versions of response to NRC request for add1 info re improved thermal design procedures
 TUCKER.H B Duke Power Co 82/12/08 DENTON.H R Office of
 Nuclear Reactor Regulation. Director ADENSAME 0 Licensing Branch
 A 2pp 16406 092 24X Fiche 50-413.82/12/08.8212140263
- --8212140312 Affidavit of RA Wiesemann re Westinghouse proprietary info in util submittal on improved thermal design procedures HIESEMANN.R A Westinghouse Electric Corp 82/12/02 7pp 16406 099 24X Fiche 50-413,82/12/08.8212140263
- --8212140318 Submits response to NRC request for add1 info on improved thermal design procedures Nonproprietary version enc1 Proprietary version withheld TMOSODD,F.J Westinghouse Electric Corp 82/12/03 CANADY,K 8 Duke Power Co 51pp 16406 102 24X Fiche 50-413,82/12/08,8212140263

- B212140267 Requests Westinghouse proprietary matl in util submittal re improved thermal design procedures be withheld (ref 100FR2 790) Affidavit encl
 WIESEMANN, R A Westinghouse Electric Corp B2/12/02 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ADENSAM, E G
 Licensing Branch 4 ip 16406 094 24% Fishe 50~413, B2/12/08,
 B212140267
- 8212160044 Forwards summary of 821116-18 meetings w/Westinghouse & NRC in Bothesda. MD re open items from previous meetings List of attendess encl
 TUCKER. H B Duke Power Co 82/12/08 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAN.E G Licensang Branch
 4 11pp 16446-077 24K Fiche 50-413.82/12/08.8212160044
- B212150232 Notification of 821214 meeting w/util in Bethesda.MD to discuss resolution of Reactor Sys Branch open items & conterns JABBOUR.K N Licensing Branch 4 82/12/09 ADENSAM,E G Licensing Branch 4 3pp 16446-356 24X Fiche.50-413.82/12/09.8212150232
- 8212220D15 Notification of 821215 meeting w/util & Nestinghouse in Bethesds, MD to discuss resolution of Containment Sys Branch open items JABBOUR, K N Licensing Branch 4 82/12/09 ADENSAM, E 0 Licensing Branch 4 3pp 16529 097 24X Fiche 50-413,82/12/09,82122220015
- 8212290354 Forwards response to question re diesel generator operation during adverse environ conditions.per 821013 request Based on past 30 urs of weather data, lowest recorded outside temp was ~5 F
 TUCKER.H B Duke Power Co 82/12/07 DENTIN.H R Office of Nuclear Reactor Regulation, Director ADENSAN.E G Licensing Branch 4 9pg 16586 168 24X Fiche 50-413, 82/12/09, 8212290354
- 8212160345 Forwards responses or revised responses to open items of listed technical review branches to facilitate completion of FEAR revised Responses to be included in FEAR Revision 7 TUCKER. H B Duke Power Co B2/12/10 DENTON.H R Office of Nuclear Reactor Regulation, Director ADEN5AN.E G Licensing Branch 4 43pp 16442 040 24X Fichs 50-413.82/12/10.8212160345
- 82:12170422 Notafication of 82:1213 meeting w/util an Bethesda.MD to discusa resolution of Reactor Bys Branch open items re safety valve sizing analyses JABBBUR,K N Licensing Branch 4 82/12/10 ADENSAM.E Q Licensin Branch 4 20pp 16478 114 24X Fiche 50-413,82/12/10,8212170422
- BRI2270261 Transmits responses to open items of listed technical review branches to complete FBAR review Responses will be included in FBAR Revision 7 M/23 oversize drawings Aperture cards are available in PDR Three drawings illegible TUCKER.H B Duke Power Ca. B2/12/15 DENTON.H R Office of Nuclear Redctor Regulation, Director ADENBAM.E Q Licensing Branch 4 B4pp 16533 316 24% Fiche 50-413.82/12/15.8212270261
- 8212220227 Forwards response to 821220 generic ltr re NUREG-0612.
 "Control of Heavy Loads," Section 2 2 for spent fuel pool ereas & Section 2 4 for auxiliary bldgs lee condenser bridge trans design specs listed
 TUCKER, H B Duke Power Co 82/12/16 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 A Sipp 16518 332 24X Fiche 50-413,82/12/16,8212220327
- D NRC Draff/Final Environmental Statements, supple & correspondence
- B212220073 Requests mgt review & comment on FEB scheduled for issuance on B30105 Comments & changes must be forwarded by noon on B21217 to allow time for final approval ADENSAM E O. Licensing Branch 4 82/12/13 LEAR, 9 E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch TOALSTON. A Antitrust & Economic analysis Branch (Vt11ity Finance) 2pp 16526 346 24X Fiche 50-413, 82/12/13, 8212220093
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212030317 Forwards, for review & comment, Reactor Sys Branch preliminary fraft SER Input Transmittal provides for identification & resolution of addl analysis, missing info.clarifications or other work necessary to resolve outstanding issues NOVAN, T H Assistant Director for Licensing 82/11/30, TUCKER, H Duke Power Co 46pp 16316 169 24X Fiche 50-413,82/11/30, 82/11/30,

- F Security, medical, emergency & fire protection plans
- 8212130069 Forwards info on emergency offsite facilities (EQF), per R Birkel 821203 request & Generic Ltr 81-10 Const of permanent primary & backup EOF completed TUCKER, H B Duke Power Co 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16390 186 24X Fiche 30-000.82/12/03,8212130069
- \$212230093 Releases public version of revision to crisis mgt plan & revisions to crisis mgt plan implementing procedures
 FELTON.J M Division of Rules and Records 82/12/15 Document Management Branch 1p 16542 026 24X Fiche 50-000.82/12/15, B212230093
- --0212230108 Forwards public version of Revision 7 to crisis mgt plan & revisions to crisis mgt plan implementing procedures TUCKER:H B Duke Power Co 82/12/02 DENTON:H R Diffice of Nuclear Reactor Regulation, Director 2pp 16542 027 24 X Fiche 50-000, 82/12/15, 8212230093
- --8212230124 Public version of Rovision 7 to crisis mgt plan One oversile pamphlet encl Aperture card available in PDR VAUGHN,R E Duke Power Co 82/11/27 9pp 16542 029 24X Fiche 50-000,82/12/15,8212230093
- --B212230134 Public version of revised crisis mgt plan implementing procedures including Procedures 5 3 2 re crisis news group plan & 5 3 11 re McGuire crisis phone directory VAUGHN, R E Duke Power Co B2/11/29 280pp 16542 038 24X Fiche 50-000, B2/12/15, B212230073
- G Adjudicatory correspondence
- GP12040135 Memorandum & order reflecting decisions made following 821007-00 second prehearing conference in Charlotte, NC impact of ALAB-687 on contentions determined & addicate contentions re DES considered KELLEY, J. L. Atomic Gefety and Licensing Board Panel 82/12/01 27pp 16314-040 24X Fiche 50-413,82/12/01,8212060135
- 87:2060243 Order extending time until 82(2)0 for Commission to act to leview ALAB-687 CHILK,S J Office of the Secretary of the Commission 82/12/03 Commissioners ip 16312 236 24X Fiche 50-413.82/12/03.
- B212070178 Interrogatories & requests to produce re Carolina Environ Study Group Contention 18/Pajmetto Alliance Contention 44 Certificate of Svc encl Related Correspondence Bucks Power Co 82/12/03 Carolina Environmental Study Group 15pp 16334 297 24X Fichs 50-413,82/12/03,82/2070178
- 8212100096 Response supporting NRC 821122 motion for sanctions against Palmetto Alliance for failure to comply w/ABLB ordered discovery, or alternatively, for dismissal of Alliance Contentions 8,16 & 17 Certificate of Svc encl CARR. A V Duke Power Co 82/12/07 Atomic Sefety and Licensing Board Panel 49pp 16379 191 24X Fichs 50-413.82/12/07, 82(2100074
- 8212130352 Requests review of encl ASLB 821201 memorandum & order, containing add1 info re ASLB views on what NAC comments should address Updates may be necessary ADENSAM.E Q Licensing Branch 4 82/12/08 LEAR,G E Hydrologic & Ceotechnical Engineering Branch BALLARD,R L Environmental Engineering Branch TOALSTON, A Antitrust & Economic analysis Branch (Utility Finance) 2pp 16412 183 24x Fiche 50-413.62/12/08.8212130362
- S212130230 Motion for resumption of discovery as listed Several discovery matters remain outstanding Certificate of Svc encl Related correspondence MCGARRY.J M Dute Power Co MCGARRY.J M Debevoise & Liberman 62/12/09 Atomic Safety and Licensing Board Panel 5pp 16396 264 24X Fiche 50-413,82/12/09.8212130230
- Bil2:30214 Order extending time until 82:217 for Commission to act to review ALAB-687.
 CHILK:8 J Office of the Secretary of the Commission 82/12/10 Commissioners in 16370 116 24% Fiche 50-413:92/12/10. 8212130214
- 8212150127 Statement of position on applicability of Table 8-4 to transshipment of spent fuel from Oconee & McGuire to Catawba Environ impact of spent fuel transportation properly considered in OL hearings W/Certificate of Svc. JOHNSON.0 E Hearing Branch 4 82/12/13 18pp 16430 320 24% Fiche 50-413,82/12/13,8212150127

- 8212160261 Position on consideration of Oconee & McGuire spent fuel transportation issues in proceeding Environ effects of transporting fuel to Catamba should not be litigated in instant proceeding Certificate of Svc encl MCGARRY, J M Debevoise & Liberman 82/12/13 22pp 16446 173 24X Fiche 50-413,82/12/13,8212160261
- 8212150124 Forwards NRC first set of interrogatories & document production requests, to replace lost copy Confirms stipulation reached in 821213 telcon that responses will be provided by 821228

 JGHNSON, 0 E Hearing Branch 4 82/12/14 PRESCER, H
 Charlotte-Mecilenterg Environmental Coalition ip 16430 310 24X
 Fiche 50-413,82/12/14,8212150124
- GP12160235 Motion for protective order re listed Palmetto Alliance third set of interrogatories Interrogatories seek infounds third is irrelevant requires compilation of matis not readily available or is protected by work product doctrine JOHNSON, 0 E Hearing Branch 4 B2/12/15 Atomic Safety and Licensing Board Panel 9pp 16443 101 24X Fiche 30-413,82/12/15,82/12/60235
- --8212160240 Response to third set of interrogatories & requests to produce re Palmetto Alliance Contentions 16 & 44 Prof qualifications & Certificate of Svc encl JOHNSON, 0 E Hearing Branch 4 82/12/15 Palmetto Alliance 163pp 16443 i10 24% Fishe 50-413,82/12/15,8212160235
- BP12160256 Third set of interrogatories & document production requests Certificate of Svc encl
 JCHNSON, O.E. Hearing Branch 4 82/12/15 Palmetto Alliance
 10pp 16446 163 24% Fiche 50-413.82/12/15.8212160256
- 9:412160303 Second set of interrogatories & document production requests Certificate of Svc enct JOHNSON.C E Hearing Branch 4 82/12/15 Carolina Environmental Study Group 10pp 16442 322 24X Fiche 50-413, 82/12/15, 62/12/46/303
- B212170180 Forwards RO Conzales affidavit & second page of JJ Bury statement of prof qualifications, inadvertently omitted from NRC 021215 responses to Palmetto Alliance third set of interrogatories & requests to produce JUNNSON, 0 E Hearing Granch 4 02/12/16 0VILD, R Guile, R 4pp 16450 188 24X Fiche 50-413, 82/12/16, 6212170180
- GP12170186 Motion to compel full responses to NRC first set of interrogatories & document production requests to Palmetto Alliance on Contention 7 Intervenor must answer contentions om factual & legal bases Certificate of Svc encl JOHNSON, 6 E. Hearing Branch 4 82/12/16 Atomic Safety and Licensing Board Panel 10pp 16450 168 24X Fiche 50-413, 82/12/16, 6212170186
- GP:12210242 Order extending time until 821223 for Commission to act to 1 eview ALAB-687 CHILK: 5 J Office of the Secretary of the Commission 82/12/17 Commissioners ip 16484 080 24X Fiche 50-413,82/12/17, 8212210242
- 82:12210317 Advises that NRC does not intend to file answer to util B2(20) motion re discovery NRC already answered Palmetto Allience Contention 44 & filed motion to compel answers to NRC interrogatories on Palmetto Contention 7
 JOHNSON.0 E Hearing Branch 4 82/12/20 KELLEY, J L , FOSTER, R F , CALLIKAN.D Atomic Bafety and Licensing Board Panel ip 16496 290 24% Fiche 50-413,82/12/20,8212210317
- 821.2220232 Motion to compel Prairie Alliance answers to util interrogatories re Palmetto Alliance Contentions 6 & 7 or alternatively, to dismiss contentions Alliance fails to satisfy Commission rules & regulations MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 32pp 16518 234 24X Fichs 50-413,82/12/20,8212220232
- --8212220237 Response apposing Palmetto Alliance motion for protective order from applicant discovery Alliance motion impermissibly vague & fails to demanstrate applicability of atty/client privilege or work product doctrine W/Certificate of Svc MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 14pp 16518 266 24X Fiche 50-413,82/12/20,8212220232
- 92:12270244 Motion to compel Palmetto Alliance to respond further to interrogatories re Alliance Contentions 6 & 7 Discovery of bases for contentions permitted Contention 7 should be dismissed MCGARRY. J M Duke Power Co MCGARRY, J, M Debevoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 32pg 16537 166 24X Fiche 50-413.82/12/20.8212270244

- BP12270321 Response apposing Palmetto Alliance 820428 motion for protective order re Contentions 6 & 7 Alliance has not demonstrated applicability of atty-client or work product privileges MCGARRY, J M Duke Power Co MCGARRY, J M Debgvoise & Liberman 82/12/20 Atomic Safety and Licensing Board Panel 12pp 14530 266 24X Fiche 50~413,82/12/20,8212270321
- 8D12280132 Objections to ASLB 821201 order & motion for reconsideration or for certification Contentions 18 re emergency dissel generator operation & 17 re corbicula infestation effect on cooling sys should be admitted Certificate of Syc encl GUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group GUILD.R Quild.R 82/12/20 Atomic Safety and Licensing Board Panel Bpp 16563 212 24X Fiche 50-413.82/12/20, 8212280132
- 82:12280138 Comments on transshipment of spant fuel from Oconee & McQuire for storage at Catauba Table 5-4 inapplicable Contentions DES 10 & DES 19 should be admitted QUILD.R Palmetto Alliance QUILD.R Caralina Environmental Study Group QUILD.R Quild. R 82/12/20 Atomic Safety and Licensing Board Panel 5pp 16563 207 24X Fiche 50-413,82/12/20,8212280139
- 8P12270226 Memorandum & order ruling on various disputes Palmetto Alliance waived all claims to grivilege & thus must answer interrogatories Alliance 820830 motion for protective order & NRC motion for sanctions denied KELLY. J L. Atomic Safety and Licensing Board Panel 82/12/22 Palmetto Alliance 93pp 16535 004 24X Fiche 50-413.82/12/22, 2012/27/27
- B2:12270251 Order establishing Commission review of ASLAB Decision ALAB-687 Commission will review issues re Atomic Energy Act. Section 187a & definition of good cause for late filing Oriefs due in 30 days & reply briefs in 50 CHILK, S.J. Office of the Secretary of the Commission 82/12/23 3pp 16530 055 24X Fiche 50-413,82/12/23,8212270251
- SP12280174 Requests complete copy of Paimetto Alliance & Carolina Environ Study Group objections to ASLE 821201 order & motion for reconsideration or certification GARR.A V Duke Power Co 82/12/23 GUILD.R Guild. R RILEY, J L Affiliation Unknown 1p 16863 141 24X Fiche 50-413, 82/12/23, 82/12/20174
- SP12270002 Requests complete capy of Palmetto Alliance & Carolina Environ Study Group 821220 objections to ASLB 821201 order & motion for reconsideration or certification JCRNSON, O E Hearing Branch 4 82/12/27 GUILD, R Palmetto Alliance GUILD, R Quild, R 1p 16582 240 24x Fiche 50-413, 82/12/27, 8212270002
- G212300010 Serves Commission B21223 order & underlying decision AL87-687 M/o encl STUCKY, BV Docketing & Services Branch 82/12/28 Natural Resources Defense Council lp 16598 261 24X Fiche-50-413,82/12/28,8212300010
- Q Inspection reports. IE Bulletins & correspondence
- B208190240 IE Bulletin B2-03, Revision i, "Btress Cracking in Thick-Wall:Large-Diameter, Stainless Bteel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8212090482 Ack receipt of IE Insp Repts 50-413/82-24 & 50-414/82-22 No proprietary info TUCKER.N B Dute Power Co 82/10/28 O'REILLY.J P Region 2, Office of Director 1p 16363 286 24X Fiche 50-413,82/10/28, G212090482
- BPOB190245 IE 1nfo Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolominascent Dosimeters " Svc list enc!

 COBB.L. I Division of Fuel Facilities, Materials & Safeguards B2/11/05. Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fichs 30-000.82/11/05.8208190245
- 8212090233 Advises that no piping subassemblies exist within scope of IE Bulletin 82-01. Revision 1. Suppl 1. in response to 820818 transmittal TUCKER. H B Duse Power Co 82/11/05 O'REILLY, J P. Region 2. Office of Director 1p 16361 348 24X Fiche 50-413.82/11/05.
- 8P12070442 Ack receipt of IE Insp Repts 50-413/82-25 & 50-414/82-23 No proprietary info TUCKER.H B Dute Pawer Co 82/11/11 O'REILLY.J P Region 2, Office of Director. 1p 16364 252 24X Fiche 50-413.82/11/11, 8212070442

- B212090459 Forwards IE Insp Repts 50-413/B2-28 & 50-414/B2-26 on B21026-29 No noncompliance noted DANCE.H C Bivision of Project & Resident Programs B2/11/15 TUCKER.H B Duke Power Ca 2pp 16363 357 24x Fichs 50-413, 82/11/15, 8212090459
- --8212070465 IE Insp Repts 50-413/82-28 & 50-414/82-26 on 821026-29 No noncompliance noted Major areas inspected instrumentation components & sys work activities, OC records, instrumentation cables & action on previous insp matters 01880NS, T D : CONLON-T E Division of Engineering & Technical Programs 82/11/10 App 16363 359 24% Fiche 50-413,82/11/15,8212090459
- B212090522 Ack receipt of IE Insp Repts 50-413/82-26 & 50-414/82-24 No proprietary info TUCKER.H B Duke Power Co 82/11/17 O'REILLY.J P Region 2. Office of Director ip 16366 362 24X Fiche 50-413,82/11/17. B212090522
- 820B190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24: Fiche 50-000 82/11/18.8208190251
- 8212090232 Ack receipt of 821029 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-413/82-21 & 50-414/82-19
 LEWIS.R C Division of Project & Resident Programs 82/11/18
 TUCKER.H B Duke Power Ca ip 16362 314 24X
 Fiche 50-413.82/11/18,8212090232
- --8212090239 Responds to NRC 820930 ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19 Corrective actions defactive base metal indication in Class B weld repaired Clearance criteria added to Design Drawing 108-4-20 4 TUCKER: H B Duke Power Co 82/10/29 O'REILLY, J P. Region 2, Office of Director 4pp 16362 315 24X Fiche 50-413,82/11/18, 82120970232
- --8212090246 Forwards IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0825 & notice of violation LEWIS.R C. Division of Project & Resident Programs 82/09/30 TUCKER.H B Duke Power Co 2pp 16362 319 24X Fiche 50-413,82/11/18,8212090232
- ~-8212090251 Notice of violation from insp on 820726-0825 & Division of Project & Resident Programs 82/09/30 3pp 16362 321 24X Fiche 50-413,82/11/18,8212090232
- --8212090261 IE Insp Repts 50-413/82-21 & 50-414/82-19 on 820726-0885 Noncompliance noted failure to evaluate rejectable defect identified by radiography adequately & failure to include qualitative acceptance criteria in drawings VANDOURN.P K, BRYANT.J C Division of Project & Resident Programs 82/09/29 Bpp 16362 324 24X Fichs 50-413,82/11/18,8212090232
- 3212070317 Forwards IE Insp Repts 50-413/82-27 % 50-414/82-25 on 821026-29 No noncompliance nated DANCE, H C Division of Project & Resident Programs 82/11/19 TUCKER, H B Duke Power Co Rap 16365 105 24% Fiche 50-413,82/11/19,82(2050317.
- -8212090324 IE Insp Repts 50-413/82-27 & 50-414/82-25 on 821026-29 No noncompliance noted Major areas inspected const progress, reactor vessel internals & licensee action on previous enforcement matters at licensee action on previous ECONOMOS, N. BLAKE, J. Division of Engineering & Technical Programs, 82/11/12 App. 16365 107 24X Fiche 50-413.82/11/19, 8212090317
- 208190256 1E Info Notice 82-46, "Defective & Obsolete Combination Padlocks," Svc list encl DEYDUNG, R. C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fische 50-000.82/11/26.8208190256
- POB190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radiosctive Matl " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82711/30 Consolidated Edison Co of New York, Inc 35App 16387-028 24X Fiche 50-000.62/11/30.8208190257
- 'OBI90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list enc! DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/22/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259

- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Societs " Svc list encl JURDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24X Fithe 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND, R C Director's Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JURDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000.82/12/20.8208190268
- S Reportable occurrences, LERs & related correspondence
- 8212090079 Significant Deficiency Rept SD 414/81-30 re Swegco 8-inch Schedule 40 min-wall violation Initially reported on 811231 As-found condition of pipe satisfies design requirements & will be installed TUCKER, H B Duke Power Co 82/11/29 D'REILLY, J P Region 2, Uffice of Director 3pp 16357 332 24X Fiche 50-414,82/11/29, 8212090079
- 8212090323 Interim Significant Deficiency Rept SD 414/82-16 re large arc strike on body of Borg-Warner gate valve Institutly reported on 820803 Valve replaced Investigation of deficient valve underway Next rept will be submitted by 830701 TUCKER.H B Duke Power Co 82/12/01 O'REILLY, J.P. Region 2. Office of Director 2pp 16365 125 24X Fiche 50-414.82/12/01. 8212070323
- G212170256 Interim Significant Deficiency Rept SD 413-414/82-23 reviolation of approved const procedures for mixing & placing SikaTop 122 during drill hole repair initially reported on S21109 Test program initiated Final rept due by S03050 TUCKER.H B Duke Power Co 82/12/08 O'REILLY, J.P. Region 2. Defice of Director 3pp 16457 170 24X Fiche 50-413,82/12/08,8212170256
- 8212150086 PNO-II-82-135 on 821209, contractor employee arrested & charged w/blackmaıl.including extortion & threat to kill. Injure or intimidate Arrest followed 3 day investigation as result of bomb threats on 821206,07 & 08 MDORE, D E . BRYANT, J C Region 2. Office of Director 82/12/09 Epp 16401 024 24% Fiche 50-413,82/12/09,8212150086
- 82122(0231 Significant Deficiency Rept SD 413-414/82-24 re ITT Darton Class IE transmitters exhibiting thermal non-repeatability Initially reported on 821112 Problem eliminated by addition of insulating spacers between potentiometers & brackets TUCKER-H B Duke Power Co 82/12/10 0'REILLY, J P Region 2, Office of Director 4pp 16483 351 24X Fiche 50-413.82/12/10, 8212210231
- DOCKET 50-416 GRAND OULF NUCLEAR STATION. UNIT 1

 F Security, medical, emergency & fire protection plans
- 8212010176 Discusses util compliance w/Reg Guide 1 97 Final response to Reg Ouide 1 97 at present time would not be in keeping w/intent of SECV-B2-ill for integrated emergency response capability review DALE-L.F Mississippi Power & Light Co B2/11/29 DENTON.H R Office of Nuclear Resetor Regulation, Director 7pp 16258 102 24X Fiche 50-416,82/11/29,8212010176
- BP12090436 Confirms 821124 arrangements or 821202 enforcement conference in Atlanka. GA to discuss circumstances concerning security violation & to discuss resolution of autstanding items O'REILLY. J P Region 2. Office of Director 82/12/01, STAMPLEY. N L Mississippi Fower & Light Co 2pp 16364 269 24X Fiche 50-416.82/12/01,8212090436
- B212290207 Submits supplemental info on emergency preparedness at facilities State of LA revised radiological emergency preparedness plan will be submitted in Feb 1983 due to delays at state level
 THOMAS. IM Federal Emergency Management Agency B2/12/17
 DIRCKS.W Office of the Executive Director for Operations ip 16578 202. 24% Fiche 50-416,82/12/17.8212290207

- 8212270235 Forwards add1 info re adequacy of onsite communication sys. per 821115 telcon Communication sys testing during startup phase will provide confidence that use of two-way radios is restricted as required DALE/L F Mississippi Power & Light Co 82/12/22 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 13pp 16536 253 24X Fiche 50-416,82/12/22,8212270235
- Q Adjudicatory correspondence
- 8212100113 Decision ALAB-704, affirming ASLB 821020 decision denying State of LA 820721 petition to intervene subj to final outcome of judicial proceedings before US Supreme Court in NRC vs NRDC SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 13pp 16375 346 24X Fiche 50~416.82/12/08.8212100113
- P Operating license stage documents & correspondence
- E711230066 Generic Ltr 82-27 to all BWR licensees of operating reactors escept LACENR. Big Rock Point, Dresden I. Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 Svc list encl Wo stated encl EIEENHUT.D G Division of Licensing 92/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24x Fiche 50-000, 82/11/15, 9211230066
- GP12090429 Forwards 821102 mreting summary re activities authorized by Licenses NPF-13 % CPPR-13 Meating beneficial & provided better understanding of issues W/o encl
 D'REILLY, JP Region 2, Office of Director 82/11/15 LEWIS, F W
 Hiddle South Utilities, Inc Middle South Energy, Inc 2pp
 16344 274 24X Fiche 50-000, 82/11/15, 8212090429
- 9:12060379 Forwards enhanced copy of approved offsite dose calculation manual SCHWENCER.A Licensing Branch 2 82/11/16 MCGAUGHY, J P Mississippi Power & Light Co 2pp 16323 068 24X Fiche 50-416.82/11/16.8212060379
- --8212060386 Revised offsite dose calculation manual • Applied Physical Technology, Inc. 82/01/12 75pp 16323 070 24 Fiche 50-416,82/11/16,8212060379
- GP12010027 Notifies that process control program approved per B2042/ Itr Future changes should be handled as described in 10CFR50 71 for revisions to FSAR re replacement pages, change indicators & certification GCHMENCER.A Licensing Branch 2 B2/11/19 MCGAUGHY, J P Mississippi Pouer & Light Co 2pp 16271 357 24x Fiche 50-416.82/11/19.8212010027
- GP12010176 Discusses util compliance w/Reg Guide 1 97 Final response to Reg Guide 1 97 at present time would not be in keeping w/intent of SECY-02-111 for integrated emergency response capability review DALE.L F Mississippi Power & Light Co 82/11/29 DENTON.H R Uffice of Nuclear Reactor Regulation. Director 7pp 16258 102 24X Fiche 50-416,82/11/29.8212010176
- 8:12070274 Forwards balance of info to close Humphrey containment concerns, including "Evaluation Rept on Modified SDLA-VOF Code" & "Survay of Fests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode" & proprietary Figures 18 25 DALE.4. F Mississippi Power & Light Co 82/12/03 DENTON.H R Office of Noclear Reactor Regulation, Director &2pp 16340 128 24X Fiche 50-4(6.82/12/03.82)2070274
- -8212070276 "Evaluation Rept on Modified SOLA-VOF Code"
 HIRT.C W. SICILIAN, J M Flow Science, Inc 82/10/18 11pp
 16340 170 24% Fiche 50-416,82/12/03,8212070274
- --8212070278 Revision A to "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode"

 so Quadrex Corp QUAD-1-82-245 REV A 82/11/30 51pp
 16340 201 24X Fiche 50-416, 82/12/03,8212070274
- B?/12170278 Comments on BWRDG-8260, "NURFG-0737, Item II K 3 18, Mod of Autoratic Depressuriation Sys Logic " Option 4, providing bypass timer delay, will assure adequate core cooling during worst case conditions

 UALE, L. F. Mississippi Power & Light Co. 82/12/14 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 2pp 14461 152 1/4X Fiche 50-416,82/12/14.8212170278
- BP12230252 Discusses util responses to recently discussed unresolved NRC concerns re automatic depressurization sys air sys DALE, L F Mississippi Power & Light Co 82/12/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 14511 063 04X Fiche 50-416,82/12/20,8212230252

- 8212300184 Forwards Amend 5 to License NPF-13, safety evaluation & notice of issuance & availability Amend changes schedule for completion of open items & corrective actions for environ qualification of safety-related electrical equipment SCHMENCER. A Licensing Branch 2 82/12/20 MCOAUGHY, J P Mississippi Power & Light Co 4pp 16613 086 24X Fiche \$0-466,82/12/20,8212300184
- --8212300188 Amend 5 to License NPF-13, changing schedule for completion of corrective actions for safety-related electrical equipment to end of first refueling outage EISENNUT.D 6 Division of Licensing 82/12/20 7pp 16613 060 24% Fiche 50-416,82/12/20,8212300184
- --B212300194 Safety evaluation supporting Amend 5 to License NPF-13 * Office of Nuclear Reactor Regulation, Director \$2/12/20 3pp 16613 O67 24X First 50-416,82/12/20.8212300184
- 8212300203 Notice of issuance & availability of Amend 5 to License NPF-13
 BDURNIA, A , SCHWENCER, A Licensing Branch 2 82/12/20 3pp
 16613 070 24X Fishe 50-416, 82/12/20, 8212300184
- GE:12270147 Application for amend to License NPF-13, adding provision to license Condition Item 2 C(42)h re installing protective sleeves un bottom entry in-core assemblies & revising License Condition 2 C(42); re startup source replacement MCOAUOHY. J P Mississippi Power & Light Co. 82/12/22 DENTON, H & Office of Nuclear Reactor Regulation, Director. 3pp. 16538-060-24X Fithe 50-416.62/12/22,8212270147
- --8212270153 Proposed changes to Tech Specs re installing protective sleeves on bottom entry in-core assemblies & reducing sleeves on bottom entry in-core assemblies & reducing * Mississipp: Power & Light Co 82/12/22 4pp 16538 063 24x Fiche 50-416.82/12/22.8212270147
- 92:12270154 Submits updated qualification status & justification for interim operation of NSSS equipment not meeting SQRT criteria, originally submitted 920405 NALE:L.F. Hississippi Power & Light Co. 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16598 343 P4X Fische 50-446.82/12/22.8212270154
- ⊕ Inspection reports, IE Bulletins & correspondence
- BR0B190240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Wall/Large-Diameter; Stainless Steel/Recirculation Bys Piping at BMR Plants " Svc list encl
 DEVDUNO, R C Director's Office. Office of Inspection and
 Inforcement B2/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000.82/10/28.8268190240
- B212090414 Approves issuance of BALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Ngt attentive to matters of nuclear safety Weaknesses in Unit 1 preoperational testing & training programs noted O'REILLY, J P Region 2, Office of Director 82/11/01 STAMPLEY, N L Minstssippi Power & Light Co 2pp 16365 013 24% Fiche 50-416, 82/11/01.8212090414
- --8212090421 Forwards SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Comments requested within 20 days LEMIS.R C Division of Project & Resident Programs 82/07/22 STAMPLEY.N L Mississippi Power & Light Co 2pp 16365 014 24x Fiche 50-416,82/11/01.8212090414
- --8212090427 SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Weaknesses in Unit 1 preoperational testing & training programs noted * Region 2. Office of Director 82/07/22 15pp 16365 017 24x Fiche 50-416,82/11/01,8212090414
- G20B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!

 CDBB.L. I Division of Fuel Factilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05.8208190245.
- 8/08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDÁN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 179 24X Fiche 50-000,82/11/18,8208190251
- BP08190256 IE Info Notice 92-46, "Defective & Obsolete Combination Padlacks" Svc list enci DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065, 24% Fiche 50-000.82/11/26.8208190256

- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities. Materials & Safeguards 82/11/30 Consplidated Edison Co of New York, Inc 364pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8212090282 Ack receipt of 820927 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-414/82-58 LEWIS.R C Division of Project & Resident Programs 82/12/01 STAMPLEY.N L Wississippi Power & Light Co ip 16365 243 24X Fiche 50-416.82/12/01.8212090282
- --8212090270 Responds to NRC 820827 ltr re violation noted in IE Imsp. Rept 50-416/82-58-02 Corrective actions 10CFR50 59 safety evaluation of Chem-Nuclear solidification sys performed a personnel instructed to perform evaluation prior to mod MCGAUGHY, J.P. Mississippi Power & Light Co. 82/09/27 O'REILLY, J.P. Region 2, Office of Director 2pp. 16265 244 249 Fiche 50-416.82/12/01.8212090282
- --B212070303 Responds to NRC B20827 ltr re violations noted in IE Insp Rept 50-416/82-58 Violation denied as stated Caused by misinterpretation of plant administrative Procedurs 01-8-08-5, "Radiological Surveys & Surveillance" MC0AU6HV.J P Mississippi Power & Light Co B2/09/27 D'REILLY.J P Region 2. Office of Director 2pp 16365 246 24) Fiche 50-416,82/12/01.8212090282
- --8212090310 Responds to NRC 820827 ltr re violations noted in IE Insp. Rept 50-416/82-58 Corrective actions 10CFR50 37 evaluation required prior to mod of radwaste solidification sys will be performed & procedures revised MCGAUGHY. J P Mississippi Power & Light Co 82/09/27 O'REILLY. J P. Region 2. Office of Director 2pp 16365 248 24x Fiche 50-416,82/12/01,8212090282
- --8212090315 Forwards IE Insp Rept 50-416/82-58 on 820802-05 & notice of violation
 LEHIS.R C Division of Project & Resident Programs 82/08/27 STAMPLEY.N L Mississippi Power & Light Co 2pp 16365-250 24% Fiche 50-416,82/12/01.8212090282
- --8212090320 Notice of violation from insp on 820802-06 * Region 2, Office of Director 82/08/27 2pp 16365 252 24x Fiche 50-416.82/12/01.8212090282
- --8212070332 IE Insp Rept 50-416/82-58 on 820802-06 Noncompliance noted failure to review Chen-Nuclear solidification sys prior to use, safety evaluation not unitten on alterations to raduate sys & surveys not performed in restricted areas COLLINS.T R , BARR.K P Division of Engineering & Technical Programs 82/08/30 6pp 16365 254 24X Fiche 50-416.82/12/01, 8212090282
- 8P12090436 Confirms B21124 arrangements re 821202 enforcement conference in Atlanta, GA to discuss circumstances concerning security violation & to discuss resolution of outstanding items
 O'REJELY, J P Region 2, Office of Director 82/12/01
 STAMPLEY, N L Mississippi Power & Light Co 2pp 16364 269 24X Fiche 50~416, 82/12/01, 8212090436
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Contashment Electrical Panetration Assemblies " Svt list encl DEYOUNG.R C Director's Defice. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-00D.82/12/03.8208190259
- 8208190261 JE Info Notice 82-48, "failures of Agastat CR 0095 Relay Bockets " Svc list enc! JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24x Fishe 50-000.82/12/03.8208190261.
- 5:'OB190267 IE Into Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNG.R C Director's Defice. Defice of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16,8208190267
- 8208190268 IE Info Natice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list enc! JORDAN,E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 241 Fiche 50-000,82/12/20,8208190268
- R Periodic operating reports & related correspondence
- G212200103 Forwards monthly operating rept for Nov 1982 MCGAU9HY,J P Mississippi Power & Light Co 82/12/15 BEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 16470 079 24X fiche 50-416,82/12/15,8212200103

- S Reportable occurrences, LERs & related correspondence
- B212020033 Forwards updated LER 82-081/99X-1 MCGAU9HY, J P Mississippi Power & Light Co 82/11/22 D'REILLY, J F Region 2. Defice of Director Ip 16272 054 2AX Fiche 50-416. 82/11/22.0212020033
- --6212020037 Updated LER 82-081/97X-1 on 820916, during preoperational testilocal instrument check revealed discrepancies in containment ventilation monitoring sys effluent flourate monitor indications Caused by clogged manifold BYRD.R Mississippi Power & Light Co 82/11/22 Region &, Office of Director 2pp 16272 055 24X Fiche 50-416, 62/11/22.
- 8712020050 Forwards LER 82-108/97L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/11/24 O'REILLY, J P Region 2, Office of Director (p 16272 060 24. Tiche 50-416, 82/11/24, 8212020050
- --821202006) LER 82-108/99L-O on 821027. discovered surveillance requirements for some fire detection instruments not met & no documentation axisted to indicate that heat detectors listed in Table 3 3 7 9-1 tested Cause not stated FREEMAN.M 5 Mississippi Power & Light Co 82/11/24 Region 2. Office of Director 2pp 16272-061 24X Fiche 50-416,82/11/24. B212020050
- BP1202005B Forwards updated LER 82-103/01X-1 MCGAUGHY.J P Mississippi Power & Light Co 82/11/24 O'REILLY.J P Region 2: Office of Director 1p 14272 063 24X Fiche 50-416.82/11/24.8212020058
- GP12020138 Forwards LER 82-105/01T-0 NCGAUGHY. J P Mississippi Power & Light Ca 82/11/24 O'REILLY. J P Region 2, Office of Director 1p 16274 161 24% Fiche 50-416.82/11/24.8212020138
- --B212020144 LER B2-109/017-0 on B21110, design review revealed turbine trip condition in FBAR analysis less conservative than that caused by circulating water pump trip Caused by failure to account for 5-s steam bypass operation after turbine trip BYRD: R Mississippi Power & Light Co. 82/11/24 Region 2, Office of Director ip 16274 162 24X Fiche 50-416,82/11/24.
- GP12090078 Forwards LER 62-109/03L-0 NCGAUGHY, J P Mississipp: Power & Light Co 82/12/01 O'REILLY, J P Region 2, Office of Director 1p 16357 330 24X Fiche 50-414, 82/12/01, 8212090078
- --B212090061 LER B2-109/03L-0 on B21102, diesel generator air start receiver pressure discovered less than required 175 psig Caused by open circuit breaker Breaker closed RCHRER.M V Mississippi Power & Light Co B2/12/01 Region & Office of Director ip 16357 331 24X Fiche 50-416,82/12/01. B212090078
- SE:12090110 Forwards LER 82-128/03L-0 NCGAUGHY.JP Mississippi Power & Light Co 82/12/01 O'REILLY.JP Region 2. Office of Director 1p 16357 301 24X Fiche 50-416, 82/12/01.8212090110
- 8212090113 LER 82-128/03L-0 on 821102, standby diesel generator 12 placed in maint mode while diesel generator 11 also down for maint Caused by need to perform regular maint Cenerator 11 repaired & returned to svc on 821118 FREEMAN. 4 S Mississippi Power & Light Co 82/12/01 Region 2. Office of Director 1p 16357 302 24X Fishe 50-416,82/12/01, 8212090160
- 07:12090131 Forward* LER 82-127/031,~0 MCGAUCHY.JP Hisrissippi Power & Light Co 82/12/01 O'REILLY.JP Region 2. Office of Director 1p 16359 179, 24X Fiche 50-416.82/12/01.8212090131

- --8212090136 LER 82-127/03L-0 on 821102 during cold shutdown shutdown cooling loop B of RMR sys declared inoperable in order to perform work on butterfly valve Caused by valve being installed backward due to const error Work completed 82!124 RDIRER, M V Mississippi Power & Light Co 82/12/01 Region 2, Office or Director 1p 16359 180 24X Fiche 50-416.82/12/01,
- 87:2090177 Forwards Interim LER 82-123/99X-0 MCGAUGHY, J P Mississippi Power & Light Co 82/12/01 O'REILLY, J P Region 2. Office of Director 1p 16359 211 243 Fiche 50-416, 82/12/01, 8212090177
- -8212090184 Interim LER 82-123/99X-0 on 821102, cabinet 1H12P700 A.B.D & E. HH13P735A & B & HH13P714A & B fire barrier penetrations in control bldg at 166 ft, broken for planned maint Hourly fire watch established Updated rept to be submitted by 830202 FLOVD. J M Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16359 212 24X Fiche 50-416,82/12/01, 8212090177
- GP12090326 Forwards LER 82-126/99L-0
 HCGAUGHY, J P Mississippi Power & Light Co 82/12/01
 O'REILLY, J P Region 2, Office of Director ip 16365 [13 24X fiche 50-416, 82/12/01, 82(2090326)
- --8212090344 LER 82-126/99L-O on 821026, several fire dams & penetration seals broken while replacing shorted cable running from control room to computer room Fire dams restored Work still progressing on penetration seals Update by 830202 FREE/ANIM S Mississippi Power & Light Co 82/12/01 Region 2, Office of Director 1p 16365 114 24X Fiche 50-416,82/12/01. 82/12/0090326
- 87:12090074 Forwards LER 82-119/03L-0 MCGAV9HY, J P Mississippi Fower & Light Co B2/12/02 D'REILLY, J P Region 2. Office of Director 1p 16357 362 24X Fiche 50-416, 82/12/02, 8212090074
- ~~B212090075 LER 82-119/03L-0 on 821104, smoke detectors in zone covering auxiliary bldg east corridor annunciated Caused by dust accumulation Detectors cleaned & program instituted to clean detectors periodically FLOYD.J M Mississippi Power & Light Co 82/12/02 Region 2, Office of Director ip 16357 363 24X Fiche 50-414,82/12/02, 8212090074
- GP:12090151 Forwards LER 62-118/03L-0 NGGAUGHY, J P Mississippi Power & Light Co 92/12/02 B'REILLY, J P Region 2. Office of Director in 16359 117 24X Fiche \$0-414.82/12/02.8212090151
- ~-8212090158 LER 82-118/03L-0 on 821104, smoke detectors in piping penetration. RHR C pump & LPCS rooms of auxiliary bldg ampunciated w/o presence of smoke or fumes Caused by accumulation of dust on detectors
 FLOYD. J M Mississippi Power & Light Co 82/12/02 Region 2
 Office of Director ip 16359 118 24X Fiche 50-416,82/12/02,8212090151
- G;12090159 Forwards LER G2-112/03L-0 MCGAUJHY, J P Mississippi Power & Light Ca 82/12/02 U'REILLY, J P Region R, Office of Director 1p 16359 100 24X Fiche 50-416, 82/12/02, 8212090159
- --8212070164 LER 82-112/03L-0 on 821105, smoke detector in east switchgrar & piping penetration rooms of auxiliary bidg, elevation 117 ft. alarmed & would not reset Caused by dust in detector Detector cleaned & returned to see on 821108 FREEMAN, M S Mississippi Power & Light Co 82/12/02 Region 2, Office of Director ip 16359 101 24X Fiche 50-416,82/12/02, 82/12090159
- 8:12090191 Forwards LER 82-110/03L-0 MCGAU9HY, J P Mississippi Power & Light Co O'REILLY, J P Region 2. Office of Director | Ip 16361 298 24X Fiche 50-416, 82/12/02, 8212090191
- --8212070175 LER 82-110/03L-0 on 821105, auxiliary bldg east corridor area smake detectors at 119 ft alarmed & did not reset Caused by accumulation of dust Ionization smake detector cleaned & returned to syc Periodic detector cleaning initiated ROMRER.M V Mississippi Power & Light Co 82/12/02 Region 2, Office of Director ip 16361 279 24X Fiche 50-416,82/12/02, B212070171
- B?/12100297 Forwards LER 82-114/03L-0 NGGAUGHY.J P Mississipp: Power & Light Co 82/12/07 G'REILLY.J P Region 2. Office of Director ip 16376 219 24X Fiche 50-416.82/12/07.8212100297

- --8212100306 LER 82-114/03L-0 on B2110B, smoke detector in zone covering control bldg. Elevation 166 ft & 177 ft, alarmed & would not reset Caused by damage to detector due to installation work in area Detector replaced & tested satisfactorily FREEMAN.8 Mississippi Power & Light Co 82/12/07 Region 2. Office of Director 1p 16376 220 24X Fiche 50-416, B2/12/07, 8212100297
- B212170137 Forwards LER 82-120/99X-0 MCGAU9HV.J P. Mississippi Pawer & Light Co. 82/12/13 O'REILLY.J P. Region 2. Office of Director 1p. 16450 274 24X Fiche 50-416, 82/12/13.8212170137
- --9212170146 LER 82-120/97X-O on 821105, during shutdown, fire door 1Al06 opened to drain standby syc water loop B by allowing passage of hose to channel water from flush & drain of loop Boor will be restored Final rept expected by 830212 FLOYD. J M Mississippi Power & Light Co 82/12/13 Region 2, Office of Director Ip 16450 275 24X Fiche 50-416, 82/12/13, 82/12/1319.
- B212170209 Farwards LER B2-13D/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/12/13 D'REILLY, J P Region 2, Office of Director 1p 16459 347 24X Fiche 50-416, 82/12/13, 8212170209
- --B212170213 LER 82-130/03L-0 on 821112, shutdown cooling loops A & B of RHR sys simultaneously inoperative Caused by need to bring down loop A to perform surveillance tests & add water to reactor vessel Surveillance performed FREEMAN, M B Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 1p 16459 348 24% Fiche 50-416, 82/12/13, 8212770209
- B7/2170222 Forwards LER B2-122/99X-0 NCGAUGHY,J P Mississippi Power & Light Co 82/12/13 O'REILLY,J P Region 2, Office of Director ip 16459 319 24X Fiche 50-416.82/12/13.8212170222
- --B212170227 LER B2-122/97X-0 on B21104 during shutdown cover to HVAC chase on elevation 148 ft in control bldg lower cable spreading room found removed Cause unknown Cover reinstalled investigation continuing FLOYD. J M Mississippi Power & Light Co. B2/12/13 Region 2. Office of Director 1p 16459 320 24X Fiche 50-416, 82/12/13.
- 82:12170263 Forwards LER 92-125/03L-0 MCGAUGHY.J P Mississippi Power & Light Co 82/12/13 O'REILLY.J P Region 2. Office of Director 1p 16456 211 24X Fichs 50-416.82/12/13.8212170263
- --B212170277 LER 82-125/O3L-O on B21113,200 gallons of potentially contaminated plant svc water drained to storm drains Effluent not sampled prior to release Caused by personnel error Personnel instructed ROHRER, M V Mississippi Power & Light Co B2/12/13 Region 2, Office of Director ip 16456 212 24X Fiche 50-416, 82/12/13, B21270263
- B212170313 Forwards LER 82~129/03L~0 MCGAUGHV.JP Mississippi Power & Light Co 82/12/13 O'REILLY.JP Region 2: Office of Director 1p 16456 153 24X Fiche 50~416.82/12/13.8212170313
- --B212170327 LER 82-129/03L-0 on 821113,14 & 15, smake detectors in auxiliary bidg new & spent fue; pool, east corridor, northeast corridor equipment & steam tunnel root areas annunciated & would not reset Caused by dust in detectors ROMRER.M V Mississippi Power & Light Co 82/12/13 Region 2, Office of Director 2pp 16456 154 24X Fiche 50-416,82/12/13,8212170313
- 8212170334 Forwards LER 82-075/97X-0 MCGAUGHY, J P Mississipp: Power & Light Co 82/12/13 D'REILLY, J P Region 2. Office of Director 1p 16456 160 24X Fiche 80-414, 82/12/13. 8212170334
- --8212170339 LER 82-095/99*-0 on 821106, three fire rated doors in auxiliary bidg blocked open due to painting suppression pool Caused by need to route sandblasting hoses from outside bidg into suppression pool Hourly fire watch established FREEMAN, M S Mississippi Power & Light Co 82/12/13 Region 2, Office of Director ip 16456 161 24% Fiche 50-416,82/12/13, 82(2170334
- 8712210155 Forwards LER 82-063/79X-1 MCGAUGHY, J P Mississipp; Power & Light Co 82/12/14 O'REILLY, J P Region 2, Office of Director ip 16484,241 24X Fiche 50-416,82/12/14,8212210155

- --8212210182 LER 82-063/99x-1 on 820902, during shubdown, several firerated cable penetration seals were broken on field termination cabinets in control room to allow routing of add1 cable Seals repaired fullowing maint activities ALBERT, J M Mississippi Power & Light Co 82/12/14 Region 2, Office of Director ip 16484 242 24X Fiche 50-416, 62/12/14, 8212210155
- 82:12210179 Forwards LER 82-132/01T-0 NCGAUGHY. J P Mississipp: Power & Light Co 82/12/14 O'REILLY. J P Region 2. Office of Director 1p 16484 339 24X Fiche 80-416, 82/12/14, 8212210177
- --B212210192 LER B2-132/01T-0 on B21130 & 1202, several fire-rated electrical penetrations found open Penetration openings authorized by maint work orders w/o notifying control room instructions issued to responsible persons FREEMAN, B Mississippi Power & Light Co B2/12/14 Region 2, Office of Director 2pp 16484 340 24X Fiche 50-416, B2/12/14, 8212210179
- 8212210191 Forwards LER 82-011/99X-1 NCGAUGHY.J P Mississippi Power & Light Co 82/12/14 O'REILLY.J P Region 2: Office of Director ip 14485 014 24X Fiche 50-416, 82/12/14, 8212210191
- --B212210205 LER 82-011/97X-1 on 820722, during functional testing of diesel generator 12.generator tripped due to high water jacket temp Gaused by elevated cooling water temps due to isolated cooling water outlet valve Design change made MONREM. M V Mississippi Power & Light Co 82/12/14 Region 2 Office of Director 2pp 16485 017 24X Fiche 50~416,82/12/14,8212210171
- BP12210367 Forwards interim LER 82-027/99X-1 MCGAUGHY.J P Mississipp: Power & Light Co 82/12/14 O'REILLY.J P Region 2. Office of Director 1p 16494 273 24X Fiche 50-416.82/12/14.8212210367
- ---821221037i Interim LER 82-027/59X-1 on 820727. during special insp. seal AV-8D discovered not installed in spare HVAC penetration to containment exhaust filter train room Threaded conduit plug installed Design change requested ROHRER. M V Mississippi Power & Light Co 82/12/14 Region 2, Office of Director 1p 16494 274 24X Fiche 50-416, 82/12/14, 8212210367
- 8212210212 Forwards LER 82-021/99X-t MCGAUGHY, J P Mississippi Pawer & Light Co B2/12/15 O'REILLY, J P Region 2. Office of Director 1p 16483 359 24X Fiche 50-416, 82/12/15, 8212210212
- --8212210227 LER 82-021/97X-1 on 820720, limiting condition for operation entered due to quarterly test of radioactive liquid effluent manitoring sys not being performed by 820720 Caused by inadequate sys design Design change implemented ROMRER, N V Mississippi Power & Light Co 82/12/15 Region &, Office of Director 1p 16483 360 24X Fiche 50-416,82/12/15,8212210212
- 82122(0375 Interim Deficiency Rept 4 re corroded terminal boards on transmitters initially reported on 820421 Corrosion attributed to moisture Final rept expected by 830128 MCGAUGHY.J P Mississippi Power & Light Ca 82/12/15 D'REILLY,J P Region 2, Office of Director 2pp 16494-314 24X Fiche 50-416.82/12/15.8212210375
- 8212280080 Forwards interim LER 82-031/97X-1 HCGAUGHY, J P Mississippi Power & Light Co 82/12/15 O'REILLY, J P Region 2: Office of Director 1p 16564 236 24X Fiche 50-416, 82/12/15, 8212280080
- --8212280081 Interim LER 82-031/99X-1 on 820722.HVAC penetration seal CV-190 found not installed during insp Caused by const oversight Maint work order released to install seal & hourly fire watch established until task completed ROMRER.M V Mississippi Power & Light Co 82/12/15 Region 2, Office of Director 1p 16564 237 24X Firhe 50-416,82/12/15,8212280080
- 8212280377 Final Deficiency Rept PRD-82/33 re excessive length of capacreus in standby diesel generator air start valve assembly potentially resulting in valve failure Initially reported on 820623 Deficiency not reportable per Port 21 MCGAUGHY, J F Mississippi Power & Light Co 82/12/15 O'REILLY, J P. Region 2, Office of Director 5pp 16959 006 24) Fiche 50-416,82/12/15,8212280377.
- 8212280056 Forward: LER 82-140/97X-0 MCGAUDHY.J P Mississippi Power & Light Co 82/12/16. O'REILLY.J P Region 2. Office of Director 1p 16568 141 24X Fichs 50-416.82/12/16.8212280036

- --B212280057 LER 82-140/97X-0 on 821112.during shutdown, fire door LA2(J (entrance to valve room 1A220) blocked open for hose which supported local leak rate testing Fire watch in effect Fire door secured upon test completion FLOYD.J M Mississippi Power & Light Co 82/12/16 Region 2. Office of Director 1p 16565 142 24X Fiche 50-416,82/12/16,82/280054
- GP12280150 Forwards Interim LER 82-138/97X-0 MCGAUGHV, J P Kississippi Power & Light Ca 62/12/16 O'REILLY, J F Region 2. Office of Director 1p 16563 113 24X Fichs 50-416, 82/12/16, 82/2280150
- --8212280154 Interim LER 92-138/99X-0 on 821112.during shutdown, several duct covers could not be installed due to cables extending through ducts Caused by faulty design document Engineering evaluation underway AMBROSINO, R A Hississippi Power & Light Co 82/12/16 Region 2. Office of Director 1p 16563 114 24X Fiche 50-416,82/12/16.
- 8212280177 Forwards LER 82-139/03L-0 MCGAUGHY.J P Mississippi Power & Light Co 82/12/16 O'REILLY.J P Region 2. Office of Director 1p 16562 179 24X Fiche 50-416, 82/12/16, 8212280177
- --B212280183 LER 82-139/03L-0 on 821118, smake detector in control cabinet room alarmed & would not reset No smoke or fumes present in area Caused by defective detector Fire watch established & detector replaced ROHRER, M V Mississippi Fower & Light Co 82/12/16 Region 2, Office of Director Ip 16562 180 24X Fiche 50-416, 82/12/16, 821280177
- 8212280241 Forwards LER 82-137/03L-0 MCGAUCHY.J P Mississippi Power & Light Co 82/12/16 D'REILLY.J P Region 2. Office of Director 1p 16561 205 24X Fiche 50-416,82/12/16,82/2280241
- --8212280245 LER 82-137/03L-0 on 821117, fire rated doors 00503 & 00501 blocked open by hases being used in sealing of control room penetrations during shutdown Caused by planned maint activities Hourly fire watch established AMBROSIND R A Mississippi Power & Light Co 82/12/16 Region 2. Office of Director ip 14561 206 24X Fiche 50-416.82/12/16, 8212280241
- BP12280386 Forwards LER 82-142/99X-0 NCGAUGHY, J P Mississippi Power & Light Co 82/12/16 D'REILLY, T P Region 2, Office of Director 1p 16958 360 24X Fiche 50-416, 82/12/16, 8212280386
- --8212280387 LER 82-142/97X-0 on 821118, during shutdown, fire barriers broken in control room to allow cable rerouting per approved maint work order Fire watch established Fire barriers reseated following completion of work FLOYD.J M Mississippi Power & Light Co 82/12/16 Region & Office of Director 1p 16558 361 24X Fiche 50-416,82/12/16.82/1220336
- 8212280458 Forwards LER 82-141/99X-0 MCGAVOHY, J P Mississippi Pawer & Light Co 82/12/16 D'REILLY, J P Region 2, Office of Director 1p 16556 020 24X Fiche 50-416, 82/12/16, 8212280458
- --8212280463 LER 82-141/99X-0 on 821112, fire doors 1A308 & 1A316 blocked open to route hoses to sandblasting operations in suppression pool Caused by planned maint activity Upon work completion doors will be restored
 BYRD, R Mississippi Power & Light Co 82/12/16 Region 2, Office of Director ip 16556 021 24X Fiche 50-416, 62/12/16, 82/1220158
- 8212280466 Forwards LER 82-135/99X-0 MCGAUGHY.J P Mississippi Power & Light Co 82/12/16 O'REILLY.J P Region 2. Office of Director 1p 16556 018 24X Fiche 50-416, 82/12/16, 8212280466
- --8212280475 LER 82-135/97X-0 on 821105, smoke detectors in auxiliary bldg steam tunnel covered to prevent fumes from causing erronsous alarms Caused by paint fumes from planned maint activity fire watch established until 821208 AMBROSING R A Mississippi Power & Light Co 82/12/16 Region 2, Office of Director 1p 16556 019, 24X Fiche 50-416,82/12/16,8212280466
- B212280402 Forwards LER 92-133/03L-0 MCGAUBHY,J P Mississippi Power & Light Co 82/12/17 U'REILLY,J P Region 2, Office of Director 1p 16560 053 24% Fiche,50-416,82/12/17,8212280402

2:

- --8212280412 LER 82-133/O3L-O during 821027-29, RMR & LPCS rendered inoperable when suppression pool drained to allow painting of carbon steel components Limiting conditions for operation entered Painting completed & pool filled 821204 AMBROSING.R A Mississippi Power & Light Co 82/12/17 Region 2, Office of Director 2pp 16560 O54 24X Fiche 50-416, 82/12/17.8212280402
- 02)2280194 Forwards LER 82-123/97X-1 MCGAUGHY, JP Mississippi Power & Light Co 82/12/20 O'REILLY, JP Region 2, Office of Director 1p 16562 294 24X Fiche 50-416, 82/12/20, 8212280194
- --8212280198 LER 82-123/99X-1 on 821102, fire barrier penetrations to cabinets in control bldg broken to complete planned maint activity Fire watch established Penetrations resealed Limiting conditions for operation cleared FLOYD, J M Mississippi Power & Light Co 82/12/20 Region 2, Office of Director ip 16562 295 24X Fithe 50-416,82/12/20,8212280194
- 9212280308 Forwards LER 82-134/03L-0 MCGAUDHY, J P Mississippi Power & Light Co B2/12/20 O'ARTILLY, J P. Region 2. Office of Director ip 16561 133 24X Fiche 50-416, 82/12/20.8212280308
- --8212280311 LER 82-134/03L-0 on 821201, during cold shutdown, RHR loop A shut down to allow flush of RHR loop B piping Caused by need to maintain RHR loop B for return to operation RHR loop A returned to svc ROMRER. II V Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16561 134 24X Fiche 50-416, 82/12/20.
- 8:12280312 Forwards LER 82-048/99X-0 MCGAUGHY. J P Mississippi Power & Light Ca 82/12/20 O'REILLY. J P Region 2. Office of Director 1p 16561 361 24X | iche 50-416,82/12/20,8212280312
- --B212280314 LER 82-048/97X-0 on 820812, discovered unsealed fire berrier between two control room cabinets Caused by const oversight Fire barrier sealed by maint work order on 820919 ROHRER. W. Mississippi Power & Light Co. 82/12/20 Region 2, Office of Director 1p. 16561-362 24X Fiche 50-416, 82/12/20, 8212280312
- G212280327 Forwards LER B2-107/03X-1 MCGAUGHY,JP Mississippi Power & Light Co 62/12/20 U'REILLY,JP Region 2. Office of Director 1p 14541 064 24X Liche 50-416, 62/12/20, 6212280327
- --8212280336 LER 82-107/03X-1 on 821014, when entering Mode 3, requirements of Tech Spec 3 6 5 c not satisfied Caused by inoperable drywell post-LOCA vacuum breaker position indicators indicators replaced Tech Specs amended ALBERTIJM Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 1p 16561 065 24X Fiche 50-414,82/12/20,8212280327
- B£12280344 Forwards LER 82-033/99X-i MCOAUGHY.JP Mississippl Power & Light Ca 62/12/20 G'REILLY.JP Region 2. Office of Director ip 16561 035 24X Fiche 50-416.82/12/20.6212280344
- --8212280352 LER B2-033/99X-1 on 920814, HPCS diesel generator 13 started on low reactor vessel level indication & tripped on overspeed Caused by faulty tachometer relay Dynalco relay replaced & sys restored on 820818

 BYRD, R Mississippi Power & Light Co 82/12/20 Region 2, Office of Director 2pp 16561 036 24X Fiche 50-416,82/12/20, 8212280344
- G212300039 Forwards LER 82-146/03L-0 NCGAUGHY, J P Mississippi Power & Light Co B2/12/22 O'REILLY, J P Region 2. Office of Director 1p 16599:196 24X Fiche 50-416, 62/12/22, 8212300037
- --B212300047 LER 82-146/03L-0 on 821124, drywell to containment differential pressure not verified within proper frequency during hot shutdown Caused by inadequate procedure Procedure revised ROMRER, M V Mississippi Power & Light Co 82/12/22 Region 2, Office of Director ip 16598 197. 24X Fiche 50-416, 82/12/22, 821200039
- 8212300084 Forwards LER 82-143/03L-0.
 MCGAUOHY. J P Mississippi Power & Light Co 82/12/22
 O'REILLY. J P Region 2. Office of Director 1p 16599 027 24:
 Fiche 50-416: 82/12/22:8212300084

- --8212300087 LER 82-143/03L-0 on 821201.seismic switch alarmed & would not reset No seismic event had occurred Caused by instrument cover touching cover bracket resulting in spurious alarms when personnel walked across floor Cover repositioned ROHRER, M V Mississippi Power & Light Co 82/12/22 Region 2, Office of Director ip 16599 028 24X Fiche 50-416.82/12/22, 8212300084
- 8212300114 Forwards LER 82-144/03L-0 MCGAUGHY, J P Mitsissippi Power 5 Light Co 82/12/22 O'REILLY, J P Region 2. Office of Director 1p 16598 231 24X Fiche 50-416. 82/12/22.8212300114
- --B212300119 LER B2-144/03L-O on B21125.fire detection zones 2-7 & 2-8 alarmed W/no fire or smoke present Cause undetermined Smoke detectors N531G & N707B reset BYRD.R Mississippi Power & Light Co B2/12/22 Region 2, Office of Director 1p 16598 232 24X Fiche 50-416.82/12/22.
- 82:12300186 Forwards LER 82-145/03L-0 MCGAUGHY, J P Mississippi Power & Light Co 82/12/22 D'REILLV.J P Repion 2. Office of Director 1p 16578 029 24X Fiche 50-416,82/12/22,8212300186
- --B212300200 LER B2-145/03L-O on B21127, meteorological monitoring systemoved from syc for approx 7 5 h to perform work as required by Design Change Package B2-457 Caused by planned maint outage Change implemented BYRD, R Mississippi Power & Light Co B2/12/22 Region 2, Office of Director 1p 16578 C30 24X Fichs 50-416,82/12/22,8212300186
- --B212300228 LER 82-153/79T-O on 821207, during daily channel check, channel A wind direction sensor at elevation 162 ft gave erroneous indication Caused by defective sensor Sensor replaced & channel returned to svc ROHRER, M V Mississippi Power & Light Co 82/12/23 Region 2 Office of Director 1p 16598 035 24X Fiche 50-416,82/12/23,8212300222
- DOCKET 50-417 ORAND QULF NUCLEAR STATION, UNIT 2

 A Application/construction stage focuments & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBER, Big Rock Point Dreaden 1. Humboldt Bay, applicants for OL & holders of CP re transmittel of NUREO-0763 & NUREO-0783 Svc list encl W/o stated encl EISENNUT.D O Division of Licensing 82/11/13 General Public Utilities OPU Service Corp 22pp 16387 004 24% Fiche 50-000.82/11/15,8211230066
- 8212070274 Forwards balance of info to close Humphrey containment concerns, including "Evaluation Rept on Modified BOLA-VOF Code" & "Burvey of Tests & Analyses on Effectiveness of RHR Bys in Pool-Cooling Mode" & proprietary Figures 18 25 DALE, L.F. Mississippi Power & Light Co. 82/12/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 62pp. 16340-128 24X Fichs 50-416,82/12/03,8212070274
- ---8212070276 "Evaluation Rept on Modified SOLA-VDF Code "
 HIRT.C W , BICILIAN, J M Flow Brience, Inc 82/10/18 11pp
 16340 190 24% Fiche 50~416,82/12/03,8212070274
- --8212070278 Revision A to "Survey of Tests & Analyses on Effectiveness of RHR Sys in Pool-Cooling Mode"

 * Guadrex Corp GUAD-1-82-245 REV A 82/11/30 5tpp.
 16340 201 24X Fiche-50-416,82/12/03.8212070274
- 8212170278 Comments on BWR00-8260. "NUREO-0737, Item II K 3 18, Mod of Automatic Depressurization Sys Logic "Option 4, providing bypass timer delay, will assure adequate core cooling during worst case conditions
 DALE: L.F. Mississippi Power & Light Co 82/12/14 DENTON, H R Office of Nuclean Reactor Regulation, Director. Rpp 16461 152 24X Fiche 50-416, 82/12/14, 8212170278
- 8212230252 Discusses util responses to recently discussed unresolved NRC concerns re automatic depressurization sys air sys.

 DALE: L F Hississippi Power & Light Co 82/12/20 DENTON: H R Office of Nuclear Reactor Regulation. Director. 4pp 16511 063 24X Fithe: 50-416:82/12/20.8212230252

- 8212270154 Submits updated qualification status & justification for interim operation of NSSS equipment not meeting SGRT criteria.originally submitted 820405
 DALE, L.F. Mississippi Power & Light Co. 82/12/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 16538-343
 24X Fiche 50-416.82/12/22.8212270154
- F Security, medical, emergency & fire protection plans
- B212290207 Submits supplemental info on emergency preparedness at facilities State of LA revised radiological emergency preparedness plan will be submitted in Feb 1983, due to delays at state level
 THOMAS. I M Federal Emergency Management Agency B2/12/17
 DIRCKS.N Office of the Executive Director for Operations ip 16578 202 24X Fiche 50-416,82/12/17.8212290207
- 8212270235 Forwards add1 info re adequacy of onsite communication sys, per 821115 teleon Communication sys testing during startup phase will provide confidence that use of two-way radios is restricted as required DALE. I Mississippi Power & Light Co 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 16536 253 24% Fiche 50-416,82/12/22,8212270235
- O Adjudicatory correspondence
- 8P12100113 Decision ALAB-704. affirming ASLB 821020 decision denying 8tate of LA 820721 petition to intervene subj to final outcome of judicial proceedings before US Supreme Court in NRC vs NRDC SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 13pp 16375 346 24X Fiche 50-416.82/12/08.8212100113
- G Inspection reports. IE Bulletins & correspondence
- 8208190240 1E Bulletin 82-03.Revision i. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at DWR Plants " Syc list encl DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8212090357 Forwards IE Insp Rept 50-417/82-16 on 821012-15 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/10/28 STAMPLEY,N L Mississippi Power & Light Co 2pg 16365 152 24X Fiche 50-417,82/10/28,8212090357
- --B212090364 IE Insp Rept 50-417/82-16 on B21012-15 No noncompliance noted Major areas inspected structural concrete HARIS, JR. CONLON.T E Division of Engineering & Technical Programs B2/10/26 3pp 16365 154 24X Fiche 50-417,82/10/28,8212090387
- 8212070414 Approves issuance of BALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1780-June 1781 Mgt attentive to matters of nuclear safety Heaknesses in Unit! preoperational testing & training programs noted O'REILLY, J P Region 2, Office of Director 82/11/01 STAMPLEY, N L Mississippi Power & Light Ca 2pp 16365 013. 24X Fiche 30-416.82/11/01.8212070414
- --B212090421 Forwards SALP Repts 50-416/82-45 & 50-417/82-11 for Jul 1980-June 1981 Comments requested within 20 days LEHIB.R C Division of Project & Resident Programs 82/07/22 STAMPLEY.N L Mississippi Power & Light Co 2pp 16365 014 24X Fiche 50-416,82/11/01.8212090414
- --B212090427 SALP Repts 50-416/B2-45 & 50-417/B2-11 for Jul 1980-June 1981 Heaknesses in Unit ! preoperational testing & training programs noted # Region 2. Office of Director 82/07/22 15pp 16365 017 24x Fiche 50-416,82711/01,8212090414
- B20Bi90245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl.
 CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372:142 24X Fiche 30-000.B2/11/05, 820B190245,
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JURDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24X he 50-000.82/11/18.8208190251

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Redicactive Matl " Svc list encl CD88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 cansolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000.82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUND:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000:82/12/03:8208190259
- 8208190261 IE Info Notice 82~48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Syc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 8708190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JGRDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24x Fiche 50-000.82/12/20.8208190268
- S Reportable occurrences. LERs & related correspondence
- 8212280377 Final Deficiency Rept PRD-82/33 re excessive length of capscrews in standby diesel generator air stant valve assembly potentially resulting in valve failure Initially reported on 820623 Deficiency not reportable per Part 21 MCGAUGHY. JP Mississippi Power & Light Co 82/12/15 O'RETLLY.JP Region 2. Office of Director 5pp 16559 006 24 Fiche 50-416, 82/12/15, 8212280377

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

- B212290061 Requests lists of reviewers from each branch who will be assigned to plant OL applications & list of SRP sections for which reviewers will be performing safety reviewe YOUNGBLOOD, B J Licensing Branch 1 82/12/09 THUMAS, C Standardization & Special Projects Branch EVANS, L J Fuel Facility Safeguards Licensing Branch MCCORKLE, G W Power Reactor Safeguards Licensing Branch 2pp 16606 360 24X Fiche 50-000, 82/12/09, B212290061
- 8212300072 Responds to 821207 memo requesting identification of reviewers & associated SRP sections for forthcoming OL reviews EW McPeek & FD Anderson chosen to review Sections 13 & & 16 Orrespectively
 THOMAS.C D Standardization & Special Projects Branch 82/12/23
 YOUNDBLOOD, B J Licensing Branch 1 1p 16624.263 24X
 Fiche 50-000,82/12/23,8212300072
- C Utility Environmental Report (ER), amends & correspondence
- 8212300023 Notifies that environ rept acceptable DES input should be completed within 2 months of receipt of PRA YOUNOBLOOD.B J Licensing Branch 1 82/12/22 HULMAN,L & Accident Evaluation Branch 1p 16624 282 24X Fiche 50-423.82/12/22.8212300023
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- B212300029 Notifies that environ rept acceptable DES input should be completed within 2 months of receipt of PRA
 YOUNOBLOOD, B J Licensing Branch i 82/12/22 HULMAN, L Q
 Accident Evaluation Branch ip 16624 282 24X
 Fiche 50-423.82/12/22.8212300023

F Security, medical, emergency & fire protection plans

- 8:12210355 Forwards revision to physical security plan Revision withheld (ref 10CFR2 790)
 COUNSILM G. CAONETTA, J.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSILM G. Northeast Utilities. 82/12/09
 BENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 16489-176. 24X Fiche 50-423.82/12/09.8212210355
- O Inspection reports, IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03. Revision i. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants "Svc list encl
 DEVOUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York. Inc
 112pp 16462 163 24% Fiche 50-000. 82/10/28, 8208190240
- 62/08/19/245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 30-000.82/11/05.8208190249
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consoludated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000,82/11/18.8208190251
- B212060187 Forwards IE Insp Rept 50-423/82-13 on 821018-22 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 82/11/22 CGUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 16311 050 24X Fiche 50-423,82/11/22,8212060187
- --B212050190 IE Insp Rept 50-423/82-13 on 821018-22 No noncompliance noted Major areas inspected matl receipt insp of electrical components, cable & cable tray installation & GC insp of electrical work
 RICHARDS S , BETTENHAUSEN, L Division of Engineering & Technical Programs 82/11/17 App 16311 082 24X Fiche 50-423.82/11/22, 8212060187
- 820B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.820B190256
- 8212140322 Forwards IE Insp Rept 50-423/82-12 on 820918-30 & 1001-23 No noncompliance noted STAROBTECKI.R Division of Project & Resident Programs 82/11/29 COUNSIL,W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 14401 273 24X Fiche 50-423,82/11/29,8212140322
- --8212140337 IE Insp Rept 50-423/82-12 on 820718-30 & 1001-23 No noncompliance noted Major areas inspected followup of previous insp findings, plant tours, electrical cable pulling & installation of reactor vessel internals HATTIA: J C , ELSASSER, T Division of Project & Resident Programs 82/11/23 7pp 16401 275 24% Fiche 50-423,82/11/29,8212140322
- B208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list and COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York. Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Builetin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl BEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp. 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24 Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Oas Monitoring " Svc list encl DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York

- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Helays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- S Reportable occurrences. LERs & related correspondence
- B2120B0541 Interim deficiency rept re failure of motor pinion gear shear keys in Limitorque Model BBO (8D-25) motor operated valves Initially reported on 820B04 Vendor info inconclusive Evaluation continuing COUNSIL W O . CACKETTA J P Northeast Nuclear Energy Co (subs of Northeast Utilities) CACKETTA J P Northeast Utilities 82/11/24 HAYNES.R C Region 1. Office of Director 2pp 16352 Q38 24X Fiche 50-423.82/11/24.9212080541
- 8212160470 Interim deficiency regt re cracks related to embedments in containment crane wall (8D-99) Initially reported on 821105 Investigation continuing Update will be provided by 830215 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 82/12/07 HAYNES.R C Region i. Office of Director 1p 16442 112 24X Fiche 50-423,82/12/07.8212160470
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 0212280356 Advises that submittal of QA organizational change in Chapter I7 of PSAR will be delayed until Feb or Mar 1983, to allow for inclusion of addl info on refinements to QA program DUTYON, D E Georgia Power Co 82/12/21 EISENHUT, D O Division of Licensing ip 16560 099 24% Fiche 50-424.82/12/21.8212280336
- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants "Syc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York. Inc 112pp 14462 163 24X Fiche 50-000.82/10/28.8208190240
- 6P1.ROPO24B Forwards IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted DANCE, H C Division of Project & Resident Programs 82/11/02 KELLY, R J Georgia Power Co 2pp 16363 350 24X Fiche 50-424.82/11/02.8212090248
- --B212090258 IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted Major areas inspected diesel generator storage, observation of cable tray support installation, GA audits & GA/GC procedures
 HUNT-M D . CONLON-T E Division of Engineering & Technical Programs 82/10/29 4pp 16363 352 24% Fiche 80-424,82/11/02,8212090248
- 8212090227 Forwards IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted DANCE,H C Division of Project & Resident Programs 82/11/03 KELLY,R J Georgia Fower Co 2pp 16361 300 24X Fiche 50-424.82/11/03.8212090227
- --8212090245 IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted Major areas inspected primary containment auxiliary bldg, control bldg, fuel handling bldg, steam generator mods & pipe spool & control panel insp SANDERS.W F , BROWNLEE.V L Division of Project & Resident Programs 82/11/01 6pp 16361 302 24X Fiche 50-424,82/11/03,8212090227
- 8708190245 IE Info Notice 82-42, "Defects Observed in Panasunic Model BOI & Model 802 Thermoluminescent Dosimeters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, B2/11/05, B208170245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance, 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000.82/11/18,8208190251
- B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUND,R C Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411,065 24X Fiche 50-000,B2/11/26,B208190256

- 6208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Motl " Svt list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 62/11/30 Consolidated Edison Co of New York. Inc 356pp 16387 028 24x Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list enc! BEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fichs 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JORDANIE L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000.82/12/03.8208190261
- 820B190267 IE Info Notice B2-49. "Correction for Sample Conditions for Air & Gas Honstoring " Svc list encl
 DEYOUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 1642B 191 24X Fiche 50-000, B2/12/16.820B190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24) Fiche 50-000, 82/12/20, 8208190268
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8212280356 Advises that submittal of QA organizational change in Chapter 17 of PSAR will be delayed until Feb or Mar 1983, to allow for inclusion of addl info on refinements to QA program DUTTON, D E Georgia Power Co. 82/12/21 EISENHUT, D O Division of Licensing 1p 16560 099 24X Fiche 50-424, 82/12/21, 8212280356
- @ Inspection reports, IE Bulletins & correspondence
- B208170240 IE Bulletin B2-03. Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BUR Plants " Syc list encl

 PEYDUNG, R C Director's Office. Office of Inspection and
 Enforcement B2/10/28 Consolidated Edison Co of New York. Inc
 112pp 16462 163 24X Fiche 30-000. 82/10/28. 8208170240
- 8212030248 Forwards IE Insp Repts 50-424/62-25 & 50-425/82-25 on 821018-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 82/11/02 MELLY,R J Georgia Power Co. 2pp 16363 350 24X Fiche:50-424,82/11/02,8212090248
- --8212090258 IE Insp Repts 50-424/82-25 & 50-425/82-25 on 821018-20 No noncompliance noted Major areas inspected diesel generator storage, observation of cable tray support installation, GA audits & GA/GC procedures
 HUNT: M D . CONLON.T E Division of Engineering & Technical Programs 82/10/29 4pp 16363 352 24X Fiche 50-424,82/11/02,8212090248
- 8212090227 Forwards IE Insp Repts 80-424/82-24 & 80-425/82-24 on 820911-1010 No honcompliance noted. DANCE,H C Division of Project & Resident Programs 82/11/03 KELLY,R J Georgia Power Co 2pp 16361 300 24X Fiche 50-424,82/11/03.8212090227
- --B212070245 IE Insp Repts 50-424/82-24 & 50-425/82-24 on 820911-1010 No noncompliance noted Major areas inspected primary containment, auditiary bldg. control bldg. fuel handling bldg. steam generator mods & pipe spool & control penal insp SANDERS.W F. BROWNLEE.V L Division of Project & Resident Programs B2/11/01 App 16361 302 24X Fiche 50-424.82/11/03, 6212090227
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosameters " Svc list onci.

 COBS.L I Division of Fuel Facilities, Materials & Sefeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372:142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24) Fiche: 50-000, 82/11/18, 8208190251

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Gvc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COB9.L I Division of Fuel Facilities, Materials & Safeguards 82711/30 Consolidated Edison (& of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- B20B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Flectrical Penetration Assemblies " Svc list encl DEYDONG.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 JE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Ouality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24% Fiche 50-000, 82/12/03, 8208190261
- 8.º08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 820819026B IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Nelays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 243 Fiche 50-000.82/12/20.820819026B
- DOCKET STN-90-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- 8212270418 Responds to FDIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREO-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, 8 C Upion of Concerned Scientists 3pp 16547 233 24X Fiche 50-000, 82/11/26, 8212270418
- --B211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o ancl NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24X Fiche 50-000,82/11/26,8212270418
- 8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PMRs Results do not adversely impact present position on reliance on natural circulation NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic 8afety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000, 82/12/14. 8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo ra Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NDVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fishe 50-000.82/12/14.8212220461
- 8212270481 Notifies that manufacturing license for Offshore Power Bys will be issued on 821217 DIRCKS,W J Office of the Executive Director for Operations 82/12/15 PALLADING,N J. GLLINSKY,V, AMEARNE,J Commissioners ip. 14848 362 24% Fiche 50-437.82/12/19,8212270481
- 8P12270423 Forwards Manufacturing License ML-1 for production of up to eight floating nuclear plants & FR notice of Issuance EISENHUT, D 0 Division of Licensing 82/12/17 THOMAS, R A DFfshore Power Systems (subs of Westinghouse Electric Corp) 2pp 16871 293 24X Fiche 50-437,82/12/17.8212270423
- --8212270425 Manufacturing License ML-1 for production of up to eight floating nuclear plants EISENHUT.D @ Division of Licensing 82/09/30 13pp 16571 295 244 Fiche 50-437,82/12/17,8212270423
- --8212270424 Notice of issuance of Manufacturing License ML-1 ADENBAM G Licensing Beanch 4 82/12/17 4pp 16571 309 24X Fiche 50-437, 82/12/17, 8212270423

G Adjudicatory correspondence

- BR1207016B Memorandum & Order CLI-82-37, finding that immediate effectiveness review does not apply to mfg licenses Mfg Commissioners Ollinsky & Ahearne separate views encl CHILK, S J Office of the Secretary of the Commission B2/12/06 12pp 16335 299 24X Fiche 50-437, B2/12/06, B21207016B
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin B2-03. Revision i, "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Stys Piping at BNR Plants "Svc list encl
 DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000. 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBP.L J Division of Fivel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 16372 142 24X Fiche 50-000,82/11/05,8208190245
- B208170251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consultdated Edison Co of New York, Inc 109pp 16411 179 24X Fiche 50-000, 82/11/18,8208170251
- 8±08170256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks "Svc list encl DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 80-000.82/11/26.8208170256
- 8206190257 lE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enci COB9.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Firthe 50-000.82/11/30,8208190257
- B20B190259 TE Dulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc J13pp 15411 317 24X Fiche \$0-000,82/12/03,8208190259
- B):081702&1 lE Info Notice 8R-48. "Failures of Agastat CR 0078 Relay Bockets " Svc list encl JURDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 044 24) Fiche 50-000: 82/12/03.82081902&1
- 8708190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche \$0-000.82/12/16.8208190267
- 820819026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20, Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000, 82/12/20, 8208190268
- 1 Hearing transcripts on non-antitrust matters
- 8212020226 Unofficial transcript of 821123 affirmation/discussion & vote in Mashington.DC re SECV-82-425 & SECV-82-449 * Commissioners 82/11/23 8pp 16308 193 24X Fiche 50-000.82/11/23.8212020226
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8212100046 Responds to R Heron 811202 telcon request re emergency apprations facility (EOF) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided KAMMER, D S Tennesses Valley Authority 82/12/06 ADENSAM. E Licensing Branch 4 ip 16379 071 24X Fiche 50-000, 82/12/06, 82/12/00046

J Insurance & indemnity information

- 8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 DUCK, J. R. Marsh & McLennan, Inc., M & M. Nuclear Consultants, Inc. Div. 62/11/18 HAINES, H.L. American Nuclear Insurers ip 16288 336 24X Fiche 50-000,82/11/18,8212020269
- K Utility Final Safety Amalysis Report (FSAR) & amends
- B212280437 Forwards affidavit of LM Mills certifying svc of Amend 23 to FSAR on 821221 MILLS,L M Tennessee Valley Authority 82/12/22 ADENSAM,E Licensing Branch 4 1p 16556 059 24% Fiche 50-438,82/12/22
- 0 Inspection reports, IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl
 DEYQUNO, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co. of New York, Inc
 112pp 16462 163 24X Fiche: 50-000, 82/10/28, 8208190240
- B208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list encl COBs.L I Division of Fuel Facilities, Naterials & Safeguards 62/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24x Fiche 50-000,82/11/05,8208190245
- 8212090028 Forwards IE Insp Repts 50-430/82-27 & 50-439/82-29 on B21026-29 No honcompliance noted VERRELLI, D M Division of Project & Resident Programs 82/11/12 PARTS, H Q Fennessee Valley Authority 2pp 16366-303 24X Fiche 50-428, 82/11/12, 8212090528
- --8212090536 IE Insp Reptz 50-438/82-29 & 50-439/82-29 on 821026-29 No noncompliance noted Major areas inspected Eigenses action on previous enforcement matters, RCPB pipe welds, safety-related pipe support & restraint sys & IE Bulletins 79-02 & 79-14 GIRARD, E H . LIU.W C . BLAKE, J J Division of Engineering & Technical Programs 82/11/10 10pp 16:366 305 24X Fiche 50-438,82/11/12.8212090528
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8208190286 IE Info Notice 82-46, "Defective & Phsolete Combination Padlocks "Svc list encl BEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127gp 14411 065 24% Fiche 50-000,82/11/26.8208190286
- 8P08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Naterials & Safeguards 82/11/30 Consolidated Edison Co of New York Inc 354pp 14387 028. 24X Fichs. 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEVOUNO:R C. Director's Office of Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208170261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDANGE L. Division of Engineering & Quality Assurence 82/12/03 Consolidated Edison Co. of New York. Inc. 110pp. 16462 064 24X Fiche 50-000, 82/12/03,8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list enc!
 DEYOUNG:R C Director's Office: Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16.8208190267

- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24X Fighs 50-000.82/12/20.8208190268
- S Reportable occurrences, LERs & related correspondence
- B212020107 Seventh interio dericiency rept re old grease pumped on motor winding of reactor bldg cooling fans Initially reported on B10128 Tubing removed & grease relief holes plugged Next rept by 830223 Also reportable per Part 21 HILLS.L H Tennessee Valley Authority 82/11/23 0'REILLY, J P Region 2. Office of Director 2pp 16272 029 24X Fiche 50-438.82/11/23.8212020107
- 8P12020139 Final deficiency rept re water in rock anchor tendon head protective grease cans Initially reported on 790323 Ground water will not prevent prestressing sys from performing intended functions Components tested for corrosion MILLS-L M Tennessee Valley Authority 82/11/23 D'REILLY, J P Region 2. Office of Director 3pp 16274 164 24X Fiche 50~438.82/11/23,8212020139
- 8212020137 First interim deficiency rept re unqualified flux hose connections Initially reported on 821027 Package of all info re flux hose assembled for reanalysis Next rept expected by 830430 MILLS.L H Tennessee Valley Authority 82/11/24 0'REILLY, J P Region 2, Office of Director 2pp 16274 159 24X Fiche 50-438,82/11/24,8212020137
- B212020149 First interim deficiency rept re failure to analyse isometrics & load tables Initially reported on B21026 Analysis check errors subsequently identified Deficiency will be addressed when errors resolved Next rept by B30322 HILLS.L.H. Tennessee Valley Authority B2/11/24 O'REILLY, J.P. Region 2. Office of Director 2pp 16274 157 24X Fiche 50-438, 82/11/24. 8212020149
- 8P12020162 First interim deficiency rept re failure to review diagrams properly initially reported on B21027 Review of revisions to functional control logic diagrams continuing Next rept will be submitted by 830722 MILLS: L.M. Tennesses Valley Authority 82/11/24 O'REILLY, J.P. Region 2. Office of Director 2pp 16274 174 24X Fiche 50-438, 82/11/24, 8212020162
- 8212030008 First interim deficiency rept re easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on B21026 Proposed disposition to replace Star Model GE sprinkler heads under review MILLS: L H Tennessee Valley Authority 82/11/29 0'REILLY, J P Region 2. Dffice of Director 2pp 16304 212 24X Fiche 50-003, 82/11/29, 8212030001
- BP12030072 Fourth interim deficiency rept re chiller unit piping components mfg by Dunham-Bush improperly welded Initially reported on 820111 Next rept expected by 830620 Also reportable per Part 21 HILLS, L.H. Tennessee Valley Authority 82/11/29 0'REILLY, J.P. Region 2, Office of Director 2pp 16304 214 24X Fiche 50-438, 82/11/29, 8212030072
- 8212030152 Second interim deficiency rept re design problems w/B&W steam generators Initially reported on 820830 Addition of external header investigated Next rept expected by 830131 Also reportable per Part 21 MILLS, L M Tennessee Vallay Authority 82/11/29 0/REILLY, J P Region 2. Office of Director 2pp 16303 305 24X Fiche 50-438,82/11/29,8212030152
- 8212090163 Final deficiency rept re-steam pressure regulator malfunction verification requirements Initially reported on 810519 DNRR requirements met No evidence found that deficiency exists MILLS, L h Tennessee Valley Authority 82/12/03 0'REILLY, J P Region 2. Office of Director 2pp 16359 096 24% Fiche 50-438,82/12/03,8212090163
- B212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure GA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects HILLS,L M Tennessee Valley Authority 82/12/06 0'REILLY, J P Region 2, Office of Director 1p 16377 136 24x Fiche 50-000, 82/12/06, 8212100270

- 8212140047 Seventh interim deficiency rept re miscategorization of main feedwater & containment isolation valves Initially reported on 810106 Atwood & Morrill seismic & attess rept re awing check valves qualification approved Next rept by 830331 MILLS.L M Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2. Office of Director 2pp 16408 279 24X Fiche 50-438.82/12/06.8212140047
- 8212140415 Final deficiency rept re conduit loading on annulus framing in reactor bidg Initially reported on 820802 No corrective action nocessary Sub; nonconformance determined not reportable per 100FR50 55(e) NILLS.L H Tennessee Valley Authority 82/12/06 G'REILLY, J P Region 2, Office of Director 2pp 16403 318 24% Fiche 50-438,82/12/06,8212140419
- 8212150079 Revised final deficiency rept re pipe hanger documentation error Initially reported on 810128 Const informed by 810601 memo that final approval by div of engineering design manager must be received before installation of hangers MILLS.L M Tennessee Valley Authority 82/12/08 G'REILLY, J.P. Region 2. Office of Director 2pp 16431 019 24X Fiche 50-438,82/12/08,8212180079
- 8212170157 Fourth interim deficiency rept re improper use of foam plastic installation on stainless steel pipe Instially reported on 820203 Instruction memo re insulation types & drawings revised Next rept expected by 830321.
 MILLS.L M Tennessee Valley Authority 82/12/10 0'REILLY. J P Region 2. Office of Director 2pp 16462 026 24X
 Fiche 50-438,82/12/10,8212170157
- B212170160 Second revised final deficiency rept re Johnson Machine Works welds on revolving platform trucks Initially reported on B11106 Also reportable per Part 21 New welding manetic particle or dye penetrant tested & training initiated MILLS.L M Tennesse Valley Authority B2/12/10 G'REILLY, J P Region 2. Office of Director 3pp 16462 023 24X Fiche 50-438.82/12/10,8212170160
- B212170221 Supplemental deficiency rept re unacceptable replacement for component cooling water pump shaft initially reported on 820301 Completion of corrective actions expected by \$30201 Also reportable per Part 21 MILLS.L. M Tennesse Valley Authority 82/12/10 0'REILLY, J P Region 2, Office of Director 1p 16459 356 24X Fiche 50-438,82/12/10,8212170221
- 8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No add1 info available until action team 821215 rept Next rept will be submitted by 830420 MILLS.L M Tennessee Valley Authority 62/12/13 O'REILLY, J P Region 2. Office of Director ip 16473 362, 24X Fiche 50-000, 82/12/13, 8212200001
- 8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422 MILLS,L M Tennesses Valley Authority, 82/12/13 O'REILLY, J P. Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000,82/12/13,8212200017
- 8212210256 Fifth interim deficiency rept re potential stress corrosion cracking in RCS supports & restraints for bolt torques Initially reported on 810824 Util program to survey RCS matl properties continuing Also reported per Part 21 MILLS, L.M. Tennessee Valley Authority 82/12/13, 0'REILLY, J.P. Region 2, Office of Director 2pp 16483-301 24X Fiche 50-438,82/12/13,8212210256
- 6212210026 Fourth interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412. Multiple supports attached to plates \(\omega/ \) design review of plate capacity Preliminary const spec issued Next rept by 830404. MILLS, L. H. Tennessee Valley Authority, \(\textit{82}/12/14 \) O'REILLY, \(\omega \) Priche 50-000, 82/12/14, 8212210026
- 8212210122 Fourth interim deficiency rept re omissions to auxiliary feedwater pump drawings Initially reported on 820225 Auxiliary feedwater pump vants, drains & turbine cooling water piping incorporated into drawings Next rept by 830407 MILLS,L M Tennesse Valley Authority 82/12/14 0'REILLY, J. P. Region 2. Office of Director 2pp. 14485 128 24X Fiche 50-438, 82/12/14, 8212210122
- BRI2210364 Third interim deficiency rept re valves mfg by Target Rock Valve Co & YARMAY Corp not qualified as active components initially reported on 820412 Gualifying documentation expected by 830330 MILLS, L M Tennessee Valley Authority 82/12/14 0'REILLY, J P Region 2, Office of Director 2pp 16493 096. 24X Fiche 50-438, 82/12/14, 8212210364

- B212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on B20120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by B30322 MILS.L M Tennessee Valley Authority B2/12/15 O'REILLY.J P Region 2. Defice of Director 2pp 16489 168 24X Fiche 50-000, B2/12/15, B212210431
- 8212280358 First interim deficiency rept re substitution of grouted anchors for wadge bolts w/o ensuring adequate shear load capacities initially reported on 82117 TVA uill evaluate deficiency Next rept will be submitted by 830328 MILLS.L.M Tennesses Valley Authority 82/12/15 D'REILLY, J P Region 2. Office of Director 3pp 16558 357 24X Fiche 50-438.82/12/15.8212280358
- 8212300006 Final deficiency rept re allowable stresses for pipe support design Initially reported on 811207 Nonconformance not reportable per 10CFR50 55(e) because condition not nonconforming or adverse to safe operation MILS.L M Tennesses Valley Authority 82/12/16 0'REILLY, J P Region 2. Office of Director 8pp 16598 136 24X Fiche 50-438.82/12/16.8212300006
- 8212220419 First interim deficiency rept re improper use of alternate analysis elbolets Initially reported on 821118 Piping w/elbolets qualified by alternate criteria identified & evaluated Next rept due by 830323 MILLS.L M Tennessee Valley Authority 82/12/17 Q'REILLY.J P Region 2. Office of Director 2pp 16503 272 24X Fiche 50-438.82/12/17.8212220419
- 8212280064 Second interim deficiency rept re shielded power cable bend radius Initially reported on 820806 Cable samples will be tested for worst case bend installation Next rept will be submitted by 830722
 HILLS.L M Tennessee Valley Authority 82/12/20 O'REILLY, J P Region 2. Office of Director 2pp 16565 197 24X Fiche 50-438.82/12/20.8212280064
- 8212280305 Final Deficiency Repts 50-438/62-58 & 50-439/82-52 re nonconforming reactor bldg door weld by Johnson Machine Works Initially reported on 820816 Reactor bldg equipment hatch doors to be reworked Also reported per Part 21 MILLS, L M Tennessee Valley Authority 82/12/20 0'REILLY, J P Region 2, Office of Director 3pp 16562 055 24X Fiche 50-438, 82/12/20, 8212280305
- 8212280328 Third interim deficiency rept to B&W design of RCS supports & restraints initially reported on 820618 B&W recommended disposition reviewed & comments returned for evaluation Next rept will be submitted by 830620 MILLS, L M Tennesse Valley Authority 82/12/20 O'REILLY, J P Region 2, Office of Director 2pp 16561 062 24X Fiche 50~438, 82/12/20, 8212280328
- 8212280100 Fourth interim deficiency rept re small globe valves in auxiliary feedwater sys exceeding weight & length limitations Initially reported on 820222 Valves replaced on Unit I Unit 2 drawings revised Next rept due by 830415 MILLS.L.M Tennessee Valley Authority 82/12/21 0'REILLY, J P Region 2, Office of Director 2pp 14564 219 24X Fiche 50~438,82/12/21,8212280100
- 8212280210 Supplemental deficiency rapt re GE relays Initially reported on 810513 Add1 relay coils needed for replacement in intake pumping station Completion expected by 830430 Also reportable under Part 21 MILLS.L.M. Tennessee Valley Authority 82/12/21 0'REILLY, J.P. Region 2, Office of Director ip 16562 286 24X Fiche: 50-438, 82/12/21, 8212280210
- 8212280340 Second interim deficiency rept re steam generator support bolts mfg by Lekeside Bridge & Steel Initially reported on 820723 Applicant awaiting results of bolt testing & evaluation Next rept will be submitted by 830331 MILLERL M Tennessee Valley Authority 82/12/21 O'REILLY, J. P Region 2, Office of Director 2pp 16560:097 24X Fiche 50-438.82/12/21.8212280340
- DOCKET 50-437 BELLEFONTE NUCLEAR PLANT, UNIT 2
 F. Security, medical, emergancy & fire protection plans
- 8212100046 Responds to R Heron 811202 telcon request re emergency operations facility (EOF) Response to Generic Ltr 81-10 on 810602 describes util plans to utilize central emergency response ctr Project-specific details to be provided KAMMER, D. S. Tennessee Valley Authority 82/12/06 ADENSAM, ELicensing Branch 4 ip 16379 071 24X Fiche 50-000, 82/12/06, 8212100046

- J Insurance & indemnity information
- 8212020269 Submits info re const & warehouse values located offsite as result of revised site descriptions under ANI/MAELU nuclear liability insurance facility form policies

 DUCK. J R Harsh & McLennan, Inc. / A M Nuclear Consultants, Inc. Div B2/11/18 HAINES, H C American Nuclear Insurers | p | 16288 356 24X Fiche 50-000, 82/11/18.82(2020269
- 8212300300 Forwards Endorsement 16 to NELIA Policy NF-258
 DUCK, J.R. Marsh & McLennan.Inc. H & M. Nuclear Consultants, Inc. Div
 B2/12/27 BALTIMAN. J. Assistant Director For State & Licensee
 Relations 2pp 16574 195 24X Fiche 50-438.82/12/27.8212300300
- K Utility Final Bafety Analysis Report (FSAR) & amends
- BP12280437 Forwards affidavit of LM Mills certifying svc of Amend 23 to FSAR on B21221 MILLS. L M Tennessee Valley Authority 82/12/22 ADENSAM, E Licensing Branch 4 1p 16556 059 24X Fiche 50~438, 82/12/22, 8212980437
- 0 Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8WR Plants " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L I Division of Fuel Facilities. Meterials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24 Fiche 50-000, 82/11/05. 8208190281
- 8212070528 Forwards IE Insp Repts 90-438/82-29 % 50-437/82-29 on 821026-27 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 82/11/12 PARRIS,H O Tennessee Valley Authoraty 2pp 16366 303 24X Fichs 50-438, 82/11/12,8212070528
- ---B212090536 IE Insp Repts 50-438/82-29 & 50-439/82-29 on 821026-29 No noncompliance noted Major areas inspected licenses action on previous enforcement matters. RCPB pipe welds, safety-related pipe support & restraint sus & IE Bulletins 79-02 & 79-14 GIRARD, E H . LIU, W C . BLAKE, J J Division of Engineering & Technical Programs 62/11/10 10pp 16366 305 24X Fiche 50-438, 82/11/12. 821E090528
- B208190251 IE Info Notice B2-44. "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDANIC L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc. 109pp 16411 199 24X Fiche 50-000. B2/11/18.820B190251
- 8208190256 IE info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 33App 14387 028 24X Fiche 50-000, 82/11/30 6208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462.064 24X Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-47. "Correction for Sample Conditions for Air & Qas Monitoring " Syc list encl DEYOUNG,R C Director's Office of Effice of Inspection and Enforcement. 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267

- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000, 82/12/20, 8208190268
- S Regortable occurrences. LERs & related correspondence
- 8212020107 Seventh interim deficiency rept to old grease pumped an motor winding of reactor bldg cooling fams initially reported on 810128 Tubing removed & grease relief holes plugged Neit rept by 830223 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 82/11/23 0'REILLY.J P Region 2. Office of Director 2pp 16272 029 24X Fiche 50-438, 82/11/23, 8212020107
- 8212020139 Final deficiency rept re water in rock anchor tendom head protective grease cans Initially reported on 790523 Ground water will not prevent prestressing sys from performing intended functions Components tested for corrosion MILLS, L M Tennessee Valley Authority 82/11/23 B/REJLLY, J P Region 2. Office of Director 3pp 16274 164 24X Fiche 50-438,82/11/23,8212020139
- B212020137 First interin deficiency rept re unqualified flux hose connections initially reported on 821027 Package of all info re flux hose assembled for reanalysis Next rept expected by 830430 MILLS.L.H. Tennessee Valley Authority 82/11/24 0'REILLY, J.P. Region 2. Diffice of Director Epp 16274 159 24X Fiche 50-438.82/11/24.8212020137
- 8212020149 First interim deficiency rept re failure to analyze isometrics & load tables initially reported on 821026 Analysis check errors subsequently identified Deficiency will be addressed when errors resolved Next rept by 830322 MILLS: L. H. Tennessee Valley Authority 82/11/24 0'REILLY, J. P. Region 2. Office of Director 2pp 16274 157 24X Fiche 50-438, 82/11/24, 8212020149
- 8212020162 First interim deficiency rept re failure to review diagrams properly initially reported on 821027 Review of revisions to functional control logic diagrams continuing Next rept will be submitted by 830722
 MILLS.L H Tennessee Valley Authority 82/11/24 O'REILLY. J P Region R. Office of Director 2pp 16274 174 24X
 Fiche 50-438.82/11/24.8212020162
- 8212030001 First interim deficiency rept to easily bent heat collecting fins & corroding sprinkler heads in fire suppression sys Initially reported on 821026 Proposed disposition to replace Star Model 0E sprinkler heads under review MILLS,L H Tennessee Valley Authority 82/11/29 O'REILLY, J P Region 2. Office of Director 2pp 16304 212 24X Fichs 50-000,82/11/27,8212030001
- 8212030072 Fourth interim deficiency rept re chiller unit piping components neg by Dunham-Bush improperly welded Initially reported on 82011 Next rept expected by 830620 Also reportable per Part 21 MILLS.L H Tennessee Valley Authority 82/11/29 0'REILLY.J P Ragion 2. Office of Director 2pp 16304 214 24% Fiche 30-438,82/11/29,8212030072
- B212030152 Second interim deficiency rept re design problems w/R&W steam memerators Initially reported on 820830 Addition of external header investigated Next rept expected by 830131 Also reportable per Part 21 HILLS, L.N. Tennesses Valley Authority 82/11/29 O'REILLY, J, P. Region 2. Office of Director 2pp 16303 305 24X Fiche 50-438,82/11/29,8212030152
- 8212090143 Final deficiency rept to steam pressure regulator malfunction verification requirements Initially reported on 810519 UNBR requirements met No svidence found that deficiency stists.

 MILLS,L H Tennessee Valley Authority 82/12/03 0'REILLY, J P Region 2 Office of Director 2pp 16359 096 24X
 Fiche 30-438,82/12/03,8212090163
- 9212100270 Fifth interim distiniency maps the lack of Div of Engineering design sys to ensure QA procedures issued before work begins Initially reported on 811020 Finel mept will not be submitted until decision made on deferral of projects MILLS, L. H. Tennesses Valley Authority 82/12/04 O'REILLY, J. P. Region 2: Office of Director ip 16377, 136 24X Fiche 50-000, 82/12/06, 8212100270

- 8212140047 Seventh interim deficiency rept re miscategorization of main feedwater & containment isolation valves firstially reported on 810106 Atwood & Morrill seismic & stress rept re swing check valves qualification approved Next rept by 830331 MICLS, L K Tennessee Valley Authority 82/12/06 O'REILLY, J P Region 2, Office of Director 2pp 16408 279 24x Fiche 50-438,82/12/06,8212140047
- 8212140415 Final deficiency rept re conduit loading on annulus framing in reactor bldg Initially reported on 820802 No corrective action necessary Bub, nonconformance determined not reportable per 10CFR50 85(e) MICLS, L M Tennessee Valley Authority 82/12/06 0'REILLY, J P Region 2, Office of Director 2pp 16403 318 24% Fiche 50-438, 82/12/06, 8212140415
- 8212140371 Second interim deficiency rept re faulty I-T-E relays in auxiliary power distribution sys by Brown Bovers Electric Initially reported on 820528 Vendor rept pending Next rept expected by 830924 Also reportable under Part 21 MILLS,L M Tonnessee Valley Authority 82/12/07 O'REILLY, J P Region 2. Office of Director 2pp 16401 149 24X Fiche 50-439,82/12/07,8212140371
- 8212150079 Revised final deficiency rept re pipe hanger documentation error initially reported on 810128 Const informed by 810401 memo that final approval by div of engineering design manager must be received before installation of hangers NILLS,L M Tennessee Valley Authority 82/12/08 0'REILLY, J P Region 2, Office of Director 2pp 16431 019 24% Fiche 50-438,82/12/08,8212150079
- 8212;70:97 Fourth interim deficiency rept re improper use of foam plastic installation on stainless steel pipe Initially reported on 820203 Instruction memo re insulation types & drawings revised Next rept expected by 830321 MILLS,L M Tennessee Valley Authority 82/12/10 0'REILLY, J P Region 2, Office of Director 20p 16462 026 24X Fiche 50-438,82/12/10,8212170157
- 8P12170160 Second revised final deficiency rept re Johnson Machine Horks welds on revolving platform trucks Initially reported on 811106 Also reportable per Part 21 New welding magnetic particle or due penetrant tested & training initiated MILLS.L H Tennessee Valley Authority 82/12/10 0'REILLY, J P Region 2. Office of Director 3pp 16462 023 24X Fiche 50-438,82/12/10.8212170160
- 8212200001 Third interim deficiency rept re gameric deficiency in design review Initially reported on 811215 No addl info available until action team 821215 rept Next rept will be submitted by 830420 MILLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2. Office of Director ip 16473 362 24X Fiche 30-000, 82/12/13, 8212200001
- B212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on 810717 Corrective action to be based on action team rept to be issued approx 821215 Next rept expected by 830422 MILLS,L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2. Office of Director Epp 16473 085 24X Fiche 50-000,82/12/13,8212200017
- 8212210256 Fifth interim deficiency rept re potential stross corrosion cracking in RCS supports & restraints for bolt torques initially reported on 810824 Util program to survey RCS mati properties continuing Also reported per Part 21 MiLLS.L M Tennessee Valley Authority 82/12/13 0'REILLY.J P Region 2. Office of Director. 2pp 16483 301 24% Fiche 50-438.82/12/13.8212210256
- 8212210026 Fourth interim deficiency meptine potentially overstressed embedded plates initially reported on 820412 Multiple supports attached to plates w/o design review of plate capacity Preliminary const spec issued Next mept by 830404 MILLS, L. M. Tennesses Valley Authority 82/12/14 0'REILLY, J. P. Region 2, Office of Director 2pp 16485 260 24X Ficha 50-000, 82/12/14, 8212210026
- 8212210122 Fourth interim deficiency rept re omissions to auxiliary feedwater pump drawings Initially reported on 820225 Auxiliary feedwater pump vents drains & turbine cooling water prining incorporated into drawings Next rept by 830409 HILLS, L M Tennesses Valley Authority 82/12/14 O'REILLY, J P Region 2, Office of Director 2pp 16485 128 24X Fiche 50-438, 82/12/14, 8212210122
- 82:22:0364 Third interim deficiency rept re valves mfg by Target Rock Valve Co & YARMAY Corp not qualified as active components initially reported on 82:04:2 Qualifying documentation expected by 83:0330 Mills.L ff Tennessee Valley Authority 82:12/14 0'REILLY. J P Region 2, Office of Director 2pp 16493 096 24x Fiche 50-438,82:12/14,82:122:10364

- 82122(0431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MELS.L M Tennessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Defice of Director 2pp 16489 168 24X Fiche 50-000.82/12/15.8212210431
- 8212280358 First interim deficiency rept re substitution of grouted anchors for wedge bolts w/o ensuring adequate shear load capacities Initially reported on 821117 TVA will evaluate deficiency Next rept will be submitted by 830328 MILL8,L M. Tennessee Valley Authority 82/12/15 0'REILLY, J P Region 2, Office of Director 3pp 16558 357 24% Fiche 50-438,82/12/15,8212280358
- 8212300006 Final deficiency rept re allowable stresses for pipe support design Initially reported on 811207 Nonconformance not reportable per 10CFR50 55(e) because condition not nonconforming or adverse to safe operation MILLS.C. M. Tennessee Valley Authority 82/12/16 0'REILLY.J.P. Region 2. Office of Director App. 16598 136 24X Fiche 50-438,82/12/16.8212300006
- 8212220419 First interim deficiency rept re improper use of alternate analysis elbolets Initially reported on 821118 Piping W/elbolets qualified by alternate criteria identified & evaluated Next rept due by 830323 MILLS, L M Tennessee Valley Authority 82/12/17 O'REILLY, J P Region 2. Office of Director 2pp 16503 272 24X Fishe 50-438, 82/12/17, 8212220419
- 82:12280064 Second interim deficiency rept re shielded power cable bend radius Initially reported on 820806 Cable samples will be tasted for worst case bend installation Next rept will be submitted by 830722
 MILLS.L M Tennessee Valley Authority 82/12/20 O'REILLY, J P Region 2. Office of Director 20p 16565 137 24X
 Fiche 50-438.82/12/20.8212280064
- 82:12280305 Final Deficiency Repts 50-438/82-58 % 50-439/82-52 re nonconforming reactor bldg door weld by Johnson Machine Works Initially reported on 820816 Reactor bldg equipment hatch doors to be reworked Also reported per Part 21 MICLS.L M Tennessee Valley Authority 82/12/20 O'REILLY.J P Region 2, Office of Director 3pp 16962 055 24X Fiche 50-438.82/12/20.8212280305
- B212280328 Third interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820618 B&W recommended disposition reviewed & comments returned for availuation Next rept will be submitted by 830620 MILLS.L M Tennessee Valley Authority 82/12/20 O'REILLY, J P Region 2. Office of Director 2pp 16561 062 24X Fiche 50-438. B2/12/20, 8212280328
- 6912280100 Fourth interim deficiency rept re small globe valves in auxiliary feedwater sys exceeding weight & length limitations Initially reported on 82022 Velves replaced on Unit 1 Unit 2 drawings revised Next rept due by 830415 MILLS.L.M. Tennessae Valley Authority 82/12/21 O'REILLY, J.P. Region 2, Office of Director 2pp 16564 219 24X Fiche 50-438.82/12/21.8212280100
- 82i22802i0 Supplemental deficiency rept re 0E relays Initially reported on 8i05i3 Add1 relay coils needed for replacement in intake pumping station Completion expected by 830430 Also reportable under Part 2i MILLS.L M Tennesses Valley Authority 82/12/21 0'REILLY, J P Region 2, Office of Director 1p 16562.286 24X Fiche 50-438,82/12/21,82i22802i0
- 8212280340 Second interim deficiency rept re steam generator support bolts mfg by Lakeside Bridge & Steel Initially reported on B20723 Applicant awaiting results of bolt testing & evaluation Next rept will be submitted by B30331 MILLS, L M Tennessee Valley Authority 82/12/21 O'REILLY, J P Region 2. Office of Director 2pp 16560 097 24X Fiche 50-438.82/12/21.8212280340
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B212290031 FOIA request for five categories of documents HIATT.8 L Ohio Citizens for Responsible Energy 82/11/04 FELTON.J M Division of Rules and Records 1p 16607 132 24X Fiche 50-440.82/11/04.8212290031

- 8212060484 Forwards "Human Factors Engineering Control Room In-Progress Audit "Requests schedule for NRC final control room design audit including close-out of TMI Action Plan Item I D 1 & II K 3 27 prior to licensing BCMMENCER, A Licensing Branch 2 82/11/12 DAVIDSON, D R Cleveland Electric Illuminating Co 2pp 16343 248 24X Fiche 50~440, 82/11/12, 8212060484
- --B211110457 "Audit Rept Human Factors Engineering Control Room In Progress Audit " MODRE, J W Laurence Livermore Laboratory 82/10/26 51pp 16343 250 24% Fiche 50-440, 82/11/12,8212060484
- 8211230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBURR, Big Rock Point Dreaden i. Humboldt Bay.
 applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISENHUT.D C Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16397 004 24X
 Fiche 50-000, 82/11/15, 9211230066
- 8212070451 Ack receipt of 821116 memo to A Schwencer clarifying procedure for controlling document transmittals Superseded transmittals will be returned as requested Future transmittals should be addressed to BJ Youngblood STEFANO, JJ Licensing Branch i BZ/II/ZP KINKADE, J Cleveland Electric Illuminating Co ip 16355 324 24X Fiche 50~440,
- B212070466 Forwards requests for add1 info to be furnished prior to site audit for seismic & dynamic equipment qualification reviews Scheduled time period for audit also requested YOUNOBLOOD, B. J. Licensing Branch 1. 82/11/30 DAVIDSON, D. R. Cleveland Electric Illuminating Co. 28pp. 16354-244 24X Fishes 50-440, 82/11/30, 8212070466
- B212080021 Memorializes 921124 telcon w/ubil & Gilbert Associates re safety relief valve hydrodynamic loads test STEFAND.J.J. Licensing Branch i 62/11/30 YOUNGBLODD.B.J. Licensing Branch i 2pp 16367 167 24X Fiche 50-440,82/11/30. B212080021
- G212080115 Summary of 821122 meeting w/util, Gilbert Associates & Nuclear Technology in Bethesda. MD re util proposal for not performing safety relief valve hydrodynamic load discharge tests
 STEFANO. J Licensing Branch i 82/11/30 YOUNGBLOOD. B J Licensing Branch i 4pp 16368 291 24X Fiche 50-440.82/11/30. G212080115
- B212070237 Amplifies Justifications provided in 920721 application for amend of CPPR-148 & CPPR-149 to extend const completion dates Reduced demand, increased regulations & high interest rates delayed need for capacity supplied by facilities

 EDELMAN.M.R. Cleveland Electric Illuminating Co. 82/12/01

 YOUNGBLOOD.J Licensing Branch 1 2pp 14329 311 24%

 Fiche 50-440, 82/12/01.8212070237
- 8212290036 Responds to FOIA request for five categories of documents Forwards documents listed in App A Review of occuments relitent 1 continuing FELTON.J M Division of Rules and Records 82/12/02 HIATT.S.L Chio Citizens for Responsible Energy 2pp 16607 133 24X Fiche 50-440, 82/12/02,8212290036
- B212230385 Discusses JJ Stefano B21130 meeting rept summarizing discussions re need to conduct safety relief valve hydrodynamic load tests Potential thermal gradient stresses of concern Guestions encl for response formulating concern YOUNGBLOOD, B J Licensing Branch | 82/18/14 RDELMANM R Cleveland Electric Illuminating Co 3pp 16540 242 24X Fiche 50-440, 82/12/14, 82:2230385
- 8212300077 Notification of 830111-13 meetings w/util in Lake County, GH to assess status of const & completion schedules
 BTEFANG, J. J. Licensing Branch 1 82/12/15 YQUNONLQOD, D. J. Licensing Branch 1 5pp. 16624 275. 24X Fiche 50-440,82/12/15, 8212300077
- 8212280255 Responds to NRC 821017 Questions 260 10-260 13 requesting add1 info & clarification of Table 3 2 1 in FSAR Amends 8 & 9 re 0A EDELMAN, K.R. Cleveland Electric Illuminating Co 82/12/21 YOUNGOLOOD, B J Licensing Dranch 1 7pp 16561 297 24X Fiche 50-440, 82/12/21, 8212280255
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8212210435 Advises that EIS & EIA reviewed by all interested state agencies No concerns stated BRACHMAN,J.Y Ohio, State of 82/10/27 BCHWENCER,A Licensing Branch 2 ip 16489 177 24X Fiche 50-440,82/10/27,8212210435

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8212010377 Summarites findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls SCHWENCER, A Licensing Branch 2 82/11/26 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 16271 094 24X Fiche 50-440.82/11/26.8212010377
- 8212070460 Requests that util formally endorse BMR owners group proposal to modify automatic depressurization sys initiation to allow NRC to complete generic review of TMI Item II K 3 18 Info needed to resolve SER Confirmatory Issue 7 YOUNOBLOOD, B J Licensing Branch 1 82/11/30 DAVIDSON, D R Claveland Electric Illuminating Co 2pp 16355 319 24X Fiche 50-440, 82/11/30, 8212070460
- 8212070397 Responds to SER Outstanding Issue 10 re continuous containment purge & Confirmatory Issue 20 re subcompartment pressure analysis FSAR will be revised w/resolution of issues EDELMAN, M.R. Cleveland Electric Illuminating Co. 82/12/02 YOUNGBLOOD, J. Licensing Branch 1 5pp 16336 328 24X Fiche 50-440.82/12/02.8212070397
- 8212270002 Notification of 821214 meeting w/applicants & GA Intl in Bethesda MD to discuss unresolved containment issues cited in SER (NUREG-0887) STEFANO, J Licensing Branch 1 82/12/09 YOUNGBLOOD B Licensing Branch 1 3pp 16551 287 24X Fiche 50-440,82/12/09,
- 8212270189 Responds to SER Confirmatory Issue 44 re radiation & shielding design of inclined fuel transfer sys tubes Info in Amend 10 to FSAR should resolve issue EDELMAN, N R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLOOD, B J Licensing Branch 1 ip 16578 195 24X Fiche 50-440.82/12/21.8212270189
- 8212290305 Forwards response to NRC 820708 ltr.Question 640 2, re SER Outstanding Issue 21. Section 13 5 2 2 on reanalysis of transients & accidents & development of emergency operating procedures Submittal supplis 821116 response EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21 YQUN081000, B J 41censing Branch 1 2pp 16588 016 24X Fichs 50-440, 82/12/21, 8212270305
- 82:12290325 Forwards response to SER Confirmatory Issues 41 & 42 re design for mobile gas effluent monitors & design for sampling & analysis of plant effluents, per NUREG-0737. Items II F I ; & II F I 2. respectively EDELMAN, M R Cleveland Electric Illuminating Go 82/12/21 YOUNOBLOOD, B J Licensing Branch I 4pp 16587 158 24X Fiche 50-440. 62/12/21. 8212270325
- 8212270481 Forwards final draft of SER Suppl 2 for release approval Suppl to be issued by 830103 Written approval should be provided by 821227 to meet issue date Urges suppl be reviewed to ensure evaluation inputs not altered W/o encl NOVAK.T M Assistant Director for Licensing 82/12/21 JOHNSTON.W V Assistant Director for Materials & Qualifications Engineering KNIGHT.J P Assistant Director for Components & Structures Engineering HOUSTON.R W Assistant Director for Radiation Protection 2pp 16573 344 24X Fiche 50-440, 82/12/21, 8212270481

F Security, madical, emergency & fire protection plans

- SRI 2010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gypsum board walls SCHWENCER.A Licensing Branch 2 82/11/26 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 3pp. 16271 094 24X Fichs 50-440 82/11/26.8212010377
- B212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility
 KEPPLER.J G Region 3. Office of Director 82/12/16
 Commonweelth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16, 8212220306
- O Adjudicatory correspondence
- B21Z010208 Memorializes B21123 telcon w/ASLB, OH Citizens for Responsible Energy, Sunflower Alliance, NRC & util rediscovery & scheduling matters Bvc list encl Related correspondence.

 BILBERG-J E Shaw, Pittman, Potts & Trowbridge SILBERG-J E. Cleveland Electric Illuminating Co B2/11/29 BLOCH, P B. KLINE-J R. SHON-F J. Atomic Safety and Licensing Board Panel. 4pp 16258 003 24X Fiche 50~440, 82/11/27,8212010208

- 8212010212 Updated response to OH Citizens for Responsible Energy B20728 Interrogatory 4-2 Svc list encl Related correspondence SILBERO.J E Cleveland Electric Illuminating Co SILBERO,J E Shaw, Pittman, Potts & Trowbridge B2/11/29 Ohio Citizens for Responsible Energy 2pp 16258 007 24X Fiche 50-440.82/11/29, 83:2010212
- 6212060108 Resubmission of sixth set of interrogatories & motion requesting presiding officer to require NRC answers Centificate of 8vc encl Related correspondence HIATT'S L Ohio Citizens for Responsible Energy 82/11/30 Office of the Executive Legal Director 9pp 16314 022 24x Fiche 50-440.82/11/30.8212060108
- 8212030181 Motion for deadline for particularization of Issue 9 by DH Citizens for Responsible Energy & for filing motions for summary disposition of Issue 9 ABLB 820712 memorandum & order failed to establish date Certificate of Svc encl CUTCHIN.J M Hearing Branch 4 82/12/01 Atomic Safety and Licensing Board Panel 4pp 16303 224 24X Fiche 50-440,82/12/01.8212030181
- 8212080264 Requests to make limited appearance statement at OL hearings SCHAEFER, K Affiliation Unknown 82/12/01 NRC No Datailed Affiliation Given 1p 16354 110 24X Fiche 50-440,82/12/01,
- 8212090495 Brief opposing NRC motion for summary disposition of Issue 3 re inadequate QA program Serious problems still exist Proof of Svc encl Related correspondence WILT.D D Cleveland Electric Illuminating Co WILT.D D Sunflower Alliance 82/12/02 Atomic Safety and Licensing Board Panel 50pp 16363 288 24% Fiche 50-440.82/12/02.8212090495
- 8212070196 Response in opposition to applicant B21118 motion for directed certification of ASLB B21029 memorandum & order re laterfiled Contentions 21-26 Applicant second attempt as deficient as first Certificate of Bvc encl HIATT, S L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Appeal Panel 10pp 16335 001 24X Fiche 50-440, 82/12/03, 8212070196
- 8212070199 Response in support of NRC 821107 motion for summary disposition of Isaus 5 Discovery on issue incomplete Request for site tour withdrawn Certificate of Svc encl Related correspondence HIATT, 8 L Unio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16334 362 24X Fiche 50-440,82/12/03.8212070199
- 8212070203 Response in opposition to NRC 821112 motion for summary disposition of Issue 7 NRC has not met burden of proof Certificate of Svc encl Related correspondence HIATT, S L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 9pp 16334 341 24X Fiche 50-440,82/12/03.8212070203
- 8212070358 Answer supporting NRC 821027 motion for summary disposition of Issue 3 Applicant mgt reacted properly to NRC Feb 1978 findings Applicant overall GA program has not been called into question since Feb 1978 Related correspondence SILBERG. J E Cleveland Electric Illuminating CO SILBERG. J E Shaw. Pittman. Potts & Trowbridge 82/12/03 Atomic Safety and Licensing Board Panel 8pp 16337 143 24X Fiche 50-440.82/12/03. G212070358
- --8212070365 Affidavit of MR Edelman & RL Farrell supporting NRC 821029 motion for summary disposition of Issue 3 re inadequate GA program Const completed by Feb 1978 acceptable & GA program effective, Certificate of Svc encl
 EDELMAN, M R., FARRELL, R L Claveland Electric Illuminating Co 82/11/30 65pp 16337 151 24X Fiche 50-440, 82/12/03, 8212070358
- B212100120 Requests to make limited appearance statement at DL hearings
 LieBERMAN.A. Affiliation Unknown B2/12/03 Commissioners 1p
 16376-014 24% Fiche 50-440,82/12/03,8212100120
- 8212130241 Answer supporting NRC 621109 motion for summary disposition of Issue 5 Break in piping of screm discharge vol would not cause unrecoverable LOGA related correspondence SILBERG, J Cleveland Electric Illuminating Co BILBERG, J Shaw, Pittman, Potts & Trowbridge 82/12/03 Atomic Safety and Licensing Board Panel 2pp 16396 199 24X Fichs 50-440,82/12/03,8212130241

1

- --B212130246 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated stram discharge vol piping rupture does not present threat to long-term core cooling capability Certificate of Svc encl ROSS, M A Cleveland Electric Illuminating Co ROSS, M A General Electric Co B2/12/01 15pp 16396 201 24x
 Fiche 50-440,82/12/03,8212130241
- 8212070155 Motion for reconsideration of ASLB 820303 Memoranoum & Order 189-82-15, admitting Issue 8 Issue Inadmissible ab initio & not particularized as ASLAB required Certification of Svc enc!

 CUTCHIN, J M Hearing Branch 4 82/12/06 Atomic Safety and Licensing Board Panel 9pp 16326 229 24% Fiche 50-440,82/12/06,8212070195
- B212080273 Forwards MA Ross signed original affidavit supporting NRC motion for summary disposition of Issue 5
 SILBERO, J E Shaw, Pittman, Potts & Trowbridge SILBERO, J E Cleveland Electric Illuminating Co 82/12/06 Docketing & Services Branch 2pp 16354 225 24X Fiche 50-440,82/12/06,8212080293
- --B2120B0301 Affidavit of MA Ross supporting NRC B21109 motion for summary disposition of Issue 5 Postulated scram discharge vol rupture does not present threat to long-term core cooling capability postulated in NUREG-0785 RUSS, MA ARC No Detailed Affiliation Given ROSS, MA General Electric Co B2/12/01 13pp 16354 227 24X Fiche 50-440, 82/12/06, 8212080293
- B212090196 Answer supporting NRC B21112 motion for summary disposition of Issue 7 Util provided for early warning of asiatic clam establishment in area Plant monitoring sys will detect any clam infestation
 SILBERG, J E Cleveland Electric Illuminating Co B2/12/07
 Atomic Bafety and Licensing Board Panel 4pp 16363 004 24X
 Fiche S0-440, 82/12/07, 8212090196
- --8212090201 Affidavit of RS Nugent supporting NRC 821112 motion for summary disposition of Issue 7 Likelihood of asiatic clams establishing in Lake Erite is low but util will monitor for clams Prof qualifications enc!
 NUOENT.R S Cleveland Electric Illuminating Co NUGENT.R S NUE Corp 82/12/03 12pp 16363 008 24X Fiche 50-440,82/12/07,8212090196
- --8212090206 Affidavit of RA Pender & RL Scherman supporting NRC 821112 motion for summary disposition of Issue 7 Util committed to plant monitoring program to detect asiatic clams Prof qualifications & Centificate of Syc encl
 PENDER, RA, SCHERMAN, RL Cleveland Ejectric Illuminating Co 82/12/03 17pp 16363 020 24X Fiche 50-440,82/12/07,8212070176
- B212130218 Requests to make limited appearance statement at OL hearings
 JONES.R Affiliation Unknown 82/12/07 Atomic Safety and
 Licensing Board Panel 1p 16390 117 24X Fiche 50-440,82/12/07,
 8212130218
- 8212090228 Response supporting util 821118 motion for directed certification of portion of ASLB 821029 memorandum & order admitting three late-filed contentions ASLB improperly found good cause for admitting issues Certificate of Svc encl CUTCHIN.J H Hearing Branch 4 WODDHEAD.C P Hearing Branch 1 82/12/08 Atomic 88fety and Licensing Appeal Panel 13pp 16361 308 24X Fichs 50-440,82/12/08.6212090228
- B21210010B Memorandum & order denying Sunflower Alliance B21110 motion for order requiring NRC to answer third set of interrogatories Sunflower failed to demonstrate relevance of unanswered discovery requests to admitted contention BLOCH.P B . KLINE.J R . SHON.F J Atomic Bafety and Licensing Board Panel 82/12/08 Sunflower Alliance 3pp 16373 350 24% Fiche 50-440, 82/12/08, 8212100108
- 8212130249 Memorandum listing interpretations of DH Citizens for Responsible Energy interrogatories on Issue 8. stated by ASLB during 821209 telcon 8LOCH.P B Atomic 8afety and Licensing Board Panel 82/12/10 ip 16389:314 24X Fiche 50-440,82/12/10.8212130249
- 8212140445 Forwards RA Pender & RL Schermen original affidavit supporting NRC motion for summary disposition of Issue 7 Svc list enc!

 81LBERG, J E Bhaw, Pittman, Potts & Trowbridge BILBERG, J E Cleveland Electric Illuminating Co 62/12/10 Docketing & Services Breach 2pp 16405 011 24X Fiche 80-440, 82/12/10, 8212140445
- 8212140465 Requests to make limited appearance statement at OL hearings BARTH, K P Affiliation Unknown 82/12/10 Docketing & Services Branch ip 16404 349 24X Fiche 50-440, 82/12/10, 8212140465

- 8212150041 Memorandum & order denying NRC 821206 motion for reconsideration of admission of Issue B re hydrogen control NRC motion untimely & is dismissed on merits BLOCH.P B. KLINE.J R. SHON.F J. Atomic Safety and Licensing Board Panel 82/12/13 Office of the Erecutive Legal Director Spp 16421 248 24x Fiche 50-440.82/12/13.8212150041
- B212150118 Forwards notes from B21209 telcon involving ABLB.applicants, NRC.Sunflower Alliance & OH Citizens for Responsible Energy re three pending motions CUTCHIN.J M Hearing Branch 4 82/12/13 BLOCH.P B , SHON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 5pg 14425 244 24% Fiche 50~440.82/12/13.8212150118
- GP12160247 Answers to eighth set of interrogatories Certificate of Sycenci STLBERG, J.E. Cleveland Electric [lluminating Co. STLBERG, J.E. Bhaw, Pittman, Potts & Frowbridge 82/12/13 Ohio Citizens for Responsible Energy 8pp 16446 195 24X Fiche 50-440.82/12/13, B212160247
- G212160251 Answers to second set of interrogatories, Numbers 20, 28 & 31 Certificate of Svc encl SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 82/12/13 Sunflower Allxance
- 8212200105 Notice of appearance in proceeding Certificate of Svc encl SMIGER.M A Cleveland Electric Illuminating Co SWIGER.M A Shaw, Pittman. Potts & Trowbridge 82/12/14 3pp 16470 071 24X Ficher 50-440, 82/12/14, 8212200105
- 8212230267 Informs of withdrawal of Interrogatories 6 8 of sixth sat of interrogatories Info provided via FOIA procedures Related correspondence HIATT.S L. Ohio Citizens for Responsible Energy 82/12/14 BLOCH.P.B. Atomic Safety and Licensing Board Panel 1p 16507 052 24X Fiche 50-440,82/12/14,8212230267
- 8212230319 Eighth discovery progress rept Certificate of Svc encl Related correspondence HIATT'S L. Ohio Citizens for Responsible Energy 82/12/14 3pp 16507 028 24X Fiche 50-440,82/12/14,8212230319
- 8212230345 Motion in opposition to NRC 821105 motion for summary disposition of Issue 4 Genuine issues of matl fact still to be heard Certificade of Svc encl Related correspondence HIATT.S L. Ohio Citizens for Responsible Energy 82/12/14 Atomic 8afety and Licensing Board Panel 9pp 16505 176 24X Fiche 50-440, 82/12/14-8212230345
- 82:2230368 Response to NRC 82:122 motion for summary disposition of Issue 12 FES should be amended to reflect existence of NUREO/CR-2891 Certificate of Syc enci Related correspondence
 HIATT.S L. Ohio Citizens for Responsible Energy 82/12/14
 Atomic Safety and Licensing Board Panel 3pp 14511 204 24K
 Fiche 50-440, 82/12/14, 82:12230368
- B212200061 Answer supporting NRC B21105 mation for summary disposition of Issue 4 Thirty-degree sector steam test not specifically required by App K GE performed test for simulated BNR/6 core Distribution of core spray flow hot safety issue SILBERO. J E Cleveland Electric Illuminating Co SILBERO. J E Shaw. Pittman. Potts & Trombridge 82/12/15 Atomic Safety and Licensing Board Panel 3pp 16473 315 24% Fichs 50-440.82/12/15, B212200061
- --8212200072 Affidavit of WA Sutherland supporting NRC 821105 motion for summary disposition of Issue 4 App K does not require fullscale 30-degree sector steam test Certificate of Svc encl SUTHERLAND, WA Cleveland Electric Illuminating Co SUTHERLAND, WA General Electric Co 82/12/15 24pp 16473 318 24X Fiche 50-440,82/12/15,8212200061
- 8212200093 Memorandum & Order ALAB-706, denying applicant 821029 motion for directed certification of LBP-82-98, admitting OH Citizens for Responsible Energy three late-filed contentions ASLAB intercession not yet warranted TOMPKINS.8 A Atomic Safety and Licensing Appeal Panel 82/12/15 Cleveland Electric Illuminating Co Bpp 16474 292 24X Fiche 50-440, 82/12/15, 8212200093
- 8212220240 Requests to make limited appearance statement at OL hearings LONG, B M Affiliation Unknown 82/12/15 Docketing & Bervices Branch 1p 16518 329 24X Fiche 50-440.82/12/15,8212220260

- 8212210321 Answer supporting NRC 821122 motion for summary disposition of Issues II & 12 Sunflower Alliance withdrew Issue II on 821110 No genuine issue of mati fact remains for Issue 12 Certificate of Svc encl SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J, E Shaw, Pittman, Potts & Trowbridge 82/12/16 Atomic Bafety and Licensing Board Panel 5pp 16496 311 24% Fiche 50-440,82/12/16,8212210321
- 8212210345 Forwards signed original affidavits of KA Matheny & RA Stratman re applicant 821213 answers to interrogatories & WA Sutherland re support of NRC motion for summary disposition of Issue 4
 SILBERO, J & Shaw, Pittman, Potts & Troubridge SILBERO, J & Cleveland Electric Illuminating Co 82/12/17 Docketing & Bervices Branch 3pp 16496 337 24X Fiche 50-440.82/12/17, 8212210345
- B212220339 Requests to make limited appearance statement at OL hearings DAVIS.H M Affiliation Unknown 82/12/17 Docketing & Services Branch Ip 14517 151. 24% Fithe 50-440.82/12/17.8212220339
- 82:2210318 Answer apposing OH Citizens for Responsible Energy 82:130 mattern for order requiring NRC to answer sixth set of interrogatories Certificate of 8 for encil CUTCHIN. J M Hearing Brench 4 82/12/20 Atomic Safety and Licensing Board Panel 37pp 16496-253 24X Fichs 50-440,82/12/20,82/2210318
- 8212280319 Forwards SL Histt affidavit supporting Sunflower Alliance opposition to NRC motion for summary disposition of Issue 3 MILT.D D Wilt.D D Sunflower Alliance 82/12/20 BLOCK.P B , SHOR,F J , KLINEJ,R Atomic Safety and Licensing Board Panel 1p 16556 146 24X Fiche 50-440.82/12/20.8212280319
- --8212280324 Affidavit of 8t Histt re exam of facility quarterly GA assessments & trend analysis repts
 HIATT.S L. Ohin Citizens for Responsible Energy 82/12/14 lipp
 16556 147 24X Fichs 50-440.82/12/20.8212280319
- 8212230339 Suppls applicant response to Sunflower Alliance
 Interrogatory 2 re standby liquid control sys initiation Svc
 list encl Related correspondence
 QLASSPIEGEL.H Shaw, Pittman, Poets & Trowbridge 82/12/21
 HIATT, S.L. Obio Citizens for Responsible Energy 3pp 16505 159
 24X fiche 50-440.82/12/21.8218230339
- 8212230351 Order granting NRC motions for summary disposition of GA.
 Corbicula & screm discharge vol contentions except for
 genuine issues of fact specified
 BLOCH, P B. KLINE, J R., SHON, F J. Atomic Bafety and Licensing Board
 Panel 82/12/22 Office of the Executive Legal Director 17pp
 16517 133 24X Fiche 50-440,82/12/22,8212230351
- 8212300054 Requests to make limited appearance statement at OL hearing WOODSIDE, P Affiliation Unknown 82/12/22 NRC No Detailed Affiliation Given [p 16598 190 24% Fiche 50~440,82/12/22,8212300.54
- 8212280192 Notice of ASLB reconstitution PB Block chairman & JR Kline & GD Bright members.
 COTTER B P Atomic Safety and Licensing Board Panel 82/12/23
 2pp 14562 304 24X Fiche 50-440,82/12/23.8212280192
- B212300018 Memorandum & order directing NRC to respond as listed to OH Citizens for Responsible Energy interrogatories on Issue 8 re hydrogen generation BLOCH.P B. BRIGHT.Ø D Atomic Safety and Licensing Board Panel 82/12/23 Office of the Erecutive Legal Director 10pp 16598 208 24X Fiche. 50-440, 82/12/23. 8212300018
- 3212300051 Requests to make limited appearance statement at QL hearing FRITZ.E J Affiliation Unknown 82/12/24 Docketing & Services Branch Ip 16598 193 24% Fiche 50-440, 82/12/24, 8212300051
- 2012300013 Updates applicant 820924 response to Interrogatory 3-4 of OH Citizens for Responsible Energy 820830 third set of interrogatories Svc list encl, Related correspondence SWIGER, H A Shaw, Pittman, Potts & Troubridge SWIGER, H A Cleveland Electric Illuminating Co 82/12/27 HTATT, S L Ohio Citizens for Responsible Energy 3pp 16598-224 24X Fiche 50-440, 82/12/27, 8212300013

H Qeneral correspondence

- G212070015 Submits mgt changes effective B21201 DR Davidson to become senior vice president & MR Edelman to become vice president, nuclear group & staff contact for correspondence DAVIDSON, D R Cleveland Electric Illuminating Co 82/12/02 YOUNOBLOOD, B J Licensing Branch i ip 16327 243 24X Fiche 50-440,82/12/02,8212070015
- 8212200051 Requests that USOS evaluate risk of catastrophic explosion of propene leak from underground storage wells into Morton Salt Mine FSAR & FEG deny possibility of event BIMBER.R N Affiliation Unknown 82/12/14 STEFAND, J J NRC ~ No Detailed Affiliation Given 2pp 16470 006 24X Fiche 50-440, 82/12/14, 8212200051
- --8212200098 Trip rept of 730912 site safety visit re specific features associated ω/proposed site

 * Atomic Energy Commission 73/12/13 Atomic Energy Commission 3pp 16470 008 24X Fiche 50~440.82/12/14. 6212200051
- K Utility Final Safety Analysis Report (FSAR) & amends
- BP12020098 Amend 10 to FSAR W/629 oversize drawings Aperture cards are available in PDR # Cleveland Electric Illuminating Co # B2/11/29 420pp 16274 179 24X Fiche 50-440.82/11/23.8212020091
- M Antitrust correspondence
- B212150012 Requests NRC review of Cleveland Electric Illuminating Co 821119 filling w/FERC for increase in rates for firm power svc Also requests NRC consideration of petition to intervena in matter PANDY.J Cleveland, OH 82/12/02 TOALSTON.A Antitrust & Economic analysis Branch (Utility Finance) 37pp 16421 139 24X Fiche 30-000.82/12/02.8212150012
- SP12220075 Forwards NRC 790625 ltr to util transmitting 790625 order requiring util to file transmission svc tariff at FERC.per S1120B telcon VOGLER.B H Hearing Branch 2 82/12/09 DAVIS.P Arnold & Porter ip 16516 094 24X Fiche 50-440.82/12/09.8212220075
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Builetin 82-03. Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Svc list encl DEYQUNO. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermaluminescent Dosimeters " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 30-000.82/11/05,8208190245
- BPOBI90251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251
- B208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190287 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of Naw York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 8212080019 Forwards NRR input to SALP rept for Oct 1981-Sept 1982 Overall rating of Category I given for licensee performance STEFANO.J J Licensing Branch 1 82/11/30 EISENNUT.D 0 Division of Licensing 2pp 16367 169 24X Fiche 50-440.82/11/30. 8212080019
- BPOB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list whol DEYOUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259

1

- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay
- Sockets " Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fichs 50-000.82/12/03,8208190261
- 8212290412 Forwards IE Insp Repts 50-440/82-16 & 50-441/82-15 on 820801-1031 No noncompliance noted KKOP.R C Division of Project & Resident Programs 82/12/15 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 16384 311 24X Fiche 50-440,82/12/15.8212290412
- noncompliance noted Major areas inspected containment done installation, shield bldg done concrete placement, refueling bridge rail concrete placement, refueling bridge rail concrete placement by general housekeeping GILDNER, M. L. KUNKLIN, J. E. Division of Project & Resident Programs 82/12/14 App 16584-313 24X Fiche 50-440,82/12/15,8212290412 -- H212290417 IE Insp Repts 50-440/82-16 & 50-441/82-15 on 820801-1031 No
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG, R C Director's Defice. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type (TE-27 " Svc list encl
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20
 Consolidated Edison Co. of New York, Inc. 108pp. 16628 293 24X Fiche 50-000, 62/12/20, 8208190249
- S Reportable occurrences, LERs & related correspondence
- 8/12020296 Interim deficiency rept re contact leads on HMA relays supplied by GE Initially reported on 820917 Deficiency not reportable based on design function of relay C61A-K2 Rept for Unit 2 HMA relays will be submitted by 831031 DAVIDSON,D R Cleveland Electric Illuminating Co 82/11/24 KEPPLER,J O Region 3, Office of Director 2pp 16277 357 (tche 50-440,82/11/24,8212020296 24X
- G212020379 Revised 820315 final deficiency rept re cladding fissures adjacent to weld seams in stainless steel suppression pools litems 2 & 3 of proposed corrective action deleted Placement of annulus concrete in pool region will reduce stress level BAVIDSQN.D R Cleveland Electric Illuminating Co 62/11/24 KEPPLER.J G Region 3. Office of Director 2pp 16278 258 Fiche 50-440, 82/11/24,8212020395
- B212170153 Supplemental final deficiency rept re biological concrete shield walls Unit I repairs will not be completed until 830501 due to changes in const scheduling Unit 2 repairs on
- B012170241 Revised final deficiency rept to defective Bettis Model T3 series actuation yokes on Henry Pratt Co valves Due to delay in receipt of replacement parts & const scheduling.required mods not yet completed
 EDEUMAN.M R Cleveland Electric Illuminating Ca 82/12/10
 KEFPLER.J O Region 3. Office of Director 1p 16459 336
 Liche 50-440, 82/12/10, 8212170241 241
- GP12210370 Final deficiency rept to dowel counterbore in link rod in standby dissel engine Initially reported on 801000 Link rod inspected Deficiency determined not reportable per 10CFR50 55(e)
- EDELMAN. M.R. Cleveland Electric Illuminating Co. 82/12/10 KEPPLER. J. G. Region 3. Office of Director 1p. 16493 360 Fiche 50-440.82/12/10,8212210370
- 87:1228027: Final deficiency rept re potential defect in starting air sys check valve mfg by Transamerica Delaval Initially reported on 8:1218 Check valve disc assembly will be replaced by 830701

 CDELMAN.H R Cleveland Electric Illuminating Co 82/12/15

 KEPPLER.J O Region 3, Office of Director 2pp 16560 102

 Fiche 50-440, 82/12/15, 8212280271 DAY
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2 A Application/construction stage documents & correspondence
- BP12270031 F01A request for five categories of documents HEATT.8 L Ohio Citizens for Responsible Energy 62/11/04 FELTON, J M Division of Rules and Records 1p 16607 132 Fishe 50-440, 82/11/04, 8212270031 DAY

- 8212060484 Forwards "Human Factors Engineering Control Room In-Progress
 Audit "Requests schedule for NRC final control room design
 audit.including close-out of TNI Action Plan Item (D I &
 II K 3 27 prior to licensing
 SCHHENCER.A Licensing Branch 2 82/11/12 DAVIDSON.D R
 Cleveland Electric Illuminating Co 2pp 16/343 248 24X
 Fiche 50-440, 82/11/12,8212060484
- BP11230066 Ceneric Ltr 82-27 to all BWR licensess of operating reactors except LACBHR, Big Rock Point, Dresden 1, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 Svc list encl H/o stated encl EISEAHUT, D G, Division of Licensing 82/11/15 General Public Utilities 900 Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230044
- B212070451 Ack receipt of B21116 memo to A Schwencer clarifying procedure for controlling document transmittals Superseded transmittals will be returned as requested Future transmittals should be addressed to BJ Youngblood STEPAND, J J Licensing Branch 1 82/11/29 KNKADE, J Clm Electric Illuminating Co ip 16355 324 24X Fiche 50-440. 82/11/29, 82(2070451
- B212070466 Forwards requests for add1 info to be furnished prior to site audit for seismic & dynamic equipment qualification reviews Scheduled time period for audit also requested YOUNOBLOOD, B J Licensing Branch ! 82/11/30 DAVIDSON, D R Cleveland Electric Illuminating Co 28pp 16054 244 24X Fiche 50-440,82/11/30,8212070466
- 8P120B0021 Memorializes 821124 telcon w/vtil & Gilbert Associates re safety relief valve hydrodynamic loads test STEFANO.J J Licensing Branch 1 82/11/30 YOUNOBLOOD, B J Licensing Branch 1 2pp 16367 167 24X Fiche 50-440,82/11/30.
- 8712080115 Summary of 821122 meeting w/util.0ilbert Associates & Nuclear Technology in Bethesda, MD re util proposal for not performing safety relief valve hydrodynamic load discharge tests STEFAND, J J Licensing Branch 1 82/11/30 YOUNGBLOOD, B J Licensing Branch 1 4pp 16368 271 24% Fiche 50-440, 82/11/30, 8212080115
- 8P12070237 Amplifies justifications provided in 820721 application for amend of CPPR-148 & CPPR-149 to extend const completion dates Reduced demand. Increased regulations & high interest rates delayed need for capacity supplied by facilities EDEL/MAN. M R Cleveland Electric Illuminating Co 82/12/01 YOUNDELOOD, J Licensing Granch 1 2pp 16329 311 24X Fiche 50-440, 82/12/01, 8212070237
- 82:2270036 Responds to FOIA request for five categories of documents forwards documents listed in App A Review of documents re Tormaros accuments listed in App A Review of accuments reliem i continuing
 FELTON.J M Division of Rules and Records 82/12/02 HIATT, S L.
 Ohio Citizens for Responsible Energy 2pp 16607 133 24X
 fich 50-440.82/12/02.8212290036
- BP12230385 Discusses JJ Stefano B21130 meeting rept summarizing discussions re need to conduct safety relief valve hydrodynamic load tests Potential thermal gradient stresses of concern Questions encl for response formulating concern YOUNGBLOOD B J Licensing Branch 1 82/12/14 EDELMAN, M R Cisveland Electric 111uminating Co 3pp 16540 242 24X Fiche 50-440, 82/12/14, 8212230385
- 8212300077 Notification of 830111-13 meetings w/util in Lake County.OH to assess status of const & completion schedules STEFANO.J J Licensing Branch 1 82/12/15 YOUNGBLOOD.B J Licensing Branch 1 5pp 16624 275 24x Fithe 80-440,82/12/15. 8212300077
- BP12280255 Responds to NRC 821019 Questions 260 10-260 13 requesting add1 info & clarification of Table 3 2 1 in FBAR Amends G & 9 re QA
 EDELHAN M R Cleveland Electric Illuminating Co 82/12/21 Cleveland Electric Illuminating Co 82/ I licensine Branch i 7pp 16961 297 YOUNGBLOOD, B J Licensing Granch 1 7pp Fiche 50-440, 82/12/21, 8212280255
- D NRC Draft/Final Environmental Statements, supple & correspondence
- GP12210435 Advises that EIS & EIA reviewed by all interested state agencies No concerns stated BRACHMAN, J Y Ohio. State of B2/10/27. SCHWENCER, A Licensis Branch 2 Ip 16489 177 24X Fiche 50-440.82/10/27.8212210435

- E NRC Safety Evaluation Report (SER), supple & correspondence
- B212010377 Summarizes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 35 re documentation or test of 3-h fire resistance of gypsum board walls SCHNERGER.A Licensing Branch 2 B2/11/26 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 16271 094 24X Fiche 50-440, 82/11/26, 8212010377
- B212070460 Requests that util formally endorse BWR owners group proposal to modify automatic depressuriation sys initiation to allow NRC to complete generic review of TMI Item II K 3 18 info needed to resolve SER Confirmatory Issue 7 YOUNGBLOOD.B J Licensing Branch I B2/11/30 DAVIDSON.D R Cleveland Electric Illuminating Co 2pp 16355 319 24X Fiche 50-440,82/11/30.8212070460
- B212070397 Responds to SER Dutstanding Issue 10 re continuous containment purge & Confirmatory Issue 20 re subcompartment pressure analysis FSAR will be revised w/resolution of issues EDELMAN, HR Cleveland Electric Illuminating Co 82/12/02 YOUNGBLOOD, J. Licensing Branch 1 5pp 16336 328 24X Fiche 50-440, 82/12/02, 8212070397
- BP12270002 Notification of B21214 meeting w/applicants & QA intl in Brthesda. HD to discuss unresolved containment issues cited in SER (NUREG-0BB7) STEFAND, J J Licensing Branch i 82/12/09 YGUNOBLOOD, B Licensing Branch 1 3pp 16551 287 24X Fiche 50-440, 82/12/09, 8212270002
- 8212290189 Responds to SER Confirmatory Issue 44 re radiation & shielding design of inclined fuel transfer sys tubes Info in Amend 10 to FSAR should resolve issue EDELHAN.M R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLGDD.B J Licensing Branch 1 lp 16578 195 24X Fichs 50-440,82/12/21.8212290189
- 8212290305 Forwards response to NRC 820908 ltr. Question 640 2.re SER Outstanding Issue 21. Section 13 5 2 2 on reanalysis of transients & accidents & development of emergency operating procedures Submittal suppls 821116 response EDELMAN, M R Cleveland Electric Illuminating Co 82/12/21 YOUNGBLOOD, B J Licensing Branch 1 2pp 16588 016 24X Fiche 50-440.82/12/21, 8212290305
- G212270325 Forwards response to SER Confirmatory Issues 41 & 42 re design for noble gas effluent monitors & design for sampling & analysis of plant effluents, per NUREG-0737, Items II F I 1 & II F I 2 respectively EDELMANIM R Cleveland Electric Illuminating Co 62/12/21 YOUNGBLOOD B J Licensing Branch 1 4pp 14587 158 24X fiche 50-440, 82/12/21, 8212290325
- 8212270481 Forwards final draft of SER Suppl 2 for release approval Suppl to be issued by 830103 Written approval should be provided by 821227 to meet issue date Urges suppl be reviewed to ensure evaluation inputs not altered 4/o encl NOVAK. I M. Assistant Director for Licensing 82/12/21 JOHNSTON, W. Assistant Director for Materials & Qualifications Engineering KNIGHT. J.P. Assistant Director for Components & Structures Engineering HOUSTON. R.W. Assistant Director for Radiation Protection 2pp 16593 344 24X Fiche 50-440, 82/12/21, 8212290481
- F Security, medical, emergency & fire protection plans
- 8212010377 Summarijes findings on SER Outstanding Issues 15 & 16 re fire protection & Confirmatory Issue 36 re documentation or test of 3-h fire resistance of gupsum board walls SCHKENCER:A Licensing Branch 2 62/11/26 DAVIDSON, D R Cleveland Electric Illuminating Co 3pp 16271 094 24X [iche 50-440,82/11/26,8212010377
- 8212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-sate emergency operations facility
 KEPPLER, J O Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000,82/12/16,821220306
- G Adjudicatory correspondence
- B212010208 Memorializes B21123 telcon w/ASLB.OH Citizens for Responsible Energy. Sunflower Alliance.NRC & util rediscovery & scheduling matters Svc list encl Related correspondence
 SILBERO.J E Shaw, Pittman, Potts & Troubridge SILBERO.J E Cleveland Electric Illuminating Co B2/11/29 BLOCH.P B .
 KLINEJ R . SHON.F J Atomic Safety and Licensing Board Panel 4p 16258 003 24X Fiche 50-440.82/11/29.8212010208

- 8212010212 Updated response to OH Citizens for Responsible Energy 820928 Interrogatory 4-2 Svc list encl Related correspondence SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 82/11/29 Ohio Citizens for Responsible Energy 2pp 16258 007 24X Fiche 50-440.82/11/29, 802(2010)242
- 8212050108 Resubmission of sixth set of interrogatories & motion requesting presiding officer to require NRC answers Certificate of 8vc encl Related correspondence HIATT, S. L. Obio Citizens for Responsible Energy 82/11/30 Office of the Executive Legal Director 9pp 16314 022 24X Fiche 50-440,82/11/30,8212060108
- B2120301B1 Motion for deadline for particularization of Issue 9 by CH Citizens for Responsible Energy & for filing motions for summary disposition of Issue 9 ASLB 820712 memorandum & order failed to establish data Certificate of Svc encl CUTCHIN.J M Hearing Branch 4 82/12/01 Atomic Bafety and Licensing Board Panel 4pp 16303 224 24X Fiche 50-440.82/12/01, 8212030181
- 8212080264 Requests to make limited appearance statement at OL hearings SCHAEFER, K Affiliation Unknown 82/12/01 NRC No Detailed Affiliation Given 1p 16354 110 24X Fiche 50-440, 82/12/01, 82:5080264
- 8212090495 Brief opposing NRC motion for summary disposition of Issue 3 re inadequate GA program Serious problems still exist Proof of Svc encl Related correspondence WILT, D D Cleveland Electric Illuminating Co WILT, D D Sunflower Alliance G2/12/02 Atomic Sefety and Licensing Board Panel 50pp 16363 288 24X Fiche 50-440.82/12/02.8212090495.
- 8212070196 Response in apposition to applicant 821118 motion for directed certification of ABLB 821027 memorandum & order re laterfiled Contentions 21-26 Applicant second attempt as deficient as first Certificate of 8vc encl HIATT.S L Dhio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Appeal Panel 10pp 16335 001 24X Fiche 30-440,82/12/03,8212070196
- GP12070197 Response in support of NRC 821107 motion for summary disposition of Issue 5 Discovery on issue incomplete Request for site tour withdrawn Certificate of SVC encl Related correspondence HIATT 5 L Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 2pp 14334 352 241 fiche 50-440.82/12/03.8212070197
- 8P12070203 Response in opposition to NRC 821112 motion for summary disposition of Issue 7 NRC has not met burden of proof Certificate of Suc enci. Related correspondence HIATT/S L. Ohio Citizens for Responsible Energy 82/12/03 Atomic Safety and Licensing Board Panel 9pp 16334,341 24X Fiche 50-440.82/12/03.8212070203
- BP12070358 Answer supporting NRC 821027 motion for summary disposition of Issue 3 Applicant mgt reacted properly to NRC Feb 1978 findings Applicant overall GA program has not been called into question since Feb 1978 Related correspondence SILBERG, J E Claveland Electric Illuminating CO SILBERG, J E Shaw, Pittman, Potts & Troubridge 82/12/03, Atomic Bafety and Licensing Board Panel Bpp 16337 143 24% Fiche 50-440,82/12/03,8212070358
- --8212070365 Affidavit of MR Edelman & RL Farrell supporting NRC 821029 motion for summary disposition of Issue 3 re inadequate QA program Const completed by Feb 1978 acceptable & QA program effective Certificate of Svc encl EDELMAN.M R , FARRELL,R L Cleveland Electric Illuminating Co 82/11/30 45pp 16337 151 24X Fiche 50-440,82/12/03,8212070358
- B212100120 Requests to make limited appearance statement at QL hearings LIEBERMAN.A Affiliation Unknown 82/12/03 Commissioners Ip 16376 014 24X Fiche 50-440,82/12/03,8212100120
- B212130241 Answer supporting NRC B21109 motion for summary disposition of Issue 5 Break in piping of scram discharge vol would not cause unrecoverable LOCA Related correspondence SILBERO, J. Chevland Electric Illuminating Co. SILBERO, J. Shaw, Pittman. Potts & Troubridge B2/12/03 Atomic Bafety and Licensing Board Panel 2pp 16396 199 24X Fiche 30-440.82/12/03, B212130241

- --8212130246 Affidavit of MA Ross supporting NRC 821109 motion for summary disposition of Issue 5 Postulated scram discharge vol piping rupture does not present threat to long-term core cooling capability Certificate of Svc encl ROSS, MA Cleveland Electric Illuminating Co ROSS, MA General Electric Co 82/12/01 15pp 16396 201 24X Fiche 50-440,82/12/03,8212130241
- B212070155 Motion for reconsideration of ASLB 820303 Memorandum & Order LBP-82-15, admitting Issue B Issue inadmissible ab initio & not particularized as ASLAB required Certification of Svc encl CUTCHIN, J M Hearing Branch 4 82/12/06 Atomic Safety and Licensing Board Panel 9pp 16326 229 24X Fiche 50-440,82/12/06,8212070155
- 8212080293 Forwards MA Ross signed original affidavit supporting NRC motion for summary disposition of Issue 5 SILBERG, J E Shaw, Pittman, Potts & Trombridge SILBERG, J E Cleveland Electric Illuminating Co 82/12/06 Docketing & Services Branch 2pp 16354 225 24X Fiche 50~440,82/12/06,8352080293
- --8212080301 Affidavit of MA Ross supporting NRC 821109 motion for summary disposition of Issue 5 Postulated scram discharge vol rupture does not present threat to long-term core cooling capability postulated in NVMEO-0785 ROSS, M A NRC No Detailed Affiliation Given ROSS, M A General Electric Co 82/12/01 ISpp 16354 227 24X Fiche 50-440,82/12/06.8212080293
- B2:2090176 Answer supporting NRC B2:1112 motion for summary disposition of Issus 7 Util provided for early warning of asiatic clam establishment in area Plant monitoring sys will detect any clam infestation
 SILBERO, J E Cleveland Electric Illuminating Co 82/12/07
 Atomic Safety and Licensing Board Panel 4pp 16363 004 24X
 Fiche 50~440,82/12/07.8212090176
- --8212070201 Affidavit of RS Nugent supporting NRC 821112 motion for summary disposition of Issue 7 Likelihood of asiatic clams establishing in Lake Erry is low but util will monitor for clams Prof qualifications encl NUGENT.R S Cleveland Electric Illuminating Co NUGENT.R S NUE Corp 82/12/03 12pp 16363 008 24X Fiche 50-440,82/12/07,8212090196
- --8212090204 Affidavit of RA Pender & RL Scherman supporting NRC 821112 motion for summary disposition of Issue 7 Util committed to plant monitoring program to detect asiatic clams Prof qualifications & Certificate of Svc encl PENDER:RA A BCHERMAN.R L Cleveland Electric Illuminating Co 82/12/03 17pp 16363 020 24% Fiche 50-440,82/12/07,8212090196
- 0212130218 Requests to make limited appearance statement at OL hearings
 JONES R Affiliation Unknown 82/12/07 Atomic Safety and
 Licensing Board Panel 1p 16390 117 24X Fiche 50-440,82/12/07,
- 821207022B Response supporting util 821118 motion for directed certification of portion of ABLB 821027 memorandum & order admitting three late-filed contentions ABLB improperly found good cause for admitting issues Certificate of Svc encl CUTCHIN. J H Hearing Branch 4 WOODHEAD.C P. Hearing Branch 1 82712708 Atomic Safety and Licensing Appeal Panel 13pp 16361 308 24X Fiche 50-440.82/12/08.8212070228
- G21210010B Memorandum & order denying Sunflower Alliance B21110 motion for order requiring NRC to answer third set of interropatories Sunflower failed to demonstrate relevance of unanswered discovery requests to admitted contention BLOCH-P B . KLINE, J R . SHON.F J Atomic Bafety and Licensing Board Panel B2/12/0B Sunflower Alliance 3pp 16373 350 24% Fiche. S0-440, 82/12/08, 82/12/0010B
- 8212130249 Memorandum listing interpretations of OH Citizens for Responsible Energy interrogatories on Issue 8. stated by ASLB during 821209 telcon BLOCH.P B Atomic Safety and Licensing Board Panel 82/12/10 ip 16387-314 24X Fiche 50-440,82/12/10,8212130249
- B212140445 Forwards RA Pender & RL Schermen original affidavit supporting NRC motion for summary disposition of Issue 7 Bvc list encl SLOBERO, J E Shaw. Pittman, Potts & Trowbridge SILBERO, J E Cleveland Electric Illuminating Co 82/12/10 Docketing & Services Brench 2pp 16405,011 24X Fiche,50-440,82/12/10,8212140445
- 8212140465 Requests to make limited appearance statement at OL hearings.
 BARTH, K.P. Affiliation Unknown 82/12/10 Docketing & Services Branch ip 16404 349 24X Fiche: 50-440, 82/12/10, 8212140465

- 8212150041 Memorandum & order denying NRC 821206 motion for reconsideration of admission of Issue 8 re hydrogen control NRC motion untimely & is dismissed on merits BLOCH.PB, KLINE, JR, SHON, FJ Atomic Safety and Licensing Board Panel 82/12/13 Office of the Executive Legal Director Upp 16421 248 24X Fiche 50-440,82/12/13,8212150041
- 8212150118 Forwards notes from 821209 telcon involving ASLB.applicants. NRC.Sunflower Alliance & OH Citizens for Responsible Energy re three pending motions
 CUTCHIN.J M Hearing Branch 4 82/12/13 BLOCH.F B . SHON, F J .
 KLINE-J R Atomic Safety and Licensing Board Panel Spp
 16425 244 24X Fishe 50-440.B2/12/13.8212150118
- 9212160247 Answers to eighth set of interrogatories Certificate of Svc enc! SILBERO, J E Cleveland Electric Illuminating Co SILBERO, J E Shaw, Pittman, Potts & Troubridge 92/12/13 Ohio Citizens for Responsible Energy 8pp 16446 195 24X Fiche 50-440,82/12/13, U212160247
- GP12160251 Answers to second set of interrogatories, Numbers 20, 28 & 31 Certificate of Syc encl SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Troubridge 82/12/13 Sunflower Alliance 9pp 16446 [54 24% Fiche 50-440, 82/12/13, 821216025]
- SP12200105 Notice of appearance in proceeding Certificate of Svc encl SWIGER,M A Cleveland Electric Illuminating Co SWIGER,M A Show, Pittman, Potts & Trowbridge B2/12/14 3pp 16470 091 24X Fiche 50-440, 82/12/14, 8212200105
- GP12230267 Informs of withdrawal of Interrogatories 6 8 of sixth set of interrogatories Info provided via FDIA procedures Related correspondence HIATT.S L Dhio Citizens for Responsible Energy 62/12/14 BLOCH.P B Atomic Safety and Licensing Board Panel ip 16507 352 24X Fiche 50-440.82/12/14.6212230267
- B212230319 Eighth discovery progress rept Certificate of Svc encl Related correspondence HIATT, S.L. Ohio Citizens for Responsible Energy 82/12/14 3pp 16307 028 24X Fiche 50-440,82/12/14,8212230319
- B212230345 Motion in opposition to NRC 821105 motion for summary disposition of Issue 4 Genuine issues of math fact still to be heard Certificate of Svc encl Related correspondence HIATT.S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 14505 176 24X Fiche 50-440-82/12/14-8212230345
- B212230360 Response to MRC B21122 mution for summary disposition of lasue 12 FES should be amended to reflect existence of NUREG/CR-2991 Certificate of Svc encl Related correspondence HIATT-S L Ohio Citizens for Responsible Energy 82/12/14 Atomic Bafety and Licensing Board Panel 3pp 16311 204 24X Fiche 50-440,82/12/14,8212230368
- BP12200061 Answer supporting NRC 821105 motion for summary disposition of Issue 4 Thirty-degree sector steam test not specifically required by App K GE performed test for simulated BMR/d core Distribution of core Spray flow not safety issue SILDERO, J E Cleveland Electric Illuminating Co SILDERO, J E Shaw, Pittman, Potts & Troubridge 82/12/15 Atomic Safety and Licensing Board Panel Spp 14473 315 24X Fiche 50-440,82/12/15, 4212200061
- --B212200072 Affidavit of WA Sutherland supporting NRC 821105 motion for summary disposition of Issue 4 App K does not require full-scale 30-degree sector steam test Certificate of Svc encl SUTHERLAND. WA Cleveland Electric Illuminating Co SUTHERLAND. WA General Flectric Co 82/12/15 24pp 16473 318 24X Fiche 50-440.82/12/15.8212200061
- 821220093 Memorandum & Order ALAB-706, denying applicant 821029 motion for directed certification of LBP-82-98, admitting GH Citizens for Responsible Energy three late-filed contentions ASLAB intercession not yet warranted TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 82/12/15 Cleveland Electric Illuminating Co Bpp 16474 292 24X Fiche 50-440, 82/12/15,8212200093
- BP12220260 Requests to make lamited appearance statement at OL hearings
 LONG.B M Affiliation Unknown 82/12/15 Docketing & Services
 Branch 1p 16518 329. 24X Fiche 50-440,82/12/15,8212220260

- 8:12210321 Answer supporting NRC 821122 motion for summary disposition of Issues 11 & 12 Sunflower Alliance withdrew lesue 11 on 821110 No genuine issue of math fact remains for Issue 12 Certificate of Svc enci SILBERG. J E Cleveland Electric Illuminating Co SILBERG. J E Shaw. Pittnan. Potts & Trowbridge 82/32/36 Atomic Safety and Licensing Board Panel Spp 14474 311 24X Fiche 50-440,82/12/16, 82/12/164
- 87:12210345 Forwards signed original affidavits of KA Matheny & RA Stratman re applicant 82:1213 answers to interrogatories & WA Sutherland re support of NRC notion for summary disposition of Issue 4 STUBERG, JE Shaw, Pittman, Potts & Trowbridge SILBERG, JE Cleveland Electric Illuminating Co 82/12/17 Docteting & Services Branch 3pp 14494 337 24x Fiche 50-440.82/12/17, M212210345
- GF12220339 Requests to make limited appearance statement at OL hearings DAVIS.H H Affiliation Unknown 62/12/17 Docketing & Services Branch 1p 16517 131 24X Fiche 50-440. 82/12/17, 8212220339
- 8:12210318 Ansuer opposing OH Citizens for Responsible Energy 821130 motion for order requiring NRC to answer sixth set of interrogatories Certificate of Svc enci CUTCHNION Hearing Branch 4 82/12/20 Atomic Safety and Licensing Board Panel 37pp 16496 253 24Y Fiche 50-440,82/12/20, openingles
- 6/12280319 Forwards SL Hiatt affidavit supporting Sunflower Alliance opposition to NRC motion for summary disposition of Issue 3 MILT.DD Wilt, DD WILT.DD Sunflower Alliance 82/12/20 MLCD.PB. SHOTLF J. KLINEJ R. Atomic Safety and Licensing Board Panel 1p 16556 146 24X Fiche 50-440.62/12/20.8212280319
- 8212280324 Affidavit of SL Hiatt re exam of facility quarterly GA assessments 5 trend analysis repts
 HIATT, S L Ohio Citizens for Responsible Energy 82/12/14 lipp 16556 147 24% Fiche 30-440,82/12/20,8212280319
- 82/12/20039 Suppls applicant response to Sunflower Albiance
 Interrogatory 2 re standby liquid control sys initiation Svc
 list encl Related correspondence
 OLASSPIECEL, H. Shau, Pittman, Potts & Trowbridge 82/12/21
 HIATT, S. & Dhio Citizens for Responsible Energy 3pp 16505-159
 P4X Fiche 50-440,82/12/21.8212230337
- 8./12230351 Order granting NRC motions for summary disposition of QA.
 Corbicula A scram discharge vol contentions except for
 genuine issues of fact specified
 BLOCH.P.B. ALINE, J.R. SHON, F.J. Atomic Bafety and Licensing Bource
 Panel 62/12/22 Orfice or the Executive Legal Director 17pp
 16517 133 24X Fiche 50-440.62/12/22,8212230351
- BP12300054 Requests to make limited appearance statement at OL hearing MODDSIDE.P Affiliation Unknown 82/12/22 NRC No Detailed AFFiliation Given Ip 16598 190 24% Fiche 50-440.82/12/22.8212300054
- GP12280192 Notice of ASLO reconstitution PD Bloch, chairman & JR Kline & GD Bright.nembers COTTER, B P Atomic Safety and Licensing Board Panel 82/12/23 2pp 16562 304 24X Fiche 50-440, 82/12/23, 8212280192
- BE/12300018 Memorandum & order directing NRC to respond as listed to DR Citizens for Responsible Energy interrogatories on Issue 8 rs hydrogen generation BLOCH.P B . BRIGHT.6 O Atomic Safety and Licensing Board Panel B2/12/23 Office of the Executive Legal Director 10pp 14598 208 24% Fiche 50-440,82/12/23.8212300019
- G212300051 Requests to make limited appearance statement at DL hearing FRITZ.E J Affiliation Unknown 82/12/24 Docketing & Services granch ip 16598 193 24x Fiche 50-440, 82/12/24.8212300051
- 8P12300013 Updates applicant 820724 response to interrogatory 3-4 of OH Citizens for Responsible Energy 820830 third set of interrogatories Svc list encl Related correspondence SWIGER, M A Shaw, Pittman, Potts & Troubridge. SWIGER, M A Cleveland Electric Illuminating Co 82/12/27 HIATT.S L Ohio Citizens for Responsible Energy 3pp 16578 824 24X Fiche 50-440, 82/12/27, 8212300013

- H General correspondence
- G212070015 Submits mgt changes effective B21201 DR Davidson to become senior vice president & MR Edelman to become vice president, nuclear group & staff contact for correspondence DAVIDSON, D R Cleveland Electric Illuminating Co B2/12/02 YOUNDBLOOD, B J Licensing Granch 1 ip 16327 243 24X Fisher 50-440, B2/12/02.B218070015
- B212200051 Requests that USGS evaluate risk of catastrophic explosion of propane leak from underground storage wells into Morton Salt Mine FSAR & FES deny possibility of event HIMBER.R M Affiliation Unknown B2/12/14 STEFANO, J J NR(No Detailed Affiliation Unven 2pp 16470 006 24X Fisher 50-440.82/12/14,8212200051
- --8212200058 Trip rept of 730912 site safety visit re specific features associated w/proposed site
 * Atomic Energy Commission 73/12/13 Atomic Energy Commission 3pp 16470 008 24X Fiche 50-440, 82/12/14, 82/200151
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8212020098 Amend 10 to FSAR W/629 oversize drawings Aperture cards are available in FDR

 * Cleveland Electric Illuminating Co 82/11/29 420pp 162/4 179 24X Fichs 50-440, 82/11/23, 8212020091
- M Antitrust correspondence
- GP12150012 Requests NRC review of Cleveland Electric Illuminating Co B21119 filling w/FERC for increase in rates for firm power syc Also requests NRC consideration of petition to intervene in matter PANDY. J Cleveland, OH 82/12/02 TOALSTON, A Antitrust & Economic Analysis Branch (Utility Finance) 37pp 16421 139 24X Fiche 50-000, 82/12/02.8212150012
- 8212220075 Forwards NRC 770625 itr to util transmitting 770625 order requiring util to file transmission svc tariff at FERC.per 811208 telron VOGLER, BH Hearing Branch 2 82/12/09 DAVIS,P Arnold & Porter 1p 16516 094 24X Fiche 50-440,82/12/09,8212220075
- @ Imagection reports. IE Bulletins & correspondence
- 87:08190240 IE Bulletin 82-03 flovision 1, "Stress Cracking in Thick-Wall: Large-Diameter: Stainless Steel, Rocirculation Bys Piping at BMF Plants "Svc list enc!

 UEYOUNG: R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 82/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Sefeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000,82/11/08,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl URRDAN.E.L. Division of Engineering & Quality Assurance 82/11/18, Consolidated Edison Co of New York, Inc. 109pp 16411 199 24X Fiche 50-000.82/11/18.8208190251
- 8208190256 IE info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list enc! BEYOUNG, R C Director's Office. Office of Inspection and Enforcement BEY11/26 Consolidated Edison Co of New York, Inc 127pp 16411.065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L 1 Division of Fuel Facilities. Naterials & Bafeguards B2/11/30. Consolidated Edison Co of New York. Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8212080019 Forwards NRR input to SALP rept for Oct 1981-Sept 1982 Overall rating of Category I given for licenses performance. STEFANO.J J Licensing Branch I 62/11/30 ETBENNUT, D 0 Division of Licensing 2pp 16367.169 24X Fiche 50-440,82/11/30, 8212080019
- BPOBI90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Syc list encl DEYBUNG.R.C Director's Dffice, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp. 18411 317. 24X Ficha 50-000,82/12/03,8208190259

- BP08190261 IE Info Notice 82-48, "Failures of Agestat CR 0095 Relay
- poglyddol iz info Multe B2-49, Frailores of Agastat Ex 0045 Relay Sockets " Svt list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 P4; Fiche 50-000: 82/12/03,8208190261
- 8212270412 Forwards IE Insp Repts 50-440/82-14 % 50-441/82-15 on 912290412 Powards IE 1989 Repts 30-440/82-15 & 30-441/82-15 on 828801-1031 No noncompliance noted KNDP.R C Division of Project & Resident Programs 82/12/15 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 16584 311 24X Fiche 50-440,82/12/15,8212290412
- electual le insp Repts 50-440/82-16 & 50-441/82-15 on 820801-1031 honcompliance noted Major areas inspected containment dome installation, shield bldg dome concrete placement, refueling bridge rail concrete placement & general housekeeping GILDNER, M. L. KONKLIN, J. E. Division of Project & Resident Programs 82/12/14 App. 16584-313 24X Fiche 50-440,82/12/15,8212290412 ~-8212270417 IE Insp Repts 50-440/82-15 & 50-441/82-15 on 820801-1031 No
- B20B190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Qas Monitoring " Svc list encl
 DEYOUND.R C Director's Office. Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 82/08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24) Fiche 50-000,82/12/20,8208190268
- S Reportable occurrences. LERs & related correspondence
- B212020395 Revised B20315 final deficiency rept re cladding fissures adjacent to weld seams in stainless steel suppression pools licems 2 & 3 of proposed corrective action deleted Placement of annulus concrete in pool region will reduce stress level DAVIDSON.D R Cleveland Electric Illuminating Co 82/11/24 REPPLER.J G Region 3, Office of Director 2pp 14278 258 24X Fiche 50-440.82/11/24.8212020395
- BP12170153 Supplemental final deficiency rept re-biological concrete shield walls Unit 1 repairs will not be completed until 830501 due to changes in const scheduling Unit 2 repairs on EDELMAN.M R Cleveland Electric Illuminating Co 82/12/10 KEPPLER.J O Region 3, Office of Director 1p 16450 225 24X Fiche 50-440, 82/12/10, 8212170153
- GP12170241 Revised final deficiency rept re defective Bettis Model 73 series actuation yokes on Henry Pratt Co valves Due to delay in receipt of replacement parts & const scheduling required ends not yet completed

 EDELMAN,M R Cleveland Electric Illuminating Co 82/12/10

 KEPPLER,J O Region 3. Office of Director 1p 16459 336

 Fiche 30-440, 82/12/10,8212170241 241
- 8212210370 Final deficiency rept re dowel counterbore in link rod in standby diesel engine Initially reported on 801008 Link rod inspected Deficiency determined not reportable per
- Inspected Deficiency describing to the control of t 82/12/10 244
- Bi:12280291 Final deficiency rept re potential defect in starting air tys check valve mfg by Transamerica Delaval Initially reported on 811218 Check valve disc assembly will be replaced by 830701 LDELMAN.M R Cleveland Electric Illuminating Ca 82/12/15 KEPPLER.J O Region 3. Office of Director 2pp 16560 102 24X fiche 50-440,82/12/15,8212280291
- DOCKET 50-443 SFARROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- GP12100102 FOIA request for nine categories of documents re GA program at Pacilities KINDER:ET New Hampshire, State of 82/10/27 Division of Rule, and Records 3pp 16388 094 24x Fiche 50-443,82/10/27,8212100102 Division of Rules
- 8212100105 Responds to FDIA request for nine categories of documents re GA program at facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
 FELTON J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire, State of ip t6388 097 24X Fiche 50-443, 82/11/18, B212100105

- --8212100109 Excerpt from FSAR to OA program corrective actions for design & const * Yankee Atomic Electric Co 86 Fiche 53-443.82/11/18,8212100105 82/11/18 2pp 16388 098 24Y
- --8212100112 Safety evaluation supporting approval of QA program contained in PSAR Chapter 17 Approval contingent upon applicant resolution of outstanding issues to supervision of QA activities during design & const phases

 * Atomic Energy Commission. Directorate of Licensing 74/08/14
 20pp 16388 100 24% Fiche 50-443,82/11/18,8212100105
- 8:12020286 Responds to open items reindependent safety engineering group charter (SRP 13 4 3. Licensee Qualification Branch)
 Revised FSAR Section 13 4 3 & Tech Spec 6 2 3 forwarded
 DEVINCENTIS. J Yantee Atomic Electric Co DEVINCENTIS. J Public
 Service Co of New Hampshire 82/11/23 KNIGHTON. G W Licensing
 Branch 3 4pp 16279 142 24X Fiche 50-443.82/11/23,8212020386
- --9212020316 Revised Tech Spec & 2 3 re independent safety engineering group function, composition, responsibilities & authority

 * Yankee Atomic Electric Co * Public Service Co of New
 Hampshire 82/11/23 lp 16279 146 24X Fiche 50-443,82/11/23,
 8212020286
- Bil2080545 Forwards "Control of Heavy Loads at Nuclear Power Plants, Seabrouk Units 1 & 2," draft technical evaluation rept, per util 820724 ltr Comments requested by 821216 Conference call uill be arranged to discuss resolution of open items KNIGHTON.G W Licensing Branch 3 82/11/23 TALLMAN, W C Public Service Co of New Hampshire 2pp 16370 157 24X Fiche 50-443,82/11/23,8212080545
- --8212080551 "Control of Heavy Loads at Nuclear Power Plants, Seabrook Units 1 & 2," draft technical evaluation rept JENSEN, S. A., STICKLEY, T. H. E000, Inc. 82/11/30 NRC No Detailed Affiliation Given 26pp 16370 159 24X Fiche 50-443, 82/11/23, 8212080545
- 0212020027 Forwards responses to Containment Sys Branch SRP open items re-containment purge sys Response will be included in OL application. Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Publi-Service Co of New Hampshire 82/11/26 KN10HTDN: G W Licensin Branch 3 4pp 16272 050 24% Fiche 50-443,82/11/26,8212020029
- 8712020334 Forwards "Tests of Anchorages to Determine Effects of 'Ig0200334 Forwards "lests of Anchorages to Determine Effects of Phyling," final rept.revising 820930 response to Mechanical Engineering Branch 820618 Request for Addl Info 210 7043RP 3 91 Rept uill be included in Amend 48 to OL application DEVINCENTIS. J Public DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hanpshire 82/11/26 KNIGHTON, 0 W Licensing Branch 3 2pp 16279 231 24% Fiche 50-443,82/11/26.8212020334
- --B21202033B "Tests of Anchorages to Determine Effects of Pruing." fin rept BURDETTE,E G Tennessee, Univ of 82/08/31 86pp 16279 233 24X Fiche 50-443,82/11/26.8212020334
- GP12030194 Summarizes caseload forecast panel 821116-17 plant tour & meeting w/RRC re status of const Picture of bridge B over ductwork 87-6 will be submitted by 821215 Supporting documentation & attendance list encl DEVINCENTIS.J Public Service Co of New Hampshire 82/11/29 RNIGHTON GW Licensing Branch 3 41pp 16304 044 24X Fiche 50-443.82/11/29,8212030194
- 8P12060075 Summarizes Effluent Treatment Sys & Radiological Assessment Branch Open Items II 5 2:11 5-1:12 3 2:12 5 2 1 5:12 3 4.per 521014 & 0917 meetings DEVINCENTIS, J Vankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/II/27 KNIGHTON G W Licensing Branch 3 12pp 16316 055 24% Fiche 50-443-82/II/29,82120600/b
- 8P12060036 Forwards second revision to Reactor Sys Branch 820212 request for add1 into the containment sump design & effect on long-term cooling following LOCA Response will be included in Amend 48 to OL application Syc list encl
 DEVINCENTIS, J Yankes Atomic Electric Co DEVINCENTIS, J Publi Service Co of New Hampshire 82/11/30 KNIGHTON, GW Licensin Branch 3 App 16314 014 24X Fiche 50-443,82/11/30,8212060036
- BR12060074 Forwards revised response to Chemical Engineering Branch B20212 request for addl info re NUREO-0737. Item II B 3, "Post-Accident Sampling Sys " Info will be provided in OL application Amend 49 DEVINCENTIS.J Vankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hampshire 82/12/01 KNIGHTON.O W Licensing Branch 3 22pp 14315 001 24% Fiche 50-443,82/12/01.8212060074

- B212060151 Forwards three photographs of SF6 ductwork & bridges per L Wheeler request during B21116-17 site tour DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire B2/12/01 KN16HTDN. 6 W Licensing Branch 3 Spp 16313 140 24X Fiche 50-443.82/12/01.8212060151
- 87:2070100 Provides revised schedule for completion of facilities
 Fuel load scheduled for Sept 1984 for Unit I & Dec 1984 for
 Unit 2 Commercial operation should begin in Dec 1986 for
 Unit 1 & Mar 1987 for Unit 2 Press release encl
 BEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Publis
 Service Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing
 Branch 3 5pp 16327 272 24X Fiche 50-443,82/12/02,8212070100
- 8212080224 Submits responses to Chemical Engineering Branch open items Addl info on secondary water chemistry requested to complete review DEVINCENTIS. J. Yankes Atomic Flectric Co. DEVINCENTIS. J. Public
 - review DEVINCENTIS, J Yankom Atomic Electric Co DEVINCENTIS, J Public Gervice Co of New Hampshire 82/12/02 KNIGHTON, G W Licensing Branch 3 15pp 16354 092 24X Fiche 50-443,82/12/02,8212080224
- 8212080190 Forwards info omitted from 820930 response to Mechanical Engineering Branch 820618 request for add1 info re tees or branch connections in Class i piping DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KN19HTON.O W Licensin Branch 3 4pp 16354 096 24X Fiche 50-443.82/12/03.8212080190
- GP12080207 Agrees to modify Teth Spec surveillance requirements for chargency feedwater sys DEVINCENTIS. J Public Service Co of New Hampshire 82/12/03 KNIGHTON, 9 W Licensing Beanch 3 2pp 16354-005 24X Fiche 50-443.82/12/03.8212080207
- B212080860 Natification of contract execution. Mod 2 to "Follow on Review of Beabrook Nuclear Station, Units 1 & 2 " Contractor Fugro, Inc SILVIS: R M Technical Assistance Contracts Branch Fin B-682/82/12/03 DENTON: H R Office of Nuclear Reactor Regulation, Director JACKSON, R E NRC NO Detailed Affiliation Given 1p 16368 353 24X Fiche 50-443.82/12/03.8212080560
- --8212080568 Hod 2.deobligating funds, to "Follow on Review of Seabrook Nuclear Station, Units 1 & 2" MADSEM, 8 H Fugro, Inc GUBTAVE, R P Technical Assistance Contracts Branch FIN B-6827 82/12/03 1p 16368 354 24X Fichs 50-443, 82/12/03, 8212080560
- 6212090498 Forwards supplemental response to Reactor Sys Branch 620212 & 0426 Requests for Addl Info 440 89 & 440 127 re locked rotor event Info will be included in OL application. Amend 48.

 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of Neu Hampshire 82/12/07 KNIGHTON. W Licensing Branch 3 3pp 16365 332 24% Fiche 50-443, 82/12/07, 8212090498
- 8212140235 Forwards revision to FSAR in response to open item identified by D Powers of Containment Sys Branch Revision to be included in QL application, Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNIGHTON O W Licensing Branch 3 3pp 16408 352 24X Fiche 50-443,82/12/08,8212140235
- 8212270279 Forwards "Tost Rept on Emergency Spray Bys Testing Using Transco Therma-Wrap," in response to NRC 821203 request for add inforce RCS thermal insulation Transco insulation aimost identical to Quent-Corning insulation DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNICHTON, 0 W Licensing Branch 3 2pp 16530 284 24% Fiche 50-443,82/12/08,8212270279
- ~~8212270281 "Test Repts on Emergency Spray Bys Testing Using Transco Therma-Wrap" * Transco. Inc. TTR-28N 82/07/27 3pp 16530 286 24X Fiche 50-443.82/12/08.8212270279
- --9212270286 "Transco Flexible Therma-Wrap Blanket Type Insulation " * Transco, Inc 82/05/04 5pp 16530 287 24X Fiche 50-443,82/12/08,8212270279
- --B212270289 Topical rept evaluation of OCF-1. "Nuclear Containment Insulation Sys " Rept acceptable. * NRC - No Detailed Affiliation Given 82/12/08 13pp 16530 297 24X Fiche: 50-443, 82/12/08.8212270279
- 8212270188 Responds to Core Performance Branch open items in safety review re cladding collapse.ECCS calculations & conformance w/App A of SRP Section 4 2 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/20 KNIGHTON, OW Licensing Branch 3 9pp 16539 270 24X Fiche 50-443,82/12/20,8212270188

- 8P12270146 Forwards draft revised FSAR Section 17 2, "GA During Upgrations Phase." in response to GA Branch request Section will be included in Amend 43 of OL application DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTON.0 W Operating Reactors Branch 3 61pp 16538-067 24X Fiche 50-443,82/12/21,82(270144)
- 8212270270 Informs that FSAR Section 4 2 2 3 a re rod cluster assembly revised per SRP 4 2 Encl revised page will be included in Amend 48 to OL application DEVINCENTIS, J Yankes Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTON, G W Licensing Branch 3 2pp 16530 311 24X Fiche 50-443,82/12/21.8212270270
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 8P12060068 Submits supplemental info re use of steel H-frame structures along Newington transmission line right-of-way per FES Installation of H-frames w/less bulk reduces visual impact & minimizes environ impact DEVINCENTIS. J Public Service Co of New Hampshire 82/12/01 KNIGHTON. G W Licensing Branch 3 Spp 16316 079 24X Fiche 50-443, 82/12/01.8212060068
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- GP12010375 Bummary of B21019-1029 meetings w/util re open items in safety review & safety requirements remaining to be met prior to BER issuance WHEELER,L Licensing Branch 3 B2/11/08 Licensing Branch 3 2p 16267 170 24X Fiche 50-443,62/11/08,8212010375
- --8211040225 Notification of 621017-1130 meetings w/util in Bethesda. Hb to discuss remaining open items in safety review WHEELER. L. Licensing Branch 3 62/10/14 KERRIGAN, J.D. Licensing Branch 3 2pp 16267 172 24X Fiche 50-443, 82/11/08. 8212010375
- BP:12100105 Responds to FDIA request for nine categories of documents to GA program at facilities Forwards safety evaluation & excerpt from FBAR & Buppl 3 to SER 4td 750314 FELTON.J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire. State of 1p 16388 097 24% Fiche 50-443.82/11/18.
- --8212100114 Suppl 3 to SER supporting approval of GA program contained in PSAR Chapter 17 Resolution of outstanding issues re review & approval of contractor GA procedures & manuals verified in 741106 insp. rept # Atomic Energy Commission, Directorate of Licensing 75/03/14 3pp 16388 120 24X Fishe 50-443,82/11/18-8212100105
- BR12040059 Submits addI design changes to emergency feedwater sys per SER Startup feedwater pump circuit breaker installed in alternate electrical supply cubicle on emergency electrical bus E5 Changes will be incorporated into FBAR revision DEVINCENTIS. J. Public Service Co of New Hampshire 82/11/30 KNIGHTON. 6 W. Licensing Branch 3 3pp 16314 077 24X Fiche 50-443. 82/11/30, 8212060059
- F Security, medical, emergency & fire protection plans
- BP12080163 Forwards summary info on primary & alternate emergency operations facilities per L Wheeler request DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Sarvice Co of New Hampshire 62/12/03 KN10HTON, O W Licensing Branch 3 3pp. 16354 085 24X Fiche 50-443,82/12/03,8212080163
- Adjudicatory correspondence
- 82:120:10385 Forwards response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
 PERLIS:R 0 Hearing Branch 3, 82:11/23 BACKUS,R A Backus, R A ig 16271 087 24% Fishe 50-443.82/11/23.82:2010:385
- --8212010387 Responds to Seacoast Anti-Pollution League first set of Interrogatories & request for production of documents * Commissioners 82/11/23 Seacoast Anti-Pollution League 3pp 16271.088 24% Fiche 50-443.82/11/23,8212010385
- --8212010376 Affidavit of MC Thadani re NRC response to Sescoast Anti-Follution League first set of interrogatories & request for production of documents THADANI,M C Division of Licensing 62/11/23 lp 16271:091 24% Fiche 50-443.82/11/23.8212010385

- B212020323 Forwards NRC response to State of NH first set of interrogatories & request for production of documents PERLIS, R G Hearing Branch 3 82/11/30 KINDER, E T New Hampshire: State of 1p 16279 164 24X Fiche 50-443,82/11/30,8212020323
- --B2[2020326 Response to first set of interrogatories & request for production of documents
 PERLIS.R 9. LESSY.R P. Hearing Branch 3. B2/11/30. New Hampshire. State of 29pp 16279 165. 24X Fiche 50-443.82/11/30, 8212020323
- Origo70242 Request for clarification of ASLB 820713 memorandum & order representation of contentions on offsite emergency planning Time for resubmission unclear Certificate of Svc enc!

 SHOTMELL, J A Massachusetts, State of 82/11/30 Atomic Safety and Licensing Board Panel App 16327 292 24X 1 iche 50-443, 82/11/30, 8212070242
- 89:12030163 Advises that NRC will take no position on State of NH 821115 motion to compel util answers to first set of interrogatories
 PERLIS.R O Hearing Branch 3 82/12/01 HDYT.H , LUEBKE.E A ,
 HARBOUR.J Atomic Safety and Licensing Board Panel 2pp
 16306 013 24x Fichs 50-443,82/12/01,8212030163
- EPI20A0020 Confirms 821201 telcon from Judge Hoyt Parties invited to B21210 tour w/Judge Prehearing conference scheduled for B30111 to be rescheduled AVallability of FEMA representative at next prehearing conference uncertain LEGSY.R P Hearing Branch 3 82/12/02 HOYT.H LUEBKE.E A AHARBOUNJ Atomic Safety and Licensing Board Panel 2pp 16313 298 24X Fiche 50-443, 82/12/02, 8212060020
- OXIZ140212 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence DIGNAN.T 0. GAD.R K. Public Service Co. of New Hampshire DIGNAN.T 0. Ropes & Gray. 92/12/08 — Coastal Chamber of Commerce of New Hampshire. 110pp. 16406-153 — 24X Fiche 50-443,82/12/08. 0212140212
- BP12140217 Interrogatories & request for production of documents Cartificate of 8vc encl Related correspondence BIONAN.T G. GAD.R K. Public Service Co of New Hampshire BIONAN.T G. Ropes & Gray 82/12/08 Seacoast Anti-Pollution League 108pp 16406 307 24X Fiche 50-443,82/12/08.8212140217
- SP12140430 Interrogatories & request for production of documents Certificate of Svc enci Related correspondence NIGNAM. T G . GAD, R K Public Service Co of New Hampshire DIONAM. T G . Ropes & Gray 82/12/08 New Hampshire, State of 110pp 16405 031 24X Fiche 50-443, 82/12/08, 8212140430
- BP12140441 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence DIONANI, TO , QAD.R K Public Service Co of New Hampshire DICNANI, TO Ropes & Gray B2/12/08 New England Coalition on Nuclear Pollution 111pp 16404 063 24X Fiche 50-443, 82/12/08, B212140441
- BP12140227 Motion to file responsive pleading re State of NH motion to compel answers to first set of interrogatories to util Certificate of Svc encl Related correspondence MINDER.E T New Hampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel 3pp 16408 343 24% Fiche 50-443,82/12/09,8212140227
- 82:12140234 Withdrawal of motion to compel answers to interrogatories & response to applicant answer interrogatories 9 6.9 16 & 10 2 withdrawn Util should answer 9 1.9 8 & 10 1 & SAPL 3 7.3 10 & 3 11 W/Certificate of Svc Related correspondence KINDER, E T New Hampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel Spp 16408 346 24X Fiche 50-443,82/12/09, 9212140234
- 8212140426 Motion for continuance of discovery deadline to 830601 Continuance fair in light of rescheduling of projected fuel loading dates Previous deadline burdensome & would impede litigation of intervenor contention Related correspondence BACKUS,R A Sescost Anti-Pollution League BACKUS,R A Backus, R A 82/12/09 Atomic Safety and Licensing Seard Panel 2pp 16404 174 24X Fiche 50-443,82/12/09.8212140426
- --B212140437 Advises of results of const scheduling study Study indicates 10-month slippage, changing projected fuel loading dates for Unit 1 to Sept 1984 & Unit 2 to Dec 1986 Svc list encl.
 DIGNAM.T O Ropes & Gray DIGNAM.T O Public Service Co of Now Hampshire 82/11/30 HOYT.H., LUEBKE, E A., HARBOUR, J Atomic Safety and Licensing Soard Pamel 2pp 16404 176. 24X Fiche 50-443,82/12/09.8212140426

- 8212160281 Motion to extend time until 830315 for discovery on admitted contentions Present schedule does not allow sufficient time to complete requests Certificate of 8vc enc1 Related correspondence KINDER, ET. BISBES, GD New Hampshire, State of 82/12/13 Atomic Safety and Licensing Board Panel 6pp 16446 058 24X Fiche 50-443, 82/12/13, 8212160281
- B212160321 Responses to interrogatories & requests for document production Svc list encl Related correspondence DDUGHTY. J Searcast Anti-Pollution League B2/12/13 Office of the Executive Legal Director Spp 16442 332 24X Fiche 50-443, 82/12/13, 8212160321
- 8212200039 Forwards motion for extension of time for discovery & LL Bishop notice of appearance CURRAN, D. Harmon & Weiss CURRAN, D. New England Coalition on Nuclear Pollution 82/12/15 HDYT, H. F., LUEBKE, E. A., HARBDUR, J. Atomic Safety and ticensing Board Panel 1p. 16474 255 24X Fiche 50-443, 82/12/15,8212200039
- --B212200049 Motion for extension of time for discovery until 830315
 Sheer vol of math to be processed to prepare or answer
 interrogatories on large number of complex technical issues
 makes compliance impossible Certificate of Svc encl
 CURRAN.D r. BISHOP.L. L. New England Coalition on Nuclear Pollution
 CURRAN.D Harmon & Weiss B2/12/15 Atomic Safety and
 Licensing Board Panel Spp 16474 256 24X Fiche S0-443,
 82/12/15.8212200039
- 8212220255 Amended answer to State of NH Interrogatory 9 8 Certificate of 8vc encl DIGNAN.T G. GAD.R K Public Service Co of New Hampshire DIGNAN.T G Ropes & Gray 62/12/15 New Hampshire. State of 4pp 16518 GO1 24X Fiche 50-443.82/12/15.8212220255
- 8212230346 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence KINDER,E T. 818888,0 D. New Hampshire. State of 82/12/15 Office of the Executive Legal Director 14pp 16505 162 24X (1chs 50-443,82/12/15,8212230346
- 8:12230348 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence KINDER.E T . BISBER 0 D New Hampshire. State of 82/12/15 Public Service Co of New Hampshire 24pp [6511 240 24X Fiche 90-443,82/12/15,8212230348
- G212200079 Motion for continuance of G21215 deadline for discovery until G30601 Burden of short discovery period & re-election campaign precluded submittal of documents in timely manner five list encil HGLL1/16/HGRTH, B Coastel Chamber of Commerce of Naw Hampshire G2/12/16 Atomic Gafety and Licensing Board Panel Sapp 16474 306 24x Fiche 50-443.82/12/16.6212200079
- 8212210228 Answers to second set of interrogatories & request for production of documents on Contentions I A 2.I B 1.I B 2 & 1 C & motion for protective order Centificate of Svc encl DIONAN.T G . ADD.R K Public Service Co of New Hampshire DIGNAN.T G Ropes & Gray 92/12/16 New England Coalition on Nuclear Pollution 71pp 16484 001 24% Fiche 50-443.82/12/16.8212210228
- 8212230334 Second set of interrogatories & request for production of documents Svc list encl Related correspondence BACKUS,R A Backus, R A Backus, R A Backus, R A BACKUS,R A Backus, R A BACKUS, B A
- 8212230203 Order admitting Towns of Brentwood & Hampton, NH as interested municipalities List of admitted contentions enc!
 HOYT, H F Atomic Safety and Licensing Board Panel 82/12/20
 Brentwood, NK 10pp 16510 270 24X Fiche 50-443, 82/12/20, 8212230203
- 8212270208 Memorandum & order ruling on State of NH 821115 motion to compel applicants to answer first set of interrogatories. Applicants must identify persons w/supervisory capacity for control from design & installation HOYT, H F Atomic Safety and Licensing Board Panel 82/12/22 Public Service Co. of New Hampshire App 16534 356. 24X Fiche 50-443, 62/12/22,6212270208
- 8212280017 Advises that NRC will not take position re applicant 821217 motion for protective order for New England Coalition on Nuclear Pollution Interrogatory & Dispute is between applicant & intervenor PERLIB.R 9 Hearing Branch 3. 82/12/23 HOYT.H , LUEBKE.E A . HARBOUR.J Atomic Safety and Licensing Board Panel 1p 16564 288 24% Fiche 50-443.82/12/23,8212280017

- 8212270270 Response to first set of interrogatories & request for documents on Contentions I A 2, I, V. II B 1-5. II C. II D. II F. II G. II B II L II N Affidavits & Certificate of Svc
 - LEGSY,R P Hearings Division 82/12/28 New England Coalition on Nuclear Pollution 100pp 16581 115 24% Fiche 50-449,82/12/28, 8212280290

M Antitrust correspondence

- Bil2080527 Forwards notice of receipt of antitrust info w/recent application for OL Notice to be published in FR.Electric light & Power, Public Utils Forthnightly & Rural Liectrification, trade journals KNIGHTON, O W Licensing Branch 3 82/11/29 TALLHAN, W C Public Service Co of New Hampshire 2pp 16370 191 24X Fiche 50-443, 82/11/29, 8212080527
- --8212080532 Notice of receipt of antitrust info Requests for reevaluation & addl info must be received by 830107 KNIGHTON, G W. Licensing Branch 3 82/11/29 2pp 16370 193 244 Fiche 50-443.82/11/29.8212080527

O Inspection reports. IE Bulletins & correspondence

- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking im Thick-Wall-Large-Diameter, Stainless Steel. Recirculation Sys Piping at BNR Plants " Svc list entl DEYGUNO. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 143 24% Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!
- onci
 LOBBL I Division of Fuel Facilities, Materials & Sefeguards
 02/11/05 Consolidated Edison Co of New York, Inc 110pp
 14372 142 24% Fiche 50-000,82/11/05,8208170245
- 8/08190251 [É Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl UGRDANE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24 Fiche 50-000, 82/11/18, 8208190281
- 8:08:90256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocis" Svc 1ist entl DEYOUND.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBS.L I Division of Fuel Facilities, Materials & Safeguards 827/17/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 870B190259 (E Bultetin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYBUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113ps 16411 317 24X Fichs 50-000,82/12/03.8208190259
- 8208190261 IE info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svr list encl JORDAN, EL Division of Engineering & Quality Assurance, 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8212080321 Ack receipt of 821117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-10 & 50-444/82-10
 - STARDSTECKI.R Division of Froject & Resident Programs 82/12/03 TALLHAN, U.C. Public Service Co. of New Hampshire 1p 16353-337 P4X Fiche S0-443.82/12/03.8212080321
- --B212080329 Responds to NRC 821020 ltr re violations noted in 1E Insp Repts 50-443/82-10 & 50-444/82-10 Corrective actions technical procedure sessed to resolve clearance problems & drawing revised to indicate required bolt & nut matl DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/17 STARROSTECKI. R Devision of Project & Resident Programs 4pp. 16353 338 24% Fiche 50-443,82/12/03.8212080321
- 8212210270 Forwards IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 & notice of violation STAROBTECKIR, Division of Project & Resident Programs 82/12/06 TALLMAN, U.C. Public Service Co. of New Hampshire 2pp 16483 035, 24X Fiche 50-443,82/12/06,8212210270

- --8212210275 Notice of violation from insp on 821001-1105 * Division of Project & Resident Programs 82/12/04 [p 16483 037 24X Fishe 80-443,82/12/06.8212210270
- --B212210282 IE Insp Repts 50-443/82-13 & 50-444/82-11 on 821001-1105 Noncompliance noted failure to conduct & document insp of pipe support Kwik-bolting activities per procedural hold-point requirements

 CERNE, A C . GRAMM.R A . GALLO.R M Division of Project & Resident Programs 82/11/17 9pp 16483 038 24X Fiche 50-443,82/12/06,8212210270
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16.8208190267
- BROBI9026B IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 1662B 293 24x Fiche: 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

- 5212060079 PND-I-82-075 on \$21201, util announced 10-month delay & new commercial operation dates for Unit 1 (\$21231) & Unit 2 (\$70331) projected Total cost revised by 44% Caused by increased design & engineering complexity KELLY.E. GALLO,R., GREENMAN.E. Region I. Office of Director 82/12/01 2pp 16314 342 24% Fiche 50-443,82/12/01,8212060079
- GP12210287 Final deficiency rept re seat leakage in ASCO solenoid valves mounted on Posi-Seal Intl butterfly valves Initially reported on B21103 Posi-Seal Intl supplied relubrication kits to correct problem DEVINCENTIS. J Yankee Atamic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/12/08 STARDSTECKI. R Division of Project & Resident Programs 3pc 16497 039 24% Fiche: 50-443, 82/12/08, 8212210287
- 8212210273 Enterim deficiency rept re adequacy of tornado missile shield protection on north to west walls of fuel storage bldg Initially reported on 82110 Engineering evaluation results will be reported by 830401 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STARDSTECKI, R Division of Project & Resident Programs 2pp 16483 233 24X Fiche 50-443,82/12/14,8212210273
- 8212210447 Interim deficiency rept re potential for pipe & component overstress due to exceeding pipe pulling limits during welding fit-up Initially reported on 821110 Nonconformance rept dispositioned to rework complete Next rept by 830715 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire 82/12/14 STAROSTECKI. R Division of Project & Resident Programs 3pp 16489 178 24X Fiche 50-443, 82/12/14, 8212210449

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- BP12100102 FOIA request for nine categories of documents re GA program at facilities. KINDER: T New Hampshire, State of B2/10/27 Division of Rules and Records 3pp 16388 094 24X Fiche 50-443,82/10/27,8212100102
- 8212100105 Responds to FOIA request for nine categories of documents re GA program at facilities Forwards safety evaluation & excerpt from FARR & BUPPI 3 to 8ER dtd 750314 FELTON, J M Division of Rules and Records 82/11/18 KINDER, E T New Hampshire, State of 1p 14388 097 24% Fichs 50-443, 82/11/18, 82/2100105
- --8212100109 Excerpt from FSAR re QA program corrective actions for design \$\(\text{const} \) const + Yankes Atomic Electric Co \(\text{B2} / 1 \text{11} / 18 \) 2pp \quad \(16388 \) 098 \quad 24X \quad \(\text{Fiche 50-443.82} / 11 / 18 \) 8212100105
- --8212100112 Bafety evaluation supporting approval of QA program contained in FBAR Chapter 17 Approval contingent upon applicant resolution of outstanding issues re supervision of QA activities during design & const phases # Atomic Energy Commission, Directorate of Licensing, 74/08/14 20pp 16388 100 24X Pichs 50-443.82/11/16,8212100105

- 8212020286 Responds to open items re independent safety engineering group charter (SRP 13 4 3.Licensee Gualification Branch)
 Revised FSAR Section 13 4 3 & Tech Spec 6 2 3 forwarded DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/23 KNIGHTON G W Licensing Branch 3 4pp 16279 142 24X Fiche 50-443,82/11/23,8212020286
- --8212020316 Revised Tech Spec 6 2 3 re independent safety engineering group function.composition.responsibilities & authority * Yankee Atomic Electric Co * Public Service Co of New Hampshire 82/11/23 1p 16279 146 24X Fiche 50-443.82/11/23.8212020286
- 8212080545 Forwards "Control of Heavy Loads at Nuclear Power Plants.

 Seabrook Units I & 2." draft technical avaluation rept, per
 util 820724 itr Comments requested by 821216 Conference call
 will be arranged to discuss resolution of open items
 KNIGHTON, O W Licensing Branch 3 82/11/23 TALLMAN, H C Public
 Service Co of New Hampshire 2pp 16370 197 24X

 Fiche 50-443, 82/11/23, 8212080545
- --B212080551 "Control of Heavy Loads at Nuclear Power Plants, Seabronk Units 1 & 2." draft technical evaluation rept JENSEN, 8 A. STICKLEY, TH. EGGO, Inc. 82/11/30 NRC No Detailed Affiliation Given 26pp 16370.159 24X Fichs 50-443, 82/11/23, 82(2080545
- 8212020029 Forwards responses to Containment Sys Branch SRP open items re containment purge sys Response will be included in OL application, Amend 48 DEVINGENTIS, J. Ventee Atomic Electric Co DEVINGENTIS, J. Public Service Co of New Hampshire 82/11/26 KNIOHTON, O.W. Licensing Branch 3 4pp 16272 050 24% Fichs 50-440, 82/11/26, 8212020029
- 8212020334 Forwards "Tests of Anchorages to Determine Effects of Prying," final rept.revising 820930 response to Mechanical Engineering Branch 820618 Request for Add1 Info 210 70(8RP 3 9) Rept will be included in Amend 48 to GL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/11/26 KN10HTUN, 0 W Licensing Branch 3 2pp 16279 231 24% Fiche 50-440382/11/26.8212020334
- --B212020338 "Tests of Anchorages to Determine Effects of Prying," final rept
 BURDETTE, E 9 Tennessee, Univ of 82/08/31 84pp 16277 233
 24X Fiche 50-443,82/11/26,8212020334
- 8212030194 Summarizes caseload forecast panel 821116-17 plant tour & meeting w/RRC re status of const Picture of bridge 8 over ductwork 8F-6 will be submitted by 821215 Supporting documentation & attendance list encl DEVINCENTIS.J. Public Service Co of New Hampshire 82/11/29 KNIOHTUN.O W Licensing Branch 3 Alpp 16304 044 24X Fiche 50-443,82/11/29.8212030194
- 8212060075 Summarizes Effluent Treatment Sys & Radiological Assessment Branch Open Items ii 5 2,11 5-1,12 3 2,12 5 2 1 & 12 3 4,per 821014 & 0917 meetings DEVINCENTIB, J. Public Service Co of New Hampshire 82/11/29 KNIGHTON, G W Licensing Branch 3 12pp 16316 055 24X Fiche 50-443,82/11/29,8212060075.
- 8212060056 Forwards second revision to Reactor Sys Branch #20212 request for add1 info re containment sump design & effect on long-term cooling following LOCA Response will be included in Amend 48 to OL application Svc list encl.
 DEVINCENTIS, J Yankee Atomic Electric Co. DEVINCENTIS, J Public Service Co of New Hampshire 82/11/30 KN70HTON, OW. Licensing Branch 3 6pp 16314 014 24X Fiche 50-443,82/11/30,8212060056
- B212060094 Forwards revised response to Chemical Engineering Branch
 B20212 request for add1 info re NUREO-0737, Item II 8 3,
 "Post-Accident Sampling 8ys " Info will be provided in
 OL application. Amend 48
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 82/12/01 KNIGHTON, 0 W Licensing
 Branch 3 22pp 16315 001 24X Fichs 50-443, 82/12/01, 8212040094
- 8212060151 Forwards three photographs of SF6 ductwork & bridges per L Wheeler request during 821116-17 sits tour. DEVINCENTIS, J Yankse Atomic Electric Co. DEVINCENTIS, J Public Service Co of New Hampshire 82/12/01 KNIOHTON, 0 W Licensing Branch 3 5pp 16313 140 24X Fiche 50-443,82/12/01.8212060151
- 8212070100 Provides revised schedule for completion of facilities
 Fuel load scheduled for Sept 1984 for Unit 1 & Dec 1984 for
 Unit 2 Commercial operation should begin in Dec 1986 for
 Unit 1 & Har 1987 for Unit 2 Press release enci
 DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIB, J. Public
 Service Co. of New Hampshire 82/12/02 KNIGHTON, 0 W. Licensin,
 Branch 3. 5pp 16327 272, 24X Fiche 50-443,82/12/02,8212070100

- B212080224 Submits responses to Chemical Engineering Branch open items Addl info on secondary water chemistry requested to complete review DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co of New Hampshire B2/12/02 KNIGHTON, G W Licensing Branch 3 15pp 16354 072 24X Fiche 50-443.82/12/02.8212080224
- B212080190 Forwards info omitted from 820930 response to Mechanical Engineering Branch 820618 request for addl info re tees or branch connections in Class i piping DEVINCENTIS.J Yankse Atomic Electric Co DEVINCENTIS.J Fublic Service Co of New Hampshire 82/12/03 KNIGHTON.OW Licensing Branch 3 4pp 16354 056 24x Fiche 50-443.82/12/03.8212080190
- 8212080207 Agrees to modify Tech Spec surveillance requirements for emergency feedwater sys
 DEVINCENTIS, J. Public Service Co. of New Hampshire 82/12/03
 KNIGHTON, G.W. Licensting Branch J. 2pp. 14394 005 24X
 Fichs 50-443
- B212080560 Notification of contract execution.Mod 2 to "Follow on Review of Seabrook Nuclear Station.Units 1 & 2 " Contractor Fugro.Inc SILVIS.R M Technical Assistance Contracts Branch FIN 8-682/82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director JACKSON.R E NRC No Detailed Affiliation Given Ip 16368 353 24% Fiche 50-443.82/12/03.8212080540
- --8212080568 Mod 2.deobligating funds to "Follow on Review of Seabrook Nuclear Station Units 1 & 2 " MADEEN B H Fugro. Inc OUBTAVE R F Technical Assistance Contracts Branch FIN B-6827 82/12/03 ip 16368 354 24X Fiche 50-443,82/12/03.8212080560
- 8212090498 Forwards supplemental response to Reactor Sys Branch 820912 & 0426 Requests for Addl Jafo 440 89 & 440 127 re locked rotor event Info will be included in OL application. Amend 48
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/07 KNIGHTON. 6 W Licensing Branch 3 3pp 16365 332 24X Fiche 50-443,82/12/07.0212090490
- 8212140235 Forwards revision to FSAR in response to open atem identified by D Powers of Containment Sys Branch Revision to be included in OL application. Amend 4B DEVINCENTIS, J Yankse Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 KNICHTON, OW Licensing Branch 3 3pp 14408 352 24X Fiche 50-443, 82/12/08, 8212140235
- B212270279 Forwards "Test Rept on Emergency Spray Sys Testing Using Transco Therma-Weap." in response to NRC B21203 request for add1 info re RCS thermal insulation Transco insulation almost identical to Owens-Corning Insulation DEVINCENTIS.J Yankee Atomic Electric Co DEVINCENTIS.J Public Service Co of New Hangshire B2/12/08 KNIOHTON.G W Licensing Branch 3 2pp 14530 284. 24X Fiche 50-443.82/12/08.8212270279
- --B212270281 "Test Repts on Emergency Spray Bys Testing Using Transco Therma-Wrap " * Transco, Inc TTR-25N 82/07/27 3pp 16530 286 24X Fiche 50-443,82/12/08,8212270279
- --8212270286 "Transco Flexible Therma-Wrap Blanket Type Insulation "
 * Transco, Inc. 82/05/04 5pp. 16530 287 24X
 Fiche 50-443,82/12/08,8212270279.
- 82:227018B Responds to Core Performance Branch open items in safety review re cladding collapse.ECCS calculations & conformance w/App A of SRP Section 4.2

 DEVINCENTIS, J Vankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire B2/12/20 KNIGHTON, 0 W Litencang Branch 3 9pp 16539.290 24X Fiche 50-443.82/12/20.821227019B
- 8212270146 Forwards draft revised FSAR Section 1/ 2, "GA During Operations Phase." in response to GA Branch request Section will be included in Amend 43 of OL application DEVINCENTIS, J Yanke Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire B2/12/2), KNIGHTON, Q H Operating Reactors Branch 3 61pp 16538 067 24X Fiche 50-443, 82/12/21, 8212270146
- BRI2R70270 Informs that FBAR Section 4 2 2 3 a re rod cluster assembly revised per SRP 4 2 Encl revised page will be included in Amend 48 to OL application

 DEVINCENTIS, J Yantes Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/21 KNIGHTUN, Q W Licensing Branch 3. 2pp 16530 311 24X Fiche 50-443,82/12/21,8212270270

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- B21206006B Submits supplemental info re use of steel H-frame structures along Newington transmission line right-of-way per FEB Installation of H-frames w/less bulk reduces visual impact Installation of K-rrames wiles but & mainistes environ inpact DEVINCENTIS. J Public Service Co ENIGHTON. O W Licensing Branch 3 Fiche 50-443.82/12/01.8212040068 from impact
 Public Service Co of New Hampshire, 82/12/01
 Licensing Branch_3 5pp 16316 079 24X
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- B212010375 Summary of B21019-1029 meetings w/util re open items in safety review & safety requirements remaining to be met prior to SER issuance WHEELER.L Licensing Branch 3 82/11/08 Licensing Branch 3 2pg 16267 170 24% Fiche 50-443,82/11/08,8212010375 WHEEL FR. I
- --B211040225 Notification of 821019-1130 meetings w/util in Bethesda, MD The discuss remaining open items in safety review

 HHEELER.L L. Licensing Branch 3 82/10/14 KERRIGAN, J D

 Licensing Branch 3 2pp 16267 172 24X Fiche 50-443, 82/11/08,
 8212010375
- 8212100105 Responds to FDIA request for nine categories of documents re GA program at facilities Forwards safety evaluation & excerpt from FSAR & Suppl 3 to SER dtd 750314
 FELTON, J M Division of Rules and Records 82/11/18 KINDER, E T
 New Hampshire, State of 1p 16388 097 24% Fichs 50-443,82/11/18,8212100105
- --BR12100114 Suppl 3 to SER supporting approval of GA program contained in PSAR Chapter 17 Resolution of outstanding issues re review & approval of contractor GA procedures & manuals verified in 74106 insp rept

 * Atomic Energy Commission, Directorate of Licensing 75/03/14

 3pp 16388 120 24X Fiche 50-443.82/11/18.8212100105
- 8212060057 Submits add1 design changes to emergency feedwater sys per SER Startup feedwater pump circuit breaker installed in alternate electrical supply cublicle on emergency electrical bus ES Changes will be encorporated into FBAR revision DEVINCENTIS, J. Public Service Co. of New Hampshire 82/11/30 KNIGHTON-0 W. Licensing Branch 3. 3pp. 16314-077 24x Fishe 50-443.82/11/30.8212060059
- F Security, medical, emergency & fire protection plans
- 8212080163 Forwards summary info on primary & alternate emergency operations facilities per L Wheeler request DEVINCENTIS, J Public Service Co of New Hampshire 82/12/03 KNIGHTON, 0 W Licensing Branch 3 3pp 16354 095 24X Fiche 50-443,82/12/03.8212080163
- O Adjudicatory correspondence
- 8212010385 Forwards response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents
 PERLIS.R O Hearing Branch 3 82/11/23 BACKUS.R A Backus.RA
 1p 16271 087 24X Fichs 50-443.82/11/23,8212010385
- --8212010389 Responds to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents secommissioners, 82/11/23 Seacoast Anti-Pollution League 3pp 16271 088 24x Fiche 50-443.82/11/23.8212010385
- --8212010396 Affidavit of MC Thadami re NRC response to Seacoast Anti-Pollution League first set of interrogatories & request for production of documents THADANIAM C Division of Licensing 82/11/23 10 16271 091 24X Fiche 50-443,82/11/23,8212010385
- BR12020323 Forwards NRC response to State of NH first set of interrogatories & request for production of documents. PERLIB.R G Hearing Branch 3 82/11/30 KINDER.E T New Hampshire. State of ip 14279 144 24X Fiche 50-443.82/11/30, 8212020323
- --8212020326 Response to first set of interrogatories & request for production of documents
 PERLIS.R G., LESEY.R P Hearing Branch 3 82/11/30 New Hampshire. State of 29pp 16279 165 24X Fiche 50-443.82/11/30.8212020323

- 8212070242 Request for clarification of ASLB 820913 memorandum & order re resubmission of contentions on offsite emergency planning Time for resubmission unclear Certificate of Svc SHOTHELLA SHOTWELL, J.A. Massachusetts, State of 82/11/30 and Licensing Board Panel App. 16329 292 24% Fiche 50-443, 82/11/30, 8212070242
- 8212030163 Advises that NRC will take no position on State of NH 621115 motion to compel util answers to first set of interrogatorses PERLIS.R G Hearing Branch 3 82/12/01 HOYT,H , LUEBKE,E A , HARBOUR,J Atomic Safety and Licensing Board Panel 2pp 16906 013 24% Fiche 50-443,82/12/01.6212030163
- 8212060020 Confirms 821201 telcon from Judge Hout Parties invited to 821210 tour w/Judge Prehearing conference scheduled for 830111 to be rescheduled Availability of FEMA representative at next prehearing conference uncertain
 LESSY.R P Hearing Branch 3 82/12/02 HDYT.H , LUEBKE.E A ,
 HARBOUR.J Atomic Safety and Licensing Board Panel 2pp
 16313 298 24X Fiche 50-443, 82/12/02, 8212060020
- 8P12140212 Interrogatories & request for production of documents
 Certificate of Svc encl Related correspondence
 DIGNAN.T 9. GAD.R K Public Service Co of New Hampshire
 DIGNAN.T 6 Ropes & Gray 82/12/08 Coastal Chamber of Comme
 of New Hampshire 110pp 16406 153 24X Fiche 50-443,82/12/08,
- 8212140217 Interrogatories & request for production of documents
 Certificate of Svc ancl Related correspondence
 DIGNANT 0 , OAD, R K Public Service Co of New Hampshire
 DIGNANT 0 Ropes & Oray 82/12/08 Seacoast Anti-Ppillution
 League 108pp 16406 307 24X Fiche 50-443.82/12/08.8212140217
- BP12140430 Interrogatories & request for production of documents Certificate of Syc enci Related correspondence
 DIGMAN, T 0 . GAD.R K Public Service Co of New Hampshire
 DIGMAN, T 0 . Ropes & Gray 82/12/08 New Hampshire. State of
 110pp 16405 031 24% Fiche 50-443,82/12/08,8212140430
- B212140441 Interrogatories & request for production of documents Certificate of Svc encl Related correspondence
 DIGNALT 0 GADLR K Public Service Co of New Hampshire
 DIGNALT 0 Ropes & Dray 82/12/08 New England Coaltien on
 Nuclear Pollution 111pp 16404 069 24X Fiche 50-443.82/12/08,
- 8212140227 Motion to file responsive pleading re State of NH motion to compel answers to first set of interrogatories to util Certificate of Svc encl Related correspondence KINDER, ET New Mampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel 3pp 16408 343 24X Fiche 50-443,82/12/09, 8212140227
- 8212140234 Withdrawal of motion to compel answers to interrogatories & response to applicant answer Interrogatories 9 6,9 16 & 10 2 withdrawn Util should answer 9 1,9 8 & 10 1 & BAPL 3 7,3 10 & 3 11 M/Certificate of Svc Related correspondence KINDER, E T New Hampshire, State of 82/12/09 Atomic Safety and Licensing Board Panel Opp 1640B 346 24X Fiche 50-443,82/12/09, 8212140234
- BP121404R6 Motion for continuance of discovery deadline to 830401 Continuance fair in light of rescheduling of projected fuel loading dates Previous deadline burdensome & would impede litigation of intervenor contention Related correspondence BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, R A 82/12/07 Atomic Safety and Licensing Board Panel 2pp 16404 174 24X Fiche 50-443,82/12/07.8212140426
- --9212140437 Advises of results of const scheduling study Study indicates 10-month slippage.changing projected fuel loading dates for Unit I to Sept 1984 & Unit 2 to Dec 1986 Svc list encl DIGNAN, T O Ropes & Gray DIGNAN, T O Public Service Co of New Hampshire 82/11/30 HDYT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 16404 176 24X Fiche 30-443, 82/12/09, 8212140426
- 8212160281 Motion to extend time until 830315 for discovery on admitted contentions Present schedule does not allow sufficient time to complete requests Certificate of Svc encl Related c orrespondence KINDER, E T , BIBBEE, O D New Hampshire, State of 02/12/1 Atomic Safety and Licensing Board Panel Spp 16446 058 Fiche 50-443, 82/12/13, 8212160281
- 8212160321 Responses to interrogatories & requests for document production Svc list encl Related correspondence DOUGHTY. J Seacoast Anti-Pollution League 82/12/13 Off: the Executive Legal Director Spp 16442 332 24X Fiche. 80-443, 82/12/13, 8212160321. Office of

- 8212200039 Forwards motion for extension of time for discovery & LL 91shop notice of appearance CURRAN,D Harmon & Weiss CURRAN,D New England Coalition on Nuclear Poliution 82/12/15 HOYT,H F, LUEBKE,E A, HARBOUR, J Atomic Safety and Licensing Board Panel 1p 16474 255 24X Fiche 50-443,82/12/15.8212200039
- --8212200049 Hotion for extension of time for discovery until 830315

 Sheer vol of math to be processed to prepare or answer
 interrogatories on large number of complex technical issues
 makes compliance impossible Certificate of Svc encl
 CURRAN.D. BISHOP.L. New England Coalition on Nuclear Pollution
 CURRAN,D. Harmon & Weiss 82/12/15 Atomic Safety and
 Licensing Board Panel 8pp 16474 256 24X Fiche 50-443,
 82/12/15,8212200039
- BP12220255 Amended answer to State of NH Interrogatory 9 8 Certificate of 6vt enci BlONAN, T O. GAD,R K. Public Service Co. of New Hampshire BLONAN, T O. Ropes & Gray 82/12/15 New Hampshire, State of 4pp 16518 001 24X Fiche 50-443,82/12/15,8212220255
- 8212230346 Second set of interrogatories & request for production of documents Certificate of Syc encl Related correspondence KINDER.E T. BISBEE.G D New Hampshire. State of 82/12/15 Office of the Executive Legal Director 14pp 16505 162 24X Fiche 50-443,82/12/15,8212230346
- 8212230348 Second set of interrogatories & request for production of documents Certificate of Svc encl Related correspondence KINDER.E T. BIBBEE.G D New Hampshire, State of 82/12/15 Public Service Co of New Hampshire 24pp 16511 240 24X Fiche 50-443,82/12/15,8212230348
- BP12200079 Motion for continuance of B21215 deadline for discovery until B30601 Burden of short discovery period & re-election campaign precluded submittal of documents in timely manner Svc list encl HOLLINGWORTH. B Coastal Chamber of Commerce of New Hampshire B2/12/16 Atomic Safety and Licensing Board Panel 3pp 16474 306 24X Fiche 50-443,82/12/16.8212200079
- 8.12210228 Answers to second set of interrogatories & request for production of documents on Contentions I A 2.I B 1.I B 2 & 1 C & motion for protective order Certificate of Svc encl DIONAN.T G. GAD.R K Public Service Co of New Hampshire DIGNAN.T G. Ropes & Gray 82/12/16 New England Coalition on Nuclear Pollution 71pp 16484 001 24X Fichs 50-443.82/12/16.8212210228
- 8212230334 Second set of interrogatories & request for production of documents Svc list encl Related correspondence BACKUS,R.A. Seacoast Anti-Pollution League BACKUS,R.A. Backus. R.A. 82/12/16 Diffice of the Executive Legal Director 3pp 16505 128 24% Fiche 50-443,82/12/16,8212230334
- 8:12230203 Order admitting Towns of Brentwood & Hampton, NH as interested municipalities List of admitted contentions one!

 HOYT.H F Atomic Safety and Licensing Board Panel 82/12/20
 Brentwbood, NH 10pp 16510 270 24x Fiche 50-443,82/12/20,8212230203
- 60:12270208 Hemorandum & order ruling on State of NH 821115 motion to compel applicants to answer first set of interrogatories Applicants must identify persons wisupervisory capacity for control room design & installation HOYT.H F Atomic Safety and Licensing Board Panel 82/12/22 Public Service Co of New Hampshire App 14534 356 24% Fiche 50-443.82/12/22.8212270208
- 82:12280017 Advises that NRC will not take position re applicant 82:217 motion for protective order for New England Coalition on Nuclear Pollution Interrogatory 6 Dispute is between opplicant & intervenor PERLIS.R O Hearing Branch 3 82:12:23 HOYT.H , LUEBKE.E Å , HARBGUR.J Atomic Safety and Licensing Board Panel ip 16564 288 24X Fiche 50-443.82:12:23,82:12280017
- BP12270270 Response to first set of interrogatories & request for documents on Contentions I A 2, I V. II, B 1-5, II C, II D, II F, II G, II I L = II N Affidavits & Gertificate of Svc encl
 LESSY, R P Hearings Division 82/12/28 New England Coalition on Nuclear Pollution 100pp 16581 115 24X Fiche 50-443,82/12/28,82/290290

M Antitrust correspondence

- 8212080527 Forwards notice of receipt of antitrust info w/recent application for OL Notice to be published in FR. Electric Light & Power. Public Utils Forthrightly & Rural Electrification. trade journals KNIOHTON. 0 W Licensing Branch 3 82/11/29 TALLMAN. W C Public Service Co of New Hampshire 2pp 16370 191 24X Fiche 50-443. 82/11/29.8212080527
- --8212080532 Notice of receipt of antitrust info Requests for reevaluation & addl info must be received by 830107 KNIGHTON-0 H. Licensing Branch 3 82/11/29 2pp 16370 193 24X Fiche 50-443-82/11/29.8212080527
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Dismeter Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs, 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosineters " Svc list enc!

 COBB.L. 1 'Division of Fuel Facilities, Materials & Gafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24% Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list enci JORDANIE L. Division of Engineering & Quality Assurance 62/11/18 Consolidated Edison Co. of New York, Inc. 107pp 16411 199 24X Fiche 50-000,82/11/18,8208190251
- B208190256 IE Info Notice 82-46, "Defective & Disolete Combination Padlocks " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256
- BPO8190257 IE info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list ancl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 354pp 14387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 62-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Byc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X fiche 50-000.82/12/03.8208190259
- 820Bi90261 IE Info Notice B2-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDÁN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- BB120B0321 Ack receipt of 821117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-449/82-10 & 50-449/82-10 BTAROBTECKI, R Division of Project & Resident Programs. BB/12/03 TALLMAN, W C Public Service Co of New Hampshire 1p 16959 337 24X Fiche 50-443/82/12/03/82120B0321
- --B2120B0329 Responds to NRC B21020 ltr re violations noted in IE Insp
 Repts 50-443/82-10 % 50-444/82-10 Corrective actions
 technical procedure issued to resolve clearance problems &
 drawing revised to indicate required both & nut mat)
 DEVINCENTIS, J Yankee Atomic Electric Co. DEVINCENTIS, J Public
 Service Co of New Hampshine B2/11/17 STARGBTECKI, R Division
 of Project & Resident Programs 4pp 16053 338 24%
 Fiche 50-443,82/12/03,8212080321
- 8212210270 Forwards IE Insp Repts 50-443/82-13 & 50-444/82-11 on B21001-1103 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 82/12/06, TALLMAN, W C Public Service Co of New Hampshire 2pp 16483 035 24X Fiche 50-443,82/12/06,8212210270
- --B212210282 IE Insp Repts 50-443/82-13 & 50-444/82-11 on B21001-1105 Noncompliance noted failure to conduct & document insp of pipe support Kwik-bolting activities per procedural hold-point requirements CERNE, A C. GRAMM.R A. GALLO.R M. Division of Project & Resident Programs 82/11/17. 9pp 16483 039 24X Fiche: 50-443, 82/12/04, 8212210270

- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Syc list encl BEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000, 82/12/20, 8208190268
- S Reportable occurrences. LERs & related correspondence
- 8212060079 PNO-I-82-075 on 821201.util announced 10-month delay & new commercial operation dates for Unit 1 (821231) & Unit 2 (870331) projected. Total cost revised by 44% Caused by increased design & engineering complexity KELLY.E., GALLO,R., GREENMAN,E. Region 1, Office of Director 82/12/01 2pp 14314.342 24% Fiche: 50-443,82/12/01.8212060079
- 8212210287 Final deficiency rept re seat leakage in ASCO solenoid valves mounted on Posi-Seal Inti butterfly valves Initially reported on 821103 Posi-Seal Inti supplied relubrication lits to correct problem DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/08 STAROSTECKI, R Division of Project & Resident Programs 3pp 16497 0.39, 24X Fiche 30-443, 82/12/08, 8212210287
- 3212210273 Interim deficiency rept re adequacy of tornado missile shield protection on north & west walls of fuel storage bldg Initially reported on S21110 Engineering evaluation results will be reported by 830401.

 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 82/12/14 STAROSIECKI, R Division of Project & Resident Programs 2pp 16483 233 24%

 Fiche 50-443,82/12/14,8212210273
- 212210449 Interim deficiency rept re potential for pipe & component overstress due to exceeding pipe pulling limits during welding fit-up Initially reported on 821110 Nonconformance rept dispositioned to rework complete. Next rept by 830715 DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS. J Public Service Co. of New Hampshire. B2/12/14 STAROSTECKI, R Division of Project & Resident Programs. 3pp 16489 178 24X Fiche 50-443,82/12/14.8212210449
- ICKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA. JUNIT 1
 Application/construction stage documents & correspondence
- 12270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREO-0784, Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records. 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16547 233 24X siche 50-000, 82/11/26, 82(2270418
- 8211050027 Forwards summary of memiscale test results & advises that board notification re test results issued. W/o anci NOVAK,T M Assistant Director for Licensing 82/09/24 Division of Licensing Ip. 16549 278 24X Fiche 50-000.82/11/26, 8212270418
- 12080106 Notification of \$21216 meeting w/util in Bethesda, MD to fiscuss util plans for independent design verification program URWELL, S.B. Licensing Branch 1, \$2712/01 YQUNOBLQDD, B.J. icensing Branch 1 \$29 16368 297 \$24X Fiche 50-445,82/12/01,1212080106
- 2160428 Forwards proposed process control program establishing oundary conditions for operation of ATCOR radwaste olidification systems. B R Texas Utilities Generating Co. 82/12/09 DENTON.H R Defice of Nuclear Reactor Regulation. Director 14pp. 16442 132 4X Fiche 50-445.82/12/09.8212160428
- 2220440 Board Notifications 82-125 & 82-125A: forwards info re Etherington evaluation of flow blockage during natural inculation of FWRs Results do not adversely impact present osition on reliance on natural circulation VAKIT N Assistant Director for Licensing 82/12/14, Atomic sfety and Licensing Board Panel 5pp 16523 135, 24% iche 50-000, 82/12/14, 8212220440.

- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 8-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000.82/12/14.8212220461
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212170337 Forwards "Human Factors Control Room Design Review of Committee Peek Steam Electric Station," to resolve SER (NUREP-0797) open issue GARY,R J Texas Utilities Generating Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16460 001 24X Fiche 50-445,82/12/15,8212170337
- --B212170342 "Human Factors Control Room Design Review of Commanche Peak Steam Electric Station " GARY: N Texas Utilities Generating Co 82/12/31 5(Opp 16460 002 24X Fiche 50-445, 82/12/15,82(2170337
- F Security, medical, emergency & fire protection plans
- BRI2070403 Responds to B21202 request re Generic Ltr 81-10, "Emergency Operations Facility Survey "Emergency operations facility const completed Aug 1782 Protection factor upgraded Equipment wifl be installed prior to fuel load SCHM10T.H C Texas Utilities Services, Inc 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 16336-343 243 Fiche 50-445,82/12/03,8212070403
- 8212140298 Forwards Revision 2 to security training & qualification plan Revision withheld (ref 10CFR73 21)

 9ARY.R J Texas Utilities Generating Co 82/12/06 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 16402 080
 24X Fiche 50-445,82/12/06,8212140298
- G Adjudicatory correspondence
- B212090095 Order advising that record will not be closed at present time due to unresolved issues & incomplete analyses Parties directed to file provisional proposed findings on all issues covered in record Admitted Intervenor exhibits listed MILLER, M E Atomic Safety and Licensing Board Panel 82/12/07 opp 16357 313 24X Fiche B0~445, B2/12/07, B212090095
- 8212140409 Motion for reconsideration of 821207 order establishing schedule for simultaneous filing of proposed findings of fact Applicants bear ultimate burden of proof in proceeding & should be allowed time to respond to proposed findings REYNOLDS.N S , HORIN,W A Teras Utilities Generating Co REYNOLDS.N S Debavoise & Liberman 82/12/10 Atomic Safety and Licensing Board Panel App 16403 327 24X Fiche 50-445,82/12/10,8212140409
- 8212230182 Motion to suppl exhibits accepted by 821202 order Enclexhibits constitute new & significant info which should be in record Certificate of Svc encleLLIS.J Citizens Association for Sound Energy 82/12/14 Atomic Safety and Licensing Board Panel 50pp 16510 319 24X Fiche 50-445,82/12/14,8212230182
- 82:2230195 Motion for reconsideration of ASLB 82:207 order directing simultaneous filing of proposed findings of fact Since fuel load not expected until Dec 1983 deadline for Walsh/Dayle allegation findings may be extended W/Certificate of Svc ELLIS, J Citizens Association for Sound Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 16511 021 24X Fiche 50-445, 82/12/14, 8212230195
- 8212230353 Reconsideration of 821207 order, extending deadline Until 830225 to file provisional proposed findings of fact MILLER,ME Atomic Safety and Licensing Board Panel 82/12/21 Teras Utilities Generating Co 4pp 16517
- 8212300009 Brief in opposition to NRC exceptions to ASLB 820930 order denying reconsideration of orders to produce info Affidavit & Centificate of Svc encl.

 ELLIS, J Citizens Association for Sound Energy 82/12/21 Atomic Safety and Licensing Appeal Panel 175pp 16399 036 24X Fiche 50-445, 82/12/21, 8212300009
- 8212300045 Affidavit of J Ellis, attesting to truth of statements in Citizens Assoc for Sound Energy brief in opposition to NRC exceptions to ASLB order denying reconsideration of 820930 order ELLIG. J Citizens Association for Sound Energy 82/12/21 App 14598 194 24X Fiche 50-445,82/12/21,8212300045

- 2/0317 Forwards MP Osborne affidavit confirming that value of ENDR regions above limiting value of 1 30 w/or w/o boron confirming that value of ENDR region tank to yNOLDS: N S Debevoire & Liberman REYNOLDS: N S Texas Utilities REForating Co 82/12/22 MillER, M E. MCCGLLOM. K A. COLE. R Ocomic Safety and Licensing Board Panel 2pp 16530 278 24X picne 50-445. 82/12/22. 8212270317
- 12270320 Affidavit of MP Osborne confirming that value of DNBR smains above 1 30 limit for pertinent steam line break analyses w/o boron injection tank DBORNE. M P Texas Utilities Generating Co 82/11/29 ip 1630 280 24X Fiche 50-445,82/12/22,8212270317
- 121270332 Brisf in response to NRC B2100B exceptions to ASLB 820930 order denying reconsideration of ASLB 820804 order to show order asks ASLBS review required to decide if party to proceeding the projudiced M/Certificate of Svc way Prejudiced M/Certificate of Svc WayNRLDS, N S Texas Utilities Generating Co REYNDLDB, N S RESPONSE & Liberman 82/12/22 Atomic Safety and Licensing Co Debevise & Liberman 82/12/22 Atomic Safety and Licensing Co Debevise & Liberman 82/12/22 Atomic Safety and Licensing Co Debevise & Liberman 82/12/22 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety and Licensing Co Debevise & Liberman 82/12/20 Atomic Safety Saf
- B2: 2580273 Response in opposition to Citizens Assoc for Sound Energy (CASE) 821214 motion to suppl exhibits info to be presented in applicant brief should be considered in disposing of CASE in stant motion Certificate of Svc encl REYNOLOS, N S., HORIN, H A. Texas Utilities Generating Co. REYNOLOS, N S. Debevise & Liberman 82/12/23 Atomic Safety and Licensing Board Panel Supplement 82/12/23 Atomic Safety and Licensing Board Panel Supplement 82/12/23, B212280273
- 8212300016 Notifies that oral argument on issues raised by NRC appeal from ASLB 820930 order denying NRC motion for Technideration of 820804 order will be held on 830119 in 8 ethesda. MD SHOEHAKER, C. J. Atomic Safety and Licensing Appeal Panel 82/12/27 TURK, S.E. Office of the Executive Legal Director ELLIS, J. C. itizens Association for Sound Energy REYNOLDS, N.S. Debevoise & L. iberman ip 16598 309 24X Fiche 50-445, 82/12/27, 8212300016
- 🚉 🗸 🕻 tilitų Final Safetų Analysis Report (FSAR) & amends
- BE12130301 Forwards tabled revisions to F5AR, Amend 36 MARSHALL, 5 Texas Utilities Bervices, Inc 82/12/10 BURNELL, 5 B Division of Licensing 7pp 16389 333 24) F1che 50-445, 82/12/10.8212130301
- 8212150166 Forwards Amend 36 to FSAR
 GARY,R J Texas Utilities Generating Co 82/12/10 DENTON, H R
 Office of Nuclear Reactor Repulation, Director 2pp 16428 001
 24X Fiche 50~445,82/12/10,8212150166
- -- 8212150171 Amend 36 to FSAR * Texas Utilities Generating Co 82/12/10 SBpp 16427 001 24X Fische 50-445,822/12/10.8212150166
- B212210391 Forwards Amend 37 to FSAR

 GARY, R J Texas Utilities Generating Co 82/12/17 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 2pp 16494 330

 24X Fiche 50-445,82/12/17,8212R10391
- --B212210394 Amend 37 to FSAR

 * Texas Utilities Generating Co 82/12/17 187pp 16494 332 24X Fiche 50-445,82/12/17,8212210391
- 4. Inspection reports. IE Bulletins & correspondence
- OB190240 IE Bulletin B2-03, Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Flants" Svc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 820B190240
- B212010354 Board Notification 82-116 forwards mathre welds in main Control panel at sites Licensee has not provided info Tecssary to resolve item identified in IE Insp Rept 50-445/82-19 NOVAK, TH Assistant Director for Licensing 82/11/04 Atomic Safety and Licensing Board Panel 4pp 16271 206 24X Fiches 50-445,82/11/04,8212010334
- ₱₽○Bi90245 IE Info Notice B2-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list Bnc1 CDBB,L I Division of Fuel Facilities, Materials & Safegyards, B2/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000, B2/11/05, B20Bi90245

- 8212030151 Forwards IE Insp Rept 50-445/82-22 on 821019-20 No noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 82/11/10 QARY, R J Texas Utilities Generating Co 2pp 16303 299 24X Fiche 50-445,82/11/10,8212030151
- --8212030156 IE Insp Rept 50-445/82-22 on 821019-20 No nencompliance noted Major areas inspected const activities TOMLINSON. D P. STEMART.R C. ROBERDS.M J. Region 4. Office of Director 82/11/02 4pp 16303 301 24X Fiche 50-445,82/11/10, 8212030151
- B2:2280329 Responds to IE Bulletin 82-01.Revision 1.Suppl 1.
 "Alteration of Radiographs of Welds in Piping
 Subassemblies " All but six welds will meet applicable code
 requirements
 OARY.R J Texas Utilities Generating Co B2/11/17 COLLINS.J T
 Region 4. Office of Director 2pp 16560 104 24X
 Fiche 50-445.02/11/17.0212280329
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDÁN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411,179 24X Fiche 50-000,82/11/18,8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 80-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl. COBB.L I Division of Fuel Facilities. Materials & Safeguards BZ/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30.8208170257
- 8208190259 JE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUND: R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- BR08190261 IE Info Notice 82-4B, "Failures of Agastat CR 0095 Relay Sockets " Svc list enci JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8212140157 Advises that IE Insp Rept 50-445/82-14 on 820803-30 issued on 821108 supersedes insp rept issued on 620927, due to add1 info reported re structural welding performed by NP9 Industries MADSEN. 0 L Division of Resident, Reactor Project & Engineering Programs 82/12/07 QARY.R J Texas Utilities Generating Co 2pp 16409 346 24X Fiche 50-445.82/12/09.8212140157
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list entl DEYOUNG.R C Director's Office Office of Inspection and Enforcement BAP12/16 Consolidated Edison Co of New York, Inc 127pp | 6628 171 24% Fiche 80-000.82/12/16.8208190267
- 8P08190266 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27 " Svc list enc] JORDAN,E L Division of Engineering & Guality Assurance, 82/12/20 Consolidated Edison Co of New York, Inc 108pp, 18628 273 24x Fiche 50-000,82/12/20,8208190288
- 8212300121 Forwards QA Program Insp Repts 99700784/82-01 & 99700761/82-01, which impact work at facility, per 821208 SALP meeting Insp repts of NPSI & ITT Orinnell will follow M/o encis COLLINS, J. Region 4, Diffice of Director 82/12/27 CLEMENTS, B R Teras Utilities Generating Co ip 16598 233 24X Fishe 50-445, 82/12/27, 8212300121
- DOCKET 50-444 COMANCHE PEAK STEAM ELECTRIC BTA .UNIT 2

 A Application/construction stage documents & correspondence
- 9212270419 Responds to FOIA request for documents re proposed revision \$\(\text{\$\text{A}\$}\) or update to reactor safety study referred to in NURSO-0784. Chapter 10 as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app. FELTON, J M Division of Rules and Records 92/11/26 9HOLLY/8 C Union of Concerned Scientists 3pp 16549:233 24X Fiche 50-000. 82/11/26, 8212270418

1

DOCKETED ITEMS

- -8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK.7 M Assistant Director for Licensing 82/09/24 Division of Licensing ip 16549 278 24X Fiche 50~000.82/11/26, 821270418
- 8212080106 Notification of 821216 meeting w/util in Bethesda MD to discuss util plans for independent design verification program BURMELL.S B ticensing Branch 1 82/12/01 YOUNGBLOOD, B J Licensing Branch 1 3pp 16368 279 24X Fiche 50-445,82/12/01,6212080106
- 8212160428 Forwards proposed process control program establishing boundary conditions for operation of ATCOR radwaste solidification sys CLEMENTS B R Texas Utilities Generating Co 82/12/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 16442 132 24X Fiche 50-445,82/12/09,8212160428
- 8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PHRs Results do not adversely impact present position on reliance on natural circulation NOVAK, T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000,82/12/14,8212220440
- 8212220441 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24% fiche 50-000.82/12/14.8212220461
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B212170337 Forwards "Human Factors Control Room Design Review of Comancho Peak Steam Electric Station," to resolve SER (NVREQ-0797) open issue OARY.R J Texas Utilities Openrating Co 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p (6460 001 24X Fichs 50-445, 82/12/15, 8212170337
- --8212170342 "Human Factors Control Room Design Review of Commenche Poak Steam Electric Station " GARY,R J Teras Utilities Generating Co 82/12/31 510pp 16460 002 24X Fiche 50-445, 62/12/15.8212170337
- F Security, medical, emergency & fire protection plans
- 8212070403 Responds to 821202 request re Generic Ltr Bi-10, "Emergency Operations Facility Survey " Emergency operations facility const completed Aug 1982 Protection factor upgraded Equipment will be installed prior to fuel load SCHMIDT.H C Teras Utilities Services, Inc 82/12/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 16336 343 24X Fiche 50-445.82/12/03.8212070403
- BP12140278 Forwards Revision 2 to security training & qualification plan Revision withheld (ref 100FR73 21)
 GARY.R J Texas Utilities Generating Co 82/12/06 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 16402 OBO
 24X Fiche. 50-445.82/12/06.8212140298
- O Adjudicatory correspondence
- 82:2070075 Order advising that record will not be closed at present time due to unresolved issues & incomplete analyses Parties directed to file provisional proposed findings on all issues covered in record Admitted intervenor exhibits listed MILLER, M E Atomic Safety and Licensing Board Panet 82/12/07 4pp 16357 313 24X Fiche 50-445,82/12/07,8212090095
- 8212140409 Motion for reconsideration of 821207 order establishing schedule for simultaneous filing of proposed findings of fact Applicants bear ultimate burden of proof in proceeding & should be allowed time to respond to proposed findings REYNOLDS: N S , HORIN, W A Teras Utilities Generating Co REYNOLDS: N S Debevoise & Liberman 82/12/10 Atomic Safety and Licensing Board Panel 4pp 16403 329 24% Fiche 50-445.82/12/10, 82/12/40409
- B212230182 Motion to suppl exhibits accepted by B21202 order Encl exhibits constitute new & significant info which should be in record Certificate of Svc encl ELLIS.J. Citizens Association for Sound Energy B2/12/14 Atomic Bafety and Licensing Board Panel. 50pp 14510 319 24X Fiche 50-445-82/12/14.8212230182

- 8212230195 Motion for reconsideration of ASLB 821207 order directing simultaneous filing of proposed findings of fact Since fuel load not expected until Dec 1983, deadline for Walsh/Doyle allegation findings may be extended W/Certificate of Svc ELLIS. J Citizens Association for Sound Energy 82/12/14 Atomic Safety and Licensing Board Panel 9pp 16511 021 24X Fiche 30-443, 82/12/14, 82/2230195
- 8212230353 Reconsideration of B21207 order, extending deadline until B30225 to file provisional proposed findings of fact MILLER, M E Atomic Safety and Licensing Board Panel B2/12/21 Texas Utilities Generating Co 4pp 16517 129 24X Fiche 50-445, 82/12/21, 8212230353
- 8212300009 Brief in opposition to NRC exceptions to ASLB 820930 order denying reconsideration of orders to produce info Affidavit & Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 82/12/21 Atomic Safety and Licensing Appeal Panel 175pp 16599 036 24X Fiche 50-445.82/12/21.8212300009
- B212300045 Affidavit of J Ellis, attesting to truth of statements in Citizens Assoc for Sound Energy brief in apposition to NRC exceptions to ABLB order denying reconsideration of 820930 order ELLIS, J Citizens Association for Sound Energy 82/12/21 2pp 16598 194 24% Fichs 50-445, 82/12/21, 8212300045
- B212270317 Forwards MP Osborne affidavit confirming that value of BNBR remains above limiting value of 1 30 w/or w/o boron injection tank REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 82/12/22 MILLER, M E , MCCOLLOM, K A , COLE, R Atomic Safety and Licensing Board Panel 2pp 16530 278 24X Fiche 50-445, 82/12/22, 8212270317
- --8212270320 Affidavit of MP Osborne confirming that value of DNBR remains above 1 30 limit for pertinent steam line break analyses w/o boron injection tank OSBORNE-M P Texas Utilities Generating Co 82/11/29 1p 1633 280 24X Fiche 50~445,82/12/22,8212270317
- 8212270332 Brief in response to NRC 821008 exceptions to ASL8 820930 order denying reconsideration of ASL8 820804 order to show cause ASLAB review required to decide if party to proceeding was prejudiced W/Certificate of Svc REYNOLDS,N S Texas Utilities Generating Co REYNOLDS,N S Debevoirs & Liberman 82/12/22 Atomic Bafety and Licensing Appeal Panel 21pp 16530 016 24X Fiche 50-445,82/12/22,8212270332
- 8212280273 Response in opposition to Citizens Assoc for Bound Energy (CASE) 821214 motion to suppl exhibits Info to be presented in applicant brief should be considered in disposing of CASE instant motion Certificate of Svc encl REYNOLDS,NS, HORIN.WA Texas Utilities Generating Co REYNOLDS,NS Debavoise & Liberman 82/12/23 Atomic Safety and Licensing Board Panel 11pp 16561 232 24X Fiche 80-445,82/12/23,8212280273
- B212300016 Notifies that oral argument on issues raised by NRC appeal from ASLB 820930 order denying NRC motion for reconsideration of 820804 order will be held on 830119 in Bethesda,MD SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel B2/12/27 TURK,S E Office of the Executive Legal Director ELLIB,J Citizens Association for Sound Energy REYNOLDS,N S Debevoise & Liberman 1p 16598 309 24X Fiche 50-445,82/12/27,8212300016
- K Utility Final Bafety Analysis Report (FBAR) & amends
- G212130301 Forwards tabled revisions to FSAR. Amend 36 MARSHALL, J 9 Texas Utilities Services, Inc 82/12/10 BURWELL, S 8 Division of Licensing 7pp 16389:333 24 Fiche 50-445:62/12/10.8212130301
- B212150166 Forwards Amend 36 to FBAR GARY,R J Texas Utilities Generating Co 82/12/10 DENTON.H R Uffice of Nuclear Reactor Regulation, Director 2pp 16428 001 24X Fichs 50-445,82/12/10,8212150166
- --8212150171 Amend 36 to FSAR
 * Texas Utilities Generating Co 82/12/10 88pp 16429:001
 24X Fiche:50-445.82/12/10.8212150166
- B212210391 Forwards Amend 37 to FSAR.

 ORRY.R J Texas Utilities Generating Co 82/12/17 DENTON.H R
 Dffice of Nuclear Reactor Regulation. Director 2pp 16494 330
 24X Fiche, 50-445, 82/12/17, 8212210391

- --8212210394 Amend 37 to FSAR
 * Texas Utilities Generating Co 82/12/17 187pp 16494 332 24X Fiche 50-445.82/12/17.8212210391
- Q Inspection reports, IE Bulletins & correspondence
- B20B190240 IE Bulletin B2-03.Revision i. "Btress Cracking in Thick-Wall/Large-Diameter:Btainless Steel.Recirculation Sys Piping at BNR Plants " Svc list encl
 DEYGUNO,R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- B212010354 Board Notification 82-116 forwards matl re welds in main control panel at sites Licensee has not provided info necessary to resolve item identified in IE Insp Rept 50-445/02-19
 NOVAK.T M Assistant Director for Licensing B2/11/04 Atomic Safety and Licensing Board Panel 4pp 16271 206 24X Fichs 50-445, 82/11/04, 8212010354
- 8208190245 IR Info Notice 82-42, "Defects Observed in Panasonic Hodel 801 & Model 802 ThermolumInescent Desimeters " Svc list enc! COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- B212280329 Responds to IE Bulletin B2-01.Revision 1.Suppl 1.
 "Alteration of Radiographs of Welds in Piping
 Bubassemblies." All but six welds will meet applicable code
 requirements
 GARY.R J Texas Utilities Generating Co 82/11/17 COLLINS.J T
 Region 4. Office of Director 2pp 16560 104 24X
 Fiche 50-445.82/11/17.8212280329
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 35App 14387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24X Fiche 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462.064 24X Fiche: 50-000, 82/12/03, 8208190261
- B208190267 lE Info Notice 82~49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND.R.C Director's Office, Office of Inspection and Enforcement. B2/12/16 Consolidated Edison Co of New York, Inc 127pp. 16628,191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82~50, "Mod of Solid State AC Undervoltage Relags Type ITE-27" Svc list encl JURDAN: E L Division of Engineering & Guality Assurance. 82/12/20 Consolidated Edison Co. of New York, Inc 108pp 16628
- 8212300121 Forwards QA Program Insp Repts 99900784/82-01 & 99900761/82-01, which impact work at facility, per 821208 SALP meeting Insp repts of NPSI & ITT Orinnell will follow W/o encls CQLLINB, J.T Region 4, Office of Director, 82/12/27 CLEMENTS, B R Texas Ubilities Generating Co ip. 16598 233 24X Fichs 50-445,82/12/27,8212300121.

- 5 Reportable occurrences, LERs & related correspondence
- B212280267 Interim deficiency rept re linear indications in diese) generator auxiliary skid Initially reported on B20709 Completion of evaluation expected by 840113 GARY.R J Texas Utilities Generating Co B2/12/16 MADSEN.G C Division of Resident. Reactor Project & Engineering Programs 1:16561 310 24X Fiche 50-446,82/12/16.8212280267
- DDCKET STN-50-447 GESSAR-238
- A Application/construction stage documents & correspondence
- 8212150203 Notification of 821213 meeting w/GE in Dethesda.MD to discuss GESSAR-11 soil structure interaction SCALETTI.D C Standardization & Special Projects Branch B2/12/10 THOMAS. C Standardization & Special Projects Branch 3pp 16437 347 24X Fiche 50-447.82/12/10.8212150203
- GP12150209 Notification of B21216 meeting w/GE in Dethesda, MD to propose BWR/6 Mark III GESSAR-II seismic event analysis SCALETTI.D C Standardization & Special Projects Branch G2/12/10 THOMAS.C D Standardization & Special Projects Branch 3pp 16447 065 24X Fiche 50-447, B2/12/10.8212150209
- 8212280510 Notification of location change for 821216 meeting w/0E in Bethesda.MD to propose BWR16 Mark III GESSAR-II seismic event analysis SCALETTI, D C Standardization & Special Projects Branch 82/12/10 THOMAS, C D Standardization & Special Projects Branch (p 16590 113 24X Fiche 50~447,82/12/10,8212280510
- 8212200041 Summarijes 821214 mpeting discussions between NRC & GE re status of GESSAR-II final design approval (FDA) review OIFFORD.L S Oeneral Electric Co 82/12/15 THOMAS.C Standardijati on & Special Projects Branch 2pp 16474 264 24X Fiche 50-447, 82/12/15, 8212200041
- G212230328 Forwards final draft responses to Radiation Assessment Branch.Effluent Treatment Sys Branch.Auxiliary Sys Branch & Power Sys Branch 820825 info request SHERNOOD, 0 General Electric Co G2/12/17 EISENHUT, D O Division of Licensing 179pp 14505 193 24X Piche 50-447, G2/12/17, B212230328
- SP12290119 Forwards final draft responses to Commission 821005 info request re OESSAR-II Instrumentation & Control Sys Branch responses will be provided following GE/NRC meeting in Jan 1983 SHERWOOD, 0 General Electric Co 82/12/22 EISENHUT, D Q Division of Licensing 169pp 16582 250 24% Fiche 50-447, 82/12/22, 8212290119
- 8212300196 Requests additinfore review of severe accident portion of QE application for final design approval Responses to encl questions should be provided by 830201 MIRAQLIA,F U Assistant Director for Safety Assessment 82/12/23 SHERNDOD,O G General Electric Co 27pp 16612 302 24X Fiche 50-447,82/12/23,8212300196
- D Utility Proliminary Safety Analysis Report, amends
- BP12130172 Forwards proprietary Amend 10 to QESSAR 11 re enhanced level instrumentation Amend withheld (ref 10CFR2 790) SHERNDUD, 0 G General Electric Co B2/11/23 EISENHUT, D Q Division of Licensing 2pp 16390 i14 24X Fiche 50-447, 82/11/23, B212130172
- B21214034B Forwards proprietary portion of Amend 11 to GESSAR-II re PRA Affidavit for withholding only encl SHERNDOD, 0 G General Electric Co 82/12/03 EISENHUT, D G Division of Licensing 8pp 14403 159 24X Fiche 50-447,82/12/03, G21214034B
- B212140447 Forwards nonproprietary Amend 11 to GESBAR II, revising App 15D, Section 3, "PRA of BURA'S Std Plant "Proprietary version only encl & withheld (ref 10CFR2 790) SHERMODD.0 Q General Electric Co 82/12/03 EIGENHUT, D G Division of Licensing 2pp 16403 212 24X Fiche 50-447,62/12/03, B212140449
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212230301 Forwards response to Mechanical Engineering Branch draft SER questions Remaining responses will be completed by 830114 Amend scheduled for Jan 1983 will formalize responses requiring changes to facility SHERNODD. 9 Q General Electric Co 82/12/17 EIGENHUT. D 9 Division of Licensing 144pp 16508 001 24X Fiche 50-447. 8212230301

- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B211270530 Application to amend applications for OL.consisting of Amend 40 to FBAR TRANKI,TR Commonwealth Edison Co. 82/11/19 DENTON,HR Office of Nuclear Reactor Regulation, Director 3pp. 16227-348 24X Fiche 30-000.82/11/19.8211270530
- 8212070177 Requests withholding of proprietary Hestinghouse info inadvertantly encl in revisions to App C of FSAR in 820818 & 0902 Its returbine missiles TRAMM.T R Commonwealth Edison Co 82/11/29 DENTON.H R Offic of Nuclear Reactor Regulation, Director 2pp 16329 169 24X Fiche 80-800.82/11/29,8212070177
- --8212070187 Affidavit re Westinghouse application for withholding proprietary info antl in App C to FSAR in IR Tramm 820818 & 0702 ltrs to NRC concerning turbine missiles
 CCULIERA R Westinghouse Electric Corp 82/11/08 8pp
 16329 171 24X Fiche 50-000.82/11/29.8212070177
- --8212070198 Forwards nonproprietary version of revised FBAR re protection against possible turbine missiles TRAMN-T R Commonwealth Edison Co 82/09/02. DENTON, H R Office of Nuclear Reactor Regulation. Director 35pp 16329 179 24X Fiche 50-000,82/11/29.8212070177
- --B212070207 Forwards nonproprietary version of revisions to FBAR reprotection against possible turbine missiles
 TRAMM.TR Commonwealth Edison Co 82/08/18 DENTON, HR Office
 of Nuclear Reactor Regulation. Director 70pp 16329 214 24X
 Fichs 50-000, 82/11/29, 8212070177
- G212220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Conerating Stations"
 SWARTI,E.D Commonwealth Edison Co 82/12/14 HAASS,W P Quality Assurance Branch. 1p. 14518 007 24X Fiche 50-000, 82/12/14, 82/22/2012
- --8212220231 "OA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000, 82/12/14,8212220212
- 8212280212 Forwards updated scheduls for engoing environ qualification testing programs, per 810528 commitment SWARTZ-E, D. Commonwealth Edison Co. 82/12/22 EISENKUT, D. G. Division of Licensing 18pp. 16556 161 24X Fichs 50-000, 82/12/22, 8212280212
- E NRC Basety Evaluation Report (SER), supply & correspondence
- BR12070249 Clarifies seismic qualification program b pump valve operability program evaluated in SER & reviewed in audit during uk of 820913

 TRAMM.T R Commonwealth Edison Co 82/12/02 DENTON.H.R Office of Nuclear Reactor Regulation. Director 5pp 16327 323 24X Fichs 30-000.82/12/02.8212070249
- 8212300019 Forwards draft SER Suppl 2 for comments & approval Response expected by 821223 M/o encl
 NOVAK.T M Division of Licensing 82/12/21 ERNST,M Division of Systems Integration (post S1005). JOHNSTON, W Assistant Director for Materials & Qualifications Engineering RUSENSTEIN,L Assistant Director for Core & Plant Systems 2pp 16624 286 24X Fiche 50-454,82/12/21,8212300019
- F Security, medical, emergency & fire protection plans
- 8212080120 Notification of cancellation of 821207 meeting w/otil in Bethesds.ND to discuss fire protection programs specifically, emergency communications sys & sprinklers in cable spreading room DLSHAN,L Licensing Branch 1 82/11/10 YOUNDSLOOD,B J Licensing Branch 1 3pp 16368 288. 24X Fiche 50-454.82/11/10, 8212080120
- 6212080494 Forwards SALP Repts 50~454/82-13 & 50~455/82-09 for Jul 1980-Dec 1981, per IE 620518 mgt meeting. Overall regulatory performance satisfactory although specific areas need to be strengthened KEPPLER. J 9. Region 3. Office of Director 82/12/02 REED. C Commonwealth Edison Co 3pp 16052 122 24X Fiche 50~454.82/12/02, 8212080494
- --8212080503 SALP Repts 30-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of GA program require improvements * Region 3, Office of Director 82/05/31 27pp 16352 125 24x Fiche-50-454,82/12/02,8212080494.

- 8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests info previously submitted by telcon Request for written response unnecessary burden on licensee DELOGORGE, L. D. Commonwealth Edison Co. 82/12/03 EISENHUT, D. Q. Division of Licensing 2pp. 16369-051 24X Fishe 50-000-82/12/03. 8212090383
- 82/2130017 Releases public version of Revision I to Emergency Plan Implementing Procedure EG-2. "Pre-Established Onsite & Offsite Monatoring Lucations (Hapa)" FELTON. J M Division of Rules and Records 82/12/07 Document Management Branch 1p 16417 062 24X Fiche 50-000, 82/12/07, 82/12/2017
- --8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents enc! PAJOHSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NHC No Detailed Affiliation Given 2pp 16417 063 24X Fiche 50-000,82/12/07,8212130017
- -8212130041 Public version of Revision 1 to Emergency Plan Implementic; Procedure EG-2, "Pre-Established Unsite & Offsite Monitoring Locations (Maps) " PAUDMBRI, J E Commonwealth Edison Co 82/11/27 4pp 16417 065 24% Fiche 50-000,82/12/07,8212130017
- 8212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMH, TR Commonwealth Edison Co. 82/12/07 DENTON, H. R. Dffice of Nuclear Reactor Regulation, Director 2pp 16409 302 24X Fiche 50~000, 82/12/07, 8212140243
- 8212220304 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J.O. Region 3, Office of Director 82/12/16
 Commonwealth Edison Co. 3pp. 16503 351 24% Fiche 50-000,82/12/16,0212220304
- B212300167 Releases public version of revised generating station emergency plan telephone directory FELTON, J M Division of Rules and Records 82/12/20 Document Management Branch 1p 16612 215 24X Ficha 50-000,82/12/20,8212300167.
- --B212300179 Forwards public version of revieed generating station emergency plan telephone directory MODRE.R B Commonwealth Edison Co 82/12/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24% Fiche 50-000, 82/12/20, 8212300167
- ~-8212300179 Public version of revised generating station emergency plan telephone directory GALLE,D P Commonwealth Edison Co 82/11/05 60pp 16612 217 24% Fiche: \$0-000.82712/20.8212300167
- 8212270247 Forwards corrected Pages 1-5 & 4-2 of Revision 7 to security plan Pages withheld (ref 10CFR73 21)
 DELGEDROE-L. O Commonwealth Edison Co. 82/12/22 DENTON, H & Office of Nuclear Reactor Regulation, Director 1p 16582 111 24x
 Fiche 50-454, 82/12/22, 8212270247
- O Adjudicatory correspondence
- 8212040010 Response opposing Rockford League of Women Voters 821112 motion to require NRG answers to Rockford 821022 interrogatories. Answers unnecessary for proper decision Certificate of Byc encil 90L086R0.8 C. Hearing Branch 4 82/12/02 Atomic Safety and Licensing Board Panel 12pp 16313 313 24X Fiche 50-454,82/12/02,8212040010
- 8212070157 Forwards revised Page 3 of NRC 821202 response to Rockford League of Women Voters motion to require interrogatory answers OOLDBERG, S C Hearing Branch 4 82/12/06 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 16335 316 24X Fiche SO-454,82/12/06,8212070157
- --8212070161 Revised Page 3 to NRC 821202 response to Rockford League of Homen Voters motion to require interrogatory answers Citation corrected * Office of the Executive Legal Director 82/12/06 Atomic Bafety and Licensing Board Panel ip 16335-317 24X Fichs 50-454,82/12/06.8212070157

1

DOCKETED ITEMS

- G. 12080235 Motion for entry of order approving \$21206 stipulation re litigation of contentions GOLDBERG, S. Hearing Branch 4. BIEWALSKI, A. Commonwealth Edison Co * League of Momen Voters of Rockford, IL. 82/12/06. Atomic Safety and Licensing Board Panel 1 p. 16354 127 24X Fiche 50-454, 82/12/06.8212080235
- --8212080245 Stipulation re litigation of contentions Contentions 28, 32, 34, 41, 47, 53, 54, 61, 63, 71 & 77 withdrawn Contentions 8, 19, 22, 39, 42, 62, 106, 108, 109, 112 & portions of 111 will be litigated GOLDBERG, 5 Hearing Branch 4 BIEWALSKI, A Commonwealth Edison Co * League of Women Voters of Rockford, IL 82/12/06 9pp 15354 128 24X Fiche 50-454, 82/12/06, 8212080235
- Spi2090231 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821118 motion to direct NRC to commence special insp ASLS lacks authority to supervise regional investigation or dictate pace GOLDERRO, S C Hearing Branch 4 82/12/08 Atomic Safety and Licensing Board Panel 3pp 16361 322 24X Fiche 50-454,82/12/08,8212090231
- --8212070836 Affidavit of DW Hayes providing status of Region 3 special insp on allegations re GA/GC Certificate of Svc encl HAYES D W Division of Project & Resident Programs 82/12/07 8pp 16361 325 24X Fiche 50-454.82/12/08.8212070231
- B212200102 Memorandum & order denying Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ B21118 motion to direct NRC to commence special investigation into allegations on GA/QC ASLB lacks requisite authority SMITH.I W Atomic Safety and Licensing Board Panel B2/12/16 Dekalb Area Alliance for Responsible Energy ip 16470 148 24% Fiche 50-434, 82/12/16, 8212200102
- GP12200107 Memorandum & order approving joint party G21206 stipulation on procedural problems w/one listed revision COLE,R F , SMITH,I W Atomic Safety and Licensing Board Panel G2/12/16 2pp 16470 094 24X Fiche 50-454.62/12/16.8212200107
- B212200113 Supplemental response to Rockford League of Homen Voters proposed interrogatories to NRC Certificate of Svc encl RAHSONR J Hearing Branch 4 B2/12/17 League of Women Voters of Rockford IL 12pp 16470 164 24X Fiche 50-454,82/12/17,8212200113
- 8212280188 Answers to NRC second set of interrogatories re Contention 1A Certificate of Svc encl Related correspondence MORRISON, P League of Women Voters of Rockford, IL 82/12/22 Office of the Executive Legal Director 5pp 14562 266 24X Fiche 50-454,82/12/22.8212280188

- B212280176 Notifies of change in mailing address for NRC licensing matl WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) B2/12/20 EISENHUT, D O Division of Licensing Ip 14956 135 24X Fiche 50-000,82/12/20,8212280176
- K Utility Final Safety Analysis Report (FSAR) & amends
- GRIIGROSSO Application to amend applications for OL, consisting of Amend AO to PSAR TRANM.TR Commonwealth Edison Co 82/11/19 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X fiche 50-000, 82/11/19, 8211290530
- --D211270559 Amend 40 to FBAR

 * Commonwealth Edison Co 62/11/30 234pp 16227 351 24X
 Fishe 50-000,82/11/19,821(270530
- G./122B0306 Forwards Affidavit of Svc re distribution of FBAR Amend 40 per RS Boyd 781020 ltr to C Reed
 TRAMM-T R Commonwealth Edison Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X
 Fiche 50-000, 82/12/17, 82122B0306
- Q Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Bvc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 62/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240

- 82/8190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermaluminescent Dostmeters " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05. 8208190245
- 8208190251 IE Info Notice 82-44, "Charification of Emergency Plan Exercise Requirements " 8vc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. (09pp. 16411 179 24) Fiche 50-000, 82/11/18.8208190251
- 8212100296 Forwards IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 & notice of violation SPESBARD, R L Division of Project & Resident Programs 82/11/23 REED, C Commonwealth Edison Co 2pp 16376 281 24x Fiche 50-454, 82/11/23, 8212100296
- --8212100302 Notice of violation from insp on 820701-1031 BFESSARD.R L Division of Project & Resident Programs B2/11/23 5pp 16376 283 24% Fiche 50-454.82/11/23.8212100296
- --8212100308 IE Insp Repts 50-454/82-22 & 50-455/82-16 on 820901-1031 Noncompliance noted installation of wireplate incomplete. failure to determine impact of deficiency on testing & care of safety equipment & QC insps not performed FORNEY, W L , CONNAUGHTON, K , HAYES, D W Division of Project & Resident Programs 82/11/19 11pp 16376 288 24x Fiche 50-454,82/11/23,8212100296
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411
- 82/08190257 IE Into Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 355pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 821<a080494 Forwards SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981, per IE 8205/8 mgt meeting Overall regulatory performance satisfactory although specific areas meed to be strengthened KEPPLER, J G Region 3, Office of Director 82/12/02 REED, C Commonwealth Edison Co 3pp 16392 122 24X Fiche 80-454, 82/12/02, 8212080494
- --8212080503 SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of QA program require improvements * Region 3, Office of Director 82/05/31 27pp 16352 125 24X Fiche 50-454,82/12/02.8212080494
- 8212170106 Forwards IE Insp Rept 50-454/82-21 on 821006-29 No noncompliance noted LITTLE.W S Division of Engineering & Technical Progrems 82/12/02 REED. C Commonwealth Edison Co 2pp 16450 311 24X Fiche 30-454, 82/12/02, 8212170106
- ---8212170118 IE Insp Rept 50-454/82-21 on 821006-27 No noncompliance noted Major areas inspected preoperational testing & test results evaluation, previous open items & test program implementation
 RINO, M A. JACKIM, I N Region 3, Office of Director 82/11/24 6pp 16450.313 24% Fiche 50-454,82/12/02,8212170106
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNO.R.C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317. 24K Fiche 50-000, 82/12/03, 8208190259
- B208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Borkets " 8vc list enc! JORDAM:E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064. 24x Fiche 50-000: 82/12/03:8208190261
- B212100324 Ack receipt of B21018 itr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-454/82-12 NORELIUS, C E Division of Engineering & Technical Programs 82/12/07 REED, C. Commonwealth Edison Co 2pp 16377 070. 24X Fiche 50-454, 82/12/07.8212100324

- --8212100330 Responds to NRC 820910 ltr re violations noted in IE Insp. Rept 50-454/82-12 Corrective actions administrative procedures revised to include use of new form for communicating test problems.

 DELOGORGE, LO Commonwealth Edison Co 82/10/18 KEPPLER, J G Region 3, Office of Director 5pp 16377 072 24X Fiche: 50-454, 82/12/07.8212100324
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Honitoring " Svc list encl
 DEYDUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche-50-000,82/12/16,8208190267
- 8908190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list entl JORDANIE L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14628 293 24 Fiche 50-000, 82/12/20,8208190268
- 8212280433 Ack receipt of 821105 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
 NORELIUS, C E Division of Engineering & Technical Programs
 82/12/21 REED, C Commo
- ~-8212280448 Suppls 820817 & 0922 responses to NRC 820424 ltr reviolations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Corrective actions training/qualification records of GC inspectors will be reviewed STIEDE, W L Commonwealth Edison Co 82/11/05 KEPPLER, J G Region 3, Office of Director 3pp 16956-063 24X Fiche 50-454,82/12/21,8212280433
- S Reportable occurrences, LERs & related correspondence
- 9212020329 Interim Deficiency Rept 92-08 re unavailable insprecords for high strength bolt connections of structural steel bolting Initially reported 821021 Reinsp planned Final rept expected by 830115
 IRAMM, T.R. Commonwealth Edison Go 82/11/24 KEPPLER, J.O. Region 3, Office of Director 2pp 16277 277 24X Fichs 50-454, 82/11/24, 8212020329
- 8P12170192 Interim deficiency rept re failure of several dc cables in underground duct Initially reported on 820916 Circuits utilizing faulted cables rerouted so that cables can be pulled for insp Final rept will be provided by 830401 TRAMM, T.R. Commonwealth Edison Co. 82/12/06 KEPPLER, J.G. Region G. 81/12/08 First of Director 2pp 16450 006 24% Fiche 50-494, 82/12/06, RECOUNTED
- DOCKET STN-50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8211290530 Application to amend applications for OL consisting of Amend 40 to FSAR TRAMM, T R Commonwealth Edison Co 82/11/19 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 16227 348 24X fiche 50-000, 82/11/19, 8211290530
- 8P12070177 Requests withholding of proprietary Westinghouse info inadvertantly encl in revisions to App C of FBAR in 820818 & 0902 ltrs re turbine missiles. TRAMM.T R Commonwealth Edison Co 82/11/29 DENYON.H R Office of Nuclear Reactor Regulation, Director 2pp 16329 169 24X Fiche: 50-000.82/11/29.8212070177.
- ~-B212070187 Affidavit re Westinghouse application for withholding proprietary (nfo encl in App C to FSAR in TR Tramm 820818 & 0702 ltrs to NRC concerning turbine missiles COLLIER: A R Westinghouse Electric Corp. 82/11/08 App 16327 171 24X Fiche 50-000-82/11/29-8212070177.
- --B212070198 Forwards nonproprietary version of revised FSAR reprotection against possible turbine missiles
 TRAMM.TR Commonwealth Edison Co B2/09/02, DENTON, HR Office
 of Nuclear Reactor Regulation, Director 35pp, 16329 179 24X
 Ficher 50-000, 82/11/29, 8212070177.
- --B212070207 Forwards nonproprietary version of revisions to FSAR re protection against possible turbine missiles TRAMM.TR Commonwealth Edison Co 82/08/19. DENTON.HR Office of Nuclear Reactor Regulation. Director 70pp 16329 214 24X Fiche. 50-000.82/11/29.8212070177.

- SP12220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations" SMARTZ-E D Commonwealth Edison Co 62/12/14 HAASS.W P Quality Assurance Branch 1p 16518 QO7 24X Fiche 50-000.82/12/14.
- --8212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000,82/12/14.8212220212
- B212280212 Forwards updated schedule for ongoing environ qualification testing programs.per 810528 commitment SHARTIRE D Commonwealth Edison Co 82/12/22 EISENHUT.D Q Division of Licensing 18pp 16956 161 24X Fiche 50-000.82/12/22.
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during uk of 820913
 IRAMM.T R Commonwealth Edison Co. 82/12/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 16329 323 24X Fiche 50-000.82/12/02.8212070249
- 8212300019 Forwards draft SER Buppl 2 for comments & approval Response expected by 821223 W/o encl NOVAK.T H Division of Licensing 82/12/21 ERNST, M Division of Bystems Integration (post 811008) JOHNSTON.W Assistant Director for Amaterials & Gualifications Engineering RUBENSTRIN.L Assistant Director for Core & Flant Bystems 2pp 16624 286 24X Fiche 50-454.82/12/21.8212300019
- F Security, medical, emergency & fire protection plans
- 8212080120 Notification of cancellation of 821207 meeting w/util in Bethesds.ND to discuss fire protection program, specifically, emergency communications sys & sprinklers in cable spreading room CUSHAN, L Licensing Branch 1 82/11/10 YOUNGBLOOD, B J Licensing Branch 1 3pp 16368 288 24X Fiche 50-454,82/11/10,82/2080120
- BR12080494 Forwards BALP Repts 50-454/82-13 & 50-495/82-09 for Jul 1980-Dec 1981.per IE 820518 mgt meeting Overall regulatory performance satisfactory although specific areas need to be strengthened KEPPLER.J 9 Region 3. Office of Director 82/12/02 REED.C Commonwealth Edison Co 3pp 16352 122 24X Fichs 50-454.82/12/02.8212080474
- ---8212080503 SALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of GA program require improvements * Region 3, Office of Director 82/05/31 27pp 16352 125 24x Fichs 50-454,82/12/02,8212080494
- 8212090383 Forwards info re emergency operations facilities per 821182 & 1202 requests Info previously submitted by telcon Request for written response unnecessary burden on licensee DELGEORGEL D. Commonwealth Edison Co 82/12/03 EISENHUT. D 0 Division of Licensing 2pp 16365 051 24X Fiche 50-000.82/12/03, 8212090383
- 8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EO-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
 FELTON, J M Division of Rules and Records 82/12/07 Document Management Branch 1p. 16417 062 24X Fiche 50-000,82/12/07,6212130017
- --8212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents encl PAJONSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC No Detailed Affiliation Given 2pp 16417.063 24X Fiche 50-000,82/12/07,8212130017
- --82(2)30041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
 PAJONEKI, J E. Commonwealth Edison Ca 82/11/29 4pp 16417 065 24% Fiche 50-000.82/12/07.82(2)30017
- 82:12140243 Advises of distribution of revisions to "Generating Station Emergency Plan." Braidwood annex not prepared TRAMMITR Commonwealth Edison Co 82/12/07 DENTON, HR Office of Nuclear Reactor Regulation Director 2pp 16409 302. 24X Fiche 50-000, 82/12/07.82:2140243

- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility KEPPLER.J G Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16.
- 8P12300167 Releases public version of revised generating station emergency plan telephone directory FELTON.J M Division of Rules and Records 82/12/20 Document Hanagement 8ranch 1p 16612 215 24X Fiche 50-000.82/12/20, 8212300167
- --8212300179 Forwards public version of revised generating station emergency plan telephone directory MODRE.R D Commonwealth Edison Co 82/12/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 16612 216 24X Fiche 50-000,82/12/20,8212300167
- --B212300197 Public version of revised generating station emergenty plan telephone directory GALLE, D.P. Commonwealth Edison Co. B2/11/05 GOpp. 16612 217 244 Fiche 50-000, 82/12/20, B2123300167
- GP12290247 Forwards corrected Pages 1-5 & 4-2 of Revision 7 to security plan Pages withheld (ref 10CFR73 21)
 DELGEORGE, L O Commonwealth Edison Co 82/12/22 DENTON, H R
 Office of Nuclear Reactor Regulation, Director ip 16582 111 24X
 Fiche 50-454, 82/12/22.8212290247

& Adjudicatory correspondence

- BP12060010 Response opposing Rockford League of Women Voters 821112 motion to require NRC answers to Rockford 821022 interrogatories Answers unnecessary for proper decision Certificate of 8vc encl GOLDBERG, S.C. Hearing Branch 4 82/12/02 Atomic Safety and Licensing Board Panel 12pp 16313 313 24X Fiche 50-454,82/12/02,8212060010
- 8212070157 Forwards revised Page 3 of NRC 821202 response to Rockford League of Momen Voters motion to require interrogatory answers
 GOLDBERG, S C Hearing Branch 4 82/12/06 SMITH, I W, GOLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 16335 316 24X Ficho 50-454,82/12/06,8212070157
- --0212070161 Revised Page 3 to NRC 921202 response to Rockford League of Momen Voters motion to require interrogatory answers Citation corrected 4 Office of the Executive Legal Director 82/12/06 Atomic Safety and Licensing Board Panel 1p 16335 317 24X Fiche 50-454-82/12/06.8212070157
- 8212080235 Motion for entry of order approving 821206 stipulation re litigation of contentions GQLDBERG: S Hearing Branch 4 DIEWALSKI, A Commonwealth Edison Co * League of Women Voters of Rockford, IL 82/12/06 Atomic Safety and Licensing Board Panel 1p 16354 127 24X Fiche 50-454, 82/12/06,8212080235
- --82i2080245 Stipulation re litigation of contentions Contentions 28, 32, 34, 41, 47, 53, 54, 61, 63, 71 & 77 withdrawn Contentions 8, 19, 22, 39, 42, 62, 106, 108, 109, 112 & portions of 111 will be litigated GOLDBERG, S Hearing Branch 4 BIEMALSKI, A Commonwealth Edison Co * League of Women Voters of Rockford, IL 82/12/06 9pp 14354 128 24% Fiche 50-454, 82/12/06, 8212080239
- 8P12090231 Response opposing Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821118 motion to direct NRC to commence special insp ASLB lacks authority to supervise regional investigation.or dictate pace GOLDBERG.S C Hearing Branch 4 82/12/08 Atomic Safety and Licensing Board Panel 3pp 16361 322 24X Fiche 30-454,82/12/08,6212990231
- --8212070236 Affidavit of DW Hayes providing status of Region 3 special insp on allegations re GA/GC Certificate of Svc encl HAYES, D W Division of Project & Resident Programs 82/12/07 Spp 16361 325 24X Fiche: 50-454.82/12/08.8212070231
- SP12200102 Memorandum & order denying Dakalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ 821118 motion to direct NRC to commence special investigation into allegations on QA/QC ASLB lacks requisite authority SMITH, I W Atomic Safety and Licensing Board Panel 82/12/16 DeKalb Area Alliance for Responsible Energy 1p 16470 148 24X Fiche 50-454,82/12/16,8212200102

- GP12200107 Memorandum & order approving joint party 821206 stipulation on procedural problems.w/one listed revision COLE.R F . SMITH.I H Atomic Safety and Licensing Board Panel B2/12/16 2pp 16470 094 24X Fiche 50-454.82/12/16.8212200107
- 8212200113 Supplemental response to Rockford League of Homan Voters proposed interrogatories to NRC Certificate of Svc oncl RAHSON, J Hearing Branch 4 82/12/17 League of Homen Voters of Rockford, IL 12pp 16470 164 24X Fiche 50-454,82/12/17, 8312300113
- 8212280188 Answers to NRC second set of interrogetories re Contention IA Certificate of 8vc encl Related correspondence MDRRISON.P League of Homen Voters of Rockford, IL 82/12/22 Office of the Executive Legal Director 3pp 16562 268 24X Fiche 30-454, 82/12/22, 8212280188

- 8212280176 Notifies of change in mailing address for NRC licensing mat!
 WRIGHT, O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health). 82/12/20 EISENHUT, D 9 Division of Licensing 19 16556 135 24% Fiche S0-000, 82/12/20, 8212280176
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8211290530 Application to amend applications for OL, consisting of Amend 40 to FBAR TRAMM, TR Commonwealth Edison Co 82/11/19 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X Fiche 50-000, 82/11/19, 8211290530
- --8211270559 Amend 40 to FBAR # Commonwealth Edison Co 82/11/30 234pp 16227 351 24X Fiche 50-000, 82/11/19, 8211270530
- 8212280306 Forwards Affidavit of Svc re distribution of FEAR Amend 40 per R5 Boyd 781020 ltr to C Reed
 TRAMM, T R Commonwealth Edison Co 82/12/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X
 Fiche 50-000, 82/12/17, 8212280306
- O Inspection reports. IE Bulletins & correspondence
- 8:08170240 IE Builatin 82-03. Revision 1, "Stress Cracking in Thick-Hall. Large-Diameter. Stainless Strel. Recirculation Sys Piping at BWR Plants "Sve list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enc!
 CDBB.L I Division of Fuel Facilities. Materials & Safeguards Consolidated Edison Co of New York. Inc 110pp 16372 148 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list enci JRDAN;E L. Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche, 50-000, 82/11/18, 8208190251
- BP12100276 Forwards IE Insp Repts 50-454/82-22 & 50-455/82-16 on B20701-1031 & notice of violation SPESSARD, R L Division of Project & Resident Programs B2/11/23 REED, C Commonwealth Edison Co 2pp 16376 281 24X Fiche 50-454, 82/11/23, 8212100276
- --B212100302 Notice of violation from insp on 820901-1031 8PE89ARD, R L. Division of Project & Resident Programs B2/11/23 5pp 16376,283 24X Fiche 50-454,82/11/23,8212100296
- --B212100308 IE Insp Repts 50-454/B2-22 & 50-455/82-16 on B20701-1031 Noncompliance noted installation of wireplate incomplete, fallure to determine impact of deficiency on testing & care of safety equipment & GC insps not performed FORNEY, W L , CONNAUGHTON, K , HAYES. D W Division of Project & Resident Programs B2/11/19 11pp 16376 288 24X Fiche 50-454,82/11/23,8212100276
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256

- 8008190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list anc) C088.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 80-000,82/11/30,8208190257
- 8212080494 Forwards SALP Repts SD-454/82-13 & 50-455/82-09 for Jul 1780-Dec 1781.per IE 820518 mgt meeting Overall regulatory performance satisfactory although specific areas need to be strengthened KEPFLER, J O Region 3. Office of Director 82/12/02 REED. C Commonwealth Edison Co 3pp 16352 122 24X Fiche 50-454,82/12/02,8212980494
- --8212080503 BALP Repts 50-454/82-13 & 50-455/82-09 for Jul 1980-Dec 1981 Procedure control & implementation of GA program require improvements * Region 3. Office of Director 82/05/31 27pp 16352 125 24x Fiche 50-454.82/12/02.8212080494
- 8208190289 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-600, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,9208170261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, 8208190267
- 820B190248 IE Info Notice 82-50, "Mad of Golid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 14628 293 24) Fiche 50-000.82/12/20.820B190268
- 8212280433 Ack receipt of 821105 ltr informing MRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
 NORELIUS, C E Division of Engineering & Technical Programs 82/12/21 REED. C Commonwealth Edison Co 2pp. 16556 061 24X
 Fiche 50-454.82/12/21.8212280433
- --B212280448 Suppls 820817 & 0922 responses to NRC 820624 ltr reviolations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Corrective actions training/qualification records of GC inspectors will be reviewed STIEDE.# L. Commonwealth Edison Co. 82/11/05 KEFPLER, J. G. Region 3. Defice of Director 3pp. 14554 043 24X Fiche 50-454,82/12/21,8212280433

S Reportable occurrences. LERs & related correspondence

- 8212020329 Interim Deficiency Rept 82-08 re unavailable insprecords for high strength bolt connections of structural steel balting Initially reported B21021 Reinsp glanned final rept expected by 830115
 TRAMMIN R Commonwealth Edison Co 82/11/24 KEPPLER, J. G. Region 3, Office of Director 2pp 14277 277 24X Fiche 50-454,82/11/24,
- 8212170192 Interim deficiency rept re failure of several do cables in underground duct Initially reported on 820916 Circuits utilizing faulted cables renouted so that cables can be pulled for insp Final rept will be provided by 830401 TRAMM.TR Commonwealth Edison Co 82/12/06 KEPPLER.J O Region 3. Office of Director 2pp 14450 006 24X Fiche 50-454,82/12/06,8212170192

DOCKET STN-50-456 BRAIDHOOD STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B212010014 Forwards order *rtending const completion dates for CPPR-132 from 821101 to 800430. in response to 820930 itr Safety evaluation also encl EISENHUT, D C Division of Licensing 82/11/15 DELGEORGE, L. C Commonwealth Edison Co 2pp 16290. 208 24% Fiche 50-456, 82/11/15, 8212010014.

- --8212010017 Order extending const completion date for CPPR-132 from 821101 to 880430 EISENHUT, D g Division of Licensing 82/11/15 Commonwealth Edison Co 3pp 14290 210 24X Fiche 50-456, 82/11/15, 8212010014
- --8212010020 Safety evaluation supporting extension of const completion dates for CPPR-132 & CPPR-133 to 870430 & 880430, respectively OLSHAN, L., YOUNGBLOOD, B. J. Licensing Branch 1 82/11/08 4pp 16290 213 24X Fiche 50-456,82/11/15.8212010014
- 8211290530 Application to amend applications for OL, consisting of Amend 40 to FSAR TRAMM-T R Commonwealth Edison Co 82/11/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24X Fiche 50-000,82/11/19,8211290530
- 8212070177 Requests withholding of proprietary Westinghouse info inadvertantly encl in revisions to App C of FSAR in 820818 & 0902 ltrs re turbine missiles TRAMM.T R Commonwealth Edison Co 82/11/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16329 169 24X Fiche 50~000.82/11/29.8212070177
- --B212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FSAR in TR Tramm B20818 & 0902 ltrs to NRC concerning turbine missiles COLLERA R Westinghouse Electric Corp B2/11/08 Bpp
- --82/2070198 Forwards nonproprietary version of revised FSAR re protection against possible turbine missiles TRAMM.IR Commonwealth Edison Co 82/09/02 DENJON,H R Offic, of Nuclear Reactor Regulation, Director 35pp, [4829 179 24X Fiche 50-000,82/11/29,8212070177
- --8212070207 Forwards nonproprietary version of revisions to FSAR reprotection against possible turbine missiles
 TRAMM.T R Commonwealth Edison Co 82/08/18 DENTON.H R Office
 of Nuclear Reactor Regulation, Director 70pp 16329 214 24X
 Fiche 50-000,82/11/29/8212070177
- 8P12220212 Forwards Revision 22 to CE-1-A, "QA Program for Nuclear Generating Stations" SWARTZ.E D Commonwealth Edison Co 62/12/14 HAASS.W P Quality Assurance Branch Ip 16518 007 24X Fiche 50-000,82/12/14. 6212220212
- --8212220231 "GA Program for Nuclear Generating Stations." Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17pp 16518 009 24X Fiche 50-000,82/12/14,8212220212
- B212280212 Forwards updated schedule for ongoing environ qualification testing programs.per 810528 commitment SHARTZ.E.D. Commonwealth Edison Co. 82/12/22 EISENHUT,D.Q. Division of Licensing 18pp. 16556 161 24X Fiche 50-000.82/12/22.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- Bil2070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during wk of 820913
 TRANM.TR Commonwealth Edison Co. 82/12/02 DENTON.HR Office of Nuclear Reactor Regulation. Director 5pp 16329 323 24X
 Fiche 50-000.82/12/02.8212070249
- F Security, medical, emergency & fire protection plans
- 8212090383 Forwards info re emergency operations facilities per 821122 & 1202 requests. Info previously submitted by telcon Request for written response unnecessary burden on licensee DELOEOROE, L O Commonwealth Edison Co 82/12/03 EISENHUT. D 6 Division of Licensing 2pp 16365 051 24% Fiche 50-000.82/12/03, 8212090383
- B212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EO-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 FELTON.J.M Division of Rules and Records B2/12/07, Document Management Branch ip 16417 062 24X Fiche 50-000, B2/12/07, B212130017.
- --B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure E0-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "Revised table of contents enc! PAJJUNSKI, J Commonwealth Edison Co 82/11/01 DENTON, H R NRC -No Detailed Affiliation Given 2pp 16417 063 24X Fiche: 50-000, 82/12/07, 8212130017

- --B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2: "Fre-Established Onsite & Offsite Monitoring Locations (Maps)"
 PAJGMENIJ E Commonwealth Edison Co B2/11/29 4pp 16417 065 244 Fiche 50-000.82/12/07.8212130017
- 8P12140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMM.TR Commonwealth Edison Co 82/12/07 DENTON,HR Office of Nuclear Reactor Regulation. Director 2pp 16409 302 24X Fishe 50-000.82/12/07.8212140243
- 8212220306 Discusses layout of communications equipment required in control room, ensite technical support ctr & near-site emergency operations facility
 KEPPLER.J G Region 3, Office of Director 82/12/16
 Commonwealth Edison Co. 3pp 16503 351 24X Fiche 50-000,82/12/16.

- BP12280176 Notifies of change in mailing address for NRC licensing mat!
 WRIGHT.O N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT.D O Division of Licensing p 16556 135, 24% Fiche 50-000,82/12/20,8212280176
- K Utility Final Safety Analysis Report (FSAR) & amends
- B291290530 Application to amend applications for OL:consisting of Amend 40 to FSAR
 TRAMM.TR Commonwealth Edison Co \$2/11/19 DENTON.HR Office of Nuclear Reactor Regulation, Director 3pp 16227 348 24% Fiche 50-000. B2/11/19, B211290530
- --8211270557 Amend 40 to FSAR

 * Commonwealth Edison Co 82/11/30 234pp 16227 351. 24X
 Fiche 50-00,82/11/19,8211270530
- ER12280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40 per RS Boyd 781020 ltr to C Reed TRAMM.T R Commonwealth Edison Co 92/12/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X Fiche 50-000, 82/12/17,8212280306
- G Inspectson reports. IE Bulletins & correspondence
- 87/08170240 IE Gulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter: Stainless Steel. Recirculation Sys Piping at BMR Plants "Svc list encl
 bEYOUND.R C Director's Office. Office of Inspection and
 Conferement 82/10/28 Consolidated Edison Co of New York. Inc
 112pp 16462 163 24X Fichs 50-000. 82/10/28. 8208190240
- 82/08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermaluminescent Dosimeters " Svc list enc! COSB,L I Division of Fuel Facilities, Materials & Safeguards 82/11/09 Consolidated Edison Co. of New York, Inc.
- COSB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24% Fiche 50~000,82/11/05.8208190245
- 8:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl URDAN: EL Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8200190296 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list enc! DEYOUNG: C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc. 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8200190256
- BP08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc. 354pp 16387 028 24X Fiche 50-000.8R/11/30.8208190257
- 8PO8190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " 8vc list encl DEYOUND R. C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc. 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8:°OB190261 IE Info Notice 82~48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp 16462 064 24 Fiche.50-000, 82/12/03,8208170261.

- 8212270275 Forwards IE Insp Rept 50-456/82-06 on 82102-22 & 26-27 & notice of violation
 NORELUG. C Division of Engineering & Technical Programs
 82/12/10 REED. C Commonwealth Edison Co 2pp 16530 069 24X
 Fiche 30-456.82/12/10.8212270275
- --8212270308 Notice of violation from insp un B21021-22 & 26-27 NORELIUS: C E Division of Engineering & Technical Programs B2/12/10 5pp 16530 071 24X Fiche 50-484, B2/12/10, B212270275
- --8212270318 IE Insp Rept 50-454/82-06 on 821021-22 & 26-27 Noncompliance noted failure to translate design criterion into Tech Specs. power cable insp not adequately performed & nonconforming components not controlled or identified MENDEZ, R, NATDU, K, WILLIAMS, C C Region 3, Office of Director 82/12/03 9pp 16530 076 24% Fiche 50-456,82/12/10,8212270275
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc!
 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267.
- 8708190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type IYE-27" Svc list encl JORDAN, E. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8212010014 Forwards order sitending const completion dates for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430, in response to 820430 ltr Bafety evaluation also encl EISEMMUT, DO Division of Licensing 82/11/15 DELGEDROE, L O Commonwealth Edison Co 2pp 16270 208 24% Fiche 50-456, 82/11/15, 8212010014
- --8212010017 Order extending const completion date for CPPR-132 from 821101 to 870430 & CPPR-133 from 831101 to 880430 EISENHUT, D g Division of Licensing 82/11/15 Commonwealth Edison Co 3pp 16270 210 24X Fiche 50-436,82/11/15.8212010014
- --8212010020 Safety evaluation supporting extension of const completion dates for CPPR-132 & CPPR-133 to 870430 & 880430, respectively GLSHAN, L., YOUNOBLOOD, B. J. Licensing Branch 1, 82/11/08 4pp 16290 213 24X Fiche, 50-456, 82/11/15, 8212010014
- 8211290530 Application to amend applications for DL, consisting of Amend 40 to FBAR TRAMM, T.R. Commonwealth Edison Co. 82/11/19 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director Spp. 16227 348 24X Ficha 30-000, 82/11/19, 8211290530.
- 8212070177 Requests withholding of proprietary Westinghouse info inadvertantly encl in revisions to App C of FSAR in 820818 & 0902 Its re turbine missiles TRAMM.T R Commonwealth Edison Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16329 169 24X Fichs 50-000.82/11/29,8212070177
- --8212070187 Affidavit re Westinghouse application for withholding proprietary info encl in App C to FSAR & in TR Tramm 820818 & 0902 ltrs to NRC concerning turbine missiles CCLLIER, A R. Westinghouse Electric Corp 82/11/08 Bpp 16329 171 24X Fiche: 50-000, 82/11/29,8212070177
- --B212070198 Forwards nonproprietary version of revised FSAR reprotection against possible turbine missiles, TRAMM.TR Commonwealth Edison Co B2/09/02 DENTON.HR, Office of Nuclear Reactor Regulation, Director. 35pp 16329 179 24X Fiche 50-000,82/11/29.8212070177.
- --B212070207 Forwards nonproprietary version of revisions to FBAR re protection against possible turbine missiles. TRAMM.TR Commonwealth Edison Co B2/08/18 DENTON.HR Office of Nuclear Reactor Regulation. Director. 70pp. 16329 214. 24X Ficha 50-000, 82/11/29, B212070177
- SPI2220212 Forwards Revision 22 to CE-i-A, "GA Program for Nuclear Generating Stations" SMARTJE, D. Commonwealth Edison Co. 82/12/14 HAASS, W.P. Quality Assurance Branch ip. 16518 007 24X Fiche 50-000, 82/12/14, 8212220219

- --8212220231 "GA Program for Nuclear Generating Stations," Revision 22 * Commonwealth Edison Co CE-1-A R22 82/11/01 17cp 16518 009 24X Fiche 58-000.82/12/14.8218220212
- 8212280212 Forwards updated schedule for ongoing environ qualification testing programs, per 810528 commitment
 SHARTZ.E D Commonwealth Edison Co 82/12/22 EISENHUT.D 0
 Division of Licensing 18pp 16556 161 24X Fiche 50-000,82/12/22,
 8212280212
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8212070249 Clarifies seismic qualification program & pump valve operability program evaluated in SER & reviewed in audit during wk of 820913

 TRAMM.T R. Commonuealth Edison Co. 82/12/02 DENTON.H R. Office of Nuclear Reactor Regulation, Director 5pp 16329 323 24X Fiche 50-000, 82/12/02.8212070249
- F Security, medical, emergency & fire protection plans
- 8212090393 Forwards info re emergency operations facilities per 821122 & 1202 requests Info previously submitted by telcon. Request for written response unnecessary burden on licensee DELOGERGE, L. O. Commonwealth Edison Co. 82/12/03 FIERHHUT.D 0 Division of Licensing 2pp 16365 051 24X Fiche 50-000,82/12/03,8212090393
- 8212130017 Releases public version of Revision 1 to Emergency Plan Implementing Procedure EO-2. "Pre-Established Onsite & Offsite Monitoring Locations (Maps)"
 FELTON. J M Division of Rules and Records 82/12/07 Document Management Branch ip 16417 062 24X Fiche 50-000,82/12/07. 8212130017
- --B212130028 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) " Revised table of contents enc! PAJONSKI, J. Commonwealth Edison Co. 82/11/01 DENTON.H R. NRC No Detailed Affiliation Given 2pp 16417-063 24% Fiche 50-000.82/12/07.8212130017
- --B212130041 Public version of Revision 1 to Emergency Plan Implementing Procedure EG-2, "Pre-Established Onsite & Offsite Monitoring Locations (Maps) "
 PAJDMSKI,J E Commonwealth Edison Co 82/11/29 4pp 16417 065 244 Fiche 50-000-82/12/07, 8212130017
- B212140243 Advises of distribution of revisions to "Generating Station Emergency Plan" Braidwood annex not prepared TRAMM, T R Commonwealth Edison Co 82/12/07. DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 16409 302 24X Fichs 50-000, 82/12/07, B212140243
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & mear-site emergency operations facility
 KEPPLER.J O Region 3. Office of Director
 Commonwealth Edison Co 3pp 16503 351 24X Fiche-50-000, 82/12/16, RB12203064
- H General correspondence
- B212280176 Notifies of change in mailing address for NRC licensing mat1 MRIGHT, G N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) B2/12/20. EISENHUT. D G Division of Licensing Ip 16556 135 24x Fiche 50~000, 82/12/20, 8212280176
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8P11290830 Application to amend applications for GL.consisting of Amend 40 to FSAR
 TRANH.T R Commonwealth Edison Co 82/11/19 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 3pp 16227:348 24X
 Fiche 50-000.82/11/19.2211290830
- --8231290559 Amend 40 to FSAR # Commonwealth Edison Co 82/11/30 234pp 16227.351 24X Fiche 50-000,82/11/19.8211290530
- 8212280306 Forwards Affidavit of Svc re distribution of FSAR Amend 40 per RS Boyd 781020 ltr to C Reed TRAMM.T R. Commonwealth Edison Co. 82/12/17 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 16561 095 24X Fiche 50-000,82/12/17.8212280306

- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYDUNG, R C Director's Office, Office of Inspect) on and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 820Bi90245 IE Info Notice 02-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 30-000.82/11/05,8208170245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24 Fiche 50-000.82/11/18.8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc
 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- B20B190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list entl COBE.L Division of Fuel Facilities, Materials & Safeguards B2/11/30. Consolidated Edison Co of New York
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, luc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82~48. "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDÁN.E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24X Ficha 50~000.82/12/03.8208190261
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYDUNO,R.C Director's Office. Office of Inspection and Enforcement 62/12/16 Consolidated Edison Co of New York, Inc 127pp 16628,191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN-E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- DUCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR, Big Rock Point Dresden I. Humboldt Bay. applicants for OL & holders of CP re transmittal of NOREO-0763 & NOREO-0769 Svc list encl W/o stated encl EISENHUT, D O Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066
- BP12220274 Forwards action plan addressing add1 containment issues raised in NRC 820623 & 0723 ltrs Util will summarize responses to containment issue approx 30 days after end of owners group program Cross ref of containment issues encl. BCOKER. J E GUIF States Utilities Co 82/12/09 SCHWENCER. A Licensing Branch 2 59pp id517 294 24X Fiche 50-458, 82/12/09, 82/12220274
- BD12220049 Forwards clarification of NRC criteria re remote shutdown station designs.per util 820813 position on remote shutdown capability W/o encl SCHWENCER.A Licensing Branch 2 82/12/13 CAHILL.W J Oulf States Utilities Co 2pp 16526 353, 24X Fichs 50-458,82/12/13,8212220049

1

F Security, medical, emergency & fire protection plans

8212270491 Requests additinfore emergency plan. Revised plan should be submitted within 60 days of receipt of ltr List of required info & comments encl SCHMENCER. A Licensing Branch 2 82/12/16 CAHILL, W J Owlf States Utilities Co 27pp 16551 016 24X Fiche 50-458,82/12/16,82(2270491

G Adjudicatory correspondence

- G9:12100117 Motion for extension of time until 840115 to file contentions Util requested extensions of CP until 851231 so that scedule for OL hearing will probably slip SER will not be issued until 831202 Certificate of 8vc encl LINDSEY.I D Louisiana, State of 82/12/02 Commissioners 4pp 16374 015 24X Fiche 50-458, 82/12/02.8212100117
- 8212230192 Contentions of State of LA Certificate of Evc encil LINDSEY.I D Louisians, State of 82/12/15 Atomic Safety and Licensing Board Panel 8pp 16511 112 24X Fichs 50-458,82/12/15, 821220192
- GP12210261 Response in opposition to State of LA B21202 motion for extension of time within which to file contentions Thirtaen-month delay would significantly interfere w/timely completion of hearing Certificate of Svc encl CONNER, T B , KETTERHAHMM J Oulf States Utilities Co CONNER, T B Conner & Wetterhahm B2/12/17 Atomic Safety and Licensing Board Panel. Bpp 16483 258 24% Fiche 50-458, 82/12/17, 8212210261
- 63:12230215 Order granting State of LA 821202 motion for extension of time for filling contentions Contentions must be filed by 830315, answers by 830415 & responses by 830503 Prehearing conference will be held on 830524 COTTER.8 P Atomic Safety and Licensing Board Panel 82/12/21 Louisiana, State of 2pp 16511 047 24X Fiche 50-458, 82/12/21, 8212230215
- BE12230315 Forwards order, granting in part & denying in part, motion for extension of 13 months to file contentions Order reconstituting ASLB by appointment of 6A Linenberger also encl W/o encl COTYER, 8 P Atomic Safety and Licensing Board Panel 82/12/21 LINDSEY, I D Justice, Dept of 1p 16511 125 24X Fiche 50-45B, 82/12/21, 8212230315

G. Inspection reports. IE Bulletins & correspondence

- 8208170240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Hall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24X Fiche 50-000.82/10/28.8208170240
- 8708190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model GO1 & Model GO2 Thermoluminescent Dosimeters " Svc list rnc! COBB.L I Division of Fuel Fatilities, Materials & Safeguards 62/11/05. Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDANIE L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18, 8208190251
- 8708190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks "Svc list enc! DEYOUNG.R C Director's Office. Office of Inspection and Enforcement. 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411:065 24X Fiche 50-000.82/11/26.8208190256
- 8PO8190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CO88.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc. 356pp 16387 028 244 Fiche 50-000.82/11/30.8208190257.
- 9212200076 Forwards IE Insp Rept 50-458/82-14 on 921001-31 No honcompliance noted MADSEN.O L Division of Resident, Reactor Project & Engineering Programs 82/12/01 CAHILL.W J Gulf States Utilities Co 2pp 14470 030 24X Fichs 50-458,82/12/01,8212200076

- --B212200086 IE Insp Rept 50-458/82-14 on 821001-31 No noncompliance noted Hajor areas inspected followup of previous inspected followup of previous inspection findings licensee identified const deficiencies: safety-related pipe welding & reactor coolant pipe welding BROWN.R L . CROSSMAN.W A Division of Resident. Reactor Project & Engineering Programs 82/12/01 6pp. 16470 032 24X Fiche 50-458.82/12/01.8212200076
- 8212100236 Ack receipt of 820809 & 1101 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-459/82-03 MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/12/02 CAHILL, H J Gulf States Utilities Co Ip 16376 064 24X Fiche 50-458,82/12/02.8212100236
- --B212100239 Responds to NRC 820708 & 0929 ltrs re violations noted in IE insp. Rept 50-458/82-03 Corrective actions pipe supports designed per ABME code requirements BOOKER.JE Outf States Utilities Co. 82/11/01 COLLINS.JT Region 4. Office of Director. 2pp 16376 065 24X Fiche 50-458.82/12/02.82/1200236
- BPOB190259 IE Bulletin B2-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG-R C Director's Dffice. Dffice of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B20B190261 IE Info Notice 82-48, "Failures of Agastat CR 0093 Relay Sockets." Svc list encl JORDAN, E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 820B190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Cas Monitoring." Svc list encl
 BEYQUNG.R C Director's Office, Office of Inspection and
 Enforcement 82/12/14 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc 108μp 16688 293 24X Fiche 50-000, 82/12/20,8208190268

8 Reportable occurrences, LERs & related correspondence

- BP12100033 Interim deficiency rept re cracked, spalled & chipped concrete around main steam & other penetrations through drywell wall to steam tunnel Initially reported on B20806 Investigation continuing Next rept will be issued by B30127 BQDKER, J E Ouif States Utilities Co 82/12/03 COLLINS, J T Region 4. Office of Director 1p 16379 035 24X Fiche 50-458, 82/12/03, 8212100033
- 8212210176 Interim deficiency rept re violation of requirements for min spacing between drills in anchors & adjacent embedment plates initially reported on 821109 Investigation re reporting criteria continuing Next rept expected by 830127 BODKER, J E Quif States Utilities Co 82/12/09 COLLINS, J T Region 4. Office of Director 1p 16484 249 24% Fiche 50-458, 82/12/09, 8212210176
- BRI 2210136 Fine 1 Deficiency Rept DR-68 re application of non-specified preservative (Tactyl 506) on high pressure core spray diesel engine pistons & valve mechanisms Initially reported on B21122 All Yectyl 506 to be removed BUDKER, J E Quif BEates Utilities Co 82/12/10. COLLINS, J T. Region 4, Office of Director 2pp 16485 144 24X Fiche 50-458, 82/12/10,8212210136
- B2122701B3 Interim deficiency rept re installation & insp of undersized fillet weld Initially reported on B2111B Investigation not completed Next rept expected by B303227 BOOKER.J E Oulf States Utilities Co 82/12/15 COLLINS.J T Region 4. Office of Director ip 16534 362. 24X Fichs.50-458,82/12/15,8212270183
- 8212270236 Interim Deficiency Rept DR-72 re improper installation, testing & insp of concrete drilled in expansion-type anchors Initially reported on 820830 Investigation complete. Final rept to be submitted by 830228 BOOKER.J E. Gulf States Utilities Co 82/12/15 COLLINS, J T Ragion 4, Office of Director ip 16530 356, 24X Fiche 50-458,82/12/15,8212270236
- B212280196 Interim Deficiency Rept DR-79 re failure to follow weld procedures on field weld Initially reported on 82123 Investigation continuing Next rept expected by 830228. HOCKER. J E Oulf Btates Utilities Co 82/12/17. COLLINS. J T Region 4. Office of Director ip 16562 090 24X Fiche: 50-458, 82/12/17, 8212280196

8212280252 Interim Deficiency Rept DR-80 re Transamerica Delaval piston stirt castings installed in emergency diesel generator engines Initially reported on 821124 Evaluation cannot proceed until const around blog complete Nert rept 830530 BOOKER, J E Gylf States Utilities Co 82/12/17 COLLINS, J T Region 4, Office of Director 1p 16561 270 24X Fiche 50-458, 82/12/17,8212280252

DOCKET SO-459 RIVER BEND STATION: UNIT 2

- A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BHR licensees of operating reactors except LACEHR, Big Rock Point, Dreaden i, Humboldt Bau, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0789 Svc list encl H/o stated encl EISENHUI, D O Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16397 004 24X Fiche 50-000,82/11/15,8211230066
- 8212220274 Forwards action plan addressing addl containment issues raised in NRC 820623 & 0723 ltrs Util will summarize responses to containment issue approx 30 days after end of owners group program Cross ref of containment issues encl BROKER. J E Quif States Utilities Co 82/12/09 SCHMENCER. A Licensing Branch 2 59pp 16517 274 24X Fiche 50-458.82/12/09.8212220274
- 8212220049 Forwards clarification of NRC criteria to remote shutdown station designs, per util 820813 position on remote shutdown capability M/o encl
 SCHMENGER.A. Licensing Branch 2 82/12/13 CAHILL.W.J. Oulf States Utilities Co. 2pp. 16526 353 24% Fiche 30-458.82/12/13.8212220049

F. Security, medical, emergency & fire protection plans

- G Adjudicatory correspondence
- 8P12100117 Motion for extension of time until 840115 to file contentions Util requested extension of CP until 851231 so that scedule for OL hearing uill probably slip SER will not be issued until 831202 Certificate of Svc encl iNDSEY: I D Louisiana, State of 82/12/02 Commissioners 4pp 16376 015 24X Fiche 50-458,82/12/02,8212100117
- 8212230192 Contentions of State of LA Certificate of Svc encl LINDSEY, I D Louisiana, State of 82/12/15 Atomic Safety and Licensing Board Panel, Spp 16511 112 24X Fiche 50-458.82/12/15, 82/2230192
- B212210261 Response in apposition to State of LA B21202 motion for extension of time within which to file contentions. Thirteenmenth delay would significantly interfere w/timely completion of hearing Certificate of Svc encl CONNER. T B . WETTERHAMN.M J Gulf States Utilities Co CONNER. T B . Conner. & Wetterhahn 82/12/17 Atomic Safety and Licensing Board Panel Bpp. 16489 258 24% Fiche 50-458.82/12/17.8212210261
- 8212230215 Order granting State of LA 821202 motion for extension of time for filing contentions. Contentions must be filed by 830315.answers by 830415 & responses by 830503 Prehearing conference will be held on 830824 COTTER.S P Atomic Safety and Licensing Board Panel. 82/12/21 Louisiana. State of 2pp 16511 047 24X Fiche 50~458,82/12/21,8212230215
- 82:2230315 Forwards order granting in part & denying in part, motion for extension of 13 months to file contentions Order reconstituting ASLB by appointment of CA Lineaberger also oncl W/o encl
 COTTER.B P Atomic Safety and Licensing Sound Panel 62/12/21
 LINDSEY, I.D Justice, Dept of 1p 16511 125 24X
 Fiche 50-458, 82/12/21, 8212230315
- A Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter: Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list end!
 DEYOUNG, R C. Director's Defice, Office of Inspection and Enforcement. B2/10/28. Consolidated Edison Co. of New York, Inc 112pp 16462 163 24% Fiche. 50-000, 82/10/28, 8208190240

- 8208170245 IE Info Notice 62-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/09 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fichs 50-000.82/11/05,8208170245
- 6208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JGRDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24 Fiche 50-000,82/11/18.8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24% Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I, Division of Fuel Facilities, Materials & Safeguards 82/11/30, Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNO, R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8POB190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03,8208190261
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYGUNO.R C Director's Office, Office of Inspection and Enforcement \$2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 62/12/16, 8208190267
- 8208190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc! JORDAN E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- S Reportable occurrences, LERs & related correspondence
- 8212210136 Final Deficiency Rept DR-68 re application of non-specified preservative (Tectyl 806) on high pressure core spray diesel engine pistons & valve mechanisms Initially reported on 82122 All Tectyl 506 to be removed 800KER. J E Gulf States Utilities Co 82/12/10 COLLINS. J T Region 4. Office of Director 2pp 16485 144 24X Fiche 50-458, 82/12/10, 8212210136
- DDCKET 50-460 WPP88 NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8212230J63 Trip rept of Commissioners Gilinsky & Abbott 821202 sate visit Agenda & vieugraphs enc! ABBOTT E C Commissioners 82/12/17 Commissioners 26pp 16511 170 24X Fiche 50-397,82/12/17,8212230363
- 9212280440 Requests that Topical Repts BAW-10092P, Revision 3 & BAW-10154P be considered as part of OL application for Unit i so that work on TMI Action Item II K 3 30 can commence BOUCHEY, O D Washington Public Power Supply System 82/12/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16556 057 24X Fiche 50-460, 82/12/21,8212280440
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8212060341 Forwards request for addl info needed to complete review & prepare SER input
 NOVAN.T M. Assistant Director for Licensing 82/11/26,
 FERGUSON.R L Washington Public Power Supply System 18pp
 16323 327 24X Fiche 50-460,82/11/26.8212060341

F Security, medical, emergency & fire protection plans

8212100256 Forwards util 800616 & 1212 & 810320 & 0408 ltrs reemergency response facilities (ERF) in response to Generic Ltr 81-10.per NRC request Util does not plan to provide backup ERF Requested info provided BOUCHEY, 0 D Washington Public Power Supply System 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 14376 149 24X Fiche 50-377.82/12/03.8212100256

@ Adjudicatory correspondence

- 8212020344 Order scheduling 830119-20 prehearing conference in Richland. MA to discuss standing of parties, specific issues to be considered at evidentiary hearing, scheduling & possible consolidation GROSSMAN. H Atomic Safety and Licensing Board Panel 82/11/30 4pp 16277 255 24X Fiche 50-460.82/11/30,8212020344
- 8212020360 Order scheduling 830119-20 special prehearing conference in Richland.WA re standing of parties, specific issues to be considered at evidentiary hearing & further scheduling GROSSMAN.H Atomic Sefety and Licensing Board Panel 82/12/01 4pp 16278 018 24X Fiche 50-460,82/12/01,8212020360
- 8212080272 Ack receipt of 821110 ltr requesting intervention as interested state to make limited appearance statement. Statement allowable w/o intervening Intervention requests will be considered at prehearing conference GROSSMAN. H Atomic Safety and Licensing Board Panel 82/12/06 LEWIS.N D Washington, State of 1p 16354 210 24X Fiche 50-460.82/12/06.8212080272
- B212140418 Motion for delay of B30119 & 20 prehearing conference Schedule burdensome due to two major holiday periods Four days of preparation lost Certificate of Svc encl BELL.N Coalition for Safe Power B2/12/09 Atomic Safety and Licensing Board Panel 3pp 16403 312 24X Fiche 50-397, 82/12/09, 8212140418
- BP12200104 Order rescheduling 830119 & 20 prehearing conferences for B30106-27 Coelition for Safe Power allowed to file suppls to requests for hearing no later than 15 days before conference GROSSMAN.H Atomic Safety and Licensing Board Panel B2/12/15 2pp 16470 089 24% Fiche 50-397,82/12/15,8212200104
- S212230314 Requests supplemental pleadings be served on applicant counsel in Washington.DC per ASLB 821215 order Pleadings expected by 830111 Pleadings served to util in Richland,WA do not constitute svc in proceeding REYNOLDS.N S Debevoise & Liberman REYNOLDS.N S Washington Public Power Supply System 82/12/20 ROSOLIE.E Coalition for Safe Power ip 16507 027 24X Fiche 50-397.82/12/20,8212230314
- 8212270327 Response supporting Coalition for Safe Power 821209 motion for 1-wk delay of prehearing conference scheduled for 830119-20 Applicant does not concede that basis for request constitutes good cause Certificate of Svc entl REVNOLDS:N S Washington Public Power Supply System REYNOLDS:N S Boevelse & Liberman 82/12/22 Atomic Safety and Licensing Board Panel 5pp 16530 184 24X Fiche 50-460.82/12/22,8212270329
- BE:12280277 Forwards repsonses to petitioner motion for delay of 630119 & 22 prehearing conference, for inclusion in records Related correspondence Wid encl REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Hashington Fublic Power Supply System 82/12/22 ORDSSMAN, H Atomic Safety and Licensing Beard Panel ip 16561 311 24X Fiche 50-397, 82/12/22, 8212280277
- B212280274 Response in opposition to Coalition for Safe Power B21207 motion for delay of 830119 \$ 20 prehearing conference Allegations set Forth do not constitute good cause for extension Certificate of Svc encl REYNOLDS,N S Washington Public Power Supply System REYNOLDS,N S Debevoise & Liberman 82/12/22 Atomic Safety and Licensing Board Panel App 16562 001 24X Fiche 50-460, B2/12/22, 8212280294

H General correspondence

8212170314 Notifies that RL Ferguson,managing director of util, resigned on 821129, effective 830601.due to health reasons
BOUCHEY. 0 D Washington Public Power Supply System 82/12/08.
DENTON: R Office of Nuclear Reactor Regulation, Director 2pp
16456 158 24X Fiche 50-397.82/12/08.8212170314

G. Inspection reports, IE Bulletins & correspondence

- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl
 DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112p 16462-163 24X Fiche 80-000.82/10/28.8208190240
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 244 Fiche 50-000, B2/11/05, 8208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 30-000, B2/11/18, B208190251
- 8208190256 IE Info Natice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUND: R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fichs 50-000.82/11/30,8808190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYOUNG: R C Director's Office Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411-317 24K Fiche 50-000.82/12/03.8208190259
- 8208170261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list enc! JDRDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03.8208170261
- B20B190267 IE lnfd Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring." Svc list encl DEYOUND:R C Director's Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628.191 24X Fiche 50-000.82/12/16.8208190267
- BPO819026B IE Info Notice B2-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 1662B 293 24X Fiche 50-000, B2/12/20, B20819026B

S Reportable occurrences, LERs & related correspondence

- 8212210251 Interim deficiency rept re potentially defective switch on OE electrically operated low voltage circuit breaker types AKR30 & AKR50 of perfore Nay 1980 Initially reported on 821115 Breakers will be corrected by Apr 1983 RODITA W Washington Public Power Supply System 82/12/06 STERNBERO.D M Division of Resident, Reactor Project & Engineering Programs 2pp 16483 309 24X Fiche 50-440.82/12/06.8212210251
- 8212280428 Interim deficiency rept re rusting & pitting condition detected in noncorrosion resistant surfaces of reactor vessel flange stud hales Initially reported on 821115 Final rept will be submitted following B&W evaluation ROOT:R W Washington Public Power Supply System 82/12/14 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 2pp 16559 023 24X Fiche 50-460.82/12/14,8212280428

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8212280125 Advises of project mgt reorganization to provide supplemental staff GERSTNER.W C Jowa Electric Light & Power Co 82/10/06, KEPPLER.J O. Region 3, Office of Director 2pp 16564:071 24X Fiche 50-461,82/10/06.8212280125

- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR. Big Rock Point Dresden i, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl EISEKHUT, D 9 Division of Licensing B2/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 50-000,82/11/15,8211230066
- 8212040144 Notifies of intended action to complete prerequisite re identification of type of discontinuity on weld map Detailed plan for disposition of drywell refueling bellows will be available by 830101
 HALL.D.F. Illinois Power Co. 82/11/23 KEPPLER.J. 0 Region 3, Defice of Director 2pp 16313 158 24X Fiche 50-461.82/11/23.8212060144
- 8212020142 Forwards request for add1 info justifying acceptance criteria for piping vibration preoperational test procedures Proposed criteria in FSAR Amend 20 not acceptable
 THOMAS.C 0 Standardization & Special Projects Branch 82/11/24
 HULLER,O Illinois Power Co Spp 16308 271 24X
 Fiche 50-461.82/11/24.8212020142
- 8212020396 Summary of 821026 meeting w/util & Sargent & Lundy re use of ASME code for containment & drywell structures Design spec adequate Const acceptability should be confirmed by independent insp of records Supporting documentation encl WILLIAMS. J H Licensing Branch 2 82/11/24 SCHMENCER. A Licensing Branch 2 40pp 16308 132 24X Fiche 50-461.82/11/24, 8212020376
- 8212060105 Forwards proprietary response for Action Plan Issue 14, corresponding to Humphrey Issue 4.5 re suppression pool thermal stratification of affidavit supporting proprietary classification encl Response withheld (ref 10CFR2 770) WULLER, 0 & Illinois Power Co. 82/11/24 THOMAS, C D Standardisation & Special Projects Branch 4pp 16315 023 243 Fiche 50-461, 82/11/24, 8212060105
- 8212020088 Advises that immediate review of containment purge issue commenced in response to NRC 921112 ltr GERBINER, W C Illinois Power Co 82/11/30 THOMAS, C O Standardization & Special Projects Branch 29p 16272'021 24X Fiche 50-461,82/11/30,8212020088
- B212040320 Ack receipt of 821123 itr concerning action to be taken redefect on weld map & location of ultrasonic analysis All other prerequisites satisfied Plan will be reviewed by 830103 KEPPLER, J 9 Region 3, Office of Director 82/12/02 GERSTNER, W C 1111nois Power Co 1p 16312 078 24% Fithe 50-461,82/12/02, B212060320
- 8212280101 Forwards procurement recovery plan, indicating method by which util will correct inadequacies identified in 820318 stop work action Procedures implementing plan will be available for insp Review & concurrence requested HALL.DP Illinois Power Co 82/12/03 KEPPLER, J.P Region 3, Office of Director 19pp 16556 078 24% Fiche 50-461,82/12/03,8212280101
- 8212170303 Submits followup on containment vent & purge sys.per 821130 itr Design changes to existing containment purge sys to implement Grand Gulf type configuration should begin immediately.per 821130 itr HULLER.O E Illinois Fower Co. 82/12/13 SCHHENCER.A Licensing Branch 2 ip 14493 205 24X Fiche 50-461.82/12/13,8212170303
- 8212220233 Forwards seismic & dynamic qualification summary & status for balance of plant & NSSS mechanical equipment important to safety, in response to \$20604 & 1211 requests Tables 3 10-1 & 3 10-2 will be incorporated into FSAR amend WULLER, 0 E Illinois Power Co 82/12/15 SCHMENCER, A Licensing Branch 2 506pp 16319 031 24X Fiche 50-461, 62/12/17, 8212220233
- 8212210313 Forwards listing of revised full-size P&IDs, identified in FBAR Table 1 7-2 Drawings will be sent under separate cover HULLER, 0 E Illinois Fower Co. 82/12/20 SCHHENCER, A Licensing Branch 2 7pp 16497.127 24X Fichs.50-461.82/12/20,8212210313
- 8212280108 Comments on proposed improvement program/master mgt plan
 Interim planning & scheduling sys covering items defined in
 820901 confirmatory action itr required prior to lifting
 stop work actions.
 SPESSARD, R L Division of Project & Resident Programs 82/12/20
 OERSTNER, W C. Illinois Power Co 3pp 16564 188 24X
 Fiche: 50-461, 82/12/20, 8212280108
- 8212280235 Forwards info re tube bundle assembly & single stage moisture separator reheater One oversize drawing encl Aperture card is available in PDR, WULLER, 0 E Illinois Power Co 82/12/20 ABELSON, H Licensing Branch 2 3pp 14554 048 24X Fiche 50-441.82/12/20,8212280235

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8212070125 Provides justification for use of 8% bypass leakage fraction.closing out SER Outstanding Issue 10(e) Draft Tech Specs & FSAR Chapter 15 will be revised to reflect new calculated post-accident doses WULLER O E Illinois Power Co 82/11/30 THOMAS, C D Standardization & Special Projects Branch 2pp 16327 087 24% Fiche 90-461.82/11/30.8212070125
- 8212070200 Advises of masonry blockwall test program to determine modules of rugture of concrete block masonry walls to resolve SER Confirmatory Issue 7 (3 8 3) ARC welcome to witness testing on 821220 & 21 at Const Technology Labs WULLER, G E Illinois Power Co 82/12/02 THUMAS. C U Standardization & Special Projects Branch 2pp 16334 350 24X Fiche 50-461,82/12/02,8212070200
- 8212170330 Forwards "Control Bys Failure Review & Evaluation Program," final rept re outstanding Issues 14 & 15 of SER. NUREQ-0835 Outstanding Issue 14 addressed for operating reactors per 1E Builetin 77-27 WULLER.0 E Illinois Power Co 82/12/09 SCHWENCER.A Licensing Branch 2 2pp 16458 070 24X Fiche 50-461,82/12/09.8212170330
- --8212170335 "Control Sys Failure Review & Evaluation Program," final rept + Quadrex Corp GUAD-1-82-244 82/11/12 454pp 16458 072 24X Fiche 50-461,82/12/09,8212170330.
- 8212290179 Submits info re SER Outstanding Issue 6 (Section 3 9 2),
 "Steady State Vibration Acceptance Criteria for Balance-ofPlant Piping "Proposed Stress levels acceptable for
 steady-state vibration
 WULLER.0 E Illinois Power Co 82/12/10 SCHWENCER.A Licensing
 Branch 2 2pp 16578 036 24X Fiche 50-461.82/12/10.8212290179
- F Security, medical, emergency & fire protection plans
- 8212080014 Notifies of acceptance of security plan & training & qualification plan submitted in 820827 & 0930 Itrs Encl to Itrs withheld (ref 10CFR73 21)
 8CHMENCER.A Licensing Branch 2 82/12/01 WULLER, @ Illinois Power Co 2pp 16367 177 24X Fiche 50-461,82/12/01,8212080014
- B212070229 Confirms info re status of emergency operations facility, per 821203 request More detailed info available in FSAR App 13 B. emergency plan: Section 10 MULLER, 0 E Illinois Power Co 82/12/03 SCHWENCER, A Licensing Branch 2 2pp 16329 321 24X Fiche 50-461,82/12/03,8212070229
- 8212220306 Discusses layout of communications equipment required in control room ansite technical support ctr & near-site emergency operations facility
 KEPPLER.J 9 Region 3. Office of Director 82/12/16
 Commonwealth Edison Co. 3pp 16503 351 24X Fiche 50-000.82/12/16.8212220306

@ Adjudicatory correspondence

- 8212270322 Marked-up petition for leave to intervene & request for hearing Certificate of Svc encl SAMELSON A Prairie Alliance 81/03/30 Atomic Safety and Licensing Board Panel 36pp 16530 230 24X Fiche 50-461.81/03/30. 8212270322
- 8212220119 Advises of corrected address for J Foy, spokesperson for Prairie Alliance GODDARD, R J Hearing Branch 3 82/12/17 CLARK, H K , PARIG, O H , FERCUSON, G A Atomic Safety and Licensing Board Panel 1p 16503 025 24X Fiche 50-461,82/12/17,8212220119

- 8212280176 Notifies of change in mailing address for NRC licensing matl WRIGHT.6 N Illinois, State of, Dept Nuc Safety (formerly Dept Public Health) 82/12/20 EISENHUT, D G Division of Licensing 1p 16556 135 24X Fiche 50-000,82/12/20,8212280174
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall-Large-Diameter.Stainless Steel.Recirculation Sys Piping at BNR Plants "Syc list encl
 DEYGUND.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York. Inc 112p 16462 163 24X Fichs.50-000.82/10/28.8208190240

- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list enc!
 - encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24/ Fiche 50-000,82/11/05,8208190245
- 82:12280360 Responds to NRC 82:006 confirmatory action itr re util overinsp program Util terminated all new overinsp work on 82:1005 No further insps will be performed until proper overinsp program developed
- 821005 No further inspection of performed until proper overings program developed HACL, D.P. Illinois Power Co. 82/11/08 SPESSARD, R.L. Division of Project & Resident Programs 3pp. 16560 074 24X Fiche 30~461,82/11/08,8212280360
- 8208190251 IE Info Notice 82-44. "Charification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000, 82/11/18,8208190251
- 82:2080561 Forwards IE Insp Rept 90-461/82-14 on 820801-0930 & notice of violation KNOP.R C Division of Project & Resident Programs 82/11/22 GERSTNER.W C Illinois Power Co 2pp 16352 042 24% Fiche 50-461.82/11/22.8212080561
- --8212080567 Notice of violation from insp on 820801-0930 KNDP.R C Division of Project & Resident Programs 82/11/22 ip 16352 044 24% Fiche 50-461,82/11/22,821208056i
- --8212080973 IE Insp Rept 50-461/82-14 on 820801-0930 Noncompliance noted radwaste reprocessing sys recirculation chemical test & dump evolution performed w/o applicable procedures LIVERMERE. H Bivision of Project & Resident Programs HAYES, D W Region 3. Office of Director 82/11/22 7pp 16352 045 24% Fiche 50-461,82/11/22,8212080561
- 8212060093 Requests approval of encl description of proposed Phase RA-2 of insp of structural steel.insp of remainder of uninspected fixed connections & reinsp of expension connections in containment Deficiency rept filed W/o encl HALL-DP lilinois Power Co 82/11/23 KEPPLER, J Q Region 3, Defice of Director 2pp 16316 121 24X Fiche 50-461,82/11/23, B212060073
- 8212100329 Forwards 1E Insp Rept 50-461/82-18 on 820927-30 & 1005-08 & notice of violation NORELIUS, C E Division of Engineering & Technical Programs 82/11/23 GERSTMER.W C Illinois Power Co 2pp 16377 Q31 24X Fiche 50-461
- --8212100337 IE Insp Rept 50-461/82-18 on 820927-30 & 1005-08 Noncompliance noted failure to update QA manual & failure to follow procedures for qualification of QC personnel HASSE,R A . KISH.J N . PESCHEL.J M Region 3. Office of Director 82/11/16 12pp 16377 036 24X Fiche 50-461,82/11/23,8212100329
- B212100226 Forwards IE Insp Rept 50-461/82-19 on 821001-1101 & notice of violation KNOP,R C Division of Project & Resident Programs 82/11/24 CERSTMER,W C Illinois Power Co 2pp 16376 096 24X Fiche 50-461,82/11/24,8212100226
- --8212100230 Notice of violation from insp on 821001-1101. KNOP,R C Division of Project & Resident Programs 82/11/24 ip 16376 098 24X Fichs 50-461.82/11/24.8212100226
- --8212100240 IE Insp Rept 50-461/82-17 on 821001-1101 Noncompliance noted containment gas control boundary structure pressure test performed w/o approved procedure.

 LIVERNORE H H , HAYES, D W Division of Project & Resident Programs 82/11/24 6pp 16376 099 24X Fiche 50-461.82/11/24, 8212100226
- B20B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Syc list and DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc E27pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDB8;L 1 Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 35åpp 16387 028 24X Fichs 50-000.82/11/30,6208190257

- 82:2280485 Forwards minutes of 82:026 meeting w/util & Bargent & Lundy re use of ABME Code requiring insp by ASME authorized inspector BASR.R L Engineering & Technical Support Branch RNOP.R C Division of Project & Resident Programs 3pp 16592 247 24X Fiche 50-461.82/12/01.821280485
- ---8212280489 Forwards draft FSAR revisions for Section 3 B re ASME Code required insp to be discussed at 821026 meeting LAUNI.C N Sargent & Lundy, Inc. 82/10/21 HILLIAMS, H Standardization & Special Projects Branch 32pp 16592 253 24x Fiche 50-461,82/12/01,8212280485
- 8212080366 Confirms 821118 meeting & 821119 telcon w/util & NRC concurrence in partial release of work addressed in 820901 confirmatory action ltr re Stop Work Action 016 Release limited to 467 electrical conduits SPESSARD.R L Division of Project & Resident Progrems 82/12/02 GERBTNER.W C Illinois Power Co ip 16353 320 24X Fires 80-461.82/12/02.8212080366
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYDVNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24; Fiche 80-000, 82/12/03, 8208190261
- 8212090472 Confirms 821118 telcon discussing util 821115 ltr & 820901 & 1006 confirmatory action ltrs re plans for overinsp & record verification Concurs w/plans SPE58ARD.R L Division of Project & Resident Programs 82/12/03 GERSTNER.W C Illinois Power Co 2pp 16363 345 24X Fiche 50-461.82/12/03.8212090472
- 8212170330 Forwards "Control Bys Failure Review & Evaluation Program," final rept re outstanding Issues 14 & 15 of SER, NURGO-0835 Clustsanding Issue 14 addressed for operating reactors per IE Bulletin 79-27 WULLER, G E Illinois Power Co 82/12/09 BCHWENCER, A Licensing Branch 2 2pp 16458 070 24% Fiche 50-461.82/12/09,8212170330
- --8212170335 "Control Bys Failure Review & Evaluation Program," final rapt & Quadrex Corp GUAD-1-82-244 82/11/12 454pp 16458 072 24X Fiche 50-461,82/12/09,8212170330
- 8212280375 Forwards IE Mgt Moeting Rept 50-461/82-23 on 821122 No noncompliance noted KEPPLER, J O Region 3. Office of Director 82/12/10 GERSTNER, W C Illinois Power Co 2pp 16560 062 24% Fiche 50-461,82/12/10, R212280375
- --8212280381 IE Mgt Meeting Rept 50-461/82-23 on 821122 No noncompliance noted Major areas discussed master mgt plan improvement program KEPPLERJ O Region 3, Office of Director KNOP,R C , HAYES,D W Division of Project & Resident Programs 82/12/08 3pp 16360:064 24% Fiche 50-461.82/12/10.8212280375
- 8212210413 Confirms 821209 discussion between A Budnick & DH Hayes. extending response data re items of noncompliance noted in 1E Insp Rept 50-461/82-1B to 830107 due to postal delays NGRELIUS.C E Division of Engineering & Technical Programs 82/12/13 GERSTNER.H C Illinois Power Co ip 16493 085 24% Fiche 50-461.82/12/13,8212210413
- 820B190267 IE Info Notice 82-49. "Correction for Bample Conditions for Air & Gas Monitoring." Svc list and DEYOUNG, R C Director's Office. Office of Inspection and Enforcement. 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fichs 50-000,82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enci. JORDANA E. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24x Fiche 50-000, 82/12/20, 8208190268

S Reportable occurrences, LERs & related correspondence

- 8212020333 Interim Deficiency Rept 82-11 re incorrect identification of base meth & weld procedures on piping hanger travelers Initially reported on 821020 Review of additravelers continues Finei rept expected in approx 60 days HALL.D.P. Illinois Power Co. 82/11/19 KEPPLER.J.O. Region 3. Office of Director 4pp 16279.156 24X Fiche SO-461.82/11/19. 821202033
- 8212020324 Interim Deficiency Rept 82-12 re overwelding at connection between sway strut type pipe syelet & threaded rod on affected male rod extension piece initially reported on 821021 inspite cellist revised on 821021 to include binding MALL.D P. Illinois Power Co. 82/11/20 KEPPLER.J Q. Region 3, Office of Director 4pp 16277 273 24X Fishe 80-461,82/11/20,821203024
- 8212140057 Interim deficiency rept re instrument data sheets Initially reported on 820902 Instrument data sheet books collected a reissued as controlled copies Investigation continuing Final rept will be filed in 90 days HALL-D P Illinois Power Co 82/12/04 KEPPLER. J G Region 3. Office of Director App 16408 302 24X Fiche 50-461.82/12/04.82/12/0057
- T Hearing transcripts on non-antitrust matters
- 8P12220051 Forwards JY Lee testimony & ME Wangler testimony & affidavit re Clinton Contention V on effects of routine low level redicactivity to be released from plant PATTERSON, W F Hearing Branch 3 82/12/17 FGY. J Prairie Alliance 3pp 16516 049 24X Fiche 50-461.82/12/17.8212220051
- --8212220066 Testimony of JY Lee re Contention 11a on methods used to calculate atmospheric effluents Estimates used to calculate routine effluent releases not conservative Prof qualifications encl
 LEE.J Y Effluent Treatment Systems Branch 82/12/17 App 16916 082 24x Ficher 50-461.82/12/17.821222005
- --8212220070 Testimony of ME Wangler te Prairie Alliance Contention 11(b) on effects of low level radiation, Incremental risk to public health & safety from exposure to radiation from plant operation is small WANGLER.ME Radiological Assessment Branch 82/12/17 4pp 16516 056 24X Fiche 50-461.82/12/17.8212220051
- --8212220073 Affidavit of ME Wangler re Contention V(b) on effects of low level radiation Incremental risk to public health & safety from exposure to radiation released in normal plant operation is small WANDLER, ME Radiological Assetsment Branch 82/12/16 34pp 16516 060 24X Fiche 50-461.82/12/17.8212220051

DUCKET 50-462 CLINTON POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensess of operating reactors except LAGBUR, Big Rock Point, Dresden i, Humboldt Bag, applicants for DL & holders of CP re transmitted of NUREG-0763 & NUREG-0763 & VILLED BY COMMENT OF LICENSING B2/11/15 General Public LISENHUT, D 0 Division of Licensing B2/11/15 General Public Utilities OPU Service Corp 22pp 16387,004 24X Fiche 50-000,82/11/15,8211230046
- F Security, medical, emergency & fire protection plans
- 8212220306 Discusses layout of communications advipment required in control room unsite technical support off & near-site temperature of the support of the control room unsite technical support of the near-site temperature of the support of the control results of the communication of the support of the communication of the communications advised in the control of the communications advised in the control of the communication of the control of the
- G Adjudicatory correspondence
- 8212270322 Marked-up petition for leave to intervene & request for hearing. Certificate of Svc encl SAMELSON. A Prairie Alliance 81/03/30 Atomic Safety and Licensing Board Panel 36pp 16530 230 24X Fiche 50-461.81/03/30.8212270322

- Q Inspection reports, IE Bulletins & correspondence
- B208190240 IE Bullstin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter: Stainless Steel, Recirculation Sys Piping at BUR Plants "Syc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fiche 30-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 CBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc \$10pp 16372 142 24X Fiche 50-000, 82/11/05,8208190245
- BROB190251 IE Info Notice B2-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/ff/t8 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000.82/11/18.8208190251
- 8208190856 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNG, C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000.82/11/30.8208190287
- 8212280485 Forwards minutes of 821026 meeting w/util & Sargent & Lundy re use of ABME Code requiring insp by ASME authorized inspector BAERA L. Engineering & Technical Support Branch 82/12/01 KNOPAR C Division of Project & Resident Programs 3pp 16592 24/24X Fiche 50-461,82/12/01,8212280485
- 8208190289 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc List encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Go of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list enc! JORDAN,E L Division of Engineering & Quality Assurance 62/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24 Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! DEYQUNG, R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Ficha 50-000.82/12/16,8208190267
- 8208190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20,8208190268
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

 G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1. "Strass Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc List encl DEYOUNG, C Director's Office, Office of Inspection and Enforcement, 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche, 50-000, 82/10/28, 8208190240
- 8808190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list uncl COBBL I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,8208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24x Fiche 50-000,82/11/18,8208190251

- 820819025& IE Info Notice 82-46, "Defective & Obsolete Combination Fadlocis " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.820819025&
- 8208;90257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 33App 16/387 028 24X Fichs 50-000,82/11/30,8208190257
- 8208/90257 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies " Syc list encl BEYOUNG.R C Director's Office. Office of Inspection and Enfarcement 82/12/03 Cansolidated Edison Co of New York. Inc 1/3pp 16411 317 24X Fiche 50-000.822/12/03.820819/0259
- 8708190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24) Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Difice of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268
- DOCKET STN-50-482 WOLF CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 8212140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J lsham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000, 82/11/03, 8212140001
- --8001280032 Forwards NRC Response to WH Ward request that NRC partially suspended CP SSE is adequately conservative Recommends that petition be denied

 JACKSON.R E Geosciences Branch 80/01/04 PARR,O D Light
 Water Reactors Branch 3 7pp 16436 339 24X
 Fiche 50-000,82/11/03.8212140001
- 8212020005 Notification of 821214 meeting w/utils & SNUPPS in Bethesda, MD to discuss equipment qualification EDISON, O & Licensing Branch 1 82/11/22 YQUNORLOOD, B J Licensing Branch 1 4pp 16310 358 24% Fiche 50-000,82/11/22, 8212020005
- 62:12030127 Forwards application for amend to CPPR-147, extending const completion date to 840701 KDESTER: 0 L Kansas Oas & Electric Co 82/11/24 DENTON: H R Office of Nuclear Reactor Regulation, Director 1p 16306 018 24X Fiche 50-482,82/11/24.8212030127
- --9212030135 Application for amend to GPPR-147, extending const completion date to 860701 KOESTER, O L. Kansas Gas & Electric Co. 82/11/24 2pp 16306 019 24X Fiche 30-482,82/11/24,8212030127
- 82/12/70288 Forwards Tech Spec revising visual examivisual exam acceptance criteria & functional testing of snubbers PETRICK.N A Standardized Nuclear Unit Power Plant System 82/12/15. DENTON, HR Office of Nuclear Reactor Regulation, Director ip 16456 119 24% Fiche. 50-000, 82/12/15, 82(2170288
- --8212170273 Proposed Tech Spec revising visual eram visual exam acceptance criteria & functional testing of snubbers
 * Standardized Nuclear Unit Power Plant System 82/12/15 Bpp
 16456 120 24X Fiche 50-000, 82/12/15,8212170288
- 8212280236 Forwards Revision 5 to QA programs for design & const PETRICK,N A Standardized Nuclear Unit Power Plant System 82/12/22 DENTON,H R Office of Nuclear Reactor Regulation, Director Ip 16562 185 24X Fiche 50-000,82/12/22,8212280236

- ---8212280240 Revision 5 to QA programs for design & const * Standardized Nuclear Unit Power Plant System 82/12/22 7pp 16562 186 24X Fiche 50-000, 82/12/22,8212280236
- C Utility Environmental Report (ER), amends & correspondence
- 8212270187 Forwards Revision 4 to environ rept OL stage, deleting Chapters 1.9, 11 & portion of Chapter 8, updating meteorology data in Chapters 2 & 6 & revising meteorological concentration analysis in Chapter 5 Certificate of Svc encl KOESTER, 0 L. Kansas Gas & Electric Co. 82/12/07 DENTON.H R. Office of Nuclear Reactor Regulation. Director 7pp. 16539 022 24X Fiche 50-482,82/12/07,8212270187
- --8212270193 Revision 4 to environ rept OL stage * Kansas Gas & Electric Co 82/11/30 26/pp 16539 029 24X Fiche 50-482,82/12/07,8212270187
- F Security, medical, emergency & fire protection plans
- B212070222 Advises of status of emergency operations facility activities Full operation expected after equipment delivery, installation & testing KOESTER.O L. Kansas Gas & Electric Co. 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 16336 318 24X Fiche 50-482,82/12/03.8212070222
- B212270022 Forwards requests for add1 info for review of Revision 9 to emergency plan Plan should be revised to reflect resolution of comments
 YOUNDBL000.B J Licensing Branch 1 82/12/06 KDESTER.9 L Kansa:
 048 & Electric Co 19pp 16551 317 24X Fiche 50-482,82/12/06,82/12/062
- H General correspondence
- 8212170324 Notifies that util mpt organization was further revised on 82126 Nuclear activities responsibilities not affected FSAR will be revised to reflect revision W/o encl announcement KDESTER.0 L Kansas Gas & Electric Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16453 190 24X Ficher 50-482, 82/12/10, 8212170324
- Q Advisoru Committee on Reactor Safequards recorts & correspondence
- GRI2010502 Summary of 265th ACRB meeting on 620506-08 in Washington, BC re Ginna restart safety evaluation, Molf Creek CL review, Palisades BEP review, mmergency response capability of plants & safety-related equipment qualification program # ACRS Advisory Committee on Reactor Bafeguards 62/11/26 ACRS Advisory Committee on Reactor Safeguards 605pp 16294 131 24X Fiche 50-000,82/11/26,8212010502
- @ Inspection reports. IE Bulletins & correspondence
- 820B190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall/Large-Diameter-Stannless Steel, Recirculation Sys Piping at BNR Plants," Syc list enc!

 DEYQUNO.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp. 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 9212030109 Forwards IE Insp Rept 50-482/82-14 during Sept 1982 No noncompliance noted SEIDLE-W C. Division of Resident. Reactor Project & Engineering Programs 82/11/02 KDESTER. O. L. Kansas Gas & Electric Co 2pp 16303 029 24X Fichs 50-482,82/11/02.82/2030109
- --B212030115 IE Insp Rept 60-482/82-14 during Bept 1982, No noncompliance noted Major areas inspected followup on previous inspected finding.observation of installation activities for RCPD piping & other piping sys
 VANDEL.T E . JOHNSON.W.D Division of Resident, Reactor Project & Engineering Progress 82/10/27. App 16303:031 24X
 Fiche 50-482.82/11/02.8212030109
- 8212030044 Forwards IE Insp Rept 50-482/82-15 on 821004-08.No noncompliance noted SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/11/03. KGESTER, Q L Kansas Cas & Electric Co 2pp 14307:150 24X Fithe 50-482,82/11/03,8212030044
- --8212030058 IE insp Rept 50-482/82-15 on 821004-08 No noncompliance noted Major areas inspected site tour observation of work, review of records for welding & nondestructive exam of safety-related piping.

 GLBERT, L. D. JOHNSON, W. D., HUNNICUTT, D. M. Division of Resident, Reactor Project & Engineering Programs 82/11/02 5pp 16307 152 24X Fiche 50-482, 82/11/03,8212030046

- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards Consolidated Edison Co of New York, Inc 110pp 16372 142 24 Fiche 50-000.82/11/05, 8208190245
- B208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Elercise Requirements " Svz list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24) Fiche 50-000, 82/11/18,8208190251
- 820B190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Syc list enc! DEYQUNOR C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 1641: 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! C088.L I Division of Fuel Facilities, Materials & Safequards 62/11/30 Consolidated Edison Co of New York
- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Pemetration Assemblies " Syc list encl DEYGUNG: R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259
- 8208190261 IE Info Notice 82~48, "Failures of Agastat CR 0095 Relay Bockets " Svc list enc! JORDAN.E.L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50~000.82/12/03.8208190261
- 8212170288 Forwards Tech Spec revising visual eram, visual exam acceptance criteria & functional testing of snubbers PETRICK.N A Standardized Nuclear Unit Power Plant System 82/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16456 119 24X Fiche 50-000,82/12/15,8212170288
- --B2(2170293 Proposed Tech Spec revising visual examivisual exam acceptance criteria & functional testing of snubbers * Standardized Nuclear Unit Power Plant System 82/12/15 Spp 16486-120 24% Fiche 50-000.82/12/15,8212170288
- 8208170267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293 24X Fiche 50-000,82/12/20,8208190268
- & Reportable occurrences, LERs & related correspondence
- 8212210115 Final deficiency rept re malfunction in GE IE 480-volt AKR 30/50 breakers initially reported on 921108 Replacement spring lever will have ear on end to preclude breaker famiures Also reported per Part 21 KOESTER, G L. Kansas Oas & Electric Co. 82/12/09 GEIDLE, W C. Division of Resident. Reactor Project & Engineering Programs 2pp 16485 123 24X Fiche 50-482,82/12/09,8218210115
- 8212280338 Interim deficiency rept re inadequate math control for special scope items Initially reported on 820514 Numerous math items identified prior to beginning analysis of installed special scope items. Next rept expected by 830601 KOESTER, O. L. Kansas Gas & Electric Co. 82/12/13 SIEDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 1: 16561 052 24X Fiche 50-482,82/12/13,8212280338
- 8212270249 PNO-IV-82-051 on 821222 loose parts found in secondary side of steam generators B & C during inso Inside surfaces of steam generators also found covered within layer of grit-type mati. No immediate safety concern identified JCHNSON H. D. SCHUN. W S. Rejon 4. Office of Director 82/12/24 1p. 16582:190 24X Fiche: 50-482,82/12/24,8212270249

- DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B212020005 Notification of B21214 meeting w/utils & SNUPPS in Bethesda, MD to discuss equipment qualification EDISON 0 E Licensing Branch 1 82/11/22 YOUNGBLOOD, B J Licensing Branch 1 4pp 14310 358 24X Fiche 30-000, 82/11/22, B212020005
- 8212270418 Responds to FDIA request for documents re proposed revision Afor update to reactor safety study referred to in NUREO-0784.Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON.J M Division of Rules and Records 82/II/26 SHOLLY.S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000.82/II/26.8212270418
- --8211050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAK.T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24% Fiche 80-000.82/11/28, 8212270418
- 8212220440 Board Notifications 82-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PNRs Results do not adversely impact present position on reliance on natural circulation NDVAK. T H Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing 802/12/14 Atomic Fiche 50-000.82/12/14.8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale 6-UT-8 test results Phenomena of core level depression 6 loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461
- 8212170288 Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers PETRICK,N A Standardized Nuclear Unit Rower Plant System 82/12/15 DENYON,H R Office of Nuclear Reactor Regulation, Director 1p 16436-119 24X Fiche 50-000,82/12/15,8212170288
- 8212280236 Forwards Revision 5 to QA programs for design & const PETRICK.N A Standardized Nuclear Unit Power Plant System 82/12/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16562 185 24% Fiche 50-000.82/12/22.8212280236
- F Security, medical, emergency & fire protection plans
- BP12080256 Forwards info re emergency operations facility for NRC survey
 SCHNELL.D F Union Electric Co 82/12/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 16354 179 24X
 Ficha 50~483,82/12/03,8212080256
- B212280426 Forwards 821027 rept in response to NRC request for finding & determination on adequacy of offsite plans & preparadness for plant insufficient factual basis available to render finding & determination KRIMM.R W Federal Emergency Management Agency 82/12/15 GRIMES. B Division of Emergency Preparadness 3pp 16359 025 24% Fiche 50-483,82/12/15,8212280426
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPFLER.J G Region 3, Office of Director 82/12/16
 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000, 82/12/16, 8212220306

į.,

G Adjudicatory correspondence

- 8212090093 Hemorandum & order ruling on contentions Contentions 1,2,4 through 10,13 & 14 & portions of 3 & 15 admitted Contention 12 denied Add info on Contention 11 required BRIGHT, G O, KLINEJ R, QLEASON, JP Atomic Sefety and Cicensing Board Panel 62/12/07 Reed, J O 6pp 16357 168 24X Fische 50-483, 82/12/07,8212090093
- B212130197 Memorandum & order granting applicant motion to compel JO Reed to answer listed portions of util B21020 interrogatories KLINE, J.R., GLEABUN, J.P. Atomic Safety and Licensing Board Panel B2/12/09 Union Electric Co. Spp. 16396 174 24X Fiche 50-483, 82/12/09,8212130197
- BP12150026 Partial initial decision ruling on GA program & const defects No serious safety, environ or common defense & security matters exist All GA matters in controversy resolved in favor of authorizing facility operation BRIGHT, © O., KLINE, J.R., GLEASON, J.P. Atomic Safety and Licensing Board Panel & 82/12/13 121pp 16421 009 24X Fiche 50-483, 82/12/13, 8212150026
- 8212210276 Answers to interrogatories per ASLD 821213 order Certificate of Svc encl REED.J G Reed, J G 82/12/13 Union Electric Co 8pp 16483 223 24X Fiche 50-463.82/12/13.8212210276
- G212280179 Motion for unlargement of time until 830131 to file exceptions to ASLB 821214 partial initial decision Delay needed since deptision is extensive & counsel is involved w/litigation in federal courts Certificate of Svc encl CHACKES.K M Joint Intervenors-Gallaway CHACKEB.K M Chackes & Hoare 82/12/23 Atomic Safety and Licensing Appeal Panel 3pp 16562 314 24X Fiche 50-483.82/12/23.8212280179
- 8212300226 Calls attention to errors on witness list (App I) to 821213 partial initial decision BC Typ & JV Laux erroneously identified as emplayees of Bechtel Svc list encl BAXTER.T A Shaw, Pittman, Potts & Trombridge BAXTER.T A Union Electric Co 82/12/28 GLEASON.J P. BRIGHT.G O. KLINE, J R Atomic Safety and Licensing Board Panel Jpp 16598 001 24X Fiche 50-483.82/12/28.8212300226

J Insurance & indemnity information

- BP12280334 Forwards Endorsement 11 to NELIA Policy NF-264
 NADEL-M Marsh & McLennan. Inc. , M & M Nuclear Consultants, Inc. Div
 B2/12/20 SALTZMAN.J Assistant Director for State & Licensee
 Relations 2pp 16561 144 24X Fiche 50-483, 82/12/20, 8212280334
- G Inspection reports, IE Bulletins & correspondence
- 8208170240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants "Syc list encl
 DEVOUNG, R C Director's Office, Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000.82/10/28,8208170240
- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model B02 Thermoluminescent Dosimeters " Svc list enc!

 C088.L I Division of Fuel Facilities, Materials & Safeguards G2/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000,82/11/05,8208190245
- 8212010049 Forwards NRR input for SALP for 811001-821001 No comments received on draft SALP input YOUNGBLOOD, B J Licensing Branch I 82/11/17 EISENHUT, D 9 Division of Licensing Spp 16271 333 24X Fiche 50-483, 82/11/17, 8212010049
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl DEYDUNO.R C Director's Office. Office of Inspection and Enforcement. 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256.
- BP12100234 Forwards IE Insp Rept 50-483/82-15 on 821001-31 & motice of violation SPESSARD,R L. Division of Project & Resident Programs 82/11/26 SCHNELLID F. Union Electric Co. 2pp. 16376-192 24X Fiche 50-483, 82/11/26,82

- --8212100238 Notice of violation from insp on 821001-31 SPE68ARD, R L Division of Project & Resident Programs 82/11/26 1p 16376 174 24% Fiche 30-483,82/11/26,8212100234
- --B212100242 IE Insp Rept 50-483/82-15 on 821001-31 Noncompliance noted inadequate design of Class IE conduit supports NEISLER.J H , KONKLIN, J E Region 3, Office of Director 82/11/26 5pp 16376 195 24X Fichs 50-483,82/11/26,8212100234
- B20B190257 IE Info Notice B2-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Bafeguerds B2/11/30 Comsolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- B208190259 IE Bulletin B2-04. "Deficiencies in Frimary Containment Electrical Penetration Assemblies " Svr list encl DEYQUNO.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B208190261 IE Info Notice 92-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03,8208190261
- 8212170205 Forwards IE Insp Rept 50-483/82-16 on 821026-29 No noncompliance noted LITTLE, W S Division of Engineering & Technical Programs 82/12/03 SCHNELL, D F Union Electric Co 2pp 16459 218 24X Fiche, 50-483, 82/12/03, 8212170205
- ---8212170284 IE Insp Rept 50-483/82-14 on 821026-29 No noncompliance noted Major areas inspected items identified during previous insps
 LOVE.R S , WILLIAMS.C C Division of Engineering & Technical Programs 82/12/01 Spp 16459 220 24X Fiche 50-483.82/12/03,8212170205
- B21217028B Forwards Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers PETRICK, N A Standardized Nuclear Unit Power Plant System B2/12/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 16486 119 24X Fiche 50-000, 82/12/15, 821217028B
- --8212170293 Proposed Tech Spec revising visual exam, visual exam acceptance criteria & functional testing of snubbers * Standardized Nuclear Unit Power Plant System 62/12/15 Bpp 16456 120 24X Fiche 50-000, 62/12/15.8212170288
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUND, R C Director's Office, Defite of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16, B208190267
- 8208190268 IE Info Natice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Syc list enc! JORDAN,E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24: Fiche 50-000,82/12/20,8208190268
- S Reportable occurrences. LERs & related correspondence
- 8212020257 Final deficiency rept relevel on closing spring interlock of GE IE 480-volt AKR breakers overtraveling armature linkage pin Initially reported on 821105 0E will replace levers Also reportable per Part 21 SCHNELL, D.F. Union Electric Co. 62/11/19 KEPPLER, J.O. Region 3, Office of Director 1p. 16279 354 24X Fiche 50-483,82/11/19,8212020259
- T Hearing transcripts on non-antitrust matters
- B212270204 Memorandum & order making encl transcript corrections to evidentiary record of proceeding GLEASON, J P Atomic Safesty and Licensing Board Panel 82/12/22 16pp. 16534 338 24X Fiche 50-483-82/12/22.8212270204

- DOCKET STN-50-485 STERLING POWER NUCLEAR PROJECT, UNIT 1

 Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wail. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants "Svc list encl DEYGUNG. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York. Inc 112pp 16462 143 24% Fiche 50-000.82/10/20.82/8190240
- B20B190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model B01 & Model 802 Thermoluminescent Dosimeters" Syc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50-000,82/11/05,820B190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list enti JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24: Fiche-50-000, 82/11/18, 8208190251
- B20B170256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks "Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2711/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208170256
- 8708190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L [Division of Fuel Facilities. Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257
- BP08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG.R. C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fishe 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pg 16462 064 241 Fiche 50-000.82/12/03.8208190261
- BPOB190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 UEYOUNG:R C Director's Office of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York, Inc
 127pp 1662B 191 24X Fiche: 50-000, 82/12/16.8208190267
- B20B19026B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 10Spp 16628 293 24X Fiche 50-000, 82/12/20,820819026B

DOCKET STN-50-486 CALLAHAY PLANT, UNIT 2

- F Security, medical, emergency & fire protection plans

 8212280424 Forwards 821027 rept in resonne to NRC request.
- 8212200426 Forwards 821027 rept in response to NRC request for finding & determination on adequacy of offsite plans & preparedness for plant Insufficient factual basis available to render finding & determination
 KRIMM-R W Federal Emergency Management Agency 82/12/15
 GRIMES.IP Division of Emergency Preparedness 3pp 16589 025 24X
 Fiche 50-483, 82/12/15,8212280426
- 8212220306 Discusses layout of communications equipment required in control room onsite technical support ctr & near-site emergency operations facility KEPPLER. J G Region 3. Office of Director 82/12/16 Commonwealth Edison Co 3pp 16503 351 24X Fiche 50-000.82/12/16.8212220306
- DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

 O Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Builetin 82-03, Revision 1. "Stress Cracking in Thick-Wallstorge-Diameter-Stainless Steel, Recirculation Bys Piping at 84R Plants." Svc list encl
 DEVOUND, R C Director's Office. Office of Inspection and Enfercement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 90-000.82/10/28,8208190240

- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermojuminescent Dosimeters " Svc list ent! COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 62/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 244 Fiche 50-000 82/11/05 6208190245
- 8208190291 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JURDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24x Fiche 50-000.82/11/18.8208190251
- 8208190256 IE Info Notice 82-46. "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127p 16411 065 24X Fiche 50-000, 82/11/26, 9208190256
- 8200190257 IE info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fichs 30-000, 82/11/30, 8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 820819026) IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets" Svc list encl JONDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fichs 50~000.82/12/03.820819026!
- 8708190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Gas Monitoring " Svc list encl BEYDUNG,R C Director's Office. Office of Inspection and Enforcement 82/12/14 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fichs 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20,8208190268
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

 @ Inspection reports: IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list encl DEYQUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp | 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- \$208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" 8vc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199. 24X Fiche 50-000.82/11/18.8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUND.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Syc list encl CD89.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028, 24X Fiche 50-000,82/11/30,8208190257
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc 1.st encl DEYGUNO.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259

- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462-064 24X Fiche 50-000.82/12/03.8208190261
- B208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl
 DEYOUNG.R C Director's Office. Diffice of Inspection and
 Enforcement B2/12/16 Consolidated Edison Co of New York. Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8,08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list and JURDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 293 24x Fishe 50-000.82/12/20.8208190268

DOCKET BIN-50-490 PERKINS NUCLEAR STATION, UNIT 3

- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Syc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Syc list enci COBB.L I COSB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc. 110pp 16972-142 24% Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 243 Fiche 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiots "Svc list and Devolves of State of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000: 82/11/26, 8208170256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COSB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24% Fiche 50-000.82/11/30.8208190257
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl
 DEYDUNO.R C Director's Office, Office of Inspection and
 Enforcement 82/12/03 Consolidated Edison Co of New York, Inc
 113pp 16411 317 24X Fiche, 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/12/0 Consolidated Edison Co of New York, Inc 110pp 16462 064 i Fiche 50-000,82/12/03.8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG: R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Boild State AC Undervoltage Relays Type ITE-27" Svc list encl JORDANGE L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24x Fiche 50-000,82/12/20,8208190268
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall-Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, In 112pp 16462 163, 24X Fiche 50-000, 82/10/28, 8208190240 of New York, Inc

- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list enci COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consulidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE lnfo Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JGRDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18, 8208190251
- 8208190254 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list entl COBB.L I, Division of Fuel Facilities, Materials & Gafeguards 82/11/30 Consolidated Edison Co of New York, Inc 395pp 16387 028 24X Fiche 90-000,82/11/30,8208190257
- 8208190257 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- B208190241 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JDRDAN,E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG:R C Director's Office Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8008190268 IE info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list and JARDAN, E.L. Division of Engineering & Guality Assurance 82/12/20 Consplidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2 Q Inspection reports. IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03, Revision 1. "Stress Cracking in Thick-Hall.Large-Diameter, Stainless Steel, Recirculation Sys Piping at BRR Plants "Syc list encl BEYOUNG.R C. Director's Office, Office of Inspection and Enforcement. 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24x Fichs 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc list COSB.L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc. 110pp 14372.142 24X Fiche 50-000,82/11/05,8208190248
- 8208170251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Buc list encl JURDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199. 24x Fiche 50-000.82/11/18.8208190251
- 8208190256 IE Info Notice 82~46, "Defective & Obsolete Combination Padlocks" Svc list enc! DEYDUND,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190286
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati " Svt list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 62(11/30) Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30,8208190257.
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement. 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259

- B70B19026: IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462-064 24: 11che 50-000, 82/12/03, 820819026:
- 8208190267 [E Info Notice 82-49, "Correction for Sample Conditions for Agr & Oas Monitoring " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Comsolidated Edison Co of New York. Inc 12/pp 14628 191 24X Fichs 50-000.82/12/14.8208190267
- 8208190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/2 Consolidated Edison Co of New York, Inc. 108pp 16428 273 2 Fiche 50-000, 82/12/20, 8208190268
- DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3 A Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall-Large-Diameter.Stainless Steel-Recirculation Sys Piping at BNR Plants "Svc list encl
 DEYGUNG.R C Director's Office. Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 112pp 16462 163 24X Fiche 50-000,82/10/28.8208170240
- 8208190245 [E Info Notice 82-42, "Defects Observed in Papasonic Model 80[& Model 802 Thermoluminescent Dosimeters " Svc list (OSS, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fiche 50-000,82/11/05,8209190245
- 80°08170251 IE Info Notice 82~44, "Clarification of Emergency Plan Liercise Requirements" Svc list encl JORDANIE L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp. 16411 199—24) Fiche 50-000, 82/11/18,8208170251
- 8208170256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list encl
 DEYOUNG: R C Director's Office. Office of Inspection and
 Enforcement 82/11/26 Consolidated Edizon Co of New York, Inc 24x Fiche 50-000,82/11/26,8208190256 16411 065
- B./08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mat!" Svc list enci CODB.L. I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24x Fishe 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consultdated Edison Co of New York, 1 1(3pp 1644! 317 24X Fiche 50-000, 82/12/03,8208190259 of New York, Inc.
- 820819026] lE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Cd of New York, Inc 110pp 16462 064 24X Fiche 50-000: 82/12/03:8208190261
- 63'08190267 IE Info Notice 92-49, "Correction for Bample Conditions for Air & Gas Honitoring " Svc list encl DEYOUNG:R C Director's Office of Office of Inspection and Enforcement B2752/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- BLOB19026B IE Info Notice B2-50, "Mod of Solid State AC Undervoltage Kelays Type I7E-27" Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24: Fiche 50-000.82/12/20.820819026B
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8212020254 Forwards FSAR effective page listing through Amend 26 HISENBURG M R Houston Lighting & Power Co 82/11/09 NOVAK, Assistant Director for Licensing 73pp 16288 257. 24X Fiche, 50-498, 82/11/09, 8212020254 NOVAK, T H

- 8211230066 Peneric Ltr 82-27 to all BWR licensess of operating reactors except LACBWR, Big Rock Point, Dresden i, Humboldt Bay, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 Skc list encl Wo stated enci EISENHUT, D 0 Division of Licensing 62/11/15 Peners Corp 22pp 16387 004 24X Fichs 50-000, 82/11/15, 8211230066
- BP12010414 Notification of B21207 meeting w/util & Bechtel in Bethesda, MD to discuss Bechtel review & assessment of Brown & Root soil structure interaction analysis
 SCHIERLING.H Licensing Brench 3 82/11/18 KNICHTON, C W
 Licensing Brench 3 3pp 16267 339 24X Fiche 50-478,82/11/18, Licensing Branch 3 8212010414
- 8212010449 Summary of 821005 meeting w/util.Bechtel.Westinghouse & Torrey Pines in Houston,TX re control room design review program plan
 SECLES,D Licensing Branch 3 82/11/18 Licensing Branch 3 program plem SELLS.D Licensing Branch 3 82/11/18 Licensing Branch 3 71pp 16267 209 24X Fiche 50-498.82/11/18.8212010443
- 8212170450 Notification of 821215 meeting w/util in Houston, TX & 821216 site visit to discuss status of project, including const activities

 BCHIERLING: H Licensing Granch 3 82/12/07 KNIGHTON, C W
 Licensing Branch 3 3pp 16478 158 24X Fiche 50-498,82/12/07,
 G212170450
- 8P12220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation NOVAK.T M Assistant Director for Licensing 82/12/14 Safety and Licensing Board Panel 5pp 16523 135 24X Fiche 50-000.82/12/14.8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-B test results Phenomena of core level depression & loop seel clearing may be more complex than previously supposed previously supposed NOVAK,T M Assistant Director for Licensing 82/1 Safety and Licensing Board Panel 7pp 16523 169 Fiche 50-000, 82/12/14,8212220461 Atomic
- 8212170120 Forwards Amend 8 to application for OLs, SEC info, financial statements & annual financial repts
 90LDBERO, J H Houston Lighting & Power Co 82/12/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 16451 001 24X Fiche 50~498, 82/12/15, 8212170120
- --8212170124 Amend 8 to application for OLs. OCLOBERG.J H Houston Lighting & Power Co 82/ 16451 002 24X Fiche 50-478.82/12/15.8212170120 82/12/15 34pp
- --8212170128 Annual Financial Rept, yr ending 820131 81698, G SPRVCE, J K San Antonio City Public Service Board 82/12/15 24pp 16451 135 24X Fiche 50-499,82/12/15,8212170120
- ~~8212170131 Annual Financial Rept 1981 SEC info encl BURCHELT.M L Central Power & Light 82/03/01 125pp 16451 158 24X Fiche 50~498.82/12/15.8212170120
- --8212170133 Annual Financial Rept 1981 JORDAN, D D Houston Industries, Inc 24% Fiche 50-498, 82/12/15, 8212170120 82/03/22 52pp 16451 283
- C Utility Environmental Report (ER), emends & correspondence
- 8212140381 Forwards Amend 6 to environ rept Amend describes high voltage dc terminal facility to be located onsits GDLDBERG. J H Houston Lighting & Power Co 82/12/10 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 16401 248 24X Fiche: 50-498,82/12/10,8212140381
- --8212140383 Amend 6 to environ rept QQLDBERG.J H Houston Lighting & Power Co 82/ 16401 250 24X Fiche 50-498.82/12/10,8212140391 82/12/10 2100
- G Adjudicatory correspondence
- 0212040083 Comments on plant tour & general licensing process & warns 212020033 Comments on plant tour & general licensing process that Commissioner concern for fairness, legality & truth is not shared by remainder of NRC SINKIN.L. Affillation Voknown 82/11/20. ASSELSTINE, J. K. Commissioners 3pp 16314-322 24X Fichs 50-498,82/11/20,8212060083

- 82:12:100125 Motion to reopen record to take evidence on TX Public Util Commission rulings finding mismaneagement of plant TX Commission special expertise should be heard Issue relevant to NRC hearings Certificate of Svc encl SINKIN.L. Citizens Concerned About Nuclear Power, Inc 82/12/06 About Bafety and Licensing Board Panel 13pp 16376 029 24X Fiche 50-498, 82/12/06,8212100125
- B212280279 Advises, per BL Lex testimony, that util & Bechtel executed contract providing for performance of AE & const mgt svcs Certificate of Svc encl Related correspondence NEWHAN.J R Lowenstein Newman.Reis, Axelrad & Toll NEWMAN.J R Houston Lighting & Power Co B2/12/21 BECHMOEFER.C., LAMB.J C. HILL.E E Atomic Safety and Licensing Board Panel Spp 16561 225 24X Fiche 50-498.82/12/21.8212280279
- BP12280282 Response in opposition to Citizens Concerned About Nuclear Power 821206 motion to reopen record Receipt of evidence would involve ASLB in nonpertinent ratemaking matters Certificate of Svc encl
 NEWHARL J R Houston Lighting & Power Co NEWHAN. J R Louenstein. Newman. Reis. Axelrad & Toll 82/12/21 Atomic Safety and Licensing Board Panel Bpp 16561 217 24X
 Fiche: 50~498, 82/12/21, 8212280282
- 82:2270003 Response in apposition to Citizens Concerned About Nuclear Power 82:206 motion to reopen Phase I record Nexus between TX Public Util Commission findings on util financial ability & issue of util competence not shown W/Certificate of Svc GUTIERREZ. J M Hearing Branch 3 82/12/27 Atomic Safety and Licensing Board Panel Spp 16583 240 24X Piche 50-498.82/12/27, 8212270003
-] Financial information
- 8212170120 Forwards Amend 8 to application for OLs, SEC info, financial statements & annual financial repts

 GOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R,
 Office of Nuclear Reactor Regulation. Director ip 16451 GOI. 24

 Fiche 50-498, 82/12/15, 8212170120
- --8212170128 Annual Financial Rept, yr ending 820131 81908.0 . SPRUCE, J K Sam Antonia City Public Service Board 82/12/15 24pp 16451 135 24X Fiche 50-498,82/12/15,8212170120
- --8212170131 Annual Financial Rept 1981 SEC info enc1 BORCHELT.M L Central Power & Light 82/03/01 125pp 16451 158 24X Fithe 50-498, 82/12/15,8212170120
- --BQ12170133 Annual Financial Rept 1981 JORDAN, D. D. Houston Industries, Inc. 82/03/22 52pp 16451 283 24X Fiche 50-498,82/12/15,8212170120
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8212070262 Forwards Amend 27 to FSAR, intotporating organizational changes CA revisions, Tech Spec deletions, revised responses to NRC questions & miscellaneous FSAR text revisions & editorial changes

 OLDBERG, J H Houston Lighting & Power Co 82/11/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16339 159

 24X Fichs 50-496,82/11/29,8212070262
- ---8212070263 Amend 27 to FSAR * Mouston Lighting & Power Co 62/11/29 325pp 16339:163 24X Fishe 50-479,82/11/29.8212070262
- 8312090377 Forwards Amend 28 to FSAR, describing high voltage direct current (HVDC) terminal facility to be located at site Info re removed of personnel from HVDC facility will be included in emergency plan FSAR Chapter 8 will be updated GOLDBERG, J H Houston Lighting & Power Co. 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16344 175 24X Fiche. 50-498, 82/12/06, 8212090377
- --8212090382 Amend 28 to FSAR * Houston Lighting & Power Co 82/12/06. 42pp 16364.199 24X Fishe: 50-498,82/12/06.8212090377
- Q. Inspection reports: IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall.Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants "Syc list encl
 DEYDUNG.R C. Director's Office. Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 li2pp 1A462.163 24X Fiche 50-000.82/10/28,8208190240.

- 820B;90245 IE Info Notice 82-42, "Defects Observed in Panasanic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list uncl COBB.i. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,820B;90245
- 8:08190281 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24: Fiche \$0-000,82/11/18,820&190251
- GPOB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUND,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256
- 8208190257 IE Info Notice B2-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list and COBB.L I Division of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 4X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462-064 24X Fiche 50-000, 82/12/03, 8208190261
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York. Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE linfo Natice 82-50. "Mod of Solid State AC Undervoltage Relays Type lTE-27" Svc list encl JDRDAN,E L Division of Engineering & Goality Assurance 82/12/20 Consolidated Editon Cu of New York. Inc 108pp 16428 293 24) Ficher 50-000. 82/12/20.0208190268
- 8 Reportable occurrences, LERs & related correspondence
- 8212030100 Eighth interim deficiency rept re breakdown an quality program-procurement cycle of purchased matls Initially reported on 800613. Bechtel assessment continuing Next rept will be submitted by 830603 OPREA: 0 W Houston Lighting & Power Co 82/11/19 COLLINS, J T Region 4, Office of Director 4pp 16304 243 24X Fiche 50-498, 82/11/19, 8212030100
- 8Pi2270172 Suppl to final deficiency rept re structural step beam to column connection design Initially reported on 800924 Bechtel method of enalysis & design in final phase summarized OPREA: O H Houston Lighting & Power Co 82/12/16 COLLINS: J 7 Region 4, Office of Director 10pp 16538 023 24X Fiche, 50-498, 82/12/16, 8212270172
- 8P12290202 Bixth interim deficiency rept re computer verification program Initially reported on 810508 Bechtol method for reviewing Brown & Root.Inc computer calculations established & results discussed Next rept expected by 830512 OPREA.0 W Houston Lighting & Power Co 82/12/22 COLLING.J T Region 4. Office of Director 4pp 16578.048 24X Fiche: 50-498.82/12/22,8212290202
- A Application/construction stage documents & correspondence
- BP12020254 Forwards FBAR effective page listing through Amend 26 WISEMBURG,M R. Houston Lighting & Power Go 82/11/09 NOVAK,T H Assistant Director for Licensing. 73pp 16288 257 24X Fiche 50-498, 82/11/09, 8212020254
- 8211230066 Cemeric Ltr 82-27 to all BWR licenses of operating reactors except LACBWR, Big Rock Point, Dreaden 1, Humboldt Bag, applicants for OL & holders of CF re transmittal of NUREG-0763 & NUREG-0783 Bvc list encl W/o stated encl EIBENNUT, D Q. Division of Licensing. 82/11/15 General Public Utilities GFU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066

- 8212010414 Notification of 821207 meeting w/util & Bechtel in Bethesda.

 MD to discuss Bechtel review & assessment of Brown & Root
 soil structure interaction analysis
 SCHIERLINO.H Licensing Branch 3 82/11/18 KNIGHTON.O W
 Licensing Branch 3 3pp 16267 359 24X Fiche 50-498.82/11/18.
 8212010414
- B212010443 Summary of 821005 meeting w/util, Bechtel, Westinghouse & Torrey Pines in Houston, TX re control room design review program plan SELLS, D Licensing Branch 3 82/11/18 Licensing Branch 3 71pp 16287 209 24X Fiche 50-498, 82/11/18, 8212010443
- G212170450 Notification of 821215 meeting w/util in Houston.TX & 821216 site visit to discuss status of project, including const activities
 SCHIERLING, H Lacensing Branch 3 82/12/07 KNIGHTON, G & Licensing Branch 3 3pp 16478 158 24X Fiche 90-498.82/12/07, B212170450
- B212220440 Board Notifications B2-125 & B2-125A forwards info re H Etherington evaluation of flow blockage during matural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation NOVAK-T M Assistant Director for Licensing B2/12/14 Atomic Safety and Licensing Board Panel Spp 14523 135 24X Fiche 50-000, B2/12/14, B212220440
- B212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461
- 8212170120 Forwards Amend Ø to application for OLs. SEC info, financial statements & annual financial repts
 GOLDBERG, J H Houston Lighting & Power Co 82/12/15 DENTON, H R
 Office of Nuclear Reactor Regulation. Director ip 16451-001 24x
 Fiche 50-498, 82/12/15, 8212170120
- --8212170124 Amend 8 to application for QLs GDLDBERO, J H Houston Lighting & Power Ca 82/12/15 34pp 16451 002 24X Fiche 50-498.82/12/15.8212170120
- C Utility Environmental Report (ER), amends & correspondence
- 8212140381 Forwards Amend 6 to environ rept Amend describes high voltage dc terminal facility to be located onsite GDLDBERG, J H Houston Lighting & Power Co 82/12/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16401 248 24X Fichs 50-498,82/12/10,8212140381
- --B2121403B3 Amend 6 to environ rept
 GOLDBERG, J H Houston Lighting & Power Co 82/12/10 21pp
 16401 250 24% Fiche 50-498,82/12/10,8212140381
- O Adjudicatory correspondence
- 82:204:00B3 Comments on plant tour & general licensing process & warns that Commissioner concern for fairness, legality & truth is not shared by remainder of NRC 81NKIN.L Affiliation Unknown 82/11/20 ASSELSTINE, J K Commissioners 3pp 16314 322 24X Fiche 50-498,82/11/20,8212040083
- 8212100125 Notson to reopen record to take evidence on TX Public Util Commission rulings finding mismanagement of plant TX Commission special expertise should be heard Issue relevant to NRC hearings Certificate of Svc encl SINKIN.L Citizens Concerned About Nuclear Power, Inc 82/12/04 Atomic Safety and Licensing Board Panel 13pp 16376-027 24X Fiche 50-498,82/12/06,8212100125
- 8212280279 Advises per BL Lex testimony, that util & Bechtel executed contract providing for performance of AE & const mgt sycs Certificate of BY enclared correspondence MEWHAN, JR Lowenstein, Newman, Reis, Atelrad & Toll NEWMAN, JR Houston Lighting & Power Co 82/12/21 BECHROFFER, C. LAMB, J C. HILLE, Atomic Safety and Licensing Board Panel Spp 16561 225 24X Fiche 50-496,82/12/21,8212280279
- 8212280282 Response in opposition to Citizens Concerned About Nuclear Power 821206 motion to reopen record Receipt of evidence would involve ASLB in nonpertinent ratemaking matters Cartificate of Syc anci NEHMAN, J R Houston Lighting & Power Co NEHMAN, J R Lowenstein, Neuman, Reis, Axelrad & Toll 82/12/21 Atomic Safety and Licensing Board Panel 8pp 16561 217 24X Fiche 50-498,82/12/21,8212280282

- 8212270003 Response in opposition to Citizens Concerned About Noclear Power 821206 motion to reopen Phase I record Nexus between TX Public Util Commission findings on util financial ability & issue of util competence not shown W/Certificate of 8vc GUTIERREZ, J M Hearing Branch 3 82/12/27 Atomic Bafety and Licensing Board Fanel 8pp 16583 240 24X Fiche 50-498,82/12/27,8212270003
- I Financial information
- G212170120 Forwards Amend 8 to application for DLs, SEC info, financial statements & annual financial repts
 ODLDEERG, J H Howston Lighting & Power Co 62/12/15 DENTON, H H
 Office of Nuclear Reactor Regulation, Director ip 16451 001 24x
 Fiche 50-498, 82/12/15, 8212170120
- --B212170128 Annual Financial Rept, yr ending B20131 B1005,0 , SPRUCE,J K San Antonio City Public Service Board B2/12/15 24pp 1645! 135 24x Fiche 50-498,82/12/15,8212170120
- --8212170131 Annual Financial Rept 1981 SEC info encl BDRCHELT.M L Central Power & Light B2/03/01 125pp 16451 158 24X Fiche 50-478, 82/12/15,8212170120
- --8212170133 Annual Financial Rept 1981 JCRDAN, D D Houston Industries, Inc 82/03/22 52pp 16451 28J 244 Fiche 50-495,82/12/15.8212170120
- A Utility Final Safety Analysis Report (FSAR) & amends
- 6P12070262 Forwards Amend 27 to FSAR, incorporating organizational changes, (AA revisions, Tech Spec deletions, revised responses to NRC questions & miscellaneous FSAR text revisions & editorial changes GOLDBERG, J.H. Houston Lighting & Power Co. 82/11/29 DENTON, H. Office of Nuclear Reactor Regulation, Director. 4pp. 16339 159 24x Fichs 50-498,82/11/29,8212070262
- --8212070263 Amend 27 to FBAR * Houston Lighting & Power Co 82/11/29 325pp 16339 163 24X Fiche 50-499,82/11/29,8212070262
- 82)2090377 Forwards Amend 28 to FSAR, describing high voltage direct current (HVDC) terminal facility to be located at site Info re removal of personnel from HVDC facility will be included in emergency plan FSAR Chapter 8 will be updated OCLBERG, J H Houston Lighting & Power Co 82/12/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 16364 195 24x Fiche 50-498,82/12/06,8212090377
- --B212070382 Amend 28 to FSAR * Houston Lighting & Power Co 82/12/06 42pp 16364 199 74x F1che 50-478,82/12/06,8212070377
- Q Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Stoel, Recirculation 8ys Piping at BWR Plants "Syc list encl DEYGUNO, R C Director's Office, Office of Inspection and Enforcement 8210/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24x Fiche 50-000, 82/10/28, 8208190240
- 8708190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl COSB, L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYQUNO,R C. Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co. of New York, Inc 127pp. 16411 065 24X Fiche, 50-000, 82/11/26, 8208170256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Syc list encl COBB. L I Division of Fuel Facilities, Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, 82/11/30, 8208190257

- E:08:90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies' Svc list encl UEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets" Svc list enci JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche 50-000, 82/12/03. 8208190261
- 8:08190247 lE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc! BEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190247
- BPG819026B IE Info Notice 82-80, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- 5 Reportable occurrences, LERs & related correspondence
- BP12030100 Eighth interim deficiency rept re breakdown in quality program-procurement cycle of purchased matls Initially reported on 800613 Bechtel assessment continuing Next rept will be submitted by 830603 GPREA.G W Houston Lighting & Power Co B2/11/19 COLLINS.J T Region 4. Office of Director 4pp 16304 243 24X Fiche 50-498.82/11/19.8212030100
- B212270172 Suppl to final deficiency rept re structural steel beam to column connection design Initially reported on 800924 Dechtel method of analysis & design in final phase cummarized OPREA. G W Houston Lighting & Power Co 82/12/16 COLLINS. J T Region 4. Office of Director 10pp 16838 023 24X Fiche 50-498.82/12/16.8212270172
- 6:12290202 Sirth interim deficiently rept to computer verification program [nitially reported on 810508 Bechtel method for reviewing Brown & Root.Inc. computer calculations established & results discussed Next rept expected by 830512 OPREA.6 W Houston Lighting & Power Co 82/12/22 COLLINB. J T Region 4, Office of Director 4pp 14578 048 24X Fitche 50-498.82/12/22.8212270202
- DDCKET STM-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

 A Application/construction stage documents & correspondence
- Bri2190244 Notification of B21207 meeting w/util in Bethesda, MD to discuss shift of responsibility as project manager from D Wheeler to A Vietts VIETTI, A Licensing Branch 3 82/11/29 KNIGHTON, G W Licensin Branch 3 3pp 16410 335 24X Fiche \$0-508.82/11/29,8212130244
- 82:2150021 Forwards marked-up FSAR pages transmitted as supplemental info re conformance w/SRP (NUREG-0800) Changes will be incorporated into subsequent FSAR amend BOUCHEY.G D Washington Public Power Supply System 82/11/30 KNICHTON.G W Licensing Branch 3 13pp 16421 218 24X Fiche 50-508,82/11/30.8212:50021
- G./L2150029 Forwards responses to 820820 acceptance review questions re DL application, scheduled for NRC review in Nov Manked-up FSAR pages included where changes became necessary due to responses BOUCHEY, O D Washington Public Power Supply System 82/11/30 KNIGHTON, O W Licensing Branch 3 22pp, 16481.254 24X Fiche 50-508,82/11/30,8212150029
- GP1223020B Forwards Category 1 tank enclosure structure figures in response to acceptance review questions
 BdUCHEY, 0 D Washington Public Power Supply System B2/12/21
 RNICHTON.6 W Licensing Branch 3 32pp, 16510 280 24x
 | iche 50-508, B2/12/21, B21223020B
- C Utility Environmental Report (ER). amends & correspondence
- 81:12220011 Forwards Siting Analysis Branch request for info re regional socioeconomic impacts per environ rept Responses expected no later than 830211 KNIQHTQN.0 W Licensing Branch 3 82/12/06 FERGUGON.R L Washington Public Power Supply System 3pp 14529 100 24X Fiche 30-508, 82/12/06, 8212220011

- 8212140194 Forwards Amend 1 to environ rept Distribution list encl BOUCHEY, 0 D Washington Public Power Supply System 82/12/09 KNIGHTON, 0 W Licensing Branch 3 3pp 16407 055 24X Fiche 50-508, 82/12/09, 8212140194
- --82(2140201 Amend 1 to environ rept * Washington Public Pawer Supply System 82/12/31 177pp 16407 059 24X Ficher \$0-508, 82/12/09, 8212140194
- F Security, medical, emergency & fire protection plans
- GP1207013i Forwards Revision 1 to physical security plan Revision withheld (ref 100FR73 21)

 BQUCHEY, 0 D Washington Public Power Supply System 62/12/01

 DENTCN: H R Office of Nuclear Reactor Regulation, Director 2pp 14327 030 24X Fiche 50-508.82/12/01.8212070131
- 8212100256 Forwards util B00616 & 1212 & 810320 & 0408 ltrs respense to Generic Ltr GirlD.per NRC request Util does not plan to provide backup ERF Requested info provided B0UCMEY, Q D Washington Public Power Supply System 82/12/03 DENTON, HR Office of Nuclear Regulation, Director 2pt 16376 147 24X Fiche 50-397.82/12/03.8212100256
- if General correspondence
- B2/12/70314 Notifies that RL Ferguson, menaging director of util, resigned on 82/12/9, effective 830601, due to health reasons BDUCHEY, O D Mashington Public Power Supply System 82/12/0B DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 16456 158 24X Fiche 50-397, 82/12/08, 82/2170314
- K Utility Final Safety Analysis Report (FBAR) & amends
- BP12)30033 Forwards Amend 2 to FBAR Amend contains supplemental inforce conformance w/BRP (NUREO-OBDO) & responses to NRC Aug 1982 acceptance review questions
 BOUCHEY, O D. Washington Public Power Supply System 82/11/30
 KNIGHTON, O W. Licensing Branch 3 2pp 16393 197 24X
 Fiche 50-508, 82/11/30, 82/12130033
- --B212130036 Amend 2 to FSAR * Washington Public Power Supply System B2/11/30 977pp 16393 159 24X Fiche 50-50B, B2/11/30,8212130033
- @ Inspection reports, IE Builetins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall. Carge-Diameter, Stainless Steel. Recirculation Sys Piping at BUR Plants "Syc list entl DEYQUNO, R. C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462 163 24X Fiche 59-000, 82/10/28. 8208190240
- 82'08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Nodel 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 CD88.L I Division of Fuel Facilities, Materials & Safeguards
 62/11/05 Consolidated Edison Co of New York, Inc 110pp
 14372.142 248 Fiche 50-000, 82'11/05, B2081970245
- BP12060240 Forwards lE Insp Rept 50-50B/82-19 on 821001-31 k notice of violation STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs B2/11/15. LEDDICK: R S Hashington Public Power Gupply System 2pp 16312 150 24X Fiche 60-50B.82/11/15.8212060240
- --8212060264 Notice of violation from insp on 821001-31 BODDS,R T Division of Resident, Reactor Project & Engineering Programs 82/11/15 ip 16312 152 24% Fiche 50-808.82/11/15.8212060240
- --8212040274 IE Insp Rept 50-508/82-i9 on 821001-31 Noncompliance noted tension ring welds of left-in-place dome form work made by unqualified weld procedure ALBERT, W. G. DDDDS, R. T. Division of Resident, Reactor Project & Engineering Programs 62/11/12 6pp 16312,153, 24X Fiche 50-508,82/11/15,8212060260
- ByDB190251 IE Info Notice B2~44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDÁN:E L Division of Engineering & Guality Assurance B2/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 179 24X Fiche 50~000.82/11/18,8208190231

- 8708190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CO88,L l Division of Fuel Facilities, Materials & Safequards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000.02/11/30,8208190257
- 8212170354 Forwards JE Insp Rept 50-508/82-20 on 821004-08 & 1101-03 & notice of violation
 STERNBERO, P.M. Division of Resident, Reactor Project & Engineering Programs 82/12/02 LEDDICK, R.S. Washington Public Power Supply System 2pp 16459.179 24X Fichs 50-508.82/12/02.8212170354
- --8212170361 Notice of violation from insp on 821004-08 t 1101-03 DDDDS,R T Division of Resident, Reactor Project & Engineering Programs 82/12/02 3pp 16459 181 24X Fichs 50-508,82/12/02, 8212170354
- ~6212170370 IE Insp Rept 50-508/82-20 on 821004-08 & 1101-03 Noncompliance noted failure to perform design verification of posite design changes per Ebasco Procedure E-76 & failure to conduct calculations per Ebasco Procedure E-30 MAIST, D D. DDDDS.R T Division of Resident, Reactor Project & Engineering Programs 82/11/30 7pp 16459 184 24X Fiche 50-508,82/12/02,8212170354
- 8212210187 Forwards IE Mgt Mesting Rept 50-508/82-21 on 821104 ENGELKERAR H Region 5. Office of Director 82/12/02 LEDDICKAR S Hashington Public Power Supply System 1p 16484 332 24X Fiche 50-508.82/12/02.8212210189
- --B212210195 IE Mgt Meating Rept 50-508/82-21 on 821104 Major areas discussed results of 820802-06 & 30-0903 insp.including onsite design change control & NRC actions to be taken FAULKENBERRY,B. DODDS,R T. ALBERT,W Q Division of Resident, Reactor Project & Engineering Programs 82/12/02 3pp 16484 333 24X Fiche 50-508.82/12/02,8212210189
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYBUND.R C Director's Office, Gffice of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113p 1641 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JRRDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc 110pp. 16462-064 24X Fiche 50-000, 82/12/03, 8208190261
- 821228012! Responds to NRC 821115 ltr re violations noted in IE Insp Rept 50-508/82-19 Corrective actions Ebasco evaluating matter to determine whether problem was (solated occurrence Rept of corrective actions will be submitted by 83013! LEDDICK.R S Washington Public Power Supply System 82/12/15 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs 1p 16564 180 24X Ficke 50-508.82/12/15.8212280121
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp, 16628 191 244 Fiche 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp 16628 293. 24: Fiche 50-000, 82/12/20, 8208190268
- 82:2280299 Forwards IE Ngt Meeting Rept 50-508/82-24 on 82:209 No noncompliance noted CREWS, J L Division of Resident, Reactor Project & Engineering Programs 82/12/22 LEDDICK, R S Hashington Public Power Supply System Ip 16561 135 24X Fiche 50-508, 82/12/22,82:12280299
- --0212280301 IE Mgt Heeting Rept 50-508/82-24 on 821209 No noncompliance noted Major areas discussed site design change control & licensee involvement & actions taken to tighten site change control process

 CREMS.J L. STERNBERG.D M., DODDS.R T. Division of Resident, Reactor Project & Engineering Programs 62/12/21 2pp 16561 136 24% Fiche 50-508, 82/12/22, 8212280299
- BP12300070 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-04 BTERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/23, LEDDICK, RS Washington Public Power Supply System Ip 16599 018. 24X Fiche 50-508, 82/12/23,8212300070

- ~-8212300075 Responds to NRC 820413 ltr re violations noted in Ik Insp Rept 50-508/82-04 Corrective actions Ebasco reviewed all Chicago Bridge & Iron Class D structures & determined that failure would not affect components LEDDICK:R S Washington Public Power Supply System 82/12/02 GTERNBERO, D M Region 5. Office of Director Spp 16599 019 24% Fiche 50-508/82/12/23/8212300070
- 8212300268 Ack receipt of 821210 ltr informing NRC of status of noncompliance item noted in IE Insp Repts 50-508/82-04 & 50-509/82-03 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK, R S Washington Public Power Supply System Ip 16595 253 24X Fiche 50-508, 62/12/23, 6212300268
- ~-8212300274 Suppls 820528 response to NRC 820426 ltr re violations noted in IE Insp Repts \$0.508/82-06 & 50-509/82-03 New compliance date re absence of specific preventive maint control for shutdown cooling HX will be submitted by 830315 LEDDICK: R S Washington Public Power Supply System 82/12/10 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 1p 16595 254 24X Fiche 50-508,82/12/23,8212300268
- 8212300320 Ack receipt of 821210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-16
 STERNBERG D M Division of Resident Reactor Project & Engineering Programs 82/12/23 LEDDICK, RS Washington Public Power Supply System ip 14894 077 24% Fiche 50-508 82/12/23 8212300320
- --B212300324 Responds to NRC 821022 ltr re violations noted in IE Insp Rept 50-508/82-16 Corrective actions resident engineering instruction will be issued, all concrete blocks in seismic zones will be examined & prism tests will continue LEDDICK: R S Washington Public Power Supply System 82/12/10 STERNBERG. D M Division of Resident. Reactor Project & Engineering Programs 4pp 16594 078 24X Fiche 50-508,82/12/23,8212300320
- DOCKET STN-50-509 WPPSB NUCLEAR PROJECT, UNIT 5
- Q Inspection reports, IE Bulletins & correspondence
- 8:08190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000, 82/11/26,8208190256
- 8212300070 Ack receipt of 821202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-04 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/12/23 LEDDICK, R 8 Washington Public Power Supply System 1p 14599 018 24X Fiche 50-508, 82/12/23,8212300070
- 8212300268 Ack recript of 821210 ltr informing NRC of status of noncompliance item noted in IE Insp Repts 50-508/82-06 & 10-509/82-03 STERNBERO, D M Division of Resident. Reactor Project & Engineering Programs 82/12/23 LEDDICK, R S Washington Public Power Supply Bystem 1p 16595 263 24X Fiche 50-508/82/12/23.8212300268
- --B212300274 Suppls B20528 response to NRC B20426 ltr re violations noted in IE Insp Repts 50-508/82-06 & 50-507/82-03 New compliance date re absence of specific preventive maint control for shutdown cooling HX will be submitted by B30315 LEDDICK.R S Washington Public Power Supply System 82/12/10 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs ip 16595 254 24X Fiche 50-508,82/12/23,8212300268
- DOCKET 50-513 MPPSS NUCLEAR PROJECT, UNIT 4
- A Application/construction stage documents & correspondence
- 8712230363 Trip rapt of Commissioners Gilinsky & Abbott 821208 site visit Agenda & vieugraphs enc! ABBOTY, E.C. Commissioners 82/12/17 Commissioners 25pp 16511 170 24X Fiche 50-397,82/12/17,8212230363
- S Reportable occurrences, LERs & related correspondence
- 8212210251 Interim deficiency rept re potentially defective switch an GE electrically operated low voltage circuit breaker types AKR30 & AKR30 mfg before May 1980 Initially reported on 821115, Breakers will be corrected by Apr 1983 ROOT,R.W. Washington Public Power Supply System 82/12/06 STERNBERG,D M Divysion of Resident, Reactor Project & Engineering Programs 2pp 16483,309 24X Fiche 50~460,82/12/06,8212210251

DOCKET SO-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- G Adjudicatory correspondence
- BP12060002 Response to applicant 821112 motion to withdraw application for CPs & for termination of proceeding NRC does not appose motion Certificate of Svc encl GODDARD, R J Hearing Branch 3 82/12/02 Atomic Safety and Licensing Board Panel 3pp 16313 310 24% Fiche 30-514,82/12/02,8212060302
- Q Inspectson reports, IE Bulletins & correspondence
- 8708190240 IE Bulletin 82-03, Revision i, "Stress Cracking in Thick-Wall: Large-Diameter: Stainless Steel: Recirculation Sys Piping at BKR Plants " Svc list encl DEYOUNDS C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 87/08/90245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 601 & Model 602 Thermoluminescent Dosimeters " Svc list enc!

 6.088,L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fichs 50~000.82/11/05,8208/90245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24 Fiche 50-000, 82/11/18,8208190251
- 82-08190256 tE Info Notice 82-46. "Defective & Obsolete Combination Padlocks "Svc list encl DEYOUNG.R C Director's Office. Dffice of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24% Fiche 50-000.82/11/26.8208190256
- 82:08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Natl " Syc list encl COBS.C. I Division of Fuel Facilities, Materials & Bafeguards 82:711/30 Consolidated Edison Co. of New York, Inc 354pp 14:587 088 24X Fishe 50-000.82/11/30.8208190257
- 87:08190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Clectrical Penetration Assemblies " Svc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24% Fiche 50-000, 82/12/03,8208170259
- 8/08190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAM, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche 50-000:82/12/03.8208190261
- B.º08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Syc list encl DEYOUND, R C Director's Office. Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16629 191 24% Fiche 50-000.82/12/16/8208190267
- 8:08190268 IE thro Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24y Fiche 90-000, 82/12/20, 8208190268

DOCKET 50-515 PEDBLE SPRINGS NUCLEAR PLANT, UNIT 2

- G Adjudicatory correspondence
- SP12060002 Response to applicant S21112 motion to withdraw application for CPs & for termination of proceeding NRC does not oppose motion Certificate of Svc enci CUDDARD, R J Hearing Branch 3 82/12/02 Atomic Safety and Licensing Board Panel 3pp 16313 310 24X Fiche 50-514, 82/12/02, 6212060002
- G Inspection reports, IE Bulletins & correspondence
- 87/08190240 IE Bulletin 82-03.Revision i, "Stress Cracking in Thick-Wall: Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163, 24% Fiche 50-000, 92/10/28, 8208190240

- B208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list rnc1 COBBL I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York Inc 110pp 16372 142 24x Fiche \$0-000.82/11/05.8208190245
- 8708190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 247 Fiche 50-000, 82/11/18, 8208190251
- 820B190256 IE Info Notice 82-96. "Defective & Obsolete Combination Padlocks " Svc list enc! DEYGUND:R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 045 24X Fiche 50~000.82/11/26.8208190256
- GROB190257 IE Info Notice 92-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl CDBB.L I Division of Fuel Facilities, Materials & Safeguards G2/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000, B2/11/30, 8208190257
- 8POB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG: R C Director's Office, Diffice of Inspection and Enforcement. B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- BP08190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Syc list encl JURDAK, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 249 Fiche 50-000, 82/12/03, 8208190261
- 8708190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list enci DEYUUNO.R C Director's Office of Inspection and Enforcement 82/12/16 Consultdated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- 8:08190268 IE Info Notice 82~50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24) Fiche 80-000, 82/12/20, 8208190268

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

- BP11230066 Opneric Ltr B2-27 to all BWR incensees of operating reactors except LACEUR, Big Rock Point. Dresden I. Humboldt Bay, applicants for QL & holders of CP re transmittel of NUREO-0763 & NUREO-0783 Svc list encl W/o stated encl EISENHUT, D 9 Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 50-000, 82/11/15, 8211230066
- 8P12070055 Forwards "Succommonic Monitoring & Mittigation Rept." & "Const Employee Monitoring Errata Rept"
 MILLS.L M Tennessee Valley Authority 82/11/30 FIBENHUT, D & Division of Licensing 1p 14366 027 24% Fiche 50-518,82/11/30,8212070055
- --B212090055 "Sociesconamic Manitoring & Mitigation Rept"

 * Tennesses Valley Authority HNP SMR-12 02/10/31 11pp
 16966 028 24X Ficha 50-518 02/11/30 0212090055
- --8212090058 "Const Employee Monitoring Errata Rept "
 * Tennessee Valley Authority 82/10/31 66pp 16366 039 24X
 Fiche 50-518,82/11/30.8212090055
- @ Inspection reports: IE Bulletins & correspondence
- B208190240 lE Bulletin 82-03, Revision 1, "Btress Cracking in Thick-Well, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc. 112pp 16462 163 24% Fiche 50-000, 82/10/28, 8208190240
- 820Bi90245 IE Info Notice 82-42, "Defects Observed in Penasonic Model BOI & Model BOZ Thermoluminescent Dosimeters " Syc list one! COBB.L I Division of Fuel Facilities, Materials & Safeguards. 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372:142 24X Fiche 50-000.82/11/08.8208190245

- 8208190251 [E Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 15411 199 243 Fiche. 50-000, 82/11/18, 8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list anci DEYBUND, R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Editon Co. of New York, Inc 127p 16411 065 24X Fiche 50-000, 82/11/26, 8208190256
- 82/08/90257 IE info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards 82/11/30 Consolidated Edison Co of New York. Inc 356pp 16387 028 24x Fiche 50-000.82/11/30.8208190257
- 820B190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Evr list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edisan Co of New York, Inc 113pp 16411.317 24X Fiche 50-000,82/12/03.8208190259
- 8208190261 lE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " 5vc list encl JORDAN: E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 14628 191 24% Fiche 50-000.82/12/16.8208190267
- 8208190268 IE info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Bvc list encl JORDAN, E.L. Bivision of Engineering & Quality Assurance 82/12/20 Consolidate Edison Co of New York, Inc. 108pp. 18628-293-240 Fiche 50-000, 82/12/20, 8208190268
- S Reportable occurrences, LERs & related correspondence
- BFI(2100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure QA procedures issued before work begins initially reported on Bi1020 Final rept will not be submitted until decision made on deferral of projects submitted until decision made on deferral of projects NULLS, L Tennesse Valley Authority B2/12/04 Q'REILLY, J P Repion 2. Office of Director ip 16377 136 24X Fiche 50-000.82/12/06.8212100270
- B212140141 First interim deficiency rept to Henry Pratt pneumatic butterfly valve actuator gake failure Initially reported on G21107 Valves will be modified on site Next rept due 830607 Also reportable per Part 21 MILLG.L M Tennessee Valley Authority 62/12/07 O'REILLY, J P Region 2, Office of Director Spp 16408 166 24% Fiche 50-000: 82/12/07, 8212140141
- 8212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No addI info available until action team 821215 rept Next rept will be submitted by 830420 MILLS.L. M. Tennesse Valley Authority 82/12/13 0'REILLY.J.P. Region 2. Office of Director ip 14473 362 24x Fiche 50-000.82/12/13.8212200001
- B212200017 Fifth interim deficiency rept re design review process interface coordination activity initially reported on 8(0717. Corrective action to be based on action team rept to be issued approx 82(215 Next rept expected by 830422 MILLS.L M Tennessee Valley Authority 82/12/13 G'REILLY, J. P Region 2. Office of Director 2pp. 16473 085 24X Fiche: 50-000, 82/12/13, 82(2200017
- 8212200052 Final deficiency rept re Atlas QA documentation on auxiliary & fuel bldg structural steel Initially reported on 811113 QA hold placed on suspect items until further testing performed Also reportable under Part 21 MILLS.L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2. Defice of Director 4pp 16470 011 24X Fiche: 50-518, 82/12/13, 8212200052
- BP:12210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sand by 830322.

 MILLS, L M Tennesses Valley Authority 82/12/15 DYREILLY, J P Region 2. Office of Director 2pp 16489 168 24X Fiche 50-000, 82/12/15, 8212210431

- DOCKET STN-50-519 HARTSVILLE MUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BP11230066 Generic Ltr 82-27 to all BMR licensees of operating reacters except LACBUR. Big Rock Point Dresden 1. Hymboldt Bay, applicents for DL & holders of CP re transmittal of NUREG-0763 & NUREG-0763 Syc [ist enc] V/4 stated enc] EISE/HHUT.D G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24% Fiche 50-000, 82/11/15, 8211230066
- & Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BAR Plants "Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Nat 112pp 16462 163 24X Fiche 80-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!
 COBG.L. [Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 30-000.82/11/05,8208190245
- 820B190251 IE Info Notice 82-44, "Clarification of Emergency Plan Frencise Requirements" Svc list encl JORDAN E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24% Fithe 50-000, 82/11/18,8208190281
- B:/OB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Fadjocks" Svc list encl DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, luc 127pp 16411 065 24% Fiche 50-000, 82/11/26, 8208190256
- 8708190297 IE Info Notice 82-47. "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 354pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- B2:08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sackets " Svc list encl JORDAN,E L. Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000,82/12/03,8208190261
- 820B190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement. B2712/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche, 50-000, 82/12/16, 8208190267
- BP08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JGRDAN,EL Division of Engineering & Guality Assurance B2/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000, 82/12/20, 9208190264
- 3 Reportable occurrences, LERs & related correspondence
- 8212140141 First interim deficiency rept re Henry Pratt pneumatic butterfly valve actuator yoke failure Initially reported on 821107. Valves will be modified on site Next rept due 830607 Also reportable per Part 2! MILLS.L M Tennessee Valley Authority 82/12/07 D'REJLLY. J P Region 2. Office of Director 3pp 16408 166 24X Fiche 50-000.82/12/07.8212140141

- DOCKET STM-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- B211230066 Generic Ltr B2-27 to all BWR licensees of operating reactors except LACBWR. Big Rock Point. Drosden i. Humboldt Bay, applicants for GL & holders of CP re transmittal of NUREO-0783 & NUREO-0783 Svc list encl 4/o stated encl EISENHUT. D 0 Division of Licensing B2/11/15 General Public Utilities GPU Service Corp 22pp 16/387 004 24X Fiche 50-000.82/11/15.8211230066
- 8712070055 Forwards "Socioeconomic Monitoring & Mitigation Rept." & "Const Employee Monitoring Errato Rept." MILLS, L. M. Tønnessee Valley Authority 82/11/30 EISENHUT, D. G. Division of Licensing 1p 16366-027 24X Fiche 50-518, 82/11/30, 8212070055
- --8212090056 "Bocioeconomic Monitoring & Hitigation Rept "
 * Tennessee Valley Authority HNP SMR-12 82/10/31 11pp
 16366 028 24X Fiche 50-518,82/11/30,8212090055
- --B212070058 "Const Employee Monitoring Errata Rept "
 * Tennessee Valley Authority 82/10/31 66pp 16366 037 24X
 Fiche 50-516, 82/11/30, 8212070055
- G Inspection reports, IE Bulletins & correspondence
- 8F08190240 IE Bulletin 82-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants " Syc list encl DEYGUNG,R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs 50-000, 82/10/28,8208190240
- 8PO8190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc! COB8,L I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000,82/11/03,8208190245
- 8208190251 lE Info Notice 92-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp. 16411 199 24x Fishe 50-000.82/11/18,8208190251
- OPDB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYQUNG.R C Director's Office. Diffice of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190856
- B:'08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L. I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 354pp 14397 028 24X Fiche 50-000.82/11/30.6208190257
- 87/08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 02/12/03, 8208190259
- 82'08170261 IE Info Notice 82-48. "Failures of Agastat CR 0075 Relay Dockets " Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Jiche, 50-000, 82/12/03, 8208170261
- BPOB190267 JE Info Notice B2-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc!

 BEYOUND.R. C Director's Office of Price of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000, 82/12/16. 8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24x Fiche 50-000, 82/12/20, 8208190268

- B Reportable occurrences, LERs & related correspondence
- B212100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure GA procedures issued before work begins Initially reported on 811020 Final rept will not be submitted until decision made on deferral of projects MILLS.L M Tennessee Valley Authority 82/12/06 0'REILLY.J P Region 2, Office of Director ip 16377 136 24X Fiche 50-000, 82/12/06,8212100270
- B212200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No add1 info available until action team 821215 rept Next rept will be submitted by 830420 MILLS.L M Tennesses Valley Authority 82/12/13 0'REILLY.J P Region 2. Office of Director ip 16473 362 24X Fiche 50-000.82/12/13.8212200001
- 8212200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on BIO717 Corrective action to be based on action team rept to be issued approx B21215 Next rept expected by 830422 MTLLS, L M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2. Office of Director 2pp 16473 085 24X Fiche 50-000, 82/12/13, 8212200017
- 8212200052 Final deficiency rept re Atlas QA documentation on auxiliary & fuel bldg structural steel Initially reported on Silli3 QA hold placed on suspect items until further testing performed Also reportable under Part 21 MTLLS.L.M Tennessee Valley Authority 82/12/13 O'REILLY, J P Region 2, Office of Director 4pp 16470 011 24X Fiche 50-518, 82/12/13, 8212200052
- 8712210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MILLS, L M Tennessee Valley Authority. 82/12/15 0'REILLY, J P Region 2. Office of Director 2pp 16489 168 24X Fiche 50-000, 82/12/15, 8212210431
- DOCKET STN-50-521 HARTSVILLE MUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licenses of operating reactors except LACBWR, Big Rock Point, Dresden 1. Humboldt Bay, applicants for 0.5 holders of CP be transmittal of NUREO-0763 & NUREO-0783 Bvc list encl W/o stated encl EISEMHUT, D & Division of Licensing 82/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24x Fiche 50-000, 82/11/15,8211230066
- **G** Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BHR Plants " Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp. 16462 163 24X Fiche 50-000, B2/10/28,8208190240
- BEOB190245 IE Info Notice B2-42, "Defects Observed in Panasonic Model BO & Model BO Thermoluminescent Dosimeters" Svc list enc!
 CDBB.L. I Division of Fuel Fecilities, Materials & Gafeguards B2/11/05 Consolidated Edison Co of New York, Inc 110pp 14372 142 24X Fishs 50-000.82/11/05.B208190245
- 820819025: IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl, JORDAN.E L. Division of Engineering & Quality Assurance. 82/11/18 Consolidated Edison Co. of New York, Inc. 107pp 16411,179 24X Fichs 50-000.82/11/18.8208190251
- GPOB190296 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocts" Bvc list encl. DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pg 16411 065 24X Fiche, 50-000, 82/11/26, 8208190256
- BPOBI90257 IE Info Notice SR-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list entl COBB.L I Division of Fuel Facilities, Materials & Bafeguards S2/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche: 50-000, 82/11/30, 8208190257

- 8208190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list enc! DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16418 317 24X Fichs 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Bockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24 Fiche 50-000,82/12/03,8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG: R C Birector's Office: Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- 820B19026B IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list and I JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 10Bpp 1662B 293 24X Fiche 50-000.82/12/20.820B19026B

DOCKET 50-522 SKACIT NUCLEAR POWER PROJECT. UNIT 1

- A Application/construction stage documents & correspondence
- B211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBHR. Big Rock Point, Dreaden 1, Humboldt Bay, applicants for GL 24 holders of CP retransmittal of NUREO-0783 EV list entl W/O stated encl EISE/HHUT.D 0 Division of Licensing B2/11/15 General Public Utilities GPU Service Corp 22pp 16387 004 24X Fiche 50-000.02/11/15.8211230066
- 8212140419 Forwards suppl to 820222 response to request for info re Unresolved Safety Issue A-39 concerning safety relief valve paol dynamic loads, per NUREG-09202. NUREG-0763 & NUREG-0753 HYERS.R V Puget Sound Power & Light Co 82/12/08 DENTON. H R Office of Nuclear Reactor Regulation. Director 4pp 16404 186 24X Fiche 30-522.82/12/08.8212140419
- B Utility Preliminary Safety Analysis Report, amends
- 8210190729 Forwards final draft of Amend 28 to PBAR.consisting of responses to NRC Questions 231 5, 231 14 & 231 15, revisions to PBAR Section 2 5 & Apps 2K & 2R M/25 oversize figures Aperture cards are available in PDR BPANGENBERG.F Northwest Energy Services Co 82/10/15 ADENSAN, ELicensing Branch 4 201pp 15751 035 24X Fiche 50-522, 82/10/15, 8210190729
- @ Adjudicatory correspondence
- B212010038 Brief opposing admission of Yakima Indian Nation reworded proposed Contention 10 Nation special relationship w/US does not exempt Nation from Commission rules & regulations Specificity requirements not met Certificate of Swc encl DEWEY-L S Hearing Branch 3 82/11/30 Atomic Safety and Licensing Board Panel 7pp 16260 334 24X Fiche 50-522,82/11/30,8212010038
- 6212020376 Memorandum & order granting NRDC motion for amend to Contention 3 as adopted in ASLB 921102 memorandum & order WDLF, J F Atomic Safety and Licensing Board Panel 82/11/30 Natural Resources Defense Council 2pp 16278 090 24X Fiche 50-522,92/11/30,8212020376
- 8212020379 Memorandum & order granting NRDC 821122 motion to substitute NRDC for Coalition for Safe Power as lead party for Contention 3 WDLF.J F. Atomic Safety and Licensing Board Panel 82/11/30 Natural Resources Defense Council 2pp 16278 102 24% Fiche 50-522, 82/11/30, 8212020379
- BP12070172 Request for production of documents & interrogatories.per 10CFR2 740(h) & 10CFR2 741 Certificate of Svc encl Related correspondence
 THATCHER, T.L. National Wildlife Federation THATCHER, T.L. Oregon Environmental Council 82/12/01 Portland General Ejectric Co 10pp 16334 331 24X Fiche 50-522,82/12/01.8212070172
- 6212070239 Brief re admissibility of Yaking Indian Nation Proposed Contention 10 Clarification needed on procedural rule of Commission & scope of contention Certificate of Sec encl THOMSEN.F.T Puget Sound Power & Light Co THOMSEN.F.T Perkins. Coie. Stone. Oisen & Williams 82/12/01 Atomic Bafety and Licensing Board Panel 13pp. 16329.298 24X Fiche 50-522.82/12/01, 8212070239

- 8P12100116 Advises that time for Commission to act to review ALAB-700 has expired Commission declined review Decision became final agency action on 821208 CHILKIS J Office of the Secretary of the Commission 82/12/09 Office of the Executive Legal Director 1p 16376 019 24X Fiche 50-522 82/12/09 8212100116
- B212140333 Certifies svc of brief on admissibility of reworded proposed Contention 10, motion for retunsideration of ASLB B21027 memorendum & order.R Jim affidavit & notice of counsel law firm change on B21210 HOVIS.J B Yakima Indian Nation HOVIS.J B Hovis. Cockrill. Heaver & Bjur 82/12/10 4pp 16402 008 24% Fiche 50-522.82/12/10.8212140333
- B212140345 Brief supporting admissibility of Yakima Indian Nation reworded proposed Contention 10 Attempt to terminate reserved rights of Yakima Indian Nation violates fifth amend Land cannot be taken by inverse condemnation HOVIG. J. B. Yakima Indian Nation HOVIS. J. B. Hovis, Cockrill, Paver & Bjur 82/12/10 Attonic Safety and Licensing Board Panel 9pp 16401 010 24X Fiche 50-522.88/12/10.8212140345
- 8212140354 Motion for reconsideration of ASLB 821029 memorandum & order re Yalima Indian Nation Contentions 7.8 & 9 Nation right to enjoy reservation pascefully given by 1895 treaty should be protected by ASLB HOVIS. J B Yakima Indian Nation HOVIS. J B Hovis. Cockrill. Weaver & Bjur 82/12/10 Atomic Safety and Licensing Doard Panel 3pp 16401 035 24% Fiche 50-522,82/12/10,8212140354
- 8212140386 Notice of counsel new law firm affiliation, as of 820901 HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 ip 16401 305 24X Fiche 50-522, 82/12/10, 8212140386
- 8212140455 Affidavit of R Jim supporting Yakims Indian Nation brief on admissibility of Nation reworded proposed Contention 10 & motion for reconsideration Nation has right to pasture horses & gather roots even though US holds title to land JIM.R Yakima Indian Nation 82/12/10 3pp 16403 154 24X Fiche 30-522.82/12/10,8212140455
- 8212160267 Motion to clarify & amend Contentions 7 & 8 Contentions should be reorganized to facilitate coordinated evidentiary presentations for environ matters ASLO set out as Contentions 4,7 & 8 Certificate of Svc encl
 THATCHER, T & National Wildlife Federation HAPATO, S T Columbia River Inter-Tribal Fish Commission BELL, N Coalition for Safe Power 82/12/13 About Safety and Licensing Appeal Panel 10pp 16446 048 24X Fiche 50-522,82/12/13,8212160267
- B212270225 Response to 821201 discovery requests Certificate of Svc encl THOMSEN.FT Puget Sound Power & Light Co THOMSEN.FT Perkins. Coie. Stone. Olsen & Williams 82/12/20 National Wildlife Federation 16pp 16536 237 24X Fiche 50-522,82/12/20,8212270225
- B212280287 Response supporting intervenor 821213 motion to clarify & amend Contentions 7 & 8 Quantification of environ impacts not practicable due to subjective nature Certificate of Svc encl FRANTZ, 8 P Puget Sound Power & Light Co FRANTZ, 8 P Lowenstvin, Neuman, Reis, Axelrad & 7011 B2/12/23 Atomic Safety and Licensing Roard Panel 11pp 16561 075 24X Fithe 50-522, 82/12/23, 2812280289
- O Inspection reports. IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Hall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at 8MR Plants " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000. 82/10/28, 8208190240
- 820B19024B IE Info Notice 82-42, "Defects Observed in Panasonic Model BOI & Model BO2 Thermoluminescent Dosimeters " Svc list encl. COBB.L I pivision of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372-142 24X Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Fiche 50-000,82/11/18,8208190251

- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82711/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82711/30,8208190257
- BPO8190259 IE Bulletin B2-04, "Deficienties in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Ficha 50-000, B2/12/03, B208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462 064 24 Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl
 DEYGUNG,R C Director's Office, Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000, 82/12/16,8208190267
- 8,08170268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24) Fiche 50-600.82/12/20,8208170268
- 1 Hearing transcripts on non-antitrust matters
- 8212070334 Transcript of 821202 prehearing conference in Olympia.WA (*p 78-175 * Atomic Safety and Licensing Board Panel 82/12/02 102pp 16337 306 24X Fiche 50-522,82/12/02,8212070334
- DOCKET 50-923 SKAGIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- GP1(230056 Generic Ltr 82-27 to all BMR licensees of operating reactors except t.ACDMR. Big Rock Point Dreaden 1. Humboldt Day, applicants for OL & holders of CP re transmittal of NUREO-0763 & NUREO-0783 Svc list encl Wo stated encl EIBENNUT.D Q Division of Licensing 82/11/15 Oeneral Public Utilities OPU Service Corp 22pp 16387 004 24X Fiche 30-000, 82/11/15,8211230066
- 8212140419 Forwards suppl to 820222 response to request for info re Unresolved Safety Issue A-39 concerning safety relief valve pool dynamic loads, per NURGO-0020, NURGO-0783 & NURGO-0783 MYERS, R. V. Puget Sound Power & Light Co. 82/12/08 DENTON, H. R. Hiffice of Nuclear Reactor Regulation, Director 4pp 16404 186 44X Fiche 50-522, 82/12/08, 8212140419
- B Utility Preliminary Safety Analysis Report, amends
- BP10190729 Forwards final draft of Amend 28 to PSAR, consisting of responses to NRC Questions 231 5.231 14 & 231 15, revisions to PSAR Section 2 5 & Apps 28 & 2R W/25 oversize figures Aperture cards are available in PDR SPANGENBERG, F Northwest Energy Services Co 82/10/15 ADENSAM, E Licensing Branch 4 201pp 15751 035 244 Fiche 50-522, 82/10/15, 82(0190729
- G Adjudicatory correspondence
- BP12010038 Brief opposing admission of Yakima Indian Nation reworded proposed Contention 10 Nation special relationship w/US does not exempt Nation from Commission rules & regulations Specificity requirements not met Certificate of Svc encl BEMEY.L S Hearing Branch 3 B2/11/30 Atomic Safety and Literaing Board Panel 7pp 16260 334 24% Fiche 50-522,82/11/30,6212010038
- 8212020376 Memorandum & order granting NRDC motion for amend to Contention 3 as adopted in ASLB 821102 memorandum & order WOLF.J F Atomic Safety and Licensing Board Panel 82/11/30 Natural Resources Defense Council 2pp 16278 090 24X Fiche 50-522, 82/11/30, 8212020376

- 8212020379 Memorandum & order granting NRDC 821122 motion to substitute NRDC for Coalition for Safe Power as lead party for Contention 3 WOLF, J.F. Atomic Safety and Licensing Board Fanel B2/11/30 Natural Resources Defense Council 2pp 16278 102 24X Fiche 50-522,82/11/30,8212020379
- B212070172 Request for production of documents & interrogatories.ppr 100FR2 740(b) & 100FR2 741 Certificate of Svc entl Related correspondence THATCHER.T L National Wildlife Federation THATCHER.T L Oregon Environmental Council 82/12/01 Portland General Electric Co 10pp 16334 331 24X Fiche 50-522.82/12/01.8212070172
- 8212070239 Brief re admissibility of Yaking Indian Nation Proposed Contention 10 Clarification needed on procedural rule of Commission & scope of contention Certificate of Svc end Fouget Study Court of THOMSEN,FT Perkins. Caie. Stone. Olsen & Williams 82/12/01 Atomic Safety and Licensing Board Panel 13pp 16329 298 24% Fiche 50-522.82/12/01, B212070239
- 8232100116 Advises that time for Commission to act to review ALAB-700 has expired Commission declined review Decision became final agency action on 821208
 CHILK, S. J. Office of the Secretary of the Commission 82/12/09
 Office of the Executive Logal Director 19 16376 019 24X
 Fiche 50-522,82/12/09,8212100116
- B212140333 Certifies svc of brief on admissibility of reworded proposed Contention 10 mation for reconsideration of ASLB B21029 memorandum & order, R Jim affidavit & notice of counsel law firm change on B21210 MOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Meaver & Bjur B2/12/10 4pp 16402 008 24X Fiche: 50-522.82/12/10,8212140333
- 82:12140345 Brief supporting admissibility of Yakima Indian Nation reworded proposed Contention 10 Attempt to terminate reserved rights of Yakima Indian Nation violates fifth amend Land cannot be taken by inverse condemnation HOVIG.J B Yakima Indian Nation HOVIG.J B Hovis, Cockril, Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel 9pp 16401 010 24% Fiche 50-522.82/12/10.8212140345
- 8212140354 Motion for reconsideration of ASLB 821027 memorandum & order re Vakima Indian Nation Contentions 7,8 & 9 Nation right to enjoy reservation pacefully given by 1855 treaty should be protected by ASLB HOVIS, J B Yakima Indian Nation HOVIS, J B Hovis, Cockrill, Weaver & Bjur 82/12/10 Atomic Safety and Licensing Board Panel 3pp 16401 035 24% Fiche 50-522,82/12/10,8212140354
- B212140386 Notice of counsel new law firm affiliation, as of 920701 HOVIG.JB Yakima Indian Nation HOVIS.JB Hovas, Cockrill, Meaver & Bjur B2/12/10 ip 16401 305 24X Fiche 50-522, 82/12/10.8212140386
- 8212140455 Affidavit of R Jim supporting Yakima Indian Nation brief on admissibility of Nation reworded proposed Contention 10 & motion for reconsideration Nation has right to pasture horses & gather roots even though US holds title to land JIM.R Yakima Indian Nation 82/12/10 3pp 16403 154 24% Fiche 50-522.82/12/10.8212140454
- 8212160267 Motion to clarify & amend Contentions 7 & 8 Contentions should be reorganized to facilitate coordinated evidentiary presentations for environ matters ASLB set out as Contentions 4,7 & 8 Certificate of Svc encl THATCHER,T L National Wildlife Federation WAPATO.9 T Columbia River Inter-Tribal Fish Commission BELL,N Coalition for Safe Power 82/12/13 Atomic Safety and Licensing Appeal Panel 10pp 16446 048 24X Fiche 50-522,82/12/13,8212160267
- BP12270225 Response to B21201 discovery requests Certificate of Svc encl THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie, Stone, Olsen & Williams 82/12/20 National Wildlife Federation 14pp 14596 237 24X Fiche 50-522,82/12/20,8212270225
- 0212280289 Response supporting intervenor 021213 motion to clarify & amend Contentions 7 & 8 Quantification of environ impacts not practicable due to subjective nature Certificate of Svc enc!
 FRANTZ.S P Puget Sound Power & Light Co FRANTZ.S P Lowenstein Newman. Reis: Azelrad & Toll 82/12/23 Atomic Bafety and Licensing Board Panel 11pp 16561 075 24X
 Fiche 50-522: 82/12/23: 8212280289

- Q Inspection reports: IE Bulletins & correspondence
- B208190240 IE Bulletin B2-03.Revision 1. "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Flants." Syc list encl
 DEYGUNO.R C Director's Dffise. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 14462-163 24X Fiche. 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Convolidated Edison Co of New York, Inc 110pp 14372 142 244 Fiche 50-000, 82/11/05.8208190285
- B20Bi90251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000.82/11/18.8208190251
- 8208170296 (E Info Notice 82-44, "Defective & Obsolete Combination Padlocks" Syc list enc!
 DEYOUNG:R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 1641
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C088.L I Division of Fuel Facilities, Materials & Safequards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fichs 50-000.82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primery Containment Electrical Prnetration Assemblies" Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000.82/12/03.8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 18628 191 24X Fiche 50-000.82/12/16.8208190267
- 8208190268 IE info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc.) JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 273 24) Fiche 50-000.82/12/20.8208190268
- T Hearing transcripts on non-antitrust matters
- 8212070334 Transcript of 821202 prehearing conference in Olympia.WA Pp 78-175.

 A stomic Safety and Licensing Board Panel 82/12/02 t02pp 16337 306 24% Fiche \$0-522.82/12/02.8212070334
- DOCKET STN-50-928 PALO VERDE NUCLEAR STATION, UNIT I

 A Application/construction stage documents & correspondence
- B21201044B Summary of 821020 meeting w/util.C-E & Bechtel in Bethesds, MD re pipe whip restraints
 LICITRALE A Licensing Branch 3 82/11/18 Licensing Branch 3 5pp 16270 226 24% Fiche 50-528.82/11/18.821201044B
- 8211290135 Forwards "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3," Vol 1, "Executive Summary." Vol 2, "Program Results" & Vol 3, "Potential Finding Repts "
 TURLEY, K L. Arizona Public Service Co. 82/11/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp. 16298-001
 24X Fiche 30-528,82/11/19,8211290135
- --B2!1290142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1, 2 & 3,"

 Vols 1, 2 & 3 No reason seen to prohibit issuance of full power QL for Units 1, 2 & 3

 SIMON.W A Torrey Pines Technology 82/11/19, DENTON, H R

 Office of Nuclear Reactor Regulation, Director ip 16278:003, 24X Fiche 50-528,82/11/19,8211290135

- --B211290148 "Independent 0A Evaluation of Palo Verde Nuclear Generating Station Units 1.2 & 3." Vol 1. "Executive Summary" Terrey Pines Technology GA-C16924 Vol 82/10/31 27pp 16278 004 24X Fiche 50-528,82/11/19,8211290135
- --8211290150 "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3," Vol 2, "Program Results " * Torrey Pines Technology GA-C16924 Vo2 82/10/31 163pp 16298 192 24X Fiche 50-528,82/11/19,8211290135
- --8211290155 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3," Vol 3, "Potential Finding Repts," Books 1 & 2 * Torrey Pines Technology QA-C16924 VO3 82/10/31 140App 16298 355 24X Fiche 50-528,82/11/19,8211290135
- 8212080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by 821215 U/o stated enc! KNIGHTQN:O W Licensing Branch 3 82/11/23 VAN BRUNT,E E Arizona Public Service Co 1p 16368 352 24X Fiche 50-528,82/11/23,8212080564
- B212130409 Responds to B21028 request to authorize use of AEME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable subj to indicated conditions Code Case N-339 approved for general use KNIOHTON, O W Licensing Branch 3 82/11/23 VAN BRUNT, E E Arizona Public Service Co 2pp 16412 100 24X Fiche. 50-528, 82/11/23, 8212130405
- 8212270418 Responds to FOIA request for documents re proposed revision b/or update to reactor safety study referred to in NUREO-0784. Chapter 10 as RS 11 & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON.J.M Division of Rules and Records 82/11/26 SHOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418
- --8211050027 Forwards summary of semiscale test results & advises that board notification re test results (assed W/o encl NOVAK, T M Assistant Director for Licensing 82/09/24 Division of Licensing 1p 16549 278 24% Fiche 50-000,82/11/26, 8212270418
- 8212080666 Notification of 821208 meeting w/util, SANL, C-E & Burns & Roe in Maricopa County. AZ to discuss shutdown heat removal sys design for CESSAR Sys 80 plant LfCITRALE A Licensing Branch 3 82/12/01 KNIGHTON, 0 W Licensing Branch 3 3pp 16379 243 24X Fiche 50-528.82/12/01.8212080666
- G2:2220053 Summary of 82:1117 meeting w/util & Bechtel in Bethesda, ND re natural circulation testing & training per TMI Action Item 1 0 1 LICITRALE A Licensing Branch 3 82/12/01 Licensing Branch 3 5pp 16526 348 24X Fiche 50-528, 82/12/01, 82:2220063
- 8212070109 Forwards comments on draft environ protection plan NRC should accept other federal agency findings w/o further review WAN BRUNT, E E Arizona Public Service Co 82/12/02 NOVAK, T M Assistant Diractor for Licensing App 16327 291 24X Fiche 50-528, 82/12/02, 8212070109
- B212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes N-S-R Public Power Agency as co-owner EISENHUT, D 0 Division of Licensing 62/12/06 VAN BRUNT, E & Arizona Public Service Co 4pp 16354 061 24X Fiche 50-528, 62/12/06, 8212080179
- --8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-8-R Public Power Agency as co-owner EISENHUT, D o Division of Licensing 82/12/06 App 16354 065 24% Fiche 50-528, 82/12/06, 8212080179
- --8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143 KNIGHTON.0 W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528,82/12/06,8212080179

- 8912290473 Trip rept of 821103-04 site visit by Instrument & Control Sys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria Control cabling acceptable LICITRA.E A Licensing Branch 3 82/12/13 Licensing Branch 3 10pp 16606 048 24X Fichs 50-529,82/12/13,8212290473
- 8212220440 Board Notifications 82-125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation NOVAK: T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Fanel 5pp 16523 135 24X Fiche 50-000.82/12/14.8212220440
- 8212220961 Board Notification 82-124 forwards RJ Mattson 821123 memo re Semiscale S-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461
- 8212270129 Forwards change to FSAR Section 1 8.adding fission chamber detectors & sealed sources to exception taken to Reg Guide 1 38 Change will be included in upcoming FSAR amend VAN BRUNTLE E Arizona Public Service Co 82/12/21 NOVAK.T M Assistant Director for Licensing 3pp 16538 149 24X Fiche 50-528.82/12/21.8218270129

E. NRC Bafety Evaluation Report (SER), supple & correspondence

- 8212210107 Discusses confirmatory issue re-motor operators powered from vital sources, per SER (NUREC-0857) Plant design modified to include motor operators on appropriate valves VAN DRUNT, E E Arizona Public Service Co 82/10/28 NOVAK, T M Assistant Director for Licensing 2pp 16491 049 24X Fiche 50-528, 82/10/28 8212210107
- 8212030031 Forwards schedule for submitting requested info & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER. For NRC 829727 ltr
 VAN BRUNT.E E Arizona Public Service Co 82/11/27 NOVAK.T M Assistant Director for Licensing App 16305 076 24X
 Fiche 50-528.82/11/29.8212030031
- 82:12130292 Advises that all piping components in essential ASME Code Class 1,2 & 3 piping sys designed to Levels C & D syc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met

 VAN BRUNTLE Arizona Public Service Co 82/12/09 NOVAK, T M Assistant Director for Licensing App 16390 062 24X

 Fiche 50-528,82/12/09,8212130292

F Security, medical, emergency & fire protection plans

- BP12080157 Forwards response to 821202 telephone request re emergency operations facility Conceptual design for upgraded emergency response facilities under NRC review

 VAN BRUNTLE E Arizona Public Service Co 82/12/06 NOVAK. T M
 Assistant Director for Licensing 4pp 16/354 088 24%
 Fiche 50-528,82/12/06/8212080157
- & Adjudicatory correspondence
- BP12010202 Requests consideration of West Valley Agricultural Protection Council, Inc. supplemental memorandum supporting Council patition to intervene Brief includes useful analysis

 BERLIN, K. Affiliation Unknown B2/11/27 LAZO, R.M., CALLIHAN, D., COLE, R.F. Atomic Safety and Licensing Board Panel 1p 16258 053 24X Fiche 50-528, 82/11/29, 8212010202
- B212040075 Requests West Valley Agricultural Protection Council, Inc B21018 supplemental memorandum supporting petition to intervene be stricken from record If not stricken, Joint Applicants answer should be allowed CRAWFORD, V.A. Snell & Wilmer CRAWFORD, V.A. Joint Applicants-Pelo Verde B2/11/27 LAZO, R. N. CALLIHAN, D., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 16316-073 24% Fishe 50-598, 82/11/27, 8212060095
- B212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines GA/GC plan DEWEY, L. 5 Hearing Branch 3 82/12/09 BERNABEI, L. Harmon & Weiss. BERNABEI, L. Hourshan, P. 3pp 16503 022 24X fiche 50-528, 82/12/09, 8212220118

K Utility Final Safety Analysis Report (FSAR) & amends

- 8212070328 Forwards Amend 10 to FSAR VAN DRUNT.E E Arisona Public Service Co 82/12/06 Office of Nuclear Reactor Regulation, Director 2pp 16345.047 24X Fiche 50~528,82/12/06.8212070328
- --8212070331 Amend 10 to FSAR Two oversize drawings and Aparture cards are available in PDR * Artiona Public Sarvice Co 82/12/31 318pp 16345 049 24X Fiche 50-528.82/12/05.8212070328
- 8212210075 Forwards Proof of Svc for Amend 10 to FSAR VAN SRUNT,E E Arizone Public Service Co 82/12/15 Office of Nuclear Reactor Regulation, Director 3pp 16485 252 24X Fiche 50-528, 82/12/15, 8212210075

M Antitrust correspondence

- 8212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes N-B-R Public Power Agency as co-owner EISENHUT, D 0 Division of Licensing 82/12/06 VAN BRUNT, E E Arizona Public Service Co 4pp 16354 061 24X Fiche 50-528, 82/12/06, 8212080179
- --8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-S-R Public Power Agency as co-owner EISENUUT, D @ Division of Licensing 82/12/06 App 16354 045 24X Fiche 50-528,82/12/06,8212080179
- --8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143 # Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24X Fiche 50-528.82/12/06.8212080179
- --8212080204 Notice of issuance & availability of Amend 5 to CPPR-141, CPPR-142 & CPPR-143 KNIGHTON,0 W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528,82/12/04,8212080179

@ Inspection reports, IE Bulletins & correspondence

- 820B190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Rectroclation Sys Piping at BNR Plants " Syc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112p 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 8208190245 IE Info Notice 92-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc! COBBLL I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000, 82/11/05, 8208190245
- B212040143 Requests extension to respond to items of noncompliance in IE Insp Repts 50-528/62-25, 50-529/82-09 & 50-530/62-10 Rept will be submitted by 821119

 VAN BRUNT, E E Arizona Public Service Co 82/11/10 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 1p 16314 069 24% Fiche 50-528,82/11/10.8212060143
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl. JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 14411
- B20B190254 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " 8vc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B2/11/24 Consolidated Edison Co of New York, Inc. 127pp 16414 065 24X Fishe 80-000, 82/11/26.8208190254
- 8212130207 Forwards IE Insp Rept 50-528/82-30 on 821018-1119 & notice of violation
 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 82/11/29 ANDOGNINI.0 C Arizona Public Service Co 2pp 16397 005 24X Ficho 50-528,82/11/29,8212130207
- --B212130207 Notice of violation from insp on 821018-1119
 YOUNG,T Division of Resident, Reactor Project & Engineering
 Frograms 82/11/29 ip 16397 007 24X Fiche 50-528,82/11/29,8212130207.

- --8212130215 IE [nsp Rept 50-528/82-30 on 821018-1119 Noncompliance noted unplanned introduction of water into steam generator 1 did not mest chemical specs FIORELLT, 0 . JOHNSTON, 6 . YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16397 008 24X Fiche 50-528,82/11/29.9212130207
- 8208190297 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COB9.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000,82/11/30.8208190257
- 8212210203 Forwards IE Insp Repts 50-528/82-29, 30-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted STERNBERG-ID M Division of Resident, Reactor Project & Engineering Programs 82/11/30 VAM BRUNT-E Aritona Public Service Co 2pp 16485 022 24X Fichs 50-528,82/11/30,8212210203
- --8212210211 IE Insp Repts 50-528/82-29.50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted Major areas inspected licenses action on previous insp findings.electrical cable installation & containment structural steel welding ECKHARDTIJ H. D'ANGELOIA, YOUNG.T Division of Resident. Reactor Project & Engineering Programs 82/11/29 7pp 16485-024 24X Fiche 50-528.82/11/30.8212210203
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000,82/12/03,8208190261
- 8212090546 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE insp on 820934-0903 STERNBERG D A Division of Resident. Reactor Project & Engineering Programs 82/12/03 VAN BRUNT, E Ari
- --B212090552 Responds to NRC 821008 ltr re violations noted in IE insp on 820830-0903 Corrective actions as-built weld pattern reconciled against weld pattern of Comsip Customline Corp VAN BRUNTLE E Arizona Public Service Co B2/f1/22 BTERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 6pp 16366-345 24% Fiche 50-528,82/12/03,8212090546
- 8208190267 IE Info Natice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Svc list enc!
 DEYOUNG: R C Director's Office: Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc. 108pp. 16628
- S Reportable occurrences, LERs & related correspondence
- 8212050229 Interim deficiency rept re Bechtel supplier document register errors which may allow nutdated C-E procedures to be used for instrument calibr Initially reported on 820421 Final rept delayed until 821209 due to evaluation VAN BRUNTLE E. Arizona Public Service Co. 82/11/22 STERNBERG, D. M. Division of Residents Reactor Project & Engineering Programs. 2pp 16312 231 24X Fiche: 50-528,82/11/22,8212060229
- 8212060240 Interim deficiency rept re instrument ac circuit breakers left set below trip range after testing Initially reported on 820806 Extension requested to submit final rept until 821229 due to extensive investigation & evaluation VAN BRUNT.E E Arizona Public Service Co. 82/11/22 STERNBERG, D M Division of Resident Reactor Project & Engineering Programs 2pp, 16312 237 24X Fiche 50-528.82/11/22.8212060240
- 8212060275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubicles b/o seismically qualified design. Initially reported on 821021 Anchorage will be provided on all four sides Also reportable under Part 21 VAN BRUNTIE E. Aritona Public Service Co. 82/11/22 STERNBERO, D. M. Division of Resident, Reactor Project & Engineering Programs Spp 14312, 139. 24% Fiche 50-528,82/11/22,8218060275

- 8712060283 Final Deficiency Rept DER 82-39 re Cooper Energy Svcs diesel generator crankcase sumps internal coating flaking off into Jubs oil Initially reported on 821021 Condition not reportable since flaking will not affect lube oil sys VAN BRUNTLE E Arisona Public Service Co 82/11/22 STERNDERC, D H Division of Resident. Reactor Project & Engineering Programs Spe 16312 074 24X Fiche 50-528,82/11/22,8212060283
- 8212130267 Interim Deficiency Rept DER-82-61 re reactor coolant pumps diffusorming cap screws which may fail & damage pump Cap screw math heat treatment will be changed so that math will not be susceptible to cracking VAN BRUNT.E E Apriona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 138 24% Fiche SO-528.82/11/22,8212130267
- 9212130320 Interim deficiency rept re failure of EBF actuation sys do power supply ground detectors supplied by C-E to meet preoperational test requirements Instally reported on 821021 Evaluation continuing Final rept expected by 830209 VAN BRUNTLE Arizona Public Service Co 82/11/22 STERNDERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16389 329 24% Fiche 50-528,82/11/22,8212130320
- 8212130216 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank Initially reported on 821026 Bechkel performing independent detailed analysis Final rept expected by 830210 VAN BRUNT, E E Arizona Public Service Co 82/11/24 STERNDERO, D plivision or Resident, Reactor Project & Engineering Programs 3pp 16390 120 24% Fiche 50-528.82/11/24.8212130216
- 8212210077 Interim Deficiency Rept DER 81-14 re A-354 anchor bolt failures Initially repurted on 810529 Final rept including Teledyne & Battelle repts will be submitted by 830131 Delay due to extensive evaluations
 VAN BRUNT, E.E. Arizona Public Service Co. 82/11/29 STERNBERG, D. H. Division of Resident, Reactor Project & Engineering Programs 2pp 16485 248 24% Fiche 50-528,82/11/29,8212210077
- 8212210086 Deficiency Evaluation Rept 82-64 re installation of dissimilar metal socket wolds, restricted by Revision 10 of PM-204, due to delay in receipt of revised drawings Deficiency not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 82/11/27 STERNDERO, D M Division of Resident, Reactor Project & Engineering Programs 2pp 16493 018 24% Fiche 50-528, 82/11/29, 8212210086
- 8212210237 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe lining failure in ERCW sys Initially reported on 820710 Final rept will be submitted by 830208 VAN BRUNT, E. E. Arizona Public Service Co. 82/12/01 SYERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 16483 348 24% Fiche 30-328,82/12/01,8212210237
- 02:122:10077 Final Deficiency Rept DER-48 or Dragon Valve Co instrument line check valves seized upen by welding heat Movable internal poppet for excess flow check valve redesigned by vendor to preclude binding from welding valve in place VAN SRUNT.E E Arizone Public Service Co 92/12/07 STERNBERG.D M Division of Resident. Reactor Project & Engineering Programs Spp 14491 083 24% Fiche 50-528.62/12/07.8212210097
- 82:2210225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri lond ctrs w/improperly crimped AMP termination lugs Initially reported on 8208:3 All terminations utilizing AMP crimp type lugs will be inspected for compliance VAN BRUNT, E E Arizona Public Service CO 82:12/07 STERNDER9.D M Division of Resident, Reactor Project & Engineering Programs App 16484 227 24X Fiche 50-528,82/12/07,8212210225
- 8212280148 Final Deficiency Rept DER 82-17 re C-E documents for instrument calibr not updated in Bechtel supplier document register Initially reported on 820421 Condition not reportable under 10CFR50 55(e)

 VAN BRUNT.E E Arizona Public Service Co 82/12/09 SYERNBERO.D & Division of Resident. Reactor Project & Engineering Programs 4pp 16563 115 24X Fiche 50-528,82/12/09,8212280148
- B212280227 Interim Deficiency Regt 82-68 re underground cables to startup transformers Initially reported on 821126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by B30222 VAN BRUNT.E.E Arizona Public Service Co 82/12/13 STERNBERG,D H Division of Resident, Reactor Project & Engineering Programs Spp 16562 261 24X Fichs 50-528,82/12/13,8212280227

- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BP12010448 Summary of 821020 meeting w/util.C-E & Bechtel in Bethesda, MD re pipe whip restraints LICITRALE A Licensing Branch 3 82/11/18 Licensing Branch 3 5pp 16270 226 24X Piche 50-528.82/11/18.821201044B
- 82:1290:35 Forwards "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1.2 & 3." Vol 1. "Executive Surmary." Vol 2. "Program Results" & Vol 3. "Potential finding Repts "
 TURLEY, K L. Arizona Public Service Co 82/11/19 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 2pp 16298 001 24X Fiche 50-528.82/11/19.8212290135
- ---8211290142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3."

 Vois 1,2 & 3 No reason seen to prohibit issuance of full power QL for Units 1,2 & 3

 SIMON, W A Torrey Fines Technology 82/11/19 DENTON, H R OFFice of Nuclear Reactor Regulation, Director 1p 16278 003

 24X Fiche 50-528,82/11/19.8211270135
- --8211270148 "Independent GA Evaluation of Palo Verde Nuclear Cenerating Station Units 1.2 & 3," Vol 1. "Executive Summary " * Torrey Pines Technology GA-C16924 Vol 82/10/31 27pp 16298 004 24% Fiche 50-528,82/11/19.8211290135
- --8211270150 "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3." Vol 2, "Program Results" * Torrey Pines Technology GA-C16924 VO2 B2/10/31 163pp 16298 192 24% Fiche 50-528,82/11/17,8211270135
- --8211290155 "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1.2 & 3." Vol 3. "Potential Finding Repts." Books 1 & 2 * Torrey Pines Technology GA-014924 VO3 B2/10/31 1404pp 14278 355 24X Fiche 50-528.82/11/19.8211290135
- 8P12080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by 821215 M/o stated enci KNIGHTON.O W Licensing Branch 3 82/11/23 VAN BRUNT,E & Ariiona Public Bervice Co ip 16368 352 24X Tiche 50-528.82/11/23,8212080564
- 87:2130405 Responds to 82:028 request to authorize use of ABME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable subj to indicated conditions Code Case N-339 approved for general use KNIOHTON.O W Licensing Branch 3 82/11/23 VAN BRUNT.E E Arizona Public Service Co 2pp 16412 100 24X Fiche 50-528.82/11/23.82:2130405
- B212270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as RB II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON; J M Division of Rules and Records 82/11/26 SHGLLY, S C Union of Concerned Scientists 3pp. 16549 233 24X Fiche 50~000;82/11/26,8212270418
- --82;1050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl NOVAX, T H Assistant Director for Licensing 82/09/24 Division of Licensing ip 16549 278 24% Fiche 50-000,82/11/26,8212270418
- 8212080654 Notification of 821208 meeting w/util, SANL, C-E & Burns & Roe in Maricopa County, AZ to discuss shutdown heat removal sys design for CESSAR Sys 80 plant.
 LICITRA, E A Licensing Branch 3 82/12/01 KNIGHTON, G W
 LICENSING Branch 3 3pp 16379 243 24X Fiche 50-528,82/12/01,8212880444
- 8212220063 Summary of 821117 meeting w/util & Bechtel in Bethesda, MD re natural circulation testing & training per TMI Action Item 1 G t LICITRA, E A Licensing Branch 3 82/12/01 Licensing Branch 3 5pp 16526 348 24X Fich
- 8212070109 Forwards comments on draft environ protection plan. NRC should accept other federal agency findings w/o further review UAN BRUNT, E E Arizona Public Service Co 82/12/02 NOVAK, T & Assistant Director for Licensing 4pp 16327: 291 24X Fiche 50-528,82/12/02,8212070109

- 8P12080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes h-S-R Public Pawer Agency as co-owner FISENHUT, D 0 Division of Licensing 82/12/06 VAN BRUNT, E Arizona Public Service Co App 16354 061 24X fiche 50-528, 82/12/06, 8212080179

 --8212080168 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-S-R Public Power Agency as co-owner EISENHUT, D 0. Division of Licensing 82/12/06 App 16354 065 24X Fiche 50-528, 82/12/06, 8212080179
- --8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143
 * Office of Nuclear Reactor Regulation, Director 82/12/04 2pp 16354 071 24% Fiche 50-528.82/12/06.8212080179
- --8212080204 Notice of issuance & availability of Amend 5 to CPPR-141. CPPR-142 & CPPR-143 KNIGHTON.O W Licensing Branch 3 82/12/06 2pp 16354 073 24% Fiche 50-528.82/12/06.8212080179
- 8212290473 Trip rept of 821103-04 site visit by Instrument & Control Sys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria. Control cabling acceptable LICITRALE A Licensing Branch 3 82/12/13 Licensing Branch 3 10pp 16606 048 24X Fiche 50-528,82/12/13,8212290473
- 8212220440 Board Notifications 82~125 & 82-125A forwards info re H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on reliance on natural circulation NOVAK-T K Assistant Director for Licensing 82/12/14 Atomic Safety and Licensing Board Panel Spp 16523 135 24X Fiche 50-000.82/12/14.8212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Bemiscale B-UT-8 test results Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NOVAK.T M Assistant Director for Licensing 82/12/14 Atomic 8afety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000.82/12/14.8212220461
- 8212270129 Forwards change to FSAR Section 1 8, adding fission chamber detectors & sealed sources to exception taken to Reg Ouise 1 38 Change will be included in upcoming FSAR amend VAN DRUNT.E E Arizona Public Service Co 82/12/21 NOVAK, T M Assistant Director for Licensing 3pp 16538 149 24X Fiche 50-528, 82/12/21, 8212270129
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- B212210107 Discusses confirmatory issue remotor operators powered from vital sources, per BER (NUREC-OB57) Plant design modified to include motor operators on appropriate valves VAN BRUNTLE Arisona Public Service Co 82/10/28 NOVAK, T M Assistant Director for Licensing 2pp 16491,049 24X Fiche 50-528,82/10/28,8212210107
- B212030031 Forwards schedule for submitting requested info & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER.per NRC 820927 ltr VAN BRUNT.E E Arizona Public Service Co 82/11/29 NBVAK.T M Assistant Director for Licensing App 16305 076 24X Fiche 50-528,82/11/29,8212030031
- B212130292 Advises that all piping components in essential ABME Code Class 1:2 & 3 piping sys designed to Levels C & D syc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met VAN BRUNT, E E Aritona Public Service Co B2/12/09 NOVAK, T. M Assistant Director for Licensing. App 16390-062 24X Fiche 50-528, 82/12/09, 82/12/39292
- F Security, medical, emergency & fire protection plans
- 8212080157 Forwards response to 821202 telephone request re emergency operations facility Conceptual design for Upgraded emergency response facilities under NRC review VAN BRUNT, E E Arizona Public Service Co 82/12/06 NOVAK, T M Assistant Director for Licensing 4pp 16354 088 24X Fiche 50-528, 82/12/06, 8212080157

Q Adjudicatory correspondence

- 9212010202 Requests consideration of West Valley Agricultural Protection Council Inc supplemental memorandum supporting Council petition to intervene Brief includes useful analysis
 BERLIN.K. Affiliation Unknown 92/11/29 LAZD.R M , CALLIHAN.D , CDLE.R F Atomic Safety and Licensing Board Panel 1p 16258 053 24X Fiche 50-528.82/11/29.8212010202
- 8212060095 Requests West Valley Agricultural Protection Council, Inc 821018 supplemental memorandum supporting petition to intervene be stricken from record if not stricken. Joint Applicants answer should be allowed CRAMFORD, V A Snell & Wilmer CRAMFORD, V A Joint Applicants-Palo Verde 82/11/29 LAZO.R M. CALLIHAN.D., COLE.R F Atomic Safety and Licensing Board Panel. 2pp. 16316-073 24X Fiche S0-528, 82/11/29, 8212060095
- 8212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines QA/QC plan DEMEY.L. S. Hearing Branch J. 82/12/09 BERNABEI.L. Harmon & Weiss BERNABEI.L. Hourihan, P. Jpp. 16503 022 24X Fiche 50-528, 82/12/09, 8212220118
- K Utility Final Gafety Analysis Report (FSAR) & amends
- 8212070328 Forwards Amend 10 to FSAR
 VAN BRUNTLE E Arizona Public Bervice Co 82/12/Q6 Office of
 Nuclear Reactor Regulation, Director 2pp 16345 047 24X
 Fiche 50-528, 82/12/06, 8212070328.
- --8212070331 Amend 10 to FSAR Two oversize drawings encl Aperture cards are available in FDR

 * Artiona Public Service Co 82/12/31 318pp 16345 049 24X
 Fiche. 50-528.82/12/06.8212070328
- 8212210075 Forwards Proof of Svc for Amend 10 to FSAR VAN BRUNT, E. E. Arisona Public Service Co. 82/12/15, Office of Nuclear Reactor Regulation, Director 3pp, 16485-252 24X Ficher 50-528, 82/12/15, 8212210075

M Antitrust correspondence

- BRI2080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuance & availability Amend deletes M-S-R Public Power Agency as co-owner EISENHUT, D O Division of Licensing 82/12/06 VAN BRUNT, E Arizona Public Service Co 4pp. 16354 061 24X Fiche 50-528,82/12/06,8212080179
- --8212080188 Amend 5 to CFPR-141, CPPR-142 & CFPR-143, deleting M-6-R Public Power Agency as co-owner EISEMNUT, D. 0 Division of Licensing, 82/12/04 6pp. 16354-065 24X Fiche 50-528,82/12/06,8212080179
- --B212080195 Safety evaluation supporting Amend 5 to CPPR-141.CPPR-142 to CPPR-143
 * Office of Nuclear Reactor Regulation, Director, 82/12/04 2pp 16334 071 24X Fichs 50-528,82/12/06.8212080179
- --B212080204 Notice of insuance & availability of Amend 5 to CPPR-141, CPPR-142 & GPPR-143 KNIGHTON.O H Licensing Branch 3 B2/12/06 2pp 16354 073 24% Fiche 50-528,82/12/06.8212080179
- G Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1. "Stress Cracking in Thick-Wall. Large-Plameter. Stainless Steel. Recirculation Sys Piping at 5MR Plants " Svc list encl
 DEYOUND. R. C. Director's Office. Office of Inspection and
 Enforcement 82/10/28 Consolidated Edison Co of New York, Inc
 11200 16462 163 24X Fiche 50-000. 82/10/28. 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list encl
- enci COBB.L I. Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142. 24X Fiche 50-000,82/11/05,8208170245
- 8212050143 Requests extension to resgond to items of noncompliance in IE Insp Repts 50-528/82-25,50-529/82-07 & 50-530/82-10 Rept will be submitted by 821119. VAN BRUNT, E.E. Arizona Public Service Co. 82/11/10 STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs Ip 16314:067 24X Fiche 50-528,82/11/10,8212060143.

- 820B190251 JE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York. Inc. 109pp 16411 199 24) Fiche 50-000.82/11/18.8208190251
- 8208190284 IE Info Notice 82-46. "Defective & Obsolete Combination Padiotek " Svc list encl DEYDUNO,R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127sp 16411 085 24X Fiche 50-000.82/11/26.8208190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24x Fiche 50-000,82/11/30.8208190257
- 8212210203 Forwards IE Insp Repts 50-928/02-27.50-527/02-12 & 50-530/02-13 on 821004-08 No noncompliance noted STERNBERG.D M Division of Resident Reactor Project & Engineering Programs 92/11/30 VAN SRUNT.E E Ariona Public Service Co 2pp 16485 022 24X Fiche 50-528.82/11/30.8212210203
- --B21221021i IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on B21004-08 No noncompliance noted Major areas inspected licensee action on previous insp findings, electrical cable installation & containment structural steel welding ECKMARDT, J H. D'ANGELD, A. YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/11/29 7pp 16485 024 24X Fiche 50-528,82/11/30,8212210203
- BPOBI90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG.R.C Director's Defice, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Int 113pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 6208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Syr list encl JORDAN, E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24x Fiche 50-000, 82/12/03, 8208190261
- 8212090546 Ack receipt of 821122 ltr informing NRC of steps taken to correct violations noted in IE insp on 820834-0903 STERNBERO, D.M. Division of Resident Reactor Project & Engineering Programs 82/12/03 VAN BRUNT, E E Arijona Public Service Co 1; 16366-344 24X Fiche 50-528-82/12/03.8212090546
- --8212070552 Responds to NRC 821008 ltr re violations noted in IL insp on 820830-0903 Corrective actions as-built weld pattern reconciled against weld pattern of Comsip Customline Corp VAN BRUNTLE E Arizona Public Service Co 82/11/22 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 14264 345 24X Fiche 50-528,82/12/03.8212090546
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Oas Monitoring " Svc list encl
 DEYGUND, R C Director's Office. Office of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127p 16628 191 24X Fichs 50-000.82/12/16.8208190267
- 8208190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Syc list enel JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 248 Fiche 50-000,82/12/20,8208190268
- S Reportable occurrences, LERs & related correspondence
- 8212060275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubicles w/o seismically qualified design Initially reported on 821021 Anchorage will be provided on all four sides Also reportable under Part 21 VAN DRUNY, E E Arizona Public Service Co 82/11/22 STERNBERG, D M Division of Resident. Reactor Project & Engineering Programs 3pp 16312 137 24X Fiche 50-528,82/11/22,8212060275
- 8212130267 Interim Deficiency Rept DER-82-61 re reactor coolant pumps diffusor-ring cap screws which may fail & damage pump Cap screw mail heat treatment will be changed so that matl will not be susceptible to cracking VAN BRUNT.E E Arizona Public Service Co 82/11/22 STERNBERG.D N Division of Resident. Reactor Project & Engineering Programs 3pp 16390 158 24X Fiche 50-528.82/11/22.8212130267

- 8212130216 Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank Initially reported on 821026
 Bechtel performing independent detailed analysis Final rept expected by 830210
 VAN BRUNTLE E Arizona Public Service Co 82/11/24 STERNBERO, Division of Resident, Reactor Project & Engineering Programs 16390 120 24X Fiche 50-528,82/11/24.8212130216
 - 82/11/24 STERNBERG, D M
- 8212210077 Interim Deficiency Rept DER 81-14 to A-354 anchor bolt failures Initially reported on 810527 Final rept including Teledyne & Battelle repts will be submitted by 830131 Delay
- due to extensive evaluations

 VAN BRUNT: E Arizona Public Service Co 82/11/29 STERNBERG. D i

 Division of Resident. Reactor Project & Engineering Programs 2pp
 14485 248 248 Fiche 50-528,82/11/29.8212210077 82/11/29 STERNBERG, D M
- 8212210086 Deficiency Evaluation Rept 82-64 re installation of distantial metal socket welds, restricted by Revision 10 of PM-204, due to delay in receipt of revised drawings beficiency not reportable per 10CFR50 55(s) VAN BRUNTLE E Arizona Public Service Co 82/11/29 STERNBERG, D N Division of Resident, Reactor Project & Engineering Programs 2pp 16493 OIB 24X Fiche 50-528,82/11/29,8212210086
- 82122(0225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri load ctry w/improperly crimped AMP termination lugs Initially reported on 820813 All terminations utilizing AMP crimp type lugs will be inspected for compliance
 VAN BRUNTLE E Arizona Public Service Co 82/12/07 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 16484 227 24X Fiche 50-528,82/12/07,8212210225
- B212280227 Interim Deficiency Rept 82-68 re underground cables to startup transformers Initially reported on 821126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by 830222 VAN BRUNTLE E Arizona Public Service Co 82/12/13 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16562 261 24X Fiche 50-528,82/12/13.82122802227
- 8P12280407 Interim Deficiency Rept BER 82-43 re Commit main control panels w/improperly crimped termination lugs Initially reported on 820813 Due to extensive evaluation, next rept will not be submitted until 830207 VAN BRUNT, E.E. Arizona Public Service Co. 82/12/13 STERNBERG, VAN BRUNT,E E Arizona Public Service Co 82/12/13 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 2pp 16539 039 24% Fiche 50-529,82/12/13.8212280407
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8212010448 Summary of 821020 meeting w/util,C-E & Bechtel in Bethesda, MD re pipe whip restraints LICITRA.E A Licensing Branch 3 82/11/18 Licensing Branch 3 Bpp 16270 226 24% Fichs 50-528,82/11/18,8212010448
- 8211270135 Forwards "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1.2 & 3." Vol 1, "Executive Summary," Vol 2, "Program Results" & Vol 3, "Potential Finding Repts " TURLEY,K L Arizona Public Service Co 82/11/19 DENTON,H R Uffice of Nuclear Reactor Regulation, Director 2pp 16278 001 24X Fiche 50-528,82/11/19,8211270135
- --B211270142 Forwards, under separate cover, "Independent QA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3," Vols 1,2 & 3 No reason seem to prohibit issuance of full power OL for Units 1,2 & 3
 SIMON, WA Torrey Pines Technology 82/11/19 DENTON, HR
 DFfice of Nuclear Reactor Regulation, Director 1p 16278 003
 24X Fiche 50-528,62/11/19,8211270135
- --8211290148 "Independent GA Evaluation of Palo Varde Nuclear Generating Station Units 1.2 & 3," Vol 1. "Executive Summary " * Torrey Pines Technology GA-C16924 Vol 82/10/31 27pp 16298 004 24% Fiche 50-528,82/11/17.8211290135
- --B211290150 "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1.2 & 3." Vol 2. "Program Results" # Torrey Pines Technology 0A-C16924 VO2 B2/10/31 163pp 16278 192 24% Fiche 50-528,82/11/19.8211290135
- --B211290155 "Independent GA Evaluation of Palo Verde Nuclear Generating Station Units 1,2 & 3," Vol 3, "Potential Finding Repts," Books 1 & 2 * Torrey Pines Technology GA-C16724 VO3 82/10/31 1404pp 14278: 355 24X Fich* 50-528, 82/11/19, 8211290135

- 8212080564 Requests addl info re probability study of tornado missile damage to UHS (spray pond) to complete review of PRA open item Response should be provided by 821215 W/o stated encl KNIGHTON.G W Licensing Branch 3 82/11/23 VAN BRUNT,E E Aritona Public Bervice Co 1p 16368 352 24X Fiche 50-520.82/11/23.8212080564
- 8212130405 Responds to 821028 request to authorize use of ASME Code Cases N-338 & N-339 in component const Code Case N-338 conditionally acceptable sub; to indicated conditions Code Case N-339 approved for general use KNIGHTON.O W Licensing Branch 3 82/11/29 VAN BRUNT,E E Arizona Public Service Co 2pp 16412 100 24% Fiche 50-528,82/11/23,8212130405
- 8P12270418 Responds to FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREQ-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 8HOLLY, S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000, 82/11/26, 8212270418
- --82:1050027 Forwards summary of semiscale test results & advises that board notification re test results issued W/o encl MGVAK.T K Assistant Director for Licensing 82/09/24 Division of Licensing ip 16549 278 24X Fiche 50-000.82/11/26.
- 8212090666 Notification of 821208 meeting w/util,8ANL,C-E & Burns & Roe in Maricapa County.AZ to discuss shutdown heat removal sys design for CESBAR 8ys 80 plant LICITRA:E A Licensing Branch 3 82/12/01 KNIGHTON,G W Licensing Branch 3 3pp. 16379 243 24X Fiche 50-528,82/12/01,6212080666
- B212220069 Summary of B21117 meeting w∕util & Bechtel in Bethesda.MD re natural circulation testing & training per TML Action Item 1 G 1 LICITRA, E. A. Licensing Branch 3 82/12/01 Licens 5pp 16926 348 24% Fiche 50-528, 82/12/01, 8212220063 Licensing Branch 3.
- 8212770109 Forwards comments on draft environ protection plan NRC should accept other federal agency findings w/o further review
 VAN BRUNT.E E Aritona Public Service Co 82/12/02
 Assistant Director for Licensing 4pp 16327 291 ;
 Ficha 50-528, 82/12/02, 8212070109 NOVAK, T. H. 944
- B2120B0179 Forwards Amend 5 to CPPR~141.CPPR-142 & CPPR-143.safetu 2120B0179 Forwards Amend 5 to CPPR-141. CPPR-142 & CPPR-143. safety evaluation & notice of issuance & availability Amend deletes M-8-R Public Power Agency as co-owner EIBENHUT, D 0 Division of Licensing 82/12/06 VAN BRUNT, E E Arisona Public Service Co 4pp 16354.061 24X Fiche 50-528.82/12/06.8212080179
- --8212080188 Amend 5 to CPPR-141, CPPR-142 & CPPR-143, deleting M-B-R Public Power Agency as co-owner. EISENMUT,D Q Division of Licensing 82/12/06 6pp 16354 065 24X Fiche 50-528,82/12/06.8212080179
- --8212090195 Bafety evaluation supporting Amend 5 to CPPR-141.CPPR-142 & CPPR-143 ness. Office of Nuclear Reactor Regulation, Director 62/12/06 2pp 3354 071 24X Fiche 50-528,82/12/06,8212080179
- --8212080204 Notice of issuance & availability of Amend 5 to CPPR-141. CPPR-142 & CPPR-143 KNIGHTON,O W Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528,82/12/06.8212080179
- 8212270473 Trip rept of 821103-04 site visit by Instrument & Control Bys Branch re physical arrangement & installation of instrumentation & control electrical equipment in accordance w/design criteria Control cabling acceptable LICITRA, E.A. Licensing Branch 3 82/12/13 Licensing Branch 3 10pp 16606 048 24X Fiche 50-528,82/12/13,8212290473.
- 8212220440 Board Notifications 82-125 & 82-125A forwards info re 212220440 Board Notifications B2-125 & 82-125A forwards into H Etherington evaluation of flow blockage during natural circulation of PWRs Results do not adversely impact present position on refiance on natural circulation NOVAK.T.M Assistant Director for Licensing B2/12/14 Safaty and Licensing Board Fanel. Spp 16523 135 24X Fiche 50-000, B2/12/14, B212220440
- 8212220461 Board Notification 82-124 forwards RJ Mattson 821123 memo re Samiscale S-UT-S test results. Phenomena of core level depression & loop seal clearing may be more complex than previously supposed NGVAK,T M Assistant Director for Licensing, 82/12/14 Safety and Licensing Board Panel 7pp 16523 169 24X Fiche 50-000, 82/12/14, 8212220461 Atomic

- 8212270129 Forwards change to FSAR Section 1 8, adding fission chamber detectors & sealed sources to exception taken to Reg Guide 1 38 Change will be included in upcoming FSAR amend VAN BRUNT, E E Arizona Public Service Co 82/12/21 NOVAK, T M Assistant Director for Licensing 3pp 16538 149 24X Fiche 50-528, 82/12/21, 8212270129
- E NAC Safety Evaluation Report (SER), supple & correspondence
- 8212210107 Discusses confirmatory issue re motor operators powered from vital sources, per SER (NUREG-0857) Plant design modified to include motor operators on appropriate valves VAN BRUNT, E.E. Arizona Public Service Co. 82/10/28 NOVAK, T.M. Assistant Director for Licensing. 2pp. 16491.049 24X Fiche \$0-528,82/10/28,8212210107
- B212030031 Forwards schedule for submitting requested into & remaining outstanding & confirmatory issues discussed in Suppl 3 to SER, per NRC B20929 ltr
 VAN BRUNT, E E Arizona Public Service Co 82/11/29 NOVAK, T H
 Assistant Director for Licensing 6pp 16305 076 24X
 Fiche 90-528, 82/11/29, 8212030031
- 8212130292 Advises that all piping components in essential ASME Code Class 1.2 & 3 piping sys designed to Levels C & D syc limits evaluated against emergency & faulted conditions imposed by screening criteria All criteria met VAN BRUNT, E E Arizons Public Service Co 82/12/09 NOVAK, T M Assistant Director for Licensing App 16390-062 24X Fiche 50-528, 82/12/09,8212130292
- F Security, medical, emergency & fire protection plans
- 9212080157 Forwards response to 821202 telephone request to emergency operations facility Conceptual design for upgraded emergency response facilities under NRC review.

 VAN BRUNT.E E Arizona Public Service Co 82/12/06 NDVAK.T M Assistant Director for Licensing 4pp 16/354 088 24X

 Fiche 50-528,82/12/06,8212080157
- O Adjudicatory correspondence
- B212010202 Requests consideration of West Valley Agricultural Protection Council, Inc. supplemental memorandum supporting Council petition to intervene Brief includes useful analysis

 BERLIN, K. Affiliation Unknown 82/11/29 LAZO, R. M., CALLIHAN, D., COLE, R. F. Atomic Safety and Licensing Board Panel 1p 16258 053 24X Fiche 50-526,82/11/29,8212010202
- 8212060075 Requests West Valley Agricultural Protection Council, Inc 821018 supplemental memorandum supporting petition to intervene be stricken from record if not stricken Joint Applicants answer should be allowed CRAMFORD. V A Should Wilmen CRAMFORD. V A Joint Applicants-Palo Verde 82/11/27 LAZD.R M. CALLIMAN.D. COLE.R F Atomic Safety and Licensing Board Panel 2pp 16316 073 24X Fiche 50-528.82/11/29.8212060075
- 8212220118 Forwards Torrey Pines Technology 820714 ltr & revision to Torrey Pines CA/GC plan DENEY.L S Hearing Branch 3 82/12/07 DERNABEL,L Harmon & Weiss BERNABELL Hourihan, P 3pp 16503 022 24X Fiche 50-528, 82/12/07.8212220118
- : Utility Final Bafety Analysis Report (FSAR) & amends
- 3212070328 Forwards Amend 10 to FBAR VAN DRUNT, E.E. Arizona Public Service Co 82/12/06 Uffice of Nuclear Reactor Regulation, Director. 2pp 16345 047 24X Fishe 30-528, 82/12/06, 8212070328
- -B212070331 Amend 10 to FSAR Two oversize drawings encl Aperture cards are available in PDR # Arizona Public Service Co 82/12/31 318pp 16345 049 24X Ficha 50~528,82/12/06,8212070328
- 212210075 Forwards Proof of Svc for Amend 10 to FBAR
 VAN BRUNT, E. E. Arisona Public Service Co. 82/12/15 Office of
 Nuclear Reactor Regulation, Director Jop 16485 252 24X
 Fishe: 50-528, 82/12/15, 8212210075
- Antitrust correspondence
- 212080179 Forwards Amend 5 to CPPR-141, CPPR-142 & CPPR-143, safety evaluation & notice of issuence & availability Amend deletes M-5-R Public Power Agency as co-numer EIBENHUT, D © Division of Licensing 82/12/06 VAN BRUNT, E.E. Arizona Public Service Co 4pp 14354,061, 24X Fiche 50-528,82/12/06,8212080179

- --8212080188 Amend 5 to CPPR-141. CPPR-142 & CPPR-143. deleting M-S-R Public Power Agency as co-owner EISENHUTL 0 D Division of Licensing 82/12/06 App 16354 065 24X Fiche 50-528.82/12/06.8212080179
- --8212080195 Safety evaluation supporting Amend 5 to CPPR-141, CPPR-142 & CPPR-143

 * Office of Nuclear Reactor Regulation, Director 82/12/06 2pp 16354 071 24% Fiche 50-528,82/12/06 8212080179
- --8212080204 Notice of issuance & availability of Amend 5 to GPPR-141, GPPR-142 & GPPR-143 KNIGHTON, G W. Licensing Branch 3 82/12/06 2pp 16354 073 24X Fiche 50-528 82/12/06 8212080179
- Q Inspection reports, IE Bulletins & correspondence
- 820B190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diameter.Stainless Steel.Recirculation Sys Piping at BMR Plants "Syx list encl
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28.8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters" Svc list encl
 COSBLE I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fichs 90-000,82/11/05,8208190245
- 8212060143 Requests extension to respond to items of noncompliance in IE Insp Repts 50-528/82-25,50-529/82-09 & 50-530/82-10 Rept will be submitted by 821119

 VAN BRUNT, E E Arizona Public Service Co 82/11/10 STERNBERG D N Division of Resident, Reactor Project & Engineering Programs ip 14314 049 24% Fiche 50-528,82/11/10,8212040143
- BROBI90251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements " Syc list encl JORDAN,E L Division of Engineering & Guality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18, 8208190251
- B20B190256 IE Info Notice B2-46, "Defective & Obsolete Combination Padlacis " Svc list encl DEYDUNG.R C Director's Office. Office of Inspection and Enforcement S2/II/26 Consolidated Edison Co of New York. Inc 127pp 16411 065 24X Fiche 50-000.82/II/26.8200190256
- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- 8212210203 Forwards IE Insp Repts 50-528/82-29,50-529/82-12 & 50-530/82-13 on 821004-08 No noncompliance noted STERNBERO,D M Division of Resident, Reactor Project & Engineering Programs 82/11/30 VAN BRUNT,E E Arizona Public Service Co App 16485 022 24X Fiche 50-528,82/11/30,8212210203
- ---8212210211 IE Insp Repts 50-528/82-29, 50-529/82-12 & 50-530/82-13 on 821004-08 No nencompliance noted Major areas inspected licensee action on previous Insp findings, electrical cable installation & containment structural steel welding ECKHARDTJJ.H., D'ANGELO,A., VOUNG,T. Division of Resident, Reactor Project & Engineering Programs 62/11/27 7pp 14485-024 24X Fiche. 50-528, 82/11/30, 8212210203
- BPOBI90259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, luc 113pp 16411 317 24X Fiche 50-000.82/12/03.8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JRRDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche, 50-000, 82/12/03, 8208190261
- B212090946 Ack receipt of B21122 ltr informing NRC of steps taken to correct violations noted in IE insp on B20834-0903
 STERNBERG, P M Division of Resident, Reactor Project & Engineering Programs. 82/12/03 VAN BRUNT, E E Arizons Public Service Co 1; 16366 344 24X Fiche 50-528.82/12/03.8212090546

- -8212070552 Responds to NRC 821008 ltr re violations noted in IE inspon 820830-0903 Corrective actions as-built weld pattern reconciled against ueld pattern of Comsip Customline Corp VAN BRUNT.E E Arizona Public Service Co 82/11/22 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 5pp 16366 345 24x Fiche 50-528.82/12/03.8212090546
- 9208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list enc!
 DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 171 24% Fiche 50-000, 82/12/16,8208190267
- 8208190268 IE Info Notice 92-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp. 16628 293 24X Fiche 50-000, 82/12/20, 8208190268
- S Reportable occurrences, LERs & related correspondence
- 82:12060082 Final deficiency rept re Pullman 24-inch pipe spools w/internal surface indications violating min wall thickness Initially reported on 820831 Visual exam performed Deficiancy determined not reportable per 10CFR80 55(e) VAN ORUNT.E E Arizona Public Service Co 82/11/19 STERNBERG.D M Division of Resident, Reactor Project & Engineering Programs App 16316 069 24X Fiche 50-530.82/11/19.8212060082
- EP12040275 Final Deficiency Rept DER 82-58 re Cooper Energy Svcs diesel generator high voltage cubirles w/o seismically qualified design Initially reported on 821021 Anchorage will be provided on all four sides Also reportable under Part 21 VAN BRUNT, E E Arizona Public Service Co 82/11/22 STERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16312 139 24X Fiche 50-528,82/11/22,8212060275
- B./12130259 Final deficiency rept re nonconforming matl certification for diesel generator piston Initially reported on B20930 Nonconformance Rept M0-1445 issued to control & document piston replacement prior to unit startup VAN BRUNT. E E Ariiona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs. 3pp 16396 244 24X Fiche 50-330,82/11/22,8212130259
- GP12130267 Interim Deficiency Rept DER-82-61 re reactor coolant pumps diffusor-ring cap screws which may fail & damage pump Cap screw math heat treatment will be changed so that math will not be susceptible to cracking VAN BRUNT, E E Artiona Public Service Co 82/11/22 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 158 24X Fiche 50-528,82/11/22,8212130267
- 8212130309 Final deficiency rept re improperly crimped termination lugs in control blds switchgear supplied by GE Initially reported on 820802 Connectors not meeting vendor specs will be corrected Also reported per Part 2!

 VAN BRUNT. E E Arizona Public Service Co 82/11/23 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs Spp 16387 340 24% Fiche 50-530.82/11/23,8212130309
- 821213D216 Interim Deficiency Rept DER 82-43 re design calculation error in refueling water tank Initially reported on 821026 Bechtel performing independent detailed analysis Final rept expected by 830210 VAN BRUNT.E E Arizona Public Service Co 82/11/24 STERNBERG.
- ON BRUNTIE E Arizona Public Service Co 82/11/24 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 3pp 16390 120 24% Fiche 50-528,82/11/24,8212130216
- GP12210077 Interim Deficiency Rept DER Bi-14 re A-354 anchor bolt failures Initially reported on 810329 Final rept including Teledyne & Battelle rapta will be submitted by 830131 Delay due to extensive evaluations
 VAN BRUNT,E E Arisona Public Service Co 82/11/29 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs 2pp 16485 248 24x Fiche 50-528.82/11/29,8212210077
- G2:2210086 Deficiency Evaluation Rept 82-64 re installation of distinctal metal sucket welds, restricted by Revision 10 of PM-204 due to delay in receipt of revised drawings beficiency not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 82/11/27 STERNBERO, D. M Division of Resident, Reactor Project & Engineering Programs 2pp 16493 018 24X Fiche 50-528, 82/11/27, 8212210086
- 82:12210225 Final Deficiency Rept DER 82-44 re Gould-Brown Boveri load ctrx w/improperly crimped AMP termination lugs Initially reported on 820813 All terminations utilizing AMP crimp type logs will be inspected for compliance
 VAN BRUNTLE E Arizona Public Service Co 82/12/07 STERNBERG,D M Division of Resident, Reactor Project & Engineering Programs App 16484 227 24X Fiche 50-528,82/12/07.8212210225

- 8212280227 Interim Deficiency Rept 82-68 re underground cables to startup transformers Initially reported on 82126 Cables may not be adequately sized for worst case site soil temp & thermal resistivity conditions Next rept due by 830222 VAN BRUNT.E E Arisona Public Service Co 82/12/13 BTERNBERO, D M Division of Resident, Reactor Project & Engineering Programs 3pp 16562 261 24X Fiche 50-528,82/12/13.8212280227
- DOCKET 50-537 CLINCH RIVER BREEDER REACTOR
- A Application/construction stage documents & correspondence
- 8212230253 Forwards radiological dose calculations used in assessing potential impact of CRBR accidents on Oak Ridge Gaseous Biffusion Plant & Y-12 Plant operation LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/10/28 CHECK, P.S. Clinch River Breeder Reactor Program Office 5pp 16511 049 24% Fiche 50~537.82/10/28.8212230253
- 8P12270484 Notification of contract execution "Casework-CRBR." awarded to 8BA FLEEK/OR.C Technical Assistance Contracts Branch FIN B-8601 B2/11/05 CHECK.P S Clinch River Breeder Reactor Program Office MCRIS.B /RC No Detailed Affiliation Given 1p 16549 360 24X Fiche 50-537.82/11/05.8212270484
- --B212270501 Contract Casework-CRBR." awarded to 8BA

 * Engineering & Economics Research. Inc * 8mall Business
 Administration HAGAN.T F Division of Contracts FIN B-8601
 B2/11/05 2pp 16949 361 24X Fiche 50-537.82/11/05,8212270484
- 8212060395 Supplemental response to 820906 FOIA request for eight categories of documents Forwards documents listed in App A for Items 4 & 5 No other documents subj to request located FELTON. J M Division of Rules and Records 82/11/08 AUDIN.L Affiliation Unknown 2pp 16322 342 24X Fiche 50-320,82/11/08,8212060395
- --8212060403 Items of interest re CRBR fuel cycle environ review, spent fuel reprocessing & TMI-2 waste mgt task force for wk ending 820709 * Office of Nuclear Material Safety & Safeguards, Director 82/07/09 ip 16322 345 24% Fiche 50-000, 82/11/08, 8212040395
- 8212230262 Bummarizes 821108 meeting re CRBR plant steam supply syscomponent degradation monitoring Viewgraphs encl LONGENECKERJ Energy Dapt of, Clinch River Breeder Reactor Plant 82/11/09 CHECK.PS Clinch River Breeder Reactor Program Office lipp 16508 189 24X Fiche 50-537.82/11/09.8212230262
- GP12010161 Forwards summary of 620915 meeting w/NRC in Gethesda,MD re thermal margin beyond design basis Meeting agenda,viewgraphs & attendance list enci LONGENECKER,J Energy,Dept of, Clinch River Breeder Reactor Plant 62/11/12 CHECK,PS Clinch River Breeder Reactor Program Office 140pp 16299 253 24X Fiche 50-537,82/11/12,8212010161
- 8212030323 "SSC Development, Validation & Application & CRBR Balance of Plant Modeling," monthly highlights for Oct 1982 OUPPY, J O Brookhayen National Laboratory FIN A-3015 8212030323 B2/11/12 CURTIS:R T Severe Accident Assessment Branch 7pp 16316 329 24X Fichs 50-537:82/11/12.8212030323
- 8212010146 Forwards addl info for items identified in DDE 820904 ltr re summary for Mechanical Engineering Branch/CRBR 820908-09 mesting LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/11/23 CHECK, P.S. Clinch River Breeder Reactor Program Office 27pp 14260 239, 24% Fiche 50-537, 82/11/23,8212010146
- B212130157 A SIMULANT-MATERIAL EXPERIMENTAL INVESTIGATION OF FLOW DYNAMICS IN THE CRBR UPPER CORE STRUCTURE WILHELM, D. BTARKOVICH, V S. CHAPYAK, E J Los Alamos Scientific Laboratory FIN A-7235 NUREO/CR-2866 82/11/30 Division of Accident Evaluation 82pp 16415 284 24X Fiche 50-837.82/11/30, 021012/01/57
- 8212020262 Summarizes 821123 meeting w/NRC.Burns & Ros.GE & Westinghouse re resolution of equipment qualification items LONGENECKER.J Energy Dept of 82/12/01 CHECK.P 8 Clinch River Breeder Reactor Program Office. Spp 16279 347 24X Fiche 50-537.82/12/01.8212020262
- 8212020303 Forwards update to PBAR Section 6 2 re open containment Update responds to Item 6 of action items from 821018 containment sys meeting Remaining PBAR amonds will be submitted in early Dec LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant 82/12/01. CHECK, PS Clinch River Breeder Reactor Program Office. 7pp. 16278 166 24X Fiche 50-537,82/12/01,8212020303

- 8212080127 Notification of 821216 meeting w/applicants & DDE in Bethesda.MD to discuss shutdown heat removal sys STARK.R M Clinch River Breeder Reactor Program Office 82/1 CMECK.P S Clinch River Preeder Reactor Program Office 3pp 16368 285 24X Fiche 50-537.82/12/02.8212080127 82/12/02
- 8212080143 Notification of 821208-09 meetings w/applicants & DOE in Bethesda, MD to discuss structural engineering review 82/12/02

STARK, R M Clinch River Breeder Reactor Program Office BHECK, P S Clinch River Breeder Reactor Program Office 16367 359 24X Fiche 30-537,82/12/02,8212080143

- 8212070226 Forwards revised responses to NRC 430 Series questions Revisions incorporate mode re electric power & mechanical sys PSAR Sections 8 31 2 14 & 8 3 1 A revised Responses will be incorporated into PSAR, Amend 74 LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/06 CHECK, P 8 Clinch River Breeder Reactor Program Office 920pp 16335 338 24X Fiche 50-537, 82/12/06, 8212070226
- 8P12070243 Forwards addl info requested during B20921-22 & 1118-19 instrumentation working meetings Amended PBAR pages will be incorporated into future PBAR revision LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/06 CHECK.PS Clinch River Breeder Reactor Program Office 77pp 16333 214 24X Fiche 50-537.82/12/06.8212070243.
- 8212070311 Discusses reactor design (Chapter 4) open items raised at 82125-26 working meeting & forwards add1 info documenting NRC issues & project resolutions LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK, P S Clinch River Breeder Reactor Program Office, 13pp 16343 168 24X Fiche 50-537, 82/12/06, 8212070311
- 8212160200 Documents commitments made at 821202-03 meeting w/ Westinghouse, ORNL & Burns & Roe re CRBR control room design Draft revisions to App H. Item I D 1 encl LONOENECKER. J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/06 CHECK.P 8 Clinch River Breeder Reactor Program Office 7pp 16446 116 24% Fiche.50-537.82/12/06,8212160200
- B212140374 Forwards info on thermal margins beyond design base, per B20913 meeting between NRC & CRBR project mgt LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant B2/12/07 CHECK, PS Clinch River Breeder Reactor Program Office 2pp 16401 156 24% Ficher 50-537,82/12/07.8212140374
- --B212140380 "Aerosol Release From Sodium-Concrete Reactions "
 Frototype hydrogen filter preliminary test results encl
 MUHLEGTEIN L, D : COLBURN, R P. Hanford Engineering Development
 Laboratory 82/10/31 23pp 16401 158 24X
 Fiche 50-537,82/12/07.8212140374
- --B212140388 "Hydrogen Distribution in Breeder Reactor Containments," summary rept Miscellaneous updates to CRBRP-3.Vol 2 info on containment cleanup sys & revised response to Guestion C8760 144 on axisymmetric distribution of temps encl BLODM. Q R Hanford Engineering Development Laboratory 82/10/31 67pp 16401 181 24X Fiche 50-537.82/12/07.8212140374
- 8212170190 Forwards marked-up revision to CRBRP-3,Vol 1. "Structural Margin Beyond Design Base," in response to Guestion C8760 162 CO:00 102 LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/13 CHECK, P.B. Clinch River Breeder Reactor Program Office. 5pp 16450 001 24X Ficher50-537,82/12/13,8212170190 82/12/13
- 6212220160 Summary of 820915 meeting w/Sandim in Bethesda, MD re details on venting of reactor cavity, operability of containment ventipungs & cleanup sys & open issues from B20817 meeting STARK, R M Clinch River Brøeder Reactor Program Office B2/12/13 Clinch River Breeder Reactor Program Office B2/12/13 Clinch River Breeder Reactor Program Office Spp 16525 347 24X Fiche 50-537,82/12/13,8212220160
- B212190054 Summarizes Mechanical Engineering Branch/CRBR Project B21122-23 meeting Matrix indicating resolution status &/or addl info for items identified in 820904 Itr & PSAR pages documenting resolution of items encl.
 LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant
 82/12/14 CHECK, P S Clinch River Breeder Reactor Program Office
 915pp 14426 241 24X Fichs 50-337, 82/12/14,8212150054
- 8212150133 Forwards add1 info requested during 820921,22 & 1118 & 19 meetings re instrumentation & control (PSAR Chapter 7) Encl amended PSAR pages will be incorporated into future PSAR 82/12/14, 8212150133

- 8212200077 Forwards add1 clarification re training program per PEAR/ SRP, Section 13 2 Mod will be incorporated info future amond LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant 82/12/17 CHECK.P S Clinch River Breeder Reactor Program Office 3pp 16470 038 24X Fiche 50-537.82/12/17.8212200077
- 8212210045 Summaries 821216 meeting w/NRC.BNL.ANL.Westinghouse,EG&Q & Barthold & Assoc re shutdown heat removal Viewgraphs encl LONGENECKER.J Energy.Dept of, Clinch River Breeder Reactor Plant 82/12/20 CHECK.P S Clinch River Breeder Reactor Program Dffice 40pp 16490 227 24x Fiche 50-537.82/12/20.8212210045
- BP12210050 Forwards responses to NRC comments & amended sections of PSAR Chapter 9, "Plant Auxiliary Bys." per 821215 meeting w/NRC Info will be incorporated into Amend 75 of PSAR, scheduled for Jan 1983 LONGENECKER. J Energy, Dept of, Clinch River Breeder Reactor Plant led for Jan 1983 ECKER.J Energy, Dept of, Clinch River Breeder Reactor Plant 20 CHECK.P S Clinch River Breeder Reactor Program Office 16490 267 24X Fiche 50-537.82/12/20,8212210050
- 8212210095 Forwards add1 info requested at 820921 & 22 & 1118 & 19 working meetings on PSAR Chapter 7, "Instrumentation" & info inadvertently omitted from 821206 submittal Info will be incorporated into future PSAR revision

 LONGEMECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant
 82/12/20 CHECK, P S Clinch River Breeder Reactor Program Office
 11pp 16492 237 24X Fichs 50-537,82/12/20.8212210055
- 8212230007 Summarizes 821220 environ qualification meeting w/Burns & Roe, Westinghouse, NRC & GE Agreements, commitments & viewgraphs encl viewgraphs encl LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P.S. Clinch River Breeder Reactor Program Office 38pp 14511 047 24% Fiche 50-537,82/12/21,8212230007
- 8212230237 Forwards responses to action stoms generated at 821208 meeting w/NRC re filter efficiency for venturi scrubber & plugging of vent pipes behind liners during DBA & thermal margin beyond design base conditions
 LONGEMECKER.J Energy.Dept of, Clinch River Breeder Reactor Plant
 B2/12/21 CHECK.P S Clinch River Breeder Reactor Program Office
 dpp 16511 054 24X Fich= 50-537.02/12/21.8212230237
- 8212230263 Summarizes 821220 reliability program meeting Viewgraphs incl LCHGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/21 CHECK, P.S. Clinch River Breeder Reactor Program Diffice 25pp 16508 213 24X Fiche 50-537, 82/12/21, 8212230263
- 8212230300 Forwards analysis of structural margin beyond design base loads on reactor yessel support ledge.in response to 821209 request LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 82712/21 CHECK,P S Clinch River Breeder Reactor Program Office 13pp 14508 286 24X Fiche 50-537,82/12/21,8212230300
- G2:2230321 Forwards add1 info re secondary control rod sys.per 82:1015 ltr re meeting summary for reactor mechanical shutdown 821914 working meeting EWORKING Meeting LECKERJ Energy Dept of, Clinch River Breeder Reactor Plant 21 CHECK.PS Clinch River Breeder Reactor Program Office 16507 031 24X Fiche 50-537,82/12/21,8212230321 LONGENECKER, J 82/12/21
- BP12270231 Forwards response to NRC 821012 request for add1 info re intermediate heat transport sys tee overtemp problem LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/22 CHECK, P.S. Clinch River Breeder Reactor Program Office 5pp 16537 207 24X Fiche 50-537.82/12/22.8212270231
- 8212270302 Forwards response to request for addl info re DDE 821214 ltr summarizing Mechancial Engineering Branch & CRBR 821122-24 meeting Encl info will be incorporated into Amend LONGENECKER, J. Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/22 CHECK, P.S. Clinch River Breeder Reactor Program Office 33pp 16530 128 24X Fiche 50-537,82/12/22,8212270302
- GP12270185 Forwards addl info re PSAR Chapter 4, "Reactor" Chapter 4 3, Item 1 e & Chapter 4 4, Item 1 d will be incorporated in Amend 75 to PSAR scheduled for submittal LONG ENECKER, J CNECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 2/23 CHECK,P S Clinch River Breeder Reactor Program Office 16539 013 24X Fiche 50-537,82/12/23,8212270185
- 8P12270227 Forwards add1 info requested at 821118-17 meetings re instrumentation (Chapter 7) Amended PSAR pages will be incorporated into Amend 75 of PSAR to be submitted in Jan 1983 LONGENECKER, J Energy Dept of, Clinch River Breeder Reactor Plant 82/12/23 CHECK,P S. Clinch River Breeder Reactor Program Office 8pp 16537 212. 24% Fiche 50-537.82/12/23,8212270229

- 8212270248 Forwards add1 info requested at 820921 meeting on energetics analysis
 - analysis LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/23 CHECK, P.S. Clinch River Breeder Reactor Program Office 10pp 16534 03B 24K Fiche 50-537, 82/12/23, 8212270248
- --8212270250 "Assessment of Unprotected Loss of Flow Accident at End of Cycle-4 in CRBR Heterogeneous Core Design " CAHALAN.J E., DUNN.F E., CRUBER.E E. Argonne National Leboratory 82/12/31 G7pp 16534 048 24X Fiche 30-537,82/12/23,8212270248
- --8212270254 "Freezing of Driver Fuel Upon Entry to Inner Blanket " EFBTEIN,M Fauske & Associates, Inc 82/12/23 4pp 16534 136 244 F1che 50-537,82/12/23,8212270248
- --8212270260 "Results of Reactor Matl Fuel Dispersal Tests GAP-3 & GAP-4 "
 SPENCER.B W , VETTER.D L , WESEL.R Argonne National Laboratory 82/12/23 36pp 16534 140 24X Fiche 50-537, 82/12/23, 8212270248
- G212300215 Forwards add1 info re plant procedures, per agreement Response will be incorporated into PSAR Amend 75, scheduled for submittal in Jan 1983 LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/28 CHECK, P. S. Clinch River Breeder Reactor Program Office 3pp 16598 047 24X Fiche 50-537,82/12/28,8212300215
- G212300253 Forwards add1 info re seismic qualification discussed in PSAR Section 3 10 & revision to Question 270 10 per 821123 request 1 ONGENECKER. J. Energy, Dept. of. Clinch River Brander Reactor Plan
- LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 82/12/28 CHECK,P S Clinch River Breeder Reactor Program Office 6pp 16595 228 24x Fiche 30-337,82/12/28,8212300253
- G212300299 Forwards updated responses to Questions 412 1.2 & 4 re project technical resources, training & utilization of industry experience Updated PSAR Pages H-7 & 8 encl Responses & questions will be incorporated in PSAR amend LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/28 CHECKP S Clinch River Breeder Reactor Program Office 111pp 16594 084 24% Fiche 50~527, 82/12/28.8212300299
- GM:12300343 Forwards illustration of margin in plant protection syssatpoints demonstrating application of instrument channel uncertainties.per NRC request LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant BZ/12/28 CHECK.P S Clinch River Breeder Reactor Program Office Ppp 16594 225 24X Fiche 50-537.82/12/28.8212300343
- B21230024B Application to amend application for CP, consisting of Amend 74 to PBAR Amend revises responses to NRC Questions CB430 1 through 104 LONGENECKER, J Energy, Dept of, Clinch River Breader Reactor Plant, B2/12/30 CHECK, P B Clinch River Breader Reactor Program Office App 16395 284 24X Fiche 50-537, B2/12/30, B21230024B
- & Utility Preliminary Safety Analysis Report, emends
- 8&12150177 Forwards JR Ellwanger affidavit certifying distribution of PSAR. Amend 73 to listed govt agencies & officials on 821130 LONGENECKER. J. Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/07 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 16430 158 24X Fiche 50-537, 82/12/07,8212159177
- BR1230024B Application to amend application for CP, consisting of Amend 74 to PSAR Amend revises responses to NRC Questions CS430 1 through 104 LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/30 CHECK, P. S Clinch River Breeder Reactor Program Office 4pp 16975 284 24X Fiche 50-537, 82/12/30, 8212300248
- --B212300249 Amend 74 to PBAR

 * Energy,Dept of, Clinch River Breeder Reactor Plant 82/12/31
 715pp 16598 288 24% Fiche 50-537,82/12/30,8212300248
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- B212080201 Offers no comments on Suppl 1 to FES for facility
 NEEL A W East Tennessee Development District 82/11/18
 CHECK, P S Clinch River Breeder Reactor Program Office 1p
 16353 362 24X Fiche 50-537.82/11/18.8212080201

- F Security, medical, emergency & fire protection plans
- 8212010011 Forwards Draft B to "CRBR Fire Hazard Analysis Rept," for NRC assessment of intended coverage for plant Add1 work will be required at FBAR stage to completely define & describe procedures & techniques LONDENECKER, J Energy. Dept of, Clinch River Breeder Reactor Plant 82/11/30 CHECK, P S Clinch River Breeder Reactor Program Office ip 16261 809 24% Fiche 50-537.82/11/30.8212010011
- --8212010015 "CRBR Fire Hatard Analysis Rept." Draft B HONG, C Burns & Roe Co ES-26NS-10-004 DRF B 82/11/01 664pp 16261 010 24X Fiche 50-537, 82/11/30, 8212010011
- 8212270294 Forwards responses to requests for addl info re emergency planning, including location of plant emergency personnel & plant éata transmission & control room locations Encl info will be included in Amend 75 to PBAR LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant B2/12/92 CHECK, PS Clinch River Breeder Reactor Program Office 7pp 16530 001 24x Fiche 50-537,82/12/22.8212270294
- G Adjudicatory correspondence
- B212040113 Notification of pending litigation Cases include petition for review & application for stay of Commission B20817 order. EPA & NRC GRBR Project Ofc agreement issue & LMFBR program statement Certificate of Syc encl EDOAR. © L. Project Management Corp. BERGHOLZ, W.E. Energy, Dept of B2/12/03 17pp 16316 085 24X Fiche 50-537, 82/12/03, 82/12060113
- SRI2080257 Suggestions for procedures & scheduling re Court of Appeals, DC Circuit. B21202 remand of applicant elemption requests to Commission Certificate of Sive encl ORECNBERO, E. V. FINAMORE. B. A. Natural Resources Defense Council ORECNBERO, E. V. Bierra Club. B2/12/07 9pp 16354 117 24% Fiche 50-537, 82/12/07, 8212080257
- BP12150123 Forwards chart illustrating proposed witness schedule for contentions to be addressed on B21213-17 during concluding phase of LWA evidentiary hearings SWANSON,D T Hearing Branch 1 82/12/07 MILLER.M., HAND,C H, LINENBERGER.Q Atomic Safety and Licensing Board Panel 2pp 16425 240 24X Fichs 50-507,82/12/07.8212150123
- GP12090082 Notification of pending litigation Court of Appeals, DC Circuit, remanded case re exemption to allow site preparation activities to Commission to reconsider 10CFR50 12 availability M/Certificate of Svc EDGAR, G L Project Management Corp DERGHOLZ, W E Energy, Dept. of 82/12/08 ilpp 16357 335 24% Fiche 50-537, 82/12/08, 82/12/090082
- 8212130205 Order establishing procedures for reconsidering whether exigent circumstances exist warranting grant of applicant request for exemption Order issued per Court of Appeals. DC Circuit remand of record re exemption request CHILK. B. J. Office of the Secretary of the Commission. 82/12/10 6pp. 16396-193 24X Fiche 50-537.82/12/10.8212130205
- 8P12200015 Brief in response to Commission 821210 order. Commission should reaffirm 820817 decision Section 30 12 procedures appropriately involed due to compelling or extraordinary circumstances present Certificate of Sv. encl EDOAR, G L. Project Management Corp. SILVERSTROM, L. Energy, Dept of 82/12/15 27pp. 16473-055 24X Fiche 50-537.82/12/15, G212200015.
- 82/2210326 Forwards corrected Page 3 to Commission 82/210 order. STUCKY,8 W Docketing & Services Branch 82/12/17 Office of the Executive Legal Director 1p, 16496-244 24X Fiche 50-537, 82/12/17, 82/12210326
- ---B212210328 Corrected Page 3 to Commission 821210 order * Commissioners 82/12/17 ip 16496 245 24X Fiche 50-537,82/12/17,8212210326
- 8212230200 Brief in response to Commission 821210 order establishing procedure for reconsideration of existence of exigent circumstances warranting licensing relief under 10CFR50 12 No such circumstances exist Certificate of Svc enci GREENBERG, E V , FINAMORE, B A Natural Resources Defense Council GREENBERG, E V Sierra Club 62/12/21 Commissioners 33pp. 16510 237 24X Fiche 50-537.82/12/21,8212230200

- BP12270245 Advises that "Conference Rept on Continuing Resolution for FY83." published in B21220 Congressional Record Language cited in NRDC & Bierra Club B21221 brief appears on Page HIO636 CREENBERGE V Gallousy & Greenberg B2/12/23 PALLADINO, N J.
- GREENBERG, E V Gallouay & Greenberg 82/12/23 PALLADING, N J . GFLINSKY, V . ROGERTS, T M Commissioners 6pp 16537 160 24X Fiche 50-537, 82/12/23, 8212270245
- 8212300011 Reply in opposition to intervenor response to Commission 821210 order Circumstances surrounding CRBR clearly warrant relief under 100FR50 12 Order eliminates 9-month delay Commission order should be affirmed EDGAR.G L. Project Hanagement Corp. SILVERSTROM.L. Energy, Dept of 82/12/28 Atomic Bafety and Licensing Board Panel 16pp 16598 262 24X Fiche 50-537.82/12/28.8212300011
- O Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03. Revision 1, "Stress Cracking in Thick-Wall. Large-Diameter. Stainless Steel. Recirculation Sys Piping at BMR Plants " Svc list encl DEYGUNG. R C Director's Office. Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- B208190245 IE Info Notice 82-42, "Defects Dbserved in Panasanic Model 801 & Model 802 Thermaluminescent Dosimeters" Svc list encl
 C088.L I Division of Fuel Facilities, Materials & Safeguards
 B2/11/05 Consolidated Edison Co of New York, Inc 110pp
 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 82°08190251 |E Info Notice 82~44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 1641: 199 24X Fiche 50~000, 82/11/18, 8208190251
- BPOB190256 IE info Notice 82-46, "Defective & Obsolete Combination Padlocks" Sic list anci DEVQUNO.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26,8208190256
- 82/08190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Bafeguards 92/11/30 Consolidated Edison Co of New York, Inc 35/pp 16587 028 24X Fiche 50-000.82/11/30.8208190257
- 8P12080148 Notification of 821208 meeting w/applicants & DDE in Bethesda.MD to discuss inservice inspireview items STARK.R M Clinch River Breeder Reactor Program Office 82/12/02 CHECK.P S Clinch River Breeder Reactor Program Office 3pp 16367 273 24% Fiche 50-537.82/12/02.8212080148
- 8708190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03.8208190259
- 8208170261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Bockets " Svc list encl JORDAN E L Division of Engineering & Guality Assurance 82/12/03 Consolidated Edison Co of New York. Inc 110pp 16462 064 24x Fzche 50-000 82/12/03.8208190261
- 8:'OB190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYOUND, R C Director's Office, Office of Inspection and Enforcement B2/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- 8208190268 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.82/12/20.8208190268
- T. Hearing transcripts on non-antitrust matters
- 8212030005 Transcript of ACRS Morking Oroup on Structures & Matls for CRBR 821201 meeting in Bethesda. MD Pp 1-214 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 82/12/01 330pp 16307 160 24X Fichs 50-537.82/12/01.8212030005

- 8212170083 Transcript of 821213 hearing in Oak Ridge,TN Pp 4,947-5,283 * Atomic Safety and Licensing Board Panel 82/12/13 311pp 16452 015 24X Ficha 50-537,82/12/13,8212170083
- 8212200066 Transcript of 821214 hearing in Dak Ridge, TN Pp 5.254-5./04 * Atomic Safety and Licensing Board Panel 82/12/14 449pp 16474 312 24X Fiche 50-537.82/12/14.8218200066
- B212210099 Transcript of B21216 hearing in Oak Ridge.TN Pp 6:141-6:634 Supporting documentation encl * Atomic Safety and Licensing Board Panel B2/12/16 493pp 16491 086 24X Fichs 30-837.B2/12/16.B212210099
- 8212210094 Transcript of 821217 hearing in Oak Ridge, TN Pp 6, 635-6, /31 * Atomic Safety and Licensing Board Panel 82/12/17 97pp 16492 278 24X Fiche 50-537, 82/12/17, 8212210094
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8212080121 Submits daily highlight for 821126 Util submitted GL application Acceptance review will begin upon receipt of appropriate portions of application Fuel loading of Unit 1 scheduled for June 1986 & Dec 1987 for Unit 2 DOOLITTLE.E L Livensing Branch 1 82/11/26 CASE.E , CARTLR.J Office of Nuclear Reactor Regulation, Director EISENHUT.D Division of Licensing 1p 16/367/362 24% Fiche 50~546.82/11/26.8212080121
- B212080114 Requests assistance in performing OL acceptance review Results of review should be received by 830114 Requests for addlinfo should be forwarded to T Novak or BJ Youngblood YOUNOBLOOD, B J Licensing Branch i 62/11/30 JACKSON, R E Geosciences Branch LEAR, G E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch ip 16368 295 24X Fiche 50-546, 82/11/30, 8212080114
- 8712270061 Requests lists of reviewers from each branch who will be assigned to plant CL applications & list of SRP sections for which reviewers will be performing safety reviews YOUNGBLOOD. B. J. Licensing Branch 1 82/12/07 THOMAS. C Standardization & Special Projects Branch EVANS. L. Fuel Facility Safeguards Licensing Branch MCCORKLE. G. W. Power Reactor Safeguards Licensing Branch MCCORKLE. G. W. Power Reactor Safeguards Licensing Branch 2pp 16606 360 24% Fiche 80-000,82/12/09,82/12/09.
- 8212300092 Responds to 821209 memo requesting identification of reviewers & associated SRP sections for forthcoming OL reviews EW McPeek & FD Anderson chosen to review Sections 13 & b 16 0, respectively THOMAS. C O Standardization & Special Projects Branch 92/12/23 YOUNOBLOOD, B J Licensing Branch 1 ip 16624 263 24X Fiche 50-000, 82/12/23,8212300092
- F Security, medical, emergency & fire protection plans
- B212080630 Releases public version of acceptance review copy of emergency plan
 FELTON, JR Division of Rules and Records B2/12/02 Document Management Branch ip 16380 001 24% Fiche 50-546, 82/12/02, B012080630
- --B212080633 Forwards public version of acceptance review copy of emergency plan
 SHIELDS,S W Public Service Co of Indiana. Inc B2/11/23
 DENTON,H R Office of Nuclear Reactor Regulation, Director. Upp
 16380 002 24% Fiche 50-546,82/12/02.8212080630
- --8212080637 Public version of acceptance review copy of emergency plan * Public Service Co of Indiana, Inc. 82/10/31 210pp 16380 005 24X Fiche 50-546, 82/12/02, 8212080630
- 8212220306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER. J O Region 3. Office of Director
 Commonwealth Edison Co 3pp 16503 351 24X Fichs 30-000.82/12/16.8212220306
- B21229049B Requests acceptance review of fire protection rept submitted w/OL application Results requested by B30114 AddI info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood YOUNDBLDGD.B. J Licensing Branch 1 B2/12/16 BENARGYA, V Chemical Engineering Branch 1p 14605 145 24X Ficher S0-546, B2/12/16, B21229049B

1

- B212290502 Requests acceptance review of emergency plan submitted w/UL application by 830114 Addi info required for detailed review should be described in request format & submitted to T Novak application by 830114 Add1 info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblood YOUNGBLOOD, B J Licensing Branch 1 82/12/16 PAGAND, F O Licensing Branch 1 82/12/16, 82/12/16, 82/290502
- GP12290112 Informs of plans to begin const on emergency operations facility & joint public infortr Review of adequacy of protection factors & contingencies requested by 830215 SHIELDS.5 W Public Service Co of Indiana, Inc 82/12/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 16582 243 24% Fiche 50-546.82/12/21.8212290112

C Adjudicatory correspondence

- 8212300086 Notifies that copies of NRC correspondence to applicant will no longer be sent unless requested Documents available at
- irum YOUNOBLOOD,B J Licensing Branch I 82/12/22 FREY.D 0 Audul Society 2pp 16624-264 24X Fiche 50-546.82/12/22.8212300086

O Inspection reports, IE Bulletins & carrespondence

- 8208190240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants " Syc list enci
- at BMR Plants "Syc list enti DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 90-000.82/10/28,8208190240
- 8.708190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 2 Model 802 Thermolominescent Dosimeters" 8vc list COBB.L I Division of Fuel Facilities, Materials & Safeguard 02/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24% Fiche 50-000,82/11/05,8208190245
- 8:08190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24X Liche 50-000 82/11/18.8208190251
- G./12080398 Forwards IE Insp Repts 50-546/82-14 & 50-547/82-14 on G20801-1008 & notice of violation KNDP.R C Division of Project & Resident Programs 82/11/22 SHIELDS,8 W Public Service Co of Indiana, Inc. 2pp 16352 24X Fiche 50-546,82/11/22,8212080398 16352 293
- --8212080402 Notice of violation from insp on 820801-1008 KNDP, R C Division of Froject & Resident Programs (16352 275 24X Fiche 50-544.82/11/22.8212080398 B2/11/22 1o
- 8212080407 IE lnsp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 Noncompliance noted failure to implement preservation program for matis & equipment HARRISON. J J , KONKLIN. J E Division of Project & Resident Programs 82/11/22 lipp 16352 276 24X Fiche 50-546.82/11/22, 8212080379
- BJOB190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.82/11/26.8208190256
- 82/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Mati "Syr list encl COBE.L I Division of Fuel Facilities, Materials & Gafeguards 62/11/30 (Consolidated Edison Co of New York, Inc 354pp 16367 028 24X Fiche 50-000,82/11/30,8208190257
- 8708190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000,82/12/03,8208190259
- 8208190261 IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/12/ Consolydated Edison Co of New York, Inc J10pp 16462 064 (Fiche 50-000, 82/12/03,8208190261 82/12/03
- 8712290406 Forwards IE Insp Repts 50-946/82-19 & 50-947/82-19 on B21201-03 No noncompliance noted

 KNOP, R C Division of Project & Resident Programs 82/12/14

 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp. 16587 102 24x Fiche 50-\$46,82/12/14,8212290406

- --8212270414 IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No non-compliance noted Major areas inspected site tool & discussions w/licensee staff PECKER.PR & KONKLIN.JE Division of Project & Resident Programs 82/12/13 2pp 16587 104 24X Fiche 50-546,82/12/14,8212270406
- 620B190247 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Qas Monitoring " Sve list encl BEYDUNG.R C Director's Office of Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000, 82/12/16,820B190267
- B2:12280304 Advises that onsite radiograph sets of piping subassemblies supplied by ITT-Orinnell reviewed, in response to IE Bulletin B2-01, Revision 1. Suppl 1 Two subassemblies rejected Results of Investigation until be provided by 83020f SHELDS, 8 W Public Service Co of Indiana, Inc B2/12/16 KEPFLER, J O Region 3, Office of Director 2pp 16561 097 24X Fiche 50-546, 82/12/16, 8212280304
- 8212280321 Responds to IE Bulletin 82-04 Bunker-Ramo electrical penetrations not planned for use in safety-related sys SHIELDS.S W Public Service Co of Indiana, Inc 82/12/16 KEPPLER, J O Region 3, Office of Director 2pp 16561 066 Fiche 50-546, 82/12/16, 82/228032
- 8208190268 IE Info Natice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24) Fiche 50-000, 82/12/20,8208170268
- S Reportable occurrences, LERs & related correspondence
- B212100181 Final deficiency rept re conduit & cable tray hanger insprepts Initially reported on 820721 Commonwealth-Lord
 Joint Venture revised insprocedures to clarify
 documentation requirements
 SHIELD8.S W Public Service Co of Indiana. Inc 82/12/03
 KEPPLER, J O Region 3. Office of Director 2pp 16373 353 24X
 Fiche 50-546.82/12/03.8212100181
- 82:12170329 Interim deficiency rept re operation of centrifugal charging pumps during high energy line repture Initially reported on 800509 Westinghouse evaluating util alternative proposal for equipment mod Next rept will be provided by 830429 SHIELDS. S. W. Public Service Co. of Indiams. Inc. 82/12/09 KEPPLER, J. O. Region 3. Office of Director 2pp. 16456-164 24X (iche 50-546.82/12/09,8212170329
- 82:12280157 Interim deficiency rept re design of Robertshaw Controls Conthermostatic valves installed in Colt Industries diesel generators Initially reported on 820802 Procedure to inspect & modify valves being developed Aiso reported per Part 21 GHIELDS, S W Public Service Co of Indiana, Inc 82/12/17 KEPPLER, J O Region 3, Office of Director 2pp 16554 096 24X Fiche 50-546, 82/12/17,8212280157
- 8P12280462 Interim deficiency rept re procedural changes requiring spec/design changes be contractually imposed on suppliers & contractors Initially reported on 821208 Special process procedure issued Next rept expected by 830730 8HEELDS, S.W. Public Service Go. of Indiana. Inc. 82/12/17 KEPPLER, J.Q. Region 3, Office of Director. 2pp. 16556-027 2/ Fiche 50-546, 82/12/17.8212280462 24 X
- S2:12280272 Interim deficiency rept re approval of disposition of contractor nanconformance rept w/o design subcontractor review of equipment Initially reported on 820811 Action to redisposition rept taken Next rept expected by 830218 SHIELDS 8 W Public Service Co of Indiana, Inc 82/12/20 KEPPLER. J O Region 3. Office of Director 2pp 16556 136 Fiche 50-546, 82/12/20,8212280272
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8P120B0121 Submits daily highlight for 821126 Util submitted OL application Acceptance review will begin upon receipt of appropriate portions of application Fuel loading of Unit 1 scheduled for June 1986 & Dec 1987 for Unit 2 DOOLITTLE.E L Licensing Branch 1 82/11/26 CASE.E , CARTER.J Office of Nuclear Reactor Regulation, Director EISENHUT.D Division of Licensing 1p 16367 362 24X Fiche 50-546,82/11/26,82/2080121

- 8212080114 Requests assistance in performing GL acceptance review Results of review should be received by 830114 Requests for add1 info should be forwarded to T Novak or BJ Youngblood YOUNDBLOOD, BJ Licensing Brench 1 82/11/30 JACKSON, R E Geosciences Branch LEAR, O E Hydrologic & Geotechnical Engineering Branch BALLARD, R L Environmental Engineering Branch 1p 16368 295 24X Fich# 50-546,82/11/30,8212080114
- B212290061 Requests lists of reviewers from each branch who will be assigned to plant OL applications & list of SRP sections for which reviewers will be performing safety reviews YOUNGBLOOD, B. J. Licensing Branch 1 B2/12/09 THOMAS, C. Standardization & Special Projects Branch EVANS, L. J. Fuel Facility Safeguards Licensing Branch MCCCRKLE, B. W. Power Reactor Safeguards Licensing Branch Zpp 16606 360 24X Fichs 50-000, 82/12/09, 8212270061
- 8212300092 Responds to 821209 memo requesting identification of reviewers & associated SRP sections for forthcoming OL reviews EM McPeek & FO Anderson chosen to review Sections 13 4 & 16 O, respectively THOMAS. C O Standardization & Special Projects Dranch 82/12/20 YDUNOSLOOD, B J Licensing Branch 1 1p 16624 263 24X Fiche 50-000.82/12/23,8212300092
- F Security, medical, emergency & fire protection plans
- B212080630 Releases public version of acceptance review copy of emergency plan FELTON, J H Division of Rules and Records 82/12/02 Document Management Branch ip 16380 001 24X Fiche 90-546, 82/12/02, 82/1280630
- ~~8212080633 Forwards public version of acceptance review copy of emergency plan SHIELDS,S W Public Service Co of Indiana, Inc. 82/11/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 16390 002 24X Fiche 50-546,82/12/02,8212080630
- --8212080637 Public version of acceptance review copy of emergency plan * Public Service Co of Indiana, Inc 82/10/31 210pp 16380 005 24% Fiche 50-546, 82/12/02, 8212080630
- 8212223306 Discusses layout of communications equipment required in control room, onsite technical support ctr & near-site emergency operations facility
 KEPPLER, J O Region 3, Office of Director
 Commonwealth Edison Co 3pp. 16503 351 24X Fiche 50-000,82/12/16.
- 82;2270498 Requests acceptance review of fire protection rept submitted w/OL application Results requested by 830114 Add1 inforeguired for detailed review should be described in request format & submitted to T Nayak or BJ Youngblood YOUNGBLOOD, BJ Licensing Branch I 82/12/16 BENAROYA, V Chemical Engineering Branch I 9 16608 165 24X Fiche 50-546, 82/12/16, 8212270498
- 8212290502 Requests acceptance review of emergency plan submitted w/OL application by 830114 Addl info required for detailed review should be described in request format & submitted to T Novak or BJ Youngblook YOUNGBLOOD, B J Licensing Branch 1 82/12/16 PAGAND, F G EP Licensing Branch 1p. 16605 164 24% Fiche 50-546,82/12/16. 8212270502
- 82:12270112 Informs of plans to begin const on emergency operations facility & joint public info ctr Review of adequacy of protection factors & contingencies requested by 830015 SHIELDS, 8 W. Public Service Co. of Indiana. Inc. 82/12/21 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16882 243 244 Fichs 50-546,82/12/21,8212270112
- G Adjudicatory correspondence
- BR12300086 Notifies that copies of NRC correspondence to applicant will no longer be sent unless requested Documents available at LPDR YOUNGELOOD.B J Licensing Branch ! 82/12/22 FREY.D Ø Audubon Society Rpp 16624.264 24x Fiche.50-546.82/12/22.8212300086
- O Inspection reports, IE Bulletins & correspondence
- B20Bi90240 IE Bulletin 82-03, Revision 1. "Btress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bys Piping at BMR Plants " Syc list end!
 DEYQUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000, 82/10/20, 8208190240

- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model BO2 Thermolominescent Dosimaters" Svc list onc!

 CODB.L I Division of Fuel Facilities, Materials & Bafeguards 82/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list enc! JORDAN:E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York. Inc 109pp 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8212080378 Forwards IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 & notice of violation KNOB,R C Division of Project & Resident Programs 82/11/22 SHIELDS,S W Public Service Co of Indiana, Inc 2pp 16352 293 24X Fiche 50-546/82/11/22.8212080398
- --8212080402 Notice of violation from insp on 820801-1008 KNDP.R C Division of Project & Resident Programs 82/11/22 ip 16392 295 24X Fiche 50-546.82/11/22, 2212080398
- --8212080407 IE Insp Repts 50-546/82-14 & 50-547/82-14 on 820801-1008 Noncompliance noted failure to implement preservation program for matts & equipment HARRIGON, J. J., KONKLIN, J.E. Division of Project & Resident Programs 82/11/22 lipp 16352 296 24X Fiche 50-846,82/11/22. 8212080398
- 820B190254 IE Info Notice 82-46, "Defective & Obsolete Combanation Padlocks" Svc list encl DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, lic 127pp 16411 065 24X Fiche 50-000, 82/11/26, 8208190254
- 82/08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enci CD88-t I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 394pp 16387 028 24X Fiche 50-000.82/11/30.8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYGUND, R C Director's Defice, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York. Inc 113pp 16411 317 24X Fiche 50-000 82/12/03 8208190259
- 82:08190261 IE info Notice 82-48, "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JARDAN E L. Division of Engineering & Quality Assurance 82/12/0J Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 30-000:82/12/03.8208190261
- BP12290406 Forwards IE Insp Repts 50-546/B2-19 & 50-547/B2-19 on B21201-03 No noncompliance noted NUDP, R C Division of Project & Resident Programs 62/12/14 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 16587 10P 24X Fich 50-546.82/12/14, B212290406
- --8212290414 IE Insp Repts 50-546/82-19 & 50-547/82-19 on 821201-03 No noncompliance noted Major areas inspected sits tour & discussions w/licensee staff PELKE, PR : MONKLIN. J E Division of Project & Resident Programs 82/12/13 2pp 16587 104 24X Fiche 50-546,82/12/14,8212290406
- 8F08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Qas Monitoring " Svc list encl DEVOUNG: R C Director's Office. Office of Inspection and Enforcement 92/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24% Fiche 50-000.82/12/16.8208190267
- 8212280304 Advises that onsite radiograph sets of piping subassemblies supplied by ITT-Grinnell reviewed. In response to IE Bulletin 82-01. Revision 1. Suppl 1 Two subassemblies rejected Results of investigation will be provided by 830201 SHIELDB.S W Public Service Co of Indiana, Inc 82/12/16 KEPPLER. J O Region 3, Office of Director 2pp 16961 097 24% Fiche 50-546, 82/12/16.8212280304
- 8212280321 Responds to IE Bulletin 82-04 Bunker-Ramo electrical penetrations not planned for use in safety-related sys SHIELDS. 8 W Public Service Co of Indiana. Inc 82/12/16 KEPPLER.J G Region 3. Office of Director 2pp 16561 066 24X Fiche 50-546,82/12/16,8212280321
- 820B190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type 17E-27" Svc list and: JORDAN E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24X Fiche 50-000.62/12/20.8208190268

ŕ

S Reportable occurrences, LERs & related correspondence

- 8::12100181 Final deficiency rept re conduit % cable tray hanger insprepts Initially reported on 820721 Commonwealth-Lord Joint Venture revised inspracedures to clarify documentation requirements SHIELDS, S.W. Public Service Co. of Indiana, Inc. 82/12/03 KEPPLER, J. G. Region 3, Office of Director 2pp. 16373 353 24% Fiche 50-546, 62/12/03, 8212100181
- B212170329 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on B00509 Hestinghouse evaluating util alternative proposal for equipment nod Next rept will be provided by B30429 SHEELDS,S W Public Service Co of Indiana, Inc B2/12/09 KEPPLER.J O Region 3, Office of Director 2pp 16456 164 24X Fiche 50-546, B2/12/09.8212170329
- GP12280157 Interim deficiency rept re design of Robertshaw Controls Conthermostatic valves installed in Colt Industries dissels generators Initially reported on 620602 Procedure to inspect & modify valves being developed Also reported per Part 21 SHEEDES W Public Service Co. of Indiana. Inc. 62/12/17 REPPLER. J & Region 3. Office of Director 2pp 16556-096 24X Fiche 50-546. 82/12/17.8212280157
- 82/12280462 Interim deficiency rept re procedural changes requiring spec/design changes be contractually imposed on suppliers & contractors Initially reported on 82/1208 Special process procedure issued Next rept expected by 830730 SHIELDS.5 W Public Service Co of Indiana. Inc 82/12/17 KEPPLER.J G Region 3, Office of Director 2pp 16556 029 24X Fiche 50-546.82/12/17.8212280462
- 87:12380272 Interim deficiency rept re approval of disposition of contractor nonconformance rept w/o design subcontractor review of equipment Initially reported on 820811 Action to redisposition rept taken Next rept expected by 830218 5HIELDS, S W Public Service Co of Indiana, Inc. 82/12/20 KEPPLER, J O. Region 3, Office of Director 2pp. 16556-136 24X Fiche 50-546, 82/12/20, 8212280272

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B211230066 Generic Ltr 82-27 to all BWR licensess of operating reactors except LACSWR, Big Rock Point Dresden 1. Humboltt Bay, applicants for GL & holders of CP re transmittal of NUREG-0763 & NUREG-0783 Svc list encl W/o stated encl [ISENHUT, D G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X [ICHE 50-000, 82/11/15, 8211230066]
- O Inspection reports, IE Bulletins & correspondence
- 82-08190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall.Large-Diamster.Stainless Steel.Recirculation Sys Piping at BMR Plants "Svc list enc!

 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/0/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28.8208190240
- 82-03190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermolyminescent Dosimeters " Svc list incl C088,L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Go of New York, Inc 110pp 16372 142 24% Fiche 50-000,82/11/05,8208190245
- 82/08/190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN.E. L. Division of Engineering & Quality Assurance 82/11/18 Comsolidated Edison Co of New York, Inc. 109pp. 14411 199 2/4X Fiche 50-000, 82/11/18, 8208190251
- 8708170256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " Syc list enc! DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208170256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Syc list encl. COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24% Fiche 50-000,82/11/30.6208190257

- BPOSIFO259 IE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEVOUNG.R C Director's Office. Office of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fichs 50-000, B2/12/03, B20B190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0075 Relay Borkets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 16462 064 24X Fiche 50-000, 82/12/03, 8208190261
- 8208190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNGS C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp 16628 191 24X Fiche 50-000,82/12/16,8208190267
- BPO8190268 IE info Notice 82-50, "Mod of Solid State AC Undervoltage Kelays Type ITE-27" Svc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16428 293 24X Fiche 50-000, 82/12/20, 8208190268
- BOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8211230066 Generic Ltr 82-27 to all BWR licensees of operating reactors except LACBWR.Big Rock Point.Dresden 1. Humboldt Bay, applicants for DL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list encl U/o stated encl EISENHUT.D G Division of Licensing 82/11/15 General Public Utilities OPU Service Corp 22pp 16387 004 24X Fich* 50-000, 82/11/15,8211230066
- G Inspection reports. IE Bulletins & correspondence
- BE08190240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter: Stainless Strel, Recirculation Sys Piping at BNR Plants " Syc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24% Fichs 50-000.82/10/26,8208190240
- 82/08190245 IE Info Notice 82-42. "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L. I Division of Fuel Facilities. Haterials & Safeguards 82/11/05 Consolidated Edison Co of New York. Inc 110pp 16372 142 24% Fiche 50-000, 82/11/05. 82081 70245
- 820Bi90251 IE Info Notice B2-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 16411 199 24) Fiche 50-000, 82/11/18, 920Bi90251
- B20B190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks" Svc list encl DEYOUNO,RC Director's Office, Office of Inspection and Enforcement B2/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000.B2/11/26.B20B190256
- 8P08190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl C088; L. I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidate Edison Co of New York, Inc 354pp 16387 028 24X Fichs 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies "Svc 11st encl DEYOUNO.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp. 16411 317 24X Fiche 50-000.82/12/03.8208190289
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Backets " Syc list encl JORDAN, EL Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462 064 24X Fiche: 50-000, 82/12/03, 8208190261
- 8:08190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 127pp. 16628 191. 24X Fiche 50-000.82/12/16.8208190267

8208190268 IE info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.EL Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York. Inc 108pp 16628 273 24X Fiche 50-000,82/12/20.8208190268

DOCKET BIN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

8P11230066 Generic Ltr 82-27 to all BWR licensees of operating reactors **PICEODA'S Generic Ltr BZ-Z/ to all MAN Incenses of ope except (ACSMR,Big Rock Point,Dresden 1.4kmboldt Bay, applicants for CL & holders of CP re transmittal of NUREO-0763 & NUREO-0763 Svc list entl W/o stated entl EISENMUT.D 0 Division of Licensing 82/11/15 Ge Utilities - OfU Service Corp 22pp 16387 004 24X Fiche 50-000,82/11/15.8211230066 General Public

G Inspection reports, IE Bulletins & correspondence

BPOB190240 IE Bulletin B2-03.Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Bgs Piping at BWR Plants " Bvc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc

16462 163 24X Fiche 50-000, 82/10/28, 8208190240

8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list COSB,L I Division of Fuel Facilities, Materials & Safeguards B2/11/05 Consolidated Edison Co of New York, Inc. 110pp 16372 142 24X Fiche 50-000,82/11/05,8208190245

8208(9025) IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 109pp 16411 199 24X Fiche 50-000, 82/11/18, 8208190251

8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padiocks" Svc list encl
UEYOUNG,R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, 127pp 16411 065 24X Fiche 50-000.82/11/26.6208190256 of New York. Inc

8208190257 IE Info Notice 82-47, "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COBB.L I Bivision of Fuel Facilities, Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 39App 16387 028 24X Fiche 50-000.82/11/30.8208190257

8208190299 IE Bulletin 62-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 14411 317 24% Fiche 50-000, 82/12/03, 8208190259

920819024(IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Bockets " Svc list enc! JORDAN.E L Division of Engineering & Quality Assurance 82/12/0 Consolidated Edison Co of New York, Inc. 110pp 16462 064 : Fiche 50-000,62/12/03,8208190261

8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Honitoring " Syc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York, Inc 24X Fiche 50-000, 82/12/14, 8208170267 16628 191

BROB190266 IE Info Notice 82-50. "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN.E L Bivision of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000.82/12/20.8208190268

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

82(1230056 Generic Ltr 62-27 to all BWR licensees of operating reactors ercept LACSHR.Big Rock Point Dreaden i Humboldt Bay, applicants for GL & holders of CP re transmittal of NURGO-0743 & NURGO-0743 Sv [ist encl W/a stated encl EISENHUT.D @ Division of Licensing 82/11/15 Ce Utilities - OPU Service Corp 22pp 16387 004, 24x Fiche 50-000, 82/11/15,8211230066 . Ceneral Public

- Q Inspection reports: IE Bulletins & correspondence
- 8208170240 IE Bulletin 82-03. Revision i, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping Wall, Large-Usameter stainless greel rectificulation by Piping at BMR Plants " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000.82/10/28,0200170240
- 8:08190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list and! COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Comsolidated Edison Co of New York, Inc. :10pp 16372 142 24X Fiche 50-000,82/11/05,8208190245
- 8:708190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN, E.L. Division of Engineering & Guality Assurance 82/1 Consciidated Edison Co of New York, Inc. 109pp 16411 199 Fiche 30-000, 82/11/18:8208190281 62/11/18
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks "Svc list and!
 DEYOUNG,R C Director's Office, Office of Inspection and
 Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 14411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Notice 82-47, "Transportation of Type A Guantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities, Materials & Gafeguards 82/11/30 Comsolidated Edison Co of New York, Inc 355pp 16387 028 24X Fiche 50-000.82/11/30,8208190257
- BPOB190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies" Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc #13pp 16411 317 24X Fiche 50-000, 82/12/03, 8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc 110pp 14462 064 24X Fiche 50-000, 82/12/03,8208190261
- 8208190267 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl BEYOUNG: R C Director's Office. Office of Inspection and Enforcement 82/12/16 Consolidated Edison Co of New York. Inc 127pp 16428 191 24X Fiche 50-000:82/12/16:8208190267
- GP-08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list enc! JORDAN.E L Division of Engineering & Guality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 74: Fiche 50-000.82/12/20.8208190268

DOCKET STN-50-546 YELLOW CREEK NUCLEAR PLANT, UNIT 1

- Q Inspection reports, IE Bulletins & correspondence
- 8208190240 IE Bulletin 82-03 Revision 1, "Stress Cracking in Thick-208190240 1E Bulletin 82-03.Revision i, "Stress Cracking in Thick-Wall. Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000,82/10/28,8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Syc 11st enci COBB.L. I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co. of New York, Inc. 110pp 16372 142 24x Fiche 50-000,82/11/05,8208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Syc list encl JORDAN.E L Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc. 109pp 16411 199 24x Fiche 50-000, 82/11/18,8208190251
- 8208190256 IE Info Notice 82-44. "Defective & Obsolete Combination Padlocks " Svc Iist encl DEYUUNOR C Director's Office, Office of Inspection and Enforcement 82/11/28 Consolidated Edison Co of New York, Inc 127pp 16411 065. 24X Fiche 50-000.82/11/26,8208190256

- 82/08/90257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Math " Svc list encl COBB-L I Division of Fuel Facilities, Materials & Safeguards B2/11/30 Consolidated Edison Co of New York, Inc 356pp 14/307 028 24X Fiche 50-000/82/11/30/8208190257
- 8708190259 IE Bulletin 82-04. "Deficiencies in Primary Containment Flactrical Penetration Assemblies "Svc list encl DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208170261 IE Info Notice 82-48. "Failures of Agastat CR 0075 Relay Sockets " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462 064 24x Fiche 50-000. 82/12/03,8208170261
- 87:08190267 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEFOLNOR, R C Director's Office, Office of Inspection and Cinforcement 82/12/16 Consolidated Edison Co of New York, Inc 12799 16628 191 24X Fiche 50-000, 82/12/16,8208190267
- 62:08190248 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svr list encl JORDAN, E.L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co. of New York, Inc. 108pp 16628 293 24; [iche 50-000, 62/12/20, 8208190248]
- S Reportable occurrences, LERs & related correspondence
- B):12100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure GA procedures issued before work begins Initially reported on Bi1020 Final rept will not be submitted until decision made on deferral of projects MILLS, L.M. Tennessee Valley Authority 82/12/06 0'REILLY, J.P. Region 2, Orice of Director ip 16377 136 24x Fisher 50-000, 82/12/06, 8212100270
- Si'12200001 Third interin deficiency rept re generic deficiency in design review initially reported on 811215 No addl info evailable until action team 821215 rept Next rept will be submitted by 830420 MILLS, L M Tennessee Valley Author; ty 82/12/13 O'REILLY, J P Region 2, Office of Director ip 16473 362 24X Fiche 50-000, 82/12/13, 8212200001
- BP12200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on B10717 Corrective action to be based on action team rept to be lassed approx B21215 Next rept expected by 830422 MILLS, L M Tennesser Valley Authority B2/12/13 O'REILLY, J P Region 2, Office of Director 2pp 16473 085 24X Fiche 50-000, 82/12/13, 8212200017
- B7:2210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MILLS, L M Tonnessee Valley Authority 82/12/15 O'REILLY, J P Region 2, Office of Director 2pp 16489 168 24X Fiche 50-000, 82/12/15, 8212210431
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2 O Inspection reports, IE Bulletins & carrespondence
- 87/08170240 IE Bulletin 82-03.Revision 1. "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BNR Plants " Svc list encl
 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fichs 50-000, 82/10/28, 8208170240
- 92/09190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 60% Model 60% Thermoluminescent Dosimeters " Svc list cnc! COB6.L I Division of Fuel Facilities, Materials & Safeguards 62/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24% Fiche 90-000,82/11/05,8208190245
- B2:08170251 IE Info Notice 82-44, "Clarification of Emergency Plan Exertise Requirements" Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co. of New York, Inc. 107pp 16411 179 24; Fiche 50-000, 82/11/18, 8208170251

- 8FOR190254 IE Info Notice 82-44, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 16411 065 24X Fiche 50-000,82/11/26,8208190256
- 8208190257 IE Info Natice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl COBB.L I Division of Fuel Facilities. Materials & Safeguards 62/11/30 Consolidated Edison Co of New York, Inc 356pp 14387 028 24X Fiche 50-000.82/11/30.8208190257
- 82'08190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DRYDUNO.R C Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24x Fiche 50-000,82/12/03.62/08190259
- 8/08/9026 | IE Info Notice 82-48. "Failures of Agastat CR 0095 Relay Sockets' Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp 16462-064 24x Fiche 50-000.82/12/03.820819026.
- 82/08190247 IE Info Notice 82-49. "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl DEYOUNG:R C Director's Office. Office of Inspection and Enforcement 82/12/16 Conselidated Edison Co of New York, Inc #27pp 16628 191 24X Fiche 50-000.82/12/16.8208190247
- 8:08190268 IE Info Notice 82-50, "Mod of Solid State AC Undervoltage Relays Type ITE-27 " Svc list encl JORDAN, E. L. Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24X Fiche 50-000,82/12/20,8208190268
- S Reportable occurrences, LERs & related correspondence
- 8212210431 Fourth interim deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 Const activities for Yellow Creek & Hartsville deferred Next rept will be sent by 830322 MILLS.L. M. Tennesses Valley Authority 82/12/15 0'REILLY, J.P. Region 2. Office of Director 2pp 16489 168 24X Fiche 50-000.82/12/15,8212210431
- GP12100270 Fifth interim deficiency rept re lack of Div of Engineering design sys to ensure GA procedures issued before work begins initially reported on Bit020 Final rept will not be submitted until decision made on deferral of projects MILLS.L. M. Tennessee Valley Authority 82/12/06 0'REILLY, J.P. Region 2. Office of Director 1p 16377 136 24X Fiche 50-000.82/12/06.8212100270
- 8912200001 Third interim deficiency rept re generic deficiency in design review Initially reported on 811215 No add1 info available until action toam 821215 rept Next rept will be submitted by 830420 MILLS.L.M. Tennessee Valley Authority 82/12/13 O'REILLY, J.P. Region 2. Office of Director ip 16473 362 24X Fiche 50-000.82/12/13.8212200001
- GP12200017 Fifth interim deficiency rept re design review process interface coordination activity Initially reported on H10717 Corrective action to be based on action team rept to be issued approx B21213 Next rept expected by 830422 NILLS, L M Tennessee Valley Authority B2/12/13 D'REILLY, J P Region 2. Office of Birector 2pp 16473 095 24X Fiche 50-000, 82/12/13, 8212200017

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA
- G2:22:0240 Forwards IE Safeguards Insa Rept 70-0025/82-10 on B2:0:18-20 & 1:0:1-05 No noncompliance noted NORDERHAUO,L R Division of Radiological Safety & Safeguards Program 82/12/14 FIELER,F W Rockwell International Corp 2pp 16483 0:14
- --8212210246 IE Safeguards Insp Rept 70-0025/82-10 on 821018-20 & 1101-05 No noncompliance noted Major areas inspected physical inventory & inventory verification & independent safeguards insp effort Details withheld (ref 10CFR2 790) NELSON, G B, WIEDERA V, BROCK. B L Division of Radiological Safety & Safeguards Program 82/12/13 ip 14483 016

- 8212270058 Requests review & recommendations for action on licensee request for withholding group organizational info & resumes from renewal application for Licensee BNP-21 M/o encl KETILACH,N Uranium Fuel Licensing Branch 82/12/14 ABRAMS.N E Operations & Administrative Division 2pp 16607 051
- 8212300234 Forwards IE Enforcement Conference Rept 70-0025/82-11 on 821122 8PENCER.G S Division of Radiological Safety & Safeguards Program 82/12/22 REMLEY.M E Rockwell International Corp 1p 16595 280
- --8212300240 IE Enforcement Conference Rept 70-0025/82-11 on 821122 Major areas discussed reported radiation overesposure.NRC enforcement applions & concerns & licensee mgt responsibilities UNHNECN.A D., THOMAS.R D. & BOCK.H E. Div[sion of Radiological Safety & Safegyards Program 82/12/21 3pp 16595 281

DOCKET 70-0027 BABCOCK & WILCOX CO . LYNCHBURG, VA

- B212130062 Ack receipt of B21025 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/82-22 01850N.4 F Division of Engineering & Technical Programs 82/11/05 ECKERT.J P Babcack & Wilcor Co ip 16390 169
- --8212130067 Responds to NRC 821004 ltr re violations noted in IE Insp Rept 70-0027/82-22 Corrective actions employee instructed in transfer documentation procedures Procedures will be reviewed by all personnel ECKERT.J P Babcock & Wilcox Co 82/10/25 01850N.A F Division of Engineering & Technical Programs 2pp 16390 169
- --8212130071 Forwards IE Imsp Rept 70-0027/82-22 on 820913-17 & notice of violation Rept & notice of violation withheld (ref 10CFR2 790) GISSON A F Division of Engineering & Technical Programs 82/10/04 ECKERT, J P Babcock & Wilcox Co 2pp 16390 171
- GR12270404 Proposes extension until 830131 to respond to request for addl info in support of renewal of License SNM-42 Delay due to plant shutdowns for Thankspiving & Christmas holidays KELLY, U.W. Babcock & Walicox Co. 82/11/16 KETZLACH.N. Division of Fuel Cycle & Material Safety ip 16572-356
- 8212270537 Requests exception to 10CFR70 51 (e)(3)(i) allowing performance of Nov/Dec 1982 inventory to begin on 830107 Handling of inventory described in 810922 request Administrative amend fee encl KELLY, J W Babtock & Wilcox Co 82/11/16 EVANS, L J Fuel Facility Safeguards Licensing Branch Jpp 16346.358
- 8212090430 Forwards IE Insp Rept 70-0027/82-27 on 821101-03 No noncompliance noted GIBSON A F Division of Engineering & Technical Programs. 82/11/19 ECKERT-J P Babcock & Wilcox Co 2pp 16364-354
- --8212090439 IE Insp Rept 70-0027/82-27 on 821101-03 No noncompliance noted Major areas inspected internal & external exposure control program & procedures HARY, JR. BARR, K.P. Division of Engineering & Technical Programs 62/11/17 Spp 16364-356
- 8212080045 Issues Amend 18 to License SNM-42, authorizing production scale fabrication of box type research reactor fuel elaments
 PAGE,R 9 Uranium Fuel Licensing Branch 82/11/26 KELLY, J & Babcock & Wilcox Co ip 16367 138
- --8212080049 SER supporting D&M 820903 application to amend License SNK-42 authorizing production scale fabrication of box type research reactor fuel elements KETZLACH N Uranium Fuel Licensing Branch 82/11/26 3pp 163e7 139
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC . ATTLEBORD, MA
- 8212270024 Forwards application for Amend 1 to License 8NM-23, authorising termination of license SHERMAN.F.L., SCHEMBFIER,R. Texas Instruments, Inc. 62/11/02 PAGE,R.Ø. Uranium Fuel Licensing Branch 2pp 16551 086
- --8212270030 Application for Amend 1 to License BNM-23, authorizing termination of license W/one oversize figure Aperture card is available in PDR OGETZ, W. CHURCHILL, R. SHERMAN, F. L. Texas Instruments, Inc. 82/11/01 48pp 14551 090

- DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- GP:2010369 Forwards negative declaration & EIA supporting renewal of License GNM-33 PAGE.R G Uranium Fuel Licensing Branch 82/11/24 LICHTENDERGER Combustion Engineering, Inc. 1p. 16271-113
- --B212010372 Negative declaration re renewal of License SNM-33 PAGE,R O Uranium Fuel Licensing Branch 82/11/23 1p 16271 114
- --8212010374 EIA supporting renewal of License SNM-33 + Division of Fuel Cycle & Material Safety 82/11/30 74pp 16271 115
- B212300078 Trip rept of 821208-09 visit to C-E in Hematite.MD re license renewal application BIDINGER.G H Uranium Fuel Licensing Branch 82/12/16 CROW.N (Uranium Fuel Licensing Branch 1p 16624 274
- DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA
- 8212220436 Forwards IE Safeguards Insp Rept 70-0135/82-09 on 821115-19 No noncompitation on tended MARTIM T T Division of Engineering & Technical Programs 82/12/17 COLEMAN, W.L. Babcock & Wilcox Co 2pp 66533 093
- --8212220437 IE Safeguards Insp Rept 70-0135/82-09 on 821115-19 No noncompliance nuted Major areas inspected organization, operations, measurements, internal control & mgt HOLTMER.E . ZIBULSKY.H . GODY.A T Division of Engineering & Technical Programs 82/12/13 3pp 16503 328
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- SPOS290112 FOIA request for repts re inventory differences at NFS plant in Erwin. TN & correspondence between NRC & NFS concerning fuel inventory differences from 1979 to present BARLETT, D L. Philadelphia Inquirer 82/09/15 FELTON, J M Division of Rules and Records ip 16566 084
- GP12080006 Addl response to FDIA request for seven categories of info re NFS.Erwin, TN facility Forwards App A documents denoted w/asterisk FELTON, J M Division of Rules and Records 82/10/25 WEISS, C R Harmon & Weiss 3App 16347 001
- --8212080018 Forwards preprint of "Use of Process Monitoring Data for Enhancement of Matl Control at High Enrichment U Fabrication Facility: "classified confidential-restricted data Official NUREO rept will be submitted within next few wix W/o enc! SMITH. C N Material Control Licensing Branch 79/10/04 HENSLEY, K D Nuclear Fuel Services, Inc. (subs. of Getty 0:1 Cc.) ip 16369-037
- --B212080088 Discusses 791030 NFS.Erwin meeting concerning results of fill investigation Rept of investigation dtd 791015 not yet received by NRC HONARD, E M Division of Safeguards Inspections 79/11/01 STELLO, V Office of Inspection & Enforcement, Office of the Director 19 16370 132
- --B212080073 Submits proposed agenda for Commission 791106 briefing on NFS HUNARD,E M Division of Safeguards Inspections 79/11/01 STELLO,V Office of Inspection & Enforcement, Office of the Director 1p 16370 133
- -- 4212080099 Recommends proposed license conditions for NFS be adopted All items on inventory should be remeasured regardless of period generated except matl shipped offsite & independently verified by receiver
 STELLO, V Office of Inspection & Enforcement, Office of the Director 79/11/05 BURNETT, R F Division of Safeguards 19 14370 134
- --B212080105 Comments on proposed license conditions for NFS & mod of NFS order to allow limited processing New matls balance period should not be considered as starting 791004 physical inventory GAREILLY, J.P. Region 2, Atlanta, Office of the Director 79/11/01 BURNETT, R.F. Division of Safeguards 3pp 16370 135

11

- -8212080113 Discusses 791105 meeting w/NFS re license conditions Bafeguards requirements, including math control & physical security, will be upgraded BLAYLOCK, J. Division of Safeguards Inspections 79/11/06 CHAPELL, D.R. Division of Safeguards Inspections ip 16370 138
- --B2120B0117 Discusses Commission 791106 briefing re NFS status FBI investigation uncovered no evidence of illegal employee activity Cause for inventory difference not identified BLAYLOCK, J. Division of Safeguards Inspections 77/11/08 CHAPELL, D.R. Division of Safeguards Inspections 14pp
- --B212080129 Advises of B10103 or 0104 informal briefing for congressional aides from Oversight Committee in Washington, DC on status of NFS Erwin Briefing requested by Acting Chairman Ahearne in view of recent media interest HOMARD, E.M. Division of Safeguards Inspections 79/12/28 STELLO, V. Office of Inspection & Enforcement, Office of the Director ip 16370 153
- --B212080149 Supplemental PNS-II-79-102K on 791102, initial reinventory efforts resulted in partial reconciliation of 790917 difference Unresolved inventory difference in excess of regulatory limits for continued operation remains LEE.TD Region 2, Atlanta, Office of the Director 79/11/02 ip 16370 155
- ~~B212080154 Documents telcon w/F Qillespie,Region 2 re ongoing NFS events NRC will issue press release to head off publicity Region 2 will prepare briefing for Commission 791106 meeting on NFS Semifinished fuel will not be processed SLAYLOCK.J Division of Safeguards Inspections 77/11/06 CHAPELL.D R Division of Safeguards Inspections ip 16370-156
- 9212160072 Forwards Revision 2 to safeguards contingency plan Revision withheld MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/11/05 EVANS,L J Fuel Facility Safeguards Licensing Branch ip 16447 252
- 83'121&0420 Forwards request for amend to License SNM-124 Administrative amend fee encl Amend withheld (ref 10CFR2 790)
 HENSLEY,K D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 62/11/09 EVANS,L J. Fuel Facility Safeguards Licensing Branch
 1p. 16447 191
- 82:12090240 Ack receipt of IE Insp Rept 70-0143/82-26 No proprietary Info NANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 92/11/10 GIBSON.A F Division of Engineering & Technical Programs 1p 16363-245
- 8212160429 Ack receipt of IE Insp Rept 70-0143/82-36 No proprietary info MANSER, W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 82/11/10 GIBSON, A F Division of Engineering & Technical Programs 1p 16447 188
- 82:2090469 Ack receipt of IE Insp Rept 70-0143/82-38 on 82:013 No proprietary info MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/11/11 OIRSON, A F Division of Engineering & Technical Programs 1p 16363 246
- G212090507 Forwards IE Insp Rept 70-0143/82-42 on B21025-29 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs B2/11/12 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 20s 16366
- --B212090517 IE Insp Rept 70-0143/B2-42 on B21025-29 No noncompliance noted Major areas inspected external & internal radiation exposure.contamination control.audits & insps & ALARA rept KAHLE.J B , BARR.K P Bivision of Engineering & Technical Programs B2/11/09 6pp 16366.354
- 8212090533 Forwards IE Safeguards Insp Rept 70-0143/82-43 on 821004-29 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs 82/11/12 MANSER, M C Nuclear Fuel Services, Inc (subs of Oetty Oil Co)

- --8212090539 IE Bafeguards Insg Rept 70-0143/82-43 on 821004-29 No noncompliance noted Major areas inspected facility operation. criticality safety, radiation/environ/physical protection & SNM control & accounting LEE, T D , MCALPINELE J Division of Engineering & Technical Programs 82/11/10 Spp 16366 333
- 8212100111 Responds to FOIA request for seven categories of info re NFS.Erwin, TN Forwards documents listed in App A Documents listed in App B withheld (ref FOIA Exemptions 3 & 5) FELTON, J M Division of Rules and Records 82/11/12 WEISS, E R Harmon & Weiss App 16388 157
- --0212100121 Forwards addl comments on proposed license conditions for NFG-Erwin re emergency preparedness GRIMGS.8 K Division of Emergency Preparedness 62/03/23 PAGE.R G Vranium Fuel Licensing Branch ip 16388 £64
- --8212100128 Ack receipt of 820225 concerns re timeliness of alerting & notifying nearby residents in event of certain type of emergency at NFS Inc Emergency planning license conditions for NFS discussed TROJANDHSKI.R Region 2. Office of Director 82/03/12 ORAHAM.J A Tennessee. State of 2pp 16488 165
- 82120903B5 Ack receipt of 82100B itr expressing concerns re health physics program at NFS Facility safely operated based upon previous insp findings Mods being made to improve security & radiological controls

 O'REILLY, J P Region 2. Office of Director 82/11/17 HOBLEY, M H
 Tennessee. State of ip 16364 242
- --8212070393 Discusses unfavorable impressions of NFB facility Facility appears to operate in manner warranting shutdown Review of itensee activities requested MOBLEY.M H. Tennessee. State of 82/10/08 O'REILLY, J.P. Region 2, Office of Director Spp. 16364 243
- 8212150293 Forwards "Daily Summary of Stack Monitoring.Oct 1982" MAKSER.W C Nuclear Fuel Services. Inc (subs of Getty Oil Co) 82/11/17 O'REILLY,J P Region 2. Office of Director 1p 16437 393
- --8212150298 "Daily Summary of Stack Monitoring.Oct 1982 "

 * Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 82/11/17

 4pp 16437 354
- 8212090402 Forwards IE Safeguards Insp Rept 70-0143/82-40 on 821104-13
 No moncompliance noted
 GIBSON, A.F. Division of Engineering & Technical Programs 82/11/26
 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.)
 Ppp. 16365-037
- --8212070413 IE Safeguards Insp Rept 70-0143/82-40 on 821104-13
 No moncompliance noted Major areas inspected MC95206-8
 MBA-5 inprocess measurements & MC95213-B MBA-5 physical
 inventory verification Details withheld (ref 10CFR2 790)
 CLAY.E L . MCALPINE.E J Division of Engineering & Technical
 Programs B2/11/24 1p 14365 039
- SP1209040B Forwards IE Safeguards Insp Rept 70-0143/82-46 on 821102-05 No noncompliance noted CIBSON.A F Division of Engineering & Technical Programs 82/11/30 MANSER:W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) Upp 16365 048.
- --8212070416 IE Safeguards Insp Rept 70-0143/82-46 on 821102-05 No noncompliance noted Major areas inspected measurements, measurement control program & followp on greviously identified items Details withheld (nef 10CFR2 770) BATES.J W. SADADOS.J.W. MCALPINE.E J Division of Engineering & Technical Programs 82/11/30 ip 16365 050
- 8P12220527 Informs of interim organizational change affecting License MNM-524, Section 200 Administrative manager position vacant Safety & decommissioning manager directly responsible to general manager All other positions unchanged.

 1DEKER, R L Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/11/30 FAGE, R O Uranium Fuel Licensing Branch 2pp 16522 352
- BP12130189 Responds to NRC 821103 notice of violation contained in IE
 Insp Rept 70-0142/82-37 Corrective actions radiological
 contingency plan will be revised to clarify definition of
 explosion.
 MANSER W C Nuclear Fuel Services, Inc. (subs of Getty Bil Co)
 82/12/01 GIBSON A F Division of Engineering & Technical Programs
 200 16410 358

- 8212270078 Add1 response to FOIA request for repts & correspondence re inventory differences at NFS plant in Erwin. IN Documents completely & partially withheld (ref FOIA Exemptions 3 & 4) FELTON. JM Division of Rules and Records 82/12/03 BARLETT. D L Philadelphia Inquirer. Spp 16566 085
- --B212270112 "Technical Assessment of Inventory Differences at NFS," Jan 1978 - Mar 1980 # Region 2, Atlanta, Safeguards Branch 80/05/27 33pp
- --8212270116 Forwards outline & description of NFS insp program to verify math balance emphasizing measured discards Summary rept detailing further actions will be prepared following insp G*REILLYJ P Region 2. Atlanta, Office of the Director 77/06/07 HOWARD,E M Division of Safaguards Inspections Spp 16566-130
- ~-8212270124 Forwards final rept re 790920 preliminary draft, "Summary Rept of High Enriched Herfluoride Leak,790807 " MANSER:N C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/10/29 OILLESPIE,F P Region 2, Atlanta, Safeguards Branch 15pp 16566 175
- --9212270128 Forwards Fuel Facility & Matis Safety Branch input for Safeguards Branch assessment re NFS inventory differences GIBSON A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/05/20 GILLESPIE.F P Region 2. Atlanta, Safeguards Branch 30pp 14566 212
- 8212150088 PND-11-82-133 on 821013, physical inventory resulted in inventory difference of gain exceeding calculated limit of error Investigation conducted for probable cause MCALPINE, E. J. Region 2, Office of Director 82/12/08 Ip 14/41 004
- 8P12100011 Requests Commission review suggested questions for relevancy & materiality & allow NRC & other parties to respond in writing in lieu of oral session Adequate record can be developed w/written questions Certificate of Svc encl FONNER, R L Regulations Division. 82/12/09 App 16379 154
- 8212270544 Provides results of determinations on spiked unine sample received from RESL, per 821006 ltr request Average of results is 399 DPM U per liter MANSER.U C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82212709 MONTOOMERY.D Region 2. Office of Director 2pp 16546 344
- 82:12:50:38 Forwards IE Safeguards Insp Rept 70-0143/82-44 on 82:11:5-19 No noncompliance noted 018:80N.AF Division of Engineering & Technical Programs 82/12/13 MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 2pp 16423 229
- --8212150143 IE Safeguards Insp Rept 70-0143/82-44 on 821115-19 No noncompliance noted Major areas inspected security plan & implementing procedures.records & repts & physical barriers-protected areas Details withheld (ref 10CFR73 21) TILLMAN.A. MCGUIRE.D R Division of Engineering & Technical Programs 82/12/10 ip. 14423 241
- 8212200021 Response to ARC 821207 request to answer questions in writing Opposes NRC proposal to cancel oral session All parties should answer questions in writing & propose followup questions Certificate of Svc encl MEISS E R Natural Resources Defense Council WEISS E R Harmon & Weiss 82/12/15 Opp 16473 OS7
- 8212210253 Comments on proposed NRDC questions re hypothetical programmatic alternatives to continued operation of plant, in preparation for proceeding on matter Certificate of Svc cocl
 LEIKEN, L. Energy, Dept of 82/12/20 App 16483 303
- 82:2270238 Comments on proposed NRDC questions Seventeen questions beyond scope of proceeding Questions 31 34 & 37 relate to safeguards & security Certificate of Svc encl
 LEIKEM L Energy, Dupt of 82/12/20 dpp 16530 058
- 82:12220224 Advises that Div of Security completed security review of questions filed by NRDC on 82:109 for Commission oral hearing Mati contains no classified info STUCKY-8 W Docketing & Services Branch 82:12/2: Office of the Erecutive Legal Director ip. 165:17-267.
- --8212220248 Classified inserts to NRDC proposed questions to Commission Div of Security determined that mat1 contains no classified info. Certificate of Svc encl WEISB.E R Natural Resources Defense Council WEISB.E R. Harmon & Weiss 82/11/10, 12pp 16517 268.

- B212230344 Order suspending schedule set forth in S21001 order for oral session CHILK.S J Office of the Secretary of the Commission 82/12/21 in 16505 131
- B212300239 Transcript of Commission B21221 meeting in Washington.DC replans for hearing to modify NFS Erwin.TN liconis Pp 1-72 Commissioners 82/12/21 75p 16612 335
- 8212280270 Request to comment on scope of proceeding NRDC entitled to rebut NRC arguments that NRDC questions beyond proper scope of proceeding Suggested response date is 830110 Certificate of Svc enci
 WEISS.E R Natural Resources Defense Council WEISB.E R Harmon & Weiss 82/12/27 Commissioners 5pp 16561 244
- DOCKET 70-0146 SPENCER CHEMICAL CO , KANSAS CITY, MO
- 8212280009 Add1 response to FOIA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A f-ELTON,J M Division of Rules and Records 62/11/29 BARNES, C Affiliation Unknown 2pp 16590 141
- --8212280016 Requests that rept on levels of fixed & removable U contamination, including radiation levels existing on applicable bldgs, equipment & property, he submitted prior to termination of License SNM-154
 NUSGBAUMER.D A Atomic Energy Commission 64/01/06
 OREGNLEE, N A Spencer Chemical Co 1p 16570 148
- --8212280019 Forwards licenses 640302 ltr specifying results of residual contamination survey Closeout insp requested to permit termination of License 8NM-154 NUSSBAUMER. D A Atomic Energy Commission 64/04/07 DUBINSKI-L Atomic Energy Commission 19 16590 151
- --8212280022 Trip rept of 640430 visit to Jayhawk Works site located 22 miles south of Pittsburgh KS. to conduct closeout insp of License SNN-154, in response to TW Brackett 640413 request HALKER.D I Atomic Energy Commission 64/05/20 DUDINSKI.L Atomic Energy Commission 5pp 16590 152
- --8212280024 Recommends that License SNM-154, covering activities performed at Jayhawk Works plant near Pittsburgh, KS, be terminated LAYFIELD, R. L. Atomic Energy Commission 64/12/28 Atomic Energy Commission 1p 16570 158
- --B2122B0026 Outlines soil sample procedures & results of Bi1009 contamination survey of Jayhauk burn site under License SMM-154 No significant difference noted in geiger counter readings on matls or water Field sample diagram encl PURCELL, L D Spencer Chemical Co BI/10/14 SCOTT, L M Spencer Chemical Chemical
- ---8212280030 Forwards results of 810810 radiation survey of advanced matis plant/bidg & pressure veasel test lab.in response to 820512 request No detectable amounts of natural U or thorium found at either bidg site MCCORMACK.0 M Gulf Gil Corp 82/06/04 CAIN.C L Region 4. Office of Director 3pp 16590 163

DOCKET 70-0258 ILLINOIS, UNIV OF, URBANA, IL

- 8212140396 Forwards IE Safeguards Insp Repts 50-151/82-01,50-356/82-02 to 70-0258/82-01 on 821(17-19 to notice of violation Insp rept details withheld (ref 10CFR2 790)

 MILLER, JR Division of Engineering & Technical Programs 82/12/09 MILEY, G H Illinois, Univ of, Urbane-Champaign 2pp 16404 344 24X Fiche 50-151,82/12/09,8212140396
- --B212140414 IE Safeguards Insp Repts 50-151/82-01.50-356/82-02 & 70-0258/82-01 on 821117-17 Noncompliance noted failure to include items containing SNM on annual inventory & to submit 742 forms Details withheld (ref 100FR2 770) MADEDA.T J , CREED.J R Division of Engineering & Tachnacal Programs 82/12/06 ip 16404 347 24X Fichs 50-151.82/12/09, 82/2140396

- DOCKET 70-0340 SPENCER CHEMICAL CO , KANSAS CITY, MO
- 8212280009 Add1 response to FOIA request for six categories of documents re Spencer Chemical Co Forwards documents listed in App A FELTON, J M Division of Rules and Records 82/11/29 BARNES, C Afriliation Unknown 2pp 16590
- --8212280012 Requests correspondence re Spencer Chemical Co be sent to listed address COBB.G H Kerr-McQee Corp 62/09/06 JOHNSON.L Atomic Energy Commission ip 16590 144
- DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT
- 8212010338 Requests add1 info re 820224 application for renewal of License SNM-368 Info should be submitted in 60 days to continue review CRGW-W T Uranium Fuel Licensing Branch 82/11/19 KIRK.W F United Nuclear Corp 6pp 16271 318
- 8P12010497 Advises that info requested in NRC B11216 ltr re Amend 16 on environ sampling for nonradioactive matls & deminimis U release concentrations must be provided within 30 days Failure constitutes basis for denial per 100FR2 108 PAGE.R © Uranium Fuel Licensing Branch 82/11/24 KIRK.W F United Nuclear Corp ip 16270 209
- G-12150266 Lists priority items in B21014 & 26 license change submittals KIRK.W F United Nuclear Corp B2/11/24 PAGE,R G Urahium Fuel Licensing Branch 1p 16446 283
- GP12270541 Discusses request for amend to eliminate non-radiological environ monitoring from NRC license control for License SNM-348 Licensee also subj to CT Dept of Environ Protection regulation for facility efficient & discharge control KIRK.N F United Nuclear Corp 82/12/01 PAGE.R G Fuel Process & Fab Branch (Pre 790727) 3pp 14546 353
- DOCKEF 70-0687 UNION CARBIDE CORP , TUXEDO, NY
- B212160245 Forwards revised fundamental nuclear matts control plan in accordence w/10CFR70 32 Revision incorporates organizational changes & implementation of U-235 recovery in wasts form SNM not affected W/o enci MCGOVERN. J Union Carbide Corp 82/11/04 JACKSON, R L Office of Nuclear Material Safety & Safeguards, pirector ip 16447 202
- 8212070173 Forwards response to 821104 request for addl info & addl Tech Spec changes re renewal fo License R-Bi VOTH,M H Union Carbide Corp 82/11/22 THOMAS,C D Standardization & Special Projects Branch 14pp 16937 001 24X I (che 50-054,82/11/22,8212070173
- 8Pi216033i Requests technical assistance in reviewing seismic info from enci Union Carbide Corp environ submittal Info supports application for renewal of SNM license W/o encl ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/11/23 JACKSDN,R E Ocosciences Branch 1p 16447 201
- 8212210376 Forwards IE Insp Rept 70-0687/82-07 on 821102-05 & notice of violation MARTIK.T T Division of Engineering & Technical Programs 82/12/06 MCGOVERN.J J Union Carbide Corp 2pp 16474 316
- --8212210379 Notice of violation from insp on 821102-05 * Division of Engineering & Technical Programs 82/12/06 ip. 16494 318
- ---8212210390 IE Insp Rept 70-0487/82-02 on 821102-05 Noncompliance noted failure to maintain stored U solution in doubly sealed container & post new waste storage facility w/"caution radioactive matl" sign ROTH. J. GODY, A T. Division of Engineering & Fechnical Programs 82/11/30 9pp 16494 319
- DOCKET 70-0598 WESTINGHOUSE ELECTRIC CORP. PITTSBURGH, PA
- 8212080654 Advises that License SNM-770 renewed for 5 yrs, expiring 871031 Renewal issued following preparation of EIA Negative declaration approved per 100FRS1 FR notice issued 821026 License SNM-770 & SER forwarded PAGE: R G Uranium Fuel Licensing Branch 82/11/30 NARDI, A J Westinghouse Electric Corp 1p 16379 310

- --B212080671 License SNM-770 for Westinghouse, authorizing use of all byproduct math. SNM & source maths (U. depleted U & thorium) in forms & amounts listed, per 810529 revised application & 810807 & 820427 suppls PAGE.R © Division of Fusi Cycle & Material Safety 82/11/30 4pp 16379 311
- --82120B0695 SER supporting renewal of License SNM-770 per 810529 application & 810807 & 820427 suppls subj to listed conditions KETZLACH, N., SUDNG, A. Division of Fuel Cycle & Material Safety 82/10/31 29pp 16379-319
- DOCKET 70-0734 GA TECHNOLOGIES, INC , SAN DIEGO, CA
- 8212010503 Advises of issuance of Amend 5 to License 8NM-696, changing components ownership & name to GA Technologies, Inc PAGE, R G Uranium Fuel Licensing Branch 82/11/26 MOWRY, W R CA Technologies, Inc /General Atomic Co ip 16308 326
- 82:12300207 Forwards IE Insp Rept 70-0734/82-09 on 82:1018-22 & notice of violation BPENCER: 0 S Division of Radiological Safety & Safeguards Program 82/12/08 PARKER, J W OA Yechnologies, Inc /General Atomic Co 2pp 14597 338
- ~-8212300R10 Notice of violation from insp on 821018-22 THOMAS,R D Region 5. Office of Director 82/12/08 ip
- ~-82)2300213 IE Insp Rept 70~0734/82-07 on 821018-22 Noncompliance noted licensee 820309 waste shipment to Chem-Nuclear Bys 8C burial site arrived w/total of 11 holes in two boxes BRCCK-B t. ZURAKGMSKI-P R. THOMAS.R D. Division of Radiological Safety & Safeguards Frogram 82/12/08 12pp 16597 341
- DOCKET 70-0784 GENERAL ELECTRIC CO . PLEASANTON, CA
- 8P12280276 Requests delay to respond to 821021,1112 & 19 memoranda & orders, due to inaccessability of documents needed for complete response Partial response to 0E 821123 requests provided
 TURK, J. Affiliation Unknown 82/12/20 FRYE, J. H., LINENBERGER, Q., FOREMAN, H. Atomic Safety and Licensing Board Panel 2pp
 16561 230 24X Fiche 50-070, 82/12/20, 8212280276
- B212300022 Grants J Turk petition for extension until 830105 to respond to ASLB 821117 memorandum & order Other petitioners & intervenors granted same extension NRC response due by 83017
 FRYE.J H Atomic Safety and Licensing Board Panel 82/12/27
 TURK.J Affiliation Unknown ip 16598 310 24X
 Fiche 50-070,82/12/27,9212300022
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JCT . RI
- B212290351 Forwards IE Safeguards Insp Rept 70-0820/82-11 on B21101-05 No noncompliance noted MARTINI T T Division of Engineering & Technical Programs 82/12/15 AMY. O 0 United Nuclear Corp 2pp 16586 240
- --8212270352 IE Safeguards Insp Rept 70-0820/82-11 on 821101-05 No noncompliance noted Major areas inspected holdup measurements for decommissioning ZIBULEKY-H, WQLINER.E., DELLA RATTA.A Region 1, Office of Director. 82/12/13 2pp 16586 242
- 82:2270252 Ack receipt of 820225 ltr informing NRC of steps taken to correct violations noted in IE Imap Rapt 70-0820/81-10 Severity Level V re discharges into storage tank appropriate & will remain as cited MARTIN.T T Division of Engineering & Technical Programs 82/12/21 AMY-0 0 United Nuclear Corp 2pp. 16530 319
- --8212270256 Responds to NRC 820208 ltr re violations noted in IE Insp Rept 70-0820/81-10 Corrective actions liquid sample from storage tank analyzed for nitrate & fluoride ions Severity Level V categorization disputed GRE00.R.J United Nuclear Corp 82/02/25 MARTIN.T T Division of Engineering & Technical Programs 3pp 14530 321

- DOCKET 70-0824 BABCDCK & WILCOX CO , LYNCHBURG, VA
- 8212090252 Forwards IE Insp Rept 70-0824/82-09 on 821018-19 No
 - noncompliance noted
 GIBSON A F Division of Engineering & Technical Programs 82/11/02
 ENGELOER, T C Babcock & Wilcor Co 2pp 14361 336
- --8212070265 IE Insp Rept 70-0824/82-09 on 821018-19. No noncompliance noted Hajor areas inspected info notices, safety committees, procedure control.maint, fecility changes & mods, operations & criticality safety TROUP.C L. MCALPINE.E J Davision of Engineering & Technical Programs 82/11/01 4pp 16361 338
- 8212090292 Forwards IE Insp Rept 70-0824/82-08 on 821020 No noncompliance noted OIBSON.AF Division of Engineering & Technical Programs 82/11/16 ENGELDER,T C Babcock & Wilcox Co 2pp 16365 177
- --8212090294 IE Insp Rept 70-0824/82-08 on 821020 No noncompliance noted Major areas inspected emergency preparedness MARBION,R R., JENKINS, G R Region 2, Defice of Director 82/11/15 Spp 14365.179
- 8212090477 Ack receipt of 821104 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0824/82-07 OIBSON, A F Division of Engineering & Technical Programs 82/11/22 ENGELDER, F C Babcock & Wilcox Co Ip 16365 309
- --8212070489 Responds to NRC 821019 ltr re violation noted in IE Insp Rept 70-0824/82-07 Corrective actions, segmented gamma scan operator instructed in need for data recording & retention. Procedure for waste scanning will be revised by 821215 ENGELDERIT C. Babcock & Wilcox Co 82/11/04 01880N.A F. Division of Engineering & Fechnical Programs 2pp 16365.310
- --B212070497 Forwards IE Insp Rept 70-0824/82-07 on B2092B-30 & notice of violation Rept & notice of violation withheld (ref 10CFR2 770)
 G1850N.A F Division of Engineering & Technical Programs
 82/10/19 ENGELDER, T G Babcock & Wilcox Co 2pp. 16365-312
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT
- 8212160004 Requests extension from 821030 to 821315 to submit math balance summary for period ending 820930 Request necessary due to heavy production schedule & generation of accompanying documentation BOWIE: TB Combustion Engineering, Inc 82/10/26 JACKSON, R NRC No Detailed Affiliation Given. 2pp 16447:283
- B212030029 Forwards IE Insp Rept 70-1100/82-09 on 820929-1001 No noncompliance noted.

 HARTIN, T T Division of Engineering & Technical Programs 82/11/19

 LIGHTENBERGER Combustion Engineering, Inc. 2pp 14305 054
- --B212030032 IE Insp Rept 70-1100/82-09 on B20929-1001 No noncompliance noted Major areas inspected radiation protection program termination repts, source lenk tests, bioassay, dosimetry, surveys & training CLEMONS, P. ORSENMAN, E. Region 1. Office of Director. 82/11/12 5pp 16305:036
- 8212290360 Forwards IE Safeguards Insp Rept 70-1100/82-10 on 821018-22 No noncompilance noted MARTIM T T. Division of Engineering & Technical Programs. 82/12/14 LICHTENBERGER Combustion Engineering, Inc. 2pp 16586:256
- ---B212270363 IE Safeguards Insp Rapt 70-1100/82-10 on 821018-22 No noncompliance noted Major areas inspected measurement & statistical controls, internal control & inventory verification ITBULSKY, H., GODY, A. T. Region 1. Office of Director 82/12/09 3pp 16586-258.
- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON, NC
- B2:2090264 Forward: IE Safeguards Insp Rept 70-1113/82-22 on 82:018-22 No noncompliance noted OIBSON A. Division of Engineering & Technical Programs B2/11/04 LONG, J.A. General Electric Co. 2pp. 16361 282

- --8212090270 IE Safeguards Insp Rept 70-1113/82-22 on 821010-22 No noncompliance noted Major areas inspected statistical controls associated winuclear math accountability measurements Details withheld (ref 10CFR2 790)
 JCKES.D H. MCALPINE.E J Division of Engineering & Technical Programs 82/11/04 1p 16361 284
- B212160423 Forwards revisions to fundamental nuclear mati control plan Encls withheld (ref 100FR2 790) VAUGHAN.C M General Electric Co B2/11/18 EVANS.L J Fue) Facility Bafeguards Licensing Branch ip 14447 190
- 8212160378 Comments on review of draft license conditions regroundwater monitoring outlined in 821008 ltr Conditions acceptable w/listed deletions
 HAKILD.C North Carolina, State of 82/11/24 CROW, W T Uranium
 Fuel Licensing Branch 1p 16447 199
- 8212230085 Forwards revised page from 820331 amend application for License SNM-1097 to increase plant capacity Revision reflects use of new equipment which will provide timely operational support VAUCHAN.C M General Electric Co 82/12/07 CROW.H T Uranium Fuel Licensing Branch 1p 16544 265
- ---0212230103 Revised page for \$20331 amend application to License 8NM-1097, reflecting new equipment to provide timely operational support VAVOHAN, C M General Electric Co 02/12/07 CROW, W T Uranium Fuel Licensing Branch Ip 16544 266
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8212150262 Forwards final survey results for weld pit in Pu fuels development lab Pit meets unquelified release criteria & should be released for unrestricted use Pit will be backfilled & opening sealed MARDI.A J Hestinghouse Electric Corp 82/11/09 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch Spp 18446 284
- B212220124 Forwards Revision 14 to application for amend to License SNM-1120 revising Page 2 5-3 re meteorological tower maint requirements NAROLA J Westinghouse Electric Corp B2/11/09 ROUSE.L C Division of Fuel Cycle & Material Safety 2pp 16525 356
- ---8212220134 Revision 14 to application for amend to License SNM-1120. revising Page 2 5-3 re metaporological tower maint requirements 4 Westinghouse Electric Corp 82/11/30 4pp 16525 358
- 8212170014 Forwards Amend 8 to License SNM-1120, revised license puggs & SER Amend revises requirements for maintaining meteorological tower RQUSELC Advanced Fuel & Spent Fuel Licensing Branch 82/12/07 NARDI.A J Westinghouse Electric Corp ip 16480 327
- --8212170017 Amend 8 to Westinghouse License SNM-1120, revising requirements for maintaining meteorological tower ROUSE, L C Division of Fuel Cycle & Material Bafety 82/12/07 3pp 16480 328
- --8212170020 BER supporting proposed Amend 8 to License SNH-1120, revising requirements for maintaining meteorological tower KRATZKE, R T Advanced fuel & Spent Fuel Licensing Branch 82/12/07 2pp 16480 331
- 8212230330 Forwards IE Insp Rept 70-1143/82-05 on 821018-22 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 82/12/08 JACO81.W M Westinghouse Electric Corp 2pp 16505 138
- --8212230333 Notice of violation from insp on 821018-22

 * Division of Engineering & Technical Programs 82/12/08 | Ip
- --B212230335 IE Insp Rept 70-1143/B2-05 on 821018-22 Noncompliance noted failure to maintain records of training for two individuals from Jan 1978-821020 ROTH. J., GDDY, A.T. Division of Engineering & Technical Programs 82/11/15 16pp 16505 141
- 8212230136 Advises that weld pit in Pu fuels development lab meets unqualified release criteria Westinghouse may proceed to backfill pit & seal opening ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/13 NARDI.A J Hestinghouse Electric Corp 1p 16544 259

- --8212330141 Bafety evaluation supporting release of weld pit in Pu fuels development lab for unrestricted use KRATZKE,R T , ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 82/12/13 2pp 16544 260
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B21209042B Forwards IE Safeguards Insp Rept 70~1151/B2-21 on 82102B-1102 No noncompliance noted GIBSON.A F Division of Engineering & Technical Programs B2/11/17 D'AHORE, M Westinghouse Electric Corp 2pp 16363 347
- --B212090445 IE Safeguards Insp Rept 70-1151/82-21 on 821028-1102 No moncompliance noted Major areas inspected physical inventory observation Details withheld (ref 10CFR2 790) TODD, G A . LANKFORD, J B , MCALPINE, E J Division of Engineering & Technical Programs 82/11/17 ip 16363 349
- 8212070547 Forwards IE Insp Rept 70-1151/82-20 on 821101-05 No noncompliance noted GIBSON, A F Division of Engineering & Technical Programs 82/11/17 D'AMORE, M Westinghouse Electric Corp 2pp 16366-325
- --8212090555 IE Insp Rept 70-1151/B2-20 on 821101-05 No noncompliance noted Major areas inspected onsite emergency preparedness & offsite state & local support for licensee emergency organization HUFFMAN, 0 N , JENKINS, G R Region 2, Office of Director B2/11/16 4pp 16366 327
- 9212020209 Trip rept of 821103-04 visit to Columbia facility to discuss pending amend application & to observe facilities & equipment to be used in bulk handling BIDINGER, G H Urenium Fuel Licensing Branch 82/11/19 CROW, W T Uranium Fuel Licensing Branch 92/11/19
- GP12130340 Forwards add1 info re 820326 application to amend License SMM-1107.consisting of Revision 13a.per NRC 821102 request NARDI.A J Westinghouse Electric Corp 82/11/19 PAGE.R 0 Uranium Fuel Licensing Branch 18pp 16446 246
- 64:2150238 Forwards "Columbia Plant ALARA Rept. Jan-June, 1982," in support of application for renewal of License BNM-1107 RETILER.E K. Hestinghouse Electric Corp. 82/11/22 BIDINGER, G. H. Uranium Fuel Licensing Branch 1p 16446 302
- --B212150244 "Columbia Plant ALARA Rept Jan-June, 1982 " RETTLER,E K , SANDERS, C F , GOODWIN,W L Westinghouse Electric Corp 82/08/20 50pp 16446 303
- 8:12090269 Forwards IE Safeguards Insp Rept 70-1151/82-23 on 821115-18
 No honcompliance noted
 CIBSON.A F Division of Engineering & Technical Programs 82/12/01
 D'ANGRE,M Hestinghouse Electric Corp 2pp 16365-286
- --B212070278 IE Safeguards Insp Rept 70-i151/82-23 on 821115-i8
 No noncompliance noted Major areas inspected measurements,
 measurement control program & followup of previously
 identified items Details withheld (ref 10CFR73 21)
 BATES, J W. MCALPINE, E. J. Division of Engineering & Technical
 Programs 82/12/01 1p 16365 288
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP . OKLAHDMA CITY, OK
- 8212280013 Forwards check covering fee for administrative changes requested in 821015 ltr re license renewal SHELLEY, W J Kerr-McGee Corp 82/10/18 WEISS, D License Fee Management Branch 2pp 16593 110
- ---8212280018 Notifies that GJ Sinke will be assuming OM France function as nuclear criticality inspector Depressed U industry led to discharge of GM France Changes will be reflected in updated standby license
 SHELLEY.W J Kerr-McGee Corp 82/10/13 ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 2pp 16593 112
- BOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA
- B212090333 Forwards IE Insp Rept 70-1201/82-18 on B21020-22 No nomcompliance noted GIBBON A F Division of Engineering & Technical Programs 82/11/02 ALTO, R.A Babtock & Wilcox Co 2pp. 16364 001.

- --BR12090340 IE Insp Rept 70-1201/82-18 on 821020-22 No noncompliance noted Major areas inspected organization, procedures, safety committees training, maint, facility changes & mods, criticality safety, operations & info notices ROUP.0 L , MCALPINE,E J Division of Engineering & Technical Programs 82/11/01 App 16364 003
- 8212070263 Forwards IE Insp Rept 70-1201/82-16 on 821021-22 No noncompliance noted GISBON, AF Division of Engineering & Technical Programs 82/11/16 ALTO,R A Babcock & Wilcox Co 2pp 16362 337
- --8212090274 IE Insp Rept 70-1201/82-16 on 821021-22 No noncompliance noted Major areas inspected emergency preparedness MARSTON, R R, JENKING, Q R Division of Engineering & Technical Programs 82/11/15 4pp 16362 339
- GR12230025 Forwards revised pages to 810227 license renewal application per agreement reached at 821129 meeting FORD. J T Babcock & Wilcox Co 82/12/06 PAGE.R G Uranium Fuel Licensing Branch 2pp 16544 269
- --8212230031 Revised Pages 6.8,10-13 & 78 to 810227 renewal application for License 8MM-1168 = Babroot & Wilcox Co 82/12/06 7pp 16544 271
- DOCKET 70-1257 EXXDN NUCLEAR CO . INC . RICHLAND, WA
- 8212180276 Revision 7 to application for renewal of License 8NM-1227, changing "quarterly" to "monthly" on Page 3 48

 * Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 82/11/17 5pp.
- DDCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA
- 8212130148 Notification of 821116 meeting w/GE in Silver Spring. HD to discuss potential changes, tests & experiments re thermal & dosingtry measurements involving Ridihalgh, Eggers & Assoc dry spent fuel cask ROBERTS. J P Advanced Fuel & Spent Fuel Licensing Branch ROBERTS. L C Advanced Fuel & Spent Fuel Licensing Branch Rpp
- DOCKET 70-1334 AVCO EVERETT RESEARCH LABORATORY, INC., EVERETT, MA
- 8212100178 Issues Amend 7 to License SNM-1308 in response to 820913 application Amend incorporates encl guidelines as Condition 14 of license PAGE.R O Uranium Fuel Licensing Branch 82/12/02 SCHLIER.R E Avco Everett Research Laboratory, Inc. ip 14378 358
- --B212100180 Safety evaluation supporting issuance of Amend 7 to License SMM-1308 Amend incorporates encl guidelines as Condition 14 of license GOONO,A L , CROW.H T Uranium Fuel Licensing Branch 82/12/02 2pp 16398 359
- DOCKET 70-1359 IRT CORP. . SAN DIEGO. CA
- 8212090068 Forwards IE Safeguards Insp Rept 70~1359/82-03 on 821021-R2 No noncompilance noted NORDERHAUG,L R Division of Radiological Safety & Safeguards Program 82/12/06 MERTZ,R L IRT Corp 2pp. 16359 090
- --8212070071 IE Safeguards Insp Rept 70-1359/82-03 on 821021-22 No noncompliance moted Major areas inspected implementation of nuclear mat1 control & accounting procedures, facility organization & operation, shipping & receiving & storage HIEDER, A V. NELSON, G. S. . NORDERHAUG, L. R. Division of Radiological Safety & Safeguards Program 82/12/04 4pp 16359 092
- DUCKET 70-1430 MT. BINAI HUSP MEDICAL CENTER, CHICAGO, IL
- B212150040 Forwards IE Safeguards Insp Repts 50-112/82-02 & 70-1430/82-02 on 821025-29 No noncompliance noted MADERN, G L Division of Resident, Reactor Project & Engineering Programs 82/12/09 UPTHEOROUG, W R Oklahoms, Univ of 2pp 16421 322 24X Fiche 50-112.82/12/09,8212150040

--9212150049 IE Safeguards insp Repts 50-112/82-02 & 70-1430/82-02 on 821025-29 No noncompliance noted Major areas inspected nuclear dati control & accountability.including facility organization & operation Details withheld (ref 100FR2 790) CALDWELL, R A. KELLY, J A. Division of Resident. Reactor Project & Engineering Programs 82/11/30 ip 16421-324 24% Fiche 50-112,82/12/09.8212150040

DOCKET 70-1621 DUQUESNE LIGHT CO . PITTSBURGH, PA

8212270173 Forwards Endorsement 60 to NELIA Policy NF-226 & Endorsement 52 to MAELU Policy MF-87
BARNETT, J E Conover & Associates, Inc Insurance 82/12/20
DINIT2-I Antitrust & Economic analysis Branch (Utility Finance)
3pg 16537 004

8212280254 Forwards Endorsements 1,2 & 3 to NELIA & HAELU Certificates N-58 & M-58, respectively BARNETT, J E Conover & Associates, Inc Insurance 82/12/22 DINITZ: I Antitrust & Economic analysis Branch (Utility Finance) 17pp 16061 278

DOCKET 70-2487 ST CLARE'S HOSP , DENVILLE, NJ

9212140303 Notifies of expiration of License SNM-1708, per 920812 telcon Statement explaining method of disposal of math & repts for individuals engaged in activities under expired license requested HARTIN.T I Division of Engineering & Technical Programs 82/11/20 COUREY, K M St Claire's Hosp Denvilla.NJ 2pp 16402 078

DUCKET 70-2792 LOWER BUCKS HOSP , BRISTOL, PA

8212030014 Act receipt of 821027 ltr providing policy/procedure for controlling nuclear pacemakers
KINNEMAN, J Division of Engineering & Technical Programs
82/11/24 THOMAS.C J Lowell General Hosp Lowell, MA 1p
16304 238

--B2(2030020 Forwards policy/procedure for controlling nuclear pacematers THOMAS,C J Lowell General Hosp Lowell, MA 82/10/27 DAVIS, J Region I, Office of Director 4pp 16304 239

DOCKET 70-2872 RS HOLDING. INC . CLEVELAND, OH

8212100245 Discusses IE insp of Licenses SNN-1826.34-[8233-01 & 34-18156-01 on 820621-25 & forwards notice of violation SERNIAMBSKID J Division of Engineering & Technical Programs 82/12/02 KEMPE.R A Reuter-Stokes Inc Zpp 16376 111

---B212100249 Notice of violation from insp on B20621-25 Noncompliance noted film bedges (saued which did not monitor for fast neutrons SRENIAWSKI.D J Division of Engineering & Technical Programs B2/12/02 (p. 16376-113

BOCKET 70-2895 SPECTRO CHEM LABORATORIES, INC , FRANKLIN LAKES, NJ

B212140251 Discusses lE Insp Rept 70-2895/82-01 on 820826 & forwards notice of violation MARTIN,T T Division of Engineering & Technical Programs 82/11/30 VAN DIEN,E I Spectro-Chem Laboratories, Inc. 2pp 16409 324

--8212140248 Natice of violation from insp on 820825 Noncompliance noted failure to check urine for U semiannually & to perform surveys u/survey ester 810407-820712

• Division of Engineering & Technical Programs 82/11/30 1p 16409 326

DOCKET 70-2926 DETROIT EDISON CO , DETROIT, MI

8212130424 Forwards revised application for license to receive possess/
repackage for shipment transfer & store SNM License should
be issued before 830225 to allow receipt of unirradiated
fuel onsite to support 830613 fuel load
IAUEER. H Detroit Edison Co 82/11/09 DAVIS. J Office of Nuclear
Material Safety & Safeguards Director 1p 16413 057

--B212130427 Revised application for license to receive, possess/
repackage for shipment, transfer & store SNM Request license
be issued before B30225 to allow receipt of unirradiated
fuel onsite to support B30413 fuel load
TAUGER.H Detroit Edison Co B2/10/31 24pp 14413 058

DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY

8212170004 Advises of issuance of Amend 1 to License SNM-1873, extending espiration date to 850831 SER encl PAGE.R of Uranium Fuel Licensing Branch 82/12/08 MILLS, L M Tennessee Valley Authority 1p 16478 001

--8212170011 SER supporting Amend 1 to License SNM-1873 extending expiration date to 850831 BIDINGER.0 H. CROW.W T. Uranium Fuel Licensing Branch 82/12/08 ip 16478 002

DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANODDA, TN

8212270026 Advises of issuance of Amend 1 to License SNM-1883, extending expiration date to 860531 SER encl PAGE.R © Uranium Fuel Licensing Branch 82/12/16 Mitt.S.L M Tennessee Valley Authority ip 16551 342

~-8212270029 SER supporting issuance of Amend I to License SNM-1883 CROW W T Uranium Fuel Licensing Branch 82/12/16, 1p 16551 343

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO , PHOENIX, AZ

B212130146 Transmits Amend 3 to physical security plan in support of License SNM-887 Amend withheld (ref 10CFR2 790 % 10CFR7 %)
Ex-core detectors from C-E expected on site by B21201
ANDBONINI.G C Arizona Public Sprvice Co B2/11/12 Office of Nuclear Material Safety & Safeguards, Director 1p 16410 287

DOCKET 70-2958 EDLOW INTERNATIONAL CO , WASHINGTON, DC

8211090494 Requests that Reporting Identification Symbol XX8 be used for all matl stored at St Louis. IL site Symbol would apply to Licenses SMC-1377 & SNM-1903 matl SHAM-A Edlow International Co 82/10/12 PAGE.R 0 Uranium Recovery Licensing Branch 1p 16021 001

DOCKET 70-2957 FLORIDA POWER & LIGHT CO , MIAMI, FL

8212190204 Application for Amend 1 to License SNM-1902 amending License Condition 11 to remove potentially unnecessary constraint in Initial fuel assembly unloading UHR10.RE Florida Fower & Light Co 82/11/17 PAGE.R Q Uranium Fuel Licensing Branch 1p 16447 068

BP121302B5 Advises of issuance of Amend 1 to License BNM-1902.

modifying Condition II re control of fuel assemblies

PAGE:R O Uranium Fuel Licensing Branch 82/12/03 UHRIO.R E
Florida Power & Light Co ip 16418 241

--8212130287 Safety evaluation supporting Amend 1 to License SNM-1902 SERINI.B L . CROW.W T Uranium Fuel Licensing Branch 62/12/03 2pp 16418 242

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO . WICHITA, KS

82:2100187 Forwards request for add1 info to complete initial safety review of application for receipt & storage of fresh fuel assemblies, fission chambers & fission counter SERIMI, B L Uranium Fuel Licensing Branch 82/12/02 KOESTER, 9 t. Kansas Gas & Electric Co Spp 16397 023

DOCKET 70-2944 CONSUMERS POWER CO . JACKSON, MI

82:2080007 Forwards request for add1 info re review of 820022 application to receive inspect, possess, store & transfer fresh fuel assemblies Killinogn, H M Uranium Fuel Licensing Branch 82/11/26 COOK, J W Cansumers Power Co 3pp 16367 182

CP12230112 Forwards revised security plan for new irradiated fuel assemblies Info withheld (ref 10CFR73 21) COOK.J W Consumers Power Co 82/11/27 DAVIS,J G Office of Nuclear Material Safety & Safeguards, Director 3pp 14544 262

DOCKET 70-2945 CONSUMERS POWER CO . JACKBON, MI

B212080007 Forwards request for addl info re review of 820622 application to receive, inspect, possess, store & transfer fresh fuel assemblies KILLINOER, H Uranium Fuel Licensing Branch B2/11/26 COOK, J W Consumers Power Co 3pp 16367 182

8712830112 Forwards revised security plan for new irradiated fuel assemblies Info withheld (ref 10CFR73 21)
CODK, J W Consumers Power Co 62/11/27 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 3pp 16544 262

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO . CLEVELAND, OR

8212060493 Requests ack of receipt of matl license application & supple dtd 820830 & 0930, respectively KILLINGER, H H Uranium Fuel Licensing Branch 82/11/30 STEFAND, J Office of Nuclear Reactor Regulation, Director CUTCHIN, J Hearing Branch 4 ip 16348 014

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0170 GENERAL ELECTRIC CO

8212160020 Forwards QA program approval for Radioactive Matl Package 0170, Revision 2 MACDQNALD, C E Transportation Branch 82/11/30 CUNNINGHAM, 0 E General Electric Co 1p 16447 274

--9212160023 GA program approval for Radioactive Matl Package 0170, Revision 2 MACOUNALD.C E Transportation Branch 82/11/30 1p 16447 275

DOCKET 71-0206 PRYOR FOUNDRY, INC.

GP12100057 Forwards QA program approval for Radioactive Matl Package 0206.Revision 1 MACDONALD.C E Transportation Branch \$2/11/30 GILBREATH.J H Pryor Foundry Inc 1p 16398 335

--6212100062 QA program approval for Radioactive Matl Package 0206, Revision 1 MACDDNALD,C E Transportation Granch 82/10/20 1p 16398 336

DOCKET 71-0370 AMERSHAM CORP

9212100066 Forwards GA program approval for Radioactive Matl Package 0370.Revision O MACDOMALD.C E Transportation Branch 82/11/30 BAOBY.L A Amersham Corp ip 16399 039

--9212100069 GA program approval for Radioactive Hatl Package 0370, Revision O MACDUNALD.C E Transportation Branch 82/11/30 ip 16399 040

DOCKET 71-0394 NUCLEAR SOURCES & SERVICES, INC

B212130222 Forwards portions of revised GC manual for review GALLAGHER.R D. Nuclear Sources & Services, Inc. B2/11/22 MACDONALD.C.E Transportation Branch 29pp 16414 059

DOCKET 71-0454 ATOMIC ENERGY OF CANADA, LTD

B212160134 Forwards Revision 1 to QA program for design, testing & fabrication of radioactive meth transport packages per B20712 request Current designation is AECL-CP Document U.O1-AA O2. Revision 1
RIDOUT.EF Canada 82/11/12 MACDONALD, CE Transportation Branch 4pp 16449 023

--9212160148 Revision 1 to QA program for design, testing & fabrication of radioactive math transport packages RIDDUT,E.F. BROWN, M. Canada 82/11/10 26pp 16449 027

8212130068 Forwards GA program approval for Radioactive Matl Package 0454 Revision 1 MACDDNALD, C E Transportation Branch 82/11/30 RIDOUT, E F Atomic Energy of Canada, Ltd 1p 16417 253

--B212130074 GA program approval for Radioactive Matl Package 0454, Revision 1 MACDONALD, C E Transportation Branch 82/11/30 1p 16417 254

DOCKET 71-0474 NAVY, DEPT OF

8212230156 Requests GA program approval for Certificate of Compliance 0474 be modified to allow shipment of radioactive matl & exchange old cesium source radiac calibrator for new type PERRY. J M Navy, Dept of 62/12/09 GDRDON, L NRC ~ No Detailed Affiliation Given 1p 16544 039

DOCKET 71-0483 FAIRCHILD WESTON SYSTEMS, INC.

B212100037 Responds to B20929 request for approve) of QA program Schlumberger, Inc must approve program MACDDNALD,C E Transportation Dranch B2/12/03 PRATT,T E Fairchild Heston Systems, Inc. 1p 16399 344

DOCKET 71-0484 NEBRASKA PUBLIC POWER DISTRICT

B212160433 Requests concurrence that GA program approval in 791207 ltmeets 10CFR71 51(d) requirements to issue general license to deliver licensed metl to carrier for transport.
PILANT.J M Nebraska Public Power District 82/11/30
MACDUNALD.C E Transportation Branch 1p 16447 187

B212230036 Forwards QA program approval for Radioactive Matl Package 0484, Revision 0 MACDONALD,C E Transportation Branch B2/12/10 PILANT,J M Nebraska Public Power District ip 16545-348

--B212230039 GA program approval for Radioactive Matl Packags 0484, Revision O MACDONALD,C E Transportation Branch B2/12/10 ip 14545-349

DOCKET 71-0494 INTEC INSPECTION. INC.

B212160026 Forwards QA program approval for Radioactive Matl Package O486.Revision O MACDONALD,C E Transportation Branch 82/11/18 BAKER,T Intec Inspection, Inc. ip 16447-272

--8212160028 GA program approval for Radioactive Matl Package 0486, Revision O MACDONALD, C E Transportation Branch 82/11/18 1p 16447 273

DOCKET 71-0487 ARMY, DEPT OF

B212220531 Forwards QA program approval for Radioactive Matl Package O487, Revision O MACDDNALD, C E Transportation Branch 82/12/09 TARAS, J N Army, Dept of, White Sands Missile Range. 1p 14522 350

--8212220538 GA program approval for Radioactive Matl Package 0487. Revision O MACDONALD.C E Transportation Branch 82/12/09 ip 16822 35i

DOCKET 71-0488 RAMSEY CONSTRUCTION & FABRICATING CO . INC

8212210501 Forwards QA program for industrial radiography BTALLINS, J E Ramey Engineering Company 82/11/02 MACDONALD.C E NRC - No Detailed Affiliation Qiyan 1p 15002 356

--8212210504 9A program for industrial radiography
* Ramsey Engineering Company. 82/11/03. 3pp 14502,357

821222051B Forwards QA program approval for Radioactive Matl Package O48B Revision O MACDDNALD, C E Ramsey Construction & Fabrication Co , Inc 1p. 16523 025

--B212220526 GA program approval for Radicactive Hatl Package 0488. Revision O MACDONALD: E Transportation Branch 82/12/09 1p 16523:026 .

DOCKET 71-0469 SACRAMENTO MUNICIPAL UTILITY DISTRICT

- B212160009 Ack receipt of B21019 ltr of confirmation of registration for Cask CNS 14-195-H requesting info re CA program Since Rencho Seco plant CL granted BA program already approved HILLER,R Secramento Municipal Utility District 82/11/18 MACDONALD,C Transportation Branch ip 16447 282
- BRI2160177 Forwards QA program approval for Radioactive Matl Package O489, Revision O MACDDNALD.C E Transportation Branch 82/12/03 MILLER,R Sacramento Municipal Utility District 1p 16447 204
- --B212160185 GA program approval for fladicactive Matl Package 0489. Revision O MACDOMALD, C E Transportation Branch 82/12/03 ip 16447-205

DOCKET 71-0490 INSPECTION SERVICES CORP

- 621227001B Forwards GA program for shipping radioisotopes BROTTON,G C Inspection Services Corp 82/12/07 MACDONALD.C E Transportation Branch 1p 16951 043
- --B212270027 GA program for shipping radioisotopes.

 BROTTON.0 C Inspection Services Corp. B2/12/07 3pp
 1.4551 044
- DOCKET 71-4909 MODEL GE 21PF-1, GENERAL ELECTRIC CO
- 8212140513 Forwards Revision 1 to Certificate of Compliance 4909 for Model 05-219F-1 MACDONALD.C E Transportation Branch 82/11/19 VAUGHAN.C M Company Flactors Co. 10 16431 323
- --8212140517 Certificate of Compliance 4909.Revision 1.for Model GE-21PF-1 Approval record entl MACDONALD.C E Transportation Branch 82/11/19 3pp 16431 324
- 8212130175 Requests registration of DDE.Union Carbide Corp & of Goodyear Atomic Gorp as users of Model DR-5 HEISKELM H Energy, Dept of 82/11/30 MACDONALD, C E Transportation Branch 2pp 16410 338
- 82:2160727 Notification of registration as user of Model GE-21PF-1 in response to B21130 request MACDONALD.C E Transportation Branch B2/12/09 FORD.C L Union Carbide Corp ip 16466 022
- 8212160733 Notification of registration as user of Model GE 21PF-1 in response to 821130 request MACDCMALD.C E Transportation Branch 82/12/09 TAYLOR, J. C Union Carbide Corp ip 16466 007
- 8212160738 Notification of registration as user of Model QE 21PF-1 in response to 821130 request MACDDNALD, C E Transportation Branch 82/12/09, BLALOCK, L Energy, Dept of 1p 16466-006
- B212220041 Notification of registration as user of Model GE 21PF-1 in response to B21130 request MACDONALD.C E Transportation Branch 82/12/09 SIMPSON.W R Goodyear Atomic Corp ip 16527 004

DOCKET 71-5084 MODEL UNC-2400, UNITED NUCLEAR CORP

- 8212160425 Requests registration as user of Model UNC-2600 KELLY, J. W. Babcock & Wilcox Co. 82/11/15 MACDONALD, C. E. Transportation Branch 1p 16447 189
- 82/2170001 Notification of registration as user of Model UNC-2600 in response to 82/115 request MACDONALD, C E Transportation Branch 82/12/07. KELLY, J W Babcock & Wilcox Co ip 16502, 238

DOCKET 71-5461 MODEL ORNE TRU, ENERGY, DEPT OF

B212160755 Notification of registration as user of Models QRNL TRU & DRNL TRU & CALIF in response to 821015 request MACDONALD.C E Transportation Branch 82/12/09 GADDIS.C K. Energy, Dept of 1p 16465-355

- DOCKET 71-5469 MODEL HNPF SPENT FUEL SHIPPING CASK, ENERGY, DEPT OF
- 8212220036 Forwards request for add1 info to complete review of Model HNPF spent fuel shipping casks per 780802 ltr Response within 30 days of receipt of ltr requested MACDONALD.C E Transportation Branch 82/12/09 PRICHARD.R P Energy, Dept of 3pp 14529 079
- DOCKET 71-5740 MODEL DRNL TRU CALIF , ENERGY, DEPT OF
- 8212160755 Notification of registration as user of Models DRNL TRU & GRNL TRU & CALIF in response to 821015 request MACDONALD.C E Transportation Branch 82/12/09 GADDIS.C K Energy, Dept of 1p 16465-355
- DOCKET 71-5796 MODEL 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC
- 8212160043 Application for revision of Certificate of Compliance 5/96, modifying Model 181375 overpack shipping container bolt lug position & head tiedown sys Revised pages & drawings encl IRWIN-H R Advanced Medical Bystems, Inc 82/11/01 MACOUNALD.C L Transportation Branch 26pp 16447 285
- --8212160050 Requests payment of minor amend fee for 821101 application for revision of Certificate of Compliance 5796 JACKSON.O License Fee Management Branch 82/11/10 IRWIN.H R Advanced Medical Systems. Inc. ip 16447 311
- DOCKET 71-5814 MODEL NRBK-41, -42 & -43, ENERGY, DEPT OF
- B212160086 Requests registration as user of NRBX-41 shipping container OLSEN, A.F. Babcock & Wilcox Co. 82/11/17 Transportation Branch ip 16447 251
- 8212230132 Advises that amend to Certificate of Compliance 5814 must be requested to include general license provision MACDUMAD,C E Transportation Branch 82/12/15 OLSEN.A F Babcock & Wilcox Co ip 16544 344
- DOCKET 71-9907 MODEL ORNL IN PILE CAPSULE, ENERGY, DEPT OF
- B212140509 Forwards request for add1 info re 780731 application for approval of Model ORNL in-pile capsule MACDONALD.C E Transportation Branch 82/12/03 PRICHARD.R P Energy, Dept of 4pp 16431 327
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CO
- 8212150274 Requests registration as user of Model GE 1900 for transport of radioactive matl while involved in beneficial uses of nuclear byproducts program PIERCE, J D Sandia Laboratories 82/11/05 MACDUNALD, C E Transportation Branch 1p 16446 275
- BR12160743 Notification of registration as user of Model GE-1500 in response to 821105 request MACDOMALD.C E Transportation Branch 82/12/09 PIERCE.J D Sandia Laboratories ip 16466 005
- DOCKEY 71-5942 MODEL: GE-700, GENERAL ELECTRIC CO
- 8212130010 Notification of registration as user of Models GE-200 & GE-700 in response to 821026 request MACDCNALD.C E Transportation Branch 82/11/18 ANSELMO.A. A EQUO. Inc. 1p 16417 069
- DOCKET 71~5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY
- 8212210527 Application for Revision 9 to Certificate of Compliance 5957, revising SAR pages to basket integrity BURIAN.R J Battelle Memorial Institute, Pacific Northwest Laboratory 82/11/23 MACDUNALD, C E Transportation Branch. 3pp 14502 313
- B212130212 Forwards replacement Page 1 6 & corrected replacement page schedule to B21123 application for Amend D to Certificate of Compilance 5957
 BURIANR J Battelle Memorial Institute, Columbus Laboratories.
 82/11/24 MACDUNALD, C & Transportation Branch 1p 16447 059

- --8212150218 Replatement Page 1 & & corrected replacement page schedule to 821123 application for Amend D to Certificate of Compliance 5957

 # Battelle Hemorial Institute, Columbus Laboratories 82/11/24
 3pp 16447 060
- B212280010 Notifies of future use of Model BMI-1 FIEDLER,P B General Public Utilities - OPU Service Corp B2/12/01 Division of Fuel Cycle & Material Safety 1p 16593 109
- DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO
- 8212130010 Natification of registration as user of Models GE-200 & GE-700 in response to 821026 request MACDONALD, C E Transportation Branch 82/11/18 ANSELMO, A A EG&G, Inc. 19 16417 069
- DOCKET 71-4003 MODEL M-130, ENERGY, DEPT OF
- Q21216003B Forwards Revision 2 to Certificate of Compliance 6003 for Model N-130 MACDONALD, C E Transportation Branch 82/11/19 ENGEL, WP Energy, Dept of 1p 16447 259
- ~-8212160041 Certificate of Compliance 6003, Revisson 2, for Model M-130 Approval record and MACDUNALD, C E Transportation Branch 82/11/19 7pp 16447 260
- DOCKET 71-6144 MODEL 8-2, U S ECOLOGY
- 0212270479 Requests registration as user of Models B-2 & GE-1600 AYRES, J AMC, Inc 82/12/07 MACDONALD, C E Transportation Branch 1p 16591 055
- DOCKET 71-6347 MODEL FSV-3, GENERAL ATOMIC CO
- BP12130038 Notification of registration as user of Model FBV-3 in response to 821105 request MACDDNALD.C E Transportation Branch 82/11/22 COUNEY.M J Philadelphia Electric Co 1p 16417 050
- DOCKET 71-4495 MODEL PADUCAH DEMONSTRATION CASK, ENERGY
- BP1R130122 Forwards safety summary rept for Certificate of Compliance 4495 Model Paducah demonstration cask & certificate of compliance PRICHARD, R P Energy, Dept of 82/11/17 MACDONALD, C E Transportation Branch 1p 14418
- --8212130129 Certificate of Compliance 6495, Revision O. for Model Paducoh demonstration cask DUVAL, P.A. Energy, Dept of 82/04/05 8pp 16418 022
- --B212130138 "Safety Summary Rept.Paducah Demonstration Cask (Packaging of Radicactive & Fissile Matls)"

 * Rockwell International Corp DPSU 71-124-4 82/02/28 147pp 16416 006
- BOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 97:12150222 Requests registration as user of Model HN-200 ORAVES.R H Connecticut Yankee Atomic Power Co 92/11/12 MACDONALD.C E Transportation Branch 1p 16446 359
- B212160750 Notification of registration as user of Models HN-200 & HN-100 Series 3 in response to B21112 request MACDUNALD.C E Transportation Brench B2/12/07 GRAVES.R H Connecticut Yankee Atomic Power Co ip 14465 356
- DOCKET 71-6501 MODEL CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC
- B212130136 Notification of registration as user of Model CNB B-120 in response to 821022 request MACDONALD, C E Transportation Branch 82/11/18 WILLIAMSON, E D Knolls Atomic Power Laboratory ip 16417 147

- DOCKET 71-6717 MODEL 6717-B. CAMMA INDUSTRIES
- 8212130078 Notification of registration as user of Models 67178,20, 20A,50,50A,100,100A,200,200A & C-8,in response to 821007 request MACDONALD.C E Transportation Branch 82/11/18 BRDTTON,0 C Inspection Services Corp 1p 16417 255
- 8212100420 Notification of registration as user of Model 6717-8 in response to 820923 request MACDONALD.C E Transportation Branch 82/11/23 CLARK.R L Clark Inspection Service. Inc 1p 16389 060
- 8212160169 Notification of registration as user of Model 6717-8 in response to 820927 request MACDUNALD, G.E. Transportation Branch 82/11/30 BAKER, T International Technical Service 1p 16447 209
- 8712230001 Requests registration as user of Model 6717-B OORNES. J W Dayton Power & Light Co 82/12/10 MACDONALD, C E Transportation Branch ip 16544 348
- DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO
- 8212150216 Suppl to application to amend Certificate of Compliance 9001. Revision 14. reinstating use of Model QE IF-300 for BWR fuel shipment in response to 821029 request for addlined DAMSDN.DM General Electric Uranium Management Corp 82/11/32 MACDONALD.C E Transportation Branch 35pp 16447 026
- B212140472 Requets registration as user of Hodel IF-300 PlLANT, J M. Nebraska Public Power District B2/11/30 MACDONALD, C E Transportation Branch 1p 16431 318
- B212230018 Notification of registration as user of Model IF-300 in response to 821120 request MACDDNALD.C E Transportation Branch 82/12/10 PILANT,J M Nebraska Public Power District Ip 16544 362
- DOCKET 71-9006 MODEL 500-8U. AUTOMATION INDUSTRIES, INC
- BP12160012 Forwards Revision 3 to Certificate of Compliance 9006 for Model 500-8U MACDONALD,C E Fransportation Branch 82/11/23 SANTORO,M P SRL, Autometrix 3pp 16447 276
- --B212160016 Certificate of Compliance 9006, Revision 3. for Model 500-BU Approval record encl MACDUNALD. C Transportation Branch 82/11/23 3pp 16447 277
- 8212160361 Requests registration as user of Models 650 & 500-8U CASH, A Yuba Heat Transfer Corp 82/12/03 Transportation Branch 1p 16447 200
- DOCKET 71-9010 MODEL NLT-1/2, NL INDUSTRIES, INC
- B212130001 Notification of registration as user of Model NLI-1/2 in response to B21018 request MACDDNALD, C E Transportation Branch 82/11/18 LENTINE, F 0 Commonwealth Edison Co Ip 16417 071
- DUCKET 71-9015 MODEL TN-8. -BL. NO USERS
- 8212270069 Application for revision of Certificate of Compliance 9015 to delete initial fuel pin pressure at 100 F from Bi0707 Revision 3 as content condition, to allow transport of PWR fuel whigher initial pressures of helium GOLDMANN. K Transpoclear, Inc 82/12/03 MACDONALD, C E Transportation Branch 2pp 16553 129
- --8212270071 Revision 0 to "TN-8 & TN-9 SAR, Becond Addendum for TN-8 & TN-8L Packagings"

 * Transnuclear, Inc E-3508 R00 82/12/03 18pp 18953 131
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- BP12130114 Notification of registration as user of Models 650,660 & 660E in response to 821029 request MACDUNALD.C E Transportation Branch 82/11/18 GILBREATH, J H Pryor Foundry Inc. 1p 16417 151

- B212160361 Requests registration as user of Models 650 & 500-SU CASH A Yuba Heat Transfer Corp B2/12/03 Transportation Branch Ip 16447 200
- DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC
- 8212130116 Notification of registration as user of Models 650,660 & 660E in response to 821029 request MACDUNALD,C E Transportation Branch 82/11/18. GILBREATH.J H Pryor Foundry Inc. ip 16417 151
- DOCKET 71-9044 HODEL GE-1600, GENERAL ELECTRIC CO
- 8212270479 Requests registration as user of Models 8-2 & GE-1600 AYRES, J. AMC, Inc. 82/12/07 MACDONALD, C.E. Transportation Branch ip 1655: 055
- DOCKET 71-9073 HODEL: OH-142, NUCLEAR PACKAGING, INC
- 8212270408 Application for renewal of Certificate of Compliance 9073 for Model OH-142 SIMCKYK, J D. Nuclear Packaging, Inc. 82/10/20 MACDUNALD, C. E. Transportation Branch. 205pp 14572 125
- 8212270485 Requests addl info re 821020 consolidated application for renewal of Certificate of Compliance 9073 for Model CH-142 Info should be submitted within 60 days MACDONALD,G E Transportation Branch 82/12/16 SIMCHUK,J D Nuclear Packaging, Inc. 2pp. 16548 360
- DOCKET 71-9079 MODEL HN-100, SERIEB 2 & 2A, HITTMAN NUCLEAR
- 8212270377 Application for renewal of Certificate of Compliance 9079, incorporating listed changes to SAR Renewal fec encl SIMCHUK, J.D., Nuclear Packaging, Inc. 82/11/29. MACDONALD, C. E. Transportation Branch 2pp 16573
- --8212270382 "Consolidated SAR for NUPAC 140-2 O Casks to 10CFR71 Type A & Low Specific Activity Packaging Requirements " * Nuclear Packaging, Inc 82/11/29 53pp 16573 295
- B21216074B Advises that B21127 application for renewal of Certificate of Compliance 9077 satisfies condition for timely renewal Certificate will not expire until final determination made by NRC MACDONALD, C E Transportation Branch 82/12/09 SIMCHUK, I D Nuclear Packaging, Inc. 3pp 16465 360
- DOCKET 71-9081 MODEL. CNS-1600, CHEM-NUCLEAR SYSTEMS: INC.
- 8212150202 Forwards response to 820917 ltr re Model CN81 1-13C Review & certification requested Revised pages to SAR encl POPPE, L K Chem-Nuclear Systems. Inc 82/11/15 MACDONALD. C E Transportation Branch 7pp 16447 047
- --8212150206 "SAR for Model CNS 1-13C Package to 10CFR71 Type R Packaging Requirements," Revision 1,Vol 1 * Chem-Nuclear Bystems, Inc 82/11/15 48pp 16447 078
- 8212100425 Natification of registration as user of Model CNS-1600 in response to 821026 request MACDONALD, C E Transportation Branch 82/11/30 AUSTON, M A Babcock & Wilcox Co 1p 16389.059
- DOCKET 71-9084 HODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV. CORP
- B212140505 Forwards request for add1 info re B20723 application for renewal of Certificate of Compliance 7084 for Model HN-100. Series 1
 MACDONALD,C E Transportation Branch 82/11/29 MALLORY,C W
 Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp
- DOCKET 71-9089 HODEL HN-1008; HITTMAN NUCLEAR & DEVELOP. CORP.
- 8212130004 Notification of registration as user of Models HN-1006 & HN-100 Series 3 in response to 821015 request. MACDONALD, C. E. Transportation Branch 82/11/30 KENYON, B.D. Fennsylvania Power & Light Co. 1p. 16417 070

- DOCKET 71-9094 MODEL CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC
- BP12130141 Notification of registration as user of Model CNB 14-195-H in response to 821013 request MACDONALD.C E Transportation Branch 82/11/18 LUNDVALL.A E Baltimore Oas & Electric Co Ip 16410 357
- DUCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC
- S212230037 Requests registration as user of Model CNS 21-300 SMEDIRA: C Neutron Products. Inc. 82/12/09 MACDONALD, C & Transportation Branch 1p 16544 268
- DOCKET 71-9099 MODEL ATR. EXXON NUCLEAR IDAHO CO
- B212160032 Forwards Revision 2 to Certificate of Compliance 9099 for Model ATR MACDDNALD.C E Transportation Branch 82/11/23 WILLIAMS,C F Energy, Dept of 2pp 16447 267
- --8212160035 Certificate of Compliance 9099, Revision 2, for Model ATR Approval record encl MACDONALD, C. E. Transportation Branch 82/11/23 3pp 16447 269
- DOCKET 71-9111 MODEL CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC
- 8212130107 Notification of registration as user of Model CNS9-80-2 in response to 821024 request MACDONALD.C E Transportation Branch 82/11/18 MATHIS.C J Boston Edison Co ip 16417 256
- DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES
- B212130098 Notification of registration as user of Models 67170.20, 20A.50, 50A.100, 100A.200.200A & C-8, in response to 821007 request MACDDNALD.C & Transportation Branch 82/11/18 BROTTON, G C Inspection Services Corp 1p 16417 255
- DOCKET 71-9127 MODEL 100, 100A, 200, 200A, GAMMA INDUSTRIES
- 8P12130098 Notification of registration as user of Models 67178,20, 20A,50,50A,100,100A,200,200A & C-8, in response to 821007 request MACDONALD.C E Transportation Branch 82/11/18 BROTTON, G C Inspection Services Corp Ip 16417 255
- DOCKET 71-9128 NODEL C-8, GAMMA INDUSTRIES
- B212130098 Notification of registration as user of Models 67178,20, 200,50,500,100,1000,200,2000 & C-8, in response to 821007 request MACDONALD, C E Transportation Branch 82/11/18 BROTTON, G C Inspection Services Corp ip 16417 255
- DOCKET 71-9132 MODEL T-3, ENERGY, DEPT OF
- 8212160437 Forwards revision to SAR for Certificate of Compliance 9132. Model T-3 PRICHARD.R P Energy, Dept of 82/11/30 MACDONALD.C E Transportation Branch 1p 16447:183
- --B212160438 Forwards Page 7-5, revision to Model T-3 SAR # Energy, Dept of B2/11/10 MACDONALD,C E Transportation Branch 3pp 16447 184
- 8212/70005 Forwards Revision 4 to Certificate of Compliance 9132 for Model T-3 MACDDNALD,C E Transportation Branch, 82/12/09 PETERSON,J M Energy, Dept of 2pp 16480 288
- ---82[2170010 Certificate of Compliance 9132.Revision 4, for Model T-3. MACDONALD.C.E. Transportation Branch 82/12/07 5pp 16480 270

DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT DF

- 8212140502 Confirms that no action will be taken on 820818 request for mod to Certificate of Compliance 9150 for Model PAT-2 Meeting to discuss scope & content of revised application will be held on 830113 in Silver Spring.MD MACDONALD,C E Transportation Branch 82/11/30 CAUDLE,R E Energy, Dept of 3pp 16431 333
- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP
- 8.412180270 Requests registration as user of Model HN-100, Series 3 FIEDLER.P B General Public Utilities - GPU Service Corp 82/11/10 Division of Fuel Cycle & Material Safety ip 16446 282
- 8212160407 Forwards revised amend request to Certificate of Compliance 9151 re Model HM-100 Series 3 POFFE, L. K. Chem-Nuclear Systems, Inc. 82/11/16 MACDONALD, C. E. Transportation Branch ip 16447-172
- --8212160418 Revised amend to Certificate of Compliance 9151, "Optional Configuration Request," re Model HN-100 Series 3 * Chem-Nuclear Bystems, Inc. 82/11/14 5pp 14447 173
- G212150282 Advises that response to B21018 request for info will be submitted by B21130 Application revised per B21112 meeting. to continue operation at package weight specified in Certificate of Compliance 7077 MALLORY.C W Hittman Nuclear & Development Corp (subs Hittman Corp) B2/11/17 MACDQNALD,C Transportation Branch 1p 16437 361
- 8212130134 Notification of registration as user of Model HN-100 Series 3 in response to 821103 request MACDONALD, C.E. Transportation Branch 82/11/18 GARRITY, J.H. Haine Yankee Atomic Power Co. 1p. 16417-190
- 8932130142 Notification of registration as user of Model HN-100 Series 3 in response to 882103 request MACDONALD, C.E. Transportation Branch 82/11/18 HUNTER, R. 8 Indiana & Michigan Power Co. 19 16418 006
- GP12130055 Forwards add1 info requested by NRC BR101B ltr re BR0715 application for certification of HN-100 Series 2 casks as HNDC HN-100 Series 3A casks HALLGRY,C W Hittman Corp B2/11/23 MACDUNALD.C Transportation Branch Bpp 16418 030
- --8212130061 "Addendum to BAR for HN-100 Series 3A Radwaste Shipping Cask " a Hittman Corp STD-R-02-004 82/11/23 96pp 16418 038
- BP12270088 Advises that encl 820812 application for amend of Certificate of Compliance 9151 & two oversize drawings marked 'proprietary" should be placed in PDR MACDONALD.C E Transportation Branch 82/11/24 800TT, 5 Document Management Branch 1p 16606 279
- SP12130004 Notification of registration as user of Models HN-100S & HN-100 Series 3 in response to 821015 request MACDDMALD,C & Transportation Branch 82/11/30 KENYON,B D Pennsylvania Power & Light Co 1p 16417 070
- B212170002 Notification of registration as user of Model HN-100 theres 3 in response to 321110 request MACDONALD.CE Transportation Branch 82/12/07 FIEDLER.P B General Public Utilities GPU Service Corp ip 14480 333
- G212160750 Notification of registration as user of Models HN-200 & NN-100 Series 3 in response to 821112 request MACDENALD.C E Transportation Branch 82/12/09 GRAVES.R H Connecticut Yankee Atomic Power Co 1p 16465 356
- CP12160760 Notification of registration as user of Model HN-100 Spries 3 in response to 821012 request MACDONALD.C E Transportation Branch 82/12/09 SELLERS.D Maine Yankee Atomic Power Co 1p 16465 394
- DOCKET 71-9156 MODEL 1R-50, INDUSTRIAL NUCLEAR CO
- B212130089 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request MACDENALD.C E Transportation Branch 82/11/18 RICHARDSON,H D Nuclear System ip 16416 005

- G212130082 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request MACDONALD.C E Transportation Branch B2/11/22 Nuclear Systom ip 16417 252
- DOCKET 71-9157 MODEL IR-100, INDUSTRIAL NUCLEAR CO
- 8212130089 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request
 MACDONALD.C & Transportation Branch 82/11/18 RICHARDSON,H D
 Nuclear System is 16416 009
- 8212130082 Notification of registration as user of Models IR-100 & IR-50 in response to 821012 request MACDONALD,C E Transportation Branch 82/11/22 Nuclear System ip 16417 252
- DOCKET 71-9167 MODEL TYPE B, AMERSHAM CORP
- GP12150230 Advises that responses to NAC 821029 inquiries & revised gages to application will be provided by 821203 BAGBY.L. A Amersham Corp 82/11/23 MACDUNALD.C Transportation Branch. 1p 16446 360
- DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT OF
- BP12280020 Forwards Revision O to Certificate of Compliance 9852 for Model DT-14 MACDONALD,C E Transportation Branch 82/12/20 PRICHARD,R P Energy, Dept of 19 16593 t14
- --B212280021 Certificate of Compliance 9852 Revision O, for Model DT-14 MACDDNALD.C E Transportation Branch 82/12/20 5pp 16593 115

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

- DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.
- 8212130148 Notification of 821116 meeting w/9E in Silver Spring,MD to discuss potential changes, tests & experiments re thermal & dosimetry measurements involving Ridihalgh, Eggers & Assoc dry spent fuel cask
 ROBERTS.J P Advanced Fuel & Spent Fuel Licensing Branch
 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 2pp
 16410 285

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

- 8212220170 Advises that application for dry cask IBFSI ducketed on S21015 Application evaluated for completeness & acceptability Details of cask must be provided to NH Davison before licensing action can be completed ROUSE, C.C. Advanced Fuel & Spent Fuel Licensing Branch 82/12/03 LEASBURG, R.H. Virginta Electric & Power Co. 2pp. 16523 361 24X Fiche 50-280, 82/12/03, 8212220170
- Q212220005 Forwards notice of consideration of matl license for storage of spent fuel transmitted to Ofc of FR for publication ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 82/12/06 LEASBURG, R.H. Virginia Electric & Power Co. 2pp. 16529 144 24X Fiche 50-280, 82/12/06,8212220005
- ~-B212R20007 Notice of consideration of matl license for storage of spent fuel ROUSE, L G Advanced Fuel & Spent Fuel Licensing Branch B2/12/03 4pp 14529 146 24% Fiche 50-280, B2/12/06, B2/2220005
- G212230147 Natice of correction of typographical error in S21209 FR natice re consideration of matls license for storage of spent fuel ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch G2/12/10 2pp 16544 056 24X Fiche 50-280, 82/12/10, 8212230147

LOCER COMMISSION MEETING RECORDS 8212010078 Unofficial transcript of Commission 821119 meeting in Hashington.DC re briefing on hydrogen control program Pp 1-83 Viewgraphs encl * Commissioners 82/11/19 110pp 16290 001 8212010518 Staff requirements memo re Commission 821122 briefing in Mashington DC on draft rept on legislative reform Ref to "Heaning of Adequate Protection to Public Health & Safety" requested CHILK. B J Office of the Secretary of the Commission M821122A 82211/24. TOURTELLOTTE Regulatory Reform Task Force BICKWIT.L Office of the Oeneral Counsel 1p 16270 263 8212010522 Staff requirements memo re Commission 821118 meeting w/DOE, EPA & Natl Academy of Sciences in Washington.DC on proposed technical rule for disposal of high level radwaste in geological repositories.SECY-82-427
CHILK, B J Office of the Sacretary of the Commission M821118D B271724 DIRCKB, W J Office of the Executive Director for Operations 2pp 16270 264 8212010530 Staff requirements memo re Commissioners 821123 affirmation/ discussion & vote in Washington.DC on SECY-82-449 & BECY-82-425 Petition to disqualify NRC atty from Zimmer proceeding denied CHILK, S. J. Office of the Secretary of the Commission ALAB-686 82/11/24 Office of the Secretary of the Commission 2pp 14270 2AB B21202000B Addi response to FOIA request for documents re final rule on environ qualification Forwards App A Documents 12,23,28,35,41,45,53,65,66,70 & 73, Document 65 listed incorrectly Info completely & partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records, B2/11/08 CURRAN, D Harmon & Weiss 7pp 16297 112 --8212020067 Discusses Commission 820601 briefing on proposed final rule re environ qualification of electrical equipment CHILK.8 J. Office of the Secretary of the Commission 82/06/10 Office of the Secretary of the Commission. 1p 16297 291 8212020223 Unofficial transcript of 821117 public meeting in Hashington, DC re NRC actions w/respect to recent USGS position Pp 1-49 Commissioners 82/11/19 53pp 16308 201 B212030277 Unofficial transcript of B21201 briefing in Washington, BC on pressurized thermal shock Pp 1-86 Viewgraphs encl * Commissioners 82/12/01 135pp 16317 076 8212100035 Unofficial transcript of 821207 public meeting in Washington, DC re briefing of Regulatory Reform Task Force Commissioners 82/12/07 104pp 16399 238 B212130407 Unofficial transcript of Commission B21207 meeting in Washington, DC re discussion/possible vote on pressurized thermal shock actions Pp 1~71. Commissioners 82/12/09 72pp 16413 160 8212220003 Staff requirements memo re 821119 briefing on USGS clarification of seismic issues No requests made or requirements placed on staff CHILK.8. J Office of the Secretary of the Commission H821119C 82/11/24 Office of the Secretary of the Commission ip

0212230393 Unofficial transcript of Commission 821214 meeting in Washington.DC re briefing on human factors program plan Pp 1-11 Viewpraphs encl.

* Commissioners. 82/12/14 146pp 16544 113

```
8212270050 Staff requirements memo re 821122 open discussion of draft
    policy & planning guidance for FYB3 Revised document
requested for B21207 meeting
CHILK,S J Office of the Secretary of the Commission M821122B
B2/11/24 ZERBE,J E Office of Policy Evaluations Ip 16551 349
8212270542 Unofficial transcript of Regulatory Reform Task Force 821220
         lefing in Washington, DC re legislative proposals Pp 1-89
Commissioners 82/12/20 92pp 16550 234
8212290274 Unofficial transcript of Commission 821216 briefing by Ad
Noc Committee on Regulatory Reform in Washington, DC Pp 1-
106. Supporting documentation encl
                                                 82/12/16 142pp 16606 107
B212300151 Staff requirements memo re briefing on human factors program plan outlined in SECY-82-468 Add1 meeting should be
       scheduled to complete NRR briefing & allow Ofc of Policy
    Evaluation to comment
CHILK.S J Office of the Secretary of the Commission M821214
82/12/23 DIRCKS,W J Diffice of the Executive Director for
Operations 1p 16624 185
B212300159 Staff requirements memo re status of B21104 staff requirements memo on installation of inadequate core cooling instrumentation say (SECY-B2-407) & B21215 daily staff notes info provided on B21220 CHILK, B J Office of the Secretary of the Commission M821216b B2/12/22 Office of the Secretary of the Commission ip 16624 181
                             ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
 ACRS
 820829027 Comments on draft rept on pressurized thermal shock, ಟ/
special attention to Sections 4,5,7 & 10 Conclusions are
     8208290028 Comments on B&W primary sys & steam generator modeling for accident analysis re ECCS Subcommittee 820928 meeting Verification of vendor models using integral facility recommended Sumiscale facility will supply sufficient data CATTON, I ACRB - Advisory Committee on Reactor Safeguards 82/09/30 BUEHNERT, P NRC - No Detailed Affiliation Given in
8208270027 Comments on "Integrated Human Factors Program Plan" Agrees w/remarks found in project status rept Program elements reasonably titled Needs & reasons must be stated in plan CATION. I California. Univ of. Los Angeles CATION. I ACRS - Advisory Committee on Reactor Safeguards 62/09/20 FISCHER. D ACRS - Advisory Committee on Reactor Safeguards 5pp 16267 322
```

8208270030 Comments on ACRS Subcommittee on Human Factors 82070/ meeting re integrated human factors program plan KLYSERLING.W. ACRS — Advisory Committee on Reactor Safeguards 82/07/13 WARD.D ACRS — Advisory Committee on Reactor Safeguards 3pp. 16267 330

8208290032 Discusses ACRS 820930 meeting re pressurized thermal shock Appropriate framework needed to establish real margins & limits "PHR Downcomer Fluid Temp Transients Due to High Pressure Injection at Stagnated Loop Flow" ent.]
THEOFANDUS: T G Purdue Univ. THEOFANDUS: T G ACRS - Advisory Committee on Reactor Safeguards 82/10/04 [ONE, E ACRS - Advisory Committee on Reactor Safeguards 22/07 174

---8212010428 "PWR Downcomer Fluid Temp Transiants Due to High Pressure Injection at Stagnated Loop Flow" presented at 820914-15 Joint NRC/ANS meeting in Bethesda. MD THEOFANOUS. T. 9. NOURBAKHSH. H. P. Purdue Univ. 82/09/15 Sipp

16267 178

- B212010362 Summary of ACRS Subcommittee on Safety Research Program B20811 meeting in Washington.DC re format & content of proposed long-range research plan Viewgraphs enc!

 * ACRS Advisory Committee on Reactor Safeguards 82/10/02
 ACRS Advisory Committee on Reactor Safeguards 18pp 16271 18 18pp 16271 188
- 8212010365 Summary of ACR5 ECCS Subcommittee 820728 meeting w/B&W owners goup in Washington.DC re modeling of small breat LGCA for B&W plants.reactor coolant pump trip status.results of recent semiscale tests & status of MOD-5 proposal * ACRS Advisory Committee on Reactor Safeguards 82/10/08 ACRS Advisory Committee on Reactor Safeguards 12pp 16271 101
- GP12020041 Summary of ACRS Subcommittee on Regulatory Activities 820908 meeting in Washington, DC re proposed Revision I to Reg Quide 1 145, "Atmospheric Dispersion Models for Potential Accident Consequence Assessments at Nuclear Power Plants"

 ** ACRS Advisory Committee on Reactor Safeguards 82/10/07 ACRS Advisory Committee on Reactor Safeguards 12pp 16310 344
- 8212020046 Summary of AGRS Subcommittee on Transportation of Radioactive Matis 820824 meeting in Washington.DC re adequacy of activities of Transportation Certification Branch of NMSS # AGRS Advisory Committee on Reactor Safeguards 82/10/07 ACRS Advisory Committee on Reactor Safeguards 10pp 16317 063
- 8212020048 Explores & quantifies some fundamentals of problem re ELEVENUTE Exprores & quantifies some fundamentals of problem reflow blockage by steam during natural circulation in PMRs ETHERINGTON, H. ACRS — Advisory Committee on Reactor Safeguards 82/09/07 SHEWMON, P. G. ACRS — Advisory Committee on Reactor Safeguards 13pp 16317-050
- 8212080406 Submits comments from 271st ACRS meeting on 821104-05 re NRC integrated human factors program plan Redrafted plan improved & responsive to concerns expressed in R Fraley 148proves of responsive to constitution on Reactor Safeguards 8MEMMON, P. ACRS - Advisory Committee on Reactor Safeguards 82/11/09 DIRCKS.W J. Office of the Executive Director for Operations 2pp 16297 349
- 0212030280 Discusses options available to ATWS subcommittee for PIZOGORBO Discusses options available to Aimo success.

 establishment of ATWS rule

 establishment of ATWS rule

 establishment of ATWS rule

 EPLER, E P Epler, E P EPLER, E P ACRS - Advisory Committee on

 Reactor Safeguards 82/10/21 ACRS - Advisory Committee on

 Reactor Safeguards 5pp 16317 359
- 8212060153 Summary of 263rd ACRS meeting on 820304-06 in Washington DC * ACRS Advisory Committee on Reactor Safeguards 82/03/06 ACRS Advisory Committee on Reactor Safeguards 434pp 16324 001
- 8212040162 Transcript of ACRS Subcommittee on Metal Components 821202 public meeting in Washington.DC Summary of EPRI work on improved stainless steel pipe & pressure vessel insp & viewgraphs and:

 * ACRS - Advisory Committee on Reactor Safequards 62/12/02
 368pp 16315 027
- B212040323 Discusses primary sys failure mechanism during high pressure

transient CATTON 1 ACRS - Advisory Committee on Reactor Safeguards 82/10/29 SHEMMON,P, KERR,W ACRS - Advisory Committee on Reactor Safeguards ip 16323 350

- 8212060325 Discusses util group ATMS proposal for ATMS subcommittee EPLER:E P Epler, E P EPLER:E P ACRS Advisory Committee on Reactor Safeguards 82/10/23 KERR, N ACRS Advisory Committee on Reactor Safeguards 6pp 16322 347
- B212040399 Comments on ACRS Subcommittee on ATWS 821022 meeting PRA el200037Y Comments on ACMS Subcommittee on AIMS 821022 meeting PRI discussions not convincing Data on scram failure poor Existence of Inoperable state of scram sys may not be evident until tested or need arises for operation DITTO.S J Ditto.S J 82/10/26 BOENNERT.P ACRS - Advisory Committee on Reactor Safeguards 3pp 16322 337
- 8212060514 Comments on ACRS ATMS Subcommittee 821022 meeting PRA & util group value impact analysis make positive contribution toward resolution of ATMS issue LEE.J C ACRS Advisory Committee on Reactor Safeguards 82/10/26 BDEHNERT, P. A. ACRS Advisory Committee on Reactor Safeguards 3pp 16344 013
- 8212070431 Comment, on ACRS ATHS Subcommittee 821022 meeting ATMS issue should be closed within reasonable period of time at least expense possible MVELLER.C J Argonne National Laboratory MVELLER.C J MUELLER,C J Argonne National Laboratory MUELLER,C J ACRS -Advisory Committee on Reactor Safeguards 82/10/25 KERR,W , BOEHNERT,P ACRS - Advisory Committee on Reactor Safeguards 4pp LA355: 332

- 82:2070438 Discusses design margins of Class IE electrical sys above SSE for plants under SEP & near-term OLs Analysis should be conducted to determine whether non-Class IE loads should be automatically disconnected austmatically electronecteu LIPINSKI,W C Argonne National Laboratory LIPINSKI,W C ACR Advisory Committee on Reactor Safeguards 82/10/15 OKRENT,D - Advisory Committee on Reactor Safeguards 3pp 16355 337
- 8212070440 Summary of 820914-15 joint NRC/ANS meeting in Bethesda.MD re basic thermal hydraulic mechanisms in LGR analysis CATTON.I ACRS Advisory Committee on Reactor Safeguards 82/10/25 BOEHNERT.P ACRS Advisory Committee on Reactor Safeguerds 5pp 16355 340
- 8212090076 Transcript of AGRS Subcommittee on Regulatory Policy & Procedures 821207 meeting in Washington, DC Pp i-144
 Supporting documentation enc!
 * AGRS Advisory Committee on Reactor Safeguerds 82/12/07 16357 001
- 8212100001 Transcript of ACRS Subcommittee on Generic Items 821208 meeting in Washington, DC re prioritization of generic safety issues Fp 1-79 * ACRS Advisory Committee on Reactor Safeguards 82/12/08 117ap 16377 153
- 8212100017 Transcript of ACRS Subcommittee on Safety Research Program 821208 meeting in Washington.DC Pp 1-239 Viewgraphs encl * ACRS Advisory Committee on Reactor Safeguards 82/12/08 330pp 16373 001
- 8212100018 Transcript of ACRS Subcommittee on Advanced Reactors 821208 meeting in Washington DC Pp 1-104 + ACRS Advisory Committee on Reactor Safeguards 82/12/08 123pp 16373 042
- 8212100022 Transcript of ACRS Subcommittee on ECCS 821202 meeting in San Jose.CA Pp 1~246 Supportive documentation encl * ACRS Advisory Committee on Reactor Safeguards 82/12/02 401pp 16374 001 40100
- B212130040 Transcript of 272nd ACR5 general meeting on 821209 in Washington.DC Pp 1-285 Supporting documentation and 1 * ACR5 Advisory Committee on Reactor Safeguards 82/12/09 499pp 16392 018
- G212130045 Transcript of ACRS Subcommittee on ECCS B21203 meeting in San Jose CA Pp 247-414 Viewgraphs encl = ACRS Advisory Committee on Reactor Safeguards 82/12/03 319pp. 16390 205
- 8212130043 Transcript of 272nd ACRS general meeting on 821210 in Mashington DC Pp 286-392 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 82/12/10 511pp 16423 269
- 8212210277 Transcript of ACRS Subcommittees on Reliability & Probabilistic Assessment & Extreme External Phenomena B21215 meeting in Washington DC Pp 1-94 Supporting documentation encl ** ACRS - Advisory Committee on Reactor Safeguards 82/12/15 176pp 16483 047
- 8212230284 Transcript of AGRS Subcommittes on Class 7 Accidents 821221 meeting in Washington, DC Pp 1-250 Visugraphs encl * ACRS Advisory Committee on Reactor Gafeguards 82/12/21 340pp 16508 299
- B212280429 Transcript of ACRS Subcommittee on Electrical Sys B21222 meeting in Washington.DC Pp 1-202 Viewgraphs encl * ACRS Advisory Committee on Reactor Safeguards B2/12/22 284pp. 16557 097

COMMISSION NRC COMMISSIONERS

- B212060470 Responds to 821004 ltr re draft "NRC Staff Evaluation of Pressurized Thermal Shock." & draft ORNL rept. "Pressure Vessel Thermal Shock at US PWRs Events & Precursors, 1963-Mid-1981 "Comments will be considered PALLADINO, N J Commissioners 82/11/29 MARKEY, E J House of Rep 16343 301
- -8209150008 Expresses disappointment at failure to inform of NRC draft evaluation & DRNL precursor rept re nuclear reactor pressure vassel thermal shock Concerned w/dagree reactor vassels of operating PHRs have become vulnerable to cracking MARKEY,E J House of Rep., Interior & Insular Affairs 82/10/04 PALLADING,N Commissioners 4pp 16343 304

- 8212070090 Responds to 820813 itr repolicies & practices for conduct of investigation, specifically solicitation of public comments prior to policy adoption Most policies & procedures inappropriate for public comment PALLADING.N J Commissioners 82/11/23 CHARNOFF, G, HICKEY, J P Shaw, Pittman, Potts & Troubridge ip 16354 310
- --8212070076 Requests public comments solicited for proposed policies of investigations CHARNOFF,O . HICKEY,J P. Shaw. Pittman. Potts & Troubridge 82/08/13 PALLADING.N J Commissioners 7pp 16354 311
- 8212070342 Informs of redirection of LOFT program Sufficient financial support available for DDE to proceed w/formation of intl LOFT consortium forwards NRC/DDE interagency agreement on LOFT program responsibility PALLADING.N J Commissioners 82/11/22 BEVILL,T House of Rep , Appropriations ip 16356 247
- --BR1207035i Informs of redirection of LOFT program Sufficient financial support available for DOB to proceed w/formation of intl LOFT consortium Forwards NRC/DDE interagency agreement on LOFT program responsibility PALLADINO.N.J Commissioners 82/11/22 UDALL,M House of Rep. Interior & Insular Affairs tp 16336 248
- ~-8212070368 Informs of redirection of LOFT program Bufficient financial support available for DOE to proceed w/formation of intl LOFT consortium Forwards NRC/DOE interagency agreement on LOFT program responsibility PALLADING.N J Commissioners 82/11/22 HATFIELD.N O Senate, Appropriations ip 16356 250
- --BR12070372 Informs of redirection of LDFT program Sufficient financial support available for DDE to proceed w/formation of intl LOFT consortium Forwards NRC/DDE interagency agreement on LOFT program responsibility PALLADING.N.J. Commissioners 82/11/22 OTTINGER.R L. House of Rep. Energy & Commerce ip 16356 231
- --B212070378 Interagency agreement re LOFT program responsibility between NRC & DOE Responsibilities & obligations of parties for operation of LOFT facility delineated DIRCKS.W J Office of the Executive Director for Operations BREWER.S T Energy, Dept of 82/11/22 2pp 16356 252
- BP12070385 Informs that B21020 meeting to discuss QA & to provide informal feedback on initiatives being implemented helpful Initiative in providing comments commendable & appreciated FALLADINO,N J Commissioners B2/11/22 JACKBON, J P Management Analysis Co ip 16355-255
- --8208290147 Forwards comments re specific implementation of QA organization for NRC per Dircks 820820 memo to Commissioners

 JACKBON, J P Management Analysis Co 82/09/21 PALLADIND, N J Commissioners 7pp 16355 256
- 8212080005 Forwards FR notice of proposed rule recommending 5-yr reporting period to replace annual reporting for licensees distributing radioactive consumer products PALLADING,N J Commissioners 82/11/23 COEHLD,T House of Repip 16368 306
- --8212080009 Notice of proposed rule modifying reporting requirements for licensees distributing consumer products w/small quentities of radioactive matl HUYLEJ C Office of the Secretary of the Commission 82/11/1/15pp 16368 307
- 8212080023 Forwards rept of nundisclosure of safeguards info for quarter ending 820730 W/o encl PALLADINO,N J Commissioners 82/11/19 O'NEELL,TP House of Rep. Speaker of the House, ip 16367 155
- --8212080025 Forwards rept of nondisclosure of safeguards info for quarter ending 820930 PALLADING, N J Commissioners 82/11/19 BUSH, O H W Senate, Fresident of the Senate 8pp 16367 156
- 8212130334 Weekly info rept for wk ending 821203 REHM.T A Office of the Executive Director for Operations 82/12/09 44pp 16412 318

- 8212160634 Responds to RE Dickenson 821007 request for info re NRC involvement in archeological data recovery & survey activities for FY81-82 List of 1981-82 archeological activities & titles of survey repts encl DENTON.H R Office of Nuclear Reactor Regulation, Director 82/12/08 ATEN,L Interior.Dept of National Park Service 9pp 14466 023
- ---8212160643 Forwards questionnaires per annual rept to Congress on scope, effectiveness, cost & results of Federal archeological survey & data recovery program Return requested by 821130 DICKEMSON, R & Interior. Dept of, National Park Service 82/10/0/PALLADINO, N J Commissioners 5pp 16466 032
- 8212220512 Weekly info rept for wk ending 921210 REHM: T A Office of the Esecutive Director for Operations 82/12/16 32pp 16523 053
- 82122Q0555 Discusses M Holt 821122 itr to R Amsden re LERs from nuclear power plants All LERs from nuclear power plants made public None withheld or classified LERs containing security-related info are public w/proprietary info deleted DIRCKS W J Gfeice of the Executive Director for Operations 82/12/14 COHEN.W S Sonate 2pp 16523 030
- --8212220558 Requests info in response to encl constituent M Holt 821122 ltr re LERs filed w/NRC AMSDEN.R L Senate 82/11/23 D!RCKS,W J Office of the Executive Director for Operations 3pp 16523 032
- BP:12290521 Weekly info rept for wk ending 821217 REHM.T A Office of the Executive Director for Operations B2/12/27 3Bpp 16605 114
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- SP1201038) Notification of contract elecution, Nod 1 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor Univ of Toledo William Carlson Library
 LITTLE: M Administrative Contracts Branch NRC-10-82-410
 82/11/23 FELTON.J M Division of Rules and Records GOUNDER.J
 NRC No Detailed Affitiation Olven 1p 16271 092
- --B2120103B3 Mod 1,adding govt-furnished microfiche filing cabinet to "Maint & Operation of Local Public Document Rooms (LPDRs) "

 * Toledo, Univ of REBELLO.J & Division of Contracts
 NRC-10-B2-410 B2/ti/23 1p 16271 093
- B212010388 Notification of contract execution.Mod 2 to "Maint & Operation of Local Public Document Roems (LPDRs) "Contractor QA Dow Memorial Library.Middlend MI LITTLE.M Administrative Contracts Branch NRC-10-81-691 82/11/23 FELTCN.J M Division of Rules and Records SOUDER.J NRC No Detailed Affiliation Given 1p 16271 089
- --8212010391 Mod 2,adding four-drawer ltr-size cabinet,to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 * Midland County, MI REBELLO, J & Division of Contracts NRC-10-81-691 82/11/23 ip 16271 086
- 82/2010395 Notification of contract execution.Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor Minneapolis MN Public Library & Info Ctr
 LITTLE,M Administrative Contracts Branch NRC-10-01-696
 82/11/23 FELTON,J M Division of Rules and Records SQUDER,J
 NRC No Detailed Affiliation Given ip 16271 083
- --8212010398 Mnd 2,adding four-drawer ltr-size cabinet,to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 SHANNON, Z Minneapolis Mn REBELLO, JE Division of Contracth
 NRC-10-81-696 82/11/23 ip 16271 084
- BPI2010403 Notification of contract execution.Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor Crystal River.FL Public Library
 LITTLE.M. Administrative Contracts Branch NRC-10-81-694
 B2/11/23 FELTON.JM Division of Rules and Records SQUDER.J
 NRC No Detailed Affiliation Given 1p 16271 078
- --8212010406 Mod 2.adding four-drawer ltr-size cabinet, to "Maint & Operation of Local Public Document Rooms (LPDRs) "

 Crystal River.FL REBELLO, J E Division of Contracts
 NRC-10-81-694 82/11/23 1p 16271.079
- 8212010419 Notification of contract execution.Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor AR Tech Univ Library
 LITTLE, M Administrative Contracts Branch NRC-10-81-405
 82/11/23 FELTON.J M Division of Rules and Records SOUDER.J
 NRC No Detailed Affiliation Given ip 16267 339

- --8212010423 Mod 2,adding govt-furnished microfiche cabinet,to "Maint & Operation of Local Public Document Rooms (LPDRs)" Arkansas Tech Univ REBELLO, J E Division of Contracts NRC-10-81-405 82/11/23 Ip 16267 340
- G212010425 Notification of contract execution, Mod 2 to "Maint & Operation of Local Public Document Rooms (LPDRs) "Contractor Morris, IL Public Library LITTLE: M Division of Contracts NRC-10-81-407 82/11/23 FELTON, J M Division of Rules and Recards SDUDER, J NRC No Detailed Affiliation Given ip 16267 337
- --8212010430 Mod 2.adding govt-turnished microfiche cabinet,to "Maint & Operation of Local Public Document Rooms (LPDRs) " * Morris, IL REBELLD.JE Division of Contracts NRC-10-81-407 82/11/23 ip 16247 338
- 8212010432 Notification of contract execution.Mod 2 to "Maint & Decration of Local Public Document Roams (LPDRs) "
 Contractor Oconee County-SC Library
 LITTLE,M Administrative Contracts Branch NRC-10-81-381
 82/11/23 FELTON,J M Division of Rules and Records SQUDER,J
 NRC No Detailed Affiliation Given 1p 16267 333
- --8212010434 Mod 2.adding govt-furnished microfiche cabinet, to "Maint & Operation of Local Public Document Rooms (LFDAs) "

 # Oconee County, SC REBELLO, J E Division of Contracts
 NRC-10-81-381 92/11/23 ip 16267 334
- 8212010433 Notification of contract execution, Mod i to "Maint & Operation of Local Public Document Rooms (LPDRs) "
 Contractor Charlevoix, MS Public Library
 LITTLE: M Purchasing Section NRC-10-82-699 82/11/23
 FELTON, J M Division of Rules and Records SQUDER, J NRC No Detailed Affiliation Given ip 16267 335
- --8212010438 Mod 1.adding govt-furnished microfiche filing cabinet to 'Maint & Operation of Local Public Document Rooms (LPDRs) " • Charlevoix MI REBELLO, JE Division of Contracts NRC-10-82-649 82/11/23 ip 16247 336
- GP12020189 Notification of contract execution, Mod 6 to "In-Process Control of SNM" Contractor Science Applications, Inc FIELDS.J A Technical Assistance Contracts Branch MRC-02-61-040 B2/10/29 DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director MENDELSOHN, B NRC No Detailed Affiliation Given 1p 16308 299
- --8212020194 Mod 6.modifying due date for submittal of revised interim reptito "In-Process Control of SNM" HAGAN.T F Science Applications, Inc Contracts NRC-02-81-040 82/10/29 ip 16308 260
- G2120203B7 Notification of contract execution, Mod 6 to "Cyprus Mines Corp. Hansen Project Hill Tailings Evaluation " Contractor FC Hart Associanc MCLEAREN, T Technical Assistance Contracts Branch FIN B-6927 NRC-02-79-056. B2/11/24 DAVIS, U G Office of Nuclear Material Safety & Safeguards, Director ip 16277-360
- ~8212020390 Mod 6.Incorporating indirect rate & adding add1 funds.to "Cyprus Mines Corp. Hansen Project Mill Tailings Evaluation" Fred C Hart Associates, Inc. HACAN, T F. Division of Contracts FIN 8-6927 NRC-02-79-056 82/11/24 2pp 16297 361
- BP12020402 Notification of contract execution.Mod 1 to "Site Security Evaluation Model Test" Contractor TRH. Inc MCLEAREN.7 Technical Assistance Contracts Branch FIN B-6391-8 NRC-02-78-050 B2/11/24 DAVIB.J @ Office of Nuclear Material Safety & Safeguards.Director 1p 16297-394
- --8212020404 Mod 1. incorporating final indirect rates & deobligating unliquidated balance of funds, to "Site Security Evaluation Model Test"

 HERBERT, J.P. TRW. Inc. HAGAN, T.F. Technical Assistance Contracts, Branch FIN 8-6391-8 NRC-02-78-050 82/11/24 ip 16297 355
- B?12030236 Notification of contract execution, Mod 7 to "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity of Intersection "Contractor Purdue Research Foundation SILVIS.R M Technical Assistance Contracts Branch FIN 8-5971 NRC-04-76-323 B2/11/30 BATSON.W Office of Nuclear Regulatory Research, Director STEUER.N NRC No Detailed Affiliation Given 1p 16317 346

- --8212030243 Ltr Contract NRC-04-76-323,Mod 7,deobligating funds,to "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity "

 Accepted by RA Greenkorn on 821104

 OUSTAVE,R P Technical Assistance Contracts Branch FIN 8-5971

 NRC-04-76-323 82/10/26 DAVIS,R L Purdue Research Foundation

 1p 16317 347
- 8212030246 Notification of contract execution. Mod 4 to "Study to Develop Integrated Sys Concepts for Safeguards" Contractor General Research Corps SILVIB.R M Research Contracts Branch FIN B-5716 NRC-04-76-331 82/11/30 BATSON.W Office of Nuclear Regulatory Research, Director BERGOREN, J NRC No Detailed Affiliation Given 1p 16316 344
- --B212030266 Mod 4.deobligating funds to "Study to Develop Integrated Bys Concepts for Safeguards" VAN MORN, M. P. General Research Corp. GUSTAVE, R. P. Research Contracts Branch FIN B-5716 NRC-04-74-331 82/11/30 lp 16316
- 8212060114 Notsfication of grant execution.Mod 1 to "Fundamental Problems in Hodeling BWR Containment Bys Flows " Grantee MIT MCDERMGIT, D. Research Contracts Branch FIN G-1025 NRC-0-04-81-028 82/11/30 BATSON.W. LEE, T. Office of Nuclear Regulatory Research, Director ip 16323 011
- --B212060120 Mod 1, extending period of performance to 821230 at no cost, to "Fundamental Problems in Modeling BWR Containment Bys Flows"

 DUMMER, G H Massachusetts Institute of Technology MORTON, K V Research Contracts Branch G-1025 NRC-G-04-B1-02B B2/11/30 15 16323 012
- BP12060297 Notification of contract execution, Mod 8 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" Contractor Science Applications, Inc FLYNN, M J Technical Assistance Contracts Branch FIN B-8609 NRC-03-82-096 82/11/12 EISENHUT. D 6 Division of Licensing JOHNSON, B NRC No Detailed Affiliation Given 1p 16323 359
- --8212060304 Mod 8, providing incremental funding, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" * Science Applications, Inc HAGAN,TF Division of Contracts FIN N-8607 NRC-03-82-076 82/11/12 2pp 16223 360
- B212060405 Notification of contract execution.Mod 3 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " Contractor 9 Charnoff LITTLE.M Administrative Contracts Branch FIN 8-8179 NRC-18-82-481 82/11/17 ROTHSCHILD.T Office of the General Counsel ip 14322-316
- --8212060413 Mod 3, providing for miscellaneous expenses, extending period of performance to 830410 & increasing monetary value, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals" CHARNOFF. O Charnoff, Q REBELLO, J E Division of Contracts FIN 8-8179 NRC-18-82-481 82/11/17 ip 16322 317
- ©212060502 Notification of contract execution.Mod 2 to "Economic Impact of Nuclear Energy Ctrs " Contractor Univ of PA MCLEAREN, T Technical Assistance Contracts Branch NRC-02-75-155 82/09/07 DAVIS, J Ø Office of Nuclear Material Safety & Safeguards, Director ip 16948 012
- --8212060506 Ltr contract, Mod 2, deobligating unliquidated balance, to "Economic Impact of Nuclear Energy Ctrs" HAGAN, TF Technical Assistance Contracts Branch NRC-02-75-185 B2/09/02 KELLEY, D E Pennsylvania, Univ of 1p 16348 013
- 8212070424 Notification of contract execution "Cobalt Teletherapy Calibr Course," awarded to MD Anderson Hosp HOVLE: A Administrative Contracts Branch, FIN B-5090 NRC-08-83-267 82/11/17 KERR.G W Office of State Programs, Director BOLLING.L A NRC - No Detailed Affiliation Given Ip 16306 254
- --B212070429 Contract "Cobalt Teletherapy Calibr Course," awarded to MB Anderson Hosp GILLEY,E R M D Anderson Hosp , Houston, TX * Division of Contracts FIN 8-5090 NRC-06-83-267 82/11/17 4pp 16396 255
- B212070450 Notification of contract execution.Mod 1 to "Microfiche Verification & Retrofit " Contractor SBA: Subcontractor Labat-Anderson, Inc. PAGE: M Administrative Contracts Branch NRC-10-82-425 82/11/29 BESAM: W Division of Technical Information & Document Control STOCZLAB. J. SCOTT.S NRC No Detailed Affiliation Given ip 14355 345

- ~-8212070453 Mod I, issuing assignment of claim, to "Microfiche Verification & Retrofit " * Labat-Anderson, Inc * Small Business Administration SMITN:P A Division of Contracts NRC-10-82-425 82/11/29 2pp 16355 346
- 8P12080022 Notification of contract execution.Mod 2 to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities"
 Contractor Nuclear Associates Intl
 GUSTAVE.R Research Contracts Branch FIN B-7479 NRC-04-81-201
 62/11/26 BATSON.W . SCOTT.H Office of Nuclear Regulatory
 Research. Director (p. 16367 165
- --8212080024 Mod 2.adding FY83 incremental funding to "Evaluation of Power Reactor Fuel Rod Analysis Capabilities"

 * Nuclear Associates International GUSTAVE R P Research
 Contracts Branch FIN B-7474 NRC-04-81-201 82/11/26 ip
 16367 166
- B212080070 Notification of contract execution. Hod & to "Newspaper Clipping Byc " Contractor Press Intelligence. Inc CILDEMORN Division of Contracts NRC-10-81-397 82/11/10 SPRINGER. M L Office of Administration CONYNGHAM, M NRC - No Detailed Affiliation Given 1p 16367 356
- -B2120B0103 Mod 6.extending period of performance to B21107.to
 "Newspaper Clipping Svc "
 JONES.J M Press Intelligence.Inc SMITH.P A Division of
 Contracts NRC-10-B1-357 B2/11/10 2pp 16267 357
- 8212080572 Notification of contract execution, Mod 2 to "Ad Hec Committee for Review of Nuclear Reactor Licensing Reform Proposals " Contractor OH State Univ.College of Engineering LITTLE, M Administrative Contracts Branch FIN 8-8179 NRC-18-82-481-0 82/12/03 ROTHSCHILD, T Office of the General Counsek 1p 14368 335
- --8212080577 Mod 2, extending period of performance to 830410 & increasing total funds to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals"

 REDMOND, R F Ohio State Univ REBELLO, J E Division of Contracts FIN B-8179 NRC-18-82-481-0 82/12/03 ip 34048 334
- 9212080580 Notification of contract execution, Mod 1 to "Keypunch & Verification Sycs " Contractor Info Sys & Networks Corp FERLMAN, J Administrative Contracts Branch NRC-25-82-318 82/12/02 TROUTMAN, C Division of Automatic Data Processing Support OLIVER, D NRC - No Detailed Affiliation Given ip 14348 330
- --B2120805B3 Mod 1, adding Task 7, to "Keypunch & Verification Sycs ' MALKANI,R Information Systems & Network Corp Hill.D Small Business Administration SMITH.P A Division of Contracts NRC-25-82-318 B2/12/02 2pp 1636B 331
- GP1210D124 Notification of grant execution. Mod 2 to "Partial Support of Committee on Seismology" Grantee Natl Academy of Sciences HCDERMOTT. D. Research Contracts Branch FIN G-102B NRC-G-04-B1-023 82/12/03 BATSON W Office of Nuclear Regulatory Research, Director MURPHY. A NRC No Detailed Affiliation Given ip 16378 361
- --8212100133 Mod 2.extending grant period to 830930, increasing funding & incorporating 820723 renewal proposal, to "Partial Support of Committee on Seismology"

 SHITH: P H National Academy of Sciences MORTON, K V Research Contracts Branch FIN 0-1028 NRC-0-04-81-023 82/12/03 1p 16.398 362
- 8212100154 Notification of contract execution.Mod 1 to "Fuel Cycle Project Review " Contractor Science Applications.Inc WOLLETT'S Research Contracts Branch FIN 8-6494 NRC-04-80-17H 82/11/29 FOREHAND.W Diffice of Nuclear Regulatory Research: Director ENG.C. NRC - No Detailed Affiliation Given 1p 16398 340
- --B212100162 Mod 1.changing completion date from 921130 to 930115, to "Fwel Cycle Project Review"
 BRAINARD M F Science Applications, Inc GUSTAVE, R P Division of Contracts FIN 8-6694 NRC-04-80-178 92/11/29 ip
- B212100167 Notification of contract execution. Mod 1 to "Lab Studies Dynamic Response of Prototypical Piping Sys " Contractor ANCO Engineers, Inc & EFRI BAISDEN, L Technical Assistance Contracts Branch FIN B-8907 NRC-04-82-025, 82/11/29 FOREHAND, W Office of Nuclear Regulatory Research, Director, O'BRIEN, J Q NRC No Detailed Affiliation Given ip 16398 337

- --82(2100172 Ltr Contract NRC-04-82-025, Mod i.extending period of performance to 82(118, to "Lab Studies Dynamic Response of Protypical Piping Sys "
 MORTOL, K V Division of Contracts FIN 8-8907 NRC-04-82-025
 82/11/29 HOWARD, O E ANCO Engineers, Inc. RYTKONEN, B B Electric Power Research Institute 2pp 16398 338
- 6212130155 Notification of contract execution. Mod 5 to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated w/U Recovery Operations "Contractor Williams-Robinette & Assoc FIECDS, J A Technical Assistance Contracts Branch NRC-0-2-81-039 B2/12/01 DAYIS, J Office of Nuclear Material Safety & Bafeguards, Director Lp 16410 283
- --BR12130160 Mod 5.changing NRC technical representative under Article XII.to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated w/U Recovery Operations " # Williams-Robinette & Associates, Inc. GUSTAVE, R.P. Technical Assistance Contracts Branch NRC-02-81-039 82/12/01 1p
- B21213017B Notification of contract execution.Mod 7 to "Review of Tailings Mgt" Contractor CO State Univ FIELDS.J A Technical Assistance Contracts Branch NRC-02-80-082: B2/11/Q3 DAVIS.J Office of Nuclear Material Safety & Safeguards.Director FLEMING.T NRC No Detailed Affiliation Given 19 16410 360
- --8212130182 Mod 7.extending draft & final evaluations due date to 830630.to "Review of Tailings Mgt " BROWN,J F Colorado State Univ HAGAN,T F Division of Contracts NRC-02-80-82 82/11/03 lp 14410 341
- B212130364 Contract "Word Processing Svcs," awarded to Press Intelligence Inc # Press Intelligence Inc MATTIA M J Division of Contracts NRC-10-83-298 82/11/08 22pp 16412 161
- 8212160593 Notification of contract execution Mod 2 to "Licensing Assistance/Qeotechnical & Hydrological Evaluations" Contractor Shannon & Wilson: Inc FIELDS, JA Technical Assistance Contracts Branch NRC-02-80-003-06 82/12/03 DAVIS.J Office of Nuclear Material Safety & Safegards, Director OARCIA, P NRC No Detailed Affiliation Given 1p 16466 037
- --8212160608 Mod 2.changing controller address & incorporating revised manual chapter to "Licensing Assistance/Geotechnical & Hydrological/Evaluations"
 MILLER, R P Shannon & Wilson: Inc HAGAN, T F Division of Contracts NRC-02-80-033-06 82/12/03 ip 16466.038
- 82/2170378 Notification of contract execution Nod 24 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions "Contractor Franklin Inst FLYNI, M J Technical Assistance Contracts Dranch FIN 8-6570 NRC-703-79-118 82/11/23 EIBENNUT, D Division of Licensing BAJWA, B NRC No Detailed Affiliation Oiven 1p 14478 146
- --8212170401 Mod 24, obligating funds, incorporating award fee earned from Jan-June 1982 & substituting key personnel, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"

 * Franklin Institute/Franklin Research Center HAGAN, T F Division of Contracts FIN B-6590 NRC-03-79-118 82/11/23 4pp 16478 147
- --8212170402 Notifies NRC of resignation of AA Conzale: as assistant project manager for contract Proposes TA Bhook to assume responsibility
 ABHTUN, A K Franklin Institute/Franklin Research Center NRC-03-79-118 B2/10/28 HAOAN, T Technical Assistance Contracts Branch 19 16478 151
- B012220018 Notification of contract execution. Mod 7 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2" Contractor Franklin Inst FLYNN.M J Technical Assistance Contracts Branch FIN 8-6891 NRC-03-81-130 82/11/22 EISENHUT.D 6 Division of Licensing BAJWA.8 NRC No Detailed Affiliation Given ip 14529 093
- --8212220024 Mod 7, increasing funds, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2"

 * Franklin Institute/Franklin Research Center HAGAN, T. F
 Division of Contracts FIN B~6891 NRC~03-81~130 82/11/22
 20a 16529 094

- 82:1220019 Notification of contract execution, Mod 2 to "Availability of Medical Treatment to Minimize Early Fatalities Post-Bevere Reactor Accidents " Contractor SBA Subcontractor Andrulis Research Corp FLEETINGS ON Technical Assistance Contracts Branch NRC-03-82-128 82/11/03 MATTSON, R J Division of Systems Integration (post Bi1005) CHU, A NRC No Detailed Affiliation Given ip 16529 071
- --8212220027 Mod 2. substituting project officer. to "Availability of Medical Treatment to Minimize Early Fatalities Post-Severe Reactor Accidents"

 * Small Business Administration * Andrul's Research Corp MAGAN. T F Division of Contracts NRC-03-82-128 82/11/03 1 15529 092
- B212220025 Notification of contract execution.Mod 2 to "Matl Balance Capability of Process Similar to NFS.Erwin.TN " Contractor NUSAC Inc GILDENHORN.A J Administrative Contracts Branch FIN 8-1314 NRC-19-82-491. 82/12/07 ZERBE.JE, ONO.C Office of Policy Evaluations Ip 16529 082
- --B2[2220034 Mod 2.adding add1 work.extending period of performance through B2[23] & increasing funding.to "Mat] Balance Capability of Process Similar to NrS.Erwin.TN "PEVENTEIN.JE NUSAC.Inc SMITH.P A Division of Contracts FIN B-1314 NRC-19-82-491 82/12/07 2pp 16529 083
- BP12220522 Notification of contract execution, Mod 12 to "Study of Seismicity & Tectonics in New England" Contractor Boston College JACOBS, A Research Contracts Branch FIN A-4056 NRC-04-74-238 82/12/07 BASTON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Given in
- --8212220528 Mad 12 extending period of performance to 831031 w/add1 workscope & funds.to "Study of Spismicity & Tectonics in Neu England"
 SMITH, J R Boston College GUBTAVE, R P Division of Contract: FIN A-4056 NRC-04-74-238 82/12/07 5pp 16522 398
- 8212220524 Notification of contract execution.Mod 8 to "Regional Tectonics & Seismicity of KS" Contractor Univ of KS JACO85.A Research Contracts Branch FIN B-6172 NRC-04-77-017 82/12/14 BATSON.W Diffice of Nuclear Regulatory Research, Director MURPHY.A NRC No Detailed Affiliation Given 1p
- --8212220535 Hod B, extending period of performance for 3 months, to "Regional Tectonics & Seismicity of KS" HORDWITE, F D Kansas, Univ of QUSTAVE, R P Division of Contracts FIN 8-6172 NRC-04-77-017 82/12/14 29p 14522, 355
- B212220536 Notification of contract execution. Mod 2 to "Support in Geotechnical Engineering for Nonreactor Facilities" Contractor Army Corp of Engineers BILVIS.R H Research Contracts Branch FIN B-6846 NRC-03-80-129 B2/12/09 DENTON. HR Office of Nuclear Reactor Regulation, Director is 16522 348
- --8212220542 Mod 2.deobligating funds,to "Support in Centechnical Engineering for Nonreactor Facilities" KAVANAUGH.P F Army.Dept of, Corps of Engineers GUSTAVE.R P Division of Contracts FIN 8-6846 NRC-03-80-125 82/12/09 ip 16522 349
- 8212220549 Notification of contract execution.Mod 2 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities "Contractor State of OA SILVIS.R M Research Contracts Branch FIN 8-5203 NRC-D5-79-252 82/12/15. COBB.L Training & Administration Staff COHEN.L NRC NO Detailed Affiliation Given 1p 16523 349
- --8212220553 Mod R. deobligating funds, to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within State of OA & Selected by Commission "
 LEDRETTER.J. L. Georgia, State of, GUSTAVE.R.P. Division of Contracts FIN 8-5203 NRC-05-79-252 82/12/15 ip 16523 350
- B212230044 Notification of contract execution. Mod 5 to "Fuel Cycle Licensing" Contractor. Duke Univ SILVIB. R M Technical Assistance Contracts Branch FIN A-9005 AT(40-1)-4399 82/12/15 DAVIS. J G Defice of Nuclear Material Safety & Safeguards. Diractor 1p. 16544 344

- --8212230051 Mod 5, deabligating & abligating funds, to "Fuel Cycla Licensing" SHUMATE D R Duke Univ GUSTAVE, R P Division of Contracts | 112 A-9005 AT(40-1)-4399 82/12/15 1p 16544 347
- 821227004B Responds to FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svcs," awarded to Alderson Reporting Co.Inc Forwards documents listed in App A FELTON.J M Division of Rules and Records FIN B-131(NRC-17-B0-448-0 82/11/19 OALLO.J Isham, Lincoln & Beale Spp. 1554-044
- --B212270052 Request for procurement action 80-SEC-448, executing Mod # to 'Stenographic Reporting Svcs " Mod obligates add! funds CHILK, B Uffice of the Secretary of the Commission FIN 8-1311 RRC-17-80-448-0 82/01/18 2pp 16566 049
- --8212270055 Forwards unexecuted Mod 8 to "Stenographic Reporting Eves," extending period of performance to 820318 & obligating add1 funds Approval requested
 LEBO.C D Administrative Contracts Branch FIN 8-4311
 RRC-17-80-448-0 82/02/01 SHARP, R A Alderson Reporting 2pp
 18564 051
- --B212270059 Forwards Mod 8 to "Stenographic Reporting Svcs," extending period of performance to 820318 % obligating addl funds LEBO.C D Division of Contracts FIN B-1311 NRC-17-80-44H-0 82/02/08 SHARP.R A Alderson Reporting 1p 16566 059
- --8212270065 Mod 8, extending period of performance to 820318 & increasing funds obligated to "Stenographic Reporting Svcs " Findings & determination encl SHARP, A Alderson Reporting LEBO,C D Division of Contracts FIN 8-1311 NRC-17-80-448-0 82/02/02 2pp 16566 054
- --8212270080 Notification of contract execution. Mod 8 to "Stenographic Reporting Bors" Contractor Alderson Reporting Co. Inc PADE: M. Administrative Contracts Branch FIN 9-1311 NRC-17-80-448-0 82702702 CHILK. S. J., SULLIVAN. P. Office of the Secretary of the Commission MCNAMARA. A Atomic Sarcty and Licensing Board Panel 1p. 16566 056
- --B212270084 Request for procurement action 80-5EC-448, executing Nod 9 to "Stenographic Reporting Svcs " Mod extends period or performance to B20501 & obligates addl funds HOYLE-J C Office of the Secretary of the Commission FIN 8-1311 NRC-17-80-448-Q 82/02/23 2pp 16566 057
- --8212270088 Forwards unexecuted Mod 9, extending period of performance to B20501 & obligating addl funds to "Stenagraphic Reporting Sycs " Approval requested LEBD.C D Division of Contracts FIN 8-1311 NRC-17-80-448-0 B2/03/05 SHARP.R A Alderson Reporting 2pp 1656-6059
- --8212270091 Forwards Mod 9.extending period of performance to 820501 % obligating add1 funds to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co.Inc LEBO.C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/03/15 SHARP.R A Alderson Reporting Ip 16566 063
- --B212270095 Request for procurement action BO-SEC-448, executing Mod 10 to "Stenographic Reporting Svcs " Mod extends period of performance to 820806 & obligates addl funds HOYLEJ C Office of the Secretary of the Commission FIN B-1311 NRC-17-80-448-0 82/05/04 2pp 16566 065
- --B212270107 Forwards Unexecuted Mod 10.extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested SMITH.P A Administrative Contracts Branch FIN B-1311 NRC-17-B0-44B-0 82/05/28 SMARP.R A Alderson Reporting 2pp 14556 070
- --8212270110 Forwards Mod 10.extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Svcs "SMITH-P A Administrative Contracts Branch FIN 8-1311 NRC-17-80-448-0 82/06/11 Alderson Reporting 1p 16566 0/3
- --8212270114 Request for procurement action 80-SEC-448 executing Mod 1) to "Stenographic Reporting Svcs" Mod extends period of performance to 821115 & obligates addl funds CHIKK 3 Office of the Secretary of the Commission FIN 8-1311 NRC-17-80-448-0 82/07/16 2pp 16566 075
- --B212270123 Forwards unexecuted Mod 11, extending period of performance to B21115 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested SHITH-P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 B2/08/07 SHARP-R A Alderson Reporting 2pp 16564 077

- --8212270127 Forwards Mod 11.extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Sycs"
 SMITH.P A Administrative Contracts Branch FIN B-1311
 NRC-17-80-448-0 82/08/20 Alderson Reporting 1p 16566 OBI
- --8212270131 Mod 11.extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs" SHARP.R A Alderson Reporting SMITH.P A Division of Contracts FIN 8-1311 NRC-17-80-448-0 82/08/20 1p 16566 082
- --8212270133 Notification of contract execution, Mod ii to "Stenographic CIRC/VIGG Notification of contract execution Mod 11 to "Steno Reporting Sucs " Contractor Alderson Reporting Co, Inc PAGE.M Administrative Contracts Branch FIN 8-1311 NRC-17-80-448-0 82/08/20 CHILK.S J. SULLIVAN.P Office Secretary of the Commission MCNAMARA.A Atomic Safety and Licensing Board Panel 1p 16366 083 Office of the
- 62:2270410 Notification of contract execution. Mod 5 to "Geotechnical Engineering Review of SEP Plants " Contractor US Army Corps of Engineers
 FIELDS J A Technical Assistance Contracts Branch NRC-03-81-12;
 82/11/16 VOLLHER, R H . HELLER, L Division of Engineering 1p
 16055 358
- --B212270412 Mod 5, extending period of performance to B31231, to
 "Geotechnical Engineering Review of SEP Plants"
 KAVANAUGH, PF Army, Dept of, Carps of Engineers HAGAN, TF
 Division of Contracts NRC-03-81-122 82/11/16 2pp 16555 359
- G212270415 Notification of contract execution.Mod 1 to "Fire Protection Review & Evaluation " Contractor Rolf Jensen & Assoc, Inc FIELDS, J A Technical Assistance Contracts Branch NRC-03-82-093-01 82/11/23 VOLLMER, R H , FERGUSON, R Division of Engineering 1p 16555 361
- --8212270417 Mod i,changing address for controller ofc & revising manual chapter to "Fire Protection Review & Evaluation"

 WEBB.W A Rolf Jensen & Associates, Inc HAGAN,T F Division Contracts NRC-03-82-093-01 82/11/23 ip 16555 362 Division of
- 8212270419 Notification of contract execution, Mod 9 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" Contractor Science Applications, Inc FLYNN.M J Technical Assistance Contracts Branch FIN 8-8609 NRC-03-82-076 82/11/30 EISENHUY, D G , SILVER, H Division of Licensing ip 16566 033 EISENHUT, D G , SILVER, H Division of
- --8212270422 Mod 9, providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2" * Science Applications, Inc GUSTAVE, R P Division of C FIN B-8609 NRC-03-82-096 82/11/30 2pp 16546 034
 - GUSTAVE,R P Division of Contracts 82/11/30 2pp 16566 034
- 8212270446 Notification of contract execution, Mod 4 to "Review & Critique of Pu Package Certification " Contractor Natl Academy of Sciences
 SILVIS.R M Technical Assistance Contracts Branch FIN B-148/-/
 NRC-02-77-004 B2/12/20 DAVIS.J 0 NUSBBAUMER.D Office of
 Nuclear Material Safety & Safeguards, Director 1p 16548 348
- --8212270447 Mod 4, deabligating funds to "Review & Critique of Pu Package Certification SMITH P National Academy of Sciences GUSTAVE, R P Contracts FIN B-1487-7 NRC-02-77-004 82/12/20
- B212270470 Notification of contract execution "Press Clipping Svr," awarded to Press Intelligence, Inc DURBEY, M., BAZIN, J. Administrative Contracts Branch NRC-10-83-248 S2/11/08 BESAU, W. J. Division of Technical Information & Document Control 1p 16566 359
- 8212270496 Notification of contract execution Mod 1 to "Reproduction of Copies Re Stanislaus Nuclear Project Unit 1,NRC Docket P-564-A " Contractor Speigel & McDiarmid & Northern CA Power Agency CA Power Agency SMITH.P.A Division of Contracts NRC-10-79-391 82/12/17 SPRINGER.M., WOOD.R Office of Administration ip 16348 358
- --8212270502 Mod 1.deobligating funds to, "Reproduction of Copies Re Stanislaus Nuclear Project,Unit 1.NRC Docket P-564-A" * Northern California Power Agency, California.State of, TRAUGER.T C Spiegel & McDiarmid SMITH.P A Division of Contracts NRC-10-79-391 82/12/17 ip 16548 359
- 8212270503 Notification of contract execution.Mod R to "Electrical & Instrumentation Technology & Codes Course" Contractor GE GUSTAVE.R P Technical Assistance Contracts Branch FIN B-1258 NRC-05-81-261 82/12/16 BLAHA.J.L. Director's Office, Office of Inspection and Enforcement THAYER,C W NRC No Detailed Affiliation Given 1p 16548 355

- ~-8212270506 Mad 2.authorizing revision of course text, to "Electrical & Instrumentation Technology & Codes Course '
 CALK, J C General Electric Com MORTON, K V Division of Contracts FIN 8-1258 NRC-05-81-241 82/12/16 2pp 16548 356
- 8212270509 Notification of contract execution.Mod 2 to "Synergisite Effects of Low Level Radiation" Contractor Modidman SMITH.P A Contract Policy Branch FIN B-8049 NRC-03-82-114 B2/12/17 DENTON,H Office of Nuclear Reactor Regulation, Direct CONGEL.F NRC No Detailed Affiliation Given 1p 16948 353
- --8212270513 Mod 2, deabligating funds for close autito "Synergistic Effects of Low Level Radiation" GULDMAN,M Ooldman,M SMITH.P A Division of Contracts FIN B-8049 NRC-03-82-114 82/12/17 Ip 16548 354
- G2:12270510 Notification of contract execution Mod 5 to "Card-Entru Access Control Sys " Contractor Racal Vikonics.Inc GILDENHORINA J Administrative Contracts Branch NRC-10-82-399 82/12/07 SPRINGER.M L Administrative Contracts Branch FINGER.R NRC No Detailed Affiliation Given 1p 16548 350
- --8212270516 Mod 5.clarifying acceptance test requirements & extending period of performance due to govt delay to 834131.to "Card-Entry Access Control Sys "

 Racal Visonics, Inc SMITH.P A Division of Contracts NRC-10-82-399 82/12/07 2pp 16548 351
- B?1227051B Notification of contract execution, Mod 2 to "Long-Term Performance of Matis Used for High Level Waste Packaging " Contractor BNML SILVIS,R M Technical Assistance Contracts Branch FIN B-6764 NRC-04-082-015 82/12/17 BATSON,W Office of Nuclear Regulatory Research, Director KIM,K NRC No Detailed Affiliation Given Research, Director 1p 16546 361
- --8212270521 Med 2,granting incremental funding to "Long-Term Performance of Matl Used for High Level Waste Packaging" * Battelle Memorial Institute, Columbus Laboratories GUSTAVE, R P Division of Contracts FIN B-6764 NRC-04-62/12/17 1p 16546 362 NRC-04-82-015
- GP12270527 Notification of contract execution.Mod 3 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "Contractor FC Hart Associator February Technical Assistance Contracts Branch NRC-02-79-031-04 82/11/03 BAVIS, J G Office of Nuclear Material Safety & Sareguards, Director ROSSBACH, L NRC No Detailed Affiliation Oliven ip 16551 004
- --8212270530 Mod 3, extending period of performance to 820630 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation " STASCO.W M Fred C Hart Associates, Inc. HAGAN, T.F. I Contracts NRC-02-79-031-04 82/11/03 1p 16551 005
- 8712270539 Notification of contract execution.Mod 4 to "Analysis of Safeguards Needs for Transport of High Level Waste " Contractor BNML Contractor BMML
 FIELDS, J A Technical Assistance Contracts Branch FIN B-6990-3
 NRC-02-BI-030 B2/11/29 DAVIS, J Office of Nuclear Material
 Safety & Safeguards, Director SAWYER, C NRC - No Detailed
 Affiliation Given ip 16546
- ~~8212270543 Mod 4, obligating funds to "Analysis of Safeguards Needs for Transport of High Level Waste " * Battelle Memorial Institute, Columbus Laboratories HAGAN.T J Blvision of Contracts FIN B-6970-3 NRC-02-81-030 82/11/29 16546 357
- BP12270555 Notification of contract execution, Mod 8 to "In-Process of SNM" Contractor Science Applications, Inc FIELDS, J A Technical Assistance Contracts Branch FIN 8-7315-3 NRC-02-81-040 82/11/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MENDELSCHN, 8 NRC No Dotailed Affiliation Given ip 14546 340
- --8212270556 Mad B.obligating funds to "In-Process Control of SNM" * Science Applications. Inc FIN B-7315-3 NRC-02-81-040 82/11/29 ip 16546 341
- BP12270558 Notification of contract execution, Mod 1 to "Economic PIRE/USDS NOTIFICATION OF CONTRACT execution Find 1 to "Economic Consulting Svcs in Connection w/Stanislaus Nuclear Unit, Antitrust Hearing Docket P-564-A " Contractor PM Gutmann SILVIS:R M Technical Assistance Contracts Branch FIN B-6521 NRC-03-BI-120 SZ/12/21 DENTON,H R Office of Nuclear Reactor Regulation, Director TOALSTON,A NRC - No Detailed Affiliation Given. 1p 14546-338

- --B212270560 Mod 1, deobligating funds to "Economic Consulting Svcs in Connection u/Stanislaus Nuclear Unit. Antitrust Hearing Docket P-564-A" OUTMAIN.P M Outmann.P M QUSTAVE.R P Technical Assistance Contracts Branch FIN B-6521 NRC-03-81-120 82/12/21 ip
- 8212280043 Notification of contract execution. Mod 13 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co. Inc PAGE.M Administrative Contracts Branch FIN 8-1311 NRC-17-80-448 82/12/15 CHILK.S J Office of the Secretary of the Commission ip 14593 006
- --8212260044 Mod 13.extending period of performance to "Stenographic Reporting Svcs" * Aljderson Reporting SMITH,P A Division of Contracts FIN B-1311 NRC-17-80-448 82/12/15 1p 16593 007
- 50:12280047 Natification of contract execution. Mod 8 to "Kinetics of Chlorine-Ammonia in Sea Water " Contractor Univ of NC SILVIS, M Research Contracts Branch FIN B-6248 NRC-04-77-119 B2/12/15 BATSON-W Office of Nuclear Regulatory Research, Director REED, P NRC - No Detailed Affiliation Given 1p
- --8212280049 Ltr contract, Mod 8. deabligating funds, to "Kinetics of Chlorine-Anmonia in Sea Water" GUSTAVE, R P Division of Contracts FIN 8-6248 NRC-04-77-119 82/11/09 CROOK, P North Carolina, Univ of ip 16590 362
- 8212280445 Notification of contract elecution Mod 3 to "Transparent Armor Testing " Contractor US Army FIELDS.J A Technical Assistance Contracts Branch NRC-02-81-029 82/11/03 DAVIS.J Office of Nuclear Material Safety & Safeguards.Director GUINN.E NRC - No Detailed Affiliation Given Jp 16590 350
- --82(228)455 Mod 3, modifying period of performance until 821231 & changing project officer to "Transparent Armor Testing"
 RICHARDS, J. F. Army, Dept of HAGAN, T. F. Division of Contracts
 NAC-02-81-029 82/11/03 [p 16570 351
- 5212280469 Notification of contract execution, Mod 7 to "Technical Assistance for EIS on 100FR61" Contractor Dames & Moore FIELDS, JA Technical Assistance Contracts Branch FIN B-7318-3 NRC-02-81-049 82/11/15 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director ROLES, G NRC No Detailed Affiliation Given 19 16590 346
- --8212280478 Mod 7, modifying statement of work extending period of performance to 830630, obligating funds & modifying key personnel, to "Technical Assistance for EIS on 10CFR61 OJTU-ALI,O I Dames & Moore MATTLAN J Division of Contracts FIN 8-7318-3 NRC-02-81-049 82/11/15 3pp 16590 347
- B?12280486 Notification of contract execution.Mod & to "Technical Assistance in Repository Design " Contractor Coulder Associance Inc. P.IELDS., A Technical Assistance Contracts Branch NRC-02-81-01/82/11/15 DAVIS.J Office of Nuclear Material Bafety & Safeguards.Director HARTUNG.L NRC No Detailed Affiliation Given in 16590 355
- --8212280491 Mod 6, modifying statement of work & extending period of performance to 830715, to "Technical Assistance in Repository Design"
 ROVE.J W Golder Associates MATTIA.M J Division of Contracts NRC-02-81-037 82/11/15 2pp 16590-356
- 82:12270053 Notification of contract execution, Mod 7 to "Buckling Behavior of Steel Containment Shells " Contractor Lockhed Missiles & Space Go. Inc. I EELDS, J. A. Technical Assistance Contracts Branch NRC-03-80-103 82:09721 HANAUER. S. Division of Safety Technology SCHAUER. F NRC - No Detailed Affiliation Given ip 16607 053
- GP12290266 Notification of contract execution, Mod 2 to "Evaluation of NRC Executive Development & Mgt Program " Contractor Project Assoc, Inc GMITH, P Division of Contracts NRC-10-81-356 82/12/16 SPRING, M Office of Administration ALLER, R NRC No Detailed Affiliation Olven 1p 16406 262

- --8212290273 Mod 2, deobligating funds for close out, to "Evaluation of NRC Executive Development & Mgt Program "
 GONVERSANE. E Project Associates SMITH,P A Division of Contracts NRC-10-81-355 82/12/16 p 16606 263
- 8212300117 Notification of contract execution, Mod 3 to "Presentation of OE BMR Nuclear Engineering Courses " Contractor GE JACOBS, A Research Contracts Branch FIN B-1232 MRC-05-80-265 82/12/21 BLAHA, J Program Support Branch FOX.E NRC No Detailed Affiliation Olven 1p 16624 247
- --B212300123 Mod 3.adding 3-month extension to B20927 at no add1 cost.to
 "Presentation of 0E BHR Nuclear Engineering Courses "
 PIERCE, R L General Electric Co GUSTAVE, R P Division of
 Contracts FIN β-1232 NRC-09-B0-265 B2/12/21 lp 16624 249
- B212300127 Notification of contract execution.Mod 7 to "Graphics/ Photographic Svcs " Contractor Robert Charles Moles & Assoc PERLMAN, J Administrative Contracts Branch FIN B-1297 NRC-09-81-257 B2/12/20 BLAHA, J L Program Support Branch THAYER, C NRC - No Detailed Affiliation Given 1p 16624 250
- --B212300132 Mod 7, adding incremental funding to "Graphics/Photographic Sycs" * Robert Charles Moles & Associates SMITH, P.A. Division of Contracts FIN 8-1297 NRC-05-81-257 82/12/20 ip 16624 254
- 82:12300170 Notification of contract execution, Mod 2 to "Major tarthquakes on East Side of New Madrid Earthquake Zone "Contractor Vanderbilt Univ SILVIS.R M Technical Assistance Contracts Branch FIN 8-8078 NRC-04-81-195 82/12/17 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Given in 1643-073
- --8212300192 Mod 2,providing incremental funding to "Major Earthquakes on East Bide of New Madrid Earthquake Zone" * Vanderbilt Univ GUSTAVE.R P Division of Contracts FIN B-807B NRC-04-81-195 82/12/17 fp 16613 074
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8207180049 FOIA request for contract & any proposals, best & final offers, technical & cost questions & answers & related mods submitted by Parameter Inc under Request for Proposal R8-DIE-82-249
 DAVID, L T Franklin Institute/Franklin Research Center 82/08/19 FELTON, J M Division of Rules and Records 1p 16289 204
- 8708290092 F01A request for SECY-81-600A, SECY-81-622A, SECY-82-23, SECY-82-42, SECY-82-136, SECY-82-137, SECY-82-197A, SECY-82-197B, SECY-82-286 & SECY-82-315 GRABER, L Affiliation Unknown 82/09/08 Division of Rules and Records 1p 16384 294
- 8208290104 FDIA request for eight listed documents
 CONNOR.L Doc-Search Associates 62/09/14 Division of Rules and
 Records ip 16388 227
- 8708290121 FOIA request for documents & records prepared by Energy, Inc re NRC rulemaking on ATMS REVELEY, T N . CHRISTMAN. J N . EARLEY, A F Hunton & Williams FIN A-1228 82/09/22 Office of Administration 3pp 16400 009
- 8209150054 F0IA request for listed documents referenced in SECY-B2-Lil.
 Page 24
 CRABER.L Affiliation Unknown 82/09/30 Division of Rules and
 Records 1p 16400 353
- 8209150055 FOIA request for SECY-82-255 ORABER:L Affiliation Unknown 82/10/04 Division of Rules and Records 1p 16553 331
- 8207150071 FDIA request for documents setting forth policy re issuances of NRC press releases in connection w/enforcement & licensing activities & coverage of licensing & other hearings by media HARTMAN.S L Debeygise & Liberman 82/10/13 FELTON, J. M Division of Rules and Records ip 16287 001
- 8212010012 Responds to FOIA request for contract & any proposals, best & final offers, technical & cost questions & answers & related mods submitted by Parameter, Inc under Request for Proposal R8-01E-82-249
 FELTON: J M Division of Rules and Records 82/11/08 DAVID. L T Franklin Institute/Franklin Research Center ip 16289 205

- --8212010016 Technical proposal in response to NRC Request for Proposal RR-01E-82-249, "Technical Assistance to Support NRC-IE Personnel in Investigation of Incidents" LOFY.R A Parameter, Inc 82/04/02 65pp 16289 206
- --8212010021 Submits suppl to 820402 proposal re NRC RFP R6-0IE-82-249, "Technical Assistance to Support NRC-IE Personnel in Investigation of Incidents," per NRC 820615 request LOFY,R A Parameter, Inc 82/06/21 MORTON,K V Research Contracts Branch, 7pp 16289 273
- B212010027 Responds to FOIA request for documents setting forth policy re issuances of NRC press releases in connection w/ enforcement & licensing activities Forwards documents listed on app Documents also available in PDR FELTON, J M Division of Rules and Records 82/11/01 HARTMAN, S Debevoise & Liberman Spp 16287 002
- --8212010051 10CFR2 re NRC policy & procedure for enforcement actions # NRC No Detailed Affiliation Given 82/03/09 9pp 15289 005
- --B212010058 Discusses implementation of camera policy at hearings No significant problems identified in cases where cameras were allowed ABRAHAN. K Region i. Philadelphia. Office of the Director 78/10/06 FOUCHARD. J Office of Public Affairs 2pp 16289 017
- --B212010067 Forwards draft papers re camera coverage of licensing hearings Draft "Consent Calendar" recommends that Commission permanently formalize policy of permitting camera coverage of licensing hearings w/listed conditions INORAM.F L Office of Public Affairs 78/10/03 ROSENTHAL.A Atomic Safety and Licensing Appeal Panel YORE.J Atomic Safety and Licensing Counsel 14pp 16289 019
- --8212010070 Informs that F Ballard.Commissioner of Dept of Bldg & Orounds for Onondaga County has no objections to use of cameras in public safety bldg Draft public announcement of oral argument will be sent shortly INORAM, Ft. Office of Public Affairs 78/03/10 ROSENTHAL, A Atomic Safety and Licensing Appeal Panel Ip 16289 033
- --B2:2010077 Informs that E Owens has no objections to use of cameras in Courthouse 3 of Richland County Courthouse providing no interference w/judicial proceedings for both adjoining courtrooms evident INORAM, F L Office of Public Affairs 78/03/07 BMITH, I Atomic Safety and Licensing Board Panel ip 16287 034
- --8212010080 Informs that Region 5 public affairs officer J Hanchett has confirmed, w/appropriate officials, that Commission trial camera policy may be implemented re NRC proceedings held in US Customs House in San Francisco, CA INGRAM. FL Office of Public Affairs 78/03/02 LUTON, E Atomic Safety and Licensing Board Panel ip 16289 035
- --B212010071 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ASLB & ASLAB under certain conditions FGUCHARD, J J Office of Public Affairs 78/02/01 SIZEMORE, H N Seattle Times ip 16287 037
- --B212010096 Denies request to photograph proceedings of ASLB 770511 hearing. Use of cameras during actual proceeding has been prohibited Commission considers cameras to be source of distraction
 CHILK:B J Office of the Secretary of the Commission 77/05/09 SIZEMORE:H M Seattle Times ip 16289 038
- --8212010097 Expresses disappointment re denial of request to permit photographs to record ASLB 770811 proceedings in Seattle.WA SIZEMORE.H N. Seattle Times 77/08/13 CHILK.S J. Office of the Secretary of the Commission ip 16287 037
- ~-B212010102 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ABLB & ASLAB under certain conditions FDUCHARD. J. Office of Public Affairs 78/02/01 COGAN, P KING Television, Seattle, WA ip 16289 040

- --8212010105 Denies request to photograph proceedings of ASLB 770511 hearing Use of cameras during actual proceeding has been prohibited because Commission considers cameras to be source of distraction CHICK.S J Office of the Secretary of the Commission 77/05/09 COOAN.P KING Television, Seattle, WA ip 16289 041
- --8212010103 Informs that Commission will permit, on trial basis, camera coverage of proceedings before ASLE & ASLAB under certain canditions FOUCHARD, J. J. Office of Public Affairs 70/02/01 VRIESHAN, W. R Radio Television News Directors Association ip 16289-042
- -- 8212010112 Responds to 770831 ltr re use of news cameras at ASLB public hearings in Tulsa.OK Commission adherence to policy allowing cameras in hearing rooms only before & after each session was pursued during facility proceedings HEYDRIE.J M Commissioners 77/07/30 VRIESMAN,W R Radio Television News Directors Association lp 16287-043
- -- 9212010119 Protests Commission refusal to conduct official business while news cameras are present at facility hearings in Tulsa, OK Action considered discriminatory VRIESMAN, & B. Radio Television News Directors Association 77/08/31 HENDRIE, J.M. Commissioners ip 16289 044
- --8212010123 Advises that Judge Devitt has drafted itr re clarification of Rule 7d as to whether rule prohibits use of cameras under any circumstances or whether policy might be applicable to NRC proceedings held in court facilities Draft itr enci FOUCHARD. J. Office of Public Affairs 78/01/31 NELSON, J. Office of the General Counsel 2pp 16289-045
- --B212010137 Advises that 14 of 25 federal agencies surveyed have partially implemented Recommendation 72-1 re adoption of regulations encouraging broadcast coverage of proceedings involving issues of public interest YORE, JR Atomic Bafety and Licensing Board Panel 77/10/03 FOUCHARD, J Office of Public Affairs 2pp 16289 047
- --B2f2010141 Recommends that retention or existing policy re use of cameras during adjudicatory hearings Legal challenge to Cormission authority to bar cameras would be unsuccessful few.if any.federal courts permit use of cameras nUSENTHAL.A S Atomic Safety and Licensing Appeal Panel 77/09/22 FOUCHARD, J Office of Public Affairs 3pp 16289 049
- 8212010143 SECY-77-974
 Obtains Commission guidance re-policy concerning use of cameras during licensing hearings FOUCHARD. J Office of Public Affairs 77/11/11 (3pp 16287-052)
- --82120)0149 Advises of changes in draft Commission paper on camera policy Recommendation section added based upon position indicated Upon receipt of addl comments, paper will be forwarded to Commission for consideration FOUCHARD. J. Office of Public Affairs 77/11/19 ROBENTHAL, A Safety and Licensing Appeal Panel YORE, J.R. Atomic Safety and Licensing Appeal Panel YORE, J.R. Atomic Safety and Licensing Board Panel NELBON, J. Office of the General Counsel 10pp 16289 065
- --8212010157 Recommends Ofc of Public Affairs propose to Commission change of procedure & practice that would open limited appearance portion of hearing to coverage by visual media & already established print media & radio coverage ADRAHAM. A Office of Public Affairs 77/05/11 HARRIS, J J Office of Public Affairs 2pp 16287 075
- --8212010159 Forwards memo from C Wisher re camera coverage at ASLD hearings INORAM,F L Office of Public Affairs 78/07/13 YORE,J Atomic Safety and Licensing Goard Panel ip 16289 077
- --B212010162 Discusses difficulties encountered in camera policy at 780629-30 hearings WISNER,C E Region 4, Dallas, Office of the Director 78/0//07 INGRAM.F Office of Public Affairs 2pp 16289 078
- --B212010168 Comments on NRC trial policy re use of cameras during lacensing proceedings New policy is working well HANCHETT.J O Defice of Public Affairs 78/06/13 INTERRANIL.J KFRC Radio. San Francisco. CA ip 16289 080
- --B212010174 Concurs w/Commission decision to make proceedings of licensing boards open to cameras Requests rept on how sys is working INTERRANTE, J. KFRC Radio, Ban Francisco, CA. 78/06/05 HANCHETT, J. NRC - No Detailed Affiliation Given 1p. 16289 UB1

- --B212010177 Informs that L Emert of GSA has no objection to use of cameras in US Pust Ofc & Federal Bldg in Peoria IL INGRAM, F Office of Public Affairs 78/04/07 COODHOPE, A Atomic Safety and Licensing Board Panel to 16289 082
- --8212010180 Informs that Carey has no objection to use of cameras in Auxiliary Courtroom of US Court of Appeals in Everett McKinley Dirksen Bldg Use of Commission trial policy in connection u/facility remand proceeding proposed INGRAM.F Office of Public Affairs 78/04/11 MILLER.M Atomic Safety and Licensing Board Panel 19 14289 083
- --G212010187 Informs that ASLB requested guidance from Commission re television coverage of portions of Midland proceedings involving discussion of past culpable conduct of individuals Commission should set forth position in matter KELLEY, J. Uffice of the General Counsel 78/03/31 HENDRIC, J., GILINSKY, V., KENNEDY, R. Commissioners 3pp 16289 084
- --8212010196 Informs that Judge KilKenny oft has no objections to use of cameras during Pebble Springs 780411 prehearing conference in Portland OR Lite From J Hanchett to A Goodwin entil INGRAM.F L Office of Public Affairs 78/03/28 YORE, J Atomic Safety and Licensing Board Panel Ip 16289 087
- --8212010201 Informs that Judge Kilkenny ofc has no objection to use of cameras during Trojan 780417 prehearing conference in Portland, OR INGRAM. FL Office of Public Affairs 78/03/28 WOLFE, S Atomic Safety and Licensing Board Panel Ip 14287 088
- --8212010209 Confirms understanding from previous conversation that television or still cameras may be used by representatives of news media in courtroom during NRC licensing proceeding Press release explaining new Commission policy encl HANCHETT. J G Office of Public Affairs 78/03/22 OGODHIN.A U S Court of Appeals 9th Circuit ip 16287-089
- -- B212010218 Informs that S Manchett confirmed that Commission trial camera policy may be implemented in connection w/Pebble Beach evidentiary hearing to be held in Beattle, WA INGRAM, Edfice of Public Affairs 79/03/02 VENSCH, S Atomic Sarety and Licensing Board Panel 1p 16289 091
- --8212010226 Informs that K Abraham confirmed that Commission trial camera policy may be implemented in all rooms below sixth floor of Middlesex Superior Courthouse in East Cambridge/AA Trial procedures will be in effect for Pilgrim 2 hearing INORAM.F Office of Public Affairs 78/03/02 COUFAL.F Atomic Sarety and Licensing Board Panel 1p 16289 092
- --8212010230 Forwards first cut at Commission paper on camera policy Comments needed as soon as possible Other federa! agencies will be checked to determine current camera policy & info will be added to paper FOUCHARD. J J Office of Public Affairs 77/09/21 YORE. J R Atomic Safety and Licensing Board Panel ROSENTHAL. A S Atomic Safety and Licensing Appeal Panel KELLEY, J L Office of the General Counsel Spp 16289 093
- --8212010235 Informs that cameras will not be permitted in Courtroom 4 of Morris County Courthouse in Morristown,NJ in connection w/ evidentiary hearing re Radiation Yechnology, Inc Cameras banned from all courtrooms in state INGRAM, F Office of Public Affairs 78/03/30 JENSCH,S Atomic Safety and Licensing Board Panel 1p 16289 101
- --8212010238 Order convening 780503 evidentiary hearing in Morristown,NJ re Radiation Technology.inc JENSCH.S W Commissioners 78/03/28 ip 16289 102
- --8212010244 Discusses Commission policy on camera coverage of quasijudicial licensing hearings NRC follows policy of federal courts & regulatory agencies prohibiting camera coverage of hearings while in session HARRIS.J A Office of fublic Affairs 75/10/22 KETTENRING.M MSM-TV. Nashville. TN ip 16289 103
- --82[2010249 Requests comments re alternatives open to Commission re camera policy at NRC licensing hearings Alternatives re adherence to present policy of permitting cameras to be used in hearing room before & after sessions discussed HARRIS, J A Office of Public Affairs 75/04/17 SHAPER, H. K Office of the General Coursel GOODRICH, N H Atomic Safety and Licensing Board Panel ip 16289.104
- B2:2010314 F01A request for SECY-82-303 \$ SECY-82-318 GRABER,L Affiliation Unknown \$2/10/28 Division of Rules and Records 1p 16271 183

- 8212010348 Responds to FOIA SECY-82-303 & SECY-82-318 Documents withheld (ref FOIA Exemption 5) App A documents available at PDR FELTON, J M Division of Rules and Records 82/11/19 GRABER, L Affiliation Unknown 4pp 16271 184
- B212010440 FOIA request for list of all refs cited in reviews of 71 plants under Assignment 13 of contract w/Franklin Research Ctr H/ESEMANN, R A Westinghouse Electric Corp NS-RAW-82-426 82/10/20 FELTON, J M Division of Rules and Records 1p 16268 201
- BB12010446 Responds to FOIA request for list of all refs cited in reviews of 71 plants under Assignment 13 of contract W/Franklin Research Ctr FELTON.J M Division of Rules and Records NRC-03-81-118 82/10/26 WIESEMANN,R A Westinghouse Electric Corp 1p 16268 202
- --8212010451 List of all refs cited in reviews of 71 plants under Assignment 13 of NRC Contract 03-81-118 * Franklin Institute/Franklin Research Center NRC-03-81-118 82/09/27 714pp 16268 RO3
- 8212020008 Add1 response to FOIA request for documents re final rule on environ qualification Forwards App A Documents 12,23,28,35,41,45,53,65,66,70 & 73 Document 65 listed incorrectly Info completely & partially withheld (ref FOIA Exemption 5) FELTON,J M Division of Rules and Records 82/11/08 CURRAN.D Harmon & Heiss 7pp 16297 112
- ---8202180082 Responds to 811214 memo re SECY-BI-504 & 81-603 Draft version of USI A-46 Task Action Plan currently under review w/expected issue date of Mar 1982 Responses of SGRT case-bycase audits listed types of shortcomings DIRCKS.W J Office of the Executive Director for Operations 82/01/29 AHEARNE, J F Commissioners in 16297 175
- --B204130511 Requests info re status of 18 plants being considered for continued operation, per SECY-82-91 on environ qualification of electric equipment AHEANE, J Commissioners 82/03/15 Office of the Executive Director for Operations 1p 16297 179
- --B206220057 Draft Commission paper providing final rule on environ qualification of safety-related electric equipment for nuclear power plants W/o encl DIRCKS, W J Office of the Executive Director for Operations 82/06/09 3pp 16297 180
- --B212020012 Requests that rule be developed to establish criteria & schedules associated w/environ qualification of Class IE electrical equipment & to address seismic qualification CHILK.S J Office of the Secretary of the Commission COMNP-81-1 81/10/20 DIRCKB.H J Office of the Executive Director for Operations ip 16297 154
- --B212020016 Approves proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Pawer Plants " ROBERTS.T M Commissioners 81/11/30 CHILK.8 J Office of the Gecretary of the Commission ip 16297 155
- --8212020019 Advises that Commission requested to approve proposed rule to clarify & strengthen criteria for environ qualification of electrical equipment CHILK, 8 J. Office of the Secretary of the Commission #22/01/06 Office of the Secretary of the Commission ip 16297 156
- --B212020023 Approves proposed rulemaking, "Environ Qualification of Electric Equipment for Nuclear Power Plants" Date for final environ qualification should be end of first refueling outage after Mar 1982 OFLINBSY.V Commissioners B1/12/17 CHILK.S J Office of the Secretary of the Commission 1p 16297 157
- --8212020056 Notifies of Commission request for draft "Immediately Effective" rule extending 820610 deadline for qualification of electrical equipment Draft should offer choice between extension for specific period & extension by deadline CHILK.S J Office of the Secretary of the Commission 82/06/10 DIRCKS.W J Office of the Executive Director for Operations 1p 16297 290
- --8212020067 Discusses Commission 920401 briefing on proposed final rule re environ qualification of electrical equipment CHILK.B J Office of the Secretary of the Commission 82/06/10 Office of the Secretary of the Commission ip 16297 291

- --8212020075 Discusses revisions to final rule. "Environ Qualification of Safety-Related Electric Equipment for Nuclear Power Plants" Revisions re title, specific sections & coding qualification requirements for replacement parts recommended CHILK.S J Office of the Secretary of the Commission 82/06/25 DIRCKS, W J Office of the Executive Director for Operations 2pp
- --8212020080 Offers no comments re Commission paper, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Plants" DEYOUNO.R C Director's Office, Office of Inspection and Entercement 82/07/12 AGGARWAL, E.K. Electrical Engineering Branch 1p 16297-294
- GP12060410 FOIA request for computer printouts &/or floppy discs re Broad Licensed (02110), Institutional Licensed (02120) & Private Practice Facilities (02200) SAVINI, R. J. LIXI, Inc. B2/10/22 VACCA, P. Uranium Fuel Licensing Branch ip 16346-007
- 9212060415 Responds to FDIA request for computer printouts &/or floppy discs re Broad Licensed (02110).Institutional Licensed (02120) & Private Practice Facilities (02200) Forwards printouts W/o encls FELTON.J M Division of Rules and Records 82/11/08 SAVINI.R J LIXI. Inc ip 16346 008
- GRI2060420 FOIA request for certified copy of IE Bulletin \$1-01.
 "Surveillance of Mechanical Snubbers," for presentation in
 litigation
 WISHMER, J A Saul. Ewing, Remick & Saul 168-81-01 82/11/03
 ROBINSON, L Division of Rules and Records 1p 16346 009
- 8212060424 Responds to FOIA request for certified copy of IE Bulletin 81-01. "Surveillance of Mechanical Snubbers." for presentation in litigation Forwards certification FFLTCN, J M Division of Rules and Records IEB-81-01 82/11/12 WISHNER, J A Saul, Ewing, Remick & Saul ip 16346-010
- --B212060427 Certifies IE Bulletin 81-01, "Surveillance of Mechanical Shubbers " DEYDUNG, R C Director's Office, Office of Inspection and Entercement CHILK, S J Office of the Becretary of the Commission IEB-81-01 82/11/10 ip 16346 011
- 82:12040433 FOIA request for documents re NRC facsimile network resident inspector site locations & Facsimile Network Monthly Traffic Vol (Representative) for June 1982 BARTON, C Mashington Management Group, Inc 82/10/21 NRC ~ No Detailed Affiliation Given Ip 16346 019
- 8212060440 Responds to FDIA request for documents re NRC facsimile network, resident inspector site locations & Facsimile Notwork Monthly Traffic Vol (Representative) for June 1982 lorwards document FELTON, J M Division of Rules and Records 82/11/10 BARTON, C Washington Management Group, Inc. 1p 16346-020
- --8212060445 "NRC Facsimile Network NRC Resident Inspector Site Locations % NRC Facsimile Network Monthly Traffic Vol (Representative), June 1982 "

 * NRC No Detailed Affiliation Given 82/11/10 3pp 16346 021
- BP12060450 F01A request for documents re NRC investigation of Nuclear Pharmacy, Inc.
 EMSKMILLER, J. R. Wall Street Journal 82/10/26 Division of Rules and Records Ip 16346-024
- 8712050453 Responds to FOIA request for documents to NRC investigation of Nuclear Pharmacy. Inc Ofc of Inspector & Auditor will make records available per 821119 telcon during wk of 821122 FELTON, J M Division of Rules and Records 82/11/12 EMSHWILLER, J Wall Street Journal 1p 16346 025
- BP12070494 FOIA request for statement of work for contract "Explore Effects on Export Trade." awarded to JF Coates, Inc STEGER. H A Consad Research Corp 82/11/02 Division of Contracts ip 14384 195
- BP12070408 Responds to FOIA request for statement of work for contract "Explore Effects on Export Trade," awarded to JF Coates, Inc No records subj to request located FELTON. J M Division of Rules and Records 82/11/12 STEGER.W A Consad Research Corp. 16.356.176
- BD12070414 Responds to FOIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facility Records available at PDR FELTON, J.M. Division of Rules and Records 82/11/05 GUIGG, C Pollution & Environmental Problems, Inc. 4pp. 16356 002

- 8212070425 Responds to FOIA request for documents re 820809 natice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents C1-C4 partially withheld (ref FOIA Exemptions 3.5 % 7) FELTON-J M Division of Rules and Records 82/11/05 MCQARRY, J M Debevoise & Liberman Spp 16395 C03 24X Fiche 50-000,82/11/05, R312070425
- 82:2080006 Addl response to FOlA request for seven categories of infore NF6.Erwin. TN facility Forwards App A documents denoted w/asterisk
 FELTON, J M Division of Rules and Records 82/10/25 HEISS.E R
 Harmon & Weiss 36pp 16369 001
- --8212080008 Forwards final versions of "Safeguards Upgrade Schedule" & "Working Group Responsibilities" EVANS.L J Requirements Analysis Branch 77/01/24 JONES.R, MICHAELS.T Diffice of Standards Development, Director FONNER.R Office of the Executive Legal Director 16pp 16369 258
- ~-B2120B0010 Forwards general comments on safeguards rule upgrade CHAMGERS.O 8 Office of Inspection & Enforcement, Office of the Director 77/02/16 EVANS.L J Requirements Analysis Branch 2pp 16369 274
- --B212089011 Comments on 770210 draft of upgraded rules Implication of min essential sys specs unclear HATTER, B J NRC - NO Detailed Affiliation Given 77/02/16 EVANS, L J Requirements Analysis Branch 1p 16369 276
- --8212080013 Comments on 770210 memo re status rept of upgrade rule activity ARSENAULT.F U Division of Bafeguards, Fuel Cycle & Environmenta) Research 77/02/16 EVANS, L J Requirements Analysis Branch 12pp 16369 277
- --B2120B0017 Forwards comments in response to 771220 memo re issues on upgrade rule
 GUHIN,M A Assistant Director for Export/Import & International
 Bafeguards 78/01/23 EVANS,L J Requirements Analysis Branch
 118pp 16369 289
- --B212080027 Forwards paper which develops underlying ideas of containment & use (n Basic Capability 4 Paper builds upon 770131 & 0204 papers & presents different approach from 770216 submittal

 BPIRO, H J TRW, Inc 77/02/17 EVANS, L J Requirements Analysis Branch 4pp 16370 047
- ~~B2120B002B Forwards "Evaluation of Smith-Oreenberg Impinger Method for Sampling Solubla Airborne U in Environ " Recommends discontinuing air sampling in environ using method Details of evaluation available for review during subsequent insps MAMSER.W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 81/06/30 0/REILLY,J P Region 2, Atlanta, Office of the Director (81/03/01) 1p 16367 042
- ~~82120B0030 Forwards recommendations for 10CFR73 app re GA for safeguards sys SPIRD.H J TRW, Inc 77/03/01 EVANS.L J Requirements Analysis Branch 15pp 16370 051
- ~~8212080032 "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ " * Nuclear Fuel Services, Inc (subs of Getty Dil Co) 81/06/30 7pp 16369 043
- ---B212080041 Discusses subcommittee rept on consistency issues arising from comparison of proposed safeguards upgrade rule (73 50) & proposed 73, 55 KUNIHIROD M Requirements Analysis Branch HILLER, J Program Support Branch 77/02/16 EVANS, L J Requirements Analysis Branch 6pp 16370 066
- --8212080044 Forwards option paper addressing Basic Capability 4 Paper builds upon 770131 & 0204 option papers BODDE,D L TRH, Inc 77/02/16 EVANS,L J Requirements Analysis Branch 6pp 16370 072
- --B2120B0051 Comments on safeguards upgrade rule Licensees & NRC should develop methods of testing.achievement & maint of functional capabilities
 THAYER, T NRC No Detailed Affiliation Given 77/02/02
 EVANS.B NRC No Detailed Affiliation Given 2pp 16370 078
- --8212080056 Discusses characteristics of performance-priented rule & mathods of development ERICKSON, 8. NRC No Detailed Affiliation Given 77/02/02 EVANS, B NRC No Detailed Affiliation Given 14pp 16370 080

- --B212080058 Comments on matl transmitted by 770317 memo re basic capability regulatory provisions & companison of basic capabilities whasic essential elements Five capability narratives encl
 CHAMBERS, O S Division of Befeguards Inspections 77/03/24
 EVANS.L J Requirements Analysis Branch 8pp 16369 055
- --821209306; Forwards drafts of revised basic capability regulatory provisions, basic capability overview uniteup, disaggregation of basic capabilities added to see the capability of the capability
- --B212080055 Forwards comments re interdependence of basic capabilities per 770118 meeting Redundant, independent, mixed mode sys essential due to magnitude of downside risk of safeguards sye w/loopboles
 SPIRO.H J TRH. Inc. 77/01/21 EVANS.L J NRC No Detailed Affiliation Given Spp 16370 094
- --8212080066 Forwards drafts of narratives for three basic capabilities for protecting SNM in-transit Drafts are follow-on to 770309 discussions of basic capabilities paper Comments needed by 770317

 EVANSIL J Requirements Analysis Branch 77/03/15 NRC No Detailed Affiliation Given 8pp 16349 084
- --8212080070 Forwards comments on structure of basic capabilities por 770112 meeting & subsequent telcons Term "containment" should be broadly defined to include all safeguards-related conditions 8000E:0 L TRW, Inc 77/01/18 FOLTERAK, A S NRC No Detailed Affiliation Given 13pp 16370 079
- --8212080076 Comments on issues resulting from public comments re proposed upgrade rule, "Responsibility for Nuclear Security "Intervenors will be influenced by original Congressional Intent for NRC safeguards program BRIGHTSEN,R A Division of Safeguards 77/11/15 BURNETT,R F Division of Safeguards 9pp 16370 112
- --B2120B0077 Comments on Capabilities ! & 3 of "Basic Capabilities Needed to Protect SNM While in Transit" Discussion of detection sys under Capability 1 inappropriate since detection sys discussed under cargo security of Capability 2 ELLIOTT.J M Program Support Branch 77/03/17 EVANS.L J Requirements Analysis Branch 1p 16269 098
- --B212030084 Comments on draft interim companion rules Consistent ref to SSNM should be made throughout document Use of term "performance criteria" confusing THAYER, T C NRC - No Detailed Affiliation Given 76/09/14 POWERS, J A NRC - No Detailed Affiliation Given 4pp 16370 128
- --B212080092 Comments on "Basic Capabilities Needed to Protect SNM While in Transient " Capability 2 should allow air & sea transport where excort vehicles not normally used MICHAELS.T 8 Haterials Protect Standards Branch 77/03/17 EVANS.L J Requirements Analysis Branch 2pp 16369 099
- --B212083095 Discusset language for other than performance & sys spec requirements per 770308 memb KUMITHIRO.D M. Requirements Analysis Branch 77/03/11 EVANS.L J Requirements Analysis Branch 7pp 16367 101
- ~-8212080099 Recommends proposed license conditions for NFS be adopted All items on inventory should be remeasured regardless of period generated except meth shipped offsite & independently verified by receiver STELLO.V Office of inspection & Enforcement, Office of the Director 79/11/05 BURNETT.R P Division of Safeguards ip 16370 134

- --8212080101 Forwards draft of basic Capebility 5 narrative Comments requested by 770314
 EVANS.L.J. Requirements Analysis Branch
 Office of Inspection & Enforcement, Office of the Director
 JONES.R., MICHAELS.T. Office of Standards Development, Director
 400 16369 111
- --82120B0104 Comments on "Basic In-Transit Protection Capabilities"
 Second capability should be called cargo security instead
 of physical protection
 JUNES, J. Haterials Protect Standards Branch 77/03/04
 EVANS, L.S. Requirements Analysis Branch Ip 16369 131
- ---B212080107 Comments on narretive of fifth basic capability per 7/030, memo Sections redundant & contain misplaced subfunction statements

 JONES, J. Materials Protect Standards Branch 77/03/04

 EVANS, L. J. Requirements Analysis Branch 7pp 16369:132
- --B2(2080)11 Forwards revised list identifying basic elements essential for safeguards sys to be effective against design pasis threat JONES,R J Materials Protect Standards Branch 77/03/09 EVANS,L J Requirements Analysis Branch 4pp 16369-141
- --8212080113 Discusses 791105 meeting w/NF9 re license conditions Safeguards requirements, including math centrol & physical security, will be upgraded SLAYLOCK, J. Division of Safeguards Inspections 79/11/06 CHAPELL, D.R. Division of Safeguards Inspections 1p 16370 1.89
- --B2:2080116 Forwards draft "Basic Cepabilities for Transportation & Narrative for Basic Capability 4," for comment Comments should relate to whether capabilities would provide coverage of all essential functions

 EVANS,L J Requirements Analysis Branch 77/02/24 CHAMBERM;, ()

 Office of Inspection & Enforcement, Office of the Director JONES,R, MICHAELS,T Office of Standards Development, Director 23pp 16369 145
- --B212080117 Discusses Commission 791106 briefing re NFB status FUI investigation uncovered no evidence of illegal employee activity Cause for inventory difference not identified BLAYLOCK, J Division of Safeguards Inspections 79/11/08 CHAPELL, D.R. Division of Safeguards Inspections 14pp 16370 139
- --8212080126 Discusses basic capabilities for transportation protection of SNM Basic capabilities needed to assure effective response to attempt to steal mati & assure against mabbiage JONES.R.J. Materials Protect Standards Branch 77/02/24 EVANS.L. Requirements Analysis Branch 2pp 16369-168
- --B2120B0129 Advises of B10103 or 0104 informal briefing for congressional aides from Oversight Committee in Washington, DC on status of NFS Erwin Briefing requested by Acting Chairman Ahearne in view of recent media interest HOMARD, E M Division of Safeguard; Inspections 79/12/28 STELLO, V Office of Inspection & Enforcement, Office of the Orestor ip 16370 153
- --B212080133 Requests comments on encl draft "Dasic Capabilities for Transportation"
 EVANS,L J Requirements Analysis Branch 77/02/16 CHAMDERS, () Office of Inspection & Enforcement, Office of the Director JONES, R, MICHALS, T Office of Standards Development, Director Spp 16369 170
- --8212080137 Comments on 770210 memo to upgrade working group entitled "Status Rept Upgrade Rule Activity "
 ELLIOTT, J M Program Support Branch 77/02/16 EVANS, L J
 Requirements Analysis Branch 2pp 16369 179
- --B2120B0139 Supplemental PNS-II-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sys found not to exceed limits for unrestricted use CORYELL, 0 P. TDBIN, W.J. Region 2. Office of Director 79/09/25 ip 16370 154
- ---8212080142 Recommends editorial changes for basic capability narratives ERICKSON,B NRC - No Detailed Affiliation Given 77/02/17 EVANS,B NRC - No Detailed Affiliation Given ip 16349 [BI
- --8212080146 Comments on draft capability narratives & min essential requirements Basic capability narratives appear complete if coverage assumed in two basic capabilities not presented UNKES.R J Materials Protect Standards Branch 77/02/15 EVANS.L Division of Safeguards 20pp 16369 182

- --82:2080149 Supplemental PNS-II-79-102K on 79:102, initial reinventory efforts resulted in partial reconciliation of 79:09:17 difference Unresulved inventory difference in excess of regulatory limits for continued operation remains LEE,T D. GILLESPIE,F P. Region 2. Atlanta, Office of the Director 79:11/02 ip 16:370 155
- --8212080161 Forwards status of upgrade rule activity Work proceeding to develop alternative approaches to implementing upgrade Examples of drafts useful for developing third option reperformance requirements encl EVANS. J. Requirements Analysis Branch 77/02/10 CHAMBERS. D. Diffice of Inspection & Enforcement. Office of the Director JUNES, R., MICHAELS, T. Office of Standards Development, Director 24pp 16369-202
- --8212080167 Requests comments on safeguards upgrade rule structure & first performance capability narrative drafts by 770201 EVANS.L J Requirements Analysis Branch 77/01/26 JONES.R . MICHAELS.T Office of Standards Development. Director FONNER.R Office of the Executive Legal Director 13pg 16347 237
- --8212080008 Forwards final versions of "Safeguards Upgrade Schedule" & "Morking Group Responsibilities " EVANS, L. J. Requirements Analysis Branch 77/01/24 JONES, R. MICHAELS, T. Office of Standards Development, Director FDNNER, R Office of the Executive Legal Director 16pp 16367 258
- --8212080010 Forwards general comments on safeguards rule upgrade CHAMBERS.O S Office of Inspection & Enforcement, Office of the Director 77/02/16 EVANS.L J Requirements Analysis Branch 2pp 16367 274
- --8212083011 Comments on 770210 draft of upgraded rules Implication of min essential sys specs unclear HATTER.B J NRC - No Detailed Affiliation Given 77/02/16 EVANG.L J Requirements Analysis Branch ip 16369 276
- --8212039013 Comments on 770210 memo re status rept of upgrade rule activity ARSENAULT: F J Division of Safeguards. Fuel Cycle & Environmental Research 77702/16 EVANS.L J Requirements Analysis Branch 12pp 16369 277
- --8212080017 Forwards comments in response to 771220 memo re 1ssues on upgrade rule OWHIM A Assistant Director for Export/Import & International Safeguards 78/01/23 EVANS.L J Requirements Analysis Branch 118pp 16369 289
- --8212080027 Forwards paper which develops underlying ideas of containment & use in Basic Capability 4 Paper builds upon 77011 & 0204 papers & presents different approach from 770216 submittal SPIRD.H J TRW. Inc 77/02/17 EVANS,L J Requirements Analysis Branch 4pp 16370 047
- --8212080028 Forwards "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborne U in Environ " Recommends discontinuing air sampling in environ using method Details of evaluation available for review during subsequent insps MANSER. H C Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 81/06/30 0/REILLY, J.P. Region 2, Atlanta, Office of the Director (81/03/01) 1p 16349 042
- --8212080030 Forwards recommendations for 10CFR73 app to GA for safeguards sys SPIRO,H J TRW, Inc 77/03/01 EVANS,L J Requirements Analysis Branch 15pp 16370 051
- --8212080032 "Evaluation of Smith-Greenberg Impinger Method for Sampling Soluble Airborns U in Environ"

 * Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 81/06/30
 7pp 16369 043
- --B212080041 Discusses subcommittee rept on consistency issues arising from comparison of proposed safeguards upgrade rule (73 50) & proposed 73 55

 KUNITHIRO,D M Requirements Analysis Branch MILLER, J Program Support Branch 77/02/16 EVANS,L J Requirements Analysis Branch 6pp 16370 066
- --B2120B0044 Forwards option paper addressing Basic Capability 4 Paper builds upon 770131 & 0204 option papers BODDE.D L TRW. Inc. 77/02/16 EVANS.L J Requirements Analysis Branch App 16370 072
- --8212080051 Comments on safeguards upgrade rule Licensees & NRC should develop methods of testing, achievement & maint of functional capabilities
 THAYER.T NRC No Detailed Affiliation Given 77/02/02
 EVANG.B NRC No Detailed Affiliation Given 2pp 16370 078

- ~-8212080056 Discusses characteristics of performance-oriented rule & methods of development ERICKSON.8 NRC No Detailed Affiliation Given 77/02/02 EVANS, B NRC No Detailed Affiliation Given 14pp 16370 080
- ~-B2120B005B Comments on matl transmitted by 770317 memo re basic capability regulatory provisions & comparison of basic capabilities u/basic assential elements Five capability narratives encl
 CHAMBERS.O S Division of Safeguards Inspections 77/03/24
 EVANS.L J Requirements Analysis Branch Spp 16069 055
- --8212080061 Forwards drafts of revised basic capability regulatory provisions basic capability overview writeup, disaggregation of basic capability flarts & cross-ref comparison of basic capabilities w/basic essential elements

 EVANS.L J Requirements Analysis Branch 77/03/17 NRC No Detailed Affiliation Given 21pp 16367 064
- --8212080065 Forwards comments re interdependence of basic capabilities per 770118 meeting Redundant, independent, mixed mode sys essential due to magnitude of downside risk of safeguards eys w/loopholes 6PIRO, H J YRH, Inc 77/01/21 EVANS, L J NRC No Detailed Affiliation Given 5pp 16370 094
- --B212080066 Forwards drafts of narratives for three basic capabilities for protecting SNM in-transit Drafts are follow-on to 770307 discussions of basic capabilities paper Comments needed by 770317 EVANS.L J Requirements Analysis Branch 77/03/15 NHC -- Nn Detailed Affiliation Given -- Bpp 16369 084
- --8212080070 Forwards comments on structure of basic capabilities per 770112 meeting & subsequent telcons Term "containment" should be broadly defined to Include all safeguards-related conditions BODDE, D L TRW, Inc 77/01/18 POLTERAK, A S NRC - No Detailed Affiliation Given 13pp 16370 099
- --B2120B007A Comments on issues resulting from public comments re proposed upgrade rule. "Responsibility for Nuclear Security "Intervenors will be influenced by original Congressional intent re NRC safeguards program BRIGHTSEN.R A Division of Bafeguards 77/11/15 BURNETT,R F Division of Safeguards 9pp 14370 112
- --8212080079 Comments on Capabilities 1 & 3 of "Basic Capabilities Needed to Protect SNM While in Transit" Discussion of detection sys under Capability 1 imappropriate since detection sys discussed under cargo security of Capability 2 ELLIOTT. J M Program Support Branch 77/03/17 EVANS, L J Requirements Analysis Branch 19 16369 098
- --8212080081 Forwards expanded chart showing applicability of interim & companion rules to MOX fuel cycle & RD&D activities Chart raises important issues re scope of interim rule & definition of Category III Pu BODDE, D L TRW, Inc 76/04/09 EVANS, L J Division of Safeguards 7pp 16370 121
- --8212080084 Comments on draft interim companion rules Consistent ref to SSNM should be made throughout document Use of term "performance criteria" confusing THAYER, T C NRC - No Detailed Affiliation Given 76/09/14 POWERS
- --8212080092 Comments on "Basic Capabilities Needed to Protect SNM While in Transient " Capability 2 should allow air & sea transport where escort vehicles not normally used MICHAELS.TS Materials Protect Standards Branch 77/03/17 EVANS.L J Requirements Analysis Branch 2pp 16369 099
- ---B2120B0095 Discusses language for other than performance & sys spec requirements per 770308 memo KUNIHIRO.D M Requirements Analysis Branch 77/03/11 EVANS.L J Requirements Analysis Branch 9pp 16367 101
- --8212080101 Forwards draft of basic Capability 5 narrative Comments requested by 770314 EVANS.L J. Requirements Analysis Branch 77/03/08 CHAMBERS,D. Office of Inspection & Enforcement, Office of the Director JONES, R. MICHAELS, T. Office of Standards Devalopment, Director 4pp 16369 111
- ---8212080104 Comments on "Basic In-Transit Protection Capabilities "
 Second capability should be called cargo security instead
 of physical protection
 JUNES:R J Materials Protect Standards Branch 77/03/04
 EVANS,L S Requirements Analysis Branch ip 16369 131

- --8212080107 Comments on narrative of fifth basic capability per 770302 memo Sections redundant & contain misplaced subfunction statements JONES.R J
 - Materials Protect Standards Branch 77/03/04 Requirements Analysis Branch EVANS, L J 9pp 16349 132
- --B2120B0iii Forwards revised list identifying basic elements essential for safeguards sys to be effective against design basis threat
 - Materials Protect Standards Branch 77/03/08 Requirements Analysis Branch 4pp 16369 141 EVANS, L J
- --8212080116 Forwards draft "Basic Capabilities for Transportation & Narrative for Basic Capabilitie 4," for comment Comments should relate to whether capabilities would provide coverage of all assential functions

 EVANS.L.J. Requirements Analysis Branch 77/02/24 CHAMBERS.O.
 Office of Inspection & Enforcement. Office of the Director JONES.R. MICHAELB.T. Office of Standards Development, Director 23ns 16348 148 16369 145
- --8212080126 Discusses basic capabilities for transportation protection of SNM Basic capabilities needed to assure effective response to attempt to steal matl & assure against sabatage JONES.R J Materials Protect Standards Branch 77/02/24 EVANS.L Requirements Analysis Branch 2pp 16369 168
- --B2120B0133 Requests comments on encl draft "Basic Capabilities for Transportation Fransportation "
 EVANS.L J Requirements Analysis Branch 77/02/16 CHAMBERS.O Office of Inspection & Enforcement. Office of the Director JONES.R., MICHEALS.T Office of Standards Development. Director 16369 170
- -8212080137 Comments on 770210 memp to upgrade working group entitled "Status Rept Upgrade Rule Activity " ELLIGIT, J M Program Support Branch 77/02/16 EVANS,L J Requirements Analysis Branch 2pp 16369 179
- --8212080139 Supplemental PNS-11-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sys found not to exceed limits for unrestricted use CORYELL.O P., TOBIN.W.J. Region 2. Office of Director 79/09/25 ig 16370 154
- --0212080142 Recommends editorial changes for basic capability racrostratives

 ERICKSEN, B NRC - No Detailed Affiliation Given 77/02/17

 EVANS. B NRC - No Detailed Affiliation Given 1p 16369
- --8212080146 Comments on draft capability narratives & min essential requirements Basic capability narratives appear complete if coverage assumed in two basic capabilities not presented JONES.R J Materials Protect Standards Branch 7: EVANS.L Division of Safeguards 20pp 16369 182
- -8212080149 Supplemental PNS-II-79-102K on 791102.initial reinventory efforts resulted in partial reconcilitation of 790917 difference Unresolved inventory difference in escess of regulatory limits for continued operation remains LEE, T D . Office PFF. Pregion 2. Atlanta. Office of the Director 79/11/02 ip 16370 155
- --B2(2080)61 Forwards status of upgrade rule activity Work proceeding to develop alternative approaches to implementing upgrade Examples of drafts useful for developing third option re examples or orares vastol for developing white option re performance requirements enc)

 EVANS, L J Requirements analysis Branch 77/02/10 CHAMBERS, D Office of Inspection & Enforcement, Office of the Director JONES, R, MICHAELS, T Office of Standards Davelopment, Director Office . JONES.R. MICHAEL 14-1. 16369 202.
- --B212080167 Requests commants on safeguards upgrade rule structure & first performance capability narrative drafts by 770201 EVANB.L J Requirements Analysis Branch 77/01/26 JUNES.R. MICHAELS:T Office of Standards Development. Director FONNER.R Diffice of the Executive Legal Director 13pp 16369 237
- 621209004B Responds to FOIA request for SECYs Forwards SECY-82-23, BECY-82-42, SECY-82-136, SECY-82-137, BECY-82-286 & SECY-82-315, SECY-81-600A available in FDR Review of SECY-81-622A, SECY-82-177A & SECY-82-197B continuing FELTON, J M Division of Rules and Records 82/10/20 GRABER, i Affiliation Unknown Ip. 16384.295
- --- 8202010383 SECY-82-023 Requests Commission approval of denial of petition that licensee be held responsible for emergency planning & response to transportation on accidents involving addoctive math. Draft FR notices, groposed rule & ltrs and DRGKE, M J Office of the Executive Director for Operations 82/01/18, E8pp 16384-301

- ~~8203090677 SECV-82~042 Requests approval of proposed amend to existing Section 274b agreement w/State of TX Proposed Agreement proposed FR agreement uproposed or in rroppsed agreement proposed re notice, staff analysis of comments, proposed press release & proposed ltr to governor encl DIRCKS, M J Office of the Executive Director for Operations 82/02/01 30pp 16385 029
- --8204160262 SECY-82-137 controles Sect-Be-13/
 Recommends that Commission approve AO recommendation re major deficiencies in mgt controls at nuclear power plant Draft FR notice encl
 Draft FR notice encl
 DRACKS_W J Office of the Executive Director for Operations
 82/03/30 9pp 16385 080
- --8204160270 SECY-82-136 2041002/0 55CY-82-136 Seeks Commission approval of AO determination re blockage of coolant flow to safety-related sys & components Draft FR notice encl DIRCKS W J Office of the Executive Director for Operations 82/03/30 19pp 16385 060
- --8209280513 SECY-82-315 Nequests Commission approve publication of for comment NUREO-0906, "Quidance for Implementation of IOCFR50 J4(g) " Section requires applicants to evaluate differences from DIRCKS, W J Office of the Executive Director for Operations 82/07/26 16pp 16385 166
- --8212090052 Advises that Commission has approved 820429 request to withdraw SECY-82-23 pending resolution of NY City/NY State lawsuit against DDT on highway routing & proposed rider on DDT FY82 authorization bill being considered in Congress CHILKS J Office of the Secretary of the Commission 82/05/2/DIRCKS, W J Office of the Executive Director for Operations in 12/03/20 16384 296
- --8212070065 Advises that Commission has approved proposed amend to existing Section 2746 Agreement w/TX Ofc of State Programs informed of action by telephone on 820226 Agreement should be forwarded for signiture of Chairman Palladino by 820312 CHILK:8 J Office of the Secretary of the Commission 582-042 82/02/26 DIRKKS, W J Office of the Executive Director for Operations Ip 16385 028
- --8212090209 Advises that Commission has approved proposed AB recommendation re blockage of coolant flow to safety-related sys & component & FR notice FR notice should be forwarded to Ofc of Secretary for publication by 820511
 CHILKS J Office of the Secretary of the Commission 82/04/27
 DIRCKS W J Office of the Executive Director for Operations 1;
- --8212090210 Advises that Commission has approved modified proposed AU recommendation re major deficiencies in mgt FR notice should be prepared & forwarded for publication CHILKS J Office of the Secretary of the Commission 82/06/03 DIRCKS,W J Office of the Executive Director for Operations in 16385 079
- ~~8212090224 SECY-82-28A ergovered stat Commission approve publication of proposed rulemaking re staffing at nuclear power plants DIRCKS.W J Office of the Executive Director for Operations 82/07/02 72pg 16385 093
- --B212070230 Advises that Commission has approved recommendation that NUREO-0706. "Guidance for Implementation of 10CFR50 34(g)." be published for comment in FR & sent to appropriate Congressional committees, reactor licensees & applicants CMILK, S J Office of the Secretary of the Commission B2/08/24 DIRCKS, W J Office of the Executive Director for Operations 19 16385 165
- B212100049 F0IA request for listing of existing major contracts.
 excluding grants & small procurements or purchase orders
 administered by NRC Listing should include autilined info
 CHAMBLEC.J A Affiliation Unknown B2/11/07 Division of
 and Records ip 16400 214 Division of Rules
- 8212100051 Responds to FOIA request for listing of existing major contracts excluding grants & small procurements or purchase orders administered by NRC Forwards computer listing dtd 82112 Document also available in PDR. FELTON, JM Drytsion of Rules and Records 82/11/18 CHAMBLEE, J A Affiliation Unknown in 16400 215
- ---B212100055 Sequential listing of existing major contracts excluding grants & small procurements or purchase orders administered by NRC NRC No Detailed Affiliation Given B2/11/12 9App 16400 216

- 8212100053 Responds to FOIA request for eight listed documents Forwards documents listed in app Items 5.6 & 8 available in
- FELTON, J M Division of Rules and Records 82/11/09 CONNOR, L Doc-Bearch Associates 2pp 16388 228
- --BOOL110507 Task Action Plan A-43 "Containment Emergency Sump Division of Reactor Safety Research 79/09/17 1300
- --8001230275 Task action plan A-44 "Station Blackout"
 * TMI-2 Unresolved Safety Issues Task Force 80/0 80/01/31 7pp
- ~~B102200777 Forwards approved Task Action Plan A-43. "Containment Emergency Sump Performance " Completion date scheduled for Sept 1983
 - Sept 1983 SHAO.L Division of Reactor Safety Research 81/01/16 DENTON, H R Office of Nuclear Reactor Regulation, Director
- --8102200784 Task Action Plan A-43 "Containment Emergency Sump Performance"
 - * Division of Reactor Safety Research 81/01/16 13pp 163B8 232
- --8204070020 Forwards task action plan for Unresolved Safety Issue (U51)
 A-47. "Safety Implications of Control Sys" for concurrence
 prior to final approval Projected completion date for draft
 NUREQ for public comment is Jan 1984
 HARMAUER, S.H. Division of Safety Technology 82/05/19
 EISENHUT, D.O. Division of Licensing 29pp 16989 010
- --B206070028 Forwards task action plan for Unresolved Safety Issue (USI)
 A-47. "Safety Implications of Control Sys", for concurrence
 prior to final approval Projected completion date for draft
 NUREO for public comment is Jan 1984
 HANAUER.8 H Division of Systems Integration (post 811005)
 82/05/149 GOLLER.K R Division of Facility Operations 25pp
 16387 012
- --8205220070 Advises that encl Revision 1 to Task Action Plan A-45, "Shutdown Decay Heat Removal Requirements," reviewed & approved by Div of Safety Technology Draff NUREG w/proposed recommendations can be available by Nov 1984 HANAUER, S.H. Division of Safety Technology 82/06/02 DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director 2
- --B206220072 Revision 1 to Task Action Plan A-45, "Shutdown Decay Heat Removal Requirements " MARCHESE, A R Generic Issues Branch 82/06/02 49pp 16388 286
- --8207120252 Forwards approved task action plan for Unresolved Safety Issue A-46 to develop guidelines & acceptance criteria for seismic & dynamic qualifications of mechanical & electrical eautoment equipment KANAUER, S. H. Division of Safety Technology 82/05/19 BENTON, H. R. Office of Nuclear Reactor Regulation, Director . 3pp 16387 017
- --8212100179 Task Action Plan A-46 "Seismic Qualification of Equipment in Operating Plants "
 * Division of Safety Technology 82/05/19 13pp 16389 039
- G: 12100084 Responds to FOIA request for documents & records prepared by Energy. Inc. re NRC rulamaking on ATMS Forwards documents listed in App A FELITON V M Division of Rules and Records 82/11/01 EARLEY, A F Hunton & Williams 2րթ 16400 012
- --8212100086 Draft "Preliminary Evaluation of Comments of Util Group on ATNS Energy Incorporated 82/09/03 ven 63pp 16400 014 NRC - No Detailed Affiliation
- --B212100087 "Evaluation of Comments of Util Group on ATW8 "
 # Energy Incorporated 62/10/31 NRC No Detailed Affiliation
 Given 63pp 16400 083
- 82:2100:11 Responds to FOIA request for seven categories of info re NFS. Erwin, TN Forwards documents listed in App A Documents listed in App A Documents listed in App A Documents listed in App B withheld (ref FOIA Exemptions 3 & 5) FELTON, J M Division of Rules and Records 82/11/12 WEISS, E R Harmon & Weiss 4pp 16388 157
- --8212100121 Forwards addl comments on proposed license conditions for NFS-Erwin re emergency preparedness QRIMES.B K Division of Emergency Preparedness 82/03/23 PAGE.R G Uranium Fuel Licensing Branch 1p 16388 164

- --B21210012B Act receipt of 820225 concerns re timeliness of alerting & of 1210012B Ack receipt of B2022D concerns re timeliness of a motifying mearby residents in event of certain type of emergency at NFS, Inc Emergency planning license conditions for NFS discussed TROJANDESKI, R Region 2, Office of Director 82/03/12 GRAHAM, J A Tennessea, State of 2pp 16388 165
- ~~821210013B Concurs w/final amend to 10CFR70 & 73, "Strengthened Physical Protection Requirements for Fuel Cycle Facilities & Transportation Involving Formula Quantities of Strategic SNM "Executive Branch comments to be forwarded SNEA, J R Office of International Programs, Director 79/01/2 GDLLER.K K Division of Siting, Health & Safeguards Standards ip 1638B 167
- --8212100142 Responds to G McCorkle 780117 comments re upgrade rule re transport protection requirements Unarmored vehicle escort, tactical needs & transportation points discussed NULSEN B Requirements Analysis Branch 78/01/27 EVANS, L J Requirements Analysis Branch 2pp 16388 168
- --8212100147 Comments on Sandia rept per Nulsen 780117 memo re upgrade rule re transport protection requirements Rept does not consider possible actions by insider in collusion w/adversary force MCCORKLE.O W Physical Security Licensing Branch 78/01/23 EVANS.L J Requirements Analysis Branch ip 16388 170
- -8212100155 Submits recommendation to change physical protection upgrade rule requirements to nine armed guards & two armored vehicle excorts for in-transit physical protection NULSEN.C K NRC No Detailed Affiliation Given 78/01/17 EVANS.L J Requirements Analysis Branch 3pp 16388 171
- -8212100158 "Convoy Security Upgrades "
 * Sandia Laboratories 78/01/17
 Oiven 11pp 16388.174 NRC - No Detailed Affiliation
- -B212100164 Forwards response to request for development of regulatory changes to safeguards upgrade rule to provide protection against internal threats Requirements developed in response to 8 Chilk 780426 memo re 780420 briefing to Commission JQNES:R J Materials Protect Standards Branch 78/05/05 MCCORKLE,Q Physical Security Licensing Branch App 14388 185
- --8212100168 Discusses incorporation of NRC comments into upgrade rulu guidance documents Outline for allocation of outstanding tasks encl EVANS.L J Requirements Analysis Branch 79/01/10 JGNES.R J Safeguards Standards Branch 2pp 16388 191
- --82121001B5 Forwards draft cover memo for final version of major issues b NRC positions re-physical protection Draft issues for policy decision encl
 EVANSIL J. Requirements Analysis Branch 77/12/20 108/20 7 EVANS.L J Requirements Analysis Branch 77/12/29 Katerials Protect Standards Branch 12pp 16388 194
- --8212100189 Forwards preliminary recommended upgrade rule changes & considerations for inclusion in paper to Commission EVANS.L J Requirements Analysis Branch 78/01/11 JONES.R Naterials Protect Standards Branch 20pp 16388 206
- --8212100138 Concurs w/final amend to 10CFR70 & 73. "Strengthened 212100138 Concurs w/final amend to 100FR70 & /s. "Strengthened Physical Protection Requirements for Fuel Cycle Facilities & Transportation Involving Formula Quantities of Strategic SNM "Executive Branch comments to be forwarded SMEA.JR Office of International Programs. Director 79/01/25 GOLLER K K Division of Siting, Health & Safeguards Standards
- 16388 167 --8212100142 Responds to 0 McCorkle 780117 comments re upgrade rule re
- transport protection requirements Unarmored vehicle escort, tactical needs & transportation points discussed NVLSEN. B Requirements Analysis Branch 78/01/27, EVANS, 78/Q1/27, EVANS, L J Requirements Analysis Branch 2pp 16388 168
- --8212100147 Comments on Sandia rept per Nulson 780117 memo re upqrade rule re transport protection requirements Rept does not consider possible actions by insider in collusion w/adversary force MCCORKLE-0 W Physical Security Licensing Branch 78/01/23 MCCORKLE. G. W. Physical Security Licensing Dranch EVANS: L. J. Requirements Analysis Branch ip 18 16388 170
- --8212100155 Submits recommendation to change physical protection upgrade rule requirements to nine armed guards & two armored vehicle escorts for in-transit physical protection NULSEN.C K. NRC No Detailed Affiliation Given 78/01/17 EVANS.L J. Requirements Analysis Branch 3pp 16388 171
- --8212100158 "Convoy Security Upgrades "
 * Sandia Laboratories 78/01/17 NRC No Detailed Affiliation
 Given 11pp. 16388.174

- --8212100164 Forwards response to request for development of regulatory changes to sefaguards upgrade rule to provide protection against internal threats Requirements developed in response to 5 Chilk 780426 memo re 780420 briefing to Commission JONES, R. J. Materials Protect Standards Branch 78/05/05 MCCORKLE.G Physical Security Licensing Branch 6pp 16388 195
- --8212100168 Discusses incorporation of NRC comments into upgrade rule guidance documents Outline for allocation of outstanding tasts encl
 EVANS.L J Requirements Analysis Branch 79/01/10 JONES.R J
 Safeguards Standards Branch 2pp 16088 191
- ---8.212100185 Forwards dreft cover memo for final version of major issues & NRC positions re physical protection Draft issues for policy decision enc! EVANS.L J. Requirements Analysis Branch 77/12/29 JONES,R Materials Protect Standards Branch 12pp 16388 194
- --8212100189 Forwards preliminary recommended upgrade rule changes & considerations for inclusion in paper to Commission EVANS.L J. Requirements Analysis Branch 78/01/11 JUNES.R Makerials Protect Stendards Branch 20pp 16388 206
- B21210035B FQIA request for listing of total quantities of microcomputers & word processing equipment either rented or purchased in FY82 GROSS:NE Verox Corp B2/10/25 Division of Rules and Records Ip. 16400 350
- 8212100362 Responds to FOIA request for listing of total quantities of microcomputers & word processing equipment either rented or jurchased in FY82 Listing encl FELTON.J M Division of Rules and Records 82/11/18 GROSS.M E Xeroz Corp ip 16400 351
- --8212100369 "FYB2 Equipment Acquisitions Word Processors & Microcomputers"
 * NRC No Detailed Affiliation Given 82/11/18 1p 16400 352
- 82:2100371 FOIA request for documents re fuel & shipment of fuel to Savannah River in State of 80 LOHENTHAL,N Sierra Club 82/10/27 Division of Rules and Records Ip 16400 348
- 8212100374 Responds to FOIA request for documents re fuel & shipment of fuel to Savannah River in State of SC Documents not located Info may be available from DOE FELTON, J M Division of Rules and Records 82/11/16 LOWENTHAL, N Sierra Club Ip 16400 349
- 8212100378 FOIA request for identity of plants for which ASLB has assigned MR Miller, KA McCollom & RF Cole & listing of FOIA requests released on maned individuals LODGE. B Dallas Morning News 82/10/18 Office of Public Affairs ip 16400 331
- 82121003B1 Responds to FOIA request for identity of plants for which ASLB has assigned ME Miller,KA McCollom & RF Cole & listing of FOIA requests released on named individuals Forwards requested info FELTON, J M Division of Rules and Records 82/11/16 LCDGE.W Dailas Morning News Ip 16400 332
- --8212100383 Listing of glants on which ME Miller, KA McCollom & RF Columbave served

 NRC No Detailed Affiliation Given 82/11/16 3pp
 16400 333
- 82:2100387 Responds to FOIA requests for seven categories of documents re facility Document 1 listed in app withheld (ref Exemption 3) Forwards Document 2 & portions of Document 1 Documents available in PDR. FELTON. JM Division of Rules and Records 82/11/15 WEISS.E R Harmon & Weiss Spp 16400 312
- 82:2100395 Responds to FOIA request for documents re implementation of employee protection provisions in Section 210 of Energy Reorganization Act of 1974 Memorrandum of understanding between NRC & Papt of Labor encl FELTON, J M Division of Rules and Records 82/11/15 MARCOUX, W C LeBoeuf, Lamb. Leiby & MacRae Ip 16400 325
- --B212100398 Hemorandum of understanding between NRC & Dept of Labor reimplementation of employer protection provisions in Section 210 of Energy Reorganization Act of 1974
 DIRCKE,N J Office of the Executive Director for Operations
 OTTER.W H Labor, Dept of 82/10/25 4pp 16400 326

- 8212100404 FDIA request for SECY-77-539 to conversion of provisional DLs to full-term licenses GRABER.L Affiliation Unknown 82/11/0! Division of Rules and Records ip 16400-323
- 8212100408 Responds to FOIA request for SECY-77-539 re conversion of provisional OLs to full-term licenses Document available in PDR FELTON.J M Division of Rules and Records 82/11/15 GRABER.L Affiliation Unknown ip 16400 324
- 83|2100412 Responds to FDIA request for two documents referenced in SECY-82-111. Page 24 Forwards documents listed in App A Documents available in PDR FELTON.JM Division of Rules and Records 82/11/15 GRABER.L Affiliation Unknown 2pp 18400 354
- --B103120528 Expresses concern w/SECY-81-19 re emergency response facilities Issuance of paper indicative of increasingly confusing structure of NRC legal requirements Features that implement current regulation should be issued in reg guide MALSCH.M O Office of the General Counsel 81/01/30 ANEARNL.J Commissioners 3pp 14400 360
- ~Bj033j025i Natifies that NRC should proceed w/issuance of NUREQ-0/3/.
 Item III A 1 2,re emergency operations facility Commission
 does not have preference for either Option 2 or Option 4
 referenced in NRC BOILD response to BOILO3O meeting
 CHILK.S J Office of the Secretary of the Commission
 CCMJA-BO-37 SI/O//21 DIRCKS.W J Office of the Executive
 Director for Operations 3pp 16400 396
- --Bi04100175 Advises of Commission approval of proposed NUREC-0696 tubj to mods revisions to reflect decisions in Bi0121 memo, more explicit seismic qualification discussion indication that NUREC provides general guidance only CHILK.8 J Office of the Secretary of the Commission Bi/07/19 DIRCKS.W J Office of the Executive Director for Operations Ip 14400 399
- 8212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON. J M Division of Rules and Records 82/11/03 GALLO. J Isham. Lincoln & Beals 2pp 16433 354 24% Fiche 50-000.82/11/03,8212140001
- --8005070778 Forwards input to SEP Topics III-6 & III-11, consisting of NUREO/CR-0891, "Saismic Review for SEP" & EQG-EA-50.5, "Summary of Piping Calculations Performed for SEP" Repts should be transmitted to licensee NUREO only encl CRUTCHFIELD, D Systematic Evaluation Program Branch BO/04/14 ZIEMANND L Systematic Evaluation Program Branch 2pp 14435 183 24X Fiche 50-000, 82/11/03,8212140001
- --B009050320 Submits proposal for seismic review of selected plants for SEP Provides detailed breakdown of \$810,000 cost estimate Lab personnel & facilities available per DOE Contract U-7405-ENG-4R w/Univ of CA SHEPARD.J C Lawrence Livermore Laboratory FIN A-0233-9 88/08/22 D&NTON.H R Office of Nuclear Reactor Regulation, Director 6pp 16435 072
- --8009180414 Discusses 800604 presentations before ACRS Subcommittee on Extreme External Phenomena re status of SEP site spectra project & initial recommendations CRUTCHFIELD, D. Systematic Evaluation Program Branch 80/06/06 LAINAB, O.C. Plant Systems Branch (Pre 791030) 1p 16436 299
- --Bi010B011B Trip rept of B01117-19 site visit to observe site-specific features re BEP structural, glectrical & sys topic review Related info encl
 MICHAELS, T & Technical Support Branch B0/12/17 RUSSELL, M f
 Technical Support Branch 171pp 16436 120 24X
 Fichs 50-000, B2/11/03. B212140001
- --Bi04230080 Advises that structural elements & review areas noted need not be considered part of NRC-03-79-18 Section 3 B of SRP defines structures to be considered PERSINKO, D Systematic Evaluation Program Branch NRC-03-79-11B 81/04/14 STILMELL Franklin Institute/Franklin Research Center 2pp 16434 274.
- --8105110512 Forwards two consultant repts & list of open items to BEP Topics III-6 re seismic design consideration & III-11 re component integrity W/o consultant repts CRUTCHFIELD, D. Openating Reactors Branch 5 t.805-81-03-048 81/03/20 FINFROCK, I. R Public Service Electric & Gas Co of New Jersey 3pp 16434 261 24X Fiche 50-000,82/11/03,8212140001.

- ---B109210340 Discusses factors impinging on finalization of site-specific spectra program Results of second questionnaire: reduction of spectra at rock sites & Vol 1 inexecutive summary needed from Ltl. & TERA before start of final review JACKBON, R & Geosciences Branch BI/OZ/O3 KNIGHT, J P Assistant Director for Components & Structures Engineering 2pp 4447 201
- --B109230665 Requests audit review of Geosciences Branch seismic reanalysis program for finalization of site-specific spectra by Feb 1981 LAINAS.G C Assistant Director for Safety Assessment B1/01/28 KNIOHT.J P Assistant Director for Components & Structures Engineering 1p 16436 278
- --8201180567 Forwards Mechanical Engineering Branch review of SEP Topic III-5 B, "High Energy Line Break Outside Containment " High energy line break analysis of auxiliary feedwater sys to be included in licenser repanse to NURFO-0737 Item II E I KNIGHT, J P Assistant Director for Components & Structures Engineering IEB-79-14 B1/12/24 LAINAS, 0 C Assistant Director for Safety Assessment 10pp 16436 067. 24X Fiche 50-000,82/11/03,8212140001
- --B202180460 Forwards Revision 1 to evaluation rept on SEP Topic V1-4, "Containment Isolation Sys." for Facility Rept considers util comments received in 810810 & 820104 ltrs Conclusions of original rept remain unchanged SPETB-TP Assistant Director for Reactor Safety B2/01/27 LAINAS, G Assistant Director for Safety Assessment 43pp 14426 078 24% Fiche 50-000, 82/11/03, 8212140001
- --8203010313 Monthly Mgt Ltr 7.Jan 1982 re systematic evaluation program NELSON,T A , SMITH.P D Lawrence Livermore Laboratory FIN A-0436 SM-82-31 82/02/12 EISENHUT,D Q Division of Licensing Spp 16434 312
- --8204010021 Forwards evaluation for SEP Topic VI-4, "Containment Isolation Sys " Outstanding items include insufficient isolation provisions in test, vent & drain lines & no isolation or leak detection provisions on ECCS subsystem SPEIS.77 Assistant Director for Reactor Safety B2/03/24 LAINAS.0 Assistant Director for Safety Assessment 34pp 16434 329 24X Fiche 50-000, 82/11/03,8212140001
- --B205040451 "BEP," Monthly Mgt Ltr 9 for Mar 1982
 NELGON,T A , BHITH,P D Lawrence Livermore Laboratory FIN
 A-0436 SM 82-112/0298M 82/04/28 EISENHUT,D Division of
 Licensing 4pp 16434 291
- --8205240413 "Revisw of Seismic-Related Topics of Selected Operating Plants for SEP," Monthly Mgt Ltr 10 for Apr 1982 LO.T Y, SMITH.P D Lawrence Livernore Laboratory FIN A-0436 BM 92-135/0298M 82/05/17 E19ENHUT.D G Division of Licensing
- ---9205270590 Forwards std order for DOE work, "Review of Seismic-Related Topics of Selected Operating Plants for SEP," w/revised statement of work.reflecting mods suggested in DOE 820322 itr
 EISENHUT.D 0 Division of Licensing FIN A-0436 82/04/26 LAORDNE.J 8 Energy, Dept of Spn 16434 281
- --8206290144 "SEP," Monthly Mgt Ltr II for May 1982 LO.T Y. SMITH,F D Lawrence Livermore Laboratory FIN A-0436 SM 82-168/0298M 82/06/17 EISENHUT,D O Division of Licensing 400 16434 317
- --B2072B0369 Lists recommendations re guidelines for seismic evaluation criteria for BEP Group II plants
 BOSMAK,R J Mechanical Engineering Branch 82/07/15
 GRUTCHFIELD,D Operating Reactors Branch 5 1p 16434 299
- --B208030436 "Technical Assistance for SEP," Monthly Mgt Ltr 12 for June 1982. LO.T Y., SMITH,P D. Lawrence Livermore Laboratory, FIN A-0436 SM 82-200/0298M 82/07/23 EISENHUT,D G. Division of Licensing 4pp 16434.308
- --8212140015 Computer printout listing SEP documents * Planning Research Corp 82/09/02 210pp 16433:358
- --8212140022 Computer printout listing documents re SEP Topic III-6 * Planning Research Corp 82/09/01 32pp 16434 208
- --8212140161 Requests participation in review of probability & statistics aspects of listed consultant repts on selamic hazard analysis
 EISENHUT, D. Q. Division of Operating Reactors 79/10/17
 HALLER, N. M. Office of Management and Program Analysis. ROMBOME, F. Probabilistic Analysis Branch (Pre 771030) 2pp 16436-304.

- 8212140080 Addl response to FOIA request for records re receipt, processing, storage or removal of source matl at Canonsburg. PA, Vitro Nfg Co & Vitro Rare Metals Co Forwards documents listed in App A Remaining info under review FELTCN, J M Division of Rules and Records B2/09/30 BLACK, A E Buchaman, Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 312
- --8212160090 Forwards 610512 & 29 & 630715 ltrs from Vitro Corp of America to AEC & 610526 & 630814 ltrs from AEC to Vitro Ltrs re Vitro recent license amend will be forwarded to PA State Health Dept W/o encls NUSSBAUMER, D A Atomic Energy Commission 35252 63/11/08 DERNIS, J M Affiliation Unknown lp 16448 246
- ---B212160074 Draft "Radiological Survey Plan-Vitro Corp of America Canonsburg, PA." Phase I * Vitro Englineering Co 82/07/30 5pp 14447 323
- --8212160103 PND-77-008 draft press release re radiation detected near premises of former AEC contractor/licensee in Canonsburg.PA forwarded Site will be surveyed by ERDA.starting 770112 W/o encl Related info encl SMITH.0 H. ROY.0 W. THOMPSON.D Director's Office. Office of Inspection and Enforcement 77/01/11 22pp 16447 328
- ---8212160160 Advises that ID Analysis Branch has been contacted & has agreed to analyse samples for U.Th-230 & Ra-226 Samples W/16entifying descriptions or number should be forwarded to CW 9111
 RUEDER. J Atomic Energy Commission TT 218 43/10/15
 KURKMAN:R W Atomic Energy Commission IP 16448 273
- --8212160323 Application for source mati license for possession of 4,374 572 tons of Port Hope residues containing 32,193 lbs of U-308 stockpiled at Canonaburg PA GENTILE, A B Vitro Engineering Co 60/02/10 ip 16448 064
- --B212160343 Forwards License R-129 & licensee 560808 ltr to Div of Licensing & Regulation, per 630314 telcon RDEDER, J R Atomic Energy Commission 63/03/14 JOHNSTON, W D Atomic Energy Commission 1p 16448 318
- --8212160970 Confirms 650615 telton re burial of U bearing residues at facility Removal of U residues not begun but state has given permission Effort may not be completed until Sept.1945
 BROCKETT.T U Atomic Energy Commission 45/06/15 KIRKMAN.R W., WALKER.D I., SMITH.R W Atomic Energy Commission Up 16488 073
- ---B212160372 Source Matl License RI-177 for Vitro Corp of America, authorizing use of 45,000 lbs containing residues through import from Canada JS:NSON,L Atomic Energy Commission 56/04/27 ip 16448 321
- --8212160380 Application for source matl license to import 22-1/2 tons milling bygraduct residual matl from Canada Moisture gross weight is 50% Matl contains 0 5% U-308
 LITTEL.E G Vitro Engineering Co 56/04/24 Atomic Energy Commission 2pp 16448 322
- --8212160386 Source Matl License RI-168 for Vitro Corp of America, authorizing use of 100,000 lbs of U containing residues through impart from Canada JOHNSON,L Atomic Energy Commission 55/11/15 lp 16448 324
- --B212160388 Discusses burial of U bearing residues at Canonsburg, PA by Vitro Corp of America Btate must issue permit Region 1 will make closeout check survey DUBINKKI, L Akonic Energy Commission 65/03/10 KIRKHAN, R W . WALKER. D I , EMITH, R W Atomic Energy Commission 1p 16448 078
- ~~B212160391 Application for source matl license to import one carload milling byproduct residue matl from Canada Wet matl has max weight of 100,000 lbs
 LITTEL,E 0 Vitro Engineering Co 55/11/14 JOHNSON, L Atomic Energy Commission Zpp 16448 325
- --B212160477 Discusses capabilities of lonics. Inc to perform analytical analyses Tailing results varied by factors up to 470 times higher than analyses performed on duplicate samples analyted ROEDER, J.R. Atomic Energy Commission 64/02/12 DUBINSKI, L. Atomic Energy Commission ip 16448:166
- --8212160493 Informs that insp of Licenses C-4269, C-4625 & R-179 was scheduled before learning facility was closed down Radioactive matt in rear yard Arrangements for insp can be scheduled through CD Brannan EPSTEIN.E Atomic Energy Commission 61/02/09 KLEVIN.P B Atomic Energy Commission 200 16449 005

- --8212160500 Submits info re disposal of source math under Licenses R-179,C-4269 & C-4625 Thorium oxide covered under License C-4269 transferred to Atlantic Research Corp in Alexandria, VA ROBBINS, E B Vitro Engineering Co 61/01/30 EPSTEIN, E Atomic Energy Conmission 3pp 16449 007
- --82(2160541 Application for source mat) license to receive 300 lbs thorium-bearing residues containing 13 lbs thorium from Natl Lead Co Matl consists of six types to be used for lab tests LITELE 6 Vitro Engineering Co 57/09/03 DOULDS,N Atomic Energy Commission ip 16449 016
- ~~B2(2160592 Advises that repts re disposition of source mat1 under Licenses R-179,C-4269 & C-4625 will be made to RC Cole,who had cognizance of plants while mat1 received under Commission licenses LITFEL,E O visto Engineering Co 61/01/19 EPSTEIN.E Atomic Energy Commission ip 16449 021
- 8212230142 Addit response to FOIA request for documents re Stepan Chemical Co in Maywood NJ Forwards draft "Backup for AEC-572" Info partially withheld (ref FOIA Exemption 6) FELTON, JM Division of Rules and Records 82/11/10 VAN DYKEN, G Affiliation Unknown 1p 16540 341
- ~~8212230150 Draft "Bactup for AEC-592" Info partially withheld (ref FOIA Exemption 6) SHOPENIAN M Atomic Energy Commission 67/11/06 11pp 14540 342
- GP12230159 FOIA request for SECY-S2-322, "Review of Director's Decision on 2 206 Patstion (PSC of NH)" & S Chilk 820816 memo to L Bickwit FICKETIK Energy Research Group, Inc. 82/10/13 Office of the Secretary of the Commission 1p 16540 313
- 8212230166 Responds to FOIA request for SECY-82-322. "Review of Director's Decision 2 206 Petition (PSC of NH)" & S Chilk memo to L Bickuit Forwards requested documents FELTON.J H Division of Rules and Records 82/11/04 OCLDSHITH.M W Energy Research Group, Inc. 1p 14540 314
- --8209010092 SECY-82-322
 Recommends that Commission not review 820706 Director's decision denying Spaceast Anti-Pollution League 820205 request for order to show cause why CP should not be suspended or revoked due to lack of financial qualification MALSCH, M G Office of the General Counsel 82/07/30 4pp 16540 315
- --8212230174 Advises that NRC has unanimously decided that no review of Director's Decision 2 206 petition (PSC of NH) needed Ofc of General Counsel notified on 820816 CHILK, S.J. Office of the Secretary of the Commission 82/08/16 BICKWIT.L. Office of the General Counsel 1p 16540 340
- 6212270023 Responds to FOIA request for SECY-82-255 Forwards document Document also available in PDR FELTON.J M Division of Rules and Records 82/11/23 ORABER.L Affiliation Unknown ip 14553 332
- B2/2270034 FOIA request for documents re FOIA Request 82-308 SEPAR.S Hunton & Williams 82/11/16 Division of Rules and Records 3pp 16553 161
- BP12270036 Responds to FOIA request for documents re FDIA Request B2-308 Documents available in PDR FELTON.J M Division of Rules and Records 82/11/23 SEPAR.8 Hunton & Williams ip 16953 164
- 82:2270045 FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svcs," awarded to Alderson Reporting Co. Inc. Response requested within IO days CALLO, J. Isham, Lincoln & Beale Fix B-1311 NRC-17-80-448-0 62/11/02 FELTON, J. Division of Rules and Records 2pp 16566-044
- 8212270048 Responds to FDIA request for documents re extensions issued in No. & Dec 1981 & proposed extensions to "Stenographic Reporting Socs," awarded to Alderson Reporting Co. Inc Forwards documents listed in App A FELTON. J. H. Division of Rules and Records FIN B-1311 NRC-17-80-448-0 82/11/19 OALLO. J. Isham. Lincoln & Beale Supplicated O46
- --8212270052 Request for procurement action BO-SEC-448, erecuting Mod B to "Stenographic Reporting Svcs " Mod obligates addl funds CHILK.B J Office of the Secretary of the Commission FIN B-1311 NRC-17-80-448-0 82/01/18 2pp 16566 049

- --8212270055 Forwards unexecuted Mod 8 to "Stenographic Reporting Sycs," extending period of performance to 820318 & obligating add1 funds Approval requested LEBO, C D Administrative Contracts Branch FIN 8-1311 NRC-17-80-448-0 82/02/01 SHARP, R A Alderson Reporting 259 16566 051
- --8212270059 Forwards Mod 8 to "Stenographic Reporting Svcs," estending period of performance to 820318 & obligating additional funds LEBO.C D Division of Contracts FIN 8-1311 NRC-17-80-448-0 82/02/08 SHARP.R A Alderson Reporting 1p 16566 053
- --B212270065 Mod B. extending period of performance to 820318 & increasing funds obligated to "Stenographic Reporting Svcs " Findings & determination encl SHARP, A Alderson Reporting LEBO,C D Division of Contracts FIN 8-1311 NRC-17-80-448-0 82/02/02 2pp 16566 054
- --8212270080 Notification of contract execution Mod 8 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co. Inc PAGE. M Administrative Contracts Branch FIN 8-1311 NRC-17-80-448-0 82/02/02 CHILK, S J , SULLIVAN.P Office of the Secretary of the Commission MCNAMARA. A Atomic Safety and Licensing Board Fanel 1p 16566 056
- --B212270084 Request for procurement action 80-BEC-448, executing Mod 9 to "Stenographic Reporting Svcs " Mod extends period of performance to 820501 & obligates add1 funds HOYLE.J C Office of the Secretary of the Commission FIN 8-1311 NRC-17-80-448-0 82/02/23 2pp 16566 057
- --8212270088 Forwards unexecuted Mod 9, extending period of performance to 820501 % obligating add1 funds to "Stenographic Reporting Sycs "Approval requested LEBO, C D Division of Contracts FIN 8-1311 NRC-17-80-448-0 82/03/05 SHARP,R A Alderson Reporting 2pp 16566 059
- --B212270091 Forwards Mod 9.extending period of performance to 820501 b obligating add1 funds to "Stenographic Reporting Svcs " contractor Alderson Reporting Co. Inc LEBO. C D Division of Contracts FIN B-1311 NRC-17-80-448-0 82/03/15 SHARP,R A Alderson Reporting Ip 16566-063
- --B212270095 Request for procurement action 80-8EC-44B, executing Mod 10 to "Stenographic Reporting Sycs" Mod extends period of performance to 820806 & obligates add1 funds HOYLE, J C Office of the Betretary of the Commission FIN B-1311 NRC-17-80-448-0 82/05/04 2pp 16566 065
- --8212270099 Informs that funded request for procurement action should be submitted for continuation of svcs pending award of followon contract for stemographic reporting svcs PAGE. M. Administrative Contracts Branch 82/05/12 SULLIVAN, P Administrative & Logistical Support Branch 1p 14546 067
- --8212270107 Forwards unexecuted Mod 10.extending period of performance to 820806 & increasing funds obligated to "Stenographic Reporting Bycs " Approval requested SHITH, P A Administrative Contracts Branch FIN 8-1311 NRC-17-80-448-0 82/05/28 SHARP, R A Alderson Reporting 2pp 14546-070
- --8212270110 Forwards Mod 10.extending period of performance to 820804 & increasing funds obligated to "Stenographic Reporting Sycs "
 SMITH: A Administrative Contracts Branch FIN 8-1311
 NRC-17-80-448-0 82/06/11 Alderson Reporting 1p 16566 073
- --8212270114 Request for procurement action 80-860-448.executing Mod II to "Stenographic Reporting Svcs " Mod extends period of performance to 821115 & obligates addl funds CHILK.6 J Office of the Secretary of the Commission, FIN B-1311 NRC-17-80-448-0 82/07/16 2pp 16566 075
- --8212270123 Forwards unexecuted Mod 11.extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Svcs " Approval requested SiTH.P A Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/09 SHARP.R.A Alderson Reporting 2pp 1554-079
- --B212270127 Forwards Mod 11.extending period of performance to 821115 & increasing funds obligated to "Stenographic Reporting Sycs "
 SMITH-P A Administrative Contracts Branch FIN 8-1311
 NRC-17-80-448-0 82/08/20 Alderson Reporting 1p. 16566 08t
- --B212270131 Mod i1, extending period of performance to 82:115 & increasing funds obligated to "Stenographic Reporting Svcs"

 SHARP,R A Alderson Reporting SMITH,P A Division of Contracts
 FIN B-13:1 NRC-17-80-448-0 82/08/20 lp 16566 082.

- --B212270133 Natification of contract execution, Mod 11 to "Stenographic Reporting Svcs " Contractor Alderson Reporting Co. Inc. PAGE.M Administrative Contracts Branch FIN B-1311 NRC-17-80-448-0 82/08/20 CHILK.S J. BULLIVAN.P Office of the Secretary of the Commission MCNAMARA.A Atomic Safety and Licensing Board Panel 1p 16366 OB3
- 8212270078 Add1 response to FOIA request for repts & correspondence re inventory differences at NFS plant in Erwin.TN Documents completely & partially withheld (ref FOIA Exemptions 3 & 4) FELTON.J M Division of Rules and Records 82/12/03 BARLETT.D L Philadelphia Inquirer 5pp 16566 085
- 8212270306 Responds to FOIA request for all records re operation (during last 30 days) & final disposition of all breeder-type nuclear reactors No documents found subj to request FELTON, J.M. Division of Rules and Records 82/11/26 ROSE, M.S. Affiliation Unknown 1p 16555-319
- 8212270311 FOIA request for all records pertaining to operation (during last 30 days) & final disposition of all breeder-type huckear power reactors
 ROSE. H Affiliation Unknown 82/11/01 Office of Administration ip 16555, 320
- G212270328 Add1 response to FOIA request for documents re IAEA safeguards Forwards App A Documents 1.7 % 10 Remaining documents in Apps A & B completely & partially withheld (ref FOIA Exemptions 1 & 5) FELTON, J M Division of Rules and Records 82/11/15 GREENBERO, E V Galloway & Greenberg 4pp 16555 329
- --B212270333 Advises that info supplied by State Dept does not clarify nature or significance of delay incurred in completing facility attachments for Swedish reactors Info partially withheld (ref FOIA Exemptions 1 & 5)

 SHERR, T S Haterial Transfer Safeguards Licensing Branch 82/02/01 DEVINE, J B Assistant Director for Export/Import & International Safeguards 1p 16555 336
- ~-B212270336 Forwards marked-up analysis consisting of detailed comments on draft Korean safeguards analysis Addl info addressing significance of effective implementation of IAEA safeguards should be included PETERSONM R Assistant Director for Export/Import & International Safeguards 82/06/22 SHERR.T 5 Material Transfer Safeguards Licensing Branch 1p 16535 337
- 8212270414 FOIA request for documents re proposed revision &/or update to reactor safety study referred to in NUREG-0784, Chapter 10 as R8 II & all documents pertaining to discussion of reactor cooling method
 SHOLLY, B C Union of Concerned Scientists 82/11/04 FELTON, J N Division of Rules and Records 1p 16549 232
- 8212270418 Responds to FOIA request for documents re proposed revision %/or update to reactor safety study referred to in NUREO-0784. Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTON, J M Division of Rules and Records 82/11/26 SHOLLY, 8 C Union of Concerned Scientists 3pp 16547 233 24X Fichs 50-000, 82/11/26, 8212270418
- --8212270438 Comments on NUREG-0739, "Approach to Quantitative Bafety Ocals for Nuclear Power Plants" Info provided by D Okrent & M Griesmeyer to AIF televant to AIF questions FRALEY,R F ACRS Advisory Committee on Reactor Safeguards 81/09/15 REMICK,F J Interoffice Steering Oroup on Development of a Safety Goal 1p 16349 236
- ---B212270442 Forwards "Discussion of Home Comments on NUREG-0739," in response to AIF Committee on Reactor Licensing & Safety B10326 comments GRIESMEYER, J M. DKRENT, D. ACRS Advisory Committee on Reactor Safeguards B1/09/11 GIRBS, C. Atomic Industrial Forum ip 14549 237
- --8212270445 "Discussion of Some Comments on NUREO-0739 "
 GRIEBMEYER, J M , DERENT, D ACRS -- Advisory Committee on Reactor
 Safeguards DERENT, D California, Univ of Los Angeles
 81/09/30 23pp 16549 238
- --8212270448 Forwards N Palladino response to Guestion 7 re alternate DHR sys Feed & bleed considered legitimate DHR method FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards 81/08/13 WARD,D A ACRS - Advisory Committee on Reactor Safeguards 1p 16547 250

- --8212270453 Forwards M Carbon questions se natural circulation & feed & bleed heat removal sys to be addressed during ACRS subcommittee 800326 meeting Tentative meeting schedule encl BATES. A ACRS Advisory Committee on Reactor Safeguards 80/03/21 TONO.L B. JOHNSTON.W., JOHNSON.C NRC No Detailed Affiliation Given 5pp 16547-258
- --B212270497 Forwards M Bender concerns re potential interaction of ferd b bleed method of DHR w/other methods Issues warrant consideration M/o sncl FRALEY,R F ACRS Advisory Committee on Reactor Safeguards B0/03/20 CARBON.M W ACRS Advisory Committee on Reactor Safeguards ip 16947 263
- ~~8212270461 Discusses food & bleed heat removal process in B&W & C-E plants BATES, A ACRS ~ Advisory Committee on Reactor Safeguards B0/03/06 CARBON, H , EBERSOLE, J , PLESSET, M NRC ~ No Detailed Affiliation Olven 2pp 16549 264
- --8212270471 Expresses concerns re clarity of NUREO-0626 concerning features of relief valves & disadvantages & advantages of pilot operated valves & bleed & feed effect on core cooling by natural circulation

 BEKNER: M ACRS Advisory Committee on Reactor Safeguards
 BO/03/04 FRALEY.R F ACRS Advisory Committee on Reactor Safeguards
- 8212280033 FOIA request for SECY-81-364 & SECY-81-366A re proposed amend to 10CFR2 & 50 concerning significant hazards considerations

 GRABER-L Affiliation Unknown \$2/10/20 Division of Rules an Records 1p 16590 173
- 8212280039 Responds to FDIA request for SECY-81-366 & SECY-81-366A re proposed amend to 10CFR2 & 50 concerning significant hazards considerations Documents withheld (ref FDIA Exemption 5) FELTON, JM Division of Rules and Records 82/11/29 GRABER, L Affiliation Unknown 2pp 16590 174
- B2122B0506 Appeals denial of FOIA request for documents on behalf of UCS re environ qualification of electrical equipment CURRAN, D . BISHOP. L. Harmon & Weiss B2/11/02 DIRCKS, W J Office of the Executive Director for Operations 3pp 16593 033
- 8212280509 Responds to appeal re denial of FOIA request for documents re environ qualification of electrical equipment Appeal denied Document withheld (ref FOIA Exemption 5) DIRCKS, U J Office of the Executive Director for Operations 82/12/08 CURRAN.D Harmon & Weiss 2pp 16593 036
- 8P12280511 FOIA request for documents he NRC investigations & repts into burning of radwastes by Dow Chemical Co DERG.P Institute for Pulicy Studies 82/11/12 FELTON, J M Division of Rules and Records 1p 16593 023
- 8P12280512 Responds to FOIA request for documents re NRC investigations to repts into burning of radwastes by Dow Chemical Co Forwards WJ Dircks 820910 ltr State of MI regulations for incineration do not relate to NRC licensing authority FELTON, J M Division of Rules and Records 82/12/07 BERG.P Institute for Policy Studies 2pp 16593 024
- --8212280515 Provides info re emission controls placed on NRC licensed incinerators & NRC authority to license incinerators w/o public input or state knowledge Dow Chemical Co incinerator not major licensing action & does not warrant notification DIRCKS,W J Office of the Executive Director for Operations B2709/10 RIEQLE,D W Senate 2pp 16593 026
- 8212280520 Final response to FOLA request for documents re proposed version &/or update to reactor safety study referenced in NUREO-0784. Chapter 10 as RS 11 & documents re reactor cooling method. No add1 documents located FELTON, J M Division of Rules and Records 82/12/07 SHOLLY, S & Union of Concerned Scientists 1p 14593 028
- 8212290007 Final response to FOIA request for SECY-81-600A, SECY-81-622A, SECY-82-23, SECY-82-42, SECY-81-136, SECY-82-137, SECY-82-177A & B.SECY-82-286 & SECY-82-318 SECY-81-622A & SECY-82-197A & B withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 82/12/03 GRABER, L Affiliation Unknown 2pp 16607 164
- 8212270014 FOIA request for SECY-82-37A, 82-197, 82-197A & 82-197B ORABER, L Affiliation Unknown 82/11/05 Division of Rules and Records 1p 14607 169

- B212270018 Forwards "Comparison of 1/13 Scale Mark II Containment Multivent Pool Swell Data H/Analytical Methods," Mark II containment program rept W/o encl 5080N.3 J Oenpral Electric Co MFN 365-77 77/09/23 PARR, D D Light Water Reactors Branch 3 ip 16607 050
- 8212290019 Responds to FOIA request for SECY-82-39A.82-197.82-197A & 82-197B SECY-82-39A available in PDR, SECY-82-197A & 82-197B previously addressed in response to FOIA Request 82-424 NRC review of SECY-82-197 incomplete FELTON.J M Division of Rules and Records 82/12/13 GRABER.L Affiliation Unknown 1p 16607 170
- BP12290036 Responds to FOIA request for five categories of documents Forwards documents listed in App A Review of documents re

Item I continuing
FELTON.JH Division of Rules and Records
B2/12/02 HIATT,S L
Uhio Citizens for Responsible Energy 2pp 16607 133

- --8212290039 SECY-82-275
 Informs Commission of public comments received on NRC,
 JM Hendrie & util group proposed ATMS rules & current status
 of rulemaking effort
 DIRCKS.M J Office of the Executive Director for Operations
 82/06/28 18pp 16607 140
- 8212290049 RO 76-12 on 760909, low pressure alarm occurred on safety injection accumulator C.resulting in pressure reduction Caused by partially open HCV 1936 & body to bonnet leaks on HCV 1878 & 1549 Valves repaired & accumulator repressurized STALLINGS, C M Virginia Electric & Power Co 266 76/10/01 MOSELEY, N C Region 2. Atlanta. Office of the Director Spp 16607 263 24X Fichs 50-000.82/11/30.8212290060
- --9212290075 R0 76-13 on 760916, normal boric acid mekeup to vol control tank could not be accomplished due to plugging of chemical & voi control sys line I-inch-CH-56-152 Cause unknown Line will be inspected for indications of solidification STACLINOS.C M Virginia Electric & Power Co 292 76/10/20 MUSELEY.N C Region 2, Atlanta, Office of the Director Spp 16607 267 24X Fiche 50-000, 82/11/30, 8212270060
- --8212290078 IE Insp Repts 50-250/75-08 & 50-251/75-08 on 750527-30 Noncompliance noted failure to use latest approved procedure in performance of surveillance test HARDIN.A K , SEIDLE.W C Region 2. Atlanta, Office of the Director IEB-75-05 75/06/24 15pp 16607 338 24X Fiche 50-000.82/11/30.6212290060
- --8212290060 RO 76-07 on 760913, monthly average of gaseous & airborne particulate westes for previous 12 months found greater than Tech Spec limit Gaused by interpretational changes in Tech Spec Section 3 ii B New Ifmit approved STALLINOS.C M Virginia Electric & Power Co 258 76/09/24 MOSELEY,N C Region 2. Atlanta, Office of the Director 5pp 16607-273 24X Fiche 50-000.82/11/30,8212290860
- --8212290085 RO 76-05 on 760918, pressurizer level fell below 45% level setpoint resulting in decreases of pressurizer pressure & vol control tank level Caused by leaking tube in steam generator A Cause of tube failure will be evaluated STALLINGS, C M Virginia Electric & Power Co 264 76/09/29 MOSELEY, N C Region 2. Atlanta. Defice of the Director 5pp 16607 278 24% Fiche 50-000, 82/11/30, 8212290060
- --8212290107 IE Insp Repts 50~250/75-16 & 50~251/75-16 on 751105-21
 Noncompliance noted failure to submit Unit 4 inservice insp
 rept to NRC within 90 days
 HARDIN,A K Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch BERATAN,L L Region 2, Atlanta, Reactor Construction &
 Engineering Support Branch 50~251/75-16 75/12/05 17pp
 16607 287 24X Fiche 50~000,82/11/30,8212290060
- --B212290114 IE Insp Repts 50-250/75-07 & 50-251/75-07 on 750512-14
 Deviation observed one tray of control cables in Unit 3
 control red drive room & cable trays exiting auxiliary
 bldg did not have fire stops installed
 HARDIN-A K Region 2. Atlanta, Office of the Director
 [EB-75-04A 75/05/27 9pp 16607 360 24X Fiche 50-000,
 82/11/30.8212290060
- --B212290137 IE Insp Repts 50-250/75-17 & 50-251/75-17 on 751209-12 & 16-19 Noncompliance noted high radiation area improperly barricaded & licensed operator requalification program not fully performed per Administrative Procedure 030) HARDINA K . DANCE.H C . JENKINS.C. R. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 50-251/75-17 76/01/12 IBpp 16607 313 24X Fiche 30-000.B2/11/30.8212290060

- --8212270138 IE Insp Rept 50~261/75-15 on 751124-25 No noncompliance noted Major areas inspected inservice insp results & procedures & eddy current insp of steam generator tubes PARKER, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch BLAKE, J J, BERATAN, L L Region 2, Atlanta, Reactor Construction & Engineering Support Branch 75/12/17 6pp 16608 010 24X Fiche 50-000, 82/11/30, 8212270060
- --B212290165 IE Insp Rept 50-261/75-14 on 751104-19 Noncompliances noted failure to follow procedures for radiation surveys/maint of instrument records & surveillance testing procedures did not provide for recording "as-found" & "as-left" calibr data PARKER.R C., DANCE.H C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch TROUP.O L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 75/12/16 17pp 16608 024 24X Fiche 50-000.82/11/30.8212290060
- --B212270184 IE Insp Repts 50-280/76-14 & 50-281/76-14 on 760715-17
 Noncompliance noted failure to follow log book entry &
 review & initial requirements specified in Administrative
 Procedure 29
 SINKULE,M V Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch JENKINS.O R, TROUP,O L Region 2, Atlanta, Fuel Facility
 & Materials Safety Branch 50-281/76-14 76/10/19 13pp
 16608 048 24X Fiche 50-000, 82/11/30,8212270060

GEN TEC IS GENERIC TECHNICAL ISSUES

- B20B290027 Comments on draft rept on pressurized thermal shock, w/ special attention to Sections 4.5.9 & 10 Conclusions are conservative GALL.H R Gall,W R GALL.W R ACRS - Advisory Committee on Reactor Safeguards 82/09/28 BENDER,M ACRS - Advisory Committee on Reactor Safeguards 2pp 14287 328
- B20B290032 Discusses ACRS B20930 meeting re pressurized thermal shock Appropriate framework needed to establish real margins & limits "PHR Downcomer Fluid Temp Transients Due to High Pressure Injection at Btagnated Loop Flow," encl. THEOFANDUS, T O PURGUE Univ THEOFANDUS, T O ACRS Advisory Committee on Reactor Safeguards B2/10/04 IONE, E ACRS Advisory Committee on Reactor Safeguards 2pp 16267 176
- 8212030277 Unofficial transcript of 821201 briefing in Washington DC on pressurized thermal shock Pp 1-86 Viewgraphs encl # Commissioners 82/12/01 135pp 16317 096
- 8212060470 Responds to 821004 ltr re draft "NRC Staff Evaluation of Pressurized Thermal Bhock." & draft ORNL rept, "Pressure Vessel Thermal Shock at US PKRs Events & Precursors.
 1963-Mid-1981 " Comments will be considered PALLADINO.N J Commissioners 82/11/23 MARKEY.E J House of Rep 3pp 16343 301
- --820915000B Expresses disappointment at failure to inform of NRC draft evaluation & ORNL precursor rept re nuclear reactor pressure vessel thermal shock Concerned w/degree reactor vessels of operating PMRs have become vulnerable to cracking MARKEY.E J House of Rep , Interior & Insular Affairs 82/10/04 PALLADINO,N Commissioners 4pp 16343 304
- 8212070414 Responds to FDIA request for all records on embrittlement, thermal shock, corrosion & cracking of reactor pressure vessel at facility Records available at PDR FELTON, JM Division of Rules and Records 82/11/05 GUIQO.C Pollution & Environmental Problems, Inc 4pp 16356 002
- B212090141 Notification of CROR B21124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Guide 1 97 Agenda summary info & proposed NUREO encl
 STELLO. V Committee to Review Generic Requirements 82/11/12
 EISENHUT, D G Division of Licensing BERNERD, R M Office of Nuclear Regulatory Research, Director HELTEMES, C J Director's Office 122pp 16361 027
- --B211120169 Forwards CROR package for Unresolved Bafety Issue A-49. "Containment Emergency Sump Performance" Issue not as significant as previously postulated CROR review of proposed actions requested DENTON, HR Office of Nuclear Reactor Regulation. Director 82/10/27 STELLO, V Regional Operations & Generic Requirements 200s 16341 151
- B2i2i30407 Unofficial transcript of Commission 82i209 meeting in Washington.DC re discussion/possible vote on prossurized thermal shock actions Pp 1--71
 * Commissioners 82/12/09 72pp 16413 160

- 8212140001 Add1 response to FDIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J H Division of Rules and Records 82/11/03 GALLO, J 15ham, Lincoln & Beale 2pp 16433 354 24X Fiche 50-000,82/11/03, 82/15/00001
- ~-BiO4230080 Advises that structural elements & review areas noted need not be considered part of NRC-03-79-118 Section 3 8 of GRP defines structures to be considered PERSINKO, D Bystematic Evaluation Program Branch NRC-03-79-118 Bi/O4/14 BTILMELL Franklin Institute/Franklin Research Center 2pp 16434 274
- B212150326 Submits status rept re plant reviews of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36" Div of Sys Integration considering making resolution of A-36 condition for OLs due to lack of util incentive DICK, OF Licensing Branch i B2/11/27 YOUNOBLOOD, B J Licensing Branch i 3pp 16446 234
- --B212150333 Forwards status rept on NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants" to help expedite project managers submittal of outstanding Phase I & II info CLEMENSON: P Auxiliary Systems Branch B2/10/08 KIPER: K Licensing Branch 2 REGUA: Q Operating Reactors Branch 1 9pp 16446 237
- 8212270042 Summary of CROR Meeting R6 on 821124 re Unresolved Safety Issue A-43: "Containment Emergency Sump Performance" & revision to Reg Ouide 1 97 STELLO V Regional Operations & Generic Requirements 82/12/10 DIRCKS W J Office of the Executive Director for Operations 5pp 16607 DOI

INSPECTION AND ENFORCEMENT

- B208190240 IE Bulletin B2-03, Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants "Svc list encl DEYOUNO, R C Director's Office, Office of Inspection and Enforcement B2/10/28 Consolidated Editor Co of New York, Inc 112pp 16462 163 24X fiche 50-000, 82/10/28, 8208190240
- 8208190245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list pac!

 COBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/05 Consolidated Edison Co of New York, Inc 1:0pp 16372 142 24X Fiche 50-000, B2/11/05, B208190245
- 8208190251 IE Info Notice 82-44, "Clarification of Emergency Plan Exercise Requirements" Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/11/18 Consolidated Edison Co of New York, Inc 109pp 14411 199 24X Fiche \$0-000, 82/11/19,8208190251
- 8208190256 IE Info Notice 82-46, "Defective & Obsolete Combination Padlocks " 8vc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pp 1641
- 8209190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list encl GDBB.L I Division of Fuel Facilities, Materials & Safeguards 82/11/30 Consolidated Edison Co of New York, Inc 35App 16387 028 24X Fiche 50-000,82/11/30,8208190257
- 8208190259 IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYDUNG, R C. Director's Office, Office of Inspection and Enforcement 82/12/03 Consolidated Edison Co of New York, lnc 113pp 16411 317 24X Fiche 50-000, 82/12/03,8208190259
- 8208190261 IE Info Notice 82~48, "Failures of Agastat CR 0095 Relay Bockets " Svc list encl JORDAN,E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co of New York, Inc. 110pp. 16462 064 24X Fiche 50~000.82/12/03.8208190261
- B20B190267 IE Info Notice 82-49, "Correction for Bample Conditions for Air & Oas Monitoring " Bvc list encl
 DEYQUNO.R C Director's Office of Grise of Inspection and
 Enforcement 82/12/16 Consolidated Edison Co of New York, Inc
 127pp. 16628 191 24X Fishe 50-000.82/12/16.8208190267.

- 8208190268 IE Info Notice 82~50, "Mod of Solid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 293 24y Fiche 50-000,82/12/20.8208190268
- 8212060079 PNG-I-82-075 on 821201.util announced 10-month delay & new commercial operation dates for Unit 1 (821231) & Unit 2 (870331) projected Total cost revised by 44% Caused by increased design & engineering complexity

 MELLY.E Region 1, Office of Director 82/12/01 2pp 16314 342
- 8212060112 PNO-III-82-130 on 821130.all safety-related welding on HVAC stopped after licenses determined GA program for welder certification & procedure qualification inadequate Photon Testing removed from list of approved vendors GARDNER.R Region 3. Office of Director 82/12/01 ip 16316-102
- 8212060132 PNO-V-82-048 on 821126.Kawai Island.Kl suffered loss of all electrical power & phone svc as result of hurricane Iwa US Navy nuclear submarine sent to island to provide electrical power THOMAS,R D Region 5. Office of Director 82/11/26 ip 16316 084
- 8212060305 PND-I-82-077 on 821201, contractor employee intentionally poisoned lunch & placed in refrigerator Employee notified licensee of actions upon discovering lunch missing Warning announced on page sys No known harm occurred ARCHITZEL Region i, Office of Director 82/12/01 ip 16312 111
- B2120B0006 Add1 response to FOIA request for seven categories of info re NFB, Grwin, TN facility Forwards App A documents denoted w/asterisk FELTON, J M Division of Rules and Records 82/10/25 WEISS, E R Harmon & Weiss 36pp 16367 001
- ---8212080137 Supplemental PNS-II-79-102E on 790924, followup of areas outside protected area identified by aerial measurements sysfound not to proceed limits for unrestricted use CORYELL-0 P. TOBIN, W.J. Region 2, Office of Director 79/09/25 ip 16370 154
- --8212080149 Supplemental PNS-II-79-102K on 791102, initial reinventory offerts resulted in partial reconciliation of 790917 difference Unresolved inventory difference in excess of regulatory limits for continued operation remains LEE, TD : 01LLESPIE, FP Region 2. Atlanta. Office of the Director 79/11/02 ip 14370 155
- 8212080514 PNO-1V-82-096 on 821206, during transfer to offshore platform radiography camera dropped 15 ft from crane to deck platform discharging 9 Ci Co-60 source Personnel evacuated Caused by improperly securing device to crane DODA: R J Region 4. Office of Director 82/12/06 ip 16352 263
- 82:2100150 PkD-III-82-134 on 82:206.briefcase containing radiopharm from Pharmatopes, Inc stolen from car in Detroit, MI Radiopharm consisted of 30 mCl Tr-97m Significant exposure unlikely dus to labeling & short half-life of matl SRENIAMSKI,D J., MULLAUER,JR Region 3, Office of Director 82/12/06 ip 16376 043
- B212100254 PNO-IV-82-044 on B21203, normal phone communication lost due to local flooding caused by heavy rains & severe weather Backup radio communications feasible from elevated ground northwest of Little Rack Addl heavy rain possible SEIDLE.W C Region 4. Office of Director 82/12/03 Ppp 16376 127
- 8212140519 EN-82-038 on 821215 notice of violation & proposed imposition of civil penalty will be issued to Orion Chemical Core receipt & use of source matl greater than IOCFR40 22 regulation permits FLOCK.E. AXELRAD.J. Director's Office. Office of Inspection and Enforcement. 82/12/10 ip 16403-211
- B212150086 PNO-11-82-135 on B21209, contractor employee arrested & charged w/blackmail.including extortion & threat to kill. injure or intimidate Arrest followed 3 day investigation as result of bumb threats on B21206.07 & OB MODRE, D E Region 2, Office of Director 82/12/09 2pp 16431 024
- B212150070 PNG-II-82-134 on 821208 bomb threat received while in final preparation for full scale emergency drill Security determined call came from security guard posted at entry gate to duner controlled area Quard fired & arrested TILLMAN A Region 2, Office of Director 82/12/09 2pp 16430 187

- 8P12160080 Addit response to FDIA request for records re receipt, processing storage or removal of source matl at Canonsburg. PA, Vitro MFg Co & Vitro Rare Metals Co Porwards documents listed in App A Remaining info under review FELTON. J M Division of Hules and Records 82/09/30 BLACK. Buchanan. Ingersoll, Rodewald, Kyle & Buerger 7pp 16447 31 BLACK A E
- -8212160103 PND-77-00B draft press release re radiation detected mear premises of former AEC contractor/licenses in Canonsburg.PA forwarded Site will be surveyed by ERDA, starting 770112 W/o entl Related info entl SMITH.O H. RDV.O W. THOMPSON.D Director's Office Of Inspectson and Enforcement 77/01/11 22pp 16447 328
- 6912170070 EN-82-040 on 821216, notice of violation & proposed imposition of civil penalty to be issued to licensee Action based on failure to ensure that licensed radioactive matl stored in unrestricted area secured against removal BROCKETT, T , AXELRAD, J Director's Office, Office of Inspection and Enforcement EA-82-40 82/12/13 lp 16450 321
- 8212200069 PNA-82-010 on 821212.0 5 Ci Cs-137 sealed source in container lost during shipment between Houma.LA & Cameron.LA Source not found Media interest anticipated 1p 16474 200 DODA: R J Region 4: Office of Director 82/12/13
- 8212210161 PNA-82-010A on 821213, lost well logging source recovered near Houma, LA NRC considering appropriate enforcement action Region 4. Office of Director 82/12/16 ip 16483 361

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8211120486 Ack receipt of "Near-Term UL Plant Technical Design Verification Program "Three-phase program outlined in rept contains concepts consistent u/independent QA design Const verification programs underway EISENHUT.D G Division of Licensing B2/10/21 NOONAN.V S ED5 Nuclear, Inc. 3pp 16043 106
- --8211120491 Forwards proprietary "Near-Term OL Plant Technical Design Verification Program " Comments appreciated Rept withheld (ref 10CFR2 79) NOONMAN V S EOS Noclear, Inc GA2-089 82/07/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 16043 109
- 8212010436 Forwards review of geology & seismology of SIC prototype reactor plant in response to 820525 request for comments No geologic hazards, including capable faults, landslide or ground collapse present at site DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/09 MCKEE, K R Energy, Dept of 16pp 16267-285
- 8212020185 Provides info clarifying USGS position re reoccurrence of 1886 Charleston. SC earthquake USGS now concludes that parthquakes should not be ruled put until deterministic & probabilistic evaluations of seismic hazard are performed DIRCKS.W J Office of the Executive Director for Operations 62/11/19 Commissioners 6pp 16308 267
- --8212020193 Clarifies position re 1886 Charleston earthquake Studies reveal earthquake potential along eastern seaboard Deterministic & probabilistic evaluations of seismic hazard should be performed for individual sites DEVINE, J.F. Interior. Dept of. Geological Survey 82/11/18 JACKSON. R.E. Geosciences Branch 1p 16308 273
- GP12040052 Authorizes regional administrators to perform certain operator licensing functions NRR will retain functions delegated to regions
 UIRCKS, N J Office of the Executive Director for Operations
 DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/22 O'REILLY, JP Region 2, Office of Director KEPPLER, J
 Region 3, Office of Director 2pp 16343 215
- --8212040058 Forwards Procedure 0128-82-03. "Delegation & Assessment to Region 2 & 3 of Certain Operator Licensing Functions "
 DENTIFICATION HR Diffice of Nuclear Reactor Regulation, Director
 82/11/22 O'REILLY, J Region 2. Office of Director KEPPLER, J G
 Region 3. Office of Director ip 18343 217
- --8212060044 Procedure 0128-82-03, "Delegation & Assignment to Region ; & 3 of Certain Operator Licensing Functions "
 DENTON-H R Office of Nuclear Reactor Regulation, Director 82/11/22 3pp 16343 218
- 8212040209 Forwards IE Security Insa Rept 0-82-70 on 820409 No noncompliance noted

 MARTIN T Division of Engineering & Technical Programs 82/11//
 COCHRAN T B Natural Resources Defense Council 2pp 16313-175 82/11/22

- --8212060212 IE Security Insp Rept 0-82-70 on 820609 No noncompliance noted Major areas inspected physical barriers, personnel identification & control, protective alarms, protective personnel & classified document control BAILEY, R. J., GODY, A. T. Division of Engineering & Technical Programs 82/11/02 3pp 16313 177
- 8212080659 "Human Factor in Nuclear Power Plant Safety Progress Since TML" published in "Progress in Nuclear Energy," Vol 10. Pages 299-347 Affiliation Unknown 81/02/09 50pp 16379 245
- 8212100217 Summarizes Nuclear Util Action Committee on Emergency Response Capabilities 821021 meeting w/NRC re implementation of SECY-82-111 provisions Committee charter & summary of ungoing activities enci GEURCE, R L . BLANCH, P Alabama Power Co 82/12/03 EISENHUT, D G Division of Licensing 12pp 16374 081
- 8212270253 Responds to 800521 ltr re Research Info Ltr 83 on steam generator integrity Research info ltrs are brief ltrs to staffs presenting findings by Ofc of Research contractors, not review of all developments SHAD.L C Assistant Director for General Reactor Safety Research 80/06/02 SHEWMON.P O Affiliation Unknown 2gp 14555 317
- 8912270432 Forwards regulatory analysis guidelines to replace revised guidelines for value impact analyses
 DIRCKS, M. J. Office of the Executive Director for Operations
 82/12/13 MRC No Detailed Affiliation Given 2nd 16571 386 82/12/13 NRC - No Detailed Affiliation Given 2pp
- --8212270439 "Regulatory Analysis Guidelines of NRC "

 # Office of the Executive Director for Operations 82/12/13
 22pp 16571 340

NURED REPORTS AND RELATED CORRESPONDENCE NUREO

B002260162 RIL-076

OO2260162 RIL-076
Research Info Ltr 76 summarizes info re use of postirradiation heat treatment to recover preirradiation
properties of commercial nuclear power plant reactor vessels
for continued safe operation
LEVINE.S Office of Nuclear Regulatory Research, Director
79/12/28 DENTON, HR Office of Nuclear Reactor Regulation,
Director MINDOUGER B Office of Standards Development, Director
double 16565 224 16569 224

0005270742 RIL-085

UU52/0742 RIL-085
Research Info Ltr 85 discusses NUREG/CR-1014, "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Vicinity of Intersection w/Extension of New Madrid Fault Zone - Annual Progress Rept FY79 "BUONITZ,R J Office of Nuclear Regulatory Research, Director 80/03/24 DENION,H R Office of Nuclear Regulatory Research, Director MINGOUE,R B Office of Standards Development, Director 7pp 14565 352

8005281047 RIL-071

Research Info Ltr 71 submits NUREG/CR-0876, "Regional Tectonics & Beismicity of East NE.Annual Rept,June 1977-May 1978 " LEVINE, 6 79/11/19 Office of Nuclear Regulatory Research, Director DENTON,H R Office of Nuclear Reactor Regulation, 5pp 16565 828 Director

Billig0045 RIL-124
Research Info Ltr 124 transmits results of research relevant to display & utilization of control room alarm & annunciator sys RIL is part of TMI Action Plan I D. 4 a(1) & based on NNREO/CR-2147 W/o enc!
MINGQUE.R B Office of Nuclear Regulatory Research, Director RIL-124 Bi/10/20 DENTON.H R Office of Nuclear Reactor Regulation, Director STELLO,V Director's Office, Office of Inspection and Enforcement 4pp 16566 029

8212010024 Comments on NUREG/CR-2815 re nat1 reliability evaluation program procedures guide UHRIG.RE Florida Power & Light Co L-82-519 82/11/29 EL-BASSIONI,A NRC - No Detailed Affiliation Given 3pp

8212010052 NUREG-0936 VOI NO3 NRC REGULATORY AGENDA Quarterly Report, July-September 17,

1982 Division of Rules and Records 82/10/31 199pp, Available at C \$7.00 16291-083

```
3712010115 NUREG/CR-2765
A MATHEMATICAL MODEL FOR RADON DIFFUSION IN EARTHEN
        MATERIALS
       MIELSON,X K. ROGERS,V C. Rogers Engineering Co., Inc. * Batte
Memorial Institute, Pacific Northwest Laboratory FIN 8-2269
PNL-4301 B2/10/31 Division of Health, Siting & Environment
49pp Available at NRC $4.75 16291.031
                                                                                                                                                                     * Battelle
 G212010138 NUREG-0485 VO4 N10
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data
As of October 31.1982 (Berge Book)
Office of Resource Management. Director 82/11/30 97pp
16293 139
  BP12010144 NUREO/CR-2566
        SHR REFILL-REFLOOD PROGRAM TASK 4 4-CCFL/REFILL SYSTEM EFFECTS TESTS (30 SECTOR) EVALUATION OF PARALLEL CHANNEL
        PHENOMENA
                                         General Electric Co FIN A-5877 EPRI NP-2373
Division of Accident Evaluation 79pp 14291 282
        82/11/30
 82:2010327 SECY-82-462
Recommends approval of NRC integrated human factors program
plan Plan represents systamatic 5 comprehensive approach for
addressing human factors concerns important to safety in
       FY63-85
       DIRCKS, W J
       DIRCKS.W J Office of the Executive Director for Operations
82/11/19 68pp 16522 053
 8212010514 Forwards "Preliminary Site Stabilization & Closure Plan for Barnwell Low Level Radwaste Disposal Facility" & NUREO/CR-2478.Vol 1.per meeting in Natural Bridge State Party, KY re Maxey Flats low level waste facility W/o encl PENNIFILL.R A Low Level Waste Licensing Branch WM 409 18 82/11/04 PAGE,R Kentucky, State of 1p 16270 262
GP12020200 Forwards Revision I to CEN-152, "C-E Emergency Procedure Guidelines Vols 1 & 2," in response to DG Eisenhut B01031 ltr V NUREO-0737, Item I C I Guidelines intended to supersede & replace guidelines in CEN-128

WELLS.R W C-E Operating Plants Duners Group WELLS.R W Northwart Utilities RW-B2-67 B2/11/22 EISENHUT, D G Division of Licensing 2pp 16272 066
      B212020212 CEN-152 ROI
             Revision 1 to CEM-152, "Emergency Procedure Guidelines"

* C-E Operating Plants Owners Group 82/11/30 723pp
              16272 070
GP:20A0429 NUREO/CR-23A4 VOI
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN
POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE
POLLUTANTS VOI 1-Introduction To The SPAHR Demographic
hadel For Health Risk
       CGLLING, J.J., LUNDY, R.T., GRAHN, D. Argonne National Laboratory

Λ-2059 ANL-81-59 82/11/30 Division of Health, Siting &

Environment 92pp 16347 124
GP12060441 NUREO/CR-2364 VO2
PRCJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN
POPULATIONS EXPOSED TO RADIOACTIVE AND NONRADIOACTIVE
POLLUTANTS Vo1 2-SPAHR Introductory Guide
COLLING.J J. LUNBY.R T Argonne National Laboratory FIN A-205
ANL-81-59 82/11/30 Division of Health, Siting & Environment
42pp 16346 026
                                                                                                                                                                 FIN A-2059
BFJ2040447 NUREG/CR-2364 VO3
FRQJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN
POPULATIONS EXPOSED TO RADIOACTIVE AND NORRADIOACTIVE
POLLUTANTS Vol 3-SPAHR Interactive Package Quide
COLLIPS.J J Argonne National Laboratory FIN A-2059 ANL-
B2/11/30 Division of Health, Siting & Environment 40pp
                                                                                                                                                                       ANL-81-59
        16346 068
BP12060451 NUREG/CR-2364 V04
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN
POPULATIONS EXPOSED TO RADIOACTIVE AND NORRADIOACTIVE
POLLUTANTS VOI 4-SPAHR User's Guide
      COLLINS.J J. LUNDY.R T Argonne National Laboratory FIN A-205
ANL-81-59 82/11/30 Division of Health, Siting & Environment
                                                                                                                                                                   FIN A-2059
      Blpp 16346 176
BP12060455 NUREG/CR-2364 V05
PROJECTION MODELS FOR HEALTH EFFECTS ASSESSMENT IN
POPULATIONS EXPOSED TO RADIOACTIVE AND MONRADIOACTIVE
POLLUTANTS Vol 5-SPAHR Programmer's Guide
COLLINS, J J LUNDY, R T Argonne National Laboratory FIN A-2054
ANL-81-59 82/11/30 Division of Health, Sizing & Environment
                                                                                                                                                                 FIN A-2059
      Bipp 16346 278
```

```
8212060458 NUREG/CR-3040
SELECTED REVIEW OF FOREIGN SAFETY RESEARCH FOR NUCLEAR
        POWER PLANTS
        FIGURE FUNDING D. THOMAS, F.A. Stevenson & Associates F. BP/11/30 Division of Engineering Technology 123pp at NRC $6.00 16347.001
                                                                                                                                                        FIN 8-6769
  9212060460 NURE9/CR-2011
       212060460 NURED/CR-2911
BEVELOPHENT OF TECHNIQUES FOR FABRICATION OF FILM PROBE
SENSOR ASSEMBLY
MORRHEAD, J Dak Ridge National Laboratory FIN B-0413
ORNL-5895 82/11/30 Division of Engineering Technology
        MOORHEAD, A J Oak R
ORNL-5875 B2/11/30
16347 327
  8212040465 NUREG/CR-2753
        ANALYSIS OF A DOUBLE-ENDED COLD-LEG BREAK SIMULATION--THIF
TEST 3 05 58
       TREN 3 05 96
CRADDICK, N C , PEVEY,R E Oak Ridge National Laboratory QRNL-86
82/10/31 Division of Accident Evaluation 118pp 16347 216
                                                                                                                                                                      ORNL-5684
  BR12060468 NUREG/CR-2960
       EXPERIMENT DATA REPORT FOR SEMISCALE MOD-2A STEAM LINE BREAK
EXPERIMENTS (TESTS 9-8F-4 AND 8-8F-5)
LARSON,R A EQ&O, Inc FIN A-6038 EQ9-2224 82/11/30
of Nuclear Regulatory Research, Director 68pp 16348 224
                                                                                                                                                                               Office
  8712060480 NUREG/CR-2807
        TEMPERATURE ESTIMATES FROM ZIRCALDY OXIDATION KINETICS AND
        MICROSTRUCTURES
       Olgen. C S E640, Inc FIN A-6053 E69-2207 82/11/30 of Accident Evaluation 53pp 16344 310
                                                                                                                                                                           D1 V16101
  8212060486 NURED/CR-2932 VO1
EQUIPMENT QUALIFICATION RESEARCH TEST OF ELECTRIC CABLE WITH
FACTORY SPLICES AND INSULATION REWORK TEST NO 2. REPORT NO
       MINDR.E E , FURGAL.D T
SANDS1-2027 82/10/31
16344 128
                                                                        Sandia Laboratories FIN A-1355
Division of Engineering Technology
                                                                                                                                                                                  7 7 p p
 8212070425 Responds to FOIA request for documents re 820809 notice of violation & order imposing civil penalty Forwards App A documents App B documents completely withheld & Documents Ci-C4 partially withheld (ref FOIA Exemptions 3.5 % 7) FELTON.J M Division of Rules and Records 82/11/05 McGARRY.J M Debevoise & Liberman Spp 16355 003 24% Fiche 50-000.82/11/09, 8212070425
 8212080626 Requests participation in 820318 peer review meeting to discuss GRNL draft rept. "Interim Source Term Assumptions for Emergency Planning & Equipment Qualification "Draft rept forwarded first wk of Mar 1982 for review & comment HULMAN, Q Accident Evaluation Brench 82/03/02 CASTLEMAN, Q Colorado, Univ of 1p 16379 354
 B2120B0678 "TMI Action [tem Plan Tracking Sys." Oct 1982 issue

* Office of Resource Management. Director 82/10/01 16lpp
       16370 202
8212090048 Responds to FDIA request for SECY* Forwards SECY-82-23, SECY-82-42, SECY-82-134, SECY-82-137, SECY-82-286 & SECY-82-315 SECY-81-400A available in PDR Review of SECY-81-402A SECY-82-1978 continuing FELTON, J M Division of Rules and Records 82/10/20 GRABER, L Affiliation Unknown Ip 14384 295
 --8209280513 SECY-82-315
Requests Commission approve publication of for comment
NUREG-0706. "Quidance for Implementation of 10CFR$0 34(g)"
Section requires applicants to evaluate differences from
           SRP
DIRCKS.W J Offi
no/07/26 16pp
                                             Office of the Executive Director for Operations
App 16305 166
B212090141 Notification of CRGR B21124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Guide 1 97 Agenda summary infa & proposed NUREO encl STELLO: V Committee to Review Generic Requirements B2/11/12 EISENBUT, D G Division of Licensing JORDAN.E L Director's Office of Nuclear Material Safety & Safeguards, Director 122pp 147341 000
 --B211120169 Forwards CRGR package for Unresolved Bafety Issue A-43,
"Containment Emergency Sump Performance " Issue not as
significant as previously postulated CRGR review of
proposed actions requested
DENTON, H R Office of Nuclear Reactor Regulation, Director
B2/10/27 STELLO,V Regional Operations & Generic Requirements
200pp 16361 151
```

8212100338 Transcript of 821101 press conference in Bethesda.MD re NUREG/CR-2239 on site meteorologic data Pp 1-32 * Office of Public Affairs 82/11/01 34pp 16388 123

891230050 Extends invitation to participate in peer review of rept.
"Interim Source Term Assumptions for Emergency Planning &
Equipment Qualifications " Comments requested for 820318
meeting to be held in Bethesda, MD
HULMAN, L. G. Accident Evaluation Branch B2/03/02 BENJAMIN, A S
Sandia Laboratories in 16417-049

G212130058 NUREO/CR-2643
A REVIEW OF SELECTED METHODS FOR PROTECTION AGAINST SAROTAGE BY AN INSIDER
GOLDMAN,L A . LOBNER, P R Science Applications, Inc & Sandia Laboratories FIN A-1210 SANPBZ-7036 B2/10/31 Division of Facility Operations 150pp 16416 198

BP1213010B NUREO/CR-2942
CRT DISPLAY EVALUATION THE MULTIDIMENSIONAL RATING OF CRT
CENERATED DISPLAYS
OERTMAN, D I , BLACKMAN, H S , BANKS, W W EQ&G, Inc Fin A-6308
E00-2220 82/11/30 Office of Nuclear Regulatory Research,
Director 43pp 16415 209

8P12130110 NUREG/CR-2899
ANALYSIS OF A PROPOSED ONE THOUSAND DOLLAR PER MAN-REM COST EFFECTIVENESS CRITERION
6FF1P, D R Sendia Laboratories FIN A-1334 SAND82-1870
62/11/30 Division of Risk Analysis 12pp 16417 155

G212190113 NUREG/CR-2170
AN ASSESSMENT OF FUEL FOAMING POTENTIAL BURING CORE
MELTDOWN ACCIDENTS
CRONENBERG, A W., CROUCHER, P. W., MACDONALD, P. E. EOKO, Inc. EGG-2191
82/11/30 Office of Nuclear Regulatory Research, Director 61pp

G212130118 NUREO/CR-2864
IDENTIFICATION OF SAFETY RELATED EQUIPMENT FOR ANALYSIS AND TESTING IN THE HYDROGEN BURN SURVIVAL PROGRAM DANDINI,V J Sandia Laboratories FIN A-1270 SAND82-1484
62/11/30 Division of Accident Evaluation 26pp 14417 225

GP12130123 NUREO/CR-2720

ANALYSIS OF PERFORMANCE OF MESTINGHOUSE REACTOR VESSEL
LEVEL INDICATING SYSTEM FOR TESTS AT SEMISCALE
HARBY, J E , MILLER, O N Oak Ridge National Laboratory FIN 8-0401
ORNL/TM-8336 82/11/30
Director 61pp 16410 220

GP12130135 NUREO/CR-2697
URANIUM GXIDE AND SGDIUM GXIDE AEROSGL EXPERIMENTS NSSP
MIXED-OXIDE TESTS 303-307.DATA RECORD REPORT
ADAMS.R E, KRESS.T S : TOBIAS.M L Gak Radge National Laboratory
FIN D-0121 GRNL/TM-8325 82/11/30 Office of Nuclear Regulatory
Research, Director 108pp (4417/258

G212130140 NURGO/BR-0051 V04 N4 POWER REACTOR EVENTS May-June 1982 MASSARO,5 A Director's Office 82/11/30 30pp 16415 250

02:2130143 NUREO/CR-2774 VO2
PHYBICS OF REACTOR SAFETY April-June 1982
* Argonne National Laboratory FIN A-2015 ANL-82-24 82/11/30
Division of Accident Evaluation 43pp 16415 164

8P32130147 NURES/CR-2918

801L-STRUCTURE INTERACTION ANALYSIS OF A 5 KO HDR EXPLOSIVE
TEST

KOT. C A , SRINIVASAN, M O , VAUQHAN, D K Argonne National Laboratory
FIX A-2217 ANL-82-53 82/11/30 Division of Engineering
Technology 118pp 16415 044

GRI 2130152 MUREC/CR-293D
EXPERIMENT DATA REPORT FOR LOFT ANTICIPATED TRANSIENT
EXPERIMENT SERIES L6-8
JARRELL,D,B, DIVINE,JM, MCKENNA,KJ E020, Inc FIN A-6043
E00-2217 82/11/30 Office of Nuclear Regulatory Research,
Director 278pp 16414 088

8212130217 Forwards "FOAM2 - Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LOCA." in response to NUREG-0565 & NUREG-0737. Item II K 3 30. TAYLOR.J.H Babcott & Wilcox Co 82/12/01 BERCOREN.J.S Standardization & Special Projects Branch 1p. 16398 142

6212130233 Provides info per 821201 telcon re submittal of App 1 to "B&W Small Break LOCA ECCS Evaluation Model " App 1 will be submitted under NUREG-0737. Item 11 K 3 31 TAYLORJU H Babbock & Wilcox Co 82/12/03 SHERON, B Reactor Bystems Branch ip 16397/016

8212130283 MURE9/CR-2296
A FIRST STUDY OF AEROSOLS PRODUCED BY NEUTRONIC HEATING OF FRESH URANIUM DIGKIDE FUEL UNDER CORE-DISRUPTIVE ACCIDENT CONDITIONS
ELRICK.R M Sandia Laboratories FIN A-1218 SAND81-1788
82/1/30 Division of Accident Evaluation 84pp 16418 [2]

8212140001 Add1 response to FOIA request for five categories of documents re SEP Forwards documents listed in App A No documents located subj to Item 3 of request Review of remaining documents continuing Documents available in PDR FELTON, J M Division of Rules and Records 82/11/03 GALLO, J lisham, Lincoln & Beale 2pp 16433 354 24% Fiche 50-000, 82/11/03, 82/2140001

--B202180460 Forwards Revision 1 to evaluation rept on SEP Topic VI-4.
"Containment Isolation Sys." for racility Rept considers
util comments received in 810810 & 820104 ltrs Conclusions
of original rept remain unchanged
SPEIS.TP Assistant Director for Reactor Safety 82/01/27
LANIAS.6 Assistant Director for Safety Assessment 43pp
16436 078 24X Fiche 50-000, 82/11/03,8212140001

~-B204010021 Forwards evaluation for SEP Topic VI-4, "Containment Isolation Sys " Outstanding items include insufficient isolation provisions in test, vent & drain lines & no isolation or leak detection provisions on ECCS subsystem SPEIS.T P Assistant Director for Reactor Safety 82/03/24 LAINAS.Q Assistant Director for Safety Assessment JApp 16434 329 24% Fiche 50-000, 82/11/03,8212140001

8212140412 Responds to Generic Ltr 82-20 re guidance for implementation of SRP (NUREG-0800) rule Substantive changes to SRP should be subjito reasonable period of public comment prior to implementation OLSON, R C Baltimore Gas & Electric Co GL-82-20 82/12/09 PURPLE, R A Division of Licensing 2pp 16403 320

BP12140464 NUREO/CR-2976

TRANSFER COEFFICIENTS FOR ASSESSING THE POSE FROM
RADIGNUCLIDES IN MEAT AND EGGS
NG-Y C . COLSHER. C S . THOMPSON: S E
FIN A-0417 UCID-19464 82/11/30 Division of Systems
Integration (post 811005) 116pp Available at NRC \$5.50
1A420.251

BP12140471 NUREO-0327 RO3
OWNERS OF NUCLEAR POWER PLANTS PERCENTAGE OWNERSHIP OF
COMMERCIAL NUCLEAR POWER PLANTS BY UTILITY COMPANIES
WOODLA S Office of State Programs, Director 82/11/30 39p;
Available at NRC \$4 50 16418 285

BP12140475 NURE9-0340 VO4 NO5 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE June 1-30, 1982 # Division of Technical Information & Document Control 82/11/30 610pp 16419 001

BP12140476 NUREG-0773
THE DEVELOPMENT OF SEVERE REACTOR ACCIDENT SOURCE TERMS 1957
- 1981
BLOND,R , TAYLOR,M , MARGULIES,T Office of Nuclear Regulatory
Research, Director 82/11/30 116pp Available at NRC \$5 5/16491 202

BP12140485 NUREG/CR-2823
A REVIEW OF THE IMPACT OF COPPER RELEASED INTO MARINE AND ESTUARINE ENVIRONMENTS
HARRISON,F L Laurence Livermore Laboratory FIN A-0119
UCRL-53042 B2/11/30 Office of Nuclear Regulatory Research.
Director 127pp Available at NRC #6 00 16431 031

B212150326 Submits status rept re plant reviews of NUREC-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36 "Div of Sys Integration considering making resolution of A-36 tondition for OLs due to lack of util incentive DICK.0 f Licensing Branch I B2/11/29 YOUNGBLOOD, B J Licensing Branch I 30p 14446 234

--8212150333 Forwards status rept on NUREG-0612. "Control of Heavy Lunds at Nuclear Power Plants" to help expedite project managers submittal of outstanding Phase I & II info CLEMENSON.F Auxiliary Systems Branch 82/10/08 KIPER.K Licensing Branch 2 REGUA, G Operating Reactors Branch I Spp 16446 237

8212160762 NUREO/CR-2134
BUR REFILL-REFLOOD PROGRAM, TASK 4 7-CONSTITUTIVE
GORRELATIONS FOR SHEAR AND HEAT TRANSFER FOR THE BUR VERSION
OF TRAC
ANDERSON, J O M, CHU, K K General Electric Co FIN 8-5877 EPRI
NP-1582 82/11/30 Office of Nuclear Regulatory Research,
Director 96pp 16464 190

- GP12160773 NUREC/CR-2975
 SDIL-TO-PLANT CONCENTRATION FACTORS FOR RADIOLOGICAL
 ASSESSMENTS
 NO.Y C , COLSHER.C S , THOMPSON, S E Lawrence Livermore Laboratory
 FIN A-0417 UCID-19463 82/11/30 Division of Systems
 Integration (post Bi1005) 140pp 16464 286
- BP12160780 NUREG-0748 VO2 N10

 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of

 Uctober 31.1982 (Orange Book)

 * Management Information Branch 82/11/30 286pp 16465 046
- B212170163 Forwards review of draft NUREO/CR-2815, "Natl Reliability Evaluation Program Procedures Guide "Comment period extension granted on B21117 Statements re containment performance conflict v/backfitting rules SCHERER.A E Combustion Engineering, Inc LD-82-097 B2/12/13 EL-BASSIONI.A Reliability & Risk Assessment Branch App 225
- BP12170204 Computer listing of status of generic issues as of 820901, (NVREG-0540)

 * NRC No Detailed Affiliation Given 82/09/01 141pp
- BP12200029 Comments on proposed rule iOCFR90 re guidance for implementation of SRP rule Supports rule GIBSON:t S Consumers Power Co 47FR47019 004 B2/12/09 Docketing & Services Branch ip 16473 350
- 6P12200036 Package of two comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule KOESTER, O L Kansas Qas & Electric Co BOUCHEY, G D Hashington Public Power Gupply System 47FR47017 82/12/10 Docketing & Services Branch 3pp 16474 001
- BP12200045 Comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule.NURE0-0706 Rule imposes requirements for performance of excessive analysis & evaluation efforts when relation to SRP not clear BRADBURY.R B Stone & Webster Engineering Corp 47FR47019 005 B2/12/10 Docksting & Services Branch 2pp 16470 001
- Bil2210535 Forwards requests for add1 info to complete review of WCAP-10079 (P), "NOTRUMP A Nodal Transient Small Break & General Network Code." & WCAP-10094 (P) "Westinghouse Small Break ECCS Evaluation Model " THOMAS.C O Standardization & Special Projects Branch B2/12/03 KAME.E P Westinghouse Electric Corp 2pp 16902 288
- --U21221053B Round I questions re Reactor Bys Branch review of WCAP-10054, "Westinghouse Small Break ECCS Evaluation Mode Using NOTRUMP Code." & WCAP-10079, "NOTRUMP Nodal Transient Small Break & General Network Code"

 Reactor Systems Branch 82/12/03 23pp 16502 270
- DPJ2220143 NUREO-0871 VO1 NO4 SUM4ARY INFORMATION REPORT July 1 - September 30, 1982 (Brown Book)
- (Brown Book) # Management Information Branch 82/11/30 52pp 16527 102
- G:12220162 NUREG/CR-2650 ALLOHABLE SHIPMENT FREQUENCIES FOR THE TRANSPORT OF TOXIC CASES NEAR NUCLEAR POWER PLANTS BENNETT, D E , HEATH, D C Sandia Laboratories FIN A-1214 SANDE2-0774 82/11/30 Division of Risk Analysis 37p; 16527 065
- G7:12220172 NUREG/CP-0033 VO2 PROCEEDINGS OF THE WORKSHOP ON CONTAINMENT INTEGRITY June 7-9.1982 BEBRELL:W A Sandia Laboratories SANDB2-1659 82/11/30 Office of Nuclear Regulatory Research, Director 370pp 16528 019
- 86/12220193 NUREO/CR-3004

 EVALUATION OF EXPERIENCES IN LONG-TERM RADON AND RADON

 DAUGHTER MEASUREMENTS

 YOUNG, J. A., JACKSON, P. O., THOMAS, V. W. Battelle Memorial Institute,

 Pacific Northwest Laboratory FIN B-2370 PNL-4507 82/12/31

 Bivision of Accident Evaluation 43pp Available at NRC \$4.75

 16527 019
- GP12220204 NUREQ/CR-2723
 ESTIMATES OF THE FINANCIAL CONSEQUENCES OF NUCLEAR POWER REACTOR ACCIDENTS
 STRIP.D R Sandia Laboratories FIN A-1334 SAND82-1110
 82/11/30 Division of Risk Analysis 180pp 16527 156

- 8212220228 NUREG/CR-2832
 BIOLOGICAL CHARACTERIZATION OF RADIATION EXPOSURE AND DOSE
 ESTIMATES FOR INHALED URANIUM MILLING EFFLUENTS Annual
 Progress Report April 1981-March 1982
 EIDSON A F Lovelace Diomed & Environmental Research Institute FIN
 A-1222 LMF-97 82/12/31 Division of Health, Siting &
 Environment 58pp Available at NRC \$4 75 16526 001
- BP1222023B NUREG/CR-3055
 REVIEW AND EVALUATION OF PALEOHYDROLOGIC METHODOLOGIES
 FOLEY,M G. ZIMMERMAND A., DOESBURG.J M Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN B-2220 PNL-4346
 B2/12/31 Division of Waste Management 74pp Available at NRC
 \$5 50 16526 058
- BP12220249 NUREO/CR-2995
 CANADIAN SETSMIC AGREEMENT Annual Report (1 July 1981-30 June 1982)
 LYANS.J A. HETMILLER.R J. ANDERSON.F Canadian Commercial Corp
 FIN B-6275 G2/11/30 Division of Health, Siting & Environment 32pp Available at NRC \$4.50 16526 152
- GP12R2O265 NUREO/CR-R526
 LOCA SIMULATION IN NRU PROGRAM Data Report For Thermal-Hydraulic Experiment 2 (TH-2)
 MOHR.C L., HESSON, G M., KING, L. L. Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN 0-2277 PNL-4164 62/11/30
 Division of Accident Evaluation 158pp Available at NRC \$6.50
- GPJ2220282 NUREG/CR-2558
 CONTEMPT 4/MOD 3: A MULTICOMPARTMENT CONTAINMENT BYSTEMS
 ANALYSIS PROGRAM
 CHENG.T C METCALFEL J HARTMAN, J E EQ&G, Inc FIN A-6439
 EGG-2159 82/2/31 Division of Bystems Integration (post
 B11005) 213pp 16525 053
- 8712220291 NUREO/CR-2927
 NUCLEAR POWER PLANT ELECTRICAL CABLE DAMAGEABILITY
 FXPERIMENTS
 LUKERS, L L Sandia Laboratories FIN A-1010-2 SANDB2-0236
 82/11/30 Division of Engineering Technology 44pp 16523 263
- G7:2220341 NUREG/CR-2875
 COMPARISON OF RADON DIFFUSION COEFFIENTS MEASURED BY
 TRANSIENT-DIFFUSION AND STEADY-STATE LABORATORY METHODS
 NIELSON, K K , RICH, P C , ROGERS, V C
 FIN D-2269 PNL-4370 82/11/30 Haste Management Branch 43pg
 Available at NRC 44 75 16525 009
- B:12220509 NUREQ/CR-2423

 MATHEMATICAL SIMULATION OF SEDIMENT AND RADIONUCLIDE
 TRANSPORT IN ESTUARIES

 OXISHI, Y. TRENT, D.S. Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN B-2271 PNL-4107 B2/11/30 Division of Health,
 Siting & Environment 81pp Available at NRC \$5 00 16525 266
- GP12220513 NUREG/CP-0033 V01
 PROCEEDINGS OF THE WORKSHOP ON CONTAINMENT INTEGRITY June
 7-9,1982
 SEBRELL, W.A. Sandia Laboratories SAND82-1659 B2/11/30 Office
 of Nuclear Regulatory Research, Director 368pp, 16524 CO1
- B212230073 Notification of commencement of 30-day review of FES re licensing requirements for Land disposal of radwasts * Oregon, State of 82/11/22 ip 16544 338
- 8212230081 Forwards "Licensing Requirements for Land Disposal of Radwaste," FES Comments due in 3 wks W/o encl OATCH.F B Maryland, State of 82/11/24 NRC No Detailed Affiliation Olven 1p 16544 326
- 8212230092 Advises of commencement of review of "Licensing Requirements for Land Disposal of Radwaste," FEB DAVISON,A Illinois, State of 82 11 22 60 82/12/06 NRC - No Detailed Affiliation Given Ip 16544 324
- BR12230388 Responds to B21026 request for info on low level was te disposal & 10CFR61 NUREG-0782. "DEB for 10CFR61," will be forwarded SCARANO,R A Low Level Haste Licensing Branch WMLL.411 4 B2/11/17 FERRARA,H R Massachusetts Institute of Technology ip 16540.239
- B212270033 NUREQ/CR-2801 V01
 TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING REFERENCE
 LIGHT WATER REACTORS FOLLOWING POSTVLATED ACCIDENTS Main
 Report
 MURPHY, E S , HOLTER, G M Battelle Memorial Institute, Pacific
 Northwest Laboratory FIN B-1171 PNL-4247 92/11/30 461pp.
 14549 001

8212270058 NUREC-0540 VD4 NO7 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE July 1-31, 1982 Division of Technical Information & Document Control | 82/11/30 P12270420 NUREG/CR-3077

HARRH-3 CODE VERIFICATION PROCEDURE

GIESEKE, J A . LEE', K W . JORDAN, H Battells Memorial Instituts.

GOIMBUS Laboratories FIN A-4063 BM1-2030 B2/11/30 Gff.cs

of Nuclear Regulatory Research, Director Sipp Available at NRC
44 75 16572 001 0212270420 NUREG/CR-3077 8P12270145 MUREO/CR-2978

EXPERIMENT DATA REPORT FOR LOFT ANTICIPATED TRANSIENT
HITHOUT SCRAM EXPERIMENT 19-4
BATT, D. L. DIVINE J. H. MCKERNA K. J. EG&G. Inc. FIN A-6043
EGG-2227 82/11/30 Office of Nuclear Regulatory Research,
Director 87pp 16550 001 BP12270435 NUREO/CR-2641
THE IK-PLANT RELIABILITY DATA BABE FOR NUCLEAR POWER PLANT
COMPONENTS Data Collection And Methodology Report
DRAGO.JP, SORKOWSKI,R J, PIKE,D H Oak Ridge National Laboratory
FIN B-0445 DRNL/TH-8271 82/11/30 Division of Risk Analysis
72pp 16571 089 821227015A NURED/CR-28A5 7) 2270156 NUBED/CR-2865 HYDROGEN CORBUSTION IN AGUEDUS FOAMS BAER.H R . GRIFFITHS.5 K . SHEPHERD, J E Sandia Laboratories FIN A-1336 SAND82-0917 82/11/30 Division of Engineering Technology 73pp 16553 249 8912270441 NUREG/CR-2900
PREDICTED RATES OF FORMATION OF IODINE HYDROLYSIS SPECIES
AT PH LEVELS CONCENTRATIONS AND TEMPERATURES ANTICIPATED IN 0212270165 MUREQ/CR-1935 QUANTITATIVE FAULT TREE ANALYSIS USING THE SET EVALUATION AT PH LEVELENTS CONCENTRATIONS HAVE THE EMBORISH THE TENDENTS BELL J T . LIETZKE, M H , PALMER, D A OAk Ridge National Laboratory FIM B-0453 ORNL-5876 82/11/30 Office of Nuclear Regulatory Research, Director 70pp 16571 021 PROGRAM (SEP) rmusmam (SEP) OLMAN, M.D. Sandia Laboratories FIN A-1241 SANDBO--2712 B2/11/30 Division of Rist Analysis 50pp 16555 267 8212270174 NUREG-0580 VII NII RECOLLATOR LICENSING STATUS SUMMARY REPORT Data as of November 30, 1982 (Blue Boot)

Management Information Granch 82/12/31 70pp 16551 203 BP12270443 NUREO/BR-0025 VOBNII INFORMATION REPORT ON STATE LEGISLATION KERR, O W Office of State Programs, Director Detailed Affiliation Given 17pp 14566 339 NRG - N. 82/12/31 8212270181 NUREC-0918 PREVENTION AND MITIOATION OF STEAM GENERATOR WATER HAMMER EVENTS IN PER PLANTS ANDERSON, N R , HAN. J T Division of Safety Technology 82/11/30 37pp Available at NRC 44 50 16551 162 5212270449 NUREG/CR-2716 VO2
REACTOR BAFETY RESEARCH PROGRAMS Quarterly Report,
April - June 1982
BDLER, S K Battelle Memorial Institute, Pacific Northwest
Laboratory FIN 8-2101 PM-4275-2 82/11/30 Office of Nuclear
Regulatory Research, Director 70pp Available at NRC \$5 00
16556 229 8012270221 NUREG/CR-3020 SELECTED REVIEW OF REGULATORY STANDARDS AND LICENSING ISSUES FOR NUCLEAR POWER PLANTS FOR NGCLEAR PURER PLANTS STEVENSON, J D. THOMAS, F.A. Stevenson & Associates FIN 8-6769 82/11/30 Division of Engineering Technology 488pp 16552 Oct BP12270454 NUREG/CR-2961
EXPERIMENT DATA REPORT FOR SEMISCALE MOD-2A PRIMARY FEED AND BLEED EXPERIMENT SERIES (TESTIS 5-5R-1 AND 5-5R-2)
FOODALLS P E046, Inc FIN A-6030 E00-2225 82/[1/30 of Nuclear Regulatory Research, Director 64pp 16572 060 Defica 8212270232 NUREO/CR-2601 VO2 TECHNOLOGY, SAFETY AND COSTS OF DECOMMISSIONING REFERENCE LIGHT WATER REACTORS FOLLOWING POSTULATED ACCIDENTS Appendices
MURAHY:E 5. HOLTER.O M Battalia Memorial Institute, Pacific
MURAHY:E 5. HOLTER.O M Battalia Memorial Institute, Pacific
Northwest Laboratory FIN B-1171 PM-4247 82/11/20 Div
of Enganeering Technology 624pp 16554 8P12270456 NUREO/CR-2894
CONSOLIDATION THEORY AND ITS APPLICABILITY TO THE DEWATERING
AND COVERING OF URANIM MILL TAILINGS
CATES. T E Battelle Hemorial Institute, Pacific Northwest
Laboratory FIN 8-2370 PNL-4402 82/11/30 Office of Nuclear
Regulatory Research, Director 48pp Available at NRC \$4 78
16566 294 GP12270243 NUREQ-0606 VO4 NO4 UNRESGLYED SAFETY ISSUES SUMMARY Data As Of November 19, 1982 (Aqua Boot)

Office of Resource Management, Director 82/12/01 50pp 8P12270459 NUREG-0713 VO3 OCCUPATIONAL RADIATION EXPOSURE AT COMMERICAL NUCLEAR POWER REACTORS - 1981 BRDOKS:8 0 Management Information Branch 92/11/30 118F 8212270414 FOIA request for documents re proposed revision \$/or update to reactor safety study referred to in MUREO-0784. Chapter IQ as RS II & all documents pertaining to discussion of reactor Management Information Branch 82/11/30 Available at NRC as KB 11 w all documents percaining to discussion topling method SHOLLY:S C Union of Concerned Scientists & Division of Rules and Records 1p 16549 232 8P1227046B NUREC/CR-2970 VOI MATERIALS SCIENCE DIVISION LIGHT-WATER REACTOR SAFETY RESEARCH PROGRAM Guarterly Progress Report * Argonns National Laboratory FIN A-2016 ANL-82-41 Division of Accident Evaluation 131pp 16570 102 82/11/04 FELTON. J M 02/11/30 8.º12270418 Responds to FDIA request for documents re proposed revision X/or update to reactor safety study referred to in NUREG-0784.Chapter 10 as RS II & all documents pertaining to reactor cooling methods Forwards documents listed in app FELTO'S.J M. Division of Roles and Records 82/11/26 SHOLLY.S C Union of Concerned Scientists 3pp 16549 233 24X Fiche 50-000.82/11/26.8212270418 BP122704B7 NUREO/CR-276B LITERATURE REVIEW OF MODELS FOR ESTIMATING SOIL EROSION AND DEPOSITION FROM WIND STRESSES ON URANIUM MILL TAILINGS COVERS
BANDER: T J Battelle Memorial Institute, Pacific Northwest
Laboratory FIN 8-2370 PNL-4302 82/11/30 Division of Health.
Siting & Environment 27pp Available at NRC \$4 50 16548 27H -- B212270471 Expresses concerns re clarity of NUREO-0626 concerning features of relief valves & disadvantages & advantages of pilot operated valves & bleed & feed effect on core cooling by natural circulation

BENDER: M ACRS - Advisory Committee on Reactor Safeguards

80/03/04 FRALEY:R F ACRS - Advisory Committee on Reactor

Safeguards 1p 16549 274 8212270492 NUREG/CR-2797 EVALUATION OF EVENTS INVOLVING SERVICE WATER SYSTEMS IN NUCLEAR POWER PLANTS NUCLAR FUNER FLANIS
HARIED, J.A. Dak Ridge National Laboratory FIN B-0755
URNL/NSIC-207 B2/11/30 Division of Safety Technology
Available at NRC \$5 00 16548 164 6900 --8212270438 Comments on NUREC-0739, "Approach to Quantitative Safety Goals for Nuclear Power Plants" Info provided by D Okrent & H Oriesmeyer to Aff relevant to Aff questions FRALEY.R F ACRS - Advisory Committee on Reactor Safeguards 81/09/15 REMICK.F J Interoffice Steering Group on Development of a Safety Goal Ip 16547-235 8212270499 NUREQ/CR-2948 19270499 NUREO/CR-2948
SIGNIFICANCE OF NICKEL AND COPPER CONTENT TO RADIATION
SENSITIVITY AND POSTIRRADIATION HEAT TREATMENT RECOVERY OF
REACTOR VESSEL, STEELS
HAWTHORNE, J. R. ENSA, Inc. FIN B-8193 MEA-2004 92/[1/2]
NO Detailed Affiliation Given 26pp 16548 137 82/11/30 NRC --8212270442 Forwards "Discussion of Some Comments on NUREQ-0739," in response to AIF Committee on Reactor Licensing & Safety GNIESKEYER, J H, DKRENT, D ACRS - Advisory Committee on Reactor Safeguards GI/09/II GIBBS.C Atomic Industrial Forum Ip. 8212270505 NUREO-0020 VO6 NO7 LICEMSED OPERATING REACTORS STATUS SUMMARY REPORT Data As of June 1982 (Grey Book) * Management Information Branch 82/11/30 374pp. 165



- GE:12270512 NUREG/CR-2845
 DIGRD AN INTERACTIVE GRID GENERATING PROGRAM
 FOOTE, H P. RICE, W A., KINCAID, C T. Battells Memorial Institute,
 Pacific Northwest Laboratory FIN 8-2272 PNL-4345 62/11/30
 Usvision of Health, Siting & Environment 6ipp Available at NRC
 \$5.00 16588 079
- G2:12270520 NUREG/CR-2982
 BUOYANCY.TRANSPORT.AND HEAD LOSS OF FIBROUS REACTOR
 INSULATION
 BROCARD.D N Alden Research Laboratory SAND82-7205 82/11/30
 Division of Safety Technology S9pp 16548 017
- GP12270559 NUREG/CR-2917
 REVIEW OF GROUND-MATER FLOW AND TRANSPORT MODELS IN THE UNSATURATED ZONE
 OSTER.C A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2220 PNL-4427 82/11/30 Division of Waste Management 175pp 16546 042
- 8P12270561 NUREG/CR-1522
 COOLING WATER CHLORINATION THE KINETICS OF CHLORINE, BROMINE
 AND AMMONIA REACTION IN SEA WATER
 JOHNSON, J D . INMAN, G W . TROFE, T W North Carolina, Univ of Fly
 B-6248 82/11/20 Division of Health, Siting & Environment
 121pp 16546 217
- BP12280520 Final response to FOIA request for documents re proposed version &/or update to reactor safety study referenced in NUREO-0784.Chapter 10 as RS II & documents re reactor cooling method No addI documents located FELTON. J H Division of Rules and Records \$2/12/07 BHOLLY, S C Union of Concerned Scientists 1p 16593 028
- 82:12280535 Advises that FES on 10CFR61. "Licensing Requirements for Land Dispotal of Radwaste," received Status of review will be provided in 22 days # Mississippi. State of MS821123-004 82/12/06 NRC - No Detailed Affiliation Given ip 16593 052
- 87:12:80542 Certifies state clearinghouse received FES on 10CFR61 Commenting agencies will review responses to comments on DES ROBERTS,T California State of 81112007 82/11/22 SMITH,R D Low Level Waste Licensing Branch 1p 16593 048
- 212280543 Advises that FES on 10CFR61 received & assigned 30-day
- G212280543 Advises that FES on 10CFR61 received & assigned 30-day review period Appropriate review agencies will comment directly to NRC BUTKO.K J New Jersey, State of NJB2-771 B2/11/23 Office of Nuclear Material Safety & Safeguards, Director 1p 16593 022
- 8212270188 Forwards CEN-227, "Summary Rept on Operability of Pressurized Safety Valves in C-E Designed Plants," in response to NUREO-0737, Item II D 1 W/o encl WELLS,R W C-E Operating Plants Cumers Oroup WELLS,R W Northeast Utilities RW-82-70 82/12/20 BERNARD,H Standardization & Epecial Projects Branch 2pp 16578 055

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- B2:08190240 IE Bulletin B2:03. Revision 1, "Stress Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BMR Plants "Svc list encl
 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 82/10/28 Consolidated Edison Co of New York, Inc 112pp 16462 163 24X Fiche 50-000: 82/10/28.8208190240
- EPOBI90245 IE Info Notice 82-42, "Defects Observed in Panasonic Model 801 & Model 802 Thermoluminescent Dosimeters " Svc list enc!

 COBB.L. I Division of Fuel Facilities, Materials & Sefeguards 62/11/05 Consolidated Edison Co of New York, Inc 110pp 16372 142 24X Fiche 50-000.82/11/05.8208190245
- 8208190251 IE Info Notice 82-44. "Clarification of Emergency Plan Exercise Requirements " Svc list encl JORDAM, E. L. Division of Engineering & Quality Assurance 82/11/18 Consoludated Edison Co of New York, Inc. 109pp. 16411 199 24X Fiche 50-000, 82/11/18,8208190251
- 8208190256 IE Info Notice 82~46, "Defective & Obsolete Combination Padlocks " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/11/26 Consolidated Edison Co of New York, Inc 127pg 16411 065 24X Fiche 50-000.82/11/26,8208190256

- 8208190257 IE Info Notice 82-47. "Transportation of Type A Quantities of Non-Fissile Radioactive Matl " Svc list enc! COBB.L I Division of Fuel Facilities. Materials & Safeguards 82/11/30 Consolidated Edison Co of New York. Inc 354pp 14387 028 24X Fichs 50~000.82/11/30.8208190257
- B20B190259 lE Bulletin B2-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " Svc list encl DEYQUNG.R C Director's Office, Defice of Inspection and Enforcement B2/12/03 Consolidated Edison Co of New York, Inc 113pp 16411 317 24% Fiche 50-000 82/12/03,8208190259
- 8208190261 IE Info Notice 82-48, "Failures of Agastat CR 0095 Relay Sockets " Svc list enci JORDAN.E L. Division of Engineering & Quality Assurance 82/12/03 Consolidated Edison Co. of New York, Inc. 110pp. 16462-064 24X Fiche 50-000.82/12/03.8208190261
- 8208190867 IE Info Notice 82-49, "Correction for Sample Conditions for Air & Gas Monitoring " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement BA/12/16 Consolidated Edison Co of New York, Inc
 127pp 16628 191 24X Fiche 50-000.82/12/16.8208190267
- BD08170268 IE Info Notice 82-50, "Mod of Bolid State AC Undervoltage Relays Type ITE-27" Svc list encl JORDAN,E L Division of Engineering & Quality Assurance 82/12/20 Consolidated Edison Co of New York, Inc 108pp 16628 273 24 Fiche 50-000,82/12/20,8208170268
- 8212010213 Responds to approval request for info collection re notices, instructions & rept to workers concerning insps.100FR19 Request approved through 851130 under OMB Number 3150-0044, per Paperwork Reduction Act
 SCURRY, N Office of Management & Budget OMB 3150-0044 82/11/24 SCOTT.6 Document Management Branch 2pp 16271 256
- 8212010219 Responds to approval request for info collection re IE bulletin: "Deficiencies in Primary Containment Electrical Penetration Assemblies" Request approved through 851130 under CIMB Number 3150-0094, per Papero
- 8212010241 Responds to approval request for info collection re 10CFR70 concerning domestic licensing of SNM Request approved through 831231 under OMB Number 3150-0009, per Paperwork Reduction Act SCURRY, N Office of Management & Budget OMB 3150-0009 82/11/19 SCOTT, S Document Management Branch 2pp 16271 260
- 8212010247 Responds to approval request for info collection re 1000R30 concerning domestic licensing of byproduct matl Request approved through 821231 under QMB Number 3150-0017, per Paperwork Reduction Act
- Paperwork Reduction Act
 SCURRY,N Office of Management & Budget QMB 3150-0017 82/11/19
 SCOTT-S Document Management Branch 2pp 16271 262
- B212010253 Responds to approval request for info collection re 100FR40 concerning domestic licensing of source mati Request approved through B30831 under OMB Number 3150-0020, per Pagerwork Reduction Act Budget OMB 3180-0020 82/11/19 SCOTT, B Document Management Branch 2pp 16271 264
- 8212010296 Responds to approval request for info collection re 100FR50 concerning domestic licensing of production & utilization facilities Request approved through 850430 under OMB Number 3150-0011, per Paperwork Reduction Act SCURRY.N Office of Management & Budget OMB 3150-0011 82/11/19 SCOTT, B Document Management Branch 2pp 16271 266
- 8212020380 Comments on proposed topic definitions & associated cost estimate for BEP.Phase III Review of need for program in light of analysis of 82P Phase II & changes made through regulatory initiatives since Nov 1977 encouraged CAQNETTALJ P Atomic Industrial Forum 82/10/19 EIBENHUT, D Q Division of Licensing. 68pp 16278: 022
- 8212070342 Informs of redirection of LOFT program Sufficient financial support evailable for DDE to proceed w/formation of intl LOFT consortium Forwards NRC/DDE interagency agreement on LOFT program responsibility PALLADIND, N J Commissioners, 82/11/22 BEVILL, T House of Rep , Appropriations, 1p 16356,247
- --8212070351 Informs of redirection of LOFT program Sufficient financial support available for DOE to proceed w/formation of inti LOFT consortium. Forwards NRC/DOE interagency agreement on LOFT program responsibility PALLADING.N.J. Commissioners. 82/11/22 UDALL,M. House of Rep., Interior & Insular Affairs 1p 16356:248

- --B212070359 Informs of redirection of LOFT program Sufficient financial support available for DDE to proceed w/formation of inti LOFT consortium forwards NRC/DDE interagency agreement on LOFT program responsibility PALLADINO, N. J. Commissioners B2/11/22 BIMPSDN, A. Benate, Environment & Public Norks 1p. 16385-249
- -B212070368 Informs of redirection of LDFT program Sufficient financial support available for DDE to proceed w/formation of intl LOFT consortium Forwards NRC/DDE interagency agreement on LDFT program responsibility PALLADIND, N J Commissioners 82/11/22 HATFIELD, N O Senete, Appropriations ip 16356-250
- --82(2070372 Informs of redirection of LOFT program Sufficient financial support available for DOE to proceed w/formation of intl LOFT consortium Forwards NRC/DOE interagency agreement on LOFT program responsibility PALLADINO, N J Commissioners 82/11/22 OTTINGER, R L House of Rep , Energy & Commerce ip 16356 251
- --8212070378 Interagency agreement re LOFT program responsibility between NRC & DDE Responsibilities & obligations of parties for operation of LOFT facility delineated DIRCKS: W J Office of the Executive Director for Operations BREWER: 6 T Energy, Dept of 82/11/22 2pp 16336-252
- 8212080227 IAEA-CN-42/253
 "Regulatory Perspective of Role of Const in Revitalizing
 US Nuclear Industry "
 STELLO, V. Regional Operations & Generic Requirements 82/12/02
 11pp 16367-124
- 8212210497 Forwards request for DMB review & supporting statement reproposed rule to IOCFR80 34(x) concerning fitness for duty NCRRY, P G Office of Administration 82/12/15 SCURRY, N Office of Management & Budget 2pp 16539 347
- 8212210505 Forwards requests for OMB review & supporting statement re extension of OMB clearances for NRC Forms 212, "Qualifications Investigation (Professional)" & 252A "Qualifications Investigation (Secretarial/Clerical)" NORRY-P O Office of Administration 82/12/15 SCURRY, N Office of Management & Budget ip 14543 001

PR PROPOSED RULE

- 82:11:60074 Forwards draft notice of proposed rulemaking 10CFR170 re proposed revision of license fee schedules NORRY.P O Office of Administration 82/11/02 STOCKMAN.D A Office of Management & Budgek 64pp 16:102,230
- 8212020118 Comments on proposed rule 10CFR34 re third party certification of industrial radiographers Opposes rule if certification allowed only by party outside of Navy Rule not opposed if permitted by Navy party independent of users HENDRIX.O W Navy, Dept of, Naval Facilities Eng Command 47FR19182 091 82/11/19 Docketing & Services Branch 4p; 16272 043
- 9212020125 Comments on proposed rule 10CFR50 which would require licensees to compare & evaluate facility against so-called SRP acceptance criteria & justify any deviations Opposes rule PARKYN, J D Affiliation Unknown 47FR47017 001 92/11/19 Docketing & Services Branch 1p 14272 039
- B212020134 Comments on proposed rule IOCFR50. "Applicability of License Conditions & Tech Specs in Emergency " Bupports rule SAMDRY, N A Professional Reactor Operator Society 47FR35996 034 82/11/19 Docketing & Bervices Branch 3pp 16272 033
- B212020154 Comments on proposed rules 10CFR30,40 & 70 re licenses responsibility for nuclear matts & procedures for termination of specific licenses
 BD0DEN,0 Western Nuclear, Inc. (subs of Phelps Dodge Corp.)
 47FR47400 002. B2/11/16 Docketing & Services Branch 2pp.
 16274 172
- 2212020166 Comments on proposed rule 10CFR20 re performance testing for personnel desimetry * National Council on Radiation Protection & Measurements 45FR18023 074 92/11/26. NRC No Detailed Affiliation Given 38pp. 16274

- 87:2020182 Comments on proposed rules 10CFR30.40 & 70 re licensee responsibility for nuclear matls & procedures for termination of specific licenses Rule should be revised to reflect activities covered by OL issued under Part 50 CLAYTON-F L Alabama Power Co 47FR47400 001 82/11/05 Docketing & Services Branch 2pp 16274 094
- 8212020238 Comments on proposed rule 10CFR2 re immediate effectiveness rule for CPs Opposes rule EDDLEMAN, W. Affiliation Unknown 47FR47260 004 82/11/19 NRC -No Detailed Affiliation Given 2pp 16274 155
- B212020242 Comments on proposed rule 10CFR2 re immediate effectiveness rule Supports rule Rule should be reinstated w/applicability to const stage & OL stage proceedings BRADBURY:R B Stone & Webster Engineering Corp 47FR47260 001 82/11/17 Docketing & Services Branch 2pp 16274 147
- 8212020251 Package of four comments supporting proposed rule 1001-R20 re personnel dosimetry processing accreditation program MOUNT, D K North Dakota, State of RUTLEDGE, B G Georgia, State of, Dept of Human Resources WONG, G C California, State of 47FR20493 82/11/29 PALLADINO, N J Commissioners 4pp 16279 355
- 8212020359 Comments on proposed rule 10CFR2 re Commission review procedures for power reactor CPs hearings Supports rule KEARNEY, J J Edison Electric Institute 47FR47260 007 82/11/24 CHILK 8 J Docketing & Services Branch 10 16280 359
- 8212020363 Comments on proposed rule 10ffR2 re immediate effectiveness rule for CP hearings Opposes rule * Union of Concerned Scientists 47FR47260 006 82/11/24 Office of the Secretary of the Commission 8pp 16278 122
- B212020366 Comments on proposed rule 10CFR2 re immediate effectiveness rule re review of ASLE CP decisions Opposes rule DUCMTY. J Seacoast Anti-Pollution League 47FR47260 005 B2/11/22 CHILK, Ø J Office of the Secretary of the Commission Ppp 16278 138
- B212020372 Comments on proposed rule 10CFR2 re review procedures fol CPs & LNAs Supports rule SCHERER,A E Combustion Engineering, Inc. 47FR47260 002 B2/11/19 Docksting & Services Branch 1p 16278 120
- 8212020375 Comments on proposed rule 10CFR2 re immediate effectiveness element for power reactor CPs Supports rule PARKYN, J D Affiliation Unknown 47FR47260 009 82/11/19 Office of the Secretary of the Commission Ip 16288 357
- 8212020378 Comments on proposed rule 10CFR2 re immediate effectiveness rule of ASLB decisions in CP hearings Opposes rule DUMERTY.D F Oulf Coast Environmental Defense Foundation, Inc 47FR47260 008 82/10/25 Defice of the Secretary of the Commission 3pp. 16278 099
- 8212020383 Comments on proposed rule 10CFR2 re immediate effectivenrss rule for CP hearings Opposes rule READ DF North Carolina, Univ of 47FR47260 003 82/11/17 Docketing & Services Branch 1p 16278.119
- 8212080575 Notifies of Commission proposal to amend regulations in IOCFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects
 NDRRY, P Office of Administration 82/11/03 UDALL, M K House of Rep , Interior & Insular Affairs 2pp 16368 333
- 8212080578 Notifies of Commission proposal to amend regulations in iOCFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects
 NURRY, P Office of Administration 82/11/03 MOFFEYT, T House of Rep , Government Operations 2pp 16368 328
- 8212080585 Notifies of Commission proposal to amend regulations in 10CFR170, revising fees charged for facilities & matls insp & review of applications for permits, licenses, amends, renewals, topical repts & special projects NORRY. P Office of Administration 82/11/03 SIMPSON, A House of Rep., Environment & Public Works 2pp 16368 326
- 8212080574 Discusses Commission proposal to amend regulations in IOCFR170, revising fees charged for facilities, matl insp. review of applications for permits licenses, amends, renewals, topical repts & special projects
 NORRY, P 0 Office of Administration 82/11/03 OTTINGER, R L House of Rep., Energy & Commerce 2pp 16368 283

- 8212160098 Ack receipt of 821005 comments on proposed rule 100FR60, "Technical Critoria for Disposal of High Level Radwaste in Geologic Repositories" Concerns & recommendations will be considered prior to issuance of final technical critoria DIRCKS.H J. Office of the Executive Director for Operations 46FR35280 090 82/10/21 MUNITZING,L M. American Nuclear Society Lp. 16446 1446
- BP12160216 Comments on proposed rule 10CFR50 re applicability of license conditions & Tech Specs in emergency attuations Supports rule COUNSIL, W 0 Connecticut Yankee Atomic Power Co COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W 0 Northeast Utilities 47FR35976 035 82/11/24 Docksting & Services Branch 2pp 16446 129
- 82:12160394 Package of two comments supporting proposed rule 100FR20 re accreditation of personnel dosimetry svcs GERUSKY,T K Pennsylvania, State of WARREN,D M, HDWARD, B N Utah, State of 45FR20493 82/12/06 PALLADINO,N J Commissioners 6pp 16442 284
- BB12160422 Comments on proposed rule 10CFR20 re accreditation of personnel dosimetry sycs Bupports rule HAZLE.A J Colorado, State of 45FR20493 074 B2/11/16 PALLADINO,N J Commissioners ip 16442 146
- B212140431 Comments on proposed rule 10CFR2 re immediate effectiveness of licensing boards decisions Recommends Commission adopt full reinstatement of original rule for all licensing actions COMAN, B Z Atomic Industrial Forum 47FR47260 011 82/11/27 Docketing & Services Branch 2pp 14442 130
- BP12160434 Comments on proposed rule 10CFR2 re immediate effectiveness of licensing boards decisions No change to proposed rule recommended MARRACK D Affiliation Unknown 47FR47260 010 82/11/22 PALLADINO, N Commissioners 1p 16442 086
- BP12160918 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Recommends reporting requirements be eliminated CCHEN.C B. Rado Watch Co., Inc. 47FR52719 002 82/11/29 Docketing & Services Branch ip 16442 116
- Q:12160524 Comments on proposed rule 190FR32 re change of record submission requirements from annual base to 5-yr plan Supports rule LESLIE: W G Northern Telecom 47FR52719 004 02/12/03 Office of the Secretary of the Commission ip 16442 115
- G212160930 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Supports tule COLE, D United Co (substant Ecodyne Corp.) 47FR92719 003 G2/11/30 Docketing & Services Branch ip 16442 114
- 8212160532 Comments on proposed rule 10CFR32 re-modified record keeping & transfer reporting requirements Opposes rule Requests
 licensing of small usors be terminated
 SIEGRISTIN Glycine-Sales & Service 47FR52719 001 82/11/29
 Docketing & Services Branch ip 16442 113
- 6212160338 Comments on proposed rule 10CFR32 re change of record submission requirements from annual to 5-yr plan Opposes rule HEIDER.M J Talley Industries, Inc. 47FR52719 005 82/12/03 Docketing & Services Branch 1p. 16442 111
- 621.2200003 Comments on proposed rule 10CFR2 re issuance of CP or LWA based on limited NRC review of ASLB decision Bupports rule BGUCHEY.G D Hashington Public Power Bupply Bystem 47R47260 012 B2/12/07 Docketing & Services Branch 1p 16474 039
- 8212200010 Comments on proposed rule 19CFR2 specifically authorizing issuance of notice of violation to nonlicensees Commission should provide list of situations where NRC has statutory authority over nonlicensees REYNGLDS.N S Debevoise & Liberman 47FR51402 002 82/12/13 CM(KK S J Office of the Secretary of the Commission 3pp 1AA37 002
- 8212200016 Comments on proposed rule 10CFR32 re degree of public exposure to radiation from byproduct matl Opposes rule ENGELMANN.J H Miles Laboratories. Inc 47FR52719 006 82/12/09 Docketing & Services Branch 3pp 16473 082,

- 8212200023 Comments on proposed rule 10CFR2 specifically authorizing issuance of notices of violations to monlicenses Rule should be revised to specifically exclude util employees from rule LEMPOES, T.E. Niagara Mchawk Power Corp. 47FR51402 002 92/12/10 CHILK, S.J. Office of the Secretary of the Commission. 2pp 14377.3GR
- B212200029 Comments on proposed rule 10CFR50 re guidance for implementation of SRP rule Eupports rule GIBBON.L S. Consumers Power Co. 47FR47019 004 B2/12/09 Docksting & Bervices Branch 1p. 16473 350
- 8212200036 Package of two comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule KOESTER.9 L. Kansas Oas & Electric Co. BDUCHEY.G D. Washington Public Power Supply System 47FR7019 82/12/10 Docketing & Services Branch. 3pp. 16474-001
- 8212200045 Comments on proposed rule 10CFR50 re proposed guidance for implementation of SRP rule, NUREG-0706 Rule imposes requirements for performance of excessive analysis & evaluation efforts when relation to SRP not clear BRADBURY.R B Stone & Wabster Engineering Corp 47FR47019 005 82/12/10 Docketing & Services Branch 2pp 16470 005
- 8212200046 Comments on proposed rule 100FR170 re revisions of license fee schedules Reconsideration urged to assure that achedule of fees be announced only after mgt controls in place BERNATH.L San Diego Gas & Electric Co 47FR52454 001 B2/12/09 Docketing & Services Branch 2pp 16470 004
- B212200053 Comments on proposed rule 10CFR170 re revisions of license fee schedules Opposes rule Charges should be made on actual cost basis DIETZ.G R Isomedix, Inc (Subs of Masefield Enterprises, Inc.) 47FR52404 002 B2/12/09 Docketing & Services Branch 19
- B21220D073 Corments on proposed rules 10CFR30,40 & 70 re licensed responsibility for nuclear matts & procedures for termination of specific licenses BOUCHEY,0 D Washington Public Power Supply System 47FR47400 003 82/12/07 Docketing & Services Branch 19 16474 309
- 8212230073 Notification of commencement of 30-day review of FES re licensing requirements for land disposal of radwaste # Oregon, State of 82/11/22 ip 16544 338
- 8212230081 Forwards "Licensing Requirements for Land Disposal of Radwaste," FES Comments due in 3 wks W/o encl CATCH,FB Maryland, State of 82/11/24 NRC ~ No Detailed Affiliation Given ip 16544 326
- 8212230072 Advises of commencement of review of "Licensing Requirement: for Land Disposal of Radwaste," FEB DAVISON.A Illinois, State of 82 il 22 60 82/12/06 NRC - No Detailed Affiliation Given 1p 16544 324
- 8212280535 Advises that FES on 10CFR41, "Licensing Requirements for Land Disposal of Radwaste," received Status of review will be provided in 22 days

 * Mississippi, State of MSB21123-004 82/12/04 NRC No Detailed Affiliation Given 1p 16593 052
- B212280542 Certifies state clearinghouse received FES on 10CFR61 Commenting agencies will review responses to comments on DES
 - DES ROBERTS,T California, State of 81112007 82/11/22 8MITH,R D Low Level Waste Licensing Branch 1p 16593 048
- B212280543 Advises that FES on 10CFR61 received & assigned 30-day review period Appropriate review agencies will comment directly to NRC BUTKO, K J New Jersey. State of NJ82-771 82/11/23 Office Nuclear Material Safety & Safeguards, Director. 1p. 16593 022
- PRM PETITION FOR RULEMAKING
- B212020243 Comments on petition for rulemaking PRM-34-3 re maintaining record of radiographic survey Supports petition
 VINCENT,R E Chicago Bridge & Iron Co 47FR52722 82/09/27
 Docketing & Services Branch. 2pp. 16274 102
- B212020247 Notice of receipt of patition for rulemaking PRM-40-24 fro Union Carbide Corp re disposition of tailing or waste from U milling operations CHILKS J. Office of the Secretary of the Commission. 47FR53889. 82/11/23

- 8212020265 Comments on getition for rulemaking PRM-50-35 re public intervention if emergency plans not adequate Supports Destition
 TAYLOR: T Affiliation Unknown 47FR51889 034 82/11/27
 CHILK: 5 J Office of the Secretary of the Commission I
- 8212020269 Comments on petition for rulemaking PRN-50-35 re amend of amergency planning rule Supports petition
 FLACK.0 Flack,0 47FR51889 033 82/11/19 CHILK.S J Office of the Secretary of the Commission ip 16279 359
- 8212020277 Package of two comments supporting petition for rulemaking PRM-50-35 re adjudicatory hearings on emergency planning issues prior to full power operation KLINE.C., Hannow, B., CURRAN, J. Affiliation Unknown 47FR51889 82/11/22 CHILK, S.J. Office of the Secretary of the Commission 5pp 16288 245
- 8212020279 Forwards petition for rulemaking PRM-40-24 re disposition of tailings & waste from U milling operations BUDNICK,C L. Union Carbide Corp. 47FR58889 82/09/29 CHILK,S Docketing & Bervices Branch 2pp 16275 239
- ~~8212020288 Patition for rulemaking PRM-40-24 re disposition of tailings & waste from U milling operations
 DUDNICK, C L. Union Carbide Corp 47FR53889 82/09/29 386pp
- B212020389 Comments an petition for rulemaking PRK-50-35 re UCS amend to 10CFR50, 47 to ensure rights of intervenors Supports rule DAVIS.J R Affiliation Unknown 47FR51889 032 B2/11/22 CHILK.S J Office of the Secretary of the Commission Ip
- 8212140209 Comments on petition for rulemaking FRM-50-34 re testing
- B212200057 Comments on petition for rulemaking PRM-50-35 re right of public to litigate contested emergency planning issues prior to issuance of full power CL Opposes petition STEWARTA E Lake County, CM 47FR51889 035 82/12/10 CHILK, S J Office of the Secretary of the Commission 1p 16474 253
- B212200060 Comments on petition for rulemaking FRM-04-3 re radiation surveys for radiographic exposure devices Supports petition DUPLISBEV.J F Catalytic, Inc. (subs. of Air Products & Chemicals, Inc.) 47FR52722 001 82/12/08 Docketing & Services Branch lp 16473 314

PROJ PROJECTS - PREDOCKET LICENSING

- 8912130435 Requests written confirmation that proprietary info in GNS, "Topical SAR for Castor Cast Type ISF81 (Dry Storage)," has been destroyed ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch 62. REISENWEAVER, D. Chemical Engineering Branch 1p. 16413 159
- 8212130438 Describes actions taken to destroy proprietary info in "Topical SAR for Castor Cask Type ISFSI (Dry Storage)," per Gesellschaft Fuer Nuclear Svc request ROBERTS.J.P. Advanced Fuel & Spent Fuel Licensing Branch 82/1 Advanced Fuel & Spent Fuel Licensing Branch 1p 16413.056 82/11/18
- 8312140501 Forwards CENPD-270, "Drg Storage Cast for 18FS1" SCHERER.A E Combustion Engineering, Inc. LD-82-088 62/11/11 ROUSE.L C. Advanced fuel & Spent Fuel Licensing Branch 19 16431 158
- --8212140510 CENPD-270
 - "Dry Storage Cask for ISFSI " * Combustion Engineering, Inc 82/10/31 41pp 16431 159
- B212210917 Summary of S11215 meeting w/Gesellschaft Fuer Nucklear Svc in Silver Spring, MD re submission of dry spent fuel storage cask design topical rept. Addl drop testing of Castor IC cask scheduled for Feb 1982, ROBERTS, JP Advanced Fuel & Spent Fuel Licensing Branch 81/12/16, ROBERTS, JC Advanced Fuel & Spent Fuel Licensing Branch. 30p

- 8212220511 Forwards rept re 820723-24 monitoring visit to site to become fully acquainted w/site activities & personnel Future monitoring visits will cover specific aspects in greater CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 92/12/20 HANNUM, W A Emergy, Dept of 7pp 16523 090
- 8212270473 Responds to 821127 request for review of C-E rept, "Dry Storage Cask for ISFSI" Casks conform w/GA program CENPD-210-A:Revision 3 Program reviewed in 1977 & accepted HAASS, W P Quality Assurance Branch 21665 82/12/08 ROUSE:L Advanced Fuel & Spent Fuel Licensing Branch 1p 16566 360 ROUSELL L
- 8212270496 Notification of contract execution.Mod 1 to "Reproduction of Copies Re Stanislaus Nuclear Project Unit 1.NRC Docket P-564-A " Contractor Speigel & McDiarmid & Northern CA Power Agency BMITH F A Division of Contracts NRC-10-79-391 B2/12/17 SPRINGER,M , WOOD,R Office of Administration ip 14548
- --8212270502 Mod 1.deobligating funds to, "Reproduction of Copies He Stanislaus Nuclear Project.Unit 1.NRC Docket P-564-A" * Northern California Power Agency, California State of, TRAUGER.T C Spingel & McDiarmid SMITH.P A Division of Contracts NRC-10-79-391 82/12/17 1p 16548 359
- 8212270558 Notification of contract execution Mod 1 to "Economic Consulting Svcs in Connection w/Stanislaus Nuclear Unit, Antitrust Hearing Docket P-564-A " Contractor PM Gumann SILVIS.R M Technical Assistance Contracts Branch FIN 8-4521 NRC-03-61-120 82/12/21 DENTON.H R Office of Nuclear Reactor Regulation, Director TOALSTON.A NRC No Detailed Affiliation Given 1p 16546 SJ8
- --8212270560 Mod 1. depbligating funds to "Economic Consulting Svcs in Connection w/Stanislaus Nuclear Unit, Antitust Hearing Docket P-564-A " GUTMAIN, PH Outmann, PM GUSTAVE, RP Technical Assistance Contracts Branch FIN B-6521 NRC-03-81-120 82/12/21 16546 339

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8212010002 Forwards McGraw Edison Part 21 rept re defective valve components Defective valves are limited to facilities in MARTIN T Division of Engineering & Technical Programs 82/11/05 SPESSARD R Division of Project & Resident Programs GAGLIARDD J Division of Resident, Reactor Project & Engineering Programs 2pp 16261 006
- 8212010095 fart 21 rept re changes incorporated into computer program. ADLPIRE Sample itr to client encl HOCHFELDER:E Wyly Go P721 882-730-000 82/11/05 COLLINS.J T Region 4. Office of Director 10pp 16260 307
- B212010154 Part 21 rept re verification of gap distances between bottom of guide tube & upper core plate in Failed guide tube support pins Investigation reaffirms 820927 position that no safety concern exists

 RAHE.E P Westinghouse Electric Corp PT21 82~727~000 82/11/12

 JORDAN.E L Division of Engineering & Quality Assurance 2pp 14258 079
- 8212010224 Part 21 rept re deficiency concerning pipe stress & support loads exceeding allowable limits Initially reported on 820817. Piping sys structure redesigned SARSTEN. G & United Engineers & Constructors, Inc (subs of Raytheon Co) PT21 82-735-000 82/10/21 Director's Office. Office of Inspection and Enforcement 18pp 16258 012
- 8212280362 Part 21 rept re C Sumrall allegations concerning Rockwell main steam isolation valves used in nuclear power plants investigation confirmed no evidence of reportable defect DUFFEY.D W Rockwell International Corp 82/12/17 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 7pp 14540 078

QUALITY ASSURANCE INSPECTIONS

8212070032 Forwards GA Program Insp Rept 99900300/82-01 on 820823-2/ No noncompliance noted
POTAPOVS, U. Division of Vendor & Technical Programs 82/11/08
MORIARTY, J Colt Industries, Inc. 2pp 16333 197

- --B212070036 GA Program Insp Rept 99700300/82-01 on 820823-27 No noncompliance noted Major areas inspected previous insp findings; mfg process control, procurement document control & nonconformances & corrective actions

 DLLERIR E . DARNES, I Division of Vendor & Technical Programs 62/10/25 15pp 16333 179
- B212070114 Forwards QA Program Insp Rept 99900794/82-01 on B21004-05 & notice of nonconformance PGTAPDVB, U Division of Vendor & Technical Programs B2/11/16 EGGERS, P E Ridihalgh, Eggers & Associates 2pp 16329 330
- --B212070122 GA Program Insp Rept 99900794/B2-01 on B21004-05 Noncompliance noted design control procedure not fully implemented & review check re-evaluation & verification process for REA 2023 design not fully planned & structured HCNETLL.N M. BARNES, I Division of Vendor & Technical Programs B2/11/08 7pp 16329 334
- 8212070156 Forwards OA Program Insp Rept 99900349/82-01 on 821012~14 & notice of violation & motice of nonconformance FOTAPOVS,U Division of Vendor & Technical Programs 82/11/15 EHRHARD,E R Automatic Switch Co 3pp 16333 184
- --8212070159 Notice of violation from insp on 821012-14

 * Division of Vendor & Technical Programs 82/11/15 ip
- ~-B212070162 Notice of nonconformance from insp on 821012-14 • Division of Vendor & Technical Programs 82/11/15 2pp 16333 168
- ~-8212070169 GA Program Insp Rept 99900369/82-01 on 821012-14
 Noncompliance noted revisions to production planning &
 control dept Procedure PP 468 implemented in fabrication
 process w/a notifying or forwarding to GC
 SUTTON.J W. BARNES.1 Division of Vendor & Technical Programs
 82/11/15 7pp 16333 190
- EP12070301 Forwards QA Program Insp Rept 99900902/82~09 on 820814-21 No noncompliance noted POTAPOVS U Division of Vendor & Technical Programs 82/11/10 HOLBROOK, W W Wyle Laboratories 2pp 16343 181
- --8212070304 OA Program Insp Rept 99900902/82-09 on 820816-21 No noncompliance noted Major areas inspected review of Terry turbine test spec & Wyle test plan % procedures & witnessing of turbine dynamic testing HUBBARD.0 T , PHILLIPS.H S Region 4, Office of Director 62/11/09 8pp 16343 183
- BP12070416 Forwards GA Program Insp Rept 99900317/82-01 on 820920-24 & notices of honconformance & violation POTAPQV8, U Division of Vendor & Technical Programs 82/11/12 STOLBA, F B Coaper Industries, inc 3pp 14336 298
- --S212070418 Notice of violation from insp on B20920-24 • Division of Vendor & Technical Programs B2/11/12 is 16336 301
- --8212070422 Notice of nonconformance from insp on 820920-24 * Division of Vendor & Technical Programs 82/11/12 3pp 16336 302
- ---B212070434 GA Program Insp Rept 99900317/82-01 on 820920-24
 Noncompliance noted disintegration of lube oil strainer
 basiet mesh not reported & signatures, clock number & dates
 not entered for completed operations
 FOSTER, W E , DARNES, I Region 4, Office of Director 82/11/02
 13pp 16336 305
- 8212100003 Ack receipt of 821108 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900003/82-02
 POTAPOVS.U Division of Vendor & Technical Programs 82/10/26
 LONG.U A General Electric Co lp 16373 358
- --8212100005 Responds to NRC 821019 itr re nonconformance noted in GA Program Insp Rept 9970003/82-02 Corrective actions engineering change request issued requesting anhydrous ammonia requirement in nitrate spec be revised LGNG. J A General Electric Co. 62/11/08. PDTAPDVB.U Division of Vendor & Technical Programs 3pp 16373 359

- 8212210091 Forwards GA Program Insp Rept 99900088/82-01 on 821018-22, notice of nonconformance & notice of violation POTAPOVS, U Division of Vendor & Technical Programs 82/12/02. GOFF, O H Harnischfeger Corp 2pp 16492 221
- --8212210094 Notice of violation from insp on 821018-22 * Division of Vendor & Technical Programs 82/12/02 ip 16492 283
- --8212210098 Notice of nonconformance from insp on 821018-22 * Region 4. Office of Director 82/12/02 2pp 16492 224
- B212210135 Forwards GA Program Insp Rept 99900282/62-01 on 821018-20 No noncompliance noted POTAPDVB,U Division of Vendor & Technical Programs B2/12/02 BEWELL,D M ITT Grinnell (subs of ITT) 2pp 14485 175
- --8212210141 GA Program Insp Rept 99900282/82-01 on 821018-20 No noncompliance noted Major areas inspected spec of incorrect wald insp requirements on hanger drawings & previous findings ELLERBHAH. E. BARNES, I. Division of Vendor & Technical Programs 82/11/26 9pp 16485 177
- B212210218 Forwards GA Program Insp Rept 99900819/82-03 on 821004-08 No noncompliance noted POTAPUS.U Division of Vendor & Technical Programs 82/12/03 KOMES.J M Rechtel Corp 2pp. 16484 081
- --8212210233 GA Program Insp Rept 99900519/82-03 on 821004-08 No noncompliance noted Major areas inspected QA program re audits & four 100FR50-55(e) Part 21 repts COSTELLO, J. R. HALE, C. J. Division of Vendor & Technical Programs 82/11/30 18pp 16484-083
- 8212210353 Forwards QA Program Insp Rept 99900346/82-01 on 820830-0903 & notice of honconformance PDTAPDVS,U Division of Vendor & Technical Programs 82/11/18 FRANCOIS,E I Velan Valve Co 2pp 16495 299
- --8212210357 Notice of nonconformance from insp on 820830-0903 • Division of Vendor & Technical Programs 82/11/18 2pp 16495 301
- --8212210366 GA Program Insp Rept 99900346/82-01 on 820830-0903
 Noncompliance noted absence of inspector stamp & date for
 verification of transfer of marking on operation & routing
 sheets for PO P3-3500-N assembly
 CONMAY, J T, BARNES, I Division of Vendor & Technical Programs
 82/11/04 8pp 16495 303
- 8212270199 Forwards CA Program Insp Rept 99900743/82-01 on 821006 & 07 & notice of nonconformance PCTAPDVS,U Division of Vendor & Technical Programs 82/12/02 DUVALL,D.D. Brown Soveri Corp (subs Brown Soveri & Co., Ltd.)
- --8212270206 Notice of nonconformance from insp on 821006 & 07 * Division of Vendor & Technical Programs 82/12/02 3pp 16535 137
- --B212270213 GA Program Insp Rept 99900743/82-01 on 821006 & 07 Noncompliance noted data not entered in data sheets to indicate change to 49-volt of control power & recorded voltage value did not satisfy min requirement FOSTER, H E . BARNESI. Division of Vendor & Technical Programs 82/11/23 11pp 14535 140.
- 8212280396 Ack receipt of 821122 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900400/82-03 PDTAPDVS,U Division of Vendor & Technical Programs 82/12/21 QUILBERT,D E Babcock & Wilcox Co 1p 16559 034
- --8212280401 Responds to NRC 821005 itr re nanconformance noted in GA Program insp Rept 99900400/82-03 Corrective actions notification of POWERTRAIN code error distributed to operational analysis unit per Exhibit C of NPG-0903-13 GUILBERT.D E Babcock & Wilcox Co 82/11/22 POTAPDV8, U Division of Vendor & Technical Programs App 16589 035

- 8212300027 Forwards QA Program Insp Rept 99900365/82-01 on 821020-22 & POTAPOVS, U Division of Vendor & Technical Programs 82/12/08 MEARS, L N Van Huffel Tube Corp 2pp 16598 178
- --8212300029 Notice of nonconformence from insp on 821020-22 * Division of Vendor & Technical Programs 82/12/08 : 16598 180
- --8212300032 GA Program Insp Rept 99900365/82-01 on 821020-22 Noncompliance noted gas flow meter encrusted w/dirt & oil preventing welders from reading gas flow rate ELLERSHAWL E. BARRES.I Division of Vendor & Technical Programs 82/11/30 App 16598 182
- 8212300212 Forwards GA Program Insp Rept 99900912/82-01 on 820830-31 & notice of violation POTAPOVS.V Division of Vendor & Technical Programs 82/1: COMOREY.R S Acton Environ Testing Corp 2pp 16598 039 82/12/10
- ---B212300214 Notice of violation from insp on 820830-31 * Division of Vandor & Technical Programs 82/12/10 16578 041
- --8212300218 GA Program Insp Rept 99900912/82-01 on 820830-31 Noncompliance noted failure to specify provisions of 10CFR21 in each procurement document for basic component issued on AGEE, J. R. PHILLIPS, H. S. Division of Vendor & Technical Programs 82/12/07 5pp 14598 042
- 8212300254 Forwards QA Program Insp Rept 99900795/82-01 on 821006-08, notice of honounformance & hotice of violation POTAPOVS.V Division of Vendor & Technical Programs 82/12/08 LOTT.J E. E L Manufacturing Peebles, Inc. 3pp 16995 211
- -8212300258 Notices of violation & nonconformance from imap on 621005-08 Division of Vendor & Technical Programs 82/12/08 4pp
- --B212300263 GA Program Insp Rept 99900795/82-01 on B21006-08 Noncompliance noted failure to adopt procedures to inform of component defects to establish measures to assure integrity of subvendor mfg operations & to perform insp steps HCNEILL.W H , BAKONBKI,P , BARNES,I. Division of Vendor & Technical Programs 82/11/26 10pp 16575 218
- 8212300276 Forwards GA Program Insp Rept 99900276/82-01 on 820830-0903 & notice of nonconformance
 POTAPOVS,U. Division of Vendor & Technical Programs B:
 CASSIDY.R F Solidstate Controls, Inc. 2pp. 16595-195 82/12/08
- --8212300278 Notice of monconformance from insp on 820830-0903 * Division of Vendor & Technical Programs 82/12/08 2p; 16893 197
- --B212300280 OA Program Insp Rept 99900276/82-01 on 820830-0903
 Nonconformance noted failure to maintain records to assure compliance w/loCFR21 procedure & failure to submit review packages to QA manager PARKER.L B., BARNES.I Division of Vendor & Technical Programs, 82/11/30 7pp 14595, 199
- 8212300301 Forwards QA Program Insp Rept 99700903/82-01 on 820831-0901 & 1025-26 & notice of nonconformance POTAPDVG.U Division of Vendor & Technical Programs 82/12/08 NUSSELL.U Georgia Institute of Technology 2pp 16594 197
- --8212300302 Notice of nonconformance from insp on 820831-0901 & 1025-26 * Division of Vendor & Technical Programs 82/12/08 ip 16594 199.
- --8212300303 GA Program Insp Rept 99900903/82-01 on 820831-0901 & 1025-26 Noncompliance noted GA program not established or SMITH.A.L. PHILLIPS:H S Division of Vendor & Technical Programs 82/11/30 7pp. 18594 200. implemented

RECOD REQULATORY CUIDES

8212020131 Comments on dreft Reg Guide OP 722-4, "Gualifications for Radiation Safety Officer in Large-Scale Non-Fuel-Cycle Radionuclide Program " Supports reg guide MEOST.N F California, Univ of, Los Angeles 82/11/07 BELL.J Office of Nuclear Regulatory Research, Director 1p 16272 036

- 8212020173 Advises that comments on draft Reg Quide HF 408-4, "Training & Certification of ISFSI Operators," should be considered as personal comments, not Bechtel position WELLB. B J Bechtel Corp 82/11/18 Docketing & Services Branch Ip 16274 106.
- B212030227 Requests comments on requirements of Reg Guide 1 97 for reactor coolant temp indication Requirements not met by Wastinghouse design Summary of NRC views enc! EISENHUT.D 0 Division of Licensing LS05-82-11-072 82/11/10 KINOSLEY.O D Wastinghouse Operating Plants Owners Group KINOSLEY.O D Alabama Power Co 5pp 14314 350
- B212090141 Notification of CRGR 821124 meeting re Unresolved Safety Issue A-43 concerning containment emergency sump performance & proposed Reg Quide 1 97 Agenda summary info & proposed NUMBU encl
 STELLD.V Committee to Review Generic Requirements 82/11.
 SIBERMUT, D G Division of Licensing JORDAN, E L Director
 Office. Office of Inspection and Enforcement CUNNINGHAM, R
 Office of Nuclear Material Safety & Safeguards, Director 12
 16361 029
- --8211120212 Forwards proposed Revision 3 to Reg Quide 1 97,
 "Instrumentation for Light Water Cooled Nuclear Power Plants
 to Assess Plant & Environ Conditions During & Following
 Accident," regulatory analysis & CRGR summary
 MINDOUER B Office of Nuclear Regulatory Research, Director
 82/11/04 SELLO,V Committee to Review Owneric Requirements
 43pp 16361 245
- 8212290062 Summary of CROR Meeting 26 on 821124 re Unresolved Safety Issue A-43, "Containment Emergency Sump Performance" & revision to Reg Ouide 1 97 STELLO. V Regional Operations & Generic Requirements 82/12/10 DIRCKS 16607 001

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

Research Info Ltr 38 re results of initial series of ACPR experiments on prompt-burst energetics w/fresh oxide fuel W/o encl NUREG/CR-0367 LEVING. Gffice of Nuclear Regulatory Research, Director 78/10/13 DENTON: HR Office of Nuclear Reactor Regulation, Director 6pp 16565 218

8002R60162 RIL-076
Research Info Ltr 76 summarises info re use of postresearch into Ltr /o summarises into re use or postirradiation heat theatment to recover preirradiation
properties of commercial nuclear power plant reactor vessels
for continued safe operation
LEVINES Office of Nuclear Regulatory Research, Director
79/12/28 DENTON-H R Office of Nuclear Reactor Regulation,
Director MINOQUE, R B Office of Standards Development, Director 14565 224

B003280100 RIL-079

posacoutou XII.-0/9
Research Info Ltr 79 transmits evaluation of seismic qualification tests for nuclear power plant equipment LEVING.S Office of Nuclear Regulatory Research, Director 79/12/20 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 16565 233

8005270762 RIL-085
Research Info Ltr 85 discusses NUREO/CR-1014, "Integrated Geophysical & Geological Study of Tectonic Framework of 38th Parallel Lineament in Victinity of Intersection w/Extension of New Madrid Fault Zone - Annual Progress Rept FY79 "
DUDNITY:R J Diffice of Nuclear Regulatory Research, Director BO/03/24 DENTON.H R Office of Nuclear Reactor Regulation. Director MINDOUE.R B Office of Standards Development, Director

8005270829 RIL-081
Research Info Ltr 81. summarizes results & analysis of Fuel research into Ltr B. Summarites results & analysis of Fuel Disruption—I series of in-reactor experiments on swelling & disruption of irradiated fuel under conditions of unprotected (nonscram) loss of flow accident in LMFBR BUDNITI.R J. Office of Nuclear Regulatory Research. Director BO/03/27 DENTON, H R Office of Nuclear Reactor Regulation. Director 10pp 16545 339

8005281047 RIL-071
Research Info Ltr 71 submits NUREO/CR-0874, "Regional Tectonics & Seismicity of East NE Annual Rept, June 1977-Mag 1978 " LEVINGS Office of Nuclear Regulatory Research, Director 79/11/19 DENTON, H. R. Defice of Nuclear Reactor Regulation. DENTON, H R 041 5pp, 16565 228 Director

8006020271 RIL-087
Research Info Ltr 87 transmits results of completed research to develop modeling capability for independent assassment of need for power estimates for util svc areas
BUDNRTT2.R J Office of Nuclear Regulatory Research, Director 80/04/04 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 16566 OOi

Big3280465 RIL-106
Research Info Ctr 106 forwards results of completed research on characterizing effects on atmospheric dispersion from bldg wakes around large reactor complex located on flat terrain
MINGQUE, R B. Office of Nuclear Regulatory Research, Directo

HINDOUE,R B Office of Nuclear Regulatory Research, Director 80/11/28 DENIDN.H R Office of Nuclear Reactor Regulation, Director SHITM,R G Office of Standards Development, Director 4pp 16565-359

8104170558 RIL-119
Research Info Ltr 117 discusses development of best-estimate
Component Code K-FIX (3D.FLX)
MINOQUE,R B Office of Nuclear Regulatory Research, Director
B1/04/14 DENTON,H Office of Nuclear Reactor Regulation, Director
17pp 16566 012

B104170664 RIL-118
Research Info Ltr 118 discusses variation of resonance
component of Doppler coefficient w/depletion.
MINDOUE.R B Office of Nuclear Regulatory Research, Director
B1/04/14 DENION,H Office of Nuclear Reactor Regulation, Director
App 16366 006

9109280378 RIL-125
Research Info Ltr 125 reviews TRAC~PD2 Code, "Advanced Best Estimate Computer Program for PWR LOCA Analysis "
MINOGUE, R B Office of Nuclear Regulatory Research, Director 81/09/11 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 10pp 16565 265

--8109280383 Speech entitled "TRAC-PD2 Development Assessment Summary," presented at 810114 ACRS Emergency Core Cooling subcommittee meeting VIGIL, J C Los Alamos Scientific Laboratory 81/01/14 32pp 15555 273

Blill30045 RiL-124

Amenanch Info Ltr 124 transmits results of research
relevant to display & utilization of control room alarm &
annunciator sys RIL is part of TMI Action Plan I D 4 a(1)
& based on NUREO/CR-2147 M/o encl
MINGOUE.R D Office of Nuclear Regulatory Research. Director
RIL-124 81/10/20 DENTON.H R Office of Nuclear Regulation. Director STELLD, V Director's Office of
Inspection and Enforcement 4pp 14546 029

OPO1150075 RIL-127
Research Info Ltr 127 transmits results of investigation of heat transfer & hydraulics during BWR large-break LOCA
MINOQUE.R B Office of Nuclear Regulatory Research, Director B-3014 81/12/04 DENTON, HR Office of Nuclear Reactor
Regulation, Director 11pp 16545 254

8PO1190563 RIL-128 Research Info Ltr 128 forwarding "PHR Lower Plenum Refill Research Results " Updates & extends results in Research Info Ltr 57. "Small-Scale Emergency Core Codiling Bypass Research Results " No add1 bypass work planned MINDOUE/R B Office of Nuclear Regulatory Research. Director FIN A-4048 RIL-128 61/12/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 11pp 16565 245

8201220270 RIL-126
Research Info Ltr 126 transmits result of initial testing & analysis of BMR small-break LOCA simulations in two-loop test apparatus
MINOGUE, R B Office of Nuclear Regulatory Research, Director 81/12/04
Director 9pp 16565 309

--8201120155 Speech entitled "Analysis of TLTA Small Break Tests & Comparisons to RELAPA/MODA Calculations:" presented at ANS Specialist Conference on Small Breaks in LWRs 810825-27 meeting in Monterey.CA BECKNER.W D NRC - NO Detailed Affiliation Given DALLMAN.R J EQUO. Inc 81/08/27 17pp 14545 318

BP02260369 RIL-129
Research Info Ltr 129 transmits results of project "Thorium
in Human Tissues " Recommends adaption of ICRP 30
methodology for internally deposited thorium
MINODUE:R B Office of Nuclear Regulatory Research, Director FJN
8-5756 B2/02/05 DAVIS.J 0 Office of Nuclear Material Safety &
Safeguards, Director 6pp 16565 236

8207200458 RIL-131
Research Info Ltr 131 responding to user need itr NRR-78-2
re significance of impingement & entrainment impacts on
Hudson River white perch
HINDOUE.R B Office of Nuclear Regulatory Research, Director
82/06/29 DETRON, H R Office of Nuclear Reactor Regulation,
Director 7pp 14565 239

8212010109 "Review of Recent Research Sponsored by DDE That Impacts on Findings of ICRP30," revision
FELICETTI.8 A New Mexico, Univ of RUNKLE, 0 E Raytheon Corp
FIN A-1165 SANDB2-7079 82/09/30 Division of Waste Management

8212010469 "Technical Assistance For Regulatory Development Simplified Repository Analysis in Hypothetical Bedded Salt Formation "PEFFING.R.E., CHU.M S Sandia Laboratories TIEM.P Science Applications, Inc. FIN A-1165 SAND82-0976 82/12/01 NRC - No Detailed Affiliation Given 72pp 16268 088

82;2010474 "Quick Look at LERs of Batteries & Battery Chargers at US Commercial Nuclear Power Plants, Jan 1976-Dec 1981 " BROWN, B R, TROJOVSKY EO&G, Inc. FIN A-6276 EOG-EA-6074 82/10/31 ROBINSON, R C Division of Risk Analysis 141pp 16296 228

B212010475 "Technical Assistance for Regulatory Development Radionuclide Concentrations for Basalt & Bedded Salt Repositories " PEPPING.R E Sandia Laboratories FIN A-1165 SAND82-1275 B2/05/31 NRC - No Detailed Affiliation Given 71pp 16270 290

8212010478 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC-Licensed Fuel Cycle Facilities," monthly progress rept for Oct 1992 SIMON-TOV.M Union Carbide Corp FIN 0-0495 82/11/14 HERNSTEIN,S Transportation & Materials Rist Branch 3pp

8212010481 "Technical Assistance for Regulatory Development Simplified Repository Analysis in Ref Tuff Site " SIEGEL, M D . CHU, M S Sandia Laboratories 82/12/01 NRC - No Detailed Affiliation Given 86pp 16268 001

8212010493 "Acoustic Emission/Flow Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly progress rept for Oct 1982 HUTTON,P H., KURTZ,R J. Gattelle Momorial Institute, Pecific Northwest Laboratory FIN 8-2088 82/11/17 MUSCARA, J. Materials Engineering Branch 21pp 16270 231

8212010486 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research." monthly highlights rept for Sept 1982 LOTTS, A L., BAYLOR. V B. HOMAN. F.J. Cak Ridge National Laboratory 82/10/25 Office of Nuclear Regulatory Research, Director 103pp 16297 007

8212010487 "Monthly Rept Representing Research Portion of Water Reactor Research Dept & Thermal Fuels Behavior Program," technical assistance rept DEARTEN.J A Idaho National Engineering Laboratory 82/09/30 NRC - No Detailed Affiliation Given 212pp 16296-016

8212020010 "Identification of Crevice Corrosion in Titanium Alloy, TiCode-12 in Simulated Rock Salt Brine at 150 C," interim rept AHN.T M . LEE, B 9 , 900.P Brookhaven National Laboratory BNL-NUREG-32107 82/09/30 MCNEIL.M 8 Office of Nuclear Regulatory Research, Director 21pp 16308 341

B212020100 "US Std Problem B Final Comparison Rept," interio rept DOBBE, C A E080, Inc. FIN A-6047 E00-NTAP-6088 B2/10/31 ODAN, F Office of Nuclear Regulatory Research, Director 48pp 16309 139

8212020104 "UB Std Problem 10 Final Comparison Rept," interim rept DDBRE.C A EG&G. Inc FIN A-6047 EGG-NTAP-6069 82/10/31 UDAR,F Office of Nuclear Regulatory Research, Director 65pp 16309 187

8212020126 "Acceleration Data in Suppression Pool Area From Kunsheng Safety Relief Valve Tests," interim rept MILLER, B.K., YUAN, C.Y. EG&G, Inc. FIN A-6415 EG0-EA-6025 82/10/31 BAGCHI.G. NRC - No Detailed Affiliation Given 70pp 16310 276

- 8212030239 "Independent Code Assessment at BNL in FY82," prepared for Tenth Water Reactor Safety Research Info meeting on 821012-15
- 15 SAMA,P, ROHATOI,US, JO,J H BRU_NUREO-32101 82/10/12 NRC No Detailed Affiliation Given 24pp 16317 001
- 8212030323 "88C Development, Validation & Application & CRER Balance of Plant Hodeling," monthly highlights for Oct 1782 GUPPY, J G Brookhaven National Laboratory FIN A-3041 92/11/12 CURTIS, R T Severe Accident Assessment Branch 7pp 16314 327
- 8212060005 "HTOR Safety Program," monthly highlights ltr for Oct 1982 SASTRE.C Brookhaven National Laboratory FIN A-3016 82/11/18 FOULDS.R Office of Nuclear Regulatory Research, Director 4pp SASTRE.C FOULDS.R 14325 337
- 8212060119 "LWR Code Assessment & Application," monthly highlight 1tr For Oct 1982 SAHA,P Broothaven National Laboratory FIN A-3215 82/10/31 ODAR,F Analytical Models Branch 6pp 16323-001
- 8212060128 "LWR Plant Analyzer Project," monthly highlights 1tr for Dot 1982 HOLEF, H Brookhaven National Laboratory FIN A-3227 82/10/31 SHOTKIN, L M Office of Nuclear Regulatory Research, Director 16322 360
- 8212070400 "Thermal Hydraulic LMFBR & LWR Safety Experiments." monthly hightlight ltr for Oct 1982 OINSBERG, T., OREENE, O. A. Brookhaven National Laboratory FIN A-3024 E2/10/31 CURTIS.R T. Severe Accident Assessment Branch
- 8212070471 "Postulated Safety Refirst Valve Line Break in Metwell Airspace of Mark I & II Containments-Risk Assessment," informal rept ECONOMOS, C., LEHNER, J. RANLET, J. Brookhaven National Laboratory FIN A-3385 SML-MUREO-31940 82/10/31 SU, T M Office of Nucl Reactor Regulation, Director 52pp 16355 265 Office of Nuclear
- 8212080262 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for Dct 1982 VAN RODYEN.D Brookhaven National Laboratory 82/10/31 NRC I Detailed Affiliation Given 4pp 16370 195
- 8212080505 "Post-Test RELAP5 Simulations of Bemiscale Mod-2A Feedwater Line Break Tests 8-8F-1.2 & 3C." interim rept STREIT.J E . NORTH.P . JOHNSON 9 W E0&6. Inc FIN A-6038 E0G-SEMI-6062 82/10/31 LANDRY.R R Office of Nuclear Regulatory Research. Director 82pp 16368 001
- 8212080510 "RSFORCE Program to Compute Fluid Induced Forces Using Hydrodynamic Gutput From RELAPS Code." interim rept MATKING.J C EC&O. Inc FIN A-6356 ECG-EA-5920 82/10/31 RICHARDEDN.J E Division of Risk Analysis 105pp 16368 085
- B212080516 "Evaluation of Thermal-Hydraulic & Radiological Effects of Removing or Bypassing LOFT Steam Generator & Pump Simulators for Experiment L2-6," interio rept DEMMIE, P N , CONNOR, J. E , OIRI, A H EG&O, Inc FIN A-6048 EGG-LOFT-6084 82/10/31 NRC No Detailed Affiliation Oiven 50pp 16368 190
- 3212080520 "RELAPS/MODI Quick Ref Manual," interim rept. HALL D. G., JOHNSON, E. C. EG&G. Inc. FIN A-6330 EGG-CDD-6027 82/10/31 CHEN, Y. Office of Nuclear Regulatory Research, Director 1636B 240
- 1212160549 "Rept of Foreign Travel of MF Osborne," foreign trip rept OSBORNE,M F Gak Ridge National Laboratory FIN 8-0127 ORNL/FTR-1429 82/11/17 SILBERBERO,M Accident Evaluation Branch 28pp 16466 214
- 212160558 "BMFT/NRC Core Melt Info Exchange Meeting.Karlsruhe.KfK." foreign trip rept PARKER.O W Cak Ridge National Laboratory FIN 8-0127 CRNL/FTR-1428 92/11/10 SILBERBERG.M Accident Evaluation Branch, 14pp 16466-200
- 212160364 "Rept of Foreign Travel of RP Wichner," foreign trip rept WICHMER.R.P Dak Ridge National Laboratory FIN 8-0127 GRNL/FTR-1426 82/11/22 SILBERBERG.M Accident Evaluation Branch 12pp. 16466-188
- 212220021 "Environ Assessments of Fuel Cycle Facilities." monthly progress rept for Oct 1982
 KELLY-M J Dak Ridge National Laboratory FIN B-0279
 GRNL/ED/EIS-179 B2/10/31 GILLEN,P M Uranium Recovery Licensing 6**P**P 14529 085.

- 8212220060 "Measurements of Iodine Partition Coefficients Status of Experimental Program." Interim rept
 BEANM.E C. SHOCKLEY.W E. Oak Ridge National Laboratory FIN B-0453 92/10/31 Office of Nuclear Regulatory Research.
 Director 14pp 16527 005
- 8212220519 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research." monthly highlights rept for Nov 1982 LOTTS, A L. BAYLOR, V B. HOMAN, F. J. Oak Ridge National Laboratory 82/12/19 Office of Nuclear Regulatory Research. Director 95pp
- 8212220523 "Chemical Spacies of Migrating Radionuclides at Commercial Shallow Land Buria) Sites," quarterly progress rept for Jul-Sept 1982 Jul-Sept 1982 KIRBY, L. J. TOSTE, A.P. Battelle Memorial Institute, Pacific Northwest Laboratory PNL-4432-2 82/10/31 NRC - No Detailed Affiliation Given 21pp 16323 001
- B212270240 RIL-130
 Research Info Ltr 130 re experimental verification of computer simulations of piping response using Heissdampfreaktor seismic tests
 MINDOUE.# B Office of Nuclear Regulatory Research, Director 82/03/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 16553 359
- 8212270416 "SIMTRAN 1 Computer Code for Simultaneous Calculation of Oxygen Distributions & Temp Profiles in Zircaloy During
 Exposure to High Temp Oxidizing Environs "
 MALANG.S Oak Ridge National Laboratory ORNL-5083 ;
 NRC - No Detailed Affiliation Olven 148pp 16570 233
- 8212270534 "Direct Reactor Auxiliary Cooling Sys Modeling in SSC," interia rept
 (HAN.B C , OUPPY, J Q , KENNETT, R J Brookhaven National Laboratory
 FIN-A-3015 BNL-NUREG-32170 92/10/31 CURTIS, R T , WOOD, P M
 Division of Accident Evaluation 38pp 16550 326
- 8212280031 "Dagradation of Steam Generator Tubing & Components by 112280031 "Degradation of Communication of PURs "
 Operation of PURs "
 WEEKS.J.R., CZAUKOWSKI.C J Brookhaven National Laboratory FIN
 A-3011 BNL-NUREO-31864 82/12/21 Office of Nuclear Regulatory
 Research, Director 13pp 16593
- 0212280040 "Properties of Radwestes & Waste Containers," quarterly progress rept, Jul Sept 1982
 SMYLER, K. J. DAYAL, R. Brookhaven National Laboratory FIN A-3027 BNL-NUREO-32049 82/11/30 KIM.K. Office of Nuclear Regulatory Research, Director 13pp 14592-354
- 8212280051 "Effect of Shape Reactivity on Rod Ejection Accident," to be presented to Topical Meeting on Advances in Reactor Computations in Salt Lake City, UT on 830531 NEAGY.P , CAROU.J F Brookhayen National Laboratory BNL-NUREO-32105 82/09/30 App 16591 358
- 8212280055 "Tests W/Income) 600 to Obtain Quantitative Stress Corrosion Cracking Data for Evaluating Svc Performance " BANDY, R , VAN RODYEN,D Brookhaven National Laboratory BNL-NNREO-31814 82/97/30 TABDADA,A Office of Nuclear Regulatury Research, Director 11pp 16592 121
- B212280518 "In-Core Detector Activation-To-Power Correlation for PWK Assembly," informal rept
 TODDSCM.R . FISENHART.L D Brookhaven National Laboratory FIN
 A-3212 BNL-NUREG-32106 B2/11/20 DUNENFELD.M Division of
 Systems Integration (post 811005) 36pp 16590 077
- 8212290512 "CRNL Projects for NRC Ofc of Nuclear Regulatory Research," fourth quarter mgt rept LOTTS:A L , BAYLDR:V B , HOMAN,F J Oak Ridge National Laboratoru B2/11/30 Office of Nuclear Regulatory Research, Director 18/pp 16593 140
- B212300137 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Ruclear Pressure Vessels:" monthly ltr progress rept for Nov 1982 HUTTON,P H. KURTZ:R J Battelle Memorial Institute: Pacific Northwest Laboratory FIN 8-2088 B2/12/17 MUSCARA. J Materials Engineering Branch 16pp 14624 197
- BRI2300402 "Accident Aerosol Characterization." informal monthly progress rept for Nov 1982 OMCAZARSKI,F C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 82/12/14 BERNSTEIN,S Division of Rick Analysis 8pp 16613 195

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8212020072 Summary of CRGR Meeting 25 on B2i116 re proposed revision to IOCFR20. "Stds for Protection Against Radiation " Revision bound reflect use of health risks as basis for radiation protection stds

STELLO, V Regional Operations & Generic Requirements 82/11/30 DIRCKS, W J Office of the Executive Director for Operations 5pp

B212070141 Notification of CRGR 821124 meeting re Unresolved Safety
Issue A-43 concerning containment emergency sump performance
& proposed Reg Quide 1 97 Agenda summary info & proposed
NUREQ encl
STELLO.V Committee to Review Generic Requirements B2/j1/12
EISENHUT.D 0 Division of Licensing JORPAN.E L Director's
Office, Office of Inspection and Enforcement CUNNINGHAM.R E
Office or Nuclear Material Safety & Safeguards, Director 122pp
16361 027

--8211120169 Forwards CRGR package for Unresolved Bafety Issue A-43, "Containment Emergency Sump Performance" Issue not as significant as previously postulated CRGR review of proposed actions requested DENTON.H R Office of Nuclear Reactor Regulation, Director 82/10/27 STELLO,V Regional Operations & Generic Requirements 200pp 16361 151

--8211120212 Forwards proposed Revision 3 to Reg Quide 1 97,
"Instrumentation for Light Water Cooled Nuclear Power Plants
to Assess Plant & Environ Conditions During & Following
Accident," regulatory analysis & CROR summary
MINOGUER B Office of Nuclear Regulatory Research, Director
82/11/04 STELLU, V Committee to Review Generic Requirements
43pp 16261 245

BD12100159 Provides rept re peer review of differing prof opinion raised by R Rogers Technical basis for approval of specific licensing action less than adequate & review process for actions should be improved DEARDIJ T Peer Review Group TAC 48232 82/11/24 0'REILLY, J P Region 2, Office of Director 4pp 16399 004

SELEITO245 Forwards long-range CROR agenda for Dec 1982 — Nov 1983 Mods for agenda items not reflecting corrent status should be forwarded to H Schwink by B30204 STELLO,V Regional Operations & Generic Requirements 82/12/16 REHM T A, MINGOUE,R B, DENTON, H R NRC — No Detailed Affiliation Given 12pp 16459 307

G21222256 Forwards CRGR monthly rept for Nov 1782 & open items from previous meetings Info will be included in Executive Director for Operations rept to Commission for wk ending G21217
GCHWINK.W Committee to Review Generic Requirements B2/12/21
Committee to Review Generic Requirements £pp 16503 345

82:2280408 Notifies of CRGR Meeting 29 on 830:06 to discuss proposed revision to 100FR\$1. "Environ Protection Regulations for Domestic Licensing & Related Regulatory Functions" Proposed revision encl
BTELLO.V Regional Operations & Generic Requirements 82/12/29
ETBERHOVID 9 Division of Licensing JORDAN-E L Director's Office. Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Bafety & Bafeguards, Director 2pp 16557 249

--B212280415 Forwards draft final rule revising 10CFR91. "Environ Protection Regulations for Domestic Licensing & Related Regulatory Functions" & related conforming amends re implementation of CEG NEPA regulations for review CUNNINGHAM. O H Office of the Executive Legal Director 82/11/17 STELLO. V Regional Operations & Generic Requirements 464pp 14557 254

B212290062 Summary of CRGR Meeting 26 on B21124 rs Unresolved Bafety Issue A-43, "Containment Emergency Sump Performance" & revision to Reg Oulds 1 77 STELLO.V Regional Operations & Generic Requirements, B2/12/10 DIRCKS.W J Office of the Executive Director for Operations Spp 16607 001

SECY POSITION PAPERS BEFORE THE COMMISSION

82:2010029 Responds to FOIA request for documents setting forth policy re issuances of NRC press releases in connection w/ enforcement & licensing activities Forwards documents listed on app Documents also available in PDR FELTON.J M Division of Rules and Records 82/11/01 HARYMAN.S Debevoise & Liberman 3pp 14287 002

--8212010143 SECY-77-574

Obtains Commission guidance re policy concerning use of cameras during licensing hearings

FOUCHARD, J. Office of Public Affairs 77/11/11 13pp
16289 052

8212010327 SECY-82-462
Recommends approval of NRC integrated human factors program plan Plan represents systematic & comprehensive approach for addressing human factors concerns important to safety in FY83-85
DIRCKS, U. J. Office of the Executive Director for Operations 82/11/19 68pp 16522 053

8212040419 GECY-82-445

Requests Commission approval of recommended near-term actions related to protection against pressurized thermal shock events

DIRCKE'S J Office of the Executive Director for Operations
82/11/23 501pp 16371 001

8212070487 SECY-82-445 ERR

Page 14 to SECY-82-445

* NRC - No Detailed Affiliation Given 82/12/02 2pp 14351 361

8212090048 Responds to FOIA request for SECYs Forwards SECY-82-23, SECY-89-42, SECY-82-134, SECY-82-137, SECY-82-286 & SECY-82-315 SECY-81-600A available in PDR Review of SECY-81-622A, SECY-812-197B continuing FELTON.J M Division of Rules and Records 82/10/20 GRABER, L Affiliation Unknown 1p 16384 295

--8203090677 SECY-82-042
Requests approval of proposed amend to existing Section 274b
agreement withate of TX Proposed agreement proposed FR
notice, staff analysis of comments, proposed press release &
groposed ltr to governor encl
DIRCKS,W J Office of the Executive Director for Operations
62/02/01 30pp 16389 029

--8204160270 SECY-82-136

Seeks Commission approval of AO determination re blockage of coolant flow to safety-related sys & components Draft FR notice encl DIRCKES W J Office of the Executive Director for Operations 82/03/30 19pp 16385 060

--B204140262 SECY-B2-137
Recommends that Commission approve AD recommendation re major deficiencies in mgt controls at nuclear power plant Draft FR notice encl
DIRCKS, W J Office of the Executive Director for Operations 82/03/30 9pp 14385 080

--8212090224 SECY-02-204

Recommends that Commission approve publication of proposed rulemaking re staffing at nuclear power plants DIRCKS.W J Office of the Executive Director for Operations 82/07/02 72pp 16385 093

--B209280513 SECY-B2-315
Requests Commission approve publication of for comment
NUREG-0906: "Quidance for Implementation of 10CFR50 34(g)"
Section requires applicants to evaluate differences from
SRP
DIRCKS.W J Office of the Executive Director for Operations
B2/07/26 16pp 16385 166

8212100088 SECY-82-447A
Suggests enci revision of Nuclear Licensing Reform Act of
1983 be inserted as replacement for Chapter II of draft rept
of Regulatory Reform Task Force Mark-up of former package
enci for ref
TOURTELLOTTE, Regulatory Reform Task Force 82/11/30 133pp

8212230166 Responds to FOIA request for SECY-82-322. "Review of Director's Decision 2 206 Petition (PSC of NH)" & 8 Chilk memo to L Bickwit Forwards requested documents FELTON.J M Division of Rules and Records 82/11/04 GOLDSMITH.M W Energy Research Group, Inc. ip 16540 314

- --B209010092 SECY-B2-322

 Recommends that Commission not review 820706 Director's decision denying Seacoast Anti-Pollution League 820205 request for order to show cause why CP should not be suspended or revoked due to lack of financial qualification MALSCH, M G Office of the General Counsel B2/07/30 App 15540 315
- 8212290036 Responds to FOIA request for five categories of documents Forwards documents 1:sted in App A Review of documents restem 1 continuing FELTON, J. M. Division of Rules and Records 82/12/02 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp 16607 133
- --8212270039 SECY-92-275
 Informs Commission of public comments received on NRC,
 UM Hendrie & util group proposed ATMS rules & current status
 of rulemaking affort
 DIRCKS, H J Office of the Executive Director for Operations
 82/06/28 18pp 16607 140

STATE PROG STATE PROGRAMS

- 8P12010496 Agrees to assist in preparation of EIA for application for low level radwaste disposal site, per 820920 request Meeting to discuss roles & responsibilities suggested NUSSBAUMER, D A Assistant Director for State Agreements Programs 82/11/04 HAZLEIA J Colorado, State of 1p 16270 256
- 8212020388 Comments on State of CO proposed policy on financial tests as surety for mill licenses Policy generally acceptable Specifics of how parent company assumes responsibility for subsidiary requested SCARANO,R A Low Level Waste Licensing Branch 82/11/02 NUSSBAUMER,D A Assistant Director for State Agreements Programs 2pp 14297 358
- B21209004B Responds to FOIA request for SECYs Forwards SECY-82-23, SECY-82-42, SECY-82-134, SECY-82-137, SECY-82-286 & SECY-82-315 SECY-81-600A available in PDR Review of SECY-81-620A, SECY-82-197B continuing FELTON, J M Division of Rules and Records 82/10/20 GRABER, L Affiliation Unknown Ip 14384 295
- --B203090677 SECY-B2-042
 Requests approval of proposed amend to existing Section 274b
 agreement W.State of TX Proposed agreements proposed FR
 notice.staff analysis of comments proposed press release &
 proposed itr to governor enc!
 DIRCKS.W J Giffice of the Executive Director for Operations
 82/02/01 30pp 16385 029
- --8212090065 Advises that Commission has approved proposed amend to existing Section 274b Agreement w/TX Ofc of State Programs informed of action by telephones on 820226 Agreement should be forwarded for signiture of Chairman Palladino by 820312 CHICK, S J Office of the Secretary of the Commission 582-042 82/02/26 DIRCKS, W J Office of the Executive Director for Operations 1p 16385 028
- 8212090157 Respands to 821112 ltr re proper reporting procedures for emergency exercise before formulation of official findings Preliminary concerns should be reported to regional state liaison officer. R Trojanowski O'REILLY, J.P. Region 2. Office of Director 82/11/22 MYERS, J. L. Alabama, State of. 2pp 16359 102
- 8212090235 Forwards "Rept & Staff Evaluation of KY Radiation Control Program for Period 810501-820423 " Rept contains NRC findings & State of KY comments on findings MODBRUFF,R L. Region 2, Office of Director 82/11/05 ADAMS, B. Kentucky, State of 1p 16363 090
- ---8212070240 "Rept & Staff Evaluation of KY Radiation Control Program for Period 810501-820423." 21st regulatory program review

 * NRC No Detailed Affiliation Given 82/11/05 138pp
- 8212070315 Responds to 820703 request for technical assistance, due to staff turnover in radiation control section. Special assistance will be provided on limited basis, in terms of consultations & ensite training O'REILLY, J.P. Region 2. Office of Director. 82/11/08 ALLEN, D.T. Kentucky, State of 2pp. 16365-044
- --8212090319 Requests NRC assistance in training personnel, due to recent staff turnover in radiation control section. ALLEN, D.T. Kentucky, State of 82/09/03 G'REILLY, J.P. Region 2, Office of Director 2pp 16365-046

- 8212090390 Confirms discussion held following review & evaluation of state radiation control program FL program for regulation of agreement mati adequate & compatible w/NRC program Minor comments developed during review encl 0/REILLY.J P Region 2. Office of Director 82/11/19 HOWELL.J J Florida, State of 4pp 16364 245
- 8212090470 Forwards "Rept & Staff Evaluation of State of SC Radiation Control Program," for period 810821-820618 WOODRUFF.R L Region 2. Office of Director 82/11/05 JACKEON.R 9 South Caroling, State of 1p 16364 030
- --8212090474 "Rept & Staff Evaluation of State of SC Radiation Control Program," for period 810521-820618 * Region 2. Office of Director 82/06/18 88pp 16364 031
- ---B2120904BI Ack receipt of NRC 1tr re recent NRC evaluation of Agreeaent State program W/o stated encl JACKSON,R S South Carolina, State of 82/07/27 O'REILLY,J F Region 2, Office of Director ip 16364 119
- 8212100111 Responds to FOIA request for seven categories of info re NFS.Erwin.TN Forwards documents listed in App A Documents listed in App B withheld (ref FOIA Exemptions 3 & 5) FELTON.J M Division of Rules and Records 82/11/12 HEJSS.E.R Harmon & Waiss 4pp 16388 157
- --8212100121 Forwards addl comments on proposed license conditions for NFS-Erwin re emergency preparedness GRIMES, B K Division of Emergency Preparedness 82/03/23 PAOE, R G Uranium Fuel Licensing Branch ip 16388 164
- --B21210012B Ack receipt of B2022S concerns re timeliness of alerting & notifying nearby residents in event of certain type of emergency at NF6. Inc Emergency planning license conditions for NFS discussed TROJANDMSKI.R Region 2. Office of Director B2/03/12 GRAHAM, J A Tennessee, State of 2pp 1638B 165
- B212200069 PNA-82-010 on 821212.0 5 C1 Cs-137 sealed source in container lost during shipment between Houma.LA & Cameron.LA Source not found Media interest anticipated DDDAR J Region 4. Office of Director 82/12/13 ip 16474 265
- 8212210161 PNA-82-010A on 821213, lost well logging source recovered near Houma, LA NRC considering appropriate enforcement action

 * Region 4, Office of Director 82/12/16 in 16483-361
- 8212220549 Notification of contract execution, Mod 2 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities "Contractor State of GA SILVIS.R M Research Contracts Branch FIN 8-3203 MRC-05-79-252 82/12/15 COBB.L Training & Administration Staff COHEN.L NRC No Detailed Affiliation Given 1p 16523 349
- --8212220553 Mod 2, deobligating funds, to "Environ Eurveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within State of GA & Selected by Commission "
 LEDBETTER, J L Georgia, State of GUSTAVE, R P Division of Contracts FIN B-5203 NRC-05-79-252 82/12/15 1p 16523 350
- 8F12270443 NUREC/BR-0025 VOGN11
 INFORMATION REPORT ON STATE LEGISLATION
 KERR.O W Office of State Programs, Director 82/12/31 NRC No
 Detailed Affiliation Given 19pp 16566 339
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- B210210467 Forwards revisions to nonproprietary WCAP-8587, Suppl 1
 "Equipment Gaulification Data Packages" & proprietary
 WCAP-8687, Suppl 2 "Equipment Gualification Test Repts "
 Proprietary repts withheld (ref 10CFR2 790)
 RAHE, E P Westinghouse Electric Corp NS-EPR-2668 82/10/13
 HILLER, J R Standardization & Special Projects Branch 2pp
 15763 090
- --8210210475 Submits application for withholding proprietary WCAP-8687. Suppl 2 "Equipment Qualification Test Repts," per 100FR2 790 Afridavit AW-80-27 encl WIESEMANN.R A Westinghouse Electric Corp AW-82-60 82/10/13 MILLER, J.R. Standardization & Special Projects Branch 11pp 15763 092

- --8210210484 WCAP-8587S1R0 ESE-18

 "Equipment Qualification Data Package," Revision 0 to Suppl 1:600P-ESE-18. "Veritrak Pressure Transmitters Qualification Qroup A "

 RAHE.E P Westinghouse Electric Corp EQDP-ESE-18 82/09/30 23pp 15763 103
- --8210210489 WCAP-858751RO ESE-38
 "Equipment Qualification Data Package," Revision O to Suppl
 1.E009-ESE-38." Veritrak Differential Pressure Transmitters
 Gualification Group A "
 RAHE, E P Westinghouse Electric Corp EGDP-ESE-38 82/09/30
 21pp 15763 126
- 9212010151 Forwards "Final Reviews of TRAP-2, POWER TRAIN & CADDS Topical Repts"

 ABRAMSON, P. B. Argonne National Laboratory FIN A-2121 82/09/02 JENSEN, W. Reactor Systems Branch 55pp 16258 148
- 8212020200 Forwards Revision 1 to CEN-152, "C-E Emergency Procedure Guidelines Vols I & 2." in response to DO Eisenhut 801031 itr & NUREO-0737. Item I C 1 Guidelines intended to supersede & replace guidelines in CEN-128 WELLS, R W C-E Operating Plants Guners Group WELLS, R W Northeast Utilities RWW-82-67 82/11/22 EISENHUT, D 0 Division of Licensing 2pp 16272 066
- --821202020B Informs that author replaces KP Baskin as chairman of C-E. owners group Policy re communications between owners group & NRC reaffirmed HELLS:R W C-E Operating Plants Owners Group WELLS:R W Northeast Utilities RWW-82-61 82/10/19 DENION.H R Office of Nuclean Reactor Regulation, Director 2pp 14272 068
- B212020212 CEN-152 R01
 Revision 1 to CEN-152, "Emergency Procedure Guidelines"
 C-E Operating Plants Owners Group B2/11/30 723pp
 16272 070
- BP12020204 Requests resources & review be made available for licensing issues to be considered in EPRI LWR standardization program Response by 821179 requested DENTON, H R Office of Nuclear Reactor Regulation, Director 82/11/15 MATTSON, R J Division of Systems Integration (post 811009) HANWER, B H Division of Systems Integration (post Division of Engineering 24pp 16302 338
- B2:2020267 Forwards proprietary "Westinghouse Advanced PWR Pretendering Module 2 Secondary Side Safeguards" Rept withheld (ref 10CFR2 790) Application for withholding & affidavit encl NAME. E P Westinghouse Electric Corp NS-EPR-2688 82/11/29 MIRAGLIA:F Assistant Director for Safety Assessment 2pp 14290 0134
- --B212020271 Application for withholding proprietary "Westinghouse Advanced PWR Protendering Module 2 Secondary Side Safeguards " Affidavit encl WIESEMANN.R A Westinghouse Electric Corp AW-82-69 62/11/29 MIRAGULA.F Assistant Director for Safety Assessment 7pp 16290 336
- B212030088 Forwards proprietary "Exxon Nuclear Co ECCS Cladding Swelling & Rupture Model," Revision 1 Rept withheld (ref 10CFR2 790) CHANDLER, J.C. Exxon Nuclear Co. Inc. (subs. of Exxon Corp.) JCC 115 82 82/12/01 THOMAS, C. D. Standardization & Special Projects Branch 1p 16304 171
- 82:12030229 Requests comments on requirements of Reg Guide 1 97 for reactor coolant temp indication Requirements not met by Westinghouse design Summary of NRC views encl EISENHUT,D 0 Division of Licensing LSO5-82-11-072 82/11/18 KINGSLEY,O D Westinghouse Operating Plants Guners Group KINGSLEY,O D Alabama Power Co 5pp 16316 350
- O212080552 Agrees w/JS Charnley 820831 ltr proposing administrative amend to licensing Topical Repts NEDE-24011-P-A-4 & NEDE-24011-P-A-4-UB Exception taken w/fuel design option change re barrier fuel, normally reviewed by NRC THOMAS.C O Standardization & Special Projects Branch 82/11/29 SHERWOOD, Q O General Electric Co 2pp 16368 360
- G212080603 Notification of 821221 meeting w/Westinghouse owners group in Bethesda,MD to discuss presentation on proposed methods for using reliability data for revising instrumentation sections of ST6
 URINKMAN,D S Standardization & Special Projects Branch 82/11/18
 THOMAS.C O Standardization & Special Projects Branch 2pp 16379 348

- 8212090003 Notification of 821207 meeting w/9E.MiT.BNL & Mark I owners group in Bethesda.MD to discuss suppression pool local to bulk temp difference analysis associated w/Mark I long-term program post-implementation review
 SIEOEL.B L Operating Reactors Branch 2 82/11/24 VASSALLO.D B Operating Reactors Branch 2 1p 16379 361
- B212090077 Advises that issue of wetwell/drywell vacuum breaker actuation during pool swell not applicable to Mark I plants; an response to B21112 questions PFEFFERIEN.H C General Electric Co MFN-186-82 02/11/28 VASSALLO
- B212090148 Forwards "Mark I Containment Program Augmented Class 2/3 Fatigue Evaluation Method & Results for Typical Torus Attached & Safety Relief Valve Piping Sys "
 PFEFFERIEN, H C General Electric Co MFN-187-B2 82/11/30 VASSALLO, D B Operating Reactors Branch 2 2pp 14359 121
- --8212090155 MPR-751

 "Mark I Containment Program Augmented Class 2/3 Fatigue
 Evaluation Method & Results for Typical Torus Attached &
 Safety Relief Valve Piping Sys "

 # MPR Associates, Inc. 62/11/30 44pp 16359 123
- 8212100052 Notifies that XN-NF-1A, "GA Program Topical Rept for Nuclear Fuel Design & Fabrication," Revision 5. acceptable HAABS.W P Quality Assurance Branch 92/12/06 VOLMER, C J Exxon Nuclear Co , Inc (subs of Exxon Corp) 2pp 16399 342
- 8212100111 Responds to FOIA request for seven categories of info re NFS, Erwin, TN Forwards documents listed in App A Documents listed in App 8 withheld (ref FOIA Exemptions 3 & 5) FELTON, JM bivision of Rules and Records 82/11/12 HEISS, ER Narmon & Weiss 4pp 16388 157
- --8212100121 Forwards addl comments on proposed license conditions for NPS-Erwin re emergency preparedness GRIMES, B K Division of Emergency Preparedness 82/03/23 PAGE, R G Uranium Fuel Licensing Branch 1p 16388 164
- 8212130097 Advises that "Application of Exxon Nuclear Co PHR Thermal Hargin Methodology to Mixed Core Configurations," Revision i.generically applicable to all open lattice PHRs COURE.0 C Exxon Nuclear Co. Inc (subs of Exxon Corp) GCC-047 82 82/12/07 HDLOWICH.J J Core Performance Branch ip
- B212130217 Forwards "FOAM2 ~ Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LDCA," in response to NUREO-0555 & NUREO-0737, Item II K 3 30 TAYLOR, J H Babcock & Wilcox Co 82/12/01 BERGGREN, J B Standardization & Special Projects Branch 1p 16378 142
- --8212130220 BAH-10155

 "FOAM2 Computer Program to Calculate Core Swell Level & Mass Flow Rate During Small Break LGCA"

 # Babcock & Wilcox Co 82/11/30 39pp 16398 t43
- GP12130233 Provides info per 821201 telcon re submittal of App 1 to "B&W Small Break LOCA ECCS Evaluation Model" App 1 will be submitted under NUREG-0737. Item II K 3 31 TAYLOR, J H Babcock & Wilcox Co 82/12/03 SHERON, B Reactor Systems Branch 1p 16397 016
- BP12130234 Notifies of withdrawal of Topical Rept BAH-10026P (NP).
 "Reactor Vessel Model Flow Test for 145 FA Core " Withdrawal based on decision to discontinue marketing nuclear steam sys
 1AYLOR, J H Babcock & Wilcox Co 62/11/23 BERGOREN, J S
 Standardization & Special Projects Branch 200 16390 143
- BR12130262 Advises that Topical Rept WCAP-10170, "Emergency Response Facilities Design & V&V Process." submitted separately for NRC review & approval concomitant w/review of design basis & functional sys requirements.

 RAHELE P Westinghouse Electric Corp NB-EPR-2689 82/12/01 THOMAS. C Standardization & Special Projects Branch 1p 16396 243
- B212130276 Forwards progriptary & nonproprietary responses to NRC 821107 questions on MCAP-9863/9864 re methodology for use on two, three & four loop plants, both first cycle & reloads Application for withholding progriptary info forwarded RAHE.E P Westinghouse Electric Corp NS-EPR-2670 82/12/10 THOMAS.C O Standardization & Special Projects Branch 1p

- --8212130302 Requests withholding of proprietary responses to NRC questions on MCAP-9863/984 per 100FR2 790 Affidavit 76-8 & nonproprietary responses w/info deleted encl MESEMANN, R A Mostinghouse Electric Corp AM-82-72 82/12/10 FMBMSC 0 Standardization & Special Projects Branch 18pp 16389 290
- 8212130360 Approves encl proposed route for transport of spent reactor fuel SHERR.T B Haterial Transfer Bafeguards Licensing Branch 82/12/01 EMBNILER.T Battells Memorial Institute, Columbus Laboratories 12pp 16415 001.
- 8212140092 Forwards affidavit attesting that Bechtel Specs J-110 & J-104 & Calculations FL-01, Revision 0.PB FC-01, Revision 1, PB FC-01, Revision 2 & FC-13, Revision 0 are proprietary & should be withheld per 10CFR2 790 KCHES, J H Bechtel Corp 82/12/09 ALLISON, D NRC No Detailed Affiliation Given 5pp 16408 273
- 8212140190 Responds to NRC consultant conclusions on XN-NF-621(P),
 Revision 1, "Exton Nuclear ENS Correlation for PNR Fuel
 Designs " One population for CHF data base recognized 1A
 test sections
 CHANDLENJ C Exxon Nuclear Co , Inc (subs of Exxon Corp)
 JCC-120 82 82/12/09 HOLONICH, J J Core Performance Branch Spp
 16410 217.
- 8212140501 Forwards CENPD-270, "Dry Storage Cask for ISFS!" SCHERER, A E Combustion Engineering, Inc. LD-82-088 82/11/11 ROUSE, L G Advanced Fuel & Spent Fuel Licensing Branch ip 16491 158
- --8212140510 CENPD-270
 "Dry Storage Cast for 19F81."
 * Combustion Engineering, Inc. 82/10/31. 41pp 16431 159
- 8212180003 Forwards Revision 1.8uppl 1 to "Gadolinia Fuel Properties for LWR Fuel Safety Evaluation" CHANDLER.J C Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC-121 82 82/12/13 THOMAS.C O Standardization & Special Projects Branch Ip 16425 [48
- --8212150005 XN-NF-79-56(NP)(A)Ri Revision 1, Suppl 1 to "Oadolimia Fuel Properties for LHR Fuel Safety Evaluation " * Exzon Nuclear Co . Inc (subs of Exxon Corp) 82/12/10 32pp. 16425 149
- 8212150055 Informs of three changes to LOCTA-[V computer code used to calculate fuel rod heatup transient in Mestinghouse ECCS evaluation nodel First change concerns modeling of distribution of energy deposition during LOCA RAME, E P Westinghouse Electric Corp NS-EPR-2699 82/11/08 HILLER, J R Standardization & Special Projects Branch 3pp 14431 004
- 8212160365 MCAP-10170
 "Emergency Response Facilities Design & V&V Process"
 GALLAOHER, J M. HERRICK-E Ø , QURCAK-A W Westinghouse Electric
 Corp 21280 1/102582 82/04/29 33pp 16442 250
- 82/2170396 Advises that Revision 22 to Topical Rept CE-1-A re QA program for nuclear power plants acceptable HARS.W P Quality Assurance Branch 62/12/09 SWARTZ.E D Commonwealth Edison Co 10 16478 141
- 8212200040 Forwards proprietary & nonproprietary responses to Revision 1 to MCAP-9179/MCAP-9224. "Properties of Fuel & Component Matis." (SER open item re Zircafoy irradiated properties) Proprietary response withhibeld RAME.E.P. Westinghouse Electric Corp. NS-EPR-2697 82/11/30 THOMAS.C.O. Standardization & Special Projects Brench 2pp 16478-095
- --B212200062 Requests withholding of responses to WCAP-9179/WCAP-9224,
 "Properties of Fuel & Core Component Matls," Revision 1
 WIESENANN.R.A Westinghouse Electric Corp AW-02-70 82/[1/30]
 THOMAS.C Q Standardization & Special Projects Branch 7pp
- S212210535 Forwards requests for add1 info to complete review of MCAF-10079 (P), "NOTRUMP A Nodel Transient Small Break & General Network Code," & WCAF-10054 (P) "Mestinghouse Small Break ECG Evaluation Model "
 THOMAS.C O Standardization & Special Projects Branch 82/12/03 RAHELE.P Mestinghouse Electric Corp 2pp 14502 289

- --B212210538 Round ; questions re Reactor Sys Branch review of WCAP-10054. "Westinghouse Small Break ECCS Evaluation Mode Using NDTRUMP Code." & WCAP-10079. "NDTRUMP Nodel Transient Small Break & General Network Code." & Reactor Systems Branch 82/12/03 23pp 16502 290
- 8212220192 Forwards add1 responses to environ & seismic open items per 821019-20 & 1201 meetings Combination of comprehensive sosting & analysis assures structural integrity & operability of motors RAHE, E.P. Westinghouse Electric Corp. NS-EAP-2695 82/12/16 NGONAM, V. Equipment Qualification Branch 28pp. 16503 055
- 6212270473 Responds to 821129 request for review of C-E rept, "Dry Storage Cask for ISFSI" Casks conform w/GA program CENPD-210-A:Revision 3 Program reviewed in 1977 & accepted HAASS.K P Guelity Assurance Branch 31645 82/12/08 RGUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 1p 16566 360
- 8212270553 Notification of rescheduled 821217 meeting w/GE,BNL.MET, Detroit Edison & Mark 1 owners group in Bethesda,MD to discuss syppression pool local to bulk temp difference analysis associated w/Mark 1 long-term program SIEGEL.B L. Operating Reactors Branch 2 82/12/02 VASSALLG.B B Operating Reactors Branch 2 1p 16546 342
- 8212280168 Forwards Amend 6 to Duke-1-A.QA program ORIER.9 W Duke Power Co 82/12/21 HAASS,WP Quality Assurance Branch 1p 16563 222
- --8212280173 DUKE-1-A AO6 Amend 6 to Duke-1-A. GA program ORIER. O W . CAMP.L F Duke Power Co 82/12/21 108pp 16552 224
- B21227018B Forwards CEN-227, "Summary Rept on Operability of Pressurized Safety Valves in C-E Designed Plants," in response to NUREO-0737. Item II D 1 W/o encl WELLS, R W C-E Operating Plants Comers Group WELLS, R W Northwast Utilities RWW-82-70 82/12/20 BERNARD. H Standardization & Special Projects Branch 2pp 16576 055
- G212290466 Summary of S21130 meeting w/Westinghouse re advanced PHK std design program MEYER.0 Standardisation & Special Projects Branch 82/12/15 Standardisation & Special Projects Branch 2pp 16608 059
- \$212300034 Forwards prepublication draft of Revision 3 to BWR emergency procedure guidelines Revision adds guidelines re secondary containment control & radioactivity release control DENTE, I J BWR Owners Group BWRD0-8262 82/12/22 EIGENHUT, D G Division of Licensing 2pp 16578 312
- --B2;2300036 Prepublication draft of Revision 3 to emergency procedure guidelines # BHR Owners Oroup 82/12/08 66pp 16578 314

WASTE MOT NUCLEAR WASTE MANAGEMENT

- B212010003 Notification of B21110 seminar entitled, "EPA High Level Waste Std Current Status & NMSS Perspective on Implementation" in Silver Spring, MD KNAPP. H R High Level Waste Licensing Management Branch B2/11/05 High Level Waste Licensing Management Branch 1p 16271 361
- B212010008 Forwards title page & table of contents to Sept 1982 final published version of PNL-3622. "AE018 Technology Demonstration for Nuclear Waste Repository in Basalt "W/o encl GCRDON.H J High Level Waste Licensing Management Branch 82/11/09 CODK.F R High Level Waste Licensing Management Branch GREEVES, J T , JUSTUS,P S High Level Waste Technical Development Branch ip 16290 224
- 8212010010 Forwards list of individuals requiring copy of Hanford site characterization rept WRIORT.R J Office of Nuclear Material Safety & Safeguards, Director 82/11/10 STILL,N , HALL, J Division of Maste Management 3pp
- 8212010013 Summary of 820427 meeting w/Dow Chemical Co in Silver Spring. MD re waste form provisions of 100FR61 JOHNSON, T.C. Low Level Waste Licensing Branch 82/11/12 MARTIN, J.B. Division of Waste Management 4pp 16270 217

- 8212010025 Forwards draft "Generic Radiological Characterization Protocol for Surveys Conducted for DOE/QQS Remedial Action Programs," in response to 821012 ltr W/cover page but w/o test
 - test MOTT-H E Energy, Dept of 82/10/26 SCARAND,R A Low Level Waste Licensing Branch 2pp 16271 359
- 8212010065 Forwards "Review Plan for Site Characterization Repts."
 "BNIP Issues Identified by NRC" & "Schedules for Production
 of BiffP Draft Site Characterization Analysis " Identified
 BHIP issues encl W/o schedules for analysis
 MILLER.H J High Level Waste Licensing Management Branch 82/11/15
 MARTIN.J R Division of Waste Management 23pp 16289 152
- ~-B212010069 Revised "Review Plan for Bite Characterization Repts"

 * Division of Waste Management 82/11/30 24pp 16289 175
- B2:2010217 Comments on revised memorandum of understanding re ACRS participation in NRC rulemaking & policy making activities
 New agreement adds at least 4 months to process New administrative steps will increase paperwork
 BUNTING, J D Licensing Process & Integration Branch 82/11/05
 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 1p
- 8212010220 Forwards ltr sent to Covernor Spellman of WA State forwarding site characterization rept & informing of NRC role in process List of addressees attached BUNTING.JO Licensing Process & Integration Branch 82/11/15 NRC - No Detailed Affiliation Given ip 16290 299
- ~-B212010221 Forwards site characterization rept for candidate high level waste repository on Hanford Reservation Procedural portion of 100FR60 repository licensing rule also end W/o ends
 DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director B2/11/15 SPELLMAN, J Washington, State of Son 16290 300
- \$212010227 Forwards branch fact sheet addressing disposal of wastes containing transurants nuclides PRAGONETTE.K Low Level Waste Licensing Branch 82/11/17 SALONON,8 Office of State Programs, Director 1p 14290 305
- -- 8212010228 "Disposal of Low Level Wastes Containing Transuranic Elements ' * Low Level Waste Licensing Branch 82/11/17 4pp 16270 304
- B212010232 Forwards "Characterization of Class B Stable Radwaste Packages of New England Nuclear Corp " Final rept W/o encl BROWNING, R E Division of Waste Management 82/11/15 DUMAS,I New England Nuclear Corp 1p 16290 312
- BP12010240 Submits editorial recommendations for Dasalt Waste Isolation Project site characterization analysis products ULECK.R B High Level Waste Licensing Management Branch BR/11/16 High Level Waste Licensing Management Branch 2pp 16270 313
- G212010242 Requests two addl copies of Basalt Waste Isolation Project sits characterization rept for hydrogeology review group WRIGHT, R J High Level Waste Licensing Management Branch 62/11/16 STILL, N NRC - No Detailed Affiliation Given ip 16290 317
- B212010245 Discusses J Kimball limited participation in review of Basalt Haste Isolation Project site characterization rept Attendance at B21115 meeting requested HRIGHT,R J High Level Waste Licensing Management Branch 82/11/17 JACKSON,R Geosciences Branch 2pp 16290 318
- B2:2010290 Forwards info on process formerly used by Luminous Processes, Inc. in mfg aircraft dials made w/tritiated paint Info should be helpful in determining Luminous Processes waste form characteristics W/o encl PERSON, L.S. Low Level Waste Licensing Granch 82/11/03 BARLETTA.R. Brookhaven National Laboratory ip 16271 251,
- 8212010252 Discusses 821013 ltr re test method for determining density changes in actimide-doped waste forms Vote of no will be recorded unless MCC-128 test procedure & Section 3 & Equation 6 revised as indicated BELLIM J High Level Waste Licensing Management Branch 82/11/12 STEINDLERIM J Argonne National Laboratory 2pp 16271 252
- B212010302 Responds to L Olson B20923 ltr re workshops & Hanford Site Characterization rept Lists question & answer mode necessary for rept clarification MILLER: H J High Level Waste Technical Development Branch B2/11/05 ANTIONEN.J H Affiliation Unknown 3pp 14271 279

- 82/2010457 Forwards editorial requirements for use in preparing all contracted products under NRC-02-82-045 No change in cost or delivery of products expected W/o encl VERNA, T R High Level Waste Technical Development Branch NRC-02-82-045 82/11/19 FOWE.J Golder Associates ip
- 8212010496 Agrees to assist in preparation of EIA for application for low level radwaste disposal sate,per 920920 request Meeting to discuss roles & responsibilities suggested NUSBBAUMER, D.A. Assistant Director for State Agreements Programs B2/11/04 HAZLE,A J. Colorado. State of 1p 16270-256
- 8212010500 Comments on 85 Grand Junction, CO vicinity properties, per 820720 request Agrees w/conditional designation of properties to need for engineering assessment phase of nemedial action SCARANO, RA Low Level Waste Cicensing Branch 82/10/29 MDTT, W E Energy, Dept of 2pp 16270 257
- 8212010505 Comments on advanced draft of "Site Recommendation Quidelines" Clarification re specific application of siting factors required Selection of repository site must satisfy 10CFR60 criteria BELL.M J High Level Waste Licensing Management Brench WMHL 3109 3 82/10/28 BALLARD.W Energy, Dept of 2pp 16270 259
- 8212010508 Concurs w/revised final remedial action concept paper, per 821001 request SCARAND:R A Low Level Waste Licensing Branch WMLL KUH 82/10/21 CAMPBELL:R H Energy, Dept of 1p 16270 261
- 8212010514 Forwards "Preliminary Bite Stabilization & Closure Plan for Barnwell Low Level Radwaste Disposal Facility" & NUREO/CR-2478.Vol 1.per meeting in Natural Bridge State Park.XY re Maxey Flats low level waste facility H/o encl PENNIFILL.R A Low Level Waste Licensing Branch HM 409 18 B2/11/04 PAGE.R Kentucky, State of 1p 16270 262
- 8212020040 Ack receipt of 821013 request to place list of Federal agencies generating low level waste on blank tape JACKSON,K C Low Level Waste Licensing Branch WMLL 204 2 3 82/10/29 JORDAN,E A Energy, Dept of ip 16317 082
- 8212020060 Forwards revised remedial action concept paper & comments, per K Hamill 820916 telcon CAMPBELL,R H Energy, Dept of 82/10/01 8CARAND,R A Uranium Recovery Licensing Branch 2pp 16317 025
- --8212020073 UMTRA-DDE/AL-33
 Revised "Remedial Action Concept Paper for U Mill Tailings at Vitro Site, Salt Lake City, UT"
 * Energy, Dept of 82/10/31 23pp 16317 027
- 8212020114 Notifies of development of draft NRC QA Review Plan for reviewing adequacy of QA programs for geotechnical investigations re site characterization activities for nuclear waste repositories Requests meeting & discussion MILLER.H J High Lavel Waste Technical Development Branch WHHT 109 4 82/11/04 BALLARD.W Energy, Dept of 1p 16317.090
- BR12020117 Forwards tape for record of latest working SPLASHWATR code Requests any prepared documentation W/o encl GORDON,M J High Level Wasto Licensing Management Branch WMHL 3109 9 B2/11/10 MILLY,C D Princeton Univ ip 16310-362
- 8212020121 Submits info re shallow land disposal of low level nuclear waste NRC responsible for regulating disposal of radwastes DDE responsible for RRD of different disposal methods Forwards NUREG-0879 & 0782 W/o entl SURMEIER, J J Division of Waste Management WMPI 411 1 82/10/21 FORBITER, J H Affiliation Unknown 2pp 16308 300
- 82:2020128 Submits instructions for Basalt Waste Isolation Project site characterization assessment authors ULECK, R B High Level Waste Technical Development Branch 82/11/05 BELL, M, MILLER, H, WRIGHT, R NRC No Detailed Affiliation Given io. 16:308 278
- 8212020132 Submits principles to be followed re submittal of documents for word processing for Basalt Waste Isolation Project site characterization assessment MILLER, H J High Level Waste Technical Development Branch. BELL.M J High Level Waste Licensing Management Branch 82/11/05 NRC No Detailed Affiliation Given 2pp 16308 296

- B212020136 Confirms conversation w/P Justus re I Alterman limited participation in review of Basalt Waste Isolation Project site characterisation rept Alterman will review Chapters 3 & 13 WRIGHT, R J High Level Waste Technical Development Branch 82/11/15 JACKSON, R Geosciences Branch 2pp 16308 294
- B212020146 Forwards requested update of waste mgt portion of ofc manual chapters & JOSFR61 W/o encl BUNTING.J O Licensing Process & Integration Branch 82/11/16 BEVERIDGE.G Program Support Branch IP 14308 290
- 5212020148 Notifies that review of DOE 821112 site characterization rept for Hanford, HA reservation has commenced Draft analysis for public comment expected by mid-Mar 1783 w/final analysis expected by Sept DAVIS, J.O. Office of Nuclear Haterial Safety & Safeguards, Director 82/11/17 Office of Nuclear Haterial Safety & Safeguards, Director 2no 16308 288
- 8212020171 Forwards correspondence from HJ Dircks indicating willingness to fund work re dosimetry of Np-237 on sole-source contract basis Contract for Natl Committee for Radiation Protetion will be initiated accordingly FEHRINGER.D J High Level Waste Licensing Management Branch 82/11/15 KNAPP, MR High Level Waste Licensing Management Branch ip 16308 285
- 8212020177 Discusses DGE designation of two Salt Lake City vicinity Properties SL037 & SL068 in conjunction w/Vitro Chemical Co inactive mill site FLGRY.C A Low Level Haste Licensing Branch 82/10/29. Low Lev Waste Licensing Dranch. 3pp 16308 280
- 6212020183 Requests DDE site characterization rept for facility be kept in library for ref purposes only HRIGHT, R. J. High Level Waste Technical Development Branch 82/11/22 CONYNOHAM, M. Library Branch 1p 14308-278
- 8212020187 Forwards trip rept of 820824-25 visit to Columbia.5C re implementation of 10CFR61 waste form requirements JOHNSON, T.C. Low Level Waste Licensing Branch 82/10/27 BROWNING, R.E. Division of Waste Management 6pp 16508 261
- 8212020195 Notifies that principle data needs per 821019 ltr & 620614 meeting satisfied by manipulating info of type contained on radioactive shipment records received at disposal sites Meeting date of 821118 confirmed JACKEON.K C Lou Level Waste Licensing Branch WHLL 204 2 3 82/11/17 COLEMAN.J A Energy. Dept of 2pp 16208 257
- 8212020196 Trip rept of 820328-23 visit to Norwood, CO to participate in Pioneer Nuclear hearing HAMILL: K. J. Low Level Waste Licensing Branch 82/11/15 BCARANO, R.A. Low Level Waste Licensing Branch 3pp 16308 254
- B212020179 Forwards BNL repts identifying phenomena applicable to assessing long-term performance of high level waste packages constructed of FiCode-12 alloy including crevice corrosion & bydrogen embrittlement W/o encl
 BELLM J High Level Waste Licensing Management Branch 82/11/08
 BALLARD,W Energy, Dept of 2pp 16308 148
- 8212020201 Forwards Chapter 18 of site characterization rept for Basalt Waste Isolation Project re GA Commonts requested by 821130 MILLER, H. J. High Level Waste Technical Development Branch 82/11/13 HAASS.W.P. Quality Assurance Branch 1p 16308 147
- B212020203 Comments on draft low level waste mgt survey questionnaire Draft provides excellent format for program to accumulate consistent low level waste data for input to common data sys JACKSON,K C Low Level Waste Licensing Branch WMLL 204 2 3 82/11/03 HARDIN,C M Conference of Radiation Control Program Directors, Inc. 1p 16308 146
- G212020246 Informs that record of decision re long-term mgt of liquid high level radwaste at Western NY Nuclean Svc Ctr. West Valley.appeared in 820915 FR DOE now able to construct & operate facility PFLUM-C O. High Level Waste Licensing Management Branch BOYLE:R R High Level Waste Licensing Management Branch Spp
- B212020386 Trip rept of 820614-15 meeting w/V Bubcommittee of VA Coal & Energy Commission in Lexington VA to hear expert witnesses from govt & academia discuss issues associated w/V mining & milling and MANILL, K J. Low Level Waste Licensing Branch 82/10/27 SCARANO, R A Low Level Waste Licensing Branch 2pp 16308 130

- 8212020387 Notification of contract execution. Mod & to "Cyprus Mines Corp. Hansen Project Mill Tailings Evaluation" Contractor FC Hart Assoc. Inc MCLEAREN. T Technical Assistance Contracts Branch FIN B-6927 NRC-02-79-05& 82/11/24 DAVIS. J G Office of Nuclear Material Safety & Safeguards. Director 1p 16297 360
- --B212020390 Mod 6, incorporating indirect rate & adding addl funds, to "Cyprus Mines Corp. Hansen Project Mill Tailings Evaluation" * Fred C Hart Associates, Inc HAGAN, TF Division of Contracts FIN 8-6927 NRC-02-79-056 B2/11/24 2pp
- 82120203B8 Comments on State of CO proposed policy on financial tests as surety for mill licenses Policy generally acceptable Specifics of how parent company assumes responsibility for subsidiary requested SCARANO, R.A. Low Level Waste Licensing Branch 82/11/02 NUSSBAUMER.D.A. Assistant Director for State Agreements Programs 2pp 16297 358
- 8212020397 Trip rept of 811026-27 visit to CO State Univ to attend U mill tailings symposium HAMILLK J Low Level Waste Licensing Branch 82/10/27 BCARANO,R A Low Level Waste Licensing Branch 1p 16297 356
- B212020400 Forwards trip rept of 820302-04 meetings w/industry & State of CO officials W/o encl HAMFLL-K J Low Level Waste Licensing Branch 82/10/29 BCARAND.R A Low Level Waste Licensing Branch 1p 16297 353
- 8212020403 Forwards plans for development of draft site characterization analysis Plans identify products needed, sequence of parallel activities & describe sequence of daily activities between 821210 & 830121
 HRIGHT.R J High Level Waste Technical Development Branch 82/11/09 BOLYELR, COOK, FR, KNAPP, M High Level Waste Licensine Management Branch 14pp 16297 327
- 8212100343 Forwards An-222 repts for Aug & Sept 1982 TLD chip probes for passive radon monitors improperly prepared by outside lab MCCLUSKEY, J.P. Cotter Corp. 20862 82/11/15 HAZLE, A.J. Colorado, State of 1p. 16389 189
- --8212100349 Rn-222 repts for Aug-Sept 1782 * Cotter Corp 20862 82/11/15 3pp 16389 170
- 8712220546 Requests complete ref to source of "Geological Aspects of Industrial Waste Disposal," to assist in search Paper unknown to geology staff JUSTUS,PS High Level Waste Technical Development Branch 82/11/24 CHU.J Tennessee Valley Authority 1p 16523 029
- Bž12230034 Responds to 821103 ltr re low level radwaste disposal regulations Final version of 10CFR61 "Licensing Requirements for Land Disposal of Radwaste" & related amends encl W/o encl DAVIS.J G Office of Nuclear Material Safety & Safeguards.Dirpotor 82/11/30 UFFEN,R J Gueen's Univ. Kingston, Canada ip 16544 278
- 8212230066 Forwards comments on draft "NWTS Program Criteria for Mined Geologic Disposal of Nuclear Wastes Repository Performance & Development Criteria, DDE/MNTS 33(3) " Final document should include criteria from 10CFR60 BELL.M J High Level Waste Licensing Management Branch 82/12/01 BALLARD.W W Energy, Dept of 11pp 16544 349
- 8212230099 Summary of 821103 meeting w/CSU & DRNL in Region 4 of reproposed topical rept on long-term stability of U tailings reclamation covers
 FLEMINO.TE Region 4. Office of Director 82/11/29 SCARANO.R A Low Level Waste Licensing Branch 130p 16544 311
- 8212230105 Summary of 821202 mgeting w/EPA in Crystal City,VA re NRC & EPA plans for addressing disposal of low activity waste by less restrictive means (de minimis waste disposal) ROLES,O H Low Level Maste Licensing Branch 82/12/10 SCARANU.R Low Level Maste Licensing Branch 4pp 16544-307
- 8212230114 Summary of 821117-19 mesting w/util at McGuire & Ocones plants re implementation of waste classification requirements of 10CFR61 ROLES,O W Low Level Waste Licensing Branch 82/12/09 SCARAND,R Low Level Waste Licensing Branch 5pp 16544 302

- B212230118 Advises of contact u/C Cooley (DDE) re J Nell ltrs on performance assessment & content of NRC draft response Meeting will be held in Jan 1983 to prioritize performance aspects KNAPP.M R Low Level Waste Licensing Branch B2/12/03 BROWNING.R E Office of Nuclear Material Safety & Safeguards.Director ip 16544 301
- BP12230126 Forwards comments on Waste Mgt section of long-range research plan Steering committee should be established to coordinate high level waste research planning BUNITING. J D Procedures & Certification Branch 82/12/01 BROWN R S Program Support Branch 22pp 16544 279
- 8212230133 Summary of state & tribal participation steering group #21001 meeting to proposed priorities before receipt of DQE first site characterization rept #ACCOUDALL.R Procedures & Certification Branch #2/12/02 BUNTINO.J O Procedures & Certification Branch #ILLER.H J High Level Waste Technical Development Branch #App 16544 339
- B21223013B Responds to questions re interface w/EPA EPA must meet statutory responsibility of setting radiological stds in areas cuvered by 10CFR2O 302(c), since section already deleted
 BUNITING.J O Procedures & Certification Branch B2/12/03
 SMITH.R D Region 4, Office of Director 1p 16544 343
- BP12230145 Advises that comments incorporated into "Technical Position Paper on Near-Surface Disposal Facility Design & Oberation" & FR notice will be published to announce availability PANGBURN.G C Low Level Waste Licensing Branch B2/11/23 HMMKINS.E F Low Level Waste Licensing Branch Ip 16544 058
- Gri2230153 Forwards compilation of updated rules & petitions for quarterly update of regulatory agenda Ofc of Nuclear Regulatory Research will provide update for 10CFR60 rulemaking BURTING, J O Procedures & Certification Branch 82/12/01 BROWN-R A Program Support Branch Spp 16544 051
- 8212230174 Summary of 821130-1203 meetings w/Dames & Moore in Bethesda, MD re Task D of Contract NRC-02-81-049, third work requirement to modify EIS calculational methodology ROLES, G W Low Level Waste Licensing Branch NRC-02-81-049 207 6/GWR/82-12 82/12/13 SGARAND, R A Low Level Waste Licensing Branch Rpp 14540 361
- BP12230171 Surmary of ANS 821117 meeting re high level waste performance assessment ORKSTEIN, P M Low Level Waste Licensing Branch 3407 26/PMD/82/ 82/12/02 KNAPP, M R High Level Waste Licensing Management Branch Jpp 16913 273
- EM12230207 Order directing State of NV.Dept of Human Resources, not to renew Radioactive Matl License 13-11-0043-02, issued to Nuclear Engineering Co.Inc WILKES.D Nevada, State of 82/10/27 Nevada, State of 1p 16544 095
- --8212230212 Findings of fact & conclusions of law re proposed renewal of Radioautive Matl License 13-11-0043-02.issued to Nuclear Engineering Co.Inc License should not be renewed WILKES D Hevada, State of 82/10/27 7pp 16544 096
- GP12230225 Forwards listing of error messages executed in NWFT/ DVM tode used in Performance Assessment Section Use of encl list should expedite initial debugging procedures HEBER, M F High Level Waste Licensing Management Branch WMHL 3109 9 82/12/03 High Level Waste Licensing Management Branch 4pp 16540 337
- BP12230231 Forwards proposed revisions to current list of committees involving Ofc of Waste Mgt personnel W/o encl BUNTING.J O Licensing Process & Integration Branch 82/11/10 BROWN.R S Program Support Branch Ip 16540 356
- Stil2230331 Proposes single document describing generic procedures for designating UMTRAP vicinity properties incorporating screening, preliminary & comprehensive surveys needed buggested outline encl BCARAMO,R A Lou Level Waste Licensing Branch 82/12/06 MOTT.W E Energy. Dept of 16pp 16540 251
- 82:12230382 Responds to 82:1022 request for comments on second draft of "Potential Health & Environ Haterds of U Mino Wastes" Recommends alternatives where regulatory gaps identified or where present stds considered inadequate MARTIN. J B Division of Waste Management 82:/11/19 8JOBLOM. C L. Environmental Protection Agency 1p 16:540-250

- B212230387 Responds to 821101 request for info on nuclear waste Excerpts from Battelle. "Understanding Radwaste" encl DOE should be contacted for info re R&D W/o encl STILL.NL Division of Waste Management 82/11/26 PRUNIER.C M Affiliation Unknown 2pp 16540 240
- 6212230398 Responds to 621026 request for info on low level waste disposal & 100FR61 NUREG-0782. "DES for 100FR61," will be forwarded SCARANO,R A Low Level Waste Licensing Branch WMLL 411 4 82/11/17 FERRARA,W R Massachusetts Institute of Technology 1p 16540 239
- 8/12230390 Responds to 821029 request for info on nuclear waste pollution Annual rept & excerpts from Battelle "Understanding Radwaste." encl M/o encl SURMEIER, J J Licensing Process & Integration Branch WMPI 411 1 B2/11/22 CLARK.G Affiliation Unknown 2pp 16540 232
- 8212230392 Forwards summary of 821029 meeting w/Chem-Nuclear Sys, Inc re proposed radwaste disposal site in CD Site selection process will delay licensing schedule from 3-9 months PANGBURN. O C. Low Level Waste Licensing Branch 82/11/22 HAWKINS.E F. Low Level Waste Licensing Branch 3pp 16540 224
- 8212230374 Submits review of Sept & Oct 1982 monthly repts for Edgement Cleanup Action Program Soil sampling map of Cottonwood & status of long-term progeny measurement program should be submitted w/Dec rept FLORY, C A Low Level Maste Licensing Branch FIN 8-2217 WMLL CA) 82/11/30 MADMANN A Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 14544 111
- 82:2270430 Ack receipt of B21028 ltr commenting on draft branch technical positions on waste form & waste classification Fositions uill be revised to incorporate comments BRDMNING.R E Division of Waste Management 82/11/23 9HEALY.H © Bouth Carolina, State of 1p 16571 363
- 8912270444 Accepts invitation to participate in 821218 workshop in tas Vegas: NV on opportunities for public involvement in NRC licensing process for high level radwaste repository MARTEN, J B Division of Waste Management 82/11/24 TUCKER, M N; 'ear Information & Resources Services ip 16971 362
- BP12270455 Offers no comments on review of annual compilation of actions taken by NRC on GAO recommendations
 BUNTING.J O Licensing Process & Integration Branch 82/11/2J
 BROWN,R S Program Support Branch 1p 16568 362
- BP12270464 Summary of B21026-R8 Maxey Flats program review in Slade KY Rept summarizing info gathered by NRC contractors & USOS will be compiled PENNIFILL, RA. SIEFKEN, D.L. Low Level Waste Licensing Branch 82/11/18 HANKINS, E.F. Low Level Waste Licensing Branch App 14568 358
- 8212280184 Submits evaluation of TX Dopt of Health 821029 submittal re TX Anaconda Rhode Ranch Required testing & 0A program sufficient to assure adequacy of liner matl SMITH,R D. Region 4. Office of Director 82/12/02 NUSSBAUMER,D A Assistant Director for State Agreements Programs 3pp 16590 340
- --8212280189 Responds to Bailly request for citation to implement NRC Comment 7 request re TX Anaconda Rhode Ranch No citation can be given as general license has not yet been issued FONNER.R L. Regulations Division 82/11/15 NUBBRAUMER.D A Assistant Director for State Agreements Programs 1p 14590 249
- B212290008 Advices that FES on 10CFR61 sent under separate cover FEB may answer 820924 questions on DES re impacts of waste mgt & disposal DRAGORETIE.K S Low-Level Waste Licensing Branch 82/12/03 GOLDSTEIN.M Massachusetts, State of 1p 16607 233
- G212290024 Concurs in final draft 1982 annual status rept to Congress on UNTRAP SGARAKOR A Low Level Maste Licensing Branch \$2/11/29 BAUBLITZ, J A Energy. Dept of ip 16607 180
- Q212290260 Responds to 821102 request for info on nuclear waste sites Excerpts from Battella Dec 1981 rept, "Understanding Radwaste" 3 map of weste disposal cites encl NRC vs DOE responsibilities explained W/o encl STILL, N L Division of Waste Management 82/11/26 STAVITZ, J H South Carolina, Univ of 2pp 16606 264

XPORTLIC EXPORT AND IMPORT LICENSES

- 821201004; Advises that export license issued w/o normal 15-day waiting period due to NRC opersight of placing license amend application in wrong file ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/28 Assistant Director for Export/Import & International Safeguards 1p 16289 105
- G212010043 Advises that license to export penetration parts to Switzerland will be issued w/o normal 15-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/25 Assistant Director for Export/Import & International Eafeguards 1p 16271 339
- 8212010044 Ltr of assurance re export of 895 kg U-235, contained in 29,032 kg U-to Japan SHIRAKAWA, T Japan 82/10/26 GRIFFIN, J A Energy, Dept of 1p 16271 337
- 8212010048 Ltr of assurance re export of 213 kg U-235, contained in /, 462 kg U-to Japan SHIRAKAMA, T Japan 82/10/22 GRIFFIN, J A Energy, Dept of ip
- 8212010054 Ltr of assurance re export of 643 kg U-235, contained in 19,769 kg U. to Japan 5HIRAMAMAT Japan 82/10/22 GRIFFIN, J A Energy, Dept of lp
- BP12010057 Forwards application to export 791 kg U-235, contained in 22,000 kg U. to Belgium
 KIEL, G R Exron Nuclear Co., Inc. (subs. of Exron Corp.) B2/10/20
 BEVINE.J B Assistant Director for Export/Import & International
 Safeguards ip 16271 342
- --8212010063 Application for license to export 791 kg U-235 contained in 22,000 kg U,to Belgium KIEL,O R Exxon Nuclear Co , Inc (subs of Exxon Corp) 82/10/20 ip 16271 343
- 8212010072 Application to amend License XT-8552, expanding list of authorized countries & issuing new license to export 100,000 kg natural thorium to selected countries BARNUM E C Molycorp. Inc 82/11/17 HEMBY, E Assistant Director for Export/Import & International Safeguards 2pp 16271 347
- 8212010076 Forwards application for amend to export license for minor nuclear export Ltr of assurance required W/o encl ZIMMERMAN, J V Assistant Director for Export/Import & International Safequards 82/11/22 ORIFFIN. J A Energy, Dept of 1p 16289 280
- 8212010081 Forwards application for export license for minor nucleal export Ltr of assurance required W/o encl ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/10/27 GRIFFIN, J A Energy, Dept of 19 14273 351
- 8212010086 Informs that License XSNM-1979 may be issued No math changed circumstances since issuance of License XSNM-1972 MODRE.R N Assistant Director for Export/Import & International Safeguards 82/10/27 Assistant Director for Export/Import & International Safeguards 1p 16271 350
- 8212010088 Requests Executive Branch position re Mitsu; & Cm (USA), Incapplication for license to export SNM to Japan
 IIMMERMANJ V Assistant Director for Export/Import & Internationa)
 Safeguards 82/11/22. STDIBERIC R State. Dept of Bureau of Ocrano
 & Internation & Scientific Affairs in 16271 349
- 8012010093 Amend 2 to Molycorp. Inc export license, authorizing litense condition stating that total amount of natural U & thorium may not exceed 500 kg to any country per yr ZIMMERAM, J V Assistant Director for Export/Import & International Bafeguards 82/11/23 1p 16289 337
- B212010095 License for Sandvik Special Metals Corp to export 50 Zircalou-4 double thimble tubes to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguerds SSM-2937 82/11/23 ip 16289 336
- 82:2010:01 License for Westinghouse to export 10 compensated constation thambers to France
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguerds ZE 40141 82/11/23 ip 16290/112

- 8212010106 License for Molycorp, Inc to export 100,000 kg natural thorium, contained in rare earth compounds, to 20 listed countries

 ILMMERMAN, J V Assistant Director for Export/Import & International Safeounds 82/11/23 10 16290 111
- B212010110 Discusses licenses issued to Molycorp. Inc re export of thorium contained in rare earth compounds Licenses issued authorizing export to all countries save Cuba. Vistnam. North Korea & Kampunchea & authorizing export over 10-yr period HEMBY.E NRC No Detailed Affiliation Given 62/11/23 NRC No Detailed Affiliation Given 62/11/23 NRC No Detailed Affiliation Given 1p 16270 113
- 8212010114 Forwards application for license to export SNM to Japan HATTORI.H Mitsui & Co. (U.S. A.).Inc. (Subs. of Mitsui & Co., Ltd.) 82/11/12 Assistant Director for Export/Import & International Safeguards Ip 16271 352
- --B212010120 Application for license to export 3,215 kg U-235, contained in 147,790 kg U dioxide to Japan NIKAHI, H Mitsui & Co (U S A), Inc (Subs of Mitsui & Co , ital) MBK-KI B2/11/12 ip 16271 353
- 8212010127 Forwards application for license to export SNM to Japan HATYORI.H Mitsus & Co. (U.S. A.).Inc. (Subs. of Mitsus & Co., Ltd.) 82/11/12 Assistant Director for Export/Import & International Safeguards Ip 16274 354
- --8212010133 Application for license to export 1,016 kg U-235, contained in 33,079 kg U dioxide, to Japan MIXAMI,H Miteui & Co (U S A), Inc (Subs of Mitsu; & Co ,Ltd.) MBK-2F1-R2 (A) 82/11/12 jp 16271 355
- 8212010189 Ltr of assurance re Exxon 821020 application to export 791 kg U-235, contained in 22,000 kg U, to Belgium MARCHAL. J European Communities, Commission of 82/10/26 CRIFFIN, J A Energy, Dept of ip 16290 298
- 8P!2010194 Forwards Maruben: America Corp application for export license for minor nuclear export Ltr of assurance required W/o snc! ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards 82/10/29 ORIFFIN.JA Energy, Dept of 1p 16290 296
- 8212010197 Forwards application for export license for minor nuclear export Ltr of assurance required M/a encl ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/10/26 ORIFFIN.J A Energy, Dept of 1p 14290 297
- B212010461 License for Transnuclear. Inc to import 13,500 kg U.enriched to 0.85% U-235, from France ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/11/18 lp 16270 221
- 821201046B Application to amend export license, increasing quantity of U-235,U-233, thorium & Purto West Germany MOWRY, & R. OA Technologies, Inc./General Atomic Co. [EL-4024 82/11/10 IMMERMAN, J. Assistant Director for Export/Import & International Safeguards. 1p. 16270-220
- 8212020044 License for GE to export primary coolant pumps, fuel charging & discharging machines.control rods & specially designed or prepared parts & components for nuclear reactors, except pressure vessels, to Spain ZIMMERMAN, JV Assistant Director for Export/Import & International Safeguards BDM-82-091 82/10/29 ip 16317 081
- 8212020169 Requests Executive Branch position re Westinghouse application for license to export specially designed components to Brazil Wo encl
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Bafeguards 82/10/27 STOIBER, C R State, Dept of Bureau of Ocuano
 & Internat Environ & Scientific Affairs 1p 16308 286
- B212020174 Revision to B21019 application to amend export license, revising description of components in Block 17 HILSCN, B D General Electric Co BDN-092-82 82/10/20 HEMBY, E C Office of International Programs, Director 2pp 14308 283
- 8R1202018t Requests Executive Branch position re Saunders-Roe Development, Inc. application to amend license increasing matls for export to United Kingdom ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards 82/10/29 STOIBER.C. R. State, Dept of, Bureau of Ocean' & Internati Environ & Scientific Affairs ip 16308 279

NONDOCKETED ITEMS

- 8212020198 License for Transnuclear, Inc to export 8,580 mC; Cf-252, in oxide form, to West Germany ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards TNF-422 82/10/29 2pp 16308 150
- B212070417 Marked-up applications to amend export licenses, requesting extension for 2 yrs
 MCRGCRBTERNA Sigma Chemical Co 82/11/15 HEMBY, E Assistant
 Director for Export/Import & International Safeguards 19
- 8212070469 Forwards Saunders-Roe Developments, Inc 821117 1tr provising add1 info re 821021 request to increase amount of mat1 authorized in apport license
 7 IMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 82/11/29 STOIRER, C R State, Dept of, Bureau of Oceans & International Environ & Scientific Affairs Ip 16356 295
- ---8212070476 Submits addl info to 821021 application to amend license to export tritium lighting devices PAISLEY,E J Saunders-Roo Developments, Ltd 82/11/17 HENBY,E Assistant Director for Export/Import & International Safeguards in 16396 296
- G212070484 Ltr of assurance re transfer of nuclear matl to Canada ELLYSON, C Canada, Atomic Energy Control Board 82/11/07 GRIFFIN, J A Energy, Dept of 1p 16354 273
- 8212070489 Forwards application for BMI to import 3,298 g U from Canada HANNETT, B A Transnuclear, Inc 82/11/29 MODRE, N Office of International Programs, Director ip 16356 291
- --92:2070503 Application for license for BMI to import 3,298 g U.containing 2,686 g U-235 & 0 70 g Pu.from Canada HANNETT,B A Transnuclear, Inc MISC-424, 92/11/29 MODRE,N Office of International Programs, Director 3pp 16356 292
- 8212070502 Forwards Nissho Iwai American Corp 821116 application to amend export license, decreasing quantity of highly enriched U to 32 976 kg U.containing 30 785 kg U-235 W/o encl ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 82/11/24 STOIGER.C R State, Dept of, Bureau of Devant & Internati Environ & Scientific Affairs 1p 16351 360
- 8212070506 Forwards Mitsui & Co 821114 application to amend export license, decreasing quantity of U-235 to 19 71 g Japanese Embassy should be notified & ltr of assurance revised accordingly N/o encl ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 82/11/23 GRIFFIN.J A Energy, Dept of ip 14334 272
- B212070513 Application for license to export 2 0 kg thorium oxide pouder to Japan COLTON, E Cerac: Inc 82/11/29 HEMBY, E NRC No Detailed Affiliation Given ip 16356 290
- SP120B0002 License for Exxon Nuclear Co.Inc to export 771 Kg U-235, contained in 22,000 Kg U, to Belgium ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 10-20-82 82/12/02 2pp 16368 324
- B212080003 License for Pacific Intl to export 90 g deuterium to Sguth Korea ZimmeRMAN.J V Assistant Director for Export/Import & International Safeguards 455 82/11/24 ip 16368-323
- B212080004 License for Teledyne Wah Chang Albany to export 100 lbs Zircaloy-2 Trex tubes to West Germany. ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 8100-769 (JFM) B2/11/24 lp 16368 322
- 8212080016 Forwards Transnuclear, Inc 821130 application for export license for minor nuclear export.Ltr of assurance required ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 82/12/02 GRIFFIN, J. A Energy, Dept of 1p 16/367 171
- 8212080029 Application for amend to import license to include add1 1.593 607 kg U.containing 46 871 kg U-235. from Hest Germany HANNETT.B.A Transnuclear. Inc 82-027/02 82/11/24 MOORE.N Office of International Programs, Director 1p 16367 154

- 8212080035 Application to amend export license, extending expiration date to 840401 HAINETTIB A Transnuclear. Inc NUK-378 82/11/29 MOORE, N Office of International Programs. Director ip 16362 146
- 8212080221 Application for license to eiport 150,927 by Zircalou-2 tube shells to Japan End use statement encl BUONOCORE, JA Mitsul 8 Co (U S A), Inc (Subs of Mitsul 8 Co (Ltd) 136280 82/11/18 2pp 16967 136
- 8212080225 Informs that License KSNM-1992 may be issued No mati changed circumstances since issuance of License XSNM-1929 MODRE, R N Assistant Director for Export/Import & International Safeguards 82/12/02 Assistant Director for Export/Import & International Safeguards 1p 16367 135
- 8212080232 Amend 2 to Transnuclear. Inc export license, extending expiration date from 830901 to 840301 PETERSON.M R Assistant Director for Export/Import & International Safeguards 62/12/02 ip 16370-201
- BX:12080237 License for Mitsui & Co (USA). Inc to export 3.650 lbs /ircalou-2 tube shells to Japan /IMMERMAN, J V Assistant Director for Export/Import / International Hafeguards 136276 82/11/30 (p 16370 200
- B212080244 Amend 1 to QA Co export license changing ref to power level of reactor from 1,000 but to 3,000 but & increasing value of items for export to Bangladesh
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-021 B2/11/23 1p 16370 199
- 8212080527 License for Mitsus & Co (USA). Inc. to export 2,710 lbs Lincaloy-2 tube shells to Japan LIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 136277 82/11/30 ip 16370 190
- 8P12080534 License for Mitsui & Co (USA). Inc to export 150,920 lbs /ircaloy-2 tube shells to Japan ZIMMERMAN, J V Assistant Director for Export/(mport & Internationa) 8afeguards 136280 82/11/30 Ip 16370 189
- 8212080538 License for C Itoh & Co (America). Inc to export 600 guide thimble tubes to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MOI-144 82/11/30 lp 16370 188
- 8212100087 Application for Amend 6 to export license increasing quantity to 2 mg Cf-252, adding end use statement \$ specifying end user SHAH. A Ediow International Co 82/11/29 HEMBY. E Assistant Director for Export/Inport & International Safeguards 1p
- B212100119 Amend 1 to Transnuclear. Inc export license, extending expiration date from 830401 to 840401 rur exports to Suitzerland PETERSON, M R Assistant Director for Export/Import & International Gafeguards 82/12/02 ip 16399 008
- 8212160791 Application to amend import license changing transport methods for imports to read "by various transport methods in compliance w/all applicable US regulations" Assistant Director for SAMANA Ediou International Co. 82/12/08 Assistant Director for Export/Import & International Cafeguards 1p 16465-353
- Billia0796 Application to amend export license, changing max element weight to 30 785 kg YAMANA;K Nissho-Iwai American Corp 82/11/17 MOGRE,N NRC No Detailed Affiliation Given 1p 16465 352
- BP12170998 License for Edium Intl Co to export 12 6 kg U-235, contained in 63 kg U, to Canada IlmeRiNAN, J V Assistant Director for Export/Import & International Safeguards AECL-1 (82) 82/12/09 ip 16480 295
- 8212170023 License for IRT Corp to export 2 24 mg Cf-252, contained in two sealed sources, to Japan ZIMMERMAN, JV Assistant Director for Export/Import & International Safeguards 82/12/08 1p 16480 334
- 8212170027 License for CERAC, Inc. to export 1 757 kg thorium, contained 1: kg thorium oxide, to Japan LimmeRfAN, J V Assistant Director for Export/Import & International Safeguards 82/12/09 ip 16480 360

- 80:12230402 Forwards Battelle 82:130 ltr to Transnuclear. Inc requesting transnuclear, inc prepare & process application for import license HAMLETT, BA Transnuclear, Inc 82/12/06 MDORE, N Office of international Programs, Director 2pp 14537-341
- OP12230406 Forwards application to export 79,000 kg U hexafivoride, enriched to 3 35% U-235 & 0 170 kg U-235 contained in 5 kg U- to The Natherlands Lir of assurance also encl HANNETI.B Transnuclear, Inc. RBU-425 82/12/06 MOORE,N Office of International Programs, Director 1p 16539 357
- --U212233410 Application for license to export 79.000 kg U hexafluorids, enriched to 3 35% U-235 & 0 170 kg U-235 contained in 5 0 kg U, to The Netherlands
 HAUNETT, B Transnuclear, Inc (RBU-425) 82/12/06 3pp
- GF12239414 Amend 1 to Sigma Chemical Co export license extending appration date to 850401 PETERSON,MR Assistant Director for Export/Import & International Sareguards D-72 82/12/06 tp 14544 f10
- GP12230418 Amend | to Sigma Chemical Co export license, extending impiration date to 850701 PETERSON.H R Assistant Director for Export/Import & International Safeguards D-80 82/12/06 Ip 16944 109
- G(12230423 Amend 1 to Sigma Chemical Co export license.extending ixpiration date to 850601 PETERSON, MR Assistant Director for Export/Import & International Nafeguards D-77 82/12/06 Ip 16544 108
- 8.42230426 Notifies that Transmuclear Inc 821129 license request for Nafteile Columbus Lab to import 3 3 kg U & O 7 g Pu from Canada uill be granted w/o normal 30-day period of notice 21MMERMAN, J V Assistant Director for Export/Import & International Cafeguards 62/12/09 Assistant Director for Export/Import & International Assistant Director for Export/Import & International Safeguards 2pp 16544 106
- 8/12230427 Discusses Exxon Nuclear Co.Inc 821021 application to import 23.200 ig U from France (mport will not be inimical to common defense & security MOORE, R N. Assistant Director for Export/Import & International Safeguards 8/11/03 Assistant Director for Export/Import & International Safeguards 1 p. 16544 105
- G/12230428 Discusses staff findings of Transnuclear. Inc 820920 application to import 21.000 kg V from France Import will not be ininical to common defense & security MOGRE, it (4 Assistant Director for Export/Import & International Gafeguards 82/11/04 Assistant Director for Export/Import & International Safeguards ip 16544-104
- G/12230431 Discusses staff findings re Edlow Intl Co 820917 application to import 5 million Kg U from various countries Import will not be innortal to common defense & security MODRE, R N Assistant Director for Export/Import & International Safeguards 62/11/05 Assistant Director for Export/Import & International Safeguards 1p 14544 103
- GP13230432 Executive Branch position re Saunders-Ade Development, Inc application to export add1 700,000 Ci to United Kingdom License should be granted DEVINE.J B State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 82/12/03 SHEALJ R Office of International (*regrans, Director 1p 16544 102
- G/12230433 Amend 1 to Sigma Chemical Co export license, extending cipination date to 850701
 PETERSON.M R Assistant Director for Export/Import & International Safeguards D-79 82/12/06 Ip 16529-360
- 82;2270072 Addendum to application for license to export 24 2mm //ircaloy-4 alloy fuel channels to Japan # Carpanter Technology Corp 82/12/13 2pp. 16553 157
- BM 2270077 Forwards application for license to export nautron calibre bounce to Taiwan HERSCH.IX Westinghouse Electric Corp. MMH-217. 82/12/08 / IMMERMAN.J V Assistant Director for Export/Import & International Safeguards. 1p. 14553-135
- --9212270079 Application for license to export 1 neutron calibr source to Taiwan HERSCHIM M Westinghouse Electric Corp MMH-217 82/12/07 ip 14553 154

- 8P12270092 Forwards application for license to export 732 kg U-235, enriched to 3 40% U hexafluoride, to Japan SHKMA-5 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5482-07 82/12/06 Assistant Director for Export/Import & International Safeguards 3pp 16553 149
- --B212270086 Application for license to export 732 kg U-235, enriched to 3 40% U hetafluoride to Japan SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-8482-07 B2/12/06 Jpp 16553 152
- G212270087 Ltr of assurance re Tokyo Electric Power Co, Inc license to export 337 kg U-235, contained in 11,279 kg U SHIRAKANA, T Japan 82/12/10 GRIFFIN J A Energy, Dept of Ip 14551-342
- BP12270090 Ltr of assurance re Japan Nuclear Fuel Conversion Cq.Ltd license to export 56 kg U-235, contained in 7,875 kg depleted U herafluoride SHIRAKAMA,T Japan 62/12/10 GRIFFIN,J A Energy, Dept of Lp 16551 361
- BP12270092 Requests Executive Branch position re Amersham Intl.Ltd application for license to re-export 2 0 mg Cf-252 to Bouth Africa ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 STOIBER.C R State, Dept of Boreau of Director for Export of Export
- GP12270094 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 21MMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 GRIFFIN. J A Energy, Dept of 1p 16531 359
- 82:12270098 Advises that export of 5 lb Zircaloy-4 trex to Canada meets requirements of Atomic Energy Act & would not be inimical to common defense & security

 /IKMERMAN.J V Assistant Director for Export/Import & International Safeguards 82:12/15 Assistant Director for Export/Import & International Safeguards ip 16551 357
- 82/12270102 Requests extension of license to import small quantity of U-235 in in-core detectors until June 1983 ANGELONE. A Mitsubishi International Corp (subs of Mitsubishi Corp) PIT-L-3249 82/12/07 WRIOHT, B NRC No Detailed Affiliation Olven ip 16351 356
- 8212270105 Addendum to application for license to export 90 2 5mm Zircelay-4 alloy fuel channels to Japan * Cargenter Technology Corp 82/12/13 2pp 16551 354
- 8212270328 Addl response to FOIA request for documents re IAEA safeguards Forwards App A Documents 1.9 & 10 Remaining documents in Apps A & B completely & partially withheld (ref FOIA Exemptions 1 & 5)
 FELTON.J M Division of Rules and Records 82/11/15
 GREENBERG.E V Calloway & Greenberg 4pp 16555 329
- ~-H212270333 Advises that info supplied by State Dept does not clarify nature or significance of delay incurred in completing facility attachments for Swedish reactors Info partially withheld (ref FDIA Exemptions 1 & 5)
 SHERRIT S Material Transfer Safeguards Licensing Branch
 82/02/01 DEVINEJJ B Assistant Director for Export/Import & International Safeguards 1p 14555 334
- 8212280149 Application for license to export two WL22792 BF3 filled proportional counters to Japan POCH4L: WF Weatinghouse Electric Corp ZE60257 82/12/01 ip 16578 035
- 8212280155 License for Exxon Nuclear Co.Inc to import 23,200 kg/m, enriched to 3 55% U-235, from France PETERSON.M R Office of International Programs, Director 82/12/03 ip 16590 358
- 8212280172 Requests amend to export license increasing usage to 970,000 Ci Orders for tritium lighting devices confirmed PAISLEY.E J Saunders-Roe Developments, Ltd 82/12/06 HEMBY.E NRC No Detailed Affiliation Given ip 16590 359

NONDOCKETED ITEMS

- 8212280178 License for BMI to import 3 278 kg U.containing up to 2 686 kg U-235 & 0 7 g Pu.contained in spont MTR fuel assemblies from Canada ZIMHERMAN. J V Office of International Programs, Director 82/12/09 2pp 16590 344
- 8212280181 Requests withdrawal of 821112 application for import license for U-235 Matl delivered by normal channels PEVEY.L E Commerce. Dept of. National Bureau of Standards 82/12/03 Assistant Director for Export/Import & International Safeguards ip 16590-360
- G212300140 Forwards list of export licenses to be consolidated on One license for export of enriched U to Sweden Requests new litense be valid until Jan 1990 BHAMIA Edjow International Co 82/11/09 Assistant Director for Export/Import & International Safeguards 2pp 16624 195
- G212300143 Forwards Transhuclear Inc 821207 ltr re new checklist for Risso Research Reactor export license application for review M/o encl
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/14 STOINER, C R State, Dept of Sureau of Oceans & Internati
- B212300148 Amend 5 to Saunders-Roe Developments, Inc export license, increasing quantity from 1 million Ci to 2 million Ci tritium
 71MMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/13 ip 16624 187
- 8212300150 License for Teledyne Wah Chang Albany to expart 5 lb /ircaloy-4 Trex w/pure zirconium liner to Canada ZiHMERNAN.J V Assistant Director for Export/Import & International Safeguards 82/12/15 lp 14624 186
- 8212300153 License for Mitsui & Co (USA), Inc to export 337 kg U-235, contained in 11.279 kg U as U hexafluoride to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/15 ip 16624 184
- 9212300155 Application for license to export 5 kg deuterium.contained in 20 kg deuterium oxide, to India EDELSTEIN,B Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 25/82 82/12/08 ip 14424 183
- 8212300158 Application for license to export 5 kg deuterium,contained in 20 kg deuterium oxide,to Argentine EDELSTEIN.8 Aldrich Chemical Co. Inc. (subs. of Sigma-Aldrich Corp.) 26/82 82/12/08 ip 16624 182

- 8212300163 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Israel EDELSTEIN,B Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp) 24/82 82/12/08 ip 16624 180
- 8212300164 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oilde, to Jamaica EDELSTEIN, B Aldrich Chemical Co. Inc. (subs of Sigma-Aldrich Corp.) 27/82 82/12/08 lp 16624 179
- 8212300166 Application for license to export 5 kg deuterium, contained in 20 kg deuterium oxide, to Merico EDELSTEIN, B. A.Jerich Chemical Co. Inc. (subs of Sigma-Aldrich Corp.) 28/82 82/12/08 ip 16624 178
- 8212300169 Application for license to export 5 kg deuterium.comtained in 20 kg deuterium oxide, to Chile EDÉLSTEIN,B Aldrich Chémical Co., Inc. (subs of Sigma-Aldrich Corp.) 29/82 82/12/08 1p 16613 055
- 82:2300172 Informs that License XSNM-1987 may be issued No math changed circumstances since issuance of License XSNM-1987 MORRE, R N Assistant Director for Export/Import & International Safeguards 82/12/16 Assistant Director for Export/Import & International Safeguards 1p 16613 054
- 8212300173 Amend 1 to import license extending expiration date to 830630 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/12/14 Ip 16613 053
- Bil2300175 Application for license to export four heater fuel rods w/n nuclear matl & one annulus test section & fittings to Taiwan
 # General Electric Co | DN-111-82 | 82/12/10 | 1p | 16613 052
- 8012300178 Application for license to export 5 lb Zircaloy-4 Trex w/pure zirconium finer to Canada AERNI, 8 L Teledyne Hab Chang Albany 82/12/13 lp 16613 051
- 82:2300:80 Application for license to export 5 kg deuterium.contained in 20 kg deuterium oxide, to India EDELSTEIN, B Aldrich Chemical Co. Inc (subs of Sigma-Aldrich Corp) 31/82 B2/12/09 ip 16613 050
- BE12300181 Application for license to export 5 kg deuterium.contained in 20 kg deuterium oxide to Chile EDELSTEIN.B Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp) 30/82 B2/12/08 ip 16613 049

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJEC 1 CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAMODT, B M	8212010195	50-207 G	AMBROSINO, R A	8212280154*	50-416 S	AXEL RAD, J	8212170345	50-259 Q
AAMODT, M M	8212020346	50~289 G	AMBROSINO R A	8212280245*	50-416 9	AXELRAD, J	8212300327	50-331 8
AAMODT, M M	8212020401*	50-287 C	AMBROSINO, R A	B212280412*	50-416 S	AXELRAD, J A	8212270388	50-271 Q
AARDN, J. R	8212020244*	50-296 8	A RIGHTSONEMA	8212280475*	50-416 B	AXCLRAD, J A	8212270390	50-269 Q
ADROTT, E C	8212230343	50-397 A	AMSDEN, R L	8212220558*	COMMISSION	AXELSON, W L	8212060017*	50-315 Q
ABBOTT, E C	8212270466*	50-327 0	AMSTUTZ, S R	8212300341*	50-155 R	AXELSON, W. L.	#BES090518B	50-295 0
ADEL B L	8515030013*	50-285 S	ANANDAPPALA	8212080381*	50-249 8	AXELSON, W. L.	8212060252*	50-409 Q
ABELSON, H	8212060393	50-352 A	ANDERSON, C R	8212280371*	50-244 P	AXELSON, W. L.	8212150019*	50-407 0
ABEL SON, H	8515090348	50-352 A	ANDFRSON, F	8212220249	NUREG	AXELSON H L	8212210124*	50-237 G 50-282 G
ADEL SON, H	8212060510	50~352 A	ANDERSON, J G M	8212140762	NUREG	AXELSON, W L	8212210340*	
ABEL SON, H	8212070473	50-352 A	ANDERSON, N. R ANDERSON, P	8212270181 8212270316	NUREC	AXLINE.J W AYRES.J	8212210342* 8212270479	50-263 P 71-6144
ADELSON H ADRAHAM K	8212080015	50-352 A	ANDERSON, P	6212270323	50-266 0 50-266 0	BACHMANN, R G	8212030223	50-170 G
ABRAHAK, K	8212010058*	FOIA	ANDERSON, B. L.	8212140420*		BACKUS, R A	8212140426	50-443 G
ADRAMSON P B	8212010157* 9212010151	FOIA TOPREP	ANDOGNINI, Q C	8212130146	50-244 P 70-2949	DACKUS,R A	8212140426	50-443 G
ACKERMAN, U.C.	8212070456	40~8584	ANDRUS, N J	8212070407	40-4492	BACKUS, R A	8212230334	50~443 G
ACKERMAN, W.C.	9212230170	40~4492	ANGFLONE, A	8212270102	XPORTLIC	BACKUS, R A	8212230334	50-443 0
ADAMS.R E	8212130135	NUREO	ANTHONY, R L	8212230352	50-352 G	DAER, M R	8212270154	NUREQ
ADDADBO, J	8212230276	50~247 U	ANTHONY, R L	6515530325	50-352 G	BAER, R	0212210250*	50-313 0
ADENGAM, E. O	8212010122*	50~390 A	ANTHUNY, R L	8212230356	50-352 G	BAER, R L	8212280485	50-461 Q
ADENSAM, E G	8212010286	50~369 P	ANTHONY, R. L.	8212230354	50-352 G	RAGBY L A	8212150230	71-9167
ADENSAM, E Q	8212010506	50~329 F	APPEL, R R	8212080042	40-8781	BAGCHI, G	B205260070*	50-244 P
ADENSAM, E C	8212070072	50~390 A	ARAND, J	8212080317#	50-373 B	BAILEY, R J	8515030038*	50-244 Q
ADENSAM, E Q	8212100409	50-329 E	ARBIB.H A	8212270420	NUREG	BAILEY, R J	B212030147*	50-247 G
ADENSAM E G	8212130362	50~413 0	ARCHI TZEL	8212060305	50-317 S	DAILEY,R J	8512040212#	MISC
ADENBAN, E Q	8212820093	50-413 D	ARCHITZEL, R E	B212100013#	50-317 G	BAIN, Q M	8212270042* 8212030017*	50-289 P 50-344 9
ADENBAN, E. O	0212270426*	50-437 A	ARIAS. J	0212280167*	50~250 B	BAIR, Q G	8212130017* 8212140355*	50-344 B
ADERHOLD, H. C. ADERHOLD, H. C.	8212140146	50-97 R	ARIAS. J ARNOLD. R	8212280175* 8212040019*	50-250 B 50-320 P	Bair, g o Baisden, L	8212100167	CONTRACT
ADERHOLD, H C	6212140232 6212140238*	50-97 R 50-97 R	ARNOLD, R	851509001 4*	50-320 P 50-320 P	BAKER C E	8212070509	40-R6B1
ADERHOLD, H C	8212140469	50-97 R	ARNOLD, R	8212060019*	50~320 P	DAKER, C E	8212270012	40-8691
ADLER, R N	6212010166	50-77 R 50-289 0	ARNOL D. R. C	8212040015	50-320 P	BALL INGER, P	8212300111*	50-278 8
ADLER, R W	8212070502	50-287 G	ARNOLD, R C	82120600B5	50~320 P	BALLINGER, P L	8212270315*	50-278 R
ADLER, R W	8212140271	50-287 Q	ARNOLD, R C	8212170119	50-289 P	DANDER, T J	8212270487	NUREG
AERNI, B L	8212300178	XPORTLIC	ARSCNAULT, F J	82120B0013*	FOIA	BANDY, R	8212280055	RES
AGARWAL, R	8209230377*	50-195 P	ABITION, A. H	8212170402*	CONTRACT	BANKS, W W	8212130108	NUREO
AGEELU R	8212300218*	QA999	ATA: H	8212270333*	50~249 B	BANON, H	8212030025*	50~155 G
AGLES, J	8212070313*	50~280 Q	AULUCK, R	8515030570	50~397 A	DARAN, R	8212270134*	50-219 R
AGRAWALIA K	8212270054*	50-289 P	AULUCK, R	8212270505	50~397 F	BARBER. G	8212010158	50-219 8
AHI ARNE, J	8204130511*	FQIA	AUST IN, Q	8212140061*	50~295 R	DARBER. O	6212300327	50-331 6
AHN, 1 M	8515050010	RES	AUTER IND. L	8212140070*	50~286 R	DARLETT.D L	8208290112	70-143
ALBANESE, S	8212230241	50-247 0	AUTER IND, L	B212290140*	50~286 R	DARNES, C	821227037 <i>9</i> 8212280524	50-148 H 50-148 P
ALBERT, J	8212020065*	50-416 8	AUT10, H A	8212140184	50~29 S	BARNES, C	8212070034*	0A999
ALBERT, J M ALBERT, J M	8212210182* 8212280336*	50-416 S 50-416 S	AUTIO,H A AUTIO,H A	9212150155 8212210278	50~29 8 50~29 8	Barnes, I Rarnes, I	9212070122*	QA997
	9218200336*	30-416 8		9212210279	50-24 8			
ALBERT, H O	8212060274*	50-508 G	AUTIO, H. A	8212270251	50-27 8	DARNES, I	8212070169*	QA999 QA999
ALBERT, W G	8212210195*	50-50B G	AUTIO, H A	8212290310	50-29 B	BARNES, I	8212070434* 8212210105*	QA999 QA999
ALBGRT, W G ALBRIGHT, R H	8212280301*	50-508 Q	AVAN1 D AVERY, R	\$212080200* \$212070077	50-187 R	DARNES, I DARNES, I	8212210141*	0A999
ALBEN'N W	8212090204* 8212160058*	50-369 G 50-277 R	AVERY, R	8212070097 8212070083*	50-247 0 50-247 0	NARNES, I	8212210366*	QA999
ALEXICH H P	8212100253	50-315 J	AXELRAD, J	821201015B	50-219 5	DARNES, I	8212270213*	QA999
ALGER, D H	8212080331	50-196 P	AXELRAD, J	8212090354	50-382 8	BARNES, I	8212300032*	0A999 0A999
ALGERMISSEN S	8212280438*	50-409 P	AXELRAD, J AXELRAD, J	8212140519	I&E	Darnes, I Barnes, I	8212300263* 8212300280*	QA999
ALLEN, D T	8212090319*	State Prog	AXELRAD, J	8212170090	[&E	BARNETT, J E.	8212270173	70~1621
ALTER, S	8212230241	50~247 G	FIVE FUNDIO	9212170170	50-247 G	DANNETHO E.	12152\01\J	

AUTHOR	ACCESSION NUMBER	N SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION PARMUN	N GUBA	
BARNETT, J E BARNUM, E C BARR, K BARR, K BARR, K P	8212280254 8212010072 821207011 9212220471 8212070439	2 XPORTLIC 1* 50-320 Q 1* 50-289 Q 2* 70-27	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8212060225 8212150046 8212150060 8212220314 82122090205	50-302 P 50-302 S 50-302 S 50-302 S 50-302 P	BINGHAM, J BIRKEL, R A RISBEE, G D BISBEE, G D BISBEE, G D	8212230274 6212150176 8212160261 6212230344 6212230346	5 50-243 5 50-359 1 50-443 5 50-443	7 U 7 P 1 Q
BARR.K P BARR.K P DARR.K P DARR.K P BARRETT.D J	8212090204 8212090332 8212090500 8212090505 8212090517	* 50-416 Q * 50-250 Q * 50-338 Q * 70-143	BAYNE, J P BAYNE, J P BAYNE, J P RAYNE, J P BAYNE, J P	8212100214 8212100288 8212130232 8212130330 8212140294	50-286 P 50-286 P 50-247 P 50-286 P 50-233 F	018HOP, L L 018HOP, L L 018HOP, L L 018HOP, L L	8212200049 8212200049 8212280191 8212280191 8212280506	* 50-443 50-358 90-358) 6
BARRETT.L BARRETT.L H BARRETT.L H BARRETT.L H BARRETT.L H	8212270293 8212270293 8212010356 8212020405 8212020407	50-320 S 50-320 P 50-320 P 50-320 P	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8212210424 8212220234 8212220452 8212270259 8212270175	50-284 P 50-284 F 50-333 F 50-284 P 50-333 P	RISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W	8212040154 8212040164 8212040251 8212040353 8212130149	50-361 50-362 50-275 50-275 50-275	9
BARRETT.L H BARRETT.L H BARRETT.L H BARRETT.L H BARRETT.L H	8212070004 8212100170 8212100176 8212130154 8212230056	50-320 P 50-320 P 50-320 R 50-320 R 50-320 R	BAZIN.J DEACH.Q BEARM.E C BEARD.J T BECHHOEFER.C	8212270470 8212060456 8212220060 8212100159 8212070164	CONTRACT 40-8064 RES REVIEW GRP 50-327 G	BISHOP.T W RISHOP.T W BISHOP.T W BISHOP.T W BISHOP.T W	8212130243 8212130327 8212170261 8212170367 8212170391	50~362 50~264 50~261 50~266 50~361	
BARRETT.L H BARRETT.L H BARRETT.L H BARRETT.L H	8212270019 8212280519 8212290040 8212300101	50-320 P 50-320 R 50-320 P 50-320 P	BECK, M BECKHAM, J T BECKHAM, J T BECKNER, W D BEILMAN, T P	8212230121 8212150009 8212170244 8201120155* 8212290358*	40-8771 50-321 F 50-321 P RES 50-316 S	DISHOP, T W BLACKMAN, H S BLACKSHAW, G L BLAHA, G BLAKE, E L	8212210197 8212130108 8212030110 8212080251 8212070134	50-341 NUREQ 50-129 50-246 50-209	a
BARTH.C A BARTH.C A BARTH.C A BARTH.D E BARTH.K P	8212090222 8212160241 8212170073 8212230350	50-263 S 50-358 Q 50-358 Q 50-400 Q 50-329 Q	BELANGER, J L DELL, J T BELL, H J BELL, H J BELL, H J	8212070376* 8212270441 8212010252 8212010505 8212020132	50-155 Q NUREO Waste mot Waste mot Waste mot	BLANE, E L BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8212070134 8212090184* 8212090324* 8212090336* 8212090536*	50-289 50-400 50-41J	00000
BARTON,C BASHAM,P W BASKIN,K P BASKIN,K P DASKIN,K P	8212040433 8212220249 8110190952* 8212020253	50-440 G FOIA NUREG 50-206 P	BELL.M J BELL.M J BELL.N BELL.N BELMORE.C J	8212020199 8212230066 8212140418 8212160267 8212210044*	WASTE MGT WASTE MGT 50-397 G 50-522 G 50-219 R	BLAKE, J J BLAKE, J J BLAKE, R A BLANCH, P BLARCOM, E C	8212280453 8212270138 8212010150* 8212100217 8212160424*	50-260 COIA 90-272 M16C 40-6500	Si P
Caskin.k P Baskin.k P Baskin.k P Baskin.k P Baskin.k P	8212040239 8212040249 8212070190 8212070264 8212070103	50-361 P 50-206 P 50-206 P 50-361 P 50-206 P	BEMIS,P BENDER,M BENNETT,DE BENTING,KW BENTING,KW	8212030004 8212270471* 8212220162 8212210330* 8212210337*	50-261 S FOIA NUREO 50-263 P 50-263 P	BLAYLOCK, J BLAYLOCK, J BLAYLOCK, J BLOCH, P B BLOCH, P B	6212080113* 6212080117* 6212080154* 6212080315	70~ 143 70~143 70~143 50~155	٥
BASKIN, K P BASKIN, K P DASKIN, K P BASKIN, K P BASKIN, K P	8212090174 8212090376 8212090376 8212130039	50-204 P 50-341 P 50-341 P 50-341 P 50-342 J	BENTLEY.N R BERATAN,L L BERATAN,L L BERG,P BERGHOLZ,H E	8212280297* 8212290109* 8212290138* 8212280511 8212060113	50-259 p F01A F01A F01A 50-537 g	DLOCH.P B DLOCH.P B BLOCH.P B BLOCH.P B BLOCH.P B	8212100108 8212130191 8212130249 8212130041 8212140509	50~266 50~266 50~440 50~440 50~155	0 0000
Baskin, k p Baskin, k p Baskin, k p Baskin, k p	8212170164 8212170208 8212200028 8212210001 8212220198	50-206 F 50-206 F 50-361 F 50-206 P	BERGHOLZ, W E BERLIN, K BERMAN, H E BERNABEI, L BERNABEI, L	8212070082 8212010202 8212230241 8212020382 8212280128	50-537	BLOCH, P. D. BLODGETT, T. H. BLODGETT, T. H. BLODGETT, T. H.	8212230351 8212300015 8212300018 8212170243 8212280187	50-440 50-195 50-440 50-369 50-389	0 0 0 R
Baskin, k p Baskin, k p Baskin, k p Baskin, k p Basso, l f	8212230240 8212230291 8212230325 8212230349 8212040304*	50-204 P 50-361 P 50-361 P 50-361 P 50-361 P	BERNABEI.L BERNARD,H BERNATH.L BERNHOFT,SL BERRY,HE	8212200044 8212170171*	50-35B Q 50-97 P PR 50-305 B 50-289 P	BLODGETT, T H BLODNI, R BLOSSOM, J N	8212280333 8212280405 8212140474 8212140388* 8212290157	50-349 50-389 NUREO 50-537 40-8452	Λ Α
BASSO, L F BASSO, L F BATES, A BATES, A BATES, J W	8212210048* 8212290282* 8212270453* 8212270461*	50-317 S 50-317 S 50-317 S FOIA FOIA	BERRY, Z E BERRY, Z E BERRY, Z E BERTOSSA, D C BETTENHAUSEN, L	8212100220* 8212210207* 8212170101*	50-250 B 50-250 S 50-250 B 50-277 P 50-336 Q	BLUBAUGH, A R BLUBAUGH, R E BLUBAUGH, R E BLUM, J M BLUM, J, M	8212160491* 8212030281 8212290123 8212060077 8212060077	50-277 40-3453 40-3453 50-247 50-247	0
BATES, J W BATT, D L BATY, D. L BAUER, E O BAUER, E O	8212070416* 8212270145 8212270047* 8212060106*	70-1151 70-143 NUREG 50-289 P 50-277 P	Bettenhausen, L Bettenhausen, L Bettenhausen, L Bettenhausen, L Bettenhausen, L	8212030200* 8212030207* 8212030221*	50-293	BLOW' A W BLOW' A W BLOW' A W	8212060089* 8212060089* 8212060098 8212060090 8212090101	50-247 50-247 50-247 50-247 50-247	0000
BAVER, E G BAWNACK, W H BAXTER, T A BAXTER, T A BAXTER, T A	8212150062* 8212030078* 8212100079 8212100079	50-278 P 50-277 P 50-333 Q 50-400 Q 50-400 Q	BETTENHAUSEN, L BETTENHAUSEN, L BEVERLY, K BEVERLY, K BEVER, B D	8212070148# 5 8212020357# 5 8212100319# 5	50-322 Q 50-329 Q 50-249 S 50-237 S 50-237 S	BLUM, J M BLUM, J M BLUM, J M BLUM, J M BLUM, J M	8212140384 8212140393* 6212140400* 8212200032 8212210238	50-247 50-247 50-247 50-247 50-247	0000
BAXTER, T A	8212200026 8212270222 8212270222 8212300226	50~312 G 50~312 G 50~400 G 50~400 G	BIALIK, E I BIBB, H E BIBB, H E BIBI, H E BIDINGER, O H	8212090537# 5 8212090542# 5 8212090544# 5	0-247	BODDE, D L BODDE, D L BODDE, D L BODINE, J C BOGART, D	8212080044* 8212080070* 8212080081* 8212040175* 8212140051*	FOIA FOIA 50~244	6
BAXTER, W F BAXTER, W F BAYLOR, V B BAYLOR, V B	8212010053+ 5 8212010290+ 5 8212010486 R 8212220519 R	50-483 G 50-389 M 50-389 M 185 ES	BIDINGER.O H BIDINGER.O H BIEWALSKI.A BIEWALSKI.A BIGGS.O	8212170011* 7/ 8212300078 7/ 8212080235 5/ 8212080245* 5/	0~2928 0~36 0~454 G 0~454 G	BOODEN, O BOOLWERK, P BONDRE, J R BOOK, H E	8212020154 8212130105 8212080684* 8212210327* 8212210327*	50-263	R H P
AYMARD, P. Y AYMARD, P. Y AYMARD, P. Y AYMARD, P. Y	8211090043 5: 8212020045 5: 8212020063 5:	ES 0-302 P 0-302 S 0-302 S 0-302 S	BILANIN, A J BILL INOB. H D BIMBER, R H BIMBORD, F T BIMOGELI, B L	8212280354* 50 8212130227* 50 8212200051 50 8212070435 50	0-498 A 0-387 P 0-29 P 0-440 H 0-250 0 0-295 S	9 H, XDOB 3 H, XDOB 4 H, XDOB 4 H, XDOB 5 H, XDOB 8 H, XDOB 8 H, XDOB	8212060168* 8212130298* 8212210185* 8212300213* 8212300240*	50-197 50-344 70-734 70-25	0 0 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ADHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8212100239* 8212210136 8212210176 8212220274 82122202183	50-458 G 50-458 S 50-458 S 50-458 A 50-458 S	BOWMAKER, N J BOWMAKER, N J BOYD, D C BOYD, D C BOYD, D C	8212080197 8212280208* 8212030129* 8212080522* 8212280251*	50-317 P 50-317 Q 50-255 Q 50-155 Q 50-315 Q	BROTTON: 6 C BROTTON: 6 C BROWN: C BROWN: C O BROWN: C G	8212270018 821227027* 8212270276 821207052* 8212020087*	71-490 71-490 50-263
BOOKER, J E BOOKER, J E BOOKER, J E BORCHELT, M L BORCHERF, R	8212270236 8212280176 8212280252 8212170131* 8212080415*	50-458 S 50-458 S 50-458 S 50-498 A 50-336 S	BOYD, D C BOYD, R BOYER, V S BOYER, V S	8212290335* 8212070111* 8212140319* 8210040253* 8212030132*	50-315 Q 50-320 Q 50-320 Q 50-352 A 50-352 A	BROWN, C 0 BROWN, H H BROWN, H H BROWN, J F	8212150108* 8212220322* 8212220374 8212220374 8212130182*	50-302 8 50-302 8 50-275 0 50-275 0 CONTRACT
DORCHERT.R RORDENICK.B M BORDENICK.B M BORDENICK.B M BORDINE.T C	8212210233* 8212210007 8212220128 8212220135 8212030017	50-336 8 50-277 0 50-322 0 50-322 0 50-155 0	DOYER, V S BOYER, V S BRACHMAN, J Y BRADBURY, R B BRADBURY, R B	8212210495* 8212270141 8212210435 8212220242 8212200045	50-352 A 50-352 A 50-440 D PR PR	BROWN. M BROWN. R G BROWN. R L BROWN. R T BROWN. 8 R	8212160148* 8212040471 8212200084* 8212010150* 8212010474	71-454 50-275 P 50-458 Q 50-272 P RES
BORDINE.T C BORDINE.T C BORES.R DORES.R J BORGMANN.E A	8212100304 8212280131 8212220274 8212030037* 8212010089	50-155 8 50-155 0 50-309 S 50-219 0 50-358 A	DRADFORD, W H BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J	8212070519# 8210040239 8212030122 8212060076 8212060106#	50-348 @ 50-352 K 50-352 A 50-277 P 50-277 P	DHOWNING, REBROWNING, REBROWNLES, VEROWNLES,	9212010232 9212270430 8212280060 9212090245* 8212090545*	WASTE MGT WASTE MGT 80-302 S 50-424 Q 50-395 Q
BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A	8212020225 8212020257 8212020320 8212020347 8212030111	50-358 S 50-358 S 50-358 S 50-358 S 50-358 S	BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J	8212070025 8212070138 8212080446 8212100075 8212100079*	50-352 A 50-352 F 50-352 A 50-278 P 50-278 P	DRUNNER, J E BRUNNER, J E BRYANT, J C BRYANT, J C BRYANT, J C	8212010035 8212210314 8212090189* 8212090241* 8212090380*	50-329 A 50-329 G 50-269 G 50-413 G 50-369 G
BORGMANN.E A BORGMANN.E A BORGMANN.E A BORGMANN.E A BORGMANN.E A	8212040030* 8212040039* 8212080472 8212070028* 8212070074	50-358 Q 50-358 F 50-358 F 50-358 F 50-358 K	BRADLEY.E J BRADLEY.E J BRADLEY.E J BRADLEY.E J	8212100274 8212130341 8212130058 8212150062* 8212170265	50-352 C 50-352 K 50-277 P 50-277 P 50-277 P	BRYANT, J C BUCKHAM, J A BUCKLES, J BUCKLES, J BUDNITZ, R J	8212150086 8212090405 8212280205 8212290213 8005071094	50-413 S 50-332 G 50-358 J 50-315 J 50-320 P
BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A	8212140340* 8212140342* 8212170080 6212170107 8212170191	50-358 A 50-358 A 50-358 K 50-358 R 50-358 R	BRADLEY,E J BRADLEY,E J BRADLEY,E. J BRADLEY,E J BRADLEY,E J	8212210398 8212210402 8212210491 8212270144 8212280209	50-352 F 50-352 A 50-352 K 50-352 F 50-352 A	BUDNITZ,R J BUDNITZ,R J BUDNITZ,R J BUNITNUJ D BUNITNUJ D	8005270712 8005270827 800620271 8212010217 8212010220	RES RES RES WASTE MOT WASTE MOT
BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A	8212170260 8212210031* 8212210545* 8212270190 8212280171*	50-358 8 50-358 0 50-358 F 50-358 8 50-358 0	BRADLEY,E J BRADLEY,R BRADY,N F BRAINARD,M F BRAMLETT,L S	8212270276 8212270431* 8212060511* 8212100162* 8212270236*	50-352 R 50-3 H 40-86 CONTRACT 50-368 R	O F'ONILNAB O F'ONILNAB O F'ONILNAB O F'ONILNAB	8212020144 8212230126 8212230138 8212230153 8212230231	WASTE MOT WASTE MOT WASTE MOT WASTE MOT
Boromann, E. A Boromann, E. A Boromann, E. A Boromann, E. A Doromann, E. A	8212290277 8212290285 8212290342 8212290343* 8212290364	50-358 8 50-358 8 50-358 8 50-358 0 50-358 8	Brandenburg, B Brandenburg, B Brandenburg, B Brandenburg, B Brandenburg, B	8212020318 8212040103 8212070087 8212070070 8212140423	50-247	DUNDINO, J O BUONDCORE, J A BURDETTE, E O BURDCIN, J F BURGER, F J	B212270455 B2120B0221 B21202033B* B212130171* B212150176*	WASTE MOT XPORTLIC 50-443 A 50-275 G 50-271 R
Borgmann, e a Borgmann, e a Borgmann, e a Borgmann, e a Borgmann, e a	8212270397 8212270425* 8212270429* 8212270438 8212270454*	50-358	Brandenburg, B Brandenburg, B Brandenburg, B Brandenburg, B Brandenburg, B	8212140439 8212140446* 8212160289 821220271 8212230187	50-247	BURGIN.R E BURIAN.R J BURKE.D J BURKE.D J	8212220262 8212150212 8212210527 8212070234* 8212070313*	40-8135 71-5957 71-5957 50-280 0 50-280 0
BDRGMANN,E A BORGMANN,E A DORKDWSKI,R J BORST,F J BORST,F J	8212290467 6212270483 8212270435 8212200043 8212200050	50-358 S 50-358 S NUREO 50-267 F 50-267 F	Brandenburg, B Brandenburg, B Brannin, J P Brannin, J P Brannin, J P	8212280273 8212300230 8212070410* 8212200085* 8212300065*	50-247	BURSTEIN, S. BURWELL, S II BUSS, R BUSS, R D BUTKO, K J	9212070079 8212080104 8212080404# 8212130202* 8212280543	50-266 F 50-445 A 50-265 B 50-254 R NUREC
BOSNAK, R J BOSNAK, R J BOUCHEY, C D BOUCHEY, C D	7912190426* 8207280369* 8210270013 8212030107 8212070131	50-204 P FOIA 50-397 A 50-397 Q 50-508 F	DRASTAD, Q W BRAUN, D J BRENNER, L BREWER, S T BRIDEN, D H	8212170379* 8212270199* 8212270220 8212070378* 8212160107*	50-397 A 50-237 P 50-322 Q COMMISSION 50-346 F	BUTLER, 8 D BYRD, R BYRD, R BYRD, R	8212090384* 8212020037* 8212020144* 8212280352* 8212280463*	50-327 0 50-416 9 50-416 9 50-416 9
BONCHEA' 6 D BONCHEA' 6 D BONCHEA' 6 D	8212100256 8212130033 8212140194 8212150021 8212150029	50-397 F 50-508 K 50-508 C 50-508 A 50-508 A	BRIGGS, L BRIGHT, Q C BRIGHT, Q C BRIGHT, Q C BRIGHTSEN, R A	8212140084* 8212070073 8212150026 8212300018 8212080076*	50-213 G 50-483 G 50-483 G 50-440 G FOIA	BYRD.R BYRD.R BYRDN.P M BYRON.P M. CAGNETTA.J P	8212300119* 8212300200* 8212100203* 8212100263* 8212020279	50-416 8 50-416 8 50-341 0 50-346 0 50-213 F
BONCHEA'O D BONCHEA'O D BONCHEA'O D BONCHEA'O D	8212170138 8212170173 8212170175 8212170314 8212170374	50-397 E 50-397 A 50-397 A 50-397 H 50-397 A	DRINKMAN, D BRINKMAN, D B BRODST, G E BROCARD, D N DROCK, B L	8212140482 8212080409 8212080448* 8212270520 8212210246*	50-362 P TOPREP 50-317 B NUREO 70-25	CAGNETTA, J P CAGNETTA, J P. CAGNETTA, J P. CAGNETTA, J, P CAGNETTA, J P	8212020380 8212070289 8212080541 8212080541 8212100277	080 50-213 P 50-423 S 50-423 S 50-245 P
BONCHEA'O D BONCHEA'O D BONCHEA'O D BONCHEA'O D	8212200003 8212200036 8212200047 8212200073 8212200074	PR PR 50-397 A PR 50-397 A	BROCK.B L BROCKETT, T BROCKETT, T BROCKETT, T W BROCKETT, T W	8212300213* 8212170090 8212170345 8212140182* 8212140342*	1&E 50-257 Q 40-6500 40-6500	CAGNETTA, J. P CAGNETTA, J. P CAGNETTA, J. P CAGNETTA, J. P CAGNETTA, J. P	9212100277 8212170279 8212170279 8212210355 8212210355	50-245 P 50-245 P 50-423 F 50-423 F
BOUCHEY, O D BOUCHEY, O D BOUCHEY, O D	8212200083 8212230208 8212270159 8212280440 8212270180	50-397 E 50-508 A 50-397 A 50-460 A 50-397 K	BROCKETT,T W BRODSKY,R.L BROEHL.D J BRONS,J C BRONS,J C	8212160370* 8212230238 8212140280 8212130355* 8212130357*	50-247 0 50-344 F 50-286 F 50-286 F	CAGNETTA, J P CAMALAN, J E CALDWELL, R A CALK, J C CALLAN, L J.	8212230257 82122702509 82121500499 82122705069 8212210208	50-112 Q CONTRACT 50-368 8
BDUCHEY, G D BOURNIA, A BOURNIA, A BOURNIA, A BOWJE, T B	6212270241 6212060381 8212130151 6212300203* 6212160004	50-397 A 50-373 P 50-373 P 50-416 P 70-1100	BRONB.JC BRONB.JC BRONB.JC. BROOKS.BC BROOKS.E.H	8212140064 8212210322 8212290156 8212270459 8212090277*	50-286 R 50-286 P 50-286 R NUREO 90-280 G	CALLANIL J CALLANIL J CALLANIL J CAMPIL F CAMPBELLIR, H	8212280345 8212290210 8212300182 8212280173 8212020060	50-313 8 50-313 8 50-349 8 1 TOPREP WASTE MOT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	Subject Category
CAMPDELL, R H CANTER, H L CANTRELL, F CANTRELL, F S CANTWELL, P F	8212170405 8212040171* 8212070519* 8212070479* 8212140327*	40-4500 50-312 0 50-348 0 50-257 0 50-275 5	CARTWRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R	8212300220* 8212300232 8212300237 8212300238* 8212300241*	50-338 S 50-338 S 50-339 S 50-338 S 50-337 S	CHILK.S J CHILK.S J CHILK.S J CHILK.S J CHILK.S J	0212070174 0212070103 8212070457* 0212070494* 0212070500*	50-329 9 50-289 9 50-298 F 50-298 T 50-298 P
CARDONE, A T CARDONE, A T CAREY, J J CAREY, J J CAREY, J J	8007180114* 8007230260* 8212020078 8212020084* 8212030142	50-206 P 50-206 P 50-334 P 50-334 P 50-334 P	CARTURIGHT, W R	8212300245 8212300247* 8212300251 8212300255* 8212300261	50-338	CHILK.S J CHILK.S J CHILK.S J CHILK.S J	8212090052* 8212090065* 8212090097 8212090209* 8212090210*	FOIA FOIA 50-275 © FOIA FOIA
CAREY, J J CAREY, J J CAREY, J J CAREY, J J CAREY, J J	9212030148 9212080474 9212080480* 9212090520 9212100041*	50-334 P 50-334 P 50-334 P 50-334 P 50-334 Q	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARUSO, R	8212300267# 8212300291# 8212300313 8212300315# 8211080107#	50-338 S 50-339 S 50-338 S 50-338 S 50-29 P	CHILK,S J CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8212090230* 8212100114 8212130205 8212130214 8212140438	F01A 50-522 G 50-537 G 50-4[3 G 50-277 G
CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8212130242 8212130243 6212130246* 6212140339 8212170200	50-334 P 50-334 P 50-334 P 50-334 P 50-334 F	CARUSO, R CARUSO, R CARVER, A M CARVER, A M CASE, E Q	8212020356 8212130228 8212030072* 8212210100* 8212130359*	50-29 P 50-29 P 50-327 S 50-328 S 50-352 G	CHILK.S J CHILK.S J CHILK.S J CHILK.S J	8212150045 8212150051 8212150057 8212140375 8212210242	50-289 G 50-275 G 50-275 G 50-247 G 50-413 G
CAREY, J J, CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8212270155 8212270161* 8212270201 8212270207* 8212270225	50-334 P 50-334 P 50-334 P 50-334 P 50-334 R	CASE, E G CASH, A CASHWELL, R. J CASSIDY, B P CASSIDY, B P	8212130361* 8212160361 8212140175 8212150137* 8212150153*	50-352 G 71-9006 50-154 S 50-382 G 50-382 G	CHILK.S J CHILK.S J CHILK.S J CHILK.S J	8212210319 8212220003 8212220004 8212220017 8212220264	50-289 T 100FR 50-3 F 50-275 P 50-289 0
CAREY, J J CAREY, J J CARLISLE, C S CARLSON, J D CARLSON, J D	8212270289* 8212300107 8212300318* 8212360261* 8212060364*	50-334 Q 50-334 F 50-397 Q 50-275 Q 50-275 Q	CATCHPOLE, G J CATCHPOLE, G J CATCHPOLE, G. J CATION, I CATTON, I	8212070461 8212070480 8212100083 8208290028 8208290029	40-8745 40-8745 40-8745 ACRS ACRS	CHILK.B J CHILK.B J CHILK.B J CHILK.B J CHILK.B J	8212230174* 8212230211 8212230344 8212230358 8212230360	FOIA 50-34f
CARNEY, W CARDW, J F CARPENTER, J H CARPENTER, T CARR, A V	8212080667* 8212280051 8212270220 8212270023 8212100096	50-322 H RES 50-322 O 50-204 Q 50-413 G	CATTON, I CATTON, I CATTON, I CAYIA, A J CERNE, A C	8208270027 8212060323 8212070440 8212270306* 8212210282*	ACRS ACRS ACRS 50-307 S 50-443 Q	CHILK,S J CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8212270050 8212270052* 8212270114* 8212270214 8212270217	10CFR FOIA FOIA 50-247 G 50-275 G
CARR, A V CARROLL, J Y CARTER, R S CARTER, R S CARTER, S	8212280174 8001140342 8212210411 8212270402* 8212020354*	50-413	CHACKES, K M CHACKES, K M CHAMBERS, O S CHAMBERS, O S CHAMBLEE, J A	8212280179 8212280179 8212280010* 8212080058* 8212100049	50-483 G 50-483 G FOIA FOIA FOIA	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	821227024	50-358 0 50-247 0 50-413 0 50-247 0 50-241 P
CARTER, B CARTWRIGHT, W CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8212070369* 8212300286 821230043 8212070064* 8212070067	50-259 S 50-339 S 50-338 S 50-338 S 50-339 S	CHAN, B C CHANCELLOR, R A CHANDLER, J C CHANDLER, J C CHANDLER, J C	8212270534 8212030306 8212030088 8212140170 8212150003	RES 40-8200 TOPREP TOPREP TOPREP	CHILK.S J CHILK.S J CHILK.S J CHILK.S J	8212300026 8212300142 8212300151 8212300159 8212300244	50-327 0 50-287 0 10CFR 10CFR 50-358 0
CARTWRIGHT, W R	8212090072* 8212090102 8212090107* 8212090112 8212090115*	50-337 S 50-339 S 50-339 S 50-338 S 50-338 S	CHANDLER, J.C. CHANDLER, L.J. CHANDLER, L.J. CHANEY, H. D. CHANG, K.C.	8212270215* 8212070007 8212070199 8212100233* 8212210005*	50-237 P 50-361 0 50-361 0 50-285 0 50-275 P	CHIN, 8 L CHIN, 8 L CHO, D H CHRISBOTIMOS, N CHRISTEL, B	8212100206 8212100291 8212070083* 8212030197* 8212170225*	50-275 P 50-275 P 50-247 D 50-254 Q 50-249 S
CARTWRIGHT, W R	0212070272 0212070207* 0212070527 0212070530* 0212150028	50-337 S 50-337 S 50-338 S 50-338 S 50-338 S	CHAPLIN.S D CHAPLIN.S D CHAPLIN.S D CHAPLIN.S D CHAPYAK.E J	8212040324* 8212150044* 8212220454* 8212270240* 8212130157	50-320 S 50-320 S 50-320 S 50-320 S 50-537 A	CHRISTEL, B CHRISTIAN, D CHRISTMAN, J CHRISTOFFER, Q CHRISTOFFER, G	8212280479# 8212100260 8208290121 8212090396# 8212280220#	50~237 S 50~389 A FOIA 50~155 Q 50~10 Q
CARTWRIGHT, W R	9212150034* 6212150074 8212150074* 6212200027 8212200037*	50-338	CHARNOFF, O CHARNOFF, O. CHASE, J H CHAUDHARY, S K CHEN, P Y	8212060413* 8212070096* 8212090479* 8212070269* 7709280656*	CONTRACT COMMISSION 50-259 Q 50-352 Q 50-237 P	CHRIBTOPHER, W CHU, K K CHU, M S CHU, M S CHUNG, J W	8212140444* 8212160762 8212010469 8212010481 8212070158*	50-259 S NUREO RES RES 50-387 Q
CARTWRIGHT.W R CARTWRIGHT.W R CARTWRIGHT.W R CARTWRIGHT.W R CARTWRIGHT.W R	8212210137 8212210147* 8212210143 8212210171* 8212210254	50-338 6 50-338 5 50-338 5 50-338 5 50-339 5	CHILK.E J CHILK.E J CHILK.E J	821220282 8112270035* 8212220345 8103310251* 8104100175*	NUREG 50~244 P 50-400 B FOIA FOIA	CHUNG.J W CHURCHILL,B W CHURCHILL,B W CHURCHILL,B W CHURCHILL,B W	8212270448* 8212100078 8212100078 8212100100 8212100100	50-387 Q 50-382 Q 50-382 Q 50-382 Q
CARTWRIGHT, W R	8212210269* 8212220244 8212220268* 8212220364 8212220368*	50-339 8 50-338 8 50-338 8 50-339 8 50-339 8	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	82[1150416 8212010076* 8212010105* 8212010317 8212010518	90-375	CHURCHILL, B W	8213230357 6212230357 6212230359* 6212230359* 6212280182	50-266 Q 50-266 Q 50-266 Q 50-266 Q 50-382 Q
CARTWRIGHT, W R	8212220387 8212220391* 8212220392 8212220397* 8212220399	50-339 8 50-339 8 50-339 8 50-339 8 50-338 8	CHILK, 8 J. CHILK, 8, J CHILK, 8 J CHILK, 8 J CHILK, 8 J	8212020012* 8212010526 8212010530 8212010530	10CFR 50-395 P 50-388 A FOIA FOIA	CHURCHILL, B W CHURCHILL, R CILIMBERG, R CILIIS, M CIPOLLA, A J	8212280182 6212270030* 6212270336* 6212130278* 6212160060	50-382 0 70-33 50-266 0 50-187 0 40-3392
CARTWRIGHT, W R. CARTWRIGHT, W R. CARTWRIGHT, W R. CARTWRIGHT, W R. CARTWRIGHT, W. R.	8212220408* 8212220410 8212220416* 8212300079 8212300104*	50-338 8 50-338 5 50-338 8 50-339 8 50-339 8	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8212020054# 8212020067# 8212020075# 8212020247 8212040092	FOIA FOIA FOIA PRM 50-289 G	CLARK, A T CLARK, A T GLARK, L CLARK, P R CLARK, P R	8212130430 8212220511 8212280406 8212060247 8212140180	50-201 P PROJ 50-20 P 50-219 P 50-289 P
CARTWRIGHT, W. R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	8212300124 8212300130* 8212300171 8212300177* 8212300217	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	CHILK, S J CHILK, S J CHILK, S J CHILK, S J CHILK, B J	8212040104 8212040242 8212040243 8212040427* 8212040427	50-275 Q 50-289 Q 50-413 Q FGIA 50-437 Q	CLARK, P R CLARK, R CLARK, R CLARK, R A CLARK, R A	8212150110 8212070033* 6212070037* 8212010234 8212010334	50-289 P 50-335 P 50-335 P 50-285 F 50-309 P

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212010417 8212010458 8212020371 8212020409 8212070082	50-307 P 50-285 P 50-285 P 50-338 P 50-247 P 50-317 P	COLLINS.J T COLLINS.J T COLLINS.J T COLLINS.J T	8212060455 8212070437* 8212070473* 8212080506 8212100197	NUREG 50-298 F 50-267 F 50-298 Q 50-298 Q	COONEY, M J COONEY, M J COONEY, M J COOPER, W E COOPER, W E	8212150061 8212160055 8212160415 8212160415 8212010206 8212080479	50-277 S 50-277 R 50-277 S 50-275 R 50-275 P
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212070084 8212070105 8212070454 8212080012 8212080031	50-267 P 50-317 P 50-309 P 50-317 P 50-318 Q	COLLINS.J T COLLINS.J T COLLINS.J T COLLINS.J T	8212140403 8212200121 8212210021 8212280423 8212280430*	50-298	COOPER.W E COOPER.W E COOPER.W E COOPER.W E COOPER.W E	8212100206 8212100291 8212140278 8212140281 8212270146	50-275 P 50-275 P 50-275 P 50-275 R 50-275 R
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212080040* 8212090032 8212090050 8212090053* 8212130092	50-318	COLLING, J T COLLING, T R COLOMBO, R COLOMBO, R COLOMBO, R	B212300121 0212070332* 0212140401 0212170235* 0212200048*	50-445 Q 50-416 Q 50-312 P 50-312 R 50-312 R	CODPER,WE COPELAND,V G COPELAND,V G COPELAND,V G COPELAND,V G	8212270205 8212070327 8212070327 8212070352* 8212070352*	50~275 P 50~155 G 50~155 G 50~155 G 50~155 G
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212130095* 8212130366 8212130357* 8212130372* 8212150226	50-309 P 50-344 P 50-344 P 50-344 P 50-267 P	COLOMBO, R COLOMBO, R COLOMBO, R H COLOMBO, R H COLOMBO, R H	8212270288# 8212270291* 8212030095* 8212030106* 8212030116*	50-312 S 50-312 S 50-312 S 50-312 S	COPFLAND, V G COPELAND, V G CORYELL, G P CORYELL, G P COSTELLO, J R	8212210285 8212210285 8212080137* 8212070451* 8212210223*	50-155 Q 50-155 Q FOIA 50-332 Q QA999
CLARX.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212150229 8212160542 8212160751 8212170024 8212210013	50-309 P 50-313 F 50-309 F 50-280 F 50-313 P	COLOMBO.R W COLOMBO.R W COLSHER.C S COLSHER.C S COLSHER.C S	82120403004 8212270285 8212140464 8212160773 8212070513	50-312 S 50-312 P NUREO NUREO XPORTLIC	COTTER.B P COTTER.B P COTTER.B P COTTON.G D COUNSIL.W G	8212230215 8212230315 8212280192 8212030168* 8211080257	50-45B
CLARK,R A CLARK,R A CLARK,R A CLARK,R A CLARK,R A	8212220551 8212270025 8212270483 8212270542 8212270544#	50-335 P 50-309 F 50-344 F 50-318 P 50-318 P	CONDON, W A CONLON, T E CONLON, T E CONLON, T E CONLON, T E	8212140479 8212090256* 8212090258* 8212090275* 8212090308*	50-259 P 50-400 Q 50-424 Q 50-387 Q 50-335 Q	COUNSIL.W 0 COUNSIL.W 0 COUNSIL.W 0 COUNSIL.W 0	8211080257 8212020297 8212040157 8212040157 8212040374	50-245 P 50-213 F 50-213 P 50-213 P 50-213 O
CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8212280082 8212280410 8212290022 8212290494 8212290499*	50-266 F 50-344 P 50-313 P 50-335 P 50-335 P	CONLON, TE CONLON, TE CONLON, TE CONLON, TE CONLON, TE	8212090321* 8212090355* 8212090364* 8212090407* 8212090465*	50-324	CONVEIT'M O CONVEIT'M O CONVEIT'M O CONVEIT'M O	8212070124 8212070124 8212070284 8212070284 8212070289	50-245 F 50-245 F 50-245 P 50-245 P 50-213 P
CLARK,R A CLARK,R A CLAY,E L CLAYTON,F L CLAYTON,F L	8212270501* 8212300041 8212070413* 8212020130 8212020182	50-335 P 50-317 P 70-143 50-348 P PR	CONNAUGHTON, K CONNER, E L CONNER, E L CONNER, T B CONNER, T B	8212100308* 8212070034* 8212130102* 8212020330 8212020330	50-454 0 50-317 P 50-307 P 50-352 G 50-352 G	COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	B212080541 B212080541 B212090114 B212090114 B212100071	50-423 S 50-423 S 50-213 F 50-213 F 50-245 Q
CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L CLAYTON.F L	8212070336 8212090295 8212090362 8212090412 8212100070	50-364	CONNER, T B CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8212020337* 8212020339* 8212210261 8212210261 8212230327	50-352	COUNSIL, W 0 COUNSIL, W 0 COUNSIL, W 0 COUNSIL, W 0	8212100071 8212100277 8212100277 8212140144 8212140144	50-245 Q 50-245 P 50-245 P 50-336 P 50-336 P
CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8212150033 8212170197 8212170234 8212170297 8212210130	50-364 P 50-348 R 50-364 P 50-364 R 50-364 P	CONNER, T B CONNER, T B CONNER, T B CONNER, T B CONNER, T B	8212230327 8212270214 8212270214 8212280185 8212280185	50-352 0 50-352 0 50-352 0 50-352 0 50-352 0	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8212140221* 8212140221* 8212150034 8212150128 8212150128	50-245 G 50-245 G 50-213 F 50-245 P 50-245 P
CLAYTON, F L CLAYTON, F L CLEMENSON, F CLEMENTS, B R CLEMONS, P	8212280280 8212300214 8212150333* 8212160428 6212030032*	50-348 P 50-364 B NUREO 50-445 A 70-1100	CONNER,T B CONNER,T B CONNOR,J E CONNOR,L CONSTABLE,Q L	8212300187 8212300187 8212080516 8208290104 8212070123*	50-352 G 50-352 G RES FOIA 50-382 G	COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	B212160216 B212160216 B212160216 B212160470 B212160470	PR PR PR 50-423 8 50-429 8
CLEVELAND, R S CLING, W E COBB. G H COBB. L I COBB. L I	8212160105* 8212070351* 8212280012* 8208170245 8208170257	40-6500 50-261	CONSTABLE, Q L CONTE, R CONTE, R CONVERSANE, E CONWAY, J T	8212280378* 8212140319* 8212220478* 8212270273* 8212210105*	50-392 G 50-320 G 50-297 G CONTRACT GA999	COUNSIL.W G COUNSIL.W G COUNSIL.W G	8212170117 8212170199 8212170199 8212170279 8212170279	50-245 P 50-245 P 50-245 P 50-245 P 50-245 P
COCKRELL, R G COOD, H COHEN, C B COHEN, E H COLFN, I	9212070185 9212230241 8212160518 8212270023 8212270388*	50-111 W 50-247 O PR 50-206 G 50-287 O	CONMAY, J T CODR, J W CODR, J W CODR, J W CODR, J W	8212210366* 8212130084* 8212020313 8212070017 8212080392	0A777 50-333 R 50-327 B 50-327 R 50-327 A	CONNSIL.W G COUNSIL.W G COUNSIL.W G	8212170321 8212170321 8212210057 8212210121 8212210121	50-245 P 50-245 P 50-213 P 50-213 P 50-213 P
COHN.B M COLARULLI.P F COLARULLI.P F COLARULLI.P F COLARULLI.P F	8204100047* 8212080310 8212080310 8212070070 8212140380*	50-344 F 50-247 G 50-247 G 50-247 G 50-537 A	COOK: J M COOK: J M COOK: J M COOK: J M	8212070066 8212100237 8212100273 8212140347* 8212170144	50-329 A 50-329 S 50-329 S 50-329 A 50-329 A	COUNGIL, H G COUNGIL, H G COUNGIL, H G COUNGIL, H G	8212210121 8212210355 8212210355 8212230257 8212270152	80-213 P 50-423 F 50-423 F 50-213 P 50-245 P
COLE.D COLE.R F COLEMAN.J M COLEMAN.J M	8212140530 8212200107 8212100104 8212100104 8212140245	PR 50-454 0 50-338 0 50-338 0 50-338 0	COOK! 7 M COOK! 7 M COOK! 7 M COOK! 7 M	8212210154 8212210309 8212230112 8212270126 8212280207	50-329 B 50-329 A 70-2764 50-329 S 50-329 D	COUNSIL, N G COUNSIL, N G COUNSIL, N G COUNSIL, N G	8212270152 8212280119 8212290447 8212290447 8212160431	50-245 P 50-213 F 50-245 P 50-245 P PR
COLEMAN, J M COLEMAN, J M COLEMAN, J M COLEY, J L COLLIEN, A R	8212140245 8212140249 8212140249 8212140249 8212070186* 8212070187*	50-338 0 50-338 0 50-338 9 50-400 0 50-454 A	CODK, J W COOK, J W COOK, J W COOK, J W	821 2280 225 821 2280 320 821 2270 203 821 2270 208* 821 2020 108	50-329 F 50-329 S 50-329 A 50-329 A 50-364 P	COWOILL.C COWFFM COX.F F COX.H T	8212210099* 8212220473* 8212170044* 8212070128* 8212300276*	50~219 0 50~280 F 50~261 8 50~261 8
COLLINS.D J COLLINS.J J COLLINS.J J COLLINS.J J	8212220358* 8212040429 8212040441 8212040447 8212040451	50-244 Q Nureo Nureo Nureo Nureo	COONEY, M J	8212130097 8212140411 8212270206* 8212230205 8212030208*	50-278 B	CDYLE, L COYLE, L COYLE, L COYLE, L COZENS, Q	8212100214* 8212170102* 8212270476* 8212210160* 8212080200*	90-249 8 50-249 8 50-237 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
CRADDICK, W G CRAIG, J CRAIL, A C CRANDALL, W E CRANE, C J	8212060465 8212060329 8212220282 8212020194 8207010124*	NUREQ 50-382 8 NUREQ 50-187 R 50-29 P	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8212070102 8212070192 8212070201* 8212070210* 8212070299	50-213 P 50-255 P 50-255 P 50-255 P 50-155 P	CUTCHIN, J M CUTCHIN, J M CUTCHIN, J M CUTCHIN, J M	8212070155 8212070228 8212070228 8212150118 8212210318 8212140476	50-440 G 50-440 G 50-440 G 50-440 G NUREG
CRANE, C J CRANE, C J CRANE, C J CRANE, C J	8207010149* 8207010394* 8207010410* 8207150169* 8212230110*	50-244 P 50-245 P 50-409 P 50-219 P 50-213 P	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	B212080169 B212080174* B212080206 B212080340 B212080374	50-409 P 50-409 P 50-219 P 50-255 P 50-29 P	CIAJKOWSKI,C J D'ANGELO,A DALE,L F DALE,L F DALE,L F	8212280031 8212210211* 8212010176 8212070274 8212170278	RES 50-528 G 50-416 P 50-416 P 50-416 P
CRANE, C J CRANE, P A CRANE, P A CRANE, P A CRANE, P A	9212230250* 8212010190 8212030190 8212030191 8212040047	50-277 P 50-275 P 50-275 P 50-275 P 50-275 R	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8212080387* 8212080403* 8212130203 8212140257 8212150030	50-29 P 50-29 P 50-255 F 50-29 P 50-155 P	DALE, L F DALE, L F DALE, L F DALEY, C DALLMAN, R J	8212230252 8212270154 8212270235 8212170311* 8201120155*	50-416 P 50-416 P 50-416 F 50-331 P RÉS
CRANE, P A	821204007B 8212070235 8212080043* 8212090084 8212130070	50-323	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	B212150039 8212150115 8212150184 8212170050 8212200008	50-409 P 50-409 P 50-409 P 50-219 F 50-244 P	DALTROFF, S L	8212040104* 8212080323* 8212090119 8212100034 8212130211	50-277 P 50-277 0 50-277 P 50-277 F 50-277 P
CRANE,P A	8212140473	50~275 P	CRUTCHFIELD, D	8212200100	50-245 P	DALTROFF, S L	8212140385	50-277 P
CRANE,P A	8212170217	50~275 R	CRUTCHFIELD, D	8212210127	50-213 P	DALTROFF, S L	8212150187*	50-277 F
CRANE,P A	8212210002	50~275 P	CRUTCHFIELD, D	8212210216	50-407 P	DALTROFF, S L	8212170248	50-277 P
CRANE,P A	8212210014	50~275 P	CRUTCHFIELD, D	8212210372	50-244 P	DALTROFF, S L	8212170289	50-277 P
CRANE,P.A	8212210070	50~323 A	CRUTCHFIELD, D	8212210457	50-255 P	DALTROFF, S L	8212210312	50-277 P
CRANE, P. A	6212220217	50-275 P	CRUTCHFIELD. D	8212220209	50-155 P	DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L DALTROFF,S L	8212230313	50-277 F
CRANE, P. A	8212230210	50-275 P	CRUTCHFIELD. D	8212220377	50-213 P		8212270167	50-277 P
CRANE, P. A	8212230296	50-275 P	CRUTCHFIELD. D	8212220429	50-155 P		8212270219	50-278 P
CRANE, P. A	8212270371	50-275 P	CRUTCHFIELD. D	8212220457	50-213 P		8212280452	50-277 P
CRANE, P. A	8212280098	50-275 P	CRUTCHFIELD. D	8212230089	50-213 P		8212270235	50-277 P
CRANE,PA CRAWFORD,VA CRAWFORD,VA CREED,JR. CREED,JR	8212270364	50~275 R	CRUTCHFIELD, D	8212230238	50-29 P	DANCE, H C	8212030102	50-302 5
	8212040075	50~528 0	CRUTCHFIELD, D	8212230243*	50-29 P	DANCE, H C	8212070195	50-338 0
	8212040098	50~528 G	CRUTCHFIELD, D	8212230277	50-237 P	DANCE, H C	8212090161	50-269 0
	8212040080*	50~346 Q	CRUTCHFIELD, D	8212230287	50-245 P	DANCE, H C	8212090187	50-369 0
	8212070394*	50~155 Q	CRUTCHFIELD, D	8212230305	50-245 P	DANCE, H C	8212090197#	50-369 6
CREED, J R	8212140414*	50-151 Q	CRUTCHFIELD, D	8212230310	50-219 P	DANCE, H C	8212070211	50-389 G
GREED, J R	8212280220*	50-10 Q	CRUTCHFIELD, D	8212230322	50-155 P	DANCE, H C	8212070215	50-280 G
GREWS, J L	8212280279	50-508 Q	CRUTCHFIELD, D	8212230354	50-155 P	DANCE, H C	8212070223*	50-280 G
CREWS, J L	8212280301*	50-509 Q	CRUTCHFIELD, D	8212270345	50-29 P	DANCE, H C	8212070227	50-424 G
GROCKER, H W	8212160406*	50-289 Q	CRUTCHFIELD, D	8212270239	50-213 Q	DANCE, H C	6212070248	50-424 G
CROCKER.H W	8212220389*	50~207 Q	CRUTCHFIELD, D	8212270242*	50-213 0	DANCE, H C	8212070262	50-370 0
CRONENBERG,A W	8212130113	NUREQ	CRUTCHFIELD, D	8212270267	90-155 P	DANCE, H C	8212070267	50-280 0
CROSSMAN,W A	8212070123*	50~382 Q	CRUTCHFIELD, D	8212270270*	50-155 P	DANCE, H C	8212070268	50-389 0
CROSSMAN,W A	8212070133*	50~112 Q	CRUTCHFIELD, D	8212270278*	50-155 P	DANCE, H C	8212070276	50-280 0
CROSSMAN,W A	8212200086*	50~458 Q	CRUTCHFIELD, D	8212270320	50-409 P	DANCE, H C	8212070300#	50-280 0
CROSBMAN, W A	6212200124*	50-382 Q	CRUTCHFIELD, D	8212300031	50-255 P	DANCE, H C	8212070302	50-335 G
CROSSMAN, W A	8212280378*	50-382 Q	CRUTCHFIELD, D	8212300038*	50-255 P		8212070317	50-413 G
CROUCHER, P W	6212130113	Nureo	CRUTCHFIELD, D	8212300044*	50-255 P		8212070331	50-387 G
CROUSE, R P	6212020270	50-346 F	CRUTCHFIELD, D	8212300330	50-155 P		8212070353	50-387 G
CROUSE, R P	8212040158	50-346 P	CVLP, G H	8212140347	50-344 F		8212070373	50-367 G
CROUSE, R P	8212070292	50-346 P	CUMMINOS, J J	8212040177*	50-275 Q	DANCE, H C	8212070404	50-387 0
CROUSE, R P.	8212100040	50-346 P	CUMMINS, J E	8212030192*	50-348 Q	DANCE, H C	8212070459	50-413 0
CROUSE, R P	8212100231	50-346 F	CUMMINS, J E	8212070123*	50-382 Q	DANCE, H C	8212070478	50-338 0
CROUSE, R P	8212130088	50-346 P	CUMMINS, J E	8212280378*	50-382 Q	DANCE, H C	8212070487	50-250 0
CROUSE, R P	8212130090	50-346 P	CUNNINGHAM, A L	8212070288*	50-261 Q	DANCE, H C	8212070470	50-250 0
CROUSE.R P	8212210081	50-346 P	Cunni Noham, o H	8212280415*	REVIEW ORP	DANCE, H C	8212070471*	50-338 0
CROUSE.R P	8212210092	50-346 P	Cunni Ngham, m	8212140476	NUREC	DANCE, H C	8212070507	50-375 0
CROUSE.R P	8212210348*	50-346 P	Curram, d	8212200039	50-443 Q	DANCE, H C	8212070510*	50-250 0
CROUSE.R P	8212220273	50-346 P	Gurram, d	8212200039	50-443 Q	DANCE, H C	8212070515	50-238 0
CROUSE.R P	8212270205	50-346 P	Gurram, d	8212200049*	50-443 Q	DANCE, H C	8212070527	50-250 0
CROUSE, R P	8212270210	50-346 P	CURRAN, D	8212200049*	50-443 G	DANCE, H C	8212070530*	50-395 0
CROUSE, R P	6212290226	50-346 Q	CURRAN, D	8212280504	FOIA	DANCE, H C	8212070531	50-335 0
CROUSE, R P	6212290455*	50-346 Q	CURRAN, J	8212020277	PRM	DANCE, H C	8212070553	50-335 0
CROW, W T.	6212010336	70-371	CURRAN, J E	8212160168*	40-6500	DANCE, H C	8212070541*	50-335 0
CROW, W T	8212020061*	70-734	CURRAN, J H	8212060012	50-362 B	DANCE, H C	8212150085	50-302 8
CROW, W T	8212100180*	70-1334	CURRAN, J M	8212170384*	50-206 Q	DANCE, H C	8212150103	50-338 8
CROW, W T.	8212130287*	70-2957	CURRAN, J M	8212270038*	50-206 Q	PANCE, H C	8212150144	50-287 6
CROW, W T	8212170011*	70-2928	CURTIS, N H	8211070019	50-387 E	DANCE, H C	8212150151	50-338 8
CROW, W T	8212270029*	70-2941	CURTIS, N H.	8212060066	50-387 P	DANCE, H C	8212270137*	FOIA
CRUTCHFIELD, D	8002270255*	50-206 P	CURTIS, N H	8212060140	50-387 F	DANCE, H C	8212270165*	FOIA
CRUTCHFIELD, D	8003070778*	50-237	CURTIS, N W	8212070214	50-387 P	DANDINI,V J	8212130118	NUREO
CRUTCHFIELD, D	8004090144*		CURTIS, N W	8212140497*	50-387 P	DANIELSON,D H	8212170074*	50-255 G
CRUTCHFIELD, D	8009180414*		CURTIS, N W	8212160317	50-387 P	DANIELSON,D H	8212270305*	50-282 G
CRUTCHFIELD, D	8105110312*		CURTIS, N W	8212160417	50-387 P	DANIELSON,D H	8212270336*	50-246 G
CRUTCHFIELD, D	8211080101		CURTIS, N W	8212170271	50-387 P	DANIELSON,D H	8212270400*	50-295 G
Crutchfield, D Crutchfield, D Crutchfield, D Crutchfield, D Crutchfield, D.	9211080105* 8211080110* 9211170509 8212020245 8212020255	50-29 P 50-29 P 50-237 P 50-409 P 50-155 P	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8212210310 8212210450 8212270272 8212280323 8212280346	50-388 A 50-387 K 50-387 P 50-388 S 50-388 S	DAVID, L T DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R DAVIDSON, D R	8207180049 8212020296 8212020395 8212070015 8212080416	FOIA 50-440 S 50-440 S 50-440 H 50-327 S
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8212020266 8212020328 8212020332 8212060063 8212070097	50-155 P 50-409 P 50-155 P 50-219 P 50-219 P	CURTIS, N H CURTIS, N H CUBTODIO, D B CUTCHIN, J H	8212260347 8212260400 8212280446 8212210377* 8212030181	50-387 P 50-387 B 50-387 P 50-219 S 50-440 O	DAVIB.C B DAVIS.D.K DAVIS.H M DAVIS.J G DAVIS.J.G	6212020110 7708090435* 8212220339 8212010221* 8212020148	50-249 P 50-10 P 50-440 B Waste Hot Waste Hot

AUTHOR	ACCESSION PERMUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DAVIS, J O DAVIS, J O DAVIS, J R DAVIS, M J DAVIS, M J	8212100183 8212230034 8212020389 8212090234* 8212090213*	40-17 WASTE MOT PRM 50-280 Q 50-280 Q	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212060151 8212070100 8212070100 8212080163 8212080163	50-443 A 50-443 A 50-443 A 50-443 F 50-443 F	DIEDERICH, G J DIETCH, R DIETCH, R DIETCH, R DIETCH, R	8212260483 8212010171 8212030157 8212030168* 8212130188	50-373 5 50-361 P 50-361 P 50-361 P 50-362 P
DAVISON, A DAWSON, D M DAYAL, R DAYAL, R DE MARCO, J H	8212230092 8212150216 8212280040 8212280514 8212230235	NUREG 71-9001 RES 50-320 P 90-247 G	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212080190 8212080190 8212080207 8212080224 8212080224	50-443 A 50-443 A 50-443 A 50-443 A 50-443 A	DIETCH, R DIETCH, R DIETZ, C R DIETZ, C R DIETZ, C R	8212130193* 8212290413 8212020048 8212020152 8212020293	50-362 P 50-361 S 50-324 S 50-324 S 50-324 S
DEAGAZIO, A W DEAGAZIO, A W DEAGIEN, J A DEBS, B T	8212130111 8212280067 8212070353* 8212010487 8212070500*	50-346 P 50-346 P 50-269 P RES 50-250 Q	DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J BEVINCENTIS. J DEVINCENTIS. J	8212080329* 8212080329* 8212090498 8212090498 8212140235	50-443 G 50-443 G 50-443 A 50-443 A 50-443 A	DIETZ, CR DIETZ, CR DICTZ, CR DIETZ, CR DIETZ, CR DICTZ, CR	8212020304 8212020315 8212020342 8212070008	50-325 S 50-324 S 50-324 S 50-325 S
DELANEY, J C DELANEY, J C DELANEY, J C DELANEY, J C	8212070083+ 8212160341* 8212160505* 8212160513* 8212160534*	50-247 0 40-3265 40-2116 40-2116 40-1606	DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212140235 8212210273 8212210273 8212210287 8212210287	50-443 A 50-443 S 50-443 S 50-443 S 50-443 S	DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DICTZ, CR	8212070208 8212070273 8212090100 8212090135 8212090147	50-325 8 50-324 6 50-325 9 50-325 8 50-325 5
NELNELLO, A B DELCEGRGE, L O DELGEGRGE, L O DELGEGRGE, L O DELGEGRGE, L O	8212130254* 8212040041 8212040045* 62120703384 6212070383	50-247 Q 50-373 F 50-10 Q 50-254 Q 50-237 F	DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J DEVINCENTIS. J	8212210447 8213210449 8212270146 8212270146 8212270188	50-443	DIETZ,C R DIETZ,C R DICTZ,C R DIETZ,C R DIETZ,C R	8212070147 8212070287* 8212070314 6212070453 8212070535	50-325 8 50-324 0 50-324 8 50-325 8 50-325 8
DELGEDROE, L O DELGEDROE, L O DELGEDROE, L O DELGEDROE, L O DELGEDROE, L O	8212100330* 8212140231* 8212210108* 82122702234 8212270303*	50-454	OFALUSCHIPS OF STRUCTURES OF S	8212270188 8212270270 8212270270 8212270279 8212270279	50-443 A 50-443 A 50-443 A 50-443 A 50-443 A	DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R	8212090543 8212100241 8212140153 8212140194 8212150112	50-325 8 50-324 R 50-325 8 50-325 8 50-325 8
DELGEORGE.L O DELLA RATTA.A DELLA RATTA.A DELLA RATTA.A DEMMJE.P N	8212270247 8212100081* 8212270352* 8212270383* 8212080516	50-454 F 50-219 0 70-820 50-244 Q RES	DEVINE, J B DEVINE, J F DEVINE, T DEVINE, T DEVINE, T D	8212230432 8212020193* 8212020358 8212020382 8212280128	XPORTLIC MISC 50-373 P 50-358 Q 50-358 Q	DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C R	8212170141 8212170216 8212210030 8212210152 8212210379	50-325 B 50-325 B 50-325 B 50-325 B 50-325 S
DENTSON, E DENTSON, E DENTSON, E DENTSON, E DENTSON, E	8212140276 8212140277* 8212150164 8212150170* 8212200080	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P	DEVINE.T D DEWEY.L S DEWEY.L S DEWITT.R B DEWITT.R B	8212280128 8212010038 8212220118 8212200075* 8212280089*	50-358	DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DICTZ, CR	8212220488 8212220474 8212280383 8212300047 8212300221	50-325 8 50-325 8 50-325 8 50-324 6 50-325 8
DENISON, E DENNING, R DENNY, I L DENTE, T J DENTON, H R	8212200095± 6212140476 6212130432 8212300034 6009110797*	50-275 P NUREG 40-2061 TOPREP 50-10 P	DEADNAC'S C DEADNAC'S C DEADNAC'S C DEADNAC'S C	821 2280107* 82081 90240 82081 90254 82081 90259 82081 90267	50-155 F 50-3 Q 50-3 Q 50-3 Q 50-3 Q	DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR DIETZ, CR	8212300229 8212300256 8212300257 8212300307 8212300316	50-325 S 50-325 S 50-325 S 50-325 S 50-325 S
DEMTON, H R	8211120169* 8211230137* 8212010436 8212020204 8212030262	REVIEW GRP 50-275 P MISC TOPREP 50-13 P	DEADNAC'S C DEADNAC'S C DEADNAC'S C DEADNAC'S C	8212020080* 8212040427* 8212070033 8212070073 8212070081*	FD1A FO1A 50~312 Q 50~247 Q 50~247 Q	DICTZ.C R DICTZ.C R DICTZ.O R DICGS.R M DICGS.R M	8212300331 8212300360 8212200033 8212010370 8212170040	50~325 B 50-325 S PR 50~33B P 50~246 P
DENION, HR DENTON, HR DENTON, HR DENION, HR DENION, HR	8212060042 8212060046* 8212060052 8212060058* 8212060064*	50-309 P 50-309 P MISC MISC MISC	DEYOUNG.R C DIAZ,N J DICK,G F DICKENSON,R E	8212070146* 8212070004 8212070009* 8212150326 8212160643*	50~312	DIGGS.R M DIGGS.R M DIGGS.R M DIGGS.R M DIGNAN.T G	8212210012 8212220641 8212220545 8212300190 8212140212	50-247 Q 50-361 P 50-263 P 50-320 P 50-443 G
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8212060142 8212060422 8212060430* 8212070170 8212080672	50-89 P 50-295 P 50-295 P 50-289 G 50-322 H	DICKERSON.N H DICKTY.F DICKTY.F DICKTY.F	8212070260* 8212220406* 8212220424* 8212270434* 8212020274	50-267 Q 50-311 S 50-311 5 50-358 A 50-373 S	DIGNAN, T C DIGNAN, T C DIGNAN, T C DIGNAN, T C DIGNAN, T C	8212140212 8212140217 8212140217 8212140430 8212140430	50-443 0 50-443 0 50-443 0 50-443 0 50-443 0
DENION, H R DENION, H R DENION, H R DENION, H R DENION H R	8212100074 8212130358 8212130359* 8212160634 8212220048*	50-219 D 50-352 G 50-352 G COMMISSION 50-282 F	DIEDERICH.O J DIEDERICH.O J DIEDERICH.O J DIEDERICH.O J DIEDERICH.O J	8212020294 8212020305 8212080308 8212080318 8212080400	50-373 & 5 50-373 & 5 50-373 & 8 50-373 & 8 50-373 & 8	PIGNAN, T G DIGNAN, T G DIGNAN, T G DIGNAN, T G DIGNAN, T G	8212140437# 8212140437* 8212140441 8212140441 8212210228	50-443
DENTON, H R DERKS, P S DESSY, R P DETULLIO, D DEVINCENTIS, J	8212270028 8212270184* 8212300004 8212210363* 8212020029	50-320 P 50-133 R 50-312 0 50-391 Q 50-443 A	DIEDERICH.O J DIEDERICH.O J DIEDERICH.O J DIEDERICH.O J	82;2080412 82;2080508 82;2100272 82;2130175 82;2140067	50-373 S 50-373 S 50-373 S 50-373 R 50-373 S	DIGNAN.T G DIGNAN.T G DIGNAN.T G DILLEN.P DIRCKB.W J	8212210228 8212220255 8212220255 8212210324* 8202010383*	50-443 G 50-443 G 50-443 G 50-286 P FDIA
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212020029 8212020286 8212020286 8212020334 8212020334	50-443 A 50-443 A 50-443 A 50-443 A 50-443 A	DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J DIEDERICH, G J	8212140119 8212170123 8212170159 8212170184 8212170211	50-373 B 50-373 B 50-373 B 50-373 B 50-373 S	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8202180082* 8203090477* 8204160262* 8204160270* 820420059*	FOIA FOIA FOIA FOIA
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212030194 8212060056 8212060056 8212060059 8212060068	50-443 A 50-443 A 50-443 A 50-443 E 50-443 D	DIEDERICH. 0 J DIEDERICH. 0 J DIEDERICH. 6 J DIEDERICH. 0 J	8212170214* 8212170233 8212170244 8212270140 8212270162	50-373 8 50-373 8 50-373 8 50-373 8 50-373 6	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8209280513* 8211170238 8212010327 8212020185 8212060052	FOIA 50-395 P (8ECY MISC MISC
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8212060075 8212060075 8212060094 8212060094 8212060151	50-443 A 50-443 A 50-443 A 50-443 A 50-443 A	DIEDERICH. 0 J DIEDERICH. 0 J DIEDERICH. 6 J DIEDERICH. 6 J DIEDERICH. 0 J	8212270175 8212270354 8212280195 8212280229 8212280447	50-373 S 50-373 B 50-373 S 50-373 S 50-373 S	DIRCKS, W J.	8212050419 8212060509 8212070062 8212070378* 8212070443*	BECY 40-86 50-287 H COMMISSION 50-298 O

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	Subject Category
Dircks, W J Dircks, W J Dircks, W J Dircks, W J	#212070452* #212080575 #212070224* #212100042 #212100378*	50-298 Q 50-358 R FOIA 50-329 U FOIA	DUBINSKI,L DUBINSKI,L DUBOIS,D L DUBRY,N E DUBRY,N E	8212140516* 8212160583* 8212160271* 8212280251* 8212270335*	40-6500 40-6500 50-278 Q 50-315 Q	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8212010014 8212010017* 8212010124* 8212010169 8212030229	50-456 A 50-456 A 50-390 A 50-387 P Toprep
DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8212130339 8212160008 8212220555 8212270428 8212270432	50-327 E PR COMMISBION 50-3 H MISC	DUCK, J R DUCK, J R DUCK, J R DUCK, J R DUCK, J R	8212020269 8212280222 8212280223 8212280261 8212280348	50-289 J 50-321 J 50-348 J 50-259 J 50-348 J	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212030253 8212060339* 8212060340 8212070027 8212070444*	50-275 P 50-280 F 50-275 P 50-289 M 50-298 Q
DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.D P	6212270481 6212280509 6212280515* 6212270039* 6212100207	50-437 A FOIA FOIA FOIA 50-410 A	DUCK, J R DUCK, J R DUCK, J R DUCK, J R DUCK, J R	8212280349 8212290150 8212290246 8212300109 8212300202	50-321 J 50-327 J 50-259 J 50-327 J 50-250 J	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8212080179 8212080188* 8212080291* 8212080443 8212080477	50-528 A 50-528 A 50-204 G 50-346 F 50-275 P
DITTO,S J DIVINE,J M DIVINE,J M DIXON,D R DIXON,O W	8212040399 8212130152 8212270145 8212160734* 8212020340	ACR8 Nureo Nureo 50-262 f 50-395 f	DUCK, J R DUCK, J R DUCK, J R DUDNICK, C L DUDNICK, C L	8212300243 8212300294 8212300300 8212020279 8212020288*	50-250 J 50-335 J 50-430 J PRM PRM	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212100361 8212130281 8212130375 8212140103 8212140161*	50-373 P 50-275 P 50-275 H 50-29 P FOIA
DIXON.O H DIXON.O H DIXON.O H DIXON.O H	8212030060 8212030089 8212030108 8212030133 8212030164	50-395 S 50-395 S 50-395 S 50-395 S 50-395 S	DUFFEY.D W DUMMER.G H DUNLAP.J M DUNLAP.J M DUNLAP.J M	8212280362 8212040120* 8212030038* 8212030090* 6212210134*	PT21 CONTRACT 50-244	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212170013 8212170014* 8212170038 8212170042 8212170057*	50-373 P 50-373 P 50-275 P 50-341 A 50-341 A
DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8212030184 8212030188 8212070024* 8212070128 8212070181	50~395 S 50~395 S 50~395 G 50~395 F 50~395 F	DUNN.F E DUPLISSEY.J.F DUPONT.S O DURR.J DURR.J P	8212270250* 6212200060 8212030197* 6212060217* 6212070136*	50-537 A PRM 50-254 Q 50-309 Q 50-322 Q	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212170373 8212210544 8212220045 8212220434 8212220482	50-275 H 50-263 P 50-282 F 50-275 P 50-275 P
DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8212070243 8212070364 8212070372 8212070422 8212070447	50-375 S 50-375 S 50-375 O 50-375 S 50-375 S	DURR, J P BURR, J P DUS, R DUS, R DUS, R	8212100064* 8212220218* 8212080413* 8212170194* 8212280215*	50-387 Q 50-397 Q 50-373 S 50-373 S 50-373 S	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8212230020 8212230023 8212230030* 8212230033* 8212230041	50-287 P 50-287 P 50-287 P 50-289 P 50-275 P
DIXON'O M DIXON'O M DIXON'O M DIXON'O M	8212090516* 8212100292 8212150077 8212150089 8212150097	50-395 Q 50-395 F 50-395 S 50-395 S 50-395 S	DUTTON.D E DUVAL.P A EAPEN.P K EAPEN.P K EARLFY,A F	8212280354 8212130129* 8212030051* 8212030200* 8212270121	50-424 A 71-6495 50-336 Q 50-293 Q FOIA	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212230045 8212230047 8212230058* 8212230070 8212230279	50-275 P 50-275 P 50-275 P 50-289 P 50-219 F
DIXON.O W DIXON.O W DIXON.O W DIXON.O W	8212150117 8212140322 8212170257 8212170287 8212200110	50-395 8 50-395 F 50-395 P 50-395 S 50-395 S	EARLEY, A F EARLEY, A F ECKERT, J P ECKHARDY, J ECKHARDT, J H	8212020381 8212020381 8212130067* 8212170281 8212130265*	50-322	FISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8212270335 8212270338* 8212270363 8212270370* 8212270376	50-269 P 50-269 P 50-346 P 50-346 P 50-312 P
DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8212220328 8212220374 8212220411 8212220428 8212220498	50-395 S 50-395 S 50-395 S 50-395 S	ECKHARDT, J H ECONOMOS, C ECONOMOS, N EDDINOS, M EDDLEMAN, W	8212210211* 8212070471 8212070324* 8212270164* 8212020238	50-528 Q RES 50-413 Q 50-327 R PR	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8212270399# 8212270409 8212270411# 8212270421 8212270423	50-312 P 50-302 P 50-302 P 50-313 P 50-437 A
DIXON,O W DIXON,O,W DOBBE,C A DOBBE,C A DODA,R J	8212230288 8212300035 8212020100 8212020104 8212020514	50-375 P 50-375 S RES RES 1&E	EDDLEMAN, W EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	8212140209 8212070237 8212070345* 8212070397 8212170153	PRM 50-440 A 50-440 G 50-440 E 50-440 B	EISENHUT, D C EISENHUT, D C EISENHUT, D C EISENHUT, D C	8212270424 8212270425# 8212270427* 8212270486* 8212280495	50-358 A 50-437 A 50-313 P 50-344 F 50-275 P
DODA,R J DODDS,R T DODDS,R T DODDS,R T DODDS,R T	8212200069 8212060178* 8212060208* 8212060264* 8212060274*	1&E 50-243 0 50-397 0 50-508 0 50-508 0	EDELMAN, M R	8212170241 8212210370 8212280255 8212280271 8212270189	50-440 S 50-440 S 50-440 A 50-440 S 50-440 E	EISENHUT, D G EISENHUT, D G EISENHUT, D G ELDRED, D T ELDRED, D T	8212280504 8212300188 * 6212300335 8212100287 * 8212170285 *	50-267 P 50-416 P 50-287 P 50-346 B 50-346 S
DODDS,R T DODDS,R T DODDS,R T DODDS,R T DODDS,R T	8212040391* 8212130270* 8212170341* 8212170370* 8212210175*	50-344 Q 50-27 Q 50-508 Q 50-508 Q 50-508 Q	EDELMAN, M R EDELMAN, M R EDELSTEIN, B EDELSTEIN, B EDELSTEIN, B	8212270305 8212270325 8212300155 8212300158 8212300163	50-440 E 50-440 E XPORTLIC XPORTLIC XPORTLIC	ELDRED, D T ELLERSHAW, L E ELLERSHAW, L, E ELLIOTT, J M, ELLIOTT, J M	8212280290* 6212210141* 6212210032* 6212080079* 6212080137*	50-346 B gayyy gayyy Fdia Fdia
PODDS,R T PODDS,R T POERFLEIN,L T POESBURG,J H POHERTY,D F	8212210427* 8212280301* 8212030078* 8212220238 8212020378	50-397 Q 50-50B G 50-333 Q NUREO PR	edelstein, B edelstein, B edelstein, B edelstein, B	8212300164 8212300166 8212300167 8212300180 8212300181	XPORTLIC XPORTLIC XPORTLIC	ELLIS, J ELLIS, J ELLIS, J ELLIS, T S	8212230182 8212230195 8212300009 8212300045 8212270196	50-445 0 50-445 0 50-445 0 50-445 0 50-322 0
DODLITTLE, E L DORSEY, M DOUGHTY, J DOUGHTY, J DOWNEY, T	8212080121 8212270470 8212020366 8212160321 8212230276	50-546 A CONTRACT PR 50-443 Q 50-247 U	edgar. C L Edgar. G L Edgar. G L Edgar. G L Edison. G E	8212020005 8212200015 8212200011 8212300011	50-537 G 50-537 G 50-537 G 50-537 G 50-482 A	ELLIB,T 8 ELLYBON,C ELRICK,R M ELROD,S A ELROD,S A	8212270194 8212070484 8212130283 8212090337* 8212090542*	50-322
DRAGD, J. P DRAGDNETTE, K. DRAGDNETTE, K S DREY, L A DRYFOOS, R J	8212270435 8212010227 8212270008 82122140486* 8212230241	NUREO HASTE MOT HASTE MOT 50-257 H 50-247 G	EDLER,S K EDHARDS,D L EICH,E EIDBON,A F EISENHART,L D	8212270449 8212270401 8212280221* 8212280228 8212280518	NUREG 40-3453 50-247 R NUREG REB	ELROD, 8 A ELBASBER, T ELBASBER, T C EMCH, R EMPEY, D C	8212090564* 8212140337* 8212140084* 8212090117 8212280373*	50~335
DRYEDALE, J A DUBINSKI, L DUBINSKI, L DUBINSKI, L DUBINSKI, L	6212220249 6212160062* 6212160123* 6212160264* 6212160366*	NUREQ 40-4500 40-4500 40-4500 40-4500	EISENHUT,D Q EISENHUT,D Q EISENHUT,D Q EISENHUT,D Q EISENHUT,D Q	8010170283* 8205270570* 8208170263 8211120486 8211230066	50-206 P FOIA 50-3 P Misc 50-217 P	EMBHWILLER, J R ENGELBRECHT, L ENGELDER, T C, ENGELKEN, R H ENGELKEN, R H	8212060450 8212080251 8212090489* 8212170088 8212170383*	FOIA 50-246 G 70-824 50-397 G 50-206 G

	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
AUTHOR ENGELKEN, R. H. ENGELKEN, R. H. ENGELMANN, J. H. ENGELMANN, R. ENGELMANN, R. ENGELF, L. B.	NUMBER 8212210180 6212210189 8212200014 8212270438 8212270407	50-344 Q 50-508 Q PR 40-8348 50-338 P	FEINBERQ, J D FEITKNECHT, C FELICETTI.S A FELL.R A FELION, J M	8212070246 8212070204	50-247 0 50-334 R RES 50-397 0 FOIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8312230152 8212230166 8212230369 8212270003 8212270013	50-313 F FOIA 50-331 F 50-305 F 50-362 F
ENGLE: L B EPLER: E P EPLER: E P EPLER: E P EFLER: E P	8212270490 8212030280 8212030280 8212030280 8212060325 8212060325	50-338 P ACRS ACRS ACRS ACRS	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212010029 8212010033 8212010042 8212010061 8212010071	FOIA 50-315 F 50-317 F 50-112 F 50-150 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212270023 8212270036 8212270039 8212270048 8212270062	FDIA FDIA 90-322 A FDIA 50-244 S
ensifin, e Epstfin, m Enickson, b Enickson, b	8212160493* 8212270254* 8212080056* 8212080142* 8212020123	FOIA 50-537 A FOIA FOIA 50-213 F	FELTON, J H FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212010092 8212010348 8212010361 8212010446 8212020008	50-320 F FDIA 50-322 A FDIA FOIA	FELTON J M FELTON J M FELTON J M FELTON J M	8212270078 8212270304 8212270315 8212270328 8212270386	FOIA 50-358 H FOIA 50-148 H
CRICKSON, P. 8 ERICKSON, P. 3 ETHERINGTON, E ETHERINGTON, H FURY, L. W FURY, L. W	8212140210 8212220438* 8212020048 8212060069 8212100082	50-213 F 50-275 P ACRS 50-261 P 50-324 P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212030268 8212030283 8212030291 8212060395 8212060415	50-254 F 50-10 F 50-309 F 50-320 P FOIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212270418 8212280007 8212280037 8212280512 8212280520	50-327
EURY, L W EURY, L W EURY, L W	8212140255 8212150004 8212170338 8212170355 8212210004	50-324 P 50-261 P 50-324 P 50-324 P 50-324 P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212040424 8212040440 8212040453 8212070408 8212070414	F01A F01A F01A F01A 50-295 P	FELTON.J M FELTON.J M FELTON.J M FELTON.J M	8212280527 8212270007 8212270009 8212270015 8212270019	50-14B P 50-361 B 50-322 A 50-322 A FOIA
EVANS, C D EVANS, L U EVANS, L U EVANS, L U	8212090521* 8212080008* 8212080061* 8212090066* 8212080101*	50-338	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212070425 8212080006 8212080057 8212080074 8212080089	50-267 F 70-143 50-275 F 50-313 F 50-315 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8212270025 8212270030 8212270036 8212270040 8212270083	50-322 H 50-204 0 50-440 A 50-244 5 50-295 F
EVANS.L U EVANS.L U EVANS.L U EVANS.L U EVANS.L U EVANS.L U	9212080116* 9212080133* 9212080161* 9212080167* 9212100168*	FOIA FOIA FOIA FOIA FOIA	FELTON.J M FELTON.J M FELTON,J M FELTON,J M FCLTON.J M	8212080100 6212080630 6212070027 8212070046 6212100051	50-259 F 50-546 F 50-358 F FOIA FOIA	FELTON, J M I ELTON, J M FELTON, J M FELTON, J M	8212270078 8212270275 8212270507 8212300167 8212300204	50-295 F 50-3 F 50-295 F 50-10 F 50-317 F
EVANSIL J EVANSIL J FABRYIJ FALCONERID FARLEYIE R	8212100185* 8212100187* 8212130185* 8212070187* 8212030282*	FOIA FOIA 50-400 A 50-269 0 40-3453		8212100053 8212100084 8212100105 8212100111 8212100362	FOIA FOIA 50-443 A 70-143 FOIA	FELTON.J M FELTON.J M FERGUSON.R L FERRARRO.O	8212300400 8212300407 8212300412 8212170100* 8212230274	50-254 F 50-387 F 50-282 F 50-397 G 50-247 U
FARMER, F 0 FARMELL, R E FARMELL, R E FARMELL, R L FASAND, A	8212020096 8212170121* 8212270348* 8212070365* 8212070111*	50-409 F 50-275 C 50-254 C 50-440 C	FELTON, J M FELTON, J M FELTON, J M	8212100374 8212100380 8212100381 8212100387 8212100395	FOIA FOIA FOIA FOIA	FICKETT.K FIEDLER.P B FIEDLER.P B FIEDLER.P B FIEDLER.P B	8212230159 8212040148 8212040332 8212080240 8212080349	FOIA 50-217 S 50-217 G 50-217 S 50-217 S
FASAND: A FASAND: A FASANO: A F AUL KENBERRY: B FAY: C W	8212140319* 821222047! 8212270233 8212210195* 8212020274	50-287 50-320 50-508	FELTON, J M	8212106399 8212100408 8212100412 8212130017 8212130132	50-344 F F01A F01A 50-10 F 50-346 F	FICOLER, P B FIEDLER, P B FIEDLER, P B FIEDLER, P B FIEDLER, P B	8212080354* 8212080388 8212080511 8212080554 8212130304	50-219 0 50-219 8 50-219 8 50-219 0 50-219 f
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8212020281* 8212100208 8212100222* 8212100223*	50-301 50-301 50-266	S FELTUN, J M S FELTUN, J M S FELTUN, J M Q FELTUN, J M Q FELTUN, J M	8212130149 8212130336 8212130352 8212140001 8212150181	50-295 F 50-298 F 50-286 F 50-10 P 50-277 F	FIEDLER, PB FIEDLER, PB FIEDLER, PB FIEDLER, PB FIEDLER, PB	8212140149 8212150270 8212210019 8212210040 8212210372	50-219 S 71-7151 50-219 P 50-219 R 50-219 S
FAY.C W FAY.C W FAY.C W FAY.C W	8212100224 8212100225 8212170161 8212170172 8212170326	50~266 * 50~266 50~266 * 50~266	S PELTON, J M S FELTON, J M S FELTON, J M S FELTON, J M P FELTON, J M	8212150248 8212150272 8212150301 8212150323 8212160080	50-243 F 50-313 F 50-346 F 50-315 F 40-6500	FIEMER.P B FIEDLER.P B FIEDLER.P B FIEDLER.P B FIEDLER.P B	8212210468* 6212210555* 6212280210 8212280218 6212280213	50-219 F 71-5957 50-219 D 50-219 P
FAY, C W FAY, C W FAY, C W FAY, C W	8212210054 8212210297 8212210297 8212220422 8212270125	50-266 50-266 * 50-266 50-266	P FELTON, J M R FELTON, J M R FELTON, J M P FELTON, J M P FELTON, J M	8212160091 8212160731 8212160745 8212160772 8212170012	50-346 F 50-262 F 50-320 F 50-313 F 50-313 F	FIELDER, J FIELDS, H C	8212290127 8212290410* 8212020335 8212030139* 8212090253*	50-250 J 50-375 S 50-375 S
FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W	8212270177 8212270202 8212270239 8212270244 8212280114	50-266 50-266 50-266 50-266	S FELTON.J M	8212170036 8212170053 8212170104 8212170445 8212170454	50-280 F 50-335 F 50-259 F 50-313 F 50-280 F	FIELDS, H C FIELDS, J A	8212090438 8212170291 8212220489 8212020189 8212130155	50-375 S 50-375 S CONTRACT CONTRACT
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8212280115 8212280158 8212280168 8212280341 8212270075	* 50-301 50-246 50-246 50-266	S FELTON, J M S FELTON, J M S FELTON, J M Q FELTON, J M P FELTON, J M	8212210508 8212210526 8212210541 8212210550 8212210556		FIELDS:JA FIELDS:JA FIELDS:JA	8212130178 8212140593 8212270415 8212270415 8212270527	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	9212290143 621229025 821229025 821229025 821229030	50-266 50-266 7* 50-266 2* 50-266	P FELTON, J M R FELTON, J M R FELTON, J M R FELTON, J M P FELTON, J M	8212220001 821222037 8212220175 821222239 8212223315	50-3 F 50-10 F 50-346 F	FIELDS, J A	8212270539 8212270555 9212280445 8212280469 8212280486	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FAY, C W FAY, C W FEE, W F FEHR INGER, D J FEIERABEND, C D	821229032 621229032 821228011 621202017 621203015	2 50-266 7* 50-266 9 50-213 1 WASTE MG	S FELTON. J M S FELTON. J M F FELTON. J M IT FELTON. J M Q FELTON. J M	8212230019 821223004 8212230067 621223007 8212230142	50-309 50-369 50-269	FIELDS, J A F FIELDS, J A F FIELDS, J A F FIEBURN, T F FINAMORE, B A FINAMORE, B A	8212260494 8212276053 8212030204 8212080257 8212230200	CONTRACT # 50-336 \$ 50-537 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	Subject Category
FINAMORE.8 A FINCH.9 L FINDLAY,J A FINK.8 FINKFL.A E	8212230200 8212220046* 8212010144 8212230270 8212030221*	50-537	FRALEY,R F FRALEY,R F FRALEY,R F FRALEY,R F FRALEY,R F	8212130273* 8212220448* 8212270438* 8212270448* 8212270457*	50-275 P 50-275 P FOIA FOIA FOIA	GARITY, J H GARRITY, J H GARY, R J GARY, R J GARY, R J	8212270376* 8212270271 8212140278 8212150166 8212170337	50-307 0 50-307 8 50-445 F 50-445 K
FIDRELLI.G FISH.H FISH.R F FITZSIMMONS.H FLACK.E	8212130215* 8212230276 8212210195* 8212170101* 8212170170	50-528 Q 50-247 U 50-344 Q 50-277 P 50-247 Q	FRANT2,8 P FRANTZ,8 P FREEMAN.M S FREEMAN.M 8 FREEMAN.M 8	8212280289 8212280289 8212020061* 8212090113* 8212090164*	50-522 0 50-522 0 50-416 S 50-416 S 50-416 S	GARY,R J GARY,R J GARY,R J GATCH,F B	8212170342+ 8212210391 8212280267 8212280329 8212230081	50-445 F 50-445 K 50-446 B 50-445 G NUREG
FLACK.O FLEFNOR.C FLEENOR.C M FLEISHER.Z S FLEISHER.Z S	8212020268 8212270484 8212220019 8212270209 8212070213	PRM 50-537 A CONTRACT 50-247 O 50-247 O	FREEMAN.M S FREEMAN.M S FREEMAN.M S FREEMAN.M S FREEMAN.B	8212090344* 8212170213* 8212170339* 8212290149 8212100304*	50-414 5 50-414 8 50-414 5 40-8768 50-414 8	GATES,T E GAVULA,J J GAYNOR,R K GEARS.G E GENTILE,A B	8212270456 8212150072* 8212010476 8212160531 8212160323*	NUREO 50-331 P 27-39 50-278 P FOIA
FLE 19HER, 7 8 FLE 15HER, 7 8 FLE 15HER, 7 8 FLE 15HER, 7 8 FLENING, 7 E	8212302593 8212300197 8212300201* 8212300201*	50-247 0 50-247 0 50-247 0 50-247 0 40-299	FREEMAN,S FRENCH,L D FRENCH,L D FRIEDLANDER,M FRITZ,E J	8212210192* 8212140187* 8212150160* 8212230241 8212300051	50~416 8 50~29 8 50~27 8 50~247 6 50~440 0	Gentillon, C D George, R L Gerdeman, F W Gerdeman, F W Gerdeman, F W	8212020095 8212100217 8211020241 8212270319 8212270340	50-155 P MISC 40-2678 40-8678 40-8678
FLEMING.T E FLEMING.T E FLOCK.E FLOCK.E	8212070045 8212230079 8212280053 8212240517 8212020177	40~8698 Waste mot 40-8698 I&E Waste mot	FRYE, J H FRYE, J H FUHRMAN, G R FUHRMAN, O R, FULLER, C	8212040234 8212300022 8212040149 8212080454 8212200128*	50-142 0 50-70 0 50-317 8 50-317 8 50-267 8	GERDEMAN, F W GERGES, A G GERSTNER, W C GERSTNER, W C	8212300120 8212230241 8212030273* 8212020088 8212280125	40-8698 50-247 0 50-254 F 50-461 A 50-461 A
FLORY, C A FLOYD, J H FLOYD, J H FLOYD, J H FLOYD, J H	8212230394 8212090075* 8212090158* 8212090184* 8212170146*	WASTE MOT 50-416 6 50-416 S 50-416 S 50-416 S	FULLER.C FULLER.C FURGAL.D T FURR.B J GAD.R K	8212270303* 8212270440* 8212060486 8212270200 8212140212	50-267 8 50-267 5 NUREO 50-261 P 50-443 Q	GERTMAN, D I GERTBCH, A J GERUSKY, T M GIBBONS, T D GIBBONS, T D	8212130108 8212290196* 8212160394 8212090407* 8212090465*	NUREG 50-313 R PR 50-390 G 50-413 G
FLOYD.J M FLOYD.J M FLOYD.J M FLYNN.M J	8212170227* 6212280057* 6212280198* 6212280389* 6212060297	50-416 S 50-416 S 50-416 S 50-416 S CONTRACT	GAD,R K GAD,R K GAD,R K GAD,R K GAD,R K	8212140212 8212140217 8212140217 8212140430 8212140430	50-443	Cibbon, a f Gibbon, a f Gibbon, a f Gibbon, a f Gibbon, a f	8212070252 8212070263 8212070264 8212070267 8212070267	70-824 70-1201 70-1113 70-1151 70-824
FLYNN, M J FLYNN, M J FLYNN, S F FODES, R L	8212170398 8212220018 8212270419 8212230366 8212060371*	CONTRACT CONTRACT CONTRACT 50-400 G 50-255 B	GAD,R K GAD,R K GAD,R K GAD,R K GAD,R K	8212140441 8212140441 8212210228 8212210228 8212220255	50-443	Gibson, a f Gibson, a f Gibson, a f Gibson, a f Gibson, a f	8212070333 8212070402 8212070408 8212070428 8212070430	70-1201 70-143 70-143 70-1151 70-27
FOBES,R L FOBES,R L FOBES,R L FOBES,R L FOBES,R L	8212040382* 8212040374* 8212040412* 8212040421*	50-255	GAD.R K GADOW.O R GAGLIARDO.J E GAGLIARDO.J E GAGLIARDO.J E	8212280255 8212290222* 8212060226 8212070432* 8212100254	50-443 Q 50-409 R 50-112 Y 50-298 F 50-313 S	GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F	8212090447 8212090477 8212090499* 8212090507 8212090533	50-332 6 70-824 70-824 70-143 70-143
FOBES.R L FOSDALL.S P FOLEY.M G FOLEY.T FONNER.R L	8212050431* 8212270454 8212220238 8212140140* 8212160011	50-255 S NUREG NUREG 50-247 Q 70-143	CALEF,SR CALL,WR GALL,WR GALL,WR GALLAGHER,JM GALLAGHER,JM	8212230235 820827002 <i>7</i> 820827002 <i>7</i> 8212140345 8212130222	50-247	GIBGON, A F GIBGON, A F GIBGON, A F GIBGON, A F GIBGON, A F	8212090547 8212130062 8212130071* 8212150138 8212270128*	70-1151 70-27 70-27 70-143 70-143
FONNER,R L FONTANA,L FONTANA,L FOOTE,H P FORD,E J	8212280189# 8212160521# 8212160521# 8212270512 8212070384#	WASTE MQT 50-382	GALLE, D P GALLE, J GALLE, J GALLE, J GALLE, J	8212300199* 8212070127 8212070127 8212070327 8212070327	50-10 F 50-155 Q 50-155 Q 50-155 G 50-155 Q	Gibson, a f Gibson, a f Gibson, a f Gibson, J Gibson, L s	8212270137# 8212270165# 8212270184# 8212270142# 8212200027	FOIA FOIA FOIA 50-336 R PR
FORD, J T FORMEY, W L FOSTER, W E FOSTER, W E FOUCHARD, J J	8212230025 8212100308* 8212070434* 8212270213* 8008240700*	70-1201 50-454 G GA799 GA779 FOIA	GALLO, J GALLO, J GALLO, J GALLO, J	8212070352* 8212070352* 8212160223 8212160223 8212160227*	50-155 G 50-155 G 50-155 G 50-155 G 50-155 G	GIESEKE, J A GIESLER, C W GIESLER, C W GIESLER, C W	8212270420 8212030074 8212060049* 8212060090 8212070149	NUREO 50-305 J 50-305 G 50-305 B 50-305 P
TOUCHARD.J J FOUCHARD.J J FOUCHARD.J J J TOUCHARD.J J J TOUCHARD.J J	8212010071* 8212010102* 8212010108* 8212010123* 8212010143*	FOIA FOIA FOIA FOIA FOIA	GALLO, J GALLO, J GALLO, J GALLO, J	8212210258 8212210258 8212210285 8212210285 8212270045	50-155	GIEBLER.C W GIEBLER.C W GIEBLER.C W GIEBLER.C W GIEBLER.C W	8212070333 8212070257 8212140143 8212140407 8212160003	50-305 P 50-305 F 50-305 P 50-305 P
FOUCHARD, J J FOUCHARD, J J FRAHM, R FRAHM, R FRAHM, R	8212010149# 8212010230# 8210210095# 8212060174# 8212060214#	FOIA FOIA 50-311 \$ 50-311 \$ 50-311 \$	CALLO,R. CALLO,R CALLO,R H CALLO,R H CALLO,R H	8212060079 8212150169* 8212030083* 8212140113* 8212210282*	50-443	GIESLER.C W GIESLER.C W GIESLER.C W. GIESLER.C.W GIESLER.C W	8212170167 8212210181 8212270007* 8212270197 8212280193	50-305 B 50-305 P 50-305 F 50-305 P 50-305 F
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8212060278* 8212060308* 8212060316* 8212080364* 8212080443*	50-272 S 50-272 S 50-272 S 50-272 S 50-311 S	GARCIA:P J GARCIA:P J GARCIA:P J GARCIA:R GARDE:B:P	8212030255 8212030272* 8212070052 8212230276 8212020358	40-1162 40-6622 40-1162 50-247 U 50-373 P	GIEBLER, C W GIEBLER, C W GIEBLER, C W GIFFORD, L S	8212280230 8212280318 8212280467 8212280211 8212200041	50-305 F 50-305 P 50-305 P 50-305 R 50-447 A
FRAHM, R FRAIM, R FRAHM, R FRAHM, R FRAHM, R	9212140040# 8212140082# 8212140085# 8212140107# 8212160054#	50-272 S 50-272 S 50-311 S 50-311 S 50-311 S	Gardner.r Carrity.j H Carrity.j H Carrity.j H Carrity.j H	8212040112 8212040259 8212100264 8212130324 8212140204	50-327 8 50-309 P 50-309 P 50-309 P 50-309 P	GILBERT, L D GILCHRIST, J, E GILDENHORN GILDENHORN, A J GILDENHORN, A J	8212030058* 8212210536 8212080070 8212220025 8212270510	50-482 G 40-8064 CONTRACT CONTRACT CONTRACT
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8212140370* 8212140414* 8212220310* 8212220385* 8212220435*	50-311 S 50-311 S 50-272 S 50-311 B 50-311 S	GARRITY, J H GARRITY, J H GARRITY, J H GARRITY, J H	8212140435 8212140453* 8212210165 8212210308 8212220370*	50-309 F 50-309 F 50-309 S 50-309 F 50-309 G	gildner, m l gilinsky, v gill, a gillen, d. m gillen, d. m	8212270417* 8212020023* 8212230248* 8212010295 8212020001	50~440 ¢ F01A 50~29 P 40~4492 40~8681

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GILLEN, D H	8212030228	40-8681	Graber, L	8207150055	FOIA	orgesch. 0 L	8212020355	50-382 0
GILLEN, D H	8212030238	40-8481	Graber, L	8212010314	FOIA	Groesch. 0 L	8212230361	50-382 0
GILLEN, D H	8212030244	40-8481	Graber, L	8212100404	FOIA	Gross, M E	8212100358	FOIA
GILLEN, D H	8212030251	40-8481	Graber, L	8212280033	FOIA	Grossman, H	8212020344	50-440 0
GILLESPIE, F P	8212080149#	FOIA	Graber, L	8212270014	FOIA	Grossman, H	8212020350	50-397 0
GILLETT, W T	8212200065*	50-316 R	GRAESSER, K L	8212020234	50-295 S	GRDSBMAN, H	8212020360	50-460 Q
GILLETT, W T	8212200122*	50-315 R	GRAEBSER, K L	8212020272	50-295 S	GROSSMAN, H	8212080272	50-460 Q
GILLETT, W T	8212240228*	50-316 R	GRAEBSER, K L	8212140055	50-295 R	GROSSMAN, H	8212200104	50-397 Q
GILLETT, W T	8212240424*	50-315 R	GRAESSER, K L	8212140321	50-295 S	GROTENHUIS, M	8212070492	50-305 P
GILLETT, W T	8212240428*	50-315 R	GRAESSER, K L	8212170307	50-295 S	GRUBER, E E	8212270250*	50-537 A
GILLEY, E R	8212070429#	CONTRACT	GRAESSER.K L	8212280244	50-295 S	GUCWA,L T	8212070127	50-321 Q
GILMAN, B	8212230276	50-247 U	GRAESSER.K L	8212280432	50-295 S	GUCWA,L T	8212070492	50-321 Q
GINEVAN, H E	8212060429	NUREO	GRAESSER.K L	8212280450	50-295 S	GUCWA,L T	8212270151	50-321 P
GINSBERG, T	8212070400	RES	GRAHN.D	8212060429	NUREG	GUHIN,M A	8212080017#	F8IA
GIRARD, E H	8212070536#	50-438 O	GRAMM.R A	8212210282*	50-443 G	GUILBERT,D E	8212280401*	QA999
GIRLA H GLASGCOCK,R B GLASGN,J P GLEASGN,J P GLEASGN,J P	8212080516 8210270016* 8212230339 8212020321 8212060241	RES 50-397 A 50-440 G 50-247 G 50-247 O	GRANTIW B GRANTIW B GRANTIW B GRANTIW B GRAVESIR H	8212020314* 8212040252* 8212100023* 8212280042* 8212080449	50-254 Q 50-409 Q 50-263 Q 50-295 Q 50-213 S	GUILD, R GUILD, R GUILD, R GUILD, R GUILD, R	8212280138 8212280132 8212280138 8212280138	50-413 G 50-413 G 50-413 G 50-413 G 50-413 O
GLEASON, J P GLEASON, J P GLEASON, J P GLEASON, J P GLEASON, J P	8212070073 8212100103 8212130177 8212130208 8212130026	50-483	GRAVES, R H GRAY, E H GRAY, J R GRAY, J R GRAY, J R	B212150222 B212070269* B212010032 8212030210 B212090242	71-6574 50-352 G 50-289 G 50-289 G 50-289 G	ONALANDO ONTERNOS M CALCOMENDO M CALCOMENTO O CALCOMENTO	8212280138 8212030028* 8212100261 8212100323 8212270534	50-413 0 50-373 0 50-373 8 50-537 A RES
GLEASON. J P	8212200097	50-247 G	GRAY.JR GREEN.HJ GREEN,HJ GREEN.HJ GREEN.HJ GREEN.HJ	B21227000B	50~289 0	GURCAK.A W	8212160365	TOPREP
GLEASON. J P	8212230181	50-247 G		B212020116	50~296 8	GUBTAVE R P	8217080024*	CONTRACT
GLEASON. J P	8212230188	50-247 O		B212020143	50~260 8	GUSTAVE.R	8212080022	CONTRACT
GLEASON. J P.	8212270204	50-483 T		B212020179	50~328 8	GUSTAVE.R P	8212020057*	50-354 G
GLEASON. J P.	8212300012	50-247 O		B212020240	50~296 8	GUSTAVE.R P.	8212030243*	CONTRACT
GLEASON, J P	8212300014	50-247	GREEN.H J	8212020241	50~274 B	GUSTAVE, R P	821 2030256#	CONTRACT
GODDARD, R J	8212040002		GREEN.H J	8212020348	50~257 S	GUSTAVE, R P	821 2080568*	50-443 A
GODDARD, R J	8212210011		GREEN.H J	8212030039	50~259 S	GUSTAVE, R P	821 21 00162*	CONTRACT
GODDARD, R J	8212220119		GREEN.H J	8212030084	50~257 S	GUSTAVE, R P	821 21 30160*	CONTRACT
GODDARD, R J	8212300174		GREEN.H J	8212090109	50~257 S	GUSTAVE, R. P	821 2220528*	CONTRACT
GODY, A T GODY, A T GODY, A T GODY, A T GODY, A T	8212030038* 8212030090* 8212030147* 8212030175* 6212030177*	50-244	OREEN,H J OREEN,H J OREEN,H J OREEN,H J	8212070143 8212070174 8212070280 8212070361 6212070551	50~240 S 50~328 S 50~259 S 50~259 S 50~259 S	GUSTAVE,R P QUSTAVE,R P GUSTAVE,R P GUSTAVE,R P QUSTAVE,R P	921 2220535* 921 2220542* 821 2220553* 921 2230051* 921 2270422*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
GDBY, A T	8212060212*	H18C	GREEN.H J	8212140198	50-328 9	QUSTAVE,R P	8212270447*	CONTRACT
GDBY, A T	8212100081*	50-217 0	GREEN.H J	8212140241	50-327 8	QUSTAVE,R P	8212270503	CONTRACT
GDBY, A T	8212210134*	50-277 0	GREEN.H J	8212140440	50-259 8	QUSTAVE,R P	8212270521*	CONTRACT
GDBY, A T	8212210351*	50-309 0	GREEN.H J	8212150066	50-259 9	QUSTAVE,R P	8212270560*	CONTRACT
GDBY, A T	8212210370*	70-487	GREEN.H J	8212150071	50-296 8	QUSTAVE,R P	8212280049*	CONTRACT
GDDY, A T GODY, A T GDDY, A T GDDY, A T. GDDY, A T.	8212220437* 8212230335* 8212270352* 8212270363* 8212270383*	70-135 70-1143 70-820 70-1100 50-244 Q	GREEN, H J GREEN, H J GREEN, H J GREEN, H J	8212150101 8212150107 8212210075 8212220463 8212280099	50-260 8 50-296 8 50-328 8 50-260 8 50-260 8	QUBTAVE,R P QUSTAVE,R P QUTIERREZ,J M QUTMANN,P M HAASS,W P	8212300123* 8212300192* 8212290003 8212270540* 8212100052	CONTRACT CONTRACT 50-478 G CONTRACT TOPREP
GODY, A T GODY, A T GOETZ, H GOGOL, E. GOLDBERG, F F	8212290443* 8212290479* 8212270030* 8212200099 8212270435	50-272 Q 50-219 Q 70-33 50-373 H Nureq	GREEN, H J GREEN, H J GREEN, K GREEN, P K	8212280111 8212280133 8212280147 8212170276* 8211040090*	50-327 8 50-328 8 50-259 8 50-250 P 50-335 8	HAASS, W.P HAASS, W.P MACKETT, D.B HAFNER, B HAFNER, B	8212170396 8212270473 8105210384* 8208290116 8209150058	TOPREP PROJ 50-263 G 50-322 A 50-322 H
QDLDBERQ.J H	8212070262	50-498 K	GREENBERG, E V	9212080257	50-537 Q	HAFNER.B	8209150064	50-322 A
GDLDBERQ.J H	8212070377	50-498 K	GREENBERG, E V	8212080257	50-537 Q	HAFNER.B	8212290006	50-322 A
GDLDBERQ.J H	8212140381	50-498 C	GREENBERG, E V	8212080257	50-537 Q	HAGAN.T F	8212020194*	CONTRACT
GGLDBERQ.J H	8212140383*	50-498 C	GREENBERG, E V	8212230200	50-537 Q	HAGAN.T F	8212020390*	CONTRACT
GGLDBERQ.J H	8212170120	50-498 A	GREENBERG, E V	8212230200	50-537 Q	HAGAN.T F	8212020404*	CONTRACT
oolddero, j h	8212170124*	50-478 A	GREENBERG, E V	8212230200	50-537 0	HAGAN, T F	6212060304*	CONTRACT
ooldbero, j r	8212010034	50-289 G	GREENBERG, E V.	8212270245	50-537 0	HAGAN, T F	6212060506*	CONTRACT
ooldbero, s	8212080233	50-454 G	GREENE, G. A	8212070400	RES	HAGAN, T F	6212130162*	CONTRACT
ooldbero, s	8212080245*	50-454 Q	GREENE, B R	8212140479	50-259 P	HAGAN, T F	6212160606*	CONTRACT
ooldbero, s c	8212040010	50-454 Q	GREENMAN	8212210417	50-286 8	HAGAN, T F	6212170401*	CONTRACT
ODLDBERG, B C	8212070157	50-454 Q	GREENMAN.E	8212030032*	70-1100	HAGAN, T. F	8212220024+	CONTRACT
GOLDDERG, G C	8212070231	50-454 G	GREENMAN.E	8212040079	50-443 6	HAGAN, T. F	6212220027+	CONTRACT
GOLDFARB, R A	8212150013*	50-247 T	GREGER.L R	8212020314*	50-254 9	HAGAN, T. F.	6212270412+	CONTRACT
GOLDFARB, R A	8212150013*	50-247 T	GREGER.L R	8212030114	50-155 8	HAGAN, T. F	6212270417+	CONTRACT
GOLDMAN, L A	8212130058	NUREQ	GREGER.L R	8212040197*	50-254 9	HAGAN, T. F	6212270501+	50-597 A
GOLDMAN, M	8212270513*	CONTRACT	GREGER.L R	8212080296*	50-295 Q	HAGAN, T.F	8212270530*	CONTRACT
GOLDMANN, K	8212270069	71-9015	GREGER,L R	8212100023*	50-263 Q	HAGAN, T.F	8212270543*	CONTRACT
GOLDSTEIN, R.	8212230241	50-247 G	GREGER,L R.	8212280062*	50-295 Q	HAGAN, T.F	8212270556*	CONTRACT
GOODE, R. W	8212030232*	50-259 G	GREGG.R J	8212270256*	70-820	HAGAN, T.F	8212280455*	CONTRACT
GOODLING, B	8212070068*	50-289 H	GREITZER,C	8212230241	50-247 Q	HAGAN, T.F	8212280501*	50-329 A
GOODMAN, L 8 GOODWIN, E F GOODWIN, W L GORDON, B B, GORDON, M J	8212280256* 8212010024 8212150244* 8211020246* 8212010008	50-409 S 50-397 D 70-1151 40-8698 Waste Mot	M C'NILLINO W C'NEAMESINO M C'NEEWE M C'NEEWE	8212280168 8212280173* 8212270442* 8212270445* 8212280307	TOPREP TOPREP FOIA FOIA 50-913 P	HAGAN,T F HAGAR,C HAHER,J HAIRSTON,W G MAIRSTON,W G	8212270056# 8212080263# 8212130185# 8212070312# 8212170207#	CONTRACT 50-219 B 50-400 A 50-364 S 50-348 R
GORDON, K J	8212020117	WASTE MOT	GRIFFITHB. 6 K	8212270156	NUREO	HAIRSTON, W 0	821217030Q#	50-364 R
GORNES, J H	8212230001	71-6717	GRIMEG. 8 K	8212100121*	70-143	HAIRSTON, W. 0	8212300223#	50-364 8
GRAABS, J	6212210324*	50-286 P	GRIMEG. 8 K	8212150140*	50-382 Q	HAIRSTON, W 0	8212300227#	50-364 8
GRADER, L	8208270072	FOIA	GROUE. J A	6212170189*	50-266 Q	HAIRSTON, W 0	8212300231#	50-364 8
GRABER, L.	8209150054	FOIA	GROCE. R H	8212290116	50-309 R	HAIRSTON, W 0	8212300234#	50-364 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HAIST.D D HAIST.D P HAIST.D P HALE,C J HALL.B L	8212170370# 8212210195# 8212280301# 8212210223# 8212030232#	50-508	HASSE.R A HASSE.R A HASSE.R A HASSELL.D F HATTER.B J	8212100339# 6212170121# 6212270339# 6212280008 6212080011#	50-461	A L.dNIH A L.dNIH A L.dNIH A L.dNIH A L.dNIH A L.dNIH	8212060172 8212060232 8212150015 8212210118 8212210329	50-254 F 50-295 0 50-409 0 50-237 0 50-282 0
HALL, D G HALL, D P HALL, D P HALL, D P HALL, D P	8212080520 8212020324 8212020333 8212040093 8212040144	RES 50-461 S 50-461 S 50-461 Q 50-461 A	HATTORI,H HATTORI,H HAWKINS,F C HAWKINS.F C HAWKINS.F C	8212010114 8212010127 8212100339* 8212170121* 8212270339*	XPORTLIC XPORTLIC 50-461 9 50-295 0 80-305 0	HINKLE, LS HINRICHS, O HINRICHS, G HINRICHS, G HINRICHS, O	8212060206+ 821208031!+ 8212150027+ 8212210133+ 8212210140+	90-317 5 50-247 9 50-247 5 50-247 5 50-247 6
HALL, D P HALL, D P HALL, D P. HALL, W J HALL, W J	8212140057 8212280101 8212280360 7907100669* 7907240319*	50-461 S 50-461 A 50-461 G 50-237 P 50-237 P	HAWKINS,F C HAWTHORNE,J R HAYES,D.W HAYES,D W HAYES,D W	8212270348* 8212270479 8212080573* 8212070236* 8212100240*	50-254	HIRT, C W HOCHBERG, A G HOCHFELDER, E HODGOON, A D HODGOON, A P	8212070276* 8212230235 8212010085 8212130227* 8212140036	50-416 P 50-247 P PT21 50-29 P 50-352 P
Mall. W J Hall. W J Hamell. K J Hamill. K J Hamill. K J	7908080624* 8005070798* 8212020196 8212020386 8212020397	50-237 P 50-237 P WASTE MOT WASTE MOT WASTE MOT	Hayes, D W Hayes, D W Hayman, R B Haymes, R C Haymes, R C	8212100308* 8212280381* 8212220249 8212030040 8212030124	50-454 Q 50-461 Q NUREO 50-322 Q 50-3 F	HODODON.A P HODODON.A P HODODON.A P HODGE.S A HOFFMAN.D P	8212200114 8212220097 8212220126 8212140479 8212300332	50-352
HAMILL,K J, HAMMER,S HAN,J T HANAUER,S H HANAUER,S H	8212020400 8212140357* 8212270181 8206070020* 8206070028*	Haste Mot 50-263 8 Nureg Foia Foia	HAYNES,R C HAYNES,R C HAYNES,R C HAYNES,R C HAYNES,R C	8212050307 8212070014 8212070021* 8212280084 8212280186	50-286 F 50-219 Q 50-219 G 50-247 F 50-286 F	HOHMAN, B HOLIAN, P D HOLIAN, P D HOLLAND, P HOLLEY, W	8212140177* 8212280213* 8212280216* 8212020280* 8212210250*	50-219 S 50-124 P 50-124 P 50-237 S 50-313 G
HANAUER, SH HANAUER, SH HANAUER, SH HANBEY, M HANCHETT, JO	8206220070* 8207120252* 8212080639 8212280538 82122010168*	FOIA FOIA MISC 27-48 FOIA	HAZLE:A J HAZLETT:T L HEATH:D C HEATHERLY:T L HEHL:C W	8212140422 8212210005* 8212220142 8212290504* 8212030004	PR 50-275 P NUREO 50-390 Q 50-261 S	HOLLINGNORTH, B HOLT, J HOLT, J HOLT, J HOLTER, O M	8212200079 8212150022 8212150022 8212250023	50-443 G 50-287 H 50-247 G 50-247 G NUREG
HANCHETTIJ O HANCHETTIJ O HANCUCKIJ A HANNETTIB HANNETTIB	8212010207* 8212210185* 8212060084 8212230406 8212230410*	FOIA 50-344 Q 50-302 H XPORTLIC XPORTLIC	HEIDEL,C H HEIDER,L H HEIDER,L H HEIDER,L H HEIDER,M J	8212010154* 8212020300 8212140379 8212290126 8212160838	50~341 K 50~27 P 50~271 P 50~27 R PR	HOLTER, G M HOMAN, F J HOMAN, F J HOMAN, F J HONG, C	8212270232 8212010486 8212220519 8212290512 8212010015*	NUREO RES RES SO-537 F
HANNETT, B A	8212070489 8212070503* 8212080020* 8212080029 8212080035	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HEISKEL,M M HELLER,J K HEMBY.E HENDRIE,J M HENDRIX,G W	8212130195 8212030129* 8212010110 8212010112* 8212020118	71-4909 50-255 G XPORTLIC FOIA PR	HOOD, D HOOD, D S HOOPER, F HOOPER, F HOPKINS, P	8212020210 8212260387 8212210296* 8212070380*	50~329 A 50~329 A 50~155 Q 50~155 Q 50~369 Q
HANNETT, BA HANNON, JN HANNON, B HANSON HARBOUR, J	8212230402 8212270108 8212020277 8212150170* 8212070167	XPORTLIC 50-3 P PRM 50-275 P 50-322 0	HENBLEY, K D HERBERT, J P HERDT, A R. HERDT, A R HERING, R F	8212160420 8212020404* 8212290109* 8212290138* 8212280165	70~143 CONTRACT 50~250 G 50~261 G 50~315 G	HOPIN, U A HORIN, W A HORIN, W A HOROWITZ, F D	8212140409 8212140409 8212280273 8212280273 8212220535*	50-445
HARDIN, A K HARDIN, A K HARDIN, A K HARDIN, A K HARDIN, A K	8212280278 8212270078* 8212270107* 8212270114* 8212270137*	50-324 \$ 50-250 0 50-250 0 50-250 0 50-250 0	HERLEKAR, A 8 HERMANN, R HERNAN, R H HERNAN, R H HERNAN, R H	8212210342* 8203310470* 8212070356 8212170074 8212220548	50~243 P 50~29 P 50~329 D 50~329 E 50~329 E	HOGEY, C M HOU, B HOUBTON, R HOUSTON, R H HOUSTON, R W	8212090500# 8212300007# 6212170238* 8212020301# 8212080332#	50-250 Ø 50-312 Ø 50-373 9 50-373 9 50-373 S
HARDING, H. R. HARDING, M. R. HARDING, M. R. HARDING, M. R. HARDING, M. R.	8212020191* 8212030092* 8212090178* 6212140207* 8212140247*	50-326 S 50-327 S 50-328 S 50-328 S 50-327 S	HERNAN, R W HERNAN, R W HERNAN, R W HERNAN, R W HERNANDEZ, G	8212280513 8212290475 8212290508 8212330185 8212170376*	50-327 E 50-327 E 50-327 A 50-327 A 50-206 Q	ACISION B Y WOLGARDH B F 181ADH B F 181ADH B AGAIGH B AGA	8212170270# 8212270148* 8212140333 6212140333 8212140345	50-373 S 50-373 S 50-522 C 50-522 C 50-522 C
HARDING, M R HARDING, M R HARDING, M R HARDING, V HARDY, B L	8212210100* 8212280116* 8212280136* 8212070441* 8212030274	50-328 8 50-327 8 50-328 8 50-278 F 40-8084	HERRICK, E O HERRING, K S HERSCH, M M HERSCH, M M HESSON, O M	8212160365 8207200474* 8212270077 8212270079* 8212220265	TOPREP 50-155 P XPGRTLIC XPGRTLIC NUREQ	KGATE'1 8 HOATE'1 8 HOATE'1 8 HOATE'1 8	8212140345 8212140354 8212140354 8212140386 8212140386	50-522 0 50-522 0 50-522 0 50-522 0 50-522 0
HARDY, B L HARDY, B L HARDY, J E HARIED, J A HAROLDSGN, R D	8212030278 8212270331 8212130123 8212270492 821207086	40-8064 40-8084 Nureg Nureg 50-407 P	HIATT,8 L HIATT,5 L HIATT,5 L HIATT,5 L HIATT,5 L	8212040108 8212070194 8212070199 8212070203 8212230247	50-440	HOWARD, B N HOWARD, E M HOWARD, E M HOWARD, J E	8212140374 8212080088* 8212080073* 8212080127* 8212170305	PR 70-143 70-143 70-143 50-293 P
HARRAN, G HARRINGTON, R M HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D	8212290229* 8212140479 8212150224* 8212150233* 8212290423*	50-245 R 50-257 P 50-273 Q 50-273 Q 50-273 Q	HIATT.S L HIATT.S L HIATT.S L HIATT.S L HIATT.S L	8212230319 8212230345 8212230368 8212280324* 8212280321	50-440 G 50-440 G 50-440 G 50-440 G 50-440 A	HOWE, P W HOYLE, A HOYLE, J C HOYLE, J C	8212090375 8212140377 8212070424 8212080009* 8212270084*	50-324 0 50-341 9 CONTRACT COMMISSION FOIA
HARRIS,A B HARRIS,J A HABRIS,J R HARRIS,R H	8212090372* 8212010244* 8212010249* 8212090364* 8212220218*	50-395 S FOIA FOIA 50-417 O 50-397 Q	HICKEY, JP HIETALA, J HIETELA, JJ HIGGINS, JC HILDEBRANO, JE	B212070076* 8212140075* 8212020327* 8212030083* 8212130060*	COMMISSION 50-373 S 50-373 S 50-322 Q 50-320 P	HOYLE, J C HOYT, G W HOYT, H F HOYT, H F HSU, T I	8212270095* 8212230203 8212230203 8212270208 8212210333*	FDIA 50-361 P 50-443 0 50-443 0 50-263 P
HARRISON: F HARRISON: F HARRISON: F. L HARRISON: J HART: T	8212100250* 8212140459 8212140485 8212080407* 8212280250*	50-324 R 50-261 P NUREO 50-546 Q 50-346 S	HILL, D HILL, K L HILL, K L HILL, K L HILL, K L,	8212080583* 8212040224* 8212140147* 8212140338* 8212210034*	CONTRACT 50-331 8 50-331 8 50-331 8 50-331 8	HUBBARD, G T HUBBARD, R B HUBBARD, R B HUBBLE, W H HUBBLE, W H	8212070304* 8212270227 8212270227 8212020076 8212020108	0A999 50-322 T 50-322 T 50-345 P 50-364 P
HARTHAN, J E HARTHAN, S L HARTZMAN, R H HARTZMAN, R H HARTZMAN, J E,	821220282 8209150071 8212220246 8212220246 8212220246 8212300174	NUREG FOIA 50-247 G 50-247 G 50-219 G	HILL,K L HILL,K L HILL,K L HILLMAN,R E HIND,J A	8212210074* 8212210358* 8212280457* 8212210044* 8212060009	50-331 8 50-331 8 50-331 8 50-217 8 50-315 0	HUETER, L. J. HUETER, L. J. HUFFMAN, G. N. HUFFMAN, G. N. HUGHEB, P. O.	8212020314* 8212040197* 8212090540* 8212090555* 8212020071*	50-254 Q 50-254 Q 50-250 Q 70-1151 50-302 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY
HUGHES, P. G. HUGHES, P. G. HUGHES, P. G. HUI ZENGA, H. W. HUI ZENGA, H. W.	8212150053* 8212150064* 8212150102* 8212270005 8212270005	50-302 5 50-302 5 50-302 5 27-47 27-47	JACKSON.R E JACKSON.R S JACOBS.A JACOBS.A	8109210340* 8212090481* 8212030037* 8212220522 8212220524	FOIA State Prog 50-219 G CONTRACT CONTRACT	JOHNSTON, U V JOHNSTON, U V JOHNSTON, W V JONES, D W JONES, O T	8107140119* 8204270491* 8211290023* 8212090270* 8212290281	50-322 H 50-255 P 50-206 G 70-1113 50-259 R
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8212060054 8212070251 8212080519 8212090284 8212090293*	50-289	JACOBS, A JACOBS, R H JACOBS, R S JACOBSON, J JAKUBAITIS, T C	8212300117 8212060508 8212230241 8212270023 8212020237*	CDNTRACT 50-287 P 50-247 G 50-206 Q 50-295 S	JONES, J M JONES, R JONES, R E JONES, R J JONES, R J	8212080103* 8212130218 8212230366 8212260104* 8212080107*	CONTRACT 50-440 0 50-400 0 FOIA FOIA
HUKILL, H D	8212090501 8212130060* 8212130104 8212140228 8212140466	50-289 P 50-320 P 50-289 P 50-289 S 50-289 P	JANG, J. C JANUSKA, A. O JAPE, F JAPE, F JAPE, F	8212030037* 8212170079* 8212090213* 8212090271* 8212090277*	50-219 0 50-373 0 90-389 0 50-370 0 50-280 0	JONES, R. J. JONES, R. J. JONES, R. J. JONES, S. Z.	8212080111* 8212080126* 8212080146* 8212100164* 8212060476	FOIA FOIA FOIA FOIA 40-8102
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8212210017 8212210232 8212270134 8212270268 8212290197	50-289 P 50-289 R 50-289 P 50-289 P 50-287 P	JAPE, F JAPE, F JAPE, F JARRELL, D B JAUDON, J P	8212070360* 8212070411* 8212070473* 8212130152 8212030112*	50~387 Q 50~387 Q 50~327 Q NUREQ 50~285 Q	JONES, W C JONES, W B JONES, W C JONES, W C	8212270244* 8212070123* 8212280378* 8212020073 8212020117	50-280 R 50-382 0 50-382 0 50-285 P 50-285 P
HULL, P HULMAN, L Q HULMAN, L Q HUNNICUTT, D M KUNNICUTT, D M	8212070348* 8212080626 8212130050 8212030058* 8212030156*	50-269 P NUREO NUREO 50-482 0 50-445 G	JAUDDN, J P JENKINS, G R JENKINS, G R JENKINS, G R	8212300182 8212090274* 8212090274* 8212090351* 8212090540*	50-368 8 70-1201 70-824 50-261 0 50-250 0	JONES, W C JONES, W C JONES, W C	8212030009 8212060032* 8212060254 8212060266 8212060438	50-285 P 50-285 P 50-285 P 50-285 Q 50-285 P
HUNNICUTT, D M HUNNICUTT, D M HUNSTAD, A A HUNSTAD, A A HUNT, M D	8212030172* 8212070133* 8212020317* 8212080429* 8212090256*	50-368	JENKINB.O R JENKINS.O R JENSCH.B H JENSEN.S A	8212070595* 6212270137* 6212270164* 6212010238* 8212060551*	70-1151 FOIA FOIA FOIA 50-443 A	JONES, W C JONES, W C JONES, W C JONES, W C	8212070150* 8212070419 8212080380 8212100244* 8212130312	50-285 Q 50-285 P 50-285 F 50-285 G 50-285 F
HUNT, M D HUNTER, R S	8212090258* 8212030125 8212030145* 8212060072 8212060296	50-424 Q 50-315 P 50-315 P 50-315 P 50-315 P	JOHNSON'Y D TENBEN'S E TENBEN'S E TENBEN'S E	8212140167 8212290199* 8212140455 8212030239 8212130270*	50-316 P 50-237 P 50-522 G RES 50-27 G	JDNES, W C JONES, W C JONES, W C JONES, W C	8212140416 8212200059 8212210022* 8212210179 8212230326*	50-285 P 50-285 R 50-285 Q 50-285 P 50-285 P
HUNTER,R S HUNTER,R S HUNTER,R S HUNTER,R S HUNTER,R S	9212100290 9212160001 9212170179 9212210125 9212270136	50-315 P 50-315 # 50-316 P 50-315 P 50-315 P	JOHNSON, A D JOHNSON, B D JOHNSON, B D JOHNSON, B D	8212300240* 8212230306 8212060047 8212060357 8212080261	70-25 50-275 P 50-255 S 50-255 S 50-255 S	JONES: W C JORDAN, D D JORDAN, E L JORDAN, E L JORDAN, E L	8212280197 8212170133* 8208190251 8208190261 8208190268	50-285 P 50-498 A 50-3 Q 50-3 Q 50-3 Q
HUNTER, R S HUSAIN, I HUSERY, D E HUTKO, K HUTTON, P H	B212280310 B212280061* B212160270* B212080525* B2120804B3	50-314 0 50-409 P 50-317 S 50-219 B RES	10 - 100 - 1	8212090409 8212100313 8212270215 8212280330 8212280460	50-255 F 50-255 S 50-255 S 50-255 Q 50-255 S	JORDAN, E L JORDAN, E L JORDAN, H JORDAN, M	8212220505 8212220508 8212280083 8212270420 8212270164*	50-335 Q 50-220 Q 50-397 Q NUREG 50-327 R
HUTTON, P. H. IDEKFR, R. L. IGNATONIS, A. INGRAM, F. INGRAM, F.	8212300137 8212220527 8212150144 8212010177* 8212010180*	RES 70-143 50-287 S FOIA FOIA	NOHNSON'S E NOHNSON'S E NOHNSON'E B NOHNSON'B M	8211220094* 8212070160 8212080520 8212150124 8212150127	50-3 P 50-237 G RES 50-413 G 50-413 G	JORGENSEN, B L JULIAN, C JULIAN, C JULIAN, C A JULIAN, C A	8212030127* 8212070313* 8212070524* 8212070234* 8212070537*	50-255
Ingram, F Ingram, F Ingram, F Ingram, F Ingram, F	8212010218* 8212010224* 8212010235* 8212010067* 8212010070*	FOIA FOIA FOIA FOIA FOIA	JOHNSON, O E JOHNSON, O E JOHNSON, O E JOHNSON, O E	8212160235 8212160240* 8212160256 8212160303 8212170180	50-413 Q 50-413 Q 50-413 Q 50-413 Q 50-413 Q	JULIAN, C A JUNGE, M A	8212070562# 8212070564# 8212150103 8212150151 8212060306#	50-335 Q 50-335 Q 50-338 B 50-338 B 50-317 S
Ingram, F. L. Ingram, F. L. Ingram, F. L. Ingram, F. L. Ingram, F. L.	8212010077* 8212010080* 8212010159* 8212010194* 8212010201*	FOIA FOIA FOIA FOIA	0 F 'NOSUNGC B O 'NOSUNGC D 'NOSUNGC D 'NOSUNGC B 'NOSUNGC	8212170184 8212210317 8212270002 8212080505 8212270561	50-413 Q 50-413 Q 50-413 Q RES NUREG	Junge, M A Junge, M A Junge, M A Justus, P S Kaeppel, F	8212210048# 8212210080# 8212290282* 8212220546 8212100335*	50-317 8 50-317 8 50-317 6 Waste Mgt 50-265 8
INNAN.Q W INTERRANTE, J IRBY, B J IRBY, B J IRBY, B J	8212270561 8212010174* 8212150067* 8212150076* 8212220472*	NUREG FOIA 50-259 B 50-296 B 50-260 B	JOHNSON, L JOHNSON, L JOHNSON, L JOHNSON, P	8212140337* 8212160352* 8212160372* 8212160386* 8212030071	40-3265 40-6500 FOIA FOIA 50-312 S	KAHLE, J B KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALMAN, K L	8212070517* 8212080370 8212100328 8212130176 8212010056	70-143 50~265 5 50-265 8 50-254 8 40-8064
IRWIN.D P IRWIN.H R ISENBERO.J IYER.J S	8212140463 8212200111 8212160043 8212130147 8212270181*	50-322 0 50-322 G 71-5796 NUREG 50-361 R	Р 1 , иювино 1 , иювино 1 , иювино 1 , иювино 1 , иювино 1 , иювино	8212040347 8212170397* 8212020325 8212010013 8212020187	90 312-06 90 365-08 90 358-08 90 378-08 90 378-08	KALMAN, K L KALMAN, K L KALMAN, K L KAMMER, D S KAMMER, D S	8212010059 8212030264 8212300017 8212100046 8212140323	40-8380 40-8380 40-8064 50-370 F 50-257 K
JABBOUR, K N JABBOUR, K N JABBOUR, K N	8212150232 8212170422 8212220015 8212170118* 8212170306*	50-413 A 50-413 A 50-413 A 50-454 Q 50-10 Q	Д , МОВИНОГ О М , МОВИНОГ О М , МОВИНОГ О М , МОВИНОГ О М , МОВИНОГ	8212300025 8212030058* 8212030112* 8212030115* 8212030126*	40-1341 50-482 Q 50-285 Q 50-482 Q 50-285 Q	KAMMER, D & KAMMER, D & KANE, W F KANGA, B K KANGA, B K	8212150010 8212270287 8212010030 8212030113 8212060322	50-327 P 50-390 A 50-397 P 50-320 R 50-320 S
JACKSON, K. C. JACKSON, J. P. JACKSON, K. C. JACKSON, K. C.	8212270386* 8212160050* 8208270147* 8212020040 8212020175	50-249 Q 71-5794 Commission Waste Mot Waste Mot	о м чозиног о м чозиног о м чозиног о м чозиног	8212030192* 8212100247 8212200033* 8212210208 8212280345	50-348	KANGA.B K KANGA.B K KANGA.B K KANGA.B K KANGA.B K	6212070143 8212130059 8212130316 8212150036 8212160764*	50-320 R 50-320 P 50-320 F 50-320 S 50-320 F
JACKSON, K. C. JACKSON, P. D. JACKSON, R. JACKSON, R. E. JACKSON, R. E.	8212020203 8212220173 8002130081* 8001280032*	WASTE MGT NUREG 50-204 P 50-482 A 50-204 P	о иодеинос н С иодеинос н С иодеинос о м иодеинос о м иодеинос	8212290210 8212290249 8212140186 8212300134 8212130215*	50-313 S 50-482 B 50-277 Q 50-277 Q 50-528 Q	KANGA, BK KANGA, BK KANGA, BK KANGA, BK KANGA, BK.	8212210018 8212220447 8212230375 8212270147 8212280370*	50-320 P 50-320 S 50-320 P 50-320 F 50-320 Q

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
Kanga. B K Kanga. B K Kanga. B. K Kanga. B K Kaplan, C	8212270233 8212270353* 8212300113 8212300240 8212140242	50-320 B 50-320 Q 50-320 P 50-320 P 50-247 Q	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	6212220306 8212270429* 6212280070 8212280375 6212280381*	50-10 F 50-359 A 50-10 G 50-441 G 50-441 G	KNIGHTON, G W KNIGHTON, G W KNIGHTON, G W KNOP, R C KNOP, R C	8212130168* 8212130405 8212220011 8212080378 6212080402*	50-341 P 50-528 A 50-508 C 50-546 Q 50-546 Q
KAPLAN, S A	8212280461*	50-295 S	KEPPLER, J G	6212270415	50-295 F	KNOP,R C	8212080561	50-461 0
KATZMAN, A J	8212230241	50-247 0	KERCH, H	6212060217*	50-309 Q	KNOP,R C	8212080567*	50-461 0
KAUCHER, J E	8207140103*	50-255 P	KERCH, H W	6212220216*	50-397 Q	KNOP,R C	8212100175	50-367 0
KAUFFMAN, J T	8212220405*	50-387 Q	KERR, G W	6212270443	NUREO	KNOP,R C	8212100178	50-341 0
KAVANAUGH, P F	8212220542*	CONTRACT	KERR, T	8212020153*	50-260 B	KNOP,R C	8212100224	50-461 0
KAVANAUOH, P F	8212270412*	CONTRACT	KERR, T	8212070153*	50-240 8	KNOP,R C	8212100230*	50-461 Q
KAY, D L	8212140128*	50-373 S	KETZLACH, N	8212020081*	70-734	KNOP,R C	8212280381*	50-461 Q
KAY, D L	8212170174*	50-373 S	KETZLACH, N	8212080047*	70-27	KNOP,R C	8212270406	50-546 Q
KAY, D L	8212270356*	50-373 S	KETZLACH, N	8212080675*	70-498	KNOP,R C	8212270412	50-440 Q
KAY, J A	8212060026	50-29 P	KETZLACH, N	8212270058	70-25	KOERTER,O L	8212030127	50-482 A
AY, J. A	8212076040	50-27 P	KEY,W J	8212290336*	50-246 Q	KDESTER.G L	8212030135*	50-482 A
AY, J. A	8212076047	50-27 P	KEYSERLING,W	8208290030	ACRS	KDESTER.G L	8212070222	50-482 F
AY, J. A	8212136223	50-27 P	KIEL,G R	8212010057	XPORTLIC	KDESTER.G L	8212170324	50-482 H
AY, J. A	8212146394	50-27 F	KIEL,G R	8212010063*	XPORTLIC	KDESTER.G L	8212200036	PR
KAY, J. A	82122860474	50-29 P	KILLINGER,M H	8212060493	70-2968	KDESTER.G L	8212210115	50-482 B
Kayer, w v	821 2290199*	50-237 P	KILLINGER, M H	8212080007	70-2964	KOESTER.O L	8212270187	50-482 C
Kearney, j j	821 2020359	PR	KIN, J W	8212150072*	50-331 P	KOESTER.O L	8212280338	50-482 S
Keimig, r	821 2060195	50-272 S	KINCAID, C T	8212270512	NUREG	KOLR.G J	8212040492	50-313 P
Keimig, r	821 21 40168	50-219 S	KINDER, E T	8212100102	50-443 A	KOLTAY.P	8212140140*	50-247 Q
Keimig, r	821 2220478*	50-289 Q	KINDER, E T	8212140227	50-443 Q	KOMES,J M	8212140092	TOPREP
KEIMIG,R R KEIMIG,R R KEISER,H W KEISER,H W KEISER,H W	8212290492* 8212300141 8212030041 8212030173 8212080295	50-193 Q 50-269 F 50-387 8 50-387 8 50-387 8	KINDER.E T KINDER.E T AINDER.E T KINDER.E T KINO.A P	8212140234 8212160281 8212230346 8212230348 8212270066	50-443	KONKLIN, JE KONKLIN, JE KONKLIN, JE KONKLIN, JE	8212080407* 8212100200* 8212100203* 8212100242* 8212270414*	50~546 0 80~367 0 50~341 0 50~483 0 50~546 0
KEISER, H W KEISER, H W KEISER, H W KEISER, H W KEISER, H W	8212080382 8212080362 8212080362 8212080320	50-387 S 50-387 S 50-387 S 50-387 S 50-387 S	KIND, L L KINNEY, W W KINTNER, L L KINTNER, L L	8212220265 8212030016 8212270472* 8212270004 8212270031	NUREG 70-2792 50-193 Q 50-358 A 50-341 A	KONKLIN, JE KOON, AR KOON, AR KOON, AR	8212290417* 8212030202* 8212090460* 8212150091* 8212150122*	50-440 0 50-395 9 50-395 9 50-395 9
HEISER, H W	8212140135	50-387 8	KINTNER,L L	8212270044	50-341 A	KOON, A R	8212220500*	50-995 5
KEISER, H W	8212140182	50-387 8	KINTNER,L L	8212290510	50-341 A	KOGI A, B	8212160457	40-8027
KEISER, H W	8212140258	50-387 8	KIRBY,L J	8212220523	RES	KOT, C A	8212130147	Nureg
KEISER, H W	8212140268	50-387 8	KIRK,W F	8212150264	70-371	KOVACK, T J	8212030273*	50-254 f
KEISER, H W	8212210052	50-387 8	KIRK,W F	8212270541	70-371	KOWALCZUK, A D	8212270137*	Fria
KEISER, H W	8212210236	50-387 S	KIRKMAN, R W	8212160140#	40-6500	KRATZKE,R T	8212170020*	70-1143
KEISER, H W	8212210343	50-387 S	KIRKMAN, R W	6212160432#	40-6500	KRATZKE,R T	8212230141*	70-1143
KEISER, H W	8212280403	50-387 S	KIRKMAN, R W	8212160436#	40-6500	KRAUBE,D F	8212170237*	50-314 8
KEISER, H W	8212280465	50-387 S	KIRKMAN, R W	8212160466#	40-6500	KRAUBE,L L	8212070116*	50-259 8
KEISER, H W	8212270441	50-387 S	KIRKMAN, R W	8212160471#	40-6900	KRECHTING,J E	8212010225*	50-275 8
Keith, H	8212210274*	50-333 E	Kirsch, DF	8212040159*	50-361 0	KRECHTINO, JE KRECHTINO, JE KRECHTINO, JE KRECHTINO, JE KRESB, TS	8212270296	50-275 P
Keith, H	8212210425*	50-333 S	Kirsch, DF	8212040170*	50-362 0		8212280160	50-275 P
Kelley, J. L	8212010187*	FOIA	Kirsch, DF	8212040241*	50-275 0		6212270231	50-275 P
Kelley, J. L	8212020336	50-400 G	Kirsch, DF	8212040344*	50-275 0		8212270458	50-279 P
Kelley, J. L	8212060135	50-413 G	Kirsch, DF	8212130245*	50-362 0		8212130135	NUREG
KELLEY, R H	8212270204*	50-237 P	Kirsch, D F	6212170374*	50~204 0	KRICH, R M	8212100248	50-255 \$
KELLY, E	8212060079	50-443 S	Kirsch, D F	6212170397*	50~361 0	KRIEGER, R W	8212020250	50-206 F
KELLY, J A	8212150049*	50-112 Q	Kirsch, D F	6212290035*	50~204 0	KRIEGER, R W	8212170158	50-206 P
KELLY, J L	8212270226	50-413 G	Kirsch, D F	6212290042*	50~206 0	KRIEGER, R W	8212200043	50-206 P
KELLY, J W	8212160426	71-5086	Kish, J N	62122100339*	50~461 0	KRIEM, R W	8212280426	50-483 F
Kerra'm a Kerra'w a Kerra'w a Kerra'a m	8212270406 8212270537 8212220021 8212040276* 8212210123*	70-27 70-27 RES 50-204 P 50-275 S	KIBIER Kibter, H Kibter, H Kister, H Kister, H B	8212210417 8212030128* 8212140140* 8212150227 8212030078*	50-286 S 50-286 Q 50-247 Q 50-410 Q 50-333 Q	KRUG, H KUCZYNSKI, L A KUCZYNSKI, L A KUCZYNSKI, L A	8212090213* 8212080342* 8212080372* 8212080378* 8212290117*	50-387 G 50-387 S 50-387 S 50-387 S 50-387 R
KELLY.W J	6212270218#	50-275 R	KISTER, H B	8212140495* 8212090336* 8212020277 821209093	50-410 Q	KUNIHIRO, D M	8212080041*	FOIA
KEMPER,J S	8212100070	50-352 F	KLEINSORGE, W P		50-387 Q	KUNIHIRO, D M	8212080095*	FOIA
KEMPER,J S	8212170315	50-277 P	KLINE, C		PRM	KURTZ, R J	8212010483	RES
KEMPIAK,A J	8212080662	50-373 P	KLINE, J R		50-483 Q	KURTZ, R J	8212300137	RES
KENNEDY.D H	6212130247	50-255 R	KLINE, J R		50-440 Q	LACEY, W S	8212300419	50-334 8
KENNEDY, R P KENNETT, R J KENNY, T J. KENT. E E KENYON, B. D.	8003070798* 6212270534 8212030128* 6212290049* 6212290096*	50-237 P RES 50-286 Q 50-206 Q 50-307 Q	KLINE, JR KLINE, JR KLINE, JR KLINE, JR	8212130191 8212130197 8212150026 8212150041 8212230351	50-266 G 50-483 G 50-483 G 50-440 G 50-440 G	LACEY, W 6 LACEY, W 6 LACEY, W 6 LACEY, W 5 LACEY, W 5	8212080451 8212080524 8212140174 8212150020 8212150025#	50-334 8 50-334 8 50-334 5 50-334 9 50-334 5
KENYON, B D. KENYON, T J KEPPLER, J G KEPPLER, J G, KEPPLER, J G	8212270115 8212010117 8212020347 8212030053 8212030178	50-387 R 50-390 A 50-255 G 50-254 G 50-10 G	KNAPP, M R, KNAPP, M R KNJCELEY, J R KNICELEY, J R KNIGHT, J P	8212010003 8212230118 821206080* 8212280220* 8201180567*	WASTE MOT WASTE MOT 50-346 Q 50-10 Q 50-255 P	LACEY, W S LACEY, N S LACEY, W S LACEY, W S	8212180075 8212150078# 821229033 <i>9</i> 8212290404 8212290439	50-334
KEPPLER,J G	8212060050	50-295	Knighton, o w	8212010175	50~382 E	Lafayette: I C	8212230241	50-247 G
KEPPLER,J G	8212060249		Knighton, o u	8212010411	50~382 F	Laggart.m H	8212210460*	50-219 G
KEPPLER,J G	8212060250*		Knighton, o u	8212080204*	50~528 A	Lagiewski.j S	8212060206*	50-317 B
KEPPLER,J G	8212060320		Knighton, o u	8212080527	50~443 M	Lagiewski.j S	8212160270*	50-317 B
KEPPLER,J G	8212080274		Knighton, o u	8212080532*	50~443 M	Lainas.g C	8109230665*	FOIA
KEPPLER, J. O	8212080494	50-454 Q	KNICHTON, C W	8212080545	50~443 A	Lainas, g C	8212010400	50-311 P
KEPPLER, J. O	8212100221	50-266 Q	KNICHTON, C W	8212080558	50~400 E	Lainas, g C	8212020034	50-278 P
KEPPLER, J. O	8212140324	50-373 Q	KNICHTON, C W	8212080564	50~528 A	Lainas, g C	8212090004	50-275 P
KEPPLER, J. O	8212140335	50-358 A	KNICHTON, C W	8212130161	50~361 P	Lainas, g C	8212270041	50-287 P
KEPPLER, J. O	8212140359	40-2061	KNICHTON, C W	8212130162*	50~361 P	Lainas, g C	8212300138	50-254 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LAM, J R LANDGRAF, L C LANDR EQU P R LANE, V M LANKFORD, J B	8212140459 8212010147 8212280067 8212160304 8212090445*	50-261 P 50-341 K 50-354 R 50-352 G 70-1151	LEVIN, J J LEVIN, J J LEVIN, J J LEVIN, J J	8212140149* 8212070087 8212070087 8212070087 8212140439 8212140439	50-29 P 50-247 9 50-247 G 50-247 G 50-247 G	LINEHAM, J J LINEHAM, J J LINER, R T LINK, R E LINVILLE, J C	8212170459* 8212300017 8211220076* 8212100202 8212030078*	40-8728 40-8064 50-3 P 50-266 8 50-333 Q
LAREY, W S LARSON: C E LARSON: C E LARSON: R A LASATER: G T	8212290373 8212090352* 8212280325 8212060468 8212070345*	50-334 S 50-263 G 50-282 G NUREG 50-155 G	FEAINE' A W FEAIN' A A FEAIN' A A FEAIN' A A	8212140446* 8212140446* 8212210320 821210394* 8212160782*	50-247	TIBEOTO M A TIBEOTO M A TIBEOTO M A TIBEOTO M A	8212070438 8212070438 8212230274 8212230312 8212270120	ACRE ACRE 50-317 P 50-318 P 50-318 P
LASATER.O T LASATER.O T LASATER.O T LATURRE.V R LAUFR.R J	8212070345* 8212210292* 8212210292* 8212130370* 8212090188	50-155	Levine, J M Levine, J M Levine, J M Levine, J M Levine, J M	8212170453* 8212210514* 8212210539* 8212270143 8212280072	50-313 F 50-313 F 50-313 F 50-313 S 50-348 S	LIPPOLD.W J LIPBCHUTZ.G E LISBON.J LISENO.R LITERSKI!L A	8212270122 6212230241 6212160457* 8212060276* 6212130041*	50-318 P 50-247 9 40-5500 50-333 8 50-10 F
LAUFR.R J EAUNI.C H LAUR.S LAURENSON.J A LAURTY.J H	8212290188 8212280489* 8212020371* 8212070167 8212070455*	50-329 T 50-461 Q 50-335 S 50-322 G 50-298 P	Levine, 8 Levine, 8 Levine, 5 Levine, 8	8212270486 7811070327 8002240162 8003280100 8005281047	50-313	LITERSKI,L A LITTEL,E G LITTEL,E G LITTEL,E G	02122202024 8212160315* 6212160350* 8212160390* 8212160391*	50-10 F 40-6500 40-3265 FOIA FOIA
LAWTON, M D LAWTON, M D LAYFIELD, R L LAZARUS, W LAZARUS, W	8212230404 8212230411* 8212280024* 8212140043 8212140160*	40-8084 40-8084 70-146 50-412 5 50-334 G	LEVINE.8 H LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8212030010 8212030212 8212030226* 8212070018 8212070030*	50-5 P 50-257 Q 50-257 Q 50-395 Q 50-395 Q	LITTEL,E O LITTEL,E O LITTEL,E O LITTEL,E O	8212160435* 8212160510* 8212160525* 8212160541* 8212160552*	40-6500 40-2116 40-2116 FOIA FOIA
LAZARUS.W LAZARUS.W LAZO.L LEAR.G E LEASBURO.R H	8212140148 8212210089* 8212170410 8009170144* 8212090175*	50-219	LEWIS.R C LEWIS.R C LEWIS.R.C LEWIS.R C LEWIS.R C	8212070080 8212070166 8212070180= 8212070232 8212070246=	50-259 Q 50-280 Q 50-280 Q 50-413 Q 50-413 Q	LITTLE, B H LITTLE, B H LITTLE, M LITTLE, M	8212100203* 8212170253* 8212010381 8212010388 8212010395	50-341 G 50-341 G CONTRACT CONTRACT CONTRACT
LEASBURG, R H LEASBURG, R H LEASE, R S LEBLANC, I LEBU, C D	8212070218* 8212070220* 8212270288* 8212270388 8212270055*	50-280 Q 50-280 Q 50-316 R 50-267 P F01A	LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8212070282 8212070278* 8212070279* 8212070316* 8212070421*	50-416 Q 50-280 O 50-324 Q 50-416 Q	LITTLE, M LITTLE, M LITTLE, M LITTLE, M LITTLE, M	8212010403 8212010419 8212010425 8212010432 8212010433	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
LEBU, C D LEBU, C D LEBU, C D LEBU, C D LEBURCHTER, J L	8212270059* 8212270065* 8212270088* 8212270071* 8212220553*	FOIA FOIA FOIA FOIA CONTRACT	LEWIS, R C LEWIS, R C. LEWIS, R C LEWIS, R C LEWIS, R C	6212070423 8212070432 6212070444* 6212070456 6212070467*	50-302	LITTLE, M LITTLE, M LITTLE, W S LITTLE, W S LITTLE, W S	8212060405 8212080572 8212170087 8212170106 8212170148	CONTRACT CONTRACT 50-258 0 50-454 0 50-155 0
LEDDICK, R S LEDDICK, R S LEDDICK, R S LEDDICK, R S LEE, B S	8212280121 8212300075* 8212300274* 8212300324* 8212020010		LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8212270107* 8212270137* 8212270138* 8212270165* 6212270184*	50-250 0 50-250 0 50-261 0 50-261 0 50-260 0	LITILE, W 8 LITTLE, W 8 LITTLE, W 8 LITTLE, W 8	8212170154* 8212170205 8212170244 8212170247* 8212170300	50~155 Q 50~483 Q 50~341 Q 50~341 Q 50~10 Q
LEE, J C LEE, J C LEE, J Y LEE, K W LEE, K Y	8212060514 82122060514 8212220066* 8212270420 8212170276*	ACRS ACRS 50-461 T NUREG 50-250 P	LICITRA,E A LICITRA,E A LICITRA,E A LICITRA,E A LICKUS,R M	8212010448 8212080666 8212220063 8212270473 8212210340*	50-528 A 50-528 A 50-528 A 50-528 A 50-282 Q	LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S	8212270292 8212270334 8212270332 8212270346 8212270376	50-262 0 50-305 0 50-266 0 50-254 0 50-249 0
1 EE, D R LEE, D R LEE, D R LEC. 1 D LEC. T D	8212200092 8212200101* 8212290367 8212080149* 8212090539*	50-267 Q 50-267 Q 50-267 Q FOIA	LIDEN, E A LIDEN, E A LIDEN, E A LIDEN, E A LIDEN, E A	8212010149 8212010155 8212130192 8212130212 8212200020	50-272 P 50-272 P 50-311 P 50-272 F 50-272 Q	LITTLE,WS LITTLE,WG LIV.WC LIVERMORE,HH LIVERMORE,HH	8212270380* 8212270387 8212270534* 8212080573* 8212100240*	50-249 G 50-295 G 50-438 G 50-461 G 50-461 G
LEHMER.J LEIKEN.L LEIKEN.L EMPGES.T E LENPGES.T E	8212070471 8212210253 8212270238 8212140029 8212140406	RES 70-143 70-143 50-220 <i>R</i>	LIDEN.E A LIPSTONE.C LIDSTONE.C LIDSTONE.C LIEBERNAN.A	8212300304 8212130128 8212230079 8212300129 8212100120	50-272 F 40-8743 40-6622 40-6622 50-440 0	LLOYD, L L LO.T Y LO.T Y LO.T Y. LOBNER, P R	8212020251 8205240413* 8204270144* 8208030436* 8212130058	PR FOIA FOIA FOIA NUREO
LEMPGES.TE LEMPGES.TE LEMPGES.TE LEMPGES.TE LEMPAHAN, JJ	8212150213 8212200023 821220477 8212270416 8212070308	96 50-220 0 96 50-220 0 50-220 5	LIETZKE, M H LIMOGES, C LIMOGES, C. LINDER, F LIMDER, F	8212270441 8212060152* 8212150084* 8212030024 8212070110		LODGE, B. LOFY, R. A LOFY, R. A LOIS, L LOMANACO, L. M	8212100378 8212010016* 8212010021* 8212230248* 8212130357*	FDIA FDIA FDIA 50-29 P 50-286 F
LENTINE,F 0 LENTINE,F 0 LENTINE,F 0 LENTINE,F 0	8212040086 8212040219 8212070045 8212130035 8212130183	50-295 P 50-295 P 50-295 F 50-295 P	Linder, F Linder, F Linder, F Linder, F Linder, F	8212070152 8212140417 8212170204 8212220323 8212280057	50-407 P	LONG.B M LONG.F J LONG.F J LONG.F J LONG.F J	8212220240 8212290078* 8212290078* 8212290108* 8212290114*	50-440 0 50-250 0 50-250 0 50-250 0 50-250 0
LENTINE, F O LENTINE, F O LENTINE, F O LENTINE, F O LEONARD, J R	8212130231 8212210369 8212210454 8212220431 8212230083	50-295 P 50-295 P 50-295 F 50-295 P	LINDER, F LINDER, F LINDER, I LINDSEY, I LINDSEY, I D	8212280075 8212280253 8212270220 8212100117 8212230172	50-407 8 50-409 8 50-458 0	LONG.F J LONG.F J LONG.F J LONG.F.J	8212270129* 8212270129* 8212290148* 8212270170* 8212270170	50-280 G
LESI IE, W 0 LESSOR, L C LESSOR, L C LESSOR, L C LESSOY, R P	8212140524 8212130344 8212290312 8212300104 8212020324	PR * 50-298 F 50-298 R 50-298 S	LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8212280045 8212010056 8212010059 8212020001 8212030228	40-8064 40-8380 40-8681	LENG, J. LONG, J. A LONG, R. L LONG, T LONGENECKER, J	8212100235# 821210005* 8212130040* 8212280239* 8212010011	9 50-320 P 9 50-320 P 9 50-346 S 50-537 F
LESSY, R P LESSY, R P LESSY, R P LETSCHE, K J LEVIN, C	9212060020 821220136 8212290270 8212140463 8212100045	50-443 G 50-312 G 50-443 G 50-322 G	L INEHAN, J J L L, MAHBINI J L L, MAHBINI J L L, MAHBINI J	8212030235 8212030238 8212030244 8212030251 8212030264	40-8681 40-8691 40-8681	LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8212010144 8212010141 8212020262 8212020303 8212070226	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LONGENECKER, J	8212070243	50-537 A	MACDONALD. C E	8212130078	71-6717	MADSEN.G L	8212290431	50-267 F
LONGENECKER, J	8212070311	50-537 A	MACDONALD. C E	8212130107	71-7111	MADSEN.G L	8212290437*	50-267 P
LONGENECKER, J	8212140374	50-537 A	MACDONALD. C E	8212130114	71-9032	MADSEN.G L	8212290460	50-267 Q
LONGENECKER, J	8212150054	50-537 A	MACDONALD. C E	8212130134	71-9151	MADSEN.S H	8212080568*	50-267 A
LONGENECKER, J	8212150133	50-537 A	MACDONALD. C E	8212130136	71-6601	MAIFR.J E	8212080291	50-244 F
Longenecker, J Longenecker, J Longenecker, J Longenecker, J	8212150177 8212160200 8212170190 8212200077 8212200045	50-537 B 50-537 A 50-537 A 50-537 A 50-537 A	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8212130141 8212130142 8212140502 8212140505 8212140509	71-9094 71-9181 71-9180 71-9086 71-5907	MAIER, J E MAIER, J E MAIER, J E MAIER, J E MAIER, J E	8212060169 8212070074 8212070075* 8212070282 8212080384	50-244 B 50-244 P 50-244 P 50-244 P 50-244 P
Longenecker, J	8212210950	50-537 A	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8212140513	71-4909	MAIER.JE	8212140240	50-244 F
Longenecker, J	8212210053	50-537 A		8212140517*	71-4909	MAIER.JE	8212140404	50-244 P
Longenecker, J	8212230007	50-537 A		8212140012	71-9006	MAIER.JE	8212140408*	50-244 P
Longenecker, J	8212230237	50-537 A		8212140016*	71-9006	MAIER.JE	8212210454	50-244 P
Longenecker, J	8212230253	50-537 A		8212140020	71-170	MAIER.JE	8212220243	50-244 P
LONGENECKER, J	8212230262	50-537 A	MACDONALD, C E	8212140023*	71-170	MAIER, J E	8212280380	50-244 P
LONGENECKER, J	8212230263	50-537 A	MACDONALD, C E	8212140024	71-486	MALANG, S	6212270414	RES
LONGENECKER, J	8212230300	50-537 A	MACDONALD, C E	8212140028*	71-486	MALKANI, R	8212080583*	CONTRACT
LONGENECKER, J	8212230321	50-537 A	MACDONALD, C E	8212140032	71-9099	MALLANDA, J J	8212170379*	50-397 A
LONGENECKER, J	8212270185	50-537 A	MACDONALD, C E	8212140035*	71-9099	MALLORY, C H	8212130055	71-9151
LONGENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8212270229 8212270231 8212270248 8212270294 8212270302	50-537 A 50-837 A 50-537 A 50-537 F 50-537 A	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8212160038 8212160041* 8212160167 8212160177 8212160185*	71-6003 71-6003 71-6717 71-489 71-489	MALLORY, C W MALMROS, M H MALONEY, C MALBCH, M Q MALSCH, M G	8212150282 8212040391* 8212230241 8003310489* 8103120528*	71-9151 50-244 0 50-247 0 50-409 P FOTA
LONDENECKER, J LONGENECKER, J LONGENECKER, J LONGENECKER, J	8212300215 8212300248 8212300253 8212300277 8212300343	50-537 A 50-537 B 50-537 A 50-537 A 50-537 A	HACDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E MACDDNALD, C E	8212160727 8212160733 8212160738 8212160743 8212160748	71-4909 71-4909 71-4909 71-5939 71-9079	MALSCH.M G MANEATIS.O A MANGAN.C V MANGAN.C V MANGAN.C V	8207010072* 8212220225* 8212020102 8212020302 8212030050*	F01A 50-275 P 50-220 P 50-220 P 50-220 Q
LOTITO, E LOTITO, E H LOTITS, A L LOTITS, A L	821@220210# 8212220208 8212010484 8212020519 8212270512	50-317 R 50-317 R RES RES RES	MACDONALD, C E	8212160750 8212160755 8212160760 8212170001 8212170002	71-6574 71-5461 71-9151 71-5086 71-9151	MANGAN, C V	8212060204 8212080159 8212090106 8212090154 8212170266	50-220 F 50-220 P 50-220 F 50-220 P 50-220 P
LOVE, R B	8212170284*	50-483 Q	MACDONALD, C E	8212170005	71-9132	MANGAN, C V	8212270265	50-220 P
LOVENDALE, P C	8212030114	50-155 B		8212170010*	71-9132	MANGAN, C V	8212270353	50-220 P
LOVENDALE, P C	8212100023*	50-263 Q		8212220036	71-5469	MANNO, S F	8212030166	50-410 S
LOW, L D	8212160243*	40-4500		8212220041	71-4909	MANNO, S F	8212140093	50-410 S
LOWENTHAL, N	8212160371	FQIA		8212220518	71-488	MANNO, S F	8212140372	50-410 S
LUETT. U LUDHIG. W C LUDHIG. W C LUCTT. U	8212140478 8212280116* 8212280136* 8212060236 8212080524*	50-259 H 50-327 S 50-328 B 50-142 0 50-373 S	MACDONALD, C E	8212220526* 8212220531 8212220538* 8212230018 8212230036	71~408 71~407 71~407 71~9001 71~404	MANNO,S F MANSER,W C MANSER,W C MANSER,W C MANSER,W C	8212280363 8212080028* 8212070260 8212070469 8212130189	50-410 S FDIA 70-143 70-143 70-143
LUETT, W R LUKERS, L L LUNA, C R LUNDVALL, A E LUNDVALL, A E	8212080410* 8212220291 8212270010* 8212060071 8212060293*	50-373 S NUREO 50-305 F 50-317 P 50-317 Q	MACDONALD, C E	8212230039* 8212230132 8212270485 8212280020 8212280021*	71-484 71-5814 71-9073 71-9852 71-9852	MANSER, W C	8212150293 8212160072 8212160429 8212270124* 8212270544	70-143 70-143 70-143 70-143 70-143 70-143
LUNDVALL, A E	8212070054	50-317 P	MACDONALD, C E MACDONALD, P E MACDOUGALL, R MADDEN, W MADDEN, W	8212270098	71-9151	MANTELL, A N	8212230331	50-247 G
LUNDVALL, A E	8212130065	50-317 F		6212130113	NUREG	MANTELL, A N	8212230336*	50-247 G
LUNDVALL, A E	8212160384	50-317 Q		8212230133	Waste Mgt	MARCHAL, J	8212010189	XPORTLIC
LUNDVALL, A E	8212170252	50-317 P		8212230147*	50-247 G	MARCHESE, A R	8206220072*	FOIA
LUNDVALL, A E	8212170349	50-318 Q		8212210351*	50-309 G	MARGULIES, T	8212140476	NUREG
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	9212200088 8212210420 8212210447 8212280199 8212290338	50-318 P 50-317 P 50-317 P 50-318 P 50-318 G	MADDEN,W J MADDEN,W J MADEDA,T J MADISON,A MADBEN,G L	8212290479* 8212030090* 8212140414* 8212030028* 8212030151	50-219	Maringas, n Markey, e Markey, e J Marrack, d Marehall, j r	8212010519* 8212230276 8209150008* 8212160434 8212030066	50~352 A 50-247 U COMMISSION PR 50~368 S
LUNDY, R T	8212060427	NUREG	MADSEN, G L	8212070119	50-382 0	MARSHALL, J R	8212030977	50-313 8
LUNDY, R T	8212060441	NUREG	MADSEN, G L	8212070126	50-112 0	MARSHALL, J R	8212030147	50-313 P
LUNDY, R T	8212060451	NUREG	MADSEN, G L	8212070137	50-298 0	MARSHALL, J R	8212040087	50-313 0
LUNDY, R T	8212060455	NUREG	MADSEN, G L	8212070223	50-382 0	MARSHALL, J R	8212040242	50-313 P
LURIA, N O	8212210414*	50-322 E	MADSEN, G L	8212070255	50-267 0	MARSHALL, J R	8212040233	50-313 P
LUSIS.E	8212230309	50-341 @	MADSEN.Q L	8212100212*	50-298	MARSHALL, J R	8212070284	50-313 P
LYANS.JA	8212220249	NUREO	MADSEN.Q L	8212100213*		MARSHALL, J R	8212070311	50-313 F
LYNCH.JL	8212040042*	50-409 @	MADSEN.Q L	8212100234		MARSHALL, J R	8212140334	50-368 Q
MA.S M	7908140789*	50-219 P	MADSEN.Q L	8212100265		MARSHALL, J R	8212140481	50-313 Q
MACCREADY,P 8	8212040334*	40-8743	MADSEN.Q L	8212140157		MARSHALL, J R	8212150288+	50-313 F
MACDONALD, C E	8212100037	71-483	MADBEN, G L	8212150040	50-112	MARSHALL, J R	8212170113	50~313 P
MACDONALD, C E	8212100057	71-204	MADBEN, G L	8212200004		MARSHALL, J R	8212170215	50~368 P
MACDONALD, C E	8212100062#	71-206	MADBEN, G L	8212200025		MARSHALL, J R	8212210027	50~368 8
MACDONALD, C E	8212100066	71-370	MADBEN, G L	8212200074		MARSHALL, J R	8212210039	50~368 P
MACDONALD, C E	8212100069#	71-370	MADBEN, G L	8212200084		MARSHALL, J R	8212210117	50~368 S
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8212100420 8212100425 8212130001 8212130004 8212130010	71-6717 71-9081 71-9010 71-9089 71-5942	MADBEN, Q L MADBEN, Q L MADBEN, Q L MADBEN, Q L MADBEN, Q L	8212200074 8212200108 8212200125* 8212200125*	50-267 F 50-267 F 50-267 F 50-382 Q 50-382 Q	MARSHALLIJ.R MARSHALLIJR MARSHALLIJR MARSHALLIJR MARSHALLIJR	8212210166 8212210169* 8212210173 8212210257 8212230165*	50~313
MACDONALD, C E	8212130038	71-6347	MADSEN, Q L	8212210023	50-267 0	Marshall, J r	8212270187	50-368 S
MACDONALD, C E	8212130048	71-454	MADSEN, Q L	8212210167	50-267 0	Marshall, J r	8212280142	50-368 S
MACDONALD, C E	8212130074*	71-454	MADSEN, Q L	8212280374	50-382 0	Marshall, J, r	8212280224	50-313 F
MACDONALD, C E	8212130082	71-9156	MADSEN, Q, L	8212280409	50-298 0	Marshall, J r	8212280457	50-368 P
MACDONALD, C E	8212130087	71-9156	MADSEN, Q L	8212280427*	50-267 P	Marshall, J r	8212270168	50-313 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8212270174 8212270178* 8212270212 8212270214 8212270234 8212270321	50-313 R 50-313 Q 50-348 B 50-348 R 50-313 S	MATLOCK, R G MATLOCK, R G MATLOCK, R G MATLOCK, R G MATTHEWE, T P	8212040179 8212040289 8212210384 8212280443 8212280443	50-397 S 50-397 S 50-397 S 50-397 G 50-285 R	MCCANN, J F MCCANN, J F MCCLUBKEY, J P MCCLUBKEY, J P MCCONNELL, T	8212070158* 8212270468* 8212230258 8212100343 8212070353*	50-387 Q 50-387 Q 40-8511 WASTE MOT 50-247 P
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J S MARSHALL, R K	8212300052 8212300057 8212300088 8212130301 8212220265	50~368 S 50~368 S 50~368 S 50~445 K NUREO	D L'AILTAM L M'AILTAM L M'AILTAM L M'AILTAM L M'AILTAM L C'AOMITTAM	8212140337* 8212130364 8212280478* 8212280471* 8212030081	50-423 0 CONTRACT CONTRACT CONTRACT 50-312 8	MCCORKLE, 0 W MCCORMACK, 0 M MCCOY, R W MCCRACKEN, C MCCREE, W B	8212100147* 8212280030* 8212160316* 8212270038 8212230083*	FOIA 70-144 50-352 6 50-289 P 50-369 F
MARSHALL,U H MARSTON,R R MARSTON,R R MARTIN,J B MARTIN,J B	8212220197 8212090274* 8212090294* 8210150165* 8212100303*	50-327 G 70-1201 70-624 50-341 F 50-331 Q	MATTIMDE, J J MATTIMDE, J J MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J	8212030084 8212030110 8212040294 8212070220 8212070277	50-312 8 50-312 5 50-312 6 50-312 0	MCCRBRY, S L MCDERMOTT, D MCDERMOTT, D MCDDNALD, R J MCDUFFIE, M A	8212100271* 8212060114 8212100124 8212020194* 8212130181	50-298 Q CONTRACT CONTRACT CONTRACT 50-400 A
MARTIN. J B MARTIN. J B MARTIN. J B MARTIN. T J MARTIN. T J	8212220460 8212230382 8212270444 8212080502 8212160024	50-341 F Waste Mot Waste Mot 50-354 S 50-354 Q	L L, SOMITTAM L L, SOMITTAM L L, SOMITTAM L L, SOMITTAM L L, SOMITTAM	8212070410 8212130337 8212140351 8212140391 8212170198	50-312 0 50-312 F 50-312 P 50-312 P 50-312 F	HCDUFFIE,M A MCBUFFIE,M A MCGARRY,J H MCGARRY,J H MCGARRY,J H	8212160036 8212210422 8207180063 8212130230 8212130230	50-400 D 50-400 C 50-298 Q 50-413 Q 50-413 Q
MARTIN, T J MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8212270444* 8212010002 8212030018 8212030027 8212030030	50-354 Q PT21 50-220 Q 70-1100 50-217 Q	MATTIME, J J	8212170220 8212170255 8212170301 8212170319 8212210439	50-312 P 50-312 P 50-312 Q 50-312 P 50-312 V	McGarry, J. M McGarry, J. M McGarry, J. M McGarry, J. M McGarry, J. M	8212160261 8212160261 8212220232 8212220232 8212220237*	50-413 Q 50-413 Q 50-413 Q 50-413 Q 50-413 Q
MARIIN, T T MARIIN, T T MARIIN, T T MARIIN, T T MARIIN, T T	8212030034 8212030035 8212030045 8212030087 8212030093	50-220 G 50-244 G 50-336 G 50-387 G 50-387 G	MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J MATTSON, R J MATTSON, R J	8212220241 8212280233 8212300353* 8212070005* 8212130287*	50-312	MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J K	8212220239* 8212270244 8212270244 8212270321 8212270321	50-413 Q 50-413 Q 50-413 Q 50-413 Q 50-413 Q
MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8212030141 8212030144 8212030165 8212030167 8212030193	50-247	MATISON,R J MAUPIN,M W MAUPIN,M W MAURIN,L V MAURIN,L V	8212220475* 8212280122 8212280135 8212280436 8212030036	50-275 P 50-338 0 50-338 0 50-382 5 50-382 8	P C YROUAGOM P C LYHOUAGOM P C LYHOUAGOM P C YROUAGOM	8212020033 8212020050 8212020058 8212020138 8212090074	50-416 8 50-416 8 50-416 9 50-416 8 50-416 8
MARIIN.T T MARTIN.T T MARTIN.T T MARTIN.T T NARTIN.T T	8212030195 8212030215 8212040187 8212040209 8212040215	50-293	MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8212030055 8212070228* 8212070203 8212100002 8212140395	50-382 8 50-382 0 50-382 F 50-382 A 50-382 S	P L YASONDON ON A C L YASONDADON	8212090078 8212090110 8212090131 8212090151 8212090159	50-416 8 50-416 8 50-416 8 50-416 8 50-416 5
MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8212060234 8212060235 8212060270 8212070120 8212070144	50-322	MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V MAURIN, L V	8212150042 8212200127* 8212200129* 8212200166 8212210172	50~382 F 50~382 G 50~382 G 50~382 S 50~382 S	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8212070177 8212070171 8212070270* 8212070303* 8212070310*	50-416 8 50-416 8 50-416 0 50-416 0 50-416 0
MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8212100038 6212100059 6212100073 8212140208 6212140225	50-334 Q 50-387 Q 50-219 Q 50-245 Q 50-333 Q	MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, C. V	8212210230 8212210281 8212270015* 8212270130 8212270138	50-382 6 50-382 5 50-382 F 50-382 8 50-382 9	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8212090324 8212100297 8212170137 8212170209 8212170222	50-416 S 50-416 S 50-416 S 50-416 !
MARTIN, T T MARTIN, T T MARIIN, T T MARIIN, T T MARIIN, T T	8212140251 8212140303 8212150121 8212160397 8212210129	70~2895 70~2487 50~333	MAURIN, L. V HAURIN, C. V MAURIN, L. V MAURIN, L. V MAURIN, L. V	8212270166 8212270166 8212270257 8212280143 8212280169	50-382 A 50-382 S 50-382 B 50-382 S 50-382 S	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8212170263 8212170313 8212170334 8212200103 8212210155	50-416 50-416 50-416 50-416 n 50-416 S
MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T MARTIN, T T	8212210263 8212210349 8212210376 8212220350 8212220383	50-309	MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, L. V MAURIN, L. V	8212280203 8212270245 8212300162 8212300178 8212300217	50-382 S 50-382 Q 50-382 A 50-382 S 50-382 S	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8212210179 8212210191 8212210212 8212210367 8212210375	50-416 8 50-416 9 50-416 9 50-416 9 50-416 9
MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8212220400 8212220434 8212230330 8212270252 8212280200	50-387 Q 70-135 70-1143 70-820 50-317 Q	MAURIN, L V MAURIN, L V MAUSSHARDT, D II MAUSSHARDT, D B MAY, E L	8212300288 8212300310 8212100174 8212100474 8212270258*	50-382 8 50-382 5 40-2061 40-2061 50-29 5	WCGVNGHA' 1 b WCGVNGHA' 1 b WCGVNGHA' 1 b WCGVNGHA' 1 b	8212270147 8212280054 8212280080 8212280150 8212280177	50-416 P 50-416 8 50-416 8 50-416 8 50-416 5
MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T NARTIN.T T	8212280385 8212270351 8212270360 8212270368 8212270375	50-320 Q 70-820 70-1100 40-8410 50-244 Q	May, f L McAlpine, e, J McAlpine, e, J McAlpine, e, J McAlpine, e, J	8212290316* 8212090265* 8212090276* 8212090276* 8212090340*	50-29 8 70-824 70-1113 70-1151 70-1201	KCGVAGHA'7 b WCGVAGHA'7 b WCGVAGHA'7 b WCGVAGHA'7 b	8212280174 8212280241 8212280308 8212280312 8212280312	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8
MARTIN.T T MARTIN.T T MARTIN.T T MASON.C C MASON.C C	8212290408 8212290435 8212290477 8212290159 8212290164*	50-219 0 50-272 0 50-219 0 50-327 R 50-327 R	Mcalpine, E. J Mcalpine, E. J Mcalpine, E. J Mcalpine, E. J Mcalpine, E. J	8212070413* 8212070416* 8212070445* 8212070451* 8212070537*	70-143 70-143 70-1151 50-332 Q 70-143	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	6212280344 8212280377 8212280384 8212280402 8212280458	50-416 8 50-416 8 50-416 8 50-416 8 50-416 \$
MASSARO,S A MASTERSON,R E MATERS,B R MATHIS,C J MATHIS,C J	8212130140 8212210327* 821213333 8212060198 8212060210	NUREG 50-243 P 50-341 A 50-293 S 50-293 S	MCALPINE, E J MCBRIDE, L M MCGABE, L M MCCABE MCCABE, E	8212150088 8212210112* 8212270374* 8212040305 8212020003	70-143 50-267 R 50-267 R 50-317 S 50-317 Q	P L,YHDUADOM PL,YHDUADOM L,YHDUADOM PL,YHDUADOM PL,YHDUADOM	8212280466 8212300037 8212300084 8212300114 8212300186	50-416 9 50-416 9 50-416 9 50-416 9 50-416 9
MATHIS, C J MATHIS, C J MATHIS, C J MATHOCK, R O MATHOCK, R O	8212210067 8212210148 8212210249 8210270016* 8212060021	50-293 B 50-293 B 50-293 B 50-397 A 50-397 G	McCabe, e c McCabe, e c McCabe, e c McCabe, e c McCabe, e c	8212070158* 8212070269* 8212100013* 8212160491* 8212270468*	50-387 Q 50-352 Q 50-317 Q 50-277 Q 50-387 Q	MCGAUGHY, J P MCGOVERN, J J MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R	8212300222 8212160245 8212030232* 8212070034* 8212070206*	50-416 8 70-487 50-259 0 50-395 0 50-338

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGURREN, H J	8212070124* 8212070185* 8212150070 8212150143* 8212170174	50-259 0 50-280 0 50-321 5 70-143 50-247 0	MIKAMI.H MILHOLLIN.O L MILHOLLIN.O L MILLER,B K MILLER,D E	8212010133* 8212070160 8212070234 8212020126 8212060197*	XPORTLIC 50-237 0 50-341 0 RES 50-254 0	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8212100270 8212140047 8212140087 8212140141 8212140164	50-370 \$ 50-439 \$ 50-370 \$ 50-390 \$ 50-390 \$
McGurren, H J McHugh. M McInnes, I D McInnes, I D McInnes, I D	8212280014 8212230276 8212210330* 8212210333* 8212210337*	50-247 Q 50-247 U 50-263 P 50-263 P 50-263 P	MILLER, D E MILLER, D E MILLER, O N MILLER, H J MILLER, H J	8212080294* 8212280042* 8212130123 8212010045 8212010302	50-295 C 50~295 Q NUREG WASTE MGT WASTE MGT	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8212140371 8212140376 8212140415 8212140415 8212150079 8212150136	50-439 5 50-390 5 50-438 5 50-438 5 50-390 5
MCINTEER, WA MCKFLVY, GA MCKELVY, GA MCKENNA, KJ MCKENNA, KJ	8212270042* 8212220415 8212220421* 8212230152 8212270145	50-287 P 50-287 F 50-287 F NUREO NUREO	MILLER, H J MILLER, H J MILLER, H J MILLER, J J MILLER, J R	8212020114 8212020132 8212020201 8212080041* 8212020310*	WASTE MGT WASTE MGT WASTE MGT FOIA 50-254 G	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212170188* 8212170134 8212170157 8212170160 8212170221	50-259 F 50-260 P 50-430 S 50-438 S
MCKEOWN,L H MCKEOWN,L M MCKIBBEN,J C MCKINNEY,C J MCKINNEY,C J	8212030175* 8212290443* 8212080331 8212030064* 8212030171*	50-213	MILLER. J R MILLER. J R MILLER. J R MILLER. J R MILLER. J R	8212060191 8212080282 8212090325 8212090343 8212090387	50-254	MILLB, L. M MILLB, L. M MILLS, L. M MILLS, L. M MILLB, L. M	8212170229 8212170236 8212170239 8212170259 8212170318	50-259 F 50-327 P 50-327 P 50-327 F 50-327 G
MCKINNEY, C J MCKINNEY, C J MCKINNEY, C J MCKINNEY, C J MCKINNEY, C. J	8212030199* 8212150681* 8212150100* 8212200115* 8212220337*	50-395 S 50-395 S 50-395 S 50-395 S 50-395 S	MILLER, J R MILLER, J R MILLER, J R MILLER, J R MILLER, J R	8212140394 8212140399* 8212280058 8212280091 8212280214	50-151	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212170388 8212200001 8212200017 8212200052 8212210026	50-327 R 50-370 S 50-390 S 50-518 E 50-390 S
MCKINNEY, C J MCKINNEY, C J MCKINNEY, E MCKINNEY, T R MCLEAREN, T	8212220384* 8212220414* 8212230276 8212290104* 8212020387	50-395 8 50-395 8 50-247 U 50-266 P CONTRACT	MILLER,L K MILLER,L K MILLER,L K MILLER,L K MILLER,M E	8212230271* 8212270280* 8212280066 8212280068* 8212070075	50-272 R 50-311 R 50-272 R 50-272 R 50-445 G	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212210122 8212210217 8212210254 8212210354 8212210360	50-438 S 50-390 S 50-438 S 50-390 S 50-391 0
MCLEAREN, T MCLEAREN, T MCNAMARA, A E MCNEILL, C A MCNEILL, C A	8212020402 8212040502 8212270166# 8212040071 8212040223	CONTRACT CONTRACT 50-244 R 50-333 S 50-333 S	MILLER, M E MILLER, R MILLER, R MILLER, R P. MILLER, W H	8212230353 8212020308 8212140009 8212140608* 8212090275*	50-445 G 50-254 G 71-489 CONTRACT 50-389 Q	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212210354 8212210431 8212210445 8212210451 821222041 <i>9</i>	50-438 S 50-390 S 50-390 S 50-390 E 50-438 S
MCNEILL.C A MCNEILL.C A MCNEILL.C A MCNEILL.C A	8212060292 8212080374 8212080394 8212130081 8212140236*	50-333 6 50-333 0 50-333 8 50-333 R 50-333 G	MILLER.W H MILLER.W O MILLER.W O MILLER.W O MILLER.W O	8212090321* 8212020157 8212070463 8212080026 8212150296	50-324 Q 50-206 P 50-331 P 50-305 P 50-324 P	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8212220424 8212220485 8212270192 8212270262 8212270265	50-390 S 50-390 B 50-259 P 50-390 A 50-390 A
MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,R MCNEILL,W M	8212150126* 8212210268 8212210415 8212140277* 8212070122*	50-333 Q 50-333 B 50-333 B 50-275 P QA999	MILLER, W O MILLER, W O MILLER, W IV MILL IGAN, M H MILLS, L M	8212220515 8212220530 8212070340* 8212160065 8212020107	50-313 P 50-302 0 50-155 0 50-322 S 50-438 S	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8212280064 8212280095 8212280100 8212280210 8212280275	50-438 S 50-259 P 50-438 S 50-438 B 50-259 P
MCNEILL. W M MCPHERSON, R MEDFORD, M O MENDEZ, R MENDONGA, M M	8212300243* 8212280104* 8212070179 8212270318* 8212040159*	QA999 50-260 S 50-361 P 50-456 Q 50-361 Q	HILLS, L # HILLS, L # HILLS, L # HILLS, L # HILLS, L #	8212020137 8212020139 8212020149 8212020162 8212020298	50-438 & 50-438 & 50-438 & 50-438 & 50-390 &	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212280305 8212280328 8212280340 8212280355 8212280358	50-438 S 50-438 S 50-438 S 50-390 S 50-438 S
MENDONCA, M M MERRIWEATHER, N MESSINGER, R W METCALFE, L J MEYER, O	8212060261* 8212070355* 8212230241 8212220282 8212270446	50~275 G 50~400 G 50~247 G NUKEG TOPREP	HILLS: L M HILLS: L M HILLS: L M HILLS: L M	8212030158 8212030071 8212030071 8212030078	50-390 B 50-390 B 50-259 R 50-43B B 80-43B B	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	821 2280437 821 2290354 821 2300006 821 2300293 821 2300351	50-438 K 50-327 P 50-438 S 50-327 P 50-327 P
Meyer, k a Meyer, k a Michaels, t s Michaels, t s Michels, s e	9212230374* 8212230377* 8101080116* 8212080072* 8212230241	50-331 F 50-331 F 50-285 P FOIA 50-247 G	HILLS, L M MILLS, L M MILLS, L M MILLS, L M	82120302204 8212040023 8212040041 8212040070 8212040074	50-259 0 50-327 P 50-327 P 50-390 E 50-327 P	MILLS, L M MINECK, D L MINECK, D L MINECK, D L	8212300357 8212170311* 8212060221 8212140134 8212140142	50-327 P 50-331 P 50-331 S 50-331 R 50-331 S
MIDURA, H J MIDURA, H J. MIDURA, H J MIDURA, H J MIDURA, H J	8210210078 8212030117 8212060165 8212060202 8212060291	50-211	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	82120600B1 8212070058 8212070142 8212070176 8212070180	50-390 A 50-390 8 50-390 S 50-327 P 50-327 F	Hineck, D. L. Hineck, D. L. Hineck, D. L. Mineck, D. L. Mineck, D. L.	8212140332 8212210033 8212210070 8212210209 8212210382	50-331 \$ 50-331 8 50-331 8 50-331 R 50-331 8
Hidura, H. J. Midura, H. J. Midura, H. J. Midura, H. J. Midura, H. J.	8212040302 8212040309 8212080354 8212080434 8212140053	50-272 8 50-272 8 50-272 8 50-311 8 50-272 8	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8212070184 8212070267 8212070288 8212070291 8212080108*	50-390 A 50-390 S 50-259 P 50-390 A 50-259 F	Minfok, D L Miner, B Miner, B Miner, B Miner, B	8212280454 8212010329 8212080110 8212170078 8212270283	50-331 8 50-302 P 50-312 P 50-312 P 50-312 P
HIDURA, H J MIDURA, H J MIDURA, H J MIDURA, H J MIDURA, H J	8212140074 8212140079 8212140079 8212140048 8212140381	50~272 8 50~311 8 50~311 8 50~311 8 50~311 8	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8212080373 8212070054 8212070055 8212070083 8212070092*	50-327 P 50-390 S 50-518 A 50-259 P 50-259 d	Minde, W J Mindek, J R Mindek, J R Mindek, J R Mindek, J R	8212220282 8212010171 8212010171 8212140428 8212140428	NUREG 50~341 0 50~341 0 50~341 0 50~341 0
MIDURA: H. J MIDURA: H. J MIDURA: H. J. MIDURA: H. J. MIDURA: H. J.	6212140379 8212220300 8212220381 6212220395 8212220420	50-311 8 50-272 8 50-311 8 50-311 8	MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8212070077 8212070150 8212070160 8212070163 8212070165	50-328	MINOQUE,R B MINOQUE,R B MINOQUE,R B MINOQUE,R B MINOQUE,R B	8103250465 8104170658 8104170664 8109280378 8111130045	res res res res res
MIDURA,H J MIDURA,H J MIDURA,H J MIGHT,A. MIKANI,H	821220433 8212230246 8212270274 8212200122* 8212010120*	50-311	MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8212070170 8212070347* 8212070365* 8212070461* 8212070541	50~327 G	Mindrue, R B Mindrue, R B Mindrue, R B Mindrue, R B Mindrue, R B	8201150075 8201180563 8201220290 8202260369 8207200458	res res res res res

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MINUGUE, R D MINUGUE, R B MINUGUE E MIRAGLIA, F MIRAGLIA, F	8211120212# 8212270240 8212260486 8211160015# 8211110483#	REVIEW GRP RES NUREG 50-237 P 50-289 P	MOSFLEY, N C MOSFLEY, N C MOSFLEY, N C MOSFLEY, N C	8212290100* 8212290101* 8212290113* 8212290121* 8212290133*	50-250 0 50-250 0 50-250 0 50-261 0 50-261 0	MYERS.R V NADEL.M NAIDU.K NAIDU.K R NARDI.A J	8212140419 8212280334 8212270318* 8212170253* 8212150262	50-522 A 50-483 J 50-456 Q 50-341 0 70-1143
MIRAGLIA.F J MIRAGLIA.F J MITCHELL.D G MITCHELL.D O MITCHELL.D O	8212280434 8212300196 8212030047* 8212030179* 8212080303*	50-409 P 50-447 A 50-387 S 50-387 S 50-387 S	MUSFLEY, N C MOSFLEY, N C MOSLAK, T MOSLY, T MOTI, W E	8212290144* 8212290158* 8212140319* 8212170311* 8212010025	50-261 0 50-261 0 50-320 0 90-331 P WASTE MOT	NARDI.A J NARDI.A J NARDDCI.P B NARDDCI.P B NARDDCI.P B	8212150340 8212220124 8212140176* 8212140434* 8212200012*	70-1151 70-1143 50-369 5 50-369 5
MITCHELL.D G MITCHELL.D G MITCHELL.D G MITCHELL.D G MITCHELL.D G	8212080328# 8212080386* 8212140138* 8212140189* 8212140261*	50-387 8 50-387 8 50-387 8 50-387 8 50-387 8	MGT), W E MDUNT, D K NDWKY, W R NROCZKA, E J NROCZKA, E J	8212220010 8212020251 8212010468 8212030180 8212030180	40-6500 PR XPORTLIC 50-245 S 50-245 S	NARDOCI, P B NARDOCI, P B NARDOCI, P B NARNOW, L NARNOW, L	8212210154* 8212280374* 8212300076* 8212070136* 8212100064*	50-367 6 50-369 8 50-369 8 50-322 0 50-387 0
MITCHELL, D G	8212140325* 821221005/* 82122102414 821221024/* 821221034/*	50-387 S 50-387 S 50-387 S 50-387 S 50-387 S	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	821 203020 1 821 203020 1 821 203022 7 821 203022 7 821 208041 4	50-334 8 50-334 8 50-334 8 50-334 8 50-334 8	NARVER,R B NEAGY,P NEEL,A W NEILD,R NEISLER,J H	8210170510* 8212280051 8212080201 8212270430* 8212100242*	50-247 F RES 50-537 D 50-220 S 50-483 G
MITCHELL, D. G MITCHELL, D. G MOBILEY, M. H MOEGGENBERG, D MOEGGENBERG, D	8212280468* 8212270446* 82120703734 8212210120* 8212210178*	50-387 S 50-387 S 70-143 50-368 S 50-368 S	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	821 2080 41 4 821 2080 44 5 821 2080 44 5 821 2160 358 821 2160 358	50-336 8 50-245 8 50-245 8 50-245 8 50-245 8	NEJFELT, O M NELSON, G B NELSON, G B NELSON, P R NELSON, R H	8212150085 8212070071* 8212210246* 8212160161* 8212210170*	50-302 5 70-1359 70-25 40-4500 50-309 5
MDEGGENBERG, D MDEGGENBERG, D MDEGGENBERG, D MDFFETT, A T MDHR, C L	8212210240+ 8212280144* 8212300042* 8212230274 8212230265	50-368 S 50-368 S 50-368 S 50-247 U NURCO	MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8212210227 8212210227 8212270137 8212270137 8212270224	90-334 8 50-336 8 50-336 R 50-336 R 50-245 R	NELSON, R H NELSON, R L NELSON, T A NELSON, T A NELSON, T A	8212290306* 8212100149* 7909180332* 8010220355* 8112160327*	50-307 8 50-305 0 50-244 P 50-245 P 80-213 P
MON) GOMERY, D M MON) GOMERY, D M MON] GOMERY, J L MODKE, D E MOORE, D E	8212070288* 8212070521* 8212200033* 8212070185* 8212150086	50-261 0 50-338 0 50-285 0 50-280 0 50-413 5	MROCZKA, E J MUCHA, E MUCLLER, C J MUCH ESTFIN, L D	8212290224 8206160113* 8212070431 8212070431 8212140380*	50~245 R 50~271 P ACRS ACRS 50~537 A	NELSON, T A NELSON, T A NELSON, T A NERSES, V NERSES, V	9203010313* 8205040451* 8210260403* 8212010439 8212090002	FOIA FOIA 50-204 P 50-389 A 50-389 A
MODICIJE NOOKEJE NOOKEJE MODICIJE MODICIJE	0212150116 6212170169 6212210267 6212210332 6212260011	50-247	MULTURD, T J MULTURD, T J MULTURD, T J MULTURD, T J MULTURD, T J	821221032/* 62:2210330* 62:2210333* 82:2210337* 62:2210342*	50-263 P 50-263 P 50-263 P 50-263 P 50-263 P	NERGES, V NERGES, V NEUMANN, M R NEUMANN, M R NEUMAN, J R	8212170408 8212220153 8212030284 8212230183 8212280279	50-369 F 50-389 A 40-8380 40-8380 50-498 Q
MODRE, R D MODRE, R R MODRE, R N MODRE, R N	8211110457# 8212300179# 8212010086 8212080225 8212280427	50-440 A 50-10 F XPORTLIC XPORTLIC XPORTLIC	HEILLAUER, JR MULLING, K MUHA, E MUHA, F HURÐÐCK, RJ	8212100150 8212070271* 6212070337* 6212070337* 6212090375*	1 t c 50-259 8 50-155 0 50-155 0 50-219 8	NEWMAN, JR NEWMAN, JR NEWMAN, JR NEWMAN, NM NEWMAN, MM	6212280279 6212280262 6212280262 7911150252* 8005070798*	50-498 0 50-498 0 50-498 0 50-237 P 50-237 P
MOORE.R N MOORE.R N MOORE.R N MOORECAD.A J MOOREAU.W N	8212230428 8212230431 8212300172 8212360460 8212140362	XPORTLIC XPORTLIC XPORTLIC NUREG 50-217 J	MURPHY, B H MURPHY, C S MURPHY, C S MURPHY, J D MURPHY, J D	8212100048 8212270033 8212270232 8212140131* 8212140193*	50-329 T Nureo Nureo 40-4500 40-4500	NICHOLSON, W O NICHOLSON, N A NO. Y C NO. Y C	8212140464 8212160773 8212060258* 8212060062* 8212070346*	NUREO NUREO 50-322 Q 50-409 Q 50-344 R
MORE HOUSE, J. H. HORGAN, C. MORCAN, C. HORGAN, C. HORGAN, C.	821128096* 812020318 8212020318 8212060103 8212060104	50-3 P 50-247 0 50-247 0 50-247 0 50-247 0	D C. YMMRUM D C. YMMRUM D M. YMMRUM D M. YMMRUM D U. YMMRUM	8212140264* 8212160464* 8212030112* 8212070133* 8212150174	40-6500 40-6500 50-265	NIX+H C NIELBON-K K NIELBON-K K NIELBON-K K	9212270204* 8212010115 8212220341 8212030023* 8212020272	50-344 R NUREO NUREO 50-220 0 50-366 6
Horgan, C Horgan, C Horgan, C Horgan, C Horgan, C	8212140423 8212140423 8212140289 8212140289 8212140289	50-247 0 50-247 0 50-247 0 50-247 0 50-247 0	MURICAY, B MURICAY, B MURICAY, R. C MURICAY, R. C MURICAY, R. C	8212160233* 8212210250* 7708140421* 7708140784* 8005280555*	50-285 G 50-313 G 50-206 P 50-219 P 50-219 P	MIX.H C MIX.H C MIX.H C	8212030170 8212070277 8212070121 8212070140 8212070142	50-321 8 50-321 8 50-346 8 50-321 8 50-366 8
MORCAN, C MORGAN, C MORGAN, C MORCAN, C MORCAN, C MORCAN, C	821220378 8212280285 8212280285 8212300230 8212300230	50-247 0 50-247 9 50-247 9 50-247 9 50-247 9	MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8212100229 8212100281 8212100325 8212130144* 8212140107*	50-346	NIX, H C NIX, H C NIX, H C NIX, H C NIX, H C	8212090190 8212090202 8212090214 8212090247 8212090329	50-366 8 50-321 8 50-321 8 50-366 8 50-366 8
NDRGAN, W E MORGENSTERN, A MORIARTY, J II MORISI, A V MORISI, A V	8212270385# 8212070417 8212210341 8212260272# 8212100031	50-249 8 XPORTLIC 50-395 S 50-293 F 50-293 F	MURRAY, T D	8212170178 8212170282 8212280075 8212280234 8212280247	50-346 5 50-346 8 50-346 5 50-346 5 50-346 8	NIX'H C NIX'H C NIX'H C	8212070330 8212070377 8212070381 8212070384 8212070387	50-321 8 50-321 8 50-366 9 50-366 8 50-366 6
MORISI.A V MORISI.A V MORISI.A V MORNILL.P J MORRIS.P A	621213003/ 9212140139 6212210456 6212060364# 6212270220	50-243 F 50-243 P 50-243 Q 50-275 Q 50-322 G	MURRAY, T D MURRAY, T D MUSELER, N J MUSELER, D MUSELER, D	8212280281 8212270307 8212270324 8212020311 8212070371	50-346 8 50-346 R 50-322 0 50-282 8 50-263 P	NIX, H, C NIX, H C NIX, H C NIX, H C	8212090437 8212100264 8212100282 8212100311 8212140115	50-366 S 50-366 B 50-366 S 50-366 S 50-366 S
MORRISON, P MORTON, K. V MORTON, K. V MORTON, K. V MORTON, K. V	8212280188 8212040120* 8212100130* 8212100172* 8212270504*	SO-454 G CONTRACT CONTRACT CONTRACT CONTRACT	MUSGLE, B MUSGLE, D MUSGLE, D MUSGLE, D MUSGLE, D	8212080420 8212090057 6212090059* 8212090172 8212140244	50-282 P 50-243 F	NIX.H C NIX.H C NIX.H C	8212140269 8212140421 8212140433 8212150007 82121500014	50-321 8 50-346 8 50-366 8 50-321 8 50-321 8
MOSFLEY, II C MOSFLEY, II C MOSFLEY, II C MOSFLEY, II C MOSFLEY, II C	8212270064* 8212270073* 8212270082* 8212270087* 8212270070*	50-250 0 50-250 0 50-250 0 50-250 0 50-250 0	NUSCLE, D MUSCLE, D MUSCLE, D MUSCLE, D MUSCLE, D	8212140279 8212140344 8212170262 8212210270 8212210325	50-282 F 50-263 B 50-282 P 50-282 P 50-263 P	NIX.H C NIX.H C NIX.H C NIX.H C	82:215003: 82:2170092 82:2170:55 82:2170:46 82:2170353	50-321 B 50-321 S 50-321 B 50-321 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIX.H C NIX.H C NIX.H C NIX.H C	8212210083 8212210188 8212210446 8212280159 8212280160	50-321 S 50-321 S 50-366 S 50-366 S 50-321 S	NULSEN. B NULSEN. C K NUSSBAUMER. D A NUSSBAUMER. D A NUSSBAUMER. D A	8212100142* 8212100155* 8212010474 8212160070* 8212160077*	FOIA FOIA WASTE MOT FOIA 40-6500	ONIGHT, Y OPREA, G W OPREA, G W OPREA, G W ORDERS, W	82;2220509 82;2030;00 82;2270172 82;2270202 82;2270208	NUREO 50-498 S 50-498 S 50-498 S 50-249 Q
NIX'H C NIX'H C NIX'H C NIX'H C	8212280387 8212300058 8212300071 8212300078 8212300265	50-321	NUSSBAUMER, DA NUSSBAUMER, DA NUSSBAUMER, DA NUSSBAUMER, DA NUSSBAUMER, DA	8212160197* 8212160214* 8212160260* 8212160273* 8212160307*	40-6500 40-6500 40-6500 40-6500 40-6500	ORDERS, W J ORNSTEIN, P M OBBORNE, M F OSBORNE, M P OSTER, C A	8212090313* 8212230191 8212160549 8212270320* 8212270559	50-280 G HASTE HGT RES 50-445 G NUREG
NIX'H C NIX'H C NIX'H C NIX'H C	8212300271 8212300277 8212300284 8212300285 8212300287	50-321	NUSSBAUMER, D A NUSSBAUMER, D A NYKIEL, A O'BRIEN, J P O'NEILL, B	8212280016* 8212280017* 8212020285* 8212060171* 8212070111*	70-146 70-146 50-278 S 50-312 G 50-320 G	DITER,W M OWCAZARSKI,P C OWEN,T B OWSLEY,G F OZTUNALI,O I	8212100378* 6212300402 8212070346* 6212280404 6212280478*	FDIA RES 50-249 P 50-316 P CONTRACT
NIX.H C NIX.H C NIX.H C NIX.H C	8212300279 8212300323 8212300328 8212300327 8212300340	50-346 6 50-346 8 50-321 8 50-321 8 50-346 8	D'NEILL, B O'NEILL, B O'NEILL, J H O'REILLY, J P	8212140319* 6212220471* 8212210222 6212210222 8212080105*	50-320 0 50-289 0 50-400 0 50-400 G 70-143	PACE, P PAGE, M PAGE, M PAGE, M PAGE, M	8212270169* 8212070450 8212270080* 8212270099* 8212270133*	50-250 R CONTRACT FOIA FOIA FOIA
NIX,H C NIXON,W A NODNAN,V S NORDERHAUG,L R NORDERHAUG,L R	8212300344 6212070474 6211120491* 8212040228 6212090048	50-366 \$ 40-2061 HISC 50-361 Q 70-1359	G'REILLY, J P G'REILLY, J P G'REILLY, J P	8212090108* 821209011 8212090129 8212090129	50-259 0 50-324 0 50-259 P 50-324 0 50-302 F	PAGE,M PAGE,R G PAGE,R G PAGE,R G PAGE,R G	8212280043 8212010349 8212010372+ 8212010489 8212010497	CONTRACT 70-36 70-36 40-2051 70-371
NORTERHAUG, L R NORTERHAUG, L R NORTERHAUG, L R NORTERHAUG, L R NORTERHAUG, L R	8212090071* 8212090532 8212130143 8212170304 8212210240	70-1359 50-206 Q 50-312 Q 50-344 Q 70-25	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	6212090157 6212090161 6212090208 6212090285 6212090315	State Prog 50-338	PAGE,R G PAGE,R G PAGE,R G PAGE,R G PAGE,R G	8212010503 8212080045 8212080654 8212080671* 8212100178	70-734 70-27 70-698 70-698 70-1334
NORDERHAUG, L R NORDERHAUG, L R NORELIUS, C E NORELIUS, C E NORFLEUS, C E	8212210246* 8212210362 8212260074 8212060318 8212080664*	50-25 C 50-342 G 50-346 G 50-331 G 50-373 P	O'REILLY, J. P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8212090346 8212090385 8212090390 8212090398 8212090406	50-259 P 70-143 State Prog 50-395 Q 50-395 Q	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE IARO,J A	8212130285 8212160191* 8212170004 8212270026 8212060252*	70-2957 40-6500 70-2928 70-2941 50-409 q
NORELIUS C E NORELIUS C E NORELIUS C E NORELIUS C E	9212100014 8212100019* 8212100324 8212100327 8212100333*	50-243	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8212070414 8212070427 8212070435 8212070436 8212070464	50-416 Q 50-382 A 50-364 Q 50-416 Q 50-261 Q	PAGLIARO, J A HAISLEY, E J HAISLEY, E J HASWOLAR	6212150019* 6212070476* 6212280172 6212130026* 6212130041*	50-409 0 XPORTLIC XPORTLIC 50-10 F 50-10 F
NORFLIUS C E NORFLIUS C E NORFLIUS C E NORFLIUS C E NORFLIUS C E	8212170105 8212170109 8212170114* 8212170145 8212170177	50-341 G 50-295 G 50-295 G 50-155 G 50-266 G	O'REILLY, J P O'REILLY, J P O'TOGLE, J D O'TOGLE, J D	8212070544 8212070558* 8212270116* 8210170497 8212030248*	50-335 Q 50-335 Q 70-143 50-247 F 50-3 F	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8212220190* 8212220202* 8212060185 8212060184* 8212060470	50-10 F 50-10 F 50-275 G 50-275 G COMMISSION
NORELIUS: C E NORELIUS: C E NORELIUS: C E NORELIUS: C E NORELIUS: C E	8212170181* 8212210029 8212210104 8212210413 8212270275	50-266 G 50-358 G 50-373 G 50-461 G 50-456 G	0.100FE' A D 0.100FE' A D 0.100FE' A D 0.100FE' A D	8212060146 8212070285 8212070296 8212080297 8212090205	50-247 S 50-3 P 50-247 Q 50-247 S 50-247 P	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8212070090 8212070342 8212070351* 8212070359* 8212070368*	COMMISSION COMMISSION COMMISSION COMMISSION
NORCLIUS, C E NORELIUS, C E NORELIUS, C E NORELIUS, C E NORRHOLM, N J	8212270295 8212270308* 8212280433 8212280324 8212260287*	50-237 G 50-456 G 50-454 G 50-266 F 50-272 G	0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D	8212130232 8212120288 8212140353 8212150023 8212150080	50-247 P 50-247 P 50-3 F 50-247 S 50-247 S	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8212070372* 8212070385 8212080005 8212080023	COMMISSION COMMISSION COMMISSION COMMISSION
NORRIS. J F NORRIS. J F NORRY, P NORRY, P NORRY, P	8212050201* 8212090225* 8212080575 8212080576 8212080585	50-261 R 30-287 S PR PR PR	0/T00LE, J D 0/T00LE, J D 0/T00LE, J D 0/T00LE, J D	8212210119 8212210128 8212220042* 8212270120 8212270361*	50-247 S 50-247 S 50-3 F 50-247 F 50-247 Q	PALNER,D A PALMER,R A PALMER,R A PALMER,R A PALMER,R A	8212270441 8212020232* 8212020287* 8212060060* 8212100259*	NUREC 50-314 8 50-315 8 50-316 8 50-315 8
NORRY, P G, NORRY, P G NORRY, P G NORRY, P G NORTH, P	8211160074 8212080574 8212210477 8212210505 8212080505	PR PR ORG ORG RES	0.1407E'' A 0.1207E'' A 0.1207E'' A 0.1207E'' A 0.1207E'' A 0.1207E'' A	8212280219 8212280237 8212280243* 8212280364 8212290302*	50-247 R 50-247 P 50-247 P 50-247 P 50-3 F	PALMER.R A PALMER.R A PALMER.R A PALMER.R A PALMER.R A PANDEY.S	8212140165# 8212170228# 8212170232# 8212170292# 8210070227#	50-314 B 50-316 B 50-316 B 50-315 B 50-250 P
NOVAK, T M	8212280123 8212280123 8212010426* 8211050027* 8212010354	50-275 G 50-275 G ACRB 50-483 A 50-445 G	O'TOOLE, J D O'TOOLE, J D OBLIGADO, A DESTMANN, M J OKRENT, D	8212300273 8212300352 8212280061* 8212170079* 8212270442*	50-247 P 80-247 P 50-409 P 90-373 Q FOIA	PANDEY, S PANDEY, S PANDEY, S PANDEY, S PANDEY, S	8210220470* 8210220483* 8210250187* 8212290536* 8212300348*	50-317 P 50-317 P 50-344 P 50-250 P 50-289 P
NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8212030269 8212030275 8212030317 8212060033 8212060341	50-329 A 50-329 A 50-413 E 50-327 E 50-440 E	OKRENT, D OKRENT, D OLACH, V R OLACH, V R OLLER, R E	8212270445* 8212270445* 8212210289* 8212210289* 8212210286*	FOIA FOIA 50~155 G 50~155 G QA999	PANDY, J PANGBURN, G C PANGBURN, G C PAPAY, L T PAPAY, L T	8212150012 8212230145 8212230392 8212130333* 8212170384*	50-346 M Waste Mgt Waste Mgt 50-206 0 50-206 0
NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T. M	8212070447# 8212080540 8212130235 8212220440 8212220461	50-298	OLMAN, M D GLMEDO, L A OLSEN, A F OLSEN, C S OLSHAN, L	8212270165 8212230241 8212160086 8212060480 8212010020*	NUREQ 50-247 0 71-5814 NUREG 50-456 A	PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J PAPERIELLO.C J	8212060051 8212060055* 8212060238* 8212060252* 8212100145	50-409 G 50-409 G 50-295 G 50-409 G 50-254 G
NOVAK, T. M NOVAK, T. M NOVAK, T. M NUDENT, R. S. NUGENT, R. S.	6212280046 6212270481 6212300019 6212070201* 6212070201*	50-327 S 50-440 E 50-454 E 50-440 G 50-440 G	DLGHAN, L OLGON, R OLGON, R OLGON, R ONDRAGIK, M	8212080120 8212020034 8212080491 8212140412 8212080280	50-454 F 40-17 50-317 F NUREO 50-289 H	PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8212140410 8212150019# 8212170077 8212210124# 8212210340#	50-409 0 50-409 0 50-373 0 50-237 0 50-282 0

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARCHEN, L J	8212220265	NUREG	PENNIFILL.R A PEPPINO,R E PEPPINO,R C PERCH,R L PERCH,R L	8212270464	WASTE MGT	POSNER, P	8212150017	50-247 G
PARIS, O H	6212060236	50-142 G		8212010469	RES	POTAPOVS, U	8212070032	QA999
PARIS, O H	6212060315	50-155 G		8212010475	RES	POTAPOVS, U	8212070116	QA999
PARIS, O H	6212160509	50-155 G		8212010030	SO-387 P	POTAPOVS, U	8212070156	QA999
PARIS, O H	6212210235	50-247 G		8212220557*	50-387 P	POTAPOVS, U	8212070301	QA999
PARISEP C PARKER Q W PARKER L B PARKER M E PARKER R C	8212270135 8212140558 8212300280* 8212380522* 8212290138*	50-354 A RES QA979 50-155 Q 50-261 Q	PERKINS, D H PERLIS, R G PERLIS, R G PERLIS, R G PERLIS, R G	8212280438* 8212010385 8212020323 8212020326* 8212030163	50-409 P 50-443 Q 50-443 Q 50-443 Q 50-443 G	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8212070416 8212100003 8212210071 8212210135 8212210216	QA999 QA999 QA999 QA999 QA999
PARKER.R C	8212290165#	50-261 Q	PERLIS.R O PERLMAN, J PERRY, J M PERSINKO, D	8212280017	50-443 Q	PDTAPOVS. U	8212210353	9A777
PARKYN.J D	8212020125	PR		8212080580	CONTRACT	POTAPOVS. U	8212270179	BA777
PARKYN.J D	8212020375	PR		8212300127	CONTRACT	POTAPOVS. U	8212280376	BA777
PARSONS.R M	8212070043	50-400 S		8212230156	71-474	POTAPOVS. U	8212300027	BA777
PARSONS.R M	8212070305	50-400 S		8104230080*	FOIA	POTAPOVS. U	8212300212	GA777
PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8212090237* 8212170183 8212170328 8212170328 8212220432 8212300326	50-400 Q 50-400 B 50-400 5 50-400 S 50-400 S	PERSON, L S PESCHEL, J M PESCHEL, J M PESCHEL, J M PESCHEL, J M PETERSEN, R J	8212010250 8212100339* 8212170121* 8212270348* 8212230108	Wasie Mgt 50-441	PDTAPOVS, U POTAPOVS, U POTAPOVS, U POULK, R M POYSER, R W	8212300254 8212300276 8212300301 8212280397* 8212280397	QA999 GA999 OA999 50-325 S 40-2259
PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J	8212020083* 8212020161* 8212020297* 8212020312* 8212020319*	50-324 S 50-324 S 50-324 S 50-325 S 50-324 B	PETERSON, D A PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8212130250* 8212080232 8212100119 8212230414 8212230418	50-255 R XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PRATTIC M PRATTIC M PRATTIC M PRATTIC M PRATTIC M PREVATTE, R	82)2220271 8212220271 8212230187 8212230187 8212230187	50-247 G 50-247 G 50-247 G 50-247 G 50-309 P
M MASIVAN D M MAVICAN J M MAVICAN J M MAVICAN J M MAVICAN	8212020365* 8212070012* 8212070118* 8212070214* 8212070275*	50-324 B 50-325 B 50-325 B 50-325 S 50-324 B	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETRICK, N A	8212230423 8212230433 8212270336# 8212280155 8212170288	XFORTLIC XPORTLIC FOIA XPORTLIC 50-482 A	PRICE,E R PRICHARD,R P PRICHARD,R P PULLANI,S V PURCELL,L D	8212140527* 8212130122 8212160437 8212070148* 8212260026*	40-6500 71-6495 71-9132 50-309 G 70-146
PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J	8212070105# 8212070137# 8212070152# 8212070173# 8212070318#	50-325 S 50-325 S 50-325 S 50-325 S 50-324 S	PETRICK,N A PETRONE,C PETRONE,F P PETTENOILL,H J PETTENOILL,H J	8212280234 8212030207* 8212280092* 8212030255 8212030272*	50-482 A 50-289 G 50-247 F 40-1162 40-6622	PUZEY, A M QUICK, D R QUICK, D R QUIGG, C QUIGLEY, T W	8212100406* 8212090384* 8212090504* 8212070411 8212060330	50-344 F 50-327 0 50-390 0 50-295 P 40-8743
AASIVA, M J	8212070463*	50-325 S	PETTENGILL, H J PETTENGILL, H J PEVFNSTEIN, J E PEVFY, L E	8212050004	40-8084	QUIGLEY.T W	821 R290145	40-8743
PASIVA M J	8212070542*	50-325 S		8212070045	40-8698	QUILLIAM,J F	821 2060471	50-275 P
L M AVIBAR	8212070550*	50-325 S		8212230391	40-8602	RABY,J	821 2290430*	50-220 S
J M AVIBAR	8212140157*	50-325 S		8212220034 *	CONTRACT	RADKEY,R L	821 2060336*	40-8743
J M AVIBAR	8212140202*	50-325 S		8212280181	XPORTLIC	RAME,E P	821 0210467	TOPREP
PASTVA, M J	8212150114*	50-325 S	PEVEY, R E PEYBER, P PFREFERLEN, H C PFREFERLEN, H C	B212060465	NUREO	RAHE, E P	8210210484*	TOPREP
PASTVA, M J	8212170156*	50-325 S		B212230276	50~247 U	RAHE, E P	8210210489*	TOPREP
PASTVA, M J	8212210032*	50-325 S		B212270325	40~6659	RAHE, E P	8212010154	PT21
PASTVA, M J	8212210157*	50-325 S		B212070077	TOPREP	RAHE, E P	8212020267	TOPREP
PASTVA, M J	8212210405*	50-325 S		B21207014B	TOPREP	RAHE, E P	8212130262	TOPREP
PASTVA: M J PASTVA: M J PASTVA: M J PASTVA: M J PASTVA: M J	8212220493* 8212220504* 8212300225* 8212300259* 8212300262*	50-325	PFLUM.C O PHILLIPS.H S PHILLIPS.H S PHILLIPS.J	821202024 <i>6</i> 8212070364* 8212300218* 8212300303* 8212290128*	WASTE MGT GA599 GA999 GA999 GA999 50-309 R	RAHE.E P RAHE.E P RAHE.E P RAHE.E P RAIMONDI.P J	8212130294 8212150055 8212200040 8212220182 8212020256	TOPREP TOPREP TOPREP TOPREP 50-356 A
PASTVA.M J	8212300309*	50-325 S	PHILLIPS, J	9212270130*	50-27 R	RAMSEY, B L	8212270104*	50-266 P
PASTVA.M J	8212300317*	50-325 S	PHILLIPS, M P	8212060238*	50-275 G	RAMSEY, C	8212170162*	50-155 C
PASTVA.M J	8212300334*	50-325 S	PHILLIPS, M P	8212210124*	50-237 G	RAMSEY, C	8212170187*	50-266 C
PAT(N.W D	8211080148	50-327 0	PICKENS, T A	8212150072*	50-331 P	RANDAZZA, J B	8212210266*	50-309 C
PAT(N.W D	8212280145	50-397 0	PICHL, R H	8212060060*	50-314 S	RANGEL, C	8212230276	50-247 L
PATTLREON, J P	8212210340*	50-282 Q	PICHL,R H	0212100327*	50-315 6	RANLET. J	8212070471	RES
PATTERSON, N F	8212220051	50-461 T	PIENCE,J D	8212150274	71-5939	RATCHFORD, W	8212230276	50-247 V
PAUL, R A	8212080276*	50-295 Q	PIENCE,R L	8212300123*	CONTRACT	RAUSCH. T J	8212030043	50-237 P
PAUL, R A	8212090433	50-409 Q	PIKF,D H	8212270435	NUREO	RAUSCH. T J	8212030056*	50-254 G
PAULK, Q L	8212070479*	50-259 Q	PILANT,J	8212070175	50-290 P	RAUSCH. T J	8212060029	50-237 G
PAUL SON, W	8212010023	50-204 P	PILANT, J H	B212030159	50-298 P	RAUSCH, TU	8212040181*	50-254 F
PAUL SON, W	8212020252	50-204 P	PILANT, J H	8212070141*	50-298 Q	RAUSCH, TU	8212040207	50-237 P
PAUL SON, W	8212070002	50-204 F	PILANT, J H	8212070402	60-298 F	RAUSCH, TU	8212040267	50-237 P
PAUL SON, W	8212130204	50-206 P	PILANT, J H	8212100171	50-298 P	RAUSCH, TU	8212080537	50-237 G
PAUL SON, W	8212010047	50-206 P	PILANT, J H	8212100293	50-298 P	RAUSCH, TU	8212090301	50-237 P
Paul Sûn, W a	8212020307	50-206 P	H L,TMAIR	8212130342*	50-298 F	RAUSCH, T J	8212140172	50-237 P
Paul Sûn, N a	8212080283	50-206 P	PILANT, J H	8212140472	71-9001	RAUSCH, T J	8212140179	50-254 F
Paul Sûn, W a	8212100009	50-206 P	PILANT, J H	8212160433	71-484	RAUSCH, T J	8212160013	50-254 P
Paul Sûn, W a	8212100020	50-206 P	PILANT, J H	8212280399	50-298 F	RAUSCH, T J	8212160326	50-237 Q
Paul Sûn, W a	8212160018	50-206 P	PILANT, J P	8212220265	NUREQ	RAUSCH, T J	8212210036	50-237 P
PAULSON,W A PAULSON,W A PAVIS,Q S PAVIS,Q S PAXION,H C	8212210293	50-204 P	PINKETT, M	8212230241	50-247 0	Rausch, t J	8212280110	50-237 Q
	8212220447	50-206 P	PIRTLE, G L	8212040080*	50-346 Q	Rausch, t J	8212280263	50-237 P
	8212140131*	50-317 S	PIZZUTO, C M	8212270330	50-382 Q	Rausch, t J	8212280357	50-254 P
	8212210303*	50-317 S	PLIML, G	8212130153*	50-275 F	Rausch, t J	8212290111	50-254 P
	8212130191	50-266 G	PLIML, G	8212270086*	50-275 F	Rausch, t J	8212290190	50-237 P
PECK, R B	8212070174*	50-329 T	PLIML, G	8212290105*	50-295 F	RAVBCH, T J	8212270407	50~254 P
PEEBLES, T	8212270151	50-346 S	PLIML, G	8212290511*	50-295 F	RAMBON, R J	8212070003	50~322 0
PEEBLES, T A	8212100263*	50-346 0	PLOSKI, T J	8212040017*	50-315 Q	RAWBON, R J	8212200113	50~454 0
PELIZZA, H S	8212030261	40-8786	PLUMLEE, G, L	8212070240*	50-267 Q	RAWBON, R J	8212280028	50~259 0
PELK, P R	8212100200*	50-367 Q	POCHAL, W F	8212280149	XPORTLIC	RAY, H B	8212280028	50~361 S
PELKE, P R PELLETIER, J P PELLETIER, J P PENDER, R A PENNIFILL, R A	8212270414* 8212270378 8212270384* 8212070204* 8212010514	50-546 Q 50-271 B 50-271 S 50-440 Q Waste Mgt	POLASKI, J P POLLOCK, M S POPPE, L K POPPE, L K PORTER, M R	8212020095 8212210338 8212150202 8212160407 8212020124*	50-155 P 50-322 A 71-9081 71-9151 50-296 S	RAY, H. B RAY, H. B RAY, H. B RAY, H. B RAY, H. B	8212070231* 8212070252 8212070259* 8212070281 8212070283	50-361 8 50-361 6 50-361 8 50-361 8 50-361 8

1
VVVVV
7222
N N N N N N N N N N N N N N N N N N N
NIC NC NC
NG NG NG NG

AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SLOJEJ ^T Categor
RAY,H B RAY,H B RAY,H B RAY,H B RAY,H B	8212070287* 8212070290 8212070293* 8212070294* 8212070324	50-361 8 50-361 8 50-361 8 50-361 8 50-361 8	REYNOLDS, N S	8212270324 8212270324 8212270329 8212270329 8212270332	50-397	ROHRER, M V ROHRER, M V ROHRER, M V ROLES, G W ROLES, G W	8212300047* 8212300087* 8212300228* 8212230105 8212230114	50-415 5 50-416 5 50-415 5 4ASTE FAT
RAY.H B RAY.H B RAY.H B RAY.H B RAY.H B	8212070329* 8212070350 8212070340* 8212070349 8212070374*	50-361 8 50-361 8 50-361 8 50-361 8 50-361 8	REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	8212270332 8212280273 8212280273 8212280277 8212280277	50-445 Q 50-445 Q 50-445 Q 50-397 Q 50-397 Q	ROLES, G W ROMAN, T W ROMINE, W D ROOD, H ROOD, H	8212230174 8212140031* 8212070178* 8212010409 8212170381	Maste F+* 50-240 50-342 50-342 50-341
RAY.H B RAY.H B RAY.H B RAY.H B	8212070379 8212070383 8212070388* 8212070399* 8212070406	50-341 8 50-341 8 50-341 8 50-341 8 50-341 8	REYNOLDE, N S REYNOLDE, N S RHEE, S RHEC, S J RHINELANDER, J	8212280294 8212280294 8212170139* 8212170130* 8212140470	50-460 0 50-460 0 50-247 8 50-237 8 40-2061	ROONEY, V L ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8212260005 8212060324• 8212070216 8212070308 8212070322	50-271 50-301 50-301 50-301 50-301
RAY.H B RAY.H B RAY.H B RAY.H B RAY.H B	8212140035 8212140035 8212140265 8212140270* 8212140272*	50~361 8 50~361 8 50~361 8 50~361 8	RHOADES, W J RHOADS, G G RHOADS, G G RKODES, M RICCARDELLA, P	8212160417* 8212070158* 8212270468* 8212160659 8212160303*	50-387 P 50-387 Q 50-387 Q 40-8027 50-331 Q	ROOT, L D ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8212090337 8212100276 8212100295 8212150070 8212170193	50-331 F 50-331 F 50-331 F 50-331 F
RAY.H B RAY.H B RAY.H B RAY.H B RAY.H B	8212140360 8212140368* 8212140398 8212140405* 8212290102	50-204 8 50-204 8 50-341 5 50-341 8 50-204 R	RICE, D A RICE, W A RICH, P C RICHARDS, J F RICHARDS, L	8212210283* 8212270512 8212220341 8212280455* 8212140253	50-27 8 NUREG NUREG CONTRACT 50-327 A	ROOT, L. D ROOT, L. D ROOT, L. D ROOT, L. D ROOT, L. D	8212170308 8212210315 8212270168 8212270298 8212280065	50-331
RAY, H B RAYMOND, W J RAYNOR, J W RAZLAFF, W J READ, D F	8212270176 8212140113* 8212210303* 8212270104* 8212020383	50~361 R 50~271 G 50~317 B 50~266 P PR	RICHARDS, 8 RICHARDS, 8 RICHARDSON, J D RICHTER, L RICHTER, L	8212030207# 8212040170# 8212200104# 8212100332# 8212280250#	50-289 Q 50-423 Q 50-416 R 50-346 S 50-346 S	RODT, R W ROOT, R W ROSAND, R ROSE, M ROSENFELD, C S	8212210251 8212280428 8212170178 8212270311 8212010150*	50-450 E 50-453 B 50-247 E FOLM 50-272 F
REAVIS, J A REAVIS, J A REDELLO, J E REDELLO, J E REDELLO, J E	82;2210045* 82;2210428* 82;2010383* 82;201037;* 82;2010378*	50-349 R 50-269 R CONTRACT CONTRACT CONTRACT	RIDDUT,E F RIDDUT,E F RINO, M A RIZZO, J S RODBINS, E B	8212160134 8212160140* 8212170118* 8212300410* 82123004	71-454 71-454 50-454 Q 50-387 F FOIA	ROSENTHAL, A S ROSENTHAL, B ROSS, F W ROSS, M A ROSS, M A	8212010141* 8212230276 8212170457* 82120803014 8212080301*	FOIA 50-247 . 40-8729 50-443 : 50-442 ;
REDELLO, J E REDELLO, J E REDELLO, J E REDELLO, J E	8212010404* 8212010423* 8212010430* 8212010434* 8212010438*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	ROBERTS, J P ROBERTS, J P ROBERTS, J P ROBERTS, J P	8212030154* 8212130148 8212130435 8212130438 8212210517	50-445 Q 70-1308 PRDJ PRDJ PROJ	ROSS, M A ROSS, M A ROSS, W J ROSS, W J ROTELLA, T S	8212130246* 8212130246* 8212140423 8212290525 8212150158*	50-640 1 50-640 3 50-272 8 50-306 8 50-305 5
REBELLO, J E REBELLO, J E REBELOWSKI, T REBELOWSKI, T REDAND, R T	8212060413* 8212080577* 8212140084* 8212140140* 8212170133*	CONTRACT CONTRACT 50-213 G 50-247 G 50-112 G	ROBERTS, T ROBERTS, T ROBERTS, T RODINSON, D ROCCO, J	8212280542 8212020016* 8212070467* 8212270384* 8212270171	NUREO FOIA 50-298 P 50-247 Q 50-206 J	ROTELLA, T 6 ROTELLA, T 5 ROTELLA, T 8 ROTELLA, T 5 ROTELLA, T 5	9212210186* 9212210376* 9212220442* 9212280366* 9212280425*	50-335 S 50-335 S 50-335 E 50-335 S 50-335 S
REDAND, R T REDMOND, R F REED, C REED, J G REEDY, R F	8212280420* 8212080577* 8212280298 8212210276 8212140447	50-298 Q CONTRACT 50-373 P 50-403 Q 50-275 R	ROCKHOLD, H C ROCKHOLD, H C RODGERB, P RODRIOJE, P RODRIQUEZ, P	8212020074 8212020108 8212030075* 8212230274 8212070189	50-395 P 50-364 P 50-368 S 50-247 U 50-247 Q	ROTH, J ROTH, J ROUP, O L ROUSE, L C ROUSE, L C	8212210370* 8212230335* 8212070340* 8212140474 8212160331	70-487 70-1343 70-1203 50-987 = 70-687
REEVES, E A RCHM. T A REHM. T A REHM. T A REIMANN, F H	8212140548 8212130334 8212220512 8212290521 8212170304*	50-364 P COMMIBBION COMMIBBION COMMIBBION 50-10 Q	RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J ROBUSON,J	8212030042 8212170231 8212200042 8212270283 8212140140*	50-312	ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C ROUSE, L C	8212170014 8212170017* 8212220005 8212220007* 8212220170	70-1843 70-1843 50-293 (50-293 r 50-293 r
REIS, H F REIS, H F REIS, H F REITER, L REITER, L	8212280541 8212280541 8212280541 8001180235* 8004090788*	27-47 27-47 27-47 50-206 P 50-206 P	RDEDER, J A RDEDER, J A RDESSET, J M RDGERS, D RDGERS, H R	B212160343* 8212140477* 8212170378* 8212100277 8212020191*	FOIA FOIA 50-275 H 50-128 S 50-328 S	ROUSE, L. C ROUSE, L. C ROUSE, L. C ROUSE, J. W	8212230136 8212230141* 8212230147 8212290474 8212280491*	70-1863 70-1863 50-290 / 50-397 E CONTRACT
REITLER, E K REITLER, E K REKITO, W A REMLEY, M E REPKA, D A	8212150236 8212150244* 8212060237* 8212210110 8212080267	70-1151 70-1151 50-247 G 50-375 W 50-322 G	RDGERS, H R RDGERS, H R, RDGERS, P ROGERS, P	821 2070 554 * 821 21 40 20 7 * 821 21 40 24 7 * 821 22 10 0 26 * 821 22 70 2 23 *	50-328 8 50-328 5 50-327 8 50-368 8 50-368 8	RDY.C W RUITLR.G H RUNKLC.G E RUBSCHER.G E RUSSFLL.L B	8212160103+ 8212270216+ 8212010107 8212220265 8212060176	FOTA 50-965 RES NURES 50-917
REPKA, D A REPKA, D A REPKA, D A REPKA, D A REPKA, D A	8212140463 8212200111 8212220106 8212220142 8212220146	50-322 0 50-322 0 50-322 0 50-322 0 50-322 0	RDGERS,P ROGERS,R F ROGERS,R F RDGERS,V C ROGERS,V C	8212300070* 8212270137* 8212270184* 8212270115 821222341	50-348 8 50-250 0 50-280 0 NUREO NUREO	RUGSELL, L B RUGSELL, L B RUGSELL, L B RUGSELL, L B RUSSELL, L B	9212050301 9212080441 9212140125 9212140259 9212210043	50-117 \$ 50-317 \$ 50-317 \$ 50-317 \$ 50-317 \$
REQUA, Q REVELEY, T W REYES, L REYES, L REYES, L A	8212220465 8208290121 8212030150* 8212270151 8212100263*	50-261 P FOIA 50-282 Q 50-346 S 50-346 Q	ROGERS, N O ROGGE, J F ROHATOI, U B ROHRER, M V ROHRER, M V	8212070134* 8212030102 8212030102 8212030102 8212100263*	50-346 0 50-302 8 REB 50-416 8 50-416 8	RUSBELL,L B RUSBELL,L B RUSBELL,L B RUSBELL,L B RUSBELL,W T	8212210076 8212210294 8212210378 8212290275 8112110356*	50-317 \$ 50-317 \$ 50-317 \$ 50-317 \$ 50-317 \$
REYES, R A REYNOLDS, J R REYNOLDS, J R REYNOLDS, N S REYNOLDS, N S	8212100149* 8212280268 8212260266 8212140409 8212140409	50-305 Q 50-275 Q 50-275 Q 50-445 Q 50-445 Q	ROHRER, M V ROHRER, M V ROHRER, M V ROHRER, M V ROHRER, M V	8212070175* 82(2170277* 8212170327* 8212210205* 8212210227*	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	RUTI FDOE, B O RYAN, A B SABADOB, J H SAHA, P SAHA, P	821202025 8212230337 8212070416* 8212030237 8212060119	PR : 1 50-247 : 1 70-143 RES ,
REYNOLDS: N S REYNOLDS: N S REYNOLDS: N S REYNOLDS: N S	8212200010 8212230314 8212230314 8212270317 8212270317	PR 50-397 Q 50-397 Q 50-445 Q 50-445 Q	ROHRER, H V ROHRER, H V ROHRER, H V ROHRER, H V ROHRER, H V.	6212260081# 6212260163#	50-416 B 50-416 B 50-416 B 50-416 B 50-416 B	BAKOWSKI,P SAMANIEGO,F J SAMELSON,A SAMELSON,A	8212300263* 8212270227 8212270227 8212270322 821223024[QAPF9 50-322 T 50-322 T 50-46t c 50-247 ;

	ACCESSION NUMBER	SUBJECT CATEGORY	AUTH O R	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR SANDERS, C F SANDERS, W F SANDRY, W A SARSOUR, B SARSTEN, G E	8212150244* 8212090245* 8212020134 8212290309* 8212010224	70-1151 50-424 G PR 50-346 R PT21	SCHWENCER. A SCHWENCER. A SCHWENCER. A SCHWENCER. A SCHWENCER. A	8212220537 8212220541 8212220552 8212220554* 8212270471	50-387 F 50-352 A 50-387 P 50-387 P 50-458 F	SHACK.W J SHACK.W J SHAFER.P W SHAFER.W SHAFER.W	8212080670* 8212080573* 8212070440* 8212040112 8212080416	50-373 P 50-373 P 50-407 G 50-329 S 50-329 S
SARSTEN, G E SASTRE, C SATTAR, D SAUNDERS, G A SAUNDERS, R T	8212070295 8212060005 8212160419* 8212170404 8212170044*	50-324 S RES 50-387 P 40-8745 50-280 F	SCHWENCER, A SCHWENCER, A SCHWENSFIER, R SCHWINK, W SCOTT, D J	82123001B4 8212300203* 8212270024 8212220256 8212020239	50-416 P 50-416 P 70-33 REVIEW GRP 50-249 S	SHAFER, W D SHANBAKY, M SHANDON, J B SHANNON, J B SHANNON, H E	8212100161 8212220358* 8212030023* 8212030285 8212220249	50-329 A 50-244 Q 50-220 Q 40-8102 NUREQ
SAVINI.R J SAHORSKI.A SAVORSKI.A SAYER, J SCALETTI.D C	8212060410 8212070349* 8212070349* 8212130346* 8212150203	FOIA 50-155 9 50-155 9 50-298 F 50-447 A	SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, D J	8212020275 8212020337 8212030286* 8212080375 8212100215	50-237 8 50-247 8 50-10 F 50-249 8 50-237 8	SHANNON, Z SHAO, L SHAO, L C SHAO, L C SHAO, R C	8212010398* 8102200777* 8002200995* 8212270253 8212270045*	CONTRACT FOIA 50-219 P MISC FOIA
SCALETTI.D C SCALETTI.D C SCARANO, R A SCARANO, R A SCARANO, R A	8212150209 8212280510 8212010500 8212010508 8212020388	50-447 A 50-447 A Waste Mot Waste Mot Waste Mot	SCOTT.D J SCOTT.D J COTT.DS J COTT.D J SCOTT.D J	8212100312 8212140112 8212170097 8212170122 8212170134	50-237 S 50-10 R 50-247 S 50-237 S 50-249 S	Sharp,r a Shaver,l Bhaw,a Shaw,a Shaw,a	8212270131* 8212160752* 8211070496 8212100087 8212160791	FOIA 50-320 F 70-2955 XPORTLIC XPORTLIC
SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A SCHAEFER, D W	8212230381 8212230383 8212230388 8212290024 8212130253	WABTE MOT 27-47 WASTE MOT WASTE MOT 50-275 S	SCOTT.D J SCOTT.D J SCOTT.D J SCOTT.D J	8212170218 8212210157 8212230028* 8212280472 8212270329	50-249 S 50-237 S 50-10 F 50-237 S 50-249 S	ehaw, a Sheal ey, w. J Shell ey, w. J Shell ey, w. J Shell ey, w. J	8212300140 8212100138* 8212100403 8212130237 8212210512	XPORTL1C FOIA 40~8748 40~2061 40~2061
SCHAEFER, K SCHERER, A E SCHERER, A E SCHERER, A E SCHERMAN, R L	8212080264 8212020372 8212140501 8212170163 8212070206*	50-440 0 PR PRDJ NUREG 50-440 0	SCOTT.D J SCOTT.D J SCOTT.D J SCOVILLE,J J	8212270344 8212270367 8212270378 8212270472 8212270010	50-237 S 50-249 S 50-237 S 50-249 S 27-48	SHELLEY, W J SHELLEY, W J SHEN, P K SHEPARD, J C	8212230379 8212280013 8212280018* 8210270018* 8009050320*	40-8027 70-1193 70-1193 50-397 A FOIA
SCHERRER, J S SCHEUER, J SCHIERLING, H SCHIERLING, H SCHIERLING, H E	8209270122* 8212230276 8212010414 8212170450 8212150217	50-409 P 50-247 U 50-498 A 50-498 A 50-275 P	SCOWN, K SCOWN, K SCOWRY, N SCOWRY, N SCOWRY, N	8212210185* 8212210204* 8212010213 8212010219 8212010241	50-344 0 50-361 0 ORO ORO ORO	SHEPHERD, J E. SHERMAN, F L SHERMAN, F L SHERR, T S SHERR, T S	8212270156 8212270024 8212270030* 8212130360 8212130363	NUREO 70-33 70-33 TOPREP 50-295 F
BCH1ERLING.H E SCHL18SEL D A SCHMIDT.C SCHMIDT.H C SCHMITENDORF.G	8212150223 8212270055 8212270264 8212270403 8212270318*	50-275 P 50-244 8 40-8783 50-445 F 50-338 R	SCURRY, N SCURRY, N SCURRY, N SEBRELL, W A SEBRELL, W A	8212010247 8212010253 8212010254 8212220172 8212220513	ORG ORG ORG NUREG NUREG	SHERR, T. S SHERR, T S SHERWOOD, O G SHERWOOD, O G	8212220517 8212220520* 8212270333* 8212130172 8212140348	50-295 P 50-295 P FOIA 50-447 B 50-447 B
SCHMOOCK, D SCHME (DER, C SCHMELL, D F SCHMLLL, D F SCHMOEDER, B A	8212080251 8212230274 8212020259 8212080254 8212140120*	50-266 9 50-247 U 50-483 8 50-483 F 50-10 R	SECKMAN, P E SEIDLE, W C SEIDLE, W C SEIDLE, W C	8212150132 8212030046 8212030104 8212030109 8212030119	50-331 J 50-482 Q 50-285 Q 50-482 Q 50-285 Q	SHERWOOD, O O SHERWOOD, O O SHERWOOD, O O SHERWOOD, O O SHEWMON, P.	8212140449 8212230301 8212230328 8212270119 8211100488	50-447 B 50-447 E 50-447 A 50-447 A 50-397 D
SCHROEDER, B A SCHROEDER, B A SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W	8212290345* 8212290409* 8212130093 8212140068 6212140289	50-237 S 50-237 S 50-373 P 50-373 P 50-373 Q	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8212030184 8212070145 8212100227 8212100228 8212100254	50-348 Q 50-285 Q 50-285 Q 50-285 Q 50-313 8	SHEFT DB' 8 A BHEMON' 5 SHEFMON' 5 SHEFMON' 6 SHEFMON' 6	9212020406 8212130305* 821220534* 9212220544* 8212080633*	ACRS 50-275 P 50-237 P 50-245 P 50-546 F
SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W SCHROEDER.C W SCHWELKE.D A	8212140402 8212210463 8212280341 8212270337 8212300417*	50-373 P 50-373 K 50-373 K 50-374 G 50-282 F	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C BEIDLE, W C	8212150280* 8212200022 8212210245 8212270078* 8212270172	50-313 F 50-285 Q 50-313 G FOIA 50-313 Q	SHIELDS, B W SHIELDS, S W SHIELDS, S W	8212100181 8212170329 8212280157 8212280272 8212280304	50-546 B 50-546 S 50-546 S 50-546 B 50-546 G
SCHULZ,R D SCHUM,W S SCHUM,W S SCHUMACHER,M C SCHUMACHER,M C	9212140495* 6212070133* 8212290249 6212060062* 6212170079*	50-410 Q 50-112 Q 50-482 S 50-407 Q	SEIGERMAN, V K SELAN, J C SELAN, J C SELLS, D SELLS, D E	8212230323 8207230424* 8212070023* 8212010443 8212070017	50-247 H 50-250 P 50-263 P 50-498 A 50-335 F	SHIELDS, S W SHIELDS, S W SHIELDS, B W SHIFFER, J D. SHIM, K	8212280321 8212280462 8212270112 8212210116 8212280247*	
SCHUMER, C SCHUSTER, M D SCHUSTER, M D SCHUSTER, R M SCHUKTER, R M	8212230276 8212130253 8212280421 8212210414* 8212280421	50-247 U 50-275 B 50-344 5	BEMMEL, H BEMMEL, H BEMMEL, H BEMMEL, H BEMMEL, H	8212020361 8212020361 8212070247 8212070247 8212070303*	50-155 Q 50-155 Q 50-155 Q 50-155 Q 50-155 Q	shima s Shirakas Shirakawa T Shirakawa T Shirakawa T	8212270082 8212270084 8212010044 8212010048 8212010054	XPORTLIC XPORTLIC XPORTLIC
SCHWE I KERT-THUL SCHWE I KERT-THUL SCHWE NCER: A SCHWE NCER: A SCHWE NCER: A	6212080453 8212080453 8212010005 8212010027 8212010377		SEMMEL, H SEMMEL, H SEPAR, S SERINI, B	8212070303* 8212250272 8212260272 8212270034 8212100187	50-155 Q 50-155 Q 50-155 Q FOIA 70-2960	SHIRAKAWA, T SHIRAKAWA, T SHOCKLEY, W E SHOEMAKER, C J. SHOEMAKER, C J	8212270087 8212270090 8212270060 8212010207 8212010216	XPDRTLIC XPGRTLIC REB 50-341 Q 50-341 Q
SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A	8212010470 8212010513 8212060037 8212060097 8212060118	50-352 A 50-322 A 50-322 A 50-352 A 50-352 A	Berini, B. L Berrand, W Bestak, F Bestak, F Bestak, F	8212130287* 8212140364 8212150195 8212150800* 8212270299*	50-206 P 50-275 P 50-275 P	SHOEMAKER, C J.	8212070114 8212100113 8212140432 8212150032 8212230367	50-358 0 50-358 0
SCHWENGER, A SCHWENGER, A SCHWENGER, A SCHWENGER, A SCHWENGER, A	8212060379 8212060484 8212080014 8212080566 8212100372		Sebtak, F Sestak, F Sestak, F Sestak, F Sestak, F	8212270301 + 8212270310+ 8212270312+ 8212280163+ 8212270207+	50-275 P 50-275 P 50-275 F	SHOEMAKER, C J SHOCAN, R P SHOLLEY, W J SHOLLY, S C	8212280156 8212300016 8212140420 8212270563 8212040077	* 50-445 Q * 50-244 P 40-8027 50-247 Q
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8212160727 8212160747 8212170034 8212220049 8212220355	50-352 A + 50-373 P 50-458 A	SESTAK, F SESTAK, F SESTAK, F SESTAK, F SHACK, W J.	8212290237# 8212290243# 8212290250# 8212290462# 8212290468#	; 50-275 P ; 50-275 P ; 50-275 P	SHOLLY, S C SHOLLY, S C SHON, F J	8212040078 8212070101 8212270414 8212080315 8212100108	50-247 0 FOIA 50-155 0

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHON, F J SHON, F J SHON, F J SHOP ENN, N M	8212150041 8212160507 8212230181 8212230351 8212210184	50-440 0 50-155 0 50-247 G 50-240 0 40-8006	SMITH, I W SMITH, J C SMITH, J L SMITH, J L SMITH, J L	8212200107 8212270132 8212010082 8212010082	50-454	SPELMAN, H J SPELMAN, H J SPELMAN, H J SPELMAN, H J SPELMAN, H J	8212130167 8212130167 8212270469 8212270469 8212270478	40-2061 40-2061 40-2061 40-2061 40-2061
SHOPENNIN M SHOPENNIN M SHOTWELLIJ A SHUMATE, D R SICILIANIJ M	8212210412 8212230150* 8212070242 8212230051* 8212070276*	40-7086 F0IA 50-443 G CONTRACT 50-416 P	THIOLEMAN SMITHIOL SM	8212010145 8212070129 8212070219 8212140339 8212210224	50-322 E 50-322 E 50-322 A 50-322 A 50-322 A	SPELMAN.H J SPENCER.B W SPENCER.G S SPENCER.G S SPENCER.G S	8212270478 8212270240* 8212130271 8212300207 8212300234	40-2061 50-537 A 50-187 Q 70-734 70-25
Sieder, J D Sieder, J D Sieder, J D Siefken, D L Biegel, B	8212220373 8212220409 8212220425 8212270464 8206140162*	50-334 P 50-334 P 50-334 P WASTE MOT 50-278 Q	SMITH, J L SMITH, J L SMITH, J L SMITH, J R SMITH, L C	8212210406 8212230259 8212270380 8212220528* 8212210005*	50-322 E 50-322 E 50-322 E CONTRACT 50-275 P	SPENCER, W C SPESSARD, R SPESSARD, R L SPESSARD, R L SPESSARD, R L	B212070305 B212070415 B212080366 B212080507 B212080515*	50-404 O 50-237 S 50-461 O 50-155 Q 50-155 Q
Siegel, B L Siegel, B L Siegel, M A Siegel, M D Siegel, S M	8212090003 8212270353 821220241 8212010481 8211020166*	ТОРКЕР ТОРЯЕР 50-247 G RES 50-275 H	SHITH, M SHITH, M SHITH, M SHITH, M SHITH, M SHITH, M	8212270308* 6212060017* 8212280130* 6212270447* 8212270266	50-3 F 50-315 0 50-338 0 CONTRACT CONTRACT	SPESSARD,R L SPESSARD,R L SPESSARD,R L SPESSARD,R L SPESSARD,R L	8212090472 8212100141 8212100144* 8212100234 8212100238*	50-461 Q 50-305 Q 50-305 Q 50-483 Q 50-483 Q
Sieofried, k a Biegriet, w Bilbero, J Bilbero, J Bilbero, J e	6212140460 6212160532 6212130241 6212130241 6212130241	50-341	SMITH.PA SMITH.PA SMITH.PA SMITH.PA SMITH.PA	8212070453* 6212080103* 6212080563* 6212220034* 6212270107*	CONTRACT CONTRACT CONTRACT CONTRACT FOIA	SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L SPESSARD, R L	8212100255 8212100257* 8212100276 8212100302* 8212140224	50-346
SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E SILBERO, J E	8212010208 8212010212 8212010212 8212070358 8212070358	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	SMITH.PA SMITH.PA SMITH.PA SMITH.PA SMITH.PA	8212270110* 8212270123* 8212270127* 8212270131* 8212270496	FOIA FOIA FOIA FOIA CONTRACT	SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L SPESSARD.R L	8212280108 8212280242 8212280246* 8212280381* 8212290330	50-461 A 50-315 G 50-315 G 50-461 G 50-315 G
Silbero, J e Silbero, J e Silbero, J e Silbero, J e Silbero, J e	8212080293 8212080293 8212090194 8212140445 8212140445	50~440 0 50~440 0 50~440 0 50~440 0 50~440 0	Smith.P A Smith.P A Smith.P A Smith.P A Smith.P A	8212270502* 8212270509 8212270513* 8212270516* 8212280044*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPESSARDIR L SPIROIH J SPIROIH J SPIROIH J SPRUCE,J K	8212270331* 8212080027* 8212080030* 8212080045* 8212170128*	50-315 G FOIA FOIA FOIA 50-498 A
SILBERG.J E SILBERG.J E SILBERG.J E SILBERG.J E SILBERG.J E	8212160247 8212160247 8212160251 8212160251 8212200061	50-440 0 50-440 0 50-440 0 50-440 0 50-440 0	SMITH.PA SMITH.PD SMITH.PD SMITH.PD	8212270273* 8212300132* 8203010313* 8203040451* 6205240413*	CONTRACT CONTRACT FOIA FOIA FOIA	GRENIAWSKI.D J GRENIAWSKI.D J GRENIAWSKI.D J GRINIVASAN,M G GT PIERRE.M	8212100150 8212100245 8212100246* 8212130147 8212210579*	1 &E 70-2872 70-2872 NUREO 50-245 F
BILBERG, J E SILBERG, J E SILBERG, J E SILBERG, J E SILBERG, J E	8212200061 8212210321 8212210321 8212210345 8212210345	50-440 C 50-440 0 50-440 0 50-440 0 50-440 0	SMITH.PD SMITH.PD SMITH.PM SMITH.RD SMITH.RD	8206290144* 8208030436* 8212100133* 8212030254 8212030270	FOIA FOIA CONTRACT 40-8452 40-6622	STADNICK, S STAHL, D M STAHMER, F STALLINGS, C M	8212030234# 8212140387 8212140387 8212140387 8212280442# 8212290069#	50-336 S 50-329 0 50-329 0 50-295 S 50-280 8
SILVER, R D SILVERSTROM, L SILVERSTROM, L SILVIS, R M SILVIS, R M	7907300565* 8212200015 8212300011 8212030236 8212030246	50-255 P 50-537 G 50-537 G CONTRACT CONTRACT	SMITH.R D SMITH.R D SMITH.R D SMITH.W G SMITH.W G	821 2170443 821 223021 9 821 2280184 821 2020229 821 2020283	40-0728 40-0745 Waste Mot 50-316 S 50-315 S	Stall inds, C M Stall inds, C M Stall inds, C M Stall inds, C M Stall ins, J E	8212290075* 8212290080* 8212290085* 8212290172* 8212210501	50-280 S 50-280 S 50-281 S 50-280 Q 71-488
SILVIS, R H SILVIS, R H SILVIS, R H SILVIS, R. H SILVIS, R M	8212080560 8212220536 8212220549 8212230044 8212270446	50-443 A CONTRACT CONTRACT CONTRACT CONTRACT	SHITH, W C SHITH, W C SHITH, W C SHITH, W C	8212060031 8212060048 8212100177 8212100251 8212100322	50-315 S 50-316 S 50-316 S 50-315 S 50-315 S	STAMIRIS: B STAMIRIS: B STAMIRIS: B STAMSBERRY: E R STAMSBERRY: W W	8212020343 8212020345 8212100095 8212130238 8212070206#	50-327 0 50-327 0 50-327 0 50-182 P 50-338 0
THE PROPERTY OF THE PARTY OF TH	8212270518 8212270558 8212280047 8212300170 8212270377	CONTRACT CONTRACT CONTRACT CONTRACT 71-9079	SHITH, W. 0 SHITH, W 0 SHITH, W 0 SHITH, W 0	8212140156 8212170224 8212170267 8212170283 8212200056	50-316 S 50-316 S 50-316 S 50-315 S 50-316 R	STARK,R M STARK,R M STARK,R M STARK,R M STARKEY,R B	8212080127 8212080143 8212080148 8212220140 8212260179	50-537 A 50-537 A 50-537 G 50-537 A 50-241 R
SINCHUK, J D BIMON, W A BIMON-TOV, M BINCLATR, J B BINCLATR, J B	8212270408 8211270142* 8212010478 8212070374 8212100310	71-9073 50-928 A RES 50-271 P 50-271 P	91171, W 0 81171, W 0 81171, W 0 91171, W 0 811711, C W	8212200119 8212290217 8212290355 8212290419 8212210234*	50-315 R 50-314 R 50-316 B 50-315 R 50-289 R	STARKEY,R B STARKEY,R B STARKOVICH,V S STAROSTECKI.R STAROSTECKI.R	8212070120 8212300272 8212130157 8212030065 8212030067	50~261 S 50~261 B 50~537 A 50~333 Q 50~322 Q
Binclair, J B, Sinclair, J B Binisi, J H, Binisi, J M Binisi, J M	8212210138 8212270212 8212280063 8212280258 8212280441	50-271 P 50-271 P 50-245 J 50-244 J 50-293 J	SNEAD.M H SNOW, B. A SNYDER. B J SNYDER. B J SNYDER. H L	8212270056* 8212290163 8212230384 8212280329 8212210558	CDNTRACT 50-244 R 50-320 P 50-320 P 40-6584	STARDSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8212030123 8212040189 8212040278 8212040285 8212070104	50-286 Q 50-412 Q 50-272 Q 50-317 Q 50-320 Q
BINISI, J M BINKIN, L BINKIN, L SINKULE, M V BIZEMORE, M M.	8212300333 8212060083 8212100125 8212290184* 8212019099*	50-29 J 50-498 Q 50-498 Q 50-280 Q FOIA	Soeon, L J Sollenberger, D Sollenberger, D Sollenberger, D Sollenberger, D	8212290018+ 8212070043 8212230391 8212270043 8212280048	F01A 40-2259 40-8602 40-299 40-8681	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212070151 8212070264 8212080314 8212080321 8212080347	50-387 Q 50-392 Q 50-277 Q 50-443 Q 50-219 Q
SKOLDS, J.L. SKOLDS, J.L. SMEDIRA, C. SMITH, A SMITH, A.L.	8212070034* 8212090545* 8212230037 8212170359* 8212300303*	50-395 @ 50-395 @ 71-9096 50-321 P GA999	SOLLENDERGER.D SOMERVILLE.K G SOO.P. SOONG.A SOONG.A L	0212280079 0212280435 0212020010 0212080695* 0212100180*	40-8452 40-8783 RE8 70-698 70-1334	STARDSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212100007 8212140074 8212140098 8212140124 8212140137	50-317 0 50-213 0 50-271 0 50-272 0 50-247 0
Smith, C. N. Smith, O. Smith, O. H Smith, I. H.	8212080018# 8212290479# 8212290443* R212160103# 8212200102	70-143 50-219 Q 50-272 Q FOLA 50-454 Q	BPANGENBERO.F BPEER.M J SPEIS.T P. SPEIS.T P. SPEIS.T P	6210190729 6212270106* 6202160460* 6204010021* 6209220450*	50-522 B 50-204 R 50-255 P 50-155 P 50-331 P	BTARDSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212140150 8212140311 8212140322 8212140397 8212140424	50-334 0 50-320 0 50-423 9 50-220 9 50-412 0

	ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	NUMBER 	CATEGORY 50-410 Q 50-309 Q 50-220 Q 50-293 Q 50-277 Q	STERNBERG. D M STERNBERG. D M STERNBERG. D M STEVENSON. J D	8212300268 8212300308 8212300320 8212300350 7906040228*	50-508 Q 50-397 Q 50-508 Q 50-312 Q 50-237 P	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8212170110 8212170392 8212210010 8212210013 8212230220	50-312 P 50-346 P 50-313 P 50-313 P 50-277 P
STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R	8212210015 8212210025 8212210038 8212210084 8212210131	50-293 F 50-293 Q 50-272 F 50-217 Q 50-220 F	STEVENSON, J D STEVENSON, J D STEVENSON, T D STEWART, A E STEWART, J P	8212060458 8212270221 8004010318* 8212200057 8212060170*	NUREQ NUREQ 50-237 P PRM 50-362 Q	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	82122703B1 8212280071* 8212280074* 8212290022 8212290288*	50-302 P 50-346 P 50-346 P 50-313 P 50-312 P
STAROSTECKI,R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212210149 8212210174 8212210177 8212210177 8212210213 8212210270	50-27 F 50-277 F 50-333 F 50-322 F 50-443 Q	STEWART, R C STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8212030156* 8212060134 8212060284 8212060303 8212070169*	50-445 G 50-280 P 50-280 P 50-280 P 50-280 G	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8212270297* 8212270450 8212300187 8212300193 8212300337*	50-312 P 50-321 P 50-321 Q 50-346 F 50-289 P
STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212210275 8212210305 8212210334 8212210344 8212210409	50-271 F 50-213 F 50-334 F 50-309 F 50-3 F	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, H L	8212090217* 8212090286* 8212090419 8212090485* 8212130319	50-280	STOUT, R B STOUT, R B STRASINGER, R STRATOULY, D STRATOULY, D	8212270206+ 8212270215+ 8212070184 8212270299+ 8212270301+	50-237 P 50-358 0 50-275 P 50-275 P
STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212210453 8212220361 8212220364 8212220386 8212220402	50-219 Q 50-213 Q 50-3 Q 50-309 Q 50-293 Q	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8212130326 8212130327 8212150048 8212150059 8212170041*	50-33B P 50-281 P 50-33B P 50-280 F 50-280 F	STRATOULY, D C	8212270310# 8212270312# 8212270237# 8212270243# 8212270250#	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P
STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R	8212220412 8212220413 8212220417 8212220418 8212220423	50~277	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8212170457* 8212210187 8212270179 8212280073 8212280201	50-280 F 50-338 P 50-280 F 50-281 P 50-338 P	STREETER, J STREETER, J STREETER, J STREETER, J STRSETER, J	8212210247 8212220207 8212270151 8212270276	50-263 6 50-237 8 50-346 8 50-263 8
STARDSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8212220430 8212220444 8212220451 8212220453 8212220459	50-309 Q 50-272 Q 50-244 Q 50-322 Q 50-289 Q	STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8212280257 8212280257 8212280349 8212270171 8212270238	50-280 P 50-337 P 50-280 P 50-280 P 50-280 R	STREETER.J F STREETER.J F STREETER.J F STREETER.J F STREETER.J F	8212030021 8212030121 8212030134 8212030187 8212040034	50-255 0 50-282 0 50-254 0 50-10 0
STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R BYAROSTECKI, R	8212220464 8212220466 8212220476 8212220470 8212270358	50-289	STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8212270248 8212270261 8212270264* 8212270317 8212270459	50-338 P 50-280 G 50-280 G 50-338 R 50-281 G	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8212040044 8212170174 8212210341 8212270178 8212270447	50-10 G 50-346 G 50-373 G 50-346 G
STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8212270065* 8212270280 8212270350 8212270371 8212270373	50-244 S 50-334 G 50-320 G 50-287 G 50-184 G	STICKLEY, T H STICKLEY, T H STIEDE, W L STIEGELMEYER, W STILL, N L	8212010519* 8212080551* 8212280448* 8212270056* 8212230387	50-352 A 50-443 A 50-454 G 50-289 P Waste Mot	STREIT.JE STRIP.DR STRIP.DR STUCKY.S W STUCKY.S W	8212130110 8212220204 8212130252 8212160297	NUREG NUREG 50-247 G 50-289 G 80-537 G
STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STASCO.W M	8212270422 8212270436 8212270463 8212270488 8212270530*	50-293	STILL,N L STILWELL,T C STOBER,G J STOLZ,J STOLZ,J F.	8212290240 8209230258* 8212070140 8212290026 8212010140	50-237 G 50-346 F 50-302 P	STUCKY, S W STUCKY, S W STUCKY, S W STUCKY, S W	821220224 8212280326 8212300010 8212230241	70-143 50-247 0 50-413 0 50-247 0
STASEK, S STEELE, R L STEFANO, J J STEFANO, J J STEFANO, J J	8212170201* 8212030011 8212070451 8212080019 8212080021	50-10 Q 50-344 S 50-440 A 50-440 G 50-440 A	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8212010164* 8212010172* 8212010173* 8212010276* 8212010330*	50-302 P 50-269 P 50-269 P 50-302 P	SULLIVAN, M D SULLIVAN, W H SUMMERS, R SUMNER, H L SUMNER, H L	8212020095 8212020297* 8212020295* 8212030174*	50-155 P 50-272 0 50-366 6 50-321 8
STEFAND, J J STEFAND, J J STEGER, W A STEGER, W A	8212080115 8212270002 8212300077 8212070404 8212230241	50-440 A 50-440 E 50-440 A FOIA 50-247 0	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8212010332* 8212010342 8212010368* 8212010418* 8212010488*	50-289 P 50-322 A 50-249 P 50-269 P	SUMMER, H L SUMMER, H L SUMMER, H L SUMMER, H L SURMETER, J J	8212070173* 8212070173* 8212070217* 8212300102* 8212020121	50-366 8 50-321 8
STELLO, V STELLO, V STELLO, V STELLO, V STELLO, V	6212020072 8212080097* 8212080227 8212090141 8212170245	REVIEW GRP 70-143 GRG REVIEW GRP REVIEW GRP	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J, F	8212030337 8212040024 8212040147 8212040310 8212040313	50-346 P 50-312 Q 50-287 P 50-269 Q * 50-269 Q	SURMEIER, J J GUTHERLAND, W A GUTHERLAND, W A SUTTON, J W GVENSSON, B A	8212200072* 8212200072* 8212070167* 8212170268*	50-440 0 50-440 0 0 04977 50-316 5
STELLO, V STELLO, V STEPHENBON, C J STERN, H J STERNBERO, D	8212280408 8212270062 8212140239* 8212230241 8212060163	REVIEW GRP REVIEW GRP 50-287 S 50-247 G 50-312 G	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	9212070459 92120806529 9212090040 9212090044 9212100365	* 50-346 F 50-346 P 50-269 F 50-277 P	SVENSSON, B A SVENSSON, B A SWALLOUS, J M SWANSON, D T SWANSON, E R.	8212200122 8212270228 8212210323 8212210331 8212280231	* 50-314 R * 50-391 0 50-537 0 * 50-315 0
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8212060173 8212060205 8212060260 8212060384 8212090546	50-243	STOLZ, J F. STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8212100393 8212100414 8212100453 6212100481 8212100488	50-346 P * 50-346 P * 50-346 P	SWANBON, E R SWARTZ, E D SWARTZ, E D SWARTZ, E D SWARTZ, E D	8212290335 6212220212 8212280117 8212280212 8212280343	50-10 P 50-237 P 50-237 P 50-237 P
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8212130207 8212130269 8212170103* 8212170354 8212210175*	50~50B Q	STOLZ.J F STOLZ.J F. STOLZ.J F. STOLZ.J F STOLZ.J F	8212130051 8212130117 8212130124 8212130124 8212160542	* 50-346 P * 50-346 P * 50-302 P * 50-313 F	SWETLAND.P SWIGER,M A SWIGER,M A SWIGER,M A	8212150169 8212200105 8212200105 8212300013 8212300013	50-440 Q 50-440 Q 50-440 Q 50-440 Q
STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M STERNBERG, D M	8212210203 8212210414 8212220213 8212280301* 8212300070	50-528 Q 50-397 Q 50-397 Q 50-508 Q 50-508 Q	STOLZ,J F STOLZ,J F STOLZ,J F STOLZ,J F STOLZ,J F	8212160544 8212160540 8212170007 8212170063 8212170089	9 50-278 P 50-312 P 1 50-277 P	SHYLER.K J SYLVESTER.E D SYRDWSKI.J H TALLEY.W T	8212280040 8212280514 8212280141 8212020205 8212130188	50-320 P * 50-312 9 50-346 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
TALNAGI. J. W TAUBER: H TAUBER: H TAUBER: H TAUBER: H	8212010074# 8212090061 8212100166 8212100267 8212130424	50-150 F 50-341 E 50-341 A 50-341 A 70-2926	TIPPS,S B TIPPS,S B TIPPS,S B TIPPS,S B TIPPB,S B	8212090149# 8212090207# 8212090254# 8212090335# 8212090341#	50-366 S 50-321 S 50-366 S 50-366 S 50-366 S	TRIPP,LE TROFE,T W TROJANOWSKI.R TROJAVSKY TROSKOSKI.W M	8212300072 8212270941 8212100126+ 8212100474 8212140160+	50-272 P MUREG 70-143 RES 50-334 0
TAUBER, H TAUBER, H TAUBER, N TAYLOR, J TAYLOR, J H	8212130427# 8212140375 8212300311 8212300328 8212130217	70-2926 50-341 F 50-341 A 50-409 P TOPREP	TIPPB.B B TIPPB.B B TIPPB.B B TIPPS.S B TIPPS.S B	8212090388* 8212090391* 8212090399* 8212090446* 8212100279*	50-366 8 50-366 8 50-366 8 50-366 8 50-366 8	TROUP, O L TROUP, G L TROUP, G L TROUBRIDGE, G F TROUBRIDGE, G F	8212090245* 8212290145* 8212290184* 8212010192 8212010192	70-924 FOLA FOLA 50-289 Q 50-289 Q
TAYLOR.J H TAYLOR.J H TAYLOR.J H TAYLOR.H TAYLOR.P	8212130233 8212130234 8212150113* 8212140474 8212040213*	TOPREP TOPREP 50-289 P NUREQ 50-389 Q	TIPPS:S B TIPPS:S B TIPPS:S B TIPPS:S B TIPPS:S B	8212100286* 8212100314* 8212140123* 8212140271* 8212140429*	50-364 \$ 50-366 \$ 50-366 \$ 50-321 8 50-366 \$	TROWBRIDGE, G F	8212010200* 8212010200* 8212020364 8212020364 8212020377	50-289
TAYLOR.P A TAYLOR.T. TERC,N M TERC,N M TERHUNE.J H	8212090360* 8212020265 8212160406* 8212220388* 8212210414*	50-389	TIPPS, 8 B TIPPS, 8 B TIPPS, 8 B TIPPS, 8 B	8212140436# 8212150011# 8212150018# 8212150037# 8212170099#	50-346 S 50-321 S 50-321 S 50-321 S 50-321 S	TROWDRIDGE,G F TROWBRIDGE,G F TROWBRIDGE,G F TSAI,N C TSAI,T	8212300246 8212300250 8212300250 8212300250 8212010036* 8005280561*	50-209 0 50-209 0 50-209 0 50-206 P 50-219 P
TERRELL, C W TERRELL, C W TESKE.M E TEST.R Z TETZLAFF.A L	#212010064# #21200230# #212280354# #7210802128	50-112 F 50-112 V 50-387 P 50-213 S 50-315 R	TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B	8212170165* 8212170202* 8212210088* 8212210196* 8212210452*	50-366 8 50-321 8 50-321 8 50-321 8 50-326 8	TECHUDI. H F TUCKER. H B TUCKER. H B TUCKER. H B TUCKER. H B	8212270307* 6212030002 8212030049 8212030060 8212060244	50-237
THADANI, H C THANUS, L THATCHER, T L THATCHER, T L THATCHER, T L	8212010396* 8212220478* 8212070172 8212070172 8212160267	50-443	TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B	8212280161* 8212280392* 8212300063* 8212300075* 8212300270*	50-346 S 50-321 S 50-366 S 50-321 S 50-321 S	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B FUCKER, H B	8212070341 8212070370 8212070079 8212070172* 8212070221	50-269 P 50-269 P 50-414 S 50-369 9 50-287 S
THAYER, T THAYER, T C THENHAUB, P G THEOFANOUS, T G THEOFANOUS, T G	8212080051* 821208084* 8212280438* 8208270032	FOIA FOIA 50-407 P ACRS ACRS	TIPPS.8 B TIPPS.5 B TIPPS.5 B TIPPS.5 B TIPPS.6 B	8212300275* 8212300281* 8212300289* 8212300290* 8212300292*	50-321 8 50-321 8 50-321 8 50-364 8 50-366 8	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8212070233 8212070235 8212070230 8212070333 8212070337	50-413 0 50-413 0 50-369 0 50-414 \$ 50-369 0
THEOFANOUS, T G THOM, T THOMAS, C J THOMAS, C O THOMAS, C O	8212010428* 8212270287* 8212030020* 8212020142 8212020311	ACRS 50-259 R 70-2792 50-461 A 50-146 P	TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8 B	8212300278* 8212300325* 8212300337* 8212300345* 8212300346*	50-366 8 50-366 5 50-321 8 50-366 8 50-366 8	TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B TUCKER.H B	8212090401 8212090420 8212090442 8212090482 8212090522	50-369 0 50-269 0 50-413 0 50-413 0 50-413 0
THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C.O THOMAS.F.A	8212080552 8212150211 8212210535 8212300072 82123040458	TÖPREP 50-20 F TÖPREP 50-423 A NUREQ	TDALBTON A L TOALBTON A L TOALSTON A L TOALSTON A L TOBIAS, M L	8212010046 8212010288 8212010292 8212010299 8212130135	50-389 M 50-389 M 50-389 M 50-389 M NUREG	TUCKER, H B	8212130069 8212130190 8212130257 8212140171 8212140263	50-269 F 50-269 P 50-413 A 50-369 S 50-413 A
THOMAS, F A THOMAS, J THOMAS, J THOMAS, J THOMAS, J	8212270221 8212140148 8212210089# 8212220473# 8212280087#	NUREO 50-219 8 50-219 0 50-219 0 50-247 F	TOBIN, W J TODD, O A TODDS, M T TODUSON, R TOMLINSON, D P	8212080139* 8212090445* 8212230235 8212280518 8212030156*	FOIA 70-1151 50-247 @ RES 50-445 @	TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B	8212140370 8212140425 8212150073 8212160044 6212160249	50-369 P 50-369 S 50-269 P 50-413 A 50-369 P
THOMAS.L. M THOMAS.M THOMAS.H THOMAS.R D THOMAS.R D	8212270207 8212070271* 8212070493* 8212040132 82123002(0*	50-414 F 50-370 G 50-327 G I&E 70-734	Tomlinson, DP Tompkins, BA Tompkins, BA Tompkins, BA Tongr, KA	8212030192* 8212200093 8212300147 8212300152 8212030137	50-34B	TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B TUCKER,H B	8212160345 8212170256 8212170290 8212200005 8212210060	50-413 A 50-413 B 50-369 P 50-369 B 50-369 B
Thomas. R. D Tromas. R. D Thomas. V. V Thompson. D Thompson. S	9212300213* 8212300240* 8212220173 8212160103* 8212140464	70-734 70-25 Nureg Foia Nureg	TONER, K A TONER, K A TONGUE, T TONGUE, T TONGUE, T H	8212130224 8212170082 8212090415 8212220207 8212170201*	50-255 P 50-155 P 50-237 B 50-237 S 50-10 Q	TUCKER, H B	8212210079 8212210145 8212210201 8212210419 8212210421	50-269 P 50-369 S 50-413 S 50-370 K 50-269 R
THOMPSON, S. E. THOMPSON, T. THOMSEN, F. T. THOMSEN, F. T. THOMSEN, F. T.	8212160773 8212280077* 8212070239 8212070239 8212270225	NUREO 50-346 6 50-522 0 50-522 0 50-522 0	TOSTE, A P TOTH, A D TOTH, A D TOURTELLOTTE, J TRAMM, T R	8219220523 8212060208* 8212130270* 8212100088 8211290530	RES 50-397 Q 50-27 Q BECY 50-454 K	TUCKER, H B	8212280327 8212230108* 8212270261 8212280331	50-413 A 50-367 F 50-269 F 50-413 A 50-269 P
THOMSEN, F.T. THOMUS, L. THOMUS, L. THOMUS, L. THOMUS, L. THOMUSERRY, R. C. THOMUSERRY, R. C.	8212270225 8212070111+ 8212140319+ 8212080071+ 8212270214	50~522 0 50~320 0 50~320 0 50~275 F 50~275 R	TRAMM.T R TRAMM.T R TRAMM.T R TRAMM.T R TRAMM.T R	8212020329 8212070177 8212070198* 8212070207* 8212070249	50-454 S 50-454 A 50-454 A 50-454 A 50-454 E	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8212290380 8212290232 8212290354 8212300093 8212300224	50-349 B 50-349 P 50-413 A 50-349 B 50-287 B
THORNE, P. D. THORNTON, P. THORNTON, P. THORPE, D. THORPE, D.	8212220238 8212210258 8212210258 8212020264* 8212150104*	NUREO 50-155 Q 50-155 Q 50-296 8 50-260 8	TRAMH.T R TRAMM.T R TRAMM.T R TRAUGER.T G TREBY.S.A	8212140243 8212170172 8212280306 8212270502* 8212010040	50-10 F 50-454 B 50-454 K CONTRACT 50-358 G	TUCKER, H B TURK, J TURK, S E TURK, S E TURK, S E	8212300264 8212280276 8212060007 8212080260 8212150131	50-207 S 50-70 G 50-302 G 50-302 G 50-362 G
THORPE.D THORSEN.E O THULL.T S THULL.T B TIEN.P.	8212150111* 8212140451 8212030189* 8212140371* 8212010469	50-296 5 50-247 0 50-245 5 50-245 6 RES	TREBY, B A TRENT, D, B TRIMBLE, D C, TRIPP, L TRIPP, L	821220001 821220509 8212100013* 8212060192* 8212020004	50-412 G 50-354 G	TURK, 8 E TURLEY, K L TWOGOOD, F J TYLER, J M TYLER, J M	9212150148* 8211270135 9212140316* 8212070330* 9212070330*	50-528 A 50-413 A 50-155 G 50-155 G
TILLHAN.A TILLHAN.A TILLHAN.A TIMHINB.D C TIPPS.6 B	8212070124* 8212150070 8212150143* 8210270018* 8212090126*	50-259 Q 50-321 S 70-143 50-397 A 50-366 S	TRIPP.L E. TRIPP.L E TRIPP.L E TRIPP.L E TRIPP.L E.	8212040178 8212040287* 8212140160* 8212210089* 8212220473*	50-334 G 50-219 G	UDALL,M K UDERITZ,R A UDERITZ,R A UMRIG,R E. UMRIG,R E	8212230341 8212030153* 8212140133* 8212010024 8212030216	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
UHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, REUHRIG, RE	8212070215 8212070200 8212070503* 8212070549* 8212070554*	50-387 8 50-389 8 50-250 0 50-335 0	VANDEWALLE.D J VANDOORN, P K VARGA, S A VARGA, S A VARGA, S A	8212280382 8212090261* 8212010462 8212030257 8212030267	50-255 F 50-413 G 50-272 F 50-247 P 50-305 P	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8212090244* 8212090273 8212090281 8212090334 8212090345	50-400 G 50-324 G 50-261 G 50-370 G 50-261 G
USRIG.RE	8212070559*	50-335 0	VARGA, B A	8212030342	50-305 P	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8212090348	50-400 0
UHRIG.RE	8212140373	50-387 A	VARGA, B A	8212040130	50-261 P		8212090354	50-327 0
UHRIG.RE	8212150048	50-335 P	VARGA, B A	8212040137*	50-261 P		8212090357	50-417 0
UHRIG.RE	8212150074	50-389 S	VARGA, B A	8212040138	50-280 F		8212090370*	50-327 0
UHRIG.RE	8212150078	50-389 S	VARGA, B A	8212040338	50-280 F		8212090400	50-390 0
UMRIG.R E	8212150129	50-389 A	VARGA, BA	8212070478*	50-295 P	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8212090486	50-327 Q
UMRIG.R E	8212150180	50-250 R	VARGA, BA	8212070482*	50-295 P		8212090497	50-390 Q
UMRIG.R E	8212150204	70-2957	VARGA, BA	8212070498*	50-305 P		8212090511	50-348 Q
UMRIG.R E	8212170127	50-335 P	VARGA, SA	8212070504*	50-305 P		8212090528	50-438 Q
UMRIG.R E	8212170269	50-389 A	VARGA, BA	8212080060	50-364 P		8212280278	50-324 S
UHR1G.R E	8212170273	50-250 P	VAROA, S A	8212080077*	50-364 P	VERRELLID M	8212280453	50-240 S
UHR1G.R E	8212170274	50-335 P	VARGA, S A	8212080083*	50-364 P	VETERE, LA	8212180008	50-247 T
UHR1G.R E	8212210101	50-389 E	VARGA, S A	8212080569	50-247 P	VETERE, LA	821220220	50-247 G
UHR1G.R E	8212210190	50-250 P	VARGA, S A	8212100012	50-280 P	VETERE, LA	8212220226*	50-247 G
UHR1G.R E	8212210348	50-389 8	VARGA, S A	8212130023	50-286 P	VETTER, DL	8212270260*	50-537 A
UHRIG,R E	8212210354	50-389 8	VARGA, B A	8212130030	50-247 P	VICTOR.R A	8212130370*	50-344 P
UHRIG,R E	8212220200	50-387 A	VARGA, B A	8212150141	50-295 P	VIETTI.A	8212130244	50-508 A
UHRIG,R E	8212270068*	50-250 Q	VARGA, B A	8212160578*	50-364 P	VIGIL.J C	8109280383*	RES
UHRIG,R E	8212270074*	50-250 Q	VARGA, B A	8212160586*	50-364 P	VINCENT.R E	8212020243	PRM
UHRIG,R E	8212270077*	50-250 Q	VARGA, B A	8212170032	50-334 F	VOGLER.B H	8212320075	50-440 M
UHRIG,R E	8212290124*	50-250 0	VARGA,S A	8212220281	50-280 F	VOGLEWEDE, J	8212230248*	50-29 P
UHRIG,R E	8212290265	50-387 E	VARGA,S A	8212220296	50-281 G	VOGT-ŁGWELL, R	6212070524*	50-250 G
UHRIG,R E	8212290357	50-335 P	VARGA,S A	8212220299*	50-281 G	VOJGT, H E	6212230355	50-341 G
UHRIG,R E	8212290359	50-335 P	VARGA,S A	8212220470*	50-261 P	VOLLMER, R H	8009270433*	50-206 P
UHRIG,R E	8212290361*	50-335 P	VARGA,S A	8212220477*	50-261 P	VOLLMER, R H	8010150236*	50-206 P
UHRIG,RE UHRIG,RO ULECK,RB ULECK,RB ULECK,RB	8212300252 8212140461 8212010240 8212020128 8212170162*	50-387 \$ 50-387 A Waste Mgt Waste Mgt 50-155 Q	VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,S A	0212220481 0212220487 0212270111* 0212270117* 0212270456*	50-280 F 50-241 F 50-3 P 50-3 P 50-295 P	VOLLMER, R H VOLLMER, R H VOLLMER, R. H VONHERRMANN, J	8010150242* 8010150246* 8010170287* 8212030265* 8212060471	80-206 P 50-206 P 50-206 P 50-275 P 50-275 P
ULIE, J	8212170189*	50-266 Q	VARGA,S A	8212290464#	50-295 P	VOTH, M H	8212030158	50-54 P
ULTRICH, J	8212130177*	50-373 R	VARGA,S A	8212290528#	50-311 P	VOTH, M H	8212070173	50-54 P
UTLEY, E E	8212100078	50-261 P	VARGA,S A	8212290532#	50-311 P	VRIESHAN, W B	8212010119*	F01A
UTLEY, E E	8212140250	50-324 P	VARGA,S A	8212290534	50-250 P	WADE, P B	8212270194*	50-368 B
UTLEY, E E	8212170210	50-324 P	VARGA,S A	8212300(pt)	50-250 P	WADE, P B	8212300059*	50-368 B
UTLEY, E E UTLEY, E E VAN BLARCOM, E VAN BRUNT, E E VAN BRUNT, E E	8212270125* 8212270155* 8212160587* 8212030031 6212060082	50-261	VARGA:S A VARGA:B A VAGGALLO:D B VAGGALLO:D B VAGGALLO:D B	8212300083 8212300195 8212020007 8212060111 8212060160	50-261 P 50-280 F 50-331 P 50-324 P 50-324 P	WAGNER, D WAGNER, D H WAGNER, M E WAGNER, P C WAGNER, P C	9212010349 8212090030 8212070165 8212010185 8212010392	50-354 C 50-335 P 50-269 Q 50-269 P 50-269 P
VAN BRUNT,E E	8212060143	50-528 0	VASSALLO, D B	821207000B	50-243 P	WAGNER, P C	8212100355	50-267 P
VAN BRUNT,E E	8212060229	50-528 5		8212070007	50-243 P	WAGNER, P C	8212210520	50-267 P
VAN BRUNT,E E	8212060240	50-528 8		8212070010*	50-243 P	WAGNER, P C	8212270421	50-267 P
VAN BRUNT,E E	8212060275	50-528 8		8212070026*	50-243 P	WAGNER, W J	8212170376*	50-206 G
VAN BRUNT,E E	8212060283	50-528 8		8212100014	50-273 P	WAKILD, C	8212160378	70-1113
VAN BRUNT,E E	8212070109	50-528 A	VASSALLO, D D VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8212130158	50-271 P	WALKER.D 1	8212280022*	70-146
VAN BRUNT,E E	8212070328	50-528 K		8212130275	50-254 P	WALKER.R	8212090415	50-237 S
VAN BRUNT,E E	8212080157	50-528 F		8212130274	50-278 P	WALKER.R	8212100261	50-373 S
VAN BRUNT,E E	8212090552*	50-528 G		8212130277	50-333 P	WALKER.R	8212210247	50-263 S
VAN BRUNT,E E	8212130216	50-528 B		8212130280	50-331 P	WALKER.R	8212220207	50-237 S
VAN DRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8212130259 8212130267 8212130292 8212130309 8212130320	50-530	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8212130284 8212130350 8212130365 8212160127 8212210007	50-220 P 50-331 P 50-331 P 50-254 F 50-263 0	WALKERIR WALKERIR D WALKERIR D WALKERIR D WALKERIS	8212270276 8212030028* 8212030197* 8212170201* 8212170094*	50-243 S 50-373 G 50-254 G 50-10 G 50-277 P
VAN BRUNT, E E	8212210075	50-528 K	VASBALLO, D B	8212210547*	50-263 P	WALLACE,E C	8212230241	50-247 0
VAN BRUNT, E E	8212210077	50-528 S		8212210552*	50-263 P	WALTON, G	8212060192*	50-412 0
VAN BRUNT, E E	8212210086	50-528 S		8212270474	50-273 P	WALTON, G	8212140043	50-412 S
VAN BRUNT, E E	8212210097	50-528 S		8212270525	50-331 P	WAMBACH, T V	8212230264*	50-27 P
VAN BRUNT, E E	8212210107	50-528 E		8212270532*	50-331 P	WANG, C H	8212150252*	50-243 F
VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8212210225 8212210237 8212270129 8212280148 8212280227	50-528 S 50-528 S 50-528 S 50-528 S	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8212270534* 8212280002 8212280003* 8212280004* 8212280007*	50-331 P 50-263 P 50-263 P 50-263 P 50-271 P	WANGLER,M E WANGLER,M E WARATO,S T WARD,E C WARD,K D	8212220070* 8212220073* 8212160267 8212300416* 8212170096*	50-461 T 50-461 T 50-522 G 50-282 F 50-255 G
VAN BRUNT, E E	8212280407	50-529 8	VASSALLO, D B	8212280027* 8212280084 8212280492 8212300143 8212140423	50~271 P	Ward, K. D	8212270305*	50-282 Q
VAN HORN, W P	8212030266*	Contract	VASSALLO, D B		50~298 P	Ward, K. D	8212270336*	50-266 Q
VAN ROOYEN, D	8212080262	Res	VASSALLO, D B		50~271 P	Warembourg, D	8212200074	50-267 R
VAN ROOYEN, D	8212280055	Res	VASSALLO, D B		50~324 P	Warembourg, D	8212200123	50-267 S
VANDEL, T E	8212030115*	50-482 g	VAUGHAN, C M		70~1113	Warembourg, D	8212210102	50-267 R
VANDEWALLE, D J	8212020351*	50-255 Q	VAUGHAN, C H	8212230085	70-1113	WAREMBOURG, D	8212270277	50-247 8
VANDEWALLE, D J,	8212070300	50-155 F	VAUGHAN, C M	8212230103*	70-1113	WAREMBOURG, D	8212270319	50-267 P
VANDEWALLE, D J	8212100218	50-155 F	VAUGHAN, D K	8212130147	Nureg	WAREMBOURG, D	8212270403	50-267 P
VANDEWALLE, D J	8212100285	50-155 F	VAUGHN, R E	8212230124*	50-249 F	WAREMBOURG, D	8212270426	50-267 8
VANDEWALLE, D J	8212170150*	50-155 Q	VAUGHN, R E	8212230134*	50-249 F	WAREMBOURG, D	8212270411*	50-267 F
VANDEWALLE, D J	8212200070	50-255 P	VERMA, T R VERNETSON, W. G VERRELLI, D M VERRELLI, D M VERRELLI, D M	8212010457	WASTE HOT	WAREMBOURG, D. H	8212200030	50-247 F
VANDEWALLE, D J	6212230275	50-255 Q		8212070009*	50-83 R	WAREMBOURG, D W	8212200035*	50-247 F
VANDEWALLE, D J	6212230242	50-155 P		8212070122	50-261 V	WAREMBOURG, D W	8212200070*	50-247 Q
VANDEWALLE, D J	8212280083	50-255 P		8212070183	50-400 G	WAREMBOURG, D W	8212200076*	50-247 F
VANDEWALLE, D J	8212280103	50-155 P		8212070229	50-400 G	WAREMBOURG, D. W.	8212200116*	50-267 F

AUTHGR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARENBOURG, D W WARENBOURG, D W WARENBOURG, D W WARENBOURG, D W WARENBOURG, D W	8212200117* 6212210024* 6212210173* 6212270328 6212290374	50-267 50-267		WESTERMAN, T F	8212070240* 8212100213* 8212100271* 8212280420* 6212020353	50-267 Q 50-278 Q 50-278 Q 50-278 Q 50-278 Q	WILLIAMSON, G O WILLIAMSON, H E WILLSEY, W B WILLSEY, W B WILSON, B D	8212280354* 8212270215* 8212020349 8212210158 8212020174	50-387 P 50-237 P 50-277 R 50-277 R XPORTLIC
WARCHBOURG, D H WARENSOURG, D H WARNICK, R WARNICK, R F WARNICK, R F	6212270371 6212270423 6212060112 6212060025 6212060416	50-247 50-267 50-329 50-358 50-329	R P S G S	WETHY.C M WETMILLER,R J WETTERHAHN.M J WETTERHAHN.M J WETTERHAHN.M J	8212170060* 8212220249 8212080288 8212080288 8212090073	50-335 F NUREO 50-358 Q 50-358 G 50-358 Q	MILSON, C MILSON, J MILSON, J MILSON, J MILSON, J MILSON, J MILSON, J	8212220265 8212020090 8212020096* 8212070086 8212090091*	NUREO 50-260 8 50-260 8 50-260 8 50-260 8
WARNICH, R F WARNICH, R F WARNICK, R F WARNICK, R F WARNICK, R F	8212140341 8212280050* 8212280054* 8212280164 8212270341		A 5 6 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8212070073 8212200089 8212200089 8212210261 8212210261	50-358	WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8212070098* 8212070130 8212070134* 8212070137* 8212070144*	50-280 8 50-281 8 50-281 8 50-281 8 50-281 8
WARNICH R F WARNICH, R F WARREN, D M WATFORD, P S WATFORD, P S	6212290391 6212290420 6212160394 6212170126* 6212280231*	50-358 50-358 PR 50-373 50-373	0 A S S	WHALEN,R J WHEELER,L WHEFLER,L L WHITE,J WHITENER,H L	B212020248* B212010375 B211040225* B212220276 B212090411*	50-249 B 50-443 E 50-443 E 50-309 B 50-389 0	WILGON, J L WILGON, J L WILGON, J L WILGON, J L	8212150067 8212150087* 8212210365 8212210383* 8212210388*	50-281 8 50-281 8 50-280 8 50-280 8 50-280 8
WATKINS.J C WATSON.M WEAVER.L U WEBN.B J WEBN.W A	8212080510 8212210210* 8212270230* 6212220265 8212270417*	RES 50-331 50-334 NUREG CONTRACT	# R	WHITFNER.H L WHITMAN.D WHITMEY.G G WHITMEY.G G WHITMEY.G G	8212290165* 8212130346* 8212060200* 8212060220* 8212210071*	50-261 0 50-298 F 50-293 5 50-293 5 50-293 8	WILSON, J Ł WILSON, J L WILSON, J L WILSON, J L WILSON, J L	8212210397* 8212280124 8212280140* 8212280152* 8212280204*	50-280 8 50-280 8 50-280 8 50-280 8 50-280 8
WEBER.M F WEEKS.E D WEEKS,J R WEGST.W F WEINRAM.E J	8212230225 8212270182 8212280031 8212020131 8212170049	WASTE MO 50-193 RES REGGD 50-322	et R A	WHITNEY.G G WHITNEY.G G WICHNER,R P WIDMANN.R K WIEDE,J	8212210153# 8212210264# 8212160564 8212230380* 8212070111#	50-293 S 90-293 S RES 40-8027 50-320 G	WILT, D D WILT, D D WILT, D D WILT, D D WINGO, M D	8212070475 8212070475 8212280317 8212280317 8212280153*	50-440 0 50-440 0 50-440 0 50-440 0 50-259 8
WEISS, D WEISS, E R WEISS, E R WEISS, E R WEISS, E R	8212160057* 8212200021 8212200021 8212210272 8212210272	40-3372 70-143 70-143 50-289 50-289	e c	WIEBE,J WIEBE,J WIEBER,A V WIEBER,A V WIESEMANN,R A	8212140319* 8212270233 8212090071* 8212210246* 8210210475*	50~320 @ 50~320 \$ 70~1359 70~25 TOPREP	WINTERHOFF, D WISENBURG, M R WISHNER, J A WISMER, M C WISNER, C E	8212280449* 8212020254 8212060420 8212220265 8212010162*	50-373 8 50-498 A FDIA NUREO FOIA
WEISS, E R WEISS, E R WEISS, E R WEISS, E R WEISS, E R	8212210336 8212210336 8212220248* 8212220248* 8212280270	50-267 50-269 70-143 70-143 70-143	ç ç	WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A WIESEMANN,R A	8212010440 8212020271* 8212040245* 8212130302* 8212140247	FOIA TOPREP 50-369 P TOPREP 50-419 A	WITHERS, B D	8212030027 8212070316 8212100044 8212210201 8212270368	50-344 P 50-344 P 50-344 P 50-344 F 50-344 P
Weiss.e R Weiss.e R Weiss.e R Weiss.e R Weiss.e R	8212280270 8212300002 8212300008 8212300008	70-143 50-289 50-289 50-289 50-289	G G O	WIESEMANNR A WIESEMANNR A WIESEMANNR A WIGGINS, J T WIGGINTON, D	8212140312* 8212200062* 8212270263* 8212010422* 8212020002	50-413 A TOPREP 50-286 P 50-309 P 50-315 P	WITHERS, B D WITHERS, B D WITHERS, B D WITTENBURG, K WITTENBURG, K	8212280190 8212280283 8212280470 8212270180* 8212270487*	50-344 B 50-344 P 50-344 P 50-373 B 80-373 B
WEISS,E R WEISS,E R WEISS,E R WEISS,E R WEISS,T	9212300242 9212300242 9212300362 9212300362 9212230276	50-289 50-289 50-289 50-289 50-247	6 6 6 U	MICHL' F H MICCINTON' D F MICCINTON' D F MICCINTON' D F	8212070472 8212010452 8212160573 8212270453 7907180391*	50-295 P 50-295 P 50-316 P 50-295 P 50-409 P	WIZNER, D O WIZNER, D O WIZNER, D O WIDFORD, A W WOFFORD, A W	8212060057# 8212140165# 8212170276# 8212010371# 8212010393#	50-314 8 50-315 8 50-315 8 50-322 A
WELLS.D J WELLS.D A WELLS.D A WELLS.R W	8212020173 8212210443 8212270359 8212270352 8212020200	REGGD 50-341 50-341 50-341 TOPREP	s s s	WILBER, H A WILBERN, L WILBERN, L WILDUNG, N WILHELM, D	8212290078* 8212100293* 8212210250* 8212220265 8212130157	50-250 Q 50-285 Q 50-313 Q NUREO 50-537 A	WOFFORD.A W WOFFORD.A W WOLF.J F WOLF.J F WOLF.B J	8212010397* 8212010401* 8212020374 8212020379 8212020342	50-322 A 50-322 A 50-522 0 50-522 0
WELLS,R W WELLS,R W WELLS,R W WELLS,R W	8212020200 8212020208* 8212270188 8212270188	TOPREP TOPREP TOPREP TOPREP TOPREP		WILKES, D WILKES, T WILLETT, D WILLETT, D WILLETT, D	8212230209 8212230212* 8212300336* 8212060178* 8212210427*	WASTE MOT WASTE MOT 50-321 8 50-243 G 50-397 G	WDLFE, 9 J WOLFE, 8 J WOLFE, 8 J WOLFE, 8 J,	8212020374 8212060088 8212070137 8212070147 8212070236	50-382 0 50-382 0 50-338 0 50-338 0
WENDERLICH: R L WENGER.L O WENSLAWSKI.F A WENSLAWSKI.F A.	8212210384* 8212140131* 8212060168* 8212130294* 8212130298*	50-317 50-317 50-204 50-187 50-187	5 9 9 9	WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C	8212170162* 8212170187* 8212170253* 8212170286* 8212270318*	50-155 0 50-264 Q 50-341 Q 50-483 Q 50-456 Q	WDLFE.B J WDLFE.S J WDLFE.S J WDLFE.S J WDLFE.S J	8212150035 8212160354 8212160503 8212160515 8212270184	50-382 0 50-382 0 50-382 0 50-382 0
WENSLAWSKI.F A WENZEL.J S WERNER.R P WERNER.R P WERNER.R P	8212210185* 8212230228 8211080257 8211080257 8212070124	50-247 50-245 50-245	0 6 P F	WILLIAMS, D WILLIAMS, D H LAMAILIW WILLIAMS, J W WILLIAMS, J W	8212030028* 8212280251* 8212020374 8211040086 8212020349	50-373 Q 50-315 Q 50-461 A 50-335 S 50-335 S	WOLFE,8 J WOLIVER,J WOLIVER,J WOLLETT,8 WOLLETT,8,	8212270247 8212140205 8212140205 8212020051 8212100154	50-382 9 50-358 9 50-354 9 CONTRACT
WERNER, R P WESEL, R WESLEY, D A WESLEY, D A WESTAFER, G R	8212070124 8212270240* 8210170510* 8212030025* 8212100004	50-537 50-247 50-155	F G G	W L. RAKIJIW W L. RAKIJIW W L. RAKIJIW W L. RAKIJIW W L. RAKIJIW	8212090354 8212090403 8212100219 8212150156 8212200071	50-250 B 50-335 B 50-250 S 50-335 B 50-335 B	WOLTNER, E WOLTNER, E WOLTNER, E WONG, O WONG, T	8212030177# 8212220437# 8212270352# 8212270251 8212040513	50-336 0 70-135 70-820 PR 40-299
WESTAFER, G R WESTAFER, G R WESTAFER, G. R WESTAFER, G. R	8212140048 8212140087 8212150099 8212150105 6212220270	50-302 50-302 50-302	R F S S	W L.8maijiiw W L.8maijiiw W L.8maijiiw W L.8maijiiw W L.8maijiiw	8212210175 8212210202 8212210389 8212220441 8212280164	50-335 S 50-250 S 50-335 S 50-335 S 50-250 B	WONG, T WONG, T WOOD, E C WOOD, R S WOODHEAD, C P	8212230184 8212270074 8212220456 8212140471 8212070013	40-299 40-299 50-309 8 NUREQ 50-142 Q
WESTAFER. G R WESTAFER. G R WESTBROOK, K B WESTERMAN, T. F WESTERMAN, Y F	82122202B4 8212290177 8212280041 8212030156* 8212070133*	50-302 40-8786 50-445	F H 3	W L.RMAILLIW W L.RMAILLIW W L.RMAILLIW W L.RMAILLIW W L.RMAILLIW	B212280170 8212280359 8212280418 8212290153 8212300041	50-250 8 50-335 8 50-335 8 50-250 R 50-335 8	WOODHEAD, C P. WOODRUFF, R L.	8212070228 8212140456 8212280139 8212280151 8212280355	50-440 0 50-142 0 50-341 0 50-341 0 9tate Prog

PERSONAL AUTHOR INDEX

	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AUTHOR	MOUSEN					R	ZIMMERMAN, J V	5515516166	WEDGE 10
HOODRUFF, R L	8212090470	State Prog	YUNDT, C P	8212290201 8212220437*	70-135		ZIMMERMAN, J V	8212010199	XPORTL IC
	8212080200*	50-187 R	ZIBOLSKY H		70-B20		ZIMMERMAN, J V	6212010461	XPORTLIC
MOODS: 7	B212300054	50-440 Q	ZIBULSKY, H	B212290352*	70-1100		ZIMMERMAN, J V	8212020044	XPORTL IC
HOODSIDE P	8212140427*	50-412 G	ZIBULSKY, H	82122703634				8212020169	XPORTL 1 C
HOOLEVER, E J HOOLEVER, E J	8212220283	50-412 M	ZIMMERMAN, D A	6515550538	NUREG		ZIMMERMAN, J V	8212020181	XPORTLIC
	8212220403	50-412 A	ZIMMERMAN, J V	8212010041	XPORTLIC		2 IMMERMAN, J V	8212020198	XPORTLIC
MOSLEYER, E J	6212220404*	50-412 A	ZIMMERMAN, J V	8212010043	XPGRTL1C		2 INMERMAN, J V	8212070469	XPORTLIC
MOOLEVER'E'	8212060004	40-8084	ZIMMERMAN J V	8212010074	XPORTLIC		ZIMMERMAN, J. V	8212070502	XPORTL IC
WOOLSEY R T		40-8084	ZIMMERMAN, J V	8212010081	XPORTLIC		ZIMMERMAN, J V	8212070506	XPORTL IC
HODLSEY, R T	9212280076 8212090439*	70-27	ZIMMERMAN, J V	8212010088	X PORTL I C		ZIMMERMAN, J V	8212080002	XPORTL10
HRAY, J R	8212040434#	/U-Z/					77145-0145-11		
		50-338 Q	ZIMMERMAN, J V	8212010093	XPORTLIC		ZIMMERMAN, J V	8212080003	XPORTL1¢
A C.YARH	8212090505*	50-155 Q	ZIMMERMAN J V	8212010095	XPORTL I C		ZIMMERMAN, J V	8212080004	XPORTLIC
MRIGHT, G C	8212080522*		ZIMMERMAN, J. V.	8212010101	XPORTL I C		ZIMMERMAN, J V	8515080019	XPORTL10
MEIGHT, G N	8212280176		ZIMMERMAN, J V	8212010106	X PORTLIC		ZIMMERMAN, J V	6515080532	XPORTLIC
HRIGHT, N. A	8212040014		ZIMMERMAN, J V	8212010194	XPORTLIC		ZIMMERHAN, J V	8212080244	XEGETLIC
HAIGHT, N. A	8212270005	50-329 G				_			
			YOUNG, T	B212050347	50-312	8	ZIMMERMAN,J V	9212080529	XPORTLIC
WRIGHT R J	8212010010	WASTE MOT	YOUNG, T	8212130209*	\$0-52 8	a	ZIMMERMAN, J V	8212080534	XPORTLIC
WRIGHT R J	8212010242	WASTE MOT	YOUNG, T	8212130215*	50-528	a	ZIMMERMAN, J V	8212080538	XPORTLIC
HRIGHT, R J	8212010245	WASTE MOT	YOUNG, T	B212170394*	50-361	G	ZIMMERMAN, J V	8212170008	XPORTL 1C
HRIGHT, R. J	8212020136	WASTE MOT	YOUNG, T	8212170397*	50-341	Q	ZIMMERMAN, J V	8212170023	XPORTLIC
HRIGHTIR J	8212020183	WASTE MOT							
			YOUNG, T	8212210211*	50~528	a	71MMERMAN, J V	8212170029	XPORTLIC
WRIGHT,R J	8212020403	WASTE MOT	YOUNG, Y A	6212030235	40-8745		ZIMMERMAN, J V	8212230426	XPORTLIC
WULFF. W	8212040128	RES	AUCHGBroop' B 1	6212010020#	50~45 6	A	ZIMMERMAN, J V	8212270072	XPORTLIC
WULLER G E	8212060105	50-461 A	AGONG BLOOD! B 7	8212010049	50~483	G .	ZIMMERIJAN, J V	6212270074	XPORTLIC
MULLER, G E	8212070125	50-461 E	YOUNGILDED, B J	8212070448	SQ-395	Ę	ZIMMERMAN, J V	8212270096	XPORTLIC
WULLER, G E	8212070200	50~461 E	1004444444					0210270070	AT OR I CAG
MOLLERY & C			ADONÖBLOOD'B 1	8212070458	5Q-35B	A	ZIMMERMAN, J V	8212270078	XPORTLIC
WULLER, G E	8212070229	50-461 F	AUCHGBEGOD: B 7	8212070460	50-440	E	ZIMMERMAN, J V	8212280178	XPORTLIC
WULLER, O. E	8212170303	50-461 A	YOUNGBLOOD, B J	8212070466	50-440	Α	ZIMMERMAN, J V	8212300143	XPORTLIC
MULLER, O. E	8212170330	50-461 E	AUNOBITOOD! B 1	8212080001	50-358	F	ZIMMERMAN, J V	8212300148	XPORTLIC
WULLER, O E	8212210313	50-461 A	YOUNGBLOOD, B J	8212080114	50-544	A	ZINMERMAN, J V	8212300170	XPORTLIC
	6212220233	50-461 A	ADDMOREGODS B. O.	GE: LODG: 1	-		I II I I I I I I I I I I I I I I I I I	9515300130	YEARICIC
HULLER, O E	0212220200	00 122	ADONGBEQDD'B 1	8212100094	50~375	P	ZIMMERMAN, J V	8212300153	XPORTLIC
	8212280235	50~461 A		B212100101*	50-395	P	ZIMMERMAN, J V		
MULLER O E	8212260233	50-461 E	ADINGBEDOD' B 7	8212100110*	50-375	P		8212300173	XPORTLIC
WULLER, G E		40-4940	AUTHORICOOD'B 1	8212170084#	50-341	A	ZIMMERITAN, R Ł	8212060444	50-255 s
HYNGARDEN, 8	8212230389	40-6940	AGAMORFOOD # 1	8212230385	50-440	Ä	ZIMMERMAN, S R	8212070013	50-241 P
HYNGARDEN, 9 D	8212020122	40-8027	ADONGBEGOD'B 1	P512530393	30 110	••	ZIMMERMAN, S R	8212070307	50-324 P
MYNGARDEN, S. D.	8212160659	40-8027		681 6826633	50-492	F	77504550000000		
		XPORTLIC	AUNNGBEGOD' B 1	8212270022 8212270061	50~423	Å	ZIMMERMAN, S. R.	B212100015	50-241 F
AANVNA K	8212160796		AGNIGHTOOD'B 1		50-395	P	ZIMHERMAN, S R	8212100021	50-24! P
YANDELL, L A	8212030126*		AONNOBEDOD' B 7	8212290067	50-375	P	ZIMMERMAN S R	8212100032	50-324 F
YANDELL, L A	8212100247		ADONGBEGGD'B 1	8212270071*	50-375	p	ZIMMERMAN, S R	8212130313	50-241 Q
YANICHKO, S E	8212140420*		AGAMBBCGOD'B 1	8212270081*	50-343	-	ZIMMERMAN, 8 R	851551009B	50-261 P
YARGER, K	8212170167*	50-346 S			E 0 E 4 4	F			
			ADOMOBEDOD'B A	9212270478	50-546	F	21MMERMAN, S R	821221041B	50-261 P
YARNICK, T. P.	8212230063	40-B102	ADANGBEGOD'B 1	8212270502	50~546	Č	ZIMMERMAN, S R	8212260078	50-261 P
YIN. I T.	8212270400#	50-275 Q	ADNMGBFCOD' B 1	8212300023	50-423		ZIMMERMAN, S R	8212280112	50-400 C
YDRE, J.R.	8212010139*	FOIA	YOUNGBLOOD, B J	8212300086	50-546	Q	ZSCHALER,W A	8212170101*	50-277 P
YOUNG, F	8212220476*	50-289 Q	YUAN, C Y	8212020126	RES		ZURAKONSKI P R	8212300213¥	70-734
YOUNG, O.	8212070184	50-358 G	•			_			
, 201101 01			YUHAB, C P	8212040148*	50-206	ā	ZWETZIQ. G B	8212130171*	50-275 Q
YOUNG, O C	8212270466*	50-327 Ö	YUNDTIC P	110000118	50-344	5	ZWETZIO, O B	8212210204*	50-361 q
YOUNG G 8	8212230084	40-6659	YUNDT C P	8212070343	50-344	R			
YOUNG, J A	8212220193	NUREO	YUNDT, C P	8212100411*	50-344	F			
YOUNG, T.	8212060167*	50-312 Q	YUNDT, C P	8212140346	50-344	8			
YOUNG, T	8212040171*	50-312 G	I MIRM I LA .						
1 animar 1									

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
AWC, Inc. Aamodts, The Advanced Medical Systems, Inc.	8212270479 8212010195 8212020346 8212020401* 8212160043	71-6144 50-289 0 50-289 0 50-289 0 71-5796
AeroVironment, Inc Alabama Power Co	8212040334* 8212020130 8212020182 8212070334 8212070273	40-8743 50-348 P PR 50-364 Q 50-364 B
	8212090312* 8212090342 8212090412 8212100070 8212100217	50-364 B 50-348 Q 50-348 Q 50-348 F MISC
	8212150033 8212170197 8212170207* 8212170234 8212170297	50-364 P 50-348 R 50-348 R 50-364 P 50-364 R
	8212170302* 8212210130 8212210132* 8212280280 8212300214	50-364 R 50-364 P 50-364 P 50-348 P 50-364 S
Alden Research Laboratory	8212300223* 8212300227* 8212300231* 8212300234* 8212270520	50-364 S 80-364 S 50-364 S 50-364 S NUREG
Alderson Reporting Aldrich Chamical Co : Inc. (subs. of	B212100048 B212270065* B212270131* B212280044* B212300155	50-329 T FOIA FOIA CONTRACT XPORTLIC
Bigma∽Aldrich Corp.)	8212300158 8212300163 8212300164 8212300166 8212300166	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Allied Chemical Corp. Allied General Nuclear Services Allied-Crossroads Nuclear Corp	8212300180 8212300181 8212140040 8212070405 8212160131*	XPORTLIC XPORTLIC 40-3392 50-332 0 40-4500
American Electric Power Service Corp American Nuclear Insurers Amersham Corp. Anabeim, CA	8212140193* 8212100253 8212300174 8212150230 8212030148*	40-4500 50-315 J 50-219 0 71-9167 50-361 P
Andrulis Research Corp. Anthony, R L Antioch School of Law, Washington, DC	8212220027* 8212230352 8212230354 8212020361	CONTRACT 50-352 0 50-352 0 50-155 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	٧
Applied Physical Technology, Inc Argonne National Laboratory	8212070247 8212070303* 8212280292 8212060386* 8212010151	50-155	0 0 0
	9212060429 9212060441 9212060447 9212060451 9212060455	NUREG NUREG NUREG NUREG NUREG	
	8212070077 8212070083* 8212070431 8212070438 8212080668*	50-247 50-247 ACRS ACRS 50-373	D 0
	8212080470* 8212080473* 8212130143 8212130147 8212270250*	50-373 50-373 NUREO NUREO 50-537	P P
Arizona Public Service Co	8212270260* 8212270468 8211290135 8212030031 8212030031	\$0-537 NUREG \$0-528 \$0-528 \$0-528	A A E
	8212030031 8212040082 8212040143 8212040229 8212040240	50-528 50-530 50-528 50-528 50-528	E 9 6 5 5
	82120 60275 82120 60275 82120 60275 82120 60283 82120 70109	50-528 50-528 50-528 50-528 50-528	8 8 8 8 8
	8212070328 8212070328 8212070328 8212070331* 8212080157	50-528 50-528 50-528 50-528 50-528	KKKKF
	8212080157 8212080157 8212070552# 8212070552# 8212070552#	50-528 50-528 50-528 50-528 50-528	F 0 0
	8212130146 8212130216 8212130259 8212130267 8212130267	70-2949 50-528 50-530 50-528 50-528	9 8 8 9
	8212130267 8212130292 8212130292 8212130309 8212130320	50-528 50-528 50-528 50-530 50-528	808

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	, 	AUTHOR AFF ILIATION	ACCESSION NUMBER	GUBJECT CATECORY	
	8212210075 8212210077 8212210077 8212210077 8212210077 8212210086	50~528 50~528 50~528	K 5 5 8 8		6212270223* 6212270234 8212270234* 8212270321 6212270321	50-368 8 50-368 8 50-368 8 50-313 8	₹
	8212210084 8212210084 8212210097 8212210107 8212210225	50-528 50-528 50-528	8 8 5 5 5		8212300052 8212300057 8212300059# 8212300042# 8212300088	50-368 50-368 50-368	6 8 9 8
	6212210237 6212270129 6212280148 6212280227 6212280227	50-528 50-528	8 A S G S	Arkansas Tech Univ Army, Dept of Army, Dept of, Corps of Engineers	8212300090* 8212010423* 8212280485* 8212220542* 8212270412*	50~368 CONTRACT CONTRACT CONTRACT CONTRACT	5
Artansas Power & Light Co	8212280407 8212030066 8212030075* 8212030097 8212030169	50-529 50-368 50-368 50-313 50-313	3 3 3	Atlas Minerals	8212030281 8212030282* 8212270401 8212270405* 8212290123	40-3453 40-3453 40-3453 40-3453 40-3453	
	8212060087 8212060262 8212060362 8212060333 8212060333	50-313 50-313 50-313 50-313 50-313	ե ե ե ն	Atomic Industrial Forum BNR Cwners Group Babcock & Wilcox Co.	8212020380 8212160431 8212300034 8212300036* 8212070487*	ORO PR TOPREP TOPREP 70-824	
	8212070284 8212070264 8212080082* 8212080082* 8212080085*	50-313 50-313 50-313 50-313 50-313	P P F F		8212130067# 8212130217 8212130220# 8212130233 8212130234	70-27 TOPREF TOPREF TOPREF TOPREF	
	8212090311 8212090311 8212100385* 8212100394* 8212140334	50-313 50-313 50-313 50-313 50-346	F F G		8212150113* 8212160086 8212160426 8212230025 8212230011*	50-289 71-5814 71-5086 70-1201 70-1201	P
	8212140481 8212150268# 8212140762# 8212140787# 8212170018#	50-313 50-313 50-313 50-313 50-313	0 F F F		8212270042* 8212270047* 8212270404 8212270537 8212280401*	50-289 50-289 70-27 70-27 QA999	P
	8212170025* 8212170113 8212170215 8212170448* 8212170453*	50-313 50-313 50-348 50-313 50-313	r ₽ F F	Backus, R A Baltimore Cas & Electric Co	8212140426 8212230334 8212010050* 8212010055* 8212040071	50-443 80-443 50-317 50-317 50-317	0 F F
	8212210027 8212210028* 8212210039 8212210117 8212210120*	50~368 50~368 50~368 50~368 50~368	2 2 3 3		8212060071 8212060147 8212060196 8212060206# 8212060293#	50-317 50-317 50-317 50-317 50-317	0 8 8
	8212210166 8212210169* 8212210193 8212210198* 8212210257	50-313 50-313 50-368 50-368 50-368	S S S S		8212060301 8212060306* 8212070054 8212070054 8212080197	50-317 50-317 50-317 50-317 50-317	9 6 6 6
	8212210260* 8212210514* 8212210531* 8212210534* 8212210539*	50-348 50-313 50-313 50-313 50-313	8 F F F		8212080197 8212080441 8212080448* 8212080456 8212080456	50-317 50-317 50-317 50-317 50-317	P 6 9 9
	8212220002# 8212220004# 8212230165# 8212230165# 8212230172#	50-313 50-313 50-313 50-313 50-313	F F F		8212080491 8212130065 8212130065 8212140125 8212140131*	50-317 50-317 50-317 50-317 50-317	F F 8 8
	8212230172* 8212270143 8212270189 8212270194* 8212280072	50-313 50-313 50-368 50-368 50-368	F 6 6 6 5 5		8212140412 8212160259 8212160270+ 8212160364 8212170252	NUREQ 50-317 50-317 50-317 50-317	8 8
	8212280142 8212280146* 8212280224 8212280224 8212280307	50-368 50-368 50-313 50-313	8 6 7 8 9		8212170349 8212200088 8212210043 8212210048* 8212210076	50-318 50-318 50-317 50-317	о Р В В
	8212280309* 8212280459 8212290168 8212290168 8212290171*	50-313 50-368 50-313 50-313 50-313	P R R R		8212210080* 8212210274 8212210303* 8212210378 8212210384*	50-317 50-317 50-317 50-317 50-317	8
	8212290171# 6212290194 8212290196# 8212290198# 8212290212	50-313 50-313 50-313 50-313 50-368	R R R Q 9		8212210420 8212210420 8212210447 8212210448* 8212220208	50-317 50-317 50-317 50-317 50-317	P P

AUTHOR AFF ILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	RY	AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEODI CATEODI	
	8212220208 6212220210* 6212220210* 6212230274 6212230274	50-317 50-317 50-317 50-317 50-317	R R Р		8212030239 8212030323 8212040005 8212040119 8212040128	RES 50-537 RES RES	Α
	8212230312 8212280179 8212280202* 8212280208* 8212270120	50-318 50-318 50-318 50-317 50-318	ե Ե ե		82120 70400 82120 7047 i 82120 80262 82122 70534 82122 8003 i	res res res res res	
	8212270122 8212270275 8212270282* 8212270338 8212300209*	50-318 50-317 50-317 50-318 50-317	С 8 8 8		8212280040 8212280051 8212280055 8212280514 8212280518	res res res 50-320 res	P
Batteile Memorial Instituta, Columbus Laboratories	8212300209* 8212300211* 8212300211* 8212140476	50-317 50-317 50-317 NUREQ 71-5957	F F	Burns & Roe Co C-E Operating Plants Owners Group	6515540168 6515050515* 6515050508* 6515050500 8515010012*	50-537 TOPREP TOPREP TOPREP TOPREP	r
	8212150218* 8212270054* 8212270420 8212270521* 8212270543*	71-5957 50-289 NUREQ CONTRACT		C F Braun & Co CONDCO,Inc (Continental Oil Co) Califernia, State of	8212080562 8212060330 8212270145 8212020251 8212220394	50-373 40-8743 40-8743 PR 50-275	Р G
Battelle Memorial Institute, Pacific Naithwest Laboratory	82120150165* 8212010115 8212010483 8212210529	NUREG RES 71-5957	F	California, Univ of, Bavis California, Univ of, Los Angeles	8212280542 8212270227 8208290029 8212020131 8212270445*	NUREO 50-322 ACRS REGOD FOIA	т
	8212220193 8212220238 8212220265 8212220341 8212220460 8212220509	NUREO NUREO NUREO NUREO 50-341 NUREO	Г	Canada Canada, Atomic Energy Control Board Canadian Commercial Corp Carolina Environmental Study Group	62121 A0134 62121 A0148* 62121 A01484 6212270484 6212220247 8212280132	71-454 71-454 XPORTLIO NUREO 50-413	G
	8212220523 8212270033 8212270232 8212270449 8212270456	RES NUREG NUREG NUREG NUREG		Carolina Power & Light Co	6212280138 6212280138 6212280138 6212020083* 6212020152	50-413 50-413 50-413 50-324 50-324	6 6 8 8
	8212270487 8212270512 8212270559 8212300137 8212300402	NUREO NUREO NUREO RES RES			8212020161* 82120201273 8212020277* 8212020306	50-324 50-324 50-324 50-325 50-325	888
Battelle New England Marine Research Laboratory	8212210044*	50-219	R		8212020312* 8212020317* 8212020362	50-324 50-324 50-324	9 9
Bear Creek Uranium Co Bechtel Corp	8212270157 8212270161* 8212020173 8212140072	40-8452 40-8452 REGOD TOPREP			8212020365* 8212060013 8212060069	50-324 50-261 50-261	9 P
Beveridge, Fairbanks & Diamond	8212170276# 6212230304* 6212100104 6212140245	50-250 50-275 50-338 50-338	P G G		8212060199 8212060201* 8212070008 8212070012*	50-261 50-261 50-325	R R S
Bastan College	8212140245 8212140249 8212140249 8212220328#	50-338 50-338 50-338 CONTRACT	6 6 7 8		8212070043 8212070043 8212070112 8212070118*	50~400 50~400 50~325 50~325	9 9
Boston Editon Co	8212040178 6212040200* 8212040210 6212040220* 6212040272*	50-293 50-293 50-293 50-293 50-293	35 89 F		8212070208 8212070214* 8212070273 8212070275* 8212070305	50~325 50~325 50~324 50~324 50~400	8090
	8212100031 8212130037 8212140139 8212150224*	50-293 50-293 50-293 50-293	F F P Q		8212070305 8212070100 8212070105* 8212070120	50~400 50~325 50~325 50~261	ខាចខាច
	8212150233# 8212170305 8212170310#	50-293 50-293 50-293	g P P		8212070128* 8212070135 8212070137* 8212070147	50~261 50~325 50~325 50~325	5 5 5 5
	8212210067 8212210071* 8212210148 8212210153* 8212210249	50-293 50-293 50-293 50-293 50-293	ខ្លួន		8212090152* 8212090167 8212090173* 8212090237*	50~325 50~325 50~325 50~400	5 6
Watch and Mount House	8212210264* 8212210458 8212210462* 8212270433*	50-293 50-293 50-293 50-293	8 0 0 0 F		8212090289* 8212090307 8212090307 8212090314	50-324 50-324 50-324 50-324	Q P P
Brigham Young Univ Brookhaven National Laboratory	8212160734* 8212160742* 8212020010	80-895 20-595	۲		8212090318* 8212090375 8212090453 8212090443*	50-324 50-324 50-325 50-325	8 9 8

AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
40	8212090535 8212090542* 8212090543 8212090550* 8212100015	50-325 50-325 50-325 50-325 50-325	5 5 5 7		8212290125* 8212290125* 8212290200 8212300067 8212300221	50-261 50-261 50-261 50-324 50-325	0 0 0 0 5
	8212100021 8212100032 8212100078 8212100078	50-261 50-324 50-324 50-261 50-324	Р Г Р Р		8212300225* 6212300227 6212300256 8212300257 6212300259*	50~325 50~325 50~325 50~325 50~325	90000
	8212100085* 8212100099 8212100099 8212100241 6212100241	50-324 50-400 50-400 50-324 50-324	P G G R R		8212300262* 8212300272 8212300296* 8212300307 8212300309*	50-325 50-261 50-261 50-325 50-325	5 5 5 5
	6212100250# 6212100250# 6212130161 6212130317#	50-324 50-324 50-400 50-261 50-261	R R A Q Q		8212300316 8212300317* 8212300326 8212300326 8212300331	50-325 50-325 50-400 50-400 50-325	9999
	8212140153 8212140159* 8212140194 8212140202* 8212140250	50-325 50-325 50-325 50-325 50-324	5 5 5 6 6 8	Carpenter Technology Carp Catalytic, Inc (subs of Air Products & Chemicals, Inc)	8212300334* 8212300360 8212270072 8212270105 8212200060	50-325 50-325 XPORTLIC XPORTLIC PRM	
	8212140250 8212140255 8212140257 8212140257* 8212140257*	50-324 50-324 50-324 50-324	6 6 6 6	Center for Law in the Public Interest Central Power & Light Cerac, Inc Chackes & Hoare Charlevoix,MI	8212280288 8212170131* 8212070513 8212280179 8212010438*	50-275 50-498 XPORTLIC 50-483 CONTRACT	a
	8212150004 8212150112 8212150114* 8212160036 8212170141	50-241 50-325 50-325 50-400 50-325	P 6 8 D 9		8212070337* 8212070345* 8212070349* 8212210289* 8212210292*	50-155 50-155 50-155 50-155 50-155	6 6 6
	8212170156* 8212170183 8212170210 8212170216 8212170328	50-325 50-400 50-324 50-325 50-400	9 6 9 8	Chernoff, G Chem-Nuclear Systems, Inc	8212210296* 8212060413* 8212150202 8212150206* 8212160407	50-155 CONTRACT 71-9081 71-9081 71-9151	G T
	8212170338 8212170338 8212170343* 8212170343* 8212170350*	50-324 50-324 50-324 50-324	Р Р Р	Chicago Bridge & Iron Co Christa-Maria	8212160418* 8212280541 8212290005 8212020243 8212020361	71-9151 27-47 27-47 PRM 50-155	G
	8212170350* 8212170355 8212170355 8212170356* 8212170356*	50-324 50-324 50-324 50-324 50-324	ቴ ቴ ቴ	Cincinnati Gas & Electric Co	8212070247 8212070303* 8212280292 8212010089 8212020225	50-155 50-155 50-155 50-358 50-358	0 0 A 0
	8212170363* 8212170363* 8212210004 8212210006* 8212210006*	50-324 50-324 50-324 50-324	р Р Р Р		8212020257 8212020320 8212020367 8212030111 8212060030*	50-358 50-358 50-358 50-358 50-358	9 9 9
	8212210030 8212210030 8212210059 8212210152 8212210159*	50-324 50-325 50-325 50-261 50-325	9 9 9 9		8212040039* 8212080288 8212080472 8212090028* 8212090031*	50-358 50-358 50-358 50-358 50-358	9 6 F F
	821221037* 8212210322 8212210405* 8212210418 8212210422	50-400 50-325 50-325 50-261	6 0 B B F		8212070034* 8212070073 8212070074 8212070074* 8212140340*	50-358 50-358 50-358 50-358 50-358	F G K K
	8212210424 8212210424# 8212210424# 8212220345	50-400 50-400 50-400 50-400	e e e e e e e e e e e e e e e e e e e		8212140342* 8212170080 8212170107 8212170191 8212170260	50-358 50-358 50-358 50-358 50-358	A R R G
	8212220493 8212220493 8212220488 8212220493*	50-400 50-400 50-400 50-325 50-325	លាលាកាលាលា C		8212200087 8212210031* 8212210545* 8212270170 8212270434*	50-358 50-358 50-358 50-358 50-358	G F S
	8212220446 8212220504* 8212230366 8212270222 8212270222	50-325 50-325 50-400 50-400	9 9 8 9 9 9		8212280171* 8212270277 8212270285 8212270342 8212270343*	50-358 50-358 50-358 50-358 50-358	0 8 5 8
	8212280078 8212280112 8212280363 8212280397*	50-241 50-400 50-400 50-325 50-325	P. C. C. S. S.	,	8212290364 8212290397 8212290425* 8212290429*	50-358 50-358 50-358 50-358	9 8 6 0

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212270438 8212270454* 8212270467	50-358 50-358 50-358	9 0 8	Colt Industries, Inc Columbia River Inter-Tribal Fish Commission	8212210341 8212160267	50-375 S 50-522 G
Citizens Against Nuclear Power	8212270483 8212200099	50-358 50-373	S H	Columbus & Southern Dhio Electric Co Combustion Engineering, Inc	8212090034* 8212020372 8212140501	50-358 F PR PROJ
Citizene Association for Sound Energy	9212230192 9212230182 9212230195 8212230195 9212300009	50-445 50-445 50-445 50-445	G G G	Commerce.Dept of Commerce.Dept of, National Bureau of	8212140510* 8212140004 8212170163 8212210411 8212280181	FROJ 70-1100 NUREO 50-184 S YPORTLIC
The state of the s	8212300007 8212300045 8212300045	50-445 50-445 50-445	0	Standards	8212270402*	50-184 Q
Citizens Concerned About Nuclear Power, Inc Citizens for Energy & Employment	82121 00125 82120 10191	50-498 50-341	G G	Communwealth Edison Co	821 1290530 821 1290530 821 1290559*	50-454 K 50-454 K 50-454 K
Cleveland Electric Illuminating Co	8212140377 8212140428 8212140460 8212010208 8212010208	50-341 50-341 50-341 50-440 50-440	0 0 0 0		8211290559* 8212020234 8212020237* 8212020239 8212020248*	50-454 K 50-275 S 50-275 S 50-247 S 50-247 S
	8212020276 8212020078* 8212010212 8212010212	50-440 50-440 50-440 50-440 50-440	С О К К S		8212020272 8212020274 8212020275 8212020280* 8212020282*	50-275 8 50-373 8 50-237 9 50-237 5 50-373 9
	8212020395 8212070015 8212070015 8212070237 8212070237	50-440 50-440 50-440 50-440 50-440	B II II A A		8212020285# 8212020274 8212020301# 82120203027#	50-275 S 50-373 S 50-373 S 50-373 S 50-373 S 50-484 S
	8212070358 8212070358 8212070365* 8212070397 8212070397	50-440 50-440 50-440 50-440 50-440	0 0 0 E E		8212020327 8212020337 8212020357# 8212030043 8212030054# 8212030273#	50-454 S 50-249 S 50-249 S 50-237 P 50-254 G 50-254 F
	8212080273 8212090196 8212090201* 8212090201* 8212090206*	50-440 50-440 50-440 50-440 50-440	0 0 0 0		6212030273* 6212030279* 6212030279* 6212030264* 6212030267*	50-254 F 50-254 F 50-254 F 50-10 F 50-10 F
	8212070206* 8212070475 8212070475 8212130241 8212130241	50-440 50-440 50-440 50-440 50-440	0 0 0 0		8212060029 8212060029 8212060029 8212060041 8212060041	50-237 Q 50-237 Q 50-237 Q 50-373 F 50-373 F
	8212130246# 8212130246* 8212140445 8212140445 8212160247	50-440 50-440 50-440 50-440 50-440	0 0 0 0		6212040045* 6212040084 6212040084 6212040161* 6212040207	50-10 0 50-275 P 50-275 P 50-254 F 50-237 P
	8212160247 8212160251 8212160251 8212170153 8212170153	50-440 50-440 50-440 50-440 50-440	0 0 C S B		8212040219 8212040219 8212040247 8212070065 8212070065	50-295 P 50-295 P 50-237 P 50-295 F 50-295 F
	8212170241 8212170241 8212200061 8212200061 8212200072*	50-440 50-440 50-440 50-440 50-440	93 95 96 9		8212070177 8212070177 8212070177 8212070177 8212070177	50-454 A 50-454 A 50-454 A 50-454 A
	8212200072* 8212200105 8212210321 8212210345 8212210370	50-440 50-440 50-440 50-440 50-440	0 0 0 9 5		821207019B+ 8212070207+ 8212070249 8212070249 8212070249	50-454 A 50-454 A 50-454 E 50-454 E 50-454 E
	8212210370 8212280255 8212280255 6212280291 8212280291	50-440 50-440 50-440 50-440 50-440	8: A A B S		8212070247 8212080235 8212080235 8212080249# 8212080245#	50-454 E 50-454 G 50-454 G 50-454 G 50-454 G
	9212270187 9212270187 9212270305 9212270305 9212270325	50-440 50-440 50-440 50-440 50-440	E F E E		8212080308 8212080317* 8212080318 8212080332* 8212080375	50-373 9 50-373 9 50-373 9 50-373 9 50-249 9
Cleveland: OH Coslition for Safe Power	8212290325 8212300013 8212150012 8212140418 8212160267	50-440 50-440 50-344 50-397 50-522	E O M O O		8212080381* 8212080390 8212080400 8212080404* 8212080410*	50-249 8 50-265 8 50-373 8 50-265 8 50-373 8
Coastal Chamber of Commerce of New Hampshire Colorado State Univ Colorado, State of	8212200079 8212130182* 8212160422	50-443 CONTRACT PR			8212080412 8212080413* 8212080508	50-373 9 50-373 9 50-373 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR	1Y	AUTHOR AFFILIATION	ACCESSI NUMBER		JECT EGORY
	6212080524* 6212080537 6212080537 6212080537 6212090301	50-373 50-237 50-237 50-237 50-237	5 Q Q Q P		82121402 82121402 82121402 82121402 82121402	43 50-1 43 50-1 43 50-1	0 F 0 F 0 F
	8212070336* 8212070336* 8212070383 8212070383 8212070383	50-254 50-254 50-237 50-237 50-237	Q Q F F F		821 21 402 821 21 402 621 21 403 821 21 403 821 21 404	92* 50-3 21 50-2 27* 50-2	173 Q 195 S 195 B
	8212090383 8212090383 8212090383 8212090383 8212100215	50-237 50-237 50-237 50-237 50-237	F F F S		62121400 82121403 82121700 82121700	26 50-2 34* 50-2 97 50-2	37 Q 37 Q 49 S
	8212100216# 8212100272 8212100275# 8212100312 8212100319#	50-237 50-373 50-373 50-237 50-237	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		82121701 82121701 82121701 82121701 82121701	23 50~3 26* 50~3 30* 50~2	173 S 173 S 137 S
	8212100328 8212100335* 8212100335* 8212130028*	50-265 50-454 50-265 50-10 50-10	9 9 F F		82121701 82121701 82121701 82121701 82121701	59 50-3 76* 50-3 84 50-3	173 S 173 S 173 S
	8212130028* 8212130028* 8212130028* 8212130028* 8212130028*	50-10 50-10 50-10 50-10 50-10	F F F		82121701 82121701 82121702 82121702 82121702	94* 50-0 ii 50-0 i4* 50-0	373 S 373 S 373 S
	8212130028* 8212130028* 8212130028* 8212130028*	50-10 50-10 50-10 50-10 50-10	F F F		82121702 82121702 82121702 82121702 82121702	33 50-3 39* 50-3 44 50-3	373 S 373 S 373 S
	8212130028* 8212130028* 8212130035 8212130035 8212130041*	50-10 50-10 50-275 50-295 50-10	F F P F		82121703 82121703 82122100 82122101 82122101	12* 50-1 36 50-1 38* 50-1	295 S 237 P 373 Q
	8212130041+ 8212130041+ 8212130041+ 8212130041+ 8212130041+	50-10 50-10 50-10 50-10 50-10	የ ፍ ፍ		82122101 82122101 82122103 82122103 82122104	50* 50-2 59 50-2 59 50-2	237 S 295 P 295 P
	8212130041* 8212130041* 8212130041* 8212130041* 8212130041*	50-10 50-10 50-10 50-10 50-10	E E E E		82122104 82122104 82122104 82122104 82122201	63 50-1 63 50-1 66* 50-1	373 K 373 K 373 K
	8212130093 8212130153* 8212130156* 8212130175 8212130177*	50-373 50-295 50-295 50-373 50-373	은 F R R		821 22 202; 821 22 202; 821 22 202; 821 22 202;	02* 50~1 12 50~1 31* 50~1	10 F 10 P
	8212130183 8212130194 8212130194 8212130194	50-295 50-295 50-254 50-254 50-254	G G R R R		85155505; 85155505; 85155505; 85155505;	31* 50-1 31* 50-1 31* 50-1	10 P 10 P
	8212130202* 8212130231 8212130234* 8212130234*	50-254 50-275 50-275 50-275 50-275	ጽ P P P		851 35505; 851 35505; 851 35505; 851 35505; 851 35205;	31* 50~1 31* 50~1 31* 50~1	10 P
	8212140055 8212140059 8212140041* 8212140041* 8212140067	50-295 50-295 50-295 50-295 50-373	R R R R		82122202 82122202 82122204 82122204 82122300	31* 50-1 31 50-2 31 50-2	10 P 295 P 295 P
	8212140068 8212140072* 8212140075* 8212140112 8212140112	50-373 50-373 50-373 50-10 50-10	P P S R R		82122300 82122300 82122300 82122300	28* 50-1 12* 50-1 12* 50-1	10 F
	8212140112 8212140119 8212140120* 8212140120* 8212140120*	50-10 50-373 50-10 50-10 50-10	R S R R R		82122701 82122701 82122701 82122701 82122701	40* 50-3 62 50-3 62 50-3	973 9 973 8 973 8
	8212140128* 8212140172 8212140179 8212140231* 6212140231*	50-373 50-237 50-254 50-373 50-373	8 F G		82122701 82122701 82122701 82122702 82122702	75 50-0 90* 50-0 23* 50-0	373 S 173 S 173 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8212270303* 8212270303* 8212270354 8212270356* 8212280110	50-237 50-237 50-373 50-373 50-237	0 0 5 9 0		8212300179* 8212300179* 8212300179* 8212300179* 8212300179*	50-10 50-10 50-10 50-10 50-10	44444
	8212280110 8212280117 8212280117 8212280117 8212280117	50-237 50-237 50-237 50-237 50-237	() የ የ የ		8212300199* 8212300199* 8212300199* 8212300199* 8212300199*	50-10 50-10 50-10 50-10 50-10	4444
	8212280117 8212280195 8212280212 8212280212 8212280212	50-237 50-373 50-237 50-237 50-237	թ թ թ	Connecticut Yankee Atomic Power Co	8212300405+ 6212300405+ 6212300409+ 6212300409+ 62123020299	50-254 50-254 50-254 50-254 50-213	F
	8212280212 8212280212 8212280212 8212280212	50-237 50-237 50-237 50-237 50-237	ր թ թ		82120 60157 82120 60376 82120 70289 82120 80449 82120 80459*	50-213 50-213 50-213 50-213 50-213	P G P S S
	8212260212 8212260212 8212260215* 6212260227 6212260231*	50-237 50-237 50-373 50-373 50-373	P P S S S		82120 70114 82121 50034 82121 50222 82121 60214 8212210057	50-213 50-213 71-6574 PR 50-213	F F
	8212280244 8212280249* 8212280263 8212280263 8212280263	50-295 50-295 50-237 50-237 50-237	9 6 P P		8212210043* 8212210121 8212210121 8212230257 8212280119	50-213 50-213 50-213 50-213 50-213	#P P P F
	8212280306 8212280278 8212280278 8212280278	50-237 50-237 50-373 50-373 50-454	p p p	Conner & Wetterhahn	8212020330 8212020339* 8212080288 821209073 8212200089	50-352 50-352 50-358 50-358 50-358	0000
	8218280306 8212280341 8212280343 8212280343 8212280343	50-454 50-373 50-237 50-237 50-237	K K P P		8212210261 8212230327 8212270216 8212280185 8212300187	50-458 50-352 50-352 50-352 50-352	G G G
	821 22 80343 821 22 80343 821 22 80357 821 22 80432 821 22 80442*	50-237 50-237 50-254 50-295 50-275	P P P S S	Conover & Associates, Inc. Insurance Consad Research Corp Consolidated Edison Co. of New York, Inc.	8212270173 8212280254 8212070404 8210170477 8212020318	70-1621 70-1621 FOIA 50-247 50-247	F
	8212280447 8212280448* 8212280448* 8212280449* 8212280450	50-373 50-454 50-454 50-373 50-275	5 G G S S		8212020318 8212030248* 8212040103 8212040103 8212040144	50-247 50-3 50-247 50-247 50-247	G F G G
	8212280461* 8212280472 8212280479* 8212280483 8212280487*	50-295 50-297 50-237 50-373 50-373	5 8 8 8		8212040152* 8212070265 8212070265 8212070265 8212070276 8212080277	50-247 50-3 50-3 50-247 50-247	8 P P P
	8212270084* 8212270084* 8212270089* 8212770089*	50-295 50-295 50-295 50-295 50-295	F F F F		6212080311* 6212090087 6212090090 8212090090 8212090205	50-247 50-247 50-247 50-247 50-247	9 0 0 0
	8212270105* 8212270110* 8212270110* 8212270111 8212270111	50-295 50-295 50-295 50-254 50-254	F F F P P		8212090205 8212130232 8212130232 8212130288 8212140353	50-247 50-247 50-247 50-247 50-3	₽ ₽ ₽
	8212290190 8212290193* 8212290247 8212290247 8212290229	50-237 50-237 50-454 50-454 50-249	р Р F 8		0212140423 8212140439 8212140439 8212140446* 8212140446*	50-247 50-247 50-247 50-247 50-247	0 0 0
	921227033* 8212270337 8212270344 8212270345* 8212270367	50-249 50-374 50-237 50-237 50-249	9 9 9 9		8212150023 8212150027# 8212150080 8212150084# 8212160289	50-247 50-247 50-247 50-247 50-247	8 8
	82122 70385* 82122 70398 82122 70407 82122 70409* 82122 70472	50-249 50-237 50-254 50-237 50-249	8 8 9 8		8212160289 8212210119 8212210128 8212210133* 8212210140*	50-247 50-247 50-247 50-247 50-247	8 8 8
	82122 90478* 82122 90511* 82122 90513* 82122 90513*	50-249 50-295 50-295 50-295 50-10	8 F F F F		8212220042* 8212220042* 8212220046* 8212220046* 8212220271	50-3 50-3 50-3 50-3 50-247	FFFG

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	_
	6212220271 6212230187 6212230187 6212230187 6212270120 6212270361*	50-247 50-247 50-247 50-247 50-247	0 0 0 F		8212170144 8212170144 8212170150* 8212200029 8212200070	50-329 50-155 PR	A G P
	8212280219 8212280221* 8212280237 8212280243* 8212280248*	50-247 50-247 50-247 50-247 50-247	R R P P		8212200075* 8212200082* 8212210156 8212210258 8212210285		P የ \$ \$
	8212280293 8212280364 8212270302* 8212270308* 8212270308*	50-247 50-247 50-3 50-3 50-3	G P F F		8212210289* 8212210292* 8212210296* 8212210309 8212210314	50-155 50-155 50-155 50-327 50-327	G G A O
Consumers Power Co	8212300230 8212300273 8212300352 8212010035 82120100313	50-247 50-247 50-247 50-329 50-329	С Р Р А Б		6212210314 6212230112 6212230275 6212230342 8212230343*	50-329 70-2964 50-255 50-155 50-155	G G P P
	8212020325 8212020331* 8212020351* 8212030019 8212030137	50-255 50-255 50-255 50-155 50-155	8 8 9 9		8212230350 8212270126 8212270126 8212270215 8212270228*	50-329 50-329 50-329 50-255 50-255	6 8 8 8
	8212060067 8212060073* 6212060357 8212060371* 8212060382*	50-255 50-255 50-255 50-255 50-255	9 4 0 a a		8212280083 8212280089* 8212280094* 8212280103 8212280107*	50-255 50-255 50-255 50-155 50-155	P P P P
	8212040392* 8212040396* 8212040412* 8212040421* 8212040431*	50-255 50-255 50-255 50-255 50-255	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8212280113* 8212280131 8212280207 8212280225 8212280225	50~155 50~155 50~329 50~329 50~329	P 0 5 F
	8212040444* 8212070017 8212070127 8212070300 8212070300	50-255 50-329 50-155 50-155 50-155	S R G F F		8212280320 8212280320 8212280330 8212280382 8212280460	50-327 50-327 50-255 50-255 50-255	5 0 F S
	8212070300 8212070300 8212070327 8212070330# 8212070337*	50-155 50-155 50-155 50-155 50-155	F G G G		6212260464* 6212270203 6212270203 6212270208* 6212300147*	50-255 50-327 50-327 50-327 50-327	SAAAA
	8212070340* 8212070345* 8212070349* 8212070352* 8212080261	50-155 50-155 50-155 50-155 50-255	0 0 0 5	Continum Dynamics, Inc Cornell Univ	8212300332 8212300341* 8212280354* 8212140146 8212140232	50-155 50-155 50-387 50-97 50-97	R R P R
	8212080271* 8212080392 8212080392 8212090046 8212090046	50-255 50-329 50-329 50-329 50-329	B A A A		8212140232 8212140238* 8212140238* 8212140469 8212140469	50-97 50-97 50-97 50-97 50-97	14 14 14 14
	8212070067# 8212070168 8212070168 8212070194# 8212070194#	50-329 50-329 50-329 50-329 50-329	A T T T	Catter Corp Crystal River,FL Cygna Energy Services	8212030258 8212100343 8212100349* 8212010404* 8212300312*	40-8511 HABTE MG HASTE MG CONTRACT 50-341	ንቸ
	821207040 7 8212100218 8212100218 8212100218 8212100237	50-255 50-155 50-155 50-155 50-329	2 E E E	Dairyland Power Cooperative	8212030024 8212070110 8212070152 8212080228 8212090440*	50-409 50-409 50-409 50-409 50-409	Р Р Р О
	8212100248 8212100273 8212100273 8212100285 8212100285	50-255 50-329 50-329 50-155 50-155	8 9 9 F		8212140417* 8212170204 8212220323* 8212220331* 8212280059	50-409 50-409 50-409 50-409 50-409	9 F F P
	8212100285 8212100304 8212100309* 8212100313 8212100317*	50-155 50-155 50-155 50-255 50-255	F S S S	•	6212260075* 6212260253 6212260256* 6212270220 6212270222*	50-409 50-409 50-409 50-409 50-409	g S R R
	8212130247 8212130250* 8212140256* 8212140367* 8212140367*	50-255 50-255 50-329 50-329 50-329	የ የ A A A	Dallas Morning News Dames & Moor≢ Dayton Power & Light Co	8212100378 8212150183* 8212280478* 8212090034* 8212230001	FOIA 50-250 CONTRAC 50-358 71-6717	F
	8212140387 8212140387 8212160223 8212160227* 8212170082	50-329 50-329 50-155 50-155 50-155	0 0 0 P	DeKalb Area Alliance for Responsible Energy Debevoise & Liberman	8212080235 8212080245* 8207180043 8209150071	50-454 50-454 50-278 FOIA	90

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ	AUTHOR AFFILIATION	ACCESTION NUMBER	SUBJECT CATEGORY	
	8212130230 8212140409 8212160261 8212200010 8212220232	50-413 50-445 50-413 PR 50-413	6 6 6		8212140263 8212140390 8212140390 8212140425 8212140434*	50-413 50-369 50-369 50-369	A P P S
	8212220232 8212220239* 8212220239* 8212230314 6212230314	50-413 50-413 50-413 50-397 50-397	6 0 0 0		8212150073 8212160044 8212160044 8212160249 8212160261	50-413 50-413 942-08	P A P G
	8212270244 8212270244 8212270317 8212270317 8212270321	50-413 50-413 50-445 50-445 50-413	0 0 0		9212140345 8212140345 8212170254 8212170254 8212170256 8212170250	50-413 50-413 50-413	A S S P
	8212270321 8212270326 8212270329 8212270332 8212270332	50-413 50-397 50-460 50-445 50-445	G G G		921220005 8212200012* 8212210060 8212210065* 8212210079	50-349 50-349 50-349	9 8 R R P
Detroat Edison Co	8212280273 8212280277 8212280277 8212280294 8212010156*	50-445 50-397 50-397 50-460 50-341	G G G K		8212210079 8212210079 8212210145 8212210184* 8212210831	50-269 50-369 50-369	ր 8 9
	8212010163# 8212090061 8212100166 8212100267 8212130303	50-341 50-341 50-341 50-341 50-341	K E A A		8212210231 8212210421 8212210421 8212210421 8212210421	50-370 50-269 50-269	9 K R R
	8212130424 8212130427# 8212140375 8212210443 8212230309	70-2926 70-2926 50-341 50-341 50-341	F ទ 0		82122 0423* 82122 0428* 82122 0428* 82122 0428* 82122 20227	50-269 50-269 50-269	K R R R
Ditte. S J	8212230355 8212270359 8212270362 8212300311 8212040399	50-341 50-341 50-341 50-341 ACRE	C G B A		8212220232 8212220239* 8212220239* 8212220239*	50-413 50-413 50-413 50-369	G G G F
Doc-Search Associates Dow Chemical Co Duke Power Co	8208270104 8212020034 8212030002 8212030003* 8212030047	FOIA 40-17 50-349 50-349 50-413	P P A		8212230074* 8212230083* 8212230108* 8212230108* 8212230108*	50-369 50-269 50-269 50-269	ቱ 6 6 7
	8212030080 8212040244 8212070178 8212070178 8212070341	50-413 50-369 50-413 50-413 50-269	A P G G P		8212230124* 8212230124* 8212230124* 8212230124* 8212230124*	50-269 50-269 50-269	부 다 구 구
	8212070348* 8212070353* 8212070370 8212070392* 8212070392*	50-269 50-269 50-269 50-269 50-269	ե ե ե ե		8212230124* 8212230124* 8212230124* 8212230134* 8212230134*	50-269 50-269 50-269	두 두 두 두
	8212070392# 8212070395# 8212070395# 8212070395# 8212090079	50-249 50-249 50-269 50-269 50-414	P P P S		8212230134* 8212230134* 8212230134* 8212230134* 8212230134*	50-269 50-269 50-269	4 4 4 4
	8212070172* 8212070221 8212070225* 8212070233 8212070237*	50-369 50-287 50-287 50-413 50-413	G G G		8212230134* 8212270244 8212270244 8212270261 8212270321	50-269 50-413 50-413 50-413 50-413	F G G A G
	8212090230 8212090323 8212090339 8212090401 8212090420	50-369 50-414 50-369 50-369 50-269	G E G G		8212270321 6212280169 8212280173* 8212280173* 8212280174 8212280351	50-413 TOPREP TOPREP 50-413 50-269	Q Q P
	8212090442 8212090482 8212090522 8212100096 8212130069	50-413 50-413 50-413 50-413 50-269	G G G C F		8212280351 8212280351 8212280347* 8212280347* 8212280347*	50-269 50-269 50-269 50-269 50-269	P P P
	8212130049 8212130069 8212130069 8212130190 8212130230	50-269 50-269 50-269 50-269 50-413	F F F P O		821 2280380 821 2280394* 821 2290232 821 2290232 821 2290354	50-369 50-369 50-369 50-369 50-413	8 8 P A
	8212130230 8212130257 8212140171 8212140176* 8212140263	50-413 50-413 50-369 50-369 50-413	0 A 9 8 A		8212290354 8212300093 6212300096* 8212300224 8212300224	50-413 50-369 50-369 50-287 50-287	8 8

AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJEC	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Duke Univ Duquesne Light Co	8212230051* 8212020076 8212020084* 8212020089* 8212030142	CONTRAC 50-334 50-334 50-334 50-334	CT P P	ENSA, Inc	8212140346 8212220282 8212270145 8212270454 8212270499	50-206 P NUREG NUREG NUREG NUREG
	8212030148 8212070204 8212080419	50-334 50-334 50-334	R	East Tennessee Davelopment District Ebasco Services, Inc. (subs. of Enserch Corp.)	8212080201 8212170243	50-537 D 50-369 R
	8212080440* 6212080451	50-334 50-334	S S	•	8212210324* 8212280187 8212280333	50-286 P 50-389 R 50-389 A
	8212080474 8212080480* 6212080484* 6212080497* 6212080526	50-334 50-334 50-334 50-334 50-334	P P S S	Edison Electric Institute Ediow International Co	8212280405 8212020357 8211090496 8212100087 8212160791	50-389 A PR 70-2955 XPORTLIC XPORTLIC
	8212080530* 8212090520 8212090526* 8212100041* 8212130242	50-334 50-334 50-334 50-334 50-334	. Р Р Q	Energy Fuels Nuclear, Inc	8212300140 8212070509 8212290012 8212290013* 8209220453*	XPORTLIC 40-8681 40-8681 40-8681 50-331 P
	8212130243 8212130245* 8212130246* 8212130244* 8212140174	50-334 50-334 50-334 50-334 50-334	Р Р	Energy Research Group, Inc Energy, Dept of	8212100086* 8212100087* 8212230159 8212010025 8212020060	FOIA FOIA FOIA WASTE MOT WASTE MOT
	8212140191* 8212140427* 8212150020 8212150025* 8212150075	50-334 50-412 50-334 50-334 50-334	0 8 8		8212020073* 8212020242 8212040113 8212070378* 8212070082	WASTE HOT 50-537 A 50-537 Q COMMISSION 50-537 Q
	8212150078* 8212160339 8212170200 8212220283 8212220373	50-334 50-334 50-334 50-412 50-334	P F H		8212130122 8212130129* 8212130195 8212150133 8212160437	71-6495 71-6495 71-4909 50-537 A 71-9132
	8212220403 8212220404* 8212220407 8212220425 8212270155	50-412 50-412 50-334 50-334 50-334	ሉ !' ድ		8212160438 * 8212170405 8212170409 * 8212200015 8212210253	71-9132 40-6500 40-6500 50-537 G 70-143
	8212270161* 8212270163* 8212270201 8212270207* 6212270209*	50-334 50-334 50-334 50-334 50-334	P P	Energy, Dept of, Glinch River Breeder Reactor Plant	6212220010 6212270238 6212300011 6212010011	40-4500 70-143 50-537 G 50-537 F
	9212270225 6212270230* 6212270267* 8212270337 6212270340*	50-334 50-334 50-334 50-334 50-334	R R G S S		8212010146 8212010161 8212020303 8212070226 8212070243	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A
	8212290373 8212290382* 8212290404 8212290411* 8212290439	50-334 50-334 50-334 50-334 50-334	ត		8212070311 8212140374 8212150054 8212150177 8212160200	50-537 A 50-537 A 50-537 A 50-537 B 50-537 A
EDS Nuclear, Inc	8212290448* 8212300107 8211120491* 8212130224	50-334 50-334 HISC 50-255	8 F		8212170190 8212200077 8212210045	50-537 A 50-537 A 50-537 A
EG&O, Inc	8212130229* 8212290104* 7908140789*	50-255 50-266	ь Б		8212210050 8212210055 8212230007	50-537 A 50-537 A 50-537 A
	8105210384* 8201120155* 8212010474 8212010519*	50-219 50-263 RES RES 50-352	G A		8212230237 8212230253 8212230262 8212230263 8212230300	50-537 A 50-537 A 50-537 A 50-537 A
	8212020076 8212020095 8212020005	50-395 50-409 50-155 RE8	P P		8212230321 8212270185 8212270229 8212270231	50-537 A 50-537 A 50-537 A 50-537 A
	8212020104 8212020108 8212020110 8212020126 8212040468	RE6 50-364 50-249 RES NUREG	P P		8212270248 8212270294 8212270302 8212300215 8212300248	50-537 A 50-537 A 50-537 A 50-537 B
	8212040471 8212040490 8212080505 8212080510 8212080514	50-295 NUREQ REB REB REB	p	Engineering & Economics Research, Inc	8212300249* 8212300253 8212300299 8212300343 8212270501*	50-537 A 50-537 A 50-537 A 50-537 A 50-537 A
	8212080520 8212080551* 8212130108 8212130113 8212130152	RES 50-443 NUREG NUREG NUREG	A	Environmental Coalition on Nuclear Power	8212270301# 8212140186 8212300134 8212030280 8212040325	50-277 9 50-277 9 ACRS ACRS

>

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEGO	ŔΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOS	
Esser Corp Ewropean Communities, Commission of Essen Corp	8212130185* 8212010189 8212030285 8212210536 8212210542*	50-400 XPDRTLIG 40-8102 40-8064 40-8064	c A		8212280170 8212280175* 8212280359 8212280366* 9212280418	50-250 50-250 50-250 50-335 50-335	
Examp Nuclear Co , Inc (subs of Example Cosp)	8212230063 8212010057	40-8102 XPORTLI			9212280425* 8212270048* 8212270094*	50-935 50-250	8 0 0
	8212010063* 8212030088 8212130097	XPORTLIC TOPREP TOPREP	G		8212290097* 8212290124*	50-250 50-250 50-250	G G
	8212140167 8212140190 8212140411 8212150003 8212150005*	50-316 TOPREP 50-282 TOPREP TOPREP	P		6212290153 8212290153 8212290153 8212290153 6212290169*	50-250 50-250 50-250 50-250 50-250	R R R R
	6212150276 8212280404 8212290199* 8212290206* 8212290215*	70-1257 50-316 50-237 50-237 50-237	р Б		8212290169+ 8212290169+ 8212290169+ 8212290265 8212290357	50-250 50-250 50-250 50-389 50-335	R R E P
Fauske & Associatos, Inc Fæderal American Partners Fæderal Emergency Management Agency	8212270254* 8212070407 8212150137* 8212150153* 8212280087*	50-537 40-4492 50-382 50-382 50-247	A G O F		8212290357 8212290361* 8212300065* 8212300065*	50-335 50-335 50-335 50-335 50-387	8 8 6 5
Flack.G Florida Power & Light Co	8212280092* 8212280426 8212290207 8212020268 8211040086	50-247 50-483 50-414 PRM 50-335	F F S	Florida Pawer Corp	8211090043 8212020045 8212020052* 8212020063 8212020071*	50-302 50-302 50-302 50-302 50-302	P 8 8
	8211040070* 8212010026 8212020349 8212020371* 8212030216	50-335 NUREO 50-335 50-335 50-389	8 9 9		6212020077 6212020087* 6212040084 6212040825 6212100006	50-302 50-302 50-302 50-302 50-302	8 9 P F
	8212070215 8212070200 8212070356 8212070371* 8212070403	50-389 50-369 50-250 50-250 50-335	8 8 9 8		8212140048 8212140051* 8212140087 6212150044 8212150052*	50-302 50-302 50-302 50-302	R R F B
	8212090410* 8212090503* 8212090549* 8212090554* 6212090559*	50-335 50-250 50-335 50-335 50-335	9 0 0 0		8212150060 8212150079 8212150102* 8212150105 8212150108*	50-302 50-302 50-302 50-302 50-302	8 8 8
	8212100217 8212100220* 8212100240 8212140373 8212140461	50-250 50-250 50-369 50-369 50-389	88 4 4		8212220270 8212220284 8212220314 8212220322* 8212270177	50-302 50-302 50-302 50-302	F 8 8 H
	8212150064* 8212150068 8212150074 8212150098 8212150129	50-302 50-335 50-387 50-389 50-389	8 6 8	Florida, Univ of, Gainesville Flow Science, Inc Fontana, L Frecture Proof Design Corp	B212070004 B212070009* B212070274* B212140521* B212270135	50-83 50-83 50-416 50-382 50-354	R R P Q
	8212150156 8212150158* 8212150180	50-335 50-335 50-250	s s r	Frankhauser D.D. Franklin Institute/Franklin Research Center	8212140205 8206140113#	50-35B 50-271	G P
	8212150180 8212150204 8212170060*	50-250 70-2957 50-335	R		8207010124* 8207010149* 8207010396*	50-29 50-244 50-245	Р Р
	8212170065* 8212170127 8212170129* 8212170269	50-335 50-335 50-335 50-389	P P A		8207010410* 8207150169* 8207180649 8209140103* 8209230258*	50-409 50-219 FOIA 50-255 50-409	Р Р Р
	8212170273 8212170274 8212200071 8212200085* 8212210101	50-250 50-335 50-335 50-335 <i>50-369</i>	E		8209230377* 8209290122* 8210070227* 8210220470* 8210220483*	50-155 50-409 50-250 50-317 50-317	թ 12 13 14 14 14 14 14 14 14 14 14 14 14 14 14
	8212210175 8212210184* 8212210170 8212210202 8212210207*	50-335 50-335 50-250, 50-250 50-250	996		B2102501B7* B2120104B1* B212170401* B212170402* B212220024*	50-344 FOIA CONTRACT CONTRACT	•
	8212210348 8212210354 8212210389 8212210376* 8212220200	50-389 50-389 50-335 50-335 50-389	8 8 6 A		8212230110* 8212230250* 8212270534* 8212270536* 8212300348*	50-213 50-277 50-250 50-250 50-289	6 6 6 6
	8212220441 8212220442* 8212280164 8212280167*	50-335 50-335 50-250 50-250	8 8 8	Fred C Hart Associates, Inc. Friends of the Earth	6212020370* 6212270530* 6212220246 6212230352	CONTRACT CONTRACT 50-247 50-352	

AUTHDR AFF ILIATION	ACCEBSION NUMBER	SUBJECT CATEOOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	1
Fugro, Inc GA Technologies, Inc /General Atomic Co Gage-Babcock Associates, Inc Gall, W R	B212230356 8212080568* 8212010468 8206100047* B208290027	50-352 50-443 XFORTLIC 50-344 ACRS	C A F		6212140744* 6212170119 6212210017 8212210018 6212210019	50-320 50-289 50-289 50-320 50-219	, F P P P P
Galloway & Oreenberg General Electric Co	8212080257 8212230200 8212270245 8212210144 8212020174	50~537 50~537 50~537 NUREO XPORTLIC	B Q G		8212210020* 8212210040 8212210232 8212210234* 8212210372	50-219 50-219 50-289 50-219	P A A R
	8212080301* 8212080301* 8212090077 8212090148 8212100005*	50-440 50-440 TOPREP TOPREP GA999	G G		8212210377* 8212210460* 8212210468* 8212210555* 8212210557*	50-219 50-219 50-219 50-219 50-219	8 0 6 F
	8212130172 8212130246* 8212130246* 8212140348 8212140449	50-447 50-440 50-440 50-447 50-447	B G B B		8212220415 8212220421* 8212220449 8212220454* 8212230295	50-287 50-289 50-320 50-320 50-320	F F S P
	8212160423 8212160762 8212170101* 8212200041 8212200072*	70-1113 NUREQ 50-277 50-447 50-440	Р А О		8212270134 8212270147 8212270268 8212280010 8212280218	50-289 50-320 50-289 71-5957 50-219	P P P
	8212230085 8212230103* 8212230301 8212230326 8212270506*	70-1113 70-1113 50-447 50-447 CONTRACT	E A		8212280313 8212280370* 8212290127 8212290134* 8212290197	50-219 50-320 50-219 50-219 50-289	ዖ ል ል የ
General Electric Uranium Management Corp	8212270018* 8212270117 8212300123* 8212300175 8212150216	FOIA 50-447 CONTRACT XPORTLIC 71-9001			821 22 70233 821 22 70240 * 821 22 70353 * 821 22 70410 * 821 23 00113	50-320 50-320 50-320 50-219 50-330	9 9 0 P
General Public Utilities - GPU Hervice Corp	8212010097* 8212030113 8212030120* 8212040015 8212040019*	50-320 50-320 50-320 50-320 50-320	F R R P	General Research Corp Georgia Power Co	8212300260 8212030266* 8212020292 8212020295* 8212030170	50-320 CONTRACT 50-366 50-366 50-321	8 8 6
	8212060022* 8212060054 8212060085 8212060148 8212060247	50-320 50-289 50-320 50-219 50-219	P F P ₽		6212030174* 6212070297 6212070121 6212070126* 6212070127	50-321 50-321 50-366 50-366 50-321	9 9 9 9
	821 2040322 821 2040324* 821 2040332 821 20701 43 821 2070251	50-320 50-320 50-219 50-320 50-289	ន ១ ៤ ೯		8212090140 8212090142 8212090145* 8212090147* 8212090190	50-321 50-364 50-321 50-366 50-366	S S S S
	8212070253* 8212080240 8212080245* 8212080349 8212080354*	50-287 50-219 50-219 50-219 50-219	្ត ទ ទ ខ		8212090193* 8212090202 8212090207* 8212090214 8212090219*	20-351 20-351 20-351 20-351 20-399	9999
	8212080359* 8212080368 8212080395* 8212080511 8212080519	50-219 50-219 50-219 50-219 50-289	ទ ន ទ ទ ৮		8212090247 8212090254* 8212090329 8212090335*	50-366 50-366 50-366 50-321 50-366	S S S S
	82120 80525* 62120 80556 62120 90264 82120 90293* 82120 90297*	50-219 50-219 50-269 50-289 50-289	5 G P P		8212090341* 8212090379 8212090381 8212090386 8212090388*	50-321 50-321 50-366 50-366 50-366	999
	8212070501 8212070508* 8212130057 8212130060* 8212130104	50-289 50-289 50-320 50-320 50-289	Ե Ե Ե		8212090389 8212090391* 8212090399* 8212090437 8212090444*	50-346 50-346 50-366 50-366 50-366	9 9 8 8
	8212130304 8212130318 8212140169 8212140177* 8212140180	50-219 50-320 50-219 50-219 50-289	투 당 당		8212070472 6212100264 6212100279* 8212100262 8212100286*	50-321 50-366 50-366 50-366 50-366	0 8 8 8
	8212140228 8212140239* 8212140362 8212140466 8212150038	50-289 50-289 50-219 50-289 50-320	8 5 7 8		82121 0031 1 82121 0031 4* 82121 40115 82121 40123* 82121 40269	50-366 50-366 50-366 50-366 50-321	8 8 8 8
	8212150044* 8212150110 8212150270 8212160752*	50-320 50-289 71-9151 50-320	8 P F		82121 40271* 82121 40421 82121 40427* 82121 40433 82121 40436*	50-321 50-366 50-366 50-366 50-366	999

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8212150007 8212150007 8212150011* 8212150014 8212150018*	50-321 50-321 50-321 50-321 50-321	8 F 8 8		8212220274 8212270183 8212270236 8212280196 8212280252	50-458 A 50-458 B 50-458 B 50-458 B	3
	8212150031 8212150037* 8212170092	50-321 50-321 50-321	5 5 8	Gutmann,P H Hanford Engineering Development Laboratory	8212270540* 8212140380*	CONTRACT 50-537 A	١
	8212170099* 8212170155 8212170165*	50-366 50-366	6 5 9	Harmon & Weiss	8212140388# 8212200021 8212200037	50-537 A 70-143 50-443 0	
	8212170144 8212170202* 8212170244 8212170353	50-321 50-321 50-321 50-321	S S P R		8212200039 8212200049# 8212200049# 8212210272 8212210336	50-443 0 50-443 0 50-443 0 50-289 0 50-289 0	} }
	8212170353 8212170359* 8212170359* 8212210083 8212210088*	50-321 50-321 50-321 50-321 50-321	R R R 8 8		8212220248* 8212280171 8212280270 8212280505 8212300002	70-143 50-358 G 70-143 FOIA 50-289 G	
	8212210188 8212210196* 6212210446 6212210452* 6212280159	50-321 50-321 50-366 50-366 50-366	8 9 9 9 8 9	Harold J Speiman & Associates	8212300008 8212300242 8212300342 8212130167 8212270449	50-289 0 50-289 0 50-269 0 40-2041 40-2061	3
	8212280161* 8212280180 8212280356 8212280387 8212280392*	50-366 50-321 50-424 50-321 50-321	8 8 4 8 8	Hittman Corp Hittman Nuclear & Development Corp (subs Hittman Corp)	8212270478 8212130055 8212130061* 8212150282	40-2061 71-9151 71-9151 71-9151	
	8212270151 8212300058 8212300063*	50~321 50~366 50~366	P 9 8	House of Rep	B212070048*	50-289 H	
	8212300091 8212300095* 8212300098	50-321 50-321 50-366	8 8 8	House of Rep , Interior & Insular Affairs	8212080689# 8212230276 8209150008* 8212230341 8212170133*	50-322 H 50-247 U COMMISSION 50-247 U 50-498 A) I
	8212300102* 8212300245 8212300270* 8212300271 8212300275*	50-344 50-321 50-321 50-321	9 8 8 5	Houston Lighting & Power Co.	8212020254 8212030100 8212070262 8212070262 8212070263*	50-478 A 50-498 S 50-498 K 50-498 K 50-498 K	\ { {
	8212300277 8212300281* 8212300284 8212300285	50-321 50-321 50-366 50-366			8212070263# 8212090377 8212090377 8212090382#	50-498 K 50-498 K 50-498 K 50-498 K	ξ ξ
	8212300287 8212300289* 8212300270* 8212300272* 8212300275	50-321 50-321 50-364 50-366 50-366	9 8 8		8212070382# 8212140381 8212140383# 8212140383# 8212140383#	50-498 K 50-498 C 50-498 C 50-498 C	
	8212300278* 8212300323* 8212300328* 8212300329 8212300327	50-366 50-366 50-366 50-321 50-321	S 9 9 9 9		B212170120 B212170120 B212170124* B212170124* B212270172 B212280279	50-478 / 50-478 / 50-478 A 50-478 B 50-478 B 50-478 G	! A A
	8212300337* 8212300340 8212300344 8212300345*	50-321 50-366 50-366 50-366 50-366	5 5 5 6	Hovis, Cockrill, Weaver & Pjur	6212260277 8212260262 8212260262 8212270202 8212140333	50-498 G 50-498 G 50-498 G 50-498 B 50-522 G	3
Georgia, State of Georgia, State of, Dept of Human Artburces Geotechnical Engineers,Inc	8515580201* 8515550221 8515550223*	CONTRAC PR 50-329		HATES GOODLESS MEGALE & MICH.	8212140333 8212140345 8212140345	50-522 9 50-522 0 50-522 0	a G
Getty Dil Co (Petrotomics)	8212230084 8212270325	40-6659 40-6659			8212140354 8212140354	50-522 G	9
Gilbert/Commonwealth Cos Glycine-Bales & Service Golder Associates Goldman,H	8212210461* 8212160532 8212280491* 8212270513*	50~244 PR CONTRAC CONTRAC	Т	Hunton & Williams	8212140384 8212140386 8208270121 8212020381 8212270034	50-522 6 50-522 6 FOIA 50-322 6 FOIA	Q
Gavernment Accountability Project Guild, R	8212280128 8212280132 8212280132 8212280138 8212280138	50-358 50-413 50-413 50-413 50-413	9 9 9 9	Idaho National Engineering Laboratory Illinois Power Co	8212270194 8212010487 8212020088 8212020324 8212020333	50-322 9 RES 50-461 A 50-461 9 50-461 9	A
Gulf Coast Environmental Defense Foundation, Inc Gulf Oil Corp	8212020378 8212280030*	PR 70-146			8212040093 8212040105		G A
Gulf States Utilities Co	8212210136 8212100237* 8212100033	50-458 50-458 50-458	8 Q SI		8212060144 8212070125 8212070200		A E
	8212210176 8212210261 8212210261	50~458 50~458 50~458	8 0 0		8212070229 8212140057 8212170303	50-4. 50-4 50-4	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8212170330 8212210313 8212220233 8212280101 8212280235	50-461 50-461 50-461 50-461 50-461	E A A A	Interior,Dept of, Fish & Hildlife Service Interior,Dept of, Geological Survey Interior,Dept of, National Park Sørvice	8212160316* 8212020173* 8212280438* 8212160643* 8212210037	50-352 M180 50-409 COMM15910 50-275	O P
Illinois, State of Illinois, State of, Dept Nuc Bafety (formerly Dept Public Health)	8212280340 8212270179 8212230092 8212280174	50-461 50-461 NUREG 50-10	<u>е</u> Е Н	lowa Electric Light & Pawer Co	821 2040221 821 2040224 * 821 2040324 * 821 2070214 821 2070308	50-031 50-031 50-331 50-331	5 7 0 P
Indiana & Michigan Electric Co	8212010037* 8212010037* 8212010039* 8212010039* 8212020229	50-315 50-315 50-315 50-316	F F F F F F F F F F F F F F F F F F F		8212070322 8212070328* 8212070337 8212100278 8212100284*	50-331 50-131 50-731 50-771 50-371	<u>የ</u> የ የ
	8212020283 8212020283 821202087* 8212030145* 8212030145* 8212040031	50-316 50-315 50-315 50-315 50-315	9 9 9 C.P.S		8212100295 8212140134 8212140142 8212140147* 8212140332	50-331 50-331 50-331 50-331	0 0 0 0
	8212040048 8212040057* 8212040040* 8212040072 8212080091*	50-316 50-316 50-316 50-315 50-315	ន ន ន ទ P		8212140336* 8212150070 8212150132 8212170193 8212170308	50-331 178-08 178-08 178-08	1) F F F F F F F F F F F F F F F F F F F
	8212080091* 8212080096* 8212080096* 8212090296 8212090296	50-315 50-315 50-315 50-315 50-315	F F P P		BR12210033 BR12210034* BR12210070 BR12210074* BR12210209	50-331 50-331 50-331 50-331	6 6 6 8
	8212100177 8212100251 8212100259* 8212100290 8212100300*	50-316 50-315 50-315 50-315 50-315	3		8212210210* 8212210315 8212210316* 6812210352 6812210358*	50-731 50-331 50-331 50-331	p P 6 6
	8212100322 8212100327# 8212140156 8212140165# 8212150329#	50-315 50-315 50-316 50-316 50-315	3 3 3 5 F		6212230374* 6212230377* 6212270168 6212270176* 6212270278	50~0 H 50 ~7 H 50 ~7 H 50 ~2 H 50 ~2 H	F F F F
	8212150329= 8212150335+ 8212150335+ 8212160001 8212160001	50-315 50-315 50-315 50-315 50-315	F F F F	Isham, Lincoln & Beale	6212280045 6212280125 6212280454 6212280457* 6212280457*	50 - 33 1 50 - 46 1 50 - 33 1 50 - 3 1 50 - 155	P G G
	8212160002* 8212160002* 8212170179 8212170188* 8212170224	50-315 50-315 50-316 50-316 50-316	F F P B		8212070327 8212070352* 8212090168 8212140387 8212160223	50-155 50-155 50-129 50-129 50-155	0 F 0
	8212170228* 8212170232* 8212170237* 8212170267 8212170268*	50-316 50-316 50-316 50-316 50-316	ន ១ ១ ១ ១	Ishikawajima — Harima Heavy Industries Co .Ltd Isomedix, Inc (Subs of Masefield	6212210256 6212210265 6212270045 6212170111*	50~155 50~155 101A 50~277	000
	8212170283 8212170292* 8212170294* 8212200056 8212200065*	50-315 50-315 50-315 50-316 50-316	ទ ទ ទ ត ត	Enterprises, Inc.) Japan	9212010044 8212010048 9212010054 6212270087 8212270090	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8212200119 8212200122* 8212210125 8212210125 8212270136	50-315 50-315 50-315 50-315 50-315	R R P P	Jersey Central Power & Light Co Joint Applicants-Palo Verde Joint Intervenors-Gallaway Joint Intervenors-Diablo Ganyon	8001140342 8212040017# 8212040075 8212280179 6212280268	50-219 50-320 50-320 50-403 50-275	11 p & Q Q
	8212280165 8212280310 8212270217 8212270228* 8212270355	50-315 50-316 50-316 50-316 50-316	0 0 R R R 8	Joint Intervenors-Waterford Justice, Dept of Justice, Dept of, Attorney General's	8212020355 8212230341 8212230341 8212010053*	50-182 50-382 50-382 50-387 50-389	00011
Information Systems & Network Corp	8212270358* 8212270417 6212270424* 6212270428* 6212270434* 6212080583*	50-316 50-315 50-315 50-315 50-315	\$ R R R	Office KFRC Radio, San Francisco, CA Kansas Gas & Electric Ca	8212010174# 8212030127 8212030135# 8212070222	FOIA 50 - 482 50 - 482 50 - 482	٠.
Inspection Services Corp Institute for Policy Studies	8212270018 8212270027* 8212020358 8212280511	71-490 71-490 50-373 FOIA	P		8212170324 8212200036 8212210115 8212270187	50-492 PR 50-482 50-482	e e
Institute of Nuclear Power Operations	8212080250* 8212140077 8212140443 8212170149	50-407 50-10 50-254 50-155	보 보 무	Kansas, Unív of Kentucky, State of	8212270173* 8212280338 8212220535* 8212070317*	50-462 50-462 CONTRACT State Pr	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	łY	AUTHOR AFF 11 JATION	ACCESSION NUMBER	SUBJECT CATEGOR	
xerr-McGee Chemical Corp (subs of Kerr-McGee Corp) Kerr-McGee Corp	8212130432 8212130237 8212210512 8212210515# 8212230379	40-2061 40-2061 40-2061 40-2061 40-8027		Louisiana Power & Light Co	8212030036 8212030048 8212030055 8212070228* 8212070228*	50-382 50-382 50-382 50-382 50-382	SSS
	8212230380* 8212270563 8212280012* 8212280013 8212280018*	40-8027 40-8027 40-1478 70-1193 70-1193			8212100002 8212100098 8212100100 8212140395 8212150042	50-382 50-382 50-382 50-382 50-382	A O G S F
Marty-McClee Nuclear Corp Martypatrick, Lockhart, Hill. Christopher & Phillips	8212100403 8212100407* 8212100410* 8212290149 8212220394	40-8748 40-8748 40-8748 40-8748 50-275	o		8212150047* 8212150050* 8212200127* 8212200129* 8212210046	50-382 50-382 50-382 50-382	F
LlX3, inc Labat-Anderson, inc Labor,Dept of Late County, OH	8212040410 8212070453* 8212100398* 8212200057 7908140421*	FOIA CONTRACT FOIA PRM 50-206	F		8212210172 8212210230 8212210281 8212270015# 8212270017#	50-382 50-382 50-382 50-382 50-382	6 6 6 F
Lawrence Livermore Laboratory	7908140784* 7909180332* 8005070798* 8005280555*	50-217 50-244 50-237 50-217	P P P		8212270130 8212270138 8212270140 8212270146 8212270257	\$0-382 \$0-382 \$0-382 \$0-382 \$0-382	8 8
	8009050320* 8010220355* 8112160327* 8203010313* 8205040481*	FOIA 50-245 50-213 FOIA FOIA	ր P		8212280143 8212280169 8212280182 8212280203 8212290245	50-382 50-382 50-382 50-382 50-382	8 9 9 9
	8205240413* 8206290144* 8208030436* 8209230424* 8210260403*	F01A F01A F01A 50-250 50-204	P P		8212300162 8212300178 8212300217 8212300288 8212300310	50-382 50-382 50-382 50-382	A 9 9 9
	8211060556* 8211110457* 8212090023* 8212130370* 8212140459	50-284 50-440 50-243 50-344 50-261	P P P	Louisiana, State of Love]ace Bigmed & Environmental Research Institute Lowell General Hosp Lowell, MA Lowenstein, Neuman, Reis, Axelrad & Toll	8212100117 8212230192 8212220228 8212230020* 8212280279	50-458 50-458 NUREG 70-2792 50-498	0.0
LeRogur, Lamb, Leiby & MacRae	8212140464 8212140485 8212160773 8212010147 8212060028	NUREO NUREO NUREO 50-341 50-285	К Р Р		8212280279 8212280282 8212280282 8212280287 8212280541	50-498 50-498 50-498 50-522 27-47	G G
League of Women Voters of Rockford, IL	6212230317 6212060235 6212060235 6212060245* 6212060245* 6212280186	50-285 50-454 50-454 50-454 50-454 50-454	G G	M D. Anderson Mosp., Houston, TX MHB Technical Associates MPR Associates, Inc Maine Yankee Atomic Power Co.	8212070429* 8212270227 8212070155* 8212030299* 6212030304*	CONTRACT 50-322 TOPREP 50-307 50-307	T F F
Lotkheed Missiles & Space Co (subs Lotkheed Aircraft Corp) Long Island Lighting Co	8212270056* 8211080125 8212010082 8212010087	CONTRACT 50-322 50-322 50-322			8212060259 8212100266 8212130324 8212130324 8212140204 8212140435	50-309 50-309 50-309 50-309 50-309	P P P F
	6212010145 8212010371* 6212010393* 6212010397* 6212010401*	50-322 50-322 50-322 50-322 50-322	A A A		8212140442* 8212140453* 8212210165 8212210170* 8212210266*	50-309 50-309 50-309 50-309 50-309	F 6 8 0
	6212020361 6212070127 6212070217 6212140337 6212140463	50-322 50-322 50-322 50-322 50-322	e A A		8212210308 8212220370* 8212220374* 8212220454 8212230057*	50-307 50-309 50-309 50-309 50-309	F Q Q S F
	6212160065 8212200111 6212210224 6212210336 6212210406	50-322 50-322 50-322 50-322 50-322	9 Q A A E		8212230048* 8212290114 8212290128* 8212290291 8212290306*	50-309 50-309 50-309 50-309 50-309	F R R G
	8212210410# 8212210414# 8212230259 8212270196 8212270324	50-322 50-322 50-322 50-322	E E G G	Malapai Resources Co Management Analysis Co Mapleton Intervenors Morsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div	8212230121 8208290147* 8212220197 8212020269 8212020249	40-8771 COMMISSI 50-327 50-259	NOI O C
Los Alamos Scientific Laboratory iouisa County, VA	8212270380 8109280383* 8212130157 8212100104	50-322 50-322 REB 50-337 50-338	A G G		8212020335 8212280043 8212280043 8212280205 8212280222	50-250 50-245 50-245 50-358 50-321	
	8212140245 8212140245 8212140247 8212140247	50-338 50-338 50-338 50-338	e 0		8212280223 8212280223	50-321 50-348 50-348	רדר

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODA		AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJEC? CATEGOR	
	8212280258 8212280261 8212280334 8212280348 8212280348	50-244 50-259 50-483 50-348 50-348	רררר		8212170278 8212170278 8212170313 8212170327* 8212170334	50-416 50-416 50-416 50-416 50-416	P P 5 5
	8212280369 8212280369 8212280441 8212290150 8212290150	50-321 50-321 50-293 50-327 50-327	נננננ		8212170339* 8212200103 8212200106* 8212210155 8212210179	50-416 50-416 50-416 50-416 50-416	6) A S
	8212270213 8212270246 8212300107 8212300107 8212300202	50-315 50-259 50-327 50-327 50-250	,,,,,		8212210182* 8212210191 8212210192* 8212210203* 8212210212	50-416 50-416 50-416 50-416 50-416	
	8212300202 8212300243 8212300243 8212300294 8212300300	50-250 50-250 50-250 50-335 50-438	ררננ		8212210227* 8212210367 8212210371* 8212210375 8212230252	50-416 50-416 50-416 50-416 50-416	4115
Maryland, State of Massachusetts Institute of Technology	8212300333 8212230081 8212040120* 8212280406 6212280411*	50-27 NUREG CONTRACT 50-20 50-20	ե 1		8212230252 8212270147 8212270153* 8212270154 8212270154	50-416 50-416 50-416 50-416 50-426	<u> </u>
Massachusetts, State of flentor,KY Metropolitan Edison Co	8212070242 8212070184 8212010192 8212010200* 8212020364	50-443 50-358 50-289 50-289 50-289	G G G		8212270235 8212270235 8212280056 8212280057* 8212280080	50-416 50-416 50-416 50-416 50-416	F 5 5
	8212020377 8212060019* 8212070134 8212300246 8212300250	50-287 50-320 50-289 50-289 50-289	9 9 9		8212280081* 8212280150 8212280154* 8212280177 8212280183*	50-416 50-416 50-416 50-416 50-416	5 5 5 8
Miami Valley Power Project Michigan, State of Michigan, Univ of Midjand County, MI	8212020382 8212280128 8212070330* 8212040514 8212010391*	50-358 50-358 50-155 ACRS CONTRACT	е е		8212280194 8212280198* 8212280241 8212280245* 8212280308	50-416 50-416 50-416 50-416 50-416	95555
Miles Laboratories, Inc Minneapolis, MN Minock, J Mississippi Power & Light Co	8212200016 8212010398* 8212010191 8212140428 8212010176	PR CONTRACT 50-341 50-341 50-416	1 0 0 9		8212280311* 8212280312 8212280314* 8212280327 8212280336*	50-416 50-416 50-416 50-416 50-416	9 9 9 9
	8212020033 8212020037* 8212020056 8212020058	50-416 50-416 50-416 50-416 50-416	9 8 8 8		8212280344 8212280352* 8212280377 8212280386 6212280389*	50-416 50-416 50-416 50-416 50-416	\$ \$ \$ \$
	8212020045* 8212020138 8212020144* 8212070274 8212070074	50-416 50-416 50-416 50-416 50-416	8 8 8		8212280402 8212280412* 8212280458 8212280463* 8212280466	50-416 50-416 50-416 50-416 50-416	# \$ \$ \$ # #
	8212090075* 8212090078 8212090081* 8212090110 8212090113*	50-416 50-416 50-416 50-416 50-416	999		8212280475# 8212300039 8212300047* 8212300084 8212300087*	50-416 50-416 50-416 50-416 50-416	8 8 8
	8212070131 8212070134* 8212070131 8212070158* 8212070159	50-416 50-416 50-416 50-416 50-416	\$ \$ \$ \$		8212300114 8212300119* 8212300186 8212300200* 8212300222	50-416 50-416 50-416 50-416 50-416	60000
	8212090144* 8212090177 8212090184* 8212090191 8212090195*	50-416 50-416 50-416 50-416 50-416	9 9 8	Mississippi, State of Missouri, Univ of, Columbia Mitsubishi International Corp (subs of Mitsubishi Corp)	8212300228* 8212260535 8212080331 8212270082	50-416 NUREO 50-186 XPORTLIC	5 P
	8212090290* 8212090303* 8212090310* 8212090326 8212090344*	50-416 50-416 50-416 50-416 50-416	0 0 3 8	Mitsui & Co (U S A), Inc (Subs of Mitsui & Co ,Ltd)	8212270086* 8212270102 8212010114 8212010120*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	2
	8212100297 8212100306* 8212170137 8212170146*	50-416 50-416 50-416 50-416	8 8 8	Malurana Tan	8212010127 8212010133* 8212080221	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	;
	821 21 70209 821 21 70213* 821 21 70222 821 21 70227*	50-416 50-416 50-416 50-416	S S S	Molycorp, Inc Monroe County, MI Montana: State of Morgan Associates	8212010072 8212020353 8212020318	50-341 PR 50-247	0
	8212170263 8212170277*	50-416 50-416	8		8212040103 8212040103	50-247 50-247 50-247	900

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	6212080310 6212090087 6212140423 6212140439 6212140439	50-247 50-247 50-247 50-247 50-247	G G G	New Jersey. State of New Mexico, Univ of	8212230346 8212230348 8212230348 8212280543 82122010109	50-443 50-443 50-443 NUREO RES	6
	8212140446* 8212140446* 8212140289 8212160289 8212210320	50-247 50-247 50-247 50-247 50-247	0 0 0 0	New York Caty Audubon Society New York Univ	8212220246 8212040077 8212040077 8212040069* 8212040069*	50-247 50-247 50-247 50-247 50-247	000
	8212210320 8212220271 8212220271 8212220378 8212220187	50-247 50-247 50-247 50-247 50-247	0 0 0 0	New York, State of New York, State of, Energy Office New York, MY	6212040098 6212230241 6212290055 6212070246 6212140242	50-247 50-247 50-244 50-247 50-247	6 5 6
Horris, IL	8212230187 8212280285 8212280285 8212300230 8212010430*	50-247 50-247 50-247 50-247 CONTRACT	G G		8212230235 6212230241 6212230241 6212230270 6212230270	50-247 50-247 50-247 50-247 50-247	0 0 0
N H Newmerk Consulting Engineering Stivices NC1 Engineering, Inc	7907100669* 7907240319* 7908080624* 7911150252* 8005280561*	50-237 50-237 50-237 50-237 50-219	P P P P	Niagara Mohawk Power Corp	8212230337 8212020102 8212020302 8212030050# 8212030144	50-247 50-220 50-220 50-220 50-410	8 9
NUG Corp NUSAC, Inc NUTICH (Nuclear Technology, Inc.)	8212010036* 8212070201* 8212220034* 8212100303* 8212150072*	50-206 50-440 CONTRACT 50-231 50-331	ቦ ራ		8212040204 8212080159 6212090106 8212090154 8212100207	50-220 50-220 50-220 50-220 50-410	F F P A
	8212210327* 8212210330* 8212210333* 8212210337* 8212210342*	50~263 50~263 50~263 50~263	ր թ թ		8212140029 8212140031* 8212140093 8212140372 8212140406*	50-220 50-220 50-410 50-410 50-220	11 12 13 13 14 14 14 14 14 14 14 14 14 14 14 14 14
National Academy of Sciences	BR1R210346# B212270307# B212270313# BE12100133# 8212270447#	50-243 50-237 50-237 CONTRACT CONTRACT			8212190213* 8212170266 8212200023 8212220479* 82122270265	50-220 50-220 PR 50-220 50-220	G G
National Council on Radiation Protection & Measurements	6212020144	яч			8212270353 8212280363	50-220 50-410	Р В
National Wildlife Federation	6212070172 6212160267	50-522 50-522	G G	Nissho-lwai American Corp	8212290416 8212290430* 8212160796	50-220 50-220 XPORTLIC	8 8
Natural Resources Defense Council	6212060257 6212200021 6212220246* 6212230200 6212280270	50-537 70-143 70-143 50-537 70-143	e e	North Carolina State Univ North Carolina, State of North Carolina, Univ of	8212070185 8212160378 8212020383 8212270361	50-111 70-1113 PR NUREO	
Navy, Dept of Naval Facilities Eng Command	0212020110	PR		North Dakota, State of Northeast Nuclear Energy Co (subs of	8212020251 8211080257	PR 50-245	
Nuvy.Dept of Nebraska Public Power District	8212230156 8212030159 8212030162* 8212070141* 8212070175	71-474 50-298 50-298 50-298 50-298	ր գ գ	Northeast Utilities)	8212030180 8212030187* 8212030201 8212030204*	50-245 50-245 50-336 50-336	£ 8 8
	8212070402 8212070491* 8212100171 8212100293 8212130342*	50-278 50-278 50-278 50-278 50-278	r r r		8212030227 8212030234* 8212070124 8212070266 8212080414	50-336 50-336 50-245 50-245 50-336	9 8 P 9
	6212130346# 6212140472 6212160433 6212260397 6212260312	50-278 71-7001 71-484 50-278 50-298	r r R		8212080415* 6212080445 6212080453* 6212080541 6212090114	50-336 50-245 50-245 50-423 50-213	9 9 9 9 8
Neutron Products, Inc Novoda. State of	8212290315# 8212300104 8212300111# 8212230207 8212230207	50-298 50-298 50-298 71-9094 WASTE MO			8212100071 8212100277 8212140144 8212140221* 8212150128	50-245 50-245 50-336 50-245 50-245	0 pp
New England Coalition on Nuclear	8212230212* 8212200037	WASTE MO 50-443	G		8212150128 8212150142* 8212150142*	50-245 50-245 50-245	P P
Pellution New Hampshire, State of	8212200039 8212200049* 8212200049* 8212100102	50-443 50-443 50-443 50-443	0 0 0 0		8212160371* 6212160371* 6212160470	PR 50~245 50~245 50~423	8 8
	6212140227 6212140227 6212140234	50-443 50-443 50-443	0 0 0		8212170117 8212170199 8212170199	50-245 50-245 50-245	P P
	8212140234 8212140281 8212230344	50-443 50-443 50-443	G G		8212170279 8212170321 8212170322* 8212210121	50-245 50-245 50-245 50-213	9 9

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFF IL TATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8212210121 8212210229 8212210233* 8212210355 8212210579*	50-213 50-336 50-336 50-423 50-245	P 9 5 F F		8212150293 8212150298* 8212160072 8212160420 8212160429	70-143 70-143 70-143 70-143 70-143
	8212210581* 8212270152 8212290139 8212290142* 8212290224	50-245 50-245 50-336 50-336 50-245	F R R	Nuclear Packaging, Inc	8212220527 8212270124* 8212270544 8212270377 8212270382*	70-143 70-143 70-143 71-9079 71-9079
Northeast Utilities	8212290229* 8212290447 8211080257 8212020200 6212020208*	50-245 50-245 50-245 TOPREP TOPREP	R P	Nuclear Sources & Services, Inc Wak Ridge National Laboratory	8212270408 8212130222 8212010486 8212060460 8212060465	71-9073 71-394 RES NUREO NUREO
	8212030180 8212030201 8212030227 8212050157 8212060157	50-245 50-336 50-336 50-213 50-213	8 8 8 B B		8212070435 8212130123 8212130135 8212140479 8212160549	50-250 P NUREQ NUREQ 50-259 P RES
	8212070124 8212070284 9212080414 8212080445 8212080453*	50-245 50-245 50-336 50-245 50-245	F P S S		8212160558 8212160564 8212220013* 8212220021 8212220060	RES RES 40-6500 RES RES
	8212080541 8212100071 8212100277 8212140144 8212140221*	50-423 50-245 50-245 50-336 50-245	8 0 P 0		8212220519 8212270416 8212270435 8212270441 8212270492	RES RES NUREO NUREO NUREO
	8212150128 8212150128 8212160216 8212160358 8212160470	50-245 50-245 PR 50-245 50-423	8 6 6	Ocomer County, 55 Office of Management & Budget	8212290512 8212010434* 8212010213 8212010219 8212010241	RES CONTRACT ORO DRO ORO
	9212170199 9212170199 9212170279 9212170321 9212170323+	50-245 50-245 50-245 50-245 50-245	ե Ե	Ogle Petroleum, Inc	8212010247 8212010253 8212010256 8212070461 8212070480	DRG ORG ORG 40-8745 40-8745
	8212210121 8212210227 8212210355 8212270152 8212270152	50-213 50-336 50-423 50-245 50-336	P 5 7 8	Ohio Citizens for Responsible Energy	8212100083 8212170404 8212170407* 8212060108 8212070196	40-8745 40-8745 40-8745 50-440 50-440 6
Northern California Power Agency, California Blate of, Northern States Power Co	8212290188 6212290224 8212290447 8212270502* 8212020311	TOPREP 50-245 50-245 CONTRACT	2 1 6 6		8212070194 8212070199 8212070199 8212070203 8212070203	50-440 6 50-440 9 50-440 9 50-440 6 50-440 6
	9212020317* 9212070391 9212080420 8212080429* 9212090057	50-262 50-263 50-282 50-282 50-282	3 P S S P		8212230267 8212230267 8212230319 8212230319 8212230345	50-440
	8212070057 8212070059* 8212070059* 8212090172 8212090172	50-282 50-282 50-282 50-282 50-282	P P P		8212230345 8212230348 8212230348 8212280324# 8212280324#	50-440 ¢ 50-440 ¢ 50-440 ¢ 50-440 ¢
	8212090352* 82121 40244 82121 40279 82121 40344 82121 40357*	50-243 50-243 50-282 50-243 50-243	0 F F 9 8	Ohio State Univ	8212290031 8212010074# 8212010079# 8212080577# 8212150252#	50-446 A 50-156 F 50-150 F CONTRACT 50-243 F
	8212170262 8212210270 8212210325 8212280325 8212300416*	50-282 50-262 50-243 50-282 50-282	Р Р Р	Ohio, State of Otlahoma, Univ of	8212150257* 8212210435 8212010064* 8212060230* 8212060233*	50-243
Northern Telecom Northrop Corp Northwest Energy Services Co	8212300417* 8212160524 8212080174 8212080200* 8210170727	50-282 PR 50-187 50-187 50-522	r R R B	Omaha Public Power District	821202093 8212030099 8212030013* 8212040028	50-285 P 50-285 P 50-285 G 50-285 G 50-285 P
Norton, Burke, Berry & French Nuclear Associates International Nuclear Energy Bervice, Inc Nuclear Energy Services, Inc (subs of Getty Oil Co)	8212280123 8212080024* 8212280061* 8212080028*	50-275 CONTRACT 50-409 FOIA	G.		8212040032* 8212040035* 8212040254 8212040244 8212040248*	50-285 P 50-285 P 50-285 P 50-285 Q 50-285 Q
•	8212080032* 8212090260 8212090469 8212130189	FOIA 70-143 70-143 70-143			8212040438 8212070150* 8212070419 8212080380 8212100244*	50-285 P 50-285 P 50-285 P 50-285 F 50-285 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	JRY .	AUTHOR AFF ILIATION	ACCESSION AUMBER	SUBJECT CATEGOS	
	8212130312 8212140416 8212200059 8212200064* 8212210022*	50-285 50-285 50-285 50-285 50-285	F P R R		8212140135 8212140138* 8212140188* 8212140187* 8212140258	50-387 50-387 50-387 50-387 50-387	88888
Orange County Alliance for Survival Oregon Environmental Council	8212210199 8212230326* 8212280197 8212290023 8212070172	50-285 50-285 50-285 50-204 50-522	P P G G		8212140261* 8212140268 8212140325* 8212140497* 8212140497*	50-387 50-387 50-387 50-387 50-387	8887
Oregon, State of Ossining, NY Pacific Oas & Electric Co	8212230073 8212150013# 8212010190 8212010190 8212030190	NUREG 50-247 50-275 50-275 50-275	Т Р Р		8212140317 8212160417 8212160419* 8212170271 8212170272*	50-387 50-387 50-387 50-387 50-387	ե ե ե
	8212030191 8212060047 8212060053* 8212060078 8212070225	50-275 50-275 50-275 50-323 50-275	P R R S P		8212210052 8212210057* 8212210236 8212210241* 8212210241	50-387 50-387 50-387 50-387 50-388	8 8 8 A
	8212080043* 8212080043* 8212080071* 8212090084 8212130070	50-275 50-275 50-275 50-275 50-275	F F G F		8212210343 8212210347* 8212210450 8212220405* 8212220405*	50-387 50-387 50-387 50-387 50-387	8 8 8 8
	9212140473 8212170217 8212170223* 8212210002 8212210005*	50-275 50-275 50-275 50-275 50-275	P R R P P		821 2280323 821 2280346 821 2280347 821 2280 400 821 2280 400	50-388 50-388 50-387 50-387 50-387	9 9 9 9
	8212210014 8212210090 8212210116 8212210123* 8212220217	50-275 50-323 50-275 50-275 50-275	ե 8 8 V		8212280403 8212280417# 8212280446 8212280465 8212280468*	50-387 50-387 50-387 50-387 50-387	8 9 9 9
	821 2220225* 821 2220229* 821 2230210 821 2230278 821 2230278	50-275 50-275 50-275 50-275 50-275	ր P P		8212270115 8212270117* 8212270441 8212270446* 8212300408*	50-387 50-387 <i>50-387</i> 50-387 50-387	R R 9 9
	8212230304* 8212230304* 8212270371 8212260098 8212280123	50-275 50-275 50-275 50-275 50-275	С Б Б Б	Pennsylvania State Univ Pennsylvania. State of	6212300410* 6212030010 6212010186 6212070502 6212160271	50-387 50-5 50-289 50-289 50-289	F P G G
	8212270182 8212270186* 8212270214 8212270218* 8212270366	50-133 50-133 50-275 50-275 50-275	R R R R	Parkins, Cole, Stone, Olsen & Williams Philadelphia Electric Co	8212160374 8212160457* 8212070237 8212270225 6210040237	PR 40-6500 50-522 50-522 50-352	Q G K
Palmetto Alliance	8212290372* 6212280132 6212280132 6212280138 6212280136	50-275 50-413 50-413 50-413 50-413	R G G G		8210040237 8210040253* 8210040267* 8210040267* 8210040272*	50-352 50-352 50-352 50-352 50-352	} ; ;
Parameter, Inc Parents Concerned About Indian Point Pathfinder Mines Corp	0212010016* 0212010021* 0212070109 0212150017 0212230155	FOIA FOIA 50-247 50-247 40-2259	O Q		8210040272* 8210040278* 8210040278* 8212020330 8212020330	50-352 50-352 50-352 50-352 50-352	C Q
Pennsylvania Power & Light Co	8212230163* 6212270132 6212270136* 6211070017 6212030041	40-2259 40-6622 40-6622 50-387 50-387	E 8		8212020339* 8212020339* 8212020349 8212020349 8212020352*	50-352 50-352 50-277 50-277 50-277	G R R R
	8212030047# 8212030096# 8212030173 8212030179# 8212040046	50-387 50-387 50-387 50-387 50-387	9 9 8 P		8212020352* 8212030122 8212030132* 8212030132* 8212030132*	50-277 50-352 50-352 50-352 50-352	R A A A
	8212040044 8212040140 8212080295 8212080303* 8212080320	50-397 50-397 50-397 50-397 50-397	P 6 8 8		6212030205 6212030208* 6212060076 6212060076	50-278 50-278 50-277 50-277 50-277	4 4 6 6
	8212080328* 8212080333 8212080342* 8212080342 8212080347	50-387 50-387 50-387 50-387 50-387	8 8 8 8		8212040104* 8212040109* 8212040109* 8212070025 8212070028	50-277 50-277 50-277 50-352 50-352	9 9 8 A
	8212080372* 8212080378* 8212080382 8212080386* 8212070214	50-387 50-387 50-387 50-387 50-387	3 S S S S S S S S S S S S S S S S S S S		8212070138 8212070138 8212080323* 8212080446 8212080446	50-352 50-352 50-277 50-352 50-352	F G A A

		BUBJECT		AUTHOR AFF IL IAT ION	ACCESSION NUMBER	SUBJECT	
AFFILIATION 82	NUMBER NUMBER 212090119 212100036 212100079*	50-277 P 50-277 P 50-277 F 50-278 P 50-278 P	•		8212100411* 8212140280 8212140346 8212140347 8212140355*	50-344 f 50-344 f 50-344 g 50-344 g	
92 82 83 83	212100090 212100274 212130211 212130341 212140385	50-352 F 50-352 C 50-277 P 50-352 K 50-277 P	; ; ;		8212210201 8212270368 8212280170 8212280283 8212280470	50-344 P 50-344 P 50-344 P 50-344 P 50-344 P	
9 9 8	2121 50058 2121 50058 2121 50051 2121 50062*		3	Power Authority of the State of New York	8212290201 8212290204* 8212020318 8212020318 8212020918	50-044 R 50-044 R 50-247 0 50-247 9 50-003 R	ļ 1
9 8 8	212150187* 212150187* 2212150193* 2212160055 2212160055	50-277 50-277 50-277 50-277	r F R R		8212040101 * 8212040103 8212040103 8212040223 8212040223	50-333 S 50-247 S 50-247 S 50-333 S 50-331 S	} } ;
5 6 8	3212160058# 3212160058# 3212160415 3212170248 3212170248	50-277 50-277 50-277 50-277	ጽ 8 የ የ		8212040292 8212040294* 8212080310 8212080310 8212080374	50~733 (50~333 (50~247 (50~233 (G Q
E 5 8 8	9212170265 9212170265 9212170275* 9212170275* 9212170280*	50-277 50-277 50-277 50-277	후 우 우		8212080394 8212080406* 8212090087 8212090090 8212090090	50-333 50-247 50-247 50-247	դ ն գ գ
	8212170289 8212170289 8212170315 8212170315 8212170315	50-277 50-277 50-277 50-277	P P P የ		6212070205 6212100214 6212100266 6212100061 6212130084#	50-286 50-286 50-337 50-333	p P P H H
	8212210158 8212210142* 8212210142* 8212210312 8212210312		Я Я Я Р		8212130232 8212130232 8212130330 8212130355* 8212130357*	50-247 50-266 50-266 50-266	ኒ 6 6
	6212210398 6212210398 6212210402 6212210491 6212210491	50-352 50-352 50-352 50-352 50-352	F A K K		8212140064 8212140070# 8212140236# 8212140294 8212140423	50-20A 50-333	8 0 1 0
	6212210495* 6212210496* 6212210498* 6212210499* 6212210499*	50-352 50-352 50-352 50-352 50-352	А С С К К		8212140423 8212140439 8212140439 8212140444* 8212140446*	50-247 50-247 50-247 50-247 50-247	0 0 0 0
	8212230313 8212230327 8212230327 8212270141 8212270141	50-277 50-352 50-352 50-352 50-352	F G G A		8212150126# 8212160289 8212160289 8212210248 8212210274#	50-323 50-247 50-247 50-333 50-333	a 0 0
	8212270144 8212270144 8212270167 8212270216 8212270219	50-352 50-352 50-277 50-352 50-278	F F O P		8212210322 8212210323* 8212210415 8212210425* 8212210426	50~204 50~333 50~333 50~205 50~204	ր 6 1
	8212280185 8212280209 8212280209 8212280452 8212290452	50-352 50-352 50-352 50-277 50-277	С А А Р		8212220234 8212220271 8212220271 8212220398 8212220452	50-266 50-247 50-247 50-247 50-337	(() () () ()
Philadelphia Inquirer Planning Research Corp	8212270276 8212300187 8208270112 8212140015* 8212140022*	50-352 50-352 70-143 FOIA FOIA	R ©		8212230187 8212230187 8212270259 8212280285 8212280285	50-247 50-247 50-266 50-247 50-247	0 0 0
Plateau Resources, Ltd.	8211020241 8211020252* 8212270319 8212270340 8212300120	40-8498 40-8498 40-8498 40-8498 40-8498	!	Prairis Alliance	8212270156 8212270160* 8212270175 8212300230 8212270322	90-284 90-285 90-333 50-247 50-461	R P 0 0
Pullution & Environmental Problems, Inc Portland General Electric Co	8212070411 8212030011 8212030017* 8212030027 8212070314	50-295 50-344 50-344 50-344 50-344	6 8 8 8	Press Intelligence,Inc Professional Reactor Operator Society Project Associates Project Management Corp	8212080103* 8212130344 8212020134 8212290273* 8212040113	CONTRAC CONTRAC PR CONTRAC 50-537	T
	8212070319x 8212070343 8212070346x 8212100044 8212100406x	50-344 50-344 50-344 50-344	8 R R F	Public Interest Research Group, New Yor	8212070082 8212200011 k 8212200011 k 8212080280	50-537 50-537 50-537 50-289 50-247	6

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Public Service Co of Colorado	8212200011# 8212200030 8212200035# 8212200043 8212200050	50-267 50-267 50-267 50-267 50-267	7 7 7 7	***************************************	82121 40235 82121 40430 82121 40430 82121 40437* 82121 40437*	50-443 50-443 50-443 50-443 90-443	A 0 0 0 0
	8212200090* 8212200092 8212200094 8212200098* 8212200101*	50-267 50-267 50-267 50-267 50-267	GI GI F GI		8212140441 8212140441 8212210228 8212210273 8212210273	50-443 50-443 50-443 50-443 50-443	9 9 9
	8212200116* 8212200117* 8212200123 8212200128* 8212210024*	50-267 50-267 50-267 50-267 50-267	r 9 8 9		82122 t0287 82122 10287 82122 10449 82122 10449 82122 20255	50-443 50-443 50-443 50-443 50-443	8888
	8212210102 8212210112* 8212210173* 8212290297 8212270303*	50-267 50-267 50-267 50-267 50-267	R G S S		8212270146 8212270146 8212270188 8212270270 8212270270	50-443 50-443 50-443 50-443 50-443	A A A
	8212270317 8212270328 8212270347 8212270374 8212270366	50-267 50-267 50-267 50-267 50-267	Р Се Р Р	Public Service Electric & Gas Co of New Jersey	8212270279 8212270279 8210210078	50-443 50-443 50-311	A A G
	8212290391 8212290394* 8212290403 8212290405* 8212290423	50-247 50-267 50-267 50-267 50-267	R R P P		8212010148 8212010148 8212010150* 8212010155 8212030117	50-272 50-272 50-272 50-272 50-271	9 9 8
Public Service Co of Indiana, Inc	6212290424 8212290440# 8212080633* 8212080637* 8212100181	50-267 50-267 50-546 50-546 50-546	8 6 8		8212030153* 8212040165 8212040174* 8212040202 8212040214*	50-272 50-311 50-311 50-311	9 9 9
	8212170329 8212280157 8212280157 8212280272 8212280304	50-546 50-546 50-546 50-546 50-546	5 5 6 6		8212040291 8212040302 8212040308* 8212040309 8212040314*	50-272 50-272 50-272 50-272 50-272 50-272	9 8 8 8
	821 2280304 821 228032 1 621 228032 1 821 2280462 821 2280462	50-546 50-546 50-546 50-546 50-546	0 0 0 5 5		8212080356 8212080364* 8212080434 8212080443* 8212080502	50-272 50-272 50-311 50-311 50-354	0 9 9 0
Public Service Co of New Hampshire	821 2020284 821 2020284 821 2020284 821 2020284	50-546 50-443 50-443 50-443 50-443	F A A A		8212130192 8212130212 8212140053 8212140060* 8212140076	50-311 50-272 50-272 50-272 50-272	P F
	8212020316 # 8212020316 # 8212020334 8212020334 821202034	90-443 50-443 50-443 50-443 50-443	A A A		8212140079 8212140082# 8212140085# 8212140099 8212140107#	50-311 50-272 50-311 50-311 50-311	
	6212030194 6212040054 6212040054 6212040059 6212040059	50-443 50-443 50-443 50-443 50-443	6 6 6		82121 40133* 82121 40024 82121 40024 82121 60046 82121 60054*	50-272 50-354 50-354 50-311 50-311	(8
	8212040048 8212040048 8212040075 8212040075 8212040074	50-443 50-443 50-443 50-443 50-443	D A A		82121 40381 82121 40390* 82121 40399 62121 40414* 62122 00020	50-311 50-311 50-311 50-311 50-272	9 9 9 9
	8212060074 8212060151 8212060151 8212070100 8212070100	50-443 50-443 50-443 50-443	^ ^ ^ A		8515550382* 8515550381 8515550310* 8515550300 85155500050	50-272 50-272 50-272 50-311 50-311	Gr Gr
	8212080143 8212080143 8212080170 8212080170 8212080207	50-443 50-443 50-443 50-443	F A A		8212220395 8212220406* 8212220420 8212220424* 8212220423	50-311 50-311 50-311 50-311 50-311	9 9
	8212080207 8212080224 8212080224 8212080329* 8212090498	50-443 50-443 50-443 50-443	A A G A		8212220435* 8212230268 8212230271* 8212270274 9212270280*	50-311 50-272 50-272 50-311 50-311	B R R R
	8212140212 8212140212 8212140217 8212140217 8212140235	50-443 50-443 50-443 50-443 50-443	0 0 0 4 A		8212280046 9212280047 9212280048* 8212270444*	50-272 50-354 50-272 50-354	R R G

Parker Carl April Apri	AUTHOR APF ILIATION	ACCESSION NUMBER	SUBJEC	IRΥ	AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	Puget Sound Power & Light Co	8212300306 8212070239 8212140419 8212270225	50-272 50-522 50-522 50-522	F G A G		8212070410 8212130337 8212140351	50-312 50-312 50-312	9 9 6
		8212010428* 8212130238 8212130240*	ACRS 50-182 50-182	Ρ		8212140391 6212140401 6212140009	50-312 50-312 71-489	P P
Reference Refe	Recal Vikonics, Inc Radio Television News Directors	82121 40447 82122 70516#	50-275 CONTRAC	R		8212170220 8212170231 8212170235* 8212170255	50-312 50-312 50-312	P R R P
Rathann College 1982 198		8515190218	PR					
Reference Refe	Raytheon Corp Reed: J O	8212210504# 8212010109 8212210276	71-469 REB 50-463			8212170320* 8212200026 8212200042	50-312 50-312 50-312	P G R
## Pare that is relate Associates Pare Pare that is relate Associates Pare that is relate Associates Pare that is related Pare		8212230404 8212230411* 8212270331	40-8084 40-8084 40-8084	,		8212220241 8212270283 8212270285	50-312 50-312 50-312	P P
Rechaster Gas & Electric Corp S012000000 S0-200 P Sandia Laboratories S01200004 P S01200004 S01200004 P		8212140276 8212140277# 8212150164	CONTRAC 50-275 50-275 50-275	T P P		8212280233 8212300353* 8212170128*	50-312 50-312 50-498	ቦ ብ ለ
	Rochester Gas & Electric Gorp	8212200080 8212200095* 8212200095	50-275 50-275 50-244 50-244	8 6 6	Sandia Laboratories	8212200046 8212010467 8212010475	PR RES RES	F
Bill 100		8212070094 8212070095* 8212070098* 8212070282	50-244 50-244 50-244 50-244	թ թ		8212040492 8212100158* 8212130058	50-313 FOIA NUREG	þ
Size		8212140240 8212140404 8212140408* 8212140413*	50-244 50-244 50-244 50-244	F P P		8212130283 8212150274 8212220162	NUREG 71-5939 NUREG	
Rackwell International Corp S212140451 S0-247 H Salphone S21220039 S0-247 H Salphone S21220039 S0-241 H Salphone S21220048 S0-261 S21220048 S0-261 S2122007476 S2122000746 S2122007476 S2122007476 S2122007476 S2122007476 S		8212220243 8212280388 8212280391* 8212270163	50-244 50-244 50-244 50-244	P P R		8212220291 8212220513 8212270154	NUREG NUREG NUREG	
Rocky Hountain Energy Co. S2122030284 S0-2410 S212030285 A0-8380		8212140451 8212230323 8212130138* 8212210110	50-247 50-247 71-6495 50-375	e H	Saul, Ewing, Remick & Saul	8212280489* 8212040420 8212070476*	50-461 FOIA XPORTLIC	
Rogers Engineering Co , Inc S212010115 B21220341 B21220341 B212270417* B212210010* B212140212		8212280373* 8212030284 8212030295* 8212230183	50-410 40-8360 40-8360 40-8360		Science Applications, Inc	6206310315* 6207030322* 6207030343*	50-231 50-255 50-213	ն 6
S212140217 S0-443 G S2121402608 S0-247 G S2121402608 S0-247 G S2121402608 S0-247 G S2121402608 S0-247 G S2121404224 S0-443 G S212140424 S0-443 G S21220334 S0-443 G S21220335 S0-443 G S21220335 S0-443 G S21220335 S0-443 G S21220335 S0-443 G S21220334 S0-443 G S21223034 S0-443 G S21223334 S0-312 S S44444 S0-444 G S21223344 S0-324 G S2122344 S0-324	Rogers Engineering Co .Inc Rolf Jansen & Associates, Inc	8212010115 8212220341 8212270417* 8212140212	NUREO NUREO CONTRAC 50-443	T G		8212010469 *4910202128 *40E0402128	RES CONTRACT CONTRACT	
Secretarian		8212140217 8212140430 8212140430	50-443 50-443 50-443	6 6		9212130058 9212140260* 9212270422*	NUREG 50-29 CONTRACT	P
## ## ## ## ## ## ## ## ## ## ## ## ##	Sacramento Municipal Utility District	8212140441 8212210228 8212220255	50-443 50-443 50-443	0 0		8212140424 8212140321 8212230334	50-443 50-443 50-443	(F
8212030116* 50-312 B Shaw, Pittman, Potts & Trowbridge 8212010192 50-289 0 8212040294 50-312 S 8212040208 50-440 6 8212040300* 50-312 S 8212040208 50-440 6 8212040300 50-312 S 8212040208 50-440 6		8212030084 8212030095* 8212030106*	50-312 50-312 50-312 50-312	8 8 8		6212100045* 6212220558* 6212270431*	50-329 CCMMISSI 50-329	UN H
		8212030114# 8212040294 8212040300*	50-312 50-312 50-312	s	Shaw, Pittman, Potts & Trowbridge	6212010208 6212010208 6212010208	50-287 50-440 50-440	6 6

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'	
	82120 10212 82120 20364 82120 70096* 82120 70134 82120 70358	50-440 50-287 COMMISSI 50-287 50-440	G G		8212170257 8212170297 8212170297 8212100110 8212200115	50-395 50-395 50-395 50-395 50-395	8 8 8 8 4
	9212070358 9212080293 9212100098 9212100099 9212100100	50-440 50-440 50-362 50-400 50-382	6 6 6 8		8212220328 82122203374 8212220376 8212220384* 8212220411	50-395 50-395 50-395 50-395 50-395	86888
	8212130241 8212130241 8212140445 8212140470 8212140247	50-440 50-440 50-440 40-2041 50-440	G G G		8212220414* 8212220428 8212220462* 8212220478 8212220500*	50-295 50-395 50-395 50-395 50-395	5 5 5
	8212160247 8212160251 8212160251 8212260026 8212260061	50-440 50-440 50-440 50-312 50-440	9 9 9 9	South Carolina, State of	8212230288 8212230294* 8212300055 8212300042* 82123090481*	50-395 50-395 50-395 50-395 State Pr	P P 9 9
	8212200105 6212210222 6212210321 6212210345 6212230339	50-440 50-400 50-440 50-440 50-440	G G G	Bouthern California Edison Co	8005050726* 8110190752* 821201017(8212020250 8212020253	50-204 50-206 50-361 50-206 50-206	Р Р Р
	6212230357 6212230357 6212230359* 6212230359* 6212270222	50-266 50-266 50-266 50-266 50-400	0 0 0 0		8212020373 6212020373 6212030157 6212030148+ 8212030250*	50-361 50-361 50-361 50-361 50-361	ե Ե
	8212270330 8212280182 8212300013 8212300226 8212300250	50~382 50~382 50~440 50~483 50~289	Q G G Q		8212060012 6212060237 6212060249 8212070190 6212070193*	50-362 50-206 50-206 50-361 50-361	5 5 6 6
Sigma Chemical Co Sinclair, M	8212080257 6212100371 8212230200 8212270417 8212280191	50-537 FOIA 50-537 XPORTLIC 50~358	G G G		8212070225 * 8212070231 * 8212070252 8212070259* 8212070259*	50-361 50-361 50-361 50-361 50-206	6 8 8
Sinnissippi Alliance for the Environment (SAIE) Email Business Administration	8212080235 8212080245* 8212070453* 8212080583* 8212220027*	50-454 50-454 CONTRACT CONTRACT			9212070281 8212070283 82120702874 8212070290 8212070293*	50-361 50-361 50-361 50-361 50-361	9 8 8 8
Snrll & Wilmer South Carolina Electric & Gas Co	8212270501* 8212040095 8212020340 8212030060 8212030064*	50-537 50-528 50-375 50-375 50-375	A G F S 9		8212070294* 8212070324 82120703397* 8212070330 8212070340*	50-361 50-361 50-261 50-361 50-361	ននេះ
	0212030087 8212030100 0212030133 8212030137* 8212030164	50-395 50-395 50-395 50-395 50-395	ន ន ន ទ ច		8212070369 8212070374 8212070377 8212070383 8212070388*	50-361 50-361 50-361 50-361 50-361	9 9 9 9
	8212030171* 8212030184 8212030188 8212030197* 8212030202*	50-395 50-395 50-395 50-395 50-395	ន ន ន ន ទ		62120703999 8212070406 8212070412# 8212090103 8212090176	50-361 50-361 50-361 50-206 50-361	8 9 9 P
	8212070026* 8212070128 8212070181 8212070243 6212070253*	50-395 50-395 50-395 50-395 50-395	ល F ព ទ ទ		8212090174 8212090174 8212090376 8212090514 8212090514	50-361 50-361 50-361 50-361	6 6 6
	8212090366 8212090372* 8212090392 8212090422 8212090438*	50~395 50~395 50~395 50~395 50~395	ន G G S S		8212130039 8212130189 8212130193* 8212130198* 8212130333*	50-362 50-206	ь Б Б
	8212090449 8212090460# 8212090516# 8212100292 8212150077	50~395 50~395 50~395 50~395 50~395	ន ១ ៤ ೯ ន		82121 40035 82121 40035 82121 40151 82121 40265 82121 40270*		9 F 8
	8212150081* 8212150087 8212150091* 8212150097 8212150100*	50~395 50~395 50~395 50~395 50~398	ន ន ន ទ		8212140272* 8212140368* 8212140368* 8212140398 8212140405*	50-206 + 50-204 + 50-361 + 50-361	9 9 9
	8212150117 8212150122* 8212160322 8212160329*	50~395 50~395 50~395 50~395	8 8 F F		6212170158 6212170164 6212170164 6212170208 6212170364	50-361	የ F F 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	82121 70394* 82121 70384* 82121 70396* 8212200028 8212200063	50-206 50-206 50-206 50-206 50-206	 Q Q Q P		8212080479 8212100206 8212100291 8212140278 8212140281	50-275 P 50-275 P 50-275 P 50-275 P 50-275 R
	82122 10001 82122 30260 82122 30260 82122 30260	50-206 50-206 50-361 50-361 50-361	P P P P		8212140285* 8212230306 8212270218* 8212270299* 8212270301*	50-275 R 50-275 P 50-271 P 50-275 P 50-275 F
	8212230271 8212230325 8212230347 8212270171 8212270038*	50-361 50-361 50-361 50-206 50-206	P P J Q		8212270310* 8212270312* 8212290146 8212290152* 8212290205	50-275 P 50-275 P 50-275 R 50-275 R 50-275 P
	82122 90102 82122 90104* 62122 90159 82122 90176 82122 90181*	50-206 50-206 50-327 50-361 50-361	R R R R	Teledyne Wah Chang Albany	8212270237* 8212270243* 8212270250* 8212270452* 8212300178	50-275 P 50-275 P 50-275 P 50-245 P XPORTLIC
Southwest Research Institute Spencer Chemical Co Spingel & McDiarmid	8212270413 8212150134* 8212170094* 8212280026* 8212270502*	50-361 50-389 50-277 70-146 CONTRACT	8 A P	Tennessee Valley Authority	8212020107 8212020107 8212020116 8212020124* 8212020137	50-438 6 50-438 6 50-296 8 50-296 8 50-438 6
Stamiris, B	8212020343 8212020343 8212020345 8212020345 8212100095	50-329 50-329 50-329 50-329 50-329	G G G		9212020137 8212020139 8212020139 8212020143 8212020149	50-438 9 50-438 9 50-438 9 50-260 9 50-438 9
Btamdardised Nuclear Unit Power Plant System	8212170288 8212170288 8212170288 8212170293* 8212170293*	50-482 50-482 50-482 50-482 50-482	A A A A		8212020149 8212020153* 8212020162 8212020162 8212020179	50-438 S 50-260 S 50-438 S 50-438 S 50-328 S
	8212170293* 8212280236 8212280236 8212280236 8212280240*	50-482 50-482 50-482 50-482 50-482	A A A A		8212020191* 8212020240 8212020244* 8212020261 8212020264*	50-328 S 50-296 S 50-296 S 50-296 S 50-296 S
State. Dept. of. Sureau of Oceans & Internat! Environ & Scientific Affairs	8212280240* 8212280240* 8212230432	50-482 50-482 XPORTLIG	A A		8212020278 8212020278 8212020348 8212020354# 8212020368	50-390 8 50-390 8 50-259 9 50-259 9 50-390 B
Stovenson & Associates Stone & Webster Engineering Corp	8212060458 8212270221 8212010225* 8212020242 8212150195	NUREG NUREG 50-275 PR 50-275	R P		8212030001 8212030001 8212030001 8212030001	50~390 S 50~390 S 50~390 S 50~390 S 50~390 S
	8212150200+ 8212200045 8212270296 8212270299+ 8212270301+	50-275 PR 50-275 50-275 50-275	P P P		8212030001 8212030039 8212030044* 8212030071 8212030071	50-370 9 50-259 9 50-259 8 50-259 8
	8212270310* 8212270312* 8212270384* 8212280160 8212280163*	50-275 50-275 50-322 50-275 50-275	د د د ا		8212030071 8212030071 8212030071 8212030071 8212030071	50-259 R 50-259 R 50-259 R 50-259 R 50-259 R
Stone & Webster, Inc	8212270231 8212270231 8212270237* 8212270243* 8212270250* 8211080127*	50-275 50-275 50-275 50-275 50-275 50-222	E 6 6 6		8212030072 8212030072 8212030086 8212030092* 8212030152	50-438 9 50-438 9 50-327 8 50-327 8 50-438 8
Structural Mechanics Associates Suffolk County, NY	8212270458 8212270452* 8210170510* 8212030025* 8212140463	50-275 50-275 50-247 50-155 50-322	Р Р Б С С		8212030152 8212030220* 8212040023 8212040021	50-438 S 50-259 Q 50-327 P 50-327 P
Sunflower Alliance TERA Corp TRW, Inc.	8212270227 8212090495 8212280319 7907180391* 8212020404*	50-322 50-440 50-440 50-409 CONTRACT	T Q Q P		8212060070 8212060070 8212060076 8212060076 8212060081	50-390 E 50-390 E 50-327 P 50-327 P 50-390 A
	8212080027* 8212080030* 8212080044* 8212080045* 8212080070*	FOIA FOIA FOIA FOIA	•		6212060081 8212070058 6212070058 6212070142 6212070142	50-370 A 50-370 9 50-370 9 50-370 9
Talley Industries, Inc Teledyne Engineering Services	8212010201# 8212010206 8212010211#	FOIA FOIA PR 50-275 50-275	R R		8212070176 8212070180 8212070186 8212070186 8212070267	50-527 P 50-327 F 50-390 A 50-390 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8212070288 8212070288 8212070288 8212070291 8212070291	50-259 50-259 50-259 50-390 50-390	Р Р А А		9212150076* 8212150079 8212150101 8212150104* 8212150107	50~276 8 50~430 8 50~260 8 50~260 9 50~276 8)) 3
	8212080108* 8212080112* 8212080112* 8212080112* 8212080373	50-259 50-259 50-259 50-259 50-327	F F F C		8212180111* 8212180136 8212190136 8212170108* 8212170108*	50~296 B 50~390 B 50~370 B 50~259 F 50~259 F	}
	8212090054 8212090055 8212090056# 8212090056# 8212090058#	50-390 50-518 50-518 50-518 50-518	5 A A A		8212170108* 6212170112* 6212170112* 8212170112* 6212170136	50-257 F 50-259 F 50-259 F 50-259 F	•
	9212090058* 9212090083 9212090083 9212090088*	50~518 50~259 50~259 50~259 50~259	А Р Р Р Р		8212170140* 8212170157 8212170157 8212170160 8212170160	50-260 P 50-438 S 50-438 S 50-438 S 50-438 S	i
	8212090088# 8212090092# 8212090079 8212090079	50-259 50-259 50-259 50-258 90-259	P P G G S		82121 70221 62121 70229 62121 70229 82121 70229 82121 70236	80-438 B 50-257 F 50-257 F 50-257 F 50-327 P	
	8212090116* 8212090143 8212090150 8212090153* 8212090140	50-259 50-240 50-390 50-260 50-390	5 8 8 8 8 8 8 8 8		82121 70236 82121 70239 82121 70239 82121 70259 82121 70318	50~327 P 50~327 P 50~327 P 50~327 F	
	8212070140 8212070143 8212070145 8212070170 8212070170	50~390 50~438 50~390 50~390 50~390	8 8 8 8	,	8212170318 8212170388 8212170388 8212170390* 8212170390*	50~327 R 50~327 R 50~327 R 50~327 R 50~327 R	! !
	8212090174 8212090178* 8212090280 8212090291* 8212090347*	50-328 50-326 50-257 50-257 50-370	8 8 8 6		85155,00001 85155,00001 85155,00001 85155,00001 85155,00001	50-390 B 50-390 B 50-390 B 50-390 B 50-390 B	
	8212090361 8212090365# 8212090369# 8212090461# 8212090341	50-257 50-327 50-257 50-259 50-390	5 G G G S		821220001 821220001 821220001 821220001 8212200017	50-390 B 50-390 B 50-390 B 50-390 B) -
	8212070541 8212070551 8212070556# 8212100046 8212100046	50-370 50-328 50-328 50-370 50-370	១ ទ ១ ៖		8212200017 8212200017 8212200017 8212200017 8212200017	50-390 B 50-390 B 50-390 B 50-390 B)
	8212100046 8212100046 8212100046 8212100270 8212100270	50-390 50-390 50-390 50-390 50-390	្រ F ទ ទ		82122 00017 8212200017 8212200017 821220002 8212200052	50-370 B 50-370 B 50-370 B 50-518 B 50-518 B	3
	8212100270 8212100270 8212100270 8212100270 8212140047	50-390 50-390 50-390 50-390 50-438	s : 5 : 5 : 5 : 5 : 5 : 5 : 5 : 5 : 5 :		6212210026 6212210026 6212210026 6212210026 6212210026	50-370 8 50-370 8 50-370 8 50-370 8]] }
	8212140047 8212140087 8212140087 8212140141 8212140141	50-438 50-390 50-390 50-390 50-390	ត្តស្ន		6212210078 6212210100* 6212210122 6212210122 6212210217	50-328 G 50-328 S 50-438 B 50-438 B 50-370 B	3
	8212140141 8212140141 8212140164 8212140164 8212140198	50-370 50-370 50-390 50-390 50-328	5 ÷ 5 ទ ទ ទ ទ ទ ទ ទ		621.22 1 0217 621.22 1 0296 621.22 1 0298 621.22 1 0398 621.22 1 0358	50-390 8 50-438 9 50-438 8 50-390 9 50-370 9	; }
	8212140207* 8212140241 6212140247* 8212140323 6212140371	50-328 50-327 50-327 50-259 50-439	5 a B K G		82122 10360 82122 10363* 82122 10364 82122 10364 82122 10401	50-391 0 50-391 0 50-430 0 50-430 0 50-390 9	ļ ,
	8212140374 8212140374 8212140415 8212140415 8212140440	50-390 50-390 50-438 50-438 50-259	s a a s s		6212210491 6212210491 6212210491 6212210491 6212210445	50-370 9 50-370 9 50-370 9 50-370 9 50-370 9	} } }
	8212140444* 8212150010 8212150066 8212150069* 8212150071	50-257 50-327 50-259 50-259 50-274	35 to	·	6212210445 6212210451 6212210451 6212220419 6212220426	50-370 S 50-370 E 50-370 E 50-438 S 50-370 S	1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFF ILIATION	ACCEBSION NUMBER	SUBJECT TO SO-1	
	8212220463 8212220472* 8212220485 8212220485 8212220192	50~260 50~260 50~390 50~390 50~259	2 2 2 2 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	Teras Utilities Services, Inc	8212270332 8212280247 8212280273 8212280329 8212070403	50-445 5 50-445 3	
	8212270242 8212270242 8212270287 8212270287 8212270355	50-390 50-390 50-390 50-390 50-390	A A A A	Toledo Edison Co	8212130301 8212020205 8212020270 8212040158 8212070292	50-45 50-745 80-745 50-745 50-745 9	
	821 2270355 821 2280064 821 2280064 821 2280085 821 2280085	50-390 50-438 50-438 50-259 50-259	A 8 8 P P		82121 00040 82121 00229 82121 00231 82121 00235* 82121 00281	50-346 P 50-346 F 50-346 F 50-346 S	
	8212280085 8212280088* 8212280088* 8212280088* 8212280079	50-259 50-259 50-259 50-259 50-260	₽ ₽ ₽ ₽		8212100297* 8212100325 8212100332* 8212130088 8212130090	50-346 S 50-346 S 50-346 P 50-346 P	
	8212280100 8212280104* 8212280111 8212280114*	50-438 50-438 50-260 50-327 50-327	<i>ទ</i> ន ន <i>ទ</i> ន		8212130137* 8212130144* 8212150310* 8212160078* 8212160107*	50-346 50-346 50-346 50-346 50-346	
	821 2280 133 821 2280 136* 821 2280 147 821 2280 153* 621 2280 210	50-328 50-328 50-259 50-259 50-438	ន		8212170178 8212170187# 8212170182 8212170285# 8212210081	50-346 \$ 50-346 \$ 50-346 \$ 50-346 \$ 50-346 \$	i i
	6212260210 6212260275 6212260275 6212260276* 6212260277*	50-438 50-259 50-259 50-259 50-259	ь 6 8		8212210072 8212210366* 8212220273 8212220302* 8212220308*	50-346 P 50-346 D 50-346 P 50-346 F 50-346 F	!
	8218280305 8212280305 8212280328 8212280328 8212280340	50-438 50-438 50-438 50-438 50-438	8 9 8 8 8 9 8		8212270205 6212270210 6212280075 6212280077* 6212280234	50-346 p 50-346 p 50-346 s 50-346 s 50-346 s	; ;
	8212260340 8212260355 8212260358 8212260358 8212260437	50-438 50-370 50-438 50-438 50-438	ទ ទ ស K		8212280237* 8212280247 8212280250* 8212280281 8212280270*	50-346 \$ 50-346 \$ 50-346 \$ 50-346 \$ 50-346 \$	î Î
	8212290164* 8212290281 8212290287* 8212290287* 8212290287*	50-327 50-259 50-259 50-259 50-259	ន ក ន ន ន	Toledo. Univ of	8212270224 8212270307 8212270309* 8212270455* 8212010383*	50-345 9 50-346 # 50-346 # 50-346 0 CONTRACT	7
	82122 90354 82122 90354 82123 00006 82123 00293 82123 00351	50-327 50-327 50-438 50-327 50-327	P B P P	Torrey Pines Technology	8211270142# 8211270148# 8211270148# 8211270148# 8211270150#	50-528 A 50-528 A 50-528 A 50-528 A	4
	8212300351 8212300355# 8212300355# 8212300397 8212300357	50-327 50-327 50-327 50-327 50-327	P P P		8211290150* 8211290150* 8211290155* 8211290155* 8211290155*	50-528 A 50-528 A 50-528 A 50-528 A	A A
Tennessee, State of Tennessee, Univ of Texas A&M Univ , College Station, TX	8212300357# 8212300359# 8212090393# 8212020338# 8212100299	50-327 50-327 70-143 50-443 50-128	P P A S	Transquelear, inc	0212270281* 0212270286* 0212070489 0212070503* 0212080020*	50-443 50-443 XPORTLIC XPORTLIC XPORTLIC	*
Texas Instruments, Inc. Texas Utilities Generating Co	8212270024 8212270030 * 8212140298 8212140409 8212140409	70-33 70-33 50-445 50-445 50-445	F G		6212080029 6212080035 6212230402 6212230406 6212230410#	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8212150166 8212150166 8212150171* 8212150171* 8212160428	50-445 50-445 50-445 50-445 50-445	K K K A	Two Rivers, WI URS Corp US Ecology, Inc (Formarly Nuclear	8212270067 8212270071* 8212080251 8212280134* 8212010476		0
	8212170337 8212170342# 8212210391 8212210391 8212210394#	50-445 50-445 50-445 50-445 50-445	K K E E	Engineering) Union 74 Minerals Exploration Co Union Carbide Corp	8212010479* 8212290010 8212210558 8212010478 8212020277	27-39 27-48 40-8584 RES PRM	
	8212210394* 8212270317 8212270317 8212270320* 8212270332	50-445 50-445 50-445 50-445 50-445	K G G		821202028# 8212030158 8212040513 8212070173	PRM (P

AUTHOR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	lY.	 AU' AFF IL	HOR ATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	6212070173 6212070162* 6212160245 6212230166 6212270074	50-54 50-54 70-687 40-297 40-279	P P			8212090112 8212090115* 8212090130 8212090134* 8212090137*	50-338 50-338 50-281 50-281 50-281	8888
Union Electric Co Union of Concerned Scientists	8212270063* 6212020259 6212080256 8212300226 8212020363	40-299 50-483 50-483 50-483 PR	S F G			8212090144* 6212090149* 6212090175* 6212090217* 6212090217*	50-281 50-280 50-280 50-280 50-280	8 0 0 0
	8212040077 8212040077 8212040089* 8212040089* 8212040098	50-247 50-247 50-247 50-247 50-247	G G G G			8212090216* 8212090220* 8212090272 8212090284* 8212090287*	50-280 50-280 50-339 50-280 50-339	0 0 8 0
	8212070101 8212140384 8212140384 8212140373* 8212140373*	50-247 50-247 50-247 50-247 50-247	0 0 0 0			8212090305 8212090419 8212090485* 8212090527 8212090538*	50-404 50-280 50-338 50-338 50-338	01 F 02 S3 S3
	8212140400* 8212140400* 8212150022 8212200032 8212210238	50-247 50-247 50-247 50-247 50-247	0 0 0 0			8212130319 6212130324 6212130327 6212150028 6212150034*	50-338 50-338 50-281 50-338 50-338	P P B S
	8212210272 8212210334 8212210339* 8212270414 8212300002	50~289 50~289 50~289 FOLA 50~289	G G O			8212150048 8212150048 8212150052# 8212150052# 8212150059	50-338 50-338 50-338 50-338 50-280	ե ե ե
Unitec Co (subs of Ecodyne Carp) United Engineers & Constructors, Inc (subs of Raytheon Co)	8212300008 8212300242 8212300362 8212160530 8212010224	50-287 50-287 50-287 PR PT21	0			8212150059 8212150059 8212150059 8212150067 8212150087*	50-280 50-280 50-280 50-281 50-281	۲ ۲ 8
United Kingdom United Nuclear Corp	8212070295 6212270066 8212080042 8212150266 8212270256*	50-324 50-244 40-8781 70-371 70-820	9 5			6212150074 6212150096* 6212170041* 6212170041* 6212170044*	50-338 50-338 50-280 50-280 50-280	9 5 7 7
Uraneri USA, Inc Uranium Resources, Inc	8212270541 8212270264 8212280435 8212280439* 8212030261	70-371 40-8783 40-8783 40-8783 40-8786				8212170457* 8212170457* 8212170458* 8212170458* 8212200027	50-280 50-280 50-280 50-280 50-338	r r r 8
Utoh, State of Vanderbilt Univ Vermont Yankee Nuclear Power Corp	8212030263* 8212160394 8212300192* 8212090374 8212100310	40-8786 PR CONTRACT 50-271 50-271	p p			0212200037* 0212210137 0212210147* 0212210163 0212210171*	50-338 50-338 50-338 50-338	99999
	82121 40379 82121 40446* 82121 50174 82121 50176* 82122 10138	50-271 50-271 50-271 50-271 50-271	P ብ ብ በ			8212210187 8212210187 8212210254 8212210269* 8212210265	50-338 50-338 50-339 50-339 50-280	P
Virginia Electric & Power Co	8212270212 8212270378 8212270384* 8212020070 8212020076*	50-271 50-271 50-271 50-260 50-260	8 8 8			8212210365 6212210303* 6212210388* 6212210397* 9212220244	50-280 50-280 50-280 50-280 50-338	99999
	8212040134 8212040134 8212040134 8212040134 8212040134	50-280 50-280 50-280 50-280 50-280	P P P P			8212220364 8212220364 8212220368 8212220387 8212220371*	50-338 50-339 50-339 50-339 50-339	8 8 8
	8212060284 8212060284 8212060284 8212060284 8212060284	50-280 50-280 50-280 50-280 50-280	ր Բ Բ			8212220397* 8212220399 8212220408* 8212220410	50-339 50-338 50-338 50-338	8 8 8
	B212040303 B212040303 B212040315* B212040315* B212040315	50-280 50-280 50-280 50-280 50-338	8 Ե Ե			0212220416* 6212270179 6212270179 6212260073 6212280122	50-280 50-281 50-338	6 ե ե
	8212070054* 8212070067 8212070072* 8212070086 8212070086	50-339 50-339 50-339 50-280 50-280	8 8 8 8 8			8212280126 8212280126 8212280130# 8212280130#	50~338 50~280 50~280 50~338 50~338	0 0 0
	8212070071* 8212070078* 8212070102 8212070107*	50-280 50-260 50-337 50-339	ទទ			8212280135 8212280135 8212280140* 8212280152* 8212280201	50~338 50~338 50~280 50~260 50~338	0 8 8 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO			AUTHDR AFF ILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	821 22 80 20 1 821 22 80 20 6 * 821 22 80 25 7 821 22 80 25 7 821 22 80 25 7	50-338 50-280 50-280 50-280 50-280	P 8 P P			8212130033 8212130036# 8212140194 8212140201# 8212150021	50-508 50-508 50-508 50-508 50-508	4 6 8
	8212280257 8212280259 8212280349 8212280349 8212280349	50-260 50-337 50-260 50-260 50-260	P P P S			8212150029 8212160003 8212170100* 8212170138 8212170173	50-508 50-305 50-397 50-397 50-397	A P G E A
	8212290075* 8212290080* 8212290172* 8212290171	50-280 50-280 50-281 50-280 50-280	9 9 9 P		•	8212170175 8212170314 8212170314 8212170374 8212170379#	50-397 50-397 50-397 50-397 50-397	A H A A
	8212290191 8212290238 8212290244+ 8212290244* 8212290248	50-280 50-280 50-280 50-280 50-338	P R R R			8212200003 8212200036 8212200047 8212200073 8212200074	PR PR 50-397 PR 50-397	A
	6212270248 6212270252* 6212270252* 6212270255* 6212270255*	50-338 50-338 50-338 50-338 50-338	ե 6 6 6			8212200083 8212210251 8212210384 8212230208 8212230314	50-397 50-460 50-397 50-508 50-397	E 65 53 A O
	8212290256* 8212290256* 8212290261 8212290264* 8212290317	50-338 50-338 50-280 50-280 50-338	5 6 6 6 7			8212270159 8212270324 6212270327 8212280121 8212280277	50-397 50-397 50-460 50-508 50-397	A 0 0
	8212290318* 8212290459 8212290474* 8212300099 8212300104*	50-339 50-281 50-339 50-339	R G S S			8212280277 8212280294 8212280428 8212280440 8212280443	50-397 50-460 50-460 50-460 50-397	6 6 8 0
	8212300126 8212300130* 8212300171 8212300177* 8212300217	50-338 50-338 50-338 50-338 50-338	8 8 8			8212270180 8212270185* 8212270241 8212300075* 8212300274*	50-397 50-397 50-397 50-508 50-508	н А В
	8212300220* 8212300232 8212300237 6212300238* 8212300241*	50-338 50-338 50-339 50-338 50-339	ងខេត្ត	Washington	State of	8212300274* 8212300318* 8212300324* 8212230162 8212230538	50-508 50-397 50-508 27-48 27-48	0 0
	8212300245 8212300247* 8212300291 8212300255* 8212300261	50-338 50-338 50-339 50-339 50-338	នេសមន	Weste Manag West Branch	ement, Inc Conservation Association	8212280941 8212270005 8212070209 8212070209 8212070213	27-47 27-47 50-247 50-247 50-247	G G
	8212300267* 8212300286 8212300291* 8212300313 8212300315*	50-338 50-339 50-339 50-338 50-338	8 8 8 8			8212070213 8212220293 8212300191 8212300191 8212300197	50-247 50-247 50-247 50-247 50-247	00000
Virginia Polytechnic Institute Vitro Engineering Co	8212280211 8212280213* 8212280216* 8212280217* 8212160094*	50-124 50-124 50-124 50-124 FOIA	Р Р Р	Hest Chicag	o, IL	8212300197 8212300201* 8212300201* 8212130167 8212270469	50-247 50-247 50-247 40-2061 40-2061	6
	6212160168* 6212160264* 6212160315* 6212160323* 6212160350*	40-4500 40-6500 40-6500 FOIA 40-3265		West Virgin Westchester		8212270478 8212030118 8212130254* 8212150008 8212150008	40-2061 50-129 50-247 50-247 50-247	
	8212160380* 8212160391* 8212160435* 8212160500* 8212160510*	FOIA FOIA 40~5500 FOIA 40-2116				8212150013* 8212150013* 8212220220 8212220220	90-247 50-247 50-247 50-247 50-247	
Wall Street Journal Washington Hanagement Group, Inc	8212160525* 8212160541* 8212160582* 8212060450 8212060433	40-2116 F01A F01A F01A F01A		Western Nuc Dodge Gorp	lear, Inc (subs of Phelps	8212220224* 8212230235 8212020154 8212130105	50-247 50-247 PR 40-116	
Washington Public Power Supply System	8210270013 8210270016* 8210270018*	50-397 50-397 50-397	A A A	Westinghous	se Electric Corp	8210210467 8210210475#	TOPREP	
	8212030107 8212060021 8212060179	50-397 50-397 50-397	Gi Gi			8210210484* 8210210489* 8212010154 8212010440	TOPREP TOPREP PT21 FOIA	
	8212100254 8212100254 8212100254	50-397 50-508 50-397 50-397	8 F F			8212020967 8212020271# 8212060245# 8212060276#	TOP REP TOPREP 50–347 50–204	

AFFILIATION	NUMBER	CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	8212070187* 8212130262 8212130294 8212130302* 8212140267	50-454 TOPREP TOPREP TOPREP 50-413	A		8212210181 8212270007* 8212270010* 6212270197 8212270203*	50-305 50-305 50-305 50-305 50-305	P F P P
	8212140267 8212140312* 8212140312* 8212140318* 8212140420*	50-413 50-413 50-413 50-413 50-244	A A A A P		8212280193 8212280230 8212280318 6212280467 6212280473*	50-305 50-305 50-305 50-305 50-305	P P P
	82121 50055 82121 50238 82121 50244* 82121 50242 82121 50340	TOPREP 70-1151 70-1151 70-1143 70-1151		Wisconsin's Environmental Decade	8212270211 8212270216# 8212270316 8212270316 8212270323	50-305 50-305 50-266 50-266 50-266	R R O O
	8212160346* 8212160365 8212200040 8212200062* 8212220124	50-334 TOPREP TOPREP TGPREP 70-1143	p	Wisconsin, Univ of, Madison Wollver, J D Woodward-Clyde Consultants, Inc	6212270323 6212140195 6212140205 7906040228* 6004010318*	50-246 50-156 50-358 50-237 50-237	0 9 9 P
	8212220134* 8212220182 8212270077 8212270079* 8212270263*	70-1143 YOPREP XPORTLIC XPORTLIC 50-286	P	Wyle Laboratories Wyly Co Wyaming. State of	8211020244# 8212270290# 8212170311# 8212010085 8212030304	40-9698 50-390 50-331 PT21 40-8200	A P
Williams-Robinette & Associates, Inc Wilt, D D	8212270266* 8212280149 8212130160* 8212280319 8212280376	50-286 XPORTLIC CONTRACT 50-440 50-266	P Ø B		8212060456 8212070456 8212170438 8212230077 8212230170	40-8044 40-8584 40-8348 40-6622 40-4492	
	8212020281* 8212070099 8212100202 8212100208 8212100211*	90-301 462-05 46-05 30-26 46-05	S F G G	Xero: Corp Yakima Indian Nation	8212300129 8212100358 8212140333 8212140333 8212140345	40-6622 FOIA 50-322 50-322 50-522	9
	8212100222* 8212100223* 8212100224 8212100225* 8212170141	50-266 50-266 50-266 50-266 50-266	0 0 8 8 8		8212140345 8212140354 8212140354 8212140386 8212140386	50-522 50-522 50-522 50-522 50-522	000
	8212170172* 8212170326 8212170326 8212170326 8212210056 8212210056	50-266 50-266 50-266 50-266 50-266	B P P	Yankee Atomic Electric Co	6212140455 6212140455 6212020029 6212020029 6212020286	50-522 50-522 50-443 50-443 50-443	G G A A
	B212210297 B212210297 B212210299* B212220422 B212220422	50-266 50-266 50-266 50-266 50-266	R ת פ פ פ		8212020286 8212020300 8212020304* 8212020316* 8212020316*	50-443 50-29 50-29 50-443 50-443	A P P A A
	8212220427* 6212220427* 6212230357 6212230357 8212230359*	50-266 50-266 50-266 50-266 50-266	p p 0 9		8212020334 8212020334 8212040024 8212040054 8212040075	50-443 50-443 50-29 50-443 50-443	A P A A
	8212230359* 8212270125 8212270177 8212270202* 8212270239	50-266 50-266 50-266 50-266 50-266	6 P G G		8212040094 8212040094 8212040151 8212040151 8212070040	50-443 50-443 50-443 50-443 50-29	A A A P
	8212270246* 8212280114 6212280115* 6212280156 6212280162*	50-266 50-301 50-301 50-266 50-266	9 6 9 9		8212070047 8212070100 8212070100 8212080163 8212080163	50-29 50-443 50-443 50-443 50-443	P A A F F
	8212280341 8212270095 8212270075 8212270143 8212270253	50-266 50-266 50-266 50-266 50-266	ዋ የ የ የ		6212080190 6212080190 6212080224 6212080224 6212080329#	50-443 50-443 50-443 50-443 50-443	A A A Q
	8212290257* 8212290262* 8212290300 8212290322 8212290327*	50-244 50-264 50-266 50-266 50-266	R R P S S		8212090498 6212100109* 6212130223 6212130227* 6212140184	50-443 50-443 50-29 50-29 50-29	Å P P
Wisconsin Public Bervice Corp	8212030076 8212060049* 8212060070 8212070149 8212070333	50-305 50-305 50-305 50-305 50-305	J q s p p		8212140187* 6212140235 6212140235 8212140394 8212150155	50-29 50-443 50-443 50-29 50-29	8 A F 8
	8212070257 8212140143 8212140407 8212170167 8212170171*	50-305 50-305 50-305 50-305 50-305	F P S S		8212150160* 6212210273 6212210273 6212210276 6212210283*	50-27 50-443 50-443 50-29 50-29	8 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER 8212210287 8212210287 8212210449 8212210449	50-443 50-443 50-443 50-443	Y 5 8 5 8	AUTHOR AFFILIATION	ACCESSION NUMBER 8212270279 8212280476 8212280480* 8212290126	50-443 50-29 50-29 50-29 50-29 50-29	1 444
	8212270146 8212270146 8212270188 8212270270 8212270270 8212270279	50-443 50-443 50-443 50-443 50-443	A A A A	Yuba Hest Transfer Corp	8212290130* 8212290251 8212290258* 8212290316* 8212290316*	50-29 50-29 50-29 50-29 50-29 71-9004	***

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEODRY	OTHER REPORT NUMBER
02-0540-1108 R00 0715J 07-0870-001 R00 24 R00 25 R00	8212130227* 8212210542* 8212270104* 8212270243* 8212270237*	40-8064 50-266 50-275	20754
24 R00 82-1033 82-4 R01 82-8 8212010109	8212270250* 8212280438* 8212280354* 8212210162* 82122101009	50-409 50-387	9 9 9 8 8AND82-7079
8212010469 8212010474 8212010475 8212010478 8212010481	8212010469 8212010474 8212010475 8212010478 8212010481	RES RES RES RES	9ANDB2-0976 E90-EA-6074 9ANDB2-1275
8212010483 8212010486 8212010487 8212020010 8212020076	8212010483 8212010484 8212010487 8212020010 8212020076	RES RES RES RES 50-375	BNL-NUREG-32107 • EGO-EA-6055
8212020086 8212020095 8212020100 8212020104 8212020108	8212020086 8212020075 8212020100 8212020104 8212020108	50-155 F RES RES	P EGG-EA-6099 P EGG-EA-5909 EGG-NTAP-6068 EGG-NTAP-6069 P EEG-EA-6078
8212020110 8212020126 8212030239 8212030323 8212040005	8212020110 8212020126 8212030237 8212030323 8212060005	50-247 F RES RES 50-537 A RES	P EGO-NTAP-6090 EGG-EA-6025 BNL-NURE9-32101
8212040119 8212040128 8212070400 8212070471 8212080262	8212060119 8212060128 8212070400 8212070471 8212080262	RES RES RES RES	BNL-NUREG-31940
8212080505 8212080510 8212080516 8212080520 8212160549	8212080505 8212080510 8212080516 8212080520 8212160549	REB REB REB REB RES	EGG-8EM1-6062 EGG-EA-5920 EGG-LOFT-6084 EGG-CDD-6027 ORNL/FTR-1429
82181 60558 82181 60564 8218220021 8218820060 8218820519	8212160558 8212160564 8212220021 8212220060 8212220519	RES RES RES RES	ORNL/FTR-1428 ORNL/FTR-1426 ORNL/ED/EIS-179
8212220523 8212270416 8212270534 8212280031 8212280040	8212220523 8212270416 8212270534 8212280031 8212280040	RES RES RES RES RES	PNL4432-2 ORNL5083 BNLNUREO-32170 BNLNUREO-31844 BNLNUREO-32069
8212280051 8212280055 8212280514 8212280518 8212270512	8212280051 8212280055 8212280514 8212280518 8212290512	RES RES 50-320 P RES RES	BNL-NUREG-32105 BNL-NUREG-31814 BNL-NUREG-32071 BNL-NUREG-32106

REPORT	ACCESSION	SUBJECT	OTHER REPORT
REBUNN	NUMBER	CATEGORY	NUMBER
8212300197	8212300137	RES	20873
8212300402	8212300402	RES	
974-74-018 801	8212210414*	50-322 E	
84-884-2534	8212210005*	50-275 P	
AV-R-9563R	6212060336*	40-8743	
BAW-10155 BG-TDP-1 R02 CE-1-A R22 CEN-152 R01 CENPD-270	8212130220* 8212230304* 8212220231* 8212020212* 8212140510*	TOPREP 50-275 P 50-10 P TOPREP PROJ	
DOE/E 18-0096-D DPSU 71-124-4 DUKE-1-A AOA E-3508 ROO EQG-1183-4210	8212170409* 8212130138* 8212280173* 8212270071* 8105210384*	40-6500 71-6495 TOPREP 71-9015 50-263 Q	21654 168-80-06
EPRI NP-2527-LD	8212170101*	50-277 P	GL-81-04
EPRI NP-81-4-LD	8212170111*	50-277 P	
ES-26NS-10-004 DRF B	8212010015*	50-537 F	
0A-C16724 V01	8211270148*	50-528 A	
0A-C16724 V02	6211270150*	50-528 A	
0A-C16924 V03	6211270155*	50-529 A	
HNP BMR-12	8212070054*	50-518 A	
IAEA-CN-42/253	8212080227	ORG	
MPR-751	8212070155*	TOPREP	
NES B1A0091 R01	8212260061*	50-407 P	
NFG 004 R01 NSP-74-101 R01 NSP-74-102 R01 NSP-74-103 R01 NSP-74-104 R01	8212210327* 8212210327* 8212210330* 8212210333* 8212210337*	50-272 P 50-263 P 50-263 P 50-263 P 50-263 P	30 2874 0101 30 2874 0102 30 2874 0103
NSP-74-105 ROI	8212210342*	50-263 P	
NSP-74-105A ROI	8212210346*	50-263 P	
NURE0-0020 VO6 NO7	8212270505	NUREG	
NURE0-0327 RO3	8212140471	NUREG	
NUREQ-0485 VO4 NIO	8212010138	NUREG	
NUREG-0540 V04 N04	8212140475	NUREG	
NUREG-0540 V04 N07	8212270069	NUREG	
NUREG-0580 V11 N11	9212270174	NUREG	
NUREG-0606 V04 N04	8212270243	NUREG	
NUREG-0713 V03	8212270459	NUREG	
NUREG-0748 V02 N10	8212160780	NUREO	
NUREG-0773	8212140476	NUREO	
NUREG-0824 DRFT	8212010100	SO-245 P	
NURFG-0871 V01 N04	8212220143	NUREO	
NUREG-0918	8212270181	NUREO	
NUREC-0936 VOI NO3	8212010052	NUREO	5AND82-1659
NUREC-0952	8212140482	50-362 P	
NUREC/9R-0025 VOBNII	8212270443	NUREO	
NUREC/9R-0051 VO4 N4	8212130140	NUREO	
NUREC/CP-0033 VOI	8212220813	NUREO	
NUREG/CP-0033 V02 NUREG/CR-0891 NUREG/CR-1922 NUREG/CR-1935 NUREG/CR-2134	8212220172 8005070798* 8212270541 8212270145 8212140762	NUREO 50-237 F NUREO NUREO NUREO	8AND82-1659 8AND80-2712 EPRI NP-1582

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGOR	
NUREO/CR-2170 NUREO/CR-2274 NUREO/CR-2364 VO1 NUREO/CR-2364 VO2 NUREO/CR-2364 VO3	8212130113 8212130283 8212040429 8212040441 8212040447	NUREO NUREO NUREO NUREO NUREO	E0G-2191 SANDB1-1788 ANL-81-59 ANL-81-59 ANL-81-59	RIL-087 RIL-106 RIL-118 RIL-119 RIL-124	8004020271 8103250465 8104170464 8104170658 8111130045	RES RES RES RES RES	
NUREO/CR-2364 VO4 NUREO/CR-2364 VO5 NUREO/CR-2423 NUREO/CR-2526 NUREO/CR-2558	8212040451 8212040455 8212220507 8212220265 8212220265	NUREG NUREG NUREG NUREG NUREG	ANL-81-59 ANL-81-59 PNL-4109 PNL-4164 E0G-2159	RIL-125 RIL-126 RIL-127 RIL-128 RIL-129	8109280378 8201220290 8201190075 8201180563 8202260369	RES RES RES RES	
NUREG/CR-2546 NUREG/CR-2601 VO1 NUREG/CR-2601 VO2 NUREG/CR-2641 NUREG/CR-2643	8212010144 8212270033 8212270232 8212270435 8212130058	NUREG NUREG NUREG NUREG NUREG	EPRI NP-2373 PNL-4247 PNL-4247 ORNL/TM-8271 SAND82-7036	RIL-130 RIL-131 BAI-186-029-05 BAI-186-029-14	8212270240 8207200458 8207030343* 8212140260*	RE8 RE8 50-213 50-29	P P
NUREG/CR-2650 NUREG/CR-2672 VO1 NUREG/CR-2697 NUREG/CR-2716 VO2 NUREG/CR-2720	8212220162 8212140479 8212130135 8212270449 8212130123	NUREG 50-259 NUREG NUREG NUREG	SAND92-0774 P ORML/TH-8119/V; ORML/TH-8325 PNL-4275-2 ORML/TH-8336	SAI-186-027-17 SAI-186-027-20 SAI-186-027-23 SAI-186-027-25 SAI-186-027-35	8212070115* 8209030322* 8212010427* 8207080445* 9208310315*	50-317 50-255 50-307 50-285 50-331	Р Р Р
NUREO/CR-2723 NUREO/CR-2753 NUREO/CR-2745 NUREO/CR-2748 NUREO/CR-2774 VOZ	8212220204 8212060465 8212010115 8212270487 8212130143	NUREG NUREG NUREG NUREG NUREG	5AND92-1110 ORML-5886 PNL-4301 PNL-4302 ANL-82-24	SECY-77-574 SECY-82-023 SECY-82-042 SECY-82-136 SECY-82-137	8212010143* 8202010383* 8203090677* 8204160270* 8204160268*	FOIA FOIA FOIA FOIA	
NURSO/CR-2797 VO2 NUREO/CR-2797 NUREO/CR-2807 NUREO/CR-2811 NUREO/CR-2822	8212060492 8212270492 8212060480 8212060460 8212140459	NUREO NUREO NUREO	P SAND02-0978 ORML/NSIC-207 E00-2207 ORML-5895 P UCRL-59041	SECY-82-275 SECY-82-286 SECY-82-313 SECY-82-322 SECY-82-447A	8212270037# 8212070224* 8207280513* 8207010072* 8212100088	FOIA FOIA FOIA SECY	
NUREO/CR-2823 NUREO/CR-2832 NUREO/CR-2845 NUREO/CR-2844 NUREO/CR-2844 NUREO/CR-2845	8212140485 8212220228 8212270512 8212130118 8212270156	NUREO NUREO NUREO NUREO NUREO	UCRL-53042 LMF-97 PNL-4345 SAND82-1684 SAND82-0917	SECY-82-462 SECY-82-465 SECY-82-465 ERR SMA 12901 03 SMA 13703 02	8212010327 8212060419 8212070487 8210190510* 8212030025*	SECY SECY SECY 50-247 50-155	F G IED-80-11
Nureo/cr-2066 Nureo/cr-2075 Nureo/cr-2068 Nureo/cr-2094 Nureo/cr-2099	8212130157 8212220341 8212060471 82122 7 0456 8212130110	NUREO	A LA-9478-MS PNL-4370 P E00-2201 PNL-4402 SAND82-1870	STD-R-02-004 TER-C5257-298 TER-C5257-325 TER-C5257-405 TER-C5257-427	8209140103* 8209230258* 8209230377* 8209270122*	50-409 50-155	P TAC 11732 P TAC 41603 P TAC 41369
NURFO/CR-2900 NUREO/CR-2917 NUREO/CR-2918 NUREO/CR-2927 NUREO/CR-2930	8212270441 8212270559 8212130147 8212220291 8212130152	NUREO NUREO NUREO NUREO NUREO	ORN5876 PNL-4427 ANL-82-53 SAND82-0236 EGQ-2219	TER-C5257-453 TER-C5257-454 TER-C5257-459 VO1-02 TER-C5257-460 TER-C5257-463	8207150169* 8207010149* 8207010396* 8212230110* 8207010124*	50-244 50-245 50-213	P TAC 42520 P IEG-79-015 P P IEB-79-018
NUREO/CR-2932 VO1 NUREO/CR-2942 NUREO/CR-294B NUREO/CR-2760 NUREO/CR-2761	8212040486 8212130108 8212270499 8212270468 8212270454	NUREO NUREO NUREO NUREO NUREO	Sandbi-2027 Egg-2220 MEA-2006 Egg-2224 Egg-2225	TER-C9257-464 TER-C9257-479 TER-C9257-480 TER-C9257-485 TER-C9257-487	8207010410* 8212270536* 8210070227* 8210250167* 8210220483*	50-409 50-250 50-250 50-344	P TAC 42470 P TAC 42471 P TAC 42471 P TAC 42494
NUREG/CR-2970 VOI NUREG/CR-2975 NUREG/CR-2974 NUREG/CR-278 NUREG/CR-2982	8212270468 8212160773 8212140464 8212270145 8212270520	NUREO NUREO NUREO NUREO NUREO	ANL-82-41 UCID-17463 UCID-17464 EGG-2227 8AND82-7205	TER-C5257-498 TER-C5257-492 TER-C5257-493 TER-C5506-64 TR-5318-1 ROO	8210220470* 8212300348* 8212230250* 8206160113* 8212290452*	50-317 50-289 50-277 50-271	P IEB-79-010 P TAC 42513 P IEB-79-01 P
NUREC/CR-2995 NUREC/CR-3004 NUREC/CR-3020 NUREC/CR-3040 NUREC/CR-3085	8212220249 8212220193 8212270221 8212060458 8212220238	NUREO NUREO NUREO NUREO NUREO	PNL-4509	TR-5317-1 TTR-25N UCID-18470 UCID-19145 UCID-19148	8212270218* 8212270281* 8212130370* 8212090023* 8209230424*	50-271 50-443 50-344 50-263	P A P
NUREG/CR-3077 DRO-4014-12 PGE-1035 PMD-PE-010 ROO GUAD-1-82-244	8212270420 8212070009* 8212070319* 8212150047* 8212170335*	50-344 50-382	BMI-2030 R P F E	UMTRA-DOE/AL-33 URS/JAB B051 WCAP-10086 WCAP-10146 WCAP-10170	8212020073+ 8212280134+ 8212140420+ 8212270244+ 8212150355	50-244 50-286	G IEIN-80-21 P P 27190 1
QUAD-1-82-245 REV A RDD-83 5489 01 RDD 83 5490/5491 02 R1L-038 R1L-071	8212070278* 8212270042* 8212270047* 7811070329 8005281047		a 5	WCAP-858751R0 ESE-18 WCAP-858751R0 ESE-38 XN-NF-79-56(NP)(A)R1 XN-NF-82-77(NP) R01 XN-NF-82-84(NP) R01	8210210484# 8210210489* 8212150005* 8212290215* 8212290204*		21280 1/102582 EGDP-ESE-18 EGDP-ESE-38
RIL-076 RIL-079 RIL-081 RIL-082 RIL-085	8002250152 8003280100 8005270829 8005071094 8005270752	res res res 50-jro res		XN-NF-82-88 RO1	8212270179*		P P

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

VCCERPIO	M MOWRER			
ENCL OSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJEC CATEOD	
700/0/0000	7717146664	00/////		
7904040228	8212140001	82/11/03	50-237	Ρ
7907100669	8212140001	82/11/03	50~237	P
7907180391	8212140001	82/11/03	50-409	b
7907240319	8212140001	82/11/03	50-237	b.
7907300965	8212140001	82/11/03	50-259	Р
7908080624	8212140001	82/11/03	50-237	P
7908090435	8212140001	82/11/03	50-10	Р
790B140421	8212140001	82/11/03	50-206	P
7908140784	8212140001	82/11/03	50-219	P
7908140789	8212140001	82/11/03	50-217	Р
7909180332	8212140001	82/11/03	50-244	P
7909200656	8212140001	82/11/03	50~237	P
7711150252	8212140001	82/11/03	50-237	P
7912190426	8212140001	82/11/03	50-206	ρ
8001110507	8212100053	82/11/07	FO1A	
0001180235	8212140001	92/11/03	50~206	P
0001230275	8212100053	82/11/09	FOIA	
8001280032	8212140001	62/11/03	50-482	A
800213 0081	B212140001	82/11/03	50-206	₽
8002200775	B212140001	82/11/03	50-219	P
8002270255	8212140001	82/11/03	50-204	P
8003310092	8212140001	82/11/03	50-206	Р
8003310489	8212140001	82/11/03	50-409	P
8004010318	8212140001	82/11/03	50-237	Р
8005050726	8212140001	82/11/03	50-204	P
8005070778	8212140001	82/11/03	50-237	Р
8005070798	8212140001	82/11/03	50-237	P
6005280555	8212140001	82/11/03	50~219	P
6005280541	8212140001	82/11/03	50-219	P
8004090144	8212140001	82/11/03	50-206	₽
8006090788	8212140001	82/11/03	50-204	P
8007180114	8212140001	82/11/03	50~204	P
6007230260	8212140001	82/11/03	50-206	P
8008240700	8212010029	82/11/01	FOIA	
8009050320	8212140001	82/11/03	FOIA	
B009110797	8212140001	02/11/03	50-10	P
8009170164	8212140001	82/11/03	50~409	₽
8009180414	8212140001	02/11/03	FOIA	
8007270433	8212140001	82/11/03	50-206	P
8010150236	0212140001	B2/11/03	50-206	P
8010150242	8212140001	82/11/03	50-204	P
8010150246	8212140001	82/11/03	50-206	P
6010170263	8212140001	82/11/03	50-206	P
8010170287	8212140001	82/11/03	50-204	P
8010220355	8212140001	82/11/03	50-245	P
8101080118	8212140001	82/11/03	50-255	Р
8102200777	8212100053	82/11/09	FOIA	
8102200784	0212100053	82/11/09	FOIA	
8103120528	8212100412	82/11/15	FOIA	
8103310251	8212100412	82/11/15	FOIA	

	PRINCIPAL	DATE	SUBJECT
ENCL DBURE	DOC UMENT	ISSUED	CATEGORY
8104100175	8212100412	02/11/15	FOIA
8104230080	B212140001	82/11/03	FOIA
8105110512	8212140001		
		82/11/03	
8105210384	8212210007	82/12/01	90-263 0
8107140119	8212270025	82/11/24	50~322 H
8107210340	8212140001	82/11/03	FOIA
B109230665	8212140001	62/11/03	FOIA
8107280383	8109280378	81/09/11	RES
B110190952	8212140001	62/11/03	50-204 P
B112110356	8212140001	82/11/03	50-206 P
8112140327	8212140001	82/11/03	50-213 P
8112270035	8212140001	82/11/03	50-244 P
8201120155	8201220290	81/12/04	REB
8201180567	8212140001	62/11/03	50-255 P
8505010383	8212090048	82/10/20	FOIA
0202180082	8212020008	82/11/08	FOIA
8202180460	8212140001	62/11/03	50-255 P
8203010313	8212140001	82/11/03	FOIA
8203090677	8212090048	82/10/20	FOTA
8203310670	8212140001	62/11/03	50-29 P
8503310670	8212140001	82/11/03	20-54 h
B204010021	B212140001	82/11/03	50-155 P
8204130511	8212020008	82/11/08	FOIA
8204160262	B212070048	82/10/20	FOIA
8204160270	8212090048	82/10/20	FOIA
8204270491	8212140001	62/11/03	50~255 P
0.604270471	D#1#140001	08/11/03	00-200 P
8205040451	8212140001	92/11/03	FOIA
8205240413	8212140001	82/11/03	FOIA
8205260070	8212140001	82/11/03	50-244 P
8205270590	8212140001	82/11/03	FOIA
8206070020	8212100053	82/11/09	FOIA
***************************************		527.1707	1 5-211
8208070028	8212100053	82/11/09	FOIA
0206100047	8212270483	62/12/14	50-344 F
8204140142	8212070425	82/11/05	50-298 Q
6204140113	8212260005	82/11/29	50~271 P
8206220059	8212020008	82/11/0B	FOIA
8206220070	8212100053	62/11/09	FDIA
8206220072	8212100053	82/11/09	FOIA
		82/11/03	
8206290144	8212140001		FOIA
8207010124	8212270365	82/12/16	50-29 P
8207010149	8212200008	02/12/13	50~244 P
8207010398	8212200100	82/12/13	50-245 P
8207010410	8212290320	82/12/21	50-409 P
8207080445	8212010458	82/11/17	50-285 P
8207120252	8212100053	82/11/09	FOIA
8207150149	8212070097	82/11/30	50-219 P
8207200474	B212140001	82/11/03	50-155 P
8207280369	B212 (4000)	82/11/03	FOIA
8208030436	B212140001	82/11/03	FOIA
8208290147	8212070385	82/11/22	COMMISSION
8208310315	8212020007	82/11/23	50-331 P
0500010010	METER DECOM	***************************************	00-031 L

	N NUMBER			ACCEBSION			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198VED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8207010072 8207030322 8207030343 8207140103 8207150008	8212230166 8212080340 8212210127 8212210459 6212060470	02/11/04 02/12/02 02/12/15 02/12/16 02/11/23	FOIA 50-255 P 50-213 F 50-255 P COMMISSION	8212010102 8212010105 8212010108 8212010112 8212010119	8212010027 8212010029 8212010029 8212010029 8212010029	92/11/01 92/11/01 92/11/01 92/11/01 92/11/01	FOIA FOIA FOIA FOIA FOIA
6209220450 8209220453 8209230258 8209230377 8209230424	8212130350 8212130350 8212150115 8212230354 8212300068	82/12/07 82/12/07 82/12/09 82/12/09 82/12/17	50-331 F 50-331 F 50-409 P 50-155 P 50-250 P	8515010156 8515010159 8515010153 8515010155	8212010114 8212010117 8212010029 8212010117 8212010117	82/11/12 82/11/19 82/11/01 82/11/19 82/11/19	XPORTLIC 50-390 A FOIA 50-390 A 50-390 A
8209280513 8209290122 8210040253 8210040267 8210040272	8212090048 8212020328 6210040239 8210040239 8210040239	82/10/20 82/11/12 82/09/30 82/09/30 82/09/30	FOIA 50-409 P 50-352 A 50-352 K 50-352 A	8212010133 8212010139 6212010141 6212010143 6212010149	8212010127 8212010029 8212010029 8212010029 8212010029	82/11/12 82/11/01 82/11/01 82/11/01	XPORTLIC FOIA FOIA FOIA FOIA
8210040278 8210070227 8210150145 8210190510 8210210098	8210040237 8212270534 8212220460 8210170477 8210210078	82/09/30 82/12/13 82/11/08 82/10/08	50-352 0 50-250 P 50-341 F 50-247 F 50-311 S	B212010150 B212010156 B212010157 B212010159 B212010162	8212010148 8212010147 8212010029 8212010029 8212010029	82/11/24 82/11/30 82/11/01 82/11/01 82/11/01	50-272 P 50-341 K FOIA FOIA FOIA
8210210475 8210210484 8210210489 8210220470 8210220483	8210210467 8210210467 8210210467 8212300041 8212300041	82/10/13 82/10/13 82/10/13 82/10/14 82/10/13	TOPREP TOPREP TOPREP 50-317 P 50-317 P	8212010163 8212010164 8212010167 8212010168 8212010172	8212010147 8212010140 8212010140 8212010029 8212010140	82/11/30 82/11/17 82/11/17 82/11/01 82/11/17	50-341 K 50-302 P 50-302 P FOIA 50-302 P
6210250167 6210260403 6210270016 6210270016 6211020166	8212280410 8212010023 8210270013 8210270013 8212130395	82/12/17 82/11/26 82/10/22 82/10/22 82/10/22	50-344 P 50-206 P 50-397 A 50-397 A 50-275 H	8212016174 8212010177 8212010180 8212010187 6212010193	8212010029 8212010029 8212010029 8212010029 8212010185	82/11/01 82/11/01 82/11/01 82/11/01 82/11/15	FOIA FOIA FOIA FOIA 50-267 P
8211020246 8211020252 8211040070 8211040225 8211050027	6211020241 6211020241 6211040086 6212010375 6212270418	82/09/17 82/09/17 82/10/25 82/11/08 82/11/26	40~8698 40-8698 50-335 S 50-443 E 50-483 A	8515010504 8515010502 8515010501 8515010149	8212010027 8212010192 8212010027 8212010185 8212010027	82/11/01 82/11/29 82/11/01 82/11/15 82/11/01	FOIA 50-289 0 FOIA 50-269 P FOIA
8211040554 8211080105 8211080107 8211080110 8211080127	9212130023 9211080101 9211080101 9211080101 9211080125	82/11/03 82/11/02 82/11/02 82/11/02	50-286 P 50-29 P 50-29 P 50-29 P 50-322 E	8515010559 8515010551 8515010518 8515010511	8212010204 8212010027 8212010220 8212010204 8212010027	82/11/26 82/11/01 82/11/15 82/11/26 82/11/01	50~275 R FOIA WASTE MOT 50~275 R FOIA
8211110457 8211110483 8211120169 8211120212 8211120491	8212060484 8212270041 8212070141 8212070141 8211120486	82/11/12 82/11/12 82/11/12 82/11/12 82/10/21	50-440 A 50-209 P REVIEW GRP REVIEW GRP MISC	8212010228 8212010230 8212010235 8212010238 8212010244	8212010227 8212010029 8212010029 8212010029 8212010029	82/11/17 62/11/01 62/11/01 62/11/01 82/11/01	WASTE MOT FOIA FOIA FOIA FOIA
8211140015 8211220096 8211230137 8211270023 8211270142	8211170509 8208170263 8212130281 8212170369 8211290135	82/10/29 82/12/09 82/12/06 82/11/30 82/11/19	50-237 P 50-3 P 50-275 P 50-206 G 50-528 A	8212010249 8212010276 8212010290 8212010330 8812010331	8212010029 8212010185 8212010268 8212010329 8212010329	82/11/01 82/11/15 82/11/16 82/11/23 82/11/23	F01A 50-269 P 50-389 M 50-302 P 50-302 P
8211270148 8211270150 8211270155 8211270557 8212010015	9211270135 8211270135 8211270135 8211270330 8212010011	82/11/19 82/11/19 82/11/19 82/11/19	50-528 A 50-528 A 50-528 A 50-454 K 50-537 F	8212010332 8212010335 8212010347 8212010368 8212010371	8212010327 8212010334 8212010342 8212010361 8212010361	82/11/23 82/11/12 82/11/17 82/11/09 82/11/09	50-302 P 50-309 P 50-289 P 50-322 A 50-322 A
8212010016 8212010017 8212010020 8212010021 8212010036	8212010012 8212010014 8212010014 8212010012 8212010023	82/11/08 62/11/15 62/11/15 62/11/09 62/11/26	FOIA 50~456 A 50~456 A FOIA 50~206 P	8212010372 8212010374 8212010383 8212010389 8212010391	8212010369 8212010369 8212010361 8212010365 6212010388	82/11/24 82/11/24 82/11/23 82/11/23 82/11/23	70-36 70-36 CONTRACT 50-443 0 CONTRACT
8212010037 8212010039 8212010050 8212010051 8212010053	8212010033 8212010033 8212010042 8212010029 8212010046	82/11/24 82/11/24 82/11/24 82/11/01 82/11/16	50-315 F 50-315 F 50-317 F FDIA 50-387 M	8212010393 8212010396 8212010397 8212010398 8212010401	8212010341 8212010385 8212010341 8212010395 8212010341	82/11/09 82/11/23 82/11/09 82/11/23 82/11/09	50-322 A 50-443 Q 50-322 A CONTRACT 50-322 A
8212010055 8212010058 8212010063 8212010066 8212010067	8212010042 8212010027 8212010057 8212010061 8212010029	82/11/24 82/11/01 82/10/20 82/11/24 82/11/01	50-317 F FOIA XPORTLIC 50-112 F FOIA	8212010404 8212010418 8212010421 8212010422 8212010423	8212010403 8212010392 8212010392 8212010417 8212010419	82/11/23 82/11/22 82/11/18 82/11/18	CONTRACT 50-269 P 50-269 P 50-309 P CONTRACT
8212010069 8212010070 8212010074 8212010077 8212010079	8212010065 8212010029 8212010071 8212010029 8212010071	82/11/15 82/11/01 82/11/24 82/11/01 82/11/24	WASTE MOT FOIA 50-150 F FOIA 50-150 F	B212010427 B212010428 B212010430 B212010434 B212010438	8212010417 8208290032 8212010425 8212010432 8212010433	82/11/18 82/10/04 82/11/23 82/11/23 82/11/23	50-309 P ACRB CONTRACT CONTRACT CONTRACT
8212010090 8212010091 8212010096 8212010097 8212010099	8212010029 8212010029 8212010029 8212010092 8212010029	82/11/01 82/11/01 82/11/01 82/11/01 82/11/24 82/11/01	FOIA FOIA FOIA 50-320 F FOIA	8212010451 8212010464 8212010477 8212010488 8212010519	8212010446 8212010458 8212010476 8212010392 8212010513	82/10/26 82/11/17 82/11/11 82/11/22 82/11/24	FOIA 50-285 P 27-39 50-269 P 50-352 A

ACCESSION					ACCES810	N NUMBER			
ENCLUSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEODRY		ENGLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY	,
8212020012 8212020014 8212020019 8212020023 8212020037	8515050033 851505000B 851505000B 851505000B 851505000B	82/11/08 82/11/08 82/11/08 82/11/08 82/11/08	FOIA FOIA FOIA FOIA 50-416	s	8212030050 8212030051 8212030054 8212030058 8212030058	8212030034 8212030045 8212030053 8212030046 8212030060	82/11/08 82/11/19 82/11/30 82/11/03 82/11/29	50-220 50-334 50-254 50-482 50-395	0 0 0 0
8212020052 8212020056 8212020057 8212020061 8212020065	8212020045 8212020008 8212020051 8212020050 8212020058	92/11/24 92/11/08 92/11/19 92/11/24 92/11/24	FOIA 50-354 50-416	8 9 6	B212030070 6212030075 6212030076 8212030083 8212030090	8212030045 8212030064 8212030045 8212030069 8212030087	62/11/19 92/11/16 82/11/18 82/11/19 82/11/19	50-333 50-348 50-333 50-322 50-387	G G G
8212020067 8212020071 8212020073 8212020075 8212020080	821202000B 8212020060 821202000B 821202000B	82/11/08 82/11/24 82/10/01 82/11/08 82/11/08	FOIA 50-302 WASTE MOT FOIA FOIA	6	9212030072 9212030075 B212030075 6212030106 6212030112	8212030086 8212030081 8212030093 8212030084 8212030104	82/11/29 82/11/16 82/11/30 82/11/24 82/11/16	50-327 50-312 50-387 50-312 50-285	5 G G
8212020081 8212020083 8212020084 8212020087 8212020089	8212010503 8212020048 8212020078 8212020077 8212020078	02/11/24 02/11/24 02/11/23 02/11/24 02/11/23	50-334 50-302	8 P 8 P	8212030115 8212030116 8212030126 8212030126 8212030128	8212030109 8212030110 8212030113 8212030117 6212030123	82/11/02 82/10/06 82/11/19 82/11/17 82/11/19	50-482 50-312 50-320 50-285 50-286	0 8 8 9
8212020096 8212020098 8212020124 8212020144 8212020153	0212020070 8212020071 8212020116 8212020138 8212020143	82/11/24 82/11/23 82/11/23 82/11/24 82/11/23	50~440 50-296 50~416	8 K K	8212030127 8212030132 8212030137 8212030137 8212030145	8212030121 8212030122 8212030127 8212030133 8212030125	82/11/17 82/11/30 82/11/24 82/11/24 82/11/29	50-255 50-352 50-482 50-395 50-315	Q A A S P
8212020161 8212020171 8212020173 8212020174 8212020208	8212020152 8212020179 8212020185 8212020189 8212020200	82/11/24 62/11/23 82/11/19 82/10/29 82/11/22		S 8	8212030147 8212030150 8212030153 8212030156 8212030162	8212030141 8212030134 8212030144 8212030151 8212030159	82/11/19 82/11/17 82/11/29 82/11/10 82/11/24	50-247 50-282 50-272 50-445 50-278	Q Q Q Q P
8212020212 8212020232 8212020237 8212020244 8212020248	8212020200 8212020229 8212020234 8212020240 8212020239	82/11/22 82/11/23 82/11/24 82/11/23 82/11/14		8 8	8212030169 8212030171 8212030174 8212030175 8212030177		82/11/24 82/11/24 82/11/16 82/11/17 82/11/17	50-361 50-395 50-321 50-213 50-336	P S O Q
8212020264 6212020271 6212020280 6212020281 6212020282	8212020261 8212020267 8212020275 8212020276 8212020274	82/11/17 82/11/29 82/11/24 82/11/24 82/11/23	50-294 TOPREP 50-297 50-266 50-373	8 8 9 8	8212030179 8212030185 8212030187 8212030192 8212030197	8212030180 8212030184	82/11/24 82/12/01 82/11/24 82/11/12 62/11/19	50-387 50-10 50-245 50-368 50-254	9 9 9 0
8212020285 8212020289 8212020289 8212020295 8212020297	8212020272 8212020279 8212020283 8212020292 8212020293	82/11/24 82/07/29 82/11/23 82/11/19 82/11/23	50-295 PRM 50-315 50-366 50-324	9 9 5 6	8212030197 9212030200 82112030202 8212030204 8212030207	8212030195 8212030184 8212030201	92/11/23 82/11/19 82/11/24 82/11/24 82/11/19	50-395 50-293 50-395 50-334 50-289	8 8 8
8212020301 8212020304 8212020310 8212020312 8212020314	8212020274 8212020300 8212020308 8212020304 8212020308	82/11/23 82/11/26 82/11/16 82/11/23 82/11/16	50-373 50-29 50-254 50-325 50-254	8 P Q S	8212030205 8212030220 8212030226 8212030226 8212030232	8212030212 8212030215 8212030212	82/11/19 82/11/30 82/11/19 82/11/30 82/11/30	50-278 50-259 50-269 50-259 50-259	9 0 0
6212020316 6212020317 6212020319 6212020326 6212020327	9212020286 9212020311 9212020315 9212020323 9212020323	92/11/23 92/11/24 92/11/23 92/11/30 92/11/24	50-443 50-262 50-324 50-443 50-373	A 6 5 0 6	8212030234 8212030245 8212030245 821203025 821203025	8212030236 8212030124 8212030157	82/11/24 82/11/30 82/11/26 82/12/01 82/10/14	50-336 CONTRAC 50-3 50-361 40-8786	7 F P
8212020331 6212020338 8212020339 8212020351 8212020352	8212020325 8212020334 8212020330 8212020347 8212020349	82/11/23 82/11/26 82/11/30 82/11/26 82/11/24	50-255 50-443 50-352 50-255 50-277	B A G G R	8212030265 8212030266 8212030275 8212030275 8212030275	8212030244 8212030270 8212030269	82/11/24 82/11/30 82/11/19 82/11/30 82/11/30	50-275 CONTRAC 40-6672 50-254 50-254	
8212020354 8212020357 8212020365 8212020371	8212020348 8212020337 8212020362 8212020369	82/11/23 82/11/15 82/11/23 82/11/23 82/11/24	50-259 50-249 50-324 50-335 CONTRACT	8888	621203029/ 621203029/ 621203029/ 621203029/	8212030283 8212030283 8212030284	82/11/09 82/11/30 82/11/30 82/11/01 82/11/30	40-3453 50-10 50-10 40-8380 50-309	F F
8212020390 8212020401 8212020404 8212030003 8212030013	8212020387 8212020346 8212020402 8212030002 8212030007	82/11/30 82/11/24 82/11/18 82/11/19 82/11/10	90-289 CONTRACT 50-369 50-285 50-344	0	821204005 821204001 821204001 821203030	7 8212060007 7 8212060015 2 8212060015	92/11/30 92/11/15 92/11/27 92/11/29 92/11/22	50~309 50~315 50~320 50~320 50~312	F G P G
8212030017 8212030020 8212030023 8212030025 8212030028	8212030011 8212030016 8212030017 8212030021 8212030021	82/11/24 82/11/17 82/11/24 82/11/18 82/11/19	70-2792 50-220 50-155 50-373 70-1100	0 0	821204003 821204003 821204003 821204003	2 8212040028 5 8212040028	82/11/30 82/11/26	50~358 50~285 50~285 50~358 50~10	0 P 0 0
8212030032 8212030033 8212030036 8212030036 8212030044 8212030047	8212030030 8212030035 8212030035	82/11/18 82/11/16 82/11/16 82/11/26 82/11/17	50-219 50-219 50-244 50-259 50-387	0 0 9 8	821206004 821206004 821206005 821206005 821206005	9 8212040044 3 8212040047 5 8212040051	82/11/30 82/11/26 82/11/24 82/11/01 82/11/24	50~309 50~305 50~275 50~409 50~316	P Q R 0 8

ACCESSION	NUMBER				ACCEBSIO	N NUMBER		
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGORY
8212040058 8212040040 8212040042 8212040044 8212040073	8212040052 8212040048 6212040051 8212040052 8212040052	82/11/22 82/11/24 82/11/01 82/11/22 82/11/29	MISC 50-314 50-409 MISC 50-255	9 9 9	8212060427 8212060430 8212060431 8212060444 8212060444	8212060424 6212060422 6212060357 6212060357 6212060440	82/11/12 82/11/30 82/11/24 82/11/24 82/11/10	FOIA 90-295 P 50-255 S 50-255 S FOIA
8212040080 8212040087 8212040101 8212040104 8212040109	8212060074 8212060077 8212060091 8212060096 8212060096	82/11/29 82/12/03 82/11/24 82/12/01 82/12/01	50-344 50-247 50-333 50-277 50-277	0 8 8 P	8212060506 8212060511 821207009 8212070012 8212070021	6212060502 6212060509 6212070004 6212070008 6212070014	82/09/07 82/11/26 82/11/30 82/11/24 82/11/30	CONTRACT 40-86 50-89 R 50-325 8 50-217 Q
8212040120 8212040137 8212040152 8212040159 8212040141	8212040114 8212040130 8212040146 8212040154 8212040154	82/11/30 82/11/18 82/11/19 82/11/19	CONTRACT 50-261 50-247 50-361 50-204	P 5 0	8212070024 8212070030 8212070034 8212070036 8212070068	8212070018 8212070018 8212070018 8212070032 8212070032	85/11/18 85/11/08 85/15/05 85/15/05	50-375 Q 50-375 Q 50-375 Q GA979 50-289 H
BR12060164 B212060167 BR12060168 BR12060170 BR12060171	9212060155 9212060163 9212060156 9212060166 9212060163	82/11/23 82/11/16 82/11/19 82/11/16	50-275 50-312 50-206 50-362 50-312	9 9	8212070081 8212070083 8212070095 8212070096 8212070098	8212070073 8212070077 8212070094 8212070090 8212070094	82/11/26 82/10/20 82/12/01 82/11/23 82/12/01	50-247 G 50-247 O 50-244 P COMMISSION 50-244 P
8212040174 8212040175 8212040177 8212040178 8212040181	8212060169 8212060169 8212060155 8212060173 8212060172	82/11/17 82/11/24 82/11/23 82/11/12 82/12/01	50-311 50-244 50-275 50-243 50-254	9 0 F	8212070111 8212070115 8212070117 8212070118 8212070122	8212070104 8212070105 8212070114 8212070112 8212070116	82/11/23 82/11/24 82/11/16 82/11/24 82/11/16	50-320 Q 50-317 P QA999 50-325 S QA999
8212040170 8212040172 8212040177 8212040200 8212040201	8212060187 8212060189 8212060191 8212060198 8212060199	82/11/22 82/11/22 82/11/23 82/11/26 82/12/03	50-423 50-412 50-254 50-293 50-261	0 0 0 8 R	8212070123 8212070130 8212070133 8212070134 6212070141	8212070117 8212070124 8212070126 8212070120 8212070137	82/11/17 82/11/11 82/11/13 82/11/23 82/12/01	50-382 0 50-112 0 50-112 0 50-322 0 50-298 0
8212040204 8212040208 8212040212 8212040214 8212040217	8212040196 8212040209 8212040202 8212040202	82/11/24 82/11/22 82/11/22 82/11/17 82/11/22	50-317 50-397 MISC 50-311 50-309	8 0	8212070146 8212070148 8212070150 8212070154 8212070158	8212070033 6212070144 6212070145 6212070151 6212070151	82/11/24 82/11/23 82/11/22 82/11/23 82/11/23	50-312 Q 50-309 Q 50-285 Q 50-387 Q 50-387 Q
8212040220 8212040224 8212040230 8212040231 8212040233	8212040210 8212040221 8212040223 8212040223	82/11/26 82/11/24 82/12/01 82/11/24 82/12/01	50-293 50-331 50-112 50-333 50-112	8	8212070159 8212070161 8212070169 8212070169 8212070182	8212070156 8212070157 8212070156 8212070156 8212070173	82/11/15 82/12/06 82/11/15 82/11/15 82/11/22	QA999 50-454 Q QA999 GA999 50-54 P
8212040237 8212040238 8212040245 8212040250 8212040252	8212040235 8212040232 6212040244 8212040247 8212040247	82/11/22 92/11/17 82/11/23 92/11/16 82/11/14	50-247 50-295 50-369 50-409 50-409	0 0 P 0 0	8212070187 8212070193 8212070198 8212070201 8212070201	8212070177 8212070190 8212070177 8212070192 8212070195	82/11/29 82/12/03 82/11/29 82/12/01 82/12/02	50-454 A 50-341 P 50-454 A 50-255 P 50-338 0
9212040255 9212040258 9212040241 9212040244 9212040248	6212040232 6212040234 6212040251 8212040240 8212040244	82/11/19 82/11/22 82/11/22 82/11/15 82/12/01	50-295 50-322 50-275 50-508 50-285	G G G G	8212070207 8212070210 8212070214 8212070228 8212070231	8212070177 8212070192 8212070208 8212070223 8212070225	82/11/29 82/12/01 82/11/24 82/12/03 82/11/18	50-454 A 50-255 P 50-325 B 50-382 G 50-361 B
B212040272 B212040274 B212040274 B212040281 B212040287	8212040270 8212040240 8212040249 8212040278 8212040278	82/11/29 82/11/15 82/12/02 82/11/22 82/11/22	50-293 50-508 50-204 50-272 50-272	F Q P Q Q	8212070253 8212070256 8212070259 6212070260 8212070263	8212070251 8212070255 8212070252 8212070255 8212070262	92/12/02 82/11/17 82/11/18 82/11/17 82/11/29	50~289 F 50~267 Q 50~361 S 50~267 Q 50~498 K
8212040293 8212040294 8212040298 8212040300 8212040304	8212040285 8212040292 8212040291 8212040294 8212060297	82/12/02 82/11/23 82/11/17 82/11/19 82/11/12	50-317 50-333 50-272 50-312 CDNTRACT	G 8 8	8212070265 6212070267 8212070275 6212070276 6212070278	B212070264 B212070264 B212070273 B212070274 B212070274	82/11/23 82/11/23 82/11/24 82/12/03 82/12/03	50-352 Q 50-352 Q 50-324 S 50-416 P 50-416 P
8212040304 8212040308 8212040313 8212040315	8212060301 8212060302 8212060303 8212060303	82/11/24 82/11/17 82/11/16 82/12/01 82/11/24	50-317 50-272 50-269 50-280 50-272	8 6 7 8	8212070287 8212070293 8212070294 8212070294 8212070303 6212070304	8212070283 8212070290 8212070281 8212070247 8212070301	82/11/19 82/11/19 82/11/19 82/12/03 82/11/10	50-361 6 50-361 8 50-361 6 50-155 0 9A979
B212060324 B212060326 B212060336 B212060339 B212060364	8212040359 8212040338 8212040338 8212040318	82/11/30 82/11/22 82/11/18 82/11/24 82/11/15	50-331 50-320 40-8743 50-280 50-275	() 5 F	B212070319 B212070329 B212070330 B212070331 B212070337	8212070316 8212070324 8212070327 8212070328 8212070327	82/11/30 82/11/24 82/12/03 82/12/06 82/12/03	50-344 P 50-341 S 50-155 Q 50-528 K 50-155 Q
B212040371 B212040382 B212040384 B212040391 B212040392	8212060357 8212060357 8212060379 8212060384 8212060357	82/11/24 82/11/24 82/11/16 82/11/15 82/11/24	50-255 50-255 50-416 50-344 50-255	8 8 8 8	8212070340 8212070345 8212070346 8212070346 8212070349	8212070327 8212070327 8212070343 8212070341 8212070327	82/12/03 82/12/03 82/08/05 82/12/01 82/12/03	50-155 0 50-155 0 50-344 R 50-269 P 50-155 0
8212040394 8212040403 8212040412 8212040413 8212040421	8212040357 8212040375 8212040357 8212040405 8212040357	82/11/24 82/11/08 82/11/24 82/11/17 82/11/24	50-255 50-320 50-255 CONTRACT 50-255	8 P 8	B212070351 B212070352 B212070353 B212070359 B212070359	8212070342 8212070327 8212070341 8212070342 8212070350	82/11/22 82/12/03 82/12/01 82/11/22 82/11/24	COMMISSION 50-155 0 50-249 P COMMISSION 50-341 S

VC CERRIO	N NUMBER			ACCESSION				
CNCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUB-JECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	1860ED DATE	SUBJECT CATEGORY	Υ
8212070365 8212070368 8212070372 8212070374 8212070378	8212070358 8212070342 8212070342 8212070369 8212070342	82/12/03 82/11/22 82/11/22 82/11/24 82/11/22	50~440 G COMMISSION COMMISSION 50~361 S COMMISSION	8212080101 8212080103 8212080104 8212080105 8212080108	8212080004 8212080040 8212080004 8212080004 8212080100	82/10/25 82/11/10 82/10/25 82/10/25 82/12/02	FOIA CONTRACT FOIA 70-143 50-259	F
8212070368 8212070392 8212070395 8212070399 8212070412	8212070379 8212070341 8212070341 8212070383 8212070406	82/11/19 82/12/01 82/12/01 82/11/18 82/11/22	50~361 S 50~269 P 50~269 P 50~361 S 50~361 S	8212080109 8212080111 8212080113 8212080113	8212080006 8212080006 8212080006 8212080006	82/10/25 82/10/25 82/12/02 82/10/25 82/10/25	FBIA FDIA 50-259 70-143 FOIA	F
8212070418 8212070422 8212070429 8212070432 8212070434	8212070416 8212070416 8212070424 8212070425 8212070416	82/11/12 82/11/12 82/11/17 82/11/05 82/11/12	QA999 QA999 CONTRACT 50-298 F QA999	8212080117 8212080124 8212080127 8212080133 8212080137	821208000A 821208000A 821208000A 821208000A	92/10/25 92/10/25 92/10/25 92/10/25 92/10/25	70-143 FOIA 70-143 FOIA FOIA	
8212070437 8212070441 8212070443 8212070444 8212070447	8212070425 8212070425 8212070425 8212070425 8212070425	82/11/05 82/11/05 82/11/05 82/11/05 82/11/05	50-278 F 50-278 F 50-278 0 50-278 0	8212080137 6212080142 6212080144 6212080149 6212080154	8212080006 8212080006 8212080006 8212080006	92/10/25 82/10/25 82/10/25 82/10/25 82/10/25	A107 A107 A107 A107 70-143	
B212070452 B212070453 B212070455 B212070457 B212070467	8212070425 8212070450 8212070425 8212070425 8212070425	82/11/05 82/11/29 82/11/05 82/11/05 82/11/05	50-298 Q CONTRACT 50-298 P 50-298 F 50-298 P	8212080161 8212080167 8212080178 8212080178 8212080188	6212080006 8212060006 8212080169 6212080169 8212080179	65/15/09 85/15/09 85/15/09 85/10/55	FOIA FOIA 50~409 50~409 50~528	P P A
8212070473 8212070476 8212070478 8212070482 8212070491	8212070425 8212070469 8212070472 8212070472 8212070425	82/11/05 62/11/29 82/11/30 62/11/30 62/11/05	50-267 F XPGRTL1C 50-295 P 50-295 P 50-298 F	8212080175 8212080200 8212080204 8212080211 8212080245	8212080179 9212080174 9212080179 8212080206 8212080235	82/12/06 82/12/06 82/12/03 82/12/06	50~528 50~187 50~528 50~219 50~454	A A P Q
8212070496 8212070498 8212070500 8212070501 8212070503	8212070425 8212070492 8212070425 8212070492 8212070469	82/11/05 82/11/29 82/11/05 82/11/29 82/11/29	50-298 T 50-305 P 50-298 P 50-305 P XPORTLIC	8212080250 8212080263 8212080271 8212080271 8212080274	8212080228 8212080240 8212080261 8212170369 8212080282	82/11/12 82/11/30 82/11/30 82/11/20	50-409 50-219 50-255 50-206 50-295	9 8 0 0
8212070504 8212080008 6212080007 8212080010 8212080011	8212070492 8212080004 8212080005 8212080004 8212080004	82/11/29 82/10/25 82/11/23 82/10/25 82/10/25	50-305 P FOIA COMMISSION FOIA FOIA	8212080301 6212080303 6212080311 6212080317 6212080323	8212080293 8212080295 8212080297 6212080308 8212080314	82/12/06 82/11/29 82/11/28 82/11/30 82/12/03	50-440 50-387 50-247 50-373 50-277	9886
8212080013 8212080017 8212080018 8212080020 8212080024	8212080006 8212080006 8212080016 8212080016	82/10/23 82/10/25 82/10/25 82/12/02 82/11/26	FOIA FOIA 70-143 XPORTLIC CONTRACT	8212080328 8212080329 8212080342 8212080342 8212080344	8212080320 8212080321 8212080318 8212080333 8212080347	82/11/29 82/12/03 82/12/01 82/11/29 82/12/03	50-387 50-443 50-373 50-387 50-219	5 G 5 G
8212080025 8212080027 8212080028 8212080030 8212080032	8212080023 8212080006 8212080006 8212080006 8212080006	82/11/19 82/10/25 82/10/25 82/10/25 82/10/25	COMMISSION FOIA FOIA FOIA FOIA	8212080359 8212080364 8212080372 8212080378 8212080381	8212080349 8212080356 8212080362 8212080367 8212080375	82/11/24 82/11/24 92/11/30 92/11/30 82/11/04	50-219 50-272 50-387 50-387 50-249	00 00 00 00
8212080034 8212080040 8212080041 8212080044 8212080049	8212080031 8212080031 8212080004 8212080004 8212080045	82/11/19 82/11/19 82/10/25 82/10/25 82/11/26	50-318 Q 50-318 Q FOIA FOIA 70-27	8212080384 6212080387 6212080375 6212080377 6212080402	8212080382 6212080376 6212080376 6212080376 6212080378	82/12/01 82/12/03 82/11/24 82/12/03 82/11/22	50-387 50-29 50-219 50-29 50-546	8 P 9
8212080051 8212080054 8212080058 8212080061 8212080063	8212080006 8212080006 8212080006 8212080006 8212080057	82/10/25 82/10/25 82/10/25 82/10/25 82/12/02	F01A F01A F01A F01A 50-275 F	8212080403 8212080404 9212080404 8212080407 8212080410	8212080374 8212080390 8212080394 8212080398 8212080400	82/12/03 82/11/30 82/12/01 82/11/22 82/11/27	50-27 50-245 50-333 50-544 50-373	р 5 0 8
8212080065 8212080066 8212080070 8212080071 8212080076	8212080004 8212080004 8212080004 8212080057 8212080004	82/10/25 82/10/25 82/10/25 82/12/02 82/10/25	FOIA FOIA FOIA 90-275 F FOIA	8212080413 6212080415 6212080425 6212080440 6212080440	8212080412 8212080414 8212080420 8212080419 8212080434	92/11/30 92/12/03 92/11/30 92/11/24 92/11/24	50-373 50-334 50-282 50-334 50-311	8888
8212080077 8212080079 8212080080 8212080081 8212080082	8212080060 8212080006 8212080060 8212080006 8212080074	82/11/24 82/10/25 82/11/24 82/10/25 82/12/01	50-364 P FOIA 50-364 P FOIA FOIG	8212080448 8212080453 8212080459 8212080480 8212080484	8212080441 8212080445 8212080449 8212080474 8212080474	82/11/29 82/12/03 82/12/02 82/11/23	50-317 50-245 50-213 50-334 50-334	8 8 8 P P
8212080083 8212080084 8212080085 8212080088 8212080091	8212080040 8212080004 8212080074 8212080004 8212080089	92/11/24 82/10/25 82/12/01 82/10/25 82/12/02	50-364 P FOIA 50-313 F 70-143 50-315 F	G212080497 6212080593 6212080515 6212080522 6212080524	8212080451 8212080474 8212080509 8212080509 8212080508	82/11/26 82/12/02 82/11/22 82/11/22	50-304 50-454 50-155 50-155 50-373	8 0 0 6
8212080092 8212080093 8212080095 8212080096 8212080099	8212080006 8212080006 8212080006 8212080087 8212080006	82/10/25 82/10/25 82/10/25 82/12/02 82/10/25	FOIA 70-143 FOIA 50-315 F 70-143	8212080525 8212080530 8212080530 8212080551 8212080547	8212080511 8212080524 8212080527 8212080545 9212080541	92/11/22 92/11/26 92/11/29 92/11/23 92/11/22	50-219 50-334 50-443 50-443 50-441	8 8 8 8

ACCESSIO	N NUMBER			ACCESSION NUMBER					
ENCL DSURE	PRINCIPAL DOCUMENT	DATE Daved	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8212080548 8212080573 8212080577 8212080583 8212080597	6212080560 6212080561 6212080572 6212080580 6212080595	82/12/03 82/12/02 82/12/03 82/11/22 82/12/03	50-443 50-461 CONTRACT CONTRACT 50-358		8212070174 8212070175 8212070177 8212070178 8212070201	8212090198 8212090191 8212090187 8212090187 8212090196	82/12/06 82/12/02 82/11/19 82/11/19 82/12/07	50-329 50-416 50-369 50-369 50-440	T 8 0 0
8212080633 6212080637 8212080647 8212080652 6212080664	8212080630 8212080630 6212080643 8212080643 8212080662	82/12/02 82/12/02 82/11/23 82/11/23 82/11/24	50~546 50~546 50~346 50~346 50~373	F F F P	8212090204 8212090204 8212090207 8212090209 8212090210	8212070187 8212070176 8212070202 8212070048 8212070048	82/11/19 82/12/07 82/11/30 82/10/20 82/10/20	50-369 50-440 50-321 FOIA FOIA	0 6
8212080A69 6212080A70 8212080A71 8212080A73 6212080A84	8212080662 8212080662 8212080654 8212080662 8212080672	92/11/24 82/11/24 82/11/30 82/11/24 82/12/03	50-373 50-373 70-498 50-373 50-322	Р Р Р	8212090213 8212090217 8212090218 8212090219 8212090220	8212090211 8212090215 8212090215 8212090216 8212090216	82/11/19 82/11/19 82/11/19 82/11/23 82/11/19	50-389 50-280 50-280 50-321 50-280	0 0 5 0
821209069 8212090695 8212090005 8212090010 8212090011	8212080672 6212080654 6212230020 6212070008 6212070007	82/12/01 82/11/30 82/11/30	50~322 70~498 50~289 50~243 50~263	Н Р Р	8212090223 8212090224 8212090225 8212090226 8212090230	8212090215 8212090048 8212090221 8212090215 8212090048	82/11/19 82/10/20 82/12/01 82/11/19 82/10/20	50-280 FDIA 50-287 \$0-280 FDIA	0 5 0
8212090012 8212090024 8212090028 8212090031	8212090008 8212090008 8212090008 8212090027 8212090027	82/11/30 82/11/30 82/12/02 82/12/02	50~263 50~263 50~263 50~358 50~358	P P P F	B212070234 B212090236 B212090237 B212090237 B212090240	8212070215 8212070231 8212070227 8212070232 8212070235	82/11/19 82/12/09 82/11/10 82/11/18 82/11/05	50-280 50-454 50-400 50-413 State Pr	0 0 0 0
8212090033 8212090034 8212090035 8212090034 8212090037	8212090030 8212090027 8212090030 8212090032 8212090030	82/12/03 82/11/30 82/12/03 82/12/03	50~335 50~358 50~335 50~317 50~335	P P P P	8212090244 8212090245 8212090246 8212090249 8212090251	8212090229 8212090227 8212090232 8212090229 8212090232	82/11/10 82/11/03 82/11/18 82/11/10 82/11/18	50-400 50-424 50-413 50-400 50-413	0 0 0 0
6212070043 6212070052 6212070053 6212070056 6212070059	8212090040 8212090048 8212090050 8212090055 8212090055	82/12/03 82/10/20 82/11/30 82/11/30 82/11/30	50-344 FDIA 50-318 50-518 50-518	Р Р А	8212070253 8212070254 8212070254 8212070256 8212070258	8212070243 8212070247 8212070229 8212070248 8212070232	82/11/18 82/11/10 82/11/10 82/11/02	50-395 50-366 50-400 50-424 50-413	8 0 0
8212070059 8212070064 8212070065 8212070069 8212070071	8212090057 8212090063 8212090048 8212090066 8212090068	85/15/09 85/15/03 85/15/01 85/15/03	50~262 50~338 FOIA 50~329 70~1359	P 8	8212090265 8212090270 8212090271 8212090274 8212090275	8212070252 8212070264 8212070262 8212070263 8212070268	82/11/02 82/11/04 82/11/17 82/11/16 82/10/26	70-824 70-1113 50-370 70-1201 50-389	Q: G:
8212090072 8212090075 8212090081 8212090088 8212090091	8212090067 8212090074 8212090078 8212090083 8212090086	82/12/01 82/12/02 82/12/03 82/12/03 82/11/30	50~339 50~416 50~416 50~259 50~280	85 85 P \$3	8212090277 8212090278 8212090284 8212090287 8212090288	8212090267 8212090269 8212090276 8212090272 8212090281	82/10/26 82/12/01 82/11/18 82/12/01 82/11/16	50-280 70-1151 50-280 50-339 50-261	Q Q S Q
8212070072 8212070074 8212070078 8212070105 8212070107	8212070080 8212070094 8212070086 8212070100 8212070102	82/12/06 82/12/03 82/11/30 82/12/01 82/11/27	50-259 50-358 50-280 50-325 50-339	0 K S S	82120902B9 8212090290 8212090291 8212090293 8212090293	8212090273 8212090282 8212090280 8212090284 8212090292	82/11/16 82/12/03 82/11/30 82/11/16	50-324 50-416 50-259 50-269 70-824	0 0 5 P
8212090108 8212090113 8212090115 8212090116 8212090124	8212070080 8212070110 8212070112 8212070107 8212070080	82/12/06 82/12/01 82/11/30 82/11/30	50~259 50~416 50~338 50~259 50~259	0 s s s c	8212090297 8212090298 8212090299 8212090300 8212090303	8212090284 8212090285 8212090273 8212090276 8212090282	82/11/30 82/11/03 92/11/16 82/11/18 92/12/01	50~269 50~280 50~324 50~280 50~416	P Q Q Q
8212090124 8212090128 8212090134 8212090136 8212090137	8212070121 8212070120 8212070130 8212070131 8212070130	82/11/30 82/11/30 82/12/03 82/12/01	50~366 50~261 50~281 50~416 50~281	80000	8212090304 8212090305 8212090308 8212090310 8212090310	8212090276 8212090285 8212090302 8212090273 8212090282	82/11/18 82/11/03 82/11/02 82/11/16 82/12/01	50~280 50~280 50~335 50~324 50~416	9
8212090139 8212090144 8212090145 8212090149 8212090152	6212090135 6212090130 6212090140 6212090142 6212090147	82/12/03 82/12/03 82/11/30 82/11/23 82/12/03	50~325 50~281 50~321 50~366 50~325	88898	8212090312 8212090313 8212090316 8212090318 8212090319	8212090295 8212090276 8212090282 8212090314 8212090315	82/12/01 82/11/18 82/12/01 82/12/03 82/11/08	50-364 50-280 50-416 50-324 State Pr	9 9 8
8212090153 8212090155 8212090158 8212090164 8212090169	8212070143 8212070146 8212070151 8212070157 8212070166	82/11/30 82/12/02 82/12/02 82/12/02	50-240 TOPREP 50-416 50-416 50-280	s s s	8212070320 8212070321 8212070324 8212070328 8212070332	8212070282 8212070273 8212070317 8212070322 8212070282	82/12/01 82/11/16 82/11/19 82/12/06 82/12/01	50-416 50-324 50-413 50-331 50-416	0 0 0 P
8212090173 8212090175 6212090178 8212090180 6212090184	8212070167 8212070166 8212070174 8212070166 8212070177	92/11/27 62/12/06 62/12/02 92/12/06 62/12/01	50-325 50-280 50-328 50-280 50-416	8 G S G S	8212090335 8212090336 8212090338 8212090340 6212090341	8212070327 8212070331 8212070325 8212070333 8212070330	82/11/30 82/11/02 82/12/03 82/11/02 82/11/23	50-366 50-387 50-254 70-1201 50-321	5 0 0
8212090185 8212090184 8212090187 8212090192 8212090193	8212070166 8212070183 8212070181 8212070187 8212070190	92/12/04 92/10/26 92/10/29 92/11/19 92/12/02	50~280 50~400 50~269 50~369 50~366	0 0 0 0 5	8312070344 8212070347 8212070351 8212070352 8212090355	8212090326 8212090334 8212090345 8212090343 8212090348	82/12/01 82/11/29 82/11/03 82/12/03 82/10/27	50-416 50-390 50-261 50-263 50-400	8 0 0

ACCESSIO	N NUMBER				ON NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DAT	
8212090360 8212090364 8212090365 8212090369 8212090370	8212090353 8212090357 8212090354 8212090361 8212090354	82/11/03 82/10/28 82/11/30 82/12/03 82/11/30	50-389 0 50-417 0 50-327 0 50-259 8 50-327 0	######################################	8212090553 82/11 821210003 82/13 8212100007 82/11 8212100007 82/11	7/17 50-335 q 2/06 qA999 1/24 50-317 q 1/24 50-317 q
8212070371 8212070372 8212070378 8212070380 8212070382	8212090354 8212090366 8212090354 8212090373 8212090377	82/12/02 82/12/03 82/11/30 82/11/04 82/12/06	50~250 9 50~395 8 50~327 0 50~369 0 50~498 K	6512100033 6212100045 6912100056 6912100056	6212100038 82/12 8212100042 82/12 8212100051 82/11	2/06 50-334 Q 2/07 50-329 U 1/18 FOIA
9212090384 8212090398 8212090391 8212090393 8212090394	8212070354 8212070381 8212070386 8212070385 8212070387	82/11/30 82/11/23 82/11/23 82/11/23	50~327 Q 50~346 8 50~364 S 70~143 50~155 Q	6212100062 8212100064 6212100069 9212100079 8212100079	8212100057 B2/11 8212100059 82/11 8212100066 82/11 8212100048 82/12 6212100075 82/12	/26 50~387 Q /30 71~370 2/08 50~329 T
8212090399 8212090407 8212090410 8212090411 8212090413	8212070387 8212070400 8212070403 8212070404 8212070402	82/11/30 82/11/01 82/12/01 82/11/09 82/11/26	50~346 B 50~370 G 50~335 S 50~387 G 70~143	8212100081 8212100085 8217100089 8217100089	6212100073 82/11 8212100082 82/12 8212100084 82/11 8212100084 82/11 8212100094 82/11	7/06 50-324 P 701 FOIA 701 FOIA
8212090416 8212090421 8212090427 6212090438 8212090439	8212090408 8212090414 8212090414 8212090422 8212090430	82/11/30 82/11/01 82/11/01 82/12/01 82/11/19	70-143 50-416 Q 50-416 Q 50-395 S 70-27	8212100104 8212100109 8212100110 8212100112 8212100114	8212100074 82/11 8212100105 82/11 8212100074 82/11 8212100105 82/11 8212100105 82/11	/18 50-443 A /30 50-375 P /18 50-443 A
9212090440 9212090444 9212090445 9212090451	8212090433 8212090378 8212090428 8212090437 8212090447	82/12/03 82/11/08 82/11/17 82/11/30 82/11/05	50-409 Q 50-395 Q 70-1151 50-364 S 50-332 Q	B212100121 B212100128 B212100133 B212100133 B212100142	8212100111 82/11 8212100111 82/11 8212100124 82/12 8212100111 82/11 8212100111 82/11	/12 70-143 /03 GUNTRACT /12 FOIA
8212090454 8212090460 8212090461 8212090463 8212090465	821207037B 8212070449 8212070456 8212070453 8212070459	82/11/09 82/12/02 82/11/12 82/12/03 82/11/15	50-398 0 50-398 8 50-259 0 50-325 8 50-413 0	8212100144 8212100147 8212100149 821210015 821210015	8212100141	/12 FOIA /23 50-305 Q /12 FOIA
8212090467 8212090471 8212090476 8212090479 8212090481	8212070456 8212070456 8212070470 8212070456 8212070470	82/11/12 82/11/12 82/11/05 82/11/12 82/11/05	50-259 Q 50-259 Q State Prog 50-259 Q State Prog	8212100162 9212100164 8212100169 8212100179	8212100154 82/11 8212100111 82/11 8212100111 82/11 8212100167 82/11 8212100053 82/11	/12 FOIA /12 FOIA /29 CONTRACT
8212090485 8212090489 8212090491 8212090493 8212090496	8212070478 8212070477 8212070478 8212070486 8212070478	82/11/12 82/11/12 82/11/12 82/11/02 82/11/12	50-338 Q 70-824 50-338 Q 50-327 Q 50-338 Q	6212100180 6212100185 6213100187 6212100203	8212100178 82/12 8212100111 82/11 8212100111 82/11 8212100195 82/11 8212100198 82/11	/12 FOIA /12 FOIA /24 50-367 0
8212090499 8212090500 9212090503 8212090504 9212090505	8212070477 8212070490 8212070487 8212070497 8212070478	82/11/12 82/11/14 82/11/14 82/11/03	70-824 50-250 Q 50-250 Q 50-390 Q 50-338 Q	8515100550 8515100513 8515100513 8515100513	8212100208 82/12 8212100197 82/11 8212100197 82/11 8212100215 82/11 8212100219 82/12	/24 50-298 0 /24 50-298 0 /24 50-237 8
8212090508 8212090510 8212090516 8212090517 8212090518	8212090501 8212090487 8212090509 8212090507 8212090487	82/12/03 82/11/14 82/11/12 82/11/12	50-289 P 50-250 Q 50-395 Q 70-143 50-250 Q	8212100233 8212100235 8212100235 812100225	82121002R1 82/12 82121002R1 82/12 82121002R4 82/12 82121002R6 82/11 82121002R8 82/11	/07 50-266 Q /03 50-266 B /24 50-461 Q
8212090519 8212090521 8212090524 8212090526 8212090530	8212090511 8212090515 8212090487 8212090520 8212090509	82/11/17 82/11/09 82/11/16 82/12/01 82/11/29	\$0-348	0812100235 0212100248 0212100239 0218100240 0212100242	8212100229 82/12 8212100234 82/11 8212100236 82/12 8212100224 82/11 8212100234 82/11	/26 50-483 Q /02 50-458 Q /24 50-461 Q
8212090534 8212090536 8212090537 8212090538 8212090539	8212070507 8212070528 8212070531 8212070527 8212070533	82/11/29 82/11/12 82/11/02 82/12/01 82/11/12	50-395 0 50-439 0 50-335 0 50-338 8 70-143	8212100244 8212100249 8212100280 8212100259 8212100259	8212100227 82/12, 8212100245 82/12, 8212100241 82/12, 8212100255 82/11, 8212100251 82/12,	/02 70-2872 /04 50-324 R /24 50-344 G
8212070540 8212070542 8212070545 8212070547 8212070550	8212090529 8212090535 8212090509 8212090544 8212090543	82/10/29 82/11/29 82/11/29 82/11/29 82/11/29	50-250 G 50-325 S 50-395 G 50-335 G 50-325 S	8212100263 8212100271 8212100275 8212100279 8212100284	8212100255 82/11. 8212100265 82/11. 8212100272 82/12. 8212100264 82/11. 8212100278 82/11.	/24 50-298 0 /02 50-373 8 /30 50-366 S
8212070552 8212070554 8212070555 8212070554 8212070558	8212070544 8212070544 8212070547 8212070551 8212070544	82/12/03 82/11/29 82/11/17 82/12/01 82/11/29	50-528 Q 50-335 Q 70-1151 50-328 8 50-335 Q	8212100286 8212100287 8212100300 8212100303 8212100303	8212100282 82/11/ 8212100281 82/12/ 8212100290 82/12/ 8212100295 82/11/ 8212100295 82/11/	/03 50-346 8 /06 50-315 P /23 50-454 G
8212090559 8212090540 8212090561 8212090562 8212090563	8212090553 8212090544 8212090553 8212090544 8212090553	82/11/17 82/11/29 82/11/17 82/11/29 82/11/17	50-335 Q 50-335 Q 50-335 Q 50-335 Q 50-335 Q	8212100304 8212100308 8212100309 8212100314 8212100317	8212100297 82/12/ 8212100294 82/11/ 8212100304 82/12/ 8212100311 82/11/ 6212100313 82/12/	'23 50-454 0 '02 50-155 8 '30 50-364 8

ACCESSIO	NUMBER				ACCESSION	I NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8212100317 6212100327 6212100330 6212100332 6212100333	8212100312 8212100322 8212100324 8212100325 8212100327	82/12/01 82/12/03 82/12/07 82/12/02 82/12/02	50-237 50-315 50-454 50-346 50-461		8212130355 8212130357 8212130357 8212130361 8212130367	8212130352 8212130352 8212130358 8212130358 8212130366	82/12/07 82/12/07 82/12/07 82/12/07 82/12/06	50~284 F 50~286 F 50~352 G 50~352 G 50~344 F	F
8212100335 8212100337 8212100347 8212100348 8212100349	9212100328 9212100329 9212100343 9212100361 9212100362	82/12/01 82/11/23 82/11/15 92/12/03 82/11/18	50-265 50-461 Waste Mo 50-373 Foia	S Q T P	8212130369 8212130370 8212130372 8212130427 8212140015	8212130366 8212130366 8212130366 8212130424 8212140001	82/12/04 82/12/06 82/12/06 82/11/09	50-344 F 50-344 F 50-344 F 70-2926 FOIA	P
8212100372 6212100383 6212100385 6212100374 6212100376	8212100361 8212100381 6212100380 6212100380 6212100395	92/12/03 92/11/14 92/12/07 92/12/07 92/11/15	50-373 FOIA 50-313 50-313 FOIA	P F F	8212140022 8212140031 8212140051 8212140060 8212140061	8212140001 8212140029 8212140048 8212140053 8212140055	82/11/03 82/12/07 82/12/09 82/11/24 82/12/09	F01A 50~220 A 50~302 A 50~272 E 50~295 A	R
8212100406 6212100407 6212100410 6212100411 6212100453	8212100399 8212100403 8212100403 8212100399 8212100414	82/12/07 82/11/09 82/11/09 82/12/07 82/11/30	50-344 40-8768 40-8768 50-344 50-346	F F P	8212140070 8212140072 8212140082 8212140084 8212140085	8212140064 8212140068 8212140076 8212140074 8212140079	82/12/09 82/12/06 82/11/24 82/11/29 82/11/24	50-286 R 50-373 F 50-272 S 50-213 G 50-311 S	P 5 0
8212100474 6212100481 6212130026 8212130036 8212130041	6212100414 6212100414 6212130017 6212130033 6212130017	82/11/30 82/11/30 82/12/07 82/11/30 82/12/07	50-344 50-344 50-10 50-508 50-10	P P F K F	8212140075 8212140105 8212140107 8212140113 8212140120	8212140067 8212140078 8212140079 8212140078 8212140112	82/12/06 82/11/30 82/11/24 82/11/30 82/12/01	50~373 S 50~271 G 50~311 S 50~271 G 50~10 R	0 5 0
6212130040 6212130041 6212130047 6212130071 6212130074	8212130059 8212130055 8212130062 8212130062 8212130068	82/12/06 82/11/23 82/11/05 82/11/05 82/11/30	50-320 71-9151 70-27 70-27 71-454	P	8212140123 8212140128 8212140131 8212140133 8212140133	8212140115 8212140117 8212140125 8212140124 8212140135	82/12/07 82/12/06 82/12/02 82/12/06 82/12/03	50-366 9 50-373 9 50-317 9 50-272 0 50-387 9	9 5 1
8212130084 8212130095 8212130099 8212130102 8212130117	8212130081 8212130072 8212130072 8212130072 8212130111	82/12/07 82/11/29 82/11/29 82/11/29 82/11/23	50-333 50-309 50-309 50-309 50-346	R P P P	6212140140 6212140147 6212140149 6212140154 6212140159	8212140137 8212140142 8212140001 8212140150 8212140153	82/11/29 82/11/03 82/11/30 82/11/30	50~247 G 50~331 S 50~27 P 50~334 G 50~325 S	3
8212130121 8212130124 8212130127 8212130137 8212130138	6212130122 6212130132 6212130132 6212130132	82/11/23 82/11/23 82/12/03 82/12/03	50-346 71-6495	P P F	8212140160 8212140161 8212140165 8212140176 8212140177	8212140150 8212140001 8212140154 8212140171 8212140169	82/11/30 82/11/03 82/12/04 82/12/03 82/12/02	50-334 G FOIA 50-316 S 50-369 S 50-219 S	3
8212130144 8212130153 8212130156 8212130160 8212130162	8212130132 8212130149 8212130149 6212130155 8212130161	82/12/03 82/12/03 82/12/03 82/12/01	50-275 50-275 Contract	F F F	8212140187 8212140189 8212140191 8212140201 8212140202	8212140184 8212140182 8212140174 8212140194 8212140194	82/12/03 82/12/01 82/12/09 82/12/09	50-29 8 50-387 8 50-334 8 50-508 0 50-325 5	3
8212130164 8212130168 8212130171 8212130177 8212130182	8212130161 8212130161 8212130169 8212130175 8212130178	82/12/07 82/12/07 82/11/26 82/12/06 82/11/03	50-361 50-275	P Q R	8212140207 8212140221 8212140231 8212140236 0212140238	8212140198 8212140208 8212140224 8212140225 8212140232	82/12/08 82/12/07 82/12/07 82/12/09 82/12/06	90-928 9 90-249 9 50-373 9 50-333 9 50-97 8	3
8212130185 8212130193 8212130198 8212130202 8212130209	8212130181 8212130188 8212130196 8212130196	82/12/07 82/12/09 82/12/01 82/12/01	50-362 50-362 50-254	A P P R G	8212140237 8212140247 8212140248 8212140256 8212140257	6212140228 8212140241 8212140251 8212140253 8212140255	82/12/02 82/12/07 82/11/30 82/12/07 82/12/06	50-289 S 50-327 S 70-2895 50-329 A 50-324 P	3
8212130215 8212130227 8212130227 8212130236 8212130236	8212130207 8212130217 8212130223 8212130224 8212130231	82/11/29 82/12/01 82/12/06 82/12/09 82/12/03	TOPREP 50-29 50-255	Q Р Р	8212140260 8212140261 8212140270 8212140271 8212140272	8212140259 8212140258 8212140265 8212140269 8212140269	82/12/09 82/12/03 82/11/30 82/11/30	50-27 P 50-387 S 50-361 S 50-321 S 50-361 S	3
8212130240 8212130245 8212130246 8212130248 8212130250	8212130238 6212130242 8212130241 8212130243 8212130247	82/12/06 82/12/07 82/12/03 82/12/06 82/12/06	50-334 50-440 50-334	P P O P R	8212140277 8212140285 8212140292 8212140312 8212140315	9212140276 8212140281 8212140289 8212140263 8212140211	82/12/08 82/12/10 82/12/07 82/12/08 82/11/30	50-275 P 50-275 R 50-373 G 50-413 A 50-320 G	1
8212130254 8212130264 8212130265 8212130270 8212130287	8212130252 8212130243 8212130263 8212130267 8212130285	82/12/10 82/12/06 82/11/29 82/11/24 82/12/03	50~334 50-362	G F G G	8212140318 8212140319 8212140325 8212140327 8212140329	8212140263 8212140311 8212140268 8212140321 8212140326	82/12/08 82/12/03 82/12/03 82/12/08 82/12/08	50-413 A 50-320 9 50-387 S 50-295 S 50-373 0	1
8212130287 8212130273 8212130274 8212130278 8212130302	8212130281 8212130291 8212130291 8212130296	82/12/06 82/12/06 82/11/24 82/11/24 82/12/10	50-275 50-187	P P G G	8212140337 8212140358 8212140340 8212140342 8212140355	8212140322 8212140332 6212140335 8212140335 8212140346	82/11/27 82/12/03 82/11/30 82/11/30 82/11/30	50-423 Q 50-331 S 50-358 A 50-358 A 50-344 S	i 1
8212130305 8212130317 8212130333 8212130342 8212130346	6212130281 6212130313 6212130329 6212130336 6212130336	82/12/04 82/12/09 82/12/09 82/12/07 82/12/07	50-261 50-206 50-298	P G G F F	8212140356 8212140357 8212140363 8212140367 8212140368	8212140351 8212140344 8212140351 8212140361 8212140360	82/12/07 82/12/04 82/12/07 82/12/09 82/12/02	50-312 P 50-263 S 50-312 P 50-329 A 50-206 S	

AC CESSION	NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUB JECT CATEGOR	
5212140380 6212140383 6212140388 6212140393 6212140393	8212140374 8212140381 8212140374 8212140384 8212140396	82/12/07 82/12/10 82/12/07 82/12/10 82/12/09	50-537 50-498 50-537 50-247 50-151	A C A Q	8212150193 8212150200 8212150203 8218150213 8218150218	8212150181 8212150195 8212150202 8212150207 8212150212	82/12/07 82/12/10 82/11/15 82/12/10 82/11/24	50-277 50-275 71-9081 50-220 71-5957	F P a
8212140400 8212140405 8212140406 8212140408 8212140413	8212140384 8212140398 8212140397 8212140404 8212140404	82/12/10 82/12/01 82/12/07 82/12/08 82/12/08	50-247 50-361 50-220 50-244 50-244	0 0 P P	8212150224 6212150233 8212150240 8212150244 , 8212150252	8212150219 8212150219 8212150236 8212150238 8212150248	82/12/10 82/12/10 82/12/07 82/11/22 82/12/07	50-293 50-293 50-302 70-115J 50-243	G Q P
8212140414 8212140417 8212140420 0212140427 8212140427	8212140396 8212140410 8212140404 8212140424 8212140421	82/12/09 82/12/08 82/12/08 82/12/07 82/11/30	50-151 50-409 50-244 50-412 50-366	0 0 0 5	8212150257 6212150256 8212150276 8212150276 8212150310	8212150249 8212150272 8212150272 8212150273 8212150301	82/12/07 82/12/08 82/12/08 82/11/17 82/12/08	90-243 50-313 50-313 70-143 50-346	F F F
8212140434 8212140436 8212140437 8212140442 8212140444	8212140425 8212140433 8212140426 8212140435 8212140440	82/11/30 82/11/30 82/12/09 82/11/24 82/12/08	50-369 50-366 50-443 50-309 50-259	9 6 F 5	8212150329 8212150333 8212160002 8212160016	8212150323 8212150326 8212150323 8212160001 8212160012	82/12/07 82/11/29 82/12/07 82/12/09 82/11/23	50-315 NUREO 50-315 50-315 71-7006	F F
8212140446 8212140448 8212140453 8212140484 8212140492	8212140437 8212140379 8212140435 8212140478 8212140470	82/12/10 82/12/07 82/11/24 82/11/23 82/11/29	50-247 50-271 50-309 50-259 50-410	0 Р Г Н О	8212140023 8212140028 8212140041 8212140050	8212160020 8212160026 8212160032 8212160038 8212160043	82/11/30 82/11/16 82/11/23 82/11/19 82/11/01	71-170 71-486 71-9099 71-6003 71-5796	
8212140495 8212140497 8212140510 8212140517 8212150005	8212140490 8212140494 8212140501 8212140513 8212150003	82/11/29 82/11/11 82/11/11 82/11/19	50-410 50-387 PROJ 71-4909 TOPREP	Q P	8212140054 8212140058 8212140047 8212140082 8212140090	8212160048 8212160055 8212160060 8212160080 8212160080	82/12/01 82/12/10 82/10/27 82/07/30 82/07/30	50-311 50-277 40-3392 40-6500 FOIA	B R
8212150011 8212150018 8212150019	8212150007 8212150008 8212150014 8212150015 8212150020	82/12/07 82/12/09 82/12/07 82/11/23 82/12/02	50-321 50-247 50-321 50-409 50-334	5 T 9 0	8212150094 8212160097 8212160098 8212160103 8212160103	8212140080 8212140080 8212140080 8212140080	02/09/30 82/09/30 82/12/08 82/09/30 82/09/30	FDIA 40-6500 50-346 FDIA 40-6500	F
9212150027 9212150034 9212150037 9212150044 9212150047	8212150023 8212150028 8212150031 8212150038 8212150042	82/11/29 82/12/08 82/12/07 82/12/01 82/12/09	50-247 50-338 50-321 50-320 50-382	8 9 5 F	8212160107 8212160123 8212160131 8212160140 8212160144	8212140091 6212140080 6212140080 8212140080	82/12/08 82/09/30 82/09/30 82/09/30	50-346 40-6500 40-6500 40-6500 40-6500	F
8217150049 8217150050 8217150052 8217150053 8217150062	8212150040 8212150042 8212150048 8212150044 8212150058	82/12/09 82/12/09 82/12/10 82/12/13	50-112 50-382 50-338 50-302 50-277	0 F P	8212160148 8212160160 8212160161 8212160168 8212160182	8212160134 6212160080 8212160080 8212160080 8212160080	82/11/12 82/09/30 82/09/30 82/09/30	71-454 FOIA 40-6500 40-6500 40-6500	
8212150064 8212150069 8212150076 8212150076 8212150078	8212150060 8212150066 8212150070 8212150071 8212150075	82/12/10 82/12/08 82/12/09 82/12/09	50-302 50-257 50-331 50-294 50-334	8 9 8 8	8212160185 8212160191 8212160197 8212160197 8212160214	6212140177 8212(40080 9212140080 6212140080 6212140080	62/12/03 62/09/30 62/09/30 62/09/30 62/09/30	71-489 40-6500 40-6500 40-6500 40-6500	
8212150081 8212150084 8212150087 8212150091 8212150094	8212150077 8212150080 8212150067 8212150089 8212150094	62/12/08 62/12/01 62/12/09 62/12/08 62/12/08	50-395 50-247 50-281 50-395 50-338	8 8 8	8212160227 8212160240 8212160243 8712160243 8212160264	8212140080 8212140080 8212140080	92/12/13 92/12/15 92/09/30 92/09/30 92/09/30	50-155 50-413 40-6500 40-6500	9
9212150100 8212150102 9212150104 9212150108	8212150097 8212150097 8212150101 8212150105 8212150107	82/12/09 82/12/07 82/12/10 82/12/07 82/12/09	50-395 50-302 50-260 50-302 50-296	5 5 5	8212160270 82(2160273 8212160273 8212160307 8212160315	8212160080 8212160080 8212160080	81/04/01 82/09/30 82/09/30 82/09/30 82/09/30	50-317 40-4500 40-6500 40-6500 40-6500	8
8212150113 8212150114 8212150122 8212150126 8212150134	8212150110 8212150112 8212150117 8212150121 8212150129	82/12/10 82/12/08 82/12/09 82/12/10 82/12/07	50-287 50-325 50-395 50-333 50-389	P 8 9 0 A	8212160316 8212160323 8212160323 8212160334 8212160337	8212160304 8212160080 8212160322 8212160326 8212160080	82/12/14 82/09/30 82/12/13 82/12/10 82/09/30	50-352 FOIA 50-395 50-237 40-3265	O F Q
6212150137 6212150140 6212150142 6212150143 6212150148	8212150131 8212150131 8212150128 6212150138 8212150131	82/12/14 82/12/14 82/12/08 82/12/13 82/12/14	50-382 50-382 50-245 70-143 50-382	С С С	8212160341 8212160343 8212160346 8212160350 8212160350	8212140080 8212140080 8212140337 8212140080 8212140080	82/09/30 82/12/08 82/09/30 82/09/30	40-3265 F01A 50-334 40-3265 40-6500	P
8212150153 8212150158 8212150160 8212150163 8212150169	8212150131 8212150154 8212150155 8212150159 8212150159	82/12/14 82/12/09 82/12/02 82/12/02	50-382 50-335 - 50-29 50-309 50-309	0 8 0	8212160362 8212160370 6212160371 6212160372 8212160380	8212160080 8212160080 8212160358 8212160060 8212160080	85/09/30 85/09/30 85/09/30 85/09/30	40-6500 40-6500 50-245 FOIA POIA	8
8212150170 8212150171 8212150176 8212150183 8212150187	8212150164 8212150166 8212150174 8212150180 8212150181	82/12/13 82/12/10 82/12/09 82/12/03 82/12/07	50-275 50-445 50-271 50-250 50-277	P ዘ R F	8212140386 8212140388 8212140389 8212140391 6212140404	8212140090 8212140080 8212140080 8212140080 8212140097	82/09/30 82/09/30 82/09/30 82/09/30	FOIA 40-6500 50-311 FOIA 50-289	e e

	ACCESS10						N NUMBER			
	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEOOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
	8212100319 8212100327 8212100330 8212100332 8212100333	8212100312 8212100322 6212100324 8212100325 6212100329	82/12/01 82/12/03 82/12/02 82/12/02	50-237 50-315 50-454 50-346 50-461	8 0 8	8212130355 8212130357 8212130359 8212130341 8212130347	8212130352 8212130352 8212130358 8212130358 8212130366	82/12/07 82/12/07 82/12/07 82/12/07 82/12/06	50-286 50-286 50-352 50-352 50-344	FOGF
	8212100335 8212100337 8212100347 8212100368 8212100369	8212100328 8212100327 8212100343 8212100341 8212100342	82/12/01 82/11/23 82/11/15 82/12/03	50-265 50-461 Waste MG 50-373 FOLA	S G IT P	8212130349 8212130370 8212130372 8212130427 8212140015	8212130366 8212130366 8212130366 8212130424 8212140001	82/12/06 82/12/06 82/12/06 82/11/09 82/11/03	50-344 50-344 50-344 70-2926 FOIA	P P P
	9212100372 6212100363 6212100365 6212100394 6212100398	8212100345 8212100380 8212100380 8212100380	92/12/03 62/11/16 62/12/07 62/12/07 62/11/15	50-373 FOIA 50-313 50-313 FOIA	P F	8212140022 6212140031 6212140060 6212140060 6212140061	8212140001 8212140029 8212140048 8212140053 8212140055	82/11/03 82/12/07 82/12/09 82/11/24 82/12/09	FOIA 50-220 50-302 50-272 50-295	R R S
	8212100405 8212100407 8212100410 8212100411 8212100453	8212100399 8212100403 8212100403 8212100399 8212100414	92/12/07 92/11/09 92/11/09 92/12/07 92/11/30	50-344 40-8768 40-8768 50-344 50-346	F F	8212140070 8212140082 8212140082 8212140084 8212140085	8212140064 8212140068 8212140076 8212140074 8212140079	82/12/09 82/12/06 82/11/24 82/11/29 82/11/24	50-286 50-373 50-272 50-213 50-311	R P S G S
	8212100474 8212100481 8212130028 8212130036 6212130041	6212100414 6212100414 6212130017 6212130033 6212130017	62/11/30 62/11/30 62/12/07 62/11/30 62/12/07	50-346 50-346 50-10 50-508 50-10	P F K F	8212140095 8212140105 8212140107 8212140113 8212140120	6212140067 6212140098 6212140099 6212140098 6212140112	82/12/04 82/11/30 82/11/24 82/11/30 82/12/01	50-373 50-271 50-311 50-271 50-10	5 5 6 8
	9212130040 8212130041 8212130067 8212130071 8212130074	8212130059 8212130059 8212130062 8212130068 8212130068	82/12/04 82/11/23 82/11/05 82/11/05 82/11/30	50-320 71-9151 70-27 70-27 71-454	P	8212140123 8212140128 8212140131 8212140133 8212140138	8212140115 8212140117 8212140125 8212140124 8212140135	82/12/07 82/12/06 82/12/02 82/12/06 82/12/03	50-366 50-373 50-317 50-272 50-367	8 8 8 8
	8212130084 8212130095 8212130099 8212130102 8212130117	9212130081 6212130092 6212130092 6212130092 8212130111	82/12/07 82/11/27 82/11/29 82/11/29 82/11/23	\$0-333 \$0-309 \$0-309 \$0-309 \$0-346	R P P P	8212140140 8212140147 8212140147 8212140154 8212140154	8212140137 8212140142 8212140001 8212140150 8212140153	82/11/29 82/12/03 82/11/03 82/11/30 82/12/06	50-247 50-331 50-29 50-334 50-325	0 5 6 6 8
	8212130121 8212130124 8212130129 8212130137 6212130138	8212130111 8212130132 8212130132	82/11/23 82/11/23 82/11/17 82/12/03 82/11/17	50-346 50-346 71-6495 50-346 71-6495	P P F	821 21 40160 821 21 40161 821 21 40165 821 21 40175 821 21 40177	8212140150 8212140001 8212140156 8212140171 8212140167	82/11/30 82/12/04 82/12/03 82/12/03	50-334 FOIA 50-316 50-369 50-219	0 8 8
	8212130144 8212130153 8212130156 8212130160 8212130162	8212130132 8212130147 8212130147 6212130155 8212130161	82/12/03 82/12/03 82/12/03 82/12/01 82/12/07	50-346 50-295 50-295 CONTRACT 50-361	FFF	821 21 40187 821 21 40189 821 21 40191 621 21 40201 821 21 40202	8212140184 8212140182 8212140174 8212140194 8212140196	82/12/03 82/12/01 82/11/26 82/12/09 82/12/06	50-29 50-387 50-334 50-508 50-325	8 S S C S
	8212130164 8212130168 8212130171 8212130177 8212130182	8212130161 8212130161 8212130169 8212130175 8212130178	82/12/07 82/12/07 82/11/26 82/12/06 82/11/03	50-361 50-361 50-275 50-373 CONTRACT	P G R	821 21 40207 821 21 40221 821 21 40231 621 21 40234 621 21 40238	8212140198 8212140208 8212140224 8212140225 8212140232	82/12/08 82/12/09 82/12/09 82/12/09	50-328 50-245 50-373 50-333 50-97	8 0 0 R
	8212130185 8212130193 8212130198 8212130202 8212130209	8212130181 8212130188 8212130186 8212130196 8212130207	82/12/07 82/12/09 82/12/09 82/12/01 82/11/29	50-400 50-362 50-362 50-254 50-528	A P R Q	8212140239 8212140247 8212140248 8212140254 8212140257	8212140228 8212140241 8212140251 8212140253 8212140255	82/12/02 82/12/07 82/11/30 82/12/09 82/12/06	50-289 50-327 70-2895 50-329 50-324	5 8 A P
	8212130215 8212130220 8212130227 8212130227 8212130236	6212130207 6212130217 6212130223 6212130224 6212130231	82/11/29 82/12/06 82/12/09 82/12/03	50-528 TOPREP 50-29 50-255 50-295	G P P	8212140260 8212140261 8212140270 8912140271 8212140272	6212140259 8212140258 8212140269 8212140269 8212140265	82/12/09 82/12/03 82/11/30 82/11/30	50-29 50-387 50-361 50-321 50-361	P 5 5 6 9
	6212130240 6212130245 6212130246 6212130248 6212130250	6212130238 6212130242 6212130241 6212130243 6212130247	82/12/05 82/12/03 82/12/06 82/12/06	50-182 50-334 50-440 50-334 50-255	P P P R	621 21 40277 621 21 40283 621 21 40292 621 21 40312 621 21 40315	8212140278 8212140281 8212140289 8212140269 8212140311	62/12/08 62/12/10 62/12/09 62/12/08 62/11/30	50-275 50-275 50-373 50-413 50-320	P R Q A
	6212130254 6212130264 6212130265 6212130270 6212130267	8212130252 8212130243 8212130263 8212130269 8212130285	82/12/10 82/12/06 82/11/29 82/11/24 82/12/03	50-247 50-334 50-362 50-27 70-2957	9 9 9	8212140318 8212140319 8212140325 8212140327 8212140327	8212140263 8212140311 8212140268 8212140321 8212140326	82/12/08 82/11/30 82/12/03 82/12/08 82/11/23	50-413 50-320 50-387 50-295 50-373	A 0 8 8
	8212130289 8212130273 8212130274 8212130276 8212130302	8212130291 8212130291 8212130291 8212130296	82/12/06 82/12/06 82/11/24 82/11/24 82/12/10	50-275 50-275 50-187 50-187 TOPREP	P G G	8212140337 8212140338 8212140340 8212140345 8212140355	8212140322 8212140332 8212140335 6212140335 8212140346	92/11/29 82/12/03 92/11/30 82/11/30	50~423 50~331 50~358 50~358 50~344	0 8 A A S
1	9212130305 9212130317 9212130333 9212130342 9212130346	8212130336 8212130336 8212130336 8212130336 8212130336	82/12/04 82/12/09 82/12/09 82/12/07 82/12/07	50-275 50-261 50-206 50-298 50-298	P Q F F	821.21.40356 821.21.40357 821.21.40363 821.21.40368 821.21.40368	8212140351 8212140344 8212140351 8212140341 8212140360	82/12/07 82/12/06 82/12/07 82/12/09 82/12/02	50-312 50-263 50-312 50-327 50-206	P S P A S

VCCESE10	NUMBER				ACCESS10	N NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJEC CATEGO	RY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGOR	
8212140380 8212140383 8212140388 8212140393 8212140399	8212140374 8212140381 8212140374 8212140384 8212140396	82/12/07 82/12/10 82/12/07 82/12/10 82/12/09	50-537 50-498 50-537 50-247 50-151	A G G	82121 50193 82121 50200 82121 50204 82121 50213 82121 50213	8212150181 8212150175 8212150202 8212150207 8212150212	82/12/07 82/12/10 82/11/15 82/12/10 82/11/24	50-277 50-275 71-7081 50-220 71-5957	F
8212140400 8212140405 8212140406 8212140408 8212140413	8212140384 8212140398 6212140397 8212140404 8212110404	82/12/10 82/12/01 82/12/07 82/12/08 82/12/08	50-247 50-361 50-220 50-244 50-244	9 9 9 9 9	8212150224 8212150233 8212150240 8212150244 , 8212150252	8212150219 8212150219 8212150236 8212150238 8212150248	82/12/10 82/12/10 82/12/07 62/11/22 82/12/07	50-293 50-293 50-302 70-1151 50-243	G G P
B212140414 G212140417 B212140420 G212140427 B212140427	8212140396 8212140410 8212140404 6212140424 6212140421	82/12/09 82/12/08 82/12/08 82/12/07 82/11/30	50-151 50-409 50-244 50-412 50-366	0 9 9 8	82121 50257 82121 50280 82121 50268 82121 50278 82121 50278	6212150248 6212150272 6212150272 6212150273 6212150301	82/12/07 82/12/08 82/12/08 82/11/17 82/12/08	50-243 50-313 50-313 70-143 50-346	FFF
8212140434 8212140436 8212140437 8212140442 8212140444	8212140425 8212140433 8212140426 8212140435 8212140440	82/11/30 82/11/30 82/12/09 82/11/24 82/12/08	50-369 50-366 50-443 50-309 50-259	8 H 8 8 8	8212150329 8212150333 8212150333 6212160002 8212160016	6212150323 8212150326 8212150323 8212160001 8212160012	82/12/07 82/11/29 82/12/07 82/12/09 82/11/23	50-315 NUREO 50-315 50-315 71-9006	F F
6212140446 6212140448 6212140453 6212140466 6212140472	8212140439 8212140379 8212140435 8212140478 8212140490	82/12/10 82/12/07 82/11/24 82/11/23 82/11/29	50-247 50-271 50-309 50-259 50-410	6 E H G	8212140023 8212140028 8212140028 8212140041 8212140041	8212160026 8212160032 8212160032	82/11/30 82/11/19 82/11/19 82/11/30	71-170 71-486 71-9099 71-6003 71-5796	
8212140495 8212140497 8212140510 8212140517 8212150005	8212140490 8212140494 8212140581 8212140513 8212150003	82/11/29 82/11/23 82/11/11 82/11/19 82/12/13	50-410 50-387 PRØJ 71-4909 TOPREP	Q P	6212160054 6212160058 621216005 6212160082 6212160090	8212160048 8212160055 8212160060 8212160080 8212160080	82/12/01 82/12/10 82/10/29 82/09/30 82/09/30	50-311 50-277 40-3372 40-6500 FOIA	R
8212150011 8212150013 8212150018 9212150019 9212150025	8212150007 8212150008 8212150014 8212150015 8212150020	82/12/07 82/12/09 82/12/07 82/11/23 82/12/02	50-321 50-247 50-321 50-409 50-334	8 7 6 6	8212140094 0212140097 020121138 070121138 0212140103	8212160080 8212160080 8212160080 8212160080	82/09/30 82/09/30 82/09/30 82/09/30	F01A 40~6500 50~346 F01A 40~6500	۳
GRIE150027 GRIE150034 GRIE150037 GRIE150044 GRIE150047	8212150023 8212150028 8212150031 8212150038 8212150042	82/11/29 82/12/08 82/12/07 82/12/01 82/12/09	50-247 50-338 50-321 50-320 50-382	8 8 8 8	6212140107 6212140123 6212140133 6212140140 6212140140	9212160090 9212160080 9212160080 9212160090	85/04/30 85/04/30 85/04/30 85/04/30 85/15/08	50-346 40-4500 40-6500 40-6500 40-6500	F
8212150049 8212150050 8212150052 8212150053 8212150062	8212150040 8212150042 8212150048 8212150046 8212150058	82/12/09 82/12/09 82/12/10 82/12/13	50-112 50-382 50-338 50-302 50-277	0 F B P	8212140148 8212140160 8212140161 8212140168 8212140182	8212140134 8212140080 8212140080 8212140080 8212140080	62/11/12 62/09/30 62/09/30 62/09/30	71-454 FOIA 40-6500 40-6500 40-6500	
8212150064 6212150069 6212150072 6212150076 8212150078	8212150060 8212150066 8212150070 8212150071 8212150075	82/12/10 82/12/10 82/12/08 82/12/09 82/12/02	50-302 50-257 50-331 50-276 50-334	8 8 8	8212140185 8212140191 8212140193 8212140197 8212140214	9212140177 9212140080 9212140080 9212140080 9212140080	82/12/03 82/09/30 82/09/30 82/09/30 82/09/30	71-489 40-6500 40-6500 40-6500 40-6500	
B912150081 B212150084 B912150087 B212150091 B212150096	8212150077 8212150080 8212150067 8212150089 8212150094	62/12/08 82/12/01 62/12/08 62/12/08	50-395 50-247 50-281 50-395 50-338	8 8 8	8212160227 8212160240 8212160243 8212160243 8212160264	8515190080 8515190080 8515190080 8515190553	82/12/13 82/09/30 82/09/30 82/09/30	50-155 50-413 40-4500 40-6500 40-6500	0
8212150100 8212150102 8212150104 8212150108 8212150111	8212150097 8212150099 8212150101 8212150105 8212150107	62/12/08 82/12/07 82/12/10 82/12/07 82/12/09	50-395 50-302 50-260 50-302 50-294	8888	8212160270 8212160273 8212160284 8212160307 8212160315	8212160259 8212160080 8212160080 8212160080 8212160080	82/09/30 82/09/30 82/09/30 82/09/30	50-317 40-6500 40-6500 40-6500 40-6500	8
B212150113 B212150114 B212150122 B212150126 B212150134	9212150110 6212150112 8212150117 8212150121 6212150127	82/12/10 82/12/08 82/12/09 82/12/10 82/12/07	50-287 50-325 50-395 50-333 50-389	P 5 6 A	8212160316 8212160323 8212160327 8212160334 8212160337	8212140304 8212140080 8212140322 8212140324 8212140080	82/12/14 82/09/30 82/12/13 82/12/10 82/09/30	50-352 FOIA 50-395 50-237 40-3265	G F O
9212150137 8212150140 8212150142 8212150143 8212150148	8212150131 8212150131 8212150128 8212150138 8212150131	82/12/14 82/12/14 82/12/09 82/12/13 82/12/14	50-382 50-382 50-245 70-143 50-382	0 0 P	8212160341 8212160343 8212160345 8212160350 8212160352	8212160080 8212160339 8212160080 8212160080	82/09/30 82/09/30 82/12/08 82/09/30 82/09/30	40~3265 FDIA 50~334 40~3265 40~6500	P
8212150153 8212150158 8212150160 8212150163 8212150169	8212150131 8212150156 8212150155 8212150157 8212150159	82/12/14 82/12/07 82/12/06 82/12/02 82/12/02	50-382 50-335 - 50-29 50-309 50-309	0 8 0 0	8212140362 8212140370 8212140372 8212140372 8212140380	8212160080 8212160358 8212160358	82/09/30 82/09/30 82/12/10 82/09/30 82/09/30	40-6500 40-6500 50-245 FDIA FOIA	B
8212150170 8212150171 8212150176 8212150183 8212150187	8212150164 8212150166 8212150174 8212150180 8212150181	82/12/13 82/12/10 82/12/09 82/12/03 82/12/07	50-275 50-445 50-271 50-250 50-277	P K R R	8212140384 8212140388 8212140389 8212140391 8212140404	8212160080 8212160080 8212160381 8212160080 8212160397	82/09/30 82/09/30 82/12/01 82/09/30 82/12/03	FOIA 40-4500 50-311 FOIA 50-289	#3 Gr

ACCESSION	NUMBER			ACCESS10A	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 03UBB1	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGOR	
8212160414 8212160418 8212160419 8212160424 8212160432	8212160399 8212160407 8212160417 8212160080 8212160080	82/12/01 82/11/16 82/12/07 82/07/30 82/07/30	50-311	8212170129 8212170130 8212170131 8212170133 8212170139	8212170127 8212170122 8212170120 8212170120 8212170134	82/12/10 82/12/15 82/12/15 82/12/15	50~335 50-237 50~498 50~498 50~249	P 8 A A 8
8212160435 8212160436 8212160438 8212160459 8212160464	8212160080 8212160080 8212160437 8212160080 8212160080	82/09/30 82/09/30 82/11/30 82/09/30 82/09/30	40-6500 40-6500 71-9132 40-6500 40-6500	8212170140 8212170146 8212170150 8212170154 8212170156	8212170136 8212170137 8212170145 8212170148 8212170141	82/12/10 82/12/03 82/12/10 82/12/10	50-240 50-416 50-155 50-155 50-325	P 8 0 8
8212160466 9212160471 8212160477 8212160485 8212160486	8212160080 8212160080 8212160080 8212160080	82/09/30 82/09/30 82/09/30 82/09/30 82/12/03	40-6500 40-6500 FOIA 40-6500 50-277 G	8212170162 8212170165 8212170168 8212170171 8212170172	8212170148 8212170155 8212170164 8212170167 8212170161	82/12/03 82/12/03 82/12/15 82/12/10 82/12/09	50~155 50~364 50~206 50~305 50~266	0 \$ 5 8
8212160491 8212160493 8212160500 8212160505 8212160506	8212160480 8212160080 8212160080 8212160080 8212160080	82/12/03 82/09/30 82/09/30 82/09/30 82/09/30	50-277 Q FOIA FOIA 40-2116 40-6500	8212170176 8212170181 8212170187 8212170188 8212170189	8212170159 8212170177 8212170178 8212170179 8212170177	82/12/09 82/11/30 82/12/09 82/12/09 82/11/30	50~373 50~266 50~346 50~316 50~266	9 9 9 0
8212160510 8212160513 8212160521 8212160521	8212160080 8212160080 8212160515 8212160515	82/09/30 82/09/30 82/09/30 82/12/15 82/09/30	40-2116 40-2116 40-6500 50-382 0 40-2116	8212170194 8212170201 8212170202 8212170207 8212170213	8212170184 8212170196 8212170166 8212170197 8212170209	82/12/09 82/12/03 82/12/07 82/12/13 82/12/13	50-373 50-10 50-321 50-348 50-416	6 6 8 8
8212160527 8212160534 8212160541 8212160544 8212160551	8212140080 8212140080 8212140080	82/09/30 82/09/30 82/09/30 82/12/07 82/12/07	40-4500 40-1606 FOIA 50-278 P 50-278 P	8212170214 8212170223 8212170225 8212170227 8212170228	8212170211 8212170217 8212170218 8212170222 8212170222	82/12/10 82/12/03 82/12/03 82/12/03	50-373 50-275 50-249 50-416 50-316	8 R 8 8
8212140552 8212140540 8212140578 8212140581 8212140583	8212160080 8212160531 8212160568 8212160080	82/09/30 82/12/07 82/12/02 82/12/02 82/09/30	FOIA 50-278 P 50-364 P 50-364 P 40-6500	8212170232 8212170235 8212170237 8212170238 8212170238	8212170224 8212170231 8212170224 8212170233 8212170244	82/12/08 82/12/07 82/12/08 82/12/09 82/12/03	50-316 50-312 50-316 50-373 50-341	5 R S G
8212160586 8212160587 8212160608 8212160643 8212160734	8212160568 8212160080 8212160573 8212160634 8212160731	85/15/10 85/15/03 85/03/30 85/03/30	50-364 P 40-6500 CONTRACT COMMISSION 50-262 F	8212170253 8212170268 8212170270 8212170272 8212170275	8212170244 8212170267 8212170264 8212170271 8212170265	82/12/03 82/12/10 82/12/10 82/12/10 82/12/15	50-341 50-316 50-373 50-387 50-277	01 55 P
8212160742 8212160752 8212160764 8212160782 8212160787	8212160731 8212160745 8212160745 8212160772 8212160772	82/12/10 82/12/10 82/12/10 82/12/10 82/12/10	50-242 F 50-320 F 50-320 F 50-313 F 50-313 F	8212170276 8212170277 8212170280 8212170285 8212170284	8212170273 8212170263 8212170265 8212170282 8212170205	82/12/03 82/12/15 82/12/15 82/12/03	50-250 50-416 60-277 50-346 50-483	P 8 8 0
8212170010 8212170011 8212170016 8212170017 8212170018	8212170005 8212170004 8212170013 8212170014 8212170012	82/12/09 82/12/08 82/12/07 82/12/07 82/12/10	71-9132 70-2928 50-373 P 70-1143 50-313 F	8212170291 8212170292 8212170293 8212170294 8212170302	8212170287 8212170283 8212170288 8212170283 8212170297	82/12/10 82/12/15 82/12/15 82/12/16 82/12/10	50-395 50-315 50-482 50-315 50-344	8 8 8 8
9212170020 8212170025 8212170030 8212170034 8212170041	8212170014 8212170012 8212170013 8212170013 8212170036	82/12/07 82/12/10 82/12/09 82/12/09 82/12/10	70-1143 50-313 F 50-373 P 50-373 P 50-280 F	8212170304 8212170310 8212170311 8212170312 8212170320	8212170300 8212170305 8212170308 8212170307 8212170319	82/11/29 82/12/15 82/12/14 82/12/09 82/12/07	50-10 50-293 50-331 50-295 50-312	0 P B P
B212170044 B212170057 B212170060 B212170065 B212170076	8212170036 8212170042 8212170053 8212170053 8212170042	82/12/01 82/12/10 82/12/10 82/12/10	50-280 F 50-341 A 50-335 F 50-335 F 50-341 A	8212170322 8212170323 8212170327 8212170335 8212170339	8212170321 8212170321 8212170313 8212170330 8212170334	82/11/22 82/11/23 92/12/13 92/12/13	50-245 50-245 50-416 50-461 50-416	P 8 8 8
8212170079 8212170084 8212170089 8212170091 8212170094	8212170077 8212170042 8212170078 8212170088 8212130211	82/12/01 82/12/01 82/12/01 82/12/10 82/12/03	50-373 0 50-341 A 50-312 P 50-397 0 50-277 P	8212170342 8212170343 8212170350 8212170356 8212170359	8212170337 8212170338 8212170338 8212170338 8212170353	82/12/13 82/12/13 82/12/13 82/12/13 82/12/07	50-445 50-324 50-324 50-324 50-321	E P P R
8212170096 8212170099 8212170100 8212170101 8212170102	8212170087 8212170092 8212170088 8212130211 8212170097	82/11/30 82/12/07 82/12/03 82/12/04	50-255	8212170361 8212170363 8212170370 8212170376 8212170378	8212170354 8212170355 8212170354 8212170369 8212170373	82/12/02 82/12/02 82/12/02 82/12/02	50-508 50-324 50-508 50-204 50-275	о Р О О Н
8212170103 8212170108 8212170111 8212170112 8212170114	8212170088 8212170104 8212130211 8212170104 8212170107	82/12/10 82/12/10 82/12/03 82/12/03	50-397 Q 50-259 F 50-277 P 50-259 F 50-295 Q	8212170379 8212170383 8212170384 8212170386 8212170390	8212170374 8212170369 8212170369 8212170369 8212170388	82/12/09 82/11/30 82/11/30 82/11/30 82/12/07	50-397 50-206 50-206 50-206 50-327	A G G G R
8212170118 8212170121 8212170124 8212170126 8212170128	8212170106 8212170109 8212170120 8212170123 8212170120	82/12/02 82/12/15 82/12/15 82/12/16	50-454 0 50-295 0 50-498 A 50-373 S 50-498 A	8212170394 8212170397 8212170401 8212170402 8212170407	8212170391 8212170391 8212170398 8212170398 8212170404	85/11/13 85/11/53 85/11/53 85/15/03	50-361 50-361 CONTRACI CONTRACI 40-8745	

ACCESSIO					ACCESS 10	N NUMBER			
ENCLOSURE	PRINCIPAL DGCUMENT	DATE ISSUED	SUBJECT CATEGOR		Shift on the	PRINCIPAL	DATE	SUBJEC.	
8212170409 8212170448 8212170453 8212170457 8212170458	8212170405 8212170445 8212170445 8212170454 8212170454	82/12/13 82/12/10 82/12/10 82/12/13	40-6500 50-313 50-313 50-280 50-280	F F F F	ENCLOSURE 8212210171 8212210173 8212210183 8212210185 8212210185	DOCUMENT 8212210163 8212210167 8212210159 8212210180 8212210178	198UED 82/12/13 82/11/02 62/12/14 62/12/02 82/12/14	50-338 50-267 50-416 50-344 50-335	27 S Q S
8212170459 8212200011 8212200012 8212200013 6212200033	8212170443 8212200006 8212200005 8212200008 8212200022	82/11/08 82/12/03 82/12/03 82/11/08	40-8728 50-267 50-369 50-244 50-285	F 8 P 0	82:2210192 62:2210195 62:2210196 62:2210198 62:2210204	8212210179 8212210189 8212210188 8212210193 8212210197	82/12/14 82/12/02 82/12/07 82/12/07 82/12/02	50-414 50-508 50-321 50-348 50-341	8 8 8
8212200035 8212200037 8212200048 8212200049 8212200058	8212200025 8212200027 8212200042 8212200039 8212200051	82/11/02 62/12/13 62/12/15 62/12/14	50-267 50-338 50-312 50-443 50-440	F 8 R 9 H	8212210205 8212210207 8212210210 8212210211 8212210223	8212210203 8212210203 8212210203 8212210203	92/12/14 82/12/15 82/12/15 92/11/30 82/12/03	50-414 50-250 50-331 50-528 QA779	5 8 9
8912200062 8212200065 8212200072 8212200075	8212200040 8212200059 8212200056 8212200061 8212200070	82/11/30 82/12/13 82/12/14 82/12/15 82/12/15	TOPREP 50-205 50-316 50-440 50-255	R R G P	8212210227 8212210233 8212210234 8212210241 8213210246	8212210212 8212210229 8212210232 8212210236 8212210240	82/12/15 82/12/10 82/12/15 82/12/07 82/12/14	50-416 50-336 50-289 50-387 70-25	8 8 8
8515500042 8515500040 8515500089 8515500085	8212200070 8212200071 8212200076 8212200084 8212200080	82/12/15 82/12/08 82/12/01 82/11/02 82/12/15	50-255 50-335 50-456 50-267 50-275	P G G P	8212210250 8212210264 8212210264 8212210266 8212210267	8212210245 8212210257 8212210249 8212210263 8212210254	82/11/05 82/12/07 82/12/10 82/12/13 82/12/13	50-313 50-348 50-293 50-309 50-339	0 8 0 8
8212200101 8212200101 8212200115 8212200115	8212200109 8212200103 8212200103 8212200092	82/11/02 82/12/15 82/12/15 82/12/13 82/11/02	50-267 50-267 50-416 50-395 50-267	F 0 R 8 F	8212210274 8212210275 8212210282 8212210282 8212210283	8212210248 8212210270 8212210270 8212210278 8212210285	82/12/09 82/12/06 82/12/06 82/12/10 82/12/17	50-333 50-443 50-443 50-29 50-155	8 9 8 9
8212200117 8212200122 8212200125 8212200126 8212200127	8212200121 8212200121 8212200121 8212200121	82/11/02 82/12/14 82/12/03 82/12/03 82/12/03	50-267 50-315 50-382 50-382 50-382	F R G G	8212210272 8212210274 8212210279 8212210303 8212210314	8212210285 8212210285 8212210297 8212210294 8212210315	82/12/17 82/12/17 82/12/10 82/12/09 82/12/13	50-155 50-155 50-266 50-317 50-331	9 8 8 P
0212200128 8212200127 6212210005 6212210006 6212210008	8212200123 8212200121 8212210002 8212210004 8212210007	82/11/24 82/12/03 82/12/13 82/12/13 82/12/01	50-267 50-382 50-275 50-324 50-263	8 9 9	6212210323 6212210324 6212210327 6812210326 <i>821221033</i> 0	8212210325 8212210325 8212210325 8212210325	82/12/15 82/12/15 82/12/15 82/12/17 82/12/15	50~286 50~266 50~263 50~537 50~263	6666
8213210020 8212210024 8212210028 8213210031	8212210019 8212210021 8212210023 8212210027 8212210029	82/12/10 82/12/14 82/11/02 82/12/06 82/12/15	50-219 50-265 50-247 50-348 50-356	P 0 0 5	B212210333 8012210337 8212210339 8212210340 8212210342	8212210325 8212210325 8212210336 8212210329	82/12/15 82/12/15 82/12/17 82/12/02 82/12/15	50-263 50-263 50-267 50-282 50-263	44004
8212210032 8212210034 8212210044 8212210046 8212210057	8212210030 8212210033 8212210040 8212210043 8212210052	85/15/10 85/15/04 85/15/10 85/15/12	50-325 50-331 50-219 50-317 50-387	8 8 8 8	6212210346 6212210347 621221035 6812210357 6212210358	8212210325 8212210343 8212210349 8212210353 8212210352	82/12/15 82/12/07 82/12/06 62/11/18 82/12/10	50-263 50-387 50-309 0A979 50-331	9 0 8
8212210063 8212210065 8212210071 8212210074 8212210080	8212210057 8212210047 8212210070 8212210076	82/12/14 82/12/15 82/12/10 82/12/10 82/12/07	50-213 50-369 50-293 50-331 50-317	P R 8 8	6012210363 8012210366 6012210369 6012210367 8012210377	8212210360 8212210353 8212210361 8212210367 8212210372	82/12/16 82/11/18 82/12/16 82/12/14 82/12/08	50-391 0A999 50-346 50-416 50-219	0 8 8
6212210087 6212210088 6212210087 6212210096 6212210098	8212210084 8212210083 8212210084 8212210091 8212210091	82/12/02 82/12/02 82/12/02 82/12/02	50-219 50-321 50-219 6A999 6A999	0 6 0	8210210379 6212210384 6212210384 8212210386 6212210390	8212210376 8212210368 8212210378 8212210365 8212210376	82/12/06 82/12/13 82/12/08 82/12/13 82/12/06	70~687 50~280 50~317 50~260 70~687	8 8
8218210120 8212210108 8212210108 8212210100	8212210075 8212210071 8212210104 8212210102 8212210117	82/12/14 82/12/02 82/12/13 82/11/01 82/12/07	50-328 94999 50-373 50-247 50-348	5 G R 8	8212210394 8212210394 6212210397 6212210405 8212210410	8212210391 8212210369 8212210365 8212210379 8212210406	82/12/17 82/12/13 82/12/13 82/12/13 82/12/14	50~445 50~335 50~260 50~325 50~322	8 8 8
8212210123 8212210124 8212210132 8212210133 8212210134	8212210129 8212210128 8212210130 8212210114	82/11/24 82/12/10 82/12/10 82/12/05 82/12/06	50-275 50-237 50-364 50-247 50-277	9 0 P 8 0	8212210414 8212210423 8212210423 8212210425 8212210425	8212210404 8212210419 8212210422 8212210415 8212210416	92/12/14 92/12/15 92/12/15 92/12/13 92/12/08	50~322 50~370 50~400 50~333 50~397	# K C 8 0
8212210140 8212210141 8212210147 8212210153 8212210154	8212210117 8212210135 8212210137 8212210148 8212210145	82/12/04 82/12/02 82/12/13 82/12/10 82/12/08	50-247 GA999 50-336 50-293 50-369	8 8 8	8212210428 8212210448 8212210452 8212210450 8212210460	8212210421 8212210447 8212210446 8212210453 8212210456	82/12/15 82/11/30 82/12/07 82/12/14 82/12/15	50-269 50-317 50-366 50-219 50-244	R P B Q P
8212210159 8212210140 8212210162 8212210169 8212210170	8212210152 8212210157 8212210158 8212210144 8212210145	82/12/14 82/12/06 82/12/15 82/12/06 82/12/07	50-325 50-237 50-277 50-313 50-309	8 R 8	8212210462 8212210466 8212210468 8212210495 8212210495	8212210458 8212210463 8212210453 8212210471 8212210471	82/12/03 82/12/13 82/12/14 82/12/17 82/12/17	50-293 50-373 50-219 50-352 50-352	Q K Q A C

ACCESSIO	NUMBER				ACCES810N				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGORY	<u>, </u>
9212210499 9212210504 9212210514 9212210515 9212210521	8212210491 8212210501 8212210508 8212210512 8212210508	82/12/17 82/11/03 82/12/10 82/11/04 82/12/10	50-352 71-488 50-313 40-2061 50-313	K F	8212220470 8212220471 8212220472 8212220473 8212220474	8212220465 8212220464 8212220463 8212220466 8212220465	82/12/10 82/12/09 82/12/17 82/12/07 82/12/10	50-289 50-260 50-219	Paser
8212210534 8212210538 8212210537 8212210542 8212210545	8212210526 8212210535 8212210526 8212210536 8212210541	82/12/13 82/12/03 82/12/13 82/09/17 82/12/10	50-313 TOPREP 50-313 40-8064 50-358	F F	8218220475 8218220477 8218220478 8218220479 8218220493	8212220461 8212220465 8212220459 8212220476 8212220488	82/12/14 82/12/10 82/12/07 82/12/16 82/12/17	50-275 50-261 50-287 50-220 50-325	P
8212210547 8212210548 8212210552 8212210555 8212210557	8212210544 8212210544 8212210544 8212210550 8212210550	82/12/10 82/12/10 82/12/10 82/12/13 82/12/13	50-243 50-243 50-243 50-219 50-219	P P F F	8212220500 8212220504 8212220520 8212220520 8212220528	8212220498 8212220494 8212220517 8212220518 8212220522	82/12/16 82/12/17 82/12/16 82/12/07 82/12/07	50-395 50-325 50-295 71-488 CONTRACT	5 5 6
8212210579 8212210581 8212220002 8212220004 8212220007	8212210576 8212210576 8212220001 8212220001 8212220005	82/12/10 82/12/10 82/12/10 82/12/10 82/12/06	50-245 50-245 50-313 50-313 50-280	F F F Y	8212220534 8212220535 8212220538 8212220542 8212220544	8212230277 8212220524 8212220531 8212220536 8212230287	82/12/14 82/12/14 82/12/09 82/12/09 82/12/16	50-237 CONTRACT 71-487 CONTRACT 50-245	P
B212220013 B212220024 B212220027 B212220034 B212220042	8212220010 8212220018 8212220019 8212220025 8212220037	82/10/26 82/11/22 82/11/03 82/12/07 82/12/13	40-6500 CONTRACT CONTRACT CONTRACT 50-3		8212220553 8212220554 8212220566 8212220557 8212220558	8212220549 8212220552 8212220552 8212220552 8212220555	82/12/15 82/12/16 82/12/16 82/12/16 82/12/14	CONTRACT 50-387 50-387 50-387 COMMISSI	ም P P N
8212220046 8212220048 8212220046 8212220070 8212220073	6212220037 6212220045 6212220051 6212220051 8212220051	82/12/13 82/12/08 82/12/17 82/12/17 82/12/17	50-3 50-282 50-461 50-461 50-461	F T T T	821223028 821223031 821223033 821223033 821223033	8212230019 8212230023 8212230025 8212230020 6212230036	82/12/15 62/12/10 62/12/06 82/12/09 82/12/10	50-10 50-289 70-1201 50-289 71-484	F P
8218220134 8218220141 8218220190 8218220202 8218220210	8212220124 8212220138 8212220175 8212220175 8212220208	82/11/09 82/12/01 82/12/10 82/12/10 82/12/15	70-1143 50-312 50-10 50-10 50-317	g F F R	8212230042 8212230051 8212230057 8212230058 8212230061	8212230017 8212230044 8212230046 8212230047 8212230056	82/12/15 82/12/15 82/12/15 82/12/07 82/12/08	50-10 CONTRACT 50-309 50-275 50-320	F F P
8212220218 8212220225 8212220225 8212220227 8212220231	8212220213 8212220217 8212220220 8212220217 8212220212	82/11/24 82/12/17 82/12/16 82/12/17 62/12/14	50-397 50-275 50-247 50-275 50-10	0 P P P	8212230068 8212230076 8212230083 8212230076 8212230103	8212230046 8212230067 8212230067 8212230089 8212230085	82/12/15 82/12/14 82/12/14 82/12/13 82/12/07	50-309 50-369 50-369 50-213 70-1113	F F F
6212220237 6212220248 6212220248 6212220247 6212220302	8212220232 8212220224 8212220244 8212220296 8212220298	82/12/20 82/12/15 82/12/15 82/12/10 82/12/10	50-413 70-143 50-338 50-281 50-346	e s o f	8212230108 8212230110 8212230124 8212230134 8212230141	8212230093 8212230089 8212230093 8212230093 8212230134	82/12/15 82/12/13 82/12/15 82/12/15 82/12/13	50-269 50-213 50-269 50-269 70-1143	F F F
8212220308 8212220322 8212220322 8212220323	8212220298 8212220300 8212220314 8212220315 8212220315	82/12/10 82/12/16 82/12/16 82/12/10	50-346 50-272 50-302 50-409 50-409	F 5 5 F F	8212230150 8212230163 8212230165 8212230172 8212230176	6212230142 6212230155 6212230152 6212230152 6212230164	62/11/10 62/11/30 62/12/15 62/12/15 62/11/04	FO1A 40-2259 50-313 50-313 FO1A	F
8212220337 8212220354 8212220358 8212220348 6212220344	8212220328 8212220350 8212220350 8212220364 8212220376	82/12/17 82/12/07 82/12/07 82/12/16 82/12/16	50-395 50-244 50-244 50-337 50-395	8 0 9 8	8212230212 8212230230 8212230243 8212230248 8212230250	8515530550 8515530538 8515530538 8515530504	82/10/27 82/12/20 82/12/17 82/12/17 82/12/20	WASTE MG 50-277 50-29 50-27 50-277	T P P P
6212220365 6212220368 6212220370 6212220371 6212220376	8212220381 8212220383 8212220384 8212220387 8212220386	82/12/08 82/12/07 82/12/17 82/12/15 82/12/17	50-311 50-267 50-307 50-337 50-309	9 9 9	8212230264 8212230271 8212230274 6212230304 8212230326	8212230239 8212230248 8212230288 8212230298 8212230317	92/12/17 82/12/10 82/12/17 82/12/21 82/12/22	50-29 50-272 50-395 50-275 50-285	P
8212220397 8212220404 8212220405 8212220406 8212220406	6212220392 6212220403 6212220400 6212220395 6212220399	82/12/15 82/12/15 82/12/08 82/12/08 82/12/15	50-339 50-412 50-387 50-311 50-338	S A G S S	8212230333 8212230335 8212230334 8212230343 8212230359	8212230330 8212230330 8212230331 8212230342 8212230357	82/12/08 82/12/08 82/12/16 82/12/20 82/12/20	70-1143 70-1143 50-247 50-155 50-266	Ç P
8212220414 8212220416 8212220421 8212220424 8212220424	6212220411 6212220410 6212220415 6212220420 6212220422	82/12/15 82/12/08 82/12/16 82/12/16	50-395 50-338 50-287 50-311 50-266	8 8 F 8 B	8212230374 8212230377 8212230380 8212230410 8212230411	8212230369 8212230369 8212230379 8212230406 8212230404	82/12/15 82/12/15 82/12/06 82/12/06 82/11/22	50-331 50~331 40-8027 XPORTLIC 40-8084	F
8212220435 8212220437 8212220438 8212220442 8212220448	8212220433 8212220434 8212220434 8212220441 8212220440	82/12/08 82/12/17 82/12/14 82/12/17 82/12/14	50-311 70-135 50-275 50-335 50-275	9 8 P	6212270007 6212270010 6212270015 6212270017 6212270027	8212270003 8212270003 8212270013 8212270013 8212270018	82/12/16 82/12/16 82/12/16 82/12/16 82/12/07	50-305 50-305 50-382 50-382 71-490	FFF
8212220454 8212220462 8212220467 8212220468 8212220469	8212220449 8212220428 8212220464 8212220466 8212220459	92/12/10 92/12/14 92/12/09 92/12/07 82/12/09	50-320 50-395 50-287 50-219 50-289	0 0 8	8212270029 8212270030 8212270042 8212270047 8212270052	8212270026 8212270024 8212270038 8212270038 8212270048	82/12/16 82/11/02 82/10/27 82/10/27 82/11/19	70-2941 70-23 50-289 50-289 FOIA	P

ACCESSION NUMBER				ACCE8910A			
PRINCIP ENCLOSURE DOCUME		BUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8212270055 8212270 8212270056 8212270 8212270057 8212270 8212270065 8212270 8212270071 8212270	048 82/11/19 038 62/10/27 048 62/11/19 048 62/11/19	FOIA 50-287 FOIA FOIA 71-9015	P	8212270382 8212270384 8212270385 8212270399 8212270405	6212270377 6212270360 6212270361 6212270396 6212270401	62/11/29 62/12/22 62/12/10 62/12/10 62/11/22	71-7079 50-322 E 50-302 P 50-312 P 40-3453
8212270079 8212270 8212270080 8212270 8212270083 8212270 8212270084 8212270 8212270086 8212270)48 82/11/19)74 82/11/24)48 82/11/19	XPORTLIC FOIA 40-299 FOIA XPORTLIC		8212270411 8212270412 8212270417 8212270422 8212270422	8212270409 8212270410 8212270415 8212270419 8212270423	92/12/10 92/11/14 92/11/23 92/11/30 92/12/17	50-302 P CONTRACT CONTRACT CONTRACT 50-437 A
8212270088 8212270 8212270091 8212270 8212270095 8212270 8212270099 8212270 8212270107 8212270	048 82/11/19 048 82/11/19 048 82/11/19	FOIA FOIA FOIA FOIA		8212270426 8212270427 8212270429 8212270431 8212270434	8212270423 8212270421 8212270424 8212270428 8212270424	82/12/17 82/12/10 82/12/16 82/12/20 82/12/16	50-437 A 50-313 P 50-358 A 50-3 H 50-358 A
8212270110 8212270 8212270111 8212270 8212270112 8212270 8212270113 8212270 8212270114 8212270	108 82/12/11 178 82/12/03 108 82/12/11	FOIA 50-3 70-143 50-3 FOIA	P P	8212270438 6212270439 6212270442 6212270445 6212270447	8212270418 8212270432 8212270418 8212270418 8212270446	92/11/24 92/12/13 92/11/26 92/11/26 92/12/20	FOIA HISC FOIA FOIA CONTRACT
8212270116 8212270 8212270117 8212270 8212270123 8212270 8212270124 8212270 8212270127 8212270	08 82/12/11 048 82/11/19 078 82/12/03	70-143 50-3 FOIA 70-143 FOIA	P	8212270448 8212270453 8212270457 8212270461 8212270466	8212270418 8212270418 8212270418 8212270418 8212270418 8212270418	82/11/26 82/11/26 82/11/26 82/11/26 82/11/26	FOIA FOIA FOIA FOIA 50-327 O
8212270128 8212270 8212270131 8212270 8212270133 8212270 8212270148 8212270 8212270153 8212270	048 82/11/19 048 82/11/19 048 82/12/13		S P	8212270471 8212270486 8212270488 8212270501 8212270502	8212270418 8212270483 8212270483 8212270484 8212270496	82/11/26 82/12/14 82/12/14 82/11/05 82/12/17	F01A 50-344 F 50-344 F 50-537 A CONTRACT
8212270161 8212270 8212270163 8212270 8212270170 8212270 8212270176 8212270 8212270180 8212270	55 82/12/15 62 82/12/13 68 82/12/20		P P G P 8	8212270506 8212270513 8212270516 8212270521 8212270530	8212270503 8212270509 8212270510 8212270518 8212270527	82/12/16 82/12/17 82/12/07 82/12/17 82/11/03	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
8212270193 8212270 8212270194 8212270 8212270202 8212270 8212270203 8212270 8212270206 8212270	97 92/12/13 77 92/12/09 97 92/12/20	50-368 50-266	C 8 5 P	8212270532 8212270536 8212270543 8212270546 8212270556	8212270525 8212270525 8212270539 8212270542 8212270555	82/12/04 82/12/04 82/11/29 82/12/04 82/11/29	50-331 P 50-331 P CONTRACT 50-318 P CONTRACT
8212270207 8212270 8212270209 6212270 8212270213 8212270 8212270216 6212270 8212270223 8212270	201 82/12/16 299 82/12/02 212 82/11/30	50-334 QA999	P P Q	8212270560 8212260003 8212260004 8212260006 8212260007	8212270558 8212280002 8212280002 8212280002 8212280005	82/12/21 82/12/04 82/12/04 82/12/04 82/11/29	CONTRACT 50-263 F 50-263 F 50-263 F 50-271 F
8212270228 8212270 8212270246 8212270 8212270250 6212270 8212270254 6212270 8212270256 8212270	137 82/12/10 148 82/12/23 148 82/12/23	50-255 50-264 50-537 50-537 70-820	9 9 A A	8212280019 8212280016 8212280018	8212280007 8212280005 8212280007 8212280013 8212280007	82/11/29 82/11/29 92/11/29 82/10/16 82/11/29	40-1478 50-271 F 70-146 70-1193 70-146
8212270260 8212270 8212270266 8212270 8212270266 8212270 8212270280 8212270 8212270281 8212270	259 82/12/06 259 82/12/06 274 82/12/10		A P P R A	8212280021 8212280022 8212280024 6212280026 6212280027	8212280020 8212280007 8212280007 8212280007 8212280005	82/12/20 82/11/29 82/11/29 82/11/29 82/11/29	71~9852 70~146 70~146 70~146 50~271 P
8212270286 8212270 8212270288 8212270 8212270287 8212270 8212270290 8212270 8212270291 8212270	283 82/12/15 279 82/12/08 287 82/12/09	50-443 50-312 50-443 50-390 50-312	A R A A R	821 2280030 821 2280044 821 2280049 821 2280050 821 2280054	8212280009 8212280043 8212280047 8212280046 8212280046	82/11/29 82/12/15 82/12/15 82/12/07 82/12/07	70-146 CONTRACT CONTRACT 50-329 8 50-329 8
8212270299 B212270 8212270301 8212270 8212270303 8212270 8212270305 B212270 8212270307 6212270	94 82/12/20 95 82/12/14 92 82/12/10	50-275 50-275 50-237 50-237 50-237	P P a a a a	8212280057 8212280041 8212280042 8212280048 8212280071	8212280054 8212280059 8212280058 8212280066 8212280069	82/12/16 82/12/16 82/12/15 82/12/15	50-416 B 50-409 P 50-295 G 50-272 R 50-346 P
8212270308 8212270 8212270310 8212270 8212270312 8212270 8212270313 8212270 8212270318 8212270	196 82/12/20 196 82/12/20 195 82/12/16	50-456 50-275 50-275 50-237 50-456	о р о о	8212280074 8212280077 8212280081 8212280087 8212280088	8212280069 8212280075 8212280080 8212280084 8212280085	82/12/10 82/12/17 82/12/15 82/12/17 82/12/17	50-346 F 50-346 B 50-416 B 50-247 F 50-259 F
8212270320 8212270 8212270333 8212270 8212270336 8212270 8212270337 8212270 8212270338 8212270	928 82/11/15 928 82/11/15 931 82/12/02	50-445 FOIA FOIA 40-8084 50-269	G P	821 2280089 821 2280092 821 2280094 821 2280095 821 2280106	9212280083 9212280084 9212280083 9212280091 8212280099	82/12/20 82/12/17 82/12/20 82/12/20 82/12/20	50-255 P 50-247 F 50-255 P 50-409 Q 50-260 8
8212270337 8212270 8212270356 8212270 8212270361 8212270 8212270367 8212270 8212270370 8212270	154 82/12/06 158 82/12/20 165 82/12/16	50-305 50-373 50-247 50-29 50-346	9 9 9 P	8212280107 8212280113 8212280115 8212280116 8212280130	8212280103 8212280103 8212280114 8212280111 8212280122	82/12/20 82/12/20 82/12/15 82/12/21 82/12/22	50-155 P 50-155 P 50-301 8 50-327 8 50-336 0

ACCE8910				ACCESSION NU	MBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	PR: ENCLOSURE DE	INCIPAL COMENT	DATE 185VED	SUBJECT	
8212280134 8212280136 8212280140 8212280146 8212280152	8212280131 8212280133 8212280124 8212280142	82/12/16 82/12/21 82/12/17 82/12/15 82/12/17	50-155 0 50-328 5 50-280 8 50-368 8 50-280 8	8212280464 82: 8212280468 82: 8212280473 82: 8212280475 82:	12280460 12280465 12280467 12280466 12260469	82/12/15 82/12/14 82/12/23 82/12/16 82/11/15	50-387 50-305	S 5 6
8212260153 8212260154 8212260154 8212260161 8212260161	8212280147 8212280150 8212280151 8212280159 8212280158	82/12/20 82/12/16 82/12/16 82/12/16	50-259 8 50-416 8 50-341 6 50-366 8 50-266 8	8212280480 821 8212280487 821 8212280487 821	12280472 12280476 12280483 12280485 12280486	82/12/13 82/12/23 82/12/01 82/12/01	50-29 50~373	5 6 0
8212280163 8212260167 8212260171 8212260173 8212260175	8212280164 8212280164 8212280166 8212280168 8212280170	85/15/50 85/15/53 85/15/53 85/15/15	50-275 F 50-250 S 50-358 C TOPREP 50-250 S	8212280515 821 8212280516 821 8212290013 821	12280494 12280512 12280513 12270012 12270015	82/11/29 82/12/07 62/12/22 82/11/24 82/11/24	FOIA	A E
8515580509 8515580505 8515580148 8515580183	8212280177 8212280184 8212280174 8212280177 8212280175	82/12/16 82/12/20 82/12/23 62/12/17	50-416 S WASTE MOT 50-416 S 50-318 P 90-280 S	8212290038 821 8212270039 821 8212270042 821	12290030 12290030 12290036 12290030 12290030	85/15/03 85/15/03 85/15/03 85/15/03	50-206 FOIA 50-206	Q G G
8212280208 8212280213 8212280215 8212280214 8212280217	8212280200 8212280211 8212280179 8212280211	62/12/22 82/12/22 82/12/22 82/12/22	50-317 G 50-124 P 50-373 B 50-124 P 50-124 P	8212270064 821 8212270065 821 8212270068 821	12290053 12290060 12290060 12290060 12290060	82/09/21 82/11/30 82/11/30 82/11/30	50-244 50-250	0 8 0 5
8212280220 8212280221 8212280231 8212280239 8212280240	9212280214 8212280219 8212280227 8212280234 8212280236	82/12/20 82/12/15 82/12/20 82/12/17 82/12/22	50-10 G 50-247 R 50-373 S 50-346 S 50-462 A	8212270075 821 8212270075 821 8212270074 821	12290067 12290060 12290060 12290067 12290060	82/12/06 82/11/30 82/12/06 82/12/06	50-250 50-260 50-395	P G S P G
8212280243 8212280245 8212280246 8212280248 8212280249	8212280237 8212280241 8212280242 8212280237 8212280244	82/12/17 82/12/16 82/12/10 82/12/17 82/12/21	50-247 P 50-416 8 50-319 0 50-247 P 50-275 9	821227091 821 8212270085 821 8212270085 821	12270060 12270067 12270060 12290060 12270083	82/11/30 82/12/04 82/11/30 82/11/30 82/12/20	50-375 50-250	8 0 8 F
8212280250 8212280251 8212280256 8212280270	8212280247 8212280242 8212280253 6212280281 8212280275	82/12/15 82/12/10 82/12/16 82/12/15 82/12/20	50-346 B 50-315 0 50-409 B 50-346 S 50-259 P	8212290089 821 8212290090 821 8212290092 821	2290060 2290083 2290060 2290060	82/11/30 82/12/20 82/11/30 82/11/30	50-250 (50-250 (0 0 0
8212280297 8212280301 8212280307 8212280311 8212280314	8212280295 6212280297 8212280307 8212280308 8212260312	82/12/20 82/12/17 82/12/20 82/12/20	50-259 P 50-508 Q 50-313 P 50-416 8 50-416 8	8212290100 821 8212290101 821 8212290104 821	2290040 2290060 2290060 2290095 2290098	82/11/30 82/11/30 82/11/30 82/12/23 82/12/20	50-250 (50-250 (50-250 (50-266 f 50-275 f	D D P
8212280324 8212280332 8212280334 8212280352 8212280354	8212280319 8212280324 8212280327 8212280344 8212280347	82/12/20 82/12/27 82/12/20 82/12/20 82/12/23	50-440 9 50-247 0 50-416 8 50-416 8 50-387 P	8212290108 821 8212290107 821 8212290110 821	2290102 2290060 2290060 2290078 2290060	82/11/15 82/11/30 82/11/30 82/12/20 82/11/30	50-204 F 50-250 C 50-250 C 50-275 F 50-260 C	9 5
8212280364 8212280367 8212280373 8212280376 8212280381	821 2280359 821 2280351 821 2280363 821 2280374 821 2280375	82/12/17 82/12/21 82/12/14 82/12/06 82/12/10	50-335 8 50-269 P 50-410 8 50-382 0 50-461 0	8212270117 821 8212270116 921 8212270121 821	2270115 2270060	82/11/30 82/11/11 82/11/30 82/11/30	50-250 (50-387 F 50-250 (50-261 (50-250 (9 3 3
82122803B9 8212280390 8212280391 8212280392 8212280394	8212280384 8212280385 8212280388 8212280387 8212280380	82/12/16 82/12/21 82/12/21 82/12/14 82/12/15	50-416 S 50-320 G 50-244 P 50-321 B 50-369 B	8212290128 821 8212290129 821 8212290130 821	2270116 2270060 2290126	82/11/30 82/11/05 82/11/30 82/11/03 82/11/30	50-261 0 50-309 8 50-250 0 50-29 8 50-261 0	₹ 3
6212280397 6212280401 6212280411 6212280412 6212280413	8212280383 8212280396 8212280406 8212280402 8212280407	82/12/18 82/12/21 82/12/22 82/12/17 82/12/08	50-325 8 GA777 50-20 P 50-416 B 50-278 0	821 8212290137 821: 8212290138 821:	2270060 2270060 2270060	82/11/11 82/12/09 82/11/30 82/11/30 82/11/12	50-219 F 40-6422 50-250 G 50-261 G 50-336 F	a a
8212280415 8212280417 8212280419 8212280420 8212280425	8212280408 8212280403 8212280410 8212280409 8212280418	82/12/23 82/12/14 82/12/17 82/12/08 82/12/17	REVIEW ORP 50-387 8 50-344 P 50-298 0 50-335 6	8212290148 821 8212290152 821 8212290155 821	2290060 2290146 2290060	82/11/30 82/11/30 82/12/24 82/11/30 82/11/30	50-261 6 50-261 6 50-275 R 50-261 6	6 1 1
8212280430 8212280438 8212280437 8212280442 8212280442	8212280423 8212280434 8212280435 8212280432 8212280433	82/12/06 82/12/17 82/10/29 82/12/17 82/12/21	50-382 Q 50-409 P 40-8783 50-295 S 50-454 Q	8212290161 821 8212290164 821 8212290165 821	2290157 2290159 2290060	82/11/10 82/12/06 82/11/12 82/11/30 82/11/05	50-286 R 40-8452 50-327 R 50-261 G 50-244 R	}
8212280449 8212280455 8212280457 8212280461 8212280463	8212280447 8212280445 8212280454 8212280450 8212280456	82/12/16 82/11/03 82/12/17 82/12/17 82/12/16	50-379 8 CONTRACT 50-331 6 50-275 8 50-416 8	8212290170 821 8212290171 821 8212290172 821	2270060 2270168 2270060	82/11/30	50-250 R 50-280 Q 50-313 R 50-280 Q 50-280 Q	

ACCE9910	NUMBER				ACCESSION	I NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENGI GRIBE	PRINCIPAL	DATE	SUBJECT	
8212290181 8212290184 6212290185 8212290184 8212290193	8212270176 8212270060 8212270180 8212270182 8212270192	82/11/15 82/11/30 82/11/23 82/11/02 82/12/21	50-361 R 50-280 G 50-397 K 50-133 R 50-237 P		ENCLOGURE 	B212290408 B212290404 B212290404 B212290404 B212290412 B212290419	198UED 	50-219 G 50-334 S 50-546 G 50-440 G 50-315 R	
8212290194 8212290198 8212290199 8212290204 8212290206	8212270174 6212270192 6212270170 6212270201 6212270190	82/11/15 82/12/23 82/12/21 82/11/03 82/12/21	50-313 R 50-313 Q 50-237 P 50-344 R 50-237 P		8212290425 8212290427 8212290428 8212290429 8212290430	8212270420 8212270421 8212270417 8212270381 8212270416	82/12/27 82/12/13 82/11/12 82/12/27 82/12/16	50-358 A 50-267 P 50-315 R 50-358 Q 50-220 S	
8212290208 8212290209 8212290215 8212290216 8212290218	8212270203 8212270205 8212270170 8212270211 8212270214	82/12/17 82/12/23 82/12/21 82/11/09 82/11/02	50-329 A 50-275 P 50-237 P 50-305 R 50-275 R		8212290432 8212290433 8212290434 8212290437 8212290440	8212270421 8212270422 8212270417 8212270421 8212270426	82/12/13 82/12/23 82/11/12 82/12/13 82/12/15	50-267 P 50-293 Q 50-315 R 50-267 P 50-267 S	!
8212279230 8212279227 8212279228 8212279223 821227923	8212270220 8212270212 8212270217 8212270224 8212270225	82/11/10 82/12/13 82/11/12 82/11/09 82/11/08	50-409 R 50-348 S 50-316 R 50-245 R 50-334 R		B212270443 B212270444 B212270446 B212270448 B212270452	8212270435 8212270436 8212270441 8212270437 8212270447	82/12/14 82/12/22 82/12/20 82/12/15 82/12/23	50-272 Q 50-354 Q 50-387 S 50-334 S 50-245 P	
8212270236 8212270237 8212270240 8212270242 8212270243	8212270234 8212270231 8212270233 8212270237 8212270231	82/11/15 82/12/23 82/12/15 82/12/21 62/12/23	50-368 R 50-275 P 50-320 8 50-213 G 50-275 P		B212290454 B212290455 B212290456 B212290461 B212290462	8212270381 8212270447 8212270453 8212270453 8212270458	82/12/27 82/12/23 82/12/20 82/12/20 82/12/22	50-358 G 50-346 G 50-295 P 50-295 P 50-275 P	
8212290244 8212290250 8212290252 8212290255 8212290255	0212270238 0212270231 0212270248 0212270248 0212270248	82/11/15 82/12/23 82/12/17 82/12/17 82/12/17	50-280 R 50-275 P 50-338 P 50-338 P 50-338 P		8212270464 8212270465 8212270468 8212270474 8212270478	8212270453 8212270463 8212270463 8212270457 8212270472	82/12/20 82/12/14 82/12/14 82/12/27 82/11/08	50-295 P 50-387 Q 50-387 Q 50-281 Q 50-249 S	
8212290257 8212290258 8212290262 8212290264 8212290270	8212270253 6212270251 6212270253 6212270261 6212270267	82/11/17 62/12/16 62/11/17 62/12/27 82/12/22	50-244 R 50-29 B 50-266 R 50-280 G 50-155 P		8212290479 8212290490 8212290492 8212290499 8212290501	8212270477 8212270488 8212270488 8212270476 8212270476	82/12/15 82/12/15 82/12/15 82/12/14 82/12/14	50-217 0 50-193 0 50-193 0 50-335 P 50-335 P	
8212290273 8212290274 8212290278 8212290282 8212290287	8212290266 8212290267 8212290267 8212290275 8212290281	62/12/16 62/12/22 62/12/22 62/12/16 62/11/10	CONTRACT 50-195 P 50-195 P 50-217 9 50-259 R		8212290511 8212290513 8212290528 8212290530 8212290532	8212270507 8212270507 8212270525 8212270525 8212270525	82/12/20 82/12/03 82/12/03 82/12/03	50-295 F 50-295 F 50-311 P 50-311 P 50-311 P	
8212290268 8212290293 8212290299 8212290299	8212270283 8212270283 8212270283	82/12/20 82/12/20 82/12/20 82/12/20	50-312 P 50-334 G 50-312 P 50-312 P 50-3		8212290535 8212290534 8212300007 8212300029 8212300032	8212270534 8212270534 8212300004 8212300027 8212300027	82/12/13 82/12/23 82/12/23 82/12/08	50-250 P 50-250 P 50-312 Q QA999 QA999	
6212270303 6212270304 6212270308 6212270307 6212270315	8212290297 8212290291 8212290295 8212290307 8212290312	82/12/08 82/12/14 82/12/20 82/11/09 82/11/02	50-267 8 50-309 9 50-3 F 50-346 R 50-298 R		8212300036 8212300036 8212300042 8212300044 8212300047	8212300034 8212300031 8212300035 8212300031 8212300037	82/12/21 82/12/21 82/12/21 82/12/21	TBPREP 50-255 P 50-395 S 50-255 P 50-416 S	1
8212270314 8212270318 8212270323 8212270327 8212270331	8212270310 8212270317 8212270320 8212270322 8212270330	82/12/17 82/11/10 82/12/21 82/12/20 82/12/15	50-29 6 50-338 R 50-409 P 50-266 8 50-315 0		8212300048 8212300057 8212300062 8212300063 8212300065	8212300041 8212300052 8212300057 8212300058 8212300061	82/12/16 82/12/21 82/12/23 82/12/16 82/12/22	50-317 P 50-348 S 50-346 S 50-346 S 50-335 S	
8212270333 8212270335 8212270336 8212270340 8212270343	8212270327 8212270330 8212270332 8212270337 8212270341	82/12/20 82/12/15 82/12/17 82/12/13 82/12/27	50-247 8 50-315 6 50-266 6 50-334 8 50-358 6		8212300071 8212300075 8212300067 8212300090 8212300095	8212300048 8212300070 8212300084 8212300088 8212300071	82/12/17 82/12/23 82/12/22 82/12/21 82/12/16	50-250 P 50-508 Q 50-416 S 50-368 S 50-321 S	
B212290345 B212290348 B212290352 B212290353 B212290358	B212270344 B212270346 B212270351 B212270350 B212270355	82/11/16 82/12/16 82/12/15 82/12/22 82/12/15	50-237 E 50-254 G 70-820 50-320 G 50-316 E		8212300076 8212300102 8212300104 8212300111 8212300117	8212300093 8212300098 8212300099 8212300106 8212300114	82/12/22 82/12/21 82/12/23 82/12/23	50-369 B 50-366 B 50-337 B 50-298 B 50-416 B	1
8212290361 8212290363 8212290372 8212290379 8212290380	8212290357 8212290360 8212290366 8212290378 8212290376	82/12/22 82/12/14 82/12/23 82/12/13 82/12/17	50-335 F 70-1100 50-275 F 50-244 C 50-249 C		8212300123 8212300130 8212300132 8212300149 8212300177	8212300117 8212300126 8212300127 8212210309 8212300171	62/12/21 62/12/20 62/12/13 62/12/13	CONTRACT 50-338 8 CONTRACT 50-329 A 50-338 8	
8212290382 8212290383 8212290384 8212290385 8212290386	8212270373 8212270375 8212270378 8212270347 8212270347	82/12/15 82/12/13 82/12/13 82/12/10 82/12/17	50-334 8 50-244 0 50-271 8 50-249 8 50-249 0	 	8212300177 8212300168 8212300192 8212300194 8212300199	8212300167 8212300184 8212300170 8212300184 8212300167	82/12/20 82/12/20 82/12/17 82/12/20 82/12/20	50-10 F 50-416 P CONTRACT 50-416 P 50-10 F	,
8212270374 8212270400 8212270402 8212270405 8212270407	8212270391 8212270387 8212270393 8212270398 8212270398	82/12/14 82/12/17 82/12/23 82/12/13 82/11/22	50-247 F 50-295 (50-184 (50-247 F 50-237 8		8212300200 8212300201 8212300203 8212300210	8212300186 8212300197 8212300184 8212300204 8212300207	62/12/22 82/12/27 82/12/20 82/12/20 82/12/08	50-416 8 50-247 9 50-416 P 50-317 F 70-734	,

8212300225 8212300221 82/12/23 50-325 8212300227 8212300212 82/12/23 50-364 8212300228 8212300222 82/12/23 50-364 8212300231 8212300216 82/12/23 50-364 8212300236 8212300216 82/12/23 50-364 8212300236 8212300232 82/12/23 50-364 8212300236 8212300232 82/12/22 50-364 8212300240 8212300232 82/12/22 50-338 8212300241 8212300234 82/12/22 50-339 8212300247 8212300248 82/12/22 50-339 8212300259 8212300248 82/12/22 50-339 8212300259 8212300254 82/12/22 50-37 8212300259 8212300255 82/12/25 50-325 8212300260 8212300254 82/12/21 50-325 8212300261 8212300264 82/12/23 50-325 8212300274 8212300274 82/12/35 50-321 8212300275					
8212300211 8212300204 82/12/20 50-317 8212300213 8212300207 82/12/08 70-734 8212300214 8212300212 82/12/10 64979 8212300218 8212300217 82/12/10 64979 8212300220 8212300217 82/12/20 50-328 8212300223 8212300214 82/12/20 50-328 8212300227 8212300221 82/12/23 50-324 8212300228 8212300216 82/12/23 50-344 8212300231 8212300216 82/12/23 50-344 8212300231 8212300216 82/12/23 50-344 8212300231 8212300232 82/12/23 50-344 8212300231 8212300232 82/12/23 50-344 8212300234 8212300234 82/12/23 50-344 8212300240 8212300232 82/12/23 50-344 8212300240 8212300234 82/12/22 50-338 8212300247 8212300248 82/12/22 50-339 8212300248 <					
8212300213 8212300207 82/12/08 70-734 8212300214 8212300212 82/12/10 0A999 8212300218 8212300212 82/12/10 0A999 8212300220 8212300212 82/12/20 50-338 8212300223 8212300214 82/12/20 50-348 8212300225 8212300221 82/12/23 50-344 8212300227 8212300221 82/12/23 50-344 8212300221 8212300222 82/12/23 50-414 8212300221 82/12/23 50-414 82/12/23 50-414 8212300221 8212300224 82/12/23 50-344 8212300231 8212300232 82/12/23 50-344 8212300240 8212300234 82/12/22 50-338 8212300247 8212300234 82/12/22 50-338 8212300247 8212300245 82/12/22 50-338 8212300250 8212300251 82/12/20 50-537 8212300253 8212300251 82/12/20 50-537 821	ENCLOSURE	DOCUMENT	18SUED	CATEOD	RY
B212300213 B212300207 B2/12/08 70-734 B212300214 B212300212 B2/12/10 QA999 B212300218 B2/12/10 QA999 B212300218 B2/12/10 B2/12/10 QA999 B2/12/00220 B2/12/20 B2/12/20 S0-328 B212300220 B2/12/20 B2/12/20 S0-328 B212300225 B2/12/20 B2/12/20 S0-328 B2/12/20 B2/12/2		671755655	02/10/04	50 017	
B212300214 B212300212 B2/12/10 0A999 B212300218 B212300212 B2/12/10 0A999 B212300218 B212300212 B2/12/10 0A999 B212300220 B212300214 B2/12/20 50-326 B212300227 B212300221 B2/12/23 50-364 B212300227 B212300222 B2/12/23 50-364 B212300228 B212300222 B2/12/23 50-364 B212300220 B212300216 B2/12/23 50-364 B212300221 B2/12/23 50-344 B212300223 B2/12/23 50-364 B212300224 B212300232 B2/12/23 50-364 B212300224 B212300232 B2/12/23 50-364 B212300224 B212300234 B2/12/22 50-364 B212300240 B212300234 B2/12/22 50-339 B212300247 B212300248 B2/12/22 50-339 B212300249 B212300248 B2/12/22 50-339 B212300259 B212300254 B2/12/23					F
B212300218 B212300212 B2/12/00 0.0497 B212300220 B212300217 B2/12/20 50-338 B212300223 B212300214 B2/12/23 50-324 B212300225 B212300214 B2/12/23 50-324 B212300228 B212300214 B2/12/23 50-344 B212300228 B212300216 B2/12/23 50-344 B212300231 B212300216 B2/12/23 50-344 B212300231 B212300216 B2/12/23 50-344 B212300231 B212300232 B2/12/23 50-344 B212300240 B212300232 B2/12/22 50-338 B212300241 B212300237 B2/12/22 50-338 B212300247 B212300237 B2/12/21 50-339 B212300249 B212300248 B2/12/20 50-339 B212300249 B212300248 B2/12/20 50-339 B212300250 B2/12/20 50-325 B212300250 B2/12/20 50-325 B212300250 B2/12/20 50-325					
8212300220 8212300217 82/12/20 50-328 8212300223 8212300214 82/12/23 50-364 8212300227 8212300221 82/12/23 50-364 8212300228 8212300221 82/12/23 50-364 8212300223 8212300222 82/12/23 50-364 8212300223 82/12/23 50-416 82/12/23 50-364 8212300230 8212300216 82/12/23 50-364 8212300231 8212300232 82/12/22 50-364 8212300234 8212300234 82/12/22 70-39 8212300240 8212300234 82/12/22 70-25 8212300247 8212300245 82/12/22 50-339 8212300248 82/12/22 50-339 8212300259 8212300251 82/12/20 50-339 8212300259 8212300251 82/12/20 50-339 8212300259 8212300251 82/12/20 50-339 8212300259 8212300254 82/12/21 50-325 8212300250 82/					
B212300223 B21230021A B2/12/23 50-364 B212300225 B212300221 B2/12/23 50-325 B212300226 B212300221 B2/12/23 50-325 B212300228 B212300222 B2/12/23 50-344 B212300221 B212300216 B2/12/23 50-344 B212300231 B212300216 B2/12/23 50-344 B212300231 B212300232 B2/12/23 50-344 B212300236 B212300234 B2/12/22 50-339 B212300240 B212300234 B2/12/22 70-25 B212300241 B212300237 B2/12/22 50-339 B212300247 B212300248 B2/12/20 50-339 B212300249 B212300251 B2/12/22 50-339 B212300258 B212300258 B2/12/22 50-339 B212300259 B212300254 B2/12/22 50-325 B212300259 B212300254 B2/12/23 50-325 B212300250 B2/12/23 50-325 B212300274 B2/12/23 <t< td=""><td></td><td></td><td></td><td></td><td>8</td></t<>					8
B212300223 B21230021 B2/12/23 50-326 B212300227 B212300216 B2/12/23 50-344 B212300228 B212300216 B2/12/23 50-344 B212300231 B212300216 B2/12/23 50-344 B212300231 B212300216 B2/12/23 50-344 B212300236 B212300232 B2/12/23 50-344 B212300240 B212300234 B2/12/22 50-339 B212300241 B212300234 B2/12/22 50-339 B212300247 B212300234 B2/12/22 50-339 B212300247 B212300235 B2/12/22 50-339 B212300258 B212300251 B2/12/22 50-339 B212300259 B212300256 B2/12/23 50-339 B212300259 B212300256 B2/12/23 50-325 B212300259 B212300256 B2/12/23 50-325 B212300259 B212300256 B2/12/23 50-325 B212300259 B212300256 B2/12/23 50-325 B212300259 B212300256 B2/12/23 50-538 B212300259 B212300256 B2/12/33 50-508 B212300259 B212300256 B2/12/16 50-321 B212300274 B212300276 B2/12/16 50-321 B212300278 B212300276 B2/12/16 50-321 B212300278 B212300276 B2/12/16 50-321 B212300288 B212300276 B2/12/08 0A999 B212300288 B212300277 B2/12/16 50-321 B212300288 B212300277 B2/12/16 50-321	DETEROUNES		DEF (8/K9	00 000	_
B212300227 B212300216 B2/12/23 B0-364 B212300228 B212300222 B2/12/23 B0-416 B212300231 B212300216 B2/12/23 B0-416 B212300236 B212300216 B2/12/23 B0-364 B212300240 B212300232 B2/12/22 B0-338 B212300240 B212300234 B2/12/22 B0-338 B212300241 B212300237 B2/12/21 B0-338 B212300247 B212300248 B2/12/22 B0-338 B212300247 B212300248 B2/12/22 B0-338 B212300258 B212300254 B2/12/23 B0-338 B212300258 B212300254 B2/12/23 B0-338 B212300258 B212300254 B2/12/23 B0-325 B212300259 B212300254 B2/12/23 B0-325 B212300257 B212300254 B2/12/23 B0-325 B212300257 B212300254 B2/12/23 B0-328 B212300274 B212300256 B2/12/23 B0-328 B212300275 B212300268 B2/12/23 B0-328 B212300276 B212300276 B2/12/16 B0-321 B212300278 B212300276 B2/12/16 B0-321 B212300288 B212300277 B2/12/16 B0-321 B212300288 B212300278 B2/12/16 B0-321 B212300288 B212300278 B2/12/16 B0-321 B212300288 B212300278 B2	212366223	B212300214	92/12/23	50~344	6
B212300238 B212300212 B2/12/23 B0-414 B212300231 B212300216 B2/12/23 B0-364 B212300236 B212300216 B2/12/23 B0-364 B212300236 B212300234 B2/12/22 70-25 B212300240 B212300234 B2/12/22 70-25 B212300240 B212300234 B2/12/22 70-25 B212300241 B212300234 B2/12/22 50-339 B212300247 B212300245 B2/12/22 50-339 B212300259 B212300251 B2/12/22 50-339 B212300259 B212300254 B2/12/23 50-339 B212300259 B212300254 B2/12/21 50-325 B212300259 B212300254 B2/12/21 50-325 B212300259 B212300254 B2/12/21 50-325 B212300259 B212300254 B2/12/21 50-325 B212300259 B212300255 B2/12/21 50-325 B212300274 B212300256 B2/12/21 50-325 B212300274 B212300257 B2/12/21 50-325 B212300275 B212300271 B2/12/21 50-321 B212300276 B212300271 B2/12/16 50-321 B212300278 B212300276 B2/12/16 50-321 B212300278 B212300276 B2/12/08 0A999 B212300280 B212300276 B2/12/08 0A999	1212300225	6212300221	82/12/23	50-325	6
B212300231 B212300216 B2/12/23 50-364 B212300236 B212300216 B2/12/23 50-364 B212300238 B212300232 B2/12/22 50-338 B212300240 B212300237 B2/12/22 70-25 B212300241 B212300237 B2/12/22 50-339 B212300247 B212300248 B2/12/22 50-339 B212300249 B212300248 B2/12/22 50-339 B212300249 B212300254 B2/12/22 50-339 B212300259 B212300254 B2/12/22 50-339 B212300259 B212300254 B2/12/20 50-325 B212300250 B212300254 B2/12/20 50-325 B212300260 B212300254 B2/12/20 6A979 B212300270 B212300271 B2/12/12 50-321 B212300274 B212300275 B2/12/16 50-321 B212300275 B2/12/16 50-321 B212300276 B2/12/16 50-321 B212300278 B2/12/16 50-321 <				50-364	S
B212300236					S
8212300240 8212300234 82/12/22 50-338 8212300241 8212300245 82/12/21 50-339 8212300247 82/12/21 50-339 8212300247 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/20 50-339 8212300258 8212300254 82/12/20 50-339 8212300259 8212300254 82/12/20 50-325 8212300259 8212300254 82/12/20 50-325 8212300257 8212300257 82/12/20 50-325 8212300257 8212300257 82/12/20 50-339 8212300257 8212300254 82/12/20 50-339 8212300257 8212300254 82/12/20 50-339 8212300275 8212300276 82/12/16 50-321 8212300275 8212300276 82/12/16 50-321 8212300278 82/12/20 804999 8212300278 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300277 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 80499 8212300280 82/12/20 80499 82/1	212300231	8212300216	82/12/23	50-364	S
8212300240 8212300234 82/12/22 50-338 8212300241 8212300245 82/12/21 50-339 8212300247 82/12/21 50-339 8212300247 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/22 50-339 8212300245 82/12/20 50-339 8212300258 8212300254 82/12/20 50-339 8212300259 8212300254 82/12/20 50-325 8212300259 8212300254 82/12/20 50-325 8212300257 8212300257 82/12/20 50-325 8212300257 8212300257 82/12/20 50-339 8212300257 8212300254 82/12/20 50-339 8212300257 8212300254 82/12/20 50-339 8212300275 8212300276 82/12/16 50-321 8212300275 8212300276 82/12/16 50-321 8212300278 82/12/20 804999 8212300278 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300277 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 804999 8212300280 8212300270 82/12/20 80499 8212300280 82/12/20 80499 82/1	AFCONFEICE	#91990091#	82/19/22	50-244	8
### 12300240 ### 12300234 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 70-25 ### 12/22 50-339 ### 12/2200247 ### 12/22 50-339 ### 12/2200258 ### 12/2200258 ### 12/2200259 ### 12/2200256 ### 12/22 50-325 ### 12/2200265 ### 12/22 50-325 ### 12/2200265 ### 12/22 50-325 ### 12/2200267 ### 12/22 50-325 ### 12/2200267 ### 12/22 50-339 ### 12/2200267 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-339 ### 12/2200277 ### 12/22 50-321 ### 12/2200277 ### 12/2200277 ### 12/2200277 ### 12/2200277 ### 12/2200278 ### 12/2200279 ### 12/2200289 ### 12/2200279 ### 12/2200289 ### 12/2200289 ### 12/2200289 ### 12/2200289 ### 12/2200289 ### 12/2200289 ### 12/2200279 ### 12/2200289 ### 12/2200279 ### 12/2200289 ### 12/2200279 ### 12/2200289 #### 12/2200279 #### 12/2200289 #### 12/2200279 #### 12/2200289 #### 12/2200279 #### 12/2200289 #### 12/2200279 #### 12/2200289 #### 12/2200279 #### 12/2200289 ##### 12/2200279 ##### 12/2200289 ####################################					5
8212300241 8212300237 82/12/21 50-339 8212300247 8212300248 82/12/22 50-339 8212300247 8212300248 82/12/22 50-339 8212300248 82/12/22 50-339 8212300258 82/12/22 50-339 8212300258 82/12/22 50-339 8212300259 8212300254 82/12/21 50-325 8212300259 8212300257 82/12/21 50-325 8212300260 8212300257 82/12/21 50-325 8212300260 8212300261 82/12/22 50-338 8212300260 8212300261 82/12/23 50-321 8212300274 8212300266 82/12/23 50-321 8212300275 8212300276 82/12/23 50-508 82/12/23 50-508 8212300276 8212300276 82/12/23 50-508 8212300276 8212300276 82/12/23 50-508 8212300276 8212300276 82/12/23 50-508 82/12/23 50-508 8212300276 8212300276 82/12/23 50-508 82/12/23					٠
### ### ### ### ### ### ### ### ### ##					6
8212300249					6
8212300255 8212300251 82/12/82 50-339 8212300259 8212300254 82/12/82 50-339 8212300259 8212300254 82/12/82 50-325 8212300259 8212300257 82/12/83 50-325 8212300242 8212300257 82/12/83 50-325 8212300261 82/12/83 50-325 8212300261 82/12/82 50-338 8212300270 8212300261 82/12/82 50-338 8212300270 8212300268 82/12/83 50-508 8212300275 8212300276 82/12/16 50-321 82/12/16 50-321 8212300276 8212300276 82/12/16 0A999 8212300280 8212300276 82/12/08 0A999 8212300280 8212300276 82/12/08 0A999 8212300280 8212300276 82/12/08 0A999 8212300280 8212300276 82/12/08 0A999 8212300280 8212300277 82/12/16 50-321					_
8212300288 8212300254 82/12/06 0A999 8212300259 8212300254 82/12/21 50-325 8212300254 82/12/21 50-325 8212300252 82/12/23 50-325 82/12/23 50-325 82/12/23 50-325 82/12/23 50-325 82/12/23 50-325 82/12/23 50-326 82/12/23 50-326 82/12/23 50-326 82/12/23 50-508 82/12/23 50-5	1212300249	8212300248	82/12/30	50-537	В
8212300289 8212300256 82/12/21 50-325 8212300262 8212300257 82/12/23 50-325 8212300263 82/12/23 50-325 8212300263 82/12/22 50-338 8212300267 82/12/24 50-338 82/12/24 50-321 8212300274 82/12/16 50-321 82/12/36 8				50-339	В
### ### ### ### ### ### ### ### ### ##					
8212300253 8212300254 82/12/08 QA999 8212300267 8212300261 82/12/16 50-338 8212300274 8212300265 82/12/16 50-321 8212300275 8212300268 82/12/16 50-321 8212300275 8212300271 82/12/16 50-321 8212300278 8212300276 82/12/08 QA999 8212300280 8212300276 82/12/08 QA999 8212300280 8212300276 82/12/08 QA999 8212300281 8212300276 82/12/08 GA999					S
8212300247 8212300241 82/12/22 50-338 8212300270 8212300245 82/12/16 50-321 8212300274 6212300248 82/12/23 50-568 8212300275 6212300271 82/12/16 50-321 8212300278 6212300274 82/12/08 0A999 8212300280 8212300274 82/12/08 0A999 8212300281 6212300275 82/12/08 0A999	1212300262	8212300257	82/12/23	50-325	8
### ### #### #########################	1242300263	821230025A	82/12/08	04999	
8212300270 8212300265 82/12/16 50-321 8212300274 8212300268 82/12/23 50-508 8212300275 8212300271 82/12/16 50-321 8212300278 8212300276 92/12/08 0A999 8212300280 8212300276 82/12/08 0A999 8212300281 8212300277 82/12/16 50-321					s
8212300274 8212300268 82/12/23 50-508 8212300275 8212300271 82/12/16 50-321 8212300278 8212300276 92/12/08 0A999 8212300280 8212300276 92/12/08 0A999 8212300281 8212300277 82/12/16 50-321		8212300265	82/12/16		5
8212300278 8212300276 92/12/08 0A999 8212300280 8212300276 92/12/08 0A999 8212300281 8212300277 92/12/16 50-321	212300274		82/12/23		ä
9212300280 8212300274 82/12/08 GA999 9212300281 8212300277 82/12/16 50~321	212300275	8212300271	82/12/16	50-321	8
2212300280 8212300274 82/12/08 GA999 9212300281 8212300277 82/12/16 50~321					
82123002B1					
					_
32123UU207 U212300287 U2/12/16 50-321					6
					8

ACCESS10	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJEC	
8212300291	8212300284	82/12/22	50-339	8
6212300292	8212300285	82/12/14	50~366	s
6212300296	8212300272	82/12/23	50-261	Š
8212300278	8212300295	82/12/14	50-366	5
8515300305	8515300301	82/12/08	QA999	-
8212300303	8212300301	82/12/08	QA999	
8212300307	8212300307	82/12/21	50-325	S
8212300312	8212300311	82/12/14	50-341	Α
8212300315	6212300313	02/12/21	50-338	5
8212300317	8515300319	82/12/23	50-325	5
8212300318	8515300308	82/12/23	50-397	G
8212300324	8212300320	02/12/23	50-50B	G
8212300325	8212300323	02/12/14	50-366	5
8212300334	8212300331	82/12/23	50-325	S
9515300339	8515300358	85/15/51	50-321	8
8212300337	8212300329	82/12/16	50-321	s
8212300339	8212300335	82/12/27	50~289	Р
8212300341	8212300332	82/11/03	50-155	R
8212300342	8212300335	82/12/27	50-289	Р
8212300345	8212300340	82/12/16	50-366	S
8212300346	8212300344	82/12/16	50-366	5
8212300348	6212300335	82/12/27	50-289	P
6212300353	8212300350	82/12/23	50-312	Q
8212300355	8512300351	82/12/23	50-327	ρ
8212300359	8212300357	85/15/53	50-327	P
8212300405	8212300400	82/12/22	50-254	F
8212300408	8212300407	82/12/22	50~387	F
8212300409	8212300400	82/12/22	50-254	F
8212300410	8212300407	82/12/22	50-387	F
8212300416	8212300412	82/12/22	50-282	F

8212300417 8212300412 82/12/22 50-282 F

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

A

- 3. Transmittal and acknowledgement letters
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process,

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications
- 2 Changes in structure of organization
- 3. Changes in service lists
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments
- 2 Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence fails in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings,
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3 Periodic personnel exposure reports.
- 4 Operational Logbooks.

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2 Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50 55e
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item 1
- 3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators
- 2. NRC examination results.
- Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license
- 2. Application to dismantle the facility and dispose of component parts
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning
- 4. Documents relating to disposal of radioactive material and decontamination of the site
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
 fuel and other radioactive materials associated with spent storage in an independent spent fuel
 storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
 site.)
- 2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record, record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

I. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

n

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978,

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. 1&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance

NOTE For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and energency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- Correspondence between NRC's Office of Standards Development and other government
 agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority
 to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.
- NOTE. For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- I Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited

Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also define at etechniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide
- 5 Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4, "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are.

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

the Commission's activities and interaction with State ate Agreements Program, whereby States may assume uclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes.

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE. For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category,

LUDO DOS					
NRC FORM 335 US NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		NUREG-0540			
4 TITLE AND SUBTITLE (Add Volume No. if expropriate) Title List of Documents Made Publicly Availab) o	2 (Leave blank)			
December 1-31, 1982	re	3 RECIPIENT'S ACCESSION NO			
7 AUTHOR(S)	- +	5 DATE REPORT C	OMPLETED YEAR		
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS <i>Unclude</i> Division of Technical Information and Document Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555	DATE REPORT ISSUED MONTH YEAR March 1983 6 (Leave blank)				
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include	Zip Code)	10 PROJECT/TASK/	WORK UNIT NO		
Same as 9, above.		11 FIN NO			
13 TYPE OF REPORT	PERIOD COVER	RED (Inclusive dates)			
Monthly	1				
15 SUPPLEMENTARY NOTES		14 (Leave plank)			
This document is a monthly publication contain received and generated by the U.S. NRC. This material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	information or plants and received The follow	n includes (1) nd other uses o and generated b ving indexes ar	docketed of radio- oy NRC re included:		
17 KEY WORDS AND DOCUMENT ANALYSIS	17a DESCRIPTOF	ts			
176 IDENTIFIERS: OPEN-ENDED TERMS					
18 AVAILABILITY STATEMENT	Uncl	Y CLASS IThis reports	21 NO OF PAGES		
Unlimited	20 SECURIT	Y CLASS (This page) assified	22 PRICE S		